
Title List of Documents Made Publicly Available

January 1-31, 1984

Office of Administration
U.S. Nuclear Regulatory Commission



Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

January 1-31, 1984

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	xv
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	11
Domestic Licensing of Special Nuclear Material — Docket 70	390
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	397
Licensing of Independent Spent Fuel Storage — Docket 72	399
Nondocketed Items	401
10 CFR — Commission Meeting Records	401
ACRS — Advisory Committee on Reactor Safeguards	401
ADVCM — NRC Advisory Committees	403
COMMISSION — NRC Commissioners	403
CONTRACT — NRC Contracts and Modifications	405
FOIA — Freedom of Information Act Requests and Releases	410
GEN TECH IS — Generic Technical Issues	428
I&E — Inspection and Enforcement	430
MISC — Public Document Room Miscellaneous	432
NUREG — NUREG Reports and Related Correspondence	433
ORG — Correspondence with Other Organizations	450
PR — Proposed Rule	452
PRM — Petition for Rulemaking	453
PROJ — Projects - Predocket Licensing	454
PT21 — Noncompliance Reports and Related Correspondence	454
QA999 — Quality Assurance Inspections	456
REGGD — Regulatory Guides	463
REVIEW GROUP — NRC Research Review Groups	463
SECY — Position Papers Before the Commission	464
STATE PROG — State Programs	468
TOPREP — Vendor Reports and Related Correspondence	469
WASTE MGT — Nuclear Waste Management	472
XPORTLIC — Export and Import Licenses	478
Personal Author Index	481
Corporate Source Index	513
Report Number Index	543
Cross Reference of Enclosures to Principal Documents	545
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

- ① P. Operating license stage documents & correspondence

② 8203090028 ③ Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
④ MILLS, L. M. ⑤ Tennessee Valley Authority. ⑥ 82/03/04. ⑦ VASSALLO, D.B.
Operating Reactors Branch 2 ⑧ 1p. 1216:254. 24XFiche: 50-259, 82/03/04,
8203090028
⑨ ⑩ ⑪ ⑫

- 1 NRC/PDR Document category (see Appendix A).
- 2 NRC Accession Number (year, month, day, and sequence number of item).
- 3 Description of information contained in the document.
- 4 Personal author(s) An asterisk in this position indicates that there is no personal author.
- 5 Corporate, agency or nonindividual source
- 6 Date of document described.
- 7 Recipient of document and NRC or corporate affiliation
- 8 Pages in this document.
- 9 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10 This three digit portion of this entry is the number of the frame on which this document starts.
- 11 The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS


The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are

- ICC FR -- Commission Meeting Records
- ACRS -- Advisory Committee on Reactor Safeguards
- COMMISSION -- NRC Commissioners
- CONTRACT -- NRC Contracts and Modifications
- DISCLOSURE -- Financial Disclosure Information
- OIA -- Freedom of Information Act Requests and Releases
- ENTECH IS -- Generic Technical Issues

I&E — Inspection and Enforcement
 MISC — Public Document Room Miscellaneous
 NUREG — NUREG Reports and Related Correspondence
 ORG — Correspondence with Other Organizations
 PR — Proposed Rule
 PRM — Petition for Rulemaking
 PROJ — Projects—Predocket Licensing
 PT21 — Noncompliance Reports and Related Correspondence
 QA999 — Quality Assurance Inspections
 REGGD — Regulatory Guides
 RES — Research and Technical Assistance Reports
 REVIEW GRP — NRC Research Review Groups
 RM — Rulemakings
 SECY — Position Papers Before the Commission
 STATE PROG — State Programs
 TOPREP — Vendor Reports and Related Correspondence
 WASH — Regulatory Publications—Pre-NUREG Series
 WASTE MGT — Nuclear Waste Management
 XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8046	West Bank Radiation Therapy Center, Minneapolis, MN	
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8064	Exxon Minerals Co., USA, Houston, TX	
27-047	Barnwell, SC Chem-Nuclear Systems, Inc.	1	40-8084	Rio Algom Corp., Moab, UT	
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8102	Exxon Co., USA, Houston, TX	
Domestic Licensing of Source Material — Docket 40			40-8331	African Metals Corp., New York, NY	
40-0017	Dow Chemical Co., Midland, MI	1	40-8348	Minerals Exploration Co., Los Angeles, CA	
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1	40-8452	Bear Creek Uranium Co., Casper, WY	
40-0281	Thiokol Corp., Danvers, MA	4	40-8584	Minerals Exploration Co., Los Angeles, CA	
40-0299	Union Carbide Corp., Grand Junction, CO	4	40-8585	Wyoming Mineral Corp., Lakewood, CO	
40-0672	Nuclear Metals, Inc., Concord, MA	4	40-8586	Kerr-McGee Nuclear Corp., Oklahoma City, OK	
40-1162	Western Nuclear, Inc., Jeffrey City, WY	5	40-8602	Silver King Mines, Inc., Casper, WY	
40-1478	Spencer Chemical Co., Kansas City, MO	5	40-8610	Stepan Chemical Co., Maywood, NJ	
40-1790	Wellman Dynamics Corp., Creston, IA	5	40-8631	Army, Dept. of, Rock Island, IL	
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	5	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	
40-2259	Pathfinder Mines Corp., Riverton, WY	6	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	
40-2298	Sprague Electric Co., North Adams, MA	6	40-8745	Ogle Petroleum, Inc., Casper, WY	
40-3453	Atlas Minerals, Inc., Denver, CO	6	40-8760	Edlow International Co., Washington, DC	
40-4492	Federal-American Partners, Riverton, WY	7	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	
40-5508	Myerson Tooth Corp., Cambridge, MA	7	40-8801	Radiation Management Corp., Northbrook, IL	
40-5577	Massachusetts Institute of Technology, Cambridge, MA	7	40-8821	Resource Engineering, Inc., Waltham, MA	
40-6500	Energy, Dept. of, Canonsburg, PA	7	40-8824	Target Research, Inc., Wharton, NJ	
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	7	40-8829	Wyoming Fuel Co., Lakewood, CO	
40-6659	Getty Oil Co.-Petrochemicals Co., Shirley Basin, WY	7	40-8833	Manlabs, Inc., Cambridge, MA	
40-6920	Automation Industries, Inc., Phoenixville, PA	7	Domestic Licensing of Production and Utilization Facilities— Docket 50		
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	7	50-3	Indian Point Station, Unit 1	
40-7455	Whittaker Metals, Los Angeles, CA	7	50-5	Pennsylvania State Univ. Research Reactor	
40-7580	Fansteel, Inc., North Chicago, IL	8	50-10	Dresden Nuclear Power Station, Unit 1	
40-7982	Honeywell, Inc., Hopkins, MN	8	50-13	Babcock & Wilcox Co. Critical Facility	
40-8011	Air Force, Dept. of, Eglin AFB, FL	8			

Docket	Name	Page	Docket	Name	Page
50-16	Enrico Fermi Atomic Power Plant, Unit 1	14	50-245	Millstone Nuclear Power Station, Unit 1	38
50-20	Massachusetts Institute of Technology Research Reactor	14	50-247	Indian Point Station, Unit 2	40
50-29	Yankee-Rowe Nuclear Power Station	14	50-249	Dresden Nuclear Power Station, Unit 3	41
50-70	General Electric Test Reactor	16	50-250	Turkey Point Plant, Unit 3	43
50-87	Westinghouse Critical Experiment	16	50-251	Turkey Point Plant, Unit 4	45
50-112	Univ. of Oklahoma Research Reactor	16	50-252	Univ. of New Mexico Research Reactor	48
50-113	Univ. of Arizona Research Reactor	16	50-254	Quad-Cities Station, Unit 1	48
50-116	Iowa State Univ. Research Reactor	16	50-255	Palisades Nuclear Plant	49
50-123	Univ. of Missouri Research Reactor	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-124	Virginia Polytechnic Institute Training Reactor	16	50-260	Browns Ferry Nuclear Power Station, Unit 2	55
50-129	West Virginia Univ. Research Reactor	17	50-261	H. B. Robinson Plant, Unit 2	58
50-131	Omaha Veterans Administration Hospital Research Reactor	17	50-262	Brigham Young Univ. Research Reactor	61
50-133	Humboldt Bay Power Plant, Unit 3	17	50-263	Monticello Nuclear Generating Plant	61
50-134	Worcester Polytechnic Institute Research Reactor	18	50-264	Dow Chemical Co.	63
50-142	UCLA Training Reactor	18	50-265	Quad-Cities Station, Unit 2	63
50-146	Saxton Nuclear Experimental Facility	19	50-266	Point Beach Nuclear Plant, Unit 1	65
50-148	Univ. of Kansas Research Reactor	19	50-267	Fort St. Vrain Nuclear Generating Station	67
50-155	Big Rock Point Nuclear Plant	19	50-269	Oconee Nuclear Station, Unit 1	69
50-160	Georgia Institute of Technology Research Reactor	22	50-270	Oconee Nuclear Station, Unit 2	71
50-166	Univ. of Maryland Research Reactor	22	50-271	Vermont Yankee Nuclear Power Station	72
50-170	National Naval Medical Center	22	50-272	Salem Nuclear Generating Station, Unit 1	74
50-184	National Bureau of Standards Reactor	22	50-274	U. S. Geological Survey Research Reactor	77
50-186	Univ. of Missouri Research Reactor	23	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	77
50-187	Space Radiation Research Reactor	23	50-276	Georgia Tech Research Reactor	82
50-199	Manhattan College Research Reactor	23	50-277	Peach Bottom Atomic Power Station, Unit 2	82
50-201	West Valley Reprocessing Plant	23	50-278	Peach Bottom Atomic Power Station, Unit 3	84
50-206	San Onofre Nuclear Station, Unit 1	23	50-280	Surry Power Station, Unit 1	85
50-213	Haddam Neck Plant	25	50-281	Surry Power Station, Unit 2	89
50-219	Oyster Creek Nuclear Power Plant	28	50-282	Prairie Island Nuclear Station, Unit 1	92
50-220	Nine Mile Point Nuclear Station, Unit 1	30	50-285	Fort Calhoun Station, Unit 1	95
50-237	Dresden Nuclear Power Station, Unit 2	33	50-286	Indian Point Station, Unit 3	97
50-243	Oregon State Univ. Research Reactor	35	50-287	Oconee Nuclear Station, Unit 3	99
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35	50-288	Reed College Research Reactor	100
			50-289	Three Mile Island Nuclear Station, Unit 1	100
			50-293	Pilgrim Nuclear Power Station, Unit 1	108

Docket	Name	Page	Docket	Name	Page
50-294	Michigan State Univ. Research Reactor	111	50-338	North Anna Power Station, Unit 1	204
50-295	Zion Nuclear Power Station, Unit 1	111	50-339	North Anna Power Station, Unit 2	206
50-296	Browns Ferry Nuclear Power Station, Unit 3	113	50-341	Enrico Fermi Atomic Power Plant, Unit 2	209
50-297	North Carolina State Univ. PULSTAR Reactor	116	50-344	Trojan Nuclear Plant	211
50-298	Cooper Nuclear Station	116	50-346	Davis-Besse Nuclear Power Station, Unit 1	213
50-301	Point Beach Nuclear Plant, Unit 2	118	50-348	Joseph M. Farley Nuclear Plant, Unit 1	216
50-302	Crystal River Nuclear Plant, Unit 3	120	50-352	Limerick Generating Station, Unit 1	220
50-304	Zion Nuclear Power Station, Unit 2	124	50-353	Limerick Generating Station, Unit 2	228
50-305	Kewaunee Nuclear Power Plant	126	50-354	Hope Creek Nuclear Station, Unit 1	234
50-306	Prairie Island Nuclear Station, Unit 2	129	50-355	Hope Creek Nuclear Station, Unit 2	235
50-309	Maine Yankee Atomic Power Plant	131	50-358	William H. Zimmer Nuclear Station, Unit 1	235
50-311	Salem Nuclear Generating Station, Unit 2	133	50-361	San Onofre Nuclear Station, Unit 2	239
50-312	Rancho Seco Nuclear Generating Station	136	50-362	San Onofre Nuclear Station, Unit 3	241
50-313	Arkansas Nuclear One, Unit 1	138	50-364	Joseph M. Farley Nuclear Plant, Unit 2	244
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	142	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	247
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	145	50-367	Bailly Generating Station	251
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	147	50-368	Arkansas Nuclear One, Unit 2	251
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	150	50-369	William B. McGuire Nuclear Station, Unit 1	254
50-320	Three Mile Island Nuclear Station, Unit 2	152	50-370	William B. McGuire Nuclear Station, Unit 2	257
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	156	50-373	LaSalle County Station, Unit 1	259
50-322	Shoreham Nuclear Power Station	159	50-374	LaSalle County Station, Unit 2	262
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	164	50-382	Waterford Generating Station, Unit 3	265
50-324	Brunswick Steam Electric Plant, Unit 2	167	50-387	Susquehanna Steam Electric Station, Unit 1	268
50-325	Brunswick Steam Electric Plant, Unit 1	171	50-388	Susquehanna Steam Electric Station, Unit 2	271
50-326	Univ. of California at Irvine Research Reactor	175	50-389	St. Lucie Plant, Unit 2	273
50-327	Sequoyah Nuclear Plant, Unit 1	176	50-390	Watts Bar Nuclear Plant, Unit 1	276
50-328	Sequoyah Nuclear Plant, Unit 2	178	50-391	Watts Bar Nuclear Plant, Unit 2	280
50-329	Midland Plant, Unit 1	180	50-395	Virgil C. Summer Nuclear Station, Unit 1	285
50-330	Midland Plant, Unit 2	187	50-397	WPPSS Nuclear Project, Unit 2	288
50-331	Duane Arnold Energy Center	193	50-400	Shearon Harris Nuclear Power Plant, Unit 1	291
50-332	Barnwell Reprocessing Plant	195	50-401	Shearon Harris Nuclear Power Plant, Unit 2	294
50-333	James A. Fitzpatrick Nuclear Power Plant	195	50-402	Shearon Harris Nuclear Power Plant, Unit 3	296
50-334	Beaver Valley Power Station, Unit 1	197	50-403	Shearon Harris Nuclear Power Plant, Unit 4	296
50-335	St. Lucie Plant, Unit 1	199	50-406	Tuskegee Institute Research Reactor	296
50-336	Millstone Nuclear Power Station, Unit 2	201	50-407	Univ. of Utah Research Reactor	296

Docket	Name	Page	Docket	Name	Page
50-409	La Crosse Boiling Water Reactor	296	STN-50-483	Callaway Plant, Unit 1	364
50-410	Nine Mile Point Nuclear Station, Unit 2	299	STN-50-486	Callaway Plant, Unit 2	368
50-412	Beaver Valley Power Station, Unit 2	300	STN-50-488	Perkins Nuclear Station, Unit 1	368
50-413	Catawba Nuclear Station, Unit 1	302	STN-50-489	Perkins Nuclear Station, Unit 2	368
50-414	Catawba Nuclear Station, Unit 2	305	STN-50-490	Perkins Nuclear Station, Unit 3	368
50-416	Grand Gulf Nuclear Station, Unit 1	309	50-496	Montague Nuclear Power Station, Unit 1	368
50-417	Grand Gulf Nuclear Station, Unit 2	313	50-497	Montague Nuclear Power Station, Unit 2	368
50-423	Millstone Nuclear Power Station, Unit 3	314	STN-50-498	South Texas Project, Unit 1	368
50-424	Vogtle Electric Generating Plant	316	STN-50-499	South Texas Project, Unit 2	370
50-425	Vogtle Electric Generating Plant	318	STN-50-508	WPPSS Nuclear Project, Unit 3	372
50-433	UC-Santa Barbara Research Reactor	320	STN-50-509	WPPSS Nuclear Project, Unit 5	373
STN-50-437	Floating Nuclear Plant	320	50-513	WPPSS Nuclear Project, Unit 4	373
50-438	Bellefonte Nuclear Plant, Unit 1	320	50-514	Pebble Springs Nuclear Plant, Unit 1	374
50-439	Bellefonte Nuclear Plant, Unit 2	323	50-515	Pebble Springs Nuclear Plant, Unit 2	374
50-440	Perry Nuclear Power Plant, Unit 1	326	STN-50-518	Hartsville Nuclear Plant, Unit 1	374
50-441	Perry Nuclear Power Plant, Unit 2	329	STN-50-519	Hartsville Nuclear Plant, Unit 2	374
50-443	Seabrook Nuclear Station, Unit 1	331	STN-50-520	Hartsville Nuclear Plant, Unit 3	374
50-444	Seabrook Nuclear Station, Unit 2	334	STN-50-521	Hartsville Nuclear Plant, Unit 4	374
50-445	Comanche Peak Steam Electric Station, Unit 1	336	50-522	Skagit Nuclear Power Project, Unit 1	375
50-446	Comanche Peak Steam Electric Station, Unit 2	339	50-523	Skagit Nuclear Power Project, Unit 2	375
STN-50-447	GESSAR-238	341	STN-50-528	Palo Verde Nuclear Station, Unit 1	375
STN-50-454	Byron Station, Unit 1	341	STN-50-529	Palo Verde Nuclear Station, Unit 2	380
STN-50-455	Byron Station, Unit 2	345	STN-50-530	Palo Verde Nuclear Station, Unit 3	384
STN-50-456	Braidwood Station, Unit 1	348	50-537	Clinch River Breeder Reactor	387
STN-50-457	Braidwood Station, Unit 2	350	STN-50-546	Marble Hill Nuclear Station, Unit 1	387
50-458	River Bend Station, Unit 1	352	STN-50-547	Marble Hill Nuclear Station, Unit 2	389
50-459	River Bend Station, Unit 2	356	STN-50-553	Phipps Bend Nuclear Station, Unit 1	390
50-460	WPPSS Nuclear Project, Unit 1	358	STN-50-554	Phipps Bend Nuclear Station, Unit 2	390
50-461	Clinton Power Station, Unit 1	358	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	390
50-462	Clinton Power Station, Unit 2	360	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	390
50-463	Fulton Generating Station, Unit 1	360	STN-50-584	GIBBSAR, Gibbs & Hill	390
50-464	Fulton Generating Station, Unit 2	360	Domestic Licensing of Special Nuclear Material — Docket 70		
STN-50-470	CESSAR System 80	361	70-0025	Rockwell International Corp., Canoga Park, CA	390
TN-50-482	Wolf Creek Generating Station	361	70-0027	Babcock & Wilcox Co., Lynchburg, VA	390
			70-0036	Combustion Engineering, Inc., Windsor, CT	391

Docket	Name	Page	Docket	Name	Page
70-0083	Harvard Univ., Cambridge, MA	391	70-2876	Veterans Administration Hospital, Brooklyn, NY	396
70-0113	Pennsylvania State Univ., University Park, PA	391	70-2887	Phelps County Memorial Hospital, Rolla, MO	396
70-0121	Interior, Dept. of, Denver, CO	391	70-2945	Union Electric Co., St. Louis, MO	396
70-0135	Babcock & Wilcox Co., Apollo, PA	391	70-2946	Louisiana Power & Light Co., New Orleans, LA	396
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	391	70-2949	Arizona Public Service Co., Phoenix, AZ	396
70-0364	Babcock & Wilcox Co., Apollo, PA	392	70-2955	Edlow International Co., Washington, DC	396
70-0368	Navy, Dept. of, Annapolis, MD	392	70-2972	Commonwealth Edison Co., Chicago, IL	396
70-0371	UNC Naval Products, Inc., Uncasville, CT	392	70-2973	Commonwealth Edison Co., Chicago, IL	396
70-0398	Commerce, Dept. of, Washington, DC	392	70-2984	Arizona Public Service Co., Phoenix, AZ	396
70-0687	Union Carbide Corp., Tuxedo, NY	392	70-2985	Duke Power Co., Charlotte, NC	396
70-0698	Westinghouse Electric Corp., Pittsburgh, PA	392	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions -- Docket 71		
70-0712	Kerr-McGee Nuclear Corp., Oklahoma City, OK	392	71-0001	ANEFco, Inc.	397
70-0734	GA Technologies, Inc., San Diego, CA	392	71-0096	Pan American World Airways, Inc.	397
70-0754	General Electric Co., Pleasanton, CA	393	71-0251	Westinghouse Electric Corp.	397
70-0820	United Nuclear Corp., Wood River Junction, RI	393	71-0510	Gesellschaft fur Nuklear Service	397
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	394	71-0511	Deltak Corp.	397
70-0938	Massachusetts Institute of Technology, Cambridge, MA	394	71-4909	Model: GE-21PF-1, General Electric Co.	397
70-1113	General Electric Co., Wilmington, NC	394	71-5450	Model: RCC -1, -2, -3, -4, Westinghouse Electric Corp.	397
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	394	71-5797	Model: Inner & Outer HPFR UN, Energy, Dept. of	397
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	394	71-5800	Model: ORNL Tritium Target Container	397
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	395	71-5939	Model: GE-1500, General Electric Co.	397
70-1201	Babcock & Wilcox Co., Lynchburg, VA	395	71-5957	Model: BMI-1, Battelle Columbus Laboratory	398
70-1257	Exxon Nuclear Co., Inc., Richland, WA	395	71-6058	Model: B-3, U.S. Ecology, Inc.	398
70-1308	General Electric Co., San Jose, CA	395	71-6346	Model: PSV-1, GA Technologies, Inc.	398
70-1331	Veterans Administration Medical Center, Buffalo, NY	395	71-6574	HN-200, Hittman Nuclear & Development Corp.	398
70-1409	Veterans Administration Medical Center, Buffalo, NY	395	71-9010	Model: NLI-1/2, NL Industries, Inc.	398
70-1470	Veterans Administration Hospital, Los Angeles, CA	395	71-9016	Model: TN-9, No Users	398
70-1795	George Washington Univ., Washington, DC	395	71-9044	Model: GE-1600, General Electric Co.	398
70-2427	John F. Kennedy Memorial Hospital, Stratford, NJ	395	71-9071	Model: AP-101, ANEFco, Inc.	398
70-2786	General Electric Co., San Jose, CA	395	71-9073	Model: OH-142, Nuclear Packaging, Inc.	398
			71-9080	Model: HN-600, NUPAC 7-100 & CNS 7-100, Hittman Nuclear & Development Corp.	398

Docket	Name	Page	Docket	Name	Page
71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	398	71-9165	Model: 855, Technical Operations, Inc.	399
71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	398	71-9175	Model: CNS6-80B, Nuclear Packaging, Inc	399
71-9093	Model: HN-400, Hittman Nuclear & Development Corp.	398	71-9181	Model: PAS-2, Nuclear Packaging, Inc.	399
71-9107	Model: 771, Technical Operations, Inc.	398	71-9183	Model: 9183, Duke Power Co.	399
71-9134	Model: ETR, Exxon Nuclear Idaho Co.	398	71-9184	Model: PAS-1, Nuclear Packaging, Inc.	399
71-9143	Model: 920, Technical Operations, Inc.	399	71-9190	Model: CASTOR V, Gesellschaft Fuer Nuklear Service, MKH	399
71-9148	Model: 770, Technical Operations, Inc	399	71-9853	Model: ORNL, BNL & NBS UNIR. CONT, Energy, Dept. of	399
71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	399	72-0001	Morris Operations, General Electric Co.	399
71-9160	Model: 20-VS & 40-VS, Gulf Nuclear, Inc.	399	72-0002	Virginia Electric & Power Co.	399
71-9161	Model: R, Gulf Nuclear, Inc.	399			

Licensing of Independent Spent Fuel Storage — Docket 72

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites -- Docket 27			Minerals Exploration Co., Los Angeles, CA	40-8348	9
Barnwell, SC, Chem-Nuclear Systems, Inc	27-047	1	Minerals Exploration Co., Los Angeles, CA	40-8584	9
Richland, WA, U.S. Ecology, Inc	27-048	1	Myerson Tooth Corp., Cambridge, MA	40-5508	7
Sheffield, IL, U.S Ecology, Inc	27-039	1	Nuclear Metals, Inc., Concord, MA	40-0672	4
Domestic Licensing of Source Material -- Docket 40			Ogle Petroleum, Inc., Casper, WY	40-8745	10
African Metals Corp., New York, NY	40-8331	9	Pathfinder Mines Corp., Riverton, WY	40-2259	6
Air Force, Dept. of, Eglin AFB, FL	40-8011	8	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	7
Army, Dept. of, Rock Island, IL	40-8631	10	Radiation Management Corp., Northbrook, IL	40-8801	11
Atlas Minerals, Inc., Denver, CO	40-3453	6	Resource Engineering, Inc., Waltham, MA	40-8821	11
Automation Industries, Inc., Phoenixville, PA	40-6920	7	Rio Algom Corp., Moab, UT	40-8084	8
Bear Creek Uranium Co., Casper, WY	40-8452	9	Silver King Mines, Inc , Casper, WY	40-8602	10
Dow Chemical Co., Midland, MI	40-0017	1	Spencer Chemical Co , Kansas City, MO	40-1478	5
Edlow International Co., Washington, DC	40-8760	10	Sprague Electric Co., North Adams, MA	40-2298	6
Energy Fuels Nuclear, Inc , Denver, CO	40-8681	10	Stepan Chemical Co., Maywood, NJ	40-8610	10
Energy, Dept. of, Canonsburg, PA	40-6500	7	Target Research, Inc., Wharton, NJ	40-8824	11
Exxon Co., USA, Houston, TX	40-8102	8	Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	10
Exxon Minerals Co., USA, Houston, TX	40-8064	8	Thiokol Corp., Danvers, MA	40-0281	4
Fansteel, Inc., North Chicago, IL	40-7580	8	Union Carbide Corp., Grand Junction, CO	40-0299	4
Federal-American Partners, Riverton, WY	40-4492	7	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Getty Oil Co.-Petrochemicals Co., Shirley Basin, WY	40-6659	7	Wellman Dynamics Corp., Creston, IA	40-1790	5
Honeywell, Inc., Hopkins, MN	40-7982	8	West Bank Radiation Therapy Center, Minneapolis, MN	40-8046	8
Kawecki Berylco Industries, Inc., Boyertown, PA	40-6940	7	Western Nuclear, Inc., Jeffrey City, WY	40-1162	5
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	5	Whittaker Metals, Los Angeles, CA	40-7455	7
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8586	9	Wyoming Fuel Co., Lakewood, CO	40-8829	11
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	10	Wyoming Mineral Corp., Lakewood, CO	40-8585	9
Manlabs, Inc., Cambridge, MA	40-8833	11	Domestic Licensing of Production and Utilization Facilities -- Docket 50		
Massachusetts Institute of Technology, Cambridge, MA	40-5577	7	Arkansas Nuclear One, Unit 1	50-313	138
			Arkansas Nuclear One, Unit 2	50-368	251
			Babcock & Wilcox Co. Critical Facility	50-13	13

Name	Docket	Page	Name	Docket	Page
		1			
Bailly Generating Station	50-367	251	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	142
Barnwell Reprocessing Plant	50-332	195	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	145
Beaver Valley Power Station, Unit 1	50-334	197	Dow Chemical Co.	50-264	63
Beaver Valley Power Station, Unit 2	50-412	300	Dresden Nuclear Power Station, Unit 1	50-10	12
Bellefonte Nuclear Plant, Unit 1	50-438	320	Dresden Nuclear Power Station, Unit 2	50-237	33
Bellefonte Nuclear Plant, Unit 2	50-439	323	Dresden Nuclear Power Station, Unit 3	50-249	41
Big Rock Point Nuclear Plant	50-155	19	Duane Arnold Energy Center	50-331	193
Braidwood Station, Unit 1	STN-50-456	348	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	156
Braidwood Station, Unit 2	STN-50-457	350	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	247
Brigham Young Univ. Research Reactor	50-262	61	Enrico Fermi Atomic Power Plant, Unit 1	50-16	14
Browns Ferry Nuclear Power Station, Unit 1	50-259	51	Enrico Fermi Atomic Power Plant, Unit 2	50-341	209
Browns Ferry Nuclear Power Station, Unit 2	50-260	55	Floating Nuclear Plant	STN-50-437	320
Browns Ferry Nuclear Power Station, Unit 3	50-296	113	Fort Calhoun Station, Unit 1	50-285	95
Brunswick Steam Electric Plant, Unit 1	50-325	171	Fort St. Vrain Nuclear Generating Station	50-267	67
Brunswick Steam Electric Plant, Unit 2	50-324	167	Fulton Generating Station, Unit 1	50-463	360
Byron Station, Unit 1	STN-50-454	341	Fulton Generating Station Unit 2	50-464	360
Byron Station, Unit 2	STN-50-455	345	General Electric Test Reactor	50-70	16
Callaway Plant, Unit 1	STN-50-483	364	Georgia Institute of Technology Research Reactor	50-160	22
Callaway Plant, Unit 2	STN-50-486	368	Georgia Tech Research Reactor	50-276	82
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	147	GESSAR-238	STN-50-447	341
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	150	GIBBSAR, Gibbs & Hill	STN-50-584	390
Catawba Nuclear Station, Unit 1	50-413	302	Grand Gulf Nuclear Station, Unit 1	50-416	309
Catawba Nuclear Station, Unit 2	50-414	305	Grand Gulf Nuclear Station, Unit 2	50-417	313
CESSAR System 80	STN-50-470	361	H. B. Robinson Plant, Unit 2	50-261	58
Clinch River Breeder Reactor	50-537	387	Haddam Neck Plant	50-213	25
Clinton Power Station, Unit 1	50-461	358	Hartsville Nuclear Plant, Unit 1	STN-50-518	374
Clinton Power Station, Unit 2	50-462	360	Hartsville Nuclear Plant, Unit 2	STN-50-519	374
Comanche Peak Steam Electric Station, Unit 1	50-445	336	Hartsville Nuclear Plant, Unit 3	STN-50-520	374
Comanche Peak Steam Electric Station, Unit 2	50-446	339	Hartsville Nuclear Plant, Unit 4	STN-50-521	374
Cooper Nuclear Station	50-298	116	Hope Creek Nuclear Station, Unit 1	50-354	234
Crystal River Nuclear Plant, Unit 3	50-302	120	Hope Creek Nuclear Station, Unit 2	50-355	235
Davis-Besse Nuclear Power Station, Unit 1	50-346	213	Humboldt Bay Power Plant, Unit 3	50-133	17
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	77	Indian Point Station, Unit 1	50-3	11
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	164	Indian Point Station, Unit 2	50-247	40

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	97	Oconee Nuclear Station, Unit 3	50-287	99
Iowa State Univ. Research Reactor	50-116	16	Omaha Veterans Administration Hospital Research Reactor	50-131	17
James A. Fitzpatrick Nuclear Power Plant	50-333	195	Oregon State Univ. Research Reactor	50-243	35
Joseph M. Farley Nuclear Plant, Unit 1	50-348	216	Oyster Creek Nuclear Power Plant	50-219	28
Joseph M. Farley Nuclear Plant, Unit 2	50-364	244	Palisades Nuclear Plant	50-255	49
Kewaunee Nuclear Power Plant	50-305	126	Palo Verde Nuclear Station, Unit 1	STN-50-528	375
La Crosse Boiling Water Reactor	50-409	296	Palo Verde Nuclear Station, Unit 2	STN-50-529	380
LaSalle County Station, Unit 1	50-373	259	Palo Verde Nuclear Station, Unit 3	STN-50-530	384
LaSalle County Station, Unit 2	50-374	262	Peach Bottom Atomic Power Station, Unit 2	50-277	82
Limerick Generating Station, Unit 1	50-352	220	Peach Bottom Atomic Power Station, Unit 3	50-278	84
Limerick Generating Station, Unit 2	50-353	228	Pebble Springs Nuclear Plant, Unit 1	50-514	374
Maine Yankee Atomic Power Plant	50-309	131	Pebble Springs Nuclear Plant, Unit 2	50-515	374
Manhattan College Research Reactor	50-199	23	Pennsylvania State Univ. Research Reactor	50-5	12
Marble Hill Nuclear Station, Unit 1	STN-50-546	387	Perkins Nuclear Station, Unit 1	STN-50-488	368
Marble Hill Nuclear Station, Unit 2	STN-50-547	389	Perkins Nuclear Station, Unit 2	STN-50-489	368
Massachusetts Institute of Technology Research Reactor	50-20	14	Perkins Nuclear Station, Unit 3	STN-50-490	368
Michigan State Univ. Research Reactor	50-294	111	Perry Nuclear Power Plant, Unit 1	50-440	326
Midland Plant, Unit 1	50-329	180	Perry Nuclear Power Plant, Unit 2	50-441	329
Midland Plant, Unit 2	50-330	187	Phipps Bend Nuclear Station, Unit 1	STN-50-553	390
Millstone Nuclear Power Station, Unit 1	50-245	38	Phipps Bend Nuclear Station, Unit 2	STN-50-554	390
Millstone Nuclear Power Station, Unit 2	50-336	201	Pilgrim Nuclear Power Station, Unit 1	50-293	108
Millstone Nuclear Power Station, Unit 3	50-423	314	Point Beach Nuclear Plant, Unit 1	50-266	65
Montague Nuclear Power Station, Unit 1	50-496	368	Point Beach Nuclear Plant, Unit 2	50-301	118
Montague Nuclear Power Station, Unit 2	50-497	368	Prairie Island Nuclear Station, Unit 1	50-282	92
Monticello Nuclear Generating Plant	50-263	61	Prairie Island Nuclear Station, Unit 2	50-306	129
National Bureau of Standards Reactor	50-184	22	Quad-Cities Station, Unit 1	50-254	48
National Naval Medical Center	50-170	22	Quad-Cities Station, Unit 2	50-265	63
Nine Mile Point Nuclear Station, Unit 1	50-220	30	Rancho Seco Nuclear Generating Station	50-312	136
Nine Mile Point Nuclear Station, Unit 2	50-410	299	Reed College Research Reactor	50-288	100
North Anna Power Station, Unit 1	50-338	204	River Bend Station, Unit 1	50-458	352
North Anna Power Station, Unit 2	50-339	206	River Bend Station, Unit 2	50-459	356
North Carolina State Univ. PULSTAR Reactor	50-297	116	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	35
Oconee Nuclear Station, Unit 1	50-269	69	Salem Nuclear Generating Station, Unit 1	50-272	74
Oconee Nuclear Station, Unit 2	50-270	71	Salem Nuclear Generating Station, Unit 2	50-311	132

Name	Docket	Page	Name	Docket	Page
San Onofre Nuclear Station, Unit 1	50-206	23	Univ. of Kansas Research Reactor	50-148	19
San Onofre Nuclear Station, Unit 2	50-361	239	Univ. of Maryland Research Reactor	50-166	22
San Onofre Nuclear Station, Unit 3	50-362	241	Univ. of Missouri Research Reactor	50-186	23
Saxton Nuclear Experimental Facility	50-146	19	Univ. of Missouri Research Reactor	50-123	16
Seabrook Nuclear Station, Unit 1	50-443	331	Univ. of New Mexico Research Reactor	50-252	48
Seabrook Nuclear Station, Unit 2	50-444	334	Univ. of Oklahoma Research Reactor	50-112	16
Sequoyah Nuclear Plant, Unit 1	50-327	176	Univ. of Utah Research Reactor	50-407	296
Sequoyah Nuclear Plant, Unit 2	50-328	178	Vermont Yankee Nuclear Power Station	50-271	72
Shearon Harris Nuclear Power Plant, Unit 1	50-400	291	Virgil C. Summer Nuclear Station, Unit 1	50-395	285
Shearon Harris Nuclear Power Plant, Unit 2	50-401	294	Virginia Polytechnic Institute Training Reactor	50-124	16
Shearon Harris Nuclear Power Plant, Unit 3	50-402	296	Vogtle Electric Generating Plant	50-424	316
Shearon Harris Nuclear Power Plant, Unit 4	50-403	296	Vogtle Electric Generating Plant	50-425	318
Shoreham Nuclear Power Station	50-322	159	Waterford Generating Station, Unit 3	50-382	265
Skagit Nuclear Power Project, Unit 1	50-522	375	Watts Bar Nuclear Plant, Unit 1	50-390	276
Skagit Nuclear Power Project, Unit 2	50-523	375	Watts Bar Nuclear Plant, Unit 2	50-391	280
South Texas Project, Unit 1	STN-50-498	368	West Valley Reprocessing Plant	50-201	23
South Texas Project, Unit 2	STN-50-499	370	West Virginia Univ. Research Reactor	50-129	17
Space Radiation Research Reactor	50-187	23	Westinghouse Critical Experiment	50-87	16
St. Lucie Plant, Unit 1	50-335	199	William B. McGuire Nuclear Station, Unit 1	50-369	254
St. Lucie Plant, Unit 2	50-389	273	William B. McGuire Nuclear Station, Unit 2	50-370	257
Surry Power Station, Unit 1	50-280	85	William H. Zimmer Nuclear Station, Unit 1	50-358	235
Surry Power Station, Unit 2	50-281	89	Wolf Creek Generating Station	STN-50-482	361
Susquehanna Steam Electric Station, Unit 1	50-387	268	Worcester Polytechnic Research Reactor	50-134	18
Susquehanna Steam Electric Station, Unit 2	50-388	271	WPPSS Nuclear Project, Unit 1	50-460	358
Three Mile Island Nuclear Station, Unit 1	50-289	100	WPPSS Nuclear Project, Unit 2	50-397	288
Three Mile Island Nuclear Station, Unit 2	50-320	152	WPPSS Nuclear Project, Unit 3	STN-50-508	372
Trojan Nuclear Plant	50-344	211	WPPSS Nuclear Project, Unit 4	50-513	373
Turkey Point Plant, Unit 3	50-250	43	WPPSS Nuclear Project, Unit 5	STN-50-509	373
Turkey Point Plant, Unit 4	50-251	45	Yankee-Rowe Nuclear Power Station	50-29	14
Tuskegee Institute Research Reactor	50-406	296	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	390
U.S. Geological Survey Research Reactor	50-274	77	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	390
UC-Santa Barbara Research Reactor	50-433	320	Zion Nuclear Power Station, Unit 1	50-295	111
UCLA Training Reactor	50-142	18	Zion Nuclear Power Station, Unit 2	50-304	124
Univ. of Arizona Research Reactor	50-113	16			
Univ. of California at Irvine Research Reactor	50-326	175			

Name	Docket	Page	Name	Docket	Page
Domestic Licensing of Special Nuclear Material — Docket 70			Phelps County Memorial Hospital, Rolla, MO	70-2887	396
Arizona Public Service Co , Phoenix, AZ	70-2949	396	Rockwell International Corp., Canoga Park, CA	70-0025	390
Arizona Public Service Co., Phoenix, AZ	70-2984	396	UNC Naval Products, Inc., Uncasville, CT	70-0371	392
Babcock & Wilcox Co., Apollo, PA	70-0135	391	Union Carbide Corp , Tuxedo, NY	70-0687	392
Babcock & Wilcox Co., Apollo, PA	70-0364	392	Union Electric Co., St. Louis, MO	70-2945	396
Babcock & Wilcox Co., Lynchburg, VA	70-1201	395	United Nuclear Corp., Wood River Junction, RI	70-0820	393
Babcock & Wilcox Co., Lynchburg, VA	70-0027	390	Veterans Administration Hospital, Brooklyn, NY	70-2876	396
Combustion Engineering, Inc., Windsor, CT	70-0036	391	Veterans Administration Hospital, Los Angeles, CA	70-1470	395
Commerce, Dept. of, Washington, DC	70-0398	392	Veterans Administration Medical Center, Buffalo, NY	70-1331	395
Commonwealth Edison Co., Chicago, IL	70-2973	396	Veterans Administration Medical Center, Buffalo, NY	70-1409	395
Commonwealth Edison Co., Chicago, IL	70-2972	396	Westinghouse Electric Corp , Pittsburgh, PA	70-1143	394
Duke Power Co., Charlotte, NC	70-2985	396	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	394
Edlow International Co., Washington, DC	70-2955	396	Westinghouse Electric Corp., Pittsburgh, PA	70-0698	392
Exxon Nuclear Co., Inc., Richland, WA	70-1257	395	ANEFco, Inc.	71-0001	397
GA Technologies, Inc., San Diego, CA	70-0734	392	Deltak Corp.	71-0511	397
General Electric Co., Pleasanton, CA	70-0754	393	Gesellschaft Fur Nuklear Service	71-0510	397
General Electric Co., San Jose, CA	70-1308	395	Model: 20-VS & 40-VS, Gulf Nuclear, Inc.	71-9160	399
General Electric Co., San Jose, CA	70-2786	395	Model: 770, Technical Operations, Inc.	71-9148	399
General Electric Co., Wilmington, NC	70-1113	394	Model: 771, Technical Operations, Inc.	71-9107	398
George Washington Univ., Washington, DC	70-1795	395	Model: 855, Technical Operations, Inc.	71-9165	399
Harvard Univ., Cambridge, MA	70-0083	391	Model: 9183, Duke Power Co.	71-9183	399
Interior, Dept. of, Denver, CO	70-0121	391	Model: 920, Technical Operations, Inc.	71-9143	399
John F. Kennedy Memorial Hospital, Stratford, NJ	70-2427	395	Model: AP-101, ANEFco, Inc.	71-9071	398
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	395	Model: B-3, U.S. Ecology, Inc.	71-6058	398
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0925	394	Model: BMI-1, Battelle Columbus Laboratory	71-5957	398
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0712	392	Model: CASTOR, V, Gesellschaft Fuer Nuklear Service, MKH	71-9190	399
Louisiana Power & Light Co., New Orleans, LA	70-2946	396	Model: CNS6-80B Nuclear Packaging, Inc.	71-9175	399
Massachusetts Institute of Technology, Cambridge, MA	70-0938	394	Model: ETR, Exxon Nuclear Idaho Co.	71-9134	398
Navy, Dept. of, Annapolis, MD	70-0368	392	Model: FSV-1, GA Technologies, Inc.	71-6346	398
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	391	Model: GE-1500, General Electric Co.	71-5939	397
Pennsylvania State Univ., University Park, PA	70-0113	391	Model: GE-1600, General Electric Co.	71-9044	398

Name	Docket	Page	Name	Docket	Page
Model: GE-21PF-1, General Electric Co.	71-4909	397	Model: ORNL Tritium Target Container	71-5800	397
Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	399	Model: ORNL, BNL & NBS UNIR CONT, Energy, Dept. of	71-9853	399
Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	398	Model: PAS-1, Nuclear Packaging, Inc.	71-9184	399
Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	398	Model: PAS-2, Nuclear Packaging, Inc.	71-9181	399
Model: HN-300, Hittman Nuclear & Development Corp.	71-9092	398	Model: R, Gulf, Nuclear, Inc.	71-9161	399
Model: HN-400, Hittman Nuclear & Development Corp.	71-9093	398	Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp.	71-5450	397
Model: HN-600, NUPAC 7-100 & CNS 7-100, Hittman Nuclear & Development Corp.	71-9080	398	Model: TN-9, No Users	71-9016	398
Model: Inner & Outer HFIR UN, Energy, Dept. of	71-5797	397	Pan American World Airways, Inc.	71-0096	397
Model: NLI-1/2, NL Industries, Inc.	71-9010	398	Westinghouse Electric Corp.	71-0251	397
Model: OH-142, Nuclear Packaging, Inc.	71-9073	398	Licensing of Independent Spent Fuel Storage --- Docket 72		
			Morris Operations, General Electric Co.	72-0001	399
			Virginia Electric & Power Co.	72-0002	399

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8401130009 Summarizes 831212-13 conference in Chicago, IL re advances in infiltration Topics included performance of shallow land burial, low level waste disposal & U mill tailings recovery & disposal
 000DE, D Geotechnical Branch (Post 831001) 83/12/21 KNAPP, M R
 Geotechnical Branch (Post 831001) 9pp 21820 355

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC

8401200304 "Hydrology of Low Level Radioactive Solid Waste Burial Site & Vicinity Near Barnwell, SC"
 CAHILL, J M Interior, Dept of, Geological Survey 82-863
 82/12/31 109pp 21871 133

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

8401120136 Forwards monthly matl receipt & burial rept for Nov 1983
 W/o encl
 WALLER, W K U S Ecology, Inc (formerly Nuclear Engineering, Inc)
 83/12/12 BROWNING, B Low Level Waste Licensing Branch 1p
 21805 062

8401110463 Requests postponement of further action on 831012 ltr until completion of B&W reevaluation of package
 WALLER, W K U S Ecology, Inc (formerly Nuclear Engineering, Inc)
 83/12/21 SCHAFFNER, J NRC - No Detailed Affiliation Given 1p
 21790 349

8401190169 Comments on amend to Byproduct/Matl License 16-19204-01, per 831222 telcon
 GAYNOR, R K U S Ecology, Inc (formerly Nuclear Engineering, Inc)
 84/01/03 SCHAFFNER, J NRC - No Detailed Affiliation Given 3pp
 21861 359

8401190253 Discusses proposed method of segregating Class A unstable waste from Class B & C stable waste for License 16-19204-01
 Disposal operations began on 831227
 SCOVILLE, J J U S Ecology, Inc (formerly Nuclear Engineering, Inc)
 84/01/04 SCHAFFNER, J NRC - No Detailed Affiliation Given 1p
 21870 097

8401190256 Requests approval for one-time disposal of liquid BNM in form of scintillation fluids in accordance w/established site operating procedures
 WALLER, W K U S Ecology, Inc (formerly Nuclear Engineering, Inc)
 84/01/06 SCHAFFNER, J NRC - No Detailed Affiliation Given 1p
 21870 096

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI

8401240393 Forwards IE Insp Repts 40-0017/B3-01 & 40-1790/B3-01 on 830807-1020 Possible enforcement actions arising from disposal of radwaste at landfill will be discussed after NRC evaluation.
 KEPLER, J G Region 3, Office of Director 83/12/08 SIMMONS, S J
 Wellman Dynamics Corp 2pp 21920 253

--8401240358 IE Insp Repts 40-0017/B3-01 & 40-1790/B3-01 on 830807-1020 Insp findings indicate thorium found on State of MI property came from activities conducted under License BTR-136
 LASUK, S R, BRENIAWSKI, D, AXELSON, W L Region 3, Office of Director, 83/11/18 12pp 21920 255

DOCKET 40-0086 W R GRACE & CO , POMPTON PLAINS, NJ

8401030014 FOIA request for documents dtd 820427 or later re radiation at WR Grace & Co in Wayne or Pompton Plains, NJ
 AIKMAN, R Record, Hackensack, NJ 83/04/21 FELTON, J M Division of Rules and Records 1p 21695 349

8401030015 Responds to FOIA request for documents dtd 820427 or after re radiation at WR Grace & Co in Wayne or Pompton Plains, NJ
 Forwards App A documents Documents also available in PDR Documents partially withheld (ref FOIA Exemption 6)
 FELTON, J M Division of Rules and Records 83/09/20 AIKMAN, R
 Record, Hackensack, NJ 9pp 21695 350

--8207110091 Requests that Commission increase radiological survey scope of former WR Grace & Co property in Wayne, NJ Boundaries of aerial survey did not include area wide enough to detect all radiation anomalies Related info encl
 BOUGUARD, M L, ROE, R A House of Rep, Science & Technology 82/08/10 PALLADINO, N J Commissioners 4pp 21695 185

--8207180008 Requests response to encl ltrs re investigation of radiation levels at WR Grace & Co property in Wayne, NJ Info deleted Related info encl
 ROE, R A House of Rep 82/08/11 PALLADINO, N J Commissioners 8pp 21695 189

--8209180025 Forwards M Resinoff preliminary assessment of thorium radiation situation in Wayne, NJ WR Grace & Co violated 10CFR20 304 in establishing burial site
 ROE, R A House of Rep 82/10/08 DIRCKB, W J Office of the Executive Director for Operations 11pp 21695 276

--8212010495 Forwards addl copies of "Radiological Survey Rept of Sheffield Brook in Wayne, NJ" Survey rept of plant site will be transmitted upon completion in Jan 1983 W/o encl
 PAGE, R G Uranium Fuel Licensing Branch 82/11/12 MOTY, W Energy, Dept of 1p 21695 316

--8401030016 Forwards press releases re thorium radiation found in NJ in hope that responsible party will remove source Info deleted
 Affiliation Unknown 82/04/30 Affiliation Unknown 4pp 21695 359

--8401030017 Forwards Oct 1982 "Radiological Survey of Sheffield Brook, Wayne, NJ," final rept Results of surveys & measurements of WR Grace & Co property will be subj of addl rept W/o encl
 Info deleted
 KINNEMAN, J D Region 1, Office of Director 82/10/27, Affiliation Unknown 1p 21695 295

--8401030020 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept W/o encl
 KINNEMAN, J D Division of Engineering & Technical Programs 82/10/27 FITZPATRICK, F Pequannock, NJ 1p 21695 298

--8401030021 Forwards Congressman Roe 820423 ltr re soil contamination at WR Grace & Co in NJ Coordination w/Region I & IE in preparing response requested
 DAVIS, J O, NRC - No Detailed Affiliation Given 82/05/12 CUNNINGHAM, R E NRC - No Detailed Affiliation Given 3pp 21695 007

--8401030022 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept W/o encl
 KINNEMAN, J D Division of Engineering & Technical Programs, 82/10/27 FELDMAN, J Environmental Protection Agency, 1p 21695 299

DOCKETED ITEMS

- B401030024 Requests addl info re investigation of WR Grace & Co & surrounding Wayne, NJ area due to indications of radiation levels & surface soil contamination exceeding unrestricted use criteria
RDE, R A House of Rep 82/04/23 PALLADINO, N J Commissioners
2pp 21696 010
- B401030025 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/27 COSOLITO, F New Jersey State of 1p 21696 300
- B401030027 Responds to B20423 ltr re WR Grace & Co property & surrounding Wayne, NJ area indicating radiation levels & soil contamination exceeding normal criteria NRC evaluating info to determine if soil should be removed
DIRCKS, W J Office of the Executive Director for Operations
82/05/13 RDE, R A House of Rep 2pp 21696 012
- B401030029 Responds to B20423 ltr re WR Grace & Co property & surrounding Wayne, NJ area indicating radiation levels & soil contamination exceeding normal criteria NRC evaluating info to determine if soil should be removed
DIRCKS, W J Office of the Executive Director for Operations
82/05/21 RDE, R A House of Rep 3pp 21696 014
- B401030031 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/27 GRISI, F Lincoln Park, NJ 1p 21696 301
- B401030033 Act receipt of B20423 ltr re investigation of thorium radiation at WR Grace & Co in Wayne, NJ Swift resolution of issue requested Related info encl
RDE, R A House of Rep 82/05/19 PALLADINO, N J Commissioners
9pp 21696 020
- B401030036 Forwards ltr from Wayne, NJ Council & B20529 reply re low level radiation emitted from site & stream bed down stream from site Related info encl no immediate hazard to health & safety of property camera identified
MOBLEY, B L W R Grace & Co 82/06/01 CROW, W NRC - No Detailed Affiliation Given 9pp 21696 034
- B401030040 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/27 JASINSKI, W Wayne, NJ 1p 21696 302
- B401030042 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 MARCO, D Affiliation Unknown 1p 21696 309
- B401030045 Comments on FDIA Request B2-219 re WR Grace & Co Review of info indicates Item 4 Encl 1 & Item 33 Pages 2 A-4, Encl 2 contain proprietary info & Items 2 a & b Encl 1 same as Item 160 Encl 2
SNYDER, G L Division of Emergency Preparedness & Operational Support 82/06/21 FELTON, J M Division of Rules and Records
1p 21696 072
- B401030046 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl Info deleted
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 Affiliation Unknown 1p 21696 310
- B401030048 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 BAUER, F Wayne, NJ 1p 21696 311
- B401030049 Responds to B20614 request for info re thorium contamination in Wayne, NJ Surveys performed to evaluate if removal of contaminated soil necessary
DIRCKS, W J Office of the Executive Director for Operations
82/07/01 BRADY, N F Senate 3pp 21696 087
- Q1030050 Responds to B20715 request for description of NRC surveys performed in Wayne, NJ Oak Ridge Assoc Univ "Radiological Survey Plan" forwarded
KINNEMAN, J D Region 1, Office of Director 82/07/21
BARTOLOZZI, A Wayne, NJ 1p 21696 092
- B401030052 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj in separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 WAKS, D Wayne, NJ 1p 21696 312
- B401030053 Requests info re program to conduct tests for thorium, radium & radon gas products onsite at WR Grace & Co
BARTOLOZZI, A R Wayne, NJ 82/07/15 KINNEMAN, J D Region 1, Office of Director 1p 21696 093
- B401030054 "Proposed Radiological Survey Plan "
* Oak Ridge Associated Univs 82/03/15 8pp 21696 094
- B401030055 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 O'BRIEN, J Wayne, NJ 1p 21696 313
- B401030057 "Radiological Survey of Sheffield Brook, Wayne, NJ," draft preliminary rept Related info encl Info deleted
FRAME, P W Oak Ridge Associated Univs 82/07/31 Division of Fuel Cycle & Material Safety 66pp 21696 102
- B401030058 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj in separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 WEBB, G Wayne, NJ 1p 21696 314
- B401030060 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 RESNIKOFF, M Council on Economic Priorities, 1p 21696 315
- B401030065 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept w/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
82/10/29 CASEY, D Affiliation Unknown 1p 21696 317
- B401030066 Forwards comments on "Radiological Survey of Sheffield Brook, Wayne, NJ," Jul 1982 preliminary rept Contractor selecting guidelines or criteria inappropriate
JOYNER, J H Region 1, Office of Director 82/08/11 CROW, W T Uranium Fuel Licensing Branch 3pp 21696 175
- B401030069 Forwards "Radiological Surveys of Sheffield Brook," preliminary rept w/o encl Related info encl
JOYNER, J H Division of Engineering & Technical Programs
82/08/16 MOBLEY, B W R Grace & Co 7pp 21696 178
- B401030070 Forwards "Radiological Survey of Sheffield Brook, Wayne, NJ," containing addendum describing Ra-226 in water analysis w/o encl
ENG, J New Jersey, State of 82/11/12 KINNEMAN, J NRC - No Detailed Affiliation Given 1p 21696 318
- B401030073 Responds to B21110 ltr re review & surveys of WR Grace & Co property & surrounding area in Wayne, NJ indicating presence of thorium Oak Ridge Assoc Univ rept will be sent when available in early 1983
GLENN, J E Division of Engineering & Technical Programs
82/12/06 COLLICA, C J Norwalk Hosp, Norwalk, CT 1p 21697 007
- B401030076 Forwards soil analysis from residences close to old WR Grace railroad siding in Pompton Plains, NJ Samples 15 & 16 indicated highest levels Further soil sampling authorization requested Info deleted
COLLICA, C J Norwalk Hosp, Norwalk, CT 82/11/10 GLENN, J Region 1, Office of Director 2pp 21697 008
- B401030081 Excerpt from rept re radioactive contamination on WR Grace & Co property & surrounding area along Sheffield Brook in Wayne, NJ
* Affiliation Unknown 82/12/09 4pp 21697 016
- B401030082 Responds to encl B20604 ltr to president re thorium waste buried on Black Oak Ridge Road in Wayne, NJ Surveys indicate presence of matl does not present immediate hazard to residents Info deleted
KINNEMAN, J D Region 1, Office of Director 82/09/27 Affiliation Unknown 2pp 21696 204

DOCKETED ITEMS

3

- B401030086 Responds to F Fitzpatrick of NJ B20823 ltr re thorium contamination found in Pequannock Township, NJ Based on NRC surveys, thorium radiation not hazardous to nearby residents
DIRCKS, W J Office of the Executive Director for Operations
B2/09/23 ROE, R A House of Rep 3pp 21696 206
- B401030089 Forwards "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct, Source & SNM," per B21201 request W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B2/12/28 RESNIKOFF, M Affiliation Unknown 1p 21697 022
- B401030092 Ack receipt of "Radiological Surveys of Sheffield Brook," final rept Listed refs requested
RESNIKOFF, M Affiliation Unknown B2/12/01 KINNEMAN, J D Region 1, Office of Director 1p 21697 023
- B401030096 Responds to F Fitzpatrick B20823 ltr re thorium contamination found in NJ Based on NRC surveys, thorium contamination not hazardous to nearby residents
DIRCKS, W J Office of the Executive Director for Operations
B2/09/23 COURTER, J House of Rep 2pp 21696 211
- B401030097 "Results of Mobile Gamma Scanning Activities at Wayne, NJ & Surrounding Communities "
* Oak Ridge National Laboratory B3/01/31 17pp 21697 032
- B401030102 Forwards draft "Radiological Survey of WR Grace & Co Property, Wayne, NJ " W/o encl
FRAME, P W Oak Ridge Associated Univs B3/01/12 CROW, W Division of Fuel Cycle & Material Safety 1p 21697 207
- B401030103 Responds to F Fitzpatrick B20823 ltr re thorium contamination found in NJ Based on NRC surveys, thorium radiation not hazardous to nearby residents
DIRCKS, W J Office of the Executive Director for Operations
B2/09/29 ROE, R A House of Rep 2pp 21696 213
- B401030104 Forwards comments on draft radiological survey of WR Grace & Co property, Wayne, NJ More complete presentations of surface & meter exposure data & clearer conclusions about actual conditions necessary
JOYNER, J H Division of Engineering & Technical Programs
B3/01/18 PAGE, R G Uranium Fuel Licensing Branch 6pp 21697 208
- B401030105 "Radiological Survey of Sheffield Brook, Wayne, NJ "
* New Jersey, State of B2/10/31 43pp 21696 223
- B401030107 Ack receipt of B20924 ltr & addl inquiry re impact of thorium contamination in Wayne, NJ on nursing facility Based on aerial radiological survey, contamination not hazardous to residents of facility W/o stated encl
ABRAHAM, K Office of Public Affairs B2/10/05 SUCH, P P Willowbrook Nursing Home Wayne, NJ, 1p 21696 267
- B401030110 Requests info re thorium levels found on Black Oak Ridge Road & Pompton Cross Road
SUCH, P Willowbrook Nursing Home Wayne, NJ, B2/09/24 ABRAHAM, K Office of Public Affairs 1p 21696 268
- B401030111 Forwards Oct 1982 "Radiological Survey of WR Grace & Co Property, Wayne, NJ," final rept W/o encl Info deleted
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 Affiliation Unknown 1p 21697 215
- B401030114 Responds to B20805 ltr re Electronuclearionics use of thorium in NJ Use of thorium caused contamination Surveys & assessments of thorium hazards in progress
KINNEMAN, J D Region 1, Office of Director B2/10/05 CRANDALL, C S Justice, Dept of, Attorney General, Office of 1p 21696 270
- B401030115 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl Info deleted.
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 Affiliation Unknown 1p 21697 216
- B401030117 Forwards B20714 ltr from Concerned Citizens Committee of Wayne & Resolution of Municipal Council of Township of Wayne re thorium storage at Electronuclearionics (related to WR Grace & Co) & radioactive dump site Info deleted
DUMONT, W H, CRANDALL, C S Justice, Dept of, Attorney General, Office of B2/08/05 KINNEMAN, J Region 1, Office of Director 3pp 21696 271
- B401030118 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 FITZPATRICK, F Pequannock, NJ 1p 21697 217
- B401030122 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 FELDMAN, J Environmental Protection Agency 1p 21697 218
- B401030124 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 COSOLITO, F New Jersey, State of 1p 21697 219
- B401030125 Responds to M Resnikoff B20912 ltr re WR Grace & Co & surrounding area in Wayne, NJ Twelve burials of up to 1,000 lbs thorium each per yr permitted per 10CFR20 304
DIRCKS, W J Office of the Executive Director for Operations
B2/10/26 ROE, R A House of Rep 2pp 21696 273
- B401030127 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 WEBB, G Wayne, NJ 1p 21697 220
- B401030130 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Region 1, Office of Director B3/02/01 RESNIKOFF, M Council on Economic Priorities 1p 21697 221
- B401030131 Advises that well water sample analysis taken from home indicated water met EPA drinking stds Info deleted
KINNEMAN, J D Region 1, Office of Director B2/09/23 Affiliation Unknown 1p 21696 275
- B401030132 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Region 1, Office of Director B3/02/01 BAUER, F Wayne, NJ 1p 21697 222
- B401030138 Forwards QA Program Insp Rept 99990001/B2-03 per B20908 telcon request Rept documents surveys of recipient property Radiation level not hazardous Info deleted
KINNEMAN, J D Region 1, Office of Director B3/10/18 Affiliation Unknown 2pp 21696 287
- B401030139 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 ORISI, F Lincoln Park, NJ 1p 21697 223
- B401030142 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 LEIDY, J Wayne, NJ 1p 21697 224
- B401030147 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 DIDONATO, J Wayne, NJ 1p 21697 225
- B401030151 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 JABINSKI, W Wayne, NJ 1p 21697 226
- B401030154 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 O'BRIEN, J Wayne, NJ 1p 21697 227
- B401030156 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl Info deleted
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/01 HAKS, D Wayne, NJ 1p 21697 228
- B401030161 Requests info re results of NRC study at WR Grace & Co site conducted in late 1982
BARTOLOZZI, A R Wayne, NJ B3/02/03 KINNEMAN, J D Region 1, Office of Director 1p 21697 229
- B401030164 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl Info deleted
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/07 Affiliation Unknown 1p 21697 230
- B401030168 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl Info deleted
KINNEMAN, J D Division of Engineering & Technical Programs
B3/02/10 Affiliation Unknown 1p 21697 231

DOCKETED ITEMS

- B401030171 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEHAN, J D Division of Engineering & Technical Programs
83/02/22 Affiliation Unknown 1p 21697 232
- B401030178 Summarizes 830201 radiological survey of WR Grace & Co property Survey is most complete rept available of radioactive contamination of company property Site extremely poor for radwaste disposal
RESNICKOFF, M Affiliation Unknown 83/02/09 JASINSKI, H.
BARTOLOZZI, A Wayne, NJ 7pp 21697 247
- B401030181 Advises that Oak Ridge Assoc Univ sampling of groundwater, wells at WR Grace & Co not representative of actual groundwater due to heavy rains 812 new wells will be sampled & included in analysis Related info encl
KINNEHAN, J D Division of Engineering & Technical Programs
83/02/16 JOYNER, J H Region 1- Office of Director 20pp 21697 234
- B401030189 Forwards "Radiological Survey of Former Thorium/Rare Earths Processing Facility (WR Grace Property, Wayne, NJ)" containing Dept of Environ Protection technical findings from Aug 1982 survey W/o stated encl Related info incl
KUHRTZ, S O New Jersey, State of 83/04/08 MACE, R W R Grace & Co 5pp 21697 274
- B401030191 "Radiological Survey of Monasite Unloading Area, Pompton Plains Railroad Spur (Pompton Plains, NJ) "
* New Jersey, State of 83/04/30 27pp 21697 279
- B401030195 Responds to 830301 ltr re health hazards of elevated levels of radionuclide concentrations & proposed cleanup operations at WR Grace & Co property & area Rept indicates no health hazards to residents in area Info deleted
MARTIN, T T Division of Engineering & Technical Programs
83/04/19 Affiliation Unknown 3pp 21697 309
- B401030200 Requests addl info on "Radiological Survey of WR Grace & Co, Property, Wayne, NJ " Info deleted
* Affiliation Unknown 83/03/01 MARTIN, T T Division of Engineering & Technical Programs 2pp 21697 312
- B401040155 Submits info re NRC requirements during removal of thorium bearing matl presently contaminating right-of-way for new water line in response to 831130 request Matter should be discussed w/DOE
MURLEY, T E Region 1, Office of Director 83/12/27 DRECHIO, F A New Jersey, State of 2pp 21702 045
- B401040162 Requests info re NRC requirements for temporary storage of thorium bearing matl presently contaminating right-of-way Matl should remain part of permanent inventory of WR Grace Co during temporary storage period
DRECHIO, F A New Jersey, State of 83/11/30 HAYNES, R Region 1, Office of Director 2pp 21702 047
- DOCKET 40-0281 THICKOL CORP , DANVERS, MA
- B401270009 IE Insp Findings & Licensee Act dtd 840112 of License 83-160 Insp findings no violations observed
NICHOLSON, J F Region 1, Office of Director 84/01/12 1p 21982 023
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 8401040448 Discusses IE insp on 830823-25 & forwards notice of violation & proposed imposition of civil penalty
COLLINS, J T Region 4, Office of Director 83/11/03 SHORTRIDGE, E Union Carbide Corp 2pp 21707 104
- 8401040456 Notice of violation & proposed imposition of civil penalty in amount of \$4,000 Violation noted audible alarm not checked daily, instrumentation used to analyze radon daughter samples & perform gamma exposure rate not calibr
COLLINS, J T Region 4, Office of Director 83/11/03 4pp 21707 106
- 1040506 Forwards IE Insp Rept 40-0299/83-02 on 830823-25 & IE Enforcement Conference Rept 40-0299/83-03 on 830921
ALL, R E Region 4, Office of Director 83/11/03 SHORTRIDGE, E W Union Carbide Corp 2pp 21705 320
- 8401040510 IE Enforcement Conference Rept 40-0299/83-03 on 830921 Major areas discussed: findings of IE Insp Rept 40-0299/83-02 on 830823-25 Eight violations noted re mgt control of licensee radiation safety program
CAIN, C L, EVERETT, R J Region 4, Office of Director 83/09/30 2pp 21705 322
- B401040514 IE Insp Rept 40-0299/83-02 on 830823-25 Violations noted failure to perform daily tests of audible alarm sys designed to warn of yellowcake stack scrubber failure & failure to survey alpha contamination
CAIN, C L, WOOLSEY, R T, BROWN, R C Region 4, Office of Director 83/10/21 11pp 21705 324
- B401270167 Discusses leakage at Union Carbide Corp Gas Hills U Mill Leakage currently 0.02 gpm & comes from perforated monitor pipe which lies under clay liner on oldest heap leach pile Liner degradation likely cause of problem
CAIN, C NRC - No Detailed Affiliation Given 83/11/18 NRC - No Detailed Affiliation Given 1p 22002 294
- B401270172 Forwards rept re leakage in heap leach monitor drain sump at Union Carbide Corp Gas Hills U Mill Arrangements made to have water flowing into heap leach monitor sump transferred to A-9 tailings area
LYONS, P J Union Carbide Corp 83/11/18 HALL, R NRC - No Detailed Affiliation Given 4pp 22002 295
- B401060637 Submits review of "Hydrogeologic Analysis of Union Carbide Corp Analysis of A-9 Pit, E Gas Hills, WY," to determine if Univ of Idaho findings agreed favorably w/verder findings No new causes of seepage uncovered
WOOLSEY, R T, PETTINGILL, H J Uranium Recovery Field Office 83/12/01 Uranium Recovery Field Office 2pp 21755 060
- B401110494 Requests addl info re const specs for buried pipelines for A-9 seepage collection sys
BARUTH, E, LAUDEN, K Wyoming, State of 83/12/07 Union Carbide Corp 1p 21795 349
- B401110483 Forwards "Water Level Evaluation Rept," monthly rept for Nov 1983 Production decreased slightly Injection well permit application will be submitted to State of WY, Dept of Environ Quality by end of Dec 1983
LYONS, P J Union Carbide Corp 83/12/09 PETTINGILL, H J Uranium Recovery Field Office 1p 21796 001
- B401110486 "Water Level Evaluation Rept," monthly rept for Nov 1983
* Union Carbide Corp 83/11/30 16pp 21796 002
- B401270155 Forwards update on reclamation schedule for inactive tailings area in East Gas Hills, WY Rept on geotechnical work will not be available until end of Feb 1984
LYONS, P J Union Carbide Corp 83/12/09 WOOLSEY, R Uranium Recovery Field Office 9pp 22002 332
- B401120432 Forwards info in response to Item 7 of NRC 830818 ltr re Union Carbide Corp request to increase capacity of A-9 tailings Area W/one oversize graph & one oversize map Aperture cards are available in PDR
LYONS, P J L Union Carbide Corp 83/12/12 PETTINGILL, H Uranium Recovery Field Office 1p 21796 262
- B401270179 Forwards response to Item 4 of NRC 831101 ltr re increased capacity of A-9 tailings area Complete response to NRC 831004 & 1101 ltrs expected first or second wk of Jan
LYONS, P J Union Carbide Corp 83/12/16 PETTINGILL, H Uranium Recovery Field Office 16pp 21992 342
- B401310459 Forwards Rev 2 to "Embankment Stability for A-9 Pit Increased Tailings Disposal Capacity Plan "
LYONS, P J L Union Carbide Corp 83/12/27 PETTINGILL, H Uranium Recovery Field Office 1p 22037 288
- B401310462 Rev 2 to "Embankment Stability for A-9 Pit Increased Tailings Disposal Capacity Plan " W/two oversize figures Aperture cards available in PDR
HARDWELL, R E Water, Waste & Land, Inc 83/12/31 35pp 22037 289
- B401270142 Forwards water level elevation rept for Dec 1983 for monitor wells near pumpback well
LYONS, P J Union Carbide Corp 84/01/10 PETTINGILL, H Uranium Recovery Field Office 1p 22002 341
- B401270147 Water level elevation rept for Dec 1983 for monitor wells near pumpback well
* Union Carbide Corp 83/12/31 16pp 22002 342
- DOCKET 40-0672 NUCLEAR METALS, INC , CONCORD, MA
- 8401100343 Ack receipt of 830928 Confirmatory Action Ltr 83-08 informing NRC of steps taken to correct violations noted in IE insp rept Actions will be examined during future insp
MARTIN, T T Division of Engineering & Technical Programs 83/12/27 TUFFIN, W B Nuclear Metals, Inc 1p 21763 291

DOCKETED ITEMS

6

--B401100351 Responds to NRC B30805 Confirmatory Action Ltr B3-08 re violations noted in IE insp rept Corrective actions four Foundry-contaminated leather palms & respective liners used as sources for dosimeter irradiations
ALLARD, D J, VUMBACQ, F J Nuclear Metals, Inc B3/09/28
MARTIN, T T Division of Engineering & Technical Programs 3pp
21763 292

DOCKET 40-1162 WESTERN NUCLEAR, INC, JEFFREY CITY, WY

B401270157 "Semiannual Radiation Safety Audit/ALARA Review, B30927-27" W/B31215 ltr
BOODEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp)
B3/09/29 PETTENGILL, H Uranium Recovery Field Office 17pp
22002 313

B401040571 Forwards IE Insp Rept 40-1162/B3-01 on B30927 & notice of violation
HALL, R E Region 4, Office of Director B3/11/09 KELLER, T
Western Nuclear, Inc (subs of Phelps Dodge Corp) 2pp
21706 298

--B401040580 Notice of violation from insp on B30927
* Region 4, Office of Director B3/11/09 1p 21706 300

--B401040591 IE Insp Rept 40-1162/B3-01 on B30927 Violation noted failure to conduct bioassay program in accordance w/ Table I & Section 5(c) of Reg Guide B 22 per License Condition 56(b)
SPITZBERG, D B, GARCIA, P J, EVERETT, R J Region 4, Office of Director B3/10/28 4pp 21706 301

B401310508 Directs Western Nuclear, Inc to activate Southwest Valley pumpback Wells A, B & C, based on review of monitoring data
GARLAND, W L, RANDEN, L D Wyoming, State of B3/12/02 BOODEN, G
Western Nuclear, Inc (subs of Phelps Dodge Corp) 1p 22037 325

B401040147 Responds to NRC ltr re violations noted in IE Insp Rept 40-1162/B3-01 Corrective actions three of seven portable survey instruments calibr/weekly contamination surveys will be conducted & signs posted
KLEIN, T J Union Minerals B3/12/05 HALL, R E Region 4, Office of Director 7pp 21702 049

B40110583 Forwards ltr sent to State of WY, Dept of Environ Quality re Southwest pumpback wells Stipulation B does not presently require activation of pumpback sys
BOODEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp)
B3/12/12 PETTENGILL, H J Uranium Recovery Field Office 4pp
21790 354

B401310484 Forwards addendum to "Semiannual Environ Monitoring Rept, Jan-June 1983"
BOODEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp)
B4/01/03 PETTENGILL, H J Uranium Recovery Field Office 1p
22042 292

--B401310488 Addendum to "Semiannual Environ Monitoring Rept, Jan-June 1983."
WALKER, B, WICKSTORM, B Western Nuclear, Inc (subs of Phelps Dodge Corp) B3/06/30 35pp. 22042 293

B401310428 Issues Amend 19 to License SUA-56, revising License Condition 11 to authorize changes to security measures in effect at Split Rock Mill during mill shutdown
SMITH, R D Uranium Recovery Field Office, B4/01/05 BOODEN, G
Western Nuclear, Inc (subs of Phelps Dodge Corp) 2pp
22034 360

--B401310431 Safety evaluation supporting issuance of Amend 19 to License SUA-56, in response to B3111 request, authorizing changes to security measures at Split Rock site during mill shutdown
GARCIA, P J, PETTENGILL, H J Uranium Recovery Field Office
B4/01/04 2pp 22034 362

DOCKET 40-1478 SPENCER CHEMICAL CO, KANSAS CITY, MO

B401250133 FOIA request for listed documents re Kerr-McGee Nuclear Corp, Licenses SMB-664 & BMM-695
BARNES, C. Affiliation Unknown, B3/10/12 FELTON, J M Division of Rules and Records 1p 21958 333.

B401250136 Responds to FOIA request for five listed documents. Forwards Documents 4 & 5 Request for Documents 1-3 referred to PDR
FELTON, J M Division of Rules and Records, B3/11/04 BARNES, C.
Affiliation Unknown 1p 21958 334.

--B401250142 Forwards Source Matl License SMB-664 Condition of license requires results of evaluation described in Item 3 of H Lambertus 621022 ltr within 30 days of completion of evaluation Public insp Drawing NPD-4 withheld (ref 10CFR2)
PRICE, E R Atomic Energy Commission 62/11/07 LAMBERTUS, H
Kerr-McGee Corp 1p 21958 348

--B401250143 Source Matl License SMB-664 for Kerr-McGee Oil Industries Inc, authorizing use of unlimited amounts of U & thorium at Cushing, OK oil refinery, per 620703 application & 620917, 1009 & 22 suppl
NUSSBAUMER, D A Atomic Energy Commission 62/11/07 1p
21958 349

--B401250146 Application for source matl license, authorizing transfer possession & sale of U & depleted U from Spencer Chemical Co
COBB, O H Kerr-McGee Corp 62/07/03 Atomic Energy Commission 7pp 21958 350

--B401250150 Responds to 621003 telcon re issuance of source matl license Request for withholding Drawings NPD-4 & NPD-5 from public disclosure, per 620917 application, withdrawn Air effluent sampling method described
LAMBERTUS, H Kerr-McGee Corp 62/10/09 NUSSBAUMER, D A Atomic Energy Commission 17pp 21958 357

--B401250153 Responds to 620821 ltr re application for source matl license Refinery located in rolling pasture land, 3 miles from Cushing, OK Gases from equipment areas vented into main exhaust manifold
LAMBERTUS, H Kerr-McGee Corp 62/09/17 Atomic Energy Commission 7pp 21959 012

--B401250157 Responds to 621018 telcon re application for source matl license Written instructions provided to employees re locker room procedures
LAMBERTUS, H Kerr-McGee Corp 62/10/22 Atomic Energy Commission 4pp 21959 019

DOCKET 40-1790 WELLMAN DYNAMICS CORP, CRESTON, IA

B401240353 Forwards IE Insp Repts 40-0017/B3-01 & 40-1790/B3-01 on B30809-1020 Possible enforcement actions arising from disposal of radwaste at landfill will be discussed after NRC evaluation
KEPPLER, J G Region 3, Office of Director B3/12/08 SIMMONS, H J
Wellman Dynamics Corp 2pp 21920 253

--B401240358 IE Insp Repts 40-0017/B3-01 & 40-1790/B3-01 on B30809 10.11 Insp findings indicate thorium found on State of MI property came from activities conducted under License STB-136
LAGUK, S R, BRENIANSKI, D, AXELSON, W L Region 3, Office of Director B3/11/18 12pp 21920 253

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP, OKLAHOMA CITY, OK

B401230554 Forwards memorandum re compliance of vendor stabilization plan w/ EPA stds in response to Item 2 of B31117 order
RHINELANDER, J, MONTAGE, C H Shaw, Pittman, Potts & Trowbridge
RHINELANDER, J Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) B3/12/21 FRYE, J H Atomic Safety and Licensing Board Panel 2pp 21902 087

--B401230558 Memorandum re compliance of Kerr-McGee stabilization plan w/ EPA stds
* Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp)
B3/12/20 43pp 21902 089

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records B3/10/18 WE188, L N
Union of Concerned Scientists 3pp. 21960 005 24X
Fiche 50-000, B3/10/18, B401250015

--B204070589 Advises that Judge McCarr denied renewed motion for preliminary injunction filed by City of West Chicago, IL & granted motion to dismiss filed by NRC Opinion follows
BICKWIT, L Office of the General Counsel SECY-82-073A, B2/03/26 1p 21960 235.

--B401250148 Summarizes B20212 District Court status hearing in City of West Chicago vs NRC City may drop lawsuit if Commission Order CLI-B2-2, disposing of hearing petitions, is followed by DEB in Spring 1982
BICKWIT, L Office of the General Counsel SECY-82-073 B2/03/14 2pp 21960 236

DOCKETED ITEMS

B401030319 Discusses impact of new environ stds on West Chicago Rare Earths Facility Table S-3 narrative explanation sent to ACRS DOE trying to obtain info re Canonsburg & fire at Edlow warehouse for storage of SNM
PAGE, R G Uranium Fuel Licensing Branch 83/12/15 DAVIS, J O
Office of Nuclear Material Safety & Safeguards, Director 2pp
21693 335

B401090127 Notifies that B31221 meeting w/IL Dept of Nuclear Safety postponed due to inclement weather Meeting will be rescheduled at convenience of state
PAGE, R G Uranium Fuel Licensing Branch 83/12/28 DAVIS, J C
Office of Nuclear Material Safety & Safeguards, Director 1p
21757 235

B401090240 Amended contentions to B30707 petition for hearing & for leave to intervene re applicant proposed stabilization & decommissioning plan Certificate of Svc encl
RAPKIN, A Illinois, State of 83/12/30 Commissioners 19pp
21725 284

B401100132 Informs that amends will not be filed to West Chicago Chamber of Commerce contentions
FANELLI, T W Affiliation Unknown 84/01/05 CHILK, S J Office of the Secretary of the Commission 1p 21761 074

B401160103 Informs that airborne Pb-212 concentrations for West Chicago facility high by 32 % Alpha counting instrumentation description sys comparison & transient equilibrium consideration encl
SHELLEY, W J Kerr-McGee Corp 84/01/05 PAPERIELLO, C J Division of Radiological & Materials Safety Programs 8pp 21815 051

B401100120 Responds to Item 6 of ASLB B31117 order, transmitting health physics manual & Kerr-McGee B21214 ltr to NRC re decommissioning DES W/o encl
MONTANGE, C H Shaw, Pittman, Potts & Trowbridge * Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 84/01/06 FRYE, J H Atomic Safety and Licensing Board Panel 2pp 21760 176

B401190255 Notification of B40112 meeting w/Kerr-McGee Chemical Corp in Silver Spring, MD to discuss Kress Creek
NIXON, W A Uranium Fuel Licensing Branch 84/01/10 CROW, W T Uranium Fuel Licensing Branch 1p 21870 095

B401240041 Summary of B31219 meeting w/Kerr-McGee re views on applicability of new EPA stds & proposed encapsulation to meet stds
NIXON, W A Uranium Recovery Licensing Branch 84/01/11 Uranium Recovery Licensing Branch 2pp 21944 260

B401160233 Informs that documents listed in attachment should be forwarded to Judges Morris & Carpenter in order to give matter appropriate & expeditious consideration W/o attachment
FRYE, J H Atomic Safety and Licensing Board Panel 84/01/13
DUNNER, R L Regulations Division 1p 21814 113

B30297 Ack receipt of B40105 ltr describing progress of investigation into possible biases in analysis for airborne 212 NRC plans to review investigation & examine 04000 inter before B40123 repair date
ERIELO, C J Region 3, Office of Director 84/01/17
LLEY, W S Kerr-McGee Corp 1p 21884 220

B30451 Forwards licensee B40120 responses to proposed contentions City of West Chicago Chamber of Commerce & to proposed intentions of People of State of IL
ARNOFF, G Shaw, Pittman, Potts & Trowbridge CHARNOFF, G Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 84/01/20
FRYE, J H, CARPENTER, J H, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 21877 087

B401230452 Response opposing proposed contentions of West Chicago Chamber of Commerce
CHARNOFF, G Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) CHARNOFF, G Shaw, Pittman, Potts & Trowbridge 84/01/20
Atomic Safety and Licensing Board Panel 9pp 21877 094

B401230460 Response to proposed contentions of People of State of IL Atty general standing to seek hearing uncontested Certain contentions re stabilization plan opposed Certificate of Svc encl
ZAHLER, R E Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 84/01/20
Atomic Safety and Licensing Board Panel 51pp 21877 103

B250225 Response recommending grant, in part, of State of IL petition to intervene & denying West Chicago Chamber of Commerce petition to intervene Notice of appearance & Certificate of Svc encl
DUNNER, R L Regulations Division 84/01/20 Atomic Safety and Licensing Board Panel 45pp 21944 134

DOCKET 40-2259 PATHFINDER MINES CORP, RIVERTON, WY

B401310456 Forwards Land Quality Div 1983 annual insp rept prepared following B31014 visit to mine Status of Pathfinders commitments to NRC in 1981 to partially drain Pond 1 & to fence seepage area uncertain Copies of NRC insp requested
ERICKSON, J Wyoming, State of 83/11/29 WOOLSEY, R Uranium Recovery Field Office 6pp 22036 313

B401060630 Submits review of remaining environ monitoring data for Fourth Quarter 1982 for Pathfinder Mines Corp Pumpback wells show significant improvement as indicated by lower radionuclide concentrations
WOOLSEY, R T, PETTENGILL, H J Uranium Recovery Field Office 83/12/02 Uranium Recovery Field Office 2pp 21755 053

B401110581 Advises that primary difference between general land use maps submitted in 1982 & 1983 is that 1983 map illustrates only two residential areas Federal American Partners camp unoccupied since approx Aug 1982
HARDGROVE, T W Pathfinder Mines Corp 83/12/07 WOOLSEY, R T Uranium Recovery Field Office 1p 21790 358

B401060293 Submits review of bioassay rept submitted for Jan-June 1983 & agrees w/Shopenn findings Licensee bioassay program in compliance w/License Condition 25 of License SUA-672 & requirements of Reg Guide B 22
WOOLSEY, R T, PETTENGILL, H J Uranium Recovery Field Office 83/12/09 Uranium Recovery Field Office 2pp 21755 165

B401270435 Forwards IE Insp Rept 40-2259/B3-01 on B30919-22 No violations or deviations noted
HALL, R E Region 4, Office of Director 83/12/13 NUQENT, E L Pathfinder Mines Corp 2pp 21980 340

--B401270439 IE Insp Rept 40-2249/B3-01 on B30919-22 No violations or deviations noted Major areas inspected U milling operations & radiation safety program, including organization, mgt & training, internal exposure control & facilities & equipment
SHOPENN, N M, EVERETT, R J Region 4, Office of Director WOOLSEY, R T Uranium Recovery Field Office 83/12/13 9pp 21980 342

B401210421 Forwards "Update Rept Groundwater Hydrology & Tailings Seepage Collection Sys Near Tailings Reservoir 1 " Pumpback sys has positive impact upon groundwater quality in study area
HARDGROVE, T W Pathfinder Mines Corp 83/12/22 WOOLSEY, R T Uranium Recovery Field Office 1p 22043 050

--B401310423 "Update Rept Groundwater Hydrology & Tailings Seepage Collection Sys Near Tailings Reservoir 1 " W/Five oversize Figures Aperture cards available in PDR
PLAYTON, S J Hydro-Engineering 83/12/31 600pp 22043 051

B401270099 Forwards one oversize Exhibit 4-2 for update rept on seepage from Tailings Reservoir 1 Aperture card available in PDR
HARDGROVE, T W Pathfinder Mines Corp 84/01/04 WOOLSEY, R T Uranium Recovery Field Office 1p 22002 269

B401270557 Ack receipt of annual rept for Pathfinder Mines Corp Lucky Mc Mine Joint review suggested of Dec 1983 update rept re groundwater hydrology & tailings seepage collection sys
WOOLSEY, R T Uranium Recovery Field Office 84/01/12 ERICKSON, J Wyoming, State of 1p 22000 334

DOCKET 40-2298 SPRAGUE ELECTRIC CO, NORTH ADAMS, MA

B401040465 IE Insp Findings & Licensee Ack dtd B31128 of Licenses SUB-778 & 20-00484-03 Insp findings no violations observed
MCGINNESS, J Region 1, Office of Director 83/11/28 1p 21707 183

DOCKET 40-3453 ATLAS MINERALS, INC, DENVER, CO

B401090660 Forwards detailed analysis re review of 40CFR190 compliance for Atlas Minerals Moab Mill Recommended changes listed
YOUNG, Y A, MARTIN, D E Low-Level Waste & Uranium Recovery Projects Branch 83/11/23 HIGGINSOOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 7pp 21757 352

B401060621 Submits review of First & Second Quarter 1983 environ monitoring data for Moab Mill Values generally below 10% max permissible concentrations
GARCIA, P J, PETTENGILL, H J Uranium Recovery Field Office 83/12/01 Uranium Recovery Field Office 3pp 21755 103

DOCKETED ITEMS

7

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

B401040494 Forwards IE Insp Rept 40-4492/B3-01 on 831003 No violations noted
HALL, R E Region 4, Office of Director 83/10/20 ANDRUS, N J
Federal American Partners 2pp 21707 155

--B401040490 IE Insp Rept 40-4492/B3-01 on 831003 No violations noted
Major areas inspected shutdown U milling facility, including
radiation safety program & tailings mgt/enviro monitoring
program
GAIN, C L, EVERETT, R J Region 4, Office of Director 83/10/17
3pp 21707 157

B401110489 Application for amend to License SUA-667, changing operating
structure & name of facilities in Gas Hills, WY New name is
Gas Hills Project, American Nuclear Corp
ANDRUS, N J American Nuclear Corp 83/11/18 JIERREE, C Uranium
Recovery Field Office 2pp 21795 350

B401110987 Advises of new mailing & ofc address of America Nuclear
Corp, Gas Hills Project
COX, E J American Nuclear Corp 83/12/08 SMITH, R D Uranium
Recovery Field Office 1p 21790 359

B401310442 Issues Amend 15 to License SUA-667, authorizing cleanup of
contaminated soil, per 830520 submittal entitled, "Cleanup of
Windblown Tailings Contamination " Const rept will be
submitted by 840301
SMITH, R D Uranium Recovery Field Office 83/12/28 Federal
American Partners 2pp 22036 330

--B401310446 Safety evaluation supporting issuance of Amend 15 to License
SUA-667, authorizing cleanup of contaminated soil immediate
follow-through, w/addl cleanup of other windblown tailings
areas, should be done to prevent recontamination
JIERREE, C C, PETTENGILL, H J Uranium Recovery Field Office
83/12/21 4pp 22036 332

B401160450 FIELD TESTING OF FUGITIVE DUST CONTROL TECHNIQUES AT A
URANIUM MILL TAILINGS PILE - 1982 FIELD TEST, GAS HILLS,
WYOMING
ELMORE, H R, HARTLEY, J N Battelle Memorial Institute, Pacific
Northwest Laboratory FIN B-2370 NUREG/CR-3510 83/12/31
Division of Health, Siting & Waste Management 60pp Available at
NRC #4 50 21822 261

B401310422 Summary of 831213 meeting w/State of WY Dept of Environ
Quality, American Nuclear Corp & TVA in Lakewood, CO re impact
of new EPA stds for U mill tailings on mgt alternatives
available for license renewal & startup of Gas Hills Mill
GARCIA, P J, JIERREE, C C, PETTENGILL, H J Uranium Recovery Field
Office 84/01/09 Uranium Recovery Field Office 4pp
22034 351

DOCKET 40-3508 MYERSON TOOTH CORP, CAMBRIDGE, MA

B401040019 Responds to FOIA request for list of schools, businesses &
shops in Cambridge, MA possessing NRC licenses for use of
radioactive compounds & for copy of licenses Forwards App A
documents
FELTON, J M Division of Rules and Records 83/10/14
CHRISTENSEN, D Citizens Against Research Bans 5pp 21731 312

--B401040282 Amend 2 to Source Matl License SUB-706 for Myerson Tooth
Corp, authorizing use of natural U as sodium uranate, for
colorant in artificial teeth, per 790314 application & 0419
& 0803 ltrs
BASSIN, N Material Licensing Branch 79/09/24 2pp 21732 102

DOCKET 40-5577 MASSACHUSETTS INSTITUTE OF TECHNOLOGY, CAMBRIDGE, MA

B401040019 Responds to FOIA request for list of schools, businesses &
shops in Cambridge, MA possessing NRC licenses for use of
radioactive compounds & for copy of licenses Forwards App A
documents
FELTON, J M Division of Rules and Records 83/10/14
CHRISTENSEN, D Citizens Against Research Bans 5pp 21731 312

--7909070339 Matl/Byproduct License SUB-687 for MA Inst of Technology is
amended in its entirety per 790426 application Amend 2
authorizes use of U in cylindrical slugs in light water &
graphite moderated assembly
VACCA, P C Material Licensing Branch 79/08/03 2pp 67052 001

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

B401030319 Discusses impact of new environ stds on West Chicago Rare
Earths Facility Table 8-3 narrative explanation sent to
ACRB DOE trying to obtain info re Canonsburg & Fire at Edlow
warehouse for storage of SNM
PAGE, R G Uranium Fuel Licensing Branch 83/12/15 DAVIS, J O
Office of Nuclear Material Safety & Safeguards, Director 2pp
21693 335

B401120140 Recommends Geotechnical & Engineering Branches complete
review of Canonsburg remedial action plan Questions
remaining after 831208 meeting w/DOE should be handled by
Hydrology Section
MILLER, H J Repository Projects Branch (Post 831001) 83/12/21
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch
1p 21805 117

B401120575 Advises that request for assistance in reviewing
geohydrology at Canonsburg site has been forwarded to L
Higginbotham who will arrange for appropriate technical
review
MILLER, H J Repository Projects Branch (Post 831001) 83/12/30
PAGE, R G Uranium Fuel Licensing Branch 1p 21796 362

DOCKET 40-6622 PATHFINDER MINES CORP, SHIRLEY BASIN, WY

B401270342 "Second Quarter 1983 Environ Monitoring Data W/Dose
Calculations " W/830909 ltr
SMITH, J C Pathfinder Mines Corp 83/06/30 BROWN, G D Region 4,
Office of Director 60pp 21975 078

B401270502 "Hydrologic Monitoring Rept, 1983 " W/nine oversize figures
Aperture cards available in PDR W/831220 ltr
MURDOCK, E S Pathfinder Mines Corp 83/12/31 KDMINSKI, O
Uranium Recovery Field Office 251pp 22000 162

DOCKET 40-6659 GETTY OIL CO - PETROCHEMICS CO, SHIRLEY BASIN, WY

B401190455 Requests written ruling re impact of proposed corporate
restructuring of domestic mineral operations on status of
Source Matl License SUA-551
COLLINS, J C Getty/Petrochemics Co 83/12/01 PETTENGILL, H
Uranium Recovery Field Office 2pp 21861 336

B401310415 Advises of review of 831201 ltr re corporate restructuring
of Getty Oil Co domestic minerals operations Transfer of
Source Matl License SUA-551 to Petrochemics Co, direct
subsidiary of Getty Oil Co, approved
SMITH, R D Uranium Recovery Field Office 83/12/30 COLLINS, J C
Getty/Petrochemics Co 1p 22035 356

DOCKET 40-6920 AUTOMATION INDUSTRIES, INC, PHOENIXVILLE, PA

B401040356 PNC-I-83-128 on 831228, inspector found Automation Industries
Model 500 SU source changer on street Changer intact,
padlocked & labeled w/radioactive yellow III label Changer
contained Ir-192 w/transport index of 1 m/h
DENNIS, N, KINNEMAN, J Region 1, Office of Director 83/12/20
2pp 21706 149

DOCKET 40-6940 KAWECKI BERYLCO IND, INC., BOYERTOWN, PA

B401030294 Forwards EIA associated w/renewal of License SMB-920 info re
fluoride contamination will be submitted in near future W/o
encl
WYNGARDEN, S D Uranium Fuel Licensing Branch 83/12/22 STANI, L V, W
Pennsylvania, Commonwealth of, 1p 21693 354

B401060226 Forwards EIA for renewal of License SMB-920 held by
Kawecki Berylco Industries Renewed license requires licensee
to monitor for fluoride in forage crops grown on land
northeast of site twice during harvest W/o encl
WYNGARDEN, S D Uranium Fuel Licensing Branch 83/12/28
MCINLEY, T Pennsylvania, Commonwealth of, 1p 21744 130

DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA

B401200109 Formalizes delivery of "Rept on Decontamination of
Aluminothemic Bldg, Whittaker Corp," dtd 830426 & compiled
by Radiation Mgt Corp
COLLINS, T J Deste Marine 83/12/13 CROWE, W Division of Fuel
Cycle & Material Safety 2pp 21872 177

DOCKETED ITEMS

DOCKET 40-7580 FANSTEEL, INC , NORTH CHICAGO, IL

B401230003 Submits License SMB-911 monthly rept Total of 580,920 lbs dry lime hydrate discharged into Pond 3 No flow evident on West well
PIERRET, J A Fansteel, Inc 83/07/22 COLLINS, J T Region 4,
Office of Director 1p 21884 306

B401230013 Submits SMB-911 monthly rept for Aug 1983 As of 830901,
925,000 lbs dry lime hydrate directly to Pond 3
PIERRET, J A Fansteel Metals (subs of Fansteel, Inc) 83/09/05
COLLINS, J T Region 4, Office of Director 2pp 21884 360

B401230300 Submits info re Pond 3 French drain had flow rate of 9.0 gpm
on 830930 As of 831003, 1,118,000 lbs dry lime hydrate
added to Pond 3 No change w/low flow on three new monitor
wells near Pond 3 noted
PIERRET, J A Fansteel Metals (subs of Fansteel, Inc) 83/10/14
COLLINS, J T Region 4, Office of Director 1p 21883 337

B401230349 Submits info re Pump 3 Pumping of longitudinal drain not
resumed because flow at French drain remains static No
line added during Oct 1983
PIERRET, J A Fansteel Metals (subs of Fansteel, Inc) 83/11/15
COLLINS, J T Region 4, Office of Director 1p 21884 268

DOCKET 40-7982 HONEYWELL, INC , HOPKINS, MN

B401230142 Forwards IE Insp Rept 40-7982/83-01 on 831108-10 & notice of
violation
WIEDEMAN, D G Region 3, Office of Director 83/12/14 JASKA, J M
Honeywell, Inc 2pp 21884 322

--B401230144 Notice of violation from insp on 831108-10
WIEDEMAN, D G Region 3, Office of Director 83/12/14 2pp
21884 324

--B401230148 IE Insp Rept 40-7982/83-01 on 831108-10 Violation noted
survey instruments not calibr at proper frequencies &
individual did not wear assigned finger badge
OBERG, C T, SHATTERLY, L W, WIEDEMAN, D G Region 3, Office of
Director 83/12/13 18pp 21884 326

B401300146 Ack receipt of B40110 ltr informing NRC of steps taken to
correct noncompliance noted in insp of License SUB-971
WIEDEMAN, D G Region 3, Office of Director 84/01/19 JASKA, J M
Honeywell, Inc 1p 21998 259

--B401300149 Responds to NRC 831214 ltr re violations noted in insp of
License SUB-971 Corrective actions all appropriate
instrumentation will be properly calibr by B40113 &
employees briefed on use of TLD badges
JASKA, J M Honeywell, Inc 84/01/10 WIEDEMAN, D G Region 3,
Office of Director 2pp 21998 260

DOCKET 40-8011 AIR FORCE, DEPT OF, EGLIN AFB, FL

B401060444 Ack receipt of 831130 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 40-8011/83-01
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/12/15 CORNETTE, J C Air Force, Dept of, Armament Laboratory
Environment 1p 21740 071

--B401060447 Responds to NRC 831018 ltr re violations noted in IE Insp
Rept 40-8011/83-01 on 830826 Corrective actions magnesium-
thorium Bomarc missile residue will not be shipped & addl
training will be provided
CORNETTE, J C Air Force, Dept of, Armament Laboratory
Environment 83/11/30 Region 2, Office of Director 2pp
21740 072

--B401060450 Discusses IE Insp Rept 40-8011/83-01 on 830826 & forwards
notice of violation
STOHR, J P Division of Emergency Preparedness & Materials Safety
83/10/18 CORNETTE, J C Air Force, Dept of, Armament Laboratory
Environment 2pp 21740 074

B401060451 Notice of violation from insp on 830826 Violation noted
source matl transferred to Agreement State license in
unauthorized form
* Region 2, Office of Director 83/10/18 1p 21740 076

DOCKET 40-8046 WEST BANK RADIATION THERAPY CENTER, MINNEAPOLIS, MN

B401100346 Ack receipt of 831219 ltr informing NRC of steps taken to
correct noncompliance noted in NRC 831107 ltr Amend request
sent to regional licensing ofc to amend License 22-03251-01
& terminate License SUB-1032
WIEDEMAN, D G Region 3, Office of Director 84/01/05 MATHEWS, M D
West Bank Radiation Therapy Center, Minneapolis, MN 1p
21763 295

--B401100355 Requests termination of License SUB-1032 & amend to License
22-03251, allowing storage of Group VI matls
MATHEWS, J A West Bank Radiation Therapy Center, Minneapolis, MN
83/12/19 Region 3, Office of Director 1p 21763 296

DOCKET 40-8064 EXXON MINERALS CO , USA, HOUSTON, TX

B401090191 Second Quarter 1983 rept re U solution mining pilot program
W/830805 ltr
SHANNON, J B Exxon Corp 83/06/30 LINEHAN, J J Uranium Recovery
Licensing Branch 9pp 21757 201

B401270183 Forwards estimated 1983 reclamation bonding requirements
recently submitted to WY Dept of Environ Quality for Exxon
Highland U Operations & recently negotiated ltr of credit
for 1982 bond
SHANNON, J B Exxon Corp 83/12/02 SMITH, R D Uranium Recovery
Field Office 7pp 22002 273

B401310504 Submits U data for original pilot observation Well O-O-7,
per 831201 telcon
CLARK, D E Exxon Corp 83/12/02 SMITH, M Wyoming, State of
2pp. 22037.326

B401110085 Forwards new Ltr of Credit 304319, State of WY Div of Environ
Quality acceptance of new ltr of credit & release of
liability of old Ltr of Credit 1-12897 W/o old ltr of
credit
SHANNON, J B Exxon Corp 83/12/07 SMITH, D Uranium Recovery
Field Office 9pp 21795 232

B401100099 Submits review of Exxon Minerals Co ltr of credit Review
involved only portion of estimated bond requirements
covering in situ leach facility
WASTLER, S L, HAWKINS, E F Uranium Recovery Field Office 83/12/13
Uranium Recovery Field Office 2pp 21768 353

--B401100103 Forwards estimated 1983 reclamation bond Bond must be
approved by State of WY Dept of Environ Quality
SHANNON, J B Exxon Corp 83/12/02 SMITH, R D Uranium Recovery
Field Office 7pp 21768 355

DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT

B401060633 Addendum to "Semiannual Environ Monitoring Rept for Jan-June
1983 "
LAWTON, K D Rio Algom, Ltd 83/11/04 34pp 21755 065

DOCKET 40-8102 EXXON CO , USA, HOUSTON, TX

B401100494 Provides assurance that input of NRC tailings
reclamation planning process timely to coordinate input
efforts between land quality div & water quality div
RANDEN, L Wyoming, State of 83/09/13 SMITH, R D Uranium
Recovery Field Office 6pp 21768 197

B401040253 Forwards IE Insp Rept 40-8102/83-01 on 830906-08 & notice
of violation
HALL, R E Region 4, Office of Director 83/10/14 SHANNON, J B
Exxon Corp 2pp 21701 137

--B401040259 Notice of violation from insp on 830906-08
* Region 4, Office of Director 83/10/14 1p 21701 139

--B401040269 IE Insp Rept 40-8102/83-01 on 830906-08 Violation noted
failure to maintain site security at main gate
SPITZBERG, D B, PANGBURN, O C, EVERETT, R J Region 4, Office of
Director 83/10/12 7pp 21701 140

B401090774 Submits list of info/data reviewed to assess adequacy of
Highland tailings basin seepage monitoring program, in
response to 831013 ltr Three addl wells proposed
PATTON, J D Exxon Corp 83/11/28 SMITH, R D Uranium Recovery
Field Office 7pp 21767 022

DOCKETED ITEMS

9

8401120178 Forwards Section 3 5 3 & several modified tables & figures of other sections of B30830 license amend application, incomplete at time of submittal
PATTON, J D Exxon Corp 83/12/02 PETTENGILL, H J Uranium Recovery Field Office 1p 21804 352

--8401120183 Application for amend to License SUA-1139 re decommissioning of mill
* Exxon Corp 83/11/30 8pp 21804 353

8401270183 Forwards estimated 1983 reclamation bonding requirements recently submitted to WY Dept of Environ Quality for Exxon Highland U Operations & recently negotiated ltr of credit for 1982 bond
SHANNON, J B Exxon Corp 83/12/02 SMITH, R D Uranium Recovery Field Office 7pp 22002 273

8401110085 Forwards new Ltr of Credit 304319, State of WY Div of Environ Quality acceptance of new ltr of credit & release of liability of old Ltr of Credit I-12897 W/o old ltr of credit
SHANNON, J B Exxon Corp 83/12/07 SMITH, D Uranium Recovery Field Office 9pp 21795 232

8401100099 Submits review of Exxon Minerals Co ltr of credit Review involved only portion of estimated bond requirements covering in situ leach facility
WASTLER, S L, HAWKINS, E F Uranium Recovery Field Office 83/12/13 Uranium Recovery Field Office 2pp 21768 353

--8401100103 Forwards estimated 1983 reclamation bond Bond must be approved by State of WY Dept of Environ Quality
SHANNON, J B Exxon Corp 83/12/02 SMITH, R D Uranium Recovery Field Office 7pp 21768 355

8401060214 Responds to B30830 request for amend to Source Matl License SUA-1139 for decommissioning & reclamation activities Plan insufficient Comments encl
PETTENGILL, H J Uranium Recovery Field Office 83/12/19 PATTON, J D Exxon Corp 4pp 21744 162

DOCKET 40-8331 AFRICAN METALS CORP, NEW YORK, NY

8401300088 Advises that License SUC-1211 terminated License encl
PAGE, R O Uranium Fuel Licensing Branch 84/01/06 SHICK, V Afrimet Indussa, Inc 2pp 22006 261

--8401300091 Evaluation supporting termination of License SUC-1211
CROW, W T Uranium Fuel Licensing Branch 84/01/06 Uranium Fuel Licensing Branch 1p 22006 262

--8401300103 Requests NRC records be updated to indicate vendor no longer owns License SUC-1211. DOE assumed ownership of matl on 830701
SHICK, V Afrimet Indussa, Inc 83/08/31 CROW, W T Uranium Fuel Licensing Branch 3pp 22006 263

--8401300108 Forwards settlement agreement transferring title of Afrimet-Indussa, Inc residues at Niagara Falls, NY & Fernald OH to DOE effective 830701
KELLER, E L Energy, Dept of 83/10/31 CROW, W T Uranium Fuel Licensing Branch 4pp 22006 266

DOCKET 40-8348 MINERALS EXPLORATION CO, LOS ANGELES, CA

8401090060 Informs that Amend 4 to Source Matl License SUA-1223, extending license expiration date until NRC determines decommissioning adequate, should be fee exempt
WASTLER, S L, HAWKINS, E F Uranium Recovery Field Office 83/12/13 MILLER, W D License Fee Management Branch 1p 21787 267

8401090410 Submits Amend 4 to Source Matl License SUA-1223, revising License Condition 4 to extend license expiration date from 831231 until NRC determines that decommissioning adequate
SMITH, R D Uranium Recovery Field Office 83/12/14 Union Oil Co. of California 1p 21768:057

DOCKET 40-8452 BEAR CREEK URANIUM CO, CASPER, WY

8401110545 Forwards environ monitoring rept for First Half 1983 No areas identified requiring licensing action
PANGBURN, G C, PETTENGILL, H J Uranium Recovery Field Office, 83/12/06 Uranium Recovery Field Office 4pp 21790 325

--8401110551 Bear Creek U Co environ monitoring rept, First Half 1983
PANGBURN, G C, Bear Creek Uranium Co 83/06/30 4pp 21790 329

8401060643 Submits review of 1983 const rept on emplacement of clay liner matl ground portions of tailings disposal area
Liner matl meets specified permeability requirement
PANGBURN, G C, PETTENGILL, H J Uranium Recovery Field Office 83/12/20 Uranium Recovery Field Office 2pp 21755 058

DOCKET 40-8584 MINERALS EXPLORATION CO, LOS ANGELES, CA

8401040467 Forwards IE Insp Rept 40-8584/83-01 on 830928 & notice of violation
HALL, R E Region 4, Office of Director 83/11/15 DYKERS, L G Minerals Exploration Co (subs of Union Oil Co of California) 3pp 21707 184

--8401040473 Notice of violation from insp on 830928
* Region 4, Office of Director 83/11/15 2pp 21707 187

--8401040475 IE Insp Rept 40-8584/83-01 on 830928 Violations noted work in areas where airborne radionuclide concentrations exceeded respirator protection factor
SPITZBERG, D B, GARCIA, P J, EVERETT, R J Region 4, Office of Director 83/11/07 6pp 21707 189

8401310496 Submits comments from State of WY Land Quality Div re analysis of long-term stability of reclaimed tailings pond, per 831115 meeting
RANDEN, L Wyoming, State of, 83/12/13 HILL, C Union 76 Minerals Exploration Co 12pp 22037 332

8401270177 Informs of condition of Sweetwater U Project tailings pond Repairs to tailings pond liner probably will not be completed until summer 1984
PAYNE, S W Wyoming, State of 83/12/16 SMITH, R D Uranium Recovery Field Office 2pp 22002 280

8401040511 Ack receipt of 831205 ltr informing NRC of steps taken to correct violations noted in IE Insp of License SUA-1350 Implementation of corrective actions will be reviewed during future insp to determine full compliance
HALL, R E Region 4, Office of Director 83/12/27 KLEIN, T J Minerals Exploration Co (subs of Union Oil Co of California) 1p 21705 305

8401310492 Submits discussion & description of prior & present tailings plans
HILL, C Z Union 76 Minerals Exploration Co 84/01/09 RANDEN, L Wyoming, State of 2pp 22037 349

8401310417 Ack receipt of 831216 ltr re insp of Minerals Exploration Co, Sweetwater U Project Joint insp to determine success of liner repair recommended Licensee informed that liner repairs should be completed at earliest possible date
PETTENGILL, H J Uranium Recovery Field Office 84/01/12 SHAFFER, R Wyoming, State of 2pp 22035 354

DOCKET 40-8585 WYOMING MINERAL CORP, LAKEWOOD, CO

8401060612 Submits Amend 4 to Source Matl License SUA-1315, revising License Conditions 1 & 2 to record name & mailing address of licensee
SMITH, R D Uranium Recovery Field Office 83/12/21 Westinghouse Electric Corp 2pp 21755 113

8401260271 Discusses 830510 & 0702 submittals requesting approval for disposal of waste ion exchange resin in Kennecott Copper Mine dump Spent ion exchange resin constitutes byproduct matl per 10CFR40 4(a-1) Request withdrawn on 831212
JIERREE, C C, PETTENGILL, H J Uranium Recovery Field Office 83/12/30 Uranium Recovery Field Office 2pp 21987 355

DOCKET 40-8586 KERR-MCGEE NUCLEAR CORP, OKLAHOMA CITY, OK

8401060248 Informs that Amend 3 to Source Matl License SUA-1330, extending expiration date to 840930 to allow NRC sufficient time for site visit & to determine that decommissioning adequate is fee exempt
HILDBRAND, P, HAWKINS, E F Uranium Recovery Field Office 83/12/14 MILLER, W D License Fee Management Branch 1p 21748:360

8401090404 Submits Amend 3 to Source Matl License SUA-1330, revising License Condition 4 to extend license expiration date from 831231 until 840930 to permit NRC to determine adequacy of site decommissioning
SMITH, R D Uranium Recovery Field Office 83/12/14 SHELLEY, W J Kerr-McGee Corp 1p 21768:058

DOCKETED ITEMS

DOCKET 40-B402 SILVER KING MINES, INC., CASPER, WY

B401060226 Forwards, for review, Silver King Mines, Inc B31122 request for extension of Source Matl License SUA-1336 & staff review of request
PANGBURN, G C Uranium Recovery Field Office 83/12/15 BROWN, W L
Region 4, Office of Director 1p 21744 123

--B401060243 Application to extend expiration date of current License SUA-1336 & defer further preoperational monitoring
WOLFF, C E Silver King Mines, Inc 83/11/22 PETTENGILL, H J
Uranium Recovery Field Office 2pp 21744 124

--B401060246 Recommends B31122 request for extension of expiration date of Source Matl License SUA-13 be granted
PANGBURN, G C, PETTENGILL, H J Uranium Recovery Field Office
83/12/16 Uranium Recovery Field Office 4pp 21744 126

DOCKET 40-B410 STEPAN CHEMICAL CO., MAYWOOD, NJ

B401100271 PNO-I-B4-DD4 on B30112, well supplying drinking water to community near facility closed during wk of B40102 due to exceeding EPA drinking water std for gross alpha activity
Add'l analysis & resampling for isotopes conducted
KINNEMAN, J, JOYNER, J Region 1, Office of Director 84/01/12
2pp 21843 247

DOCKET 40-B431 ARMY, DEPT OF, ROCK ISLAND, IL

B401050337 Forwards IE Insp Rept 40-B431/83-03 on B31130 & 1201 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/12/21
REGISTER, B Army, Dept of 2pp 21727 193

--B401050339 IE Insp Rept 40-B431/83-03 on B31130 & 1201 No noncompliance noted
Major areas inspected air sampling, contamination control, personnel exposure & instrument calibr programs
JANUSKA, A, ROZAK, S, SCHUMACHER, M Region 3, Office of Director
83/12/21 5pp 21727 199

DOCKET 40-B481 ENERGY FUELS NUCLEAR, INC., DENVER, CO

B401310416 Submits review of semiannual environ monitoring rept for Jan-June 1983
HILDBRAND, R, HAWKINS, E F Uranium Recovery Field Office
83/12/30 Uranium Recovery Field Office 5pp 22034 355

DOCKET 40-B723 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

B401090593 Submits fifteenth quarterly rept, Third Quarter 1983, for pilot in situ U operation in Converse County, WY
APPEL, R R, GARLING, R A United Nuclear Corp 83/11/15 SMITH, R D
Uranium Recovery Field Office SPEARS, R Wyoming, State of 20pp
21737 268

B401040002 Application for amend to License SUA-1373, to allow UNC Teton to discharge water from north & south Leuenberger solar evaporation ponds Analytical data rept & amend fee encl
APPEL, R R United Nuclear Corp 83/11/21 SMITH, R D Uranium
Recovery Field Office 4pp 21708 360

B401310410 Issues Amend B to Source Matl License SUA-1373 to allow one-time surface discharge of all water presently contained within south Leuenberger solar evaporation pond & to delete License Conditions 23 & 32
SMITH, R D Uranium Recovery Field Office 84/01/03 Teton
Exploration Drilling Co, Inc 1p 22035 357

--B401310412 Safety evaluation supporting licensee B31121 request for one-time surface discharge of all water presently contained within south Leuenberger solar evaporation pond & deletion of License Conditions 23 & 32
WASTLER, S L, HAWKINS, E F Uranium Recovery Field Office
84/01/03 3pp 22035 358

DOCKET 40-B745 OGLE PETROLEUM, INC., CASPER, WY

O1110383 Provides current status on compliance w/License Condition 13 re min qualifications for radiation safety officer
AJ Brown completed 4-wk training requirement Course descriptions & completion certificates encl
CATCHPOLE, G J Ogle Petroleum, Inc 83/12/07 LINEHAN, J J
Uranium Recovery Field Office 8pp 21794 316

B401060656 Submits review of Ogle Petroleum, Inc B30219-0824 semiannual rept re commercial in situ solution mining operation & B30826 annual rept submitted to State of WY No further licensing action necessary
WASTLER, S L, HAWKINS, E F Uranium Recovery Field Office 83/12/12
Uranium Recovery Field Office 3pp 21795 050

B401270160 Semiannual effluent release rept for Jul-Dec 1983 No release of radioactive effluents to unrestricted areas reported
BROWN, K J Ogle Petroleum, Inc 83/12/31 Uranium Recovery Field
Office 1p 22002 309

DOCKET 40-B760 EDLOW INTERNATIONAL CO., WASHINGTON, DC

B401050652 Confirmatory action ltr re agreement reached during B31230 telcon pertaining to mod of firewatch condition identified in Paragraph 2 B of B31209 confirmatory action ltr
KEPPLER, J G Region 3, Office of Director 83/12/30 PODHURST, B W
Edlow International Co 1p 21724 269

B401100262 Ack receipt of B31221 ltr & arson investigator preliminary rept of recent fire at Edlow Intl Co
SRENIAWSKI, D J Region 3, Office of Director 84/01/04 BROOKS, L
East St Louis, IL 1p 21759 195

B401160292 Confirmatory action ltr accepting scheduled shipment of U ore concentrates on B30111 Enforcement conference on B40119 at Region III also confirmed
HIND, J A Division of Radiological & Materials Safety Programs
84/01/11 PODHURST, B W Edlow International Co 2pp 21814 001

--B401160297 Requests permission to receive & store U ore concentrates at facility until written agreements obtained
PODHURST, B W Edlow International Co 84/01/04 AXELSON, B
Region 3, Office of Director 1p 21814 003

B401190443 Corrected confirmatory action ltr requesting that future incoming shipments of low enriched U hexafluoride be postponed until concerns resolved re fire protection sys upgrades & completion of ltr of agreement
HIND, J A Division of Radiological & Materials Safety Programs
84/01/13 PODHURST, B W Edlow International Co 2pp 21849 287

B401160091 Notice of B40119 significant licensee meeting in Glen Ellyn, IL to discuss NRC findings during recent insp, enforcement options available & licensee corrective actions
* Region 3, Office of Director 84/01/16 Region 3, Office of
Director 1p 21809 362

B401240170 Denies B40114 request to terminate firewatch until further NRC analyses complete
AXELSON, W L Region 3, Office of Director 84/01/20 PODHURST, B W
Edlow International Co 1p 21908 350

--B401240176 Requests authorization to terminate firewatch established B31230 during mods to sprinkler sys Mods requested by East St Louis Fire Dept now complete
PODHURST, B W Edlow International Co 84/01/16 AXELSON, W
Region 3, Office of Director 1p 21908 391

B401310344 PNO-III-B4-010 on B40126, approx 135 persons participated in demonstration opposing continued storage of U at util warehouse in East St Louis, IL Major fire occurred at warehouse on 831207
LASUK, S, AXELSON, W Region 3, Office of Director 84/01/27 1p
22015 058

DOCKET 40-B768 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

B401060525 Recommends Kerr-McGee design pump test on "Q" sand project so that confining characteristics of clay can be characterized
OGLE, K H Wyoming, State of 83/06/06 Wyoming, State of 2pp
21743 354

B401090205 Forwards revised "Application for Permit Rev to Mining Permit 304C, South Powder River Basin, Converse County, WY"
FREEMAN, M D Kerr-McGee Nuclear Corp 83/11/21 LINEHAN, J J
Licensing Branch 1 1p 21757 021

--B401090214 "Application for Permit Rev to Mining Permit 304C, South Powder River Basin, Converse County, WY"
* Kerr-McGee Nuclear Corp 83/06/30 129pp 21757, 023

B401110441 Forwards "Analysis of Kerr-McGee Q Sand Pump Test"
WILLIAMS, R E Williams & Associates 83/12/01 LINEHAN, J J Uranium
Recovery Field Office 1p 21795 285

DOCKETED ITEMS

11

--B40110446 "Analysis of Kerr-McGee O Sand Pump Test "
* Williams & Associates 83/11/25 29pp 21795 286

B40106071 Issues Amend 9 to Source Matl License SUA-1387, revising License Condition 44 to modify upper control limits for monitor wells & to recognize natural variability of groundwater
SMITH, R D Uranium Recovery Field Office 83/12/13 SHELLEY, W J
Kerr-McGee Nuclear Corp 3pp 21755 033

--B40106074 Submits evaluation of relevant background info & recommendation for action re Amend 9 to Source Matl License SUA-1387 Issuance of amend would not result in any extra environ impacts
HILDENBRAND, P, LINEHAN, J J Uranium Recovery Field Office 83/12/09 Uranium Recovery Field Office 7pp 21755 036

B401230044 Application for amend to License SUA-1387, changing name of licensee to Sequoyah Fuels Corp Press release & check for review fee encl
SHELLEY, W J Kerr-McGee Nuclear Corp 83/12/13 SMITH, R D
Uranium Recovery Field Office 2pp 21905 356

DOCKET 40-8801 RADIATION MANAGEMENT CORP, NORTHBROOK, IL

B401190176 Briefs of director on recent items of interest, including B40111 CRGR review, B40109 meeting re West Lake Landfill, B40110 meeting re Wood River Junction groundwater & B40111 meeting re Westinghouse license renewal
PAGE, R G Uranium Fuel Licensing Branch 84/01/12 DAVIS, J G
Office of Nuclear Material Safety & Safeguards, Director 2pp 21861 319

B401310073 Trip rept of B40109 meeting in Columbia, MO w/ORNL & Univ of Missouri, Columbia re status of contract work on evaluation of remedial action for radioactive contamination in Westlake Landfill, Bridgeton, MO
WYNWARDEN, B D Uranium Fuel Licensing Branch 84/01/18 CROW, W T
Uranium Fuel Licensing Branch 1p 22028 068

DOCKET 40-8821 RESOURCE ENGINEERING, INC, WALTHAM, MA

B401270220 IE Insp Findings & Licensee Ack dtd B40111 of License SMB-1419 Insp findings failure to calibr survey meter at required intervals
NICOLSON, J F Region 1, Office of Director 84/01/11 1p 21982 229

DOCKET 40-8824 TARGET RESEARCH, INC, WHARTON, NJ

B401130007 IE Insp Findings & Licensee Ack dtd B40105 of License SUB-1421 Insp findings records of tests to show package met Spec 7A not properly maintained per 10CFR71.5 & 49CFR173.415(a)
FRIEDMAN, L F Region 1, Office of Director 84/01/05 1p 21802 335

DOCKET 40-8827 WYOMING FUEL CO, LAKEWOOD, CO

B401110437 Responds to request to calculate vol of water yielded by confining layer during 2 09 day pump test at proposed site Behavior of confining layer cannot be predicted in advance under various injection & recovery schemes at site
WILLIAMS, R E Williams & Associates 83/11/23 WASTLER, S Uranium Recovery Field Office 8pp 21794 298

B401130128 Forwards response to NRC B31027 request for addl info re B30819 application for source matl license for proposed R&D I&L Crow Butte project
STOUT, D M Wyoming Fuel Co 83/11/25 LINEHAN, J Uranium Recovery Field Office 60pp 21820 113

B401060994 Responds to request for views on concerns discussed in constituent ltrs re leased property in vicinity of proposed Crow Butte R&D Project, NRC decision on issuances of license will be based on EIA
SMITH, R D Uranium Recovery Field Office 83/12/02 ZORINSKY, E
Senate 2pp 21755 124

B401060290 Summary of B31108 meeting w/State of NE, Dept of Environ Control in Lincoln, NE to discuss hydrologic concerns re Wyoming Fuel Co application for Crow Butte U Project
WASTLER, S L, LINEHAN, J J Uranium Recovery Field Office 83/12/06 Uranium Recovery Field Office 3pp 21748 355

--B401060257 Notifies of B31108 meeting w/State of NE Dept of Environ Control in Lincoln, NE re vendor application for Crow Butte U Project & addl info requirements
WALL, R B Nebraska, State of 83/11/01 LINEHAN, J Uranium Recovery Field Office 2pp 21748 358

B401060604 Responds to request for addl info re groundwater restoration at Teton & Ogale in situ leach projects FES for projects encl H/O encl
LINEHAN, J J Uranium Recovery Field Office 83/12/08 HOFFMAN, T
Western Nebraska Resources Council 3pp 21755 121

B401310469 Discusses State of NE Question 27 re evidence that Well PT-9 plugged w/fine matl Wyoming Fuels supplied response, that subsequent to pump test, screen was pulled from well & found to be plugged w/fine matl Screen replaced
FRENCH, P S Nebraska, State of 83/12/08 WASTLER, S Uranium Recovery Field Office 1p 22035 362

B401110500 Forwards request for addl info re permit application Consolidation of all submittals to NRC, EPA, UNL-CBD & DEC, including responses to questions, should be rewritten into application document form
LUOWIG, G H Nebraska, State of 83/12/15 JONES, P Wyoming Mineral Corp 3pp 21795 346

B401310501 Forwards Wyoming Fuel Co responses to NDEC questions re solar evaporation pond design
STOUT, D M Wyoming Fuel Co 83/12/21 WASTLER, S Uranium Recovery Field Office 4pp 22037 328

DOCKET 40-8833 MANLABS, INC, CAMBRIDGE, MA

B401040019 Responds to FOIA request for list of schools, businesses & hosps in Cambridge, MA possessing NRC licenses for use of radioactive compounds & for copy of licenses Forwards App A documents
FELTON, J M Division of Rules and Records 83/10/14
CHRISTENSEN, D Citizens Against Research Bans 5pp 21731 312

--B401040274 Source Matl License SUB-1427 for ManLabs, Inc, authorizing use of U-235, as metal & alloys, for metallurgical testing, per B30421 application & 0606 ltr
JERMAN, P C Division of Fuel Cycle & Material Safety 83/06/21 1p 21732 101

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401260290 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21785 343 24X Fiche 50-003, 84/01/20, B401260290

--B401260294 Public version of revised Emergency Plan Implementing Procedure IP-1015, "Mobilization & Operational Procedure for Offsite Monitoring Teams - Immediate Response " W/B40104 ltr
GAUNY, R D, O'DOOLE, J D Consolidated Edison Co of New York, Inc 83/12/19 MURLEY, T E Region 1, Office of Director. 17pp 21785 344 24X Fiche 50-003, 84/01/20, B401260290

B401300209 Responds to B40109 ltr forwarding correspondence from Croton-Harmon School District in Croton-on-Hudson, NY re Westchester County evacuation plan for school children in event of facility accident FEMA already responded
KRIMM, R W Federal Emergency Management Agency 84/01/24
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 1p 21994 001 24X Fiche 50-000, 84/01/24, B401300209

--B401300213 Forwards post-exercise assessment of B30928 exercise of radiological emergency preparedness plans of State of NY & Oswego County
KRIMM, R W Federal Emergency Management Agency. 84/01/23
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 2pp 21994 002. 24X Fiche 50-000, 84/01/24, B401300209

--B401300215 Post-exercise assessment of B30928 exercise of radiological emergency preparedness plans of State of NY & Oswego County
PETRONE, F P Federal Emergency Management Agency 83/12/23 102pp 21994 004 24X Fiche 50-000, 84/01/24, B401300209

DOCKETED ITEMS

--B401300219 Post-exercise assessment of exercise of State of NY & Oswego County radiological emergency plans
PETERCME, F P Federal Emergency Management Agency 82/10/29
62pp 21974 110 24X Fiche 50-000,84/01/24,8401300209

D Advisory Committee on Reactor Safeguards reports & correspondence

B401300127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee B411C3 meeting w/ARR & ENL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PPA Viewgraphs encl
ACRS - Advisory Committee on Reactor Safeguards 82/12/06
ACRS - Advisory Committee on Reactor Safeguards 33pp 21820 237
24X Fiche 50-000,82/12/06,8401300127

P Operating license stage documents & correspondence

B312190365 Generic Ltr B3-42 to all holders of OLs, applicants for OL & holders of CPs for power reactors on clarification to Generic Ltr B1-07 re response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Svc list encl
EISENHUT, D G Division of Licensing 83/12/19 Consolidated
Edison Co of New York, Inc 21pp 21685 001 24X
Fiche 50-000,83/12/19,8312190365

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,841050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,841090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors applicants for OLs & holders of CPs re availability of NUREG-CY93, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,841130084

Q Inspection reports, IE Bulletins & correspondence

B312120090 IE Bulletin B3-08 "Electrical Circuit Breakers w/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sigs" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type S-M Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

B312120104 IE Info Notice B4-02 "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 033 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 21999 284 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

B401240363 Ack receipt of B31230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-003/83-02 & 50-247/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/19
D'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
21919 340 24X Fiche 50-003,84/01/19,8401240363

--B401240369 Responds to NRC B31129 ltr re violations noted in IE Insp Rept 50-247/83-23 Corrective actions Audit 82-01-EA re 1982 environ program issued & immediate notification sys re environ matters implemented
BROSCUP, O W Consolidated Edison Co of New York, Inc 83/12/30
MARTIN, T T Division of Engineering & Technical Programs 5pp
21919 342 24X Fiche 50-003,84/01/19,8401240363

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B401030169 Forwards IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on B31108-10 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/16
CUNNINGHAM, R Pennsylvania State Univ, University Park, PA 2pp
21680 320 24X Fiche 50-005,83/12/16,8401030169

--B401030176 IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on B31108-10 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of low strategic significance
MADDEN, W, ODDY, A Region 1, Office of Director 83/12/15 2pp
21680 322 24X Fiche 50-005,83/12/16,8401030169

G Inspection reports, IE Bulletins & correspondence

B401030169 Forwards IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on B31108-10 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/16
CUNNINGHAM, R Pennsylvania State Univ, University Park, PA 2pp
21680 320 24X Fiche 50-005,83/12/16,8401030169

--B401030176 IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on B31108-10 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of low strategic significance
MADDEN, W, ODDY, A Region 1, Office of Director 83/12/15 2pp
21680 322 24X Fiche 50-005,83/12/16,8401030169

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401230434 Forwards IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 & notice of violation w/o notice of violation
NORELIUS, C E Division of Project & Resident Programs 83/12/21
REED, C Commonwealth Edison Co 2pp 21882 070 24X
Fiche 50-010,83/12/21,8401230434

--B401230442 IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 Violation noted inadequate corrective action re normal shutdown & radiation protection procedures
WALKER, R, ANDERSON, C D, PAUL, R A Region 3, Office of Director 83/12/14 21pp 21882 072 24X Fiche 50-010,83/12/21,8401230442

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C
Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000,84/01/05,8401230491

B401250082 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21946 278 24X Fiche 50-010,84/01/18,8401250082

--B401250086 Forwards public version of revised Emergency Plan implementing procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
SCOTT, D J Commonwealth Edison Co 83/11/09 DENTON, H R Office of Nuclear Reactor Regulation Director 1p 21946 279 24X
Fiche 50-010,84/01/18,8401250086

DOCKETED ITEMS

13

--8401250087 Public version of revised Emergency Plan Implementing Procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
* Commonwealth Edison Co 83/11/02 31pp 21946 280 24X
Fiche 50-010,84/01/18,8401250082

8401310174 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22035 182 24X Fiche 50-010,84/01/20, 8401310174

--8401310180 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications
SCOTT, D J Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22035 183 24X
Fiche 50-010,84/01/20,8401310174

--8401310187 Public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications
Receipt forms encl
* Commonwealth Edison Co 84/01/02 50pp 22035 185 24X
Fiche 50-010,84/01/20,8401310174

0 Adjudicatory correspondence

8401230388 Order extending time until 840203 for Commission to act to review Director's Decision DD-83-14 which denied requests of Sierra Club & State of OH & 831027 decision which denied request of Environ Policy Inst
CHILK, S J Office of the Secretary of the Commission 84/01/19 Commissioners 1p 21884 278 24X Fiche 50-000,84/01/19, 8401230388

J Insurance & indemnity information

8401200141 Forwards Endorsement 4 to NELIA Certificates N-1,2,3,29,30, 42,43 & 71 & MAELU Certificates M-1,2,3,29,30,42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant Director for State & Licensee Relations 17pp 21865 332 24X
Fiche 50-000,84/01/09,8401200141

8401200184 Forwards listed endorsements to NELIA Policies NF-43,187, 201,253 & 277 & MAELU Policies MF-22,54,64 & 104
OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant Director for State & Licensee Relations 19pp 21863 232 24X
Fiche 50-000,84/01/09,8401200184

P Operating license stage documents & correspondence

8401130224 PHYSICAL TESTS ON SOLIDIFIED DECONTAMINATION WASTES FROM DREDDEN UNIT 1
BARLETTA, R E, ADAMS, J W, DAVIS, R E Brookhaven National Laboratory FIN A-3159 NUREG/CR-3165 83/12/31 Division of Waste Management 109pp Available at NRC \$5 00 21820 001 24X
Fiche 50-010,83/12/31,8401130224

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957,267 24X
Fiche 50-000,84/01/06,8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 105pp 21744 004 24X Fiche 50-000,83/10/20, 8401060040

8401230434 Forwards IE Insp Repts 50-010/83-19,50-237/83-29 & 50-249/83-27 on 830920-1117 & notice of violation W/o notice of violation
NORELIUS, C E Division of Project & Resident Programs. 83/12/21
REED, C Commonwealth Edison Co 2pp 21882,070 24X
Fiche 50-010,83/12/21,8401230434

--8401230442 IE Insp Repts 50-010/83-19,50-237/83-29 & 50-249/83-27 on 830920-1117 Violation noted inadequate corrective action re normal shutdown & radiation protection procedures
WALKER, R, TONGUE, T M, STASEK, S Region 3, Office of Director 83/12/14 21pp 21882 072 24X Fiche 50-010,83/12/21,8401230434

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060, 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 21999 284 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche:50-000,84/01/18,8312120117

S Reportable occurrences, LERs & related correspondence

8401090632 Discusses 831209 uncoupling of trailer containing spent fuel assemblies uncoupled from tractor Cause unknown No damage to tractor, trailer, cask, or any other vehicle incurred Pull test performed successfully.
SCOTT, D J, Commonwealth Edison Co 83/12/28 KEPLER, J O Region 3, Office of Director 20pp 21786 083 24X Fiche 50-010,83/12/28, 8401090632

DOCKET 90-13 BABCOCK & WILCOX CO CRITICAL FACILITY

F. Operating license stage documents & correspondence

8401160232 Forwards application for amend to License CX-10, authorizing full length fuel pin cutting operation into lengths acceptable for DOT-6M Type B containers W/amend fee.
OLSEN, A F Babcock & Wilcox Co 84/01/06 BERNARD, H Standardisation & Special Projects Branch. 2pp. 21814 004 24X
Fiche 50-013,84/01/06,8401160232

--8401160237 Application for amend to License CX-10, authorizing full length fuel pin cutting operation into lengths acceptable for DOT-6M Type B containers, W/one oversize drawing Aperture card is available in PDR
* Babcock & Wilcox Co 84/01/06 12pp 21814 006 24X
Fiche 50-013,84/01/06,8401160232

DOCKETED ITEMS

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

G Inspection reports, IE Bulletins & correspondence

B40100430 Ack receipt of B31222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-016/B3-01
PAPERIELLO, C J Region 3, Office of Director 84/01/05
LENART, R S Detroit Edison Co 1p 21763 107 24X
Fiche 50-016, B4/01/05, B401100430

--B401100436 Responds to NRC B31123 ltr re violations noted in IE Insp Rept 50-016/B3-01 Corrective actions insp, surveillance, operating & reporting procedure, Paragraph D 5 C(1) re min water column gauge modified
JENS, W H Detroit Edison Co B3/12/22 PAPERIELLO, C J Region 3, Office of Director 3pp 21763 108 24X Fiche 50-016, B4/01/05, B401100430

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

F Security, medical, emergency & fire protection plans

B401240395 Informs that emergency plan fully implemented, per B31005 commitment
CLARK, L Massachusetts Institute of Technology, Cambridge, MA 84/01/20 THOMAS, C D Standardization & Special Projects Branch 1p 21920 358 24X Fiche 50-020, B4/01/20, B401240395

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

B401100402 Forwards Rev B to security plan & Rev 3 to security personnel training & qualification plan Revs withheld (ref 10CFR2 790)
KAY, J A Yankee Atomic Electric Co B4/01/02 MURLEY, T E Region 1, Office of Director 2pp 21762 234 24X Fiche 50-029, B4/01/02, B401100402

B401100484 Discusses upgrading of emergency procedures per NUREG-0737, Suppl 1 Approach integrates components of symptom-oriented emergency operation procedures, control room design, safety parameter display sys & operator training
KAY, J A Yankee Atomic Electric Co B4/01/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21761 304 24X Fiche 50-029, B4/01/03, B401100484

B401240466 Forwards IE Insp Rept 50-029/B3-13 on B31024-27 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B4/01/10 HEIDER, L H Yankee Atomic Electric Co 2pp 21908 177 24X Fiche 50-029, B4/01/10, B401240466

--B401240474 IE Insp Rept 50-029/B3-13 on B31024-27 No violations noted
Major areas inspected: emergency preparedness items from appraisal performed B11201-09 & prompt public notification sys insp performed B30503-04
TERC, N M, COHEN, I, CROCKER, H W Region 1, Office of Director B3/12/12 12pp 21908 179 24X Fiche 50-029, B4/01/10, B401240466

B401250111 Releases public version of revised emergency plan implementing procedure table of contents
FELTON, J M Division of Rules and Records B4/01/18 Document Management Branch 1p 21959 075 24X Fiche 50-029, B4/01/18, B401250111

--B401250116 Public version of Rev 30 to emergency plan implementing procedure table of contents W/B31227 transmittal & receipt form
* Yankee Atomic Electric Co B3/12/20 3pp 21959 076 24X Fiche 50-029, B4/01/18, B401250111

B401260052 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records B4/01/18 Document Management Branch 1p 21989 305 24X Fiche 50-029, B4/01/18, B401260052

B401260054 Public version of Change 30 to emergency plan implementing procedures, consisting of Rev 29 to table of contents W/B31110 transmittal & receipt form.
MARKT, D Yankee Atomic Electric Co B3/11/08 Document Management Branch 5pp 21989 306 24X Fiche 50-029, B4/01/18, B401260052

J Insurance & indemnity information

B401060247 Forwards Endorsement 4 to NELIA & MAELU Certificates N-4 & M-4
SINISI, J M Marsh & McLennan, Inc B3/12/27 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 21740 108 24X Fiche 50-029, B3/12/27, B401060247

B401060262 Forwards Endorsements 107 & B9 to NELIA & MAELU Policies NF-76 & MF-26, respectively
SINISI, J M Marsh & McLennan, Inc B3/12/27 BALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 21741 057 24X Fiche 50-029, B3/12/27, B401060262

P Operating license stage documents & correspondence

B401040561 Provides info re mechanical steam generator tube plugging methods, in response to NRC B31027 ltr Westinghouse B21123 ltr, w/supporting safety evaluation & certificate of conformance, encl
KAY, J A Yankee Atomic Electric Co B3/12/19 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21707 242 24X Fiche 50-029, B3/12/19, B401040561

B401060327 Notification of B40117 meeting w/util in Bethesda, MD to discuss outstanding environ qualification review issues
ERIKSDN, P B Operating Reactors Branch 5 B3/12/30 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21742 330 24X Fiche 50-029, B3/12/30, B401060327

B401090204 Responds to open item identified in Yankee integrated assessment (NUREG-0825) re SEP Topic 11-3 C concerning need for mods to drainage channel at base of southeast slopes Mod scheduled for completion during Summer 1985
KAY, J A Yankee Atomic Electric Co B3/12/30 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21750 330 24X Fiche 50-029, B3/12/30, B401090204

B401050425 Forwards Amend B1 to License DPR-3, safety evaluation, Science Applications, Inc technical evaluation rept & notice of granting relief Amend incorporates changes to inservice insp program
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/03 KAY, J A Yankee Atomic Electric Co 3pp 21730 297 24X Fiche 50-029, B4/01/03, B401050425

--B401050427 Amend B1 to License DPR-3, incorporating changes to Tech Specs re inservice insp program
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/03 15pp 21730 300 24X Fiche 50-029, B4/01/03, B401050425

--B401050432 Safety evaluation supporting Amend B1 to License DPR-3 * Office of Nuclear Reactor Regulation, Director B4/01/03 Bpp 21730 315 24X Fiche 50-029, B4/01/03, B401050425

--B401050436 "Yankee Rowe Nuclear Generating Station Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-B2-096 186-028-32 B2/08/27 NRC - No Detailed Affiliation Given 29pp 21730 323 24X Fiche 50-029, B4/01/03, B401050425

--B401050440 Notice of granting relief from ASME Code, Section XI inservice insp requirements
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/03 2pp 21730 356 24X Fiche 50-029, B4/01/03, B401050425

B401100218 Submits evaluation results re SEP Topic VIII-4, "Evaluation of Category B Low Voltage Penetrations." All Category B penetrations have at least primary protection devices
KAY, J A Yankee Atomic Electric Co B4/01/04 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21759 272 24X Fiche 50-029, B4/01/04, B401100218

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D G Division of Licensing B4/01/05 Consolidated Edison Co. of New York, Inc. 16pp 21946 190 24X Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing B4/01/06 Consolidated Edison Co. of New York, Inc 18pp 21957 267 24X Fiche 50-000, B4/01/06, B401090221

DOCKETED ITEMS

15

840130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 90-000, 84/01/13, 840130084

8401300317 Forwards addl response to Generic Ltr 83-28, describing post-trip review program & providing procedure to meet ltr requirements
KAY, J A Yankee Atomic Electric Co 84/01/13 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 21995 106 24X
Fiche 50-029, 84/01/13, 8401300317

--8401300319 Rev 1 to Administrative Procedure AP-2003, "Yankee Rowe Post-Trip Review"
* Yankee Atomic Electric Co 83/12/31 52pp 21995 111 24X
Fiche 50-029, 84/01/13, 8401300317

8401240223 Forwards EG&G info re design values for instrumentation from rept submitted w/830830 ltr, in response to Reg Guide 1 97
Top of tank should be considered at bend line before roof welded on
KAY, J A Yankee Atomic Electric Co 84/01/19 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21920 240 24X
Fiche 50-029, 84/01/19, 8401240223

8401270286 Advises that as result of Operating Reactors Branch 5 reorganization, PR Erickson appointed project manager
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/25 KAY, J A Yankee Atomic Electric Co 2pp 21976 269 24X
Fiche 50-029, 84/01/25, 8401270286

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401040619 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/83-14
STAROSTECKI, R Division of Project & Resident Programs 83/12/22 HEIDER, L H Yankee Atomic Electric Co 1p 21714 026 24X
Fiche 50-029, 83/12/22, 8401040619

--8401040624 Responds to NRC 831114 ltr re violations noted in IE Insp Rept 50-029/83-14 Corrective actions tag sys for item released from potentially contaminated area implemented & OP-8302 reviewed re release of equipment & matl
HEIDER, L H Yankee Atomic Electric Co 83/12/14 MURLEV, T E Region 1, Office of Director 4pp 21714 027 24X
Fiche 50-029, 83/12/22, 8401040619

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401050425 Forwards Amend 81 to License DPR-3, safety evaluation, Science Applications, Inc technical evaluation rept & notice of granting relief Amend incorporates changes to inservice insp program
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/03 KAY, J A Yankee Atomic Electric Co 3pp 21730 297 24X
Fiche 50-029, 84/01/03, 8401050425

--8401050427 Amend 81 to License DPR-3, incorporating changes to Tech Specs re inservice insp program
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/03 15pp 21730, 300 24X Fiche 50-029, 84/01/03, 8401050425

--8401050432 Safety evaluation supporting Amend 81 to License DPR-3
* Office of Nuclear Reactor Regulation, Director 84/01/03 8pp 21730 315 24X Fiche 50-029, 84/01/03, 8401050425

--8401050436 "Yankee Rowe Nuclear Generating Station Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 186-028-32 82/08/27 NRC - No Detailed Affiliation Given 27pp 21730 323 24X Fiche 50-029, 84/01/03, 8401050425

--8401050440 Notice of granting relief from ASME Code, Section XI inservice insp requirements
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/03 2pp 21730 336 24X Fiche 50-029, 84/01/03, 8401050425

8401190433 Forwards IE Insp Rept 50-029/83-16 on 830726 & 1118 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/01/06 HEIDER, L H Yankee Atomic Electric Co 2pp 21849 229 24X
Fiche 50-029, 84/01/06, 8401190433

--8401190436 Notice of violation from insp on 830726
* Division of Engineering & Technical Programs 84/01/06 1p 21849 231 24X Fiche 50-029, 84/01/06, 8401190433

--8401190439 IE Insp Rept 50-029/83-16 on 830726-1118 Violation noted waste shipment to Barnwell, SC contained defective drum
CLEMONS, P, PASCIAK, W Region 1, Office of Director 83/12/27 4pp 21849 232 24X Fiche 50-029, 84/01/06, 8401190433

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401240109 Forwards IE Insp Rept 50-029/83-15 on 831024-1212 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/10 HEIDER, L H Yankee Atomic Electric Co 2pp 21913 156 24X
Fiche 50-029, 84/01/10, 8401240109

--8401240126 IE Insp Rept 50-029/83-15 on 831024-1212 No violations noted Major areas inspected operational safety verification reviews, plant info rept, maint, LERS, transportation activities & SEP action items
ETCHENHOLZ, H, COLLINS, S, ELBASER, T C Region 1, Office of Director 84/01/09 24pp 21913 158 24X Fiche 50-029, 84/01/10, 8401240109

8401240466 Forwards IE Insp Rept 50-029/83-13 on 831024-27 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/10 HEIDER, L H Yankee Atomic Electric Co 2pp 21908 177 24X
Fiche 50-029, 84/01/10, 8401240466

--8401240476 IE Insp Rept 50-029/83-13 on 831024-27 No violations noted Major areas inspected emergency preparedness items from appraisal performed 811201-09 & prompt public notification sys insp performed 830503-04
TERC, N M, COHEN, I, CROCKER, H W Region 1, Office of Director 83/12/12 12pp 21908 179 24X Fiche 50-029, 84/01/10, 8401240466

8401170319 Provides addl info re problems w/performance of ultrasonic exam of reactor vessel in areas other than outlet nozzles Nuclear Energy Svcs will use floating camera manipulator for reactor protection vessel insp
KAY, J A Yankee Atomic Electric Co 84/01/12 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 21829 358 24X
Fiche 50-029, 84/01/12, 8401170319

8312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8401180195 Rejects 830315 request for exemption from 10CFR50.55a re ASME Code inservice insp requirements for personnel performing hydrostatic exams
CRUTCHFIELD, D Operating Reactors Branch 5, 84/01/17 KAY, J A Yankee Atomic Electric Co 2pp 21844 011 24X
Fiche 50-029, 84/01/17, 8401180195

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

DOCKETED ITEMS

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120261 Monthly operating rept for Nov 1983 W/831207 ltr.
WHIPPLE, S, HEIDER, L H Yankee Atomic Electric Co 83/11/30
Office of Resource Management, Director 6pp 21793 286 24X
Fiche 50-029, 83/11/30, 8401120261

8401270406 Monthly operating rept for Dec 1983 W/840109 ltr
WHIPPLE, S, HEIDER, L H Yankee Atomic Electric Co 83/12/31
Office of Resource Management, Director 6pp 21976 255 24X
Fiche 50-029, 83/12/31, 8401270406

S Reportable occurrences, LERs & related correspondence

8401270258 Updated LER 83-038/03L-1 on 831006, vital bus transfer switch
malfunctioned during operation causing approx 3 s loss of
vital bus Caused by improper manufacturer assembly Switch
repaired W/840113 ltr
MAYE, L, ST LAURENT, N N Yankee Atomic Electric Co 84/01/13
MURLEY, T E Region 1, Office of Director 3pp 21982 210 24X
Fiche 50-029, 84/01/13, 8401270258

8401300169 PNO-I-84-009 on 840124, small amount of water observed on
containment floor Leak could not be isolated & plant began
shutdown in accordance w/Tech Specs Lagging on steam
generator 1 water box vent line wet & drip observed
FERLIG, GREENAN Region 1, Office of Director 84/01/25 1p
21999 121 24X Fiche 50-029, 84/01/25, 8401300169

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Q Adjudicatory correspondence

8401090344 Motion for extension of time until 840130 to respond to
J Turk revised contentions Delay needed due to intervenor
intent to advance contentions in original petition & revised
contentions Granted by ASLB on 840105
EDGAR, G L General Electric Co EDGAR, G L, Edgar, G L 83/12/27
Atomic Safety and Licensing Board Panel 3pp 21754 097 24X
Fiche 50-070, 83/12/27, 8401090344

8401170271 Forwards stipulation & request for dismissal of license
renewal proceedings
EDGAR, G L Newman & Holtzinger EDGAR, G L General Electric Co
84/01/16 FRYE, J H Atomic Safety and Licensing Board Panel 1p
21831 074 24X Fiche 50-070, 84/01/16, 8401170271

--8401170286 Stipulation & request for dismissal of license renewal
proceedings Certificate of Evc encl
TURK, S E Hearing Branch 1 EDGAR, G L General Electric Co
TURK, J Turk, J 84/01/13 5pp 21831 075 24X
Fiche 50-070, 84/01/16, 8401170271

8401170309 Forwards notice of appearance in proceeding Certificate of
Svc encl
RASKIN, D B Newman & Holtzinger 84/01/16 Office of the
Secretary of the Commission 4pp 21833 237 24X
Fiche 50-070, 84/01/16, 8401170309

8401230400 Memorandum & order dismissing License SNM-960 renewal
proceeding, per 840116 stipulation
FRYE, J H Atomic Safety and Licensing Board Panel 84/01/20 1p
21879 152 24X Fiche 50-070, 84/01/20, 8401230400

8401310235 Response opposing J Turk 831128 contentions & revs, per ASLB
830408 order Contentions not admissible
EDGAR, G L General Electric Co EDGAR, G L Newman & Holtzinger
84/01/30 Atomic Safety and Licensing Board Panel 35pp
22021 161 24X Fiche 50-070, 84/01/30, 8401310235

-8401310239 Affidavit of RW Darnitzel re releases of water containing
radioactive matls Certificate of Svc encl
DARNITZEL, R W General Electric Co 84/01/23 4pp 22021 196
24X Fiche 50-070, 84/01/30, 8401310235

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

P Operating license stage documents & correspondence

8401190098 Requests addl info to continue review of application for
renewal of OL Preliminary questions encl Info should be
available for upcoming site visit
THOMAS, C O Standardization & Special Projects Branch 83/12/30
NARDI, A J Westinghouse Electric Corp 7pp 21870 257 24X
Fiche 50-087, 83/12/30, 8401190098

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8401260235 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 345 24X Fiche 50-112, 84/01/20,
8401260235

--8401260240 Public version of App A to revised emergency plan, consisting
of agreement ltrs from City of Norman, State of OK fire
dept, Norman Municipal Hosp & Univ of Oklahoma chief of
security
* Oklahoma, Univ of, Norman, OK 84/01/04 4pp 21959 347
24X Fiche 50-112, 84/01/20, 8401260235

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8401250105 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 114 24X Fiche 50-113, 84/01/18,
8401250105

--8401250108 Public version of Rev 1 to emergency plan W/831227 ltr
* Arizona, Univ of, Tucson, AZ 83/12/12 Office of Nuclear
Reactor Regulation, Director 43pp 21959 115 24X
Fiche 50-113, 84/01/18, 8401250105

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8401240270 Informs that licensee does not have diesel generator, per
Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators"
HENDRICKSON, R Iowa State Univ Ames, IA 84/01/19 EISENHUT, D O
Division of Licensing 1p 21910 001 24X Fiche 50-116, 84/01/19,
8401240270

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

8401120268 RD on 831229, during connection of cable from log N period
compensated ion chamber, spurious signal occurred, causing
reactor scram Caused by failure to reconnect cable after
semiannual check
BOLON, A E Missouri, Univ of, Rolla, MO 84/01/03 KEPLER, J
Region 3, Office of Director 1p 21792 071 24X
Fiche 50-123, 84/01/03, 8401120268

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR

P Operating license stage documents & correspondence

8401200012 Responds to 831216 Generic Ltr 83-41 re fast cold starts of
diesel generators No generators used at facility No
response required
HOLIAN, P D Virginia Polytechnic Institute & State Univ,
Blacksburg, VA 84/01/17 EISENHUT, D O Division of Licensing
1p 21866 361 24X Fiche 50-124, 84/01/17, 8401200012

Q Inspection reports, IE Bulletins & correspondence

8401240372 Forwards IE Insp Rept 50-124/83-01 on 831128-27 No
violations noted Rept withheld (ref 10CFR2 790)
VERRELL, D M Division of Project & Resident Programs 83/12/20
PARKINSON, T F Virginia Polytechnic Institute & State Univ,
Blacksburg, VA 2pp 21909 130 24X Fiche 50-124, 83/12/20,
8401240372

V Operator Examinations

8401040099 Describes actions to rectify violation of operator qualification program Hot-Functional test program will be used to familiarize operators w/console All procedures will be reviewed Actions adequate until unit restarted
HOLIAN, P D , PARKINSON, T F Virginia Polytechnic Institute & State Univ , Blacksburg, VA 83/12/14 THOMAS, C O Standardization & Special Projects Branch 2pp 21703 266 24X Fiche 50-124, 83/12/14, 8401040099

DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8401240193 Ack receipt of 831027 & 1209 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-129/83-01
VERRELLI, D M Division of Project & Resident Programs 84/01/03
SLACK, S West Virginia Univ , Morgantown, WV 1p 21909 271 24X Fiche 50-129, 84/01/03, 8401240193

--8401240200 Supplis 831027 response to NRC 830824 ltr re violations noted in IE Insp Rept 50-129/83-01 Corrective actions accuracy & thoroughness of records, especially insps by radiation safety ofc personnel, improved
COLLINS, W E , SLACK, S T West Virginia Univ , Morgantown, WV 83/12/07 VERRELLI, D M Division of Project & Resident Programs 4pp 21909 272 24X Fiche 50-129, 84/01/03, 8401240193

--8401240205 Ack receipt of 831027 ltr responding to violations noted in IE Insp Rept 50-129/83-01 Conclusions to be provided in near future
VERRELLI, D M Division of Project & Resident Programs 83/11/25
COLLINS, W E West Virginia Univ , Morgantown, WV 1p 21909 276 24X Fiche 50-129, 84/01/03, 8401240193

--8401240210 Responds to NRC 830824 ltr re violations noted in IE Insp Rept 50-129/83-01 No corrective steps can be taken re accuracy of recordkeeping since disposal records cannot be recreated
COLLINS, W E , SLACK, S T West Virginia Univ , Morgantown, WV 83/10/27 VERRELLI, D M Division of Project & Resident Programs 3pp 21909 277 24X Fiche 50-129, 84/01/03, 8401240193

--8401240213 Forwards IE Insp Rept 50-129/83-01 on 830622-23 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/11/25
COLLINS, W E West Virginia Univ , Morgantown, WV 2pp 21909 280 24X Fiche 50-129, 84/01/03, 8401240193

--8401240216 Notice of violation from insp on 830622-23
* Region 2, Office of Director 83/08/24 2pp 21909 282 24X Fiche 50-129, 84/01/03, 8401240193

--8401240222 IE Insp Rept 50-129/83-01 on 830622-23 Violations noted fuel rods found activated & smear on one element showed slight loose alpha contamination
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/08/10 4pp 21909 284 24X Fiche 50-129, 84/01/03, 8401240193

DOCKET 50-131 OMAHA VET ADMIN HOSP. RESEARCH REACTOR

R Periodic operating reports & related correspondence

8401230450 "Annual Rept of Facility Changes, Tests & Experiments, Jul 1982 - June 1983"
TURCOTTE, R L Veterans Admin, Hosp , Omaha, NE 83/07/07 Region 5, Office of Director 2pp 21880 356 24X Fiche, 50-131, 83/07/07, 8401230450

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

G. Adjudicatory correspondence

8401310013 Forwards opposition to licensee 831216 request for deletion of Item E(2)(e) re microseismic monitoring network, from Licensee DPR-7
SHERWOOD, M R Sierra Club 84/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p, 22023 211 24X Fiche 50-133, 84/01/26, 8401310013

--8401310016 Opposition to licensee 831216 request for deletion of Item E(2)(e) re microseismic monitoring network, from Licensee DPR-7 Plant in close proximity to three earthquake faults
Constant monitoring required Certificate of Svc encl
SHERWOOD, M R Sierra Club 84/01/26 Atomic Safety and Licensing Board Panel 4pp 22023 212 24X Fiche 50-133, 84/01/26, 8401310013

8401310146 Statement supporting public involvement in decommissioning plan Certificate of Svc encl
SHERWOOD, M R Sierra Club SHERWOOD, M R Jones, Brown & Clifford 84/01/26 4pp 22022 107 24X Fiche 50-133, 84/01/26, 8401310146

P Operating license stage documents & correspondence

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/03 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/03, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

G Inspection reports, IE Bulletins & correspondence

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 093 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120374 Monthly operating rept for Nov 1983 W/831206 ltr
DERKS, P S , WEEKS, E D Pacific Gas & Electric Co 83/11/30, NRC - No Detailed Affiliation Given 5pp 21792 015 24X Fiche 50-133, 83/11/30, 8401120374

DOCKETED ITEMS

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

R Periodic operating reports & related correspondence

B401160112 "Annual Rept. 1983"
WILBUR, L C Worcester Polytechnic Institute, Worcester, MA
B4/01/11 Office of Nuclear Reactor Regulation, Director 1p
21815 213 24X Fiche 50-134, B4/01/11, B401160112

DOCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

B401030149 Forwards ltr to Commissioners requesting deferment of action on NRC B31205 request for clarification of 10CFR73 40(a) re physical protection requirements
HIRSCH, D Committee to Bridge the Gap B3/12/27 CHILK, S J
Office of the Secretary of the Commission 1p 21682 352 24X
Fiche 50-142, B3/12/27, B401030149

--B401030157 Requests Commission defer acting on NRC B31206 request for clarification to 10CFR73 40(a) re physical protection requirements, until copy of request provided & Commission receives response
HIRSCH, D Committee to Bridge the Gap B3/12/27 PALLADINO, N J
GILINSKY, V, ROBERTS, T H Commissioners 2pp 21682 353 24X
Fiche 50-142, B3/12/27, B401030149

B401030185 Forwards errata sheet & corrected version of B31214 curtailment motion re sabotage protection plan
HIRSCH, D Committee to Bridge the Gap B3/12/27 Atomic Safety
and Licensing Board Panel 2pp 21683 043 24X
Fiche 50-142, B3/12/27, B401030185

--B401030192 Corrected version of B31214 motion for curtailment of activities re sabotage protection plan
HIRSCH, D Committee to Bridge the Gap B3/12/27 Atomic Safety
and Licensing Board Panel 4pp 21683 045 24X
Fiche 50-142, B3/12/27, B401030185

B401030189 Motion requesting evidentiary hearings be scheduled no later than B40215 re issue of adequacy of reactor security so that issue can be resolved well in advance of 1984 Olympic Games Declaration of Svc encl
HIRSCH, D Committee to Bridge the Gap B3/12/27 Atomic Safety
and Licensing Board Panel 18pp 21683 054 24X
Fiche 50-142, B3/12/27, B401030189

B401050225 Response to ASLB B31130 memorandum & order directing parties to address question re whether sale of irradiation svcs by UCLA to U West constitutes research activities Sale constitutes commercial activity W/Declaration Svc
HIRSCH, D Committee to Bridge the Gap B3/12/30 Atomic Safety
and Licensing Board Panel 9pp 21728 190 24X
Fiche 50-142, B3/12/30, B401050225

401050233 Response opposing Citizens to Bridge the Gap motion for curtailment of activities Motion premature & based on misrepresentation of factual record Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles, CA B3/12/30 Atomic Safety and Licensing Board Panel 3pp 21728 278 24X
Fiche 50-142, B3/12/30, B401050233

B401050249 Response to ASLB B31130 memorandum & order requesting further view on whether use of reactor dispositive of Contention II Renewal of Class 104 license respectfully requested Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles, CA B3/12/30 Atomic Safety and Licensing Board Panel 14pp 21729 149 24X
Fiche 50-142, B3/12/30, B401050249

401120294 Response to ASLB B31130 memorandum & order requesting views on characterization of reactor use per Section 31 of Atomic Energy Act Contention II should be dismissed Certificate of Svc encl
WOODHEAD, C P Hearing Branch 4 B3/12/30 Atomic Safety and Licensing Board Panel 11pp 21792 176 24X Fiche 50-142, B3/12/30, B401120294

101100208 Offers assistance in Ofc of Inspector & Auditor investigation re allegations of misconduct on part of leaders of Commission staff in controversy over adequacy of security precautions at facility
HIRSCH, D Committee to Bridge the Gap B4/01/05 MESSENGER, O
Ofc of Inspector & Auditor 1p 21760 187 24X
Fiche 50-142, B4/01/05, B401100208

B401100211 Informs of multiple obstacles to fulfilling ASLB request for in-depth technical analysis of UCLA testimony on shutdown mechanism, including suppls thereto Author efforts stymied by wks of UCLA foot-dragging
HIRSCH, D Committee to Bridge the Gap B4/01/05 FRYE, J H Atomic Safety and Licensing Board Panel 2pp 21760 216 24X
Fiche 50-142, B4/01/05, B401100211

B401101061 Memorandum clarifying Paragraphs 1, 2 & 3 of Contention XX re compliance w/10CFR73 40 & 10CFR73 67 Certificate of Svc encl
HIRSCH, D Committee to Bridge the Gap B4/01/06 Atomic Safety and Licensing Board Panel 10pp 21772 327 24X
Fiche 50-142, B4/01/06, B401101061

B401100148 Memorandum & order granting 1-wk extension to complete independent in-depth technical analysis of shutdown mechanism
FRYE, J H Atomic Safety and Licensing Board Panel B4/01/09
Committee to Bridge the Gap 1p 21759 362 24X
Fiche 50-142, B4/01/09, B401100148

B401130157 Motion for curtailment of reactor operation pending final determination of safety concern Irreparable injury associated w/any further delay of proceeding Declaration of Svc encl
HIRSCH, D Committee to Bridge the Gap B4/01/09 Atomic Safety and Licensing Board Panel 66pp 21802 135 24X
Fiche 50-142, B4/01/09, B401130157

B401101079 Errata to B31223 memorandum & order re Contention XX Errata changes date on Page 12 from B40123 to B40125
FRYE, J H Atomic Safety and Licensing Board Panel B4/01/10 1p-
21780 309 24X Fiche 50-142, B4/01/10, B401101079

B401160247 Forwards affidavit of NC Ostrander in support of univ B30909 response to Citizens to Bridge the Gap comments on fuel inventory, per ASLB B31223 order
CORMIER, W H California, Univ of, Los Angeles, CA B4/01/10
FRYE, J H, BRIGHT, Q O, LUEBKE, E A Atomic Safety and Licensing Board Panel 1p 21814 192 24X Fiche 50-142, B4/01/10, B401160247

--B401160249 Affidavit of NC Ostrander supporting univ B30909 response to Citizens to Bridge the Gap comments on fuel inventory Certificate of Svc encl
OSTRANDER, N C California, Univ of, Los Angeles, CA B4/01/09
4pp 21814 193 24X Fiche 50-142, B4/01/10, B401160247

B401170304 Response to Committee to Bridge the Gap B31227 second motion to curtail activities Motion deficient in form, based on factual misrepresentations & lacks merit & therefore should be denied Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles, CA B4/01/11
Atomic Safety and Licensing Board Panel 8pp 21833 216 24X
Fiche 50-142, B4/01/11, B401170304

B401250190 Advises that NRC will not comment on party responses re Contentions II & XX Party positions on Contentions II & XX already well established Commission agenda for B40127 encl
WOODHEAD, C P Hearing Branch 4 B4/01/12 FRYE, J H, BRIGHT, Q O
LUEBKE, E A Atomic Safety and Licensing Board Panel 4pp
21934 359 24X Fiche 50-142, B4/01/12, B401250190

B401240153 Reply to NRC & applicant B31230 pleadings re Contention II UCLA ceased using reactor in fashion for which license granted & therefore, should not be permitted to receive license Declaration of Svc encl
HIRSCH, D Committee to Bridge the Gap B4/01/16 Atomic Safety and Licensing Board Panel 9pp 21910 255 24X
Fiche 50-142, B4/01/16, B401240153

B401240238 Forwards review of UCLA shutdown analysis re how major power excursion at facility would self-terminate Core photographs recently provided by UCLA will be introduced as exhibits
HIRSCH, D Committee to Bridge the Gap B4/01/16 Atomic Safety and Licensing Board Panel 1p 21910 041 24X
Fiche 50-142, B4/01/16, B401240238

--B401240241 Review of UCLA analysis of facility shutdown mechanism Postulated power excursion will not self-terminate as assumed by expulsion of water out top of fuel box region through surrounding brick walls
* Committee to Bridge the Gap B4/01/16 71pp 21910 042 24X
Fiche 50-142, B4/01/16, B401240238

B401250115 Response to Committee to Bridge the Gap B31227 motion for curtailment of activities at UCLA Assertions re potential foreign terrorist attacks on reactor during 1984 Olympics unsubstantiated W/Certificate of Svc
WOODHEAD, C P Hearing Branch 4 B4/01/16 Atomic Safety and Licensing Board Panel 12pp 21936 211 24X Fiche 50-142, B4/01/16, B401250115

DOCKETED ITEMS

19

8401230416 Response to Committee to Bridge the Gap memorandum clarifying Contention XX, Paragraphs 1, 2 & 3 Committee should be made to respond to NRC motion re 10CFR73.67 Certificate of Svc encl
REIDHAAR, D L, WOODS, G R, HELWICK, C California, Univ of Los Angeles, CA 84/01/17 Atomic Safety and Licensing Board Panel 9pp 21879 133 24X Fiche 50-142, 84/01/17, 8401230416

8401310156 Memorandum & order memorializing 840123 conference call re Contention XX Informal discovery session will be held on 840208 & 09 UCLA request for extension of time to respond to motion for curtailment (III) granted
BRIGHT, G O, FRYE, J H Atomic Safety and Licensing Board Panel 84/01/27 Office of the Executive Legal Director 4pp 22022 113 24X Fiche 50-142, 84/01/27, 8401310156

T Hearing transcripts on non-antitrust matters

8401120305 Forwards testimony of W Jensen re UCLA testimony on shutdown mechanisms & compilation of transcript record w/o encl
WOODHEAD, C P Hearing Branch 4 84/01/09 FRYE, J H, BRIGHT, G O, LUEBKE, E A Atomic Safety and Licensing Board Panel 1p 21792 187 24X Fiche 50-142, 84/01/09, 8401120305

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

S Reportable occurrences, LERS & related correspondence

8401300291 RD on 831222, insp of containment vessel sump found 3.7 cm of water below Elevation 765 ft-8 inches Caused by condensation on inside walls of containment vessel above Elevation 812 ft Sump pumped successfully
MONTGOMERY, C R Saxton Nuclear Experimental Corp 83/12/30 Region 1, Office of Director 3pp 21798 293 24X Fiche 50-146, 83/12/30, 8401300291

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

P Operating license stage documents & correspondence

8401170340 Forwards revised Tech Specs for License R-78
MEGLER, R B Kansas, Univ of Lawrence, KS 84/01/11 CHU, A NRC - No Detailed Affiliation Given 1p 21831 109 24X Fiche 50-148, 84/01/11, 8401170340

--8401170344 Revised Tech Specs for License R-78
* Kansas, Univ of Lawrence, KS 84/01/31 30pp 21831 110 24X Fiche 50-148, 84/01/11, 8401170340

V Operator Examinations

8401270359 Forwards request for addl info re revised operator requalification program info requested by 840131
THOMAS, C O Standardization & Special Projects Branch 84/01/16 MEGLER, R Kansas, Univ of Lawrence, KS 2pp 21992 361 24X Fiche 50-148, 84/01/16, 8401270359

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8401060118 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document Management Branch 1p 21746 040 24X Fiche 50-155, 83/12/27, 8401060118

--8401060124 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-2 re facility actions during emergency, EPIP-3 re assembly area staffing & EPIP-5D re determining extent of core damage
* Consumers Power Co 83/11/21 Office of Nuclear Reactor Regulation, Director 1p 21746 041 24X Fiche 50-155, 83/12/27, 8401060118

--8401060128 Public version of revised emergency plan implementing procedures, including Procedures EPIP-2 re facility actions during emergency, EPIP-3 re assembly area staffing & EPIP-5D re determining extent of core damage
* Consumers Power Co 83/11/16 40pp 21746 042 24X Fiche 50-155, 83/12/27, 8401060118

8401040629 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21714 221 24X Fiche 50-155, 83/12/28, 8401040629

--8401040630 Public version of Rev 38 to Emergency Plan Implementing Procedure EPIP-2, "Site Area Emergency Notification Actions Checklist" W/831213 ltr
* Consumers Power Co 83/11/23 Office of Nuclear Reactor Regulation, Director 3pp 21714 222 24X Fiche 50-155, 83/12/28, 8401040629

8401230425 Application for extension of time until 840216 to respond to Committee to Bridge the Gap 840109 motion for Curtailment III (irreparable injury associated w/any further delay) Extension will not delay matters w/Certificate of Svc
CORMIER, W H California, Univ of Los Angeles, CA 84/01/17 Atomic Safety and Licensing Board Panel 4pp 21882 187 24X Fiche 50-142, 84/01/17, 8401230425

8401200111 Memorandum & order denying Citizens to Bridge the Gap motions for curtailment of Activities I & II for Contention XX re potential sabotage
LUEBKE, E A, BRIGHT, G O, FRYE, J H Atomic Safety and Licensing Board Panel 84/01/18 Committee to Bridge the Gap 6pp 21866 354 24X Fiche 50-142, 84/01/18, 8401200111

8401200138 Protective order covering matl produced in proceeding on proposed renewal of facility license
FRYE, J H, BRIGHT, G O, LUEBKE, E A Atomic Safety and Licensing Board Panel 84/01/18 3pp 21865 293 24X Fiche 50-142, 84/01/18, 8401200138

8401200161 Memorandum & order establishing protective order for segregation of proceedings not dealing w/sensitive info
FRYE, J H, BRIGHT, G O, LUEBKE, E A Atomic Safety and Licensing Board Panel 84/01/18 14pp 21866 198 24X Fiche 50-142, 84/01/18, 8401200161

8401240081 Reply opposing applicant 840117 request for 24-day extension to respond to Committee to Bridge the Gap 840109 motion for curtailment Reasonable extension not opposed Certificate of Svc encl
HIRSCH, D Committee to Bridge the Gap 84/01/20 Atomic Safety and Licensing Board Panel 3pp 21912 356 24X Fiche 50-142, 84/01/20, 8401240081

8401240276 Requests identity of authors of review of UCLA "Analyses of Shutdown Mechanism," filed on 840116
FRYE, J H Atomic Safety and Licensing Board Panel 84/01/20 HIRSCH, D Committee to Bridge the Gap 1p 21909 358 24X Fiche 50-142, 84/01/20, 8401240276

8401270201 Informs that T Taylor, P Leventhal & D Hirsch added to agenda for 840127 meeting re high enriched U conversion & safeguards matters as related to research reactors
HIRSCH, D Committee to Bridge the Gap 84/01/23 Atomic Safety and Licensing Board Panel 1p 21980 043 24X Fiche 50-142, 84/01/23, 8401270201

8401270374 Discusses delay in transmitting documents to parties re UCLA views about converting reactor to low enriched U fuel & univ transmittal of documents to Committee to Bridge the Gap
HIRSCH, D Committee to Bridge the Gap 84/01/23 CORMIER, W California, Univ of Los Angeles, CA 2pp 21976 039 24X Fiche 50-142, 84/01/23, 8401270374

8401300228 Forwards 840110 ltr on Commission 840127 meeting re highly enriched U used by research reactors, inadvertently omitted from 840123 submittal
HIRSCH, D Committee to Bridge the Gap 84/01/24 Atomic Safety and Licensing Board Panel 1p 22062 136 24X Fiche 50-142, 84/01/24, 8401300228

--8401300230 Requests permission to present, at Commission 840127 meeting, results of 2-yr review of issues re highly enriched U used at research reactors
HIRSCH, D Committee to Bridge the Gap 84/01/10 CHILK, S J Office of the Secretary of the Commission 2pp 22062 137 24X Fiche 50-142, 84/01/24, 8401300228

8401310348 Forwards proposed list of authorized persons who need access to protected info, in response to ASLB 840118 memorandum & order, Addition of paragraph clarifying exemption clause of protective order requested
CORMIER, W H California, Univ of Los Angeles, CA 84/01/25 FRYE, J H, BRIGHT, G O, LUEBKE, E A Atomic Safety and Licensing Board Panel 7pp 22026 237 24X Fiche 50-142, 84/01/25, 8401310348

8401300237 Memorandum & order resolving remaining procedural questions necessary prior to consideration of merits of Contention XX re security Committee to Bridge the Gap abandoned claims that fuel inventory in error
LUEBKE, E A, BRIGHT, G O, FRYE, J H Atomic Safety and Licensing Board Panel 84/01/26 9pp 22062 079 24X Fiche 50-142, 84/01/26, 8401300237

DOCKETED ITEMS

B401050018 Releases public version of rev to list of effective pages to emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21742 001 24X Fiche 50-155, 83/12/28,
 B401050018

--B401050030 Public version of Rev 23 to list of effective pages to emergency plan implementing procedures W/record of rev & receipt form
 * Consumers Power Co 83/12/14 Office of Nuclear Reactor
 Regulation, Director 3pp 21742 002 24X Fiche 50-155, 83/12/28,
 B401050018

B401060107 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21746 179 24X Fiche 50-155, 83/12/28,
 B401060107

--B401060112 Public version of Rev 38 to Emergency Plan Implementing Procedure EPIP-2: "Facility Actions During Emergency" W/
 831129 ltr.
 * Consumers Power Co 83/11/23 Office of Nuclear Reactor
 Regulation, Director 12pp 21746 180 24X Fiche 50-155,
 83/12/28, B401060107

B401030288 Responds to util 831107 submittal re implementation of guidance in NUREG-0737, Item III D 3 4, "Control Room Habitability" Util commitment adequately addresses effect of fire on control room habitability
 CRUTCHFIELD, D Operating Reactors Branch 5 83/12/30
 VANDEWALLE, D J Consumers Power Co 4pp 21680 115 24X
 Fiche 50-155, 83/12/30, B401030288

B401230270 Notifies of FEMA 840112-13 meetings in Chicago, IL re radiological emergency preparedness program to develop final FY84/FY85 emergency preparedness exercise schedule & prompt alert notification certification schedule
 PAPERIELLO, C J Region 3, Office of Director 84/01/05 COOK, J W
 Consumers Power Co 4pp 21884 207 24X Fiche 50-000, 84/01/05,
 B401230270

B401130222 Act receipt of 831214 ltr transmitting Rev 10 to security plan Rev consistent w/provisions of 10CFR50.54(g) & acceptable Encl to 831214 ltr withheld (ref 10CFR73.21)
 AXELSON, W L Region 3, Office of Director 84/01/09
 VANDEWALLE, D J Consumers Power Co 3pp 21801 354 24X
 Fiche 50-155, 84/01/09, B401130222

B401250099 Releases public version of revised controlled copyholder list
 FELTON, J M Division of Rules and Records 84/01/18 Document
 Management Branch 1p 21959 158 24X Fiche 50-000, 84/01/18,
 B401250099

--B401250102 Public version of Rev 4 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures
 * Consumers Power Co 83/11/10 Office of Nuclear Reactor
 Regulation, Director 7pp 21959 159 24X Fiche 50-000, 84/01/18,
 B401250099

B401260170 Releases public version of correction to emergency plan
 FELTON, J M Division of Rules and Records 84/01/18 Document
 Management Branch 1p 21959 359 24X Fiche 50-155, 84/01/18,
 B401260170

--B401260174 Public version of correction to emergency plan, Vol 9, App D, extracting removal of Page D-4
 * Consumers Power Co 83/12/15 2pp 21959 360 24X
 Fiche 50-155, 84/01/18, B401260170

B401240620 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/20 Document
 Management Branch 1p 21945 225 24X Fiche 50-155, 84/01/20,
 B401240620

--B401240622 Public version of Rev 40 to Emergency Plan Implementing Procedure EPIP 6J, "Monthly Communications Test" W/831228 ltr, receipt form & revised index
 * Consumers Power Co 83/12/28 9pp 21945 226 24X
 Fiche 50-155, 84/01/20, B401240620

G Adjudicatory correspondence

B401050241 Draft opinion & proposed findings of fact & conclusions of law on Christa-Maria Contention 2 & O'Neill Contention IIA re south wall of spent fuel pool Certificate of Svc encl.
 GALLO, J, COPELAND, V G Consumers Power Co GALLO, J Isham,
 Lincoln & Beale 83/12/29 26pp 21729 215 24X
 Fiche 50-155, 83/12/29, B401050241

B401050250 Forwards INPD draft rept, "Evaluation of Big Rock Point Nuclear Plant" Assertions on Pages 15-17 relevant to genuine Issues of Facts (6) & (7) under Christa-Maria Contention 2 & O'Neill Contention IIA re south wall
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
 83/12/29 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and
 Licensing Board Panel 52pp 21729 163 24X Fiche 50-155, 83/12/29,
 B401050250

B401050340 Forwards licensee 831219 filing of finding of fact & conclusions of law to be transmitted to Christa-Maria W/o encl
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
 83/12/29 BIER, J Affiliation Unknown 1p 21726 362 24X
 Fiche 50-155, 83/12/29, B401050340

B401040110 Memorializes 831229 telcons between intervenors, ASLB, NRC & licensee re spent fuel pool mod Schedule for filing of findings extended
 GODDARD, R J Hearing Branch 3 83/12/30 BLOCH, P B, SHON, F J,
 PARIS, O H Atomic Safety and Licensing Board Panel 2pp
 21703 250 24X Fiche 50-155, 83/12/30, B401040110

B401260212 Forwards intervenor proposed findings of fact & conclusion of law re several emergency planning contentions plus findings concerning Contention II-2 & info re recent snow emergency W/o findings of fact
 CHRISTA-MARIA Christa-Maria 84/01/18 BLOCH, P, PARIS, O H,
 SHON, F J Atomic Safety and Licensing Board Panel 11pp
 21956 127 24X Fiche 50-155, 84/01/18, B401260212

B401240194 Forwards DJ Vandewalle 831216 Tech Spec amend request re stack gas monitoring sys Util no longer intends to install gamma scintillation detector for continuous sampling suggested in NUREG-0737, Item II F 1
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
 84/01/20 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and
 Licensing Board Panel 11pp 21910 304 24X Fiche 50-155, 84/01/20,
 B401240194

B401260128 Forwards findings of fact re spent fuel pool mod
 BIER, J A Bier, Mills, Christa-Maria, et al 84/01/20 BLOCH, P,
 PARIS, O H SHON, F J Atomic Safety and Licensing Board Panel 1p
 21957 042 24X Fiche 50-155, 84/01/20, B401260128

--B401260129 Findings of fact re spent fuel pool mod
 * Bier, Mills, Christa-Maria, et al 84/01/20 5pp 21957 043
 24X Fiche 50-155, 84/01/20, B401260128

B401300254 Motion for extension until 840213 to file findings of fact & conclusions of law re spent fuel pool mod Delay due to heavy occupation w/family duties, wood-gathering & winterization projects
 O'NEILL, J O'Neill, J 84/01/21 Atomic Safety and Licensing
 Board Panel 2pp 21998 310 24X Fiche 50-155, 84/01/21, B401300254

B401310340 Responds to J O'Neill 840117 ltr submitting jurat & list of corrections to 831115 deposition of A Schwartz Licensee reserves right re objections to deposition once proper action for admission into evidence filed before ASLB
 COPELAND, V G Isham, Lincoln & Beale * Consumers Power Co
 84/01/24 BLOCH, P, PARIS, O H, SHON, F J Atomic Safety and
 Licensing Board Panel 2pp 22019 350 24X Fiche 50-155, 84/01/24,
 B401310340

J Insurance & indemnity information

B401100447 Forwards Endorsement 99 to NELIA Policy NF-117
 FROUNFELKER, R Consumers Power Co 84/01/06 SALTZHAN, J
 Antitrust & Economic Analysis Branch (Utility Finance) 2pp
 21761 361 24X Fiche 50-155, 84/01/06, B401100447

D. Advisory Committee on Reactor Safeguards reports & correspondence

B401160408 Summary of ACRS Subcommittee on SEP 830920-21 meetings w/util in Traverse City, MI re review of integrated plant safety assessment for facility
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/17
 ACRS - Advisory Committee on Reactor Safeguards 22pp 21823 264
 24X Fiche 50-155, 83/11/17, B401160408

B401170359 Summary of ACRS Subcommittee on SEP 831107 meeting w/util in Washington, DC re SEP integrated assessment rept for facility (NUREG-0828)
 * ACRS - Advisory Committee on Reactor Safeguards 83/12/16
 ACRS - Advisory Committee on Reactor Safeguards 13pp 21844 292
 24X Fiche 50-155, 83/12/16, B401170359

DOCKETED ITEMS

21

P Operating license stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960-005. 24X
Fiche 50-000,83/10/18,8401250015

---8401300107 Provides info on operation & testing of containment
isolation valves at facility
DIRCKB, W J Office of the Executive Director for Operations
SECY-82-143 82/04/05 19pp 21962 266 24X
Fiche 50-000,83/10/18,8401250015

8401090763 Board Notification 83-195 forwards ACRS rept on SEP
integrated plant safety assessment rept (NUREG-0828), per
util proposal to expand spent fuel pool capacity
MIRAGLIA, F Assistant Director for Safety Assessment 83/12/28
BLOCH, P B, PARIS, O H, SHON, F Atomic Safety and Licensing Board
Panel 3pp 21767 041 24X Fiche: 50-155, 83/12/28, 8401090763

8401050250 Forwards INPO draft rept, "Evaluation of Big Rock Point
Nuclear Plant" Assertions on Pages 15-17 relevant to
genuine issues of Facts (6) & (7) under Christa-Maria
Contention 2 & O'Neill Contention IIA re south wall
OALLO, J Isham, Lincoln & Beale OALLO, J Consumers Power Co
83/12/29 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and
Licensing Board Panel 52pp 21729 163 24X Fiche 50-155, 83/12/29,
8401050250

8401050376 Responds to 831020 conference call re NRC question on
validation of max critical power ratio limits Three tables
encl showing comparison of parameter values & thermal margin
comparison of COBRA w/XN-2 correlation vs COBRA/BRP
KRICH, R M Consumers Power Co 83/12/29 CRUTCHFIELD, D Operating
Reactors Branch 5 6pp 21731 040 24X Fiche 50-155, 83/12/29,
8401050376

8401050315 Forwards exemption from requirement to have two senior
reactor operators & two reactor operators on each shift, in
response to 831003 ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/30.
VANDEWALLE, D J Consumers Power Co 3pp 21727 133 24X
Fiche 50-155, 83/12/30, 8401050315

---8401050319 Exemption from certain requirements of 10CFR50.54(m)(2)
requiring two senior reactor operators & two reactor
operators on each shift during operation.
EISENHUT, D O Division of Licensing. 84/01/01 Consumers Power
Co 4pp 21727 136 24X Fiche: 50-155, 83/12/30, 8401050315

8401060190 Forwards Amend 63 to License DPR-6 & safety evaluation Amend
approves changes to administrative controls section of Tech
Specs & adds second auxiliary operator to min shift staff
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/04
VANDEWALLE, D J Consumers Power Co 4pp 21739 172 24X
Fiche 50-155, 84/01/04, 8401060190

---8401060196 Amend 63 to License DPR-6, changing administrative controls
section of Tech Specs & adding second auxiliary operator to
min shift staff
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/04 28pp
21739 176 24X Fiche 50-155, 84/01/04, 8401060190

---8401060200 Safety evaluation supporting Amend 63 to License DPR-6
* Office of Nuclear Reactor Regulation, Director 84/01/04 7pp
21739 204 24X Fiche 50-155, 84/01/04, 8401060190

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs
& holders of CPs for power reactors re NRC use of terms,
"Important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946: 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401100014 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel
Generators." Frequent starts could lead to increased wear,
but also, to increased reliability due to lubricating effect
of generator start.
KRICH, R M. Consumers Power Co 83/01/05. CRUTCHFIELD, D Operating
Reactors Branch 5. 2pp 21761 197 24X Fiche 50-155, 84/01/05,
8401100014

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing. 84/01/06. Consolidated
Edison Co of New York, Inc. 18pp. 21957 267. 24X
Fiche: 50-000, 84/01/06, 8401090221.

8401160187 Forwards Amend 64 to License DPR-6 & safety evaluation Amend
approves Tech Spec changes instituting limiting conditions
of operation & surveillance requirements for mechanical
snubbers attached to reactor depressurization sys
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/11
VANDEWALLE, D J Consumers Power Co 2pp 21815 089 24X
Fiche 50-155, 84/01/11, 8401160187

---8401160194 Comments on after-application change re mechanical snubbers
No support for change in SER Only very minor changes should
be made R Encl annotated comments dtd 840104 also submitted
SCINTO, J NRC - No Detailed Affiliation Given 83/12/22
SMITH, H NRC - No Detailed Affiliation Given 3pp 21815 091
24X Fiche 50-155, 84/01/11, 8401160187

---8401160203 Amend 64 to License DPR-6, adding limiting conditions of
operation & surveillance requirements for mechanical
snubbers to Tech Spec
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/11 4pp
21815 094 24X Fiche 50-155, 84/01/11, 8401160187

---8401160208 Safety evaluation supporting Amend 64 to License DPR-6
YIN, I T, RIDGWAY, K R. EMCH, R Office of Nuclear Reactor
Regulation, Director 84/01/11 2pp 21815 100 24X
Fiche 50-155, 84/01/11, 8401160187

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for DLs & holders of CPs re availability of
NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc. 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401190429 Forwards corrected Page 3-7 to Amend 62 to License DPR-6
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/17
VANDEWALLE, D J Consumers Power Co. 3pp 21849.171 24X
Fiche 50-155, 84/01/17, 8401190429

---8401190432 Corrected Page 3-7 to Amend 62 to License DPR-6
* Operating Reactors Branch 5 84/01/31 1p 21849 174 24X
Fiche 50-155, 84/01/17, 8401190429

8401230042 Notices of intent to load & move during power operation,
cast similar to 7-1/2 ton cast referred to in SER Also
reaffirms 74108 commitment not to use 60 ton fuel shipping
cast w/o prior NRC approval
BORDINE, T C Consumers Power Co 84/01/18. CRUTCHFIELD, D
Operating Reactors Branch 5. 2pp 21884 346 24X
Fiche 50-155, 84/01/18, 8401230042

8401240194 Forwards DJ Vandewalle 831216 Tech Spec amend request re
stack gas monitoring sys Util no longer intends to install
gamma scintillation detector for continuous sampling
suggested in NUREG-0737, Item 11 F.1.
OALLO, J Isham, Lincoln & Beale OALLO, J Consumers Power Co
84/01/20 BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and
Licensing Board Panel 11pp 21910.304 24X Fiche 50-155, 84/01/20,
8401240194

8401270325 Confirms that stack gas monitoring sys declared operable on
831223, NUREG-0737, Items 11 F.1 & 11 F.2 complete
No further action required
KRICH, R M Consumers Power Co 84/01/24 CRUTCHFIELD, D Operating
Reactors Branch 5. 1p. 21976 315 24X Fiche 50-155, 84/01/24,
8401270325

8401270174 Notification of 840314 meeting w/util in Bethesda, MD to
discuss environ qualification of equipment
EMCH, R L. Operating Reactors Branch 5 84/01/25 CRUTCHFIELD, D
Operating Reactors Branch 5 4pp 21982 098 24X
Fiche 50-155, 84/01/25, 8401270174

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Fotts & Troubridge 1p 21744-003 24X
Fiche 50-000, 83/10/20, 8401060040

---8401060190 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744-004 24X Fiche 50-000, 83/10/20,
8401060040

DOCKETED ITEMS

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 050 24X Fiche 50-000,83/12/30,B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,B312120117

R Periodic operating reports & related correspondence

B401270233 Monthly operating rept for Nov 1983 W/831206 ltr
AMSTUTZ, S J, HOFFMAN, D P Consumers Power Co 83/12/31
Director's Office, Office of Inspection and Enforcement 6pp
21982 194 24X Fiche 50-155,83/11/30,B401270233

B401270322 Monthly operating rept for Dec 1983 W/840106 ltr
AMSTUTZ, S J, HOFFMAN, D P Consumers Power Co 83/12/31
Director's Office, Office of Inspection and Enforcement 6pp
21976 308 24X Fiche 50-155,83/12/31,B401270322

S Reportable occurrences, LERs & related correspondence

B401060406 LER 83-017/01T-0 on B31214, defective Std Operating Procedure
SOP-25 re switching from cooling to heating, resulting in possible containment degradation, identified Cause Unstated
Procedure revised W/831228 ltr
KRICH, R M Consumers Power Co 83/12/28 KEPLER, J G Region 3,
Office of Director 3pp 21740 358 24X Fiche 50-155,83/12/28,
8401060406

B401300059 LER 83-018/03L-0 on B31222, during routine testing of
emergency diesel generator, drive coupling to engine cooling
water pump failed Caused by long-term wear of coupling New
coupling installed Protective sleeve modified W/840118 ltr
KRICH, R M Consumers Power Co 84/01/18 KEPLER, J G Region 3,
Office of Director 2pp 21999 168 24X Fiche 50-155,84/01/18,
8401300059

T Hearing transcripts on non-antitrust matters

B401230411 Forwards AJ Schwartz jurate, affirming accuracy of B31115
evidentiary deposition transcript & corrections Deposition
& 830517 & 06 documents will be treated as prefiled
testimony
O'NEILL, J O'Neill, J 84/01/17 BLOCH, P PARIS, D SHON, F
tomic Safety and Licensing Board Panel 3pp 21880 344 24X
iche 50-155,84/01/17,B401230411

V Operator Examinations

B401230253 Forwards updated estimated schedule for nuclear instructor
program & operator & instructor licensing programs through
FY87, per Generic Ltr 83-40
BORDINE, T C Consumers Power Co 84/01/16 EISENHUT, D G Division
of Licensing 6pp 21884 290 24X Fiche 50-000,84/01/16,
B401230253

DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B401240533 Forwards IE Insp Repts 50-160/83-02 & 50-276/83-01 on
B31213 No violations or deviations noted
LEWIS, R C Division of Project & Resident Programs 83/12/28
KARAM, R A Georgia Institute of Technology, Atlanta, GA 2pp
21918 163 24X Fiche 50-160,83/12/28,B401240533

--B401240547 IE Insp Repts 50-160/83-02 & 50-276/83-01 on B31213 No
violations noted Major areas inspected review of security
plan, security organization & surveillance & security program
review Details withheld (ref 10CFR2 790 & 73 21)
HALL, B L Region 2, Office of Director MCGUIRE, D R Division of
Emergency Preparedness & Materials Safety 83/12/27 1p
21918 165 24X Fiche 50-160,83/12/28,B401240533

G Inspection reports, IE Bulletins & correspondence

B401240533 Forwards IE Insp Repts 50-160/83-02 & 50-276/83-01 on
B31213 No violations or deviations noted
LEWIS, R C Division of Project & Resident Programs 83/12/28
KARAM, R A Georgia Institute of Technology, Atlanta, GA 2pp
21918 163 24X Fiche 50-160,83/12/28,B401240533

--B401240547 IE Insp Repts 50-160/83-02 & 50-276/83-01 on B31213 No
violations noted Major areas inspected review of security
plan, security organization & surveillance & security program
review Details withheld (ref 10CFR2 790 & 73 21)
HALL, B L Region 2, Office of Director MCGUIRE, D R Division of
Emergency Preparedness & Materials Safety 83/12/27 1p
21918 165 24X Fiche 50-160,83/12/28,B401240533

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

P Operating license stage documents & correspondence

B312220138 Forwards responses to Questions 17, 18 & 35 re SAR, in
response to NRC request Plans for grid plate & grid plate
support encl W/one oversize drawing Aperture card is
available in PDR
BELCHER, R L Maryland, Univ of, College Park, MD 83/12/19
THOMAS, C O Standardization & Special Projects Branch 18pp
21603 240 24X Fiche 50-166,83/12/19,B312220138

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

H General correspondence

B401250094 Informs that effective 840116, Captain CR Williamson, EN, USA,
assumed duties of physicist in charge of Armed Forces
Radiobiology Research Inst reactor facility Appointment
order encl
ADCOCK, B R Defense, Dept of, Defense Nuclear Agency 84/01/20
Standardization & Special Projects Branch 2pp 21939 028 24X
Fiche 50-170,84/01/20,B401250094

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

P Operating license stage documents & correspondence

B401130325 Advises that magnetically coupled contacts on mercury-wetted
contact type relays will open & initiate scram Currently,
four sub relays installed in reactor
CARTER, R S Commerce, Dept of, National Bureau of Standards
84/01/06 BERNARD, H NRC - No Detailed Affiliation Given 1p
21801 332 24X Fiche 50-184,84/01/06,B401130325

B401120155 Notification of B40113 meeting w/ACRS, NBS & LASL in
Washington, DC to discuss application for relicensing &
power increase from 10 to 20 MWt
BERNARD, H Standardization & Special Projects Branch 84/01/09
THOMAS, C O Standardization & Special Projects Branch 3pp
21805 063 24X Fiche 50-184,84/01/09,B401120155

DOCKETED ITEMS

23

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

S Reportable occurrences, LERs & related correspondence

B401250128 RD on B31215, emergency generator gasoline engine electrical interlock protective circuit tripped Caused by bent & nearly grounded electrical connecting wire spade lug Trip sensor leads placed to prevent grounding
ALGER, D M Missouri, Univ of Columbia, MO 84/01/13 THOMAS, C O Standardization & Special Projects Branch 3pp 21936 207 24X
Fiche 50-186, B4/01/13, B401250128

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

R Periodic operating reports & related correspondence

B401060008 "Natural Environ Radioactivity Survey, Sept 1982 ~ Aug 1983 " WVB31201 ltr
AVANT, D , COZENS, G , WOODS, J Northrop Research & Technical Center 83/08/31 Director's Office, Office of Inspection and Enforcement 12pp 21737 263 24X Fiche 50-187, B3/08/31, B401060008

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

P Operating license stage documents & correspondence

B401130265 Responds to B31013 ltr re implementation of operator requalification program Categories included in licensed operator exam listed
KANE, R S Manhattan College, Riverdale, NY 84/01/09 THOMAS, C O Standardization & Special Projects Branch CHU, A T NRC - No Detailed Affiliation Given 4pp 21800 342 24X
Fiche 50-199, B4/01/09, B401130265

V Operator Examinations

B401130265 Responds to B31013 ltr re implementation of operator requalification program Categories included in licensed operator exam listed
KANE, R S Manhattan College, Riverdale, NY 84/01/09 THOMAS, C O Standardization & Special Projects Branch CHU, A T NRC - No Detailed Affiliation Given 4pp 21800 342 24X
Fiche 50-199, B4/01/09, B401130265

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

G Adjudicatory correspondence

B401230388 Order extending time until B40203 for Commission to act to review Director's Decision DD-B3-14 which denied requests of Sierra Club & State of OH & B31029 decision which denied request of Environ Policy Inst
CHILK, R J Office of the Secretary of the Commission 84/01/19 Commissioners 1p 21884 278 24X Fiche 50-000, B4/01/19, B401230388

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401130273 Forwards Fee for review of fire protection plan & schedules for alternate safe shutdown submitted on B20630
MEDFORD, M O Southern California Edison Co 84/01/06 MILLER, W D License Fee Management Branch 2pp 21800 353 24X
Fiche 50-206, B4/01/06, B401130273

B401180254 Provides current status of emergency operations facility ventilation sys mod & action necessary to address in-leakage Plan to review training & educ ctr encl
MEDFORD, M O Southern California Edison Co 84/01/09 EISENHUT, D O Division of Licensing 3pp 21844 101 24X
Fiche 50-206, B4/01/09, B401180254

B401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/B3-24, 50-361/B3-39 & 50-362/B3-38 on B31205-09 No violation noted
NORDERHAUG, L R Region 5, Office of Director 84/01/12 MCCARTHY, C B Southern California Edison Co 2pp 21999 142 24X
Fiche 50-206, B4/01/12, B401300183

--B401300188 IE Emergency Preparedness Insp Repts 50-206/B3-24, 50-361/B3-39 & 50-362/B3-38 on B31205-09 No violation noted. Major areas inspected: emergency detection & classification & protective action decisionmaking
NORTH, H S Region 5, Office of Director 84/01/11 13pp 21999 144 24X Fiche 50-206, B4/01/12, B401300183

B401240382 Forwards Addendum I to physical security plan, describing temporary change to south protected area barrier Addendum withheld (ref IOCFR73 21)
HAYNES, J G Southern California Edison Co 84/01/13 MARTIN, J D Region 5, Office of Director 2pp 21914 229 24X
Fiche 50-206, B4/01/13, B401240382

B401250183 Requests exemption from requirement for state & local participation in B40229 annual emergency exercise per IOCFR50, App E requirements State & local govts participated in three annual exercises in 1981, 1982 & on B30323
BASKIN, K P Southern California Edison Co 84/01/19 EISENHUT, D O Division of Licensing 2pp 21933 210 24X Fiche 50-206, B4/01/19, B401250183

H General correspondence

B401240172 Requests all IE bulletins, info notices & other correspondence be addressed to KP Baskin KP Baskin B40103 ltr advising of recent organizational changes encl
FRANKLIN, D A Southern California Edison Co 84/01/12 DEYOUNG, R Office of Nuclear Reactor Regulation, Director 1p 21908 276 24X
Fiche 50-206, B4/01/12, B401240172

--B401240179 Advises of recent organizational changes within util Util in process of preparing appropriate changes to licensing documentation to reflect changes for submittal in near future
BASKIN, K P Southern California Edison Co 84/01/03 MARTIN, J D Region 5, Office of Director 3pp 21908 277 24X
Fiche 50-206, B4/01/12, B401240172

P Operating license stage documents & correspondence

B401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies Supporting ltrs encl
CALBOVAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, B3/10/10, B401050027

B401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies NRC has no records subj to request Utilis not required to submit insurance rating to NRC
FELTON, J M Division of Rules and Records 83/10/25 CALBOVAS, C D Affiliation Unknown 1p 21736 236 24X Fiche 50-000, B3/10/10, B401050043

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, B3/12/16, B312200154

--B312270074 Discusses recent problems w/Transamerica Delaval, Inc emergency diesel generators IE Info Notice B3-58 issued in response to problem NRC met w/utilis to understand scope & depth of problem NRR will have lead responsibility
DIRCKS, W J Office of the Executive Director for Operations 83/12/16 Region 1, Office of Director 5pp 22039 217 24X
Fiche 50-000, B3/12/16, B312200154

B401030336 Advises that Proposed Change 126 to Tech Specs to delete existing auxiliary feedwater pump requirements in Section 4.4 E does not provide adequate justification for deletion of provisions of spec
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/22 BASKIN, K Southern California Edison Co 5pp 21693 305 24X
Fiche 50-206, B3/12/22, B401030336

B401040165 Forwards 35 P&IDs, showing return to svc scope of seismic reevaluation program, in response to NRC request at B31214 meeting
KRIEGER, R W Southern California Edison Co 83/12/28 PAULSON, G A NRC - No Detailed Affiliation Given 71pp 21707 001 24X
Fiche 50-206, B3/12/28, B401040165

B401050256 Submits addl info to support util B31130 Proposed Change 126 to delete Tech Spec 4.4 E re operability of auxiliary feedwater sys Surveillance requirements in Tech Spec 4.4 E superseded by Tech Spec 4.1.9 issued in Amend 65
MEDFORD, M O Southern California Edison Co 83/12/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21729 267 24X
Fiche 50-206, B3/12/30, B401050256

DOCKETED ITEMS

8401050674 Summary of 831214 meeting w/uttl, EG&G & Bechtel in Bethesda, MD re return to svc plan for facility & analysis of vertical spectra appropriate for seismic reanalysis Viewgraphs encl
PAULSON, W A Operating Reactors Branch 5 83/12/30 Operating
Reactors Branch 5 123pp 21724 162 24X Fiche 50-206, 83/12/30, 8401050674

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp. 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing. Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp. 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401090492 Requests addl info re Transamerica Delaval emergency diesel generators in svc since 1976 Response should be provided within 30 days of ltr receipt
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/06 BASKIN, K
Southern California Edison Co 3pp 21796 046 24X
Fiche 50-206, 84/01/06, 8401090492

840110270 Forwards example calculations demonstrating implementation of acceptability criteria re return to svc plan for seismic reevaluation program Example pipe support evaluation will be provided by 840113
MEDFORD, M O Southern California Edison Co 84/01/06
CRUTCHFIELD, D Operating Reactors Branch 5 1p 21769 001 24X
Fiche 50-206, 84/01/06, 840110270

--840110273 Rev 0 to "Safe Shutdown Piping Functionality Assessment"
* Impell Corp FW-04 R00 83/02/12 271pp. 21769 002 24X
Fiche 50-206, 84/01/06, 840110270

--840110275 Rev 9 to "Safe Shutdown Piping Functionality Assessment"
* Impell Corp CV-13 R00 83/12/08 34pp 21769 273 24X
Fiche 50-206, 84/01/06, 840110270

--840110279 Rev 0 to "Safe Shutdown Piping Functionality Assessment"
* Impell Corp CV-12/MM-01 R00 83/12/20 234pp 21769 307 24X
Fiche 50-206, 84/01/06, 840110270

--840110281 "Pipe Loads on Structural Members Sample Calculations"
W/two oversize drawings Aperture cards are available in PDR
* Southern California Edison Co 84/01/31 51pp 21770 181 24X
Fiche 50-206, 84/01/06, 840110270

8401120409 Discusses SEP Topic V-6 re reactor vessel integrity 800305 evaluation (NUREG-0549) Evaluation reviewed design & const of reactor vessels for SEP plants Updated status evaluation appropriate Topic complete
PAULSON, W A Operating Reactors Branch 5 84/01/10 BASKIN, K
Southern California Edison Co 4pp 21791 141 24X
Fiche 50-206, 84/01/10, 8401120409

8401200219 Clarifies 831128 response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events"
Reactor trip breaker maint will be refined & enhanced as necessary, per IE Bulletin 83-01
MEDFORD, M O Southern California Edison Co 84/01/12
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21862 361 24X
Fiche 50-206, 84/01/12, 8401200219

840130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 840130084

840170200 Requests no addl consideration be given to removal of Tech Spec 4.5 E as part of Proposed Change 126 submitted on 831130 Removal of surveillance requirement for auxiliary feedwater sys will be handled in future proposed change
MEDFORD, M O Southern California Edison Co 84/01/13
CRUTCHFIELD, D Operating Reactors Branch 5 1p 21832 250 24X
Fiche 50-206, 84/01/13, 840170200

840180244 Summary of 831220 meeting w/uttl & Impell Corp in Bethesda, MD re outstanding environ qualification issues
PAULSON, W A Operating Reactors Branch 5 84/01/17 Operating
Reactors Branch 5 22pp 21844 130 24X Fiche 50-206, 84/01/17, 840180244

840190439 Forwards summary of proposed BNL data gathering visits to study occupational dose reduction at nuclear power plants
Permission to access ALARA data on 840409-12 requested
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/17 BASKIN, K
Southern California Edison Co 6pp 21849 281 24X
Fiche 50-206, 84/01/17, 840190439

8401240147 Forwards response to SEP open items summarized in NRC 830207 ltr & Rev 2 to Engineering Procedure S01-V-2 17, "Reactor Coolant Pump Flywheel Insp"
MEDFORD, M O Southern California Edison Co 84/01/19
CRUTCHFIELD, D Operating Reactors Branch 5 63pp 21911 114 24X
Fiche 50-206, 84/01/19, 8401240147

--8401240151 Rev 2 to Engineering Procedure S01-V-2 17, "Reactor Coolant Pump Flywheel Insp"
BRUNET, R R, CURRAN, J M Southern California Edison Co 80/12/19
4pp 21911 179 24X Fiche 50-206, 84/01/19, 8401240147

8401250124 Advises that revised schedule for capital projects to implement proposed integrated living schedule unacceptable
Proposed schedule indicates delays in implementing mods prescribed in Commission regulations
EISENHUT, D G Division of Licensing 84/01/20 BASKIN, K Southern California Edison Co 3pp 21937 073 24X
Fiche 50-206, 84/01/20, 8401250124

8401260114 Notification of 840131 meeting w/uttl in Bethesda, MD to discuss proposed seismic design criteria for plant restart
MCKENNA, E M Operating Reactors Branch 5 84/01/24 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 21957 024 24X
Fiche 50-206, 84/01/24, 8401260114

8401270218 Forwards revised inservice testing (IST) program for pumps & valves, consisting of Engineering Procedures S01-V-2 14 & S01-V-2 15 Responses to 23 open items from NRC 830202-04 meetings forwarded
MEDFORD, M O Southern California Edison Co 84/01/24
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21972 001 24X
Fiche 50-206, 84/01/24, 8401270218

--8401270225 Rev 5 to Engineering Procedure S01-V-2 14, "Inservice Testing of Pumps Program"
ROSENBLUM, R M Southern California Edison Co 84/01/24 21pp
21972 003 24X Fiche 50-206, 84/01/24, 8401270218

--8401270229 Rev 4 to Engineering Procedure S01-V-2 15, "Inservice Testing of Valve Program" List of items & responses encl
ROSENBLUM, R M Southern California Edison Co 84/01/24 76pp.
21972 025 24X Fiche 50-206, 84/01/24, 8401270218

8401270216 Informs that due to reassignments within Operating Reactors Branch 5, E McKenna assigned as new project manager
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/25 BASKIN, K
Southern California Edison Co 2pp 21982 227 24X
Fiche 50-206, 84/01/25, 8401270216

8401270340 Notification of 840208 & 09 meetings w/uttl in San Diego County, CA to discuss SEP Topic II-4 F, "Settlement of Foundations"
MCKENNA, E M Operating Reactors Branch 5 84/01/26 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 21976 108 24X
Fiche 50-206, 84/01/26, 8401270340

8401310401 Forwards addl mod to Proposed Change 120 to Tech Specs re provision for min boron concentration in RCS Info based on addl discussion w/NRC reviewers
MEDFORD, M O Southern California Edison Co 84/01/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 22018 019 24X
Fiche 50-206, 84/01/27, 8401310401

--8401310405 Proposed Change 120 to Tech Specs re provision for min boron concentration in RCS
* Southern California Edison Co 84/01/27 1p 22018 024 24X
Fiche 50-206, 84/01/27, 8401310401

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Baw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

DOCKETED ITEMS

25

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 129pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401200219 Clarifies 831128 response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events " Reactor trip breaker maint will be refined & enhanced as necessary, per IE Bulletin 83-01
MEDFORD, M O Southern California Edison Co 84/01/12
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21862 361 24X Fiche 50-206,84/01/12,8401200219

8401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/83-24, 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
NORRIS, C A Region 5, Office of Director 84/01/12
MCCARTHY, C B Southern California Edison Co 2pp 21999 142 24X Fiche 50-206,84/01/12,8401300183

--8401300188 IE Emergency Preparedness Insp Repts 50-206/83-24, 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
Major areas inspected emergency detection & classification & protective action decisionmaking
NORTH, M B, TEMPLE, G M, SCHUBERT, M D Region 5, Office of Director 84/01/11 15pp 21999 144 24X Fiche 50-206,84/01/12,8401300188

8312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUBO, R Licensing Branch 2 84/01/17 SCHWENGER, A Licensing Branch 2 21pp 22027,009 24X Fiche 50-000,84/01/17,8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000,041 24X Fiche 50-000,84/01/18,8312120117

8401240147 Forwards response to BEP open items summarized in NRC 830207 ltr & Rev 2 to Engineering Procedure 801-V-2 17, "Reactor Coolant Pump Flywheel Insp "
MEDFORD, M O Southern California Edison Co 84/01/19,
CRUTCHFIELD, D Operating Reactors Branch 5 65pp 21911 114 24X Fiche 50-206,84/01/19,8401240147

--8401240151 Rev 2 to Engineering Procedure 801-V-2 17, "Reactor Coolant Pump Flywheel Insp "
BRUNET, R R, CURRAN, J M Southern California Edison Co 80/12/19 App 21911 179 24X Fiche 50-206,84/01/19,8401240147

8401300142 Forwards IE Insp Repts 50-206/83-25, 50-361/83-40 & 50-362/83-39 on 831029-1209 No noncompliance noted
STBROP, T W Division of Resident/Reactor Project & Engineering Programs 84/01/19 MCCARTHY, C B Southern California Edison Co 2pp 21998 263 24X Fiche 50-206,84/01/19,8401300142

--8401300151 IE Insp Repts 50-206/83-25, 50-361/83-40 & 50-362/83-39 on 831029-1209 No noncompliance noted Major areas inspected operations program & Unit 3 startup test program
CHAFFEE, A E, D'ANGELO, A, STEWART, J P Region 5, Office of Director 84/01/19 10pp 21998 265 24X Fiche 50-206,84/01/19,8401300142

8401300158 Forwards IE Insp Repts 50-206/83-27, 50-361/83-42 & 50-362/83-41 on 831227-28 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 84/01/19
MCCARTHY, C B Southern California Edison Co 2pp 21999 111 24X Fiche 50-206,84/01/19,8401300158

--8401300160 IE Insp Repts 50-206/83-27, 50-361/83-42 & 50-362/83-41 on 831227-28 No noncompliance noted Major areas inspected power ascension test program & licensee actions re release of matl contaminated w/low levels of radioactivity
YUHAS, Q P, WENSLAWSKI, F A Region 5, Office of Director 84/01/19 App 21999 113 24X Fiche 50-206,84/01/19,8401300158

R Periodic operating reports & related correspondence

8401120247 Monthly operating rept for Nov 1983 W/831215 ltr
MORRIS, C A, HAYNES, J O Southern California Edison Co 83/11/30
Office of Resource Management, Director 6pp 21793 264 24X Fiche 50-206,83/11/30,8401120247

8401270234 Monthly operating rept for Dec 1983 W/840116 ltr
MORRIS, C A, HAYNES, J O Southern California Edison Co 83/12/31
Division of Data Automation & Management Information 7pp 21976 328 24X Fiche 50-206,83/12/31,8401270234

B Reportable occurrences, LERs & related correspondence

8401040320 Supplemental RD 83-005 calculated RCS peak pressure exceeded 500-psig limit Structural integrity of RCPB not threatened
Cause not stated
HAYNES, J O Southern California Edison Co 83/12/16 MARTIN, J B
Region 5, Office of Director 2pp 21708 036 24X Fiche 50-206,83/12/16,8401040320

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended Utills notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000,84/01/09,8401170186

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8401090132 Forwards status of current plans for implementation of provisions of Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability," transmitted by Generic Ltr 82-33
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/11/28 EIBENHUT, D O
Division of Licensing 23pp 21749 170 24X Fiche 50-000,83/11/28,8401090132

8312300205 Forwards list of dates acceptable to util per confirmatory orders re integrated implementation schedules for Suppl 1 to NUREG-0737, Generic Ltr 82-33, "Requirements for Emergency Response Capability "
COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W O Northeast Utilities 83/12/20 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5
Spp 21673 114 24X Fiche 50-000,83/12/20,8312300205

8401100325 Forwards IE Insp Rept 50-213/83-21 on 830926-1031 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 83/12/23
COUNSIL, W O Connecticut Yankee Atomic Power Co 2pp 21764 147 24X Fiche 50-213,83/12/23,8401100325

--8401100332 IE Insp Rept 50-213/83-21 on 830926-1031 No violations noted Major areas inspected control room, turbine bldg, primary auxiliary bldg & auxiliary feed pump room, followup on LERs & previous insp findings.
SWETLAND, P D Region 1, Office of Director, ELSSABER, T C
Division of Project & Resident Programs 83/12/16 App 21764 149 24X Fiche 50-213,83/12/23,8401100325

DOCKETED ITEMS

8401050081 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21742 005 24X Fiche 50-213, 83/12/28, 8401050081

--8401050086 Public version of Rev 17 to Emergency Plan Implementing Procedure EPIP 1 5-2, "Notification & Communication"
W/831115 ltr
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/10/31
EISENHUT, D G Division of Licensing 41pp 21742 005 24X
Fiche 50-213, 83/12/28, 8401050081

8401230156 Forwards Rev 10 to modified amended security plan Rev withheld (ref 10CFR73.21 & 10CFR2.790)
COUNCIL, W G Connecticut Yankee Atomic Power Co 84/01/11
CRUTCHFIELD, D Operating Reactors Branch 5 1p 21884 350 24X
Fiche 50-213, 84/01/11, 8401230156

8401230662 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21925 161 24X Fiche 50-213, 84/01/18, 8401230662

--8401230664 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-2 re notification & communication & EPIP 1 5-24 re manager of communications
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/12/28
EISENHUT, D G Division of Licensing 1p 21925 162 24X
Fiche 50-213, 84/01/18, 8401230662

--8401230667 Public version of revised emergency plan implementing procedures, including EPIP 1 5-2 re notification & communication, EPIP 1 5-24 re manager of communications & EPIP 1 5-33 re shift supervisor staff assistant
BROWN, J E Connecticut Yankee Atomic Power Co 83/12/15 84pp
21925 163 24X Fiche 50-213, 84/01/18, 8401230662

8401300336 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/25 Document
Management Branch 1p 22006 110 24X Fiche 50-213, 84/01/25, 8401300336

--8401300339 Forwards public version of revised emergency plan implementing procedures, including Procedure EPIP 1 5-39 re post-accident sampling & reactor coolant & EPIP 1 5-45 re emergency communication sys testing
COUNCIL, W G Connecticut Yankee Atomic Power Co 84/01/09
EISENHUT, D G Division of Licensing 1p 22006 111 24X
Fiche 50-213, 84/01/25, 8401300336

--8401300342 Public version of revised emergency plan implementing procedures, including Procedure EPIP 1 5-39 re post-accident sampling & reactor coolant & EPIP 1 5-45 re emergency communication sys testing
BARTON, W D, BEAUCHAMP, J E Connecticut Yankee Atomic Power Co 83/12/22 39pp 22006 112 24X Fiche 50-213, 84/01/25, 8401300336

J Insurance & indemnity information

8401130016 Forwards Endorsement 4 to NELIA Certificate N-11 & MAELU Certificate M-11 w/o MAELU endorsement
SINISI, J M Marsh & McLennan, Inc 83/12/27 SALTZMAN, J D
Assistant Director for State & Licensee Relations 2pp 21802 348
24X Fiche 50-213, 83/12/27, 8401130016

8401130130 Forwards Endorsement 5 to NELIA Certificates N-13 & N-16 & Endorsement 5 to MAELU Certificates M-13 & M-16
SINISI, J M Marsh & McLennan, Inc 83/12/27 SALTZMAN, J D
Assistant Director for State & Licensee Relations 5pp 21802 237
24X Fiche 50-000, 83/12/27, 8401130130

P Operating license stage documents & correspondence

8401040173 Responds to final SER dtd 821020 re SEP Topic VII-1 A, "Isolation of Reactor Protection Sys From Non-Safety Sys, Including Qualifications of Isolation Devices," resolving concerns in integrated plant safety assessment (NUREG-0826)
COUNCIL, W G Connecticut Yankee Atomic Power Co 83/12/14
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21702 018 24X
Fiche 50-213, 83/12/14, 8401040173

8401030143 Forwards evaluation of post-accident sampling sys (PASS) per TMI Item 11 B 3 Evaluation demonstrates PASS capable of obtaining representative sample for liquid & gaseous PASS subsystems
COUNCIL, W G, OPEKA, J F Connecticut Yankee Atomic Power Co 83/12/21 Office of Nuclear Reactor Regulation, Director
MURLEY, T E Region 1, Office of Director 15pp 21682 258 24X
Fiche 50-213, 83/12/21, 8401030143

8401040226 Clarifies nature of problem w/control switch terminal lug SS-50V-105B in post-accident sampling sys (TMI Action Item 11 B 3) Ring tongue connector properly installed Sketch encl
COUNCIL, W G, OPEKA, J F Connecticut Yankee Atomic Power Co 83/12/21 MURLEY, T E Region 1, Office of Director 3pp
21701 189 24X Fiche 50-213, 83/12/21, 8401040226

840100392 Discusses integrated assessment of regulatory requirements, per util 830613 & 0914 & NRC 831005 ltrs Scheduler relief from requirements identified in Encls 1 & 5 requested by 840120 issues to be included in expanded assessment encl
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/12/20 EISENHUT, D G Division of Licensing 97pp 21762 297 24X Fiche 50-000, 83/12/28, 840100392

8401030166 Informs of results of review of pump testing program relief request & grants relief, in part, from insp requirements of Section XI ASME Code SER & notice of granting of relief encl
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/29 COUNCIL, W G Connecticut Yankee Atomic Power Co 3pp 21681 298 24X
Fiche 50-213, 83/12/29, 8401030166

--8401030172 Safety evaluation supporting grant of partial relief from inservice pump testing requirements
* Office of Nuclear Reactor Regulation, Director 83/12/29 17pp 21681 301 24X Fiche 50-213, 83/12/29, 8401030166

--8401030173 Notice of granting of relief from ASME Section XI re inservice testing requirements
PAULSON, W A Operating Reactors Branch 5 83/12/29 2pp
21681 318 24X Fiche 50-213, 83/12/29, 8401030166

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401100449 Requests final radiological effluent Tech Specs, incorporating resolution of items discussed w/Franklin Research Ctr in Jan 1982 Specs due in 30 days Guidance given in encl Draft 7 of Rev 3 to NUREG-0472
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/05 COUNCIL, W G Connecticut Yankee Atomic Power Co 85pp 21762 001 24X
Fiche 50-213, 84/01/05, 8401100449

8401190126 Requests fee for review of 831024 application to amend Tech Specs re licensed operator staffing
DIGGS, R M License Fee Management Branch 84/01/05 COUNCIL, W G Connecticut Yankee Atomic Power Co 1p 21871 031 24X
Fiche 50-213, 84/01/05, 8401190126

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401101145 Notification of 840116 meeting w/util in Bethesda, MD to discuss util intent to perform in-house reload analyses Agenda encl
LYONS, J E Operating Reactors Branch 5 84/01/09 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 21772 207 24X
Fiche 50-213, 84/01/09, 8401101145

8401200164 Forwards revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual" w/o encls
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities Service Co (subs of Northeast Utilities) 84/01/09 EISENHUT, D G Division of Licensing 2pp
21866 341 24X Fiche 50-000, 84/01/09, 8401200164

8401160088 Notification of 840118-20 & 23-26 meetings w/util & BNL at plant sites to collect data on high radiation exposure jobs
SHEA, J J Operating Reactors Branch 5 84/01/11 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21815 062 24X
Fiche 50-000, 84/01/11, 8401160088

DOCKETED ITEMS

27

B401230373 Forwards SEP evaluation completion schedules for integrated plant safety assessment repts (NUREG-0826 & NUREG-0824), in response to NRC B31006 ltr
COUNSIL, W G , SEARIS, C F Connecticut Yankee Atomic Power Co
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) B4/01/11 CRUTCHFIELD, D Operating Reactors Branch 5 Bpp 21873 336 24X Fiche 50-000, B4/01/11, B401230373

B401160221 Forwards summary of three BNL contracts re study of occupational dose reduction at nuclear power plants
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/12 COUNSIL, W G Connecticut Yankee Atomic Power Co 7pp 21808 309 24X Fiche 50-000, B4/01/12, B401160221

B401230286 Discusses procedural changes to integrated plant safety assessment (NUREG-0826) re ability to balance svc water sys flow to maintain sys components below design thermal limits for active & passive failures, per SEP Topic IX-3
COUNSIL, W G Connecticut Yankee Atomic Power Co B4/01/12 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21884 198 24X Fiche 50-213, B4/01/12, B401230286

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OAs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing B4/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X Fiche 50-000, B4/01/13, B401130084

B401230151 Notification of B40101-11 meetings w/util in Bethesda, MD to discuss & resolve outstanding environ qualification issues
SHEA, J J Operating Reactors Branch 5 B4/01/20 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21884 316 24X Fiche 50-000, B4/01/20, B401230151

B401240405 Summary of B40116 meeting w/util re inhouse reload capability for Facility Viewgraphs encl
LYONS, J E Operating Reactors Branch 5 B4/01/23 Operating Reactors Branch 5 50pp 21915 260 24X Fiche 50-213, B4/01/23, B401240405

B401270198 Notifies that JE Lyons designated new project manager for facility as result of reorganization of Operating Reactors Branch 5
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/25 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 21976 359 24X Fiche 50-213, B4/01/25, B401270198

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement B3/10/20, 134pp, 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401100325 Forwards IE Insp Rept 50-213/B3-21 on B30926-1031 No violations noted
STAROSTECKI, R Division of Project & Resident Programs B3/12/23 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 21764 147 24X Fiche 50-213, B3/12/23, B401100325

--B401100332 IE Insp Rept 50-213/B3-21 on B30926-1031 No violations noted Major areas inspected control room, turbine bldg, primary auxiliary bldg & auxiliary feed pump room, followup on LERs & previous insp findings
SWETLAND, P D Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs B3/12/16 6pp 21764 149 24X Fiche 50-213, B3/12/23, B401100332

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B401030166 Informs of results of review of pump testing program relief request & grants relief, in part, from insp requirements of Section XI ASME Code SER & notice of granting of relief encl
CRUTCHFIELD, D, Operating Reactors Branch 5 B3/12/29 COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 21681 298 24X Fiche 50-213, B3/12/29, B401030166

--B401030172 Safety evaluation supporting grant of partial relief from inservice pump testing requirements
* Office of Nuclear Reactor Regulation, Director B3/12/29 17pp 21681 301 24X Fiche 50-213, B3/12/29, B401030166

--B401030173 Notice of granting of relief from ASME Section XI re inservice testing requirements
PAULSON, W A Operating Reactors Branch 5 B3/12/29 2pp 21681 318 24X Fiche 50-213, B3/12/29, B401030166

B312120093 IE Info Notice B3-04, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co. of New York, Inc 129pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R Periodic operating reports & related correspondence

B401120280 Monthly operating rept for Nov 1983 W/B31215 ltr
ELMS, A , GRAVES, R H Connecticut Yankee Atomic Power Co B3/11/30 NRC - No Detailed Affiliation Given 10pp 21792 061 24X Fiche 50-213, B3/11/30, B401120280

B401270257 Monthly operating rept for Dec 1983 W/B40115 ltr
UNIKIEWICZ, S , GRAVES, R H Connecticut Yankee Atomic Power Co B3/12/31 Office of Resource Management, Director 10pp 21982 200 24X Fiche 50-213, B3/12/31, B401270257

B Reportable occurrences, LERs & related correspondence

B401160073 LER B3-022/03L-0 on B31123, vol control tank outlet valve M111 257 control power failed Operator stationed at valve for manual operation Caused by inadequate ampacity control transformer & protective fuse Fuse replaced W/B31222 ltr
BARTON, W D , GRAVES, R H Connecticut Yankee Atomic Power Co B3/12/22 MURLEY, T E Region 1, Office of Director 2pp 21821 209 24X Fiche 50-213, B3/12/22, B401160073

B401050163 LER B3-023/03L-0 on B31201, during monthly testing, diesel generator EQ-2B assumed load greater than governor setting w/o operator action Caused by maladjusted diesel generator governor assembly Governor adjusted W/B31227 ltr
BARTON, W D , GRAVES, R H Connecticut Yankee Atomic Power Co B3/12/27 MURLEY, T E Region 1, Office of Director 3pp 21727 331 24X Fiche 50-213, B3/12/27, B401050163

B401270062 LER B3-024/01P-0 on review revealed that calculated svc water flow to containment fan coolers during normal operation may be less conservative than assumed in current containment pressure analysis Evaluation continuing
GRAVES, R H Connecticut Yankee Atomic Power Co B3/12/30 MURLEY, T E Region 1, Office of Director 1p 21981 360 24X Fiche 50-213, B3/12/30, B401270062

B401270336 Forwards LER B3-024/01T-0 & evaluation of SEP Topic IX-3, "Station Svc & Cooling Water Sys "
GRAVES, R H Connecticut Yankee Atomic Power Co B4/01/02 MURLEY, T E Region 1, Office of Director 1p 21981 220 24X Fiche 50-213, B4/01/02, B401270336

DOCKETED ITEMS

--B401270347 LER 83-024/01T-0 on B31230, discovered calculated svc water flow to containment fan coolers less conservative than assumed in current containment pressure analysis. Caused by lack of heat removal capacity.
BRASSORD, J D, GRAVES, R H. Connecticut Yankee Atomic Power Co
B4/01/12 Region 1, Office of Director 2pp 21981 221 24X
Fiche 50-219, B4/01/02, B401270336

B401270404 LER 83-025/03L-0 on B31207, during rod motion checks, bank A Subgroup 2 control rods could not be withdrawn from full out position. Caused by faulty valve cyler motor starter switch.
Switch replaced W/B40103 ltr
BOUCHARD, O H, GRAVES, R H. Connecticut Yankee Atomic Power Co
B4/01/04 MURLEY, T E Region 1, Office of Director 2pp
21981 059 24X Fiche 50-219, B4/01/04, B401270404

B401300290 PMS-I-B4-001 on B40124, bomb threat received at plant. Bomb search initiated of protected & vital areas. Results of search negative. No areas of plant evacuated.
SMITH, C, JOYNER, J. Region 1, Office of Director B4/01/25 1p
21997 344 24X Fiche 50-219, B4/01/25, B401300290

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

B401240489 Forwards Rev 5 to security officer training & qualification plan. Rev withheld (ref 10CFR73.21).
FIEDLER, P B General Public Utilities - GPU Service Corp B4/01/13
MARTIN, T T Division of Engineering & Technical Programs 2pp
21917 115 24X Fiche 50-219, B4/01/13, B401240489

B401240197 Ack receipt of B40103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-23.
STAROSTECKI, R Division of Project & Resident Programs B4/01/18
FIEDLER, P B General Public Utilities - GPU Service Corp 1p
21913 227 24X Fiche 50-219, B4/01/18, B401240197

--B401240209 Responds to NRC B31205 ltr re violations noted in IE Insp Rept 50-219/83-23. Corrective actions fire watch reestablished & operations memo requiring fire watch in diesel generator bldg issued.
FIEDLER, P B General Public Utilities - GPU Service Corp
B4/01/03 STAROSTECKI, R Division of Project & Resident Programs 2pp 21913 228 24X Fiche 50-219, B4/01/18, B401240197

P Operating license stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers. Forwards App A documents. Remaining documents under review.
FELTON, J M Division of Rules and Records B3/10/18 MEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, B3/10/18, B401250015

--B401250370 Informs of results of SEP review. Rept will be published & distributed by B31230.
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-496 B2/12/21 6pp 21967 140 24X
Fiche 50-000, B3/10/18, B401250015

B401060148 Forwards application for amend to License DPR-16, consisting of proposed Tech Spec Change Request 119 re long-term scram sys reliability.
FIEDLER, P B General Public Utilities - GPU Service Corp B3/12/21
Office of Nuclear Reactor Regulation, Director 2pp 21739 211
24X Fiche 50-219, B3/12/21, B401060148

--B401060153 Application for amend to License DPR-16, consisting of proposed Tech Spec Change Request 119 re long-term scram sys reliability. Certificate of Svc encl.
FIEDLER, P B General Public Utilities - GPU Service Corp
B3/12/21 4pp 21739 213 24X Fiche 50-219, B3/12/21, B401060148

--B401060161 Proposed Tech Spec Change Request 119 re long-term scram sys reliability.
* General Public Utilities - GPU Service Corp B3/12/21 8pp
21739 217 24X Fiche 50-219, B3/12/21, B401060148

B401030068 Requests submittal of survey rept described in Item C(4)(a) of Reg Guide 1 B6 prior to release of contaminated matls, per util B30831 ltr & B31123 telcon.
CRUTCHFIELD, D Operating Reactors Branch 5 B3/12/30 FIEDLER, P B
General Public Utilities - GPU Service Corp 3pp 21683 203 24X
Fiche 50-219, B3/12/30, B401030068

B401100318 Forwards status of unresolved safety issues re conversion of provisional license to full-term license.
FIEDLER, P B General Public Utilities - GPU Service Corp B4/01/03
CRUTCHFIELD, D Operating Reactors Branch 5 5pp 21763 277 24X
Fiche 50-219, B4/01/03, B401100318

B40110260 Suggests NRC postpone approval of B20521 Amend Request 104 & B31011 Rev 1 to request until independent review confirms adequacy of flow water from existing facility core spray sys.
SCOTT, D M New Jersey, State of B4/01/03 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 21772 356 24X
Fiche 50-219, B4/01/03, B40110260

B401180259 Requests authorization to chlorinate main condenser sys & discharge total residual chlorine at up to 0.20 mg/l from sys as measured at point of discharge to receiving waterway for up to 12 h/day. Technical justification encl.
EBERT, R W General Public Utilities - GPU Service Corp B4/01/04
MURISKI, P C New Jersey, State of 5pp 21843 253 24X
Fiche 50-219, B4/01/04, B401180259

--B401180264 "Oyster Creek Condenser Chlorination Rept."
* General Public Utilities - GPU Service Corp 104-75-7
77/03/31 58pp 21843 258 24X Fiche 50-219, B4/01/04, B401180259

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl.
EISENHUT, D O Division of Licensing B4/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D O Division of Licensing B4/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

B401160125 Forwards Amend 69 to License DPR-16 & safety evaluation. Amend reflects administrative changes re safety review & audit program.
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/12 FIEDLER, P B
General Public Utilities - GPU Service Corp 4pp 21815 226 24X
Fiche 50-219, B4/01/12, B401160125

--B401160134 Amend 69 to License DPR-16, revising Tech Specs re implementing safety review & audit program, adding position of maint & const director & removing word "entire" from Paragraph 6.5.3.1(b).
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/12 28pp
21815 230 24X Fiche 50-219, B4/01/12, B401160125

--B401160139 Safety evaluation supporting Amend 69 to License DPR-16.
ALLENSPACH, F Office of Nuclear Reactor Regulation, Director
B4/01/12 3pp 21815 258 24X Fiche 50-219, B4/01/12, B401160125

B401170154 Informs of delay of completion of plant-specific risk assessment from B31115 to Apr 1984. Assessment conducted to select mod to automatic depressurization sys logic, per MUREQ-0737, Item 11 K 3.18.
FIEDLER, P B General Public Utilities - GPU Service Corp B4/01/12
CRUTCHFIELD, D Operating Reactors Branch 5 1p 21834 127 24X
Fiche 50-219, B4/01/12, B401170154

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of MUREQ-0933, "Prioritization of Generic Safety Issues." Svc list encl.
EISENHUT, D O Division of Licensing B4/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401160280 Forwards SER & technical evaluation rept re Mark I containment long-term program pool dynamic loads issue. Mode acceptable. Commitments re vacuum breakers per Generic Ltr B3-02 will be reviewed independently.
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/13 FIEDLER, P B
General Public Utilities - GPU Service Corp 4pp 21814 227 24X
Fiche 50-219, B4/01/13, B401160280

--B401160281 Safety evaluation supporting Mark I containment long-term program pool dynamic loads issue.
* Office of Nuclear Reactor Regulation, Director B4/01/13 2pp
21814 231 24X Fiche 50-219, B4/01/13, B401160280

--B401160284 "Technical Evaluation of Oyster Creek Plant Unique Analysis Repts."
LEHNER, J R, BIENKOWSKI, G, LIN, C C Brookhaven National Laboratory FIN A-3713 04243 B3/09/30 NRC - No Detailed
Affiliation Given 26pp 21814 233 24X Fiche 50-219, B4/01/13, B401160280

DOCKETED ITEMS

29

B401180146 Forwards safety evaluation re Mark I containment long-term program structural review Deviations from NUREG-0661 acceptable Original design safety margin restored
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/13 FIEDLER, P B
General Public Utilities - GPU Service Corp 3pp 21848 312 24X
Fiche 50-219, 84/01/13, B401180146

--B401180260 Safety evaluation supporting Mark I containment long-term program structural review Mods acceptable, per NUREG-0661
& ASME Code, Sections XI & III
* Office of Nuclear Reactor Regulation, Director 84/01/13 3pp
21848 315 24X Fiche 50-219, 84/01/13, B401180146

--B309010227 "Audit for Mark I Containment Long-Term Program - Structural Analysis for Operating Reactors, Oyster Creek Nuclear Generating Station," technical evaluation rept
SUBRAMONIAN, N Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-C5906-319 83/08/30 SHAW, H NRC - No
Detailed Affiliation Given 50pp 21849 001 24X
Fiche 50-219, 84/01/13, B401180146

B401180087 Requests submittal of plant-specific responses to NUREG-0503 & Generic Ltr B1-34 re safety concerns associated w/pipe breaks in BWR scram sys piping Responses should be submitted by B40305
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/17 FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 21840 306 24X
Fiche 50-219, 84/01/17, B401180087

B401190362 Requests listed addl info re isolation condenser vent installation within 30 days, per B20802 & 1215 requests for exemption from 10CFR50.44(c)
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/17 FIEDLER, P B
General Public Utilities - GPU Service Corp 2pp 21849 361 24X
Fiche 50-219, 84/01/17, B401190362

B401240570 Forwards safety evaluation concluding that licensee failed to demonstrate ability of containment purge & vent valves to close against buildup of containment pressure in event of LOCA
MIRALIA, F J Assistant Director for Safety Assessment 84/01/20
FIEDLER, P B General Public Utilities - GPU Service Corp 3pp
21908 088 24X Fiche 50-219, 84/01/20, B401240570

--B401240572 Safety evaluation concluding that licensee failed to demonstrate ability of containment purge & vent valves to close against buildup of containment pressure in event of LOCA
Valves should be sealed closed
* Office of Nuclear Reactor Regulation, Director 84/01/20 3pp
21908 091 24X Fiche 50-219, 84/01/20, B401240570

B401270235 Requests available info re distribution of plants or animals listed or proposed to be listed as endangered or threatened species in vicinity of facility Info needed for review of request to convert provisional OL to full-term OL
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/25 KULP, C
Interior, Dept of, Fish & Wildlife Service 3pp 21976 354 24X
Fiche 50-219, 84/01/25, B401270235

B401270479 Forwards Amend 70 to License DPR-16 & safety evaluation Amend requires acceptable insps of both core spray sparger & repair assemblies at each refueling outage
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/26 FIEDLER, P B
General Public Utilities - GPU Service Corp 4pp 21980 121 24X
Fiche 50-219, 84/01/26, B401270479

--B401270487 Amend 70 to License DPR-16, modifying Paragraph 2 C (7) of OL to require insps of both core spray spargers & repair assemblies at each refueling outage by method acceptable to NRC
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/26 2pp
21980 125 24X Fiche 50-219, 84/01/26, B401270479

--B401270495 Safety evaluation supporting Amend 70 to License DPR-16
* Office of Nuclear Reactor Regulation, Director 84/01/26 3pp
21980 127 24X Fiche 50-219, 84/01/26, B401270479

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance w/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

B401240197 Ack receipt of B40103 ltr informing NRC of steps taken to correct violations noted in IE Inpt Rept 50-219/B3-23
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
FIEDLER, P B General Public Utilities - GPU Service Corp 1p
21913 227 24X Fiche 50-219, 84/01/18, B401240197

--B401240209 Responds to NRC B31205 ltr re violations noted in IL Insn Rept 50-219/B3-23 Corrective actions fire watch reestablished & operations memo requiring fire watch in diesel generator bldg issued
FIEDLER, P B General Public Utilities - GPU Service Corp
84/01/03 STAROSTECKI, R Division of Project & Resident Programs 2pp 21913 228 24X Fiche 50-219, 84/01/18, B401240197

B401270479 Forwards Amend 70 to License DPR-16 & safety evaluation Amend requires acceptable insps of both core spray sparger & repair assemblies at each refueling outage
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/26 FIEDLER, P B
General Public Utilities - GPU Service Corp 4pp 21980 121 24X
Fiche 50-219, 84/01/26, B401270479

--B401270487 Amend 70 to License DPR-16, modifying Paragraph 2 C (7) of OL to require insps of both core spray spargers & repair assemblies at each refueling outage by method acceptable to NRC
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/26 2pp
21980 125 24X Fiche 50-219, 84/01/26, B401270479

--B401270495 Safety evaluation supporting Amend 70 to License DPR-16
* Office of Nuclear Reactor Regulation, Director 84/01/26 3pp
21980 127 24X Fiche 50-219, 84/01/26, B401270479

R Periodic operating reports & related correspondence

B401120249 Monthly operating rept for Nov 1983 W/B31215 ltr
BARAN, R, FIEDLER, P B General Public Utilities - GPU Service Corp
83/11/30 Office of Resource Management, Director 8pp
21793 273 24X Fiche 50-219, 83/11/30, B401120249

B401160085 "NPDES Discharge Monitoring Rept for Dec 1983 " W/B40109 ltr
FIEDLER, P B General Public Utilities - GPU Service Corp 83/12/31
GASTON, J New Jersey, State of Bpp 21821 201 24X
Fiche 50-219, 83/12/31, B401160085

DOCKETED ITEMS

B401270259 Monthly operating rept for Dec 1983 W/B40116 ltr
BARAN R, KOTIGAN D L, FIEDLER P B General Public Utilities - GPU
Service Corp 83/12/31 Office of Resource Management, Director
7pp 21732 213 24X Fiche 50-219,83/12/31,B401270259

B Reportable occurrences, LERs & related correspondence

B401130155 LER B3-C24-C1P-0 on B31220, during review of torque switch
setpoints of Limiting Motor operated valves, setpoints
discovered set lower than manufacturers data Caused by lack
of knowledge re setpoint design basis
FIEDLER P B General Public Utilities - GPU Service Corp 83/12/21
Region 1, Office of Director 3pp 21602 230 24X
Fiche 50-219 83/12/21 B401130155

B401120435 LER B3-C25-C1P on B31223 discovered that addition of lead
for radiation shielding on fuel pool cooling HX could
overstress foundation bolts during seismic event Caused by
lack of procedure controls Decontamination effort scheduled
FIEDLER P B General Public Utilities - GPU Service Corp 83/12/23
Region 1 Office of Director App 21791 C45 24X
Fiche 50-219 83/12/23 B401120435

B401160193 LER C3-C25-CCL-0 on B31201, maint & surveillance procedures
identified as not adequately verifying excess flow check
valves open following operations Caused by inadequate maint
& surveillance procedures Procedures revised W/B40103 ltr
MURDOCK R J, FIEDLER P B General Public Utilities - GPU Service
Corp 84/01/03 MURLEY T E Region 1 Office of Director App
21609 366 24X Fiche 50-219,84/01/03 B401160193

B401160139 LER B3-C24-C1P on B31220 torque switch setpoints discovered
lower than manufacturer data Caused by lack of sufficient
knowledge Setpoints will be reset Design basis being
investigated W/B40103 ltr
FIEDLER P B General Public Utilities - GPU Service Corp 84/01/05
MURLEY T E Region 1 Office of Director 3pp 21815 263 24X
Fiche 50-219 84/01/05 B401160139

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

P Security, medical emergency & fire protection plans

B401060177 Forwards Amend 53 to license DPR-63 & safety evaluation
Amend adds limiting conditions for operation, surveillance
requirements & changes bases for fire protection programs
HERMAN, R A Operating Reactors Branch 2 83/12/20 RHODE G W
Niagara Mohawk Power Corp 3pp 21744 267 24X
Fiche 50-220 83/12/20 B401060177

--B401060165 Amend 53 to license DPR-63 adding limiting conditions for
operation, surveillance requirements & changing bases for
fire protection program
VASSALLO D B Operating Reactors Branch 2 83/12/20 35pp
21744 269 24X Fiche 50-220 83/12/20 B401060177

--B401060163 Safety evaluation supporting Amend 53 to license DPR-63
* Office of Nuclear Reactor Regulation, Director 83/12/20 2pp
21744 264 24X Fiche 50-220 83/12/20 B401060177

C401070259 Forwards evaluation of compliance w/emergency response
facility criteria presented in Suppl 1 to NUREG-0737 per
B30415 ltr Several areas identified that depart from
criteria
MANGAN C V Niagara Mohawk Power Corp 84/01/03 VASSALLO D B
Operating Reactors Branch 2 3pp 21753 329 24X
Fiche 50-220 84/01/03 B401070259

B401090326 Forwards info re safety parameter display sys. in response to
B30415 ltr Requests preimplementation review prior to
undertaking addl efforts in software development, per Suppl 1
to NUREG-0737
MANGAN C V Niagara Mohawk Power Corp 84/01/03 VASSALLO D B
Operating Reactors Branch 2 24pp 21754 314 24X
Fiche 50-220 84/01/03 B401090326

B401180208 Forwards IE Insp Rept 50-220/B3-23 on B31101-1212 No
violations observed
STARCOTECKI, R Division of Project & Resident Programs 84/01/06
RHODE G W Niagara Mohawk Power Corp 2pp 21844 165 24X
Fiche 50-220 84/01/06 B401180208

--B401180211 IE Insp Rept 50-220/B3-23 on B31101-1212 No violations
observed Major areas inspected licensee action on previous
insp findings, operational safety verification, physical
security, plant tours & surveillance testing
MUSCO B D, COLLINS B J Region 1 Office of Director 84/01/04
11pp 21844 167 24X Fiche 50-220 84/01/06 B401180208

B401190376 Forwards IE Safeguards Insp Rept 50-220/B3-23 on B31129-
1202 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/06
SUNSER, J J Niagara Mohawk Power Corp 2pp 21849 293 24X
Fiche 50-220,84/01/06,B401190376

--B401190384 IE Safeguards Insp Rept 50-220/B3-23 on B31129-1202 No
noncompliance noted Major areas inspected security
organization, security program audit, testing & maint, physical
barriers, security sys power supply & assessment aids
DUNLAP, J M, GODY, A T Region 1, Office of Director 84/01/05
3pp 21849 295 24X Fiche 50-220,84/01/06,B401190376

B401250097 Forwards fee, per B31205 request, for fire protection review
LEMPGES, T E Niagara Mohawk Power Corp 84/01/12 MILLER, W O
License Fee Management Branch 2pp 21939 026 24X
Fiche 50-220,84/01/12,B401250097

B401230573 Releases public version of revised State of NY radiological
emergency response plan, revised county radiological
emergency preparedness plan & county radiological plan
procedures
FELTON, J M Division of Rules and Records 84/01/19 Document
Management Branch 1p 21891 166 24X Fiche 50-220,84/01/19,
B401230573

--B401230576 Forwards public version of revised State of NY radiological
emergency response plan, Rev 3 to Oswego County radiological
emergency preparedness plan & county radiological emergency
plan procedures
MANGAN, C V, DILLENBACK, J R Niagara Mohawk Power Corp 84/01/06
Document Management Branch 3pp 21891 167 24X
Fiche 50-220,84/01/19,B401230573

--B401230578 Public version of revised State of NY radiological emergency
response plan & Rev 3 to Oswego County radiological
emergency preparedness plan
* Niagara Mohawk Power Corp 83/01/15 840pp 21891 170 24X
Fiche 50-220,84/01/19,B401230573

--B401230583 Public version of revised Oswego County radiological
emergency preparedness plan procedures, including Procedure A
re Dfc of Emergency Preparedness/Civil Defense, B re law
enforcement & D re schools
* Niagara Mohawk Power Corp 83/03/31 629pp 21893 290 24X
Fiche 50-220,84/01/19,B401230573

B401300209 Responds to B40109 ltr forwarding correspondence from
Croton-Harmon School District in Croton-on-Hudson, NY re
Westchester County evacuation plan for school children in
event of facility accident FEMA already responded
KRIMM, R W Federal Emergency Management Agency 84/01/24
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 21994 001 24X Fiche 50-000,84/01/24,
B401300209

--B401300213 Forwards post-exercise assessment of B30928 exercise of
radiological emergency preparedness plans of State of NY
& Oswego County
KRIMM, R W Federal Emergency Management Agency 84/01/23
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 21994 002 24X
Fiche 50-000,84/01/24,B401300209

--B401300215 Post-exercise assessment of B30928 exercise of radiological
emergency preparedness plans of State of NY & Oswego
County
PETRONE, F P Federal Emergency Management Agency 83/12/23
102pp 21994 004 24X Fiche 50-000,84/01/24,B401300209

J Insurance & indemnity information

B401230006 Forwards Endorsement 84 to NELIA Policy NF-161
RUSHMORE, J W Niagara Mohawk Power Corp 84/01/11 SALTZMAN, J
Assistant Director for State & Licensee Relations 2pp 21884 304
24X Fiche 50-220,84/01/11,B401230006

B401230486 Forwards Endorsement 70 to MAELU Policy MF-46
RUSHMORE, J W Niagara Mohawk Power Corp 84/01/11 SALTZMAN, J
Assistant Director for State & Licensee Relations 2pp 21882 114
24X Fiche 50-220,84/01/11,B401230486

K Utility Final Safety Analysis Report (FSAR) & amendments

B312280405 Forwards 339 oversize drawings referenced in Section 1 7 of
FSAR Drawing updates originally forwarded on B30425 w/Amend
cards are available in PDR
MANGAN, C V Niagara Mohawk Power Corp 83/12/16 SCHWENGER, A
Licensing Branch 2 3pp 21649 242 24X Fiche 50-220,83/12/16,
B312280405

DOCKETED ITEMS

31

P Operating license stage documents & correspondence

B401180226 Forwards QA program for facility in accordance w/10CFR50.54(a)(2) Submittal replaces 13th suppl to updated FBAR in entirety

DISE, D P Niagara Mohawk Power Corp 83/06/10 ALLEN, J M Region 1, Office of Director 1p 21842 229 24X Fiche 50-220, 83/06/10, B401180226

--B401180227 QA program for facility
DISE, D P Niagara Mohawk Power Corp 83/06/10 60pp 21842 230 24X Fiche 50-220, 83/06/10, B401180226

B401060177 Forwards Amend 53 to License DPR-63 & safety evaluation Amend adds limiting conditions for operation, surveillance requirements & changes bases for fire protection programs
HERMANN, R A Operating Reactors Branch 2 83/12/20 RHODE, G K Niagara Mohawk Power Corp 2pp 21744 267 24X Fiche 50-220, 83/12/20, B401060177

--B401060185 Amend 53 to License DPR-63, adding limiting conditions for operation, surveillance requirements & changing bases for fire protection program
VASSALLO, D B Operating Reactors Branch 2 83/12/20 35pp 21744 269 24X Fiche 50-220, 83/12/20, B401060177

--B401060188 Safety evaluation supporting Amend 53 to License DPR-63
* Office of Nuclear Reactor Regulation, Director 83/12/20 2pp 21744 304 24X Fiche 50-220, 83/12/20, B401060177

B401030196 Informs that completion of preliminary review of contractor B31128 rept re control room habitability study (TMI Action Plan Item III D 3 4), per util B30606 ltr, will be delayed until B401031
MANGAN, C V Niagara Mohawk Power Corp 83/12/23 VASSALLO, D B Operating Reactors Branch 2 1p 21681 362 24X Fiche 50-220, 83/12/23, B401030196

B401040610 Notifies that preliminary review of B20217 application for Tech Spec change for Multi-Plant Action B-24 in progress & addl info required Guidance re required supplemental items will be provided upon completion
HERMANN, R A Operating Reactors Branch 2 83/12/27 RHODE, G K Niagara Mohawk Power Corp 2pp 21714 193 24X Fiche 50-220, 83/12/27, B401040610

B401160005 Forwards safety evaluation accepting licensee B31006 commitment to comply w/new shift technical advisor staffing rule Rev to Tech Specs requested within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/12/28 RHODE, G K Niagara Mohawk Power Corp 3pp 21821 343 24X Fiche 50-220, 83/12/28, B401160005

--B401160007 Safety evaluation accepting licensee B31006 commitment to comply w/new shift technical advisor staffing requirements
* Office of Nuclear Reactor Regulation, Director 83/12/28 2pp 21821 346 24X Fiche 50-220, 83/12/28, B401160005

B401270019 Forwards safety evaluation based on analyses of reactor bldg structural integrity & intended corrective actions for crack in reactor bldg wall
VASSALLO, D B Operating Reactors Branch 2 83/12/29 RHODE, G K Niagara Mohawk Power Corp 2pp 22003 001 24X Fiche 50-220, 83/12/29, B401270019

--B401270021 Safety evaluation re reactor bldg wall crack Facility can safely operate until long-term corrective decoupling of reactor bldg & screenhouse wall completed in Spring 1984 refueling outage
* NRC - No Detailed Affiliation Given 83/12/29 1p 22003 003 24X Fiche 50-220, 83/12/29, B401270019

B401160001 Forwards safety evaluation of util B20927, B30128, 0331 & 1116 submittals re Multi-plant Action Item B-4B: "Adequacy of Station Distribution Sys Voltages," & LLL technical evaluation rept Design acceptable
VASSALLO, D B Operating Reactors Branch 2 83/12/30 RHODE, G K Niagara Mohawk Power Corp 2pp 21821 300 24X Fiche 50-220, 83/12/30, B401160001

--B401160002 Safety evaluation supporting adequacy of station electric distribution sys voltages
GILL, A S Office of Nuclear Reactor Regulation, Director 83/12/20 3pp 21821 302, 24X Fiche 50-220, 83/12/30, B401160001

--B307190298 "Adequacy of Station Electric Distribution Sys Voltages for Nine Mile Point Nuclear Station, Unit 1," technical evaluation rept
SELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-19709 83/06/13 NRC - No Detailed Affiliation Given 12pp 21821 303, 24X Fiche 50-220, 83/12/30, B401160001

B401100361 Forwards revised Tech Specs 5.5 & 5.6, per B30624 ltr, re spent fuel pool capacity expansion
MANGAN, C V Niagara Mohawk Power Corp 84/01/03 VASSALLO, D B Operating Reactors Branch 2 1p 21763 355 24X Fiche 50-220, 84/01/03, B401100361

--B401100364 Revised Tech Specs 5.5 & 5.6 re storage of unirradiated spent fuel & seismic design, respectively
* Niagara Mohawk Power Corp 84/01/03 1p 21763 356 24X Fiche 50-220, 84/01/03, B401100361

B401250520 Notifies that TMI Action Items II K 3 30 & II K 3 31 re w/ small break LOCA model complete Adequacy of core cooling w/ spray distribution utilizing existing chargers currently under review
VASSALLO, D B Operating Reactors Branch 1 84/01/04 RHODE, G K Niagara Mohawk Power Corp 2pp 21948 338 24X Fiche 50-220, 84/01/04, B401250520

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of JPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401230308 Forwards application for amend to License DPR-63, revising Tech Specs to conform to SER "Application of NUREG-0737, Item II K 3 14, 'Isolation of Isolation Condensers' to Operating BHRs," per Generic Ltr 83-19
MANGAN, C V Niagara Mohawk Power Corp 84/01/05 VASSALLO, D B Operating Reactors Branch 2 1p 21883 321 24X Fiche 50-220, 84/01/05, B401230308

--B401230314 Application for amend to License DPR-63, revising Tech Specs to conform to SER "Application of NUREG-0737, Item II K 3 14, 'Isolation of Isolation Condensers' to Operating BHRs,"
MANGAN, C V Niagara Mohawk Power Corp 84/01/13 2pp 21883 322 24X Fiche 50-220, 84/01/05, B401230308

--B401230318 Proposed Tech Spec Tables 3.2.7, "RCS Isolation Valves" & 3.6.2c & 4.6.2c, "Instrumentation that Initiates or Isolates Emergency Cooling"
* Niagara Mohawk Power Corp 84/01/05 9pp 21883 324 24X Fiche 50-220, 84/01/05, B401230308

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401130067 Forwards application for amend to License DPR-63, increasing min critical power ratio limits to allow for cycle-to-cycle variations in analysis results
MANGAN, C V Niagara Mohawk Power Corp 84/01/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21802 296 24X Fiche 50-220, 84/01/09, B401130067

--B401130071 Application for amend to License DPR-63, increasing min critical power ratio limits to allow for cycle-to-cycle variations in analysis results
MANGAN, C V Niagara Mohawk Power Corp 84/01/09 2pp 21802 297 24X Fiche 50-220, 84/01/09, B401130067

--B401130074 Proposed Tech Specs, increasing min critical power ratio limits to allow for cycle-to-cycle variations in analysis results NBHC analysis encl
* Niagara Mohawk Power Corp 84/01/09 6pp 21802 299 24X Fiche 50-220, 84/01/09, B401130067

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401190365 Forwards application for amend to License DPR-63, adding Sections 3.6.12 & 4.6.12 & bases to Tech Specs, to provide for monitoring output of motor generator sets supplying power to reactor protection sys & trip buses
MANGAN, C V Niagara Mohawk Power Corp 84/01/13 VASSALLO, D B Operating Reactors Branch 2 1p 21850 147 24X Fiche 50-220, 84/01/13, B401190365

DOCKETED ITEMS

--B401190366 Application for amend to License DPR-63, adding Sections 3 & 12 & 4 & 12 & bases to Tech Specs to provide for monitoring output of motor generator sets supplying power to reactor protection sys & reactor trip buses
HANGAN, C V Niagara Mohawk Power Corp 84/01/13 1p 21850 148
24X Fiche 50-220, 84/01/13, B401190365

--B401190369 Proposed Tech Specs 3 & 12 & 4 & 12 Supporting info, amend classification & NSHC analysis encl Amend provides for monitoring output of motor generator sets supplying power to reactor protection sys & reactor trip buses
* Niagara Mohawk Power Corp 84/01/13 8pp 21850 149 24X
Fiche 50-220, 84/01/13, B401190365

B401240155 Provides list of 38 fast cold starts of diesel generator during interval from B21201-B31201 in response to Generic Ltr B3-41 Assessment indicates no significant degradation of reliability & availability as result of fast cold starts
LEMPGES, T E Niagara Mohawk Power Corp 84/01/17 EISENHUT, D G Division of Licensing 2pp 21908 352 24X Fiche 50-220, 84/01/17, B401240155

B401240185 Submits addl info providing details of mod plans to decouple screenhouse wall from reactor bldg wall by cutting expansion joint in screenhouse wall, in response to NRC request W/three oversize drawings Aperture cards are in PDR
LEMPGES, T E Niagara Mohawk Power Corp 84/01/18 VASSALLO, D B Operating Reactors Branch 2 3pp 21910 248 24X
Fiche 50-220, 84/01/18, B401240185

0 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 12pp 21731 165 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401180208 Forwards IE Insp Rept 50-220/83-28 on B31101-1212 No violations observed
STAROSTECKI, R Division of Project & Resident Programs 84/01/06 RHODE, O K Niagara Mohawk Power Corp 2pp 21844 165 24X
Fiche 50-220, 84/01/06, B401180208

--B401180211 IE Insp Rept 50-220/83-28 on B31101-1212 No violations observed Major areas inspected licensee action on previous insp findings, operational safety verification, physical security, plant tours & surveillance testing
HUDSON, S D, COLLINS, S J Region 1, Office of Director 84/01/04 11pp 21844 167 24X Fiche 50-220, 84/01/06, B401180208

B401190376 Forwards IE Safeguards Insp Rept 50-220/83-23 on B31127-1202 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/06 SUNSER, J J Niagara Mohawk Power Corp 2pp 21849 293 24X
Fiche 50-220, 84/01/06, B401190376

--B401190384 IE Safeguards Insp Rept 50-220/83-23 on B31127-1202 No noncompliance noted Major areas inspected security organization, security program audit, testing & maint, physical barriers, security sys power supply & assessment aids
DUNLAP, J M, GODY, A T Region 1, Office of Director 84/01/05 5pp 21849 295 24X Fiche 50-220, 84/01/06, B401190376

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401030121 Nonroutine rept one Aug 1983 Cladophora (algae) sample showed Co-60 concentration slightly greater than 10 times control result Caused by liquid effluents at site No corrective actions required
LEMPGES, T E Niagara Mohawk Power Corp 83/12/07 MURLEY, T E Region 1, Office of Director 2pp 21683 113 24X
Fiche 50-220, 83/12/07, B401030121

B401170007 Monthly operating rept for Dec 1983 W/B40110 ltr
ROMAN, T W, LEMPGES, T E Niagara Mohawk Power Corp 83/12/31 Director's Office, Office of Inspection and Enforcement 5pp 21834 105 24X Fiche 50-220, 83/12/31, B401170007

S Reportable occurrences, LERs & related correspondence

B401030121 Nonroutine rept one Aug 1983 Cladophora (algae) sample showed Co-60 concentration slightly greater than 10 times control result Caused by liquid effluents at site No corrective actions required
LEMPGES, T E Niagara Mohawk Power Corp 83/12/07 MURLEY, T E Region 1, Office of Director 2pp 21683 113 24X
Fiche 50-220, 83/12/07, B401030121

B401030260 Forwards LERs B3-042/03L-0 & B3-043/03L-0
LEMPGES, T E Niagara Mohawk Power Corp 83/12/09 MURLEY, T E Region 1, Office of Director 1p 21681 012 24X
Fiche 50-220, 83/12/09, B401030260

--B401030263 LER B3-042/03L-0 on B31122, fuel zone water level measuring sys (Accurex) taken out of svc to modify program to improve accuracy Accurex modified per GE recommendations & returned to svc in 1 h
SCHNEDT, A R Niagara Mohawk Power Corp 83/12/09 Region 1, Office of Director 1p 21681 013 24X Fiche 50-220, 83/12/09, B401030260

--B401030265 LER B3-043/03L-0 on B31128, fuel zone water level measuring sys (Accurex) found in "sys idle" condition for Channel 11(A) at time of planned Surveillance Procedure NI-ISP-36-1CC Cause not yet known Investigation under way
SCHNEDT, A R Niagara Mohawk Power Corp 83/12/09 Region 1, Office of Director 2pp 21681 014 24X Fiche 50-220, 83/12/09, B401030260

B401130291 Nonroutine environ operating rept on B31122, milk samples collected in Oct 1983 analyzed on 9 days instead of required 8 days Contractor & util generated specific guidance to prevent recurrence
LEMPGES, T E Niagara Mohawk Power Corp 83/12/16 MURLEY, T E Region 1, Office of Director 3pp 21801 127 24X
Fiche 50-220, 83/12/16, B401130291

B401160160 LER B3-039/03L-0 on B31202, steam electronic relief valve tail pipe temp sensors indicated loose connections on thermocouple Cause undetermined Investigation expected during next drywell entry W/B40103 ltr
SCHNEDT, A R, LEMPGES, T E Niagara Mohawk Power Corp 84/01/03 MURLEY, T E Region 1, Office of Director 3pp 21815 332 24X
Fiche 50-220, 84/01/03, B401160160

8401160168 LER 83-041/03L-0 on 831216, Accurex fuel zone water level monitoring sys experienced loss of memory on channel 12B
Caused by failure of plant process computer interface
Program reloaded into Accurex W/840103 ltr
SCHWEDT, A R , LEMPGEES, T E Niagara Mohawk Power Corp 84/01/03
MURLEY, T E Region 1, Office of Director 3pp 21815 346 24X
Fiche 50-010, 84/01/03, 8401160168

8401270133 LER 83-045/03L-0 on 831221, site operations review committee failed to review temporary change dtd 831119 re fuel handling Procedure N1-FHP-32, "Fort St Vrain Cask Handling," within 7 day Tech Spec limitation W/840118 ltr
SCHWEDT, A R , LEMPGEES, T E Niagara Mohawk Power Corp 84/01/18
MURLEY, T E Region 1, Office of Director 3pp 21982 047 24X
Fiche 50-220, 84/01/18, 8401270133

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8401230434 Forwards IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on 830920-1117 & notice of violation w/o notice of violation
NURELIUS, C E Division of Project & Resident Programs 83/12/21
REED, C Commonwealth Edison Co 2pp 21882 070 24X
Fiche 50-010, 83/12/21, 8401230434

--8401230442 IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on 830920-1117 Violation noted inadequate corrective action re normal shutdown & radiation protection procedures
WALKER, R , ANDERSON, C D , PAUL, R A Region 3, Office of Director 83/12/14 21pp 21882 072 24X Fiche 50-010, 83/12/21, 8401230434

8401040356 Informs of completed upgrading of fire protection features & significant effort to complete remaining mods necessary for strict conformance to App R, Sections III G & III L, per Generic Ltr 83-33 Exemption requests will be provided
FARRAR, D L Commonwealth Edison Co 83/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21707 141 24X
Fiche 50-000, 83/12/23, 8401040356

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation will vary at each facility
SWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, 8401030229

8401230491 Notification of 840112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed.
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874.001 24X Fiche 50-000, 84/01/05, 8401230491

8401250082 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21946 278 24X Fiche 50-010, 84/01/18, 8401250082

--8401250086 Forwards public version of revised Emergency Plan implementing procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
BCDIT, D J Commonwealth Edison Co 83/11/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21946 279 24X
Fiche 50-010, 84/01/18, 8401250082

--8401250089 Public version of revised Emergency Plan implementing procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
* Commonwealth Edison Co 83/11/02 31pp 21946 280 24X
Fiche 50-010, 84/01/18, 8401250082

8401310174 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 22035 182 24X Fiche 50-010, 84/01/20, 8401310174

--8401310180 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications.
SCOTT, D J Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22035 183 24X
Fiche 50-010, 84/01/20, 8401310174

--8401310187 Public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications
Receipt forms encl
* Commonwealth Edison Co 84/01/02 50pp 22035 185 24X
Fiche 50-010, 84/01/20, 8401310174

G Adjudicatory correspondence

8401230388 Order extending time until 840203 for Commission to act to review Director's Decision 8D-83-14 which denied requests of Sierra Club & State of OH & 831029 decision which denied request of Environ Policy Inst
CHILK, S J Office of the Secretary of the Commission 84/01/19 Commissioners 1p 21884 278 24X Fiche 50-000, 84/01/19, 8401230388

J Insurance & indemnity information

8401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 GALTZMAN, J Assistant Director for State & Licensee Relations 17pp 21865 332 24X
Fiche 50-000, 84/01/09, 8401200141

P Operating license stage documents & correspondence

8312140234 Forwards Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively & safety evaluation Amends specify reactor pressure when conducting scram testing following refueling
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 FARRAR, D C Commonwealth Edison Co 3pp 21520 029 24X Fiche 50-237, 83/12/12, 8312140234

--8312140235 Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively, specifying reactor pressure while conducting scram testing following refueling
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 8pp 21520 032 24X Fiche 50-237, 83/12/12, 8312140234

--8312140236 Safety evaluation supporting Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/12 2pp 21520 040 24X Fiche 50-237, 83/12/12, 8312140234

--8312140237 Requests FR publication of notice of issuance of Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 MILLER, J R Operating Reactors Branch 3 3pp 21520 042 24X
Fiche 50-237, 83/12/12, 8312140234

8401040329 Discusses operability of containment purge & vent valves in response to SER Detailed list of operating evolutions, procedures used to perform evolutions & containment vent & purge valves required for evolutions encl
RYBAK, B Commonwealth Edison Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 21705 061 24X
Fiche 50-000, 83/12/21, 8401040329

8401100350 Responds to concerns re SEP Topic VI-7 C 1 addressing battery charger isolation, 125-volt ac automatic transfer & standby 250-volt battery charger
RYBAK, B Commonwealth Edison Co 83/12/30 QILBERT, R Operating Reactors Branch 5 14pp 21763 297 24X Fiche 50-237, 83/12/30, 8401100350

8401180232 Forwards response to three listed concerns of SEP Topic VI-7 C 1 re electrical instrumentation & control sys Single EH100 breaker failure will not cause loss of redundant dc divs Exhibits encl
RYBAK, B Commonwealth Edison Co 83/12/30 QILBERT, R Operating Reactors Branch 5 14pp 21843 328 24X Fiche 50-237, 83/12/30, 8401180232

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

DOCKETED ITEMS

- B401060150 List of SAMP results during 1982
 * Director's Office, Office of Inspection and Enforcement
 83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20,
 8401060040
- B401040533 Supply response to IE Bulletin 83-04 re nonconforming mats
 supplied by Tube-Line Corp. Training held to emphasize review
 of purchase documents re receipt, insp & visual item
 verification per purchase order requirements
 BARNES, P. L. Commonwealth Edison Co 83/12/20 KEPLER, J. G. Region
 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20,
 8401040533
- B401230434 Forwards IE Insp Repts 50-010/83-19, 50-237/83-29 &
 50-249/83-27 on B30920-1117 & notice of violation w/o
 notice of violation
 MORELUS, C. E. Division of Project & Resident Programs 83/12/21
 REED, C. Commonwealth Edison Co 2pp 21882 070 24X
 Fiche 50-010, 83/12/21, 8401230434
- B401230442 IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on
 B30920-1117 Violation noted inadequate corrective action
 re normal shutdown & radiation protection procedures
 WALKER, R. TONGUE, T. M., STASEK, S. Region 3, Office of Director
 83/12/14 21pp 21882 072 24X Fiche 50-010, 83/12/21, 8401230434
- B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
 W/Undervoltage Trip Feature in Use in Safety-Related
 Applications Other Than Reactor Trip Sys." Svc list encl
 DEYOUNG, R. C. Director's Office, Office of Inspection and
 Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
 Brown Boveri Electric Type 3HK Breakers." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/12/30 Consolidated Edison Co. of New
 York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093
- B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
 Voltage Levels Lower Than Analyzed." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/10 Consolidated Edison Co. of New
 York, Inc 123pp 21746 053 24X Fiche 50-000, 84/01/10, 8312120104
- B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
 Sheaths." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/10 Consolidated Edison Co. of New
 York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107
- B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/16 Consolidated Edison Co. of New
 York, Inc 127pp 21757 142 24X Fiche 50-000, 84/01/16, 8312120114
- B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
 Notification of Disability by Licensed Operators." Svc list
 encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
 York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116
- B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
 Valves Used Only During Cold Shutdowns." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
 York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- B401250013 Responds to NRC B31118 ltr re violation noted in IE Insp
 Rept 50-237/83-17 on B30606-0908 Safety significance of
 failure of shaft arm seals for torus-to-drywell vacuum
 breakers does not warrant Severity Level III civil penalty
 REED, C. Commonwealth Edison Co 84/01/20 DEYOUNG, R. C. Director's
 Office, Office of Inspection and Enforcement 9pp 21935 216 24X
 Fiche 50-237, 84/01/20, 8401250013
- R Periodic operating reports & related correspondence
- B401160144 Monthly operating repts for Dec 1983 W/B40103 ltr
 SCHROEDER, B. A., SCOTT, D. J. Commonwealth Edison Co 83/12/31
 Director's Office, Office of Inspection and Enforcement 16pp
 21814 320 24X Fiche 50-237, 83/12/31, 8401160144
- S Reportable occurrences, LERs & related correspondence
- B401050064 FOIA request for 27 listed LERs
 GRABER, L. D. NUS Corp 83/10/07 Division of Rules and Records
 2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050064
- B401160309 Documents applicability of SEP Topic III-6, "Analytical
 Techniques, Models & Seismic Evaluation of Electrical Raceway
 Sys." submitted by owners group Cable tray/conduit raceway
 program complete Sys satisfactory
 RYBAK, B. Commonwealth Edison Co 84/01/09 GILBERT, R. Assistant
 Director for Operating Reactors 1p 21814 336 24X
 Fiche 50-237, 84/01/09, 8401160309
- B401170339 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel
 Generators." Prelubrication w/some warming provided,
 therefore, generators not subjected to cold starts
 BARNES, P. L. Commonwealth Edison Co 84/01/10 EISENHUT, D. G.
 Division of Licensing 1p 21829 341 24X Fiche 50-000, 84/01/10,
 8401170339
- B401160064 Notification of 840131-0203 meetings w/util in Morris, IL to
 conduct in-progress audit of detailed control room
 design rept
 GILBERT, R. A. Operating Reactors Branch 5 84/01/12 CRUTCHFIELD, D.
 Operating Reactors Branch 5 3pp 21821 214 24X
 Fiche 50-237, 84/01/12, 8401160064
- B401160216 Requests provision of listed info to assist in-progress
 audit of detailed control room design review on 840131-0203
 CRUTCHFIELD, D. Operating Reactors Branch 5 84/01/12 FARRAR, D. L.
 Commonwealth Edison Co 3pp 21813 103 24X Fiche 50-237, 84/01/12,
 8401160216
- B401230327 Forwards draft radiological effluent Tech Specs as committed
 to on B30928 for comment
 RYBAK, B. Commonwealth Edison Co 84/01/12 DENTON, H. R. Office of
 Nuclear Reactor Regulation, Director 3pp 21883 001 24X
 Fiche 50-237, 84/01/12, 8401230327
- B401230332 Draft Tech Spec amend (RETS) to License DPR-19
 * Commonwealth Edison Co 84/01/12 142pp 21883 003 24X
 Fiche 50-237, 84/01/12, 8401230327
- B401250464 Notifies that 831212 ltr forwarding amend to Licenses DPR-19
 & DPR-25 reflects incorrect amend numbers Amend 79 should
 be changed to 7B & Amend 6B to 69
 SMITH, H. Operating Reactors Branch 5 84/01/12 BAILEY, I. Record
 Services Branch (Document Control Desk) 2pp 21948 360 24X
 Fiche 50-237, 84/01/12, 8401250464
- B401130084 Generic Ltr 84-03 to all licensees of operating reactors,
 applicants for OLs & holders of CPs re availability of
 NUREG-0933, "Prioritization of Generic Safety Issues."
 Svc list encl
 EISENHUT, D. G. Division of Licensing 84/01/13 Consolidated
 Edison Co. of New York, Inc 18pp 21946 174 24X
 Fiche 50-000, 84/01/13, 8401130084
- B401200098 Notification of 840126 meeting w/util in Bethesda, MD to
 perform equipment environ qualification review for
 facilities
 GILBERT, R. A. Operating Reactors Branch 5 84/01/19 CRUTCHFIELD, D.
 Operating Reactors Branch 5 3pp 21866 350 24X
 Fiche 50-000, 84/01/19, 8401200098
- B401250040 Informs of completed review of BWR Owners Group 801230
 response to NUREG-0737, Item II K 3 45, "Depressurization
 W/Other Than Automatic Depressurization Sys." Alternative
 modes of depressurization would not contribute to safety
 CRUTCHFIELD, D. Operating Reactors Branch 5 84/01/23 FARRAR, D. L.
 Commonwealth Edison Co 6pp 21935 240 24X Fiche 50-237, 84/01/23,
 8401250040
- B401250179 Provides review of TMI Items II K 3 30 & II K 3 31 re small
 break LOCA analysis & compliance w/10CFR50 46, App K Based on
 extensive discussions, requirements met
 CRUTCHFIELD, D. Operating Reactors Branch 5 84/01/23 FARRAR, D. L.
 Commonwealth Edison Co 2pp 21935 214 24X Fiche 50-237, 84/01/23,
 8401250179
- B401260013 Forwards safety evaluation of util 831230 response to SEP
 Topic VI-7 C 1, "Electrical Instrumentation & Control
 Reviews," in NUREG-0823, Section 4 21 Adequate relay
 coordination exists
 CRUTCHFIELD, D. Operating Reactors Branch 5 84/01/24 FARRAR, D.
 Commonwealth Edison Co 3pp 21956 294 24X Fiche 50-237, 84/01/24,
 8401260013
- G Inspection reports, IE Bulletins & correspondence
- B401060040 Responds to FOIA request for IE tabulation of SAMP results
 during 1982 Forwards IE notebook tabulating requested info
 Notebook also available in PDR
 FELTON, J. M. Division of Rules and Records 83/10/20 ZAHNER, R. E.
 Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
 Fiche 50-000, 83/10/20, 8401060040

DOCKETED ITEMS

35

B401230002 LER 83-079/03L-0 on 831118, scheduled pumpdown of drywell floor drain sump delayed approx 2 h due to maint work on drywell floor drain transmitter to correct continuous running of integrator Transmitter replaced W/831214 ltr
TURNQUEST, L, SCOTT, D J Commonwealth Edison Co 83/12/14
KEPPLER, J G Region 3, Office of Director 3pp 21884 337 24X
Fiche 50-237, 83/12/14, B401230002

B401230010 LER 83-077/03L-0 on 831119, scheduled pumpdown of drywell floor drain sump delayed due to addl maint work on drywell floor drain transmitter to correct excessive noise problem Transmitter replaced W/831214 ltr
TURNQUEST, L, SCOTT, D J Commonwealth Edison Co 83/12/14
KEPPLER, J G Region 3, Office of Director 3pp 21884 300 24X
Fiche 50-237, 83/12/14, B401230010

B401040397 LER 83-080/03L-0 on 831124, offgas log radiation monitor 2-1703-A delivered offgas hi-hi alarm & hi alarm, spiked & drifted downscale Caused by offgas monitor power supply failure Root cause unknown W/831220 ltr
WOUTULEWICZ, T, SCOTT, D J Commonwealth Edison Co 83/12/20
KEPPLER, J G Region 3, Office of Director 3pp 21708 100 24X
Fiche 50-237, 83/12/20, B401040397

B401100458 Updated LER 83-075/03X-1 on 831118, drywell floor drain sump pumpdown not performed Caused by elevated dc signal from excessive noise Amplifier replaced & transmitter R D 83-87 replaced W/831223 ltr
TURNQUEST, L, SCOTT, D J Commonwealth Edison Co 83/12/23
KEPPLER, J G Region 3, Office of Director 3pp 21761 338 24X
Fiche 50-237, 83/12/23, B401100458

B401050632 Discusses 831209 uncoupling of trailer containing spent fuel assemblies uncoupled from tractor Cause unknown No damage to tractor, trailer, tank, or any other vehicle incurred Pull test performed successfully
SCOTT, D J Commonwealth Edison Co 83/12/28
KEPPLER, J G Region 3, Office of Director 20pp 21726 083 24X Fiche 50-010, 83/12/28, B401050632

B401130043 Updated LER 83-078/03X-1 on 831121, while preparing to lower suppression pool level, valve LPCJ 1501-3A failed to open remotely Caused by potentiometer in valve control circuitry drifting out of adjustment Device readjusted W/840103 ltr
SCOTT, D J, CHRISTEL, B Commonwealth Edison Co 84/01/03
KEPPLER, J G Region 3, Office of Director 3pp 21802 339 24X
Fiche 50-237, 84/01/03, B401130043

B401130184 Updated LER 83-077/03X-1 on 830119, addl maint work on drywell floor drain transmitter prevented 1.200 pumpdown of drywell floor drain sump Entire transmitter replaced W/840103 ltr
TURNQUEST, L, SCOTT, D J Commonwealth Edison Co 84/01/03
KEPPLER, J G Region 3, Office of Director 3pp 21802 027 24X
Fiche 50-237, 84/01/03, B401130184

B401130185 Updated LER 83-076/03X-1 on 831119, unidentified drywell leakage calculated to be 3.08 gpm Caused by cut in seal ring seating on feedwater check valve body Cut silver-soldered & new seal ring installed W/840103 ltr
TURNQUEST, L, SCOTT, D J Commonwealth Edison Co 84/01/03
KEPPLER, J G Region 3, Office of Director 3pp 21802 035 24X
Fiche 50-237, 84/01/03, B401130185

B401130234 LER 83-081/03L-0 on 831210, west side torus bulkhead door found open Caused by contractor in area Operator immediately closed & locked door, station dept heads reminded to inform personnel & memo issued W/840103 ltr
ANANDAPPA, A, SCOTT, D J Commonwealth Edison Co 84/01/03
KEPPLER, J G Region 3, Office of Director 2pp 21801 222 24X
Fiche 50-237, 84/01/03, B401130234

B401160161 PNO-III-B4-004, on 840109, reactor operator omitted 20 steps in rod insertion procedure during shutdown process Procedure indicated slash when control rod inserted & operator interpreted slash as omission of step No fuel damage noted
MADISON, A, WALKER, R Region 3, Office of Director, 84/01/10 1p
21813 345, 24X Fiche 50-237, 84/01/10, B401160161

B401160293 Confirmatory action ltr re 840109 improper insertion of control rods Prior to startup from hot standby, qualified nuclear engineer will be required in control room during control rod evolution & training sessions will be conducted
KEPPLER, J G Region 3, Office of Director 84/01/10 REED, C Commonwealth Edison Co 2pp 21813 361 24X Fiche 50-237, 84/01/10, B401160293

B401270357 LER 83-082/03L-0 on 831225, while performing weekly & daily turbine checks during normal operation, control valve 4 failed to give half-acram when tested Probably caused by failed test switch CVTS-A Recorder installed W/840123 ltr
BERGAN, O W, SCOTT, D J Commonwealth Edison Co 84/01/23
KEPPLER, J G Region 3, Office of Director 2pp 21976 043 24X
Fiche 50-237, 84/01/23, B401270357

B401300281 LER 83-083/03L-0 on 831226, while lowering suppression pool level, LPC1 1501-3B valve tripped thermally Caused by underrated overload heaters (GE CR 123 L1 74A) in valve motor overload assembly Heaters replaced W/840124 ltr
CHRISTEL, B, SCOTT, D J Commonwealth Edison Co 84/01/24
KEPPLER, J G Region 3, Office of Director 3pp 21997 317 24X
Fiche 50-237, 84/01/24, B401300281

DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B401100314 Responds to NRC request for info re Generic Ltr 83-41 TRIGA reactor does not use diesel powered generators in emergency power sys
WANG, C H Oregon State Univ, Corvallis, OR 84/01/03
EISENHUT, D G Division of Licensing 1p 21759 165 24X
Fiche 50-243, 84/01/03, B401100314

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B401040174 Forwards application for exemption from scheduler requirements of 10CFR50.48 for alternative shutdown sys required by 10CFR50, App R
MAIER, J E Rochester Gas & Electric Corp 83/12/27 CRUTCHFIELD, D
Operating Reactors Branch 5 13pp 21702 021 24X
Fiche 50-244, 83/12/27, B401040174

B401060074 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21747 327 24X Fiche 50-244, 83/12/28, B401060074

--B401060077 Public version of revised emergency plan implementing procedures, including Procedures SC-212 re site evacuation, SC-213 re accountability of personnel & SC-240 re protective action recommendations
* Rochester Gas & Electric Corp 83/11/16 100pp 21747 328
24X Fiche 50-244, 83/12/28, B401060074

B401250104 Forwards "App R Alternative Shutdown Sys " New shutdown approach provides fewer rods & allows phased implementation as opposed to installation of required dedicated shutdown sys
MAIER, J E Rochester Gas & Electric Corp 84/01/16 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 21933 341 24X
Fiche 50-244, 84/01/16, B401250104

--B401250109 "App R Alternative Shutdown Sys "
* Rochester Gas & Electric Corp 83/12/31 376pp 21933 343
24X Fiche 50-244, 84/01/16, B401250104

B401250091 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21946 264 24X Fiche 50-244, 84/01/18, B401250091

--B401250095 Forwards public version of Revs 7 & 8 to Emergency Plan Implementing Procedure SC-5, "Earthquake Emergency Plan" & Rev 3 to Procedure SC-100, "Ginna Station Event Evaluation Classification"
MAIER, J E Rochester Gas & Electric Corp 83/11/10 MURLEY, T E
Region 1, Office of Director 1p 21946 265 24X
Fiche 50-244, 84/01/18, B401250091

--B401250100 Public version of Revs 7 & 8 to Emergency Plan Implementing Procedures SC-5, "Earthquake Emergency Plan" & Rev 3 to Procedure SC-100, "Ginna Station Event Evaluation Classification"
SPECTER, S M Rochester Gas & Electric Corp 83/11/09 12pp
21946 266 24X Fiche 50-244, 84/01/18, B401250091

B401310170 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22037 197 24X Fiche 50-244, 84/01/20, B401310170

--B401310212 Forwards public version of revised emergency plan implementing procedures, including Procedures SC-410 re insp of emergency equipment, SC-442 re monitoring site radiation level & SC-600 re emergency plan qualification
MAIER, J E Rochester Gas & Electric Corp 84/01/11 MURLEY, T E
Region 1, Office of Director 1p 22037 198 24X
Fiche 50-244, 84/01/20, B401310170

DOCKETED ITEMS

--B401310249 Public version of revised emergency plan implementing procedures, including Procedures SC-410 re insp of emergency equipment, SC-442 re monitoring site radiation level & SC-600 re emergency plan qualification
SPECTER, S M Rochester Gas & Electric Corp 84/01/11 30pp
22037 200 24X Fiche 50-244, 84/01/20, 8401310170

G Adjudicatory correspondence

B401580261 Requests ASLB issue order indicating that State of NY, party to proceeding & not required to file addl petition for leave to intervene if request denied, submittal should be considered as petition to intervene as interested state
FROMER, H A New York, State of, Energy Office 83/01/10
GROSSMAN, H Atomic Safety and Licensing Board Panel 2pp
21843 316 24X Fiche 50-244, 83/01/10, 8401580261

--B401580265 Petition of State of NY for leave to intervene & request for hearing
MACDONALD, J D New York, State of, Atomic Energy Council
73/01/05 Commissioners 2pp 21843 318 24X
Fiche 50-244, 83/01/10, 8401580261

B401170218 Memorandum reaffirming participation of State of NY in proceeding
GROSSMAN, H Atomic Safety and Licensing Board Panel 84/01/13
2pp 21833 292 24X Fiche 50-244, 84/01/13, 8401170218

H General correspondence

B401300132 Advises that effective 840201, HG Saddock elected executive vice president, finance & rates, JE Maier elected senior Vice President, Operations & Engineering & RW Kober elected Vice President, Electric & Steam production
MAIER, J E Rochester Gas & Electric Corp 84/01/23 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 21998 287 24X
Fiche 50-244, 84/01/23, 8401300132

P Operating license stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015

--B204060204 Informs Commission of current status of steam generator insp & repairs following B20125 steam generator tube rupture at facility
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-134 82/03/31 3pp 21962 259 24X
Fiche 50-000, 83/10/18, 8401250015

--B206110164 Informs Commission that review of B20125 steam generator tube rupture event completed & permission to restart facility granted
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-206 82/05/21 3pp 21964 232 24X
Fiche 50-000, 83/10/18, 8401250015

--B211020259 Informs Commission of results of SEP integrated safety assessment
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-403 82/10/01 11pp 21966 272 24X
Fiche 50-000, 83/10/18, 8401250015

B401040346 Forwards application for amend to License DPR-18, allowing insertion of 14x14 optimized fuel assembly design for Cycle 14 reload
MAIER, J E Rochester Gas & Electric Corp 83/12/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21704 001 24X
Fiche 50-244, 83/12/20, 8401040346

--B401040348 Application for amend to License DPR-18, allowing insertion of 14x14 optimized fuel assembly design for Cycle 14 reload
MAIER, J E Rochester Gas & Electric Corp 83/12/20 3pp
21704 002 24X Fiche 50-244, 83/12/20, 8401040346

--B401040350 Proposed Tech Spec allowing insertion of 14x14 optimized fuel assembly design for Cycle 14 reload
* Rochester Gas & Electric Corp 83/12/20 339pp 21704 005
24X Fiche 50-244, 83/12/20, 8401040346

B401040137 Responds to Generic Ltr 83-10D, "Automatic Trip of Reactor Coolant Pumps" Partial response submitted w/Westinghouse Owners Group 831201 ltr Generic rept justifying manual reactor coolant pump trip will be submitted by 840301
MAIER, J E Rochester Gas & Electric Corp 83/12/21 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 21702 076 24X
Fiche 50-244, 83/12/21, 8401040137

B401040513 Rev O to "Process Control Program" W/831227 ltr
*, MAIER, J E Rochester Gas & Electric Corp 83/12/27
CRUTCHFIELD, D Operating Reactors Branch 5 8pp 21706 001 24X
Fiche 50-244, 83/12/27, 8401040513

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

B401100356 Responds to B31216 ltr re fast cold starts of diesel generators Diesel generators originally supplied w/water jacket heaters & lube oil heating/recirculating sys Fast cold starts for unit will not meet start-load time criteria
MAIER, J E Rochester Gas & Electric Corp 84/01/06 EISENHUT, D G
Division of Licensing 1p 21764 105 24X Fiche 50-244, 84/01/06, 8401100356

B401170152 Forwards "Seismic Structural Evaluation of Main Control Board," documenting testing/analysis requested by NRC during review of SEP Topic III-6, "Seismic Considerations"
MAIER, J E Rochester Gas & Electric Corp 84/01/09 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 21834 001 24X
Fiche 50-244, 84/01/09, 8401170152

--B401170153 "Seismic Structural Evaluation of Main Control Board"
* URS Corp * John A Blume & Associates, Engineers (subs of URS Corp) URS/JAB B319 83/11/22 85pp 21834 002 24X
Fiche 50-244, 84/01/09, 8401170152

B401170009 Submits general plan to identify & resolve outstanding plant-specific issues re Suppl 1 to NUREG-0821, "Cable Tray Seismic Evaluation" Final schedule will be established after progress toward resolution of NRC questions occurs
MAIER, J E Rochester Gas & Electric Corp 84/01/10 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 21834 103 24X
Fiche 50-244, 84/01/10, 8401170009

B401230227 Advises that Guidelines 1.2.5 & 6 of NUREG-0612 re control of heavy loads fully implemented
MAIER, J E Rochester Gas & Electric Corp 84/01/11 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 21884 079 24X
Fiche 50-244, 84/01/11, 8401230227

B401130084 Generic Ltr 84-02 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401200115 Forwards safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads"
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/18 MAIER, J E
Rochester Gas & Electric Corp 2pp 21863 251 24X
Fiche 50-244, 84/01/18, 8401200115

--B401200121 Safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads"
* Office of Nuclear Reactor Regulation, Director 84/01/18 3pp
21863 253 24X Fiche 50-244, 84/01/18, 8401200115

--B312060347 "Control of Heavy Loads C-10, RE Ginna Nuclear Power Plant," technical evaluation rept
VOSEBURY, F W, BDMBERGER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5306-357 83/12/02 SINGH, A, CHAN, T NRC - No Detailed Affiliation Given 30pp 21863 256
24X Fiche 50-244, 84/01/18, 8401200115

B401250287 Forwards application for amend to License DPR-18, changing Tech Specs to delete restriction on movement of spent fuel shipping casks w/auxiliary bldg crane
MAIER, J E Rochester Gas & Electric Corp 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21943 228 24X
Fiche 50-244, 84/01/18, 8401250287

--B401250292 Application for amend to License DPR-18, changing Tech Specs to delete restriction on movement of spent fuel shipping casks w/auxiliary bldg crane
MAIER, J E Rochester Gas & Electric Corp 84/01/18 2pp
21943 229 24X Fiche 50-244, 84/01/18, 8401250287

--B401250293 Proposed Tech Spec changes deleting restriction on movement of spent fuel shipping casks w/auxiliary bldg crane
* Rochester Gas & Electric Corp 84/01/18 5pp 21943 231 24X
Fiche 50-244,84/01/18,8401250287

B401250297 Forwards application for amend to License DPR-18, changing Tech Specs to delete restrictions on spacing of recently discharged fuel in spent fuel storage racks
MAIER, J E Rochester Gas & Electric Corp 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21943 196 24X
Fiche 50-244,84/01/18,8401250297

--B401250299 Application for amend to License DPR-18, changing Tech Specs to delete restrictions on spacing of recently discharged fuel in spent fuel storage racks
MAIER, J E Rochester Gas & Electric Corp 84/01/18 2pp
21943 197 24X Fiche 50-244,84/01/18,8401250297

--B401250301 Proposed Tech Spec changes re spacing of recently discharged fuel in spent fuel storage racks
* Rochester Gas & Electric Corp 84/01/18 6pp 21943 199 24X
Fiche 50-244,84/01/18,8401250297

--B401250303 "Tornado Missile Accident Analysis for Spent Fuel Storage Racks for Rochester Gas & Electric"
WAITE, H H, WACHTER, W J, LINDER, R U S Tool & Die, Inc
8367-00-0005 83/10/04 18pp 21943 205 24X
Fiche 50-244,84/01/18,8401250297

B401250260 Forwards application for amend to License DPR-18, reducing requirement for low pressurizer water level from 12 to 10 6% & changing P-10 permissive from 10 to 8% power
MAIER, J E Rochester Gas & Electric Corp 84/01/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21943 238 24X
Fiche 50-244,84/01/19,8401250260

--B401250275 Application for amend to License DPR-18, reducing requirement for low pressurizer water level from 12 to 10 6% & changing P-10 permissive from 10 to 8% power
MAIER, J E Rochester Gas & Electric Corp 84/01/19 2pp
21943 239 24X Fiche 50-244,84/01/19,8401250260

--B401250282 Proposed Tech Specs reducing requirement for low pressurizer water level from 12 to 10 6% & changing P-10 permissive from 10 to 8% power
* Rochester Gas & Electric Corp 84/01/19 7pp 21943 241 24X
Fiche 50-244,84/01/19,8401250260

B401250016 Forwards application to amend License DPR-18, revising Tech Specs to reflect changes in mgt & correct omission in Amend 5B See encl
MAIER, J E Rochester Gas & Electric Corp 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21937 110 24X
Fiche 50-244,84/01/20,8401250016

--B401250019 Application to amend License DPR-18, revising Tech Specs to reflect changes in util mgt & correct omission in Amend 5B
MAIER, J E Rochester Gas & Electric Corp 84/01/20 3pp
21937 111 24X Fiche 50-244,84/01/20,8401250016

--B401250021 Proposed Tech Specs reflecting changes in util mgt & correcting omission in Amend 5B
* Rochester Gas & Electric Corp 84/01/20 4pp 21937 114 24X
Fiche 50-244,84/01/20,8401250016

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731,166 24X Fiche 50-000,83/12/28,8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 033 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

B401170356 Ack receipt of B31221 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/83-22
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
MAIER, J E Rochester Gas & Electric Corp 2pp 21828 274 24X
Fiche 50-244,84/01/10,8401170356

--B401170362 Responds to NRC B31121 ltr re violations noted in IE Insp Rept 50-244/83-22 Corrective actions Procedure S-14 i, "Radiation Monitoring-Related Sys Daily Plot Requirements" modified to include plot of vent header pressure
MAIER, J E Rochester Gas & Electric Corp 83/12/21 MURLEY, T E
Region 1, Office of Director 2pp 21828 276 24X
Fiche 50-244,84/01/10,8401170356

B401300270 Forwards IE Insp Rept 50-244/83-26 on B31212-16 No violation noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/13
MAIER, J E Rochester Gas & Electric Corp 2pp 21996 281 24X
Fiche 50-244,84/01/13,8401300270

--B401300274 IE Insp Rept 50-244/83-24 on B31212-16 No violation noted
Major areas inspected previous insp findings, licensed operator training & requalification training, general employee plant training & nonlicensed technical training
BISSETT, P, CAPTON, D L Region 1, Office of Director 84/01/11
7pp 21996 283 24X Fiche 50-244,84/01/13,8401300270

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

B401120411 Monthly operating rept for Nov 1983 W/B31207 ltr
MCNAMARA, A E, SNOW, D A Rochester Gas & Electric Corp 83/11/30
NRC - No Detailed Affiliation Given 6pp 21791 147 24X
Fiche 50-244,83/11/30,8401120411

B401270292 Monthly operating rept for Dec 1983 W/B40109 ltr
MCNAMARA, A E, SNOW, D A Rochester Gas & Electric Corp 83/12/31
Office of Resource Management, Director 6pp 21776 001 24X
Fiche 50-244,83/12/31,8401270292

V Operator Examinations

B401300270 Forwards IE Insp Rept 50-244/83-26 on B31212-16 No violation noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/13
MAIER, J E Rochester Gas & Electric Corp 2pp 21996 281 24X
Fiche 50-244,84/01/13,8401300270

--B401300274 IE Insp Rept 50-244/83-24 on B31212-16 No violation noted
Major areas inspected previous insp findings, licensed operator training & requalification training, general employee plant training & nonlicensed technical training
BISSETT, P, CAPTON, D L Region 1, Office of Director 84/01/11
7pp 21996 283 24X Fiche 50-244,84/01/13,8401300270

DOCKETED ITEMS

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Toubridge 6pp 21937 337 24X
Fiche 50-000, 83/11/02, 8401250163

--8305260352 Urges discussion on licensee disregard for NRC guidance re location of permanent & backup emergency operations facilities per W Dircks 821227 memo Requests explanation re Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners 83/01/05 Commissioners 2pp 21958 001 24X Fiche 50-000, 83/11/02, 8401250163

--8305260362 Responds to Commissioner Gilinsky 830106 comments on 821227 memo re implementation of emergency response facilities guidance Requested explanations re Waterford, San Onofre & Millstone plans provided
DIRCKS, W J Office of the Executive Director for Operations 83/02/15 PALLADINO, N Commissioners 2pp 21958 303 24X
Fiche 50-000, 83/11/02, 8401250163

8401090132 Forwards status of current plans for implementation of provisions of Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability," transmitted by Generic Ltr 82-33
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/11/28 EISENHUT, D G Division of Licensing 23pp 21749 170 24X Fiche 50-000, 83/11/28, 8401090132

8312300205 Forwards list of dates acceptable to util per conformity orders re integrated implementation schedules for Suppl 1 to NUREG-0737, Generic Ltr 82-33, "Requirements for Emergency Response Capability"
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/12/20 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 21673 114 24X Fiche 50-000, 83/12/20, 8312300205

8401180237 Forwards IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/03 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21842 339 24X Fiche 50-245, 84/01/03, 8401180237

--8401180249 IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted Major areas inspected evaluations of plant operations, equipment alignments & readiness, radiation protection, physical security & fire protection
LIPINSKI, D R Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs 83/12/20 14pp 21842 341 24X Fiche 50-245, 84/01/03, 8401180237

8401180204 Forwards Rev 2 to sustainability, training & qualification plan Rev withheld (ref 10CFR73.21 & 2.790)
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 84/01/10 MURLEY, T E Region 1, Office of Director 1p 21842 360 24X
Fiche 50-245, 84/01/10, 8401180204

8401180266 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/10 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21843 249 24X Fiche 50-245, 84/01/10, 8401180266

--8401180270 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23 Corrective actions withheld (ref 10CFR73.21)
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/12/06 MARTIN, T T Division of Engineering & Technical Programs 2pp 21843 251 24X Fiche 50-245, 84/01/10, 8401180266

8401260320 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21989 359 24X Fiche 50-245, 84/01/20, 8401260320

--8401260324 Public version of Change 2 to Rev 4 to Emergency Plan Implementing Procedure OP 2501, "Incident Assessment & Classification - Unit 2" W/831229 ltr
COUNCIL, W G DPEKA, J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/22 EISENHUT, D G Division of Licensing 2pp 21989 360 24X Fiche 50-245, 84/01/20, 8401260320

J Insurance & indemnity information

8401130130 Forwards Endorsement 5 to NELIA Certificates N-15 & N-16 & Endorsement 5 to MAELU Certificates M-15 & M-16
SHINIS, J M Marsh & McLennan, Inc 83/12/27 SALTZMAN, J D Assistant Director for State & Licensee Relations 5pp 21802 237 24X Fiche 50-000, 83/12/27, 8401130130

8401230477 Forwards Endorsements 90 & 91 to NELIA Policy NF-173 & Endorsements 81 & 82 to MAELU Policy MF-52
SHINIS, J M Marsh & McLennan, Inc 84/01/12 SALTZMAN, J D Assistant Director for State & Licensee Relations 5pp 21882 153 24X Fiche 50-000, 84/01/12, 8401230477

P Operating license stage documents & correspondence

8401040086 Rationalizes delay of 810430 completion date for mods to diesel generator protective trips Major portion of mods completed during 1982 refueling outage In-depth investigation underway
COUNCIL, W G DPEKA, J F Northeast Nuclear Energy Co (subs of Northeast Utilities) DPEKA, J F Northeast Utilities 83/12/15 CRUTCHFIELD, D Operating Reactors Branch 3 2pp 21702 361 24X
Fiche 50-245, 83/12/15, 8401040086

8401100333 Application for amend to License DPR-21, changing Tech Specs re reactor coolant chemistry limits to be consistent w/STS & Rev 1 to Reg Guide 1.56 Change constitutes resolution of SEP Topic V-12 A
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 83/12/28 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 21764 117 24X
Fiche 50-245, 83/12/28, 8401100333

--8401100338 Proposed Tech Specs changing reactor coolant chemistry limits to be consistent w/STS & Rev 1 to Reg Guide 1.56
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/28 6pp 21764 121 24X Fiche 50-245, 83/12/28, 8401100333

8401100392 Discusses integrated assessment of regulatory requirements, per util 830613 & 0914 & NRC 831005 ltrs Scheduler relief from requirements identified in Encls 1 & 3 requested by 840120 Issues to be included in expanded assessment encl
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/12/28 EISENHUT, D G Division of Licensing 97pp 21762 297 24X Fiche 50-000, 83/12/28, 8401100392

8401030364 THE EFFECT OF RESOLUTION OF THE MILLSTONE POINT UNIT 1 SYSTEMATIC EVALUATION PROGRAM ISSUES ON PROBABILISTIC CALCULATIONS OF RISK
SPULAK, R G, STACK, D Sandia Laboratories AMICO, P J Science Applications, Inc FIN A-1300 NUREG/CR-3233 83/12/31 Division of Safety Technology 94pp Available at NRC \$4 50 21685 256 24X Fiche 50-245, 83/12/31, 8401030364

840110184 Authorizes refund of review fee re 831101 application for Tech Spec changes covering coolant leakage monitoring
MILLER, W G License Fee Management Branch 84/01/03 COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21794 358 24X Fiche 50-245, 84/01/03, 840110184

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401200164 Forwards revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual" W/o encl
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities Service Co (subs of Northeast Utilities) 84/01/09 EISENHUT, D G Division of Licensing 2pp 21866 341 24X Fiche 50-000, 84/01/09, 8401200164

DOCKETED ITEMS

39

8401180237 Forwards IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21842 339 24X Fiche 50-245, 84/01/03, 8401180237

--8401180249 IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted Major areas inspected evaluations of plant operations, equipment alignments & readiness, radiation protection, physical security & fire protection
LIPINSKI, D R Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs 83/12/30 14pp 21842 341 24X Fiche 50-245, 84/01/03, 8401180237

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401180266 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21843 249 24X Fiche 50-245, 84/01/10, 8401180266

--8401180270 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23 Corrective actions withheld (ref 10CFR73.21)
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/06
MARTIN, T T Division of Engineering & Technical Programs 2pp 21843 251 24X Fiche 50-245, 84/01/10, 8401180266

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Beated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120203 Monthly operating rept for Nov 1983 W/831209 ltr
HARRAN, G , MROCKZA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKZA, E J Northeast Utilities 83/11/30
NRC - No Detailed Affiliation Given 7pp 21792 241 24X Fiche 50-245, 83/11/30, 8401120203

8401270442 Monthly operating rept for Dec 1983 W/840109 ltr
HARRAN, G , MROCKZA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKZA, E J Northeast Utilities 83/12/31
Office of Resource Management, Director 3pp 21980 351 24X Fiche 50-245, 83/12/31, 8401270442

S Reportable occurrences, LERs & related correspondence

8401040178 LER 83-032/03L-0 on 831125, while performing shutdown due to failed seal on reactor recirculation pump A, calculated unidentified leak rate above Tech Spec limits Caused by failed seal carbon rings New seal installed W/831225 ltr
THULL, T , MROCKZA, E J Northeast Utilities MROCKZA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/25
MURLEY, T E Region 1, Office of Director 3pp 21702 100 24X Fiche 50-245, 83/12/25, 8401040178

8401040158 LER 83-033/03L-0 on 831126, standby gas treatment train B 5-kW heater would not energize Caused by misplaced screw in OE relay 11T-15RCBXB Screw reinstalled W/831226 ltr
THULL, T S , MROCKZA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKZA, E J Northeast Utilities Service Co (subs of Northeast Utilities) 83/12/26
MURLEY, T E Region 1, Office of Director 3pp 21702 095, 24X Fiche 50-245, 83/12/26, 8401040158

8401230178 Informs that equipment installed in fulfillment of NUREG-0737, Items II F 1.1 & II F 1.2 declared operational in mid-Dec 1983 Tech Specs required by Generic Ltr 83-37 being prepared
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/01/10
CRUTCHFIELD, D Operating Reactors Branch 5 MILLER, J R Operating Reactors Branch 3 2pp 21884 174 24X Fiche 50-245, 84/01/10, 8401230178

8401160088 Notification of 840118-20 & 23-26 meetings w/util & BNL at plant sites to collect data on high radiation exposure job
SHEA, J J Operating Reactors Branch 5 84/01/11
CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21815 062 24X Fiche 50-000, 84/01/11, 8401160088

8401230373 Forwards SEP evaluation completion schedules for integrated plant safety assessment repts (NUREG-0826 & NUREG-0824), in response to NRC 831006 ltr
COUNSIL, W G , SEARS, C F Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/01/11
CRUTCHFIELD, D Operating Reactors Branch 5 8pp 21873 336 24X Fiche 50-000, 84/01/11, 8401230373

8401160221 Forwards summary of three BNL contracts re study of occupational dose reduction at nuclear power plants
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/12 COUNSIL, W G Connecticut Yankee Atomic Power Co 7pp 21808 309 24X Fiche 50-000, 84/01/12, 8401160221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401300171 Discusses implementation of degraded grid protection for Class IE power sys Mod being installed to meet recommendations of IEEE 279-1971 & will be qualified to IEEE 323-1974 & 344-1975
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/01/17
CRUTCHFIELD, D Operating Reactors Branch 5 9pp 21999 122 24X Fiche 50-245, 84/01/17, 8401300171

8401230151 Notification of 841010-11 meetings w/util in Bethesda, MD to discuss & resolve outstanding environ qualification issues
SHEA, J J Operating Reactors Branch 5 84/01/20 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21884 316 24X Fiche 50-000, 84/01/20, 8401230151

8401230449 Notification of 840216 meeting w/util, Teledyne & BNL in Berlin, CT to discuss responses to NRC 831222 request for addl info re Mark I containment long-term program - plant-unique analysis rept loads evaluation
SHEA, J J Operating Reactors Branch 5 84/01/20 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21884 240 24X Fiche 50-245, 84/01/20, 8401230449

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge lp 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

DOCKETED ITEMS

B401100007 LER 83-034/03L-0 on 831205, oil leak discovered on low side bushing of reserve station svc transformer. Caused by loose bolts on phase C of winding Y Bolts tightened W/B40103 ltr THULL, T S, MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKZKA, E J Northeast Utilities 84/01/03 NRC - No Detailed Affiliation Given 3pp 21761 203 24X Fiche 50-245, 84/01/03, B401100007

B401100423 LER 83-035/03L-0 on 831209, RST declared inoperable when insp of transformer bushings showed excessive salt contamination following alarm caused by salt spray from high winds. Bushings cleaned of contamination W/B40103 ltr THULL, T S, MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCKZKA, E J Northeast Utilities 84/01/03 NRC - No Detailed Affiliation Given 3pp 21763 101 24X Fiche 50-245, 84/01/03, B401100423

B401300137 Updated LER 83-012/03X-1 on 830326, LPC1/core spray valve permissive interlock switch 263-52B found valved out of svc. Caused by switch not being restored to proper lineup. Technicians counseled W/B40123 ltr THULL, T S, MROCKZKA, E J Northeast Utilities MROCKZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/01/23 NRC - No Detailed Affiliation Given 3pp 21998 280 24X Fiche 50-245, 84/01/23, B401300137

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401100279 Ack receipt of B31115 ltr informing NRC of steps taken to correct violations noted in IE Enforcement Conference Rept 50-247/83-20 MARTIN, T T Division of Engineering & Technical Programs 83/12/23 O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p 21798 215 24X Fiche 50-247, 83/12/23, B401100279

--B401100285 Forwards response to NRC 830908 & 1011 ltrs re violations noted in IE Enforcement Conference Rept 50-247/83-20. Corrective actions specified auxiliary fire protection equipment purchased & provided in each box by 830908 O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/11/16 MARTIN, T T Division of Engineering & Technical Programs 10pp 21798 215 24X Fiche 50-247, 83/12/23, B401100279

B401050313 Responds to B31128 ltr re intent & direction of recent NRC proposal on possible changes to emergency preparedness requirements. NRC proposal is in early stages of development & does not represent final NRC policy. PALLADINO, N J Commissioners 83/12/30 DELBELLO, A B New York, State of 1p 21729 277 24X Fiche 50-247, 83/12/30, B401050313

--B401050316 Expresses concern re intent & direction of NRC reexam of current emergency planning regulations. Safety stds need strengthening. DELBELLO, A B New York, State of 83/11/28 PALLADINO, N J Commissioners 2pp 21729 278 24X Fiche 50-247, 83/12/30, B401050313

B401240513 Forwards IE Safeguards Insp Rept 50-247/83-25 on 831212-16. No violations noted. MARTIN, T T Division of Engineering & Technical Programs 84/01/10 O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 21917 141 24X Fiche 50-247, 84/01/10, B401240513

--B401240521 IE Safeguards Insp Rept 50-247/83-25 on 831212-16. No violations noted. Major areas inspected security organization, personnel response, security program audit, testing & maint & physical barriers. MADDEN, W J, DUNLAP, J M, GOSY, A T Region 1, Office of Director 84/01/10 4pp 21917 143 24X Fiche 50-247, 84/01/10, B401240513

B401260290 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21985 343 24X Fiche 50-003, 84/01/20, B401260290

--B401260294 Public version of revised Emergency Plan Implementing Procedure IP-1015, "Mobilization & Operational Procedure for Offsite Monitoring Teams - Immediate Response" W/B40104 ltr GAUNY, R D, O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/19 MURLEY, T E Region 1, Office of Director 17pp 21985 344 24X Fiche 50-003, 84/01/20, B401260290

B401300209 Responds to B40109 ltr forwarding correspondence from Croton-Harmon School District in Croton-on-Hudson, NY re Westchester County evacuation plan for school children in event of facility accident. FEMA already responded. KRIMM, R W Federal Emergency Management Agency 84/01/24 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 1p 21994 001 24X Fiche 50-000, 84/01/24, B401300209

O Advisory Committee on Reactor Safeguards reports & correspondence

B401130127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee 821103 meeting w/MRR & BNL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PRA Viewgraphs encl. * ACRS - Advisory Committee on Reactor Safeguards 82/12/06 ACRS - Advisory Committee on Reactor Safeguards 38pp 21820 237 24X Fiche 50-000, 82/12/06, B401130127

P Operating license stage documents & correspondence

B401090381 Notifies of final review of environ qualification of electrical equipment, consisting of 50 1-day meetings w/ licensees. VARGA, S A Operating Reactors Branch 1 83/12/19 O'TOOLE, J D Consolidated Edison Co of New York, Inc 4pp 21768 063 24X Fiche 50-247, 83/12/19, B401090381

B401050308 Advises that response to reanalysis of main steam line break w/continued feedwater addition will be provided by 840315. Response to TH1 Item II B 1 re RCS vents will be sent by 840123. O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/29 VARGA, S A Operating Reactors Branch 1 2pp 21729 082 24X Fiche 50-247, 83/12/29, B401050308

B401040257 Informs that Westinghouse Owners Group rept re justification for manual reactor coolant pump trip will be completed by 840301. Assessment of justification will be completed 120 days following receipt of rept. GROSCUP, O W Consolidated Edison Co of New York, Inc 83/12/30 EISENHUT, D G Division of Licensing 1p 21701 135 24X Fiche 50-247, 83/12/30, B401040257

B401190264 Forwards SER for Item II K 2 17 re potential for voiding in RCS during transients. Voids generated in RCS accounted for in present analysis models. Steam void will not result in unacceptable consequences during transients. VARGA, S A Operating Reactors Branch 1 84/01/03 O'TOOLE, J D Consolidated Edison Co of New York, Inc 9pp 21870 070 24X Fiche 50-247, 84/01/03, B401190264

B312120108 Board Notification B4-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification. Sandia position is that NRC environ qualification program has problems. EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J, QILINSKY, V, ROBERTS, T M Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, B312120108

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl. EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl. EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl. EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401300250 Forwards responses to B20315 request for addl info. Items 5, 6(b) & 7 re control of heavy loads. Ltr completes response to all NRC questions. O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/01/20 VARGA, S A Operating Reactors Branch 1 21pp 21993 209 24X Fiche 50-247, 84/01/20, B401300250

DOCKETED ITEMS

41

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
B401060040

B401100279 Ack receipt of B31116 ltr informing NRC of steps taken to correct violations noted in IE Enforcement Conference Rept 50-247/83-20
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
O'TOOLE, J D Consolidated Edison Co of New York, Inc 1p
21758 215 24X Fiche 50-247, 83/12/23, B401100279

--B401100285 Forwards response to NRC B30908 & 1011 ltrs re violations noted in IE Enforcement Conference Rept 50-247/83-20
Corrective actions specified auxiliary fire protection equipment purchased & provided in each box by B30908
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/11/16
MARTIN, T T Division of Engineering & Technical Programs 10pp
21758 216 24X Fiche 50-247, 83/12/23, B401100279

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401100155 Ack receipt of B31202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-21
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
21760 154 24X Fiche 50-247, 84/01/03, B401100155

--B401100158 Responds to NRC B31103 ltr re violations noted in IE Insp Rept 50-247/83-21 Corrective actions Engineering Procedure OP-290-1 revised to delineate solenoid valve installation per 10CFR50.59
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/02
STAROSTECKI, R Division of Project & Resident Programs 8pp
21760 156 24X Fiche 50-247, 84/01/03, B401100155

B401180196 Forwards IE Enforcement Conference Rept 50-247/83-27 on B31213 Enforcement action will be forwarded by separate correspondence
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
21844 120 24X Fiche 50-247, 84/01/03, B401180196

--B401180203 IE Enforcement Conference Rept 50-247/83-27 on B31213 Major areas discussed inoperability of containment spray sys from B31025-1129,
JACOBSS, R H Region 1, Office of Director NORRHO, M L J Division of Project & Resident Programs 83/12/28 4pp 21844 122 24X
Fiche 50-247, 84/01/03, B401180196

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401240513 Forwards IE Safeguards Insp Rept 50-247/83-25 on B31212-16 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
21917 141 24X Fiche 50-247, 84/01/10, B401240513

--B401240521 IE Safeguards Insp Rept 50-247/83-25 on B31212-16 No violations noted Major areas inspected security organization, personnel response, security program audit, testing & maint & physical barriers
MADDEN, W J, DUNLAP, J M, GODY, A T Region 1, Office of Director 84/01/10 4pp 21917 143 24X Fiche 50-247, 84/01/10, B401240513

B312120114 IE Info Notice B4-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

B401240363 Ack receipt of B31230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-003/83-02 & 50-247/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/19
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp
21919 340 24X Fiche 50-003, 84/01/19, B401240363

--B401240365 Responds to NRC B31129 ltr re violations noted in IE Insp Rept 50-247/83-23 Corrective actions Audit 82-01-BA re 1982 environ program issued & immediate notification sys re environ matters implemented
GRUBB, C W Consolidated Edison Co of New York, Inc 83/12/30
MARTIN, T T Division of Engineering & Technical Programs 5pp
21919 342 24X Fiche 50-003, 84/01/19, B401240363

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B401230434 Forwards IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 & notice of violation W/o notice of violation
NORRHO, M L J Division of Project & Resident Programs 83/12/21
REED, C Commonwealth Edison Co 2pp 21882 070 24X
Fiche 50-010, 83/12/21, B401230434

--B401230442 IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 Violation noted inadequate corrective action re normal shutdown & radiation protection procedures
WALKER, R, WALKER, R Region 3, Office of Director 83/12/14
21pp 21882 072 24X Fiche 50-010, 83/12/21, B401230434

B401040556 Informs of completed upgrading of fire protection features & significant effort to complete remaining mods necessary for strict conformance to App R, Sections III G & III L, per Generic Ltr 83-33 Exemption requests will be provided
FARRAR, D L Commonwealth Edison Co 83/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21707 141 24X
Fiche 50-000, 83/12/23, B401040556

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection Implementation will vary at each facility
SHWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, B401030229

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, B401230491

B401230082 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21946 278 24X Fiche 50-010, 84/01/18, B401230082

DOCKETED ITEMS

--B401250086 Forwards public version of revised Emergency Plan Implementing Procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
SCOTT, D J Commonwealth Edison Co 83/11/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21946 279 24X
Fiche 50-010, B4/01/18, B401250082

--B401250089 Public version of revised Emergency Plan Implementing Procedures EPIP 300-1 re initial notifications & generating station emergency plan responses & EPIP 300-4 re emergency personnel dose limits
* Commonwealth Edison Co 83/11/02 31pp 21946 280 24X
Fiche 50-010, B4/01/18, B401250082

B401310174 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 22035 182 24X Fiche 50-010, B4/01/20, B401310174

--B401310180 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications
SCOTT, D J Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22035 183 24X
Fiche 50-010, B4/01/20, B401310174

--B401310187 Public version of revised emergency plan implementing procedures, including Procedures EPIP 200-6 re transportation accident response & EPIP 300-1 re initial notifications
Receipt Form encl
* Commonwealth Edison Co 84/01/02 50pp 22035 185 24X
Fiche 50-010, B4/01/20, B401310174

G Adjudicatory correspondence

B401230388 Order extending time until 840203 for Commission to act to review Director's Decision 8D-83-14 which denied requests of Sierra Club & State of OH & 831029 decision which denied request of Environ Policy Inst
CHILKIS, J Office of the Secretary of the Commission 84/01/19 Commissioners 1p 21884 278 24X Fiche 50-000, B4/01/19, B401230388

J Insurance & indemnity information

B401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42-43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant Director for State & License Relations 17pp 21865 332 24X
Fiche 50-000, B4/01/09, B401200141

P Operating license stage documents & correspondence

B312140234 Forwards Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively & safety evaluation Amends specify reactor pressure when conducting scram testing following refueling
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 FARRAR, D C Commonwealth Edison Co 3pp 21520 029 24X Fiche 50-237, B3/12/12, B312140234

--B312140235 Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively, specifying reactor pressure while conducting scram testing following refueling
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 8pp 21520 032 24X Fiche 50-237, B3/12/12, B312140234

--B312140236 Safety evaluation supporting Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/12 2pp 21520 040 24X Fiche 50-237, B3/12/12, B312140234

--B312140237 Requests FR publication of notice of issuance of Amends 79 & 70 to Licenses DPR-19 & DPR-25, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/12/12 MILLER, J R Operating Reactors Branch 3 3pp 21520 042 24X
Fiche 50-237, B3/12/12, B312140234

B401040329 Discusses operability of containment purge & vent valves in response to SER Detailed list of operating evolutions, procedures used to perform evolutions & containment vent & purge valves required for evolutions encl
RYBAK, B Commonwealth Edison Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 21705 061 24X
Fiche 50-000, B3/12/21, B401040329

B401100409 Forwards Amend 71 to License DPR-25 & safety evaluation Amend changes Tech Specs to prevent excessive loadings to torus if relief valve actuation occurs shortly after closure by reducing subsequent actuation
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/04 FARRAR, D L Commonwealth Edison Co App 21763 035 24X Fiche 50-249, B4/01/04, B401100409

--B401100415 Amend 71 to License DPR-25, changing Tech Specs to prevent excessive loadings to torus if relief valve actuation occurs shortly after closure by reducing subsequent actuation
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/04 5pp 21763 039 24X Fiche 50-249, B4/01/04, B401100409

--B401100421 Safety evaluation supporting Amend 71 to License DPR-25
* Office of Nuclear Reactor Regulation, Director 84/01/04 2pp 21763 044 24X Fiche 50-249, B4/01/04, B401100409

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

B401170339 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators" Prelubrication w/ some warming provided, therefore, generators not subjected to cold starts
BARNES, P L Commonwealth Edison Co 84/01/10 EISENHUT, D G Division of Licensing 1p 21829 341 24X Fiche 50-000, B4/01/10, B401170339

B401160064 Notification of B40131-0203 meetings w/ util in Morris, IL to conduct in-progress audit of detailed control room design rept
OILBERT, R A Operating Reactors Branch 5 84/01/12 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 21821 214 24X
Fiche 50-237, B4/01/12, B401160064

B401160216 Requests provision of listed info to assist in-progress audit of detailed control room design review on B40131-0203
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/12 FARRAR, D L Commonwealth Edison Co 3pp 21815 105 24X Fiche 50-237, B4/01/12, B401160216

B401230327 Forwards draft radiological effluent Tech Specs as committed to on 830928 for comment
RYBAK, B Commonwealth Edison Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21883 001 24X
Fiche 50-237, B4/01/12, B401230327

--B401230332 Draft Tech Spec amend (RETS) to License DPR-19
* Commonwealth Edison Co 84/01/12 142pp 21883 003 24X
Fiche 50-237, B4/01/12, B401230327

B401250464 Notifies that B31212 ltr forwarding amend to Licenses DPR-19 & DPR-25 reflects incorrect amend numbers Amend 79 should be changed to 78 & Amend 68 to 69
SMITH, H Operating Reactors Branch 5 84/01/12 BAILEY, I Record Services Branch (Document Control Desk) 2pp 21948 360 24X
Fiche 50-237, B4/01/12, B401250464

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401230456 Application for amend to License DPR-25, revising Tech Spec Table 3 7 1 to increase total number of inboard valves on reactor water cleanup sys from one to two
RYBAK, B Commonwealth Edison Co 84/01/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21882 182 24X
Fiche 50-249, B4/01/13, B401230456

--B401230463 Proposed Tech Spec revising Table 3 7 1 to increase total number of inboard valves on reactor water cleanup sys from one to two
* Commonwealth Edison Co 84/01/13 3pp 21882 184 24X
Fiche 50-249, B4/01/13, B401230456

DOCKETED ITEMS

43

B401200078 Notification of B40126 meeting w/uttl in Bethesda, MD to perform equipment environ qualification review for facilities
OILBERT, R A Operating Reactors Branch 5 84/01/19 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 21866 350 24X
Fiche 50-000, 84/01/19, B401200078

B401250040 Informs of completed review of BWR Owners Group B01230 response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Alternative modes of depressurization would not contribute to safety
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/23 FARRAR, D L
Commonwealth Edison Co 6pp 21935 240 24X Fiche 50-237, 84/01/23, B401250040

B401250179 Provides review of TH1 Items II K 3 30 & II K 3 31 re small break LOCA analysis & compliance w/10CFR50 4b, App K Based on extensive discussions, requirements met
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/23 FARRAR, D L
Commonwealth Edison Co 2pp 21935 214 24X Fiche 50-237, 84/01/23, B401250179

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, B401060150

B401040533 Suppls response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
BARNES, P L Commonwealth Edison Co 83/12/20 KEPLER, J G Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20, B401040533

B401230434 Forwards IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 & notice of violation w/o notice of violation
NDRELIUS, C E Division of Project & Resident Programs 83/12/21
REED, C Commonwealth Edison Co 2pp 21882 070 24X
Fiche 50-010, 83/12/21, B401230434

--B401230442 IE Insp Repts 50-010/83-19, 50-237/83-29 & 50-249/83-27 on B30920-1117 Violation noted inadequate corrective action re normal shutdown & radiation protection procedures
WALKER, R, TONGUE, T M, STASEK, S Region 3, Office of Director 83/12/14 21pp 21882 072 24X Fiche 50-010, 83/12/21, B401230442

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License " Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401160144 Monthly operating repts for Dec 1983 W/B40103 ltr
SCHROEDER, B A, SCOTT, D J Commonwealth Edison Co 83/12/31
Director's Office, Office of Inspection and Enforcement 16pp 21814 320 24X Fiche 50-237, 83/12/31, B401160144

S Reportable occurrences, LERs & related correspondence

B401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000, 83/10/07, B401050064

B401050632 Discusses B31209 uncoupling of trailer containing spent fuel assemblies uncoupled from tractor Cause unknown No damage to tractor, trailer, cask, or any other vehicle incurred Pull test performed successfully
SCOTT, D J Commonwealth Edison Co 83/12/28 KEPLER, J G Region 3, Office of Director 20pp 21726 083 24X Fiche 50-010, 83/12/28, B401050632

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Troubridge 6pp 21957 357 24X
Fiche 50-000, 83/11/02, B401250163

--B304050512 Requests Commission approval of exception for location of emergency operations facility for facilities
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-111 83/03/21 7pp 21958 033 24X
Fiche 50-000, 83/11/02, B401250163

B401260260 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21990 344 24X Fiche 50-000, 84/01/20, B401260260

--B401260263 Public version of revised Emergency Plan Implementing Procedure 1301, "Emergency Roster - Offsite Emergency Organization " W/831229 ltr
WILLIAMS, J W, JOHNSON, H D Florida Power & Light Co 83/12/15
O'REILLY, J P Region 2, Office of Director 11pp 21990 345 24X Fiche 50-000, 84/01/20, B401260260

B401310275 Forwards "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3," per B30415 commitment re Suppl 1 to NUREG-0737
WILLIAMS, J W Florida Power & Light Co 84/01/26 EISENHUT, D G
Division of Licensing 1p 22018 125 24X Fiche 50-250, 84/01/26, B401310275

--B401310277 "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3 "
* Florida Power & Light Co 83/07/30 135pp 22018 126 24X
Fiche 50-250, 84/01/26, B401310275

G Adjudicatory correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, B401250015

--B205280489 Notifies Commission that J Jaffer petition to suspend license amends for facilities has been denied
MALBACH, M G Office of the General Counsel SECY-82-193
82/05/12 13pp 21964 158 24X Fiche 50-000, 83/10/18, B401250015

DOCKETED ITEMS

8401300126 Amended petition of Ctr for Nuclear Responsibility, Inc to intervene, initially filed on 8/31/04
HODDER, M H Center for Nuclear Responsibility 84/01/25 Atomic Safety and Licensing Board Panel 7pp 22042 279 24X
Fiche 50-250, 84/01/25, 8401300126

--8401300130 Discovery request for documents listed on encl App A w/o app Certificate of Svc encl
HODDER, M H Center for Nuclear Responsibility 84/01/26
Office of the Executive Legal Director 3pp 22042 289 24X
Fiche 50-250, 84/01/25, 8401300126

8401310139 Informs of party intervenor status per 831107 petition & requests to be placed on svc list
LORION, J Center for Nuclear Responsibility 84/01/27 STEVENS
Docketing & Services Branch 1p 22022 071 24X
Fiche 50-250, 84/01/27, 8401310139

8401310357 Forwards completed copy of 840125 discovery request filed as part of amended petition to intervene in which App A inadvertently omitted
HODDER, M H Hodder, M H HODDER, M H Center for Nuclear Responsibility 84/01/27 Atomic Safety and Licensing Board Panel 1p 22015 053 24X Fiche 50-250, 84/01/27, 8401310357

--8401310364 Discovery request as part of amended petition to intervene Encl App A inadvertently omitted from original discovery request Certificate of Svc encl
HODDER, M H Hodder, M H HODDER, M H Center for Nuclear Responsibility 84/01/26 Office of the Executive Legal Director 4pp 22015 054 24X Fiche 50-250, 84/01/27, 8401310357

P Operating license stage documents & correspondence

8401060419 Summarizes 831128 meeting w/Util in Atlanta, GA re organizational changes within associated nuclear facilities, scheduled administrative bldg & simulator const activities & recent INPO findings
D'REILLY, J P Region 2, Office of Director 83/12/15
WILLIAMS, J W Florida Power & Light Co 1p 21741 078 24X
Fiche 50-250, 83/12/15, 8401060419

8401090704 Forwards Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & final determination of NSHC Amends support integrated program for vessel flus reduction & operation w/new steam generators
MCDONALD, D G Operating Reactors Branch 1 83/12/23 UHRIG, R E Florida Power & Light Co 5pp 21764 203 24X
Fiche 50-250, 83/12/23, 8401090704

--8401090715 Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively, supporting integrated program for vessel flus reduction & operation w/new steam generators
VARGA, S A Operating Reactors Branch 1 83/12/23 17pp 21764 208 24X Fiche 50-250, 83/12/23, 8401090704

--8401090728 Safety evaluation supporting Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation Director 83/12/23 15pp 21764 225 24X Fiche 50-250, 83/12/23, 8401090704

--8401090751 Notice of issuance of Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively & final determination of NSHC
VARGA, S A Operating Reactors Branch 1 83/12/23 7pp 21764 241 24X Fiche 50-250, 83/12/23, 8401090704

8401040352 Application for amend to Licenses DPR-31 & DPR-41, defining operating bypasses on ESF actuation channels
WILLIAMS, J W Florida Power & Light Co 83/12/28 EISENHUT, D G Division of Licensing 2pp 21706 142 24X Fiche 50-250, 83/12/28, 8401040352

--8401040353 Proposed Tech Spec re operating bypasses on ESF actuation channels
WILLIAMS, J W Florida Power & Light Co 83/12/28 5pp 21706 144 24X Fiche 50-250, 83/12/28, 8401040352

8401190337 Forwards Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA Amends delete nonradiological EIS re terrestrial, biological & physical monitoring programs
MCDONALD, D G Operating Reactors Branch 1 84/01/04 UHRIG, R E Florida Power & Light Co 4pp 21869 265 24X
Fiche 50-250, 84/01/04, 8401190337

--8401190340 Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively, deleting nonradiological EIS re terrestrial, biological & physical monitoring programs
VARGA, S A Operating Reactors Branch 1 84/01/04 9pp 21869 269 24X Fiche 50-250, 84/01/04, 8401190337

--8401190346 Safety evaluation & EIA supporting Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/04 App 21869 278 24X Fiche 50-250, 84/01/04, 8401190337

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401200133 Forwards SER on NUREG-0737, Item II K 2 17, "Potential for Voiding in RCS During Transients," for Westinghouse plants
Steam void will not result in unacceptable consequences during anticipated transients
VARGA, S A Operating Reactors Branch 1 84/01/06 WILLIAMS, J W Florida Power & Light Co 2pp 21872 139 24X
Fiche 50-250, 84/01/06, 8401200133

8401170517 Confirms telcon w/R Stevens scheduling 840208-09 meetings to discuss open items in Franklin Research Ctr technical evaluation repts re environ qualification of electrical equipment
MILLER, J R Operating Reactors Branch 3 84/01/09 WILLIAMS, J W Florida Power & Light Co 2pp 21847 115 24X
Fiche 50-000, 84/01/09, 8401170517

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401060431 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for Jul 1982 - June 1983
D'REILLY, J P Region 2, Office of Director 83/12/15
WILLIAMS, J W Florida Power & Light Co 3pp 21740 001 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060442 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
LEWIS, R C Division of Project & Resident Programs 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 21740 004 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060452 SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
* Region 2, Office of Director 83/10/14 49pp 21740 006 24X
Fiche 50-000, 83/12/15, 8401060431

8401030522 Act receipt of 831031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-26 & 50-251/83-26
DANCE, H C Division of Project & Resident Programs 83/12/16 WILLIAMS, J W Florida Power & Light Co 1p 21725 239 24X
Fiche 50-250, 83/12/16, 8401030522

--8401050532 Responds to NRC 830930 ltr re violations noted in IE Insp Repts 50-250/83-26 & 50-251/83-26 Corrective actions shutdown bank withdrawal criteria & operating Procedure 0204 J incorporated in guidelines
WILLIAMS, J W Florida Power & Light Co 83/10/31 D'REILLY, J P Region 3, Office of Director 3pp 21725 240 24X
Fiche 50-250, 83/12/16, 8401050522

DOCKETED ITEMS

--B401260265 Public version of revised Emergency Plan Implementing Procedure 1301, "Emergency Roster - Offsite Emergency Organization" W/831227 ltr
WILLIAMS, J W, JOHNSON, H D Florida Power & Light Co 83/12/15
O'REILLY, J P Region 2, Office of Director 11pp 21970 345
24X Fiche 50-000, 84/01/20, B401260260

B401310275 Forwards "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3," per B30415 commitment re Suppl 1 to NUREG-0737
WILLIAMS, J W Florida Power & Light Co 84/01/26 EISENHUT, D G
Division of Licensing 1p 22018 125 24X Fiche 50-250, 84/01/26, B401310275

--B401310277 "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3"
a Florida Power & Light Co 83/09/30 135pp 22018 126 24X
Fiche 50-250, 84/01/26, B401310275

G Adjudicatory correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, B401250015

--B402580489 Notifies Commission that J Jaffer petition to suspend license amendments for facilities has been denied
MALSCHE, M G Office of the General Counsel SECY-82-193
82/05/12 13pp 21964 158 24X Fiche 50-000, 83/10/18, B401250015

--B401250263 Forwards NRC brief in Lorion vs NRC (DC Circuit Court of Appeals 82-1132) case
SLAOGIE, E L Office of the General Counsel SECY-82-272
82/06/28 60pp 21964 327 24X Fiche 50-000, 83/10/18, B401250015

B401300126 Amended petition of Ctr for Nuclear Responsibility, Inc to intervene, initially filed on 831104
HODDER, M H Center for Nuclear Responsibility 84/01/25 Atomic
Safety and Licensing Board Panel 9pp 22042 279 24X
Fiche 50-250, 84/01/25, B401300126

--B401300130 Discovery request for documents listed on encl App A W/a app Certificate of Svc encl
HODDER, M H Center for Nuclear Responsibility 84/01/26
Office of the Executive Legal Director 3pp 22042 289 24X
Fiche 50-250, 84/01/25, B401300126

B401310139 Informs of party intervenor status per 831107 petition & requests to be placed on svc list
LORDON, J Center for Nuclear Responsibility 84/01/27 STEVENS
Docketing & Services Branch 1p 22022 071 24X
Fiche 50-250, 84/01/27, B401310139

B401310357 Forwards completed copy of B40125 discovery request filed as part of amended petition to intervene in which App A inadvertently omitted
HODDER, M H Hodder, M H HODDER, M H Center for Nuclear
Responsibility 84/01/27 Atomic Safety and Licensing Board
Panel 1p 22015 053 24X Fiche 50-250, 84/01/27, B401310357

--B401310364 Discovery request as part of amended petition to intervene Encl App A inadvertently omitted from original discovery request Certificate of Svc encl
HODDER, M H Hodder, M H HODDER, M H Center for Nuclear
Responsibility 84/01/26 Office of the Executive Legal
Director App 22015 054 24X Fiche 50-250, 84/01/27, B401310357

P Operating license stage documents & correspondence

B401060419 Summarizes 831128 meeting w/Util in Atlanta, GA re organizational changes within associated nuclear facilities, scheduled administrative bldg & simulator const activities & recent INPO findings
O'REILLY, J P Region 2, Office of Director 83/12/15
WILLIAMS, J W Florida Power & Light Co 1p 21741 078 24X
Fiche 50-250, 83/12/15, B401060419

B401090704 Forwards Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & final determination of NSRC Amends support integrated program for vessel flux reduction & operation w/new steam generators
MCDONALD, D G Operating Reactors Branch 1 83/12/23 UHRIG, R E
Florida Power & Light Co 5pp 21764 203 24X
Fiche 50-250, 83/12/23, B401090704

--B401090715 Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively, supporting integrated program for vessel flux reduction & operation w/new steam generators
VARGA, S A Operating Reactors Branch 1 83/12/23 17pp
21764 208 24X Fiche 50-250, 83/12/23, B401090704

--B401090728 Safety evaluation supporting Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively
a Office of Nuclear Reactor Regulation, Director 83/12/23
15pp 21764 225 24X Fiche 50-250, 83/12/23, B401090704

--B401090751 Notice of issuance of Amends 99 & 93 to Licenses DPR-31 & DPR-41, respectively & final determination of NSRC
VARGA, S A Operating Reactors Branch 1 83/12/23 7pp
21764 241 24X Fiche 50-250, 83/12/23, B401090704

B401040352 Application for amend to Licenses DPR-31 & DPR-41, defining operating bypasses on ESF actuation channels
WILLIAMS, J W Florida Power & Light Co 83/12/28 EISENHUT, D G
Division of Licensing 2pp 21706 142 24X Fiche 50-250, 83/12/28, B401040352

--B401040353 Proposed Tech Spec re operating bypasses on ESF actuation channels
WILLIAMS, J W Florida Power & Light Co 83/12/28 5pp
21706 144 24X Fiche 50-250, 83/12/28, B401040352

B401190337 Forwards Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & EIA Amends delete nonradiological ETS re terrestrial, biological & physical monitoring programs
MCDONALD, D G Operating Reactors Branch 1 84/01/04 UHRIG, R E
Florida Power & Light Co 4pp 21869 265 24X
Fiche 50-250, 84/01/04, B401190337

--B401190340 Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively, deleting nonradiological ETS re terrestrial, biological & physical monitoring programs
VARGA, S A Operating Reactors Branch 1 84/01/04 9pp
21869 269 24X Fiche 50-250, 84/01/04, B401190337

--B401190346 Safety evaluation & EIA supporting Amends 100 & 94 to Licenses DPR-31 & DPR-41, respectively
a Office of Nuclear Reactor Regulation, Director 84/01/04 4pp
21869 278 24X Fiche 50-250, 84/01/04, B401190337

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401200133 Forwards SER on NUREG-0737, Item II K 2 17, "Potential for Voiding in RCS During Transients," for Westinghouse plants
Steam void will not result in unacceptable consequences during anticipated transients
VARGA, S A Operating Reactors Branch 1 84/01/06 WILLIAMS, J W
Florida Power & Light Co 2pp 21872 139 24X
Fiche 50-250, 84/01/06, B401200133

B401170517 Confirms telcon w/R Stevens scheduling B40208-09 meetings to discuss open items in Franklin Research Ctr technical evaluation repts re environ qualification of electrical equipment
MILLER, J R Operating Reactors Branch 3 84/01/09 WILLIAMS, J W
Florida Power & Light Co 2pp 21847 115 24X
Fiche 50-000, 84/01/09, B401170517

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info, Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--8401060130 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401060431 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
O'REILLY, J P Region 2, Office of Director 83/12/15
WILLIAMS, J W Florida Power & Light Co 3pp 21740 001 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060442 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
LEWIS, R C Division of Project & Resident Programs 83/10/14
UHRIG, R E Florida Power & Light Co 2pp 21740 004 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060452 SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
* Region 2, Office of Director 83/10/14 49pp 21740 006 24X
Fiche 50-000, 83/12/15, 8401060431

8401050522 Ack receipt of 831031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-26 & 50-251/83-26
DANCE, H C Division of Project & Resident Programs 83/12/16
WILLIAMS, J W Florida Power & Light Co 1p 21725 239 24X
Fiche 50-250, 83/12/16, 8401050522

--8401050532 Responds to NRC 830930 ltr re violations noted in IE Insp Repts 50-250/83-26 & 50-251/83-26 Corrective actions shutdown bank withdrawal criteria & operating Procedure 0204 3 incorporated in guidelines
WILLIAMS, J W Florida Power & Light Co 83/10/31 O'REILLY, J P Region 3, Office of Director 3pp 21725 240 24X
Fiche 50-250, 83/12/16, 8401050522

--8401050540 Forwards IE Insp Repts 50-250/83-26 & 50-251/83-26 on 830626-0725 & notice of violation
LEWIS, R C Region 2, Office of Director 83/09/30 UHRIG, R E Florida Power & Light Co 2pp 21725 243 24X
Fiche 50-250, 83/12/16, 8401050522

--8401050550 Notice of violation from insp on 830626-0725
* Region 2, Office of Director 83/09/30 2pp 21725 245 24X
Fiche 50-250, 83/12/16, 8401050522

--8401050563 IE Insp Repts 50-250/83-26 & 50-251/83-26 on 830626-0725 Violations noted failure to maintain & implement procedures re reactor startup-cold condition to hot shutdown conditions
VOGT-LOWELL, R J, AGLES, J A, LANDIS, K B Region 2, Office of Director 83/09/22 9pp 21725 247 24X Fiche 50-250, 83/12/16, 8401050522

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401240243 Ack receipt of 831216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-35 & 50-251/83-35
DANCE, H C Division of Project & Resident Programs 84/01/06
WILLIAMS, J W Florida Power & Light Co 1p 21910 121 24X
Fiche 50-250, 84/01/06, 8401240243

--8401240253 Responds to NRC 831116 ltr re violations noted in IE Insp Repts 50-250/83-35 & 50-251/83-35 Corrective actions inservice test program revised to include max limiting stroke time of 24 s for valves MOV-3-744A & 744B
WILLIAMS, J W Florida Power & Light Co 83/12/16 O'REILLY, J P Region 2, Office of Director 2pp 21910 122 24X
Fiche 50-250, 84/01/06, 8401240243

--8401240265 Forwards IE Insp Repts 50-250/83-35 & 50-251/83-35 on 831025-28 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/11/16
WILLIAMS, J W Florida Power & Light Co 2pp 21910 124 24X
Fiche 50-250, 84/01/06, 8401240243

--8401240271 Notice of violation from insp on 831025-28
* Region 2, Office of Director 83/11/16 1p 21910 126 24X
Fiche 50-250, 84/01/06, 8401240243

--8401240278 IE Insp Repts 50-250/83-35 & 50-251/83-35 on 831025-28 Violation noted failure to provide appropriate acceptance criteria in inservice test procedure for valve exercise times
KLEINSORGE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/11/10 8pp 21910 127 24X Fiche 50-250, 84/01/06, 8401240243

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401300114 Forwards prism test procedure to be used to substantiate as-built capability of masonry walls, per IE Bulletin 80-11 criteria
WILLIAMS, J W Florida Power & Light Co 84/01/24 VARGA, S A Operating Reactors Branch 1 1p 21999 190 24X
Fiche 50-250, 84/01/24, 8401300114

--8401300118 "Procedure for Testing of In-place Mats in Existing Masonry Walls "
* Bechtel Corp 84/01/18 34pp 21999 191 24X
Fiche 50-250, 84/01/24, 8401300114

R Periodic operating reports & related correspondence

8401120363 Monthly operating Repts for Nov 1983 W/831215 ltr
GRANT, N W, WILLIAMS, J W Florida Power & Light Co 83/11/30 Division of Data Automation & Management Information 17pp 21791 330 24X Fiche 50-000, 83/11/30, 8401120363

8401270459 Monthly operating Repts for Dec 1983 W/840116 ltr
GRANT, N W, WILLIAMS, J W Florida Power & Light Co 83/12/31 Office of Resource Management, Director 17pp 21980 026 24X
Fiche 50-000, 83/12/31, 8401270459

8401130284 Responds to 831108 ltr requesting review of info summary of radioactive effluents during 1981 Info verified to be correct
WILLIAMS, J W Florida Power & Light Co 84/01/13 TICHLER, J Brookhaven National Laboratory 1p 21800 362 24X
Fiche 50-250, 84/01/13, 8401130284

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050064

8401050075 Responds to FOIA request for 27 LERs Forwards three listed LERs Remaining LERs unavailable in NRC records sys, canceled, or never issued
FELTON, J M Division of Rules and Records 83/10/25 GRABER, L D NUS Corp 1p 21736 345 24X Fiche 50-000, 83/10/25, 8401050075

8401030210 LER 83-020/03L-0 on 831123, during return to operation after addition of full-flow recirculation piping, reactor taken critical before piping hydrotested at pump discharge pressure Caused by previous outmoded hydrotest W/831222 ltr
BERRY, Z E, WILLIAMS, J W Florida Power & Light Co 83/12/22 O'REILLY, J P Region 2, Office of Director 2pp 21682 290 24X
Fiche 50-251, 83/12/22, 8401030210

DOCKETED ITEMS

8401040419 Updated LER 83-002/01X-1 on 830405, hoisting cable on fuel handling crane of spent fuel assembly X-13 parted & assembly X-13 dropped back into rack Caused by malfunction of two limit switches Switches repaired W/831222 ltr
BERRY, Z E., WILLIAMS, J W Florida Power & Light Co 83/12/22
O'REILLY, J P Region 2, Office of Director 2pp 21706 204 24X
Fiche 50-251, 83/12/22, 8401040419

8401050564 LER 83-021/03L-0 on 831207, while adding nitrogen to accumulator, accumulator 4B relief valve lifted prematurely at setpoint below Tech Spec limit Caused by premature lifting of relief valve 8588 W/831230 ltr
BERRY, Z E., WILLIAMS, J W Florida Power & Light Co 83/12/30
O'REILLY, J P Region 2, Office of Director 2pp 21726 060 24X
Fiche 50-251, 83/12/30, 8401050564

8401260099 LER 83-022/03L-0 on 831219, routine sample of boric acid storage tank boron concentration revealed three tanks exceeding Tech Spec limits Caused by lack of communication between chemistry & operations personnel W/840118 ltr
ARIAS, J., WILLIAMS, J W Florida Power & Light Co 84/01/18
O'REILLY, J P Region 2, Office of Director 2pp 21957 106 24X
Fiche 50-251, 84/01/18, 8401260099

DOCKET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8401250051 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21947 166 24X Fiche 50-252, 84/01/18, 8401250051

--8401250055 Public version of revised emergency plan W/831213 ltr
ROBERTSON, J C New Mexico Univ of Albuquerque, NM 83/11/30
THOMAS, C Standardization & Special Projects Branch 91pp
21947 167 24X Fiche 50-252, 84/01/18, 8401250055

DOCKET 50-254 QUAD CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401040556 Informs of completed upgrading of fire protection features & significant effort to complete remaining mods necessary for strict conformance to App R Sections III G & III L, per Generic Ltr 83-03 Exemption requests will be provided
FARRAR, D L Commonwealth Edison Co 83/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21707 141 24X
Fiche 50-000, 83/12/23, 8401040556

8401050099 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 237 24X Fiche 50-254, 83/12/28, 8401050099

--8401050102 Public version of Rev 11 to Emergency Plan Implementing Procedure QEP 200-T1, "Quad-Cities Emergency Action Levels" W/831117 ltr, receipt form & revised table of contents
TIEZT, G Commonwealth Edison Co 83/11/17 13pp 21736 238 24X Fiche 50-254, 83/12/28, 8401050099

8401050251 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 179 24X Fiche 50-254, 83/12/28, 8401050251

--8401050257 Forwards public version of revised Emergency Plan Implementing Procedures QEP 350-T1, "Recommended Protective Actions for Gaseous Release" & QEP 350-2, "Emergency Drills"
TIEZT, G, KOVACH, T J Commonwealth Edison Co 83/11/15 NRC - No Detailed Affiliation Given 1p 21743 180 24X
Fiche 50-254, 83/12/28, 8401050251

--8401050261 Public version of revised Emergency Plan Implementing Procedures QEP 350-T1, "Recommended Protective Actions for Gaseous Release" & QEP 350-2, "Emergency Drills"
TIEZT, G Commonwealth Edison Co 83/11/15 14pp 21743 181 24X Fiche 50-254, 83/12/28, 8401050251

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection Implementation will vary at each facility
SWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, 8401030229

8401230491 Notification of 840112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, 8401230491

8401240651 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 111 24X Fiche 50-254, 84/01/20, 8401240651

--8401240652 Public version of revised emergency plan implementing procedures, including Procedure QEP 200-2 re classification of incident involving hazardous mats & GEP 310-1 re initial notification
GERNER, L Commonwealth Edison Co 83/12/19 56pp 21945 112 24X Fiche 50-254, 84/01/20, 8401240651

8401300344 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22006 104 24X Fiche 50-254, 84/01/26, 8401300344

--8401300348 Public version of Rev 5 to Emergency Plan Implementing Procedure QEP 350-T6, "Hotline Public Hosp Radiation Emergency Area Supplies & Equipment" W/840110 transmittal & receipt form
JESSEN, D., KOVACH, T J Commonwealth Edison Co 84/01/10 5pp 22006 105 24X Fiche 50-254, 84/01/26, 8401300344

J Insurance & indemnity information

8401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 BALTZMAN, J Assistant Director for State & Licensee Relations 17pp 21865 332 24X
Fiche 50-000, 84/01/09, 8401200141

8401200184 Forwards listed endorsements to NELIA Policies NF-43, 187, 201, 253 & 277 & MAELU Policies MF-22, 54, 64 & 104
OSTER, J Commonwealth Edison Co 84/01/09 BALTZMAN, J Assistant Director for State & Licensee Relations 19pp 21863 232 24X
Fiche 50-000, 84/01/09, 8401200184

P Operating license stage documents & correspondence

8401040329 Discusses operability of containment purge & vent valves in response to SER Detailed list of operating evolutions, procedures used to perform evolutions & containment vent & purge valves required for evolutions encl
RYBAK, B Commonwealth Edison Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 21705 061 24X
Fiche 50-000, 83/12/21, 8401040329

8401300035 Requests notification whether GE small break LOCA model approved on 831213 used in LOCA analysis Correct understanding completes TH1 Items II K 3 30 & II K 3 31 Requests plans & schedules if understanding incorrect
VASSALLO, D B Operating Reactors Branch 2 83/12/28 FARRAR, D L Commonwealth Edison Co 2pp 22006 358 24X Fiche 50-254, 83/12/28, 8401300035

8401260420 Forwards SER re automatic switchover of RCIC sys Switchover design now in place satisfies requirements of NUREG-0737, Item II K 3 22 Item complete
VASSALLO, D B Operating Reactors Branch 2 83/12/29 FARRAR, D L Commonwealth Edison Co 8pp 21759 317 24X Fiche 50-254, 83/12/29, 8401260420

8401300059 Forwards SER supporting util proposed design mods re monitoring of electric power to reactor protection sys Technical evaluation rept also encl
VASSALLO, D B Operating Reactors Branch 2 83/12/29 FARRAR, D L Commonwealth Edison Co 2pp 22003 345 24X Fiche 50-254, 83/12/29, 8401300059

--8401300069 Safety evaluation supporting proposed design mods to existing reactor protection sys & applicable Tech Spec changes
* NRC - No Detailed Affiliation Given 83/12/29 2pp 22003 347 24X Fiche 50-254, 83/12/29, 8401300059

--8306140082 "Monitoring of Electric Power to Reactor Protection Sys for Quad Cities Nuclear Power Station, Units 1 & 2," technical evaluation rept
SELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-19704 83/05/18 NRC - No Detailed Affiliation Given 9pp 22003 349 24X Fiche 50-254, 83/12/29, 8401300059

DOCKETED ITEMS

49

B401050382 Generic Ltr B4-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing B4/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing B4/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

B401170339 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators" Prelubrication w/some warming provided, therefore, generators not subjected to cold starts
BARNES, P L Commonwealth Edison Co B4/01/10 EISENHUT, D G
Division of Licensing 1p 21829 341 24X Fiche 50-000, B4/01/10, B401170339

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing B4/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401200098 Notification of B40126 meeting w/util in Bethesda, MD to perform equipment environ qualification review for facilities
GILBERT, R A Operating Reactors Branch 5 B4/01/19 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 21866 350 24X
Fiche 50-000, B4/01/19, B401200098

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
B3/10/20 134pp, 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401040375 Forwards IE Insp Repts 50-254/B3-28 & 50-265/B3-27 on B31003-1202 No noncompliance noted
SHAFER, W D Region 3, Office of Director B3/12/16 REED, C
Commonwealth Edison Co 2pp 21706 223 24X Fiche 50-254, B3/12/16, B401040375

--B401040380 IE Insp Repts 50-254/B3-28 & 50-265/B3-27 on B31003-1202 No noncompliance noted Major areas inspected operational safety, LERs, design changes & mods, onsite review committee, special repts, mgt meetings, training & regional requests
CHRISTOTIMOS, N, MORRONGIELLO, D, WALKER, R D Region 3, Office of Director B3/12/14 12pp 21706 225 24X Fiche 50-254, B3/12/16, B401040375

B401040533 Suppls response to IE Bulletin B3-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
BARNES, P L Commonwealth Edison Co B3/12/20 KEPLER, J G, Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, B3/12/20, B401040533

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc 124pp, 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B401040324 Confirms plans for B40124 enforcement conference in Glen Ellyn, IL re concerns associated w/personnel error which resulted in B3110-15 degradation of secondary containment
NORELIOUS, C E Division of Project & Resident Programs B3/12/29 REED, C Commonwealth Edison Co 1p 21704 360 24X
Fiche 50-254, B3/12/29, B401040324

B312120093 IE Info Notice B3-B4, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R Periodic operating reports & related correspondence

B401170210 Monthly operating repts for Dec 1983 W/B40103 ltr
MISAK, A, KALIVIANAKIS, N Commonwealth Edison Co B3/12/31
Director's Office, Office of Inspection and Enforcement 20pp
21832 260 24X Fiche 50-254, B3/12/31, B401170210

B401170024 Forwards listing of changes, tests & experiments for Dec 1983
KALIVIANAKIS, N Commonwealth Edison Co B4/01/03 CASE, E G
Office of Nuclear Reactor Regulation, Director 2pp 21833 361
24X Fiche 50-254, B4/01/03, B401170024

S Reportable occurrences, LERs & related correspondence

B401050449 LER B3-046/03L-0 on B31128, RHR svc water pump 1C taken out of svc Caused by leakage of Teflon seal ring Thicker ring fabricated & installed Leakage eliminated W/B31209 ltr
MISAK, A, KALIVIANAKIS, N Commonwealth Edison Co B3/12/09
KEPLER, J Region 3, Office of Director 3pp 21730 205 24X
Fiche 50-254, B3/12/09, B401050449

B401040324 Confirms plans for B40124 enforcement conference in Glen Ellyn, IL re concerns associated w/personnel error which resulted in B3110-15 degradation of secondary containment.
NORELIOUS, C E Division of Project & Resident Programs B3/12/29
REED, C Commonwealth Edison Co 1p 21704 360 24X
Fiche 50-254, B3/12/29, B401040324

B401190297 LER B3-047/03L-0 on B31210, during traversing in-core proba sys valve Test G05 700-9, isolation valve 2-733-1 failed to close Caused by buildup of dry lubricant used in probe tubing Valve replaced W/B40106 ltr
EAGLE, J, KALIVIANAKIS, N Commonwealth Edison Co B4/01/06
KEPLER, J Region 3, Office of Director 2pp 21850 313 24X
Fiche 50-254, B4/01/06, B401190297

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

B401190120 Responds to B30923 ltr re proposed schedule for improvements to security program Schedule acceptable.
CRUTCHFIELD, D Operating Reactors Branch 5 B4/01/04
VANDEHALL, C J Consumers Power Co 1p 21871 036 24X
Fiche 50-235, B4/01/04, B401190120

B401230270 Notifies of FEMA B40112-13 meetings in Chicago, IL re radiological emergency preparedness program to develop final FY84/FY85 emergency preparedness exercise schedule & prompt alert notification certification schedule
PAPERIELLO, C J Region 3, Office of Director B4/01/05 COOK, J W
Consumers Power Co 4pp 21884 207 24X Fiche 50-000, B4/01/05, B401230270

DOCKETED ITEMS

8401120368 Act receipt of 831214 ltr transmitting Rev B to plant security plan changes consistent w/10CFR50 54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/01/06
VANDEWALLE, D J Consumers Power Co 1p 21792 020 24X
Fiche 50-255, 84/01/06, 8401120368

8401250099 Releases public version of revised controlled copyholder list
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21959 158 24X Fiche 50-000, 84/01/18, 8401250099

--8401250102 Public version of Rev 4 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures
* Consumers Power Co 83/11/10 Office of Nuclear Reactor Regulation, Director 7pp 21959 159 24X Fiche 50-000, 84/01/18, 8401250099

8401250249 Discusses util understanding of 10CFR50 4B & App R to 10CFR50 NRC requested to review encl logic diagrams & provide comments on completeness & accuracy
VANDEWALLE, D J Consumers Power Co 84/01/18 CRUTCHFIELD, D Operating Reactors Branch 5 18pp 21933 027 24X
Fiche 50-255, 84/01/18, 8401250249

J Insurance & indemnity information

8401100316 Forwards Endorsement 5 to NELIA & MAELU Certificates N-20 & M-20 Endorsements reflect 1984 advance premium
FRIDUNFELKER, R Consumers Power Co 84/01/06 SALTZMAN, J Office of Nuclear Reactor Regulation, Director 3pp 21763 274 24X
Fiche 50-255, 84/01/06, 8401100316

8401100388 Forwards Endorsement 80 to NELIA Policy NF-179 & Endorsement 69 to MAELU Policy MF-50
FRIDUNFELKER, R Consumers Power Co 84/01/06 SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance) 3pp 21763 140 24X Fiche 50-255, 84/01/06, 8401100388

P Operating license stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015

--8401250015 Informs of issuance of draft rept (NUREG-0820) on SEP Integrated plant safety assessment H/O encl NUREG-0820
DIRCKS, W J Office of the Executive Director for Operations SECY-82-161 82/04/15 2pp 21763 171 24X
Fiche 50-000, 83/10/18, 8401250015

--8401250325 Informs of results of facility SEP integrated safety assessment
DIRCKS, W J Office of the Executive Director for Operations SECY-82-378 82/09/15 58pp 21966 129 24X
Fiche 50-000, 83/10/18, 8401250015

8312070296 INTEGRATED PLANT SAFETY ASSESSMENT REPORT, SYSTEMATIC EVALUATION PROGRAM Palisades Plant Docket No 50-235 (Consumers Power Company)
* Division of Licensing NUREG-0820 S01 83/11/30 37pp Available at NRC 83 75 21416 281 24X Fiche 50-255, 83/11/30, 8312070296

8401040532 Submits updated info to SEP Topic III-5 A, "Operability of Leakage Detection Sys" Requested 831213 Tech Spec change reviewed & approved by nuclear safety board on 831222, not 831213 as indicated wording not affected
JOHNSON, B D Consumers Power Co 83/12/28 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21707 240 24X
Fiche 50-255, 83/12/28, 8401040532

8401040512 Informs of intention to submit action plan & completion schedule re SEP Topic III-6, "Seismic Design Consideration," per SER Plan & schedule will be submitted 30 days after receipt of SER
JOHNSON, B D Carolina Power & Light Co 83/12/29 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21707 297 24X
Fiche 50-255, 83/12/29, 8401040512

101050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/03 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401180252 Summary of 840110 meeting w/util in Bethesda, MD re outstanding environ qualification issues
PAULSON, W A Operating Reactors Branch 5 84/01/17 Operating Reactors Branch 5 11pp 21844 104 24X Fiche 50-255, 84/01/17, 8401180252

8401190409 Requests that final submission of radiological Tech Specs be written according to NUREG-0472, Rev 3, Draft 7 guidance Tech Specs should be submitted by 840731
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/17 VANDEWALLE, D J Consumers Power Co 2pp 21850 096 24X
Fiche 50-255, 84/01/17, 8401190409

8401230352 Notification of 840209 meeting w/util in Bethesda, MD to discuss NRC comments on program plan for detailed control room design review
PAULSON, W A Operating Reactors Branch 5 84/01/19 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21882 341 24X
Fiche 50-255, 84/01/19, 8401230352

8401240187 Requests exemption from App J requirements re full air lock rate test for short duration outages of less than 72 h
Exemption needed as soon as possible
JOHNSON, B Consumers Power Co 84/01/19 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21908 340 24X Fiche 50-255, 84/01/19, 8401240187

8401240397 Forwards safety evaluation of util 830301, 0812 & 1206 responses to NUREG-0737, Item II B 3 re post-accident sampling sys Nine of 11 criteria met Open items should be addressed within 45 days
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/23 VANDEWALLE, D J Consumers Power Co 37pp 21920 154 24X
Fiche 50-255, 84/01/23, 8401240397

8401270101 Notifies that WP Paulson assigned as new project manager for plant, due to reassignments within branch
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/25 VANDEWALLE, D J Consumers Power Co 2pp 21976 324 24X
Fiche 50-255, 84/01/25, 8401270101

8401300223 Requests concurrence on submitted interpretation of 10CFR50, App J, Section III D 2(b)(1) for outages greater than 72 h
JOHNSON, B D Consumers Power Co 84/01/25 CRUTCHFIELD, D Operating Reactors Branch 5 1p 22062 128 24X
Fiche 50-255, 84/01/25, 8401300223

8401300156 Requests schedule for submittal of evaluation to justify unlimited use of modified containment vent & purge sys, within 30 days of receipt of ltr Conference call will be arranged to discuss subj matter Sample Tech Specs encl
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/26 VANDEWALLE, D J Consumers Power Co 11pp 21996 270 24X
Fiche 50-255, 84/01/26, 8401300156

8401300216 Notification of 840214 meeting w/util in Bethesda, MD to discuss proposed steam generator plugging criteria & insp results Agenda encl
PAULSON, W A Operating Reactors Branch 5 84/01/26 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 21977 340 24X
Fiche 50-255, 84/01/26, 8401300216

8401300324 Requests exemption from requirements of 10CFR50, App J, Section III B 2 re personnel air lock equalizing valves Vacuum decay type test will be used to determine leak rate of containment side door equalizing valve
JOHNSON, B D Consumers Power Co 84/01/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21996 293 24X
Fiche 50-255, 84/01/26, 8401300324

Q Inspection reports, IE Bulletins & correspondence

8401040040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401040040

--8401060150 List of SALP results during 1982

* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401050381 Informs that safety injection & refueling water tank support structure insp will not be performed for tank in present partially loaded configuration Insp will not be performed until structure in fully loaded condition, per LER 83-06 JOHNSON, B D Consumers Power Co 83/12/19 KEPLER, J G Region 3, Office of Director 1p 21730 361 24X Fiche 50-255,83/12/19, 8401050381

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/26 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401300315 Forwards IE Insp Rept 50-255/83-29 during Nov-Dec 1983 No noncompliance noted SHAFER, W D Region 3, Office of Director 84/01/05 DEWITT, R B Consumers Power Co 2pp 21996 310 24X Fiche 50-255,84/01/05, 8401300315

--8401300318 IE Insp Rept 50-255/83-29 on 831107-1221 No noncompliance or deviations noted Major areas inspected plant safety, maint/mods, testing, reportable events, IE bulletins & SEP action items JORGENSEN, B L, HELLER, J K, BOYD, D C Region 3, Office of Director 84/01/04 9pp 21996 312 24X Fiche 50-255,84/01/05, 8401300318

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 129pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401300216 Notification of 840214 meeting w/util in Bethesda, MD to discuss proposed steam generator plugging criteria & insp results Agenda encl PAULSON, W A Operating Reactors Branch 5 84/01/26 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 21997 340 24X Fiche 50-255,84/01/26,8401300216

B Reportable occurrences, LERs & related correspondence

8401050381 Informs that safety injection & refueling water tank support structure insp will not be performed for tank in present partially loaded configuration Insp will not be performed until structure in fully loaded condition, per LER 83-06 JOHNSON, B D Consumers Power Co 83/12/19 KEPLER, J G Region 3, Office of Director 1p 21730 361 24X Fiche 50-255,83/12/19, 8401050381

8401040170 LER 83-077/03L-0 on 830812, w/control rods withdrawn & at less than 1/ power, temp average fell below 525 F limit Caused by corrective actions taken to compensate for turbine bypass valve problems W/831223 ltr VANDEWALLE, D J Consumers Power Co 83/12/23 KEPLER, J G Region 3, Office of Director 2pp 21702 016 24X Fiche 50-255,83/12/23, 8401040170

8401160230 PND-III-84-005 on 840108, during plant shutdown, diesel generator 1-1 overheated & was manually tripped, resulting in loss of all onsite power Caused by breaker malfunction Malfunctioning breaker replaced BOYD, D, SHAFER, W Region 3, Office of Director 84/01/10 2pp 21814 220 24X Fiche 50-255,84/01/10,8401160230

8401230190 LER 83-078/03L-0 on 830915, OA audit revealed that Tech Spec Surveillance Procedure FD-1 not performed within required frequency Caused by personnel error FD-1 will be completed prior to plant startup W/840112 ltr JOHNSON, B D Consumers Power Co 84/01/12 KEPLER, J G Region 3, Office of Director 2pp 21884 136 24X Fiche 50-255,84/01/12, 8401230190

V Operator Examinations

8401230253 Forwards updated estimated schedule for nuclear instructor program & operator & instructor licensing programs through FY87, per Generic Ltr 83-40 BORDINE, T C Consumers Power Co 84/01/16 EISENHART, D G Division of Licensing 6pp 21884 290 24X Fiche 50-000,84/01/16, 8401230253

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401030251 Ack receipt of 830902 ltr re emergency exercise scheduled during Nov 1983 Presentation of emergency exercise objectives appropriate in describing scope & objectives of upcoming exercises VERRELLI, D M Division of Project & Resident Programs 83/10/13 PARRIS, H G Tennessee Valley Authority 2pp 21681 152 24X Fiche 50-259,83/10/13,8401030251

--8401030252 Forwards description of objectives for radiological emergency exercise scheduled for wk of 831113-17 Scope of exercise will meet requirements of 10CFR50, App E for full-scale exercise MILLS, L H Tennessee Valley Authority 83/09/02 STOHR, J P Region 2, Office of Director 3pp 21681 154 24X Fiche 50-259,83/10/13,8401030251

8401050468 Forwards IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on 831031-1104 No violations noted VERRELLI, D M Division of Project & Resident Programs 83/12/02 PARRIS, H G Tennessee Valley Authority 2pp 21730 126 24X Fiche 50-259,83/12/02,8401050468

--8401050477 IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on 831031-1104 No violations noted Major areas inspected fire protection/prevention program & implementation GIBBONS, T D Region 2, Office of Director 83/11/30 7pp 21730 128 24X Fiche 50-259,83/12/02,8401050468

8401090237 Forwards IF Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16 No violations noted VERRELLI, D M Division of Project & Resident Programs 83/12/20 PARRIS, H G Tennessee Valley Authority 2pp 21730 291 24X Fiche 50-259,83/12/20,8401090237

--8401090264 IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16 No violations noted Major areas inspected emergency preparedness exercise DECKER, T R Region 2, Office of Director 83/12/13 9pp 21730 293 24X Fiche 50-259,83/12/20,8401090237

8401060438 Confirms actions discussed in 831220 telcon re failure to control vital area access All security personnel to be retrained & certified no later than 840131 O'REILLY, J P Region 2, Office of Director, 83/12/21 PARRIS, H G Tennessee Valley Authority 2pp 21740 086 24X Fiche 50-259,83/12/21,8401060438

8401240500 Confirms 840113 mgt meeting in Region II ofcs to discuss proposed changes to emergency plan & procedures, per 840109 telcon Meeting notification encl LEWIS, R C Division of Project & Resident Programs 84/01/10 PARRIS, H G Tennessee Valley Authority 2pp 21920 076 24X Fiche 50-259,84/01/10,8401240500

DOCKETED ITEMS

8401170321 Ack receipt of 831018 ltr transmitting 830815 rev to guard training & qualification plan changes inconsistent w/ provisions of 10CFR50.34p Previously approved plan must be utilized Encl withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 84/01/12
FARRIS, H G Tennessee Valley Authority 3pp 21830 350 24X
Fiche 50-259, 84/01/12, 8401170321

8401240398 Ack receipt of 831223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
O'REILLY, J P Region 2, Office of Director 84/01/13 FARRIS, H G
Tennessee Valley Authority 1p 21920 142 24X
Fiche 50-259, 84/01/13, 8401240398

--8401240407 Suppl 831123 response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
Corrective actions new health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P
Region 2, Office of Director 4pp 21920 143 24X
Fiche 50-259, 84/01/13, 8401240398

--8401240428 Forwards supplemental response to 830802 request re IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 New health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/09/07 O'REILLY, J P
Region 2, Office of Director 4pp 21920 150 24X
Fiche 50-259, 84/01/13, 8401240398

8401240611 Releases public version of revised radiological emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 252 24X Fiche 50-259, 84/01/20, 8401240611

--8401240616 Forwards public version of Rev 6 to radiological emergency plan & revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr & IP-3 re alert
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21945 253 24X Fiche 50-259, 84/01/20, 8401240611

--8401240621 Public version of Rev 6 to radiological emergency plan
* Tennessee Valley Authority 83/12/22 49pp 21945 254 24X
Fiche 50-259, 84/01/20, 8401240611

--8401240626 Public version of revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr, IP-24 re earthquake emergency procedure & IP-3 re alert
CHINN, T L Tennessee Valley Authority 83/10/12 112pp
21945 303 24X Fiche 50-259, 84/01/20, 8401240611

8401250110 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 079 24X Fiche 50-000, 84/01/20, 8401250110

--8401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure MSECC IP-6, "Emergency Preparedness" & DIPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080 24X Fiche 50-000, 84/01/20, 8401250110

--8401250126 Public version of revised emergency plan implementing procedures, including Procedures MSECC IP-6, "Emergency Preparedness" & DIPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MAXWELL, R B Tennessee Valley Authority 83/11/10 34pp
21959 091 24X Fiche 50-000, 84/01/20, 8401250110

General correspondence

1050263 Designates MP Schmierback, RJ Johnson & DM McCarthy as acting officials during author absence
IRUCH, A Tennessee Valley Authority 83/12/29 MARLAR, J
Environmental Protection Agency 1p 21728 303 24X
Fiche 50-259, 83/12/29, 8401050263

Financial information

200194 Forwards Annual Financial Rept 1982, Vols I & II
MERR, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I
FARRIS, H G Tennessee Valley Authority 84/01/12 75pp
21865 002 24X Fiche 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II
FARRIS, H G Tennessee Valley Authority 84/01/12 96pp
21865 077 24X Fiche 50-000, 84/01/12, 8401200194

P Operating license stage documents & correspondence

8401120524 Forwards Amend 93 to License DPR-33 & safety evaluation Amend revises Tech Specs to reflect mod which adds analog transmitter trip units in place of mechanical-type switches in reactor protection sys
CLARK, R J Operating Reactors Branch 2 83/12/16 FARRIS, H G
Tennessee Valley Authority 2pp 21796 168 24X
Fiche 50-259, 83/12/16, 8401120524

--8401120528 Amend 93 to License DPR-33, revising Tech Specs to reflect mod which adds analog transmitter trip units in place of switches originally used in reactor protection sys
VASSALLO, D B Operating Reactors Branch 2 83/12/16 8pp
21796 170 24X Fiche 50-259, 83/12/16, 8401120524

--8401120529 Safety evaluation supporting Amend 93 to License DPR-33
* Office of Nuclear Reactor Regulation, Director 83/12/16 7pp
21796 178 24X Fiche 50-259, 83/12/16, 8401120524

8401160008 Forwards confirmatory order on licensee 831213 commitments on pipe crack-related issues & safety evaluation accepting licensee actions to correct intergranular stress corrosion cracking Plant restart authorized
VASSALLO, D B Operating Reactors Branch 2 83/12/19 FARRIS, H G
Tennessee Valley Authority 2pp 21821 321 24X
Fiche 50-259, 83/12/19, 8401160008

--8401160011 Order confirming licensee 831213 commitments on pipe crack-related issues
EISENHUT, D G Division of Licensing 83/12/19 Tennessee
Valley Authority 7pp 21821 323 24X Fiche 50-259, 83/12/19, 8401160008

--8401160014 Safety evaluation conditionally accepting licensee actions to resolve intergranular stress corrosion cracking Plans for insp/mod of recirculation & piping sys should be submitted at least 1 month before next refueling outage
KOD, W, HAZLETON, W, CLARK, R Office of Nuclear Reactor
Regulation, Director 83/12/19 10pp 21821 330 24X
Fiche 50-259, 83/12/19, 8401160008

8401170509 Forwards request for addl info re radiological effluent Tech Specs Telcon should be scheduled within 30 days to discuss & resolve questions
VASSALLO, D B Operating Reactors Branch 2 83/12/20 FARRIS, H G
Tennessee Valley Authority 13pp 21847 137 24X
Fiche 50-259, 83/12/20, 8401170509

8401240047 Forwards Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends add stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
CLARK, R J Operating Reactors Branch 2 83/12/27 FARRIS, H G
Tennessee Valley Authority 2pp 21945 203 24X
Fiche 50-259, 83/12/27, 8401240047

--8401240091 Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively, adding stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
VASSALLO, D B Operating Reactors Branch 2 83/12/27 18pp
21945 205 24X Fiche 50-259, 83/12/27, 8401240047

--8401240054 Safety evaluation supporting Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/27 2pp
21945 223 24X Fiche 50-259, 83/12/27, 8401240047

8401260475 Notifies that TMI Action Items II K 3 30 & II K 3 31 completed, based on NRC 831213 acceptance of GE small break LOCA model Confirmation of Model use requested within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/12/28 FARRIS, H G
Tennessee Valley Authority 2pp 21959 335 24X
Fiche 50-259, 83/12/28, 8401260475

8401060051 Forwards Rev D to "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
Rept describes torus mods implemented & gives supporting analyses
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21738 098 24X
Fiche 50-259, 84/01/03, 8401060051

--B401060067 Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept "
ROCHELLE, J K, DUKE, S T, WILLIAMS, J S Tennessee Valley
Authority CEB-83-34 R00 83/12/21 20pp 21738 100 24X
Fiche 50-259, 84/01/03, B401060051

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, B401090221

B401160077 Forwards details of NUREG-0612, Section 5.1.1 guideline & compliance methodology review & response to Technical Evaluation Rept CS257-61/62/63 re special lifting device review, per B30526 ltr concerning control of heavy loads
MILLS, L M Tennessee Valley Authority 84/01/06 VASSALLO, D B
Operating Reactors Branch 2 19pp 21815 067 24X
Fiche 50-259, 84/01/06, B401160077

B401310465 Requests review of potential overvoltage condition when using backup 161 kV offsite power source Assessment of in-plant voltages & discussion of general plan to resolve condition requested within 45 days of receipt of ltr
VASSALLO, D B Operating Reactors Branch 2 84/01/06 PARRIS, H O
Tennessee Valley Authority 3pp 22036 336 24X
Fiche 50-259, 84/01/06, B401310465

B401170400 Forwards response to Generic Ltr B3-41 re fast cold starts of diesel generators Encl table for Browns Ferry shows times surveillance testing, maint activities & actual demand caused diesel generators to start
MILLS, L M Tennessee Valley Authority 84/01/11 EISENHUT, D O
Division of Licensing 3pp 21829 216 24X Fiche 50-000, 84/01/11, B401170400

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401310134 Informs that revised integrated schedule will not be available by B40131 New schedule will be submitted by B40330
MILLS, L M Tennessee Valley Authority 84/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 22022 099 24X Fiche 50-259, 84/01/26, B401310134

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401080468 Forwards IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on B31031-1104 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/02
PARRIS, H O Tennessee Valley Authority 2pp 21730 126 24X
Fiche 50-259, 83/12/02, B401080468

--B401080477 IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on B31031-1104 No violations noted Major areas inspected fire protection/prevention program & implementation.
O'BONNS, T D, Region 2, Office of Director CNLON, T E Division of Engineering & Operational Programs 83/11/30 7pp, 21730 128 24X Fiche 50-259, 83/12/02, B401080468

B401050649 Forwards IE Insp Repts 50-259/83-39, 50-260/83-39 & 50-296/83-39 on B30926-30 No violations noted
VERRELLI, D M Division of Project & Resident Programs, 83/12/08
PARRIS, H O, Tennessee Valley Authority 2pp 21725 200 24X
Fiche: 50-259, 83/12/08, B401050649

--B401050655 IE Insp Repts 50-259/83-39, 50-260/83-39 & 50-296/83-39 on B30926-30 No violations noted Major areas inspected Unit 1 weld repair exposure control
DEBS, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/16 6pp 21725 202 24X Fiche 50-259, 83/12/08, B401050649

B401090237 Forwards IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on B31115-16 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/20
PARRIS, H O Tennessee Valley Authority 2pp 21750 291 24X
Fiche 50-259, 83/12/20, B401090237

--B401090264 IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on B31115-16 No violations noted Major areas inspected emergency preparedness exercise
DECKER, T R Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety 83/12/13 9pp 21750 293 24X Fiche 50-259, 83/12/20, B401090237

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B401050452 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43
VERRELLI, D M Division of Project & Resident Programs 83/12/28
PARRIS, H O Tennessee Valley Authority 1p 21731 149 24X
Fiche 50-259, 83/12/28, B401050452

--B401050456 Responds to NRC B31118 ltr re violations noted in IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 Corrective actions tagboards & fuel transfer data sheets corrected & checked Undocumented temporary test pressure gauge removed
KAMMER, D S Tennessee Valley Authority 83/12/16 O'REILLY, J P
Region 2, Office of Director 5pp 21731 150 24X
Fiche 50-259, 83/12/28, B401050452

--B401050462 Forwards IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 on B30926-1025 & notice of violation.
VERRELLI, D M Division of Project & Resident Programs 83/11/18
PARRIS, H O Tennessee Valley Authority 2pp 21731 155 24X
Fiche 50-259, 83/12/28, B401050452

--B401050465 Notice of violation from insp on B30926-1025
* Region 2, Office of Director B3/11/18 2pp 21731 157 24X
Fiche 50-259, 83/12/28, B401050452

--B401050472 IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 on B30926-1025 Violation noted correct tagboard not verified prior to Unit 3 unload & temporary test pressure form not issued
PAULK, O L, Region 2, Office of Director CANTRELL, F B Division of Project & Resident Programs B3/11/17 7pp 21731 159 24X
Fiche 50-259, 83/12/28, B401050452

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401240461 Supply B21115 response to violations noted in IE Insp Repts 50-259/82-27, 50-260/82-27 & 50-296/82-27 GET training for operators expected by B31231 incomplete Completion expected by B40131
MILLS, L M Tennessee Valley Authority 84/01/03 O'REILLY, J P
Region 2, Office of Director 1p 21708 147 24X
Fiche 50-259, 84/01/03, B401240461

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401240398 Ack receipt of B31223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
O'REILLY, J P Region 2, Office of Director 84/01/13 PARRIS, H O
Tennessee Valley Authority 1p 21920 142 24X
Fiche 50-259, 84/01/13, B401240398

DOCKETED ITEMS

--B401240407 Supply B31123 response to NRC B30321 ltr re violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03
Corrective actions new health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P
Region 2, Office of Director 4pp 21920 143 24X
Fiche 50-259, B4/01/13, B401240398

--B401240414 Ack receipt of B30907 response re steps taken to correct violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 Supplemental response dealing w/Item B requested within 30 days
O'REILLY, J P Region 2, Office of Director 83/11/23
PARRIS, H G Tennessee Valley Authority 2pp 21920 147 24X
Fiche 50-259, B4/01/13, B401240398

--B401240422 Ack receipt of B30907 ltr containing supplemental response to IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03
Info under evaluation
LEWIS, R C Division of Project & Resident Programs 83/10/12
PARRIS, H G Tennessee Valley Authority 1p 21920 149 24X
Fiche 50-259, B4/01/13, B401240398

--B401240428 Forwards supplemental response to B30802 request re IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 New health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/09/07 O'REILLY, J P
Region 2, Office of Director 4pp 21920 150 24X
Fiche 50-259, B4/01/13, B401240398

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R Periodic operating reports & related correspondence

B401120307 Monthly operating repts for Nov 1983 W/B31209 ltr
THOM, T, JONES, G T Tennessee Valley Authority 83/11/30 Office
of Resource Management, Director 37pp 21792 072 24X
Fiche 50-259, B3/11/30, B401120307

B401270398 Monthly operating repts for Dec 1983 W/B40110 ltr
THOM, T, SHINDELL, J E Tennessee Valley Authority 83/12/31
Office of Resource Management, Director 34pp 21976 271 24X
Fiche 50-259, B3/12/31, B401270398

S Reportable occurrences, LERs & related correspondence

B401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records
2pp 21736 343 24X Fiche 50-000, B3/10/07, B401050064

B401050157 NPDES noncompliance notification on B31205, sewage treatment plant effluent grab sample collected on B31129 exceeded max permit limitations caused by excessive daily total flow
Sewage lagoon designed to replace sewage treatment plant
BRUCH, A Tennessee Valley Authority 83/12/23 MARLAR, J
Environmental Protection Agency 2pp 21727 334 24X
Fiche 50-259, B3/12/23, B401050157

B401050234 NPDES noncompliance notification on B31013, sewage treatment plant effluent limit exceeded max limits caused by high flows washing out solids in chlorine contact tank
Sewage lagoon will be replaced w/sewage treatment plant
BRUCH, A Tennessee Valley Authority 83/12/23 MARLAR, J
Environmental Protection Agency 2pp 21729 084 24X
Fiche 50-259, B3/12/23, B401050234

31120297 Telecopy RO 50-259/B3073 on B31231, reactor water sample indicated chloride concentration of 525 ppb Steam flow greater than 100,000 lbm/h caused by possible resin intrusion investigation in progress
JONES, G T Tennessee Valley Authority 84/01/03 Region 2,
Office of Director 1p 21792 174 24X Fiche 50-259, B4/01/03,
301120297

B401120427 Part 21 rept re Gilbert Mfg Co nylon bolts used to make connections between positive bus & leg of distribution panel
breakers Nylon bolts to be replaced w/brass bolts
PARRIS, H G Tennessee Valley Authority 84/01/04 O'REILLY, J P
Region 2, Office of Director 4pp 21791 013 24X
Fiche 50-259, B4/01/04, B401120427

B401240254 Part 21 rept re problems w/ELMA power supplies bought as spare parts for two mods Defective wiring, cold solder joints & overall poor quality workmanship found Parts installed only in reactor protection sys
PARRIS, H G Tennessee Valley Authority 84/01/11 O'REILLY, J P
Region 2, Office of Director 3pp 21912 359 24X
Fiche 50-259, B4/01/11, B401240254

B401240442 Updated LER B3-064/03X-1 on B31029, stack gas sample pumps A & B tripped on overcurrent Pump B tripped again on B31104 & pump A would not start Caused by shorted winding in motor A
Motor overload heater sizes increased W/B40111 ltr
SOLLEY, S W, COFFEY, J A Tennessee Valley Authority 84/01/11
O'REILLY, J P Region 2, Office of Director 3pp 21915 190 24X
Fiche 50-259, B4/01/11, B401240442

B401170248 NPDES noncompliance notification on B31221, sewage treatment plant effluent sample exceeded max permit limitations
Caused by high flows overloading treatment capacity of sys
Sewage treatment plant will be replaced in 1984
BRUCH, A Tennessee Valley Authority 84/01/12 MARLAR, J
Environmental Protection Agency 2pp 21833 331 24X
Fiche 50-259, B4/01/12, B401170248

B401170288 NPDES noncompliance notification on B31223, sample from condenser cooling water pumping station discharge showed pH value of 9.7 Suspected to be caused by loss of sodium hydroxide from tanker trailer during unloading
BRUCH, A Tennessee Valley Authority 84/01/12 MARLAR, J
Environmental Protection Agency 2pp 21832 299 24X
Fiche 50-259, B4/01/12, B401170288

B401260077 LER B3-073/01T-0 on B31231, reactor coolant sample indicated chloride concentration of 525 ppb & conductivity & offgas radiation level increased while pH decreased Caused by resin intrusion into reactor vessel Trap replaced W/B40116 ltr
LE, H C, COFFEY, J A Tennessee Valley Authority 84/01/16
O'REILLY, J P Region 2, Office of Director 3pp 21957 014 24X
Fiche 50-259, B4/01/16, B401260077

B401240004 PNO-II-B4-002 on B40118, 12-inch raw cooling water line, located 15 ft underground, broke & flooded underground vault
housing devices for treating offgas activity Cause not determined Water pumped out
CANTRELL, F S, VERRELLI, D M Region 2, Office of Director
B4/01/18 2pp 21912 307 24X Fiche 50-259, B4/01/18, B401240004

B401260138 LER B3-074/03L-0 on B31228, during refueling, degraded flow condition discovered on radiation monitor 1-RM-90-250
Caused by normal wear & degradation of Schwitzer Series 325 sample pump Pump replaced W/B40120 ltr
SHARPE, T J, COFFEY, J A Tennessee Valley Authority 84/01/20
O'REILLY, J P Region 2, Office of Director 3pp 21957 048 24X
Fiche 50-259, B4/01/20, B401260138

B401300233 LER B4-001-00 on B40103, RHR pump ID started w/o receiving automatic signal or manual start signal from control room
Caused by laborers performing decontamination work Laborers cautioned W/B40123 ltr
ROZEAR, C J, JONES, G T Tennessee Valley Authority 84/01/23
NRC - No Detailed Affiliation Given 3pp 22062 059 24X
Fiche 50-259, B4/01/23, B401300233

B401310404 LER B4-002-00 on B40103, setpoint value of pressure switches PS-64-57A-D found above Tech Spec 3.2 B limits Caused by static O-ring Model 12N-AA4 setpoint drift Switches recalled Surveillance test revised W/B40124 ltr
MORRIS, K M, JONES, J T Tennessee Valley Authority 84/01/24
NRC - No Detailed Affiliation Given 4pp 22018 043 24X
Fiche 50-259, B4/01/24, B401310404

B401300199 NPDES noncompliance notification on B40110, grab sample for sewage treatment plant effluent exceeded max limitation High flows contributed to noncompliance Sewage lagoon designed to replace sewage treatment plant Approval received B31222
BRUCH, A Tennessee Valley Authority 84/01/25 MARLAR, J
Environmental Protection Agency 2pp 21995 314 24X
Fiche 50-259, B4/01/25, B401300199

V Operator Examinations

8401060338 Requests submittal by 840119 of selected ref matl in approved list in Encl 1 to meet schedules for written & oral licensing exams scheduled for 840316 & 17, respectively
W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/12/16
GREEN, H J Tennessee Valley Authority 2pp 21741 18B 24X
Fiche 50-259, 83/12/16, 8401060338

--8401240428 Forwards supplemental response to 830802 request re IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 New health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/09/07 O'REILLY, J P
Region 2, Office of Director 4pp 21920 150 24X
Fiche 50-259, 84/01/13, 8401240398

8401240611 Releases public version of revised radiological emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21943 252 24X Fiche 50-259, 84/01/20, 8401240611

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8401030251 Ack receipt of 830902 ltr re emergency exercise scheduled during Nov 1983 Presentation of emergency exercise objectives appropriate in describing scope & objectives of upcoming exercises
VERRELLI, D M Division of Project & Resident Programs 83/10/13
PARRIS, H G Tennessee Valley Authority 2pp 21681 152 24X
Fiche 50-259, 83/10/13, 8401030251

--8401240616 Forwards public version of Rev 6 to radiological emergency plan & revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr & IP-3 re alert
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21943 253 24X Fiche 50-259, 84/01/20, 8401240611

--8401240621 Public version of Rev 6 to radiological emergency plan
* Tennessee Valley Authority 83/12/22 49pp 21943 254 24X
Fiche 50-259, 84/01/20, 8401240611

--8401240626 Public version of revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr, IP-24 re earthquake emergency procedure & IP-3 re alert
CHINN, T L Tennessee Valley Authority 83/10/12 112pp
21945 303 24X Fiche 50-259, 84/01/20, 8401240611

8401250110 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 079 24X Fiche 50-000, 84/01/20, 8401250110

--8401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure MSEC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080 24X Fiche 50-000, 84/01/20, 8401250110

--8401250126 Public version of revised emergency plan implementing procedures, including Procedures MSEC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MAXWELL, R D Tennessee Valley Authority 83/11/10 34pp
21959 081 24X Fiche 50-000, 84/01/20, 8401250110

H General correspondence

8401050263 Designates MP Schnierback, RJ Johnson & DM McCarthy as acting officials during author absence
BRUCH, A Tennessee Valley Authority 83/12/29 MARLAR, J
Environmental Protection Agency 1p 21728 303 24X
Fiche 50-259, 83/12/29, 8401050263

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II
KAMMER, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I
PARRIS, H G Tennessee Valley Authority 84/01/12 75pp
21865 002 24X Fiche 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II
PARRIS, H G Tennessee Valley Authority 84/01/12 76pp
21865 077, 24X Fiche 50-000, 84/01/12, 8401200194

P Operating license stage documents & correspondence

8401170509 Forwards request for addl info re radiological effluent Tech Specs Telcon should be scheduled within 30 days to discuss & resolve questions
VASSALLO, D B Operating Reactors Branch 2 83/12/20 PARRIS, H G
Tennessee Valley Authority 13pp 21847 137 24X
Fiche 50-259, 83/12/20, 8401170509

--8401240407 Suppls 831123 response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
Corrective actions new health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P
Region 2, Office of Director 4pp 21920 143 24X
Fiche 50-259, 84/01/13, 8401240398

8401060438 Confirms actions discussed in 831220 telcon re failure to control vital area access All security personnel to be restrained & certified no later than 840131
O'REILLY, J P Region 2, Office of Director 83/12/21 PARRIS, H G
Tennessee Valley Authority 2pp 21740 086 24X
Fiche 50-259, 83/12/21, 8401060438

8401240500 Confirms 840113 mgt meeting in Region II ofcs to discuss proposed changes to emergency plan & procedures per 840109 telcon Meeting notification encl
LEWIS, R C Division of Project & Resident Programs 84/01/10
PARRIS, H G Tennessee Valley Authority 2pp 21920 076 24X
Fiche 50-259, 84/01/10, 8401240500

8401170321 Ack receipt of 831018 ltr transmitting 830815 rev to guard training & qualification plan Changes inconsistent w/ provisions of 10CFR50.54p Previously approved plan must be utilized Encl withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 84/01/12
PARRIS, H G Tennessee Valley Authority 3pp 21830 330 24X
Fiche 50-259, 84/01/12, 8401170321

8401240398 Ack receipt of 831223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
O'REILLY, J P Region 2, Office of Director 84/01/13 PARRIS, H G
Tennessee Valley Authority 1p 21920 142 24X
Fiche 50-259, 84/01/13, 8401240398

DOCKETED ITEMS

B401240047 Forwards Amends 94, 87 & 60 to Licenses DPR-33, DPR-32 & DPR-6B, respectively & safety evaluation Amends add stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
CLARK, R J Operating Reactors Branch 2 83/12/27 PARRIS, H O
Tennessee Valley Authority 2pp 21945 203 24X
Fiche 50-259, 83/12/27, B401240047

--B401240051 Amends 94, 87 & 60 to Licenses DPR-33, DPR-32 & DPR-6B, respectively, adding stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
VASSALLO, D B Operating Reactors Branch 2 83/12/27 18pp
21945 205 24X Fiche 50-259, 83/12/27, B401240047

--B401240054 Safety evaluation supporting Amends 94, 87 & 60 to Licenses DPR-33, DPR-32 & DPR-6B, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/27 2pp
21945 223 24X Fiche 50-259, 83/12/27, B401240047

B401260475 Notifies that TMI Action Items II K 3 30 & II K 3 31 completed, based on NRC 831213 acceptance of GE small break LOCA model Confirmation of Model use requested within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/12/28 PARRIS, H O
Tennessee Valley Authority 2pp 21959 335 24X
Fiche 50-259, 83/12/28, B401260475

B401060051 Forwards Rev 0 to "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
Rept describes torus mods implemented & gives supporting analyses
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21738 098 24X
Fiche 50-259, 84/01/03, B401060051

--B401060067 "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
ROCHELLE, J K, DUKE, S T, WILLIAMS, J S Tennessee Valley Authority CEB-83-34 R00 83/12/21 20pp 21738 100 24X
Fiche 50-259, 84/01/03, B401060051

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/05, B401090221

B401060077 Forwards details of NUREG-0612, Section 5.1.1 guideline & compliance methodology review & response to Technical Evaluation Rept C5257-61/62/63 re special lifting device reviewed per 830926 ltr concerning control of heavy loads
MILLS, L M Tennessee Valley Authority 84/01/05 VASSALLO, D B
Operating Reactors Branch 2 19pp 21815 067 24X
Fiche 50-259, 84/01/05, B401060077

B401310465 Requests review of potential overvoltage condition when using backup 161 kV offsite power source Assessment of in-plant voltages & discussion of general plan to resolve condition requested within 45 days of receipt of ltr
VASSALLO, D B Operating Reactors Branch 2 84/01/06 PARRIS, H O
Tennessee Valley Authority 3pp 22036 336 24X
Fiche 50-259, 84/01/06, B401310465

B401170400 Forwards response to Generic Ltr 83-41 re fast cold starts of diesel generators Encl table for Browns Ferry shows times surveillance testing, maint activities & actual demand caused diesel generators to start
MILLS, L M Tennessee Valley Authority 84/01/11 EISENHUT, D O
Division of Licensing 3pp 21829 216 24X Fiche 50-000, 84/01/11, B401170400

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401310134 Informs that revised integrated schedule will not be available by B40131 New schedule will be submitted by B40330
MILLS, L M Tennessee Valley Authority 84/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 22022 099 24X Fiche 50-259, 84/01/26, B401310134

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 103pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401050468 Forwards IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on B31031-1104 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/02
PARRIS, H O Tennessee Valley Authority 2pp 21730 126 24X
Fiche 50-259, 83/12/02, B401050468

--B401050477 IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on B31031-1104 No violations noted Major areas inspected fire protection/prevention program & implementation
O'BONNS, T D Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/11/30 7pp 21730 128 24X
Fiche 50-259, 83/12/02, B401050468

B401050649 Forwards IE Insp Repts 50-259/83-39, 50-260/83-39 & 50-296/83-39 on B30926-30 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/08
PARRIS, H O Tennessee Valley Authority 2pp 21725 200 24X
Fiche 50-259, 83/12/08, B401050649

--B401050655 IE Insp Repts 50-259/83-39, 50-260/83-39 & 50-296/83-39 on B30926-30 No violations noted Major areas inspected Unit 1 weld repair exposure control
DEBS, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/16 6pp 21725 202 24X
Fiche 50-259, 83/12/08, B401050649

B401090237 Forwards IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on B31115-16 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/20
PARRIS, H O Tennessee Valley Authority 2pp 21750 291 24X
Fiche 50-259, 83/12/20, B401090237

--B401090264 IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on B31115-16 No violations noted Major areas inspected emergency preparedness exercise
DECKER, T R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/12/13 9pp
21750 293 24X Fiche 50-259, 83/12/20, B401090237

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DERYONG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B401050452 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43
VERRELLI, D M Division of Project & Resident Programs 83/12/28
PARRIS, H O Tennessee Valley Authority 1p 21731 149 24X
Fiche 50-259, 83/12/28, B401050452

--B401050456 Responds to NRC B31118 ltr re violations noted in IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 Corrective actions tagboards & fuel transfer data sheets corrected & checked Undocumented temporary test pressure gauge removed
HAMMER, D S Tennessee Valley Authority 83/12/16 O'REILLY, J P
Region 2, Office of Director 5pp 21731 150 24X
Fiche 50-259, 83/12/28, B401050452

--B401050462 Forwards IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 on B30926-1025 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/11/18
PARRIS, H O Tennessee Valley Authority 2pp 21731 155 24X
Fiche 50-259, 83/12/28, B401050452

--B401050465 Notice of violation from insp on B30926-1025
* Region 2, Office of Director 83/11/18 2pp 21731 157, 24X
Fiche 50-259, 83/12/28, B401050452

--B401050472 IE Insp Repts 50-259/83-43, 50-260/83-43 & 50-296/83-43 on B30926-1025 Violation noted correct tagboard not verified prior to Unit 3 unload & temporary test pressure form not issued
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/11/17 7pp 21731 159 24X
Fiche 50-259, 83/12/28, B401050452

DOCKETED ITEMS

57

B312120093 IE Info Notice B3-B4, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B401240461 Suppl B21115 response to violations noted in IE Insp Repts 50-259/82-27, 50-260/82-27 & 50-296/82-27 GET training for operators expected by B31231 incomplete Completion expected by B40131
MILLS, L M Tennessee Valley Authority B4/01/03 O'REILLY, J P Region 2, Office of Director 1p 21908 147 24X
Fiche 50-259, B4/01/03, B401240461

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Bheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401240398 Ack receipt of B31223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
O'REILLY, J P Region 2, Office of Director B4/01/13 PARRIS, H O Tennessee Valley Authority 1p 21920 142 24X
Fiche 50-259, B4/01/13, B401240398

--B401240407 Suppl B31123 response to NRC B30321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
Corrective actions new health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority B3/12/23 O'REILLY, J P Region 2, Office of Director 4pp 21920 143 24X
Fiche 50-259, B4/01/13, B401240398

--B401240414 Ack receipt of B30907 response re steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 Supplemental response dealing w/Item B requested within 30 days
O'REILLY, J P Region 2, Office of Director B3/11/23 PARRIS, H O Tennessee Valley Authority 2pp 21920 147 24X
Fiche 50-259, B4/01/13, B401240398

--B401240422 Ack receipt of B30907 ltr containing supplemental response to IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
Info under evaluation
LEWIS, R C Division of Project & Resident Programs B3/10/12 PARRIS, H O Tennessee Valley Authority 1p 21920 149 24X
Fiche 50-259, B4/01/13, B401240398

--B401240428 Forwards supplemental response to B30802 request re IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 New health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority B3/09/07 O'REILLY, J P Region 2, Office of Director 4pp 21920 150 24X
Fiche 50-259, B4/01/13, B401240398

B312120114 IE Info Notice B4-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp. 22000 001. 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Beated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp. 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R. Periodic operating reports & related correspondence

B401120307 Monthly operating repts for Nov 1983, W/B31209 ltr
THOM, T, JONES, G T Tennessee Valley Authority B3/11/30 Office of Resource Management, Director 37pp 21792 072 24X
Fiche 50-259, B3/11/30, B401120307.

B401270398 Monthly operating repts for Dec 1983 W/B40110 ltr
THOM, T, SWINDELL, J E Tennessee Valley Authority B3/12/31 Office of Resource Management, Director. 34pp 21976 271 24X
Fiche: 50-259, B3/12/31, B401270398

S Reportable occurrences, LERs & related correspondence

B401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp B3/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000, B3/10/07, B401050064

B401030225 Updated LER B3-005/03X-1 on B30216, during refueling outage, primary containment leak rate exceeded Tech Spec Caused by leak on valve 2-FCV-64-20 at flange gasket Flange bolts tightened W/B31222 ltr
GREEN, H J Tennessee Valley Authority B3/12/22 O'REILLY, J P Region 2, Office of Director 3pp 21682 344 24X
Fiche 50-260, B3/12/22, B401030225

B401050157 NPDES noncompliance notification on B31203, sewage treatment plant effluent grab sample collected on B31129 exceeded max permit limitations Caused by excessive daily total flow
Sewage lagoon designed to replace sewage treatment plant
BRUCH, A Tennessee Valley Authority B3/12/23 MARLAR, J Environmental Protection Agency 2pp 21727 334 24X
Fiche 50-259, B3/12/23, B401050157

B401050234 NPDES noncompliance notification on B31013, sewage treatment plant effluent limit exceeded max limits Caused by high flows washing out solids in chlorine contact tank
Sewage lagoon will be replaced w/sewage treatment plant
BRUCH, A Tennessee Valley Authority B3/12/23 MARLAR, J Environmental Protection Agency 2pp 21729 084 24X
Fiche 50-259, B3/12/23, B401050234

B401120427 Part 21 rept re Gilbert Mfg Co nylon bolts used to make connections between positive bus & leg of distribution panel
breakers Nylon bolts to be replaced w/brass bolts
PARRIS, H O Tennessee Valley Authority B4/01/04 O'REILLY, J P Region 2, Office of Director 4pp 21791 013 24X
Fiche 50-259, B4/01/04, B401120427

B401120309 LER B3-078/03L-0 on B31207, while isolating valve 1-FCV-74-66 for maint, RHR cross tie connection isolated Caused by maint activities on RHR sys on Units 1 & 3 Cross tie connection restored W/B40105 ltr
HOLDER, E T, GREEN, H J Tennessee Valley Authority B4/01/06 O'REILLY, J P Region 2, Office of Director 3pp 21793 360 24X
Fiche 50-260, B4/01/06, B401120309

B401170028 LER B3-079/03L-0 on B31212, discovered that Surveillance Instruction 4.2 R-1, "Instrumentation That Initiates or Controls Core Standby Cooling Sys, Reactor Low Water Level," not performed within max frequency interval W/B40110 ltr
CAMPELLE, O D, COFFEY, J A Tennessee Valley Authority B4/01/11 O'REILLY, J P Region 2, Office of Director 3pp 21834 088 24X
Fiche 50-260, B4/01/11, B401170028

B401240234 Part 21 rept re problems w/ELMA power supplies bought as spare parts for two mods Defective wiring, cold solder joints & overall poor quality workmanship found Parts installed only in reactor protection sys
PARRIS, H O Tennessee Valley Authority B4/01/11 O'REILLY, J P Region 2, Office of Director 3pp 21912 359 24X
Fiche 50-259, B4/01/11, B401240234

B401170248 NPDES noncompliance notification on B31221, sewage treatment plant effluent sample exceeded max permit limitations
Caused by high flows overloading treatment capacity of sys
Sewage treatment plant will be replaced in 1984
BRUCH, A Tennessee Valley Authority B4/01/12 MARLAR, J Environmental Protection Agency 2pp 21833 331 24X
Fiche 50-259, B4/01/12, B401170248

B401170288 NPDES noncompliance notification on B31223, sample from condenser cooling water pumping station discharge showed pH value of 9.7 Suspected to be caused by loss of sodium hydroxide from tanker trailer during unloading
BRUCH, A Tennessee Valley Authority B4/01/12 MARLAR, J Environmental Protection Agency 2pp 21832 299 24X
Fiche 50-259, B4/01/12, B401170288

B401240502 LER B3-080/03L-0 on B31214, while performing surveillance test of reactor protective sys high water level in scram discharge tank, transmitter LT-B5-450 found to exceed max response time Cause unknown W/B40110 ltr
CHAMBERS, O T, COFFEY, J A Tennessee Valley Authority B4/01/12 O'REILLY, J P Region 2, Office of Director 3pp 21907 346 24X
Fiche. 50-260, B4/01/12, B401240502

B401240004 PNO-II-B4-002 on B40118, 12-inch row cooling water line, located 15 ft underground, broke & flooded underground vault
housing devices for treating offgas activity Cause not determined Water pumped out
CANTRELL, F B, VERRELLI, D M Region 2, Office of Director B4/01/18 2pp 21912 307 24X Fiche 50-259, B4/01/18, B401240004

DOCKETED ITEMS

8401260346 LER 83-082/03L-Q on 831223, during normal operation, recirculation pump 2A tripped due to actuation of relay 2A-W21A neutral overvoltage. Caused by gouged insulation on phase C conductor in cable 2PP1005 W/840119 ltr
CHRISTOPHER, W., COFFEY, J A Tennessee Valley Authority 84/01/19
O'REILLY, J P Region 2, Office of Director 3pp 21956 021 24X
Fiche 50-260, 84/01/19, 8401260346

8401300199 NPDES noncompliance notification on 840110, grab sample for sewage treatment plant effluent exceeded max limitation High flows contributed to noncompliance. Sewage lagoon designed to replace sewage treatment plant. Approval received 831222
BRUCK, A Tennessee Valley Authority 84/01/25 MARLAR, J
Environmental Protection Agency 2pp 21995 314 24X
Fiche 50-259, 84/01/25, 8401300199

V Operator Examinations

8401060338 Requests submittal by 840119 of selected ref matl in approved list in Encl 1 to meet schedules for written & oral licensing exams scheduled for 840316 & 19, respectively
W/a encl
VERRELLI, D M Division of Project & Resident Programs 83/12/16
GREEN, H J Tennessee Valley Authority 2pp 21741 188 24X
Fiche 50-259, 83/12/16, 8401060338

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8401050046 Releases public version of revised emergency response plan & revised emergency plan procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21736 001 24X Fiche 50-261, 83/12/27, 8401050046

--8401050052 Forwards public version of Rev 1 to Emergency Response Plan PLP-007 & revised emergency plan procedures
MORGAN, R E Carolina Power & Light Co 83/11/29 O'REILLY, J P
Region 2, Office of Director 5pp 21736 002 24X
Fiche 50-261, 83/12/27, 8401050046

--8401050054 Public version of Rev 1 to Emergency Response Plan PLP-007
* Carolina Power & Light Co 83/10/19 17pp 21736 007 24X
Fiche 50-261, 83/12/27, 8401050046

--8401050061 Public version of revised emergency plan & procedures, including Procedures PEP-001 re introduction, PEP-351 re confirmation of offsite dose projections & PEP-105 re emergency control - general emergency
* Carolina Power & Light Co 83/10/06 116pp 21736 023 24X
Fiche 50-261, 83/12/27, 8401050046

8401190161 Advises that facility complies w/habitability & location requirements of emergency operations facility per Suppl 1 to NUREG-0737, based on review of 831206 submittal
VARGA, S A Operating Reactors Branch 1 84/01/03 UTLEY, E E
Carolina Power & Light Co 2pp 21870 354 24X
Fiche 50-261, 84/01/03, 8401190161

8401240408 Ack receipt of 831230 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-32
Implementation of corrective action will be reviewed during future insps
VERRELLI, D M Division of Project & Resident Programs 84/01/11
UTLEY, E E Carolina Power & Light Co 1p 21915 310 24X
Fiche 50-261, 84/01/11, 8401240408

--8401240423 IE Insp Rept 50-261/83-32 on 831011-1110 Violation noted overpressure protection sys isolated for approx 2 h w/o establishing equivalent vent path to containment
WEISE, S Region 2, Office of Director BEHIS, P R Division of Project & Resident Programs 83/11/30 18pp 21915 316 24X
Fiche 50-261, 84/01/11, 8401240408

8401240496 Forwards FEMA, "HB Robinson Nuclear Power Plant Exercise on 830921-22," final rept
VERRELLI, D M Division of Project & Resident Programs 84/01/11
UTLEY, E E Carolina Power & Light Co 1p 21920 102 24X
Fiche 50-261, 84/01/11, 8401240496

8401250141 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 035 24X Fiche 50-261, 84/01/18, 8401250141

--8401250145 Forwards public version of revised Emergency Plan Implementing Procedures PEP-102, "Emergency Control - Unusual Event," PEP-103, "Emergency Control - Alert" & PEP-104, "Emergency Control - Site Emergency"
MORGAN, R E Carolina Power & Light Co 83/12/20 O'REILLY, J P
Region 2, Office of Director 2pp 21959 036 24X
Fiche 50-261, 84/01/18, 8401250141

--8401250149 Public version of revised Emergency Plan Implementing Procedures PEP-102, "Emergency Control - Unusual Event," PEP-103, "Emergency Control - Alert" & PEP-104, "Emergency Control - Site Emergency"
* Carolina Power & Light Co 83/12/13 12pp 21959 038 24X
Fiche 50-261, 84/01/18, 8401250141

8401240647 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 196 24X Fiche 50-261, 84/01/20, 8401240647

--8401240648 Public version of Rev 2 to Emergency Plan Implementing Procedure PEP-105, "Emergency Control - General Emergency"
W/840110 ltr
* Carolina Power & Light Co 83/12/20 O'REILLY, J P Region 2, Office of Director 3pp 21945 197 24X Fiche 50-261, 84/01/20, 8401240647

8401260224 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21982 300 24X Fiche 50-261, 84/01/20, 8401260224

--8401260228 Public version of Rev 1 to Emergency Plan Implementing Procedure PEP-101, "Initial Emergency Actions" W/840110 ltr.
MORGAN, R E Carolina Power & Light Co 84/01/01 O'REILLY, J P
Region 2, Office of Director 12pp 21982 301 24X
Fiche 50-261, 84/01/20, 8401260224

G Adjudicatory correspondence

8312160014 Motion to strike Contention 2 Contention mooted by issuance of PES Certificate of Svc encl
TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/12/12 Atomic Safety and Licensing Board Panel 5pp 21544 007 24X Fiche 50-261, 83/12/12, 8312160014

8401050242 Notice of appearance in proceeding Certificate of Svc encl
SALGO, H Hartsville Group SALGO, H Salgo & Lee 83/12/28 3pp 21729 241 24X Fiche 50-261, 83/12/28, 8401050242

8401050283 Forwards notice of appearance & Certificate of Svc W/o encl Related correspondence
SALGO, H Salgo & Lee SALGO, H Hartsville Group 83/12/28
MARGULIES, M B Atomic Safety and Licensing Board Panel 1p 21726 348 24X Fiche 50-261, 83/12/28, 8401050283

8401250200 Notice of intervenor Hartsville Group withdrawal of Contention B re onsite storage bldg Certificate of Svc encl
BACHMANN, R G Hearing Branch 1 84/01/12 3pp 21937 131 24X
Fiche 50-261, 84/01/12, 8401250200

8401200086 Suppl to answer to first set of interrogatories & request to produce
ZIMMERMAN, S R Carolina Power & Light Co 84/01/17 Hartsville Group 7pp 21866 001 24X Fiche 50-261, 84/01/17, 8401200086

--8401200089 Suppl to answers to second set of interrogatories & request to produce
HARNESSE, J L, SANDERS, R L, COLEY, W V Carolina Power & Light Co 84/01/13 Hartsville Group 18pp 21866 080 24X
Fiche 50-261, 84/01/17, 8401200086

--8401200091 Suppl to answers to second set of interrogatories & request to produce Certificate of Svc encl
WILLIAMS, B M Carolina Power & Light Co 84/01/17 Hartsville Group 5pp 21866 098 24X Fiche 50-261, 84/01/17, 8401200086

8401250255 Forwards affidavit of RJ Serbu stating that NRC does not disagree w/allegations made in last paragraph of Contention 3 Proposed notice to ASLB also encl W/o encl
BACHMANN, R G Hearing Branch 1 84/01/17 MATTHEWS, B A Hartsville Group 1p 21943 250 24X Fiche 50-261, 84/01/17, 8401250255

DOCKETED ITEMS

59

B401300139 Forwards questions & document requests for assumptions & calculations embodied in ESR0 B30120 cost comparison of retirement vs steam generator replacement alternative Immediate response requested
TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F
Carolina Power & Light Co 84/01/24 RUOFF, J C Palmetto Alliance
5pp 21998 275 24X Fiche 50-261,84/01/26,8401300139

B401310292 Notices of appearance in proceeding Certificate of Svc encl
O'NEILL, J H, JONES, R E Carolina Power & Light Co O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 84/01/26 5pp 22020 266 24X
Fiche 50-261,84/01/26,8401310292

H General correspondence

B401040516 Notifies that RE Morgan recently replaced RB Starkey as general manager of plant All correspondence previously sent from branch to RB Starkey, should be sent to RE Morgan
Address remains unchanged
ZIMMERMAN, S R Carolina Power & Light Co 83/12/30 VARQA, S A
Operating Reactors Branch 1 1p 21705 360 24X
Fiche 50-261,83/12/30,8401040516

J Insurance & indemnity information

B401160007 Forwards Endorsements 76 & 77 to NELIA Policy NF-180
BARHAM, C D Carolina Power & Light Co 84/01/10 SALTZMAN, J NRC
- No Detailed Affiliation Given 3pp 21821 178 24X
Fiche 50-261,84/01/10,8401160007

B401160070 Forwards Endorsements 61 & 62 to MAELU Policy MF-49
BARHAM, C D Carolina Power & Light Co 84/01/10 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 3pp 21821 166
24X Fiche 50-261,84/01/10,8401160070

B401160121 Forwards Endorsement 4 to MAELU Certificate M-21
BARHAM, C D Carolina Power & Light Co 84/01/10 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 2pp 21821 211
24X Fiche 50-261,84/01/10,8401160121

B401160184 Forwards Endorsement 4 to NELIA N-21
BARHAM, C D Carolina Power & Light Co 84/01/10 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 2pp 21815 343
24X Fiche 50-261,84/01/10,8401160184

B401240092 Forwards Endorsement 74 to NELIA Policy NF-180
BARHAM, C D Carolina Power & Light Co 84/01/18 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 2pp 21713 141
24X Fiche 50-261,84/01/18,8401240092

B401240256 Forwards Endorsement 59 to MAELU Policy MF-49
BARHAM, C D Carolina Power & Light Co 84/01/18 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 2pp 21910 008
24X Fiche 50-261,84/01/18,8401240256

P Operating license stage documents & correspondence

B401090198 SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR REPAIR
AT H B ROBINSON STEAM ELECTRIC PLANT UNIT NO 2 Docket No
50-261 (Carolina Power And Light Company)
* Division of Licensing NUREG-1004 83/11/30 60pp Available
at NRC #425 21757 152 24X Fiche 50-261,83/11/30,8401090198

B401050615 Requests commitment to replace transmitter O-rings during yearly instrument calibr checks, be changed to replace O-rings on same frequency as Tech Spec required equipment calibr frequency
CUTTER, A B Carolina Power & Light Co 83/12/12 O'REILLY, J P
Region 2, Office of Director 1p 21726 074 24X
Fiche 50-261,83/12/12,8401050615

B401060197 Forwards NUREG-1004, SER re steam generator repair & FR notice of availability w/o NUREG
VARQA, S A Operating Reactors Branch 1 83/12/22 PERRIN, S
Environmental Protection Agency 1p 21744 178 24X
Fiche 50-261,83/12/22,8401060197

B401040072 Notification of B40118 meeting w/util in Bethesda, MD to discuss environ qualification of electric equipment open items.
REGUA, Q Operating Reactors Branch 1 83/12/23 VARQA, S A
Operating Reactors Branch 1 2pp 21711 317 24X
Fiche: 50-261,83/12/23,8401040072

B401060189 Forwards SER re steam generator repair (NUREG-1004) & FR notice of reft availability w/o NUREG
VARQA, S A Operating Reactors Branch 1 83/12/23 UTLEY, E E
Carolina Power & Light Co 2pp 21744 181 24X
Fiche 50-261,83/12/23,8401060189

--B401060192 Notice of availability of SER re steam generator repair (NUREG-1004)
VARQA, S A Operating Reactors Branch 1 83/12/23 2pp
21744 183 24X Fiche 50-261,83/12/23,8401060189

B401060210 Forwards SER re steam generator repair (NUREG-1004) w/o encl
VARQA, S A Operating Reactors Branch 1 83/12/23 WOOD, J M
Commerce, Dept of, Natl Oceanographic & Atmospheric Administration
1p 21744 172 24X Fiche 50-261,83/12/23,8401060210

B401060224 Forwards FR notice of availability of SER re steam generator repair (NUREG-1004) w/o encl
VARQA, S A Operating Reactors Branch 1 83/12/23 SMITH, P H
Advisory Council on Historic Preservation SMITH, P H, BINDER, J R
Agriculture, Dept of 6pp 21744 131 24X Fiche 50-261,83/12/23
8401060224

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,8401050382

B401100373 Describes util method for complying w/draft implementation guidelines for LOCFR61 Impell Corp WASTETRAX computer program will be utilized for waste classification
CUTTER, A B Carolina Power & Light Co 84/01/05 EISENHUT, D G
Division of Licensing 1p 21763 290 24X Fiche 50-000,84/01/05,
8401100373

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,8401090221

B401100422 Provides info re Generic Ltr B3-41 on fast cold starts of diesel generators Based on NRC definition, facility has not experienced any fast cold starts of emergency diesel generators between B21201-B31201
ZIMMERMAN, S R Carolina Power & Light Co 84/01/06 EISENHUT, D G
Division of Licensing 2pp 21763 113 24X Fiche 50-261,84/01/06,
8401100422

B401120385 Application for amend to License DPR-23, changing Tech Specs to allow use of 10 spent fuel assembly storage locations previously maintained as spares
MCDUFFIE, M A Carolina Power & Light Co 84/01/09 VARQA, S A
Operating Reactors Branch 1 2pp 21791 075 24X
Fiche 50-261,84/01/09,8401120385

--B401120394 Proposed Tech Spec rev allowing use of 10 spent fuel assembly storage locations previously intended to be maintained as spares
* Carolina Power & Light Co 84/01/09 1p 21791 077 24X
Fiche 50-261,84/01/09,8401120385

B401170217 Offers no further comments on FES
MOORE, S N Environmental Protection Agency 84/01/09 REGUA, Q
Office of Nuclear Reactor Regulation, Director 1p 21831 344 24X
Fiche 50-261,84/01/09,8401170217

B401180133 Application to amend License DPR-23, revising Tech Spec Table 3 4-1 temp requirement to 350 F for consistency w/auxiliary feedwater requirements
MCDUFFIE, M A Carolina Power & Light Co 84/01/09 VARQA, S A
Operating Reactors Branch 1 2pp 21841 342 24X
Fiche 50-261,84/01/09,8401180133

--B401180135 Proposed Tech Spec Table 3 4 1 re auxiliary feedwater flow automatic initiation
* Carolina Power & Light Co 84/01/09 1p 21841 344 24X
Fiche 50-261,84/01/09,8401180133

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

B401200188 Application for amend to License DPR-23, revising Tech Specs to incorporate NRC comments from 831215 telcon re instrumentation sys
MCDUFFIE, M A Carolina Power & Light Co 84/01/13 VARQA, S A
Operating Reactors Branch 1 2pp 21867 030 24X
Fiche 50-261,84/01/13,8401200188

DOCKETED ITEMS

--B401200189 Proposed Tech Spec changes incorporating NRC comments discussed in B31215 telcon re instrumentation sys
* Carolina Power & Light Co 84/01/13 7pp 21867 032 24X
Fiche 50-261,84/01/13,8401200189

B401200040 Suppl response to Generic Ltr B3-10D re automatic trip of reactor coolant pumps (RCP) RCP trip criterion being adopted permits RCP operation to continue during most non-LOCAs
CUTTER, A B Carolina Power & Light Co 84/01/16 EISENHUT, D G Division of Licensing 2pp 21867 010 24X Fiche 50-261,84/01/16, 8401200040

B401310057 Forwards "RELAP5 Thermal-Hydraulic Analyses of Pressurized Thermal Shock Sequences for HB Robinson, Unit 2 PWR," for placement in PDR Transients described are hypothetical & have not actually occurred
REYES, J N Division of Accident Evaluation (Pre B40101) 84/01/16 MCKNIGHT, J C Document Management Branch 1p 22029 001 24X
Fiche 50-261,84/01/16,8401310057

--B401310061 "RELAP5 Thermal-Hydraulic Analyses of Pressurized Thermal Shock Sequences for HB Robinson, Unit 2 PWR," informal rept
FLETCHER, C D, BOLANDER, M A, WATERMAN, M E E&G, Inc FIN A-6047 EGO-SAAM-6476 83/12/31 NRC - No Detailed Affiliation Given 285pp 22029 002 24X Fiche 50-261,84/01/16,8401310061

B401310296 Forwards responses to NRC B31215 questions re XN-NF-82-18(P), Suppl 2, "ECCS & Plant Transient Analyses for HB Robinson Unit 2 Operating at Reduced Primary Temp, Suppl Analyses for 30% Steam Generator Tube Plugging"
CUTTER, A B Carolina Power & Light Co 84/01/25 VARGA, S A Operating Reactors Branch 1 9pp 22018 065 24X
Fiche 50-261,84/01/25,8401310296

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20, 8401060150

B401050615 Requests commitment to replace transmitter O-rings during yearly instrument calibr checks, be changed to replace O-rings on same frequency as Tech Spec required equipment calibr frequency
CUTTER, A B Carolina Power & Light Co 83/12/12 O'REILLY, J P Region 2, Office of Director 1p 21726 074 24X
Fiche 50-261,83/12/12,8401050615

B401090114 Forwards IE Insp Rept 50-261/83-34 on B31128-1202 No violation noted
VERRELLI, D M Division of Project & Resident Programs 83/12/20 UTLEY, E E Carolina Power & Light Co 1p 21753 181 24X
Fiche 50-261,83/12/20,8401090114

--B401090119 IE Insp Rept 50-261/83-34 on B31128-1202 No violation noted
Major areas inspected plant water chemistry & inservice testing of pumps & valves
ROSS, W J Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/12/14 11pp 21753 182 24X Fiche 50-261,83/12/20,8401090119

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

B312120073 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120073

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 033 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

B401240408 Ack receipt of B31230 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-32 Implementation of corrective action will be reviewed during future insps
VERRELLI, D M Division of Project & Resident Programs 84/01/11 UTLEY, E E Carolina Power & Light Co 1p 21915 310 24X
Fiche 50-261,84/01/11,8401240408

--B401240412 Responds to NRC B31201 ltr re violations noted in IE Insp Rept 50-261/83-32 Corrective actions until procedure revised, note to ensure RCS vent path established prior to isolating LTOP entered in info book
MORGAN, R E Carolina Power & Light Co 83/12/30 O'REILLY, J P Region 2, Office of Director 2pp 21915 311 24X
Fiche 50-261,84/01/11,8401240408

--B401240413 Forwards IE Insp Rept 50-261/83-32 on B31011-1110 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/12/01 UTLEY, E E Carolina Power & Light Co 2pp 21915 313 24X
Fiche 50-261,84/01/11,8401240408

--B401240417 Notice of violation from insp on B31011-1110
* Region 2, Office of Director 83/12/01 1p 21915 315 24X
Fiche 50-261,84/01/11,8401240408

--B401240423 IE Insp Rept 50-261/83-32 on B31011-1110 Violation noted overpressure protection sys isolated for approx 2 h w/o establishing equivalent vent path to containment
WEISSE, S Region 2, Office of Director BENIS, P R Division of Project & Resident Programs 83/11/30 18pp 21915 316 24X
Fiche 50-261,84/01/11,8401240408

B401230244 Forwards revised Procedure ENO-10, "Inservice Insp Program Interval 2, B10307-910307" Rev incorporates items discussed during B31007 & 1108 telcons
ZIMMERMAN, S R Carolina Power & Light Co 84/01/13 VARGA, S A Operating Reactors Branch 1 1p 21883 227 24X
Fiche 50-261,84/01/13,8401230244

--B401230249 Revised Procedure ENO-10, "Inservice Insp Program Interval 2, B10307-910307"
* Carolina Power & Light Co 84/01/13 79pp 21883 228 24X
Fiche 50-261,84/01/13,8401230244

B312120114 IE Info Notice B4-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

B401160107 Monthly operating rept for Dec 1983 W/B40110 ltr
NORRIS, H R, SCOTT, A E, MORGAN, R E Carolina Power & Light Co, 83/12/31 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 21821 167 24X Fiche 50-261,83/12/31,8401160107

S Reportable occurrences, LERs & related correspondence

B401030217 LER B3-027/03L-O on B31122, w/unit shut down for steam generator insp outage, level transmitter LT-928 found to be out of calibr Caused by instrument drift Transmitter recalibr W/B31221 ltr
WRIGHT, C L, MORGAN, R E Carolina Power & Light Co 83/12/21 O'REILLY, J P Region 2, Office of Director 2pp 21682 322 24X
Fiche 50-261,83/12/21,8401030217

DOCKETED ITEMS

61

8401050415 LER 83-030/03L-0 on 831129, two degraded voltage relays for emergency bus E-2 found out of tolerance during calibr
Caused by instrument drift Instrument calibr W/831229 ltr
WRIGHT, C L , MORGAN, R E Carolina Power & Light Co 83/12/29
O'REILLY, J P Region 2, Office of Director 3pp 21731 137 24X
Fiche 50-261, 83/12/29, 8401050415

8401050476 LER 83-031/03L-0 on 831130, two containment isolation valves failed to close on Phase A isolation test & fire protection valve FP-25B, waste disposal valve WD-172B & second valve did not properly isolate W/831229 ltr
WRIGHT, C L , MORGAN, R E Carolina Power & Light Co 83/12/29
O'REILLY, J P Region 2, Office of Director 3pp 21730 108 24X
Fiche 50-261, 83/12/29, 8401050476

8401130132 LER 83-032/03L-0 on 831104, during testing of PORVs, valve PORV-456 failed to meet required cycle time Caused by limit switch improperly adjusted Limit switch adjusted & small air leak repaired W/840109 ltr
WRIGHT, C L , MORGAN, R E Carolina Power & Light Co 84/01/05
O'REILLY, J P Region 2, Office of Director 3pp 21802 109 24X
Fiche 50-261, 84/01/05, 8401130132

T Hearing transcripts on non-antitrust matters

8401240095 Testimony of PD Raskin, introducing repts: "Electric Rate Consequences of Retiring Robinson 2 Nuclear Power Plant " Certificate of Svc encl
RASKIN, P D Hartsville Group RASKIN, P D Energy Systems Research Group, Inc 84/01/20 140pp 21913 001 24X Fiche 50-261, 84/01/20, 8401240095

X Onsite Storage of Low Level Waste

8401130335 Confirms 831214 telcon w/PH Lohaus re errors found in Paragraph 61 55(a)(7) of 10CFR61 statement on waste form classification Util interpretation of paragraph stated
ZIMMERMAN, B R Carolina Power & Light Co 84/01/09 EISENHUT, D G Division of Licensing 1p 21801 201 24X Fiche 50-000, 84/01/09, 8401130335

DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X Fiche 50-000, 83/11/02, 8401250163

--8401250286 Forwards comments on proposed Commission papers NRC should consider significant economic impact which would result if backup emergency operation facility rejected & dismantled into two separate locations
EISENHUT, D G Division of Licensing 83/06/24 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 21958 328 24X Fiche 50-000, 83/11/02, 8401250163

8401100432 Forwards IE Insp Rept 50-263/83-21 on 831102-1201 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 83/12/20 LARSON, C E Northern States Power Co 2pp 21762 28B 24X Fiche 50-263, 83/12/20, 8401100432

--8401100440 IE Insp Rept 50-263/83-21 on 831102-1201 No noncompliance noted Major areas inspected operational safety, LERs, cold weather preparations, onsite review committee, fire protection & IE circulars & bulletins
BROWN, C H , GROBE, J A , WALKER, R D Region 3, Office of Director 83/12/19 6pp 21762 290 24X Fiche 50-263, 83/12/20, 8401100432

8401090321 Forwards "Control Room Design Review Plan," per requirements of Suppl 1 to NUREG-0737 transmitted by Generic Ltr 82-33 Summary rept of completed review to be submitted at later date
MUSOLF, D Northern States Power Co 83/12/28 Office of Nuclear Reactor Regulation, Director 1p 21754 156 24X Fiche 50-263, 83/12/28, 8401090321

--8401090328 "Control Room Design Review Plan " * Northern States Power Co 83/12/28 34pp 21754 157 24X Fiche 50-263, 83/12/28, 8401090321

8401130082 Forwards response to Generic Ltr 82-33 (NUREG-0737, Suppl 1), re compliance w/Reg Guide 1.97 concerning instrumentation for light-water-cooled nuclear plants to assess plant & environs conditions during & following accident
MUSOLF, D Northern States Power Co 83/12/30 Office of Nuclear Reactor Regulation, Director 13pp 21802 05B 24X Fiche 50-263, 83/12/30, 8401130082

8401230271 Notifies of FEMA 840112-13 meetings in Chicago, IL FEMA requests that util emergency preparedness planners attend to develop FY84/85 emergency preparedness exercise schedule & prompt alert & notification certification schedule
PAPERIELLO, C J Region 3, Office of Director 84/01/05 LARSON, C E Northern States Power Co 3pp 21884 211 24X Fiche 50-000, 84/01/05, 8401230271

8401250093 Releases public version of notice re emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21946 262 24X Fiche 50-000, 84/01/18, 8401250093

--8401250096 Public version of notice that Emergency Plan Implementing Procedure 9.1 inadvertently attached to back of 831221 corporate emergency plan - implementing procedures & should be discarded
HUDSON, Q Northern States Power Co 83/12/29 1p 21946 263 24X Fiche 50-000, 84/01/18, 8401250093

8401310254 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 22037 099 24X Fiche 50-000, 84/01/18, 8401310254

--8401310263 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.11 re accident assessment, EPIP 1.2.1 re emergency plan training & EPIP 1.2.2 re exercises & drills
FEY, F L Northern States Power Co 83/12/21 Region 3, Office of Director 2pp 22037 096 24X Fiche 50-000, 84/01/18, 8401310254

--8401310271 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.11 re accident assessment, EPIP 1.2.1 re emergency plan training & EPIP 1.2.2 re exercises & drills
HUDSON, Q , FEY, F L Northern States Power Co 83/12/21 10pp, 22037 098 24X Fiche 50-000, 84/01/18, 8401310254

J Insurance & indemnity information

8401270054 Forwards Endorsements 4, 70, 4.4 & 58 to NELA Policies M-17, NF-174, M-37, M-36 & NF-197, respectively & Endorsements 4, 58, 4.4 & 50 to MACLU Policies M-17, NF-51, M-37, M-36 & MF-68, respectively
JOHNSON, R G Northern States Power Co 84/01/23 DINI, T I Division of Engineering 11pp 21973 298 24X Fiche 50-000, 84/01/23, 8401270054

DOCKETED ITEMS

F Operating license stage documents & correspondence

B401200063 Notifies that TMI Action Items II X 3 3D & II X 3 3i completed based on NRC B31213 acceptance of GE small break LOCA model for use in plant analysis Confirmation of model use requested
VASSALLO, D B Operating Reactors Branch 2 83/12/28 MUSOLF, M P
Northern States Power Co 2pp 21872 209 24X
Fiche 50-263, 83/12/28, B401200063

B401130187 Forwards reanalysis of adequacy of facility electric distribution sys voltages per B30831 confirmatory action
1tr Reanalysis establishes allowable ranges of switchyard voltages for operation Methodology described in B30926 1tr
MUSOLF, D Northern States Power Co 83/12/30 Office of Nuclear Reactor Regulation, Director 40pp 21800 269 24X
Fiche 50-263, 83/12/30, B401130187

B401200036 Forwards Amend 19 to License DPR-22 & safety evaluation Amend provides for expanded radiation protection program & limits extent of required operations committee review of radiation protection procedures
NICOLARAS, H Operating Reactors Branch 2 83/12/30 MUSOLF, D M
Northern States Power Co 2pp 21871 069 24X
Fiche 50-263, 83/12/30, B401200036

--B401200037 Amend 19 to License DPR-22, providing for expanded radiation protection program & limiting extent of required operations committee review of radiation protection procedures
VASSALLO, D B Operating Reactors Branch 2 83/12/30 4pp
21871 071 24X Fiche 50-263, 83/12/30, B401200037

--B401200038 Safety evaluation supporting Amend 19 to License DPR-22
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp
21871 077 24X Fiche 50-263, 83/12/30, B401200038

B401250144 Grants B30929 request for extension until B40215 for implementation of licensed operator staffing requirements
SER encl
EISENHUT, D G Division of Licensing 83/12/30 MUSOLF, D M
Northern States Power Co 3pp 21959 030 24X
Fiche 50-263, 83/12/30, B401250144

--B401250152 Safety evaluation granting until B30929 request for extension until B40215 to implement licensed operator staffing requirements
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp
21959 033 24X Fiche 50-263, 83/12/30, B401250144

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130070 Summary of B31212 meeting in Bethesda, MD re deficiencies identified in Franklin Research Ctr technical evaluation
rept on environ qualification of electrical equipment
GAUTAM, A S Region 3, Office of Director 84/01/06 WILLIAMS, C C
Region 3, Office of Director 16pp 21802 278 24X
Fiche 50-263, 84/01/06, B401130070

B401170374 Responds to B31216 request for addl info re fast cold starts of diesel generators per Generic Ltr B3-41 Data provided on surveillance testing, maint activities & actual demands during period B21201-B31201
MUSOLF, D Northern States Power Co 84/01/10 Office of Nuclear Reactor Regulation, Director 2pp 21828 223 24X
Fiche 50-263, 84/01/10, B401170374

B401230216 Advises that results of review of NRC positions on post-maint testing of reactor trip sys components per Generic Ltr B3-28 will be submitted by mid-Sept 1984
MUSOLF, D Northern States Power Co 84/01/11 Office of Nuclear Reactor Regulation, Director 7pp 21884 088 24X
Fiche 50-263, 84/01/11, B401230216

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401100432 Forwards IE Insp Rept 50-263/B3-21 on B31102-1201 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/12/20 LARSON, C E
Northern States Power Co 2pp 21762 288 24X
Fiche 50-263, 83/12/20, B401100432

--B401100440 IE Insp Rept 50-263/B3-21 on B31102-1201 No noncompliance noted Major areas inspected operational safety, LERs, cold weather preparations, onsite review committee, fire protection & IE circulars & bulletins
BROWN, C H, GROBE, J A, WALKER, R D Region 3, Office of Director
83/12/19 4pp 21762 290 24X Fiche 50-263, 83/12/20, B401100432

B401040232 Forwards addendum to IE Insp Rept 50-263/B3-10 Addendum lists comparisons of beta analyses performed on liquid sample
PAPERIELLO, C J Region 3, Office of Director 83/12/27
LARSON, C E Northern States Power Co 1p 21701 174 24X
Fiche 50-263, 83/12/27, B401040232

--B401040243 Addendum to IE Insp Rept 50-263/B3-10, consisting of comparison of beta analyses performed on liquid sample collected during B30524-26 insp
* Region 3, Office of Director 83/06/27 1p 21701 175 24X
Fiche 50-263, 83/12/27, B401040232

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401120406 Revises schedule for completing installation of new inverter for uninterruptible power supply, as committed to in B31028
reevaluation of response to IE Bulletin 79-27 Completion date of B40131 anticipated
MUSOLF, D Northern States Power Co 83/12/30 Office of Nuclear Reactor Regulation, Director 1p 21791 137 24X
Fiche 50-263, 83/12/30, B401120406

B401190315 Forwards IE Insp Rept 50-263/B3-23 on B30811-12, 17-19, 25-26 & 110B-09 & notice of violation
SPESBARD, R L Division of Engineering 83/12/30 LARSON, C E
Northern States Power Co 2pp 21850 338 24X
Fiche 50-263, 83/12/30, B401190315

--B401190321 Notice of violation from insp on B30811-12, 17-19, 25-26 & 110B-09
SPESBARD, R L Division of Engineering 83/12/30 1p 21850 340 24X Fiche 50-263, 83/12/30, B401190315

--B401190324 IE Insp Rept 50-263/B3-23 on B30811-12, 17-19, 25-26 & 110B-09 Violation noted failure to conduct all appropriate tests following installation of degraded voltage protection relays
STREETER, J F, CHRISOTIMOS, N Region 3, Office of Director
SPESBARD, R L Division of Engineering 83/12/30 10pp 21850 341 24X Fiche 50-263, 83/12/30, B401190315

B401270507 Forwards SER re util responses to IE Bulletin BQ-11, "Masonry Wall Design" & technical evaluation rept issues resolved
VASSALLO, D B Operating Reactors Branch 2 84/01/06 MUSOLF, D M
Northern States Power Co 2pp 22002 208 24X
Fiche 50-263, 84/01/06, B401270507

--B401270518 Safety evaluation supporting util responses to IE Bulletin BQ-11 "Masonry Wall Design" Issues resolved & mod schemes acceptable
* Office of Nuclear Reactor Regulation, Director, 84/01/06 2pp
22002 210 24X Fiche 50-263, 84/01/06, B401270507

DOCKETED ITEMS

63

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 12pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

R Periodic operating reports & related correspondence

B401120377 Monthly operating rept for Nov 1983 W/B31212 1tr
MYRABO, A L, MUSOLF, D Northern States Power Co 83/11/30
Office of Resource Management, Director 5pp 21791 183 24X
Fiche 50-263, 83/11/30, B401120377

B401060354 Provides rept on project status re seismic Category I piping
review program through B31231 RHR & core spray suction sys
combined as one analysis model Piping evaluation & support
design complete
LARSON, C E Northern States Power Co 83/12/31 KEPPLER, J G
Region 3, Office of Director 3pp 21741 110 24X
Fiche 50-263, 83/12/31, B401060354

B401270397 Monthly operating rept for Dec 1983 W/B40109 1tr
MYRABO, A L, MUSOLF, D Northern States Power Co 83/12/31
Office of Resource Management, Director 5pp 21981 061 24X
Fiche 50-263, 83/12/31, B401270397

S Reportable occurrences, LERs & related correspondence

B401120373 LER B3-026/03L-O on B31205, outboard steam isolation valve
MD-2074 failed to close Caused by loose screw bumping lead,
causing torque switch in Limitorque valve to fail open
Switch replaced W/B40104 1tr
KOLB, M W, MUSOLF, D Northern States Power Co 84/01/04 Region
3, Office of Director 2pp 21791 360 24X Fiche 50-263, 84/01/04,
B401120373

V Operator Examinations

B401250144 Grants B30929 request for extension until B40215 for
implementation of licensed operator staffing requirements
SER encl
EISENHUT, D G Division of Licensing 83/12/30 MUSOLF, D M
Northern States Power Co 3pp 21959 030 24X
Fiche 50-263, 83/12/30, B401250144

--B401250152 Safety evaluation granting until B30929 request for extension
until B40215 to implement licensed operator staffing
requirements
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp
21959 033 24X Fiche 50-263, 83/12/30, B401250144

B401050407 Informs that written exams scheduled for B40124 & oral
exams scheduled for B40125-26 at Facility Supplies & room
arrangements for administering exams described in encl
STREEVER, J F Region 3, Office of Director 84/01/03 LARSON, C E
Northern States Power Co 3pp 21731 037 24X
Fiche 50-263, 84/01/03, B401050407

X Onsite Storage of Low Level Waste

B401170314 Discusses methodology for meeting requirements of 10CFR61 re
disposal of low level radioactive waste received after B31227
must meet waste classification & waste form requirements
MUSOLF, D Northern States Power Co 84/01/04 Office of Nuclear
Reactor Regulation, Director 2pp 21832 361 24X
Fiche 50-263, 84/01/04, B401170314

DOCKET 50-264 DOW CHEMICAL CO

F Security, medical, emergency & fire protection plans

B401270016 Grants B31223 request for extension to respond to questions
posed re emergency plan until B40302
THOMAS, C O Standardization & Special Projects Branch 84/01/10
KUCHER, C W Dow Chemical Co 1p 22002 361, 24X
Fiche 50-264, 84/01/10, B401270016

DOCKET 50-265 QUAD CITIES STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

B401040356 Informs of completed upgrading of fire protection features &
significant effort to complete remaining mods necessary for
strict conformance to App R, Sections III G & III L, per
Generic Ltr B3-33 Exemption requests will be provided
FARRAR, D L Commonwealth Edison Co 83/12/23 DENTON, H R Office
of Nuclear Reactor Regulation, Director 2pp 21707 141 24X
Fiche 50-000, 83/12/23, B401040356

B401050099 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 237 24X Fiche 50-254, 83/12/28,
B401050099

--B401050102 Public version of Rev 11 to Emergency Plan Implementing
Procedure GEP 200-T1, "Quad-Cities Emergency Action Levels "
W/831117 ltr, receipt form & revised table of contents
TIETZ, G Commonwealth Edison Co 83/11/17 13pp 21736 238
24X Fiche 50-254, 83/12/28, B401050099

B401050251 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 179 24X Fiche 50-254, 83/12/28,
B401050251

--B401050257 Forwards public version of revised Emergency Plan
Implementing Procedures GEP 350-T1, "Recommended Protective
Actions for Gaseous Release" & GEP 350-2, "Emergency
Drills "
TIETZ, G, KOVACK, T J Commonwealth Edison Co 83/11/15 NRC --
No Detailed Affiliation Given 1p 21743 180 24X
Fiche 50-254, 83/12/28, B401050251

--B401050261 Public version of revised Emergency Plan Implementing
Procedures GEP 350-T1, "Recommended Protective Actions for
Gaseous Release" & GEP 350-2, "Emergency Drills "
TIETZ, G Commonwealth Edison Co 83/11/15 14pp 21743 181
24X Fiche 50-254, 83/12/28, B401050251

B401030229 Forwards safety parameter display sys safety analysis, per
Suppl 1 to NUREG-0737, including verification & validation
(VAV) plan & criteria for parameter selection implementation
will vary at each facility
SWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office
of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, B401030229

B401230491 Notification of B40112-13 FEMA radiological emergency
preparedness program meetings at O'Hare Airport Emergency
preparedness exercise & prompt alert & notification
certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C
Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05,
B401230491

B401240651 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 111 24X Fiche 50-254, 84/01/20,
B401240651

--B401240652 Public version of revised emergency plan implementing
procedures, including Procedure GEP 200-2 re classification
of incident involving hazardous mats & GEP 310-1 re
initial notification
GERNER, L Commonwealth Edison Co 83/12/19 56pp 21945 112
24X Fiche 50-254, 84/01/20, B401240651

B401300344 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22006 104 24X Fiche 50-254, 84/01/26,
B401300344

--B401300348 Public version of Rev 5 to Emergency Plan Implementing
Procedure GEP 350-T6, "Moline Public Hosp Radiation
Emergency Area Supplies & Equipment " W/B40110 transmittal
& receipt form
JESSEN, D, KOVACK, T J Commonwealth Edison Co 84/01/10 5pp
22006 105 24X Fiche 50-254, 84/01/26, B401300344

J Insurance & indemnity information

B401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30,
42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSIER, J Commonwealth Edison Co 84/01/09 BALTZMAN, J Assistant
Director for State & Licensee Relations 17pp 21865 332 24X
Fiche 50-000, 84/01/09, B401200141

P Operating license stage documents & correspondence

B401040329 Discusses operability of containment purge & vent valves in
response to SER Detailed list of operating evolutions,
procedures used to perform evolutions & containment vent &
purge valves required for evolutions encl
RYBAK, B Commonwealth Edison Co 83/12/21 DENTON, H R Office of
Nuclear Reactor Regulation, Director 7pp 21705 061 24X
Fiche 50-000, 83/12/21, B401040329

DOCKETED ITEMS

B401300035 Requests notification whether GE small break LOCA model approved on B31213 used in LOCA analysis. Correct understanding completes TMI items 11 K 3 30 & 11 K 3 31. Requests plans & schedules if understanding incorrect. VASSALLO, D. B. Operating Reactors Branch 2 83/12/28 FARRAR, D. L. Commonwealth Edison Co 2pp 22006 358 24X Fiche 50-254, 83/12/28, B401300035

B401120458 Notification of B40105 meeting w/uttl in Bethesda, MD to discuss repairs of cracks in large pipes. BEVAN, R. B. Operating Reactors Branch 2 83/12/29 VASSALLO, D. B. Operating Reactors Branch 2 1p 21804 095 24X Fiche 50-265, 83/12/29, B401120458

B401260420 Forwards SER re automatic switchover of RCIC sys. Switchover design now in place satisfies requirements of NUREG-0737, Item 11 K 3 22. Item complete. VASSALLO, D. B. Operating Reactors Branch 2 83/12/29 FARRAR, D. L. Commonwealth Edison Co 3pp 21959 317 24X Fiche 50-254, 83/12/29, B401260420

B401300059 Forwards SER supporting util proposed design mods re monitoring of electric power to reactor protection sys. Technical evaluation rept also encl. VASSALLO, D. B. Operating Reactors Branch 2 83/12/29 FARRAR, D. L. Commonwealth Edison Co 2pp 22003 345 24X Fiche 50-254, 83/12/29, B401300059

--B401300069 Safety evaluation supporting proposed design mods to existing reactor protection sys & applicable Tech Spec changes. * NRC - No Detailed Affiliation Given 83/12/29 2pp 22003 347 24X Fiche 50-254, 83/12/29, B401300069

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl. EISENHUT, D. G. Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl. EISENHUT, D. G. Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, B4/01/06, B401090221

B401170339 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators." Prelubrication w/soot warming provided, therefore, generators not subjected to cold starts. BARNEG, P. L. Commonwealth Edison Co 84/01/10 EISENHUT, D. G. Division of Licensing 1p 21829 341 24X Fiche 50-000, B4/01/10, B401170339

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl. EISENHUT, D. G. Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, B4/01/13, B401130084

B401200098 Notification of B40126 meeting w/uttl in Bethesda, MD to perform equipment environ qualification review for facilities. GILBERT, R. A. Operating Reactors Branch 5 84/01/10 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 21866 350 24X Fiche 50-000, B4/01/10, B401200098

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR. FELTON, J. M. Division of Rules and Records 83/10/20 ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982. * Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060150

B401040375 Forwards IE Insp Repts 50-254/83-28 & 50-265/83-27 on B31003-1202. No noncompliance noted. SHAFFER, W. D. Region 3, Office of Director 83/12/16 REED, C. Commonwealth Edison Co 2pp 21706 223 24X Fiche 50-254, 83/12/16, B401040375

--B401040380 IE Insp Repts 50-254/83-28 & 50-265/83-27 on B31003-1202. No noncompliance noted. Major areas inspected: operational safety, LERs, design changes & mods, onsite review committee, safety repts, mgt meetings, training & regional requests. CHRISTOFFIMOS, N., MORRONGIELLO, D., WALKER, R. D. Region 3, Office of Director 83/12/14 12pp 21706 225 24X Fiche 50-254, 83/12/14, B401040375

B401040533 Suppls response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp. Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements. BARNEG, P. L. Commonwealth Edison Co 83/12/20 KEPPLER, J. G. Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20, B401040533

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401170210 Monthly operating repts for Dec 1983 W/B40103 ltr. MISAK, A., KALIVIANAKIS, N. Commonwealth Edison Co 83/12/31 Director's Office, Office of Inspection and Enforcement 20pp 21832 260 24X Fiche 50-254, 83/12/31, B401170210

B401170024 Forwards listing of changes, tests & experiments for Dec 1983. KALIVIANAKIS, N. Commonwealth Edison Co 84/01/03 CASE, E. G. Office of Nuclear Reactor Regulation, Director 2pp 21833 361, 24X Fiche 50-254, B4/01/03, B401170024

S Reportable occurrences, LERs & related correspondence

B401050431 LER 83-023/03L-0 on B31128, during main steam line high flow. Calibr G15 21-1, pressure switch DPIS 2-261-2K found to trip at 148.5 psid. Caused by instrument setpoint drift. Instrument recalibr W/B31206 ltr. COCHRAN, P., KALIVIANAKIS, N. Commonwealth Edison Co 83/12/05 KEPPLER, J. G. Region 3, Office of Director 2pp 21729 353 24X Fiche 50-265, 83/12/05, B401050431

B401050512 Revised LER 83-021/01T-3 on B31028, while reviewing ultrasonic test data, three linear indications identified in reactor recirculation sys piping caused by intergranular stress corrosion cracking W/B31209 ltr. CLARK, D., KALIVIANAKIS, N. Commonwealth Edison Co 83/12/09 KEPPLER, J. G. Region 3, Office of Director 2pp 21726 019 24X Fiche 50-265, 83/12/09, B401050512

DOCKETED ITEMS

65

B401050526 Revised LER 83-020/01T-1 on 831028,weld 028-89,22-inch pipe to cap,weld 028S-812,28-inch elbow to pipe & weld 028S-F14, 28-inch pipe to elbow weld had circumferential linear indications W/831209 ltr
CLARK, D. KALIVIANAKIS, N Commonwealth Edison Co 83/12/09
KEPPLER, J Region 3, Office of Director 2pp 21726 143 24X
Fiche 80-265, 83/12/09, 8401050526

B401050485 Revised LER 83-020/01T-2 on 831028,weld 105-F1,20-inch tee to pipe weld found to have circumferential linear indication in heat affected zone Caused by intergranular stress corrosion cracking W/831213 ltr
CLARK, D. KALIVIANAKIS, N Commonwealth Edison Co 83/12/13
KEPPLER, J Region 3, Office of Director 2pp 21730 123 24X
Fiche 80-265, 83/12/13, 8401050485

B401050500 LER 83-021/01T-4 on 831027,while reviewing ultrasonic test data,three linear indications identified in reactor recirculation sys piping Caused by intergranular stress corrosion cracking W/831213 ltr
CLARK, D. KALIVIANAKIS, N Commonwealth Edison Co 83/12/13
KEPPLER, J Region 3, Office of Director 2pp 21723 358 24X
Fiche 80-265, 83/12/13, 8401050500

B401050558 LER 83-024/03L-0 on 831201,three of initial 12 snubbers failed operational cycle functional test of safety-related mechanical snubbers Cause unknown Snubbers will be disassembled & inspected W/831215 ltr
CARNEY, J. KALIVIANAKIS, N Commonwealth Edison Co 83/12/15
KEPPLER, J Region 3, Office of Director 2pp 21723 237 24X
Fiche 80-265, 83/12/15, 8401050558

B401270338 Revised LER 83-024/03L-1 on 831201,while preparing operating cycle functional test of safety-related mechanical snubbers, seven addl snubbers failed functional test Cause unknown Snubbers will be disassembled & inspected W/840111 ltr
CARNEY, J. KALIVIANAKIS, N Commonwealth Edison Co 84/01/11
KEPPLER, J Region 3, Office of Director 2pp 21976 103 24X
Fiche 80-265, 84/01/11, 8401270338

DOCKET 80-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge App 21957 357 24X
Fiche 80-000, 83/11/02, 8401250163

--8306150117 Requests Commission review & disapprove divided emergency operations facility (EOF) concept for facilities
DIRCKX, H J Office of the Executive Director for Operations
SECY-83-223 83/06/07 7pp 21958 253 24X
Fiche 80-000, 83/11/02, 8401250163

--8306280028 Advises that request to relocate overall accident mgt of emergency operations Facility 100 miles from plant will be considered during second & third wks of June 1983 Proposal far exceeds current distance limitations
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/06/03 FAY, C W Wisconsin Electric Power Co 2pp 21958 291 24X Fiche 80-000, 83/11/02, 8401250163

--8306280032 Requests to be advised of date & time Commissioners will consider 820406 request to relocate emergency operations facility at corporate headquarters beyond guideline distance contained in NUREG-0696
FAY, C W Wisconsin Electric Power Co 83/03/30 CHILK, B J Office of the Secretary of the Commission, 1p 21958 289 24X
Fiche 80-000, 83/11/02, 8401250163

B401230259 Notifies of FEMA 840112-13 radiological emergency preparedness program meetings to develop final FY84 & FY85 emergency preparedness exercise & prompt alert & notification certification schedules, respectively
PAPERIELLO, C J Region 3, Office of Director 84/01/05
BURSTEIN, S Wisconsin Electric Power Co 3pp 21884 195 24X
Fiche 80-266, 84/01/05, 8401230259

B401130203 Ack receipt of 831230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-266/83-11 & 80-301/83-19
PAPERIELLO, C J Region 3, Office of Director 84/01/10
BURSTEIN, S Wisconsin Electric Power Co 1p 21801 349 24X
Fiche 80-266, 84/01/10, 8401130203

--8401130211 Responds to NRC 831130 ltr re violations noted in IE Insp Repts 80-266/83-11 & 80-301/83-19 Corrective actions drivers & technicians required to keep written instructions on file & Westinghouse health physics instructions reviewed
FAY, C W Wisconsin Electric Power Co 83/12/30 KEPPLER, J O Region 3, Office of Director App 21801 330 24X
Fiche 80-266, 84/01/10, 8401130203

B401260250 Releases public version of revised emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/19 Document Management Branch 1p 21968 001 24X Fiche 80-266, 84/01/19, 8401260250

--8401260259 Forwards public version of Rev 20 to emergency plan & emergency plan implementing procedures, including Procedures EPIP 1 1 re initial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation
FAY, C W Wisconsin Electric Power Co 83/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 1p 21968 002 24X
Fiche 80-266, 84/01/19, 8401260250

--8401260262 Public version of revised emergency plan implementing procedures, including Procedure EPIP 1 1 re initial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation
* Wisconsin Electric Power Co 83/11/11 112pp 21968 003 24X
Fiche 80-266, 84/01/19, 8401260250

--8401260301 Public version of Rev 20 to emergency plan
* Wisconsin Electric Power Co 83/11/11 200pp 21968 114 24X
Fiche 80-266, 84/01/19, 8401260250

G Adjudicatory correspondence

B401100164 Order extending time until 840113 for Commission to act to review ALAD-739
CHILK, B J Office of the Secretary of the Commission 84/01/06 Commissioners 1p 21760 168 24X Fiche 80-266, 84/01/06, 8401100164

B401170222 Order extending time until 840120 for Commission to act to review ALAD-739
CHILK, B J Office of the Secretary of the Commission 84/01/13 Commissioners 1p 21833 294 24X Fiche 80-266, 84/01/13, 8401170222

B401230388 Order extending time until 840203 for Commission to act to review Director's Decision DD-83-14 which denied requests of Sierra Club & State of OH & 831029 decision which denied request of Environ Policy Inst
CHILK, B J Office of the Secretary of the Commission 84/01/19 Commissioners 1p 21884 278 24X Fiche 80-000, 84/01/19, 8401230388

B401230476 Advises that time for Commission to review ALAD-739 expired Commission declined review Decision became final agency action on 840120
CHILK, B J Office of the Secretary of the Commission 84/01/20 ANDERSON, P Wisconsin's Environmental Decade 1p 21882 191 24X
Fiche 80-266, 84/01/20, 8401230476

J Insurance & indemnity information

B401230412 Forwards listed endorsements to NELIA Policy NF-17B, MAELU Policy MF-53, NELIA Certificates N-1B & N-19 & MAELU Certificates M-1B & M-19
DUNDAS, W J Wisconsin Electric Power Co 84/01/13 NRC - No Detailed Affiliation Given 9pp 21879 138 24X
Fiche 80-266, 84/01/13, 8401230412

P Operating license stage documents & correspondence

B401030208 Application for amend to Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 95, revising surveillance interval for evaluating integrity of post-accident recovery sys outside containment
FAY, C W Wisconsin Electric Power Co 83/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 21682 292 24X
Fiche 80-266, 83/12/23, 8401030208

--8401030211 Proposed Tech Spec Table 15 4 1-R re surveillance interval for evaluating integrity of post-accident recovery sys outside containment
* Wisconsin Electric Power Co 83/12/23 1p 21682 294 24X
Fiche 80-266, 83/12/23, 8401030208

DOCKETED ITEMS

84/01/01 - 84/01/31 PAGE 1

MONTHLY TITLE LIST
U S NUCLEAR REGULATORY COMMISSION

8401050017 Forwards Amends 80 & 84 to Licenses DPR-24 & DPR-27, respectively Amends revise monthly testing of automatic actuation logic circuitry for auxiliary feedwater pumps W/o encl
MILLER, J R Operating Reactors Branch 3 83/12/28 FAY, C W
Wisconsin Electric Power Co 2pp 21736 173 24X
Fiche 50-266, 83/12/28, 8401050017

840110304 Forwards Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends add addl reporting requirement to rept all challenges to pressurizer power operated relief & safety valves in annual rept
COLBURN, T G Operating Reactors Branch 3 83/12/28 FAY, C W
Wisconsin Electric Power Co 2pp 21795 015 24X
Fiche 50-266, 83/12/28, 840110304

--840110330 Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively, adding addl reporting requirement to rept all challenges to pressurizer power operated relief & safety valves in annual rept
MILLER, J R Operating Reactors Branch 3 83/12/28 6pp
21795 017 24X Fiche 50-266, 83/12/28, 840110330

--840110332 Safety evaluation supporting Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/28 5pp
21795 023 24X Fiche 50-266, 83/12/28, 840110332

8401050284 Submits further response to Generic Ltr 83-10D, "Resolution of TMI Action Item II K 3 5, 'Automatic Trip of Reactor Coolant Pumps' " Commitment to use Rev 1 to emergency response guidelines will be revised to Dec 1984
FAY, C W Wisconsin Electric Power Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 21726 349 24X Fiche 50-266, 83/12/29, 8401050284

8401100048 Forwards Amend 81 to License DPR-24 Amend authorizes reactor operation at 2,250 or 2,000 psia after return to power following steam generator replacement
MILLER, J R Operating Reactors Branch 3 83/12/30 FAY, C W
Wisconsin Electric Power Co 3pp 21777 163 24X
Fiche 50-266, 83/12/30, 8401100048

--8401100049 Amend 81 to License DPR-24, authorizing reactor operation at 2,250 or 2,000 psia after return to power following steam generator replacement
MILLER, J R Operating Reactors Branch 3 83/12/30 6pp
21777 166 24X Fiche 50-266, 83/12/30, 8401100049

8401120112 Forwards exemption from scheduler requirements of 10CFR50 44 for installation of RCS high point gas vents until 841231
MILLER, J R Operating Reactors Branch 3 83/12/30 FAY, C W
Wisconsin Electric Power Co 2pp 21805 221 24X
Fiche 50-266, 83/12/30, 8401120112

--8401120120 Exemption from scheduler requirements of 10CFR50 54 for installation of RCS high point gas vents until 841231
EISENHUT, D G Division of Licensing 83/12/30 Wisconsin
Electric Power Co 3pp 21805 223 24X Fiche 50-266, 83/12/30, 8401120120

8401190137 Responds to 830930 request for extension until Jan 1987 for implementation of licensed operator staffing rule, 10CFR50 54 (M)(2) Addl info required to complete action on request will be discussed at meeting scheduled for 840110
MILLER, J R Operating Reactors Branch 3 83/12/30 FAY, C W
Wisconsin Electric Power Co 2pp 21871 019 24X
Fiche 50-266, 83/12/30, 8401190137

8401130120 Grants 831010 request for extension of deadline to complete final environ qualification of Crosby lift indicating switch assemblies for facilities Extension granted until end of refueling outages beginning in Spring 1985
DENTON, H R Office of Nuclear Reactor Regulation, Director
84/01/03 BURSTEIN, S Wisconsin Electric Power Co 4pp
21820 285 24X Fiche 50-266, 84/01/03, 8401130120

8401100469 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators," providing data on number of fast cold starts from Dec 1982 to Dec 1983 increased testing frequency inappropriate
FAY, C W Wisconsin Electric Power Co 84/01/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21761 341 24X
Fiche 50-266, 84/01/04, 8401100469

8401050382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "Important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

84/01/01 - 84/01/31 PAGE 1

MONTHLY TITLE LIST
U S NUCLEAR REGULATORY COMMISSION

8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401190419 Forwards Rev 1, to "Inservice Testing Programs for Pumps & Valves" per NRC 830824 ltr Relief from ASME Code inservice testing requirements, per 770217 & 781127 applications for amend, requested
FAY, C W Wisconsin Electric Power Co 84/01/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21849 044
24X Fiche 50-266, 84/01/16, 8401190419

--8401190422 Rev 1, to "Inservice Testing Program for Pumps & Valves" Relief requests encl
* Wisconsin Electric Power Co 84/01/06 124pp 21849 047 24X
Fiche 50-266, 84/01/16, 8401190419

8401270045 Discusses steps taken to increase & stabilize operator staffing, per Generic Ltr 84-02 NRC should clarify position re placement of operator trainees in operating plants at 840125 meeting
BURSTEIN, S Wisconsin Electric Power Co 84/01/18 EISENHUT, D G
Division of Licensing 3pp 21982 018 24X Fiche 50-266, 84/01/18, 8401270045

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401130387 Responds to IE Bulletin 79-14 re as-built safety-related piping sys isometric drawings affected by mechanical corrections revised & reissued showing as-built configuration Activities required by bulletin complete
FAY, C W Wisconsin Electric Power Co 84/01/04 KEPPLER, J G
Region 3, Office of Director 1p 21798 337 24X
Fiche 50-266, 84/01/04, 8401130387

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 093 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401130203 Ack receipt of 831230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-11 & 50-301/83-19
PAPERIELLO, C J Region 3, Office of Director 84/01/10
BURSTEIN, S Wisconsin Electric Power Co 1p 21801 349 24X
Fiche 50-266, 84/01/10, 8401130203

--B401130211 Responds to NRC B31130 ltr re violations noted in IE Insp Repts 50-266/B3-11 & 50-301/B3-19 Corrective actions drivers & technicians required to keep written instructions on file & Westinghouse health physics instructions reviewed
FAY, C W Wisconsin Electric Power Co 83/12/30 KEPPLER, J O
Region 3, Office of Director 4pp 21801 350 24X
Fiche 50-266, B4/01/10, B401130203

B312120114 IE Info Notice B4-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B401240072 Responds to IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Breakers not in use in other applications
FAY, C W Wisconsin Electric Power Co B4/01/20 KEPPLER, J O
Region 3, Office of Director 1p 21913 216 24X
Fiche 50-266, B4/01/20, B401240072

R Periodic operating reports & related correspondence

B401170192 Monthly operating reports for Dec 1983 W/B40110 ltr
FAY, C W, FAY, C W Wisconsin Electric Power Co 83/12/31 NRC -
No Detailed Affiliation Given 9pp 21831 289 24X
Fiche 50-266, B3/12/31, B401170192

X Onsite Storage of Low Level Waste

B401300070 Documents implementation of new 10CFR61 regulation, effective B31227, re waste classification, waste form & high integrity containers Process control program will be updated by B40701
FAY, C W Wisconsin Electric Power Co B4/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21999 161 24X Fiche 50-266, B4/01/20, B401300070

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

B401230302 Forwards IE Insp Rept 50-267/B3-27 on B31024-28 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/22 LEE, O R
Public Service Co. of Colorado 2pp 21883 175 24X
Fiche 50-267, B3/12/22, B401230302

--B401230309 IE Insp Rept 50-267/B3-27 on B31024-28 No violations noted
Major areas inspected, licensee action on previous insp findings, operational safety verification, surveillance, maint.
MONTGOMERY, J L, BAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/12/20 8pp 21883 197 24X Fiche 50-267, B3/12/22, B401230302

B401170364 Forwards IE Insp Rept 50-267/B3-31 on B31101-30 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/28 LEE, O R
Public Service Co of Colorado 2pp 21828 179 24X
Fiche 50-267, B3/12/28, B401170364

--B401170370 IE Insp Rept 50-267/B3-31 on B31101-30, No violations noted
Major areas inspected, licensee action on previous insp findings, operational safety verification, surveillance, maint.
IE bulletin Followup & review of periodic & special repts
PLUMLEE, O L, HUNNICUTT, D M Region 4, Office of Director 83/12/28 11pp 21828 201 24X Fiche 50-267, B3/12/28, B401170364

G. Adjudicatory correspondence

B401100151 Responds to B31123 request for addl justification of B30328 request for exemption from property insurance requirements of 10CFR50.54(w) re property damage Exemption authorized by law & provides adequate safety
LEE, O R Public Service Co of Colorado 83/12/27 Office of the Secretary of the Commission 5pp 21760 204 24X
Fiche 50-267, B3/12/27, B401100151

J Insurance & indemnity information

B401100151 Responds to B31123 request for addl justification of B30328 request for exemption from property insurance requirements of 10CFR50.54(w) re property damage Exemption authorized by law & provides adequate safety
LEE, O R Public Service Co of Colorado 83/12/27 Office of the Secretary of the Commission 5pp 21760 204 24X
Fiche 50-267, B3/12/27, B401100151

P Operating license stage documents & correspondence

B401130390 Forwards application for amend to License DPR-34, changing Tech Specs to increase consistency between overall electrical sys requirements
LEE, O R Public Service Co of Colorado 83/12/30 COLLINS, J T
Region 4, Office of Director 2pp 21799 165 24X
Fiche 50-267, B3/12/30, B401130390

--B401130396 Application for amend to License DPR-34, changing Tech Specs to increase consistency between overall electrical sys STS requirements
LEE, O R Public Service Co of Colorado 83/12/30 3pp 21799 167 24X Fiche 50-267, B3/12/30, B401130390

--B401130400 Proposed Tech Specs changing auxiliary electric sys for overall consistency w/STS
* Public Service Co of Colorado 83/12/30 42pp 21799 170 24X Fiche 50-267, B3/12/30, B401130390

B401270140 Forwards application for amend to License DPR-34, consisting of Tech Spec changes re inservice insp & testing requirements
LEE, O R Public Service Co of Colorado 83/12/30 COLLINS, J T
Region 4, Office of Director 2pp 21792 255 24X
Fiche 50-267, B3/12/30, B401270140

--B401270145 Application for amend to License DPR-34, consisting of Tech Spec changes re inservice insp & testing requirements
Summary of proposed changes to inservice insp requirements encl
LEE, O R Public Service Co of Colorado 83/12/30 9pp 21792 257 24X Fiche 50-267, B3/12/30, B401270140

--B401270151 Proposed Tech Spec changes re inservice insp requirements
* Public Service Co of Colorado 83/12/30 136pp 21792 266 24X Fiche 50-267, B3/12/30, B401270140

B401100310 Requests publication of FR notice of consideration of issuance of amend to License DPR-34 & proposed NSHC determination & opportunity for hearing re min helium flow rates NSHC determination available in Central Files
JOHNSON, E H Region 4, Office of Director B4/01/03 MILLER, J B
Operating Reactors Branch 3 3pp 21763 282 24X
Fiche 50-267, B4/01/03, B401100310

B401130085 Forwards QA Co fuel surveillance rept, "Metallographic Exam of Fuel Rod From Segment 2 - Fort St Vrain Fuel Element 1-2415"
BREV, H L Public Service Co of Colorado B4/01/03 COLLINS, J T
Region 4, Office of Director 1p 21802 244 24X
Fiche 50-267, B4/01/03, B401130085

--B401130089 Issue A to "Metallographic Exam of Fuel Rod From Segment 2 - Fort St Vrain Fuel Element 1-2415"
* QA Technologies, Inc /General Atomic Co 906968 RA 83/11/09 33pp 21802 245 24X Fiche 50-267, B4/01/03, B401130085

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing B4/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/05, B401050382

B401130080 Responds to Generic Ltr B1-3B Util plans no response until clarification of requirement to respond received
BDRBT, F J Public Service Co of Colorado B4/01/05 WAGNER, P
Region 4, Office of Director 1p 21802 331 24X
Fiche 50-267, B4/01/05, B401130080

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing B4/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

DOCKETED ITEMS

8401130261 Forwards Figures 1 & 2 of Attachment 2 to 831230 ltr proposing changes to Tech Specs re electrical sys Figures inadvertently omitted from original submittal
WAREMBURG, D Public Service Co of Colorado 84/01/06
COLLINS, J T Region 4, Office of Director 1p 21800 339 24X
Fiche 50-267, 84/01/06, 8401130261

--8401130288 Figures 1 & 2 of Attachment 2 of 831230 proposed Tech Spec changes re electrical sys
* Public Service Co of Colorado 84/01/06 2pp 21800 340
24X Fiche 50-267, 84/01/06, 8401130261

8401230479 Provides alternative acceptance criteria for determining workability of concrete during period in which 1-1/2 h time requirement deleted from B16g 10 concrete spec
BREV, H L Public Service Co of Colorado 84/01/06 COLLINS, J T
Region 4, Office of Director 2pp 21884 243 24X
Fiche 50-267, 84/01/06, 8401230479

8401270180 Advises NRC re status of three commitments made in util 830517 ltr concerning environ qualification of safety-related electrical equipment Valve actuators tested & successfully passed HELB tests
BREV, H L Public Service Co of Colorado 84/01/09 COLLINS, J T
Region 4, Office of Director 2pp 21982 091 24X
Fiche 50-267, 84/01/09, 8401270180

8401230445 Certifies interpretation of radiological effluent Tech Specs re functional test requirements, per 840110 telcon w/NRC Requests response to util position re testing of instrumentation w/o control room annunciation capability
WAREMBURG, D W Public Service Co of Colorado 84/01/11
WAGNER, P Region 4, Office of Director 2pp 21884 238 24X
Fiche 50-267, 84/01/11, 8401230445

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401270441 Requests approval to dispose of 0.05 uCi or less S-35/g of medium, used for liquid scintillation counting, w/o regard to radioactivity, per 10CFR20.306 Disposal presents small potential biological hazard
BORGST, F J Public Service Co of Colorado 84/01/13 COLLINS, J T
Region 4, Office of Director 2pp 21981 286 24X
Fiche 50-267, 84/01/13, 8401270441

8401270480 Defers B-D startup testing originally scheduled for present fuel cycle to next fuel cycle due to problems w/boiler feed pump 1C Xenon stability test requires Tech Spec amend
WAREMBURG, D Public Service Co of Colorado 84/01/13 WAGNER, P
Region 4, Office of Director 2pp 21981 313 24X
Fiche 50-267, 84/01/13, 8401270480

8401270250 Requests response to questions re proposed Tech Specs concerning limitations & supporting analyses based on avoidance of laminar flow instability w/o sufficiently clear correlation between primary coolant flow & core temp
JOHNSON, E H Region 4, Office of Director 84/01/20 LEE, D R
Public Service Co of Colorado 3pp 21982 177 24X
Fiche 50-267, 84/01/20, 8401270250

8401270395 Forwards "Superheater Tube Leaks in Steam Generators of Fort St Vrain HTGR," containing results of evaluations of potential causes for tube leak Insufficient evidence exists to identify causes of leaks
LEE, D R Public Service Co of Colorado 84/01/20 COLLINS, J T
Region 4, Office of Director 4pp 21981 086 24X
Fiche 50-267, 84/01/20, 8401270395

--8401270400 Speech entitled, "Superheater Tube Leaks in Steam Generators of Fort St Vrain HTGR," presented at joint ANSI/ASME Jan 1984 conference
WONG, A H, HOLMES, H H Public Service Co of Colorado 84/01/31
40pp 21981 090 24X Fiche 50-267, 84/01/20, 8401270395

8401270242 Announces that RP Denise will become Director, Div of Resident Reactor Project & Engineering Programs, effective 840122 J Gagliardo will be Director of Chattanooga Training Ctr
COLLINS, J T Region 4, Office of Director 84/01/23 LEE, D R
Public Service Co of Colorado 1p 21982 153 24X
Fiche 50-267, 84/01/23, 8401270242

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060190 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401100313 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc" No mats identified used at facility
BREV, H L Public Service Co of Colorado 83/12/21 COLLINS, J T
Region 4, Office of Director 1p 21758 213 24X
Fiche 50-267, 83/12/21, 8401100313

8401230302 Forwards IE Insp Rept 50-267/83-27 on 831024-28 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/22 LEE, D R
Public Service Co of Colorado 2pp 21883 195 24X
Fiche 50-267, 83/12/22, 8401230302

--8401230309 IE Insp Rept 50-267/83-27 on 831024-28 No violations noted Major areas inspected emergency response program
MONTGOMERY, J L, BAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/12/20 8pp 21883 197 24X Fiche 50-267, 83/12/22, 8401230302

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers w/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401170364 Forwards IE Insp Rept 50-267/83-31 on 831101-30 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/28 LEE, D R
Public Service Co of Colorado 2pp 21828 199 24X
Fiche 50-267, 83/12/28, 8401170364

--8401170370 IE Insp Rept 50-267/83-31 on 831101-30 No violations noted Major areas inspected licensee action on previous insp findings, operational safety verification, surveillance, maint, IE bulletin followup & review of periodic & special repts
PLUMLEE, G L, HUNNICUTT, D M Region 4, Office of Director 83/12/28 11pp 21828 201 24X Fiche 50-267, 83/12/28, 8401170364

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401270140 Forwards application for amend to License DPR-34, consisting of Tech Spec changes re inservice insp & testing requirements
LEE, D R Public Service Co of Colorado 83/12/30 COLLINS, J T
Region 4, Office of Director 2pp 21972 255 24X
Fiche 50-267, 83/12/30, 8401270140

--8401270145 Application for amend to License DPR-34, consisting of Tech Spec changes re inservice insp & testing requirements Summary of proposed changes to inservice insp requirements encl
LEE, D R Public Service Co of Colorado 83/12/30 9pp
21972 257 24X Fiche 50-267, 83/12/30, 8401270140

--8401270151 Proposed Tech Spec changes re inservice insp requirements
* Public Service Co of Colorado 83/12/30 136pp 21972 266
24X Fiche 50-267, 83/12/30, 8401270140

8401100474 Notification of 840117 meeting w/util at site to discuss SALP
* Region 4, Office of Director 84/01/05 Region 4, Office of Director 1p 21761 280 24X Fiche 50-267, 84/01/05, 8401100474

8401130293 Submits notarized response to IE Bulletin 83-07 dtd 830722 No mats designated for use at facility supplied by Ray Miller, Inc
LEE, D R Public Service Co of Colorado 84/01/05 COLLINS, J T
Region 4, Office of Director 2pp 21801 133 24X
Fiche 50-267, 84/01/05, 8401130293

DOCKETED ITEMS

69

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401190417 Notifies that administrative procedures will be revised by 840131, in response to IE Insp Rept 50-267/83-24 Full compliance could not be met by 831231 due to problems encountered in production of revised authorization forms
WAREMBORO, D Public Service Co of Colorado 84/01/10
COLLINS, J T Region 4, Office of Director 1p 21849 328 24X Fiche 50-267,84/01/10,8401190417

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401180194 Monthly operating rept for Dec 1983 W/840113 ltr
FULLER, C , WAREMBORO, D Public Service Co. of Colorado 83/12/31
Director's Office, Office of Inspection and Enforcement 9pp
21841 333 24X Fiche 50-267,83/12/31,8401180194

B Reportable occurrences, LERs & related correspondence

8401170193 LER 83-053/03L-0 on 831210, bearing water makeup pump removed from svc w/reactor operating at approx 25% power, to repair associated leaking valves & filters Caused by component failure Valve & filters repaired or replaced W/840109 ltr
NOVACHEK, F J , WAREMBORO, D Public Service Co of Colorado 83/01/09
COLLINS, J T Region 4, Office of Director 3pp
21833 307 24X Fiche 50-267,83/01/09,8401170193

8401100337 Revised LER 83-050/03X-1 on 831116, PCRV CWS temp scanner surveillance not performed within required interval Caused by personnel error Personnel reminded of duties Test completed on 831121 W/831229 ltr
NOVACHEK, F J , WAREMBORO, D Public Service Co of Colorado 83/12/29
COLLINS, J T Region 4, Office of Director 3pp
21761 356 24X Fiche 50-267,83/12/29,8401100337

8401130306 LER 83-052/03L-0 on 831208, prestressed concrete reactor vessel cooling water outlet temp exceeded 120 F limit Caused by absence of svc water preventing necessary heat exchange Flow returned to Bys 46 HX W/840106 ltr
WAREMBORO, D Public Service Co of Colorado 84/01/06
COLLINS, J T Region 4, Office of Director 3pp
21833 227 24X Fiche 50-267,84/01/06,8401130306

8401230186 LER 83-054/03L-0 on 831213, emergency feedwater supply header to loop I helium circulators unavailable to drive circulator water turbines. Caused by repair to safety relief valves & pressure control valve W/840112 ltr
WAREMBORO, D , NOVACHEK, F J Public Service Co of Colorado 84/01/12
COLLINS, J T Region 4, Office of Director 3pp
21884 164 24X Fiche 50-267,84/01/12,8401230186

8401270248 LER 83-055/03L-0 on 831221, helium circular penetration safety valve failed to relieve within Tech Spec criteria Caused by lack of adjustment Valve adjusted W/840120 ltr
WAREMBORO, D , NOVACHEK, F J Public Service Co of Colorado 84/01/20
COLLINS, J T Region 4, Office of Director 3pp
21982 159 24X Fiche 50-267,84/01/20,8401270248

V Operator Examinations

8401270205 Notifies that requalification yr extended from normal ending date of 840531 to 840630 due to plant refueling & mod shutdown
WAREMBORO, D W Public Service Co of Colorado 84/01/11
COLLINS, J T Region 4, Office of Director 1p 21979 140 24X Fiche 50-267,84/01/11,8401270205

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401030216 Forwards Rev 2 to util 830414 response to Suppl 1 to NUREG-0737, consisting of changes to proposed schedule for upgraded emergency preparedness program, delaying implementation of new emergency procedures to Oct 1985
TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 21692 317 24X Fiche 50-269,83/12/27,8401030216

8401060081 Releases public version of revised emergency plan & revised emergency plan implementing procedures manual
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21747 201 24X Fiche 50-269,83/12/28,8401060081

---8401060085 Forwards public version of revised emergency plan & revised emergency plan implementing procedures manual
TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 1p 21747 202 24X Fiche 50-269,83/12/28,8401060081

--8401060090 Public version of Rev 83-8 to emergency plan implementing procedures manual
SMITH, J Duke Power Co 83/11/17 83pp 21747 203 24X Fiche 50-269,83/12/28,8401060081

--8401060094 Public version of Rev 83-2 to emergency plan
SMITH, J Duke Power Co 83/11/18 52pp 21747 286 24X Fiche 50-269,83/12/28,8401060081

8401170484 Forwards exemption from requirements of 10CFR50, App E re annual emergency preparedness exercise, in response to 830309 & 1010 requests No exemption from 10CFR50 47 required
EISENHUT, D O Division of Licensing 84/01/06 TUCKER, H B Duke Power Co 3pp 21844 271 24X Fiche 50-000,84/01/06,8401170484

--8401170491 Exemption from requirements of App E to 10CFR50 re annual emergency preparedness exercise & provisions for training & exercising of licensee employees, including headquarters support personnel in radiation emergency matters
EISENHUT, D O Division of Licensing 84/01/06 Duke Power Co 3pp 21844 277 24X Fiche 50-000,84/01/06,8401170484

8401200010 Summary of 830904 meeting w/util & State of SC re exemption request for emergency operations facility
BUERMANN, J F Operating Reactors Branch 4 84/01/09 Operating Reactors Branch 4 28pp 21871 079 24X Fiche 50-269,84/01/09,8401200010

8401310300 Forwards Rev 11 to security plan Rev withheld (re P 10CFR73 21)
TUCKER, H B Duke Power Co 84/01/16 O'REILLY, J P Region 2, Office of Director 1p 22021 362 24X Fiche 50-269,84/01/16,8401310300

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Arkansas Power & Light Co REYNOLDS, N S Duke Power Co 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000,84/01/19,8401240335

I Financial information

8401100386 Forwards addl info re 1983-85 financial forecast, per IP Dinit: 831107 request Projected figures for yr ended 831231 unavailable
TUCKER, H B Duke Power Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21763 137 24X Fiche 50-000,84/01/04,8401100386

DOCKETED ITEMS

P Operating license stage documents & correspondence

B401040304 Forwards list of mods/upgrades to control rooms to meet habitability requirements of TMI Action Plan Item III D 3 4. Complete implementation expected by end of 1984. Schedule can be provided in Feb 1984.
TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 21708 103 24X Fiche 50-269, 83/12/27, B401040304

B401090652 Responds to telcon re clarification of review of NUREG-0737, Items II K 3 1 & II K 3 2 (automatic PORV isolation) Review combined Items II K 3 7 & II K 3 2, resolving Item II K 3 7.
STOLZ, J F Operating Reactors Branch 4 83/12/28 TUCKER, H B Duke Power Co 1p 21757 359 24X Fiche 50-269, 83/12/28, B401090652

B401090364 Informs that submittal justifying reactor coolant pump manual trip setpoint will be delayed until results of analysis reviewed, in response to Generic Ltr 83-10 Submittal expected by B40330.
TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21754 060 24X Fiche 50-269, 83/12/30, B401090364

B401090508 Suppls B31104 response to Generic Ltr 83-28 "Required Actions Based on Generic Implications of Salem ATWS Events" Automatic shunt trip mode will be installed during next refueling outages. Design description encl.
TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 14pp 21751 232 24X Fiche 50-269, 83/12/30, B401090508

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl.
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401240039 Notifies of completion of review of post-accident sampling sys (NUREG-0737, Item II 3 3) Response to criterion requiring procedure for estimating core damage extent acceptable on interim basis. Plant-specific procedure due B40831.
STOLZ, J F Operating Reactors Branch 4 84/01/11 TUCKER, H B Duke Power Co 21pp 21945 001 24X Fiche 50-269, 84/01/11, B401240039

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl.
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401230188 Forwards response to Item 2 2 1-5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events" Design of electrical safety sys provides for automatic backup for equipment failure.
TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 21884 160 24X Fiche 50-269, 84/01/17, B401230188

B401240402 Advises that facility will implement, by B50101, shift technical advisor program incorporating NRC B31128 requirements. Currently approved program to remain in effect in interim program document will be submitted by B40601.
TUCKER, H B Duke Power Co 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21920 141 24X Fiche 50-269, 84/01/20, B401240402

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR.
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 109pp 21744 004 24X Fiche 50-000, 83/10/20, B401060150

B401050414 Forwards supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp. Final disposition of items under evaluation. Four pieces Schedule 40, SA-234 WPB reducing tees supplied by Tube-Line Corp.
TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 2pp 21731 135 24X Fiche 50-269, 83/12/09, B401050414

B401090216 Forwards IE Insp Repts 50-269/83-35 & 50-270/83-36 on B31128-1201 No violations noted.
DANCE, H C Division of Project & Resident Programs 83/12/16 TUCKER, H B Duke Power Co 2pp 21753 340 24X Fiche 50-269, 83/12/16, B401090216

--B401090219 IE Insp Repts 50-269/83-35 & 50-270/83-36 on B31128-1201 No violations noted. Major areas inspected: surveillance at core power distribution limits.
KRUB, H E Region 2, Office of Director JAFFE, F Division of Engineering & Operational Programs 83/12/13 3pp 21753 342 24X Fiche 50-269, 83/12/16, B401090216

B401040001 Forwards evaluations & conclusions, in response to util B30701 ltr denying one violation identified during NRC B30317-28 insp re containment integrity. Imposition of civil penalties inappropriate.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/20 TUCKER, H B Duke Power Co 3pp 21711 306 24X Fiche 50-269, 83/12/20, B401040001

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401240150 Forwards response to IE Bulletin 81-01, Item 3 re inaccessible mechanical snubber insp list of affected snubbers encl. No failures found.
TUCKER, H B Duke Power Co 84/01/10 O'REILLY, J P Region 2, Office of Director 4pp 21910 265 24X Fiche 50-269, 84/01/10, B401240150

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401200033 Monthly operating repts for Dec 1983 W/B40113 ltr.
REAVIS, J A, TUCKER, H B Duke Power Co 83/12/31 Director's Office, Office of Inspection and Enforcement 17pp 21865 260 24X Fiche 50-269, 83/12/31, B401200033

DOCKETED ITEMS

71

G Reportable occurrences, LERs & related correspondence

B401120266 LER 83-017/01T-0 on 831209, during surveillance testing, control rod drive ac breaker 10 experienced delayed trip. Caused by component failure Trip breakers replaced w/spares. Automatic trip will be installed W/831230 ltr. GUILLY, P F, TUCKER, H B Duke Power Co 83/12/30 O'REILLY, J P Region 2, Office of Director 5pp 21792 137 24X Fiche 50-269, 83/12/30, B401120266

B401230462 LER 83-020/01T-0 on 831209, control rod drive (CRD) ac breaker 10 experienced delayed trip. Caused by component failure Breakers replaced All CRD breaker trip shaft bearing assemblies will be replaced W/840111 ltr. GUILLY, P F, TUCKER, H B Duke Power Co 83/12/30 O'REILLY, J P Region 2, Office of Director 5pp 21882 174 24X Fiche 50-269, 83/12/30, B401230462

V Operator Examinations

B401200221 Forwards revised requalification program for NRC licensed personnel. Appropriate sections revised to incorporate NRC requirements. TUCKER, H B Duke Power Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21864 269 24X Fiche 50-269, 84/01/12, B401200221

--B401200223 Revised requalification program for NRC licensed personnel * Duke Power Co 83/08/19 11pp 21864 270 24X Fiche 50-269, 84/01/12, B401200221

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401030216 Forwards Rev 2 to util 830414 response to Suppl 1 to NUREG-0737, consisting of changes to proposed schedule for upgraded emergency preparedness program, delaying implementation of new emergency procedures to Oct 1985. TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 5pp 21682 317 24X Fiche 50-269, 83/12/27, B401030216

B401060081 Releases public version of revised emergency plan & revised emergency plan implementing procedures manual. FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21747 201 24X Fiche 50-269, 83/12/28, B401060081

--B401060085 Forwards public version of revised emergency plan & revised emergency plan implementing procedures manual. TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 1p 21747 202 24X Fiche 50-269, 83/12/28, B401060081

--B401060090 Public version of Rev 83-B to emergency plan implementing procedures manual. SMITH, J Duke Power Co 83/11/17 83pp 21747 203 24X Fiche 50-269, 83/12/28, B401060081

--B401060094 Public version of Rev 83-2 to emergency plan. SMITH, J Duke Power Co 83/11/18 52pp 21747 286 24X Fiche 50-269, 83/12/28, B401060081

B401170484 Forwards exemption from requirements of 10CFR50, App E re annual emergency preparedness exercise, in response to 830309 & 1010 requests. No exemption from 10CFR50 47 required. EISENHUT, D G Division of Licensing 84/01/06 TUCKER, H B Duke Power Co 5pp 21844 271 24X Fiche 50-000, 84/01/06, B401170484

--B401170491 Exemption from requirements of App E to 10CFR50 re annual emergency preparedness exercise & provisions for training & exercising of licensee employees, including headquarters support personnel in radiation emergency matters. EISENHUT, D G Division of Licensing 84/01/06 Duke Power Co 5pp 21844 277 24X Fiche 50-000, 84/01/06, B401170484

B401200010 Summary of 830906 meeting w/util & State of SC re exemption request for emergency operations facility. SUERMANN, J F Operating Reactors Branch 4 84/01/09 Operating Reactors Branch 4 28pp 21871 079 24X Fiche 50-269, 84/01/09, B401200010

B401310300 Forwards Rev 11 to security plan Rev withheld (ref 10CFR73 21). TUCKER, H B Duke Power Co 84/01/16 O'REILLY, J P Region 2, Office of Director 1p 22021 362 24X Fiche 50-269, 84/01/16, B401310300

H General correspondence

B401240035 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Svc lists should be revised accordingly. REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS, N S Arkansas Power & Light Co REYNOLDS, N S Duke Power Co 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000, 84/01/19, B401240035

I Financial information

B401100386 Forwards addl info re 1983-85 financial forecast, per IP Dinitz 831107 request. Projected figures for yr ended 831231 unavailable. TUCKER, H B Duke Power Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21763 137 24X Fiche 50-000, 84/01/04, B401100386

P Operating license stage documents & correspondence

B401040304 Forwards list of mods/upgrades to control rooms to meet habitability requirements of TMI Action Plan Item III D 3 4. Complete implementation expected by end of 1984. Schedule can be provided in Feb 1984. TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 21708 103 24X Fiche 50-269, 83/12/27, B401040304

B401090652 Responds to telcon re clarification of review of NUREG-0737, Items II K 3 1 & II K 3 2 (automatic PORV isolation). Review combined Items II K 3 7 & II K 3 2, resolving Item II K 3 7. STOLZ, J F Operating Reactors Branch 4 83/12/28 TUCKER, H B Duke Power Co 1p 21757 359 24X Fiche 50-269, 83/12/28, B401090652

B401090364 Informs that submittal justifying reactor coolant pump manual trip setpoint will be delayed until results of analysis reviewed, in response to Generic Ltr 83-10 Submittal expected by 840330. TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21754 060 24X Fiche 50-269, 83/12/30, B401090364

B401090508 Suppl 831104 response to Generic Ltr 83-28 "Required Actions Based on Generic Implications of Salem ATWS Events". Automatic shunt trip mods will be installed during next refueling outages. Design description encl. TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 14pp 21751 232 24X Fiche 50-269, 83/12/30, B401090308

B401050382 Generic Ltr 84-01 to all holders of CLs, applicants for CLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related". Svc list encl. EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for CLs & full power authorizations re notice of meeting on facility staffing. Svc list encl. EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401240039 Notifies of completion of review of post-accident sampling sys (NUREG-0737, Item II B 3) Response to criterion requiring procedure for estimating core damage extent acceptable on interim basis. Plant-specific procedure due 840831. STOLZ, J F Operating Reactors Branch 4 84/01/11 TUCKER, H B Duke Power Co 21pp 21945 001 24X Fiche 50-269, 84/01/11, B401240039

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for CLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues". Svc list encl. EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401230188 Forwards response to Item 2 2 1-5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events". Design of electrical safety sys provides for automatic backup for equipment failure. TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 21884 160 24X Fiche 50-269, 84/01/17, B401230188

DOCKETED ITEMS

8401240402 Advises that facility will implement, by 850101, shift technical advisor program incorporating NRC 831128 requirements. Currently approved program to remain in effect in interim program document will be submitted by 840601
TUCKER, H B Duke Power Co 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21920 141 24X Fiche 50-269, 84/01/20, 8401240402

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Trenchbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401050414 Forwards supplemental response to IE Bulletin 83-06 re nonconforming mats supplied by Tube-Line Corp Final disposition of items under evaluation Four pieces Schedule 40, SA-234 WPB reducing tees supplied by Tube-Line Corp
TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 2pp 21731 135 24X Fiche 50-269, 83/12/09, 8401050414

8401070225 Forwards IE Insp Rept 50-270/83-35 on 831117-19 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/13 TUCKER, H B Duke Power Co 2pp 21753 334 24X Fiche 50-270, 83/12/13, 8401070225

--8401090230 IE Insp Rept 50-270/83-35 on 831117-19 No violations noted Major areas inspected containment integrated leakage rate testing
BROOKS, E H Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/12/12 4pp 21753 336 24X Fiche 50-270, 83/12/12, 8401090230

8401090216 Forwards IE Insp Repts 50-269/83-35 & 50-270/83-36 on 831128-1201 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/16 TUCKER, H B Duke Power Co 2pp 21753 340 24X Fiche 50-269, 83/12/16, 8401090216

--8401090219 IE Insp Repts 50-269/83-35 & 50-270/83-36 on 831128-1201 No violations noted Major areas inspected surveillance at core power distribution limits
KRUG, H E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/12/13 3pp 21753 342 24X Fiche 50-269, 83/12/13, 8401090219

8401040001 Forwards evaluations & conclusions, in response to util 830701 ltr denying one violation identified during NRC 830317-28 insp re containment integrity Imposition of civil penalties inappropriate
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/20 TUCKER, H B Duke Power Co 5pp 21711 304 24X Fiche 50-269, 83/12/20, 8401040001

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 164 24X Fiche 50-000, 84/01/10, 8312120107

8401240150 Forwards response to IE Bulletin 81-01, Item 3 re inaccessible mechanical snubber Insp List of affected snubbers encl No Failures Found
TUCKER, H B Duke Power Co 84/01/10 O'REILLY, J P Region 2, Office of Director 6pp 21910 265 24X Fiche 50-269, 84/01/10, 8401240150

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401200033 Monthly operating repts for Dec 1983 W/840113 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/12/31 Director's Office, Office of Inspection and Enforcement 17pp 21865 260 24X Fiche 50-269, 83/12/31, 8401200033

V Operator Examinations

8401200221 Forwards revised requalification program for NRC licensed personnel Appropriate sections revised to incorporate NRC requirements
TUCKER, H B Duke Power Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21864 269 24X Fiche 50-269, 84/01/12, 8401200221

--8401200223 Revised requalification program for NRC licensed personnel
* Duke Power Co 83/08/19 11pp 21864 270 24X Fiche 50-269, 84/01/12, 8401200223

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8401030219 Forwards evaluation of joint state & local radiological emergency response 820218 exercise Rept describes deficiencies requiring schedule of corrective actions Next rept expected by 831230
KRIMM, R W Federal Emergency Management Agency 83/12/09 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21681 191 24X Fiche 50-271, 83/12/09, 8401030219

--8401030222 Evaluation of joint state & local radiological emergency response 820218 exercise for facility
* Federal Emergency Management Agency 82/06/09 81pp 21681 192 24X Fiche 50-271, 83/12/09, 8401030219

8401060068 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21748 066 24X Fiche 50-271, 83/12/28, 8401060068

--8401060072 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure OP 3530, "Post-Accident Sampling" & Rev 16 to Procedure OP 3506, "Emergency Equipment Readiness Check"
MARKT, D Yankee Atomic Electric Co 83/11/17 NRC - No Detailed Affiliation Given 2pp 21748 067 24X Fiche 50-271, 83/12/28, 8401060068

--8401060076 Public version of Rev 4 to Emergency Plan Implementing Procedure OP 3530, "Post-Accident Sampling" & Rev 16 to Procedure OP 3506, "Emergency Equipment Readiness Check"
PELLETIER, J Yankee Atomic Electric Co 83/11/15 56pp 21748 069 24X Fiche 50-271, 83/12/28, 8401060068

8401100303 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-29 Corrective actions will be examined during future insp
STAROSTECKI, R Division of Project & Resident Programs 84/01/05 MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 21759 167 24X Fiche 50-271, 84/01/05, 8401100303

DOCKETED ITEMS

73

--B40100312 Responds to NRC B31125 ltr re violations noted in IE Insp Rept 50-271/83-29 Corrective actions withheld (ref 10CFR73.21)
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/12/15
STAROSTECKI, R Division of Project & Resident Programs 2pp
21759 171 24X Fiche 50-271.84/01/05.8401100303

B401240516 Forwards IE Mgt Meeting Rept 50-271/83-26 on B31122
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 21908 094
24X Fiche 50-271.84/01/10.8401240516

--B401240527 IE Mgt Meeting Rept 50-271/83-26 on B31122 Major areas discussed safety significance of findings in 10CFR50, App R safe shutdown insp on B30829-0902 & reported in IE Insp Rept 50-271/83-26
PULLANI, S, ANDERSON, C Region 1, Office of Director 84/01/03
4pp 21908 096 24X Fiche 50-271.84/01/10.8401240516

J Insurance & indemnity information

B401130322 Forwards Endorsements 69, 55.5 & 5 to NELIA & MAELU Policies NF-189, NF-56, N-32 & M-32, respectively
SHADER, D Vermont Yankee Nuclear Power Corp 83/12/29 DINITZ, I
Office of Nuclear Reactor Regulation, Director 5pp 21801 323
24X Fiche 50-271.83/12/29.8401130322

P Operating license stage documents & correspondence

B401300027 Requests notification whether GE small break LOCA model approved on B31213 used in LOCA analysis Correct understanding completes TMI Items I K 3 30 & I K 3 31 Requests plans & schedules if understanding incorrect
VASSALLO, D B Operating Reactors Branch 2 84/01/04 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 22006 360 24X
Fiche 50-271.84/01/04.8401300027

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EIBENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000.84/01/05.8401050382

B401190011 Notification of B40109 meeting w/util in Bethesda, MD to discuss plans for repairing moisture-sensitive leak detection sys
ROONEY, V L Operating Reactors Branch 2 84/01/05 VASSALLO, D B
Operating Reactors Branch 2 1p 21870 316 24X
Fiche 50-271.84/01/05.8401190011

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EIBENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000.84/01/06.8401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EIBENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 17p 21946 174 24X
Fiche 50-000.84/01/13.8401130084

B401170352 Responds to NRC B31216 ltr re Generic Ltr B3-41 concerning fast cold starts of diesel generators Nonprelubricated start can lead to long-term wear of machine surface Current operation will not significantly reduce reliability
MURPHY, W P Vermont Yankee Nuclear Power Corp. 84/01/13
EIBENHUT, D O Division of Licensing 1p 21829 350 24X
Fiche 50-271.84/01/13.8401170352

B401240464 Discusses agreements reached w/NRC at B40109 meeting re operability of moisture-sensitive tape leak detection sys installed per IE Bulletin B3-02 NRC will be verbally notified of changes through 1984 refueling outage
MURPHY, W P Vermont Yankee Nuclear Power Corp 84/01/20
VASSALLO, D B Operating Reactors Branch 2 2pp 21918 185 24X
Fiche 50-271.84/01/20.8401240464

B401270492 Suppl to Proposed Change 7B to application to amend License DFR-28, revising radiological ETS
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 84/01/23
EIBENHUT, D O Division of Licensing 13pp 21980 137 24X
Fiche 50-271.84/01/23.8401270492

--B401270497 Proposed radiological ETS
* Vermont Yankee Nuclear Power Corp 84/01/23 83pp 21980 152
24X Fiche 50-271.84/01/23.8401270492

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in FDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000.83/10/20.8401060040

--B401060130 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000.83/10/20.
8401060040

B401040334 Responds to NRC B31115 request for util plans & schedule to resolve outstanding concerns re IE Bulletin B0-14 concerning facility Results of reanalysis effort & schedule will be provided by B40315
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/12/22
VASSALLO, D B Operating Reactors Branch 2 2pp 21706 333 24X
Fiche 50-271.83/12/22.8401040334

B401030074 Notification of Significant Licensee Meeting B4-04 on B40110 w/util in King of Prussia, PA to discuss IE Insp Rept 50-271/83-26
PULLANI, S V Region 1, Office of Director 83/12/27 Region 1,
Office of Director 2pp 21695 257 24X Fiche 50-271.83/12/27.
8401030074

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000.83/12/28.B312120090

B401100063 Confirms B40110 enforcement conference in King of Prussia, PA re IE Insp 50-271/83-26 Agenda encl
MARTIN, T T Division of Engineering & Technical Programs 83/12/29
MURPHY, W P Vermont Yankee Nuclear Power Corp 3pp 21761 144
24X Fiche 50-271.83/12/29.8401100063

B312120093 IE Info Notice B3-04, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 360 24X Fiche 50-000.83/12/30.8312120093

B401100303 Ack receipt of B31215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-29 Corrective actions will be examined during future insp
STAROSTECKI, R Division of Project & Resident Programs 84/01/05
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 21759 169
24X Fiche 50-271.84/01/05.8401100303

--B401100312 Responds to NRC B31125 ltr re violations noted in IE Insp Rept 50-271/83-29 Corrective actions withheld (ref 10CFR73.21)
MURPHY, W P Vermont Yankee Nuclear Power Corp 83/12/15
STAROSTECKI, R Division of Project & Resident Programs 2pp
21759 171 24X Fiche 50-271.84/01/05.8401100303

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000.84/01/10.8312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000.84/01/10.8312120107

B401240516 Forwards IE Mgt Meeting Rept 50-271/83-26 on B31122
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 21908 094
24X Fiche 50-271.84/01/10.8401240516

--B401240527 IE Mgt Meeting Rept 50-271/83-26 on B31122 Major areas discussed safety significance of findings in 10CFR50, App R safe shutdown insp on B30829-0902 & reported in IE Insp Rept 50-271/83-26
PULLANI, S, ANDERSON, C Region 1, Office of Director 84/01/05
4pp 21908 096 24X Fiche 50-271.84/01/10.8401240516

B312120114 IE Info Notice B4-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000.84/01/16.8312120114

DOCKETED ITEMS

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License : Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B401240464 Discusses agreements reached w/NRC at B40109 meeting re operability of moisture-sensitive tape leak detection sys installed per IE Bulletin B3-02 NRC will be verbally notified of changes through 1984 refueling outage
MURPHY, W P Vermont Yankee Nuclear Power Corp B4/01/20
VASBALLO, D B Operating Reactors Branch 2 2pp 21918 185 24X Fiche 50-271, B4/01/20, B401240464

R Periodic operating reports & related correspondence

B401170317 Monthly operating rept for Dec 1983 W/B40113 ltr
BURGER, F J, MURPHY, W P Vermont Yankee Nuclear Power Corp
B3/12/31 NRC - No Detailed Affiliation Given 7pp 21829 351 24X Fiche 50-271, B3/12/31, B401170317

S Reportable occurrences, LERs & related correspondence

B401130033 LER B3-033/03L-O on B31123, main steam line radiation monitor 17-25IC indication decreased, making trip setpoint more than three times greater than required Caused by zero bias voltage drift Monitor recalibr W/B31219 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp B3/12/19
MURLEY, T E Region 1, Office of Director 2pp 21802 337 24X Fiche 50-271, B3/12/19, B401130033

B401160127 LER B3-034/03L-O on B31206, condensate storage tank level instrument LT-107-5B found out of adjustment, resulting in lower setpoint for HPCI suction transfer Caused by zero shift of level transmitter W/B40105 ltr
PELLETIER, J P Vermont Yankee Nuclear Power Corp B4/01/05
MURLEY, T E Region 1, Office of Director 2pp 21815 010 24X Fiche 50-271, B4/01/05, B401160127

B401120420 PNG-1-B4-002 on B40105, reactor automatically scrammed from full power due to pressure oscillation induced by turbine generator electrical pressure regulator Alternate power supply to reactor protection sys lost
RAYMOND, W J, GALLO, R, KISTER, H Region 1, Office of Director
B4/01/06 2pp 21791 181 24X Fiche 50-271, B4/01/06, B401120420

X Onsite Storage of Low Level Waste

B401130045 Submits program for 10CFR61 implementation for review & concurrence as adequate means of implementation of requirements on waste form & classification
MURPHY, W P Vermont Yankee Nuclear Power Corp B3/12/29
HIGGINSBOTHAM, L Low Level Waste Licensing Branch 3pp 21819 333 24X Fiche 50-271, B3/12/29, B401130045

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401160186 Forwards 10CFR170 fee remittance for fire protection reviews & approvals, per B31205 ltr
LIDEN, E A Public Service Electric & Gas Co of New Jersey
B3/01/10 MILLER, W O License Fee Management Branch 1p 21815 355 24X Fiche 50-272, B3/01/10, B401160186

B401190171 Responds to B31110 ltr requesting determination re nature of proposed change to security plan to implement vital island concept Request referred to headquarters
MARTIN, T T Division of Engineering & Technical Programs B3/12/19
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 21861 357 24X Fiche 50-272, B3/12/19, B401190171

B401030244 Forwards "Exercise Evaluation Rept for Salem Exercise on B31026 "
KRIMM, R W Federal Emergency Management Agency B3/12/21
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 2pp 21681 078 24X Fiche 50-272, B3/12/21, B401030244

--B401030249 "Exercise Evaluation Rept for Salem Exercise on B31026 "
* Federal Emergency Management Agency B3/11/25 69pp 21681 080 24X Fiche 50-272, B3/12/21, B401030244

B401100383 Forwards IE Insp Rept 50-272/83-30 on B31025-27 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B3/12/21
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 21763 129 24X Fiche 50-272, B3/12/21, B401100383

--B401100400 IE Insp Rept 50-272/83-30 on B31025-27 No violations noted
Major areas inspected emergency preparedness insp & observation of licensee annual emergency full-scale exercise performed B31026
SMITH, R H Region 1, Office of Director CROCKER, H W Division of Engineering & Technical Programs B3/12/15 5pp 21763 131 24X Fiche 50-272, B3/12/21, B401100385

B401060122 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records B3/12/28 Document Management Branch 1p 21745 311 24X Fiche 50-272, B3/12/28, B401060122

--B401060127 Forwards public version of revised emergency plan implementing procedures, including Procedures EP I-1 re notification of unusual event/significant event, EP I-2 re alert & EP I-3 re site area emergency
* Public Service Electric & Gas Co of New Jersey B3/10/21
VARGA, S A Operating Reactors Branch 1 1p 21745 312 24X Fiche 50-272, B3/12/28, B401060122

--B401060136 Public version of revised emergency plan implementing procedures, including Procedures EP I-1 re notification of unusual event/significant event, EP I-2 re alert & EP I-3 re site area emergency
* Public Service Electric & Gas Co of New Jersey B3/10/21 100pp 21745 313 24X Fiche 50-272, B3/12/28, B401060122

B401110153 Requests exemption from 10CFR50, App R requirements re definition of fire areas & suppression sys (per Generic Ltr B3-33) Detailed justification will be submitted by B40131
LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/12/28
VARGA, S A Operating Reactors Branch 1 4pp 21772 294 24X Fiche 50-272, B3/12/28, B401110153

B401050270 Responds to util B31110 request that determination be made as to whether proposed change to security plan to implement vital island concept be made per 10CFR50 54 or 10CFR50 90 Request referred to headquarters for review
MARTIN, T T Division of Engineering & Technical Programs B3/12/29
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 21727 171 24X Fiche 50-272, B3/12/29, B401050270

B401110149 Forwards control room design review summary rept required by Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability " W/o encl
LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/12/29
VARGA, S A Operating Reactors Branch 1 1p 21772 211 24X Fiche 50-272, B3/12/29, B401110149

B401240056 Forwards IE Mgt Meeting Rept 50-272/83-37 on B31214
MARTIN, T T Division of Engineering & Technical Programs B4/01/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 21912 334 24X Fiche 50-272, B4/01/10, B401240056

--B401240059 IE Mgt Meeting Rept 50-272/83-37 on B31214 Major areas discussed lessons learned from previous 10CFR50, App R safe shutdown insps, App R exemption requests & licensee review of fire protection features
PULLANI, S V, ANDERSON, C J Region 1, Office of Director
B4/01/05 3pp 21912 336 24X Fiche 50-272, B4/01/10, B401240056

B401200185 Requests addl exemptions from listed 10CFR50, App R requirements, per B31228 ltr, explaining significant deviation in interpretation provided in Generic Ltr B3-33 Justification will be submitted by B40131
LIDEN, E A Public Service Electric & Gas Co of New Jersey B4/01/13
VARGA, S A Operating Reactors Branch 1 4pp 21863 354 24X Fiche 50-272, B4/01/13, B401200185

B401240566 Discusses B31107 SALP rept for Oct 1982 - Sept 1983, util B31220 ltr & B31201 meeting re operating performance List of attendees encl No changes to rept necessary
MURLEY, T E Region 1, Office of Director B4/01/19 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 4pp 21909 029 24X Fiche 50-272, B4/01/19, B401240566

--B401240577 SALP rept for Oct 1982 - Sept 1983
* Region 1, Office of Director B3/11/07 44pp 21909 033 24X Fiche 50-272, B4/01/19, B401240566

DOCKETED ITEMS

75

G Adjudicatory correspondence

B401050295 Requests 2-wk extension until 840118 to file at least one cognizable contention
DELANEY, C E Delaware, State of 83/12/28 MILLER, M E Atomic
Safety and Licensing Board Panel 1p 21728 311 24X
Fiche 50-272, 83/12/28, 8401050295

B401090343 Order extending time until 840118 for State of DE to file suppl to intervention petition Time for responses & answers extended for similar period of time
MILLER, M E Atomic Safety and Licensing Board Panel 84/01/05
Delaware, State of 2pp 21754 100 24X Fiche 50-272, 84/01/05, 8401090343

B401240161 Advises that no contention will be filed re SER for amend extending time period for performance of Type A test
Petition opposing license amend on one-time basis withdrawn
DELANEY, C E Delaware, State of 84/01/17 MILLER, M E Atomic
Safety and Licensing Board Panel 1p 21910 293 24X
Fiche 50-272, 84/01/17, 8401240161

B401250196 Motion to withdraw petition for leave to intervene & request for hearing re extension of time for Type A test Certificate of Svc encl
DELANEY, C E Delaware, State of 84/01/20 Atomic Safety and
Licensing Board Panel 3pp 21937 142 24X Fiche 50-272, 84/01/20, 8401250196

B401270304 Order dismissing proceeding re State of DE intervention petition concerning 7-month extension for performance of containment integrated leak rate Type A test State of DE withdrew petition on 840120
MILLER, M E Atomic Safety and Licensing Board Panel 84/01/25
2pp 21976 076 24X Fiche 50-272, 84/01/25, 8401270304

B401300218 Response to State of DE 840120 motion to withdraw petition for leave to intervene Licensee concurs in motion Dismissal of proceeding requested Certificate of Svc encl
CONNER, T D Pacific Gas & Electric Co CONNER, T D Conner & Wetterhahn 84/01/25 Atomic Safety and Licensing Board Panel
3pp 22062 113 24X Fiche 50-272, 84/01/25, 8401300218

P Operating license stage documents & correspondence

B401290015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401290015

--B205270663 Provides info re qualifications & experience of personnel operating plant during current strike, in response to Chairman Pelladino request
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-195 82/05/14 4pp 21964 154 24X
Fiche 50-000, 83/10/18, 8401290015

B401040175 Provides update on mods to post-accident sampling sys (PASS) Sys capabilities will be upgraded through direct tie-in of RHR pump discharge sample lines w/PASS, eliminating need for current sys
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/02 MURLEY, T E Region 1, Office of Director 2pp
21702 098 24X Fiche 50-272, 83/12/02, 8401040175

B401040203 Forwards Nuclear Oversight Committee charter First committee meeting held on 831027 & featured discussion of introductory matters, administrative details & schedule for future 1984 meetings
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/08 STAROSTECKI, R Division of Project & Resident Programs
4pp 21701 199 24X Fiche 50-272, 83/12/08, 8401040203

B401100094 Responds to TMI Item II F 2, "Inadequate Core Cooling Instrumentation" Calibr & test info for Unit 2 tentatively scheduled for submittal by 840301
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/23 VARQA, S A Operating Reactors Branch 1 3pp 21772 212
24X Fiche 50-272, 83/12/23, 8401100094

B401100301 Application for amend to Licenses DPR-70 & DPR-75, consisting of License Change Request (LCR) 83-17 re rewording of action statements for Unit 1 to agree w/Unit 2 & BTS & LCR-83-18 re diesel generator surveillance
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/12/27 VARQA, S A Operating Reactors Branch 1 10pp 21759 175
24X Fiche 50-272, 83/12/27, 8401100301

--B401100317 Proposed License Change Requests 83-17, 83-18 & 83-19 re mod of Unit 1 Tech Spec Tables 3.3-1 & 3.3-2 to be consistent w/Unit 2 & correcting typographical error re diesel generator surveillance
* Public Service Electric & Gas Co of New Jersey 83/12/27
7pp 21759 178 24X Fiche 50-272, 83/12/27, 8401100301

B401180126 SAFETY EVALUATION REPORT RELATED TO PLANT RESTART OF SALEM NUCLEAR GENERATING STATION, UNIT NOS 1 AND 2 Docket Nos 50-272 And 50-311 (Public Service Electric And Gas Company, et al)
* Division of Licensing NUREG-0995 83/12/31 117pp Available at NRC \$5 00 21847 176 24X Fiche 50-272, 83/12/31, 8401180126

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

B401200215 Forwards fee for 831227 application to amend Licenses DPR-70 & DPR-75
LIDEN, E A Public Service Electric & Gas Co of New Jersey
84/01/12 VARQA, S A Operating Reactors Branch 1 1p 21863 360
24X Fiche 50-272, 84/01/12, 8401200215

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

B401100385 Forwards IE Insp Rept 50-272/83-30 on 831025-27 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/21
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21763 129 24X Fiche 50-272, 83/12/21, 8401100385

--B401100400 IE Insp Rept 50-272/83-30 on 831025-27 No violations noted
Major areas inspected emergency preparedness insp & observation of licensee annual emergency full-scale exercise performed 831026
SMITH, R H Region 1, Office of Director CROCKER, H W Division
of Engineering & Technical Programs 83/12/15 5pp 21763 131
24X Fiche 50-272, 83/12/21, 8401100385

B401040153 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-15 & 50-311/83-12 Util position against testing 225J156 will be documented in Mar 1984
STAROSTECKI, R Division of Project & Resident Programs 83/12/23
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21701 354 24X Fiche 50-272, 83/12/23, 8401040153

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 165 24X Fiche 50-000, 83/12/28, 8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

DOCKETED ITEMS

B401100408 Ack receipt of B31220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/B3-15 & 50-311/B3-12
STAROSTECKI, R Division of Project & Resident Programs 83/12/30
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
21763 032 24X Fiche 50-272, 83/12/30, B401100408

--B401100419 Responds to NRC B31109 ltr re violations noted in IE Insp Repts 50-272/B3-15 & 50-311/B3-12 Corrective actions corporate GA organization relocated from Newark to Artificial Island
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/20 STAROSTECKI, R Division of Project & Resident Programs
2pp 21763 033 24X Fiche 50-272, 83/12/30, B401100408

B401130131 Ack receipt of B30826 & 1209 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/B3-16 & 50-311/B3-15
STAROSTECKI, R Division of Project & Resident Programs 84/01/09
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
21802 100 24X Fiche 50-272, 84/01/09, B401130131

--B401130134 Responds to NRC B30720 ltr re violations noted in IE Insp Repts 50-272/B3-16, 50-311/B3-15 & 50-311/B3-18 Corrective actions design change prepared to install permanent instrumentation
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/08/26 STAROSTECKI, R Division of Project & Resident Programs
4pp 21802 101 24X Fiche 50-272, 84/01/09, B401130131

--B401130143 Suppls response to NRC B30720 ltr re violations noted in IE Insp Repts 50-272/B3-16, 50-311/B3-15 & 50-311/B3-18 Corrective actions TRIS electrical & mechanical lineups reviewed & approved in accordance w/ existing requirements
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/09 STAROSTECKI, R Division of Project & Resident Programs
4pp 21802 103 24X Fiche 50-272, 84/01/09, B401130131

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 033 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401240056 Forwards IE Mgt Meeting Rept 50-272/B3-37 on B31214
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21912 334 24X Fiche 50-272, 84/01/10, B401240056

--B401240059 IE Mgt Meeting Rept 50-272/B3-37 on B31214 Major areas discussed lessons learned from previous 10CFR50, App R safe shutdown insps, App R exemption requests & licensee review of fire protection features
PULLANI, S V, ANDERSON, C J Region 1, Office of Director
84/01/05 3pp 21912 336 24X Fiche 50-272, 84/01/10, B401240056

B401240520 Forwards IE Mgt Meeting Repts 50-272/84-01 & 50-311/84-01 on B40105
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21918 080 24X Fiche 50-272, 84/01/10, B401240520

--B401240530 IE Mgt Meeting Rept 50-272/84-01 & 50-311/84-01 on B40105 Major areas discussed status of Util action plan for improvement of nuclear dept operations, submitted to NRC in Aug 1983
LINVILLE, J C Region 1, Office of Director NORRHOLM, L J
Division of Project & Resident Programs 84/01/05 60pp
21918 082 24X Fiche 50-272, 84/01/10, B401240520

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B401230454 Ack receipt of B31228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/B3-33 & 50-311/B3-33
STAROSTECKI, R Division of Project & Resident Programs 84/01/17
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21882 165 24X Fiche 50-272, 84/01/17, B401230454

--B401230461 Responds to NRC B31123 ltr re violations noted in IE Insp Repts 50-272/B3-33 & 50-311/B3-33 Corrective actions LER 83-048/03L filed on B31104 Shift supervisor counseled re submitting safety-related equipment failure repts
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/28 STAROSTECKI, R Division of Project & Resident Programs
2pp 21882 167 24X Fiche 50-272, 84/01/17, B401230454

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

B401240566 Discusses B31107 SALP rept for Oct 1982 - Sept 1983, util B31220 ltr & B31201 meeting re operating performance List of attendees encl No changes to rept necessary
MURLEY, T E Region 1, Office of Director 84/01/19 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 4pp 21909 029
24X Fiche 50-272, 84/01/19, B401240566

--B401240577 SALP rept for Oct 1982 - Sept 1983
* Region 1, Office of Director 83/11/07 44pp 21909 033 24X
Fiche 50-272, 84/01/19, B401240566

--B401240619 Informs of B31201 onsite meeting to discuss results of B31107 SALP rept Written comments may be provided within 20 days after meeting
STAROSTECKI, R Division of Project & Resident Programs 83/11/22
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
1p 21909 077 24X Fiche 50-272, 84/01/19, B401240566

--B401240628 Expresses concern re B31107 SALP rept statements on util operating performance Extension until B40125 requested for providing detailed response to SALP findings in functional area of plant operations
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/12/20 STAROSTECKI, R Division of Project & Resident Programs
2pp 21909 078 24X Fiche 50-272, 84/01/19, B401240566

R Periodic operating reports & related correspondence

B401240117 Monthly operating rept for Dec 1983 W/B40110 ltr
MILLER, L K, ZUPKO, J H Public Service Electric & Gas Co of New Jersey 83/12/31 Director's Office, Office of Inspection and Enforcement 23pp 21913 185 24X Fiche 50-272, 83/12/31, B401240117

B401310353 Revised monthly operating rept for Dec 1983 Change specifies shutdowns scheduled over next 6 months & changes refueling date to B40531 W/B40119 ltr
MILLER, L K, ZUPKO, J H Public Service Electric & Gas Co of New Jersey 83/12/31 Director's Office, Office of Inspection and Enforcement 2pp 22019 305 24X Fiche 50-272, 83/12/31, B401310353

B401310265 Forwards "Nuclear Oversight Committee," first quarterly rept
LIDEN, E A Public Service Electric & Gas Co of New Jersey
84/01/26 VARQA, S Operating Reactors Branch 1 1p 22018 104
24X Fiche 50-272, 84/01/26, B401310265

--B401310268 "Nuclear Oversight Committee," first quarterly rept
* Public Service Electric & Gas Co of New Jersey 84/01/23
11pp 22018 105 24X Fiche 50-272, 84/01/26, B401310265

S Reportable occurrences, LERs & related correspondence

B401100010 Outlines completion of corrective action program stemming from Feb 1983 reactor trip breaker failures, described in Item C 7 2 of B30408 ltr Intent of NRC B30506 order met Documentation sent to vendors of long-term program supplies
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/19 EISENHUT, D G Division of Licensing 2pp 21761 201
24X Fiche 50-272, 83/12/19, B401100010

B401130214 LER 83-062/99X-0 on B31122, triaxial time-history accelerometer inside bioshield on 81-ft elevation of containment bldg failed Cause not stated Accelerometer will be replaced during next outage W/B31230 ltr
RUPP, J L, ZUPKO, J H Public Service Electric & Gas Co of New Jersey 83/12/30 MURLEY, T E Region 1, Office of Director 4pp
21801 153 24X Fiche 50-272, 83/12/30, B401130214

DOCKETED ITEMS

77

B401130256 LER 83-060/03L-0 on 831203, during routine surveillance, vital heat trace channel 402B failed to draw greater than 0.5 amps as required. Caused by connections exhibiting high resistance. Terminals cleaned & tightened W/831230 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/12/30. MURLEY, T. E. Region 1, Office of Director. 4pp. 21800 333. 24X Fiche 50-272, 83/12/30, B401130256.

B401130329 LER 83-061/03L-0 on 831207, reactor trip sys & ESF actuation sys instrumentation surveillance testing not completed within 1 h limit required by Tech Specs. Caused by typographical error in procedure W/831230 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/12/30. MURLEY, T. E. Region 1, Office of Director. 5pp. 21801 337. 24X Fiche 50-272, 83/12/30, B401130329.

B401270087 LER 83-066/01T-0 on 831225 & 26, fire suppression water storage tank capacity dropped below min. Caused by ruptured elbow on sprinkler riser due to freezing. Elbow replaced & number of operating pumps increased W/840106 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 84/01/06. MURLEY, T. E. Region 1, Office of Director. 5pp. 21982 109. 24X Fiche 50-272, 84/01/06, B401270087.

B401270150 LER 83-072/01T-0 on 831229, fire suppression water storage tanks indicated level below min. capacity allowed. Caused by incorrect fire suppression storage tank capacity curves. New tank capacity curves generated W/840112 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 84/01/12. MURLEY, T. E. Region 1, Office of Director. 5pp. 21982 104. 24X Fiche 50-272, 84/01/12, B401270150.

B401270464 LER 83-064/03L-0 on 831214, fuel oil leak found on fire suppression pump diesel engine 1 & pump declared inoperable. Caused by fuel oil pressure gauge hose rupture due to wear from normal engine vibration. Hose replaced W/840112 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 84/01/13. MURLEY, T. E. Region 1, Office of Director. 4pp. 21980 322. 24X Fiche 50-272, 84/01/13, B401270464.

B401240566 Discusses 831107 SALP rept for Oct 1982 - Sept 1983, util. 831220 ltr & 831201 meeting re operating performance. List of attendees encl. No changes to rept necessary. MURLEY, T. E. Region 1, Office of Director. 84/01/19. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 4pp. 21909 029. 24X Fiche 50-272, 84/01/19, B401240566.

--B401240577 SALP rept for Oct 1982 - Sept 1983. * Region 1, Office of Director. 83/11/07. 44pp. 21909 033. 24X. Fiche 50-272, 84/01/19, B401240566.

DOCKET 50-274 U 8 GEOLOGICAL SURVEY RESEARCH REACTOR

P Operating license stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 BECY papers. Forwards App A documents. Remaining documents under review. FELTON, J. M. Division of Rules and Records. 83/10/18. WEISS, E. R. Union of Concerned Scientists. 3pp. 21960 005. 24X. Fiche 50-000, 83/10/18, B401250015.

--B401250353 Recommends issuance of encl. order granting in part & denying in part motion to direct staff to reschedule 831013 meeting re Sandia Lab preliminary evaluation of facility safety study. MALSCH, M. G. Office of the General Counsel. BECY-82-473. 82/11/30. 5pp. 21967 121. 24X. Fiche 50-000, 83/10/18, B401250015.

'R Periodic operating reports & related correspondence

B401310310 Annual operating rept for 1983. * Interior, Dept. of, Geological Survey. 83/12/31. 7pp. 22026 273. 24X. Fiche 50-274, 83/12/31, B401310310.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), supp. & correspondence

B401090163 Forwards SSER 20 final draft re items to be resolved prior to Step 2 (criticality & low power testing). Concurrence requested W/o encl. EISENHUT, D. G. Division of Licensing. 83/12/22. MATTSO, R. Division of Systems Integration (post 811005). VOLLMER, R. Division of Engineering. 1p. 21757 214. 24X. Fiche 50-275, 83/12/22, B401090163.

8312120095 Board Notification 83-192 forwards EDO 831223 memo & SSER 20 (NUREG-0675) re authorization for criticality & low power testing. EISENHUT, D. G. Division of Licensing. 83/12/29. Atomic Safety and Licensing Appeal Panel. 2pp. 21740 272. 24X. Fiche 50-275, 83/12/29, B312120095.

--B401030397 Forwards SSER 20 on criticality/low power authorization re design verification program. Issues flowing from IDVP/ITP requiring satisfactory resolution resolved. DIRCKS, W. Office of the Executive Director for Operations. 83/12/23. PALLADINO, N. C. Commissioners. 61pp. 21740 274. 24X. Fiche 50-275, 83/12/29, B312120095.

B401170143 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2. Docket Nos. 50-275 AND 50-323 (Pacific Gas and Electric Company). * Division of Licensing. NUREG-0675 S21. 83/12/31. 275pp. Available at NRC \$7.00. 21939 001. 24X. Fiche 50-275, 83/12/31, B401170143.

B401260071 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2. Docket Nos. 50-275 AND 50-320 (Pacific Gas and Electric Company). * Division of Licensing. NUREG-0675 S20. 83/12/31. 50pp. 21971 198. 24X. Fiche 50-275, 83/12/31, B401260071.

B401100387 Notifies that equipment environ. qualification files updated to reflect evaluation of equipment for revised environ. at facility. Completion of documentation fulfills commitment identified in SSER 20 Followup Item 12. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/04. KNIGHTON, G. W. Licensing Branch 3. 1p. 21763 136. 24X. Fiche 50-275, 84/01/04, B401100387.

B401190144 Forwards SSER 20 (NUREG-0676) W/o encl. KNIGHTON, G. W. Licensing Branch 3. 84/01/04. SCHUYLER, J. D. Pacific Gas & Electric Co. 4pp. 21871 006. 24X. Fiche 50-275, 84/01/04, B401190144.

B401100417 Forwards results of analysis requested at 831206 meeting re pipe sys. in high amplification area of annulus structure. Info closes SSER 20 Open Item 2. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/06. KNIGHTON, G. W. Licensing Branch 3. 2pp. 21763 065. 24X. Fiche 50-275, 84/01/06, B401100417.

B401250486 Forwards SSER 21 (NUREG-0675). Suppl. provides info on status of staff review of allegations & concerns about design, const. & operation W/o encl. KNIGHTON, G. W. Licensing Branch 3. 84/01/11. SCHUYLER, J. D. Pacific Gas & Electric Co. 4pp. 21948 347. 24X. Fiche 50-275, 84/01/11, B401250486.

B401240247 Forwards addl. info re SSER 20, Item 5 on environ. qualification of motor capacitor used in auxiliary feedwater level control valves. Util. will submit ITT General Control documentation to enable NRC to close item. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/20. KNIGHTON, G. W. Licensing Branch 3. 2pp. 21910 142. 24X. Fiche 50-275, 84/01/20, B401240247.

B401240555 Forwards list of SSER 20 open items which need to be resolved prior to initial criticality & low power testing, or prior to power ascension. Requests acknowledgement of matl. receipt. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/20. KNIGHTON, G. W. Licensing Branch 3. 5pp. 21907 332. 24X. Fiche 50-275, 84/01/20, B401240555.

B401260218 Provides basis for not plugging Row 1 steam generator tubes, in response to SSER 9 open item. Observed leakage rates low & stable. Tubes will leak rather than burst. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/23. EISENHUT, D. G. Division of Licensing. 4pp. 21956 260. 24X. Fiche 50-275, 84/01/23, B401260218.

F Security, medical, emergency & fire protection plans

B401240410 Forwards Attachments A, B & C to Rev. 11 to security plan. Attachments withheld (ref. 10CFR73.21). SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/11. MARTIN, J. B. Region 5, Office of Director. 1p. 21920 139. 24X. Fiche 50-275, 84/01/11, B401240410.

B401240134 Provides Westinghouse Owners Group revised completion schedules for resolution of TMI Action Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps." Revised emergency response guidelines will be completed by 830731. SCHUYLER, J. D. Pacific Gas & Electric Co. 84/01/19. EISENHUT, D. G. Division of Licensing. 2pp. 21910 291. 24X. Fiche 50-275, 84/01/19, B401240134.

DOCKETED ITEMS

B Adjudicatory correspondence

8401040205 Advises that util asserted failure to disclose 1977 NSC audit rpt of Pullman Power Products being considered as petition for enforcement action, per ALAB-756 request
CHANDLER, L J Hearing Branch 2 83/12/29 MOORE, T G, BUCK, J H, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 2pp
21701 204 24X Fiche 50-275, 83/12/29, 8401040205

8401050221 Errata to 831223 proposed findings of fact & conclusions of law re design QA Certificate of Svc encl
HAVIAN, E R Joint Intervenor - Diablo Canyon HAVIAN, E R Center for Law in the Public Interest 83/12/29 4pp 21728 185 24X
Fiche 50-275, 83/12/29, 8401050221

8401050200 Notifies of 840117 meeting in Washington, DC re staff briefing & comments of util, Joint Intervenor & Governor Deukmejian on staff recommendation on reinstatement of low power license for facility
CHILK, S J Office of the Secretary of the Commission 84/01/03
OHLBACH, R, CRANE, P A, LOCKE, R F Pacific Gas & Electric Co 2pp
21727 341 24X Fiche 50-275, 84/01/03, 8401050200

8401050243 Advises that author 831230 ltr incorrectly stated that Commission meeting scheduled for 840113 Correct meeting date is 840117 W/o encl
CHILK, S J Office of the Secretary of the Commission 84/01/03
OHLBACH, R, CRANE, P A, LOCKE, R F Pacific Gas & Electric Co 2pp
21729 106 24X Fiche 50-275, 84/01/03, 8401050243

8401100137 Response to Joint Intervenor & Governor Deukmejian 831223 proposed findings of fact & conclusions of law re design QA Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 84/01/04 43pp 21761 077 24X
Fiche 50-275, 84/01/04, 8401100137

8401120286 Proposed findings of fact & conclusions of law authorizing issuance of full-power DLs for Units 1 & 2 & extending License DPR-76 per 820803 & 830817 requests Certificate of Svc encl
MCOURREN, H J Hearing Branch 1 CHANDLER, L J Hearing Branch 2 84/01/04 73pp 21793 001 24X Fiche 50-275, 84/01/04, 8401120286

8401060443 Requests comments on licensee 840104 request for further reinstatement of precriticality testing authority Comments requested by 840116
CHILK, S J Office of the Secretary of the Commission 84/01/05
REYNOLDS, J R, PHILLIPS, J R Center for Law in the Public Interest
STRUMWASSER, M California, State of 6pp 21740 077 24X
Fiche 50-275, 84/01/05, 8401060443

8401100139 Requests Commission 840117 briefing on concerns requiring further review prior to NRC recommendation re low power licensing be rescheduled after House Subcommittee 840124 hearing
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor - Diablo Canyon 84/01/06 PALLADINO, N, GILINSKY, V, ROBERTS, T Commissioners 2pp 21760 361 24X
Fiche 50-275, 84/01/06, 8401100139

840110183 Forwards errata to SECY-84-001, "Mod of Commission Memorandum & Order re Operation of Diablo Canyon Nuclear Power Plant," consisting of Encl 1, inadvertently omitted from original submittal
CHILK, S J Office of the Secretary of the Commission 84/01/09
PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 1p
21772 338 24X Fiche 50-275, 84/01/09, 840110183

--840110187 Errata to SECY-84-001, "Mod of Commission Memorandum & Order re Operation of Diablo Canyon Nuclear Power Plant," consisting of Encl 1
* NRC - No Detailed Affiliation Given SECY-84-001 ERR
84/01/09 6pp 21772 339 24X Fiche 50-275, 84/01/09, 840110183

8401160204 Petition for Commission review of ALAB-756 & for reversal of ASLAB denial of motion to reopen record re const QA Certificate of Svc encl
REYNOLDS, J R Joint Intervenor - Diablo Canyon REYNOLDS, J R, Center for Law in the Public Interest 84/01/09 Commissioners 2pp 21815 143 24X Fiche 50-275, 84/01/09, 8401160204

8401170249 Petition for Commission review of ALAB-756 re denial of Governor Deukmejian motion to reopen record on const QA issue Certificate of Svc encl
STRUMWASSER, M California, State of 84/01/09 Commissioners 15pp 21832 226 24X Fiche 50-275, 84/01/09, 8401170249

8401160242 Confirms 840109 telcon wherein NRC extended deadline for filing petition re review of ALAB-756 until 840111
VAN DE KAMP, J, STRUMWASSER, M California, State of 84/01/10
CHILK, S J Atomic Safety and Licensing Appeal Panel 1p
21814 096 24X Fiche 50-275, 84/01/10, 8401160242

8401180235 Requests NRC complete three listed steps to determine validity of allegations re potential safety problems before authorizing plant operation
O'CONNELL, J California, State of 84/01/11 PALLADINO, N Commissioners 2pp 21844 096 24X Fiche 50-275, 84/01/11, 8401180235

8401180187 Comments on Commission consideration of low power license investigation of all allegations re poor const, safety & GC recommended
HART, G K California, State of 84/01/12 PALLADINO, N Commissioners 2pp 21840 348 24X Fiche 50-275, 84/01/12, 8401180187

8401180210 Recommends authorization of NRC investigation of QA/GC breakdown, independent audit of design review & independent comprehensive QA reinsp of all safety-related hardware
CHACON, P R California, State of 84/01/12 PALLADINO, N Commissioners 2pp 21842 361 24X Fiche 50-275, 84/01/12, 8401180210

8401170243 Advises that Governor Deukmejian supports util request for authority to operate at Modes 3 & 4 No safety hazards presented by precriticality operation Testing can provide valuable info re operation of plant
STRUMWASSER, M California, State of 84/01/13 PALLADINO, N Commissioners 1p 21832 241 24X Fiche 50-275, 84/01/13, 8401170243

8401170294 Informs that hot sys testing will be conducted during wk of 840123 Criticality will be achieved during wk of 840213
MANEATIS, O A Pacific Gas & Electric Co 84/01/13 PALLADINO, N J, ASSELSTINE, J K, BERNTHAL, F M Commissioners 1p 21832 326 24X
Fiche 50-275, 84/01/13, 8401170294

8401170322 Submits Joint Intervenor's opposition to util applications to permit hot sys testing (Modes 3 & 4) & low power operation Design & const deficiencies should be corrected before add'l licensing authority granted
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor - Diablo Canyon 84/01/13 PALLADINO, N, GILINSKY, V, ROBERTS, T Commissioners 11pp 21831 158 24X
Fiche 50-275, 84/01/13, 8401170322

8401170236 Order CLI-84-1, denying Joint Intervenor's request for stay of fuel loading & precriticality testing at facility
Commissioner Gilinsky separate views encl
CHILK, S J Office of the Secretary of the Commission 84/01/16
3pp 21831 359 24X Fiche 50-275, 84/01/16, 8401170236

8401250235 Confirms 840116 discussion wherein Secretary Chilk granted leave to all parties to file answers to Joint Intervenor's & Governor Deukmejian petitions for review of ALAB-756 by 840126
CHANDLER, L J Hearing Branch 2 84/01/16 CHILK, S J Office of the Secretary of the Commission 2pp 21944 130 24X
Fiche 50-275, 84/01/16, 8401250235

8401230435 Renews 830915 request that Commission briefing scheduled for 840215 re reinstatement of suspended low power license be held in San Luis Obispo, CA
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor - Diablo Canyon 84/01/17 PALLADINO, N, GILINSKY, V, ROBERTS, T Commissioners 2pp 21882 144 24X
Fiche 50-275, 84/01/17, 8401230435

8401260199 Memorandum & Order CLI-84-2, granting & authorizing further precriticality testing in Operational Modes 4 & 3 as defined in Tech Specs
CHILK, S J Office of the Secretary of the Commission 84/01/25
Pacific Gas & Electric Co 3pp 21936 138 24X
Fiche 50-275, 84/01/25, 8401260199

8401300214 Answer in opposition to Governor Deukmejian & Joint Intervenor's 840109 petition for review of ALAB-756 re const QA Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co * Norton, Burke, Berry & French 84/01/26 Commissioners 46pp 21995 258 24X
Fiche 50-275, 84/01/26, 8401300214

8401300314 Answer to Governor Deukmejian 840109 petition for review of ALAB-756 re const QA ASLAB assessment of applicability of App D correct Petition should be denied Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 84/01/26 Commissioners 14pp 21994 172 24X
Fiche 50-275, 84/01/26, 8401300314

8401310267 Responds to 840117 request that briefing on reinstatement of low power license be held in San Luis Obispo, CA Request denied Briefing will convene on 840210 in Washington, DC
CHILK, S J Office of the Secretary of the Commission 84/01/30
REYNOLDS, J R Center for Law in the Public Interest 1p
22020 342 24X Fiche 50-275, 84/01/30, 8401310267

DOCKETED ITEMS

H General correspondence

B401050294 Requests info re events at facility & questions plant operation
GLESEN, M Affiliation Unknown 83/12/28 NRC - No Detailed
Affiliation Given 1p 21728 309 24X Fiche 50-275, 83/12/28,
B401050294

B401170316 Requests that LM Gustafson replace OH Davis on mailing
lists Related correspondence
GUSTAFSON, L M Pacific Gas & Electric Co 84/01/13 CHILK, S J
Office of the Secretary of the Commission 1p 21833 286 24X
Fiche 50-275, 84/01/13, B401170316

J Insurance & indemnity information

B401110230 Forwards Endorsement 3 to MAELU Certificate M-74 & NELIA
Certificate N-74
CRANE, P A Pacific Gas & Electric Co 84/01/05 BALTZMAN, J D
Assistant Director for State & Licensee Relations 3pp 21772 360
24X Fiche 50-275, 84/01/05, B401110230

B401260076 Forwards Endorsements 37, 38 & 39 to NELIA Policy NF-228 &
Endorsements 10, 11 & 12 to MAELU Policy NF-103
CRANE, P A Pacific Gas & Electric Co 84/01/16 BALTZMAN, J D
Assistant Director for State & Licensee Relations 7pp 21957 007
24X Fiche 50-275, 84/01/16, B401260076

G Advisory Committee on Reactor Safeguards reports & correspondence

B401250193 Informs of ACRS B40118-19 meeting findings that plant mode
to Unit 1 resulting from design verification program
restored design margins to levels existing at time of ACRS
780714 rept
FRASLEY, R F ACRS - Advisory Committee on Reactor Safeguards
84/01/23 PALLADINO, N Commissioners 1p 21937 109 24X
Fiche 50-275, 84/01/23, B401250193

P Operating license stage documents & correspondence

B401050027 FOIA request for info re whether facilities rated for
earthquakes by Lloyds of London or other rating agencies
Supporting ltrs encl
CALBOYAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed
Affiliation Given 4pp 21736 232 24X Fiche 50-000, 83/10/10,
B401050027

B401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, B401250015

--B203120423 Recommends approval of proposed AD determination re seismic
design errors Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-081 82/02/25 31pp 21961 045 24X
Fiche 50-000, 83/10/18, B401250015

--B204220364 Recommends that Commission accept Fitzgerald & Rothschild
conclusions re employment of Newark to work on matters re
facility
BICKWIT, L Office of the General Counsel SECY-82-152 82/04/12
4pp 21962 319 24X Fiche 50-000, 83/10/18, B401250015

--B209160068 Informs Commission of NRC initiatives to improve GA in
nuclear project design & const Approval requested to revise
NRC statutory authority to permit implementation of
representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-352 82/08/20 37pp 21966 035 24X
Fiche 50-000, 83/10/18, B401250015

B401050043 Responds to FOIA request for info re whether facilities
rated for earthquakes by Lloyds of London or other rating
agencies NRC has no records subj to request Utilis not
required to submit insurance rating to NRC
FELTON, J M Division of Rules and Records 83/10/25 CALBOYAS, C D
Affiliation Unknown 1p 21736 236, 24X Fiche 50-000, 83/10/25,
B401050043

B401040567 Forwards rev to proposed change to FSAR Chapter 17 re QA
organization Submittal incorporates comments made during
831026 meeting w/NRC Class III fee for review encl
SCHUYLER, J D Pacific Gas & Electric Co 83/12/02 MARTIN, J B
Region 5, Office of Director, 31pp, 21714 102 24X
Fiche 50-275, 83/12/02, B401040567

B401060002 Forwards addl info re small bore piping issues, in response
to NRC 831215 request Info includes summary of amount of
Seismic Category 1 small bore piping analyzed under sample
& generic programs & evaluation of snubbers
SCHUYLER, J D Pacific Gas & Electric Co 83/12/28 KNIGHTON, G W
Licensing Branch 3 27pp 21737 236 24X Fiche 50-275, 83/12/28,
B401060002

B401100319 Forwards addl info re details of small bore piping analysis
per 831228 ltr, in response to NRC 831215 meeting concerns
Modeling method of considering actual restraint clearances
reasonable technique for piping geometries
SCHUYLER, J D Pacific Gas & Electric Co 83/12/28 KNIGHTON, G W
Licensing Branch 3 31pp 21762 097 24X Fiche 50-275, 83/12/28,
B401100319

B401120207 Submits correction to 831223 submittal re plan to initiate
nondestructive use of SLO-2 archaeological site on
831228 Const activities will be initiated on 831230
SCHUYLER, J D Pacific Gas & Electric Co 83/12/28 MARTIN, J B
Region 5, Office of Director 1p 21791 001 24X
Fiche 50-275, 83/12/23, B401120207

--B401120212 Notifies of plan to make nondestructive use of SLO-2
archaeological site Temporary parking lot will be built
on 840123 Six conditions to ensure no adverse effects
from const listed Supporting documentation encl
SCHUYLER, J D Pacific Gas & Electric Co 83/12/23 MARTIN, J B
Region 5, Office of Director 8pp 21791 002 24X
Fiche 50-275, 83/12/28, B401120207

B401060287 Requests authorization to perform precriticality hot sys
testing & to achieve criticality & conduct low power testing
by 840201 Heatup tests in Modes 4 & 3 will be completed by
840131 Certificate of Svc encl
MANEATIS, G A Pacific Gas & Electric Co 84/01/04 PALLADINO, N J
ABELSTINE, J K, JERNTHAL, F M Commissioners 4pp 21741 339 2
Fiche 50-275, 84/01/04, B401060287

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983
trip to Sandia re briefing on environ qualification Sandia
position is that NRC environ qualification program has
problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J,
KELINASKY, V, ROBERTS, T M Commissioners 2pp 21993 324 24X
Fiche 50-000, 84/01/05, 8312120108

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401070221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, B401070221

B401170156 Forwards License Amend Request 84-01, revising application
for amend to License DPR-76, changing Tech Specs Sections
& 2 & 5 re organizational relationships Info supercedes &
replaces License Amend Request 83-03 Class II fee encl
SCHUYLER, J D Pacific Gas & Electric Co 84/01/11 BENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21834 115 2/
Fiche 50-275, 84/01/11, B401170156

--B401170161 License Amend Request 84-01, revising application for amend
to License DPR-76, changing Tech Specs Sections & 2 & 5 re
organizational relationships
SCHUYLER, J D Pacific Gas & Electric Co 84/01/11 4pp
21834 116 24X Fiche 50-275, 84/01/11, B401170156

--B401170165 Proposed changes to Tech Specs Sections 6 2 & 6 5 re
organizational relationships
Pacific Gas & Electric Co 84/01/11 7pp 21834 120 24X
Fiche 50-275, 84/01/11, B401170156

B401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946, 174, 24X
Fiche 50-000, 84/01/13, B401130084

DOCKETED ITEMS

B312120125 Board Notification B4-009 forwards info re H Hudson, former vendor QA inspector, B31114 allegations concerning deviations from Pullman Power Products weld procedures & major breakdowns in util contract specs & QA programs
EISENHUT, D G Division of Licensing B4/01/16 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 3pp 21940 229 24X Fiche 50-275, B4/01/16, B312120125

--B401250217 Alleges deviations from Pullman Power Products weld procedure codes & util contract spec QA & welding requirements at facilities Related info encl
HUDSON, H Affiliation Unknown B3/11/14 GILINSKY, V Commissioners 264pp 21940 232 24X Fiche 50-275, B4/01/16, B312120125

B401240503 Forwards partial list of tests to be performed while facility in Modes 3 & 4 Info suppl B40104 ltr re activities accomplished during plant heatup & hot sys tests
SCHUYLER, J D Pacific Gas & Electric Co B4/01/16 EISENHUT, D G Division of Licensing 2pp 21920 054 24X Fiche 50-275, B4/01/16, B401240503

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing B4/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, B4/01/17, B401270536

B401240134 Provides Westinghouse Owners Group revised completion schedules for resolution of TMI Action Item 11 K 3 5, "Automatic Trip of Reactor Coolant Pumps " Revised emergency response guidelines will be completed by B30731
SCHUYLER, J D Pacific Gas & Electric Co B4/01/19 EISENHUT, D G Division of Licensing 2pp 21910 291 24X Fiche 50-275, B4/01/19, B401240134

B401260192 Forwards addl info re performance testing of relief & safety valves per NUREG-0737, Item 11 D 1, "Relief & Safety Valves "
SCHUYLER, J D Pacific Gas & Electric Co B4/01/23 KNIGHTON, G W Licensing Branch 3 16pp 21956 167 24X Fiche 50-275, B4/01/23, B401260192

1 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 093 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B401270188 Ack receipt of B40107 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/B3-26
WENSLAWSKI, F A Region 5, Office of Director B4/01/23 SCHUYLER, J D Pacific Gas & Electric Co 1p 21973 333 24X Fiche 50-275, B4/01/23, B401270188

--B401270195 Responds to NRC B31209 ltr re violations noted in IE Insp Rept 50-275/B3-26 Corrective actions importance of adhering to all radiological control procedures reemphasized
SCHUYLER, J D Pacific Gas & Electric Co B4/01/09 MARTIN, J B Region 5, Office of Director 6pp 21973 334 24X Fiche 50-275, B4/01/23, B401270188

R Periodic operating reports & related correspondence

B401120403 Monthly operating rept for Nov 1983 W/B31201 ltr
KELLY, W J, THORNBERRY, R C Pacific Gas & Electric Co B3/11/30 Office of Resource Management, Director 3pp 21791 119 24X Fiche 50-275, B3/11/30, B401120403

B401110053 Forwards supplementary info for interim Technical Rept 68, "Verification of HLA Soils Work "
DENISON, E Robert L Cloud Associates, Inc B3/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 21772 219 24X Fiche 50-275, B3/12/29, B401110053

--B401110058 "Verification of HLA Soils Work Supplementary Info," revised Pages 26, 26a, 27, 28, 30, 39, 98 & 100 to interim Technical Rept 68
DENISON, E, STEPHENS, V M Robert L Cloud Associates, Inc P105-4-B39-086 B3/12/29 9pp 21772 220 24X Fiche 50-275, B3/12/29, B401110053

B401170211 Monthly operating rept for Dec 1983 W/B40113 ltr
KELLY, W J, THORNBERRY, R C Pacific Gas & Electric Co B3/12/31 Office of Resource Management, Director 12pp 21831 220 24X Fiche 50-275, B3/12/31, B401170211

B312120120 Board Notification B4-008 forwards supplemental info re Interim Technical Rept 68, Rev 1, "Verification of HLA Soils Work "
EISENHUT, D G Division of Licensing B4/01/17 PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 3pp 21941 136 24X Fiche 50-275, B4/01/17, B312120120

S Reportable occurrences, LERs & related correspondence

B312210245 RO on B31205, fire barrier seal discovered nonfunctional Patrol established & maint informed of impairment Barrier will be repaired expeditiously Foam seal not replaced following support mod work
THORNBERRY, R C Pacific Gas & Electric Co B3/12/06 MARTIN, J B Region 5, Office of Director 1p 21600 179 24X Fiche 50-275, B3/12/06, B312210245

B401040548 LER B3-026/03L-0 on B3114, prior to fuel load, power switch to plant vent iodine sampler RE-24 found in off position Caused by personnel error during heavy const period Protective cover will be placed over switch W/B31214 ltr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co B3/12/14 MARTIN, J B Region 5, Office of Director 2pp 21707 143 24X Fiche 50-275, B3/12/14, B401040548

B401040185 LER B3-032/01T-0 on B31205, fire barrier penetration seal in RHR pump i-1 room discovered nonfunctional Maint personnel did not locate fire penetration due to insufficient info on work request W/B31219 ltr
HINDS, J R, SHIFFER, J D Pacific Gas & Electric Co B3/12/19 MARTIN, J B Region 5, Office of Director 3pp 21701 351 24X Fiche 50-275, B3/12/19, B401040185

B401040308 LER B3-027/03L-0 on B3117, diesel generator i-2 air receiver i-2a fell below min pressure setpoint Caused by starting air compressor i-2A internal relief valve not reseating Relief valve replaced W/B31219 ltr
KELLY, W J, SHIFFER, J D Pacific Gas & Electric Co B3/12/19 MARTIN, J B Region 5, Office of Director 3pp 21708 012 24X Fiche 50-275, B3/12/19, B401040308

DOCKETED ITEMS

81

8401030245 PNS-V-83-014 on 831219, accidental discharge of security weapon occurred in security ofc bldg during routine shift change Projectile struck floor, causing minor damage No injuries occurred
SCHWAN, C. NORDERHAUG, L. Region 5, Office of Director 83/12/20 1p 21680 362 24X Fiche 50-275, 83/12/20, 8401030245

8401040261 LER 83-034/01T-O on 831206, several wiring terminations discovered inconsistent w/circuit schematics affecting control power transfer relays for RHR pump control circuits Circuit inconsistency being corrected W/831220 ltr
KEBBINGER, W W, SHIFFER, J D Pacific Gas & Electric Co 83/12/20
MARTIN, J B Region 5, Office of Director 3pp 21701 131 24X
Fiche 50-275, 83/12/20, 8401040261

8401120397 LER 83-031/03L-O on 831122, discovered that Tech Spec 4.9 & 2 re load testing of auxiliary hoist performed approx 240 h prior to use of hoist, contrary to 100 h requirement Caused by misinterpretation of Tech Spec W/831222 ltr
KEBBINGER, W W, SHIFFER, J D Pacific Gas & Electric Co 83/12/22
MARTIN, J B Region 5, Office of Director 2pp 21791 094 24X
Fiche 50-275, 83/12/22, 8401120397

8401160296 LER 83-033/03L-O on 831202, source range instrumentation channels deenergized for 2 minutes during surveillance test Caused by I&C technician failing to follow written procedure I&C personnel instructed W/831229 ltr
KEBBINGER, W W, SHIFFER, J D Pacific Gas & Electric Co 83/12/29
MARTIN, J B Region 5, Office of Director 2pp 21814 337 24X
Fiche 50-275, 83/12/29, 8401160296

8401120422 PNO-V-84-002 on 840102, NRC resident inspector observed media repts of 2.5 to 2.7 magnitude earthquake reportedly occurring seven miles from Facility Plant seismic instrumentation not triggered by event
* Region 5, Office of Director 84/01/03 1p 21791 021 24X
Fiche 50-275, 84/01/03, 8401120422

8401160255 LER 83-035/03L-O on 831201, fire suppression spray & sprinkler sys & Cardox sys valve positions not verified Caused by personnel overlooking addl data sheets provided by procedure amend Personnel instructed W/840103 ltr
KEBBINGER, W W, SHIFFER, J L Pacific Gas & Electric Co 84/01/03
MARTIN, J B Region 5, Office of Director 2pp 21814 108 24X
Fiche 50-275, 84/01/03, 8401160255

8401160234 Final deficiency rept re containment spray initiation timing Timer setting for starting of containment spray pump changed from original FSAR Table B 3-4 value to value of 26 s & 22 s for pumps 1 & 2, respectively
SCHUYLER, J D Pacific Gas & Electric Co 84/01/09
MARTIN, J B Region 5, Office of Director 1p 21814 219 24X
Fiche 50-275, 84/01/09, 8401160234

8401160264 LER 83-036/03L-O on 831211, one train of control room ventilation sys inoperable for 31 minutes Caused by thermal overload trip of Fan B-36 Fan reset Investigation revealed need to rewind fan motor W/840110 ltr
KEBBINGER, W W, SHIFFER, J D Pacific Gas & Electric Co 84/01/10
MARTIN, J B Region 5, Office of Director 2pp 21814 167 24X
Fiche 50-275, 84/01/10, 8401160264

8401200044 PNS-V-84-001 on 840102-13, Abalone Alliance distributed leaflets in community surrounding Facility announcing next anti-nuclear demonstration will begin on 840113 Coordinated command ctr established for all law enforcement agencies
SCHAEFER, D W Region 5, Office of Director 84/01/12 1p 21867 029 24X Fiche 50-275, 84/01/12, 8401200044

8401260352 Updated LER 83-004/08X-1 on 830419, grinding wheel & rotary file gouges discovered on main coolant sys piping on discharge side of main coolant pump 3 Gouges intentionally caused by unknown persons Gouges repaired W/840117 ltr
KEBBINGER, W W, SHIFFER, J D Pacific Gas & Electric Co 84/01/17
MARTIN, J B Region 5, Office of Director 3pp 21955 145 24X
Fiche 50-275, 84/01/17, 8401260352

T Hearing, transcripts on non-antitrust matters

8312120112 Board Notification 84-005: forwards NRC transcript of 831215 meeting in Bethesda, MD & intervenor 831216 & 1214 ltrs re Miami Valley Power Project 2 206 petition for reconsideration of ABLB 830915 order
EISENHUT, D O Division of Licensing 84/01/10 PALLADINO, N J
QUILINBY, V, ROBERTS, T Commissioners 5pp 21928, 003, 24X
Fiche 50-000, 84/01/10, 8312120112

--8401230612 Transcript of 831215 meeting w/util in Bethesda, MD
* Commissioners 83/12/15 210pp 21928:014, 24X
Fiche 50-000, 84/01/10, 8312120112

8401170297 Corrections to transcript of 831031-1121 hearings re design QA Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 84/01/11 23pp 21832 327 24X Fiche 50-275, 84/01/11, 8401170297

8401260004 Transcript of 840112 affirmation/discussion & vote re request for stay of fuel loading at Diablo Canyon & 10CFR1 in Washington, DC Pp 1-3 Supporting documentation encl
* Commissioners 84/01/12 7pp 21969 331 24X
Fiche 50-275, 84/01/12, 8401260004

8401250088 Transcript of ACRS Subcommittee on Diablo Canyon 840119 hearing in Los Angeles, CA Pp 1-243 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/19 288pp 21935 246 24X Fiche 50-275, 84/01/19, 8401250088

U Congressional/Executive Correspondence

8401310168 Forwards rept addressing issues raised in 831101 ltr re NRC handling of drafts of QA case studies, in particular Diablo Canyon Commission has concluded no further investigation necessary
PALLADINO, N J Commissioners 84/01/09 MARKEY, E J House of Rep, Interior & Insular Affairs 1p 22032 001 24X
Fiche 50-275, 84/01/09, 8401310168

--8401310169 "Rept on Review of Issues Raised by Congressman Markey Ltr of 831101 "
DIRCKS, W J Office of the Executive Director for Operations 84/01/09 200pp 22032 002 24X Fiche 50-275, 84/01/09, 8401310168

--8401310172 Raises concerns re NRC handling of drafts of QA case studies
MARKEY, E J House of Rep, Interior & Insular Affairs 83/11/01 PALLADINO, N J Commissioners 13pp 22032 281 24X
Fiche 50-275, 84/01/09, 8401310168

8401240220 Discusses allegations by util workers re poor const QC & unsafe bldg practices NRC should perform complete review of util/Bechtel design review & reinsp of plant safety features by outside, independent authority
ISENBURG, P California, State of 84/01/12 PALLADINO, N Commissioners 1p 21910 303 24X Fiche 50-275, 84/01/12, 8401240220

8401230432 Recommends fair public hearing & thorough investigation of all credible allegations re potential safety problems at Facility
BRONZAN, B California, State of 84/01/17 PALLADINO, N Commissioners 1p 21882 324 24X Fiche 50-275, 84/01/17, 8401230432

8401240199 Urges extraordinary steps be taken to investigate all allegations of inadequacy in QA program in order to allay public concern about safety of opening facility
ROSENTHAL, H California, State of 84/01/17 PALLADINO, N Commissioners 2pp 21909 220 24X Fiche 50-275, 84/01/17, 8401240199

8401240208 Requests NRC require independent design review audit, comprehensive QC reinsp of plant & investigation of root of apparent overwhelming problems before authorization of operation
HAYDEN, T California, State of 84/01/17 PALLADINO, N Commissioners 2pp 21908 262 24X Fiche 50-275, 84/01/17, 8401240208

8401240232 Urges careful investigation into alleged safety problems & violations prior to licensing
PETRIS, N C California, State of 84/01/17 PALLADINO, N Commissioners 1p 21910 183 24X Fiche 50-275, 84/01/17, 8401240232

8401240086 Urges full investigation of allegations of potential safety problems be undertaken before granting util license to operate
BATES, T H California, State of 84/01/18 PALLADINO, N J Commissioners 2pp 21912 350 24X Fiche 50-275, 84/01/18, 8401240086

8401240269 Urges serious allegations re QA/QC be investigated prior to plant operation
BROWN, W L California, State of 84/01/18 PALLADINO, N Commissioners 1p 21909 362 24X Fiche 50-275, 84/01/18, 8401240269

DOCKETED ITEMS

8401230399 Requests NRC authorize complete investigation into causes of QA/QC breakdown, authorize independent audit of utility/Bechtel design review & authorize comprehensive QC reinsp of all safety-related hardware
WATERS, M California, State of 84/01/19 PALLADINO, N J
Commissioners 2pp 21879 150 24X Fiche 50-277, 84/01/19, 8401230399

8401240227 Recommends complete investigation into causes of QA/QC breakdown, independent audit of design review & comprehensive independent QC insp of all safety-related hardware
KLEHS, J California, State of 84/01/19 PALLADINO, N
Commissioners 2pp 21910 178 24X Fiche 50-275, 84/01/19, 8401240227

8401240493 Requests NRC investigation of allegations re QC/QA breakdown, possible mgt coverup of problems & worker harassment investigation should be completed before authorizing plant operation
VASCONELOS, J California, State of 84/01/19 PALLADINO, N
Commissioners 2pp 21920 097 24X Fiche 50-275, 84/01/19, 8401240493

8401270226 Suggests completion of IE investigation re causes of QA/QC breakdown, independent audit of utility/Bechtel design review & comprehensive QC reinsp of all safety-related hardware by independent body before authorizing operation
FARR, B California, State of 84/01/23 PALLADINO, N
Commissioners 2pp 21976 336 24X Fiche 50-275, 84/01/23, 8401270226

DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

Security, medical, emergency & fire protection plans

8401240533 Forwards IE Insp Repts 50-160/83-02 & 50-276/83-01 on 831213 No violations or deviations noted
LEWIS, R C Division of Project & Resident Programs 83/12/28
KARAN, R A Georgia Institute of Technology, Atlanta, GA 2pp
21918 163 24X Fiche 50-160, 83/12/28, 8401240533

--8401240547 IE Insp Repts 50-160/83-02 & 50-276/83-01 on 831213 No violations noted Major areas inspected review of security plan, security organization & surveillance & security program review Details withheld (ref 10CFR2 790 & 73 21)
HALL, B L Region 2, Office of Director 83/12/27 1p
21918 165 24X Fiche 50-160, 83/12/28, 8401240533

Inspection reports, IE Bulletins & correspondence

8401240533 Forwards IE Insp Repts 50-160/83-02 & 50-276/83-01 on 831213 No violations or deviations noted
LEWIS, R C Division of Project & Resident Programs 83/12/28
KARAN, R A Georgia Institute of Technology, Atlanta, GA 2pp
21918 163 24X Fiche 50-160, 83/12/28, 8401240533

--8401240547 IE Insp Repts 50-160/83-02 & 50-276/83-01 on 831213 No violations noted Major areas inspected review of security plan, security organization & surveillance & security program review Details withheld (ref 10CFR2 790 & 73 21)
HALL, B L Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/12/27 1p
21918 165 24X Fiche 50-160, 83/12/28, 8401240533

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

Security, medical, emergency & fire protection plans

8401100270 Forwards IE Insp Repts 50-277/83-34 & 50-270/83-32 on 831111-1213 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/12/22
STAROSTECKI, R Philadelphia Electric Co 2pp 21758 178 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100277 Notice of violation from insp on 831111-1213
* Region 1, Office of Director 83/12/22 2pp 21758 180 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100287 IE Insp Repts 50-277/83-34 & 50-278/83-32 on 831111-1213 Violations noted previous use of calibr maint tools not evaluated & combustible trash allowed to accumulate in turbine bldg, creating fire hazard to safety-related cabling
BLOUGH, A R, WILLIAMS, J H, TRIPP, L E Region 1, Office of Director 83/12/22 20pp 21758 182 24X Fiche 50-277, 83/12/22, 8401100270

8401090072 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 318 24X Fiche 50-277, 83/12/28, 8401090072

--8401090077 Public version of Rev 5 to Emergency Plan Implementing Procedure EP-202, "Operations Support Ctrs (DSC) Activation" Revised table of contents encl
* Philadelphia Electric Co 83/10/27 14pp 21736 319 24X
Fiche 50-277, 83/12/28, 8401090072

8401170412 Forwards exercise repts of 820616 full-scale exercise & 830628 small-scale exercise of offsite radiological emergency preparedness plan
KRIMM, R W Federal Emergency Management Agency 84/01/10
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21829 233 24X Fiche 50-277, 84/01/10, 8401170412

--8401170416 Evaluation of radiological emergency exercise for Peach Bottom Atomic Power Station on 830628
* Federal Emergency Management Agency 83/06/28 20pp
21829 235 24X Fiche 50-277, 84/01/10, 8401170412

--8401170419 Rept of observations & recommendations re Peach Bottom Atomic Power Station exercise on 820616
* Federal Emergency Management Agency 82/06/16 37pp
21829 235 24X Fiche 50-277, 84/01/10, 8401170412

8401170204 Advises that backup emergency operations facility will be provided in case existing primary facility becomes uninhabitable Conowingo Hydro Electric Station will be provided w/communication equipment
DALTROFF, S L Philadelphia Electric Co 84/01/11 STOLZ, J F
Operating Reactors Branch 4 4pp 21832 252 24X
Fiche 50-277, 84/01/11, 8401170204

8401200049 Submits third progress rept for fire protection mods, per 830223 commitment
KEMPER, J S Philadelphia Electric Co 84/01/16 EISENHUT, D G
Division of Licensing 14pp 21865 246 24X Fiche 50-277, 84/01/16, 8401200049

8401230173 Forwards addl info on implementation of NUREG-0737, Suppl 1, Item 6 & Reg Guide 1.97 re application to emergency response facilities Results of evaluation for all instrumentation variables of Reg Guide 1.97 included
DALTROFF, S L Philadelphia Electric Co 84/01/16 EISENHUT, D G
Division of Licensing 132pp 21885 267 24X Fiche 50-277, 84/01/16, 8401230173

8401250062 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21947 041 24X Fiche 50-277, 84/01/18, 8401250062

--8401250064 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-205A 1 re operation of post-accident sampling station & EP-209, App D-4 re personnel safety team
DALTROFF, S L Philadelphia Electric Co 83/12/20 MURLEY, T E
Region 1, Office of Director 2pp 21947 042 24X
Fiche 50-277, 84/01/18, 8401250062

--8401250066 Public version of revised emergency plan implementing procedures, including Procedures EP-205A 1 re operation of post-accident sampling station & EP-209, App D-4 re personnel safety team
* Philadelphia Electric Co 83/11/29 64pp 21947 044 24X
Fiche 50-277, 84/01/18, 8401250062

P Operating license stage documents & correspondence

8401190164 Discusses NRC understanding re use of OE small break LOCA model in LOCA analysis, completing TMI Items II K 3 30 & II K 3 31 Requests plans & schedule if understanding incorrect
STOLZ, J F Operating Reactors Branch 4 83/12/29 BAUER, E G
Philadelphia Electric Co 2pp 21861 195 24X
Fiche 50-277, 83/12/29, 8401190164

8401100291 Responds to issues identified by resident inspector involving Tech Spec acceptance criteria for reactor bldg leakage & ISAR accident analysis assumptions Further analysis unnecessary
DALTROFF, S L Philadelphia Electric Co 84/01/04 STOLZ, J F
Operating Reactors Branch 4 2pp 21758 208 24X
Fiche 50-277, 84/01/04, 8401100291

8401190115 Notification of 840106 meeting w/util in Bethesda, MD to discuss one-time exemption from App J requirements
GEARS, O Operating Reactors Branch 4 84/01/04 STOLZ, J F
Operating Reactors Branch 4 2pp 21871 037 24X
Fiche 50-277, 84/01/04, 8401190115

8401050382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401190328 Forwards response to Generic Ltr 83-41 re fast cold starts of diesel generators No fast start tests conducted in 1983
DALTROFF, S L Philadelphia Electric Co 84/01/13 EISENHUT, D O
Division of Licensing 2pp 21850 355 24X Fiche 50-277, 84/01/13, 8401190328

8401270474 Responds to request for commitments for plant mods & revs to Tech Specs transmitted in NRC evaluation of containment vent & purge issue, per NUREG-0737, Item II E 4.2
DALTROFF, S L Philadelphia Electric Co 84/01/25 STOLZ, J F
Operating Reactors Branch 4 3pp 21981 302 24X
Fiche 50-277, 84/01/25, 8401270474

8401310153 Forwards proposed Tech Spec Table 3.11.D.1 re safety-related shock suppressors (snubbers) which compiles changes to existing Tech Spec table resulting from proposed mods
DALTROFF, S L Philadelphia Electric Co 84/01/26 STOLZ, J F
Operating Reactors Branch 4 2pp 22018 074 24X
Fiche 50-277, 84/01/26, 8401310153

--8401310157 Proposed Tech Spec Table 3.11.D.1, "Safety-Related Shock Suppressors (Snubbers)"
* Philadelphia Electric Co 84/01/26 28pp 22018 076 24X
Fiche 50-277, 84/01/26, 8401310153

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Bhaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp, 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401100270 Forwards IE Insp Repts 50-277/83-34 & 50-278/83-32 on 831111-1213 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/12/22
STAROSTECKI, R Philadelphia Electric Co, 2pp 21758 178 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100277 Notice of violation from insp on 831111-1213
*, Region 1, Office of Director 83/12/22 2pp 21758 180 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100287 IE Insp Repts 50-277/83-34 & 50-278/83-32 on 831111-1213
Violations noted previous use of calibr maint tools not evaluated & combustible trash allowed to accumulate in turbine bldg, creating fire hazard to safety-related cabling
BLOUGH, A R, WILLIAMS, J H, TRIPP, L E Region 1, Office of Director 83/12/22 20pp 21758 182 24X Fiche 50-277, 83/12/22, 8401100270

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp, 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401240201 Modifies response to IE Bulletin 79-19 re 1983 annual retraining for shift supervisor involved in transfer, packaging & transport of radioactive matl Retraining to be completed by 840301 to accommodate program updating
DALTROFF, S L Philadelphia Electric Co 83/12/28 MURLEY, T E
Region 2, Office of Director 2pp 21909 222 24X
Fiche 50-277, 83/12/28, 8401240201

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401310161 Forwards IE Insp Repts 50-277/83-30 & 50-278/83-18 on 831031-1104 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/13
DALTROFF, S L Philadelphia Electric Co 2pp 22022 117 24X
Fiche 50-277, 84/01/13, 8401310161

--8401310166 IE Insp Repts 50-277/83-30 & 50-278/83-18 on 831031-1104 No violations noted Major areas inspected licensee action on previous insp findings, procurement & audit program
MEYER, G W, SHAUB, E T, CAPHTON, D L Region 1, Office of Director 84/01/05 10pp 22022 119 24X Fiche 50-277, 84/01/13, 8401310161

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310270 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-277/83-28
MARTIN, T T Region 1, Office of Director 84/01/25 DALTROFF, S L
Philadelphia Electric Co 2pp 22013 269 24X
Fiche 50-277, 84/01/25, 8401310270

--8401310272 Responds to NRC 831116 ltr re violations noted in IE Insp Rept 50-277/83-28 Corrective actions field change to procedure initiated to use larger transducer & Level III examiner counseled on proper use & review of procedures
DALTROFF, S L Philadelphia Electric Co 83/12/15 MARTIN, T T
Region 1, Office of Director 3pp 22013 271 24X
Fiche 50-277, 84/01/25, 8401310270

R Periodic operating reports & related correspondence

8401190404 Monthly operating repts for Dec 1983 W/840113 ltr
ALDEN, W M, COONEY, M J Philadelphia Electric Co 83/12/31
Director's Office, Office of Inspection and Enforcement 18pp
21850 191 24X Fiche 50-277, 83/12/31, 8401190404

8401200049 Submits third progress rept for fire protection mods, per 830225 commitment
KEMPER, J S Philadelphia Electric Co 84/01/16 EISENHUT, D O
Division of Licensing 14pp 21865 246 24X Fiche 50-277, 84/01/16, 8401200049

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B401120360 LER B3-023/O1X-1 on B31109, combined leakage for Type B & C tests exceeded 10CFR50, App J limit & containment isolation valves MD-2-74 & MD-23-57 failed local leak rate test
Caused by normal wear of valve internals W/831222 1tr
CODNEY, M J Philadelphia Electric Co 83/12/22 MURLEY, T E
Region 1, Office of Director 3pp 21791 355 24X
Fiche 50-277, 83/12/22, B401120360

B401260328 LER B3-026/03L-0 on B31205, during startup, moisture monitoring sys failed while undergoing surveillance testing
Caused by improperly positioned Potter & Brumfield relay
Model R10-EL-W2-V700 Relay readjusted
CODNEY, M J Philadelphia Electric Co 83/12/30 MURLEY, T E
Region 1, Office of Director 1p 21755 118 24X
Fiche 50-277, 83/12/30, B401260328

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B401100270 Forwards IE Insp Repts 50-277/83-34 & 50-278/83-32 on B31111-1213 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/12/22
STAROSTECKI, R Philadelphia Electric Co 2pp 21758 178 24X
Fiche 50-277, 83/12/22, B401100270

--B401100277 Notice of violation from insp on B31111-1213
* Region 1, Office of Director 83/12/22 2pp 21758 180 24X
Fiche 50-277, 83/12/22, B401100270

--B401100267 IE Insp Repts 50-277/83-34 & 50-278/83-32 on B31111-1213
Violations noted previous use of calibr maint tools not evaluated & combustible trash allowed to accumulate in turbine bldg, creating fire hazard to safety-related cabling
BLOUGH, A R Region 1, Office of Director 83/12/22 20pp
21758 182 24X Fiche 50-277, 83/12/22, B401100270

B401050072 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 318 24X Fiche 50-277, 83/12/28, B401050072

--B401050077 Public version of Rev 5 to Emergency Plan Implementing Procedure EP-202, "Operations Support Ctrs (OSC) Activation" Revised table of contents encl
* Philadelphia Electric Co 83/10/27 14pp 21736 319 24X
Fiche 50-277, 83/12/28, B401050072

B401170412 Forwards exercise repts of B20616 full-scale exercise & B30628 small-scale exercise of offsite radiological emergency preparedness plan
KRIMM, R W Federal Emergency Management Agency 84/01/10
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 2pp 21829 233 24X Fiche 50-277, 84/01/10, B401170412

--B401170416 Evaluation of radiological emergency exercise for Peach Bottom Atomic Power Station on B30628
* Federal Emergency Management Agency 83/06/28 20pp
21829 233 24X Fiche 50-277, 84/01/10, B401170412

--B401170419 Rept of observations & recommendations re Peach Bottom Atomic Power Station exercise on B20616
* Federal Emergency Management Agency 82/06/16 37pp
21829 233 24X Fiche 50-277, 84/01/10, B401170412

I401170204 Advises that backup emergency operations facility will be provided in case existing primary facility becomes uninhabitable
Consoling Hydro Electric Station will be provided w/communication equipment
DALTROFF, S L Philadelphia Electric Co 84/01/11 STOLZ, J F
Operating Reactors Branch 4 4pp 21832 232 24X
Fiche 50-277, 84/01/11, B401170204

B401200049 Submits third progress rpt for fire protection mods, per B30225 commitment
KEMPER, J S Philadelphia Electric Co 84/01/16 EISENHUT, D O
Division of Licensing 14pp 21863 246 24X Fiche 50-277, 84/01/16, B401200049

B401230173 Forwards addl info on implementation of NUREG-0737, Suppl 1, Item 6 & Reg Guide 1.97 re application to emergency response facilities
Results of evaluation for all instrumentation variables of Reg Guide 1.97 included
DALTROFF, S L Philadelphia Electric Co 84/01/16 EISENHUT, D O
Division of Licensing 132pp 21885 267 24X Fiche 50-277, 84/01/16, B401230173

B401250062 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21947 041 24X Fiche 50-277, 84/01/18, B401250062

--B401250064 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-205A 1 re operation of post-accident sampling station & EP-209, App D-4 re personnel safety team
DALTROFF, S L Philadelphia Electric Co 83/12/20 MURLEY, T E
Region 1, Office of Director 2pp 21947 042 24X
Fiche 50-277, 84/01/18, B401250062

--B401250066 Public version of revised emergency plan implementing procedures, including Procedures EP-205A 1 re operation of post-accident sampling station & EP-209, App D-4 re personnel safety team
* Philadelphia Electric Co 83/11/29 64pp 21947 044 24X
Fiche 50-277, 84/01/18, B401250062

P Operating license stage documents & correspondence

B401190164 Discusses NRC understanding re use of OE small break LOCA model in LOCA analysis, completing TMI items II K 3 30 & II K 3 31 Requests plans & schedule if understanding incorrect
STOLZ, J F Operating Reactors Branch 4 83/12/29 BAUER, E O
Philadelphia Electric Co 2pp 21861 193 24X
Fiche 50-277, 83/12/29, B401190164

B401100291 Responds to issues identified by resident inspector involving Tech Spec acceptance criteria for reactor bldg leakage & FSAR accident analysis assumptions
Further analysis unnecessary
DALTROFF, S L Philadelphia Electric Co 84/01/04 STOLZ, J F
Operating Reactors Branch 4 2pp 21798 205 24X
Fiche 50-277, 84/01/04, B401100291

B401050382 Generic Ltr B4-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401190328 Forwards response to Generic Ltr B3-41 re fast cold starts of diesel generators
No fast start tests conducted in 1983
DALTROFF, S L Philadelphia Electric Co 84/01/13 EISENHUT, D O
Division of Licensing 2pp 21850 335 24X Fiche 50-277, 84/01/13, B401190328

B401270474 Responds to request for commitments for plant mods & revs to Tech Specs transmitted in NRC evaluation of containment vent & purge issue, per NUREG-0737, Item II E 4 2
DALTROFF, S L Philadelphia Electric Co 84/01/25 STOLZ, J F
Operating Reactors Branch 4 5pp 21981 302 24X
Fiche 50-277, 84/01/25, B401270474

B401310153 Forwards proposed Tech Spec Table 3 II D 1 re safety-related shock suppressors (snubbers) which compiles changes to existing Tech Spec table resulting from proposed mods
DALTROFF, S L Philadelphia Electric Co 84/01/26 STOLZ, J F
Operating Reactors Branch 4 2pp 22018 074 24X
Fiche 50-277, 84/01/26, B401310153

--B401310157 Proposed Tech Spec Table 3 II D 1, "Safety-Related Shock Suppressors (Snubbers),"
* Philadelphia Electric Co 84/01/26 28pp 22018 076 24X
Fiche 50-277, 84/01/26, B401310153

DOCKETED ITEMS

85

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401100270 Forwards IE Insp Repts 50-277/83-34 & 50-278/83-32 on 831111-1213 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/12/22
STAROSTECKI, R Philadelphia Electric Co 2pp 21758 178 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100277 Notice of violation from insp on 831111-1213
* Region 1, Office of Director 83/12/22 2pp 21798 180 24X
Fiche 50-277, 83/12/22, 8401100270

--8401100287 IE Insp Repts 50-277/83-34 & 50-278/83-32 on 831111-1213
Violations noted previous use of calibr maint tools not evaluated & combustible trash allowed to accumulate in turbine bldg, creating fire hazard to safety-related cabling
BLOUGH, A R, WILLIAMS, J H, TRIPP, L E Region 1, Office of Director 83/12/22 20pp 21758 182 24X Fiche 50-277, 83/12/22, 8401100270

8401270236 Forwards proprietary NEDC-30250, "Exam of Cracked Jet Pump Beam from Peach Bottom 3," per IE Bulletin 80-07, "BWR Jet Pump Assembly Failure" Rept withheld
DALTROFF, S L Philadelphia Electric Co 83/12/22 MURLEY, T E Region 1, Office of Director 1p 21976 335 24X
Fiche 50-278, 83/12/22, 8401270236

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401240201 Modifies response to IE Bulletin 79-19 re 1983 annual retraining for shift supervisor involved in transfer, packaging & transport of radioactive matl. Retraining to be completed by 840301 to accommodate program updating
DALTROFF, S L Philadelphia Electric Co 83/12/28 MURLEY, T E Region 2, Office of Director 2pp 21909 222 24X
Fiche 50-277, 83/12/28, 8401240201

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401310161 Forwards IE Insp Repts 50-277/83-30 & 50-278/83-18 on 831031-1104 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/13 DALTROFF, S L Philadelphia Electric Co 2pp 22022 117 24X
Fiche 50-277, 84/01/13, 8401310161

--8401310166 IE Insp Repts 50-277/83-30 & 50-278/83-18 on 831031-1104 No violations noted Major areas inspected: licensee action on previous insp findings, procurement & audit program
MEYER, G W, SHAUB, E T, CAPHTON, D L Region 1, Office of Director 84/01/05 10pp 22022 119 24X Fiche 50-277, 84/01/13, 8401310161

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401190404 Monthly operating repts for Dec 1983 W/840113 ltr
ALDEN, W M, COONEY, M J Philadelphia Electric Co 83/12/31
Director's Office, Office of Inspection and Enforcement 18pp 21850 191 24X Fiche 50-277, 83/12/31, 8401190404

8401200049 Submits third progress rept for fire protection mods, per 830225 commitment
KEMPER, J S Philadelphia Electric Co 84/01/16 EISENHUT, D G Division of Licensing 14pp 21865 246 24X Fiche 50-277, 84/01/16, 8401200049

S Reportable occurrences, LERs & related correspondence

8401030159 LER 83-018/03L-0 on 831117, post-scam investigation of scram insertion times identified control rod 34-35 exceeded 7.00 s limit Caused by failure of scram solenoid valve
ABCO HVA-405 Scram valves replaced
COONEY, M J Philadelphia Electric Co 83/12/07 MURLEY, T E Region 1, Office of Director 1p 21682 289 24X
Fiche 50-278, 83/12/07, 8401030159

8401160189 LER 83-021/03L-0 on 831203, moisture monitoring sys indicated moisture alarm & trouble alarm at weld 2-AHH-2 on 12-inch recirculation piping loop A Caused by logic board misinterpretation of sensor output
COONEY, M J Philadelphia Electric Co 83/12/30 MURLEY, T E Region 1, Office of Director 1p 21815 088 24X
Fiche 50-278, 83/12/30, 8401160189

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401030444 Forwards IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31 No violation noted
DANCE, H C Division of Project & Resident Programs 83/12/07 STEWART, W L Virginia Electric & Power Co 2pp 21730 282 24X
Fiche 50-280, 83/12/07, 8401030444

--8401030447 IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31 No violation noted Major areas inspected plant operations & operating records, maint & surveillance, plant security, event followups & LERs
BURKE, D J, DAVIS, M J, ELROD, S A Region 2, Office of Director 83/12/05 5pp 21730 284 24X Fiche 50-280, 83/12/07, 8401030444

8401060422 Advises that rev to radiological emergency plan meets 10CFR50, App E requirements & acceptable Changes that do not decrease emergency preparedness can be made w/o NRC approval
DANCE, H C Division of Project & Resident Programs 83/12/13 STEWART, W L Virginia Electric & Power Co 1p 21741 077 24X
Fiche 50-280, 83/12/13, 8401060422

8401050473 Ack receipt of supplemental 831123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13
DANCE, H C Division of Project & Resident Programs 83/12/15 STEWART, W L Virginia Electric & Power Co 1p 21726 036 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050503 Notice of violation from insp on 830401-30, * Region 2, Office of Director 83/07/11 2pp 21726 045 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050517 IE Insp Repts 50-280/83-13 & 50-281/83-13 on 830401-30 Violations noted fire protection implementing Procedure ADM-36 not implemented on 830429 & inadequate measures taken to ensure that insulation on boric acid lines intact
BURKE, D J, DAVIS, M J Region 2, Office of Director JULIAN, C Division of Project & Resident Programs 83/06/30 5pp 21726 047 24X Fiche 50-280, 83/12/15, 8401050473

DOCKETED ITEMS

B401240409 Forwards corrected pages to security program, per B31121 ltr
Pages withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/12/16 MCGUIRE, D R
Division of Emergency Preparedness & Materials Safety 1p
21913 226 24X Fiche 50-280, 83/12/16, B401240409

B401050453 Ack receipt of B31104 ltr informing NRC of steps taken to
correct violations noted in IC Insp Repts 50-280/83-20 &
50-281/83-20
DANCE, H C Division of Project & Resident Programs 83/12/20
STEWART, W L Virginia Electric & Power Co 1p 21724 114 24X
Fiche 50-280, 83/12/20, B401050453

--B401050451 IE Insp Repts 50-280/83-20 & 50-281/83-20 on B30702-0805
Violations noted inadequate procedures for hydrostatic
testing of containment spray & piping, surveillance not
performed & cable tray cover not installed
BURKE, D J, DAVIS, M J, SHYLOCK, M Region 2, Office of Director
83/10/04 7pp 21724 125 24X Fiche 50-280, 83/12/20, B401050453

B401030344 Releases public version of revised corporate emergency
response plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21687 083 24X Fiche 50-000, 83/12/27,
B401030344

--B401030347 Public version of revised corporate emergency response plan
STEWART, W L Virginia Electric & Power Co 83/11/23
O'REILLY, J P Region 2, Office of Director 73pp 21687 086
24X Fiche 50-000, 83/12/27, B401030344

B401040552 Forwards fee per 10CFR170 for fire protection reviews &
approvals
STEWART, W L Virginia Electric & Power Co 83/12/27 NORRY, P G
Office of Administration MILLER, W D License Fee Management
Branch 1p 21705 394 24X Fiche 50-280, 83/12/27, B401040552

B401050023 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21735 321 24X Fiche 50-280, 83/12/28,
B401050023

--B401050025 Public version of Rev 3 to Emergency Plan Implementing
Procedure EPIP-4 23, "Post-Accident Sampling of Reactor
Coolant" W/831214 ltr
RUNNER, W R, RENTZ, F L Virginia Electric & Power Co 83/12/08
O'REILLY, J P Region 2, Office of Director 18pp 21735 322
24X Fiche 50-280, 83/12/28, B401050023

B401050400 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 006 24X Fiche 50-280, 83/12/28,
B401050400

--B401050404 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP-1 01 re
emergency manager controlling procedure & EPIP-1 02 re
response to notification of unusual event
STEWART, W L Virginia Electric & Power Co 83/12/02
O'REILLY, J P Region 2, Office of Director 4pp 21743 007 24X
Fiche 50-280, 83/12/28, B401050400

--B401050408 Public version of revised emergency plan implementing
procedures, including Procedures EPIP-1 01 re emergency
manager controlling procedure & EPIP-1 02 re response to
notification of unusual event
RUNNER, W R, RENTZ, F L Virginia Electric & Power Co 83/11/10
100pp 21743 011 24X Fiche 50-280, 83/12/28, B401050400

B401060106 Releases public version of emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21746 192 24X Fiche 50-280, 83/12/28,
B401060106

--B401060113 Public version of emergency plan W/831130 ltr
REMY, M, STEWART, W L Virginia Electric & Power Co 83/11/17
O'REILLY, J P Region 2, Office of Director 206pp 21746 193
24X Fiche 50-280, 83/12/28, B401060106

B401040279 Forwards IE Safeguards Insp Repts 50-280/83-36 &
50-281/83-38 on B31212-16 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/30
STEWART, W L Virginia Electric & Power Co 2pp 21701 298 24X
Fiche 50-280, 83/12/30, B401040279

--B401040289 IE Safeguards Insp Repts 50-280/83-36 & 50-281/83-38 on
B31212-16 No violations noted Major areas inspected site
orientation, security organization - personnel & security
organization Details withheld (ref 10CFR2 790 & 10CFR73 21)
ENNIS, J D Region 2, Office of Director MCGUIRE, D R Division
of Emergency Preparedness & Materials Safety 83/12/28 1p
21701 300 24X Fiche 50-280, 83/12/30, B401040279

B401100229 Ack receipt of B31005 ltr transmitting rev to physical
security plan Changes inconsistent w/provisions of
10CFR50 54(p) must be modified per encl comments or license
amend requested Encl withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/05
STEWART, W L Virginia Electric & Power Co 2pp 21798 268 24X
Fiche 50-280, 84/01/05, B401100229

B401170269 Forwards "Exercise of Offsite Radiological Emergency
Preparedness Plans for Surry Nuclear Power Station,"
evaluation report
KRIMM, R W Federal Emergency Management Agency 84/01/10
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 2pp 21831 005 24X Fiche 50-280, 84/01/10,
B401170269

--B401170274 "Exercise of Offsite Radiological Emergency Preparedness
Plans for Surry Nuclear Power Station," evaluation report
KRIMM, R W Federal Emergency Management Agency 83/10/31 57pp
21831 007 24X Fiche 50-280, 84/01/10, B401170269

B401300080 Advises that location of backup & primary emergency
operation facilities acceptable in response to B20408, 1206,
B30414 & 0506 ltrs
EISENHUT, D G Division of Licensing 84/01/13 STEWART, W L
Virginia Electric & Power Co 2pp 22006 316 24X
Fiche 50-000, 84/01/13, B401300080

B401200102 Notification of B40127 meeting w/util & S&W in Bethesda, MD
to discuss planned mods & schedules resulting from preaudit
& reevaluation of App R effort
ENGLE, L B Operating Reactors Branch 3 84/01/17 MILLER, J R
Operating Reactors Branch 3 3pp 21932 214 24X
Fiche 50-000, 84/01/17, B401200102

B401300106 Ack receipt of B31121 & 1216 ltrs transmitting Rev 10 to
physical security plan Rev acceptable for inclusion in plan
LEWIS, R C Division of Project & Resident Programs 84/01/24
STEWART, W L Virginia Electric & Power Co 2pp 21999 185 24X
Fiche 50-280, 84/01/24, B401300106

J Insurance & indemnity information

B401300264 Endorsements to MAELU & NELIA policies, including
Endorsement 4 to Policies M-28, N-28, M-27 & N-27, Endorsement
6 to M-70, N-70, M-63 & N-63, Endorsement 34 to MF-37,
Endorsement 71 to NF-186 & Endorsement 35 to MF-96
* Nuclear Energy Liability Insurance Association * Mutual Atomic
Energy Liability Underwriters 84/01/03 16pp 21998 344 24X
Fiche 50-000, 84/01/03, B401300264

P Operating license stage documents & correspondence

B401090162 Forwards request for addl info to continue review of
submittals re NUREG-0737, Item II B 3, "Post-Accident
Sampling Sys" Response schedule requested in 30 days
VARGA, S A Operating Reactors Branch 1 83/12/16 STEWART, W L
Virginia Electric & Power Co 8pp 21757 217 24X
Fiche 50-000, 83/12/16, B401090162

B401090633 Forwards "Definition of Operable, Kewaunee Nuclear Power
Plant," describing addl changes needed to comply w/Tech
Specs Response should be received within 30 days of ltr
receipt
VARGA, S A Operating Reactors Branch 1 83/12/19 GIESLER, C W
Wisconsin Public Service Corp 2pp 21757 344 24X
Fiche 50-000, 83/12/19, B401090633

B401090633 Forwards "Definition of Operable, Kewaunee Nuclear Power
Plant," describing addl changes needed to comply w/Tech
Specs Response should be received within 30 days of ltr
receipt
VARGA, S A Operating Reactors Branch 1 83/12/19 GIESLER, C W
Wisconsin Public Service Corp 2pp 21757 344 24X
Fiche 50-000, 83/12/19, B401090633

--B401090651 "Definition of Operable, Kewaunee Nuclear Power Plant"
FARMER, F EQ&O, Inc FIN A-6429 EQO-EA-6400 83/12/31
Division of Licensing 6pp 21757 346 24X Fiche 50-000,
83/12/19, B401090633

DOCKETED ITEMS

87

8401040560 Submits status of evaluation of NUREG-0737, Item II D 1 2 re safety & relief valve discharge piping Completion of final engineering expected in 1984
STEWART, W L Virginia Electric & Power Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 21706 316 24X Fiche 50-280, 83/12/29, 8401040560

8401060306 Provides addl response to Generic Ltr 82-10, addressing NUREG-0737, Item III D 3 4 re control room habitability requirements Completed mods to control room include installation of redundant bottled air sys
STEWART, W L Virginia Electric & Power Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 3pp 21741 352 24X Fiche 50-280, 83/12/30, 8401060306

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21746 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401160418 Notification of 840319-20 meetings w/util in Bethesda, MD to discuss equipment environ qualification issues
NEIGHBOR, J D Operating Reactors Branch 1 84/01/09 VARGA, S A
Operating Reactors Branch 1 2pp 21821 297 24X
Fiche 50-280, 84/01/09, 8401160418

8401230666 Forwards SER re TMI Action Item II, K 2 17, "Voiding in RCS During Anticipated Transients in Westinghouse Plants" Voids generated accounted for in present analysis models
VARGA, S A Operating Reactors Branch 1 84/01/09 STEWART, W L
Virginia Electric & Power Co 10pp 21925 131 24X
Fiche 50-280, 84/01/09, 8401230666

8401160075 Informs that all piping & pipe support analyses completed & all mods resulting from analyses installed Requests commitments imposed by 790313 show cause order be lifted
STEWART, W L Virginia Electric & Power Co 84/01/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 21815 261 24X
Fiche 50-280, 84/01/10, 8401160075

8401170437 Application to amend Licenses DPR-32 & DPR-37, consisting of suppl to Tech Spec change to clarify radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3
STEWART, W L Virginia Electric & Power Co 84/01/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 3pp 21827 103 24X
Fiche 50-280, 84/01/11, 8401170437

--8401170440 Suppl to proposed Tech Spec change clarifying radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3
* Virginia Electric & Power Co 84/01/11 13pp 21827 106 24X
Fiche 50-280, 84/01/11, 8401170437

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401170189 Responds to Generic Ltr 83-41 re diesel generator fast cold starts No apparent detrimental effects resulted from 137 cold starts
STEWART, W L Virginia Electric & Power Co 84/01/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 21833 312 24X Fiche 50-280, 84/01/13, 8401170189

8401250044 Advises that reduction of boren concentration in storage tanks & safety injection piping would result in reduction of approx 136 manrem in annual radiation dose, Method for establishing manrem reduction estimate provided
STEWART, W L Virginia Electric & Power Co 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 21935 225 24X
Fiche 50-280, 84/01/18, 8401250044

8401270233 Discusses status of progress on resolving operating of motor operated valves & plan for further work committed to in 831014 ltr, per ODC 17 Completion of remaining work expected prior to end of second refueling
STEWART, W L Virginia Electric & Power Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 4pp 21976 350 24X
Fiche 50-280, 84/01/20, 8401270233

8401300309 Forwards supplemental info in response to NRC 840110 request re proposed amend concerning reduction in boron concentrations
STEWART, W L Virginia Electric & Power Co 84/01/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 21996 336 24X
Fiche 50-280, 84/01/25, 8401300309

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401050444 Forwards IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31 No violation noted
DANCE, H C Division of Project & Resident Programs 83/12/07
STEWART, W L Virginia Electric & Power Co 2pp 21730 282 24X
Fiche 50-280, 83/12/07, 8401050444

--8401050447 IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31 No violation noted Major areas inspected plant operations & operating records, maint & surveillance, plant security, event followups & LERs
BURKE, D J, DAVIS, M J, ELROD, S A Region 2, Office of Director
83/12/05 5pp 21730 284 24X Fiche 50-280, 83/12/07, 8401050444

8401050464 Forwards supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp facilities Piedmont Hub supplied matl obtained from & certified by Tube-Line
STEWART, W L Virginia Electric & Power Co 83/12/09 O'REILLY, J P
Region 2, Office of Director 3pp 21730 198 24X
Fiche 50-280, 83/12/09, 8401050464

8401050473 Ack receipt of supplemental 831123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 1p 21726 036 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050480 Suppl response to NRC 831007 ltr re violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13 Corrective actions increased use of aluminum cladding over insulation initiated for chemical & vol control sys piping
STEWART, W L Virginia Electric & Power Co 83/11/23
O'REILLY, J P Region 2, Office of Director 1p 21726 037 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050483 Ack receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13
DANCE, H C Division of Project & Resident Programs 83/10/07
STEWART, W L Virginia Electric & Power Co 1p 21726 038 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050493 Responds to NRC 830711 ltr re violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13 Corrective actions operators required to review written requirements of Administrative Procedure 50 re boric acid flow path
STEWART, W L Virginia Electric & Power Co 83/08/10
O'REILLY, J P Region 2, Office of Director 4pp 21726 039 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050498 Forwards IE Insp Repts 50-280/83-13 & 50-281/83-13 on 830401-30 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/07/11
STEWART, W L Virginia Electric & Power Co 2pp 21726 043 24X
Fiche 50-280, 83/12/15, 8401050473

--8401050503 Notice of violation from insp on 830401-30
* Region 2, Office of Director 83/07/11 2pp 21726 045 24X
Fiche 50-280, 83/12/15, 8401050473

DOCKETED ITEMS

--8401050517 IE Insp Repts 50-280/83-13 & 50-281/83-13 on 830401-30
Violations noted fire protection implementing Procedure ADM-
56 not implemented on 830429 & inadequate measures taken to
ensure that insulation on boric acid lines intact
BURKE, D J, DAVIS, M J Region 2, Office of Director JULIAN, C
Division of Project & Resident Programs 83/06/30 5pp
21726 047 24X Fiche 50-280, 83/12/15, 8401050473

8401050653 Act receipt of 831104 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/83-20 &
50-281/83-20
DANCE, H C Division of Project & Resident Programs 83/12/20
STEWART, W L Virginia Electric & Power Co 1p 21724 114 24X
Fiche 50-280, 83/12/20, 8401050653

--8401050664 Responds to NRC 831007 ltr re violations noted in IE Insp
Repts 50-280/83-20 & 50-281/83-20 Corrective actions
Procedure PT 53.1 modified to include requirement to insure
proper installation of supports on affected sys
STEWART, W L Virginia Electric & Power Co 83/11/04
O'REILLY, J P Region 2, Office of Director 6pp 21724 115 24X
Fiche 50-280, 83/12/20, 8401050653

--8401050671 Forwards IE Insp Repts 50-280/83-20 & 50-281/83-20 on
830702-0805 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/07
STEWART, W L Virginia Electric & Power Co 2pp 21724 121 24X
Fiche 50-280, 83/12/20, 8401050653

--8401050676 Notice of violation from insp on 830702-0805
* Region 2, Office of Director 83/10/07 2pp 21724 123 24X
Fiche 50-280, 83/12/20, 8401050653

--8401050681 IE Insp Repts 50-280/83-20 & 50-281/83-20 on 830702-0805
Violations noted inadequate procedures for hydrostatic
testing of containment spray & piping, surveillance not
performed & cable tray cover not installed
BURKE, D J, DAVIS, M J, SHYMLOCK, M Region 2, Office of Director
83/10/04 7pp 21724 125 24X Fiche 50-280, 83/12/20, 8401050653

8401240075 Forwards IE Insp Repts 50-280/83-35 & 50-281/83-37 on
831101-30 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/21
STEWART, W L Virginia Electric & Power Co 2pp 21913 217 24X
Fiche 50-280, 83/12/21, 8401240075

--8401240082 IE Insp Repts 50-280/83-35 & 50-281/83-37 on 831101-30 No
violations noted Major areas inspected plant operations &
operating records, plant maint & surveillance & NURCO-0737
items
BURKE, D J, DAVIS, M J Region 2, Office of Director ELROD, S
Division of Project & Resident Programs 83/12/21 7pp
21913 219 24X Fiche 50-280, 83/12/21, 8401240075

401030187 Forwards relief request from ASME Code XI for 10-yr
inservice insp Unit 2 request parallel: Unit 1 830107
request w/changes to valve, line or mark numbers
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGAS, S A
Operating Reactors Branch 4 3pp 21683 051 24X
Fiche 50-280, 83/12/27, 8401030187

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

12120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

31040279 Forwards IE Safeguards Insp Repts 50-280/83-36 &
50-281/83-38 on 831212-16 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/30
STEWART, W L Virginia Electric & Power Co 2pp 21701 298 24X
Fiche 50-280, 83/12/30, 8401040279

3401040289 IE Safeguards Insp Repts 50-280/83-36 & 50-281/83-38 on
831212-16 No violations noted Major areas inspected site
orientation, security organization - personnel & security
organization Details withheld (ref 10CFR27.90 & 10CFR73.21)
ENNIS, J D Region 2, Office of Director MCQUIRE, D R Division
of Emergency Preparedness & Materials Safety 83/12/28 1p
21701 300 24X Fiche 50-280, 83/12/30, 8401040279

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 129pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators" Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120291 Monthly operating repts for Nov 1983 W/831214 ltr
JONES, V, SAUNDERS, R A, STEWART, W L Virginia Electric & Power Co
83/11/30 HALLER, N M Office of Resource Management, Director
40pp 21792 263 24X Fiche 50-280, 83/11/30, 8401120291

8401270372 Monthly operating repts for Dec 1983 W/840112 ltr
JONES, V H, STEWART, W L Virginia Electric & Power Co 83/12/31
HALLER, N M Office of Resource Management, Director 41pp
21976 117 24X Fiche 50-280, 83/12/31, 8401270372

S Reportable occurrences, LERs & related correspondence

8401050664 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records
2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050664

8401040325 Forwards LERs 83-055/03L-0 & 83-056/03L-0
SAUNDERS, R F Virginia Electric & Power Co 83/12/21
O'REILLY, J P Region 2, Office of Director 1p 21706 186 24X
Fiche 50-280, 83/12/21, 8401040325

--8401040331 LER 83-055/03L-0 on 831126, core cooling monitor A observed
displaying erratic indications & declared inoperable Caused
by faulty computer card Replacement card installed
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 2pp 21706 187 24X Fiche 50-280, 83/12/21,
8401040325

--8401040337 LER 83-056/03L-0 on 831201, feeder breakers for heat tracing
panels 2A1 & 2B2 tripped On 831202, feeder 2A1 tripped again
Caused by ground fault due to extensive insulation work on
various boric acid lines Feeder breakers reset
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 2pp 21706 189 24X Fiche 50-280, 83/12/21,
8401040325

8401040369 Forwards LERs 83-053/03L-0 & 83-054/03L-0
SAUNDERS, R F Virginia Electric & Power Co 83/12/21
O'REILLY, J P Region 2, Office of Director 1p 21708 015 24X
Fiche 50-280, 83/12/21, 8401040369

--8401040373 LER 83-053/03L-0 on 831122, RCS activity samples indicated
dose equivalent I-131 greater than allowable limit Caused by
fuel element defects in reactor core Accelerated sampling
frequency implemented
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 3pp 21708 016 24X Fiche 50-280, 83/12/21,
8401040369

--8401040376 LER 83-054/03L-0 on 831123, rod position indicators for rods
G-13 & N-9 found more than 12 steps out of alignment Caused
by instrument drift Indicators calibr
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 2pp 21708 019 24X Fiche 50-280, 83/12/21,
8401040369

DOCKETED ITEMS

89

B401170188 LER 83-057/03L-0 on 831215, RCS activity samples indicated dose equivalent I-131 limit greater than Tech Spec limit. Cause by known fuel element defects in reactor core. Accelerated sample frequency implemented W/840106 ltr. WILSON, J L Virginia Electric & Power Co 84/01/06 21833 295 24X
Region 2, Office of Director App
Fiche 50-280, 84/01/06, 8401170188

B401260003 LER 83-098/03L-0 on 831215 & 24, main feed regulator valve C did not fully close upon receipt of low lye isolation signal following reactor trip. Cause by mechanical binding. Cage tightened & operator assembly adjusted W/840113 ltr. WILSON, J L Virginia Electric & Power Co 84/01/13 21956 348 24X
Region 2, Office of Director App
Fiche 50-280, 84/01/13, 8401260003

B401310358 Forwards LERs 83-020/03X-1 & 83-059/03L-0. WILSON, J L Virginia Electric & Power Co 84/01/24 22019 297 24X
Region 2, Office of Director 1p
Fiche 50-280, 84/01/24, 8401310358

--B401310362 Updated LER 81-020/03X-1 on 810724, AE notified util of seven masonry block wall sections in fuel bldg not meeting IE Bulletin 80-11 design requirements. Cause not stated. Block walls will be replaced. WILSON, J L Virginia Electric & Power Co 84/01/24 22019 300 24X
Region 2, Office of Director 3pp
Fiche 50-280, 84/01/24, 8401310358

--B401310367 LER 83-059/03L-0 on 831225, rod position indicators 0-3 & F-12 found indicating more than 12 steps from bank. Cause by indicator F-12 signal conditioning module drift & 0-3 sticking meter 0-3 repaired & F-12 recalibr. WILSON, J L Virginia Electric & Power Co 84/01/24 22019 303 24X
Region 2, Office of Director 2pp
Fiche 50-280, 84/01/24, 8401310358

Y Dry Cask Independent Spent Fuel Storage Installations

B401030279 Trip rept of 831206 site visit w/util & Bechtel re proposed IBSI & discussion of environ info. STURZ, F Advanced Fuel & Spent Fuel Licensing Branch 83/12/19 21693 360 24X
Region 2, Office of Director 2pp
Fiche 50-280, 83/12/19, 8401030279

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401050444 Forwards IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31. No violation noted. DANCE, H C Division of Project & Resident Programs 83/12/07 21730 282 24X
STEWART, W L Virginia Electric & Power Co 2pp
Fiche 50-280, 83/12/07, 8401050444

--B401050447 IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31. No violation noted. Major areas inspected: plant operations & operating records, maint & surveillance, plant security, event followups & LERs. BURKE, D J Region 2, Office of Director 83/12/05 21730 284 24X
Region 2, Office of Director 5pp
Fiche 50-280, 83/12/07, 8401050444

B401060422 Advises that rev to radiological emergency plan meets 10CFR50. App E requirements & acceptable changes that do not decrease emergency preparedness can be made w/o NRC approval. DANCE, H C Division of Project & Resident Programs 83/12/13 21741 077 24X
STEWART, W L Virginia Electric & Power Co 1p
Fiche 50-280, 83/12/13, 8401060422

B401080473 Ack receipt of supplemental 831123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-13 & 50-281/83-13. DANCE, H C Division of Project & Resident Programs 83/12/15 21726 036 24X
STEWART, W L Virginia Electric & Power Co 1p
Fiche 50-280, 83/12/15, 8401080473

--B401050503 Notice of violation from insp on 830401-30. * Region 2, Office of Director 83/07/11 21726 045 24X
Fiche 50-280, 83/12/15, 8401050473

--B401050517 IE Insp Repts 50-280/83-13 & 50-281/83-13 on 830401-30. Violations noted: fire protection implementing Procedure ADM-56 not implemented on 830429 & inadequate measures taken to ensure that insulation on boric acid lines intact. BURKE, D J Region 2, Office of Director 83/06/30 21726 047 24X
Region 2, Office of Director 5pp
Fiche 50-280, 83/12/15, 8401050473

B401240409 Forwards corrected pages to security program, per 831121 ltr. Pages withheld (ref 10CFR73.21). STEWART, W L Virginia Electric & Power Co 83/12/16 21913 226 24X
Division of Emergency Preparedness & Materials Safety 1p
Fiche 50-280, 83/12/16, 8401240409

B401050653 Ack receipt of 831104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-20 & 50-281/83-20. DANCE, H C Division of Project & Resident Programs 83/12/20 21724 114 24X
STEWART, W L Virginia Electric & Power Co 1p
Fiche 50-280, 83/12/20, 8401050653

--B401050681 IE Insp Repts 50-280/83-20 & 50-281/83-20 on 830702-0805. Violations noted: inadequate procedures for hydrostatic testing of containment spray & piping, surveillance not performed & cable tray cover not installed. BURKE, D J, LEUHAUS, J, MATHIS, J Region 2, Office of Director 83/10/04 21724 125 24X
Region 2, Office of Director 7pp
Fiche 50-280, 83/12/20, 8401050653

B401030344 Releases public version of revised corporate emergency response plan. FELTON, J M Division of Rules and Records 83/12/27 21687 083 24X
Management Branch 1p
Fiche 50-000, 83/12/27, 8401030344

--B401030347 Public version of revised corporate emergency response plan. STEWART, W L Virginia Electric & Power Co 83/11/23 21687 086 24X
O'REILLY, J P Region 2, Office of Director 73pp
Fiche 50-000, 83/12/27, 8401030344

B401040592 Forwards fee per 10CFR170 for fire protection reviews & approvals. STEWART, W L Virginia Electric & Power Co 83/12/27 21703 354 24X
Office of Administration MILLER, W O License Fee Management Branch 1p
Fiche 50-280, 83/12/27, 8401040592

B401050023 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 83/12/28 21735 321 24X
Management Branch 1p
Fiche 50-280, 83/12/28, 8401050023

--B401050025 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP-4.23, "Post-Accident Sampling of Reactor Coolant" W/831214 ltr. RUNNER, W R, RENTZ, F L Virginia Electric & Power Co 83/12/08 21735 322 24X
O'REILLY, J P Region 2, Office of Director 18pp
Fiche 50-280, 83/12/28, 8401050023

B401050400 Releases public version of revised emergency plan implementing procedures. FELTON, J M Division of Rules and Records 83/12/28 21743 006 24X
Management Branch 1p
Fiche 50-280, 83/12/28, 8401050400

--B401050404 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-1.01 re emergency manager controlling procedure & EPIP-1.02 re response to notification of unusual event. STEWART, W L Virginia Electric & Power Co 83/12/02 21743 007 24X
O'REILLY, J P Region 2, Office of Director 4pp
Fiche 50-280, 83/12/28, 8401050400

--B401050408 Public version of revised emergency plan implementing procedures, including Procedures EPIP-1.01 re emergency manager controlling procedure & EPIP-1.02 re response to notification of unusual event. RUNNER, W R, RENTZ, F L Virginia Electric & Power Co 83/11/10 21743 011 24X
Fiche 50-280, 83/12/28, 8401050400

B401060106 Releases public version of emergency plan. FELTON, J M Division of Rules and Records 83/12/28 21746 192 24X
Management Branch 1p
Fiche 50-280, 83/12/28, 8401060106

--B401060113 Public version of emergency plan W/831130 ltr. RENEY, M, STEWART, W L Virginia Electric & Power Co 83/11/17 21746 193 24X
O'REILLY, J P Region 2, Office of Director 206pp
Fiche 50-280, 83/12/28, 8401060106

B401040279 Forwards IE Safeguards Insp Repts 50-280/83-34 & 50-281/83-38 on 831212-16. No violations noted. DANCE, H C Division of Project & Resident Programs 83/12/30 21701 298 24X
STEWART, W L Virginia Electric & Power Co 2pp
Fiche 50-280, 83/12/30, 8401040279

DOCKETED ITEMS

--B401040289 IE Safeguards Insp Repts 50-280/83-36 & 50-281/83-38 on 831212-16 No violations noted Major areas inspected site orientation, security organization - personnel & security organization Details withheld (ref 10CFR2 790 & 10CFR73 21) ENNIS, J D Region 2, Office of Director 83/12/28 1p 21701 300 24X Fiche 50-280, 83/12/30, B401040279

B401100229 Ack receipt of 831005 ltr transmitting rev to physical security plan Changes inconsistent w/provisions of 10CFR50 54(p) must be modified per encl comments or license amend requested Encl withheld (ref 10CFR73 21) LEWIS, R C Division of Project & Resident Programs 84/01/05 STEWARD, W L Virginia Electric & Power Co 2pp 21758 268 24X Fiche 50-280, 84/01/05, B401100229

B401170269 Forwards "Exercise of Offsite Radiological Emergency Preparedness Plans For Surry Nuclear Power Station," evaluation rept KRIMM, R W Federal Emergency Management Agency 84/01/10 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21831 003 24X Fiche 50-280, 84/01/10, B401170269

--B401170274 "Exercise of Offsite Radiological Emergency Preparedness Plans For Surry Nuclear Power Station," evaluation rept KRIMM, R W Federal Emergency Management Agency 83/10/31 57pp 21831 007 24X Fiche 50-280, 84/01/10, B401170269

B401300080 Advises that location of backup & primary emergency operation facilities acceptable in response to 820408, 1206, 130414 & 0306 ltrs EISENHUT, D G Division of Licensing 84/01/13 STEWARD, W L Virginia Electric & Power Co 2pp 22006 316 24X Fiche 50-000, 84/01/13, B401300080

B401200102 Notification of 840127 meeting w/util & S&W in Bethesda, MD to discuss planned nodes & schedules resulting from preaudit & reevaluation of App R effort ENGLE, L B Operating Reactors Branch 3 84/01/17 MILLER, J R Operating Reactors Branch 3 3pp 21932 214 24X Fiche 50-000, 84/01/17, B401200102

B401300106 Ack receipt of 831121 & 1216 ltrs transmitting, Rev 10 to physical security plan Rev acceptable for inclusion in plan LEWIS, R C Division of Project & Resident Programs 84/01/24 STEWARD, W L Virginia Electric & Power Co 2pp 21999 185 24X Fiche 50-280, 84/01/24, B401300106

J Insurance & indemnity information

B401300264 Endorsements to MAELU & NELIA policies, including Endorsement 4 to Policies M-26, M-26, M-27 & M-27, Endorsement 6 to M-70, M-70, M-63 & M-63, Endorsement 34 to MF-37, Endorsement 71 to NF-185 & Endorsement 35 to NF-96 * Nuclear Energy Liability Insurance Association * Mutual Atomic Energy Liability Underwriters 84/01/03 16pp 21998 344 24X Fiche 50-000, 84/01/03, B401300264

P Operating license stage documents & correspondence

B401090162 Forwards request for addl info to continue review of submittals re NUREG-0737, Item II D 3, "Post-Accident Sampling Sys" Response schedule requested in 30 days VARGA, S A Operating Reactors Branch 1 83/12/16 STEWARD, W L Virginia Electric & Power Co 8pp 21757 217 24X Fiche 50-000, 83/12/16, B401090162

B401090633 Forwards "Definition of Operable, Kaukauna Nuclear Power Plant," describing addl changes needed to comply w/Tech Specs Response should be received within 30 days of ltr receipt VARGA, S A Operating Reactors Branch 1 83/12/19 GIESLER, C W Wisconsin Public Service Corp 2pp 21757 344 24X Fiche 50-000, 83/12/19, B401090633

B401040560 Submits status of evaluation of NUREG-0737, Item II D 1 2 re safety & relief valve discharge piping Completion of final engineering expected in 1984 STEWARD, W L Virginia Electric & Power Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 2pp 21706 316 24X Fiche 50-280, 83/12/29, B401040560

B401060306 Provides addl response to Generic Ltr 82-10, addressing NUREG-0737, Item III D 3 4 re control room habitability requirements Completed nodes to control room include installation of redundant bottled air sys STEWARD, W L Virginia Electric & Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 3pp 21741 352 24X Fiche 50-280, 83/12/30, B401060306

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401160418 Notification of B40319-20 meetings w/util in Bethesda, MD to discuss equipment environ qualification issues NEIGHBORS, J D Operating Reactors Branch 1 84/01/09 VARGA, S A Operating Reactors Branch 1 2pp 21821 297 24X Fiche 50-280, 84/01/09, B401160418

B401230666 Forwards SER re TMI Action Item II K 2 17, "Voiding in RCS During Anticipated Transients in Westinghouse Plants" Voids generated accounted for in present analysis models VARGA, S A Operating Reactors Branch 1 84/01/09 STEWARD, W L Virginia Electric & Power Co 10pp 21925 191 24X Fiche 50-280, 84/01/09, B401230666

B401170437 Application to amend Licenses DPR-32 & DPR-37, consisting of suppl to Tech Spec change to clarify radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3 STEWARD, W L Virginia Electric & Power Co 84/01/11 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 3pp 21827 103 24X Fiche 50-280, 84/01/11, B401170437

--B401170440 Suppl to proposed Tech Spec change clarifying radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3 * Virginia Electric & Power Co 84/01/11 13pp 21827 106 24X Fiche 50-280, 84/01/11, B401170437

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401170189 Responds to Generic Ltr 83-41 re diesel generator fast cold starts No apparent detrimental effects resulted from 137 cold starts STEWARD, W L Virginia Electric & Power Co 84/01/13 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 1p 21833 312 24X Fiche 50-280, 84/01/13, B401170189

B401250044 Advises that reduction of boron concentration in storage tanks & safety injection piping would result in reduction of approx 136 manrem in annual radiation dose Method for establishing manrem reduction estimate provided STEWARD, W L Virginia Electric & Power Co 84/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 2pp 21935 225 24X Fiche 50-280, 84/01/18, B401250044

B401270233 Discusses status of progress on resolving rotating of motor operated valves & plan for further work committed to in 831014 ltr, per GDC 17 Completion of remaining work expected prior to end of second refueling STEWARD, W L Virginia Electric & Power Co 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 4pp 21976 350 24X Fiche 50-280, 84/01/20, B401270233

B401200309 Forwards supplemental info in response to NRC B40110 request re proposed amend concerning reduction in boron concentrations STEWARD, W L Virginia Electric & Power Co 84/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 2pp 21996 336 24X Fiche 50-280, 84/01/25, B401200309

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

DOCKETED ITEMS

91

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401050444 Forwards IE Insp Repts 50-280/83-29 & 50-281/83-24 on
831011-31 No violation noted
DANCE, H C Division of Project & Resident Programs 83/12/07
STEWART, W L Virginia Electric & Power Co 2pp 21730 282 24X
Fiche 50-280,83/12/07,8401050444

--8401050447 IE Insp Repts 50-280/83-29 & 50-281/83-24 on 831011-31 No
nonconforming matls supplied by Tube-Line Corp facilities
violation noted Major areas inspected plant operations &
operating records, maint & surveillance, plant security, event
followups & LERs
BURKE, D J, DAVIS, M J, ELROD, S A Region 2, Office of Director
83/12/05 5pp 21730 284 24X Fiche 50-280,83/12/07,8401050444

8401050464 Forwards supplemental response to IE Bulletin 83-06 re
nonconforming matls supplied by Tube-Line Corp facilities
Piedmont Hub supplied matl obtained from & certified by
Tube-Line
STEWART, W L Virginia Electric & Power Co 83/12/09 O'REILLY, J P
Region 2, Office of Director 3pp 21730 198 24X
Fiche 50-280,83/12/09,8401050464

8401050473 Ack receipt of supplemental 831123 ltr informing NRC of
steps taken to correct violations noted in IE Insp Repts
50-280/83-13 & 50-281/83-13
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 1p 21726 036 24X
Fiche 50-280,83/12/15,8401050473

--8401050480 Suppls response to NRC 831007 ltr re violations noted
in IE Insp Repts 50-280/83-13 & 50-281/83-13 Corrective
actions increased use of aluminum cladding over insulation
initiated for chemical & vol control sys piping
STEWART, W L Virginia Electric & Power Co 83/11/23
O'REILLY, J P Region 2, Office of Director 1p 21726 037 24X
Fiche 50-280,83/12/15,8401050473

--8401050483 Ack receipt of 830810 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/83-13 &
50-281/83-13
DANCE, H C Division of Project & Resident Programs 83/10/07
STEWART, W L Virginia Electric & Power Co 1p 21726 038 24X
Fiche 50-280,83/12/15,8401050473

--8401050493 Responds to NRC 830711 ltr re violations noted in IE Insp
Repts 50-280/83-13 & 50-281/83-13 Corrective actions
operators required to review written requirements of
Administrative Procedure 50 re boric acid flow path
STEWART, W L Virginia Electric & Power Co 83/08/10
O'REILLY, J P Region 2, Office of Director 4pp 21726 039 24X
Fiche 50-280,83/12/15,8401050473

--8401050498 Forwards IE Insp Repts 50-280/83-13 & 50-281/83-13 on
830401-30 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/07/11
STEWART, W L Virginia Electric & Power Co 2pp 21726 043 24X
Fiche 50-280,83/12/15,8401050473

--8401050503 Notice of violation from insp on 830401-30
* Region 2, Office of Director 83/07/11 2pp 21726 045 24X
Fiche 50-280,83/12/15,8401050473

--8401050517 IE Insp Repts 50-280/83-13 & 50-281/83-13 on 830401-30
Violations noted: fire protection implementing Procedure ADM-
56 not implemented on 830429 & inadequate measures taken to
ensure that insulation on boric acid lines intact
BURKE, D J, DAVIS, M J Region 2, Office of Director JULIAN, C
Division of Project & Resident Programs 83/06/30 5pp
21726 047 24X Fiche 50-280,83/12/15,8401050473

8401050453 Ack receipt of 831104 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-280/83-20 &
50-281/83-20
DANCE, H C Division of Project & Resident Programs 83/12/20
STEWART, W L Virginia Electric & Power Co 1p 21724 114 24X
Fiche: 50-280,83/12/20,8401050453

--8401050564 Responds to NRC 831007 ltr re violations noted in IE Insp
Repts 50-280/83-20 & 50-281/83-20 Corrective actions
Procedure PT 53.1 modified to include requirement to insure
proper installation of supports on affected sys
STEWART, W L Virginia Electric & Power Co 83/11/04
O'REILLY, J P Region 2, Office of Director 6pp 21724 115 24X
Fiche 50-280,83/12/20,8401050563

--8401050671 Forwards IE Insp Repts 50-280/83-20 & 50-281/83-20 on
830702-0805 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/07
STEWART, W L Virginia Electric & Power Co 2pp 21724 121 24X
Fiche 50-280,83/12/20,8401050653

--8401050676 Notice of violation from insp on 830702-0805
* Region 2, Office of Director 83/10/07 2pp 21724 123 24X
Fiche 50-280,83/12/20,8401050653

--8401050681 IE Insp Repts 50-280/83-20 & 50-281/83-20 on 830702-0805
Violations noted inadequate procedures for hydrostatic
testing of containment spray & piping, surveillance not
performed & cable tray cover not installed
BURKE, D J, DAVIS, M J, SHYMLOCK, M Region 2, Office of Director
83/10/04 7pp 21724 125 24X Fiche 50-280,83/12/20,8401050653

8401240075 Forwards IE Insp Repts 50-280/83-35 & 50-281/83-37 on
83101-30 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/21
STEWART, W L Virginia Electric & Power Co 2pp 21913 217 24X
Fiche 50-280,83/12/21,8401240075

--8401240082 IE Insp Repts 50-280/83-35 & 50-281/83-37 on 83101-30 No
violations noted Major areas inspected plant operations &
operating records, plant maint & surveillance & NUREG-0737
items
BURKE, D J, DAVIS, M J Region 2, Office of Director ELROD, S
Division of Project & Resident Programs 83/12/21 7pp
21913 219 24X Fiche 50-280,83/12/21,8401240075

8401030187 Forwards relief request from ASME Code XI for 10-yr
inservice insp Unit 2 request parallels Unit 1 830107
request w/changes to valve, line or mark numbers
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 3pp 21683 051 24X
Fiche 50-280,83/12/27,8401030187

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type SHK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401040279 Forwards IE Safeguards Insp Repts 50-280/83-36 &
50-281/83-38 on 831212-16 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/30
STEWART, W L Virginia Electric & Power Co 2pp 21701 298 24X
Fiche 50-280,83/12/30,8401040279

--8401040289 IE Safeguards Insp Repts 50-280/83-36 & 50-281/83-38 on
831212-16 No violations noted Major areas inspected site
orientation, security organization - personnel & security
organization Details withheld (ref 10CFR2 740 & 10CFR73.21)
ENNIS, J D Region 2, Office of Director MCQUIRE, D R Division
of Emergency Preparedness & Materials Safety 83/12/28 1p
21701 300 24X Fiche 50-280,83/12/30,8401040279

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401240477 Ack receipt of 831216 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-281/83-30
DANCE, H C Division of Project & Resident Programs 84/01/11
STEWART, W L Virginia Electric & Power Co 1p 21920 041 24X
Fiche 50-281,84/01/11,8401240477

--8401240488 Responds to NRC 831116 ltr re violations noted in IE Insp
Rept 50-281/83-30 Corrective actions required zero power
testing range procedure deviations processed to justify &
document changes made during testing
STEWART, W L Virginia Electric & Power Co 83/12/16
O'REILLY, J P Region 2, Office of Director 3pp 21920 042 24X
Fiche 50-281,84/01/11,8401240477

DOCKETED ITEMS

--B401240477 Forwards IE Insp Rept 50-281/83-30 on 830930-1003 & 06-07 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/11/16
STEWART, W L Virginia Electric & Power Co 2pp 21920 045 24X
Fiche 50-281, 84/01/11, 8401240477

--B401240512 Notice of violation from insp on 830930-1003 & 06-07
* Region 2, Office of Director 83/11/16 1p 21920 047 24X
Fiche 50-281, 84/01/11, 8401240477

--B401240517 IE Insp Rept 50-281/83-30 on 830930-1003 & 06-07 Violation
noted failure to follow 10CFR50, nuclear design check test
procedures, per 10CFR50, App B, Criterion V
DAVENPORT, K E Region 2, Office of Director JAFE, F Division of
Engineering & Operational Programs 83/11/14 6pp 21920 048
24X Fiche 50-281, 84/01/11, 8401240477

B312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

B401120291 Monthly operating repts for Nov 1983 W/831214 ltr
JONES, V J, SAUNDERS, R A, STEWART, W L Virginia Electric & Power Co
83/11/30 HALLER, N M Office of Resource Management, Director
40pp 21792 263 24X Fiche 50-280, 83/11/30, 8401120291

B401270372 Monthly operating repts for Dec 1983 W/840112 ltr
JONES, V J, STEWART, W L Virginia Electric & Power Co 83/12/31
HALLER, N M Office of Resource Management, Director 41pp
21976 117 24X Fiche 50-280, 83/12/31, 8401270372

S Reportable occurrences, LERs & related correspondence

8312200074 LER 83-053/03L-0 on 831115, operability check of containment
vacuum pump 2-CV-P-1A revealed pump inoperable. Caused by
worn impeller sliding vanes. Pump replaced W/831212 ltr
SAUNDERS, R F Virginia Electric & Power Co 83/12/12
O'REILLY, J P Region 2, Office of Director 3pp 21574 292 24X
Fiche 50-281, 83/12/12, 8312200074

B401040322 Forwards LERs 83-056/03L-0 & 83-057/03L-0
SAUNDERS, R F Virginia Electric & Power Co 83/12/21
O'REILLY, J P Region 2, Office of Director 1p 21708 040 24X
Fiche 50-281, 83/12/21, 8401040322

--B401040326 LER 83-056/03L-0 on 831122, containment spray pump 2-CS-P-1A
motor tripped upon start. Pump 2-CS-P-1B subsequently tripped
upon start. Caused by instantaneous delay trip times set
lower than 0.07 s
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 3pp 21708 041 24X Fiche 50-281, 83/12/21,
8401040322

--B401040330 LER 83-057/03L-0 on 831123, determined that several degraded
voltage & undervoltage relays for emergency buses 2J & 2H
set low. Caused by instrument drift. Relays reset
WILSON, J L Virginia Electric & Power Co 83/12/21 Region 2,
Office of Director 2pp 21708 044 24X Fiche 50-281, 83/12/21,
8401040322

B401310387 LER 83-058/03L-0 on 831228 & 29, rod position indicators
(RPIs), indicated more than 12 steps from bank. Caused by
signal conditioning module drift. Both RPIs tested & returned
to svc. W/840124 ltr
WILSON, J L Virginia Electric & Power Co 84/01/24 O'REILLY, J P
Region 2, Office of Director 3pp 22019 355 24X
Fiche 50-281, 84/01/24, 8401310387

Y Dry Cask Independent Spent Fuel Storage Installations

B401030279 Trip rept of 831204 site visit w/util & Bechtel re proposed
ISFSI & discussion of environ info
STURZ, F Advanced Fuel & Spent Fuel Licensing Branch 83/12/19
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp
21693 360 24X Fiche 50-280, 83/12/19, 8401030279

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency
operation facilities. Forwards App B documents App A & B
documents available in PDR App C documents entirely withheld
(ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J M
Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X
Fiche 50-000, 83/11/02, 8401250163

--B401250286 Forwards comments on proposed Commission papers NRC should
consider significant economic impact which would result if
backup emergency operation facility rejected & dismantled
into two separate locations
EISENHUT, D G Division of Licensing 83/06/24 JORDAN, E L
Division of Emergency Preparedness & Engineering Response (Post
830103) 3pp 21958 328 24X Fiche 50-000, 83/11/02, 8401250163

B401100180 Forwards tentative schedule of major submittals, fire
protection exemption requests & Tech Spec changes, for inPd
& planning purposes
MUSOLF, D M Northern States Power Co 84/01/04 Office of
Nuclear Reactor Regulation, Director 2pp 21759 280 24X
Fiche 50-282, 84/01/04, 8401100180

B401230271 Notifies of FEMA 840112-13 meetings in Chicago, IL. FEMA
requests that util emergency preparedness planners attend to
develop FY84/85 emergency preparedness exercise schedule &
prompt alert & notification certification schedule
PAPERIELLO, C J Region 3, Office of Director 84/01/05
LARBON, C E Northern States Power Co 3pp 21854 211 24X
Fiche 50-000, 84/01/05, 8401230271

B401180006 Forwards exemption from requirements of App R, Subsection
III G 2 re separation, fire barrier & suppression where both
trains of redundant safe shutdown located in same fire
area
MILLER, J R Operating Reactors Branch 3 84/01/09 MUSOLF, D M
Northern States Power Co 3pp 21848 292 24X
Fiche 50-282, 84/01/09, 8401180006

--B401180011 Exemption from requirements of App R, Subsection III G 2 re
train of cables necessary for safe shutdown
EISENHUT, D G Division of Licensing 84/01/09 Northern States
Power Co 7pp 21848 295 24X Fiche 50-282, 84/01/09, 8401180006

--B401180015 Safety evaluation supporting exemption from fire protection
requirements of App R, Subsection III G 2, per 830217 & 0311
requests
* Office of Nuclear Reactor Regulation, Director 84/01/09 6pp
21848 302 24X Fiche 50-282, 84/01/09, 8401180006

B401250093 Releases public version of notice re emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21946, 262 24X Fiche 50-000, 84/01/18,
8401250093

--B401250096 Public version of notice that Emergency Plan Implementing
Procedure 9 i inadvertently attached to back of 831221
corporate emergency plan - implementing procedures & should
be discarded
MUSOLF, D M Northern States Power Co 83/12/29 1p 21946 263
24X Fiche 50-000, 84/01/18, 8401250093

B401310254 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22037 095 24X Fiche 50-000, 84/01/18,
8401310254

--B401310263 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP i 1 i 1 re
accident assessment, EPIP i 2 i 1 re emergency plan training &
EPIP i 2 2 re exercises & drills
FEY, F L Northern States Power Co 83/12/21 Region 3, Office
of Director 2pp 22037 096 24X Fiche 50-000, 84/01/18,
8401310254

DOCKETED ITEMS

93

--B401310271 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 11 re accident assessment, EPIP 1 2 1 re emergency plan training & EPIP 1 2 2 re exercises & drills
HUBSON, G. FEY, F. L. Northern States Power Co 83/12/21 10pp
22037 09B 24X Fiche 50-000, B4/01/19, B401310254

B401310335 Forwards exemption requests from requirements of 10CFR50. App R re clarification of definition of intervening combustibles & safety concerns of cable derating & structural adequacy for review & approval
MUSOLF, D Northern States Power Co 84/01/23 Office of Nuclear Reactor Regulation, Director 7pp 22026 269 24X
Fiche 50-282, B4/01/23, B401310335

J Insurance & indemnity information

B401270034 Forwards Endorsements 4, 70, 4, 4 & 58 to NELIA Policies N-17, NF-174, N-37, N-36 & NF-197, respectively & Endorsements 4, 58, 4, 4 & 50 to MAELU Policies M-17, MF-51, M-37, M-36 & MF-68, respectively
JOHNSON, R G Northern States Power Co 84/01/23 DIVISION, I Division of Engineering 11pp 21973 298 24X
Fiche 50-000, B4/01/23, B401270034

P Operating license stage documents & correspondence

B401060230 Provides schedule for submittal of revised procedure for estimating extent of core damage & confirming that heat tracing will be installed on containment sampling lines by B40630, per NUREG-0737, Item II B 3
MUSOLF, D M Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director 1p 21740 111 24X
Fiche 50-282, 83/12/22, B401060230

B401200081 Forwards Rev O to "ASME Code Section XI Inservice Insp & Testing Program" Licensing Fee determination form & fee encl Seven requests for relief remain unresolved Requests for relief will be revised or withdrawn
MUSOLF, D Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director 1p 21862 001 24X
Fiche 50-282, 83/12/22, B401200081

--B401200085 Rev O to "ASME Code Section XI Inservice Insp & Testing Program"
DAHLMAN, L C Northern States Power Co 83/10/14 347pp
21862 002 24X Fiche 50-282, 83/12/22, B401200081

B401101088 Forwards Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change exposure dependence function Bu(Z) to 1 0 for all values of peak pellet exposure
DIIANNI, D C Operating Reactors Branch 3 83/12/28 MUSOLF, D M Northern States Power Co 2pp 21795 128 24X
Fiche 50-282, 83/12/28, B401101088

--B401101093 Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively, changing exposure dependence function Bu(Z) to 1 0 for all values of peak pellet exposure
MILLER, J R Operating Reactors Branch 3 83/12/28 6pp
21795 130 24X Fiche 50-282, 83/12/28, B401101088

--B40110200 Safety evaluation supporting Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/28 4pp
21795 136 24X Fiche 50-282, 83/12/28, B401101088

B401190149 Forwards SER supporting until B30826 & 1114 requests for exemption from inservice insp/testing requirements of ASME Code, Section XI Initial 10-yr insp interval extended 2 months
MILLER, J R Operating Reactors Branch 3 83/12/28 MUSOLF, D M Northern States Power Co 2pp 21871 001 24X
Fiche 50-282, 83/12/28, B401190149

--B401190154 SER supporting until B30826 & 1114 requests for exemption from inservice insp/testing requirements of ASME Code, Section XI Initial 10-yr insp interval extended 2 months
* Office of Nuclear Reactor Regulation, Director 83/12/28 2pp
21871 003 24X Fiche 50-282, 83/12/28, B401190149

B401190159 Forwards evaluation of NUREG-0737, Item II K 2 17 re potential voiding in RCS during anticipated transients Steam voids will not result in unacceptable consequences during transients
MILLER, J R Operating Reactors Branch 3 83/12/30 MUSOLF, D M Northern States Power Co 6pp 21870 356 24X
Fiche 50-282, 83/12/30, B401190159

B401100180 Forwards tentative schedule of major submittals, fire protection exemption requests & Tech Spec changes, for info & planning purposes
MUSOLF, D M Northern States Power Co 84/01/04 Office of Nuclear Reactor Regulation, Director 2pp 21759 280 24X
Fiche 50-282, B4/01/04, B401100180

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

B401180111 Provides addl info re fast cold starts of diesel generators (Generic Ltr B3-41), per B31216 request Facility experienced two fast cold starts & B1 cold starts w/emergency diesel generators from B21201 to B31201
MUSOLF, D Northern States Power Co 84/01/10 Office of Nuclear Reactor Regulation, Director 2pp 21841 356 24X
Fiche 50-282, B4/01/10, B401180111

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401190387 Forwards application for amend to License DPR-42 & DPR-60, to provide assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, Item II B 1
MUSOLF, D Northern States Power Co 84/01/13 Office of Nuclear Reactor Regulation, Director 2pp 21849 349 24X
Fiche 50-282, B4/01/13, B401190387

--B401190392 Application for amend to License DPR-42 & DPR-60, providing assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, Item II B 1
MUSOLF, D Northern States Power Co 84/01/13 6pp 21849 355 24X
Fiche 50-282, B4/01/13, B401190387

--B401190394 Proposed Tech Spec changes providing assurance of reactor coolant vent sys operability & reliability
* Northern States Power Co 84/01/13 40pp 21849 357 24X
Fiche 50-282, B4/01/13, B401190387

B401240431 Forwards general discussion minutes of B31201 meeting w/NRC re equipment qualification open items Description of methodology to establish environ qualification, item resolution & schedule for completion encl
MUSOLF, D Northern States Power Co 84/01/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 36pp 21913 206 24X
Fiche 50-282, B4/01/16, B401240431

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401200081 Forwards Rev O to "ASME Code Section XI Inservice Insp & Testing Program" Licensing Fee determination form & fee encl Seven requests for relief remain unresolved Requests for relief will be revised or withdrawn
MUSOLF, D Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director 1p 21862 001 24X
Fiche 50-282, 83/12/22, B401200081

--B401200085 Rev O to "ASME Code Section XI Inservice Insp & Testing Program"
DAHLMAN, L C Northern States Power Co 83/10/14 347pp
21862 002 24X Fiche 50-282, 83/12/22, B401200081

DOCKETED ITEMS

8401100461 Forwards IE Insp Repts 50-282/83-21 & 50-306/83-21 on 831214 No noncompliance noted
LITTLE, H S Region 3, Office of Director 83/12/23 LARSON, C E
Northern States Power Co 2pp 21761 293 24X
Fiche 50-282, 83/12/23, 8401100461

--8401100486 IE Insp Repts 50-282/83-21 & 50-306/83-21 on 831214 No noncompliance noted Major areas inspected inservice insp procedures, work activities, NDE personnel certifications & data & IE bulletin activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 83/12/23
3pp 21761 295 24X Fiche 50-282, 83/12/23, 8401100486

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature In Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401190149 Forwards SER supporting util 830826 & 1114 requests for exemption from inservice insp/testing requirements of ASME Code, Section XI Initial 10-yr insp interval extended 2 months
MILLER, J R Operating Reactors Branch 3 83/12/28 MUSOLF, D H
Northern States Power Co 2pp 21871 001 24X
Fiche 50-282, 83/12/28, 8401190149

--8401190154 SER supporting util 830826 & 1114 requests for exemption from inservice insp/testing requirements of ASME Code, Section XI Initial 10-yr insp interval extended 2 months
* Office of Nuclear Reactor Regulation, Director 83/12/28 2pp
21871 003 24X Fiche 50-282, 83/12/28, 8401190149

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401240314 Forwards IE Insp Repts 50-282/83-19 & 50-306/83-20 on 831011-1210 & notices of violation & deviation
SHAFFER, W D Region 3, Office of Director 84/01/06 LARSON, C E
Northern States Power Co 2pp 21932 178 24X
Fiche 50-282, 84/01/06, 8401240314

--8401240320 Notice of violation from insp on 831011-1210
SHAFFER, W D Region 3, Office of Director 84/01/06 1p
21932 180 24X Fiche 50-282, 84/01/06, 8401240314

--8401240321 Notice of deviation from insp on 831011-1210
SHAFFER, W D Region 3, Office of Director 84/01/06 1p
21932 181 24X Fiche 50-282, 84/01/06, 8401240314

--8401240332 IE Insp Repts 50-282/83-19 & 50-306/83-20 on 831011-1210 Noncompliance noted failure to provide required changes to procedures Deviation noted failure to perform committed test re IE bulletin
FETERABEND, C D, HARD, J E, HARTMANN, P L Region 3, Office of Director 84/01/06 12pp 21932 182 24X Fiche 50-282, 84/01/06, 8401240314

8401160128 Forwards "Inservice Insp - Exam Summary, Prairie Island Nuclear Generating Plant, Unit 1, 830927-29 " Rept describes special insp of safety injection sys boric acid suction line
MUSOLF, D Northern States Power Co 84/01/09 Office of Nuclear Reactor Regulation, Director 1p 21815 285 24X
Fiche 50-282, 84/01/09, 8401160128

--8401160135 "Inservice Insp - Exam Summary, Prairie Island Nuclear Generating Plant, Unit 1, 830927-29 " Rept summarizes safety injection sys boric acid suction line insp
* Northern States Power Co 83/12/28 28pp 21815 286 24X
Fiche 50-282, 84/01/09, 8401160128

8401170353 Forwards "Inservice Insp-Exam Summary, Prairie Island Nuclear Generating Plant, Unit 2, 830829-1001 " Integrity of sys maintained
MUSOLF, D Northern States Power Co 84/01/09 Office of Nuclear Reactor Regulation, Director 2pp 21828 003 24X
Fiche 50-282, 84/01/09, 8401170353

8401170355 "Inservice Insp - Exam Summary, Prairie Island Nuclear Generating Plant, Unit 2, 830829-1001 "
DAHLMAN, L C, ANDERSON, M T, KRUMPCS, P J Northern States Power Co 83/12/28 194pp 21828 003 24X Fiche 50-282, 84/01/09, 8401170353

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 129pp 21946 033 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310250 Forwards addendum to IE Insp Repts 50-282/83-08 & 50-306/83-08, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sample collected during insp
PAPERIELLO, C J Region 3, Office of Director 84/01/26 LARSON, C E Northern States Power Co 1p 22018 329 24X
Fiche 50-282, 84/01/26, 8401310250

--8401310252 Addendum to IE Insp Repts 50-282/83-08 & 50-306/83-08 on 830701, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sample
* Region 3, Office of Director 84/01/26 1p 22018 330 24X
Fiche 50-282, 84/01/26, 8401310250

R Periodic operating reports & related correspondence

8401120240 Monthly operating repts for Nov 1983 W/831209 1tr
DUGSTAD, D, MUSOLF, D Northern States Power Co 83/11/30 Office
of Resource Management, Director 9pp 21793 312 24X
Fiche 50-282, 83/11/30, 8401120240

8401270452 Monthly operating repts for Dec 1983 W/840109 1tr
DUGSTAD, D, MUSOLF, D Northern States Power Co 83/12/31 Office
of Resource Management, Director 9pp 21980 252 24X
Fiche 50-282, 83/12/31, 8401270452

S Reportable occurrences, LERs & related correspondence

8401050411 LER 83-032/03L-0 on 831121, discovered monthly Station Battery Test SP1096-1 not completed as scheduled Caused by temporary change in responsibilities leading to personnel error Schedule changed W/831221 1tr
HUNSTAD, A, MUSOLF, D Northern States Power Co 83/12/21 Region 3, Office of Director 2pp 21731 133 24X
Fiche 50-282, 83/12/21, 8401050411

8401050442 LER 83-033/01T-0 on 831208, isolation valve CV-31440 in nitrogen supply to accumulators exhibited excessive leakage Caused by plug to cage galling, preventing full Valve closure Plug, cage & seat replaced W/831222 1tr
HUNSTAD, A, MUSOLF, D Northern States Power Co 83/12/22 Region 3, Office of Director 2pp 21729 358 24X
Fiche 50-282, 83/12/22, 8401050442

V Operator Examinations

8401300054 Advises that written operator & senior operator licensing exams scheduled for 840320 & oral exams scheduled for 840321 & 22 Approved listed ref matl should be furnished in order to meet schedule
SPESARD, R L Division of Engineering 84/01/20 LARSON, C E
Northern States Power Co 5pp 21999 264 24X
Fiche 50-282, 84/01/20, 8401300054

DOCKETED ITEMS

95

X Onsite Storage of Low Level Waste

B401120314 Provides info re methods used to comply w/waste classification & waste form requirements of 10CFR61 for disposal of low level radwaste Radionuclides identified by direct or inferential measurement
MUSOLF, D Northern States Power Co 84/01/03 Office of Nuclear Reactor Regulation, Director 2pp 21792 042 24X
Fiche 50-285, 84/01/03, B401120314

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401230131 Forwards revised security plan Plan withheld (ref 10CFR73 21)
JONES, W C Omaha Public Power District 83/11/21 GAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 1p 21884 344 24X Fiche 50-285, 83/11/21, B401230131

B401300172 Forwards IE Insp Rept 50-285/83-26 on 831003-07 & notices of violation & deviation Details withheld (ref 10CFR73 21)
GAOLIARDO, J E Region 4, Office of Director 83/12/06 JONES, W C Omaha Public Power District 2pp 21998 289 24X
Fiche 50-285, 83/12/06, B401300172

--B401300176 Notice of violation from insp on 831003-07
* Region 4, Office of Director 83/12/06 2pp 21998 291 24X
Fiche 50-285, 83/12/06, B401300172

--B401300182 Notice of deviation from insp on 831003-07
* Region 4, Office of Director 83/12/06 1p 21998 293 24X
Fiche 50-285, 83/12/06, B401300172

--B401300189 IE Insp Rept 50-285/83-26 on 831003-07 Violations & deviation noted audit of security procedures not performed as required & arms qualification program used w/o approval Details withheld (ref 10CFR73 21)
EVANS, C A, KELLY, J A, JOHNSON, W D Region 4, Office of Director 83/11/29 1p 21998 294 24X Fiche 50-285, 83/12/06, B401300172

B401170418 Forwards IE Insp Rept 50-285/83-30 on 831114-17 No violations or deviations observed
GAOLIARDO, J E Region 4, Office of Director 83/12/22 JONES, W C Omaha Public Power District 2pp 21829 223, 24X
Fiche 50-285, 83/12/22, B401170418

--B401170422 IE Insp Rept 50-285/83-30 on 831114-17 No violations or deviations observed Major areas inspected selected portions of emergency response program
MONTGOMERY, J L, BAIRD, J B, JOHNSON, W D Region 4, Office of Director 83/12/22 6pp 21829 225 24X Fiche 50-285, 83/12/22, B401170418

B401170111 Forwards comments on 831025 detailed control room design review program plan per requirements of Suppl 1 to NUREG-0737
MILLER, J R Operating Reactors Branch 3 83/12/30 JONES, W C Omaha Public Power District 1pp 21839 331 24X
Fiche 50-285, 83/12/30, B401170111

B401100260 Ack receipt of 831121 ltr transmitting changes to physical security plan Change consistent w/provisions of 10CFR50 34(p) & acceptable
GAOLIARDO, J E Region 4, Office of Director 84/01/03 JONES, W C Omaha Public Power District 1p 21759 194 24X
Fiche 50-285, 84/01/03, B401100260

B401250020 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21948 040 24X Fiche 50-285, 84/01/18, B401250020

--B401250022 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-OSC-1 re emergency classification, EPIP-OSC-B re medical assistance & EPIP-OSC-14 re emergency duty officer
JONES, W C Omaha Public Power District 83/12/15 COLLINS, J T Region 4, Office of Director 2pp 21948 041 24X
Fiche 50-285, 84/01/18, B401250020

--B401250025 Public version of revised emergency plan implementing procedures, including Procedures EPIP-OSC-1 re emergency classification, EPIP-OSC-B re medical assistance & EPIP-OSC-14 re emergency duty officer actions.
* Omaha Public Power District 83/11/18 60pp 21948, 043, 24X
Fiche 50-285, 84/01/18, B401250020

B401260037 Releases public version of changes to radiological emergency response plan
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21989 349 24X Fiche 50-285, 84/01/18, B401260037

--B401260041 Forwards public version of changes to radiological emergency response plan W/o encl
JONES, W C Omaha Public Power District 83/10/24 COLLINS, J T Region 4, Office of Director 1p 21989 330 24X
Fiche 50-285, 84/01/18, B401260037

B401250050 Releases public version of changes to radiological emergency response plan
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21947 260 24X Fiche 50-285, 84/01/20, B401250050

--B401250054 Public version of changes to radiological emergency response plan 4/B40110 ltr & receipt form
JONES, W C Omaha Public Power District 83/12/05 COLLINS, J T Region 4, Office of Director 60pp 21947 261 24X
Fiche 50-285, 84/01/20, B401250050

B401310194 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 22035 001 24X Fiche 50-285, 84/01/20, B401310194

--B401310198 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-OSC-10 re assessment of plant parameters, EPIP-OSC-15 re control room communicator & EPIP-TSC-7 re response assistance
JONES, W C Omaha Public Power District 84/01/10 COLLINS, J T Region 4, Office of Director 2pp 22035 002 24X
Fiche 50-285, 84/01/20, B401310194

--B401310202 Public version of revised emergency plan implementing procedures, including Procedures EPIP-OSC-10 re assessment of plant parameters, EPIP-OSC-15 re control room communicator & EPIP-TSC-7 re response assistance
* Omaha Public Power District 83/12/01 67pp 22035 005 24X
Fiche 50-285, 84/01/20, B401310194

B401300157 Forwards revised pages to site security plan Pages withheld (ref 10CFR73 21)
JONES, W C Omaha Public Power District 84/01/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21999 110 24X
Fiche 50-285, 84/01/23, B401300157

J Insurance & indemnity information

B401260008 Forwards Endorsement 54 to MAELU Policy HF-63 & Endorsement 62 to NELIA Policy NF-807
PETERSEN, H E Omaha Public Power District 84/01/16 DINITZ, I Office of Nuclear Reactor Regulation, Director 3pp 21956 340 24X Fiche 50-285, 84/01/16, B401260008

P Operating license stage documents & correspondence

B401130124 Requests submission of radiological effluent Tech Specs, using Draft 7 of Rev 3 to NUREG-0472 as guidance, within 60 days of receipt of ltr w/o SER
MILLER, J R Operating Reactors Branch 3 83/12/29 JONES, W C Omaha Public Power District 2pp 21819 361 24X
Fiche 50-285, 83/12/29, B401130124

B401040233 Provides info re thermal shield degradation & reactor operation at nominal operating temp but less than 20% power, in response to 831212 telcon No thermal shield deterioration detected
JONES, W C Omaha Public Power District 83/12/30 MILLER, J R Operating Reactors Branch 3 2pp 21701 181 24X
Fiche 50-285, 83/12/30, B401040233

B401040290 Revised application for amend to License DPR-40, consisting of proposed Tech Spec changes re deletion of licensee & significant event reporting requirements & changing wording
JONES, W C Omaha Public Power District 83/12/30 MILLER, J R Operating Reactors Branch 3 1p 21701 301 24X
Fiche 50-285, 83/12/30, B401040290

--B401040293 Proposed changes to Tech Specs deleting licensee & significant event reporting requirements & changing wording
* Omaha Public Power District 83/12/30 7pp 21701 302 24X
Fiche 50-285, 83/12/30, B401040290

DOCKETED ITEMS

8401100329 Advises that installation of first new rack that does not contain Boraflex, completed 8/31/29, per license condition added to Amend 73 to License DPR-40
JONES, W C Omaha Public Power District 8/31/29 MILLER, J R
Operating Reactors Branch 3 2pp 21764 145 24X
Fiche 50-285, 8/31/29, 8401100329

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401100426 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators Emergency diesel generators provided w/prelubrication & warmup capabilities & have never been sub j to fast cold start
JONES, W C Omaha Public Power District 84/01/06 EISENHUT, D G
Division of Licensing 1p 21762 161 24X Fiche 50-285, 84/01/06, 8401100426

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401270144 Informs that, effective 8/4/22, RP Dennis became Director, Div of Resident Reactor Project & Engineering Programs, replacing J Gagliardo, now Director of Chattanooga Training Ctr
COLLINS, J T Region 4, Office of Director 84/01/23 JONES, W C
Omaha Public Power District 1p 21973 358 24X
Fiche 50-285, 84/01/23, 8401270144

8401310302 Responds to 831193 request re reactor vessel fluence associated w/current & future core configurations info including core power & calculated flux distributions at vessel wall will be sent by 840530
JONES, W C Omaha Public Power District 84/01/24 MILLER, J R
Operating Reactors Branch 3 2pp 22026 224 24X
Fiche 50-285, 84/01/24, 8401310302

Q Inspection Reports, IE Bulletins & correspondence

8401040524 Forwards IE Enforcement Conference Rept 50-285/83-25 on 830907 No violations noted
SEIDLE, W C Region 4, Office of Director 83/09/21 JONES, W C
Omaha Public Power District 2pp 21706 009 24X
Fiche 50-285, 83/09/21, 8401040524

8401040529 IE Enforcement Conference Rept 50-285/83-25 on 830909 No violations noted Major areas discussed const QA records & file room
YANDELL, L A, JOHNSON, W D Region 4, Office of Director 83/09/16 3pp 21706 011 24X Fiche 50-285, 83/09/16, 8401040524

Q60040 Responds to FOIA request for IE tabulation of SALP results ring 1982 Forwards IE notebook tabulating requested info (notebook also available in PDR)
LTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Law, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401040471 Forwards IE Insp Rept 50-285/83-23 on 830823-0930 No noncompliance noted
GAGLIARDO, J E Region 4, Office of Director 83/10/24 JONES, W C
Omaha Public Power District 2pp 21705 296 24X
Fiche 50-285, 83/10/24, 8401040471

8401040474 IE Insp Rept 50-285/83-23 on 830823-0930 No noncompliance noted Major areas inspected operational safety verification, surveillance testing, maint activities, followup of violations & NUREG-0737 items
YANDELL, L A, JOHNSON, W D Region 4, Office of Director 3/10/21 7pp 21705 298 24X Fiche 50-285, 83/10/24, 8401040471

8401040363 Forwards IE Insp Rept 50-285/83-20 on 830815-19 No noncompliance noted
GAGLIARDO, J E Region 4, Office of Director 83/10/31 JONES, W C
Omaha Public Power District 2pp 21706 155 24X
Fiche 50-285, 83/10/31, 8401040363

--8401040364 IE Insp Rept 50-285/83-20 on 830815-19 No noncompliance noted Major areas inspected radiochemistry program, including review of outstanding open items, organization, audits of radiochemistry activities & sample collection
NICHOLAS, J B, WISE, R, MURRAY, D Region 4, Office of Director 83/10/18 25pp 21706 157 24X Fiche 50-285, 83/10/31, 8401040363

8401040407 Forwards IE Insp Rept 50-285/83-32 on 831001-31 No noncompliance noted
GAGLIARDO, J E Region 4, Office of Director 83/11/21 JONES, W C
Omaha Public Power District 2pp 21705 001 24X
Fiche 50-285, 83/11/21, 8401040407

--8401040411 IE Insp Rept 50-285/83-32 on 831001-31 No noncompliance noted Major areas inspected operational safety verification, surveillance testing, maint activities, followup of NUREG-0737 items & spent fuel storage rack mods
YANDELL, L A, JOHNSON, W D Region 4, Office of Director 83/11/15 8pp 21705 003 24X Fiche 50-285, 83/11/21, 8401040407

8401040446 Forwards IE Insp Rept 50-285/83-24 on 830926-30 No noncompliance noted
GAGLIARDO, J E Region 4, Office of Director 83/11/25 JONES, W C
Omaha Public Power District 2pp 21708 074 24X
Fiche 50-285, 83/11/25, 8401040446

--8401040451 IE Insp Rept 50-285/83-24 on 830926-30 No noncompliance noted Major areas inspected radiation protection program, including radiation protection organization & qualifications, training, audits, ALARA program & open items
HOLLEY, W L, MURRAY, D, JOHNSON, W D Region 4, Office of Director 83/11/16 8pp 21708 076 24X Fiche 50-285, 83/11/25, 8401040446

8401300172 Forwards IE Insp Rept 50-285/83-26 on 831003-07 & notices of violation & deviation Details withheld (ref 10CFR73 21)
GAGLIARDO, J E Region 4, Office of Director 83/12/06 JONES, W C
Omaha Public Power District 2pp 21998 289 24X
Fiche 50-285, 83/12/06, 8401300172

--8401300176 Notice of violation from insp on 831003-07
* Region 4, Office of Director 83/12/06 2pp 21998 291 24X
Fiche 50-285, 83/12/06, 8401300172

--8401300182 Notice of deviation from insp on 831003-07
* Region 4, Office of Director 83/12/06 1p 21998 293 24X
Fiche 50-285, 83/12/06, 8401300172

--8401300189 IE Insp Rept 50-285/83-26 on 831003-07 Violations & deviation noted audit of security procedures not performed as required & arms qualification program used w/o approval Details withheld (ref 10CFR73 21)
EVANS, C A, KELLY, J A, JOHNSON, W D Region 4, Office of Director 83/11/29 1p 21998 294 24X Fiche 50-285, 83/12/06, 8401300172

8401170418 Forwards IE Insp Rept 50-285/83-30 on 831114-17 No violations or deviations observed
GAGLIARDO, J E Region 4, Office of Director 83/12/22 JONES, W C
Omaha Public Power District 2pp 21829 223 24X
Fiche 50-285, 83/12/22, 8401170418

--8401170422 IE Insp Rept 50-285/83-30 on 831114-17 No violations or deviations observed Major areas inspected selected portions of emergency response program
MONTGOMERY, J L, BAIRD, J B, JOHNSON, W D Region 4, Office of Director 83/12/22 8pp 21829 225 24X Fiche 50-285, 83/12/22, 8401170418

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp, 21731 166 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

DOCKETED ITEMS

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401170158 Forwards Rev 1 to inservice insp program plan for 1983-1993, reflecting exemptions discussed in 831115 ltr
JONES, W. C. Omaha Public Power District 84/01/10 MILLER, J. R. Operating Reactors Branch 3 1p 21834 128 24X
Fiche 50-285, 84/01/10, 8401170158

--8401170159 Rev 1 to inservice insp program plan for 1983-1993
* Omaha Public Power District 83/12/31 4pp 21834 129 24X
Fiche 50-285, 84/01/10, 8401170158

8312120114 IE Info Notice 84-03, "Exercise Frequency." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21997 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8 Reportable occurrences, LERs & related correspondence

8401230360 Revised LER 83-004/03L-1 on 830629, pressure switches A/PC-742-1 & A/PC-742-2 found initiating/actuating above 5 psig Caused by instrument drift Switches recalibr W/840112 ltr
MUELLER, R. J., JONES, W. C. Omaha Public Power District 83/07/07
GAGLIARDO, J. E. Region 4, Office of Director 5pp 21884 273 24X
Fiche 50-285, 83/07/07, 8401230360

8401050064 FOIA request for 27 listed LERs
GRABER, L. D. NUS Corp 83/10/07 Division of Rules and Records
2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050064

8401050075 Responds to FOIA request for 27 LERs Forwards three listed LERs Remaining LERs unavailable in NRC records sys, canceled, or never issued
FELTON, J. M. Division of Rules and Records 83/10/25 GRABER, L. D. NUS Corp 1p 21736 345 24X Fiche 50-000, 83/10/25, 8401050075

--8401050085 LER 83-002/03L-0 on 830307, safety-related shock suppressor safety injection sys 134 removed to accommodate maint on control element drive mechanism & not replaced within 72 h after core reloading begun Snubber replaced W/830406 ltr
BURGGRAF, M. G., JONES, W. C. Omaha Public Power District 83/03/22
SEIDLE, W. C. Region 4, Office of Director 5pp 21736 349 24X
Fiche 50-000, 83/10/25, 8401050075

8401230317 LER 83-013/03L-0 on 831215, during Surveillance Test ST-ESF-3, pressure switches A/PC-742-1 & A/PC-742-2 found inoperable Caused by instrument drift Switches recalibr W/840112 ltr
MUELLER, R. J., JONES, W. C. Omaha Public Power District 83/12/29
GAGLIARDO, J. E. Division of Resident, Reactor Project & Engineering Programs 5pp 21882 352 24X Fiche 50-285, 83/12/29, 8401230317

V. Operator Examinations

8401310242 Responds to 831221 request for estimate of need for operator licensing exams for FY84-87, per Generic Ltr 83-40 Exam schedule encl
JONES, W. C. Omaha Public Power District 84/01/25 EISENHUT, D. G. Division of Licensing 2pp 22018 325 24X Fiche 50-285, 84/01/25, 8401310242

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8401050360 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 140 24X Fiche 50-286, 83/12/28, 8401050360

--8401050372 Forwards public version of revised Emergency Plan Implementing Procedures IP-1002 re determination of release magnitude, IP-1011 re offsite monitoring & IP-1028 re core damage assessment
RYAN, T. Power Authority of the State of New York 83/12/13
NRC - No Detailed Affiliation Given 1p 21743 141 24X
Fiche 50-286, 83/12/28, 8401050360

--8401050374 Public version of revised Emergency Plan Implementing Procedures IP-1002 re determination of release magnitude, IP-1011 re offsite monitoring & IP-1028 re core damage assessment
BRONB, J. C. Power Authority of the State of New York 83/12/12
37pp 21743 142 24X Fiche 50-286, 83/12/28, 8401050360

8401050313 Responds to 831128 ltr re intent & direction of recent NRC proposal on possible changes to emergency preparedness requirements NRC proposal is in early stages of development & does not represent final NRC policy
PALLADINO, N. J. Commissioners 83/12/30 DELBELLO, A. B. New York, State of 1p 21729 277 24X Fiche 50-247, 83/12/30, 8401050313

--8401050316 Expresses concern re intent & direction of NRC reexam of current emergency planning regulations Safety stds need strengthening
DELBELLO, A. B. New York, State of 83/11/28 PALLADINO, N. J. Commissioners 2pp 21729 278 24X Fiche 50-247, 83/12/30, 8401050313

8401100258 Forwards Rev B to security plan Rev withheld (ref 10CFR73.21 & 10CFR2.790)
BAYNE, J. P. Power Authority of the State of New York 84/01/06
VARGA, S. A. Operating Reactors Branch 1 2pp 21739 190 24X
Fiche 50-286, 84/01/06, 8401100258

8401240615 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 235 24X Fiche 50-286, 84/01/20, 8401240615

--8401240617 Public version of Rev 9 to Emergency Plan Implementing Procedure IP-1070, "Periodic Check of Emergency Preparedness Equipment." W/840109 transmittal memo & revised index
DELL, D. D., BURNS, J. C. Power Authority of the State of New York 83/12/23 16pp 21945 236 24X Fiche 50-286, 84/01/20, 8401240615

8401300209 Responds to 840109 ltr forwarding correspondence from Croton-Harmon School District in Croton-on-Hudson, NY re Westchester County evacuation plan for school children in event of facility accident FEMA already responded
KRIMM, R. W. Federal Emergency Management Agency 84/01/24
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21994 001 24X Fiche 50-000, 84/01/24, 8401300209

J Insurance & indemnity information

8401050287 Forwards Endorsement 68 to NELA Policy NF-208, Endorsement 58 to MAELU Policy NF-77 & Endorsement 4 to NELA Policies N-47 & N-7 & MAELU Policies M-47 & M-7
GOLDEN, M. P. Marsh & McLennan, Inc 83/12/28 SALTZMAN, J. Assistant Director for State & License Relations 7pp 21726 334 24X Fiche 50-000, 83/12/28, 8401050287

D Advisory Committee on Reactor Safeguards reports & correspondence

840130127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee B21103 meeting w/NRR & BNL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PRA Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/06
ACRS - Advisory Committee on Reactor Safeguards 38pp 21820 237 24X Fiche 50-000, 82/12/06, 840130127

P Operating license stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J. M. Division of Rules and Records 83/10/18 WEISS, E. R. Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015

--8401250353 Recommends issuance of encl order granting in part & denying in part motion to direct staff to reschedule 831013 meeting re Sandia Lab preliminary evaluation of facility safety study.
MALBACH, M. G. Office of the General Counsel SECY-82-473
82/11/30 5pp 21967 121 24X Fiche 50-000, 83/10/18, 8401250015

#

DOCKETED ITEMS

99

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

B401240340 "Effluent & Waste Disposal Semiannual Rept Jan-June 1983 " W/840104 ltr
BRONB, J C Power Authority of the State of New York 83/06/30
MURLEY, T E Region 1, Office of Director 47pp 21908 100 24X Fiche 50-286,83/06/30,8401240340

B401120230 Monthly operating rept for Nov 1983 W/831212 ltr
KELLY, L J, BRONB, J C Power Authority of the State of New York 83/11/30 NRC - No Detailed Affiliation Given 7pp 21793 300 24X Fiche 50-286,83/11/30,8401120230

B401120267 Monthly operating rept for Dec 1983 W/840113 ltr
KELLY, L J, BRONB, J C Power Authority of the State of New York 83/12/31 Office of Resource Management, Director 8pp 21976 057 24X Fiche 50-286,83/12/31,8401120267

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

B401030216 Forwards Rev 2 to util 830414 response to Suppl 1 to NUREG-0737, consisting of changes to proposed schedule for upgraded emergency preparedness program, delaying implementation of new emergency procedures to Oct 1985
TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 21682 317 24X Fiche 50-269,83/12/27,8401030216

B401060081 Releases public version of revised emergency plan & revised emergency plan implementing procedures manual
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21747 201 24X Fiche 50-269,83/12/28,8401060081

--B401060085 Forwards public version of revised emergency plan & revised emergency plan implementing procedures manual
TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 1p 21747 202 24X Fiche 50-269,83/12/28,8401060081

--B401060090 Public version of Rev 83-8 to emergency plan implementing procedures manual
SMITH, J Duke Power Co 83/11/17 83pp 21747 203 24X Fiche 50-269,83/12/28,8401060090

--B401060094 Public version of Rev 83-2 to emergency plan
SMITH, J Duke Power Co 83/11/18 52pp 21747 286 24X Fiche 50-269,83/12/28,8401060094

B401170484 Forwards exemption from requirements of 10CFR50, App E re annual emergency preparedness exercise, in response to 830309 & 1010 requests No exemption from 10CFR50 47 required
EISENHUT, D G Division of Licensing 84/01/06 TUCKER, H B Duke Power Co 4pp 21844 271 24X Fiche 50-000,84/01/06,8401170484

--B401170491 Exemption from requirements of App E to 10CFR50 re annual emergency preparedness exercise & provisions for training & exercising of licensee employees, including headquarters support personnel in radiation emergency matters
EISENHUT, D G Division of Licensing 84/01/06 Duke Power Co 5pp 21844 277 24X Fiche 50-000,84/01/06,8401170491

B401200010 Summary of 830906 meeting w/util & State of SC re exemption request for emergency operations facility
GUERNHANN, J F Operating Reactors Branch 4 84/01/09 Operating Reactors Branch 4 28pp 21871 079 24X Fiche 50-269,84/01/09,8401200010

B401310300 Forwards Rev 11 to security plan Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 84/01/16 O'REILLY, J P Region 2, Office of Director, 1p 22021 362 24X Fiche 50-269,84/01/16,8401310300

H General correspondence

B401240339 Informs that firm name of counsel for applicants/licensees charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S Arkansas Power & Light Co REYNOLDS, N S Duke Power Co 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000,84/01/19,8401240339

I Financial information

B401100386 Forwards addl info re 1983-85 financial forecast, per IP Dinit: 831107 request Projected figures for yr ended 831231 unavailable
TUCKER, H B Duke Power Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21763 137 24X Fiche 50-000,84/01/04,8401100386

P Operating license stage documents & correspondence

B401040304 Forwards list of mods/upgrades to control rooms to meet habitability requirements of TMI Action Plan Item III D 3 4 Complete implementation expected by end of 1984 Schedule can be provided in Feb 1984
TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 21708 103 24X Fiche 50-269,83/12/27,8401040304

B401090652 Responds to telcon re clarification of review of NUREG-0737, Items II K 3 1 & II K 3 2 (automatic PORV isolation) Review combined Items II K 3 7 & II K 3 2, resolving Item II K 3 7
STOLZ, J F Operating Reactors Branch 4 83/12/28 TUCKER, H B Duke Power Co 1p 21757 359 24X Fiche 50-269,83/12/28,8401090652

B401090364 Informs that submittal justifying reactor coolant pump manual trip setpoint will be delayed until results of analysis reviewed, in response to Generic Ltr 83-10 Submittal expected by 840330
TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21754 060 24X Fiche 50-269,83/12/30,8401090364

B401090508 Suppls 831104 response to Generic Ltr 83-28 "Required Actions Based on Generic Implications of Salem ATWS Events " Automatic shunt trip mods will be installed during next refueling outages Design description encl
TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 14pp 21751 232 24X Fiche 50-269,83/12/30,8401090508

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000,84/01/05,8401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000,84/01/06,8401090221

B401240039 Notices of completion of review of post-accident sampling sys (NUREG-0737, Item II B 3) Response to criterion requiring procedure for estimating core damage extent acceptable on interim basis Plant-specific procedure due 840831
STOLZ, J F Operating Reactors Branch 4 84/01/11 TUCKER, H B Duke Power Co 21pp 21945 001 24X Fiche 50-269,84/01/11,8401240039

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000,84/01/13,8401130084

B401230188 Forwards response to Item 2 2 1-5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events " Design of electrical safety sys provides for automatic backup for equipment failure
TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 21884 160 24X Fiche 50-269,84/01/17,8401230188

DOCKETED ITEMS

B401240402 Advises that facility will implement, by 850101, shift technical advisor program incorporating NRC 831123 requirements. Currently approved program to remain in effect in interim Program document will be submitted by 840601
TUCKER, H B Duke Power Co 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21920 141 24X Fiche 50-269, 84/01/20, 8401240402

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

B401050414 Forwards supplemental response to IE Bulletin 83-06 re nonconforming mats supplied by Tube-Line Corp Final disposition of items under evaluation Four pieces Schedule 40, 84-234 WPB reducing tees supplied by Tube-Line Corp
TUCKER, H B Duke Power Co 83/12/09 O'REILLY, J P Region 2, Office of Director 4pp 21731 135 24X Fiche 50-269, 83/12/09, 8401050414

B401040001 Forwards evaluations & conclusions, in response to util 830701 ltr denying one violation identified during NRC 830317-28 insp re containment integrity Imposition of civil penalties inappropriate
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/20 TUCKER, H B Duke Power Co 5pp 21711 306 24X Fiche 50-269, 83/12/20, 8401040001

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/20 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 03-04, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 04-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 04-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 104 24X Fiche 50-000, 84/01/10, 8312120107

8401240150 Forwards response to IE Bulletin 81-01, Item 3 re inaccessible mechanical snubber insp List of affected snubbers encl No failures found
TUCKER, H B Duke Power Co 84/01/10 O'REILLY, J P Region 2, Office of Director 4pp 21910 263 24X Fiche 50-269, 84/01/10, 8401240150

8312120114 IE Info Notice 04-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 04-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 116pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 04-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

B401200033 Monthly operating repts for Dec 1983 W/840113 ltr
REAVIS, J A, TUCKER, H B Duke Power Co 83/12/31 Director's Office, Office of Inspection and Enforcement 17pp 21865 260 24X Fiche 50-269, 83/12/31, 8401200033

S Reportable occurrences, LERs & related correspondence

8401050617 LER 83-013/03L-0 on 831124, containment isolation engineered safeguard valve 3CS-5 found leaking past seal Cause undetermined Valve will be inspected during next available outage W/831222 ltr
FUELL, P F, TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P Region 2, Office of Director 4pp 21726 069 24X Fiche 50-287, 83/12/22, 8401050617

B401170208 Revised LER 83-013/03L-1 on 831124, engineered safeguards containment isolation valve 3CS-5 discovered to be leaking past seat Probably caused by component failure Redundant valve 3CS-6 deactivated & locked W/840109 ltr
FUELL, P F, TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P Region 2, Office of Director 4pp 21832 256 24X Fiche 50-287, 83/12/22, 8401170208

V Operator Examinations

8401200221 Forwards revised requalification program for NRC licensed personnel Appropriate sections revised to incorporate NRC requirements
TUCKER, H B Duke Power Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 21864 269 24X Fiche 50-269, 84/01/12, 8401200221

--B401200223 Revised requalification program for NRC licensed personnel
* Duke Power Co 83/08/19 11pp 21864 270 24X Fiche 50-269, 84/01/12, 8401200221

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8401100391 Forwards IE Insp Rept 50-288/83-02 on 831206-07 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/12/21 BROADON, P Reed College, Portland, OR 2pp 21762 220 24X Fiche 50-288, 83/12/21, 8401100391

--B401100397 IE Insp Rept 50-288/83-02 on 831206-07 No noncompliance noted Major areas inspected radiation protection program, Tech Spec requirements, preparations for 10CFR61 compliance, followup on IE info notices & transportation activities
OARCIA, E M, WENSLAWSKI, F A Region 5, Office of Director 83/12/21 5pp 21762 222 24X Fiche 50-288, 83/12/21, 8401100397

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J M Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X Fiche 50-000, 83/11/02, 8401250163

--B401250185 Discusses how SECY-82-111 unravels NRC emergency preparedness requirements, per author 821103 memo Table 111 A 1-2-2 not changed in any way by SECY-82-111 Responses to listed questions requested
OILINSKY, V Commissioners 82/11/18 Commissioners 2pp 21959 004 24X Fiche 50-000, 83/11/02, 8401250163

8401030234 Forwards IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831203 & notice of violation
MURLEY, T E Region 1, Office of Director 83/12/14 CLARK, P R General Public Utilities - GPU Service Corp 3pp 21682 279 24X Fiche 50-289, 83/12/14, 8401030234

--B401030241 IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 Violation noted, drafts containing safeguards info left unattended on desk in unlocked security storage container
MURLEY, T E, GODY, A T Region 1, Office of Director 83/12/14 2pp 21682 283 24X Fiche 50-289, 83/12/14, 8401030241

DOCKETED ITEMS

10

B401030255 Forwards IE Insp Rept 50-289/83-31 on 831103-04 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/14
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21681 164 24X Fiche 50-289, 83/12/14, 8401030255

--B401030256 IE Insp Rept 50-289/83-31 on 831103-04 No noncompliance noted Major areas inspected public prompt notification sys
COHEN, I, HANXHURST, J, CROCKER, H W Region 1, Office of Director
83/12/12 5pp 21681 164 24X Fiche 50-289, 83/12/14, 8401030259

B401040626 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21714 208 24X Fiche 50-289, 83/12/28, 8401040626

--B401040628 Public version of Rev 2 to Emergency Plan Implementing Procedure 1004 1B, "Search & Rescue"
STANOE, S J General Public Utilities - GPU Service Corp
83/11/03 11pp 21714 209 24X Fiche 50-289, 83/12/28, 8401040626

B401050092 Releases public version of temporary change notice to revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 301 24X Fiche 50-289, 83/12/28, 8401050092

--B401050096 Public version of Temporary Change Notice 1-83-0236 to Rev 3 to Emergency Plan Implementing Procedure 1004 29, "Activation of Operations Support Ctr"
BRADY, J A General Public Utilities - GPU Service Corp 83/11/15
7pp 21736 302 24X Fiche 50-289, 83/12/28, 8401050092

B401050115 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 283 24X Fiche 50-289, 83/12/28, 8401050115

--B401050119 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004 27, "Activation of Emergency Operation Facility"
STANOE, S J General Public Utilities - GPU Service Corp
83/11/15 18pp 21743 284 24X Fiche 50-289, 83/12/28, 8401050115

B401050227 Releases public version of temporary change notice to emergency planning implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 251 24X Fiche 50-289, 83/12/28, 8401050227

--B401050235 Public version of Temporary Change Notice 1-83-0251 to Rev 10 of Emergency Planning Implementing Procedure 1004 B, "Callout of Onsite & Offsite Duty Roster Personnel"
BRADY, J A General Public Utilities - GPU Service Corp 83/12/02
12pp 21743 252 24X Fiche 50-289, 83/12/28, 8401050227

B401060146 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21745 123 24X Fiche 50-289, 83/12/28, 8401060146

--B401060152 Public version of revised emergency plan implementing procedures, including Procedures 1004 4 re general emergency, 1004 15 re post-accident in-plant sampling & 1004 31 re airborne radioactivity sampling & analysis
BRADY, J A General Public Utilities - GPU Service Corp. 83/11/15
34pp 21745 124 24X Fiche 50-289, 83/12/28, 8401060146

B401060153 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21745 178 24X Fiche 50-289, 83/12/28, 8401060153

--B401060158 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004 7, "Offsite/Onsite Dose Projections"
STANOE, S J Metropolitan Edison Co. 83/11/03 70pp 21745 179 24X Fiche 50-289, 83/12/28, 8401060153

B401130117 Notification of B40106 meeting w/util in Bethesda, MD to discuss procedures generation package for developing upgraded emergency operating procedures per NUREG-0737, Suppl 1 & TMI Item I C.1
VAN ULIEY, J Operating Reactors Branch 4 83/12/30 STOLZ, J F
Operating Reactors Branch 4 2pp 21820 339 24X
Fiche 50-289, 83/12/30, 8401130117

B401130323 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-18 & 50-320/83-10 Corrective actions re min number of fire brigade members at site acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/01/05
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21801 328 24X Fiche 50-289, 84/01/05, 8401130323

B401130190 Forwards Rev O to Procedure 1292, "Fire Protection Program Plan," incorporating administrative, training & organizational changes made since 800711 due to results of recent insp findings & internal reviews
HUKILL, H D General Public Utilities - GPU Service Corp 84/01/07
STOLZ, J F Operating Reactors Branch 4 1p 21800 226 24X
Fiche 50-289, 84/01/07, 8401130190

--B401130194 Rev O to Procedure 1292, "Fire Protection Program Plan"
O'CONNOR, T A General Public Utilities - GPU Service Corp
84/01/04 42pp 21800 227 24X Fiche 50-289, 84/01/07, 8401130190

B401240445 Forwards IE Insp Rept 50-289/83-35 on 831115-18 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/09
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21915 178 24X Fiche 50-289, 84/01/09, 8401240445

--B401240457 IE Insp Rept 50-289/83-35 on 831115-18 No violations noted Major areas inspected emergency preparedness & 831116 emergency exercise
TERC, N M, CROCKER, H W Division of Engineering & Technical Programs 83/12/22 8pp 21915 180 24X Fiche 50-289, 84/01/09, 8401240445

B401230335 Forwards "Program Description & Summary Rept of Detailed Control Room Design Review of TMI Unit 1 Control Room," in response to NUREG-0737, Item I D i & Suppl 1 & NUREG-0752 & Suppl 1, including analysis of emergency operations tasks
HUKILL, H D General Public Utilities - GPU Service Corp 84/01/16
STOLZ, J F Operating Reactors Branch 4 1p 21875 159 24X
Fiche 50-289, 84/01/16, 8401230335

--B401230337 "Program Description & Summary Rept of Detailed Control Room Design Review of TMI Unit 1 Control Room"
* MPR Associates, Inc 83/11/30 100pp 21875 160 24X
Fiche 50-289, 84/01/16, 8401230335

B401260063 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21989 207 24X Fiche 50-289, 84/01/18, 8401260063

--B401260065 Public version of Rev 9 to Emergency Plan Administrative Procedure 1053, "Emergency Equipment Readiness"
NELSON, M A, TOOLE, R J, HUKILL, H General Public Utilities - GPU Service Corp 83/11/07 44pp 21989 210 24X
Fiche 50-289, 84/01/18, 8401260063

B401260288 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21992 055 24X Fiche 50-289, 84/01/20, 8401260288

--B401260291 Public version of revised Emergency Plan Implementing Procedures 1004 28 re activation of technical support ctr & 1004 32 re activation of annex to emergency operations facility (Crawford Station)
* Metropolitan Edison Co 83/12/30 19pp 21992 056 24X
Fiche 50-289, 84/01/20, 8401260288

B401300350 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22006 029 24X Fiche 50-289, 84/01/26, 8401300350

--B401300353 Public version of revised emergency plan implementing procedures, including Procedures 1004 15 re post-accident in-plant sampling & 1004 31 re airborne radioactivity sampling & analysis
STANOE, S J Metropolitan Edison Co 84/01/17 74pp 22006 030 24X
Fiche 50-289, 84/01/26, 8401300350

B401310141 Forwards abnormal transient operating guidelines procedures generation package, in response to Generic Ltr B2-33 Package includes addl info requested by NRC at B40106 meeting re implementation of NUREG-0737, Item I C.1
HUKILL, H D General Public Utilities - GPU Service Corp 84/01/26
STOLZ, J F Operating Reactors Branch 4 3pp 22022 129 24X
Fiche 50-289, 84/01/26, 8401310141

DOCKETED ITEMS

G Adjudicatory correspondence

8401230408 Partial initial decision (reopened proceeding) re restart
JORDAN, W. H., LITTLE, L. W., SMITH, I. W. Atomic Safety and Licensing
Board Panel 82/07/27 18pp 21878 254 24X
Fiche 50-289, 82/07/27, 8401230408

8401040609 FOIA request for "People Against Nuclear Energy Draft
Contentions" re facility restart
WILEY, D. K. Affiliation Unknown 83/09/26 Office of
Administration 1p 21714 195 24X Fiche 50-289, 83/09/26,
8401040609

8401040611 Responds to FOIA request for "People Against Nuclear Energy
Draft Contentions " Forwards requested document
FELTON, J. M. Division of Rules and Records 83/10/21 WILEY, D. K.
Affiliation Unknown 1p 21714 196 24X Fiche 50-289, 83/10/21,
8401040611

8312050118 Notice to Commission, ASLB, ASLB & parties transmitting
GPU 83128 news release of 83128 presentation to
Commission on restart issues Related correspondence &
svc list encl
BLAKE, E. L. Metropolitan Edison Co BLAKE, E. L. Shaw, Pittman, Potts
& Trowbridge 83/12/01 76pp 21372 237 24X
Fiche 50-289, 83/12/01, 8312050118

8312200353 First set of interrogatories & request for production of
documents re steam generator repair Related correspondence
CHURCHILL, B. W. Metropolitan Edison Co CHURCHILL, B. W. Shaw,
Pittman, Potts & Trowbridge 83/12/15 Three Mile Island Alert
38pp 21589 034 24X Fiche 50-289, 83/12/15, 8312200353

--8312200359 First set of interrogatories & request for production of
documents re steam generator repair Certificate of Svc encl
Related correspondence
CHURCHILL, B. W. Shaw, Pittman, Potts & Trowbridge CHURCHILL, B. W.
Metropolitan Edison Co 83/12/15 Joint Petitioners - TMI.
18pp 21589 092 24X Fiche 50-289, 83/12/15, 8312200359

8401030087 Forwards 831216 status rept of util response to Rehner,
Hibler & Replogle, Inc rept on licensed operator concerns
Svc list encl
BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge BLAKE, E. L.
Metropolitan Edison Co 83/12/28 EDLES, G. J., BUCK, J. H., KOHL, C. N.
Atomic Safety and Licensing Appeal Panel 21pp 21693 172 24X
Fiche 50-289, 83/12/28, 8401030087

8401040106 Response to UCS 831209 request for opportunity to respond to
NRC 831205 oral proposal for restart Certificate of Svc
encl
WAGNER, M. E. Hearing Branch 4 83/12/29 Commissioners 8pp
21703 258 24X Fiche 50-289, 83/12/29, 8401040106

8401050216 First set of interrogatories & request for production of
documents re steam generator repair Certificate of Svc encl
Related correspondence
BRADFORD, L. Three Mile Island Alert 83/12/30 Metropolitan
Edison Co 37pp 21728 145 24X Fiche 50-289, 83/12/30, 8401050216

8401100229 Suggests Commissioners indicate vote on staff NSHC
recommendation re steam generator amend before 840110
meeting
PALLADINO, N. J. Commissioners 83/12/30 GILINSKY, V., ROBERTS, T. M.,
ASSELSTINE, J. K. Commissioners 4pp 21772 323 24X
Fiche 50-289, 83/12/30, 8401100229

8401100223 Requests designation of stress corrosion cracking as
unresolved safety issue & investigation of issue prior to
restart
LEWIS, M. I. Lewis, M. 83/12/31 PALLADINO, N. J. Commissioners 1p
21759 247 24X Fiche 50-289, 83/12/31, 8401100223

8401050455 Preliminary response to interrogatories & document requests
re steam generator tube failures & repairs
DOROSHCH, J. Three Mile Island Alert 84/01/03 Metropolitan
Edison Co 43pp 21730 150 24X Fiche 50-289, 84/01/03, 8401050455

8401050459 Response to request for production of documents re steam
generator tube failures & repairs All documents already in
licensee possession or can be found in PDR Certificate of
Svc encl
DOROSHCH, J. Three Mile Island Alert 84/01/03 Metropolitan
Edison Co 5pp 21730 192 24X Fiche 50-289, 84/01/03, 8401050459

8401090353 Corrects apparent misunderstanding re prior meeting w/Kuhns
concerning resignation Util mgt deserves high marks for
efforts to keep company solvent & maintain unrestricted &
unbroken svc to all customers
ALLGOOD, I. J. National Systems, Inc 84/01/03 GILINSKY, V.
Commissioners 3pp 21754 093 24X Fiche 50-289, 84/01/03,
8401090353

8401120204 Response supporting licensee motion for reconsideration
of ASLB 831129 memorandum & order ruling on contentions
proffered by TMI Alert, J. Lee & Associates No basis provided for
nexus between amend & contention w/Certificate of Svc
RAHSON, R. J. Hearing Branch 4 84/01/03 Atomic Safety and
Licensing Board Panel 9pp 21794 016 24X Fiche 50-289, 84/01/03,
8401120204

8401100205 Comments on NRC 831205 proposals for restart Possible
degradation of fuel assemblies while in spent fuel storage
pools should be investigated prior to restart
LEWIS, M. I. Lewis, M. 84/01/04 PALLADINO, N. J. Commissioners
3pp 21760 151 24X Fiche 50-289, 84/01/04, 8401100205

8401120278 Forwards documents released by Commission in response to
two FOIA requests re nature of agreement between NRC & DDT
concerning investigation into Hartman allegations Documents
made public in future will be provided to ASLB & parties
WAGNER, M. E. Hearing Branch 4 84/01/04 EDLES, G. J., BUCK, J. H.,
KOHL, C. N. Atomic Safety and Licensing Board Panel 13pp
21792 315 24X Fiche 50-289, 84/01/04, 8401120278

8401100139 Forwards util 831222 ltr to Region I re Kr-B5 leakage paths.
Svc list encl
ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge ZAHLER, R. E.
Metropolitan Edison Co 84/01/05 CHILK, S. J. Office of the
Secretary of the Commission 9pp 21760 001 24X
Fiche 50-289, 84/01/05, 8401100139

8401120241 Forwards EDO 840103 memo memorializing views set forth in
NRC 831205 oral presentation & explaining how NRC arrived at
current position re util 830610 mgt reorganization proposal
WAGNER, M. E. Hearing Branch 4 84/01/05 EDLES, G. J., BUCK, J. H.,
KOHL, C. N. Atomic Safety and Licensing Board Panel 9pp 21793 321
24X Fiche 50-289, 84/01/05, 8401120241

8401100200 Response opposing applicant 831223 reply to UCS response to
831206 ltr re emergency feedwater flow instrumentation
Attempt to circumvent short-term lessons learned
requirements should be rejected Certificate of Svc encl
WEISS, E. R., POLLARD, R. D. Union of Concerned Scientists 84/01/06
Commissioners 13pp 21760 317 24X Fiche 50-289, 84/01/06,
8401100200

8401100201 Order extending time until 840120 for Commission to act to
review ALAB-729 & ALAB-744
CHILK, S. J. Office of the Secretary of the Commission 84/01/06
Commissioners 1p 21760 247 24X Fiche 50-289, 84/01/06,
8401100201

8401100209 Response to UCS & NRC 831205 proposals describing means by
which open issues re mgt competency/integrity (Hartman
issue) could be resolved to allow restart Commission not
responsible for finding path to restart
AAHDDT, N. O., AAHDDT, M. M. Aamodts 84/01/07 Commissioners
12pp 21760 188 24X Fiche 50-289, 84/01/07, 8401100209

8401100141 Memorandum & order partially granting util 831212 motion for
reconsideration of 831129 memorandum & order re dismissal of
TMI Alert, Inc Contentions 1(b), 1(d) & 2(c)
WOLFE, B. J. Atomic Safety and Licensing Board Panel 84/01/09,
Metropolitan Edison Co 8pp 21760 023 24X Fiche 50-289, 84/01/09,
8401100141

8401100213 Forwards NRC 840103 response to util 830610 mgt organization
proposal & any subsequent changes as of 831128 Comments by
interested parties will be received until COB 840125
CLEMENS, W. L. Docketing & Services Branch 84/01/09 Atomic
Safety and Licensing Board Panel 1p 21774 233 24X
Fiche 50-289, 84/01/09, 8401100213

--8401100217 Submits NRC response to util 830610 mgt organization
proposal & any subsequent changes as of 831128 Parties
should be given opportunity to comment & express addl views
to Commission
DIRKS, W. J. Office of the Executive Director for Operations
84/01/03 PALLADINO, N. J., GILINSKY, V., ROBERTS, T. M.
Commissioners 8pp 21774 234 24X Fiche 50-289, 84/01/03,
8401100217

8401100232 Forwards util 831206 memo revising & superseding previous
allocation of responsibilities within ofc of president Svc
list encl
BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge BLAKE, E. L.
Metropolitan Edison Co 84/01/09 EDLES, G. J., BUCK, J. H., KOHL, C. N.
Atomic Safety and Licensing Appeal Panel 6pp 21780 298 24X
Fiche 50-289, 84/01/09, 8401100232

8401100305 Ack receipt of 831214 ltr re restart Osbakken ltr &
Gilinsky response will be served on all parties per
Commission rules
GILINSKY, V. Commissioners 84/01/09 OSBAKKEN, M. Milton S
Hershey Medical Center, Hershey, PA 1p 21772 272 24X
Fiche 50-289, 84/01/09, 8401100305

DOCKETED ITEMS

103

--B40110309 Opines that NRC recommendation to restart Unit 1 premature in light of unanswered questions re competency, integrity & safety issues Further decision re restart should be delayed until issues resolved
OSBAKKEN, M Milton S Hershey Medical Center, Hershey, PA 83/12/14 QILINSKY, V Commissioners 1p 21772 273 24X Fiche 50-289, 84/01/09, 840110305

B40110264 Motion to dismiss TMI Alert, Inc (TMIA) Contentions 1 a, 1 b, 1 c & 2 b 1 re post-repair & plant performance testing & use of sulfur compounds in sys TMIA failed to provide bases for contentions
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 84/01/09 Atomic Safety and Licensing Board Panel 11pp 21792 328 24X Fiche 50-289, 84/01/09, 840110264

--B40110269 Motion to compel discovery on licensee first set of interrogatories & request for production of documents to TMI Alert, Inc re listed contentions
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 84/01/09 Atomic Safety and Licensing Board Panel 7pp 21792 339 24X Fiche 50-289, 84/01/09, 840110264

--B401102882 Motion to compel discovery on licensee first set of interrogatories & request for production of documents to Joint Intervenor's Notice of appearance for W Washington & Certificate of Bvc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 84/01/09 Atomic Safety and Licensing Board Panel 5pp 21792 346 24X Fiche 50-289, 84/01/09, 840110264

B401250107 Informs that NRC will take no position re licensee B40109 motions to compel discovery on licensee first set of interrogatories & request for production of documents to TMI Alert & Joint Intervenor's
RAMBON, R J Hearing Branch 4 84/01/11 WOLFE, S J, HETRICK, D L, LAMB, J C Atomic Safety and Licensing Board Panel 1p 21936 223 24X Fiche 50-289, 84/01/11, 8401250107

B401160256 Forwards util B40103 ltr which transmitted Suppl 2 to rept of third-party review of steam generator repair program Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Troubridge CHURCHILL, B W Metropolitan Edison Co 84/01/12 WOLFE, S J, HETRICK, D L, LAMB, J C Atomic Safety and Licensing Board Panel 11pp 21814 097 24X Fiche 50-289, 84/01/12, 8401160256

B401170231 Second set of interrogatories & request for production of documents, per ASLB 831129 memorandum & order Certificate of Bvc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 84/01/12 Three Mile Island Alert 21pp 21831 239 24X Fiche 50-289, 84/01/12, 8401170231

B401180238 Informs of misimpression incorporated in footnote on Page 4 of WJ Dircks response to util B30610 mgt organization proposal Capacity factor of 35% for 100 consecutive hours not backed by force of law & can be changed by agreement
LEWIS, M I Lewis, M 84/01/12 FALLADINO Commissioners 1p 21844 098 24X Fiche 50-289, 84/01/12, 8401180238

B401170253 Forwards responses to TMI Alert 831230 discovery request Proprietary info cannot be produced until protective order signed
CHURCHILL, B W Shaw, Pittman, Potts & Troubridge CHURCHILL, B W Metropolitan Edison Co 84/01/13 DOROSHOW, J, BRADFORD, L Three Mile Island Alert 1p 21830 243 24X Fiche 50-289, 84/01/13, 8401170253

--B401170255 Answer to first set of interrogatories & request for production of documents re steam generator repair, Certificate of Bvc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Troubridge 84/01/13 Three Mile Island Alert 105pp 21830 244 24X Fiche 50-289, 84/01/13, 8401170255

B401170261 Memorandum memorializing B40112 telcon w/NRC, licensees, Joint Intervenor's & TMI Alert Board will hear & rule upon licensee B30109 motions to compel discovery
WOLFE, S J Atomic Safety and Licensing Board Panel 84/01/13 6pp 21831 169 24X Fiche 50-289, 84/01/13, 8401170261

B401250098 Informs that based on Commission B40110 meeting & vote re steam generator repair license amend, no NRC action will be taken to issue final NSHC determination or amend until Commission decision reached
RAMBON, R J Hearing Branch 4 84/01/13 WOLFE, S J, LAMB, J C, HETRICK, D L Atomic Safety and Licensing Board Panel 1p 21939 025 24X Fiche 50-289, 84/01/13, 8401250098

B401170311 First set of interrogatories & request for production of documents re steam generator repair Certificate of Bvc encl
BRADFORD, L, DOROSHOW, J Three Mile Island Alert 84/01/16 Office of the Executive Legal Director 42pp 21833 241 24X Fiche 50-289, 84/01/16, 8401170311

B401180243 Provides clarification re Commission decision that 831219 meeting entitled "Discussion of GPU Proposal," be closed to public under Exemption 10 of Sunshine Act Meeting will be renoticed & retitled UCS 831214 request denied
CHILK, S J Office of the Secretary of the Commission 84/01/16 WEISS, E R Harmon & Weiss 2pp 21844 128 24X Fiche 50-289, 84/01/16, 8401180243

B401190174 Response to first set of interrogatories re steam generator repair Certificate of Bvc encl
BRADFORD, L Three Mile Island Alert 84/01/16 Office of the Executive Legal Director 17pp 21851 270 24X Fiche 50-289, 84/01/16, 8401190174

B401190336 Response to 831223 interrogatories re steam generator tube repairs
LEE, J, AAMODT, N O Aamodts 84/01/16 Office of the Executive Legal Director 2pp 21850 162 24X Fiche 50-289, 84/01/16, 8401190336

--B401190337 Responses to first set of interrogatories
LEE, J, AAMODT, N O Aamodts 84/01/16 Metropolitan Edison Co 5pp 21850 164 24X Fiche 50-289, 84/01/16, 8401190336

--B401190342 Interrogatories to NRC re steam generator repair (Set 1)
LEE, J, AAMODT, N O Aamodts 84/01/16 Office of the Executive Legal Director 4pp 21850 169 24X Fiche 50-289, 84/01/16, 8401190342

--B401190344 Interrogatories re steam generator repair (Set 1) Certificate of Bvc encl
LEE, J, AAMODT, N O Aamodts 84/01/16 Metropolitan Edison Co 6pp 21850 173 24X Fiche 50-289, 84/01/16, 8401190344

B401200156 Confirms telcons re licensee response to request for production of documents Documents will be available for insp in Middletown, PA Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Troubridge CHURCHILL, B W Metropolitan Edison Co 84/01/17 DOROSHOW, J Three Mile Island Alert 2pp 21865 361 24X Fiche 50-289, 84/01/17, 8401200156

B401240167 Notice of transmittal of licensee Rept NAD-83-01, "Lessons Learned Workshop"
BLAKE, E L Metropolitan Edison Co 84/01/19 134pp 21910 333 24X Fiche 50-289, 84/01/19, 8401240167

B401260116 Forwards study re cracking of nickel base austenitic alloys referenced in B40116 response to interrogatories re steam generator repairs
AAMODT, N O Joint Petitioners - TMI AAMODT, N O Aamodts 84/01/19 Atomic Safety and Licensing Board Panel 13pp 21957 027 24X Fiche 50-289, 84/01/19, 8401260116

B401230427 Forwards list of integrity issues in restart proceeding, per Commission request Parties may submit comments on issues within 20 days
CHILK, S J Office of the Secretary of the Commission 84/01/20 Office of the Executive Legal Director 12pp 21882 088 24X Fiche 50-289, 84/01/20, 8401230427

B401240213 Response to util motion to dismiss Contentions 1a, 1b, 1c & 2b1 and supplemental interrogatory responses to util Insufficient info re steam generator repair provided util position obviously untenable Certificate of Bvc encl
DOROSHOW, J Three Mile Island Alert 84/01/20 Atomic Safety and Licensing Board Panel 11pp 21908 265 24X Fiche 50-289, 84/01/20, 8401240213

B401240224 Petition for order to show cause re emergency feedwater sys OL should be suspended unless & until facility emergency feedwater sys complies w/NRC rules applicable to sys important to safety
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 84/01/20 Commissioners 31pp 21910 184 24X Fiche 50-289, 84/01/20, 8401240224

--B401240230 Rebuttal to licensee B31206 reply re emergency feedwater sys (EFW) flow instrumentation Commission urged to reject util attempt to circumvent short-term lessons learned requirements for EFW flow instrumentation
WEISS, E R, POLLARD, R D Union of Concerned Scientists WEISS, E R Harmon & Weiss 84/01/20 Commissioners 13pp 21910 215 24X Fiche 50-289, 84/01/20, 8401240230

DOCKETED ITEMS

- 8401240239 Affidavit of RD Pollard re emergency feedwater sys flow instrumentation Design does not comply w/NRC rules Operation would pose undue risk to health & safety of public Certificate of Svc encl
POLLARD, R D Union of Concerned Scientists 84/01/20 14pp
21910 234 24X Fiche 50-289, 84/01/20, 8401240224
- 8401240311 Order extending time until 840127 for Commission to act to review ALAB-729 & ALAB-744
CHILK, S J Office of the Secretary of the Commission 84/01/20
Commissioners 1p 21908 362 24X Fiche 50-289, 84/01/20, 8401240311
- 8401250189 Discusses status of licensee compliance w/ASLB imposed license conditions resulting from mgt & cheating proceeding issues Auditing & training criteria requirements satisfied
GOLDBERG, J R Hearing Branch 2 84/01/20 EDLES, Q J, KOHL, C N, BUCK, J H Atomic Safety and Licensing Appeal Panel 2pp
21937 106 24X Fiche 50-289, 84/01/20, 8401250189
- 8401260208 Motion for reopening of record to examine alleged leak rate falsification Falsification of leak rates & rept of false calculations to NRC involved elaborate sys of cheating
AAMODT, N D, AAMODT, M M Aamodts 84/01/23 Atomic Safety and Licensing Appeal Panel 9pp 21956 211 24X Fiche 50-289, 84/01/23, 8401260208
- 8401260214 Suppl to 840107 comments re NRC proposal for startup of Unit 1 at 25% power Issue of restart appears to have devolved from adjudication of adequacy to finding way to renew license Notes supporting findings encl
AAMODT, N D, AAMODT, M M Aamodts 84/01/24 Commissioners 7pp 21956 220 24X Fiche 50-289, 84/01/23, 8401260208
- 8401260222 Forwards NRC 801201 ltr transmitting comments on util operator qualification program Ltr referenced by ASLB in 820727 decision Certificate of Svc encl
AAMODT, M M Aamodts 84/01/16 EDLES, KOHL, BUCK Atomic Safety and Licensing Appeal Panel 5pp 21956 229 24X
Fiche 50-289, 84/01/23, 8401260208
- 8401300322 Forwards NRC, FEMA & Food Safety & Insp Svc correspondence in response to J Fisher ltr re Farmer emergency info pamphlet (Restart Certification Item 149) Corrective action on farmer evacuation plan requested
LEE, J Affiliation Unknown 84/01/23 PALLADINO, GILINSKY, ASSELBTINE Commissioners 7pp 21996 300 24X
Fiche 50-289, 84/01/23, 8401300322
- 8401260124 Motion for leave to file third set of interrogatories & request for production of documents to TMI Alert out of time Licensee should not be denied discovery due to Alert failure to provide relevant info W/Certificate of Svc
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 81/01/24 Atomic Safety and Licensing Board Panel 5pp 21957 058 24X Fiche 50-289, 84/01/24 8401260124
- 8401260190 Third set of interrogatories & request for production of documents Certificate of Svc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 84/01/24 Three Mile Island Alert 1pp 21956 183 24X Fiche 50-289, 84/01/24, 8401260190
- 8401260202 Motion for leave to file second set of interrogatories to Joint Intervenor out of time Motion necessary due to intervenor failure to file response to first set of interrogatories until 840116
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 84/01/24 Atomic Safety and Licensing Board Panel 2pp 21956 191 24X Fiche 50-289, 84/01/24, 8401260202
- 8401260207 Second set of interrogatories re Contention 11-1 concerning steam generator repair Certificate of Svc encl
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 84/01/24 Aamodts 18pp
21956 193 24X Fiche 50-289, 84/01/24, 8401260202
- 8401270212 Forwards 840124 ltr from D Thornburgh, Governor, Commonwealth of PA re comments on NRC rept on GPU mgt proposal
BLAZEY, D R Pennsylvania, Commonwealth of, 84/01/24 1p
21982 127 24X Fiche 50-289, 84/01/24, 8401270212
- 8401270217 Reiterates views that questions of mgt competence & integrity should be resolved prior to restart NRC should reject any proposal to separate competence & integrity issues from restart Certificate of Svc encl
THORNBERG, D Pennsylvania, Commonwealth of, 84/01/24 PALLADINO, N J Commissioners 6pp 21982 128 24X
Fiche 50-289, 84/01/24, 8401270212
- 8401260164 Comments on NRC 840103 response to GPU 830610 mgt proposal Staff fails to accept two basic propositions that corporate integrity required for NRC license & continuing pattern of lapses constitute ground for disqualification
WEISS, E R Union of Concerned Scientists 84/01/25
Commissioners 21pp 21956 039 24X Fiche 50-289, 84/01/25, 8401260164
- 8401260231 Forwards comments on NRC response to licensee mgt proposal for restart, in response to NRC 840107 ltr Early completion of Ofc of Investigation evaluation of leak rate procedure urged Certificate of Svc encl
DAUSER, D B Shaw, Pittman, Potts & Trowbridge DAUSER, D B General
Public Utilities - GPU Service Corp 84/01/25 CLEMENTS, W L
Docketing & Services Branch, 16pp 21956 265 24X
Fiche 50-289, 84/01/25, 8401260231
- 8401270288 Motion for appointment of special panel made up of expert representatives from four parties in proceeding ASLB should consider motion carefully & expeditiously
DOROSHOW, J Three Mile Island Alert 84/01/25 Atomic Safety and Licensing Board Panel 5pp 21976 013 24X Fiche 50-289, 84/01/25, 8401270288
- 8401270309 Motion for order to compel licensee to produce & disclose requested documents re steam generator repair w/o restrictions of protective order No good cause demonstrated to limit discovery
DOROSHOW, J Three Mile Island Alert 84/01/25 Atomic Safety and Licensing Board Panel 4pp 21975 356 24X Fiche 50-289, 84/01/25, 8401270309
- 8401270369 Motion for extension of time for filing response to licensee second set of interrogatories, for filing second set of interrogatories to licensee & for filing motions to compel Amount of matl to be reviewed enormous
DOROSHOW, J Three Mile Island Alert 84/01/25 Atomic Safety and Licensing Board Panel 3pp 21976 158 24X Fiche 50-289, 84/01/25, 8401270369
- 8401300256 Informs of allegation by licensee employee that JD Burg of Stress Control, Inc lacked requisite academic & license qualifications to perform psychological evaluations of employees Investigation continuing Svc list encl
DAUSER, D B Shaw, Pittman, Potts & Trowbridge DAUSER, D B General
Public Utilities - GPU Service Corp 84/01/25 EDLES, D J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 4pp
21998 316 24X Fiche 50-289, 84/01/25, 8401300256
- 8401270209 Response supporting UCS 840125 response to NRC response to GPU mgt proposal TMI Alert strenuously objects to 840127 meetings re restart issues Parties should have opportunity to address Commission Certificate of Svc encl
DOROSHOW, J Three Mile Island Alert 84/01/26 Commissioners 3pp 21982 118 24X Fiche 50-289, 84/01/26, 8401270209
- 8401300240 Informs of typographical error contained in 840125 ltr Cover ltr should state that licensee proposes temporary limit in range of 40-48% of full power Certificate of Svc encl
DAUSER, D B Shaw, Pittman, Potts & Trowbridge DAUSER, D B
Metropolitan Edison Co 84/01/26 CLEMENTS, W L Docketing & Services Branch 4pp 22062 092 24X Fiche 50-289, 84/01/26, 8401300240
- 8401310258 Forwards documents referenced in licensee answers to TMI Alert first set of interrogatories & request for production of documents which, at time of filing, were determined to contain proprietary info W/o encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Metropolitan Edison Co 84/01/26 DOROSHOW, J Three Mile Island Alert 2pp 22026 256 24X Fiche 50-289, 84/01/26, 8401310258
- 8401310218 Reply to TMI Alert (TMIA) response to licensee motion to dismiss TMIA Contentions 1 a, 1 b, 1 c & 2 b 1 ASLB should dismiss contentions because TMIA unable to provide basis for contention W/Certificate of Svc
CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 84/01/27 Atomic Safety and Licensing Board Panel 7pp 22021 324 24X Fiche 50-289, 84/01/27, 8401310218
- 8401310226 Submits tentative Commission views & plan for resolution of mgt integrity issues prior to restart Addl views of Chairman Palladino & Commissioners Bernthal, Gilinsky & Asselstine encl
CHILK, S J Office of the Secretary of the Commission 84/01/27
Office of the Executive Legal Director 19pp 22021 208 24X
Fiche 50-289, 84/01/27, 8401310226

DOCKETED ITEMS

105

8401310283 Informs that B Mehler replaced W Zewu as radwaste operations manager N Hennissey replaced D Dyckman as shift maint Foreman Resumes & documentation re mgt practices encl BAUSER, D B Shaw, Pittman, Potts & Trowbridge BAUSER, D B General Public Utilities - GPU Service Corp 84/01/27 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Board Panel 27pp 22017 325 24X Fiche 50-289, 84/01/27, 8401310283

8401310329 Objections to TMI Alert production of documents Request 22 Certificate of Svc encl CHURCHILL, B W Metropolitan Edison Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 84/01/27 Three Mile Island Alert 3pp 22019 357 24X Fiche 50-289, 84/01/27, 8401310329

H General correspondence

8401120241 Forwards EDO 840103 memo memorializing views set forth in NRC 831205 oral presentation & explaining how NRC arrived at current position re util 830610 mgt reorganization proposal WAGNER, M E Hearing Branch 4 84/01/05 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Board Panel 9pp 21793 321 24X Fiche 50-289, 84/01/05, 8401120241

840110232 Forwards util 831206 memo revising & superseding previous allocation of responsibilities within ofc of president Svc list encl BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 84/01/09 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 6pp 21780 298 24X Fiche 50-289, 84/01/09, 840110232

8401180202 Expresses concern re Commission comments during 831207 briefing/possible vote on TMI steam generators Comments reveal culpability of Chairman Palladino & Commissioner Roberts LEE, J Affiliation Unknown 84/01/12 PALLADINO, N J, QILINSKY, V, ASSELSTINE, J K Commissioners 4pp 21842 355 24X Fiche 50-289, 84/01/12, 8401180202

840130007B Requests removal of EQ Wallace from future correspondence & svc copy lists for TMI Program Ofc generated documents WETHORE, J S General Public Utilities - GPU Service Corp 84/01/12 BARRETT, L H TMI Program Office 1p 21999 166 24X Fiche 50-289, 84/01/12, 840130007B

8401310257 Requests action to prevent facility restart LONGENECKER, D Affiliation Unknown 84/01/26 BNYDER, B J TMI Program Office 2pp 22020 340 24X Fiche 50-289, 84/01/26, 8401310257

8401310349 Ack telcons w/Harrisburg, PA residents R Fritchley, K Entr & F Taylor expressing opposition to restart DAVIS, P Commissioners 84/01/27 Commissioners 1p 22018:362 24X Fiche 50-289, 84/01/27, 8401310349

J Insurance & indemnity information

8401030198 Forwards Endorsements 67, 68 & 69 to NELIA Policy NF-220 & Endorsements 98 & 99 to MAELU Policy MF-73 W/a Endorsement 67 GERETY, H F General Public Utilities - GPU Service Corp 83/12/14 SALTZMAN, J Office of Nuclear Reactor Regulation, Director 6pp 21683 083 24X Fiche 50-289, 83/12/14, 8401030198

8401260005 Forwards Endorsement 3 to NELIA Binders N-56 & N-65 GERETY, H F General Public Utilities - GPU Service Corp 84/01/16 SALTZMAN, J Office of Nuclear Reactor Regulation, Director 3pp 21956 345 24X Fiche 50-289, 84/01/16, 8401260005

8401300308 Forwards Endorsement 70 to NELIA Policy NF-220 & Endorsement 60 to MAELU Policy MF-73 GERETY, H F General Public Utilities - GPU Service Corp, 84/01/24 SALTZMAN, J F Office of Nuclear Reactor Regulation, Director 3pp 21996 338, 24X Fiche 50-289, 84/01/24, 8401300308

P Operating license stage documents & correspondence

8401090580 Further response to FOIA request for four categories of documents re facility restart Listed documents available in PDR FELTON, J M Division of Rules and Records 83/10/04 ADATO, M Union of Concerned Scientists 1p 21766 125 24X Fiche 50-289, 83/10/04, 8401090580

8401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies Supporting ltrs encl CALBOYAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given, 4pp 21736 232 24X Fiche 50-000, 83/10/10, 8401050027

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000, 83/10/18, 8401250015

--8203180400 Informs of status of staff action & plans re environ assessment of psychological stress in restart staffing plan Major milestones & resource requirements & draft workshop rept encl DIRCKS, W J Office of the Executive Director for Operations SECY-82-092 82/03/02 102pp 21961 178 24X Fiche 50-000, 83/10/18, 8401250015

--8205050087 Forwards final rept, "Summary Rept-Workshop on Psychological Stress Associated w/Proposed Restart of TMI-1," NUREG/CP-0026 DIRCKS, W J Office of the Executive Director for Operations SECY-82-092A 82/04/14 151pp 21961 287 24X Fiche 50-000, 83/10/18, 8401250015

--8206110014 Informs of status of util ability to provide addl senior reactor operator on shift by 820701 per requirements of TMI Item 1 A 1 3, "Shift Manning Requirements" DIRCKS, W J Office of the Executive Director for Operations SECY-82-219 82/06/01 6pp 21964 235 24X Fiche 50-000, 83/10/18, 8401250015

--8206300059 Informs of NRC plan for certifying completion of TMI-1 restart requirements, in response to 820316 memo DIRCKS, W J Office of the Executive Director for Operations SECY-82-290 82/06/16 16pp 21964 278 24X Fiche 50-000, 83/10/18, 8401250015

--8209200347 Informs of current status of NRC efforts re psychological stress associated w/TMI restart Natl Inst of Mental Health is reviewing proposed psychological survey DIRCKS, W J Office of the Executive Director for Operations SECY-82-346 82/08/19 2pp 21966 030 24X Fiche 50-000, 83/10/18, 8401250015

--8301070155 Informs Commission of status of psychological stress survey proposal to predict stress resulting from restart of TMI-1 & reanalyses of three studies of psychological stress caused by accident & aftermath at TMI-2 DIRCKS, W J Office of the Executive Director for Operations SECY-82-500 82/12/27 6pp 21967 216 24X Fiche 50-000, 83/10/18, 8401250015

--8301070163 Informs Commission of status of nonhearing issues on TMI-1 re auxiliary feedwater header problem & make-up nozzle cracking problem at B&W plants & steam generator tube problem at plant DIRCKS, W J Office of the Executive Director for Operations SECY-82-502 82/12/29 3pp 21967 222 24X Fiche 50-000, 83/10/18, 8401250015

--8401250106 Forwards petition for Supreme Court review of Pane psychological stress issue in TMI-1 restart case filed by solicitor general MALSCH, M G Office of the General Counsel SECY-82-016E 82/09/02 20pp 21960 016 24X Fiche 50-000, 83/10/18, 8401250015

--8401250311 Informs of status of staff effort re psychological stress associated w/TMI-1 restart DIRCKS, W J Office of the Executive Director for Operations SECY-82-346A 82/09/13 2pp 21966 032 24X Fiche 50-000, 83/10/18, 8401250015

8401170026 Final response to FOIA request for rept re mgt integrity issues for TMI-1 restart, SECY-83-167 & SECY-83-198 Rept & SECY-83-167 addressed in 830916 ltr SECY-83-198 entirely withheld (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records 83/10/20 RYAN, M L McGraw-Hill Publications Co 1p 21837 362 24X Fiche 50-289, 83/10/20, 8401170026

8401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies, NRC has no records subj to request Utilis not required to submit insurance rating to NRC FELTON, J M Division of Rules and Records 83/10/25 CALBOYAS, C D Affiliation Unknown 1p 21736 236 24X Fiche 50-000, 83/10/25, 8401050043

8401230052 Final response to FOIA request for four categories of documents Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/11/01 ADATO, M Union of Concerned Scientists 2pp 21930 271 24X Fiche 50-289, 83/11/01, 8401230052

DOCKETED ITEMS

- B401230061 Advises of NRC approval of recommendations to defer implementation date of NUREG-0737, Items II B 3, II F 1 4, II F 1 5 & II F 1 6 until 830331 or before restart Approval of Item II B 2 2 date withheld until review completed
CHILK, S J Office of the Secretary of the Commission 82/10/19
DIRCKS, W J Office of the Executive Director for Operations 1p
21930 274 24X Fiche 50-289, 83/11/01, B401230052
- B401230067 Advises that Commission approved recommendation to defer final implementation date for NUREG-0737, Item II B 2 2 until first refueling outage following restart
CHILK, S J Office of the Secretary of the Commission 83/01/05
DIRCKS, W J Office of the Executive Director for Operations 1p
21930 275 24X Fiche 50-289, 83/11/01, B401230052
- B401230070 Recommends deferral of NUREG-0737, Item II B 2 2, "Plant Shielding Mods," implementation to first refueling outage following restart
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-384A 82/12/06 4pp 21930 276 24X
Fiche 50-289, 83/11/01, B401230052
- B401230079 Informs of status of facility restart certification effort & provides update on noncertification item status
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-340 83/08/16 42pp 21930 280 24X
Fiche 50-289, 83/11/01, B401230052
- B401230001 Further response to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests App A info partially withheld (ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 83/11/07 VOIGT, H H
LeBoeuf, Lamb, Leiby & MacRae 3pp 21930 322 24X
Fiche 50-289, 83/11/07, B401230001
- B401230030 Discusses propriety of NRC civil investigation into Hartman allegation concurrent w/DOJ criminal investigation of same
Noncensored version
CUMMINGS, J J Office of Inspector & Auditor 83/05/31
JENSEN, D L Justice, Dept of 3pp 21930 343 24X
Fiche 50-289, 83/11/07, B401230001
- B401040517 Forwards addl clarification to 830209 & 1123 responses to NUREG-0737, Item II B 3 re emergency power & post-accident chloride analysis Autosampler expected to be available at site by Apr 1984
HUKILL, H D General Public Utilities - GPU Service Corp 83/12/28
STOLZ, J F Operating Reactors Branch 4 2pp 21707 295 24X
Fiche 50-289, 83/12/28, B401040517
- B401090708 Discusses review of submittal re control room habitability raised in NUREG 0737, Item III D 3 4 Two concerns raised inadequately addressed as indicated in Reg Guides 1 78 & 1 95 & SRP 6 4 W/o evaluation rept
STOLZ, J F Operating Reactors Branch 4 83/12/28 HUKILL, H D
General Public Utilities - GPU Service Corp 2pp 21757 334 24X
Fiche 50-289, 83/12/28, B401090708
- B401040415 Forwards "Abnormal Transient Operating Guidelines" per TMI Item I C 1 Finalized procedure generation package to be provided by B40131 Revised emergency operating procedure will be in effect for use by operators in Jan 1984
HUKILL, H D General Public Utilities - GPU Service Corp 83/12/29
STOLZ, J F Operating Reactors Branch 4 3pp 21706 064 24X
Fiche 50-289, 83/12/29, B401040415
- B401040417 "Abnormal Transient Operating Guidelines"
* General Public Utilities - GPU Service Corp 83/12/29 73pp
21706 067 24X Fiche 50-289, 83/12/29, B401040415
- B401050276 Confirms that scheduled submittal of design details for reactor coolant inventory trending sys. per TMI Action Item II F 2 will be provided in Jan 1984, per 831228 discussion w/ J V Vliet
HUKILL, H D General Public Utilities - GPU Service Corp 83/12/29
STOLZ, J F Operating Reactors Branch 4 1p 21727 240 24X
Fiche 50-289, 83/12/29, B401050276
- B401060333 Discusses natural circulation cooldown analysis, per Generic Ltr 81-21, using HEATING-5 code Code provides multi-dimensional capability to model vessel more accurately
HUKILL, H D General Public Utilities - GPU Service Corp 83/12/30
STOLZ, J F Operating Reactors Branch 4 1p 21740 158 24X
Fiche 50-289, 83/12/30, B401060333
- B401090312 Forwards Suppl 2 to "Third-Party Review of TMI-1 Steam Generator Repair" Suppl documents changes between Revs 2 & 3 of Topical Rept OOE EJ Wagner 831203 ltr encl
HUKILL, H D General Public Utilities - GPU Service Corp 84/01/03
STOLZ, J F Operating Reactors Branch 4 2pp 21754 192 24X
Fiche 50-289, 84/01/03, B401090312
- B401090315 Suppl 2 to "Third-Party Review of TMI-1 Steam Generator Repair" JS Wetmore 830822 & 0909 ltrs encl
BROWN, S D, HOLLAND, S A, KALINSKY, V, ROBERTS, T Cincinnati Gas & Electric Co 83/12/03 7pp 21754 194 24X Fiche 50-289, 84/01/03, B401090312
- B401130474 Submits NRC response to GPU 830610 mgt organization proposal & changes to proposal as of 831128 Proposal viable alternative to waiting for completion of ongoing OFC of Investigations inquiry
DIRCKS, W J Office of the Executive Director for Operations
84/01/03 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 19pp 21817 336 24X Fiche 50-289, 84/01/03, B401130474
- 8312120108 Board Notification B4-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J
Commissioners 2pp 21973 324 24X Fiche 50-000, 84/01/05, 8312120108
- B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382
- B401100137 Forwards util 831222 ltr to Region I re Kr-B5 leakage paths Svc list encl
ZAHLER, R E Shaw, Pittman, Potts & Trowbridge ZAHLER, R E
Metropolitan Edison Co 84/01/05 CHILK, S J Office of the Secretary of the Commission 9pp 21760 001 24X
Fiche 50-289, 84/01/05, B401100137
- B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221
- B401230544 Forwards Rev O to Parts I & II of "TMI-1 Abnormal Transient Operating Guidelines"
VAN VLIET, J A Operating Reactors Branch 4 84/01/09 STOLZ, J F
Operating Reactors Branch 4 1p 21921 138 24X
Fiche 50-289, 84/01/09, B401230544
- B401230547 Rev O to Parts I & II of "TMI-1 Abnormal Transient Operating Guidelines"
DROCKS, G L Dabcock & Wilcox Co 83/04/24 662pp 21921 139
24X Fiche 50-289, 84/01/09, B401230544
- B401170174 Submits response to 831216 telcon requesting info re Senator Specter question on total number of GPU employees now applied to TMI-1, who were Met Ed employees, having any involvement w/operation of TMI-2 prior to Mar 1979
CLARK, P R General Public Utilities - GPU Service Corp 84/01/11
BENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21834 139 24X Fiche 50-289, 84/01/11, B401170174
- B401160256 Forwards util 840103 ltr which transmitted Suppl 2 to rept of third-party review of steam generator repair program Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W
Metropolitan Edison Co 84/01/12 WOLFE, S J, HETRICK, D L, LAMB, J C Atomic Safety and Licensing Board Panel 11pp 21814 097 24X Fiche 50-289, 84/01/12, B401160256
- B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084
- B401240251 Updates 831201 restart readiness schedule, reflecting results of 840112 mgt review meeting Plant ready for final heatup Completion of prerequisites to going critical should occur by end of Jan 1984 Master restart schedule encl
HUKILL, H D General Public Utilities - GPU Service Corp 84/01/16
STOLZ, J F Operating Reactors Branch 4 2pp 21908 246 24X
Fiche 50-289, 84/01/16, B401240251
- B401300116 Staff requirements memo re B40110 discussion/possible vote on TMI steam generators License amend will not be issued until Commission votes on NSHC question
CHILK, S J Office of the Secretary of the Commission 84/01/16
DIRCKS, W J Office of the Executive Director for Operations 1p 22006 162 24X Fiche 50-289, 84/01/16, B401300116

DOCKETED ITEMS

107

B401240169 Notice of transmittal of licensee Rept NAD-83-01, "Lessons Learned Workshop"
BLAKE, E L Metropolitan Edison Co B4/01/19 134pp 21910 333
24X Fiche 50-289, 84/01/19, 8401240169

B401270190 Forwards Rev 1 to Procedure 1210-5, "Once-Through Steam Generator Tube Leak/Rupture"
HUKILL, H D General Public Utilities - GPU Service Corp B4/01/19
STOLZ, J F Operating Reactors Branch 4 1p 21982 073 24X
Fiche 50-289, 84/01/19, 8401270190

--B401270192 Rev 1 to Procedure 1210-5, "Once-Through Steam Generator Tube Leak/Rupture"
COLITZ, J J, TODLE, R General Public Utilities - GPU Service Corp
B3/12/28 12pp 21982 073 24X Fiche 50-289, 84/01/19,
8401270190

B401310522 Forwards safety evaluation & technical evaluation rept of electrical distribution sys voltage test data in 830930 ltr
Test results verify analysis evaluated by safety evaluation supporting Amend 70 to OL Issue resolved
STOLZ, J F Operating Reactors Branch 4 B4/01/19 HUKILL, H D
General Public Utilities - GPU Service Corp 5pp 22042 328 24X
Fiche 50-289, 84/01/19, 8401310522

--B401310524 "Adequacy of Station Electric Distribution Sys Voltages, TH1 Unit 1," technical evaluation rept
UDY, A C E&O, Inc FIN A-6429 E00-EA-6453 B3/12/31
DONOHEW, J Division of Licensing EMAMF, J Division of Systems
Integration (Post 811005) 16pp 22042 333 24X
Fiche 50-289, 84/01/19, 8401310522

B401310141 Forwards abnormal transient operating guidelines procedures generation package, in response to Generic Ltr 82-33 Package
includes addl info requested by NRC at 840106 meeting re implementation of NUREG-0737, Item 1 C 1
HUKILL, H D General Public Utilities - GPU Service Corp B4/01/26
STOLZ, J F Operating Reactors Branch 4 3pp 22022 129 24X
Fiche 50-289, 84/01/26, 8401310141

--B401310145 Abnormal transient operating guidelines procedures generation package
BROUGHTON, J G General Public Utilities - GPU Service Corp
B4/01/20 439pp 22022 132 24X Fiche 50-289, 84/01/26,
8401310141

B401310283 Informs that B Mehler replaced W Zewe as radwaste operations manager N Harnissey replaced D Dyckman as shift maint
foreman Resumes & documentation re mgt practices encl
BAUSER, D B Shaw, Pittman, Potts & Trowbridge BAUSER, D B General
Public Utilities - GPU Service Corp B4/01/27 EDLEB, G J,
BUCK, J H, KOHL, C N Atomic Safety and Licensing Board Panel 27pp
22017 325 24X Fiche 50-289, 84/01/27, 8401310283

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
B3/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

B401030234 Forwards IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 & notice of violation
MURLEY, T E Region 1, Office of Director B3/12/14 CLARK, P R
General Public Utilities - GPU Service Corp 3pp 21682 279 24X
Fiche 50-289, 83/12/14, 8401030234

--B401030237 Notice of violation from insp on 830911
MURLEY, T E Region 1, Office of Director B3/12/14 1p
21682 282 24X Fiche 50-289, 83/12/14, 8401030234

--B401030241 IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 Violation noted drafts containing safeguards info left unattended on desk in unlocked security storage container
MURLEY, T E, GODY, A T Region 1, Office of Director B3/12/14
2pp, 21682 283 24X Fiche 50-289, 83/12/14, 8401030234

B401030255 Forwards IE Insp Rept 50-289/83-31 on 831103-04 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B3/12/14
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21681 164 24X Fiche 50-289, 83/12/14, 8401030255

--B401030256 IE Insp Rept 50-289/83-31 on 831103-04 No noncompliance noted Major areas inspected public prompt notification sys
COHEN, I, HAWKHURST, J, CROCKER, H W Region 1, Office of Director
B3/12/12 5pp 21681 166 24X Fiche 50-289, 83/12/14, 8401030255

B401040382 Forwards rept cover & summary page of supplemental IE Investigation Rept I-83-003 on 830713-080? No violations noted Investigation covered alleged compromise of preemployment psychological exam
STAROSTECKI, R Division of Project & Resident Programs B3/12/23
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21706 242 24X Fiche 50-289, 83/12/23, 8401040382

B401100267 Forwards IE Enforcement Conference Rept 50-289/83-33 on 831108
STAROSTECKI, R Division of Project & Resident Programs B3/12/23
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21759 211 24X Fiche 50-289, 83/12/23, 8401100267

--B401100272 IE Enforcement Conference Rept 50-289/83-33 on 831108 No noncompliance noted Major areas discussed findings of IE Insp Repts 50-289/83-25 & 50-289/83-26 re procedure nonadherence
CONTE, R, CONNER, E Region 1, Office of Director B3/12/05 4pp
21759 213 24X Fiche 50-289, 83/12/23, 8401100267

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc
12pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/12/30 Consolidated Edison Co of New York, Inc
12pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B401130323 Ack receipt of B31014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-18 & 50-320/83-10 Corrective actions re min number of fire brigade members at site acceptable
MARTIN, T T Division of Engineering & Technical Programs B4/01/05
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21801 328 24X Fiche 50-289, 84/01/05, 8401130323

B401240445 Forwards IE Insp Rept 50-289/83-35 on 831115-18 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B4/01/09
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21915 178 24X Fiche 50-289, 84/01/09, 8401240445

--B401240457 IE Insp Rept 50-289/83-35 on 831115-18 No violations noted Major areas inspected emergency preparedness & B31116 emergency exercise
TERC, N M, CROCKER, H W Division of Engineering & Technical Programs B3/12/22 8pp 21915 180 24X Fiche 50-289, 84/01/09,
8401240445

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/01/10 Consolidated Edison Co of New York, Inc
12pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/01/10 Consolidated Edison Co of New York, Inc
12pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

B401260367 Forwards IE Insp Rept 50-289/83-29 on 831017-21 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B4/01/17
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21955 229 24X Fiche 50-289, 84/01/13, 8401260367

--B401260369 IE Insp Rept 50-289/83-29 on 831017-21 No violations noted Major areas inspected licensed operator requalification program, general employee training & nonlicensed technical training
BIBBETT, P H, SHAUB, E T, CAPTON, D L Region 1, Office of Director B3/12/19 10pp 21955 231 24X Fiche 50-289, 84/01/13,
8401260367

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/01/16 Consolidated Edison Co of New York, Inc
12pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

DOCKETED ITEMS

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 11pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R Periodic operating reports & related correspondence

B401190372 Monthly operating rept for Dec 1983 W/B40113 ltr
SMYTH, C W, HUKILL, H D General Public Utilities - GPU Service Corp
B3/12/31 MACDONALD, W C NRC - No Detailed Affiliation Given
6pp 21850 125 24X Fiche 50-289, B3/12/31, B401190372

S Reportable occurrences, LERs & related correspondence

B401030258 LER B3-044/01T-1 on B31114, during walkdown, emergency feedwater automatic initiation redundant circuits discovered routed in same cable bundle. Caused by failure to include circuits in upgrade design W/B31209 ltr
SZCZECHEK, R A, HUKILL, H D General Public Utilities - GPU Service Corp B3/12/09 MURLEY, T E Region 1, Office of Director 4pp 21681 008 24X Fiche 50-289, B3/12/09, B401030258

B312300285 LER B3-042/99X-O on B31004, during shift walk through of battery room A, cell 27 found leaking Root cause unknown
Possible cause may be aging of matl used to make cells Job Ticket CC203 written to replace cells W/B31213 ltr
BYEPHENSON, C J, HUKILL, H D General Public Utilities - GPU Service Corp B3/12/13 MURLEY, T E Region 1, Office of Director 4pp 21671 276 24X Fiche 50-289, B3/12/13, B312300285

B401230478 LER B3-046/01T-D on B31214, nuclear safety-related circuit for makeup pump lube oil pressure trip switches MU-PIC found incorrectly routed. Caused by trip circuits not upgraded when modified W/B31229 ltr
SZCZECHEK, R A, HUKILL, H D General Public Utilities - GPU Service Corp B3/12/29 MURLEY, T E Region 1, Office of Director 4pp 21882 158 24X Fiche 50-289, B3/12/29, B401230478

T Hearing transcripts on non-antitrust matters

B401170138 Transcript of Commission B40110 meeting in Washington, DC re discussion/possible vote on TH1 steam generators Pp 1-15
* Commissioners B4/01/10 18pp 21838 342 24X
Fiche 50-289, B4/01/10, B401170138

B401130268 Transcript of B40111 oral argument in Bethesda, MD Pp 1-222
* Atomic Safety and Licensing Appeal Panel B4/01/11 222pp 21798 017, 24X Fiche 50-289, B4/01/11, B401130268

B401260496 Transcript of Commission B40116 meeting in Washington, DC re corrosion in PORVs at TH1-1 Pp 1-16 Viewgraphs encl
* Commissioners B4/01/16 220pp 21959 224 24X
Fiche 50-289, B4/01/16, B401260496

U Congressional/Executive Correspondence

B401230001 Further response to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests App A info partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records B3/11/07 VOIGT, H H LeDoux, Lamb, Leiby & MacRae 3pp 21930 322 24X
Fiche 50-289, B3/11/07, B401230001

--B401230011 Requests explanation of conflict between NJ Palladino B30325 testimony & DL Jensen B30517 ltr re NRC investigation into allegations that leak rate calculations at TH1-2 improperly conducted prior to accident
UDALL, M K House of Rep, Interior & Insular Affairs. B3/05/23 PALLADINO, N J Commissioners 1p 21930 333 24X
Fiche 50-289, B3/11/07, B401230001

--B401230024 Responds to B30523 request for explanation of conflict between NJ Palladino B30325 testimony & DL Jensen B30517 ltr re propriety of NRC investigation into allegations that leak rate calculations at TH1-2 improperly conducted.
PALLADINO, N J Commissioners B3/07/14 UDALL, M K House of Rep., Interior & Insular Affairs 3pp 21930 337 24X
Fiche 50-289, B3/11/07, B401230001

B401110327 Declines invitation to participate in restart hearing Meeting to be held on B40110 will evaluate alternatives for addressing mgt integrity, not reach decision re restart
PALLADINO, N J Commissioners B3/12/15 SPECTER, A Senate 2pp 21795 008 24X Fiche 50-289, B3/12/08, B401110327

--B401110328 Requests delay in administrative proceedings re Unit 1 operation until conclusion of util criminal misconduct trial. Schedule conflict re witness testimony at both proceedings possible
JENSEN, D L Justice, Dept of B3/12/14 PALLADINO, N J Commissioners 2pp 21795 010 24X Fiche 50-289, B3/12/08, B401110327

--B401110329 Extends invitation to attend & participate in B31216 hearing in Harrisburg, PA re Unit 1 restart
SPECTER, A Senate B3/12/09 PALLADINO, N Commissioners 1p 21795 012 24X Fiche 50-289, B3/12/08, B401110327

B401060391 Seeks clarification of Commission plans to restart, in light of staff B31205 recommendation that Commission authorize low power operation. Commission B40110 meeting should either authorize restart or establish restart conditions
LAURENBERG, F R, BRADLEY, B, RINALDO, M J Senate B3/12/20 PALLADINO, N Commissioners 3pp 21741 093 24X
Fiche 50-289, B3/12/20, B401060391

V Operator Examinations

B401030087 Forwards B31216 status rept of util response to Rohrer, Hibler & Replogle, Inc rept on licensed operator concerns Svc list encl
BLAKE, E L Shaw, Pittman, Fotts & Troubridge BLAKE, E L Metropolitan Edison Co B3/12/28 EDLES, G J, BUCK, J H, KOHL, C N Atomic Safety and Licensing Appeal Panel 21pp 21683 172 24X
Fiche 50-289, B3/12/28, B401030087

B401260367 Forwards IE Insp Rept 50-289/B3-29 on B31017-21 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B4/01/13 HUKILL, H D General Public Utilities - GPU Service Corp 2pp, 21955 229 24X Fiche 50-289, B4/01/13, B401260367

--B401260369 IE Insp Rept 50-289/B3-29 on B31017-21 No violations noted
Major areas inspected: licensed operator requalification program, general employee training & nonlicensed technical training
BISSETT, P H, SHAUB, E T, CAPTON, D L Region 1, Office of Director B3/12/19 10pp, 21955 231 24X Fiche 50-289, B4/01/13, B401260367

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401040179 Application for amend to License DPR-33, consisting of Proposed Change B3-14 to Tech Specs re fire protection. Change represents final component of changes committed to in B30813 ltr.
HARRINGTON, W D Boston Edison Co B3/12/28 VASSALLO, D B Operating Reactors Branch 2 1p 21702 352 24X
Fiche 50-293, B3/12/28, B401040179

--B401040181 Proposed Tech Spec changes re fire protection
* Boston Edison Co B3/12/28 6pp 21702 353 24X
Fiche 50-293, B3/12/28, B401040179

B401160095 Discusses plans for establishing emergency offsite facility, per NUREG-0737, Suppl 1, in response to NRC B31103 ltr
Clarification of NUREG-0737 guidance re contained sources, leakage rates & release pathways requested
HARRINGTON, W D Boston Edison Co B4/01/10 EISENHUT, D O Division of Licensing 3pp 21915 205 24X Fiche 50-293, B4/01/10, B401160095

B401160301 Forwards BALP rept for Jul 1982 - June 1983, attendance list for B30921 meeting w/licensee & licensee response to BALP rept NRC comments on util response, including comments re plant operations & radiological controls, encl
MURLEY, T E Region 1, Office of Director B4/01/11 HARRINGTON, W D Boston Edison Co 6pp 21814 018 24X
Fiche: 50-293, B4/01/11, B401160301

--B401160307 Responds to NRC BALP rept for Jul 1982 - June 1983, discussing plant operations, radiological controls, maintenance, housekeeping, fire protection, security, surveillance, emergency preparedness & licensing activities
HARRINGTON, W D Boston Edison Co B3/10/11 STAROSTECKI, R Division of Project & Resident Programs 8pp 21814 070 24X
Fiche 50-293, B4/01/11, B401160301

DOCKETED ITEMS

109

B401190385 Remits fees for proposed Tech Spec changes re control rod drive weekly surveillance testing & fire protection Reload & reactor protection sys protective circuitry & increased core flow discussed
HARRINGTON, W D Boston Edison Co 84/01/11 DIOGS, R M License Fee Management Branch 3pp 21850 076 24X Fiche 50-293, 84/01/11, B401190385

B401180074 Forwards additions & deletions to safeguards info protection program per B30817 ltr Encl withheld (ref 10CFR73 21)
HARRINGTON, W D Boston Edison Co 84/01/12 VASSALLO, D B Operating Reactors Branch 2 1p 21844 080 24X Fiche 50-293, 84/01/12, B401180074

G Adjudicatory correspondence

B401300232 Order dismissing proceeding as moot
COTTER, B P, LINENBERGER, G Atomic Safety and Licensing Board Panel
84/01/26 2pp 21998 360 24X Fiche 50-293, 84/01/26, B401300232

H General correspondence

B401200268 Requests changes to NRC lists for distributing documents re License DPR-35
MORISI, A V Boston Edison Co 83/01/05 VASSALLO, D B Operating Reactors Branch 2 1p 21872 079 24X Fiche 50-293, 83/01/05, B401200268

J Insurance & indemnity information

B401060232 Forwards Endorsement 80 to NELIA Policy NF-188 & Endorsement 44 to MAELU Policy MF-58
BINIBI, J M Marsh & McLennan, Inc 83/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 21740 112 24X Fiche 50-293, 83/12/27, B401060232

P Operating license stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000, 83/10/18, B401250015

--B203050118 Describes calculation of proposed civil penalties Events indicated need for aggressive involvement of higher licensee mgt in assuring safe operation
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-064 82/02/12 3pp 21960 165 24X Fiche 50-000, 83/10/18, B401250015

B401040179 Application for amend to License DPR-35, consisting of Proposed Change 83-14 to Tech Specs re fire protection
Changes represents final component of changes committed to in B30513 ltr
HARRINGTON, W D Boston Edison Co 83/12/28 VASSALLO, D B Operating Reactors Branch 2 1p 21702 352 24X Fiche 50-293, 83/12/28, B401040179

--B401040181 Proposed Tech Spec changes re fire protection
* Boston Edison Co 83/12/28 6pp 21702 353 24X Fiche 50-293, 83/12/28, B401040179

B401090405 Application for Proposed Tech Spec Change 83-15 to License DPR-35, correcting error in GE Oct 1983 reload licensing
submittal for restart from Refueling Outage 4
HARRINGTON, W D Boston Edison Co 83/12/28 VASSALLO, D B Operating Reactors Branch 2 2pp 21750 246 24X Fiche 50-293, 83/12/28, B401090405

--B401090409 Proposed Tech Spec changes for Reload 4
* Boston Edison Co 83/12/28 7pp 21750 248 24X Fiche 50-293, 83/12/28, B401090405

--B401090554 Errata & addenda to NEDO-21694, "LOCA Analysis Rept for Pilgrim Nuclear Power Station"
* General Electric Co NEDO-21694 ERR 03 83/10/31 3pp 21750 255 24X Fiche 50-293, 83/12/28, B401090405

--B401090556 "GE BWR Supplemental Reload Licensing Submittal for Pilgrim Nuclear Power Station, Unit 1, Reload 4"
VERBRYKE, P A, HILF, C L, CHARNLEY, J S General Electric Co
22A1694 R00, 83/10/31 20pp 21750 258 24X Fiche 50-293, 83/12/28, B401090405

B401170283 Informs that B30927 request for extension until Apr 1984 for implementation of operator staffing requirements granted
Tech Specs should be amended accordingly Safety evaluation encl
EISENHUT, D O Division of Licensing 83/12/29 HARRINGTON, W D Boston Edison Co 2pp 21836 350 24X Fiche 50-293, 83/12/29, B401170283

--B401170289 Safety evaluation granting licensee B30927 request for extension until Apr 1984 for implementation of control room shift staffing
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp 21836 352 24X Fiche 50-293, 83/12/29, B401170283

B401250474 Notifies that TMI Action Items II K 3 30 & II K 3 31 completed based on NRC 831213 acceptance of GE small break LOCA model Confirmation requested within 30 days re use of model
VASSALLO, D B Operating Reactors Branch 2 83/12/29 HARRINGTON, W D Boston Edison Co 2pp 21948 358 24X Fiche 50-293, 83/12/29, B401250474

B401270170 Forwards Amend 73 to License DPR-35 & safety evaluation Amend revises Tech Specs to permit operation w/increased safety relief valve setpoints
LEECH, P H Operating Reactors Branch 2 83/12/29 HARRINGTON, W D Boston Edison Co 2pp 22002 284 24X Fiche 50-293, 83/12/29, B401270170

--B401270175 Amend 73 to License DPR-35, revising Tech Specs to permit operation w/increased safety relief valve (SRV) setpoints to enable increased pressure differential between operating pressure & SRV pressure setpoints
VASSALLO, D B Operating Reactors Branch 2 83/12/29 4pp 22002 286 24X Fiche 50-293, 83/12/29, B401270170

--B401270186 Safety evaluation supporting Amend 73 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 83/12/29 2pp 22002 290 24X Fiche 50-293, 83/12/29, B401270170

B401040209 Informs that implementation of vendor manual validation process into nuclear organization procedures, per Generic Ltr B3-28, will be completed by B40215 instead of B40101, due to preparation for current refueling
HARRINGTON, W D Boston Edison Co 83/12/30 VASSALLO, D B Operating Reactors Branch 3 1p 21707 140 24X Fiche 50-293, 83/12/30, B401040209

B401050382 Generic Ltr B4-01 to all holders of GLs, applicants for GLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401190148 Requests remittance of fee for review of B31109 application for Tech Spec changes re surveillance for control rod drive
MILLER, W D License Fee Management Branch 84/01/05 HARRINGTON, W D Boston Edison Co 1p 21870 353 24X Fiche 50-293, 84/01/05, B401190148

B401090221 Generic Ltr B4-02 to all applicants for GLs & full power authorizations re notice of meeting on facility staffing
Bvc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401190385 Remits fees for proposed Tech Spec changes re control rod drive weekly surveillance testing & fire protection Reload & reactor protection sys protective circuitry & increased core flow discussed
HARRINGTON, W D Boston Edison Co 84/01/11 DIOGS, R M License Fee Management Branch 3pp 21850 076 24X Fiche 50-293, 84/01/11, B401190385

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for GLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Bvc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401230370 Notifies that Harrington B31223 ltr to Vassallo misnumbered
Correct tracking number is B3-309
HARRINGTON, W D Boston Edison Co 84/01/13 VASSALLO, D B Operating Reactors Branch 2 1p 21878 253 24X Fiche 50-293, 84/01/13, B401230370

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J H Division of Rules and Records 83/10/20 ZAHLE, R E
Shaw, Pittman, Patts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
B401060040

B312190342 Notification of B31130 significant licensee meeting w/util in Plymouth, MA to discuss performance improvement program
BORCHARDT, R Region 1, Office of Director 83/11/28 Region 1,
Office of Director 1p 21573 237 24X Fiche 50-293, 83/11/28,
B312190342

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21626 060 24X Fiche 50-000, 83/12/30, B312120093

B401230415 Responds to NRC B31208 ltr re violations noted in IE Insp Rept 50-293/83-23 on B31004-1107 HPCI sys check valve & test frequency procedures revised & nuclear operations procedure will be issued by B40131
HARRINGTON, W D Boston Edison Co 84/01/03 STAROSTECKI, R Division of Project & Resident Programs 3pp 21879 147 24X
Fiche 50-293, 84/01/03, B401230415

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 128pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401160301 Forwards SALP rept for Jul 1982 - June 1983 attendance list for B30921 meeting w/licenses & licensee response to SALP rept NRC comments on util response, including comments re plant operations & radiological controls, encl
MURLEY, T E Region 1, Office of Director 84/01/11 HARRINGTON, W D Boston Edison Co 4pp 21814 018 24X
Fiche 50-293, 84/01/11, B401160301

--B401160303 Forwards SALP rept for Jul 1982 - June 1983 Meeting to discuss rept scheduled for B30921 in Braintree, MA
STAROSTECKI, R Division of Project & Resident Programs 83/09/14 HARRINGTON, W D Boston Edison Co 1p 21814 024 24X
Fiche 50-293, 84/01/11, B401160301

--B401160303 SALP rept for Jul 1982 - June 1983 Overall rating of Category 2 assigned to reactor operations, radiological controls & maint
* Region 1, Office of Director 83/08/25 45pp 21814 025 24X
Fiche 50-293, 84/01/11, B401160301

-B401160307 Responds to NRC SALP rept for Jul 1982 - June 1983, discussing plant operations, radiological controls, maint, housekeeping, fire protection, security, surveillance, emergency preparedness & licensing activities
HARRINGTON, H R Boston Edison Co 83/10/11 STAROSTECKI, R Division of Project & Resident Programs 8pp 21814 070 24X
Fiche 50-293, 84/01/11, B401160301

B401230235 Forwards revised QA program (BEGAM II) resolving comments in IE Insp Rept 50-293/83-22 Controlled document identifying BEGAM II & ANSI N18.7 requirements to be issued by B40331
HARRINGTON, W D Boston Edison Co 84/01/12 Region 1, Office of Director 2pp 21884 016 24X Fiche 50-293, 84/01/12, B401230235

-B401230237 Rev 9 to QA program
* Boston Edison Co 83/12/30 44pp 21884 018 24X
Fiche 50-293, 84/01/12, B401230235

B312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B401230137 Ack receipt of B40103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-23
STAROSTECKI, R Division of Project & Resident Programs 84/01/17 HARRINGTON, W D Boston Edison Co 1p 21884 356 24X
Fiche 50-293, 84/01/17, B401230137

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401050293 Submits summary of 1983 main breakwater survey results, in response to NRC B10203 & B30607 ltrs No damage or major stone movement to structure since 1982 rept W/two oversize drawings Aperture cards are available in PDR
HARRINGTON, W D Boston Edison Co 83/12/23 VASSALLO, D B Operating Reactors Branch 2 2pp 21726 273 24X
Fiche 50-293, 83/12/23, B401050293

B401170436 Monthly operating rept for Dec 1983 W/B40112 ltr
HAMILTON, P J, HARRINGTON, W D Boston Edison Co 83/12/31 Director's Office, Office of Inspection and Enforcement 7pp 21927 119 24X Fiche 50-293, 83/12/31, B401170436

S Reportable occurrences, LERs & related correspondence

B401120208 LER B3-058/03L-0 on B31012, mainstack monitor sys lost flow when sample pump tripped Caused by low output pressure from pressure switch due to newly installed rebuilt pump Second rebuilt pump installed W/B31221 ltr
WHITNEY, G O, HARRINGTON, W D Boston Edison Co 83/12/21 Region 1, Office of Director 2pp 21793 294 24X Fiche 50-293, 83/12/21, B401120208

B401160118 LER B3-059/03L-0 on B31129, while performing operations daily instrument check surveillance, torus temp recorder TRU-7045 found to be recording downscale Cause & completion of corrective action deferred to refuel outage W/B31228 ltr
MCCANN, W J, HARRINGTON, W D Boston Edison Co 83/12/28 Region 1, Office of Director 2pp 21815 361 24X Fiche 50-293, 83/12/28, B401160118

B401160175 LER B3-060/03L-0 on B31129, alarm observed indicating low nitrogen pressure in control rod drive 10-11 accumulator Caused by leaking accumulator gas charging valve seat Valve cartridge III replaced & successfully tested W/B31228 ltr
MCCANN, W J, HARRINGTON, W D Boston Edison Co 83/12/28 Region 1, Office of Director 2pp 21815 341 24X Fiche 50-293, 83/12/28, B401160175

B401240098 LER B3-064/01T-0 on B31219, during refueling operations, shield plugs separating dryer separator pool from refuel cavity not removed Caused by procedural inadequacy Procedure revised W/B31230 ltr
HAMILTON, P J, HARRINGTON, W D Boston Edison Co 83/12/30 Region 1, Office of Director 2pp 21913 143 24X
Fiche 50-293, 83/12/30, B401240098

B401240103 LER B3-061/03L-0 on B31203, C-7 panel position indication alarm failed to annunciate as required for vacuum breaker H Cause will be determined Maint request issued to investigate & repair alarm Followup rept will be issued W/B31230 ltr
HAMILTON, P J, HARRINGTON, W D Boston Edison Co 83/12/30 Region 1, Office of Director 2pp 21913 152 24X
Fiche 50-293, 83/12/30, B401240103

B401240145 LER B3-063/01T-0 on B31219, during insp of recirculation sys piping welds, two indications found in 12-inch lines, Cause tentatively attributed to intergranular stress corrosion cracking Ring header will be replaced W/B31230 ltr
MCCANN, W J, HARRINGTON, W D Boston Edison Co 83/12/30 Region 1, Office of Director 2pp 21910 274 24X Fiche 50-293, 83/12/30, B401240145

B401270243 LER 83-062/03L-0 on 831205 & 06, while conducting insp of secondary containment dampers, dampers AD/N-94 & 95 found to be inoperable after nylon drive gears became misaligned. Drive gears readjusted W/B40104 ltr. HAMILTON, P J, HARRINGTON, W D Boston Edison Co 84/01/04 Region 1, Office of Director 3pp 21982 156 24X Fiche 50-293, 84/01/04, B401270243

B401270162 LER 83-045/03L-0 on 831213, HPCI exhaust check valve 2301-45 found to have leakage in excess of acceptance criteria. Maint request issued to repair valve. Cause of failure & details will be provided in updated rept W/B40109 ltr. HAMILTON, P J, HARRINGTON, W D Boston Edison Co 84/01/09 Region 1, Office of Director 2pp 21982 067 24X Fiche 50-293, 84/01/09, B401270162

X Onsite Storage of Low Level Waste

B401130047 Discusses proposed methods of implementing requirements of 10CFR61 & outlines addl actions taken prior to shipment of radwaste after 831227. HARRINGTON, W D Boston Edison Co 83/12/20 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 3pp 21819 350 24X Fiche 50-293, 83/12/20, B401130047

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SARP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR. FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SARP results during 1982. * Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401110181 Withholds approval of B31121 request for exemption from App R fire protection mods contingent on NRC approval of util June 1984 installation schedule. Compliance measures should be submitted in 30 days. DENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/21 REED, C Commonwealth Edison Co 7pp 21795 001 24X Fiche 50-295, 83/12/21, B401110181

B401050084 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21736 309 24X Fiche 50-295, 83/12/28, B401050084

--B401050090 Public version of Rev 15 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group" W/B31109 ltr, receipt form & revised index. NYKIRK, J W Commonwealth Edison Co 83/11/09 5pp 21736 310 24X Fiche 50-295, 83/12/28, B401050084

B401050239 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21743 212 24X Fiche 50-295, 83/12/28, B401050239

--B401050244 Public version of Rev 0 to Emergency Plan Implementing Procedure EPIP 100-1, "Acting Station Director (Shift Engineer)" W/B31206 ltr, receipt form & revised index. PLIML, G Commonwealth Edison Co 83/12/05 Office of Nuclear Reactor Regulation, Director 12pp 21743 213 24X Fiche 50-295, 83/12/28, B401050239

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation. Will vary at each facility. SHARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X Fiche 50-000, 83/12/29, B401030229

B401190434 Forwards IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 & notice of violation. SHAHER, W D Region 3, Office of Director 83/12/30 REED, C Commonwealth Edison Co 2pp 21849 236 24X Fiche 50-295, 83/12/30, B401190434

--B401190440 Notice of violation from insp on 831111-1220. SHAHER, W D Region 3, Office of Director 83/12/30 2pp 21849 238 24X Fiche 50-295, 83/12/30, B401190434

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed. PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, B401230491

B401250120 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21959 068 24X Fiche 50-295, 84/01/18, B401250120

--B401250123 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 310-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians" W/B31214 ltr & receipt form. PLIML, G Commonwealth Edison Co 83/12/12 DENTON, H R NRC - No Detailed Affiliation Given 6pp 21959 069 24X Fiche 50-295, 84/01/18, B401250120

B401250135 Releases public version of revised emergency plan implementing procedures. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21959 030 24X Fiche 50-295, 84/01/18, B401250135

--B401250138 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 550-3, "Radiological Supplies for Medical Emergencies" W/B31228 transmittal & receipt form. PLIML, G Commonwealth Edison Co 83/12/23 DENTON, H R NRC - No Detailed Affiliation Given 9pp 21959 031 24X Fiche 50-295, 84/01/18, B401250135

B401260241 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21959 337 24X Fiche 50-295, 84/01/18, B401260241

--B401260243 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 550-5, "Technical Support Ctr, Operational Support Ctr & Main Assembly Area Radiological Supplies" W/B31212 procedure request form. FICH, C R Commonwealth Edison Co 83/12/12 8pp 21959 338 24X Fiche 50-295, 84/01/18, B401260241

B401260247 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21992 333 24X Fiche 50-295, 84/01/18, B401260247

--B401260252 Public version of Rev 6 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment" W/B31214 procedure change request form. PLIML, G Commonwealth Edison Co 83/12/14 8pp 21992 334 24X Fiche 50-295, 84/01/18, B401260247

B401260258 Releases public version of revised emergency plan implementing procedure. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21992 326 24X Fiche 50-295, 84/01/18, B401260258

--B401260263 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP 180-1, "Rad/Chem Director" W/B31214 procedure change request form. PLIML, G Commonwealth Edison Co 83/12/12 6pp 21992 327 24X Fiche 50-295, 84/01/18, B401260258

B401300200 Requests exemption from participation by States of WI & IL in B40417 emergency exercise. Major elements in governmental emergency plans performed satisfactorily in 1983 FEMA correspondence encl. FARRAR, D L Commonwealth Edison Co 84/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 21995 337 24X Fiche 50-295, 84/01/18, B401300200

DOCKETED ITEMS

B401310049 Releases public version of change request form deleting emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/18 Document
 Management Branch 1p 22031 358 24X Fiche 50-295, 84/01/18, 8401310049

--B401310051 Public version of change request form deleting Emergency Plan Implementing Procedure EPIP 350-4, "Onsite Radiological Emergency Response Equipment" W/831214 ltr & receipt form
 PLIML, G Commonwealth Edison Co 83/12/12 DENTON, H R NRC - No
 Detailed Affiliation Given 4pp 22031 362 24X
 Fiche 50-295, 84/01/18, 8401310049

B401310077 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/18 Document
 Management Branch 1p 22029 358 24X Fiche 50-295, 84/01/18, 8401310077

--B401310081 Public version of Rev 1 to Emergency Plan Implementing Procedure B2P 500-T6, "Checklist - Environ Monitoring Supplies" W/831229 ltr & receipt form
 * Commonwealth Edison Co 83/11/04 5pp 22029 359 24X
 Fiche 50-295, 84/01/18, 8401310077

B401310088 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/18 Document
 Management Branch 1p 22028 280 24X Fiche 50-295, 84/01/18, 8401310088

--B401310106 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 550-6, "Monthly Radiological Emergency Equipment Tests & Checks" W/831214 ltr, receipt form & procedure change request form
 PLIML, G Commonwealth Edison Co 83/12/12 DENTON, H R NRC - No
 Detailed Affiliation Given 10pp 22028 281 24X
 Fiche 50-295, 84/01/18, 8401310088

J Insurance & indemnity information

B401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
 OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant
 Director for State & Licensee Relations 17pp 21865 332 24X
 Fiche 50-000, 84/01/09, 8401200141

B401200184 Forwards listed endorsements to NELIA Policies NF-43, 187, 201, 293 & 277 & MAELU Policies MF-22, 34, 64 & 104
 OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant
 Director for State & Licensee Relations 19pp 21863 232 24X
 Fiche 50-000, 84/01/09, 8401200184

P Operating license stage documents & correspondence

B401120585 Forwards Amends 83 & 73 to Licenses DPR-39 & DPR-48, respectively & safety evaluation Amends change Tech Specs to allow transition from low-parasitic 15x15 fuel assemblies to 15x15 optimized fuel assemblies
 NORRIS, J Operating Reactors Branch 4 83/12/23 FARAR, D L
 Commonwealth Edison Co 2pp 21796 300 24X Fiche 50-295, 83/12/23, 8401120585

--B401120591 Amends 83 & 73 to Licenses DPR-39 & DPR-48, respectively, allowing transition from low-parasitic 15x15 fuel assemblies to 15x15 optimized fuel assemblies
 VARGA, S A Operating Reactors Branch 1 83/12/23 38pp
 21796 302 24X Fiche 50-295, 83/12/23, 8401120585

--B401120601 Safety evaluation supporting Amends 83 & 73 to Licenses DPR-39 & DPR-48, respectively
 * Office of Nuclear Reactor Regulation, Director 83/12/23
 19pp 21796 341 24X Fiche 50-295, 83/12/23, 8401120585

B401100455 Suppls B30422 response to Generic Ltr 83-10C & D Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301
 BARNES, P L Commonwealth Edison Co 84/01/04 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 1p 21761 284 24X
 Fiche 50-000, 84/01/04, 8401100455

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
 EISENHUT, D G Division of Licensing 84/01/05 Consolidated
 Edison Co of New York, Inc 16pp, 21946 190 24X
 Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
 Svc list encl
 EISENHUT, D G Division of Licensing 84/01/06 Consolidated
 Edison Co of New York, Inc 18pp 21937 267 24X
 Fiche 50-000, 84/01/06, 8401090221

B401100468 Clarifies operational status of mod re NUREG-0737, Item 111 D 3.4, "Control Room Habitability" Mod providing automatic isolation of control room outside air intake on safety injection signal completed 831222
 LENTINE, F G Commonwealth Edison Co 84/01/06 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 21761 336 24X
 Fiche 50-295, 84/01/06, 8401100468

B401170339 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators" Prelubrication w/some warming provided, therefore, generators not subjected to cold starts
 BARNES, P L Commonwealth Edison Co 84/01/10 EISENHUT, D G
 Division of Licensing 1p 21829 341 24X Fiche 50-000, 84/01/10, 8401170339

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
 EISENHUT, D G Division of Licensing 84/01/13 Consolidated
 Edison Co of New York, Inc 18pp 21946 174 24X
 Fiche 50-000, 84/01/13, 8401130084

B401240016 Notification of B40124 meeting w/util in Bethesda, MD to discuss status of equipment environ qualification for facilities
 NORRIS, J A Operating Reactors Branch 1 84/01/13 VARGA, S A
 Operating Reactors Branch 1 2pp 21949 048 24X
 Fiche 50-295, 84/01/13, 8401240016

B401300265 Updates B30817 application for amend to Licenses DPR-39 & DPR-45 re auxiliary electric power & ECCS
 LENTINE, F G Commonwealth Edison Co 84/01/25 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 21996 321 24X
 Fiche 50-295, 84/01/25, 8401300265

--B401300267 Proposed Tech Spec changes for auxiliary electric power & ECCS
 * Commonwealth Edison Co 84/01/25, 3pp 21996 323 24X
 Fiche 50-295, 84/01/25, 8401300265

Q Inspection reports, IE Bulletins & correspondence

B401040533 Suppls response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
 BARNES, P L Commonwealth Edison Co 83/12/20 KEPLER, J G Region
 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20, 8401040533

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060, 24X Fiche 50-000, 83/12/30, 8312120093

B401190434 Forwards IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 & notice of violation
 SHAFER, W D Region 3, Office of Director 83/12/30 REED, C
 Commonwealth Edison Co 2pp 21849 236 24X Fiche 50-295, 83/12/30, 8401190434

--B401190440 Notice of violation from Insp on 831111-1220
 SHAFER, W D Region 3, Office of Director 83/12/30 2pp
 21849 238 24X Fiche 50-295, 83/12/30, 8401190434

--B401190449 IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 Violations noted: failure to adhere to fire protection procedures & to use procedure for diesel generator overspeed trip setpoint adjustment
 DUNAWAY, F R, HOLZMER, M M, BOYD, D C Region 3, Office of
 Director 83/12/29 8pp 21849, 240, 24X Fiche 50-295, 83/12/30, 8401190434

DOCKETED ITEMS

113

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 129pp 21946 093 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valve Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401300005 Responds to Action Item 3, per Item 3 of IE Bulletin 83-03 re rept of insp results No leakage identified during back flow testing of diesel generator cooling water pump discharge check valves 16W010 & 16W011 on 831027
BARNES, P L Commonwealth Edison Co 84/01/19 KEPLER, J Q Region 3, Office of Director 2pp 21999 228 24X Fiche 50-295,84/01/19,8401300005

R Periodic operating reports & related correspondence

8401170020 Monthly operating repts for Dec 1983 W/840107 ltr
AUSTIN, Q, GRAEBER, K L Commonwealth Edison Co 83/12/31
Director's Office, Office of Inspection and Enforcement 12pp 21834 091 24X Fiche 50-295,83/12/31,8401170020

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs
GRAEBER, L D NUS Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000,83/10/07,8401050064

8401190415 LER 83-051/03L-0 on 831228, during periodic testing, U-1 hydrogen recombiner reached required operating temp & tripped Caused by circuit breaker arcing due to power surge from failed fuse Fuses replaced W/840112 ltr
GLOVER, J, GRAEBER, K L Commonwealth Edison Co 84/01/12
KEPLER, J Q Region 3, Office of Director 2pp 21849 322 24X Fiche 50-295,84/01/12,8401190415

8401190423 LER 83-052/03L-0 on 831222, snubber DTR8 1029 failed to lock up at design loads & 10 addl snubbers found inoperable Caused by low fluid level New ethylene propylene seals installed W/840112 ltr
PETROWSKI, S, GRAEBER, K L Commonwealth Edison Co 84/01/12
KEPLER, J Q Region 3, Office of Director, App 21849 324 24X Fiche 50-295,84/01/12,8401190423

8401270333 LER 83-033/03L-0 on 831223, safety injection accumulator tank A,B,C level transmitters found out-of-tolerance high Caused by refueling depressurization effects on capacitance level probes Calibr procedures changed W/840120 ltr
CANTWELL, P F, GRAEBER, K L Commonwealth Edison Co 84/01/20
KEPLER, J P Region 3, Office of Director 2pp 21976 319 24X Fiche 50-295,84/01/20,8401270333

8401300110 PNO-III-B4-009, on 840120, two workmen accidentally uncoupled 1/2-inch swagloc fitting on unisolable portion of in-core thimble. Flow rate was approx 100 gpm. Workmen decontaminated & swagloc fitting replaced
BOYD, D, SHAFER, M, Region 3, Office of Director, 84/01/23 2pp 21999 187 24X Fiche 50-295,84/01/23,8401300110

V. Operator Examinations

8401230366 Requests listed ref matl required for operator/senior operator licensing exams be provided Written exams scheduled for 840313 & simulator operating & oral exams scheduled for 840307-08 Info due 30 days before exams
BESSARD, R L Division of Engineering 84/01/18 REED, C, Commonwealth Edison Co, App 21884 245 24X Fiche 50-295,84/01/18,8401230366.

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
F Security, medical, emergency & fire protection plans

8401030251 Ack receipt of 830902 ltr re emergency exercise scheduled during Nov 1983 Presentation of emergency exercise objectives appropriate in describing scope & objectives of upcoming exercises
VERRELLI, D M Division of Project & Resident Programs 83/10/13
PARRIS, H Q Tennessee Valley Authority 2pp 21681 152 24X Fiche 50-259,83/10/13,8401030251

--8401030252 Forwards description of objectives for radiological emergency exercise scheduled for wk of 831113-19 Scope of exercise will meet requirements of 10CFR50, App E for full-scale exercise
MILLS, L M Tennessee Valley Authority 83/09/02 BTOHR, J P Region 2, Office of Director 3pp 21681 154 24X Fiche 50-259,83/10/13,8401030251

8401050468 Forwards IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on 831031-1104 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/02
PARRIS, H Q Tennessee Valley Authority 2pp 21730 126 24X Fiche 50-259,83/12/02,8401050468

--8401050477 IE Insp Repts 50-259/83-47, 50-260/83-47 & 50-296/83-47 on 831031-1104 No violations noted Major areas inspected fire protection/prevention program & implementation
GIBBONS, T D Region 2, Office of Director 83/11/30 7pp 21730 128 24X Fiche 50-259,83/12/02,8401050468

8401090237 Forwards IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/02
PARRIS, H Q Tennessee Valley Authority 2pp 21750 291 24X Fiche 50-259,83/12/02,8401090237

--8401090264 IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16 No violations noted Major areas inspected emergency preparedness exercise
DECKER, T R Region 2, Office of Director 83/12/13 9pp 21750 293 24X Fiche 50-259,83/12/20,8401090237

8401060438 Confirms actions discussed in 831220 telcon re failure to control vital area access All security personnel to be retrained & certified no later than 840131
O'REILLY, J P Region 2, Office of Director 83/12/21 PARRIS, H Q Tennessee Valley Authority 2pp 21740 084 24X Fiche 50-259,83/12/21,8401060438

8401240300 Confirms 840113 mgt meeting in Region II ofcs to discuss proposed changes to emergency plan & procedures, per 840109 telcon Meeting notification encl
LEWIS, R C Division of Project & Resident Programs 84/01/10
PARRIS, H Q Tennessee Valley Authority 2pp 21920 076 24X Fiche 50-259,84/01/10,8401240300

8401170321 Ack receipt of 831018 ltr transmitting 830815 rev to guard training & qualification plan Changes inconsistent w/ provisions of 10CFR50 54p Previously approved plan must be utilized Encl withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/12
PARRIS, H Q Tennessee Valley Authority 3pp 21830 350, 24X Fiche 50-259,84/01/12,8401170321

8401240398 Ack receipt of 831223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03
O'REILLY, J P Region 2, Office of Director 84/01/13 PARRIS, H Q Tennessee Valley Authority 1p 21920 142 24X Fiche: 50-259,84/01/13,8401240398

--8401240407 Suppls 831223 response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 Corrective actions new health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P Region 2, Office of Director 4pp 21920 143 24X Fiche 50-259,84/01/13,8401240398

--8401240428 Forwards supplemental response to 830802 request re IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 New health physics dose tracking sys implemented
MILLS, L M Tennessee Valley Authority 83/09/07 O'REILLY, J P Region 2, Office of Director 4pp 21920 130 24X Fiche 50-259,84/01/13,8401240398

DOCKETED ITEMS

8401240611 Releases public version of revised radiological emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21945 252 24X Fiche 50-259,84/01/20,
8401240611

--8401240616 Forwards public version of Rev 6 to radiological emergency plan & revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr & IP-3 re alert
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21945 253
24X Fiche 50-259,84/01/20,8401240611

--8401240621 Public version of Rev 6 to radiological emergency plan
* Tennessee Valley Authority 83/12/22 49pp 21945 254 24X
Fiche 50-259,84/01/20,8401240611

--8401240626 Public version of revised emergency plan implementing procedures, including Procedures IP-6 re activation of technical support ctr, IP-24 re earthquake emergency procedure & IP-3 re alert
CHINN, T L Tennessee Valley Authority 83/10/12 112pp
21945 303 24X Fiche 50-259,84/01/20,8401240611

8401250110 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 079 24X Fiche 50-000,84/01/20,
8401250110

--8401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure NSECC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080
24X Fiche 50-000,84/01/20,8401250110

--8401250126 Public version of revised emergency plan implementing procedures, including Procedures NSECC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MAXWELL, R B Tennessee Valley Authority 83/11/10 34pp
21959 081 24X Fiche 50-000,84/01/20,8401250110

H General correspondence

8401050263 Designates MP Schmierback, RJ Johnson & DM McCarthy as acting officials during author absence
BRUCH, A Tennessee Valley Authority 83/12/29 MARLAR, J
Environmental Protection Agency 1p 21728 303 24X
Fiche 50-259,83/12/29,8401050263

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II
KANMER, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000,84/01/12,8401200194

--8401200199 Annual Financial Rept 1982, Vol I
PARRIS, H O Tennessee Valley Authority 84/01/12 75pp
21865 002 24X Fiche 50-000,84/01/12,8401200194

--8401200206 Annual Financial Rept 1982, Vol II
PARRIS, H O Tennessee Valley Authority 84/01/12 95pp
21865 077 24X Fiche 50-000,84/01/12,8401200194

P Operating license stage documents & correspondence

8401170509 Forwards request for addl info re radiological effluent Tech Specs Telcon should be scheduled within 30 days to discuss & resolve questions
VASSALLO, D B Operating Reactors Branch 2 83/12/20 PARRIS, H O
Tennessee Valley Authority 13pp 21847 137 24X
Fiche 50-259,83/12/20,8401170509

8401240047 Forwards Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends add stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
ARRR, J Operating Reactors Branch 2 83/12/27 PARRIS, H O
Tennessee Valley Authority 2pp 21945 203 24X
Fiche 50-259,83/12/27,8401240047

--8401240051 Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively, adding stringent requirements to Tech Spec Section 3 & C on allowable primary coolant leakage into drywell
VASSALLO, D B Operating Reactors Branch 2 83/12/27 18pp
21945 205 24X Fiche 50-259,83/12/27,8401240047

--8401240054 Safety evaluation supporting Amends 94, 87 & 60 to Licenses DPR-33, DPR-52 & DPR-68, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/27 23p
21945 223 24X Fiche 50-259,83/12/27,8401240047

8401260475 Notifies that TMI Action Items II K 3 30 & II K 3 31 completed, based on NRC 831213 acceptance of GE small break LOCA model Confirmation of Model use requested within 30 days
VASSALLO, D B Operating Reactors Branch 2 83/12/28 PARRIS, H O
Tennessee Valley Authority 2pp 21959 335 24X
Fiche 50-259,83/12/28,8401260475

8401060051 Forwards Rev O to "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
Rept describes torus mods implemented & gives supporting analyses
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21738 098 24X
Fiche 50-259,84/01/03,8401060051

--8401060067 "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
ROCHELLE, J K, DUKE, S T, WILLIAMS, J S Tennessee Valley
Authority CEB-83-34 R00 83/12/21 20pp 21738 100, 24X
Fiche 50-259,84/01/03,8401060051

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,8401090221

8401160077 Forwards details of NUREG-0612, Section 5.1.1 guideline & compliance methodology review & response to Technical Evaluation Rept C3257-61/62/63 re special lifting device review, per 830526 ltr concerning control of heavy loads
MILLS, L M Tennessee Valley Authority 84/01/06 VASSALLO, D B
Operating Reactors Branch 2 19pp 21815 067 24X
Fiche 50-259,84/01/06,8401160077

8401310465 Requests review of potential overvoltage condition when using backup 161 kV offsite power source Assessment of in-plant voltages & discussion of general plan to resolve condition requested within 45 days of receipt of ltr
VASSALLO, D B Operating Reactors Branch 2 84/01/06 PARRIS, H O
Tennessee Valley Authority 3pp 22036 336 24X
Fiche 50-259,84/01/06,8401310465

8401170400 Forwards response to Generic Ltr 83-41 re fast cold starts of diesel generators Encl table for Browns Ferry shows times surveillance testing, maint activities & actual demand caused diesel generators to start
MILLS, L M Tennessee Valley Authority 84/01/11 EISENHUT, D O
Division of Licensing 8pp 21829 216 24X Fiche 50-000,84/01/11,
8401170400

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

8401300273 Application to amend License DPR-68, revising Tech Specs to accommodate Reload 5, Cycle 6, Class III amend fee encl
MILLS, L M Tennessee Valley Authority 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21994 186
24X Fiche 50-259,84/01/23,8401300273

--8401300278 Proposed Tech Specs to accommodate Reload 5, Cycle 6
* Tennessee Valley Authority 84/01/23 80pp 21994 188 24X
Fiche 50-259,84/01/23,8401300273

--B401300285 "Bottled-up Operation of DWR " CARRILL, D G, ECKERT, E C, HOLLAND, L K General Electric Co NEDO-20497 74/11/30 35pp 21994 268 24X Fiche 50-296, B4/01/23, B401300273

--B401300296 "Browns Ferry Nuclear Plant Reload Licensing Rept, Unit 3, Cycle 6 " * Tennessee Valley Authority TVA-RLR-001 B4/01/31 126pp 21994 302 24X Fiche 50-296, B4/01/23, B401300273

--B401300310 Errata to "LOCA Analysis for Browns Ferry Nuclear Plant Unit 3." Sheet 2 NSHC determination supporting B40123 application to amend License DPR-68 encl * General Electric Co NEDO-24194A ERR 02 B3/11/30 35pp 21993 072 24X Fiche 50-296, B4/01/23, B401300273

B401310134 Informs that revised integrated schedule will not be available by B40131 New schedule will be submitted by B40330 MILLER, L M Tennessee Valley Authority B4/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22022 099 24X Fiche 50-299, B4/01/26, B401310134

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR FELTON, J M Division of Rules and Records B3/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982 * Director's Office, Office of Inspection and Enforcement B3/10/20 105pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401030468 Forwards IE Insp Repts 50-259/B3-47, 50-260/B3-47 & 50-296/B3-47 on B31031-1104 No violations noted VERRELLI, D M Division of Project & Resident Programs B3/12/02 PARRIS, H O Tennessee Valley Authority 2pp 21730 126 24X Fiche: 50-259, B3/12/02, B401050468

--B401050477 IE Insp Repts 50-259/B3-47, 50-260/B3-47 & 50-296/B3-47 on B31031-1104 No violations noted Major areas inspected fire protection/prevention program & implementation OIBBONS, T D Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs B3/11/30 7pp 21730 126 24X Fiche 50-259, B3/12/02, B401050468

B401050449 Forwards IE Insp Repts 50-259/B3-39, 50-260/B3-39 & 50-296/B3-39 on B30926-30 No violations noted VERRELLI, D M Division of Project & Resident Programs B3/12/08 PARRIS, H O Tennessee Valley Authority 2pp 21725 200 24X Fiche 50-259, B3/12/08, B401050449

--B401050655 IE Insp Repts 50-259/B3-39, 50-260/B3-39 & 50-296/B3-39 on B30926-30 No violations noted Major areas inspected Unit 1 weld repair exposure control DEBB, B T Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs B3/11/16 8pp 21725 202 24X Fiche 50-259, B3/12/08, B401050649

B401090237 Forwards IE Insp Repts 50-259/B3-48, 50-260/B3-48 & 50-296/B3-48 on B31115-16 No violations noted VERRELLI, D M Division of Project & Resident Programs B3/12/20 PARRIS, H O Tennessee Valley Authority 2pp 21750 291 24X Fiche 50-259, B3/12/20, B401090237

--B401090264 IE Insp Repts 50-259/B3-48, 50-260/B3-48 & 50-296/B3-48 on B31115-16 No violations noted Major areas inspected emergency preparedness exercise DECKER, T R Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety B3/12/13, 7pp 21750 293 24X Fiche 50-259, B3/12/20, B401090237

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche, 50-000, B3/12/28, B312120090

B401050452 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/B3-43, 50-260/B3-43 & 50-296/B3-43 VERRELLI, D M Division of Project & Resident Programs B3/12/28 PARRIS, H O Tennessee Valley Authority 1p 21731 149 24X Fiche, 50-259, B3/12/28, B401050452

--B401050456 Responds to NRC B31118 ltr re violations noted in IE Insp Repts 50-259/B3-43, 50-260/B3-43 & 50-296/B3-43 Corrective actions tagboards & fuel transfer data sheets corrected & checked Undocumented temporary test pressure gauge removed KAMMER, D S Tennessee Valley Authority B3/12/16 O'REILLY, J P Region 2, Office of Director 5pp 21731 150 24X Fiche 50-259, B3/12/28, B401050452

--B401050462 Forwards IE Insp Repts 50-259/B3-43, 50-260/B3-43 & 50-296/B3-43 on B30926-1025 & notice of violation VERRELLI, D M Division of Project & Resident Programs B3/11/18 PARRIS, H O Tennessee Valley Authority 2pp 21731 155 24X Fiche 50-259, B3/12/28, B401050452

--B401050465 Notice of violation from insp on B30926-1025 * Region 2, Office of Director B3/11/18 2pp 21731 157 24X Fiche 50-259, B3/12/28, B401050452

--B401050472 IE Insp Repts 50-259/B3-43, 50-260/B3-43 & 50-296/B3-43 on B30926-1025 Violation noted correct tagboard not verified prior to Unit 3 unload & temporary test pressure form not issued PAULK, O L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs B3/11/17 7pp 21731 159 24X Fiche 50-259, B3/12/28, B401050452

B312120093 IE Info Notice B3-04, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B401240461 Suppl B21115 response to violations noted in IE Insp Repts 50-259/B2-27, 50-260/B2-27 & 50-296/B2-27 OET training for operators expected by B31231 incomplete Completion expected by B40131 MILLER, L M Tennessee Valley Authority B4/01/03 O'REILLY, J P Region 2, Office of Director 1p 21908 147 24X Fiche 50-259, B4/01/03, B401240461

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401240398 Ack receipt of B31223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 O'REILLY, J P Region 2, Office of Director B4/01/13 PARRIS, H O Tennessee Valley Authority 1p 21920 142 24X Fiche 50-259, B4/01/13, B401240398

--B401240407 Suppl B31123 response to NRC B30321 ltr re violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 Corrective actions new health physics dose tracking sys implemented MILLER, L M Tennessee Valley Authority B3/12/23 O'REILLY, J P Region 2, Office of Director 4pp 21920 143 24X Fiche 50-259, B4/01/13, B401240398

--B401240414 Ack receipt of B30907 response re steps taken to correct violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 Supplemental response dealing w/Item B requested within 30 days O'REILLY, J P Region 2, Office of Director B3/11/23 PARRIS, H O Tennessee Valley Authority 2pp 21920 147 24X Fiche 50-259, B4/01/13, B401240398

--B401240422 Ack receipt of B30907 ltr containing supplemental response to IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 Info under evaluation LEWIS, R C Division of Project & Resident Programs B3/10/12 PARRIS, H O Tennessee Valley Authority 1p 21920 149 24X Fiche 50-259, B4/01/13, B401240398

--B401240428 Forwards supplemental response to B30802 request re IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 New health physics dose tracking sys implemented MILLER, L M Tennessee Valley Authority B3/09/07 O'REILLY, J P Region 2, Office of Director 4pp 21920 150 24X Fiche 50-259, B4/01/13, B401240398

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

DOCKETED ITEMS

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401120307 Monthly operating repts for Nov 1983 W/831207 1tr
THOM, T, JONES, G T Tennessee Valley Authority 83/11/30 Office
of Resource Management, Director 37pp 21792 072 24X
Fiche 50-259,83/11/30,8401120307

8401270398 Monthly operating repts for Dec 1983 W/840110 1tr
THOM, T, SWINDELL, J E Tennessee Valley Authority 83/12/31
Office of Resource Management, Director 34pp 21976 271 24X
Fiche 50-259,83/12/31,8401270398

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records
2pp 21736 343 24X Fiche 50-000,83/10/07,8401050064

8401050157 NPDES noncompliance notification on 831205, sewage treatment plant effluent grab sample collected on 831129 exceeded max permit limitations Caused by excessive daily total flow
Sewage lagoon designed to replace sewage treatment plant
BRUCH, A Tennessee Valley Authority 83/12/23 MARLAR, J
Environmental Protection Agency 2pp 21727 334 24X
Fiche 50-259,83/12/23,8401050157

8401050234 NPDES noncompliance notification on 831013, sewage treatment plant effluent limit exceeded max limits Caused by high flows washing out solids in chlorine contact tank
Sewage lagoon will be replaced w/sewage treatment plant
BRUCH, A Tennessee Valley Authority 83/12/23 MARLAR, J
Environmental Protection Agency 2pp 21729 084 24X
Fiche 50-259,83/12/23,8401050234

8401040237 LER 83-060/01T-0 on 831214, nine of 12 two-stage Target Rock relief valves failed as-found set pressure testing Cause under vendor investigation Followup rept will be issued when cause determined W/831227 1tr
HOLDEN, E T, GREEN, H J Tennessee Valley Authority 83/12/27
O'REILLY, J P Region 2, Office of Director App 21701 156 24X
Fiche 50-256,83/12/27,8401040237

8401170248 NPDES noncompliance notification on 831221, sewage treatment plant effluent sample exceeded max permit limitations Caused by high flows overloading treatment capacity of sys
Sewage treatment plant will be replaced in 1984
BRUCH, A Tennessee Valley Authority 84/01/12 MARLAR, J
Environmental Protection Agency 2pp 21833 331 24X
Fiche 50-259,84/01/12,8401170248

8401170288 NPDES noncompliance notification on 831223, sample from condenser cooling water pumping station discharge showed H value of 9.7 Suspected to be caused by loss of sodium hydroxide from tanker trailer during unloading
BRUCH, A Tennessee Valley Authority 84/01/12 MARLAR, J
Environmental Protection Agency 2pp 21832 299 24X
Fiche 50-259,84/01/12,8401170288

01240004 PNO-II-84-002 on 840118, 12-inch raw cooling water line, located 15 ft underground, broke & flooded underground vault housing devices for treating offgas activity Cause not determined Water pumped out
CANTRELL, F S Region 2, Office of Director 84/01/18 2pp
21912 307 24X Fiche 50-259,84/01/18,8401240004

8401260348 PNO-II-84-003 on 840123, util began curtailing various refueling & mod activities which will result in layoff of 200 to 500 employees Operations not affected Media interest occurred No news release planned
CANTRELL, F S, VERRELLI, D M Region 2, Office of Director
84/01/23 1p 21955 126 24X Fiche 50-256,84/01/23,8401260348

01300181 LER 84-001-00 on 840103, during monthly operability test, diesel generator 3ED overheated Caused by overchlorination of emergency equipment cooling water sys header Main header piping flushed W/840123 1tr
LMER, J B, JONES, G T Tennessee Valley Authority 84/01/23
C - No Detailed Affiliation Given App 21997 352 24X
Fiche 50-256,84/01/23,8401300181

8401300199 NPDES noncompliance notification on 840110, grab sample for sewage treatment plant effluent exceeded max limitation High flows contributed to noncompliance
Sewage lagoon designed to replace sewage treatment plant Approval received 831222
BRUCH, A Tennessee Valley Authority 84/01/23 MARLAR, J
Environmental Protection Agency 2pp 21995 314 24X
Fiche 50-259,84/01/23,8401300199

V Operator Examinations

8401060338 Requests submittal by 840119 of selected ref matl in approved list in Encl 1 to meet schedules for written & oral licensing exams scheduled for 840316 & 19, respectively
W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/12/16
GREEN, H J Tennessee Valley Authority 2pp 21741 188 24X
Fiche 50-259,83/12/16,8401060338

DOCKET 90-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

H General correspondence

8401100154 Notifies that TL Brackin has been appointed acting reactor health physicist for PULSTAR facility Change in mailing address noted
TURINSKY, P J North Carolina State Univ, Raleigh, NC 84/01/04
MILLER, J R Standardization & Special Projects Branch 2pp,
21760 134 24X Fiche 50-297,84/01/04,8401100154

G Inspection reports, IE Bulletins & correspondence

8401240534 Forwards IE Insp Rept 50-297/83-02 on 831205-08 No violations or deviations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/22
TURINSKY, P J North Carolina State Univ, Raleigh, NC 1p
21918 166 24X Fiche 50-297,83/12/22,8401240534

--8401240552 IE Insp Rept 50-297/83-02 on 831205-08 No violations noted Major areas inspected organization, logs & records, review & audit, requalification training, procedures, surveillance tests, plant tour & open item
HARDIN, A K Region 2, Office of Director BEMIS, P R Division of Project & Resident Programs 83/12/17 5pp 21918 167 24X
Fiche 50-297,83/12/22,8401240534

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8401040477 Forwards IE Insp Rept 50-298/83-20 on 830906-09 & notice of violation
MADSEN, G L Region 4, Office of Director 83/09/23 PILANT, J M
Nebraska Public Power District 3pp 21707 195 24X
Fiche 50-298,83/09/23,8401040477

--8401040481 Notice of violation from insp on 830906-09
* Region 4, Office of Director 83/09/23 1p 21707 197 24X
Fiche 50-298,83/09/23,8401040477

--8401040486 IE Insp Rept 50-298/83-20 on 830906-09 Violation noted one fire door not included in monthly & annual insps
MURPHY, M E, HUNNICUTT, D M, JOHNSON, W D Region 4, Office of Director 83/09/22 5pp 21707 198 24X Fiche 50-298,83/09/23,8401040477

8401170326 Forwards IE Insp Rept 50-298/83-27 on 831003-07 & notice of violation
JOHNSON, E H Region 4, Office of Director 83/11/08 PILANT, J M
Nebraska Public Power District 2pp 21829 320 24X
Fiche 50-298,83/11/08,8401170326

--8401170328 Notice of violation from insp on 831003-07
* Region 4, Office of Director 83/11/08 1p 21829 322 24X
Fiche 50-298,83/11/08,8401170326

--8401170330 IE Insp Rept 50-298/83-27 on 831003-07, Violation noted. Failure to provide for independent emergency preparedness program review from 801103 to 831007
HACKNEY, C A, JAIRD, J B, HUNNICUTT, D M Region 4, Office of Director 83/11/08 5pp 21829 323 24X Fiche 50-298,83/11/08,8401170326

8401100463 Forwards FEMA evaluations of offsite emergency preparedness Util requested to coordinate w/state & local agencies to resolve noted deficiencies in timely manner. W/o encl
JOHNSON, E H Region 4, Office of Director 84/01/03 PILANT, J M
Nebraska Public Power District 2pp 21761 349 24X
Fiche 50-298,84/01/03,8401100463

DOCKETED ITEMS

117

B401230640 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21927 264 24X Fiche 50-298, 84/01/18,
8401230640

--B401230645 Forwards public version of revised Emergency Plan Implementing Procedures 5 7 11 re evacuation of nonessential site personnel & 5 7 27 re early warning sys
PILANT, J M Nebraska Public Power District 83/12/05
COLLINS, J T Region 4, Office of Director 1p 21927 265 24X
Fiche 50-298, 84/01/18, 8401230640

--B401230647 Public version of revised Emergency Plan Implementing Procedures 5 7 11 re evacuation of nonessential site personnel & 5 7 27 re early warning sys
WINDHAM, R, WHITMAN, D Nebraska Public Power District 83/11/08
1p 21927 267 24X Fiche 50-298, 84/01/18, 8401230640

B401260188 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21971 305 24X Fiche 50-298, 84/01/18,
8401260188

--B401260194 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure 5 7 4, "Site Area Emergency Implementing Procedure" & Rev 2 to Procedure 5 7 26, "Long-Term Environ Monitoring"
PILANT, J M Nebraska Public Power District 84/01/10
COLLINS, J T Region 4, Office of Director 1p 21971 306 24X
Fiche 50-298, 84/01/18, 8401260188

--B401260198 Public version of Rev 2 to Emergency Plan Implementing Procedure 5 7 4, "Site Area Emergency Implementing Procedure," & Rev 2 to Procedure 5 7 26, "Long-Term Environ Monitoring"
WINDHAM, R, WHITMAN, D Nebraska Public Power District 83/12/27
14pp 21971 308 24X Fiche 50-298, 84/01/18, 8401260188

B401300002 Releases public version of Rev 2 to Emergency Plan Implementing Procedure 5 7 2, "Notification of Unusual Event"
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22003 343 24X Fiche 50-298, 84/01/20,
8401300002

--B401300272 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure 5 7 2, "Notification of Unusual Event" w/o encl
PILANT, J M Nebraska Public Power District 83/12/23
COLLINS, J T Region 4, Office of Director 1p 22003 344 24X
Fiche 50-298, 84/01/20, 8401300002

B401300357 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22006 026 24X Fiche 50-298, 84/01/26,
8401300357

--B401300375 Public version of Rev 2 to Emergency Plan Implementing Procedure 5 7 2, "General Emergency Implementing Procedure" w/B40118 ltr
WHITMAN, D, PILANT, J M Nebraska Public Power District 84/01/06
COLLINS, J T Region 4, Office of Director 2pp 22006 027 24X
Fiche 50-298, 84/01/26, 8401300357

J Insurance & indemnity information

B401240007 Forwards Endorsement 4 to MAELU Certificate M-41 & Endorsement 4 to NELIA Certificate N-41
PILANT, J M Nebraska Public Power District 84/01/13 Office of
Nuclear Reactor Regulation, Director 3pp 21912 277 24X
Fiche 50-298, 84/01/13, 8401240007

P Operating license stage documents & correspondence

B401160012 Forwards safety evaluation accepting licensee compliance w/ NUREG-0737, Item II B 3, "Post-Accident Sampling Sys" Info submitted demonstrates ability of sys to function under expected accident conditions
VASSALLO, D B Operating Reactors Branch 2 83/12/07 PILANT, J M
Nebraska Public Power District 9pp 21821 348 24X
Fiche 50-298, 83/12/07, 8401160012

B401300025 Requests notification whether GE small break LOCA model approved on 831213 used in LOCA analysis Correct understanding completes TMI Items II K 3 30 & II K 3 31 Requests plans & schedules if understanding incorrect
VASSALLO, D B Operating Reactors Branch 2 83/12/28 PILANT, J M
Nebraska Public Power District 2pp 22006;362 24X
Fiche 50-298, 83/12/28, 8401300025

B401090382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401090382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401240189 Responds to 831228 ltr re use of Topical Rept NEDO 20566, "GE Analytical Model for Loss-of-Coolant Analysis in Accordance w/10CFR30, App K" Rept provides basis for analysis of core standby cooling sys & initial LOCA
PILANT, J M Nebraska Public Power District 84/01/16
VASSALLO, D B Operating Reactors Branch 2 1p 21908 339 24X
Fiche 50-298, 84/01/16, 8401240189

B401270083 Application for amend to License DPR-46, revising Tech Specs for standby gas treatment sys, auxiliary electrical sys, core & containment cooling sys, torus temp monitoring sys & other miscellaneous revs
KUNCE, L G Nebraska Public Power District 84/01/18 VASSALLO, D B
Operating Reactors Branch 2 3pp 21973 229 24X
Fiche 50-298, 84/01/18, 8401270083

--B401270085 Proposed Tech Spec Change 10 re standby gas sys & auxiliary electric sys, core & containment cooling sys, torus temp monitoring sys & miscellaneous revs
* Nebraska Public Power District 84/01/18 49pp 21973 232
24X Fiche 50-298, 84/01/18, 8401270083

B401270004 Advises that RP Denise replaced J Gagliardo as Director, Div of Resident Reactor Project & Engineering Programs, effective 840122
COLLINS, J T Region 4, Office of Director 84/01/23 PILANT, J M
Nebraska Public Power District 1p 21982 024 24X
Fiche 50-298, 84/01/23, 8401270004

G Inspection reports, IE Bulletins & correspondence

B401040477 Forwards IE Insp Rept 50-298/83-20 on 830906-09 & notice of violation
MADSEN, G L Region 4, Office of Director 83/09/23 PILANT, J M
Nebraska Public Power District 3pp 21707 195 24X
Fiche 50-298, 83/09/23, 8401040477

--B401040481 Notice of violation from insp on 830906-09
* Region 4, Office of Director 83/09/23 1p 21707 197 24X
Fiche 50-298, 83/09/23, 8401040477

--B401040486 IE Insp Rept 50-298/83-20 on 830906-09 Violation noted one fire door not included in monthly & annual insps
MURPHY, M E, HUNNICUTT, D M, JOHNSON, W D Region 4, Office of
Director 83/09/22 5pp 21707 198 24X Fiche 50-298, 83/09/23,
8401040477

B401060040 Responds to FDIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744-004 24X Fiche 50-000, 83/10/20,
8401060040

B401040463 Forwards IE Insp Rept 50-298/83-19 on 830822-26 No violations noted
JOHNSON, E H Region 4, Office of Director 83/11/03 PILANT, J M
Nebraska Public Power District 2pp 21707 167 24X
Fiche 50-298, 83/11/03, 8401040463

DOCKETED ITEMS

--B401040472 IE Insp Rept 50-298/B3-19 on B30622-26 No violations noted
Major areas inspected radwaste sys, liquid & gaseous effluent releases, records & repts of radioactive effluents & procedures for controlling effluent releases
HOLLEY, W L, MURRAY, B, HUMNICUTT, D M Region 4, Office of Director 83/09/08 14pp 21707 169 24X Fiche 50-298, B3/11/03, B401040463

B401170326 Forwards IE Insp Rept 50-298/B3-27 on B31003-07 & notice of violation
JOHNSON, E H Region 4, Office of Director 83/11/08 PILANT, J M Nebraska Public Power District 2pp 21829 320 24X Fiche 50-298, B3/11/08, B401170326

--B401170328 Notice of violation from insp on B31003-07
* Region 4, Office of Director 83/11/08 1p 21829 322 24X Fiche 50-298, B3/11/08, B401170326

--B401170330 IE Insp Rept 50-298/B3-27 on B31003-07 Violation noted
Failure to provide for independent emergency preparedness program review from B01103 to B31007
HACKNEY, C A, BAIRD, J B, HUMNICUTT, D M Region 4, Office of Director 83/11/08 3pp 21829 323 24X Fiche 50-298, B3/11/08, B401170326

B401040267 Forwards IF Insp Rept 50-298/B3-26 on B31017-21 & notices of violation & deviation
JOHNSON, E H Region 4, Office of Director 83/12/06 PILANT, J M Nebraska Public Power District 2pp 21703 339 24X Fiche 50-298, B3/12/06, B401040267

--B401040273 Notice of violation from insp on B31017-21
* Region 4, Office of Director 83/12/06 2pp 21703 341 24X Fiche 50-298, B3/12/06, B401040267

--B401040280 Notice of deviation from insp on B31017-21
* Region 4, Office of Director 83/12/06 1p 21703 343 24X Fiche 50-298, B3/12/06, B401040267

--B401040291 IE Insp Rept 50-298/B3-26 on B31017-21 Noncompliance noted
procedures for minor design changes not followed & safety review & audit board failed to review all safety evaluations for changes to equipment on sys
MURPHY, M E, SMITH, W F Region 4, Office of Director 83/12/06 11pp 21703 344 24X Fiche 50-298, B3/12/06, B401040267

B401090110 Forwards IE Insp Rept 50-298/B3-31 on B31001-1130 & notice of violation
JOHNSON, E H Region 4, Office of Director 83/12/23 PILANT, J M Nebraska Public Power District 2pp 21753 345 24X Fiche 50-298, B3/12/23, B401090110

--B401090124 Notice of violation from insp on B31001-1130
* Region 4, Office of Director 83/12/20 1p 21753 347 24X Fiche 50-298, B3/12/23, B401090110

-B401090133 IE Insp Rept 50-298/B3-31 on B31001-1130 Violation noted
Failure to fully insert control rods into reactor core before fuel load on B30523
DUBOIS, D L, HUMNICUTT, D M Region 4, Office of Director 83/12/15 11pp 21753 350 24X Fiche 50-298, B3/12/23, B401090110

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

2120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

2120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Leads" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184, 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

R Periodic operating reports & related correspondence

B401120401 Monthly operating rept for Nov 1983 W/B31208 ltr
BALLINGER, P L, THOMASON, P V Nebraska Public Power District 83/11/30 Office of Resource Management, Director 3pp 21791 111 24X Fiche 50-298, B3/11/30, B401120401

B401270475 Monthly operating rept for Dec 1983 W/B40105 ltr
BALLINGER, P L, THOMASON, P V Nebraska Public Power District 83/12/31 NRC - No Detailed Affiliation Given 3pp 21981.290 24X Fiche 50-298, B3/12/31, B401270475

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21957 357, 24X Fiche 50-000, B3/11/02, B401250163

--B306150117 Requests Commission review & disapprove divided emergency operations facility (EOF) concept for facilities
DIRCKS, W J Office of the Executive Director for Operations SECY-83-223 83/06/07 7pp 21958 253 24X Fiche 50-000, B3/11/02, B401250163

--B306280028 Advises that request to relocate overall accident mgt of emergency operations facility 100 miles from plant will be considered during second & third wks of June 1983 Proposal far exceeds current distance limitations
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/03 FAY, C W Wisconsin Electric Power Co 2pp 21958 291 24X Fiche 50-000, B3/11/02, B401250163

--B306280032 Requests to be advised of date & time Commissioners will consider B20406 request to relocate emergency operations facility at corporate headquarters beyond guideline distance contained in NUREG-0496
FAY, C W Wisconsin Electric Power Co 83/03/30, CHILK, S J Office of the Secretary of the Commission 1p 21958 287, 24X Fiche 50-000, B3/11/02, B401250163

B401230259 Notifies of FEMA B40112-13 radiological emergency preparedness program meetings to develop final FY84 & FY85 emergency preparedness exercise & prompt alert & notification certification schedules, respectively.
PAPERIELLO, C J Region 3, Office of Director 84/01/05 BURSTEIN, S Wisconsin Electric Power Co 3pp 21884 195 24X Fiche 50-266, B4/01/05, B401230259

B401130203 Ack receipt of B31230 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/B3-11 & 50-301/B3-19
PAPERIELLO, C J Region 3, Office of Director 84/01/10, BURSTEIN, S Wisconsin Electric Power Co 1p 21801 349 24X Fiche 50-266, B4/01/10, B401130203

--B401130211 Responds to NRC B31130 ltr re violations noted in IE Insp Repts 50-266/B3-11 & 50-301/B3-19 Corrective actions drivers & technicians required to keep written instructions on file & Westinghouse health physics instructions reviewed
FAY, C W Wisconsin Electric Power Co 83/12/30 KEPLER, J O Region 3, Office of Director 4pp 21801 350 24X Fiche 50-266, B4/01/10, B401130203

DOCKETED ITEMS

B401260250 Releases public version of revised emergency plan & emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/19 Document
Management Branch 1p 2176B 001 24X Fiche 50-266, B4/01/19, B401260250

--B401260259 Forwards public version of Rev 20 to emergency plan & emergency plan implementing procedures, including Procedures EPIP 1 1 re initial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation
FAY, C W Wisconsin Electric Power Co 83/11/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 1p 2176B 002 24X
Fiche 50-266, B4/01/19, B401260250

--B401260262 Public version of revised emergency plan implementing procedures, including Procedure EPIP 1 1 re initial classification, EPIP 1 3 re estimation of source term & EPIP 1 4 re radiological dose evaluation
* Wisconsin Electric Power Co 83/11/11 112pp 2176B 003 24X
Fiche 50-266, B4/01/19, B401260250

--B401260501 Public version of Rev 20 to emergency plan
* Wisconsin Electric Power Co 83/11/11 200pp 2176B 114 24X
Fiche 50-266, B4/01/19, B401260250

G Adjudicatory correspondence

B401100164 Order extending time until B40113 for Commission to act to review ALAB-739
CHILK, S J Office of the Secretary of the Commission 84/01/06
Commissioners 1p 21760 168 24X Fiche 50-266, B4/01/06, B401100164

B401170222 Order extending time until B40120 for Commission to act to review ALAB-739
CHILK, S J Office of the Secretary of the Commission 84/01/13
Commissioners 1p 21833 274 24X Fiche 50-266, B4/01/13, B401170222

B401230388 Order extending time until B40203 for Commission to act to review Director's Decision DD-83-14 which denied requests of Sierra Club & State of OH & B31029 decision which denied request of Environ Policy Inst
CHILK, S J Office of the Secretary of the Commission 84/01/19
Commissioners 1p 21884 278 24X Fiche 50-000, B4/01/19, B401230388

B401230476 Advises that time for Commission to review ALAB-739 expired Commission declined review Decision became final agency action on B40120
CHILK, S J Office of the Secretary of the Commission 84/01/20
ANDERSON, P Wisconsin's Environmental Decade 1p 21882 191 24X
Fiche 50-266, B4/01/20, B401230476

J Insurance & indemnity information

B401230412 Forwards listed endorsements to NELIA Policy NF-17B, MAELU Policy MF-53, NELIA Certificates N-18 & N-19 & MAELU Certificates M-18 & M-19
DUNDAS, W J Wisconsin Electric Power Co 84/01/13 NRC - No
Detailed Affiliation Given 7pp 21879 138 24X
Fiche 50-266, B4/01/13, B401230412

P. Operating license stage documents & correspondence

B401030208 Application for amend to Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 95, revising surveillance interval for evaluating integrity of post-accident recovery sys outside containment
FAY, C W Wisconsin Electric Power Co 83/12/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21682 292 24X
Fiche 50-266, B3/12/23, B401030208

--B401030211 Proposed Tech Spec Table 15 4 1-2 re surveillance interval for evaluating integrity of post-accident recovery sys outside containment
* Wisconsin Electric Power Co 83/12/23 1p 21682 294 24X
Fiche 50-266, B3/12/23, B401030208

B401050017 Forwards Amends 80 & 84 to Licenses DPR-24 & DPR-27, respectively Amends revise monthly testing of automatic actuation logic circuitry for auxiliary feedwater pumps W/o encl
MILLER, J R Operating Reactors Branch 3 83/12/28 FAY, C W
Wisconsin Electric Power Co 2pp 21736 173 24X
Fiche 50-266, B3/12/28, B401050017

B40110304 Forwards Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends add addl reporting requirement to rept all challenges to pressurizer power operated relief & safety valves in annual rept
COLBURN, T G Operating Reactors Branch 3 83/12/28 FAY, C W
Wisconsin Electric Power Co 2pp 21795 015 24X
Fiche 50-266, B3/12/28, B40110304

--B40110330 Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively adding addl reporting requirement to rept all challenges to pressurizer power operated relief & safety valves in annual rept
MILLER, J R Operating Reactors Branch 3 83/12/28 FAY, C W
21795 017 24X Fiche 50-266, B3/12/28, B40110304

--B40110332 Safety evaluation supporting Amends 79 & 84 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director MILLER, J R
21795 023 24X Fiche 50-266, B3/12/28, B40110304

B401050284 Submits further response to Generic Ltr B3-10D, of TMI Action Item 11 K 3 5, 'Automatic Trip of Reactor Coolant Pumps' Commitment to use Rev 1 to emergency response guidelines will be revised to Dec 1984
FAY, C W Wisconsin Electric Power Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 21726 349 24X Fiche 50-266, B401050284

B401120112 Forwards exemption from scheduler requirements for installation of RCS high point gas vents until B41231
MILLER, J R Operating Reactors Branch 3 83/12/30 FAY, C W
Wisconsin Electric Power Co 2pp 21805 221 24X
Fiche 50-266, B3/12/30, B401120112

--B401120120 Exemption from scheduler requirements of 10CFR installation of RCS high point gas vents until B41231
EISENHUT, D G Division of Licensing 83/12/30 Wisconsin Electric Power Co 5pp 21805 223 24X Fiche 50-266, B401120112

B401170137 Responds to B30930 request for extension until J implementation of licensed operator staffing rule, 10CFR 50.61 (M)(2) Addl info required to complete action on request will be discussed at meeting scheduled for B40110
MILLER, J R Operating Reactors Branch 3 83/12/30 FAY, C W
Wisconsin Electric Power Co 2pp 21871 019 24X
Fiche 50-266, B3/12/30, B401170137

B401130120 Grants B31010 request for extension of deadline for final environ qualification of Crosby lift indicating assemblies for facilities Extension granted until end of refueling outages beginning in Spring 1985
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/03 BURSTEIN, S
Wisconsin Electric Power Co 4pp 21820 285 24X Fiche 50-266, B4/01/03, B401130120

B401100469 Responds to Generic Ltr B3-41, "Fast Cold Starts Generators," providing data on number of fast cold starts from Dec 1982 to Dec 1983 Increased testing frequency inappropriate
FAY, C W Wisconsin Electric Power Co 84/01/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21717 019 24X
Fiche 50-266, B4/01/04, B401100469

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Edison Co of New York, Inc 18pp 21946 170 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & fuel assemblies re notice of meeting on facility staffing, Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401190419 Forwards Rev 1, to "Inservice Testing Programs for Valves" per NRC B30824 ltr Relief from ASME Code inservice testing requirements, per 770217 & 781127 applications for amend, requested
FAY, C W Wisconsin Electric Power Co 84/01/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21736 173 24X
Fiche 50-266, B4/01/16, B401190419

DOCKETED ITEMS

--8401190422 Rev 1 to "Inservice Testing Program for Pumps & Valves"
Relief requests encl
* Wisconsin Electric Power Co 84/01/06 124pp 21849 047 24X
Fiche 50-266,84/01/16,8401190419

8401270045 Discusses steps taken to increase & stabilize operator
staffing, per Generic Ltr 84-02 NRC should clarify position
re placement of operator trainees in operating plants at
840125 meeting
BURSTEIN, S Wisconsin Electric Power Co 84/01/18 EISENHUT, D G
Division of Licensing 3pp 21982 018 24X Fiche 50-266,84/01/18,
8401270045

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401130387 Responds to IE Bulletin 79-14 re as-built safety-related
piping sys Isometric drawings affected by mechanical
corrections revised & reissued showing as-built
configuration Activities required by bulletin complete
FAY, C W Wisconsin Electric Power Co 84/01/04 KEPLER, J G
Region 3, Office of Director 1p 21798 357 24X
Fiche 50-266,84/01/04,8401130387

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401130203 Ack receipt of 831230 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-266/83-11 &
50-301/83-19
PAPERIELLO, C J Region 3, Office of Director 84/01/10
BURSTEIN, S Wisconsin Electric Power Co 1p 21801 349 24X
Fiche 50-266,84/01/10,8401130203

--8401130211 Responds to NRC 831130 ltr re violations noted in IE Insp
Repts 50-266/83-11 & 50-301/83-19 Corrective actions drivers
& technicians required to keep written instructions on file &
Hestingshouse health physics instructions reviewed
FAY, C W Wisconsin Electric Power Co 83/12/30 KEPLER, J G
Region 3, Office of Director 4pp 21801 350 24X
Fiche 50-266,84/01/10,8401130203

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators" Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401240072 Responds to IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Breakers not in
use in other applications
FAY, C W Wisconsin Electric Power Co 84/01/20 KEPLER, J G
Region 3, Office of Director 1p 21913 216 24X
Fiche 50-266,84/01/20,8401240072

R Periodic operating reports & related correspondence

8401170192 Monthly operating repts for Dec 1983 W/840110 ltr
FAY, C W, FAY, C W Wisconsin Electric Power Co 83/12/31 NRC -
No Detailed Affiliation Given 9pp 21831 885 24X
Fiche 50-266,83/12/31,8401170192

X Onsite Storage of Low Level Waste

8401300070 Documents implementation of new 10CFR61 regulation, effective
831227, re waste classification, waste form & high integrity
containers Process control program will be updated by
840701
FAY, C W Wisconsin Electric Power Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21999 161
24X Fiche 50-266,84/01/20,8401300070

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8401100475 Forwards IE Safeguards Insp Rept 50-302/83-21 on 830801-05 &
notice of violation Notice of violation & insp rept details
withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/11/28 WILGUS, W S
Florida Power Corp 2pp 21761 301 24X Fiche 50-302,83/11/28,
8401100475

--8401100480 IE Safeguards Insp Rept 50-302/83-21 on 830801-05
Noncompliance noted inadequate vital area barrier &
violation of escort requirements Details withheld
(ref 10CFR73 21)
URYC, D, MCQUIRE, D R Division of Emergency Preparedness &
Materials Safety 83/09/22 1p 21761 303 24X
Fiche 50-302,83/11/28,8401100475

8401050543 Ack receipt of 831222 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Rept
50-302/83-28
LEWIS, R C Division of Project & Resident Programs 84/01/03
WILGUS, W S Florida Power Corp 1p 21726 138 24X
Fiche 50-302,84/01/03,8401050543

--8401050551 Responds to NRC 831127 ltr re violations noted in IE
Safeguards Insp Rept 50-302/83-28 Corrective actions
withheld
BAYNARD, P Y Florida Power Corp 83/12/22 O'REILLY, J P Region 2,
Office of Director 1p 21726 139 24X Fiche 50-302,84/01/03,
8401050543

--8401050559 Forwards IE Safeguards Insp Rept 50-302/83-28 on 831017-21 &
notice of violation Notice withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 83/11/29
WILGUS, W S Florida Power Corp 2pp 21726 140 24X
Fiche 50-302,84/01/03,8401050543

--8401050568 IE Safeguards Insp Rept 50-302/83-28 on 831017-21 Violation
noted Details withheld (ref 10CFR73 21)
HALL, D L, MCQUIRE, D R Region 2, Office of Director 83/11/21
1p 21726 142 24X Fiche 50-302,84/01/03,8401050543

8401090323 Ack receipt of 831220 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/83-26
LEWIS, R C Division of Project & Resident Programs 84/01/03
WILGUS, W S Florida Power Corp 1p 21754 138 24X
Fiche 50-302,84/01/03,8401090323

--8401090361 IE Insp Rept 50-302/83-26 on 830831-0922 Noncompliance
noted failure to meet limiting condition of operation for
reactor coolant pump power monitors
BETKA, T F Region 2, Office of Director, PANCIERA, V Division
of Project & Resident Programs 83/11/01 11pp 21754 145 24X
Fiche 50-302,84/01/03,8401090323

8401240421 Forwards summary of licensee safeguards 831220 meeting
w/util in Region 11 ofc to discuss forthcoming changes to
physical security plan in order to reduce impact on security
& operations
LEWIS, R C Division of Project & Resident Programs 84/01/05
WILGUS, W S Florida Power Corp 3pp 21913 200 24X
Fiche 50-302,84/01/05,8401240421

DOCKETED ITEMS

121

B401100420 Ack receipt of B31223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-21
Implementation of corrective actions will be examined during future insps
O'REILLY, J P Region 2, Office of Director 84/01/06 WILGUS, W S
Florida Power Corp 1p 21763 115 24X Fiche 50-302, 84/01/06, B401100420

--B401100425 Forwards response to NRC B31128 ltr re violations noted in IE Insp Rept 50-302/83-21 Corrective action withheld
BAYNARD, P Y Florida Power Corp 83/12/23 O'REILLY, J P Region 2, Office of Director 1p 21763 116 24X Fiche 50-302, 84/01/06, B401100420

B401240419 Ack receipt of B30902 & 16 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-17
Violations clarified
O'REILLY, J P Region 2, Office of Director 84/01/06 WILGUS, W S
Florida Power Corp 2pp 21916 027 24X Fiche 50-302, 84/01/06, B401240419

--B401240433 Forwards IE Insp Rept 50-302/83-17 on B30531-0627 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/05
WILGUS, W S Florida Power Corp 2pp 21916 035 24X
Fiche 50-302, 84/01/06, B401240419

--B401240446 IE Insp Rept 50-302/83-17 on B30531-0627 Violation noted failure to rept procedural inadequacy that could have prevented safety sys from functioning & to test containment isolation valves in accident flow direction
BETKA, T F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/08/04 12pp 21916 039 24X
Fiche 50-302, 84/01/06, B401240419

P Operating license stage documents & correspondence

B401240142 Forwards request for addl info re B30610 GA program
LEWIS, R C Division of Project & Resident Programs 83/12/27
WILGUS, W S Florida Power Corp Bpp 21910 279 24X
Fiche 50-302, 83/12/27, B401240142

B401100406 Responds to NRC B31006 request for plan of action re improvement of LPIS availability per TMI Item II K 3 17
Primary reason for high unavailability caused by malfunction of valves DHV-110 & DHV-111 Analog control sys installed.
WESTAFER, O R Florida Power Corp 84/01/03 STOLZ, J F Operating Reactors Branch 4 2pp 21762 286 24X Fiche 50-302, 84/01/03, B401100406

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, B401090221

B401260467 Summary of B31215 meeting w/util, Gilbert Assoc & NUS Corp in Bethesda, MD re safety-related electrical equipment qualifications program to resolve open items in B30111
technical evaluation rept
HERNAN, R Operating Reactors Branch 4 84/01/10 Operating Reactors Branch 4 16pp 21959 301 24X Fiche 50-302, 84/01/10, B401260467

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401180200 Advises that diesel generators not subjected to cold fast starts for surveillance testing & maint activities, per Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators" Small percentage of total starts w/o prelubrication noted
WILGUS, W S Florida Power Corp 84/01/13 EISENHUT, D G Division of Licensing 3pp 21841 330 24X Fiche 50-302, 84/01/13, B401180200

B401200222 Application for Tech Spec Change Request 111 for amend to License DPR-72 re silicon controlled rectifiers associated w/control rod trip breakers in response to Generic Ltr B3-28
WESTAFER, O R Florida Power Corp 84/01/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 21867 039 24X
Fiche 50-302, 84/01/16, B401200222

--B401200224 Proposed Tech Spec re control trip breakers, per Generic Ltr B3-28
* Florida Power Corp 84/01/16 3pp 21867 044 24X
Fiche 50-302, 84/01/16, B401200222

B401230405 Application for amend to License DPR-72 & proposed Tech Spec Change Request 106, Rev 1 re control of personnel access to high radiation areas Certificate of Svc encl
WESTAFER, O R Florida Power Corp 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 21879 123 24X
Fiche 50-302, 84/01/17, B401230405

--B401230413 Tech Spec Change Request 106, Rev 1 proposing that unenclosed areas w/1,000 m/h dose rate be roped off, conspicuously posted & flashing light activated as warning device
* Florida Power Corp 84/01/17 2pp 21879 127 24X
Fiche 50-302, 84/01/17, B401230405

B401310078 Forwards corrected transmittal ltr & safety evaluation of util response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re accident monitoring instrumentation
STOLZ, J F Operating Reactors Branch 4 84/01/18 WILGUS, W S
Florida Power Corp 1p 22029 347 24X Fiche 50-302, 84/01/18, B401310078

--B401310082 Forwards safety evaluation of util B21018 response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re accident monitoring instrumentation Requirements of NUREG items met
STOLZ, J F Operating Reactors Branch 4 84/01/18 WILGUS, W S
Florida Power Corp 10pp 22029 348 24X Fiche 50-302, 84/01/18, B401310078

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to F01A request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401100475 Forwards IE Safeguards Insp Rept 50-302/83-21 on B30801-05 notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/11/28 WILGUS, W S
Florida Power Corp 2pp 21761 301 24X Fiche 50-302, 83/11/28, B401100475

--B401100480 IE Safeguards Insp Rept 50-302/83-21 on B30801-05 Noncompliance noted inadequate vital area barrier & violation of escort requirements Details withheld (ref 10CFR73 21)
URVC, B . MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/09/22 1p 21761 303 24X
Fiche 50-302, 83/11/28, B401100475

B401050469 Responds to B31129 request for addl info on IE Bulletin 80-11, "Masonry Wall Design" Requested info will be provided by B40227
WESTAFER, O R Florida Power Corp 83/12/13 STOLZ, J F Operating Reactors Branch 4 1p 21729 362 24X Fiche 50-302, 83/12/13, B401050469

B401060387 Forwards final SALP Rept 50-302/83-22 for Jul 1982 - June 1983
O'REILLY, J P Region 2, Office of Director 83/12/13 WILGUS, W S
Florida Power Corp 2pp 21741 127 24X Fiche 50-302, 83/12/13, B401060387

--B401060392 Forwards interim SALP Rept 50-302/83-22 for Jul 1982 - June 1983 Meeting scheduled for B31020 to discuss rept
LEWIS, R C Division of Project & Resident Programs 83/10/14
WILGUS, W S Florida Power Corp 2pp 21741 129 24X
Fiche 50-302, 83/12/13, B401060387

--B401060393 SALP Rept 50-302/83-22 for Jul 1982 - June 1983
* Region 2, Office of Director 83/12/13 25pp 21741 131 24X
Fiche 50-302, 83/12/13, B401060387

DOCKETED ITEMS

- B401060397 Ack receipt of B31014 ltr re SALP rept for Jul 1982 - June 1983 Util concurs w/basic conclusions of Rept
BAYNARD, P Y Florida Power Corp 83/11/09 LEWIS, R C Division
of Project & Resident Programs 2pp 21741 156 24X
Fiche 50-302, 83/12/13, B401060387
- B401050602 Ack receipt of B30921, 1012 & 1130 ltrs informing NRC of
steps taken to correct violations noted in IE Insp Rept
50-302/83-18
LEWIS, R C Division of Project & Resident Programs 83/12/21
WILGUS, W S Florida Power Corp 1p 21729 209 24X
Fiche 50-302, 83/12/21, B401050602
- B401050612 Responds to NRC B30822 ltr re violations noted in IE Insp
Rept 50-302/83-18 Corrective actions identified errors will
be completed by B40131 & addl deficiencies corrected by
B40917
BAYNARD, P Y Florida Power Corp 83/11/30 O'REILLY, J P Region
2, Office of Director 3pp 21725 210 24X Fiche 50-302,
83/12/21, B401050602
- B401050619 Responds to NRC B30822 ltr re violations noted in IE Insp
Rept 50-302/83-18 Corrective actions action to correct
drawing errors incorporated into mods initiated
WESTAFER, G R Florida Power Corp 83/10/12 O'REILLY, J P
Region 2, Office of Director 4pp 21723 213 24X
Fiche 50-302, 83/12/21, B401050602
- B401050629 Responds to IE Insp Rept 50-302/83-18 Requests extension
until B31012 to analyze cause Initial corrective action
ineffective
WILGUS, W S Florida Power Corp 83/09/21 O'REILLY, J P Region
2, Office of Director 1p 21723 217 24X Fiche 50-302, 83/12/21,
B401050602
- B401050635 Forwards IE Insp Rept 50-302/83-18 on B30628-0729 & notice
of violation
LEWIS, R C Division of Project & Resident Programs 83/08/22
WILGUS, W S Florida Power Corp 2pp 21723 218 24X
Fiche 50-302, 83/12/21, B401050602
- B401050640 Notice of violation from insp on B30628-0729
* Region 2, Office of Director 83/08/22 2pp 21723 220 24X
Fiche 50-302, 83/12/21, B401050602
- B401050648 IE Insp Rept 50-302/83-18 on B30628-0729 Violation noted
failure to complete corrective actions & prevent recurrence
of nonconformances in response to IE Insp Rept 50-302/82-11
re valve lineups
STETKA, T F Region 2, Office of Director PANCIERA, V Division
of Project & Resident Programs 83/12/21 12pp 21723 222 24X
Fiche 50-302, 83/12/21, B401050602
- B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090
- B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type SHK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093
- B401030543 Ack receipt of B31222 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Rept
50-302/83-28
LEWIS, R C Division of Project & Resident Programs 84/01/03
WILGUS, W S Florida Power Corp 1p 21726 138 24X
Fiche 50-302, 84/01/03, B401030543
- B401050551 Responds to NRC B31129 ltr re violations noted in IE
Safeguards Insp Rept 50-302/83-28 Corrective actions
withheld
BAYNARD, P Y Florida Power Corp 83/12/22 O'REILLY, J P Region
2, Office of Director 1p 21726 139 24X Fiche 50-302, 84/01/03,
B401050543
- B401050559 Forwards IE Safeguards Insp Rept 50-302/83-28 on B31017-21 &
notice of violation Notice withheld (ref 10CFR73.21)
LEWIS, R C Division of Project & Resident Programs 83/11/29
WILGUS, W S Florida Power Corp 2pp 21726 140 24X
Fiche 50-302, 84/01/03, B401050543
- B401050568 IE Safeguards Insp Rept 50-302/83-28 on B31017-21 Violation
noted Details withheld (ref 10CFR73.21)
HALL, B L, McGUIRE, D R Region 2, Office of Director 83/11/21
1p 21726 142 24X Fiche 50-302, 84/01/03, B401050543
- B401090323 Ack receipt of B31220 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/83-26
LEWIS, R C Division of Project & Resident Programs 84/01/03
WILGUS, W S Florida Power Corp 1p 21754 138 24X
Fiche 50-302, 84/01/03, B401090323
- B401090336 Responds to NRC B31121 ltr re violations noted in IE Insp
Rept 50-302/83-26 Corrective actions review of Tech Spec
amends expanded to include operations qualified reviewer &
immediate temporary change issued on B30911
BAYNARD, P Y Florida Power Corp 83/12/20 O'REILLY, J P Region
2, Office of Director 3pp 21754 139 24X Fiche 50-302,
84/01/03, B401090323
- B401090352 Forwards IE Insp Rept 50-302/83-26 on B30821-0922 & notice
of violation
LEWIS, R C Division of Project & Resident Programs 83/11/21
WILGUS, W S Florida Power Corp 2pp 21754 142 24X
Fiche 50-302, 84/01/03, B401090323
- B401090355 Notice of violation from insp on B30831-0922
* Region 2, Office of Director 83/11/21 1p 21754 144 24X
Fiche 50-302, 84/01/03, B401090323
- B401090361 IE Insp Rept 50-302/83-26 on B30831-0922 Noncompliance
noted failure to meet limiting condition of operation for
reactor coolant pump power monitors
STETKA, T F Region 2, Office of Director PANCIERA, V Division
of Project & Resident Programs 83/11/01 11pp 21754 145 24X
Fiche 50-302, 84/01/03, B401090323
- B401090420 Ack receipt of B30712 & 1216 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Rept
50-302/83-14
DANCE, H C Division of Project & Resident Programs 84/01/03
WILGUS, W S Florida Power Corp 1p 21753 232 24X
Fiche 50-302, 84/01/03, B401090420
- B401090425 Forwards supplemental response to B30617 ltr re violations
noted in IE Insp Rept 50-302/83-14 Corrective actions all
other applicable welds reviewed to verify proper weld
coverage No discrepancies revealed
WESTAFER, G R Florida Power Corp 83/12/16 O'REILLY, J P
Region 2, Office of Director 2pp 21753 253 24X
Fiche 50-302, 84/01/03, B401090420
- B401090433 Responds to NRC B30617 ltr re violations noted in IE Insp
Rept 50-302/83-14 Corrective actions pipe weld Figure
CB 1 16 reexamined No defects identified Request to revise
Radiographic Procedure RT-002 initiated
WESTAFER, G R Florida Power Corp 83/07/12 O'REILLY, J P
Region 2, Office of Director 2pp 21753 255 24X
Fiche 50-302, 84/01/03, B401090420
- B401090443 Forwards IE Insp Rept 50-302/83-14 on B30510-13 & 17-20 &
notice of violation
LEWIS, R C Division of Project & Resident Programs 83/06/17
WILGUS, W S Florida Power Corp 2pp 21753 257 24X
Fiche 50-302, 84/01/03, B401090420
- B401090445 Notice of violation from insp on B30510-13 & 17-20
* Region 2, Office of Director 83/06/17 1p 21753 259 24X
Fiche 50-302, 84/01/03, B401090420
- B401090451 IE Insp Rept 50-302/83-14 on B30510-13 & 17-20 Violation
noted failure to meet ASME Code Section XI re volumetric
exam of pipe welds & to meet IWB/IWC-2520 insp requirements
ECONOMOS, N Region 2, Office of Director BLAKE, J J Division of
Engineering & Operational Programs 83/06/15 11pp 21753 260
24X Fiche 50-302, 84/01/03, B401090420
- B401100420 Ack receipt of B31223 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/83-21
Implementation of corrective actions will be examined during
future insps
O'REILLY, J P Region 2, Office of Director 84/01/06 WILGUS, W S
Florida Power Corp 1p 21763 115 24X Fiche 50-302, 84/01/06,
B401100420
- B401100425 Forwards response to NRC B31128 ltr re violations noted in
IE Insp Rept 50-302/83-21 Corrective action withheld
BAYNARD, P Y Florida Power Corp 83/12/23 O'REILLY, J P Region
2, Office of Director 1p 21763 116 24X Fiche 50-302, 84/01/06,
B401100420
- B401240419 Ack receipt of B30902 & 16 ltrs informing NRC of steps taken
to correct violations noted in IE Insp Rept 50-302/83-17
Violations clarified
O'REILLY, J P Region 2, Office of Director 84/01/06 WILGUS, W S
Florida Power Corp 2pp 21916 027 24X Fiche 50-302, 84/01/06,
B401240419

--8401240423 Responds to NRC 830805 ltr re violations noted in IE Insp Rept 50-302/83-17 Corrective actions containment leak test revised to test valves HSBV-3,4,5 & 6 in direction of post-accident flow
WESTAFER, G R Florida Power Corp 83/09/16 O'REILLY, J P
Region 2, Office of Director 5pp 21916 029 24X
Fiche 50-302,84/01/06,8401240419

--8401240429 Advises that response to IE Insp Rept 50-302/83-17, due 830902, will be submitted 830916 Addl time necessary for further mgt review of violations due to complex nature of issues involved
BAYNARD, P Y Florida Power Corp 83/09/02 O'REILLY, J P Region 2, Office of Director 1p 21916 034 24X Fiche 50-302,84/01/06,8401240419

--8401240433 Forwards IE Insp Rept 50-302/83-17 on 830931-0627 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/08/05
WILGUS, W S Florida Power Corp 2pp 21916 035 24X
Fiche 50-302,84/01/06,8401240419

--8401240439 Notice of violation from insp on 830931-0627
* Region 2, Office of Director 83/08/05 2pp 21916 037 24X
Fiche 50-302,84/01/06,8401240419

--8401240446 IE Insp Rept 50-302/83-17 on 830931-0627 Violation noted Failure to rept procedural inadequacy that could have prevented safety sys from functioning & to test containment isolation valves in accident flow direction
STETKA, T F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/08/04 12pp 21916 039 24X
Fiche 50-302,84/01/06,8401240419

8401240562 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-23
LEWIS, R C Division of Project & Resident Programs 84/01/09
WILGUS, W S Florida Power Corp 1p 21909 080 24X
Fiche 50-302,84/01/09,8401240562

--8401240568 Forwards response to NRC 831107 ltr re violations noted in IE Insp Rept 50-302/83-23 Corrective actions short-term instruction issued to operations personnel for independent verification of switches & breakers
BAYNARD, P Y Florida Power Corp 83/12/22 O'REILLY, J P Region 2, Office of Director 3pp 21909 081 24X Fiche 50-302,84/01/09,8401240562

--8401240575 Notifies NRC of delay in submitting LERs 83-051 & 83-052 & response to IE Insp Rept 50-302/83-23 Addl investigation & mgt reviews required
SIMPSON, E C Florida Power Corp 83/12/07 O'REILLY, J P Region 2, Office of Director 1p 21909 084 24X Fiche 50-302,84/01/09,8401240562

--8401240581 Forwards IE Insp Rept 50-302/83-23 on 830730-0830 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07
WILGUS, W S Florida Power Corp 2pp 21909 085 24X
Fiche 50-302,84/01/09,8401240562

--8401240585 Notice of violation from insp on 830730-0830
* Region 2, Office of Director 83/11/07 1p 21909 087 24X
Fiche 50-302,84/01/09,8401240562

--8401240589 IE Insp Rept 50-302/83-23 on 830730-0830 Noncompliance noted failure to meet intent of NUREG-0737, Item I C & re independent verification of sys & components
STETKA, T F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/11/02 6pp 21909 088 24X
Fiche 50-302,84/01/09,8401240562

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Breezings " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401240391 Ack receipt of 840103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-27
LEWIS, R C Division of Project & Resident Programs 84/01/11
WILGUS, W S Florida Power Corp 1p 21908 001 24X
Fiche 50-302,84/01/11,8401240391

--8401240394 Responds to NRC 831205 ltr re violations noted in IE Insp Rept 50-302/83-27 Corrective actions RCS leakage determination satisfactorily completed & automated tracking program for control rod 3 initiated
WESTAFER, G R Florida Power Corp 83/01/03 O'REILLY, J P Region 2, Office of Director 4pp 21908 002 24X
Fiche 50-302,84/01/11,8401240391

--8401240396 Forwards IE Insp Rept 50-302/83-27 on 830923-1027 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/12/05
WILGUS, W S Florida Power Corp 2pp 21908 005 24X
Fiche 50-302,84/01/11,8401240391

--8401240399 Notice of violation from insp on 830923-1027
* Region 2, Office of Director 83/12/05 2pp 21908 008 24X
Fiche 50-302,84/01/11,8401240391

--8401240401 IE Insp Rept 50-302/83-27 on 830923-1027 Violations noted failure to determine RCS leakage within required surveillance interval & to review & approve control rod drive procedures prior to implementation
STETKA, T F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/12/02 12pp 21908 010 24X
Fiche 50-302,84/01/11,8401240391

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401160167 Monthly operating rept for Dec 1983 W/840109 ltr
GRAHAM, D, WESTAFER, G R Florida Power Corp 83/12/31
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 21815 332 24X Fiche 50-302,83/12/31,8401160167

8401100304 Forwards ltrs submitted to EPA re 316 study info, per ETS, Part II, Section 3.2 re thermal impacts from plant operation & larval entrainment & adult impingement
WESTAFER, G R Florida Power Corp 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21763 143 24X
Fiche 50-302,84/01/05,8401100304

--8401100309 "First Quarterly Progress Rept, Crystal River Studies "
* Stone & Webster Engineering Corp 83/11/30 4pp 21763 145
24X Fiche 50-302,84/01/05,8401100304

8401240206 Forwards "Second Quarterly Progress Rept, Crystal River Studies " & "Plan of Study Summary " per Tech Specs, App B, Part II, Section 3.2, submitted to EPA
WESTAFER, G R Florida Power Corp 84/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21917 148 24X
Fiche 50-302,84/01/19,8401240206

--8401240212 "Second Quarterly Progress Rept, Crystal River Studies "
* Stone & Webster Engineering Corp * Mote Marine Laboratory
84/01/03 200pp 21917 150 24X Fiche 50-302,84/01/19,8401240206

--8401240219 "Plan of Study Summary "
* Florida Power Corp 84/01/19 90pp 21917 351 24X
Fiche 50-302,84/01/19,8401240206

S Reportable occurrences, LERs & related correspondence

8401030077 LER 83-055/03L-0 on 831118, ESF actuation sys Train A Channel RC4 failed to ack low pressure injection bistable trip
Caused by mercury wetted relay failing to operate properly
Mercury relay card assembly replaced W/831219 ltr
BUFE, J L, BAYNARD, P Y Florida Power Corp 83/12/19
O'REILLY, J P Region 2, Office of Director 3pp 21683 196 24X
Fiche 50-302,83/12/19,8401030077

DOCKETED ITEMS

B401030236 LER 83-057/03L-0 on 831122, during emergency feedwater sys operability demonstration, motor actuator for turbine driven emergency feedwater pump steam admission valve ASV-5 found inoperable. Caused by contact failure W/B31220 ltr
CARBIENER, R E , BAYNARD, P Y Florida Power Corp 83/12/20
O'REILLY, J P Region 2, Office of Director 3pp 21682 325 24X
Fiche 50-302, 83/12/20, B401030236

B401030276 LER 83-056/03L-0 on 831122, during Surveillance Procedure SP-3498, governor on emergency feedwater pump discovered incorrectly set. Caused by inadvertent error in knob setting W/B31220 ltr
CARBIENER, R E , BAYNARD, P Y Florida Power Corp 83/12/20
O'REILLY, J P Region 2, Office of Director 2pp 21681 001 24X
Fiche 50-302, 83/12/20, B401030276

B401040248 LER 83-050/03L-0 on 830717, mode ascension occurred prior to completing surveillance testing of LPIS & engineered safeguards components. Caused by inadequate procedures. Procedures revised W/B31222 ltr
BUFE, J L , BAYNARD, P Y Florida Power Corp 83/12/22
O'REILLY, J P Region 2, Office of Director 4pp 21701 294 24X
Fiche 50-302, 83/12/22, B401040248

B401040314 LER 83-058/03L-0 on 831103, during maint on 120-volt ac vital bus transfer switch, fuse blew, rendering inverter 3A inoperable. Caused by maint personnel inadvertently shorting out lamp base inverter repaired W/B31222 ltr
CARBIENER, R E , BAYNARD, P Y Florida Power Corp 83/12/22
O'REILLY, J P Region 2, Office of Director 3pp 21708 028 24X
Fiche 50-302, 83/12/22, B401040314

B401040143 LER 83-059/03L-0 on 831125, 27, 1206 & 08, multipoint recorder for post-accident monitoring sys inoperable. Caused by inadequate procedure, shorted input wire, worn slip clutch & worn bushing, respectively W/B31227 ltr
CARBIENER, R E , BAYNARD, P Y Florida Power Corp 83/12/27
O'REILLY, J P Region 2, Office of Director 4pp 21702 036 24X
Fiche 50-302, 83/12/27, B401040143

01050641 LER 83-060/03L-0 on 831129, decay heat cooler B discharge temp indicator DH-2-T12 found indicating erroneously. Cause unknown. Component will be monitored W/B31229 ltr
CARBIENER, R E , BAYNARD, P Y Florida Power Corp 83/12/29
O'REILLY, J P Region 2, Office of Director 3pp 21725 193 24X
Fiche 50-302, 83/12/29, B401050641

B401120395 LER 83-061/03L-0 on 831204, while performing control rod exercises, absolute position indication for rod A, group 2 failed to indicate +/- 2% motion. Caused by failed reed switch. Indicator tube will be replaced W/B40103 ltr
BUFE, J L , WESTAFER, G R Florida Power Corp 84/01/03
O'REILLY, J P Region 2, Office of Director 3pp 21791 085 24X
Fiche 50-302, 84/01/03, B401120395

B401120414 Updated LER 83-053/03L-1 on 831109, safety-related hydraulic snubber MSH-252 declared inoperable when lack of oil level indication noted in sightglass. Caused by loose jam-nut on stationary end of snubber, allowing rotation W/B40106 ltr
BUFE, J L , WESTAFER, G R Florida Power Corp 84/01/06
O'REILLY, J P Region 2, Office of Director 3pp 21791 163 24X
Fiche 50-302, 84/01/06, B401120414

B401120419 Updated LER 83-058/03L-1 on 831103, while performing maint on 120-volt ac vital bus transfer switch, fuse blew, rendering inverter 3A inoperable. Caused by personnel inadvertently shorting out lamp base inverter repaired W/B40106 ltr
CARBIENER, R E , WESTAFER, G R Florida Power Corp 84/01/06
O'REILLY, J P Region 2, Office of Director 3pp 21791 037 24X
Fiche 50-302, 84/01/06, B401120419

B401130160 LER 83-062/03L-0 on 831208, recorder for reactor bldg pressure (BS-65-PR) determined inoperable. Caused by procedural inadequacy. Revised drawing used for mod omitted wire to recorder. Correction installed 831227 W/B40106 ltr
CARBIENER, R E , WESTAFER, G R Florida Power Corp 84/01/06
O'REILLY, J P Region 2, Office of Director 3pp 21802 227 24X
Fiche 50-302, 84/01/06, B401130160

B401160298 NPDES noncompliance notification on 831226 & 27, temp limits exceeded. Caused by massive inflow of dead & stunned fish as result of rapidly declining cooling water temp accompanied by high winds intake structures cleaned
WESTAFER, G R Florida Power Corp 84/01/09, DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 21814 339 24X
Fiche 50-302, 84/01/09, B401160298

B401240135 LER 83-063/01T-0 on 831226, while performing routine surveillance, level indicators FS-1-L1 & FS-2-L1 & sensing lines for fire svc tanks found frozen. Caused by unusually cold weather. Water added to tanks W/B40107 ltr
WESTAFER, G R , MANSFIELD, S D Florida Power Corp 84/01/09
O'REILLY, J P Region 2, Office of Director 3pp 21911 111 24X
Fiche 50-302, 84/01/09, B401240135

B401230401 Updated LER 83-030/03X-1 on 830721, during routine surveillance, once-through steam generator A operating range level recorder indicated level corresponding to 119 inches, rendering recorder inoperable W/B40110 ltr
CULLEN, D P , BUFE, J L , WESTAFER, G R Florida Power Corp 84/01/10
O'REILLY, J P Region 2, Office of Director 5pp 21882 213 24X
Fiche 50-302, 84/01/10, B401230401

B401300323 LER 83-064/03L-0 on 831219, during routine walkdown of control room, reactor bldg radiation monitor RM-A6 indicated low flow alarm. Caused by blown lamp in local indicator lamp & fuse replaced W/B40118 ltr
CARBIENER, R E , WESTAFER, G R Florida Power Corp 84/01/18
O'REILLY, J P Region 2, Office of Director 3pp 21996 290 24X
Fiche 50-302, 84/01/18, B401300323

X Onsite Storage of Low Level Waste

B401120107 Advises that util will use NSA/IMPELL rept, "Methodologies for Classification of Low Level Radwaste From Nuclear Power Plants," in order to comply w/requirements of 10CFR61. Revised process control program due by 840229
BAYNARD, P Y Florida Power Corp 83/12/27, STOLZ, J P Operating Reactors Branch 4 2pp 21805 232 24X
Fiche 50-302, 83/12/27, B401120107

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B40110181 Withholds approval of 831121 request for exemption from App R fire protection mods contingent on NRC approval of util June 1984 installation schedule. Compliance measures should be submitted in 30 days
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/21, REED, C Commonwealth Edison Co 7pp 21795 001 24X
Fiche 50-295, 83/12/21, B40110181

B401050084 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21736 309 24X
Fiche 50-295, 83/12/28, B401050084

--B401050090 Public version of Rev 15 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group" W/B31109 ltr, receipt form & revised index
NYKIRK, J W Commonwealth Edison Co 83/11/09 5pp 21736 310 24X
Fiche 50-295, 83/12/28, B401050084

B401050239 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21743 212 24X
Fiche 50-295, 83/12/28, B401050239

--B401050244 Public version of Rev 0 to Emergency Plan Implementing Procedure EPIP 100-1, "Acting Station Director (Shift Engineer)" W/B31206 ltr, receipt form & revised index
PLIML, G Commonwealth Edison Co 83/12/05 Office of Nuclear Reactor Regulation, Director 12pp 21743 213 24X
Fiche 50-295, 83/12/28, B401050239

B401190434 Forwards IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 & notice of violation
SHAHER, W D Region 3, Office of Director 83/12/30 REED, C Commonwealth Edison Co 2pp 21849 236 24X
Fiche 50-295, 83/12/30, B401190434

--B401190440 Notice of violation from insp on 831111-1220
SHAHER, W D Region 3, Office of Director 83/12/30 2pp 21849 238 24X
Fiche 50-295, 83/12/30, B401190434

--B401190449 IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220. Violations noted failure to adhere to fire protection procedures & to use procedure for diesel generator overspeed trip setpoint adjustment
DUNAWAY, F R Region 3, Office of Director 83/12/29 8pp 21849 240 24X
Fiche 50-295, 83/12/30, B401190434

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport. Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05, REED, C Commonwealth Edison Co 4pp 21874 001 24X
Fiche 50-000, 84/01/05, B401230491

DOCKETED ITEMS

8401250120 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 068 24X Fiche 50-295, 84/01/18.
8401250120

--8401250123 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 310-2, "Generating Station Emergency Plan Training Requirements for Rad/Chem Technicians " W/831214 ltr & receipt form
PLIML, O Commonwealth Edison Co 83/12/12 DENTON, H R NRC - No
Detailed Affiliation Given 6pp 21959 069 24X
Fiche 50-295, 84/01/18, 8401250120

8401250135 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 050 24X Fiche 50-295, 84/01/18.
8401250135

--8401250138 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 350-3, "Radiological Supplies for Medical Emergencies " W/831228 transmittal & receipt form
PLIML, O Commonwealth Edison Co 83/12/23 DENTON, H R NRC - No
Detailed Affiliation Given 9pp 21959 051 24X
Fiche 50-295, 84/01/18, 8401250135

8401260241 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 337 24X Fiche 50-295, 84/01/18.
8401260241

--8401260243 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 350-5, "Technical Support Ctr. Operational Support Ctr & Main Assembly Area Radiological Supplies " W/831212 procedure request form
FICH, C R Commonwealth Edison Co 83/12/12 8pp 21959 338 24X Fiche 50-295, 84/01/18, 8401260241

8401260247 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21992 333 24X Fiche 50-295, 84/01/18.
8401260247

--8401260252 Public version of Rev 6 to Emergency Plan Implementing Procedure EPIP 350-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment " W/831214 procedure change request form
PLIML, O Commonwealth Edison Co 83/12/14 8pp 21992 334 24X
Fiche 50-295, 84/01/18, 8401260247

8401260258 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21992 326 24X Fiche 50-295, 84/01/18.
8401260258

--8401260263 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP 180-1, "Rad/Chem Director " W/831214 procedure change request form
PLIML, O Commonwealth Edison Co 83/12/12 6pp 21992 327 24X
Fiche 50-295, 84/01/18, 8401260258

8401300200 Requests exemption from participation by States of WI & IL in 840417 emergency exercise Major elements in governmental emergency plans performed satisfactorily in 1983 FEMA correspondence encl.
FARRAR, D L Commonwealth Edison Co 84/01/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 21995, 337 24X
Fiche 50-295, 84/01/18, 8401300200

8401310049 Releases public version of change request form deleting emergency plan implementing procedure.
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22031 358 24X Fiche 50-295, 84/01/18.
8401310049

--8401310051 Public version of change request form deleting Emergency Plan Implementing Procedure EPIP 350-4, "Onsite Radiological Emergency Response Equipment." W/831214 ltr & receipt form
PLIML, O Commonwealth Edison Co 83/12/12 DENTON, H R NRC - No
Detailed Affiliation Given 4pp, 22031 362 24X
Fiche 50-295, 84/01/18, 8401310049.

8401310077 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22029 358 24X Fiche 50-295, 84/01/18.
8401310077

--8401310081 Public version of Rev 1 to Emergency Plan Implementing Procedure B2P 300-TB, "Checklist - Environ Monitoring Supplies " W/831229 ltr & receipt form
* Commonwealth Edison Co 83/11/04 5pp 22029 359 24X
Fiche 50-295, 84/01/18, 8401310077

8401310088 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22028 280 24X Fiche 50-295, 84/01/18.
8401310088

--8401310106 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 350-6, "Monthly Radiological Emergency Equipment Tests & Checks " W/831214 ltr, receipt form & procedure change request form
PLIML, O Commonwealth Edison Co 83/12/12 DENTON, H R NRC -
Detailed Affiliation Given 10pp 22028 281 24X
Fiche 50-295, 84/01/18, 8401310088

J Insurance & indemnity information

8401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 BALTZMAN, J Assistant Director for State & License Relations 17pp 21865 332 24X
Fiche 50-000, 84/01/09, 8401200141

P Operating license stage documents & correspondence

8401120585 Forwards Amends 83 & 73 to Licenses DPR-39 & DPR-4B, respectively & safety evaluation Amends change Tech Specs to allow transition from low-parasitic 15x15 fuel assemblies to 15x15 optimized fuel assemblies
NORRIS, J Operating Reactors Branch 4 83/12/23 FARRAR, D L Commonwealth Edison Co 2pp 21796 300 24X Fiche 50-295, 83/12/23
8401120585

--8401120591 Amends 83 & 73 to Licenses DPR-39 & DPR-4B, respectively, allowing transition from low-parasitic 15x15 fuel assemblies to 15x15 optimized fuel assemblies
VAROA, S A Operating Reactors Branch 1 83/12/23 38pp 21796 302 24X Fiche 50-295, 83/12/23, 8401120585

--8401120601 Safety evaluation supporting Amends 83 & 73 to Licenses DPR-39 & DPR-4B, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/23 17pp 21796 341 24X Fiche 50-295, 83/12/23, 8401120585

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation will vary at each facility
BHARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, 8401030229

8401100495 Suppl 1 830422 response to Generic Ltr 83-10C & D Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301
BARNES, P L Commonwealth Edison Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21761 284 24X
Fiche 50-000, 84/01/04, 8401100495

8401080382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401080382

8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing, Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401100468 Clarifies operational status of mod re NUREG-0737, Item III, D, 3.4, "Control Room Habitability " Mod providing automatic isolation of control room outside air intake on safety injection signal completed 831222
LENTINE, F O Commonwealth Edison Co 84/01/06 DENTON, H R, Office of Nuclear Reactor Regulation, Director 2pp 21761 335 24X
Fiche 50-295, 84/01/06, 8401100468

DOCKETED ITEMS

8401170339 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators - Prelubrication w/some warming provided, therefore, generators not subjected to cold starts
BARNES, P L Commonwealth Edison Co 84/01/10 EISENHUT, D G Division of Licensing 1p 21829 341 24X Fiche 50-000, 84/01/10, 8401170339

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401240016 Notification of 840124 meeting w/util in Bethesda, MD to discuss status of equipment environ qualification for facilities
NORRIS, J A Operating Reactors Branch 1 84/01/13 VARGA, S A Operating Reactors Branch 1 2pp 21945 048 24X Fiche 50-295, 84/01/13, 8401240016

8401300265 Updates 830817 application for amend to Licenses DPR-39 & DPR-45 re auxiliary electric power & ECCS
LENTINE, F G Commonwealth Edison Co 84/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21996 321 24X Fiche 50-295, 84/01/25, 8401300265

--8401300267 Proposed Tech Spec changes for auxiliary electric power & ECCS
* Commonwealth Edison Co 84/01/25 3pp 21996 323 24X Fiche 50-295, 84/01/25, 8401300265

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060150

8401040533 Suppls response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
BARNES, P L Commonwealth Edison Co 83/12/20 KEPPLER, J O Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20, 8401040533

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120073 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120073

8401190434 Forwards IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/12/30 REED, C Commonwealth Edison Co 2pp 21849 236 24X Fiche 50-295, 83/12/30, 8401190434

--8401190440 Notice of violation from insp on 831111-1220
SHAFFER, W D Region 3, Office of Director 83/12/30 2pp 21849 238 24X Fiche 50-295, 83/12/30, 8401190440

--8401190449 IE Insp Repts 50-295/83-24 & 50-304/83-25 on 831111-1220 Violations noted failure to adhere to fire protection procedures & to use procedure for diesel generator overspeed trip setpoint adjustment
DUNAWAY, F R, HOLZMER, M M, BOYD, D C Region 3, Office of Director 83/12/29 8pp 21849 240 24X Fiche 50-295, 83/12/30, 8401190449

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Shafts " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401170020 Monthly operating repts for Dec 1983 W/840109 ltr
AUSTIN, G, GRAESSER, K L Commonwealth Edison Co 83/12/31 Director's Office, Office of Inspection and Enforcement 12pp 21834 091 24X Fiche 50-295, 83/12/31, 8401170020

S Reportable occurrences, LERs & related correspondence

8401130334 LER 83-045/01T-0 on 831213, pinhole leak in one tube of cooling coil of reactor containment fan cooler 2C found
Caused by internal pitting Bank containing leaking tube isolated w/blind Flanges W/831221 ltr
HARRSCH, R, GRAESSER, K L Commonwealth Edison Co 83/12/21 KEPPLER, J O Region 3, Office of Director 3pp 21801 198 24X Fiche 50-304, 83/12/21, 8401130334

8401130078 LER 83-046/03L-0 on 831129, safeguards sys train B would not reset after completion of PT-10A Cause unknown Test equipment will be used to monitor circuitry points W/831229 ltr
KAPLAN, S, GRAESSER, K L Commonwealth Edison Co 83/12/29 KEPPLER, J O Region 3, Office of Director 2pp 21802 316 24X Fiche 50-304, 83/12/29, 8401130078

V Operator Examinations

8401230366 Requests listed ref matl required for operator/senior operator licensing exams be provided Written exams scheduled for 840313 & simulator operating & oral exams scheduled for 840307-08 Info due 30 days before exams
SPESBARD, R L Division of Engineering 84/01/18 REED, C Commonwealth Edison Co 4pp 21884 245 24X Fiche 50-295, 84/01/18, 8401230366

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

A Application/construction stage documents & correspondence

8401060245 Notification of 840105 meeting w/util in Bethesda, MD to discuss request to extend time to meet operator staffing rule
NEIGHBOR, J D Operating Reactors Branch 1 83/12/29 VARGA, S A Operating Reactors Branch 1 2pp 21748 361 24X Fiche 50-305, 83/12/29, 8401060245

F Security, medical, emergency & fire protection plans

8401030313 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document Management Branch 1p 21693 055 24X Fiche 50-305, 83/12/27, 8401030313

--8401030315 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual event, EP-AD-4 re alert & EP-AD-5 re site emergency
QIESLER, C W Wisconsin Public Service Corp 83/11/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21693 056 24X Fiche 50-305, 83/12/27, 8401030315

DOCKETED ITEMS

127

--B401030317 Public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual event, EP-AD-4 re alert & EP-AD-5 re site emergency
* Wisconsin Public Service Corp 83/10/27 3pp 21693 058 24X
Fiche 50-305, 83/12/27, B401030313

B401040240 Requests approval for exemption from scheduler requirements of 10CFR50, App R requirements re interim post-fire shutdown capability Util will implement two NRC positions stated in B31207 ltr
QIESLER, C W Wisconsin Public Service Corp 83/12/28 VARQA, S A
Operating Reactors Branch 1 5pp 21701 176 24X
Fiche 50-305, 83/12/28, B401040240

B401230347 Informs of FEMA B40112-13 radiological emergency preparedness program meetings in Chicago, IL to develop final FY84/85 emergency preparedness exercise & prompt alert & notification certification schedules
PAPERIELLO, C J Region 3, Office of Director 84/01/05
QIESLER, C W Wisconsin Public Service Corp 3pp 21882 360 24X
Fiche 50-305, 84/01/05, B401230347

B401190330 Ack receipt of B31230 ltr informing NRC of steps taken to correct exercise weaknesses noted in IE Insp Rept 50-305/83-16
PAPERIELLO, C J Division of Radiological & Materials Safety Programs 84/01/13 QIESLER, C W Wisconsin Public Service Corp 1p 21850 358 24X Fiche 50-305, 84/01/13, B401190330

--B401190333 Responds to NRC ltr re exercise weaknesses noted in IE Insp Rept 50-305/83-16 Corrective actions plan implementing procedures will be revised to include forecast of area micrometeorology for radiological dose assessment
QIESLER, C W Wisconsin Public Service Corp 83/12/30
PAPERIELLO, C J Division of Radiological & Materials Safety Programs 3pp 21850 359 24X Fiche 50-305, 84/01/13, B401190330

B401310372 Requests approval for extension in scheduler requirements of App R, per NRC B31207 ltr Justifications for remaining two interim positions & actions for compliance prior to startup from Spring 1984 refueling outage listed
QIESLER, C W Wisconsin Public Service Corp 84/01/25 VARQA, S A
Operating Reactors Branch 1 3pp 22012 345 24X
Fiche 50-305, 84/01/25, B401310372

J Insurance & indemnity information

B401100191 Forwards Endorsement 59 to NELIA Policy NF-204 & Endorsement 49 to MAELU Policy MF-71
QIESLER, C W Wisconsin Public Service Corp 83/12/12 DINITZ, I
Office of Nuclear Reactor Regulation, Director 3pp 21760 264 24X Fiche 50-305, 83/12/12, B401100191

B401260043 Forwards Endorsement 4 to NELIA Certificate N-44, Endorsements 63 & 64 to NELIA Policy NF-204 & Endorsements 50 & 51 to MAELU Policy MF-71
QIESLER, C W Wisconsin Public Service Corp 84/01/18 DINITZ, I
Office of Nuclear Reactor Regulation, Director 7pp 21957 128 24X Fiche 50-305, 84/01/18, B401260043

P Operating license stage documents & correspondence

B401090633 Forwards "Definition of Operable, Kewaunee Nuclear Power Plant," describing addl changes needed to comply w/Tech Specs Response should be received within 30 days of ltr receipt
VARQA, S A Operating Reactors Branch 1 83/12/19 QIESLER, C W
Wisconsin Public Service Corp 2pp 21757 344 24X
Fiche 50-000, 83/12/19, B401090633

--B401090651 "Definition of Operable, Kewaunee Nuclear Power Plant"
FARMER, F EQ&O, Inc FTA A-6429 EQO-EA-6400 83/12/31
Division of Licensing 6pp 21757 346 24X Fiche 50-000, 83/12/19, B401090633

B401230219 Forwards technical evaluation rept re Util B30824 proposed changes to Tech Specs to comply w/model Tech Specs Definition of operable less comprehensive than that proposed by NRC B00410 ltr
VARQA, S A Operating Reactors Branch 1 83/12/19 QIESLER, C W
Wisconsin Public Service Corp 2pp 21927 330 24X
Fiche 50-305, 83/12/19, B401230219

B401030278 Forwards Rev 1 to "Emergency Operating Procedure Rewrite Program" & Rev C to "Emergency Operating Procedure Writer Manual," in response to B30415 commitment
QIESLER, C W Wisconsin Public Service Corp 83/12/28
EISENHUT, D G Division of Licensing 2pp 21680 141 24X
Fiche: 50-305, 83/12/28, B401030278

--B401030280 Rev 1 to "Emergency Operating Procedure Rewrite Program"
* Wisconsin Public Service Corp 83/09/09 8pp 21680 143 24X
Fiche 50-305, 83/12/28, B401030278

--B401030281 Rev C to "Emergency Operating Procedure Writer Manual"
* Wisconsin Public Service Corp 83/12/20 23pp 21680 151 24X Fiche 50-305, 83/12/28, B401030278

B401090149 Notification of B40120 meeting w/util in Bethesda, MD to discuss equipment environ qualification issues
NEIGHBORS, J D Operating Reactors Branch 1 83/12/28 VARQA, S A
Operating Reactors Branch 1 3pp 21757 233 24X
Fiche 50-305, 83/12/28, B401090149

B401190237 Forwards Amend 51 to License DPR-43 & safety evaluation Amend administrative in nature & cover changes to rod misalignment limits & turbine overspeed protection sys
GRDTEHUIS, M Operating Reactors Branch 1 83/12/28 QIESLER, C W
Wisconsin Public Service Corp 3pp 21870 163 24X
Fiche 50-305, 83/12/28, B401190237

--B401190243 Amend 51 to License DPR-43, changing rod misalignment limits & turbine overspeed protection sys
VARQA, S A Operating Reactors Branch 1 83/12/28 29pp 21870 168 24X Fiche 50-305, 83/12/28, B401190237

--B401190246 Safety evaluation supporting Amend 51 to License DPR-43
* Office of Nuclear Reactor Regulation, Director 83/12/28 4pp 21870 197 24X Fiche 50-305, 83/12/28, B401190237

B401090578 Informs that addl info needed to complete evaluation of B30930 request for extension until B40701 for implementation of licensed operator staffing rule Compensatory actions will be discussed at B40105 meeting
VARQA, S A Operating Reactors Branch 1 83/12/30 QIESLER, C W
Wisconsin Public Service Corp 2pp 21757 256 24X
Fiche 50-305, 83/12/30, B401090578

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401100427 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators" Diesel generators equipped w/continuous lubrication sys Frequent fast cold starts reduce reliability & availability of diesel generators
QIESLER, C W Wisconsin Public Service Corp 84/01/06
EISENHUT, D G Division of Licensing 2pp 21763 111 24X
Fiche 50-305, 84/01/06, B401100427

B401200126 Forwards SER on NUREG-0737, Item II K 2 17, "Potential for Voiding in RCS During Transients," For Westinghouse plants Steam void will not result in unacceptable consequences during anticipated transients
VARQA, S A Operating Reactors Branch 1 84/01/06 QIESLER, C W
Wisconsin Public Service Corp 4pp 21872 160 24X
Fiche 50-305, 84/01/06, B401200126

B401240014 Summary of B40105 meeting w/util & Bechtel in Bethesda, MD re B30930 request for extension of date to comply w/shift manning rule until B40701 List of attendees encl
NEIGHBORS, J D Operating Reactors Branch 1 84/01/12 Operating
Reactors Branch 1 4pp 21945 030 24X Fiche 50-305, 84/01/12, B401240014

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401230429 Application for amend to License DPR-43, revising Tech Specs re limiting conditions, surveillance requirements & administrative controls to comply w/updated inservice insp program
QIESLER, C W Wisconsin Public Service Corp 84/01/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 21882 218 24X Fiche 50-305, 84/01/13, B401230429

DOCKETED ITEMS

--B401230444 Proposed Tech Specs revised to comply w/limiting conditions, surveillance requirements & administrative controls contained in updated inservice insp program
* Wisconsin Public Service Corp 84/01/13 13pp 21882 227
24X Fiche 50-305,84/01/13,8401230429

--B401230444 Proposed Tech Specs revised to comply w/limiting conditions, surveillance requirements & administrative controls contained in updated inservice insp program
* Wisconsin Public Service Corp 84/01/13 13pp 21882 227
24X Fiche 50-305,84/01/13,8401230429

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

B401190393 Forwards IE Insp Rept 50-305/83-15 on 831016-1215 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/12/28 QIESLER, C W
Wisconsin Public Service Corp 2pp 21850 079 24X
Fiche 50-305,83/12/28,8401190393

--B401190396 Notice of violation from insp on 831016-1215
SHAFFER, W D Region 3, Office of Director 83/12/28 2pp
21850 081 24X Fiche 50-305,83/12/28,8401190393

--B401190401 IE Insp Rept 50-305/83-15 on 831017-1209 Violation noted failure to submit LER re boric acid transfer pump 0 & failure to tag equipment in controlled status
NELSON, R L, JACKMAN, I N Region 3, Office of Director 83/12/28
7pp 21850 083 24X Fiche 50-305,83/12/28,8401190393

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

B401040378 Advises that response to IE Bulletin 80-11, "Seismic Qualification of Masonry Walls," will not be transmitted until 840201 due to delays in NDE of safety-related masonry walls
QIESLER, C W Wisconsin Public Service Corp 83/12/30 VAROA, S A
Operating Reactors Branch 1 1p 21707 362 24X
Fiche 50-305,83/12/30,8401040378

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

101190330 Ack receipt of 831230 ltr informing NRC of steps taken to correct exercise weaknesses noted in IE Insp Rept 50-305/83-16
PAPERIELLO, C J Division of Radiological & Materials Safety Programs 84/01/13 QIESLER, C W Wisconsin Public Service Corp 1p 21850 338 24X Fiche 50-305,84/01/13,8401190330

B401190333 Responds to NRC ltr re exercise weaknesses noted in IE Insp Rept 50-305/83-16 Corrective actions plan implementing procedures will be revised to include forecast of area micrometeorology for radiological dose assessment
QIESLER, C W Wisconsin Public Service Corp 83/12/30 PAPERIELLO, C J Division of Radiological & Materials Safety Programs 3pp 21850 359 24X Fiche 50-305,84/01/13,8401190330

01230429 Application for amend to License DPR-43, revising Tech Specs re limiting conditions, surveillance requirements & administrative controls to comply w/updated inservice insp program
QIESLER, C W Wisconsin Public Service Corp 84/01/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 21882 218
24X Fiche 50-305,84/01/13,8401230429

B312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

B401160089 Monthly operating rept for Dec 1983 W/B40110 ltr
RUITER, G H, QIESLER, C W Wisconsin Public Service Corp 83/12/31
Director's Office, Office of Inspection and Enforcement 5pp
21821 186 24X Fiche 50-305,83/12/31,8401160089

S Reportable occurrences, LERS & related correspondence

B401040321 LER 83-030/03L-0 on 831117, sampling pump for containment gaseous & particulate radiation monitor R-11 failed to operate Caused by bare wires shorting out paper drive fast speed motor Fast & slow speed motors replaced W/831216 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 83/12/16 KEPLER, J G Region 3, Office of Director 2pp 21708 038 24X Fiche 50-305,83/12/16,8401040321

B401040309 LER 83-031/03L-0 on 831121, during full power operation, IRPI channel for rod J-10 removed from svc for maint Caused by remote indicator span drifting high Indicator span recalibr W/831221 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 83/12/21 KEPLER, J G Region 3, Office of Director 2pp 21708 108 24X Fiche 50-305,83/12/21,8401040309

B401060348 LER 83-032/03L-0 on 831201, containment spray pump breaker 1B failed to close when requested during monthly pump & valve surveillance test Cause unknown Pump monitored W/831230 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 83/12/30 KEPLER, J G Region 3, Office of Director 2pp 21741 175 24X Fiche 50-305,83/12/30,8401060348

B401120378 LER 83-033/03L-0 on 831205, motor operated isolation valve SI-2A in boric acid suction line to safety injection pump failed to open during monthly surveillance test Caused by broken finger in auxiliary contact block W/840104 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 84/01/04 KEPLER, J G Region 3, Office of Director 2pp 21791 168 24X Fiche 50-305,84/01/04,8401120378

B401130324 LER 83-034/03L-0 on 831206, containment fan coil unit 1D removed from svc to repair svc water leaks Caused by sand & water erosion of return bends in svc water cooling coils. Affected bends replaced W/840105 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 84/01/05 KEPLER, J G Region 3, Office of Director 2pp 21801 330 24X Fiche 50-305,84/01/05,8401130324

B401140278 LER 83-035/03L-0 on 831210, RPI drifted downwards when voltage regulator failed Caused by low voltage output due to tarnished contact point in voltage regulator Voltage adjust pot wiped & voltage readjusted W/840109 ltr
MARCHEL, M L, SCHROCK, C A, QIESLER, C W Wisconsin Public Service Corp 84/01/09 KEPLER, J G Region 3, Office of Director, 3pp 21813 354 24X Fiche 50-305,84/01/09,8401140278

B401230354 LER 83-037/03L-0 on 831213, during full power, svc water pump 1A2 taken out of svc Caused by packing leak on svc water strainer Strainer repacked & pump tested W/840112 ltr
BERNHOF, S L, THORGERSEN, J G, QIESLER, C W Wisconsin Public Service Corp 84/01/12 KEPLER, J G Region 3, Office of Director 2pp 21882 339 24X Fiche 50-305,84/01/12,8401230354

DOCKETED ITEMS

1

B401230369 LER 83-036/03L-0 on 831213, shield bldg ventilation fan 1A failed to start during monthly surveillance test caused by procedural error Charcoal filter heat detector test procedure revised W/840112 ltr
BERNHOF, S. L., THORP, J. G., QIESLER, C. W. Wisconsin Public Service Corp 84/01/12 KEPLER, J. G. Region 3, Office of Director 3pp 21873 355 24X Fiche 50-000, 84/01/12, B401230369

V Operator Examinations

B401200015 Forwards tentative schedule for operator license applications through 1987 per Generic Ltr 83-40 Exam dates & number of applicants tentative & are meant only to assist in program planning Schedule based on NRC fiscal yrs
QIESLER, C. W. Wisconsin Public Service Corp 84/01/16 EISENHUT, D. O. Division of Licensing 2pp 21864 343 24X Fiche 50-000, 84/01/16, B401200015

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records 83/11/02 D'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X Fiche 50-000, 83/11/02, B401250163

--B401250286 Forwards comments on proposed Commission papers NRC should consider significant economic impact which would result if backup emergency operation facility rejected & dismantled into two separate locations
EISENHUT, D. O. Division of Licensing 83/06/24 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 21958 328 24X Fiche 50-000, 83/11/02, B401250163

B401100180 Forwards tentative schedule of major submittals, fire protection exemption requests & Tech Spec changes, for info & planning purposes
MUSOLF, D. M. Northern States Power Co 84/01/04 Office of Nuclear Reactor Regulation, Director 2pp 21759 280 24X Fiche 50-282, 84/01/04, B401100180

B401230271 Notifies of FEMA 840112-13 meetings in Chicago, IL. FEMA requests that util emergency preparedness planners attend to develop FY84/85 emergency preparedness exercise schedule & prompt alert & notification certification schedule
PAPERIELLO, C. J. Region 3, Office of Director 84/01/05 LARSON, C. E. Northern States Power Co 3pp 21884 211 24X Fiche 50-000, 84/01/05, B401230271

B401180006 Forwards exemption from requirements of App R, Subsection III Q 2 re separation fire barrier & suppression where both trains of redundant safe shutdown located in same fire area
MILLER, J. R. Operating Reactors Branch 3 84/01/09 MUSOLF, D. M. Northern States Power Co 3pp 21848 292 24X Fiche 50-282, 84/01/09, B401180006

--B401180011 Exemption from requirements of App R, Subsection III Q 2 re train of cables necessary for safe shutdown
EISENHUT, D. O. Division of Licensing 84/01/09 Northern States Power Co 7pp 21848 293 24X Fiche 50-282, 84/01/09, B401180006

--B401180015 Safety evaluation supporting exemption from fire protection requirements of App R, Subsection III Q 2, per 830217 & 0311 requests
* Office of Nuclear Reactor Regulation, Director 84/01/09 6pp 21848 302 24X Fiche 50-282, 84/01/09, B401180006

B401250093 Releases public version of notice re emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 84/01/18 Document Management Branch, 1p 21946 262 24X Fiche 50-000, 84/01/18, B401250093

--B401250096 Public version of notice that Emergency Plan Implementing Procedure 9.1 inadvertently attached to back of 831221 corporate emergency plan - implementing procedures & should be discarded
HUDSON, G. Northern States Power Co 83/12/29 1p 21946 263 24X Fiche 50-000, 84/01/18, B401250093

B401310254 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 84/01/18, Document Management Branch, 1p 22037, 095 24X Fiche 50-000, 84/01/18, B401310254

--B401310263 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.1 re accident assessment, EPIP 1.2.1 re emergency plan training & EPIP 1.2.2 re exercises & drills
FEY, F. L. Northern States Power Co 83/12/21 Region 3, Office of Director 2pp 22037 096 24X Fiche 50-000, 84/01/18, B401310254

--B401310271 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.1 re accident assessment, EPIP 1.2.1 re emergency plan training & EPIP 1.2.2 re exercises & drills
HUDSON, G., FEY, F. L. Northern States Power Co 83/12/21 10pp 22037 098 24X Fiche 50-000, 84/01/18, B401310254

B401310335 Forwards exemption requests from requirements of 10CFR50, App R re clarification of definition of intervening combustibles & safety concerns of cable derating & structural adequacy for review & approval
MUSOLF, D. M. Northern States Power Co 84/01/23 Office of Nuclear Reactor Regulation, Director 7pp 22026 269 24X Fiche 50-282, 84/01/23, B401310335

J Insurance & indemnity information

B401270054 Forwards Endorsements 4.70, 4.4 & 50 to NELIA Policies N-17, NF-174, N-37, N-36 & NF-197, respectively & Endorsements 4.50, 4.4 & 50 to MAELU Policies M-17, MF-51, M-37, M-36 & MF-69, respectively
JOHNSON, R. G. Northern States Power Co 84/01/23 DINITZ, I. Division of Engineering 11pp 21973 298 24X Fiche 50-000, 84/01/23, B401270054

P Operating license stage documents & correspondence

B401060230 Provides schedule for submittal of revised procedure for estimating extent of core damage & confirming that heat tracing will be installed on containment sampling lines by 840630, per NUREG-0737, Item II B 3
MUSOLF, D. M. Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director 1p 21740 111 24X Fiche 50-282, 83/12/22, B401060230

B401200081 Forwards Rev O to "ASME Code Section XI Inservice Insp & Testing Program" Licensing fee determination form & fee encl. Seven requests for relief remain unresolved Requests for relief will be revised or withdrawn
MUSOLF, D. M. Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director 1p 21862 001 24X Fiche 50-282, 83/12/22, B401200081

--B401200085 Rev O to "ASME Code Section XI Inservice Insp & Testing Program"
DAHLMAN, L. C. Northern States Power Co 83/10/14 347pp 21862 002 24X Fiche 50-282, 83/12/22, B401200081

B401101889 Forwards Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change exposure dependence function Bu(2) to 1.0 for all values of peak pellet exposure
DIANNI, D. C. Operating Reactors Branch 3 83/12/28 MUSOLF, D. M. Northern States Power Co 2pp 21795 128 24X Fiche 50-282, 83/12/28, B40110188

--B40110193 Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively, changing exposure dependence function Bu(2) to 1.0 for all values of peak pellet exposure
MILLER, J. R. Operating Reactors Branch 3 83/12/28 6pp 21795 130 24X Fiche 50-282, 83/12/28, B40110188

--B40110200 Safety evaluation supporting Amends 67 & 61 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/28 4pp 21795 136 24X Fiche 50-282, 83/12/28, B40110188

B401190159 Forwards evaluation of NUREG-0737, Item II K 2.17 re potential voiding in RCS during anticipated transients Steam voids will not result in unacceptable consequences during transients
MILLER, J. R. Operating Reactors Branch 3 83/12/30 MUSOLF, D. M. Northern States Power Co 6pp 21870 356 24X Fiche 50-282, 83/12/30, B401190159

B401100180 Forwards tentative schedule of major submittals, fire protection exemption requests & Tech Spec changes, for info & planning purposes
MUSOLF, D. M. Northern States Power Co 84/01/04 Office of Nuclear Reactor Regulation, Director 2pp 21759 280 24X Fiche 50-282, 84/01/04, B401100180

DOCKETED ITEMS

B401050382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms. "important to safety & "safety-related " Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLS & Full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 16pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401180111 Provides addl info re fast cold starts of diesel generators (Generic Ltr 83-41), per 831216 request Facility experienced two fast cold starts & 81 cold starts w/emergency diesel generators from 821201 to 831201
MUSOLF, D Northern States Power Co 84/01/10 Office of Nuclear
Reactor Regulation, Director 2pp 21841 356 24X
Fiche 50-282, 84/01/10, B401180111

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 16pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401190387 Forwards application for amend to Licenses DPR-42 & DPR-60, to provide assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, item 11 B 1
MUSOLF, D Northern States Power Co 84/01/13 Office of Nuclear
Reactor Regulation, Director 2pp 21849 349 24X
Fiche 50-282, 84/01/13, B401190387

--B401190392 Application for amend to License DPR-42 & DPR-60, providing assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, item 11 B 1
MUSOLF, D Northern States Power Co 84/01/13 6pp 21849 351
24X Fiche 50-282, 84/01/13, B401190392

--B401190394 Proposed Tech Spec changes providing assurance of reactor coolant vent sys operability & reliability
* Northern States Power Co 84/01/13 40pp 21849 357 24X
Fiche 50-282, 84/01/13, B401190394

B401240431 Forwards general discussion minutes of 831201 meeting w/NRC re equipment qualification open items Description of methodology to establish environ qualification, item resolution & schedule for completion encl
MUSOLF, D Northern States Power Co 84/01/16 DENTON, H R Office
of Nuclear Reactor Regulation, Director 36pp 21915 206 24X
Fiche 50-282, 84/01/16, B401240431

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Treubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
B401060150

B401200081 Forwards Rev O to "ASME Code Section XI Inservice Insp & Testing Program " Licensing fee determination form & fee encl Seven requests for relief remain unresolved Requests for relief will be revised or withdrawn
MUSOLF, D Northern States Power Co 83/12/22 Office of Nuclear
Reactor Regulation, Director 1p 21842 001 24X
Fiche 50-282, 83/12/22, B401200081

--B401200085 Rev O to "ASME Code Section XI Inservice Insp & Testing Program "
DAHLMAN, L C Northern States Power Co 83/10/14 347pp
21862 002 24X Fiche 50-282, 83/12/22, B401200085

B401100481 Forwards IE Insp Repts 50-282/83-21 & 50-306/83-21 on B31214 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/12/23 LARSON, C E
Northern States Power Co 2pp 21761 293 24X
Fiche 50-282, 83/12/23, B401100481

--B401100484 IE Insp Repts 50-282/83-21 & 50-306/83-21 on B31214 No noncompliance noted Major areas inspected inservice insp procedures, work activities, NDE personnel certifications & data & IE bulletin activities
WARD, K D, DANIELSON, D H Region 3, Office of Director 83/12/23
9pp 21761 275 24X Fiche 50-282, 83/12/23, B401100484

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401240314 Forwards IE Insp Repts 50-282/83-19 & 50-306/83-20 on B31011-1210 & notices of violation & deviation
SHAFFER, W D Region 3, Office of Director 84/01/06 LARSON, C E
Northern States Power Co 2pp 21932 178 24X
Fiche 50-282, 84/01/06, B401240314

--B401240320 Notice of violation from insp on B31011-1210.
SHAFFER, W D Region 3, Office of Director 84/01/06 1p
21932 180 24X Fiche 50-282, 84/01/06, B401240314

--B401240321 Notice of deviation from insp on B31011-1210
SHAFFER, W D Region 3, Office of Director 84/01/06 1p
21932 181 24X Fiche 50-282, 84/01/06, B401240314

--B401240332 IE Insp Repts 50-282/83-19 & 50-306/83-20 on B31011-1210 Noncompliance noted failure to provide required changes to procedures Deviation noted failure to perform committed test re IE bulletin
FEIERABEND, C D, HARD, J E, HARTMANN, P L Region 3, Office of Director 84/01/06 12pp 21932 182 24X Fiche 50-282, 84/01/06,
B401240314

B401170353 Forwards "Inservice Insp-Exam Summary Prairie Island Nuclear Generating Plant, Unit 2, B30829-1001 " Integrity of sys maintained
MUSOLF, D Northern States Power Co 84/01/09 Office of Nuclear
Reactor Regulation, Director 2pp 21828 003 24X
Fiche 50-282, 84/01/09, B401170353

--B401170355 "Inservice Insp - Exam Summary Prairie Island Nuclear Generating Plant, Unit 2, B30829-1001 "
DAHLMAN, L C, ANDERSON, M T, KRUMFOLZ, P J Northern States Power Co 83/12/28 194pp 21828 005 24X Fiche 50-282, 84/01/09,
B401170353

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 093 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21828 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butter Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

B401310250 Forwards addendum to IE Insp Repts 50-282/83-08 & 50-306/83-09, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sample collected during insp
PAPERIELLO, C J Region 3, Office of Director 84/01/26
LARSON, C E Northern States Power Co 1p 22018 329 24X
Fiche 50-282, 84/01/26, B401310250

DOCKETED ITEMS

131

--B401310232 Addendum to IE Insp Repts 50-282/83-08 & 50-304/83-08 on 830701, consisting of confirmatory measurements program sheet comparing results of analyses of beta emitters in liquid sample
* Region 3, Office of Director 84/01/26 1p 22018 330 24X
Fiche 50-282, 84/01/26, B401310230

R. Periodic operating reports & related correspondence

B401120240 Monthly operating repts for Nov 1983 W/B401209 1tr
BUSTAD, D., MUSOLF, D Northern States Power Co 83/11/30 Office
of Resource Management, Director 9pp 21793 312 24X
Fiche 50-282, 83/11/30, B401120240

B401270432 Monthly operating repts for Dec 1983 W/B40109 1tr
BUSTAD, D., MUSOLF, D Northern States Power Co 83/12/31 Office
of Resource Management, Director 9pp 21980 232 24X
Fiche 50-282, 83/12/31, B401270432

V Operator Examinations

B401300054 Advises that written operator & senior operator licensing exams scheduled for 840320 & oral exams scheduled for 840321 & 22 Approved listed ref matl should be furnished in order to meet schedule
SPESBARD, R L Division of Engineering 84/01/20 LARSON, C C
Northern States Power Co 3pp 21999 264 24X
Fiche 50-282, 84/01/20, B401300054

X. Onsite Storage of Low Level Waste

B401120314 Provides info re methods used to comply w/waste classification & waste form requirements of 10CFR61 for disposal of low level radwaste Radionuclides identified by direct or inferential measurement
MUSOLF, D Northern States Power Co 84/01/05 Office of Nuclear
Reactor Regulation, Director 2pp 21792 042 24X
Fiche 50-282, 84/01/05, B401120314

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X
Fiche 50-000, 83/11/02, B401250163

--B304030153 Recommends Commission concurrence w/approval for exception to location of backup emergency operations facility beyond 20 miles for Maine Yankee Atomic power plant
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-192 83/05/19 5pp 21958 167 24X
Fiche 50-000, 83/11/02, B401250163

B401090515 Responds to 830929 request for assistance re emergency evacuation issue raised by Sensible Maine Power Evacuation routes will be inspected & exercise evaluation simulation facility analyzed by B40201
KRIMM, R W Federal Emergency Management Agency 83/11/23
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 21750 362 24X Fiche 50-309, 83/11/23, B401090515

B401100300 Forwards IE Insp Rept 50-309/83-17 on 831021-23 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/21
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 21758 170 24X
Fiche 50-309, 83/12/21, B401100300

--B401100308 IE Insp Rept 50-309/83-17 on 831021-23 No violations noted
Major areas inspected emergency preparedness & observation of licensee annual emergency exercise performed on 831022
GORDON, C Z Region 1, Office of Director, CROCKER, H W Division
of Engineering & Technical Programs 83/12/12 6pp 21758 172
24X Fiche 50-309, 83/12/21, B401100300

B401100431 Forwards IE Insp Rept 50-309/83-16 on 830919-1031 No violations noted
STARDTECKI, R Division of Project & Resident Programs 83/12/23
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 21762 170 24X
Fiche 50-309, 83/12/23, B401100431

--B401100442 IE Insp Rept 50-309/83-16 on 830919-1031 No noncompliance noted Major areas inspected control & feed pump room, spray, turbine, primary auxiliary & reactor containment bldgs, plant operations, radiation protection & physical security
HOLDEN, C F, SMETLAND, P D Region 1, Office of Director
GREENMAN, E G Division of Project & Resident Programs 83/12/23
9pp 21762 172 24X Fiche 50-309, 83/12/23, B401100431

B401030359 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21686 190 24X Fiche 50-309, 83/12/27, B401030359

--B401030363 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 50 1 re notification of unusual event, 2 50 2 re alert & 2 50 3 re site area emergency
* Maine Yankee Atomic Power Co 83/10/14 Region 1, Office of
Director 2pp 21686 191 24X Fiche 50-309, 83/12/27, B401030359

--B401030367 Public version of revised emergency plan implementing procedures, including Procedures 2 50 1 re notification of unusual event, 2 50 2 re alert & 2 50 3 re site area emergency
* Maine Yankee Atomic Power Co 83/10/13 250pp 21686 193
24X Fiche 50-309, 83/12/27, B401030359

B401160143 Informs that control room design review completed Draft rept prepared for internal review Earlier human factor review incorporated as result of NUREG-0737 to accurately reflect human factors considerations
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/06 MILLER, J R
Operating Reactors Branch 3 1p 21813 006 24X
Fiche 50-309, 84/01/06, B401160143

B401230121 Forwards revised security plan pages & justification for changes, per NRC 790223 & B20915 & util B20401 ltrs Encl withheld (ref 10CFR73 21)
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/16 Office of
Nuclear Reactor Regulation, Director 2pp 21884 348 24X
Fiche 50-309, 84/01/16, B401230121

B401240175 Application for amend to License DPR-36, changing Tech Spec which stipulates limiting conditions for operation & surveillance requirements for alternate shutdown sys, per 10CFR50, App R License amend fee encl
RANDAZZA, J B Maine Yankee Atomic Power Co 84/01/16
EISENHUT, D G Division of Licensing 8pp 21908 295 24X
Fiche 50-309, 84/01/16, B401240175

--B401240180 Proposed Tech Spec changes which stipulate limiting conditions for operation & surveillance requirements for alternate shutdown sys, per 10CFR50, App R
* Maine Yankee Atomic Power Co 84/01/16 6pp 21908 297 24X
Fiche 50-309, 84/01/16, B401240175

B401260156 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21982 327 24X Fiche 50-309, 84/01/18, B401260156

--B401260158 Public version of Rev 18 to Emergency Plan Implementing Procedure 2 50 4, "Emergency Equipment Readiness Check" 4/831219 transmittal, receipt form & revised index
* Maine Yankee Atomic Power Co 83/12/13 18pp 21982 328 24X
Fiche 50-309, 84/01/18, B401260156

P Operating license stage documents & correspondence

B401040319 Confirms compliance w/Confirmatory Action Ltr 83-18 prior to return to operation following recent plant outage
WHITTIER, G D Maine Yankee Atomic Power Co 83/12/19 MURLEY, T E
Region 1, Office of Director 1p 21707 101 24X
Fiche 50-309, 83/12/19, B401040319

B401110521 Forwards Amend 71 to License DPR-36 & safety evaluation Amend modifies Tech Specs re inservice insp
HEITNER, K L Operating Reactors Branch 3 83/12/21 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21790 334 24X
Fiche 50-309, 83/12/21, B401110521

--B401110526 Amend 71 to License DPR-32, revising Tech Specs re inservice insp
MILLER, J R Operating Reactors Branch 3 83/12/21 5pp
21790 336 24X Fiche 50-309, 83/12/21, B401110521

--B401110531 Safety evaluation supporting Amend 71 to License DPR-36
* Office of Nuclear Reactor Regulation, Director 83/12/21 2pp
21790 341 24X Fiche 50-309, 83/12/21, B401110521

DOCKETED ITEMS

- 8401090520 Forwards SER based on encl technical evaluation rept of util response to NUREG-0612, Section 5.1.1 & 5.3 re control of heavy loads
MILLER, J R Operating Reactors Branch 3 83/12/30 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21768 115 24X
Fiche 50-309, 83/12/30, 8401090520
- 8401090522 Safety evaluation in support of util response to NUREG-0612, "Control of Heavy Loads at Nuclear Plants," Phase 1
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp
21768 117 24X Fiche 50-309, 83/12/30, 8401090520
- 8312060211 "Control of Heavy Loads (C-10) at Maine Yankee Nuclear Power Station," technical evaluation rept
BOMBERGER, C Franklin Institute/Franklin Research Center
NRC-03-B1-130 TER-CS506-365 83/12/02 SINGH, A, CHAN, T NRC
No Detailed Affiliation Given 28pp 21768 117 24X
Fiche 50-309, 83/12/30, 8401090520
- 8401090374 Informs of 840109 meeting to discuss 830930 request for extension until 840701 for implementation of licensed operator staffing rule. Compensatory actions to provide equivalent level of protection will be discussed
MILLER, J R Operating Reactors Branch 3 83/12/30 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21757 251 24X
Fiche 50-309, 83/12/30, 8401090374
- 8401090382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401090382
- 8401190131 Requests schedule for formal submittal of radiological effluent Tech Specs & offsite dose calculation manual
MILLER, J R Operating Reactors Branch 3 84/01/05 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21871 025 24X
Fiche 50-309, 84/01/05, 8401190131
- 8401190134 Requests response to 830920 ltr re Proposed Change 43 to Tech Specs re App J Restart of plant depends on satisfactory resolution of listed items before next refueling outage
MILLER, J R Operating Reactors Branch 3 84/01/05 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21871 023 24X
Fiche 50-309, 84/01/05, 8401190134
- 8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on Facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221
- 101160159 Submits addl info re integral neutron sources for future core configurations, per NRC 831202 request re pressurized thermal shock. Addl response will be submitted by end of Jan 1984
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/06 MILLER, J R
Operating Reactors Branch 3 2pp 21809 360 24X
Fiche 50-309, 84/01/06, 8401160159
- 8401160269 Forwards response to NRC 831012 ltr re radiological ETS. Withdrawal of Proposed Change 68 requested since performance record demonstrates compliance w/NRC regulations
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/06 MILLER, J R
Operating Reactors Branch 3 6pp 21813 309 24X
Fiche 50-309, 84/01/06, 8401160269
- 8401170287 Notifies of mods necessary to allow required containment leak testing per 10CFR50, App J requirements. Mods scheduled to be completed by end of 1985 re fueling outage. Requests comments on encl changes by 840229
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/11 MILLER, J R
Operating Reactors Branch 3 100pp 21832 122 24X
Fiche 50-309, 84/01/11, 8401170287
- 1401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084
- 8401240101 Notifies that Weston Geophysical Corp rept, "Seismological & Geological Studies, Miramichi Area, New Brunswick & Central Nfld." may be reclassified nonproprietary
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/13 MILLER, J R
Operating Reactors Branch 3 1p 21912 293 24X
Fiche 50-309, 84/01/13, 8401240101
- 8401190231 Requests Class III fee payment for 810403 & 821007 requests for amends to License DPR-36. Class II fee payments inadequate
DIGGS, R M License Fee Management Branch 84/01/16 GARRITY, J H
Maine Yankee Atomic Power Co 1p 21870 203 24X
Fiche 50-309, 84/01/16, 8401190231
- 8401240175 Application for amend to License DPR-36, changing Tech Spec which stipulates limiting conditions for operation & surveillance requirements for alternate shutdown sys. per 10CFR50, App R License amend fee encl
RANDAZZA, J B Maine Yankee Atomic Power Co 84/01/16
EISENHUT, D G Division of Licensing 8pp 21908 293 24X
Fiche 50-309, 84/01/16, 8401240175
- 8401240180 Proposed Tech Spec changes which stipulate limiting conditions for operation & surveillance requirements for alternate shutdown sys. per 10CFR50, App R
* Maine Yankee Atomic Power Co 84/01/16 6pp 21908 297 24X
Fiche 50-309, 84/01/16, 8401240175
- 8401240184 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators. By design, do not cold start. Frequent fast cold starts have detrimental effect on reliability & availability
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/18 MILLER, J R
Operating Reactors Branch 3 3pp 21908 344 24X
Fiche 50-309, 84/01/18, 8401240184
- 8401240284 Application for amend to License DPR-36, consisting of Proposed Change 103 re steam generator water level setting
RANDAZZA, J B Maine Yankee Atomic Power Co 84/01/19 MILLER, J R
Operating Reactors Branch 3 3pp 21909 335 24X
Fiche 50-309, 84/01/19, 8401240284
- 8401240291 Proposed Tech Spec change re steam generator water level setting
* Maine Yankee Atomic Power Co 84/01/09 2pp 21909 338 24X
Fiche 50-309, 84/01/19, 8401240284
- 8401310304 Forwards draft Rev O to Operating Procedure AOP 2-12, "Bus 5 &/or Bus 6 Undervoltage." Procedure governs operator action for degraded grid condition during non-accident situation
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/25 MILLER, J R
Operating Reactors Branch 3 7pp 22026 286 24X
Fiche 50-309, 84/01/25, 8401310304
- Q Inspection reports, IE Bulletins & correspondence
- 8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PBR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040
- 8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744, 004 24X Fiche 50-000, 83/10/20, 8401060040
- 8401040319 Confirms compliance w/Confirmatory Action Ltr 83-18 prior to return to operation following recent plant outage
WHITTIER, G D Maine Yankee Atomic Power Co 83/12/19 MURLEY, T E
Region 1, Office of Director 1p 21707:101 24X
Fiche 50-309, 83/12/19, 8401040319
- 8401100300 Forwards IE Insp Rept 50-309/83-17 on 831021-23 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/21
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 21758 170 24X
Fiche 50-309, 83/12/21, 8401100300
- 8401100308 IE Insp Rept 50-309/83-17 on 831021-23 No violations noted. Major areas inspected emergency preparedness & observation of licensee annual emergency exercise performed on 831022
GORDON, C Z Region 1, Office of Director CROCKER, H W Division of Engineering & Technical Programs 83/12/12 6pp 21758 172 24X
Fiche 50-309, 83/12/21, 8401100300
- 8401110521 Forwards Amend 71 to License DPR-36 & safety evaluation. Amend modifies Tech Specs re inservice insp
HEITNER, K L Operating Reactors Branch 3 83/12/21 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 21790 334 24X
Fiche 50-309, 83/12/21, 8401110521
- 8401110526 Amend 71 to License DPR-32, revising Tech Specs re inservice insp
MILLER, J R Operating Reactors Branch 3 83/12/21 5pp
21790 336 24X Fiche 50-309, 83/12/21, 8401110521.

DOCKETED ITEMS

133

--840110531 Safety evaluation supporting Amend 71 to License DPR-36
* Office of Nuclear Reactor Regulation, Director 83/12/21 2pp
21790 341 24X Fiche 50-309,83/12/21,840110531

8401100431 Forwards IE Insp Rept 50-309/83-16 on 830919-1031 No
violations noted
STAROSTECKI, R Division of Project & Resident Programs 83/12/23
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 21762 170 24X
Fiche 50-309,83/12/23,8401100431

--8401100442 IE Insp Rept 50-309/83-16 on 830919-1031 No noncompliance
noted Major areas inspected control & feed pump room, spray,
turbine, primary auxiliary & reactor containment bldgs, plant
operations, radiation protection & physical security
HOLDEN, C F, SWETLAND, P D Region 1, Office of Director
GREENMAN, E G Division of Project & Resident Programs 83/12/23
9pp 21762 172 24X Fiche 50-309,83/12/23,8401100431

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEYQUNO, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401190127 Ack receipt of 831027 ltr responding to IE Insp Rept
50-309/83-10
STAROSTECKI, R Division of Project & Resident Programs 84/01/04
RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 21871 027 24X
Fiche 50-309,84/01/04,8401190127

--8401190129 Responds to violations noted in IE Insp Rept 50-309/83-10
Corrective actions instruction issued to provide safety
evaluations for mods to component cooling water HX
procedures
WHITTIER, G D Maine Yankee Atomic Power Co 83/10/27
MURLEY, T E Region 1, Office of Director 2pp 21871 029 24X
Fiche 50-309,84/01/04,8401190127

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc. 123pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401170390 Ack receipt of 831121 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-309/83-18
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 21828 288 24X
Fiche 50-309,84/01/10,8401170390

--8401170399 Revises 831109 response to violations noted in IE Insp
Rept 50-309/83-18 Previous full hatch test failures
occurred Failures attributable to O-rings on hinges
& quickly corrected
RANDAZZA, J B Maine Yankee Atomic Power Co 83/11/21
MURLEY, T E Region 1, Office of Director 1p 21828 289 24X
Fiche 50-309,84/01/10,8401170390

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142, 24X Fiche 50-000,84/01/16,8312120114

8401230563 Ack receipt of 831117 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-309/83-06
STAROSTECKI, R Division of Project & Resident Programs 84/01/16
RANDAZZA, J B Maine Yankee Atomic Power Co 1p 21900 299 24X
Fiche 50-309,84/01/16,8401230563

--8401230572 Suppls response to NRC 830808 ltr re violations noted in IE
Insp Rept 50-309/83-06 Corrective actions plant sys drawings
will be revised to designate containment integrity valves
locked closed
WHITTIER, G D Maine Yankee Atomic Power Co 83/11/17
MURLEY, T E Region 1, Office of Director 1p 21900 298 24X
Fiche 50-309,84/01/16,8401230563

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License "
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401120299 Monthly operating rept for Nov 1983 W/831209 ltr
BIEMILLER, S, ANDERSON, P L Maine Yankee Atomic Power Co 83/11/30
HARTFIELD, R A Management Information Branch 5pp 21792 110
24X Fiche 50-309,83/11/30,8401120299

8401270261 Monthly operating rept for Dec 1983 W/840110 ltr
BIEMILLER, S, MCUMBER, J T Maine Yankee Atomic Power Co 83/12/31
HARTFIELD, R A Management Information Branch 5pp 21792 222
24X Fiche 50-309,83/12/31,8401270261

S Reportable occurrences, LERs & related correspondence

8401050258 LER 83-042/03L-0 on 831123, surveillance testing on steam
generator level transmitters revealed two transmitters had
drifted high in nonconservative direction Caused by
defective amplifier card in one transmitter W/831227 ltr
GARRITY, J H, WHITTIER, G D Maine Yankee Atomic Power Co 83/12/27
MURLEY, T E Region 1, Office of Director 3pp 21729 269 24X
Fiche 50-309,83/12/27,8401050258

8401100348 LER 83-043/01L-0 on 831203, during hot shutdown, charging flow
control valve CH-F-38 failed open Caused by locked closed
containment isolation valve CH-39 being opened to
depressurize charging line Valve repaired W/831228 ltr
TIFFANY, T A, WHITTIER, G D Maine Yankee Atomic Power Co 83/12/28
MURLEY, T E Region 1, Office of Director 3pp 21764 106 24X
Fiche 50-309,83/12/28,8401100348

8401100288 LER 83-046/03L-0 on 831201, during plant startup, discovered
current rev to plant startup procedure not used Caused by Rev
26 withdrawn prior to updating file cabinet & reinserted
after procedure revs changed W/831229 ltr
STEVENSON, J L, WHITTIER, G D Maine Yankee Atomic Power Co 83/12/29
MURLEY, T E Region 1, Office of Director 4pp 21799 157 24X
Fiche 50-309,83/12/29,8401100288

8401230455 LER 83-044/03L-0 on 831210, during plant startup, motor
driven steam generator auxiliary feedwater pump discovered
out of svc Caused by damaged radial & thrust bearings &
out of tolerance balancing drum clearance W/840109 ltr
TAYLOR, J M, WHITTIER, G D Maine Yankee Atomic Power Co 84/01/09
MURLEY, T E Region 1, Office of Director 3pp 21882 146 24X
Fiche 50-309,84/01/09,8401230455

V Operator Examinations

8401100414 Requests exemption from shift manning rule only until
840315 instead of Jul 1984 requested in 830930 ltr
Individuals judged eligible for operator license
WHITTIER, G D Maine Yankee Atomic Power Co 84/01/05 MILLER, J R
Operating Reactors Branch 3 1p 21763 064 24X
Fiche 50-309,84/01/05,8401100414

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8401160165 Forwards 10CFR170 fee remittance for fire protection reviews
& approvals, per 831205 ltr
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/01/10 MILLER, W D License Fee Management Branch 1p
21815 355 24X Fiche 50-272,83/01/10,8401160165

8401190171 Responds to 831110 ltr requesting determination re nature of
proposed change to security plan to implement vital island
concept Request referred to headquarters.
MARTIN, T T Division of Engineering & Technical Programs 83/12/19
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21861 357 24X Fiche 50-272,83/12/19,8401190171

DOCKETED ITEMS

B401030244 Forwards "Exercise Evaluation Rpt for Salem Exercise on 831026"
KRIMM, R W Federal Emergency Management Agency 83/12/21
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 21681 078 24X Fiche 50-272, 83/12/21, 8401030244

--B401030249 "Exercise Evaluation Rpt for Salem Exercise on 831026"
* Federal Emergency Management Agency 83/11/25 69pp
21681 080 24X Fiche 50-272, 83/12/21, 8401030244

B401060122 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21745 311 24X Fiche 50-272, 83/12/28, 8401060122

--B401060127 Forwards public version of revised emergency plan implementing procedures, including Procedures EP 1-1 re notification of unusual event/significant event, EP 1-2 re alert & EP 1-3 re site area emergency
* Public Service Electric & Gas Co. of New Jersey 83/10/21
VARQA, S A Operating Reactors Branch 1 1p 21745 312 24X Fiche 50-272, 83/12/28, 8401060122

--B401060136 Public version of revised emergency plan implementing procedures, including Procedures EP 1-1 re notification of unusual event/significant event, EP 1-2 re alert & EP 1-3 re site area emergency
* Public Service Electric & Gas Co. of New Jersey 83/10/21
100pp 21745 313 24X Fiche 50-272, 83/12/28, 8401060122

B401101033 Requests exemption from 10CFR50, App R requirements re definition of fire areas & suppression sys (per Generic Ltr 83-33) Detailed justification will be submitted by 840131
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/12/28 VARQA, S A Operating Reactors Branch 1 4pp 21772 294 24X Fiche 50-272, 83/12/28, 8401101033

B401050270 Responds to util 831110 request that determination be made as to whether proposed change to security plan to implement vital island concept be made per 10CFR50.54 or 10CFR50.90
Request referred to Headquarters for review
MARTIN, T T Division of Engineering & Technical Programs 83/12/29
UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 3pp
21727 171 24X Fiche 50-272, 83/12/29, 8401050270

B401101049 Forwards control room design review summary report required by Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" W/o encl
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/12/29 VARQA, S A Operating Reactors Branch 1 1p 21772, 211 24X Fiche 50-272, 83/12/29, 8401101049

B401200185 Requests addl exemptions from listed 10CFR50, App R requirements, per 831228 ltr, explaining significant deviation in interpretation provided in Generic Ltr 83-33
Justification will be submitted by 840131
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
84/01/13 VARQA, S A Operating Reactors Branch 1 4pp 21863 354 24X Fiche 50-272, 84/01/13, 8401200185

B401240566 Discusses 831107 SALP rpt for Oct 1982 - Sept 1983, util 831220 ltr & 831201 meeting re operating performance List of attendees encl No changes to rpt necessary
MURLEY, T E Region 1, Office of Director 84/01/19 UDERITZ, R A Public Service Electric & Gas Co. of New Jersey 4pp 21907 029 24X Fiche 50-272, 84/01/19, 8401240566

--B401240577 SALP rpt for Oct 1982 - Sept 1983
* Region 1, Office of Director 83/11/07 44pp 21907 033 24X Fiche 50-272, 84/01/19, 8401240566

> Operating license stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000, 83/10/18, 8401250015

--B205270663 Provides info re qualifications & experience of personnel operating plant during current strike, in response to Chairman Palladino request
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-195 82/05/14 4pp 21964 154 24X Fiche 50-000, 83/10/18, 8401250015

B401040175 Provides update on mods to post-accident sampling sys (PASS) Sys capabilities will be upgraded through direct tie-in of RHR pump discharge sample lines w/PASS, eliminating need for current sys
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/12/02 MURLEY, T E Region 1, Office of Director 2pp
21702 098 24X Fiche 50-272, 83/12/02, 8401040175

B401040203 Forwards Nuclear Oversight Committee charter First committee meeting held on 831027 & featured discussion of introductory matters, administrative details & schedule for future 1984 meetings
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/12/08 STAROSTECKI, R Division of Project & Resident Programs 4pp 21701 199 24X Fiche 50-272, 83/12/08, 8401040203

B40110094 Responds to TMI Item II F 2, "Inadequate Core Cooling Instrumentation" Calibr & test info for Unit 2 tentatively scheduled for submittal by 840301
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
83/12/23 VARQA, S A Operating Reactors Branch 1 3pp 21772 212 24X Fiche 50-272, 83/12/23, 840110094

B401100301 Application for amend to Licenses DPR-70 & DPR-75, consisting of License Change Request (LCR) 83-17 re rewording of action statements for Unit 1 to agree w/Unit 2 & STS & LCR-83-18 re diesel generator surveillance
UDERITZ, R A Public Service Electric & Gas Co. of New Jersey
83/12/27 VARQA, S A Operating Reactors Branch 1 10pp 21759 175 24X Fiche 50-272, 83/12/27, 8401100301

--B401100317 Proposed License Change Requests 83-17, 83-18 & 83-19 re mod of Unit 1 Tech Spec Tables 3.3-1 & 3.3-3 to be consistent w/Unit 2 & correcting typographical error re diesel generator surveillance
* Public Service Electric & Gas Co. of New Jersey 83/12/27
7pp 21759 178 24X Fiche 50-272, 83/12/27, 8401100301

B401180126 SAFETY EVALUATION REPORT RELATED TO PLANT RESTART OF SALEM NUCLEAR GENERATING STATION, UNIT NOS 1 AND 2 Docket Nos 50-272 And 50-311 (Public Service Electric And Gas Company, et al)
* Division of Licensing NUREG-0995 83/12/31 117pp. Available at NRC \$5 00 21847 176 24X Fiche 50-272, 83/12/31, 8401180126

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

B401200215 Forwards fee for 831227 application to Amend Licenses DPR-70 & DPR-75
LIDEN, E A Public Service Electric & Gas Co. of New Jersey
84/01/12 VARQA, S A Operating Reactors Branch 1 1p 21863 360 24X Fiche 50-272, 84/01/12, 8401200215

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Petts & Troubridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401040153 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-15 & 50-311/83-12 Until position against testing 228J156 will be documented in Mar 1984
STAROSTECKI, R Division of Project & Resident Programs 83/12/23
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21701 354 24X Fiche 50-272, 83/12/23, 8401040153

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 9HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

840100408 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-15 & 50-311/83-12
STAROSTECKI, R Division of Project & Resident Programs 83/12/30
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
21763 032 24X Fiche 50-272, 83/12/30, 840100408

--840100419 Responds to NRC 831109 ltr re violations noted in IE Insp Repts 50-272/83-15 & 50-311/83-12 Corrective actions corporate QA organization relocated from Newark to Artificial Island
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/20 STAROSTECKI, R Division of Project & Resident Programs
2pp 21763 033 24X Fiche 50-272, 83/12/30, 840100408

8401130131 Ack receipt of 830826 & 1209 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-14 & 50-311/83-15
STAROSTECKI, R Division of Project & Resident Programs 84/01/09
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
21802 100 24X Fiche 50-272, 84/01/09, 8401130131

--8401130134 Responds to NRC 830720 ltr re violations noted in IE Insp Repts 50-272/83-14, 50-311/83-15 & 50-311/83-18 Corrective actions design change prepared to install permanent instrumentation
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/08/26 STAROSTECKI, R Division of Project & Resident Programs
4pp 21802 101 24X Fiche 50-272, 84/01/09, 8401130131

--8401130143 Suppls response to NRC 830720 ltr re violations noted in IE Insp Repts 50-272/83-14, 50-311/83-15 & 50-311/83-18 Corrective actions TRIB electrical & mechanical lineups reviewed & approved in accordance w/existing requirements
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/09 STAROSTECKI, R Division of Project & Resident Programs
4pp 21802 105 24X Fiche 50-272, 84/01/09, 8401130131

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 129pp 21946 033 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401240520 Forwards IE Mgt Meeting Repts 50-272/84-01 & 50-311/84-01 on 840105
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21918:080 24X Fiche 50-272, 84/01/10, 8401240520

--8401240530 IE Mgt Meeting Rept 50-272/84-01 & 50-311/84-01 on 840105 Major areas discussed status of util action plan for improvement of nuclear dept operations, submitted to NRC in Aug 1983.
LINVILLE, J C Region 1, Office of Director NORRHOLM, L J Division of Project & Resident Programs 84/01/06 40pp
21918 082 24X Fiche 50-272, 84/01/10, 8401240520

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957:142 24X Fiche 50-000, 84/01/16, 8312120114

8401230454 Ack receipt of 831228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-33 & 50-311/83-33
STAROSTECKI, R Division of Project & Resident Programs 84/01/17
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
21882 165 24X Fiche 50-272, 84/01/17, 8401230454

--8401230461 Responds to NRC 831123 ltr re violations noted in IE Insp Repts 50-272/83-33 & 50-311/83-33 Corrective actions LER 83-048/03L filed on 831104 Shift supervisor counseled re submitting safety-related equipment failure repts
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/12/28 STAROSTECKI, R Division of Project & Resident Programs
2pp 21882 167 24X Fiche 50-272, 84/01/17, 8401230454

8312120116 IE Info Notice 84-03, "Compliance w/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401240566 Discusses 831107 SALP rept for Oct 1982 - Sept 1983, until 831220 ltr & 831201 meeting re operating performance List of attendees encl No changes to rept necessary
MURLEY, T E Region 1, Office of Director 84/01/19 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 4pp 21909 029 24X Fiche 50-272, 84/01/19, 8401240566

--8401240577 SALP rept for Oct 1982 - Sept 1983
* Region 1, Office of Director 83/11/07 44pp 21909 033 24X Fiche 50-272, 84/01/19, 8401240566

--8401240619 Informs of 831201 onsite meeting to discuss results of 831107 SALP rept Written comments may be provided within 20 days after meeting
STAROSTECKI, R Division of Project & Resident Programs 83/11/22
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 21909 077 24X Fiche 50-272, 84/01/19, 8401240566

--8401240628 Expresses concern re 831107 SALP rept statements on util operating performance Extension until 840125 requested for providing detailed response to SALP findings in functional area of plant operations
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/12/20 STAROSTECKI, R Division of Project & Resident Programs
2pp 21909 078 24X Fiche 50-272, 84/01/19, 8401240566

R Periodic operating reports & related correspondence

8401230004 Monthly operating rept for Dec 1983 W/840110 ltr MILLER, L K, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/12/31 Director's Office, Office of Inspection and Enforcement 16pp 21885 005 24X Fiche 50-311, 83/12/31, 8401230004

8401310265 Forwards "Nuclear Oversight Committee," first quarterly rept
LIDEN, E A Public Service Electric & Gas Co of New Jersey
84/01/26 VARQA, S Operating Reactors Branch 1 1p 22018 104 24X Fiche 50-272, 84/01/26, 8401310265

--8401310268 "Nuclear Oversight Committee," first quarterly rept
* Public Service Electric & Gas Co of New Jersey 84/01/23 11pp 22018 105 24X Fiche 50-272, 84/01/26, 8401310265

S Reportable occurrences, LERs & related correspondence

8401100010 Outlines completion of corrective action program stemming from Feb 1983 reactor trip breaker failures, described in item C 7 2 of 830408 ltr Intent of NRC 830506 order met Documentation sent to vendors of long-term program supplies
LIDEN, E A Public Service Electric & Gas Co of New Jersey, 83/12/19 EISENHUT, D G Division of Licensing 2pp 21761 201 24X Fiche 50-272, 83/12/17, 8401100010

8401240002 LER 83-062/03L-0 on 831128, during vital instrument bus transfer, RHR common suction valve 2RH2 closed, resulting in loss of RHR flow through RCS Caused by pressure transmitter PT-405 spike due to voltage transient W/831223 ltr RUPP, J L, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/12/23 MURLEY, T E Region 1, Office of Director 4pp 21912 303 24X Fiche 50-311, 83/12/23, 8401240002

DOCKETED ITEMS

8401130285 LER 83-065/03L-0 on 831207, diesel generator 20 voltage regulator failed, causing generator breaker to trip on overcurrent. Caused by grounded voltage regulator control power transformer. Transformer replaced W/831230 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/12/30 MURLEY, T. E. Region 1, Office of Director 4pp 21801 117 24X Fiche 50-311, 83/12/30, 8401130285

8401130320 LER 83-061/03L-0 on 831207, during maint shutdown, safeguards equipment control Channel 2A inadvertently actuated while testing, causing vital bus 2A to be deenergized. Caused by reversing polarity of leads W/831230 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/12/30 MURLEY, T. E. Region 1, Office of Director 5pp 21798 300 24X Fiche 50-311, 83/12/30, 8401130320

8401130333 LER 83-064/03L-0 on 831202, during surveillance test on low pressure carbon dioxide fire suppression sys, pilot valve 2FF377 did not completely seat. Caused by frost on valve seat. Valve seated properly W/831230 ltr. RUPP, J. L., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/12/30 MURLEY, T. E. Region 1, Office of Director 4pp 21801 194 24X Fiche 50-311, 83/12/30, 8401130333

8401240566 Discusses 831107 SALP rept for Oct 1982 - Sept 1983, until 831220 ltr & 831201 meeting re operating performance. List of attendees encl. No changes to rept necessary. MURLEY, T. E. Region 1, Office of Director 84/01/19 UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 4pp 21909 029 24X Fiche 50-272, 84/01/19, 8401240566

--8401240577 SALP rept for Oct 1982 - Sept 1983
* Region 1, Office of Director 83/11/07 4pp 21909 033 24X
Fiche 50-272, 84/01/19, 8401240566

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities. Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5). FELTON, J. M. Division of Rules and Records 83/11/02 O'NEILL, J. H. Shaw, Pittman, Potts & Traubridge 4pp 21957 337 24X
Fiche 50-000, 83/11/02, 8401250163

--8401250241 Recommends approval of request for exception under requirements & conditions of COMJIA-80-35 & SECY-82-111 for location of emergency operations facility. DIRCKS, W. J. Office of the Executive Director for Operations SECY-82-390 82/09/21 10pp 21958 293 24X
Fiche 50-000, 83/11/02, 8401250163

101030264 Forwards "Exercise Evaluation Rept of 830927 Exercise of Offsite Radiological Emergency Preparedness Plans, Rancho Seco". KRIMM, R. W. Federal Emergency Management Agency 83/12/07 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21681 016 24X Fiche 50-312, 83/12/07, 8401030264

--8401030267 "Exercise Evaluation Rept of 830927 Exercise of Offsite Radiological Emergency Preparedness Plans, Rancho Seco".
* Federal Emergency Management Agency 83/10/28 6pp 21681 018 24X Fiche 50-312, 83/12/07, 8401030264

8401030266 Forwards progress rept on offsite emergency preparedness at facility. Statement of adequacy of offsite emergency preparedness will be submitted after State of CA provides schedule for correction of unresolved deficiencies. KRIMM, R. W. Federal Emergency Management Agency 83/12/07 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 12pp 21680 348 24X Fiche 50-312, 83/12/07, 8401030266

8312290261 Forwards IE Insp Rept 50-312/83-28 on 830926-29 No violations noted. NORDERHAUG, L. R. Region 5, Office of Director 83/12/15 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 21658 224 24X Fiche 50-312, 83/12/15, 8312290261

--8312290264 IE Insp Rept 50-312/83-28 on 830926-29 No noncompliance noted. Major areas inspected emergency preparedness exercises & associated critiques. FISHER, F., SCHUSTER, M. D. Region 5, Office of Director 83/12/15 5pp 21658 226 24X Fiche 50-312, 83/12/15, 8312290261

8401160146 Forwards comments on detailed control room design review program plan. Majority of Suppl 1 to NUREG-0737 requirements addressed. Plan provides inadequate basis for design review. Meeting suggested to discuss deficiencies. STOLZ, J. F. Operating Reactors Branch 4 83/12/22 RODRIGUEZ, R. J. Sacramento Municipal Utility District 15pp 21822 338 24X
Fiche 50-312, 83/12/22, 8401160146

8401100172 Resubmits request for exemption from Section III Q 2 of App R to 10CFR50 for electrical penetration area of auxiliary bldg. Util proposes to install 1 h fire barrier W/ one oversize drawing. Aperture card is in PDR. RODRIGUEZ, R. J. Sacramento Municipal Utility District 84/01/04 STOLZ, J. F. Operating Reactors Branch 4 2pp 21759 358 24X
Fiche 50-312, 84/01/04, 8401100172

8401160219 Forwards IE Safeguards Insp Rept 50-312/83-33 on 831219-28. No violations observed. Rept withheld (ref 10CFR2 790 & 73 21). NORDERHAUG, L. R. Region 5, Office of Director 84/01/09 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 21814 222 24X Fiche 50-312, 84/01/09, 8401160219

8401170514 Informs that refund to Util for Class III fee remitted w/821015 application will be applied to Class III fee due NRC for 830317 application re 10CFR50, App R W/o encls. MILLER, W. O. License Fee Management Branch 84/01/11 RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp 21847 135 24X Fiche 50-312, 84/01/11, 8401170514

O Adjudicatory correspondence

8401230482 Order extending time until 840124 for Commission to act to review ALAB-746. CHILK, S. J. Office of the Secretary of the Commission 83/01/20 Commissioners 1p 21882 162 24X Fiche 50-312, 83/01/20, 8401230482

8401060275 Order extending time until 840110 for Commission to act to review ALAB-746. CHILK, S. J. Office of the Secretary of the Commission 84/01/03 Commissioners 1p 21741 178 24X Fiche 50-312, 84/01/03, 8401060275

8401120243 Order extending time until 840117 for Commission to act to review ALAB-746. CHILK, S. J. Office of the Secretary of the Commission 84/01/10 Commissioners 1p 21793 262 24X Fiche 50-312, 84/01/10, 8401120243

8401190190 Order extending time until 840124 for Commission to act to review Director's Decision DD-83-19. CHILK, S. J. Office of the Secretary of the Commission 84/01/17 Commissioners 1p 21691 304 24X Fiche 50-312, 84/01/17, 8401190190

8401260215 Order extending time until 840131 for Commission to act to review ALAB-746. CHILK, S. J. Office of the Secretary of the Commission 84/01/24 Commissioners 1p 21956 126 24X Fiche 50-312, 84/01/24, 8401260215

P Operating license stage documents & correspondence

8401030027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies. Supporting ltrs encl. CALSOYAS, C. D. Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, 83/10/10, 8401030027

8401030043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies. NRC has no records subj to request. Utilis not required to submit insurance rating to NRC. FELTON, J. M. Division of Rules and Records 83/10/25 CALSOYAS, C. D. Affiliation Unknown 1p 21736 236 24X Fiche 50-000, 83/10/25, 8401030043

8401120318 Requests extension until 840115 for submittal of NUREG-0737 Tech Specs for RCS vents, in response to Generic Ltr 83-37. RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/12/09 STOLZ, J. F. Operating Reactors Branch 4 2pp 21794 142 24X
Fiche 50-312, 83/12/09, 8401120318

8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants. MATHEWS, C. S. Transamerica Delaval, Inc 83/12/16 NOVAK, T. M. Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, 83/12/16, 8312200154

DOCKETED ITEMS

137

8401030134 Forwards seismic & stress calculations for reactor bldg
squalling valves SFV-53603 & SFV-53610 Encl info should
satisfy NRC 831207 questions
GABRIELLI, E M Sacramento Municipal Utility District 83/12/27
STOLZ, J F Operating Reactors Branch 4 94pp 21683 221 24X
Fiche 50-312, 83/12/27, 8401030134

8401130103 Requests addl info in order to complete evaluation of 830922
request for extension until 850401 for implementation of
licensed operator staffing rule, 10CFR50 54(m)(2) Meeting
arranged to discuss info
STOLZ, J F Operating Reactors Branch 4 83/12/30 RODRIGUEZ, R J
Sacramento Municipal Utility District 2pp 21821 122 24X
Fiche 50-312, 83/12/30, 8401130103

8401170480 Forwards Amend 51 to License DPR-54 & notice of issuance
& availability Amend requires radiographic insp of HPI
nozzles C & D during refueling outages
MINER, B Operating Reactors Branch 4 84/01/03 RODRIGUEZ, R J
Sacramento Municipal Utility District 4pp 21844 282 24X
Fiche 50-312, 84/01/03, 8401170480

--8401170499 Amend 51 to License DPR-54, adding radiographic insp of HPI
nozzles C & D during refueling outages
STOLZ, J F Operating Reactors Branch 4 84/01/03 1p
21844 286 24X Fiche 50-312, 84/01/03, 8401170480

--8401170522 Notice of issuance & availability of Amend 51 to License
DPR-54
STOLZ, J F Operating Reactors Branch 4 84/01/03 2pp
21844 287 24X Fiche 50-312, 84/01/03, 8401170480

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401310165 Forwards SER accepting licensee assessment that reactor sys
would withstand effects of asymmetric LOCA loads & provide
high assurance that reactor could be brought safely to cold
shutdown condition Multi-Plant Issue D-10 resolved
STOLZ, J F Operating Reactors Branch 4 84/01/16 RODRIGUEZ
Sacramento Municipal Utility District 2pp 22034 114 24X
Fiche 50-312, 84/01/16, 8401310165

--8401310167 SER accepting licensee assessment that reactor would
withstand effects of asymmetric LOCA loads & be capable of
being brought safely to cold shutdown condition
* NRC - No Detailed Affiliation Given. 84/01/16 65pp
22034 116 24X Fiche 50-312, 84/01/16, 8401310165

8401240246 Advises that intent of 10CFR50 54, "Licensed Operator
Staffing at Nuclear Power Plants," met w/combination of
assigned senior licensed & licensed personnel & licensed
shift technical advisor
RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp
21910 138 24X Fiche 50-312, 84/01/20, 8401240246

8401310261 Suppl 2 to 840217 application for proposed Amend 83 to
License DPR-54, limiting conditions for operation re RCS &
accident monitoring instrumentation, in response to Generic
Ltr 83-37.
RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/23
EISENHUT, D G Division of Licensing 1p 22021-309 24X
Fiche 50-312, 84/01/23, 8401310261

--8401310264 Proposed Tech Specs re limiting conditions for operation for
RCS & accident monitoring instrumentation
* Sacramento Municipal Utility District 84/01/23 14pp
22021 310 24X Fiche 50-312, 84/01/23, 8401310261

8401310351 Application for amend to License DPR-54, in partial response
to Generic Ltr 83-37 & requirements of NUREG-0737, Items
II E 1.1, II F 1, II F 2 & III D 3.4 concerning control room
habitability requirements
RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/23
EISENHUT, D G Division of Licensing 2pp 22026 244 24X
Fiche 50-312, 84/01/23, 8401310351

--8401310355 Proposed Tech Specs re Generic Ltr 83-37, including both
new limiting conditions for operation & new surveillance
requirements per TMI Action Items II F 1, "Noble Gas
Effluent Monitors" & II F 2, "Subcooling Margin Monitor"
* Sacramento Municipal Utility District 84/01/23 5pp
22026 246 24X Fiche 50-312, 84/01/23, 8401310351

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E
Shaw, Pittman, Putts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

8401030226 Forwards IE Enforcement Conference Rept 50-312/83-30 on
831130 No violations noted
MARTIN, J B Region 5, Office of Director 83/12/12 RODRIGUEZ, R
Sacramento Municipal Utility District 1p 21682 340 24X
Fiche 50-312, 83/12/12, 8401030226

--8401030230 IE Enforcement Conference Rept 50-312/83-30 on 831130 No
violations noted Major areas discussed violations identified
during Sept 1983 insp
MARTIN, J B, YOUNG, T, JOHNSON, A D Region 5, Office of Director
83/12/07 3pp 21682 341 24X Fiche 50-312, 83/12/12, 8401030226

8312290261 Forwards IE Insp Rept 50-312/83-28 on 830926-29 No
violations noted
NORDEHAUG, L R Region 5, Office of Director 83/12/15
RODRIGUEZ, R J Sacramento Municipal Utility District 2pp
21658 224 24X Fiche 50-312, 83/12/15, 8312290261

--8312290264 IE Insp Rept 50-312/83-28 on 830926-29 No noncompliance
noted Major areas inspected emergency preparedness exercises
& associated critiques
FISH, R F, SCHUSTER, M D Region 5, Office of Director 83/12/15
3pp 21658 226 24X Fiche 50-312, 83/12/15, 8312290261

8401040539 Responds to IE Bulletin 80-04, "Main Steam Line Break
W/Continued Feedwater Addition" Pump specialist contacted &
preliminary evaluations indicate pump damage will not occur
Final analysis report will be submitted by 840201
RODRIGUEZ, R J Sacramento Municipal Utility District 83/12/19
STOLZ, J F Operating Reactors Branch 4 1p 21706 328 24X
Fiche 50-312, 83/12/19, 8401040539

8401100404 Forwards IE Insp Rept 50-312/83-31 on 831018-1204 No
violations noted
BISHOP, T W Division of Resident, Reactor Project & Engineering
Programs 83/12/27 RODRIGUEZ, R Sacramento Municipal Utility
District 2pp 21762 236 24X Fiche 50-312, 83/12/27, 8401100404

--8401100413 IE Insp Rept 50-312/83-31 on 831018-1204 No violations
noted Major areas inspected operational safety verification,
EBF sys walkdown, monthly maint observations & monthly
surveillance observations
CANTER, H L, PEREZ, G P, YOUNG, T Region 5, Office of Director
83/12/20 8pp 21762 238 24X Fiche 50-312, 83/12/27, 8401100404

8312120070 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120070

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type SHM Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060, 24X Fiche 50-000, 83/12/30, 8312120093

8401200017 Forwards IE Insp Rept 50-312/83-26 on 831122-23 No
noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/12/30
RODRIGUEZ, R J Sacramento Municipal Utility District 2pp
21864-345 24X Fiche 50-312, 83/12/30, 8401200017

DOCKETED ITEMS

--B401200023 IE Insp Rept 50-312/83-26 on 831122-23 No noncompliance noted Major areas inspected followup of reported resin bag failures & post-implementation insp of NUREG-0737, Items 11 D 3 re post-accident sampling & 11 F 1 re monitoring NORTH, H S , WENSLAWSKI, F A Region 5, Office of Director 83/12/30 7pp 21864 347 24X Fiche 50-312,83/12/30,8401200017

B401170480 Forwards Amend 51 to License DPR-54 & notice of issuance & availability Amend requires radiographic insp of HPI nozzles C & D during refueling outages MINER, S Operating Reactors Branch 4 84/01/03 RODRIGUEZ, R J Sacramento Municipal Utility District 4pp 21844 282 24X Fiche 50-312,84/01/03,8401170480

--B401170499 Amend 51 to License DPR-54, adding radiographic insp of HPI nozzles C & D during refueling outages GIDUZ, J F Operating Reactors Branch 4 84/01/03 1p 21844 286 24X Fiche 50-312,84/01/03,8401170480

B401160219 Forwards IE Safeguards Insp Rept 50-312/83-33 on 831219-28 No violations observed Rept withheld (ref LOCFR2 790 & 73 21) NORDERHAUG, L R Region 5, Office of Director 84/01/09 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 21814 222 24X Fiche 50-312,84/01/09,8401160219

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

B312120107 IF Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

B401300277 Forwards IE Insp Rept 50-312/83-34 on 831107-1216 & notice of violation w/o notice BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/11 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 21995 347 24X Fiche 50-312,84/01/11,8401300277

--B401300280 IE Insp Rept 50-312/83-34 on 831107-1216 Noncompliance noted temporary change deleted precautions in operating & in-core instrumentation surveillance procedures w/o proper review CANTER, H L , YOUNG, T , JOHNSON, A D Region 5, Office of Director 84/01/09 4pp 21995 349 24X Fiche 50-312,84/01/11,8401300277

I312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

J401300028 Notification of B40126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators CARUSO, R Licensing Branch 2 84/01/17 SCHWENCER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000,84/01/17,8401300028

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

B401300311 Ark receipt of 831227 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-312/83-25 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/25 RODRIGUEZ, R J Sacramento Municipal Utility District 1p 21996 330 24X Fiche 50-312,84/01/25,8401300311

--B401300313 Responds to NRC 831128 ltr re violations noted in IE Insp Rept 50-312/83-25 Corrective actions memo distributed to personnel stressing importance of following procedures as written & Procedure AP 22 will be reviewed & revised GABRIELLI, E M Sacramento Municipal Utility District 83/12/27 MARTIN, J B Region 5, Office of Director 5pp 21996 331 24X Fiche 50-312,84/01/25,8401300311

R Periodic operating reports & related correspondence

B401130206 Monthly operating rpt for Dec 1983 W/B40106 ltr COLONBO, R , RODRIGUEZ, R J Sacramento Municipal Utility District 83/12/31 Director's Office, Office of Inspection and Enforcement 4pp 21801 342 24X Fiche 50-312,83/12/31,8401130206

S Reportable occurrences, LERs & related correspondence

B401040144 LER 83-038/03L-D on 831110,DHR pump B suction isolation valve SPV-25004 from borated water storage tank failed to open Caused by packing binding on valve stem, leading to motor trip Packing readjusted W/831208 ltr COLONBO, R W , RODRIGUEZ, R J Sacramento Municipal Utility District 83/12/08 MARTIN, J B Region 5, Office of Director 2pp 21703 208 24X Fiche 50-312,83/12/08,8401040144

B401040537 PND-V-83-040 on 831215,w/svc air compressor C out of svc, compressor B tripped out of svc Pressure dropped to 95 psig Temporary air compressors installed & pressure returned to normal Plant will be placed in cold shutdown YOUNG, T Region 5, Office of Director 83/12/15 1p 21707 241 24X Fiche 50-312,83/12/15,8401040537

B401040214 RD 83-39 on 831214,during review of surveillance procedures, auditor noticed that shift data for pressurizer level did not satisfy acceptance criteria On 831215,three channels retested & passed requirements for operability QUARE, R P Sacramento Municipal Utility District 83/12/16 MARTIN, J B Region 5, Office of Director 1p 21701 214 24X Fiche 50-312,83/12/16,8401040214

B401120353 LER 83-037/01T-D on 831214,during review of surveillance procedures,shift data obtained for pressurizer level did not satisfy acceptance criteria Caused by lack of training in Tech Specs W/831227 ltr COLONBO, R W , GABRIELLI, E M Sacramento Municipal Utility District 83/12/27 MARTIN, J B Region 5, Office of Director 3pp 21791 350 24X Fiche 50-312,83/12/27,8401120353

B401160240 Followup LER 83-037/03L-1 on 831008,during Surveillance Test SP 203 06A, valve HV-26105 motor operator torqued out & would not open valve Caused by low torque switch setting & bypass switch setting Switches readjusted W/B40105 ltr COLONBO, R W , RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/05 MARTIN, J B Region 5, Office of Director 4pp 21814 215 24X Fiche 50-312,84/01/05,8401160240

B401160265 LER 83-040/03L-D on 831209,auxiliary feedwater flow transmitters FT-31802,31803,31902 & 31903 determined not properly calibr Caused by incorrectly sized orifice plates Correct plates will be installed on 840201 W/B40109 ltr COLONBO, R W , RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/09 MARTIN, J B Region 5, Office of Director 3pp 21813 302 24X Fiche 50-312,84/01/09,8401160265

B401170186 Part 21 rept re loose flexible coupling drive hubs,mfg by Lowagay Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utills notified BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000,84/01/09,8401170186

B401260098 RD 83-08 on 830909 & 1121,problems w/computer code used to generate meteorological repts identified Dose commitment to public for 1982-83 recalculated using conservative default meteorology New sys (MIDAS) will be functional by Jan 1985 RODRIGUEZ, R J Sacramento Municipal Utility District 84/01/13 MARTIN, J B Region 5, Office of Director 3pp 21957 021, 24X Fiche 50-312,84/01/13,8401260098

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

B401170307 Advises that on 820818,throttle valve 3 failed to close fully,resulting in main steam header pressure decrease below 600 psig On 810808,unidentified individual observed running toward turbine bldg MARSHALL, J R Arkansas Power & Light Co 83/09/27 COLLINS, J T Region 4, Office of Director, 5pp 21833 224 24X Fiche 50-313,83/09/27,8401170307

B401270066 Forwards IE Safeguards Insp Repts 50-313/83-23 & 50-368/83-23 on 830822-26 & notice of violation IE insp repts withheld (ref LOCFR73 21) GRIFFIN, J E Region 4, Office of Director 83/12/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21982 001 24X Fiche 50-313,83/12/20,8401270066

--B401270072 Notice of violation from Insp on 830822-26 Violation noted two of four explosive detectors did not meet 95% accuracy criterion & switch over to secondary emergency security power supply did not operate
* Region 4, Office of Director 83/12/20 2pp 21982 003 24X
Fiche 50-313, 83/12/20, B401270066

B401060181 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21744 185 24X Fiche 50-313, 83/12/28,
B401060181

--B401060186 Public version of Rev 9 to emergency plan W/831212 ltr & revised table of contents
MARSHALL, J R Arkansas Power & Light Co 83/11/30 COLLINS, J T
Region 4, Office of Director 91pp 21744 186 24X
Fiche 50-313, 83/12/28, B401060181

B401170377 Clarifies NRC approval of util exemption request for emergency planning exercises at facility Reduction of exercise will result in higher quality performance & improvement in exercises which are held
MARSHALL, J R Arkansas Power & Light Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 21828 339
24X Fiche 50-313, 83/12/30, B401170377

B401170259 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25
QAOLLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 84/01/10 GRIFFIN, J M Arkansas Power & Light Co 1p
21830 353 24X Fiche 50-313, 84/01/10, B401170259

--B401170264 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 Corrective actions memo issued providing clarification of documentation requirements & fire watch training program revised
MARSHALL, J R Arkansas Power & Light Co 83/12/15
QAOLLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 5pp 21830 354 24X Fiche 50-313, 84/01/10, B401170259

B401240182 Forwards documentation supporting 831230 request for exemption from requirement for full-scale emergency planning exercise in 1984, per Region IV emergency planning staff request
MARSHALL, J R Arkansas Power & Light Co 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 21908 303
24X Fiche 50-313, 84/01/18, B401240182

B401250057 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21947 151 24X Fiche 50-313, 84/01/18,
B401250057

--B401250060 Public version of Rev 0 to Emergency Plan Implementing Procedure 1903 34, "Administration of Potassium Iodide"
W/831122 transmittal & receipt form
LEVINE, J M Arkansas Power & Light Co 83/11/22 14pp
21947 152 24X Fiche 50-313, 84/01/18, B401250057

B401250081 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21946 311 24X Fiche 50-313, 84/01/18,
B401250081

--B401250085 Public version of Rev 8 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equipment" & Rev 4 to Procedure 1903 61, "Communications Equipment Tests"
W/831110 transmittal & receipt form
LEVINE, J M, BAKER, D Arkansas Power & Light Co 83/11/09 5pp
21946 312 24X Fiche 50-313, 84/01/18, B401250081

B401260024 Releases public version of amended nuclear contingency plan & revised nuclear contingency plan procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21990 301 24X Fiche 50-313, 84/01/18,
B401260024

--B401260027 Forwards public version of Amend 3 to nuclear contingency plan & revised nuclear contingency plan procedures, including Procedures 2 re notifications & 7 re response guides/ checklists
MARSHALL, J R Arkansas Power & Light Co 83/12/12 EISENHUT, D G
Office of Nuclear Reactor Regulation, Director 1p 21990 302
24X Fiche 50-313, 84/01/18, B401260024

--B401260029 Public version of Amend 3 to nuclear contingency plan
* Arkansas Power & Light Co 83/11/30 3pp 21990.303 24X
Fiche 50-313, 84/01/18, B401260024,

--B401260032 Public version of revised nuclear contingency plan procedures, including Procedures 1 re assignment of personnel to emergency response organization, 2 re notifications & 7 re response guides/checklists
GRIFF, J M Arkansas Power & Light Co 83/12/04 29pp 21990 308
24X Fiche 50-313, 84/01/18, B401260024

B401260245 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21971 361 24X Fiche 50-313, 84/01/18,
B401260245

--B401260251 Public version of Rev 6 to Emergency Plan Implementing Procedure 1903 22, "Fire or Explosion" W/831229 receipt form
LEVINE, J M Arkansas Power & Light Co 83/12/29 NRC - No
Detailed Affiliation Given 3pp 21987 359 24X
Fiche 50-313, 84/01/18, B401260245

B401260301 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21990 356 24X Fiche 50-313, 84/01/20,
B401260301

--B401260305 Public version of Rev 5 to Emergency Plan Implementing Procedure 1903 31, "Exclusion Area Evacuation" W/831228 receipt form
LEVINE, J M Arkansas Power & Light Co 83/12/22 NRC - No
Detailed Affiliation Given 7pp 21990 357 24X
Fiche 50-313, 84/01/20, B401260301

B401260312 Releases public version of revised nuclear contingency plan & procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21990 341 24X Fiche 50-313, 84/01/20,
B401260312

--B401260316 Forwards public version of Amend 3 to nuclear contingency plan, Rev 3 to Nuclear Contingency Plan Procedures 1, 2, 3 & 7 & Rev 2 to Procedure 9 W/a encl
MARSHALL, J R Arkansas Power & Light Co 83/12/12 COLLINS, J T
Region 4, Office of Director 1p 21990 342 24X
Fiche 50-313, 84/01/20, B401260312

B401310458 Releases public versions of revs to util nuclear contingency plan & implementing Procedures 1, 2, 3, 7 & 9
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22036 306 24X Fiche 50-313, 84/01/20,
B401310458

--B401310460 Forwards revs to nuclear contingency plan & implementing Procedures 1, 2, 3, 7 & 9 W/a encl
MARSHALL, J R Arkansas Power & Light Co 83/12/15 COLLINS, J T
Region 4, Office of Director 1p 22036 307 24X
Fiche 50-313, 84/01/20, B401310458

B401300361 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22006 001 24X Fiche 50-313, 84/01/26,
B401300361

--B401300364 Public version of revised emergency plan implementing procedures, including Procedure 1903 32 re area evacuation & 1903 44 re duties of emergency recovery team W/840112 transmittal & receipt form
LEVINE, J M Arkansas Power & Light Co 84/01/11 NRC - No
Detailed Affiliation Given 24pp 22006 002 24X
Fiche 50-313, 84/01/26, B401300361

H General correspondence

B401240335 Informs that firm name of counsel for applicants/licensees charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S South Carolina Electric & Gas Co REYNOLDS, N S
Texas Utilities Generating Co 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000, 84/01/19,
B401240335

P Operating license stage documents & correspondence

B40120100 Forwards 8FR & LLL technical evaluation rept re verification testing for adequacy of station electric distribution sys voltage analysis Analysis acceptable Amend to Tech Specs for feeder breakers due in 30 days
BTOLZ, J F Operating Reactors Branch 4 83/12/19 GRIFFIN, J M
Arkansas Power & Light Co 2pp 21805 187 24X
Fiche 50-313, 83/12/19, B40120100

DOCKETED ITEMS

--8401120104 SER re verification testing for adequacy of analysis of station electric distribution sys voltages Analysis acceptable
* Office of Nuclear Reactor Regulation, Director 83/12/19 2pp
21805 191 24X Fiche 50-313,83/12/19,8401120100

--8312140428 "Technical Evaluation Rept on Tests Conducted to Verify Analyses Performed on Adequacy of Station Electric Distribution Sys Voltages for Arkansas Nuclear One, Unit 1"
RELAN, J C Lawrence Livermore Laboratory FIN A-0250
UCID-19721 83/10/07 NRC - No Detailed Affiliation Given
7pp 21805 193 24X Fiche 50-313,83/12/19,8401120100.

8401090313 Forwards review of interim reliability evaluation program (IREP) analysis Operator error contribution may be significantly higher than study assumed
STOLZ, J F Operating Reactors Branch 4 83/12/23 GRIFFIN, J M
Arkansas Power & Light Co 1pp 21768 147 24X
Fiche 50-313,83/12/23,8401090313

8401040485 Notifies that B&W rept re NUREG-0737, Item II K 3 5, "Reactor Coolant Pump Trip," will not be available until Jan 1984
Addl time required to prepare plant-specific portion of submittal Final submittal will be provided by 840331
MARSHALL, J R Arkansas Power & Light Co 83/12/27 STOLZ, J F
Operating Reactors Branch 4 1p 21705 348 24X
Fiche 50-313,83/12/27,8401040485

8401040541 Informs that core damage estimate procedure will be developed as result of review to satisfy NUREG-0737, Item II B 3 re post-accident sampling sys & address concerns raised in 830714 & 1031 1trs Schedule expected by 840131
MARSHALL, J R Arkansas Power & Light Co 83/12/27 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 21706 323 24X Fiche 50-313,83/12/27,8401040541

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,8401050382.

1401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,8401090221

401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

8401170382 Forwards response to safety evaluation outstanding questions re NUREG-0737, Item II F 2 on detection of inadequate core cooling requirements Scheduled dates for completion of milestones listed
MARSHALL, J R Arkansas Power & Light Co 84/01/13 STOLZ, J F
Operating Reactors Branch 4 6pp 21828 282 24X
Fiche 50-313,84/01/13,8401170382

401230402 Provides results of analyses of isotopic activity used by Radiological & Environ Sciences Lab in preparation of unknown liquid sample Official documentation of analyses will appear in next confirmatory measurements insp rept
GAOLLIARDO, J E Region 4, Office of Director 84/01/16
GRIFFIN, J M Arkansas Power & Light Co 2pp 21879 193 24X
Fiche 50-313,84/01/16,8401230402

401310312 Submits addl info re proposed sealed source leak testing Tech Specs, in response to NRC 831108 request
MARSHALL, J R Arkansas Power & Light Co 84/01/20 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 8pp 22026 300 24X Fiche 50-313,84/01/20,8401310312

1401270420 Advises that RP Denise will become new Director, Div of Resident, Reactor Project Engineering Programs, effective 840122.
COLLINS, J T. Region 4, Office of Director 84/01/23 GRIFFIN, J M
Arkansas Power & Light Co 1p. 21981 154 24X
Fiche 50-313,84/01/23,8401270420

8401300186 Advises that response to Generic Ltr 83-37 re Tech Spec changes for 11 NUREG-0737 items will not be completed until 840319, due to lengthy Unit 2 outage
MARSHALL, J R Arkansas Power & Light Co 84/01/23. STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 21997 345 24X Fiche 50-313,84/01/23,8401300186.

8401310237 Advises that core damage estimate methodology will be completed by 840131, per NUREG-0737, Item II B 3 "Post-Accident Sampling Sys" Estimate used for informational purposes only
MARSHALL, J R Arkansas Power & Light Co 84/01/24 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 22021 159 24X Fiche 50-313,84/01/24,8401310237

Q Inspection reports, IE Bulletins & correspondence

8401130332 Ack receipt of 830722 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-10 & 50-368/83-10
SEIDLE, W C Region 4, Office of Director 83/08/02 GRIFFIN, J M
Arkansas Power & Light Co 1p 21801 188 24X
Fiche 50-313,83/08/02,8401130332

--8401130339 Responds to NRC 830615 ltr re violations noted in IE Insp Repts 50-313/83-10 & 50-368/83-10 Corrective actions
Procedure 1622 017, "Operation of Control Point," will be issued on 830930
MARSHALL, J R Arkansas Power & Light Co 83/07/22 SEIDLE, W C
Region 4, Office of Director 5pp 21801 189 24X
Fiche 50-313,83/08/02,8401130332

8401270505 Responds to violations noted in IE Insp Repts 50-313/83-20 & 50-308/83-20 Corrective actions personnel collecting milk samples will notify analytical lab staff when samples obtained from local dairies
MARSHALL, J R Arkansas Power & Light Co 83/10/09 SEIDLE, W C
Region 4, Office of Director 3pp 21981 348 24X
Fiche 50-313,83/10/09,8401270505

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info.
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401040444 Ack receipt of 830920 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-17 & 50-368/83-17 Addl info requested within 30 days
GAOLLIARDO, J E Region 4, Office of Director 83/10/27
GRIFFIN, J M Arkansas Power & Light Co 1p 21708 087 24X
Fiche 50-313,83/10/27,8401040444

--8401040452 Responds to NRC 830819 ltr re violations noted in IE Insp Repts 50-313/83-17 & 50-368/83-17 Corrective actions Energy Supply Procedure (ESP) 202 reviewed & revised to comply w/ AP&L-TOP-1A, effective 830901
MARSHALL, J R Arkansas Power & Light Co 83/09/20 SEIDLE, W C
Region 4, Office of Director 4pp 21708 088 24X
Fiche 50-313,83/10/27,8401040444

8401040107 Forwards BALP Repts 50-313/83-22 & 50-368/83-22 for Jul 1982 - June 1983
COLLINS, J T Region 4, Office of Director 83/11/28 GRIFFIN, J M
Arkansas Power & Light Co 4pp 21701 221 24X
Fiche 50-313,83/11/28,8401040107

--8401040111 BALP Repts 50-313/83-22 & 50-368/83-22 for Jul 1982 - June 1983
JOHNSON, W D, SEIDLE, W C Region 4, Office of Director 83/09/15
48pp 21701:227 24X Fiche 50-313,83/11/28,8401040107.

--8308150373 Forwards evaluation of LERs for BALP for Jul 1982 - June 1983 LERs consistent & reasonably detailed to permit understanding events
SEYFRIT, K V Reactor Operations Analysis Branch 83/08/03
GAOLLIARDO, J E Division of Resident, Reactor Project & Engineering Programs. 3pp. 21701 275. 24X Fiche 50-313,83/11/28,8401040107

--8308090279 Evaluates LERs for BALP input for Jul 1982 - June 1983 Boss LERs should have been updated to identify final corrective action when corrective actions different from actions postulated in original LER
SEYFRIT, K V Reactor Operations Analysis Branch 83/07/28
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 8pp 21701 278. 24X Fiche 50-313,83/11/28,8401040107

--8401040212 Responds to NRC 830929 ltr re findings of BALP Repts 50-313/83-22 & 50-368/83-22. Unqualified spare part replaced
MARSHALL, J R. Arkansas Power & Light Co. 83/11/03
GAOLLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 5pp 21701 283 24X Fiche 50-313,83/11/28,8401040107

DOCKETED ITEMS

141

8401170350 Forwards Rockbestos Co GA program insp rept. identifying one violation & 11 noncompliances, for info & action Ack of rept receipt requested W/o encl
QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 83/11/29 GRIFFIN, J M Arkansas Power & Light Co 2pp 21829 344 24X Fiche 50-313, 83/11/29, 8401170350

8401270066 Forwards IE Safeguards Insp Repts 50-313/83-23 & 50-368/83-23 on 830822-26 & notice of violation IE insp repts withheld (ref 10CFR73 21)
QAOLIAIRDD, J E Region 4, Office of Director 83/12/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21982 001 24X Fiche 50-313, 83/12/20, 8401270066

--8401270072 Notice of violation from insp on 830822-26 Violation noted two of four explosive detectors did not meet 95% accuracy criterion & switch over to secondary emergency security power supply did not operate
* Region 4, Office of Director 83/12/20 2pp 21982 003 24X Fiche 50-313, 83/12/20, 8401270066

8401230492 Requests extension of response date to 840207 to respond to 831209 notice of deviation
MARSHALL, J R Arkansas Power & Light Co 83/12/22 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 1p 21880 362 24X Fiche 50-313, 83/12/22, 8401230492

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 129pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401170241 Ack receipt of 831216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-17 & 50-368/83-17
QAOLIAIRDD, J E Region 4, Office of Director 84/01/10 GRIFFIN, J M Arkansas Power & Light Co 1p 21827 156 24X Fiche 50-313, 84/01/10, 8401170241

--8401170487 Responds to NRC 830819 & 1027 ltrs re violations noted in IE Insp Repts 50-313/83-17 & 50-368/83-17 Corrective actions
Rev B to Energy Supply Procedure 202, "Design Process," now includes necessary documentation
MARSHALL, J R Arkansas Power & Light Co 83/12/16 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 4pp 21827 157 24X Fiche 50-313, 84/01/10, 8401170241

8401170259 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-23 & 50-368/83-23
QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 84/01/10 GRIFFIN, J M Arkansas Power & Light Co 1p 21830 333 24X Fiche 50-313, 84/01/10, 8401170259

--8401170264 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-23 & 50-368/83-23 Corrective actions memo issued providing clarification of documentation requirements & fire watch training program revised
MARSHALL, J R Arkansas Power & Light Co 83/12/15 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 5pp 21830 354 24X Fiche 50-313, 84/01/10, 8401170259

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8401270097 Grants 831222 request to extend response date to 831209 notice of deviation until 840207
QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 84/01/20 GRIFFIN, J M Arkansas Power & Light Co 1p 21973 361 24X Fiche 50-313, 84/01/20, 8401270097

8401270269 Forwards Rockbestos Co GA Program Insp Repts 99900277/83-02 & 99900277/83-04 for action Significance of reported findings & ack of rept receipt requested W/o encl
QAOLIAIRDD, J E Region 4, Office of Director 84/01/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21976 111 24X Fiche 50-313, 84/01/20, 8401270269

8401270432 Forwards GA Program Insp Rept 99900400/83-01 identifying Vendor Program Branch concerns Evaluation of findings re quality & acceptability of product or svc requested W/o encl
QAOLIAIRDD, J E Region 4, Office of Director 84/01/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21981 217 24X Fiche 50-313, 84/01/20, 8401270432

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120396 Monthly operating rept for Nov 1983 W/831215 ltr
MORTON, K L, MARSHALL, J R Arkansas Power & Light Co 83/11/30 BASSETT, H S Division of Data Automation & Management Information 7pp 21791 088 24X Fiche 50-313, 83/11/30, 8401120396

8401270399 Monthly operating rept for Dec 1983 W/840113 ltr
MORTON, K L, MARSHALL, J R Arkansas Power & Light Co 83/12/31 BASSETT, H S Office of Resource Management, Director 7pp 21976 048 24X Fiche 50-313, 83/12/31, 8401270399

S Reportable occurrences, LERs & related correspondence

8401170307 Advises that on 820818, throttle valve 3 failed to close fully, resulting in main steam header pressure decrease below 400 psig On 810808, unidentified individual observed running toward turbine bldg
MARSHALL, J R Arkansas Power & Light Co 83/09/27 COLLINS, J T Region 4, Office of Director 5pp 21833 224 24X Fiche 50-313, 83/09/27, 8401170307

8401100052 Revised LER 83-023/03X-5 on 830916, 17, 1011, 13, 14, 15, 16, 17, 22, 23, 1106, 15, 16 & 19, fire protection deficiencies observed
Complete fire protection sys walkdown insp in progress
Interim controls placed on const activities W/831214 ltr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/12/14 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 14pp 21761 130 24X Fiche 50-313, 83/12/14, 8401100052

8401030170 Updated LER 83-023/03X-6 on 830916-1120, fire protection deficiencies discovered Caused by inadequate original installation specs & acceptance criteria Walkdown insp in progress Insp program being developed W/831220 ltr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/12/20 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 15pp 21681 331 24X Fiche 50-313, 83/12/20, 8401030170

8401130318 LER 83-027/03L-0 on 831128, control room ventilation sys for fan 2VBF-9 operated for greater than 720 h since last filter test Caused by erroneous reading Procedure rev to provide cross-checking data issued W/831228 ltr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/12/28 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 2pp 21798 306 24X Fiche 50-313, 83/12/28, 8401130318

8401130210 LER 83-029/03L-0 on 831129, bottoms of carbon filter for penetration room ventilation fans found wet Caused by water from hydrogen purge sys carried over into plant vent during hydrogen purge sys operation Filters replaced W/831229 ltr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/12/29 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 2pp 21801 140 24X Fiche 50-313, 83/12/29, 8401130210

8401130215 LER 83-028/03L-0 on 831130, during radwaste processing, crack discovered in discharge piping of clean waste transfer pump P-478 Probably caused by overheating of pipe during installation of valve along w/piping stresses W/831230 ltr
ROGERS, P, MARSHALL, J R Arkansas Power & Light Co 83/12/30 QAOLIAIRDD, J E Division of Resident, Reactor Project & Engineering Programs 3pp 21801 150 24X Fiche 50-313, 83/12/30, 8401130215

DOCKETED ITEMS

B401230242 LER 83-023/03X-7 on B30916, during insp, excessive gap observed between listed fire doors & floor or threshold. Caused by original specs not addressing gaps. Deficient doors repaired W/B40110 ltr. ROGERS, P., MARSHALL, J. R. Arkansas Power & Light Co. B4/01/10. GAGLIARDI, J. E. Division of Resident, Reactor Project & Engineering Programs. 7pp. 21884 001. 24X Fiche 50-313, B4/01/10, B401230242.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

B401040193 Forwards Rev 1 to "Program Plan Rept for Detailed Control Room Design Review for Indiana & Michigan Electric Co. DC Cook Units 1 & 2 to NRC." Rept defines overall process by which plan will be implemented. ALEXICH, M. P. Indiana & Michigan Electric Co. B3/12/29. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 21703 018. 24X Fiche 50-315, B3/12/29, B401040193.

--B401040196 Rev 1 to "Program Plan Rept for Detailed Control Room Design Review for Indiana & Michigan Electric Co. DC Cook Units 1 & 2 to NRC." * American Electric Power Service Corp. * Westinghouse Electric Corp. * Canyon Research Corp. B3/12/02. 160pp. 21703 020. 24X Fiche 50-315, B3/12/29, B401040193.

B401230525 Notices of FEMA radiological emergency preparedness program meetings on B40112 & 13 in Chicago, IL. Emergency preparedness & prompt alert & notification schedules will be developed. PAPERIELLO, C. J. Region 3, Office of Director. B4/01/05. DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 3pp. 21878 217. 24X Fiche 50-315, B4/01/05, B401230525.

B401160237 Ack receipt of F. Arsenaault B31212 ltr requesting approval of proposed course of fire for semiautomatic rifle. Recommendations & request forwarded to NMSS for response. AXELSON, W. L. Region 3, Office of Director. B4/01/12. DOLAN, J. E. Indiana & Michigan Electric Co. DOLAN, J. E. American Electric Power Service Corp. 1p. 21834 231. 24X Fiche 50-315, B4/01/12, B401160237.

B401240406 Forwards revised Pages 5-5 & 5-6 & Figure 5 i 2 of modified amended security plan Pages & figure withheld (ref 10CFR72.21). ALEXICH, M. P. Indiana & Michigan Electric Co. B4/01/12. KEPPLER, J. O. Region 3, Office of Director. 1p. 21920 140. 24X Fiche 50-315, B4/01/12, B401240406.

101250127 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records. B4/01/18. Document Management Branch. 1p. 21959 039. 24X Fiche 50-315, B4/01/18, B401250127.

1401250130 Public version of Change Sheet 1 to Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP 029, "Initial Core Damage Assessment." TOWNLEY, E. Indiana & Michigan Electric Co. B3/12/22. 8pp. 21959 060. 24X Fiche 50-315, B4/01/18, B401250127.

401260242 Releases public version of rev to emergency plan procedure. FELTON, J. M. Division of Rules and Records. B4/01/20. Document Management Branch. 1p. 21985 302. 24X Fiche 50-315, B4/01/20, B401260242.

--B401260244 Public version of Rev 4 to Emergency Plan Procedure PMP 2080 EPP 001, "Emergency Plan Activation & Condition Classification." W/B40106 ltr & receipt form. MURPHY, C. E., TOWNLEY, E. L. Indiana & Michigan Electric Co. B4/01/06. Region 3, Office of Director. 37pp. 21985.303. 24X Fiche 50-315, B4/01/20, B401260242.

P. Operating license stage documents & correspondence

B401100166 Forwards Amends 7B & 59 to Licenses DPR-5B & DPR-74, respectively & safety evaluation Amends revise Tech Specs re DHR capability & refueling water cavity level. WIGGINTON, D. L. Operating Reactors Branch 1. B3/11/22. DOLAN, J. Indiana & Michigan Electric Co. DOLAN, J. American Electric Power Service Corp. 2pp. 21768 264. 24X Fiche 50-315, B3/11/22, B401100166.

--B401100171 Amends 7B & 59 to Licenses DPR-5B & DPR-74 respectively, revising DHR capability & refueling water cavity level. VARGA, S. A. Operating Reactors Branch 1. B3/11/22. 36pp. 21768 286. 24X Fiche 50-315, B3/11/22, B401100166.

--B401100179 Safety evaluation supporting Amends 7B & 59 to Licenses DPR-5B & DPR-74, respectively. * Office of Nuclear Reactor Regulation, Director. B3/11/23. 3pp. 21768 322. 24X Fiche 50-315, B3/11/22, B401100166.

B401030304 Forwards safety evaluation re Westinghouse Owners Group study on potential for voiding in RCS during anticipated transients, per TH1 Action Item II K 2.17 Void will not result in unacceptable consequences during transients. VARGA, S. A. Operating Reactors Branch 1. B3/12/16. DOLAN, J. Indiana & Michigan Electric Co. DOLAN, J. American Electric Power Service Corp. 9pp. 21693 341. 24X Fiche 50-315, B3/12/16, B401030304.

B401030167 Grants extension to B40123 for implementing Tech Spec changes associated w/Amends 7B & 59 to Licenses DPR-5B & DPR-74, respectively, re DHR capability & refueling water cavity level. VARGA, S. A. Operating Reactors Branch 1. B3/12/22. DOLAN, J. Indiana & Michigan Electric Co. DOLAN, J. American Electric Power Service Corp. 2pp. 21695 249. 24X Fiche 50-315, B3/12/22, B401030167.

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl. EISENHUT, D. O. Division of Licensing. B4/01/05. Consolidated Edison Co. of New York, Inc. 16pp. 21946 190. 24X Fiche 50-000, B4/01/05, B401050382.

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl. EISENHUT, D. O. Division of Licensing. B4/01/06. Consolidated Edison Co. of New York, Inc. 18pp. 21957 267. 24X Fiche 50-000, B4/01/06, B401090221.

B401130292 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators." Maint of preheat & prelubrication eliminates engine stresses caused by cold starts. Fast start engine stress mitigated only by reducing frequency of starts. ALEXICH, M. P. Indiana & Michigan Electric Co. B4/01/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 21801 130. 24X Fiche 50-315, B4/01/06, B401130292.

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl. EISENHUT, D. O. Division of Licensing. B4/01/13. Consolidated Edison Co. of New York, Inc. 18pp. 21946 174. 24X Fiche 50-000, B4/01/13, B401130084.

B401200076 Forwards minutes of B30913 meeting w/American Electric Power Svc Corp in Bethesda, MD re proposed resolution of numerous environ qualification deficiencies identified by Franklin Research Ctr. per B31024 request. ALEXICH, M. P. Indiana & Michigan Electric Co. B4/01/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 26pp. 21864 290. 24X Fiche 50-315, B4/01/17, B401200076.

B401250028 Application for amend to Licenses DPR-5B & DPR-74, revising Tech Specs re RCS vents, per NUREG-0737, Item II B.1 Proposed specs modeled as suggested in Generic Ltr B3-37. ALEXICH, M. P. Indiana & Michigan Electric Co. B4/01/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 21935.227. 24X Fiche 50-315, B4/01/20, B401250028.

--B401250033 Proposed Tech Specs re RCS vents. * Indiana & Michigan Electric Co. B4/01/20. 11pp. 21935.227. 24X Fiche 50-315, B4/01/20, B401250028.

insurance & indemnity information

140044 Forwards Endorsements 5B & 59 to NELIA Policy NF-206, endorsements 47 & 48 to MAELU Policy MF-79, Endorsement & to IA Certificates N-45 & N-64 & Endorsement & to MAELU bifurcates M-45 & M-64. GLEB, J. A. Marsh & McLennan, Inc. B3/12/22. SALTZMAN, J. Assistant Director for State & Licensee Relations. 7pp. 21739 227. Fiche 50-315, B3/12/22, B401060044.

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060190 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401130270 Forwards final response to IE Bulletin 82-02 re degradation of threaded fasteners in RCPB Procedures reviewed for adequacy & updated where necessary
ALEXICH, M P Indiana & Michigan Electric Co 83/12/28
KEPPLER, J G Region 3, Office of Director 4pp 21800 346 24X Fiche 50-315, 83/12/28, 8401130270

8401190408 Forwards IE Insp Repts 50-315/83-19 & 50-316/83-20 on 831021-1210 & notice of violation
SHAFFER, W D Region 3, Office of Director 83/12/28 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 21849 329 24X Fiche 50-315, 83/12/28, 8401190408

--8401190410 Notice of violation from insp on 831021-1210
SHAFFER, W D Region 3, Office of Director 83/12/28 3pp 21849 331 24X Fiche 50-315, 83/12/28, 8401190408

--8401190412 IE Insp Repts 50-315/83-19 & 50-316/83-20 on 831021-1210 Violations noted diesel generator day tank level column valving error, explosive mixture action requirement not met & inoperable containment air recirculation sys
SWANSON, E R, DUBRY, N E, HELLER, J K Region 3, Office of Director 83/12/28 13pp 21849 334 24X Fiche 50-315, 83/12/28, 8401190408

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401040102 Confirmatory action ltr re 831227 telcon concerning 831117 confirmatory action ltr Schedule for corrective actions due by 840120
KEPPLER, J G Region 3, Office of Director 83/12/30 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 21703 265 24X Fiche 50-315, 83/12/30, 8401040102

8401120227 Forwards IE Insp Repts 50-315/83-18 & 50-316/83-19 on 830627-0701 & 1018-20 & notice of violation
SPESSARD, R L Division of Engineering 83/12/30 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 21794 088 24X Fiche 50-315, 83/12/30, 8401120227

--8401120238 Notice of violation from insp on 830627-0701 & 1018-20
SPESSARD, R L Division of Engineering 83/12/30 5pp 21794 090 24X Fiche 50-315, 83/12/30, 8401120227

--8401120255 IE Insp Repts 50-315/83-18 & 50-316/83-19 on 830627-0701 & 1018-20 Violation noted failure of nuclear safety & design review committee to review QA audit findings, nonreportable plant condition repts & NRC insp findings
FARRELL, R E, HOLZMER, M M, HUNTER, D R Region 3, Office of Director 83/12/30 8pp 21794 095 24X Fiche 50-315, 83/12/30, 8401120227

8401100407 Confirms 840131 IE mgt meeting at Region III ofcs to discuss status of regulatory performance improvement program, per 831222 discussion
NORELIUS, C E Division of Project & Resident Programs 84/01/05, DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co, 1p 21762 296 24X Fiche: 50-315, 84/01/05, 8401100407

8401120232 Confirms 840109 mgt meeting in Glen Ellyn, IL to discuss draft response to NRC 831117 confirmatory action ltr re committee activities & engineering design verification
NORELIUS, C E Division of Project & Resident Programs 84/01/06 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 21793 307 24X Fiche: 50-315, 84/01/06, 8401120232

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401260078 Forwards IE Insp Repts 50-315/83-22 & 50-316/83-23 on 831220-23 & notice of violation
HIND, J A Division of Radiological & Materials Safety Programs 84/01/11 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 21957 110 21X Fiche 50-315, 84/01/11, 8401260078

--8401260084 Notice of violation from insp on 831220-23
HIND, J A Division of Radiological & Materials Safety Programs 84/01/11 1p 21957 112 24X Fiche 50-315, 84/01/11, 8401260078

--8401260090 IE Insp Repts 50-315/83-22 & 50-316/83-23 on 831220-23 Noncompliance noted failure to sample & analyze dissolved oxygen at least once per 72 h
ROZAK, S, SLAWINSKI, W J, SCHUMACHER, M Region 3, Office of Director 84/01/11 6pp 21957 113 24X Fiche 50-315, 84/01/11, 8401260078

8312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401230367 Ack receipt of 840110 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-315/83-16 & 50-315/83-17
SHAFFER, W D Region 3, Office of Director 84/01/18 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 21873 359 24X Fiche 50-315, 84/01/18, 8401230367

--8401230374 Responds to NRC 831123 ltr re noncompliance noted in IE Insp Repts 50-315/83-16 & 50-316/83-17 Corrective actions personnel counseled re proper movement of remaining concrete shield blocks
ALEXICH, M P Indiana & Michigan Electric Co 84/01/10
KEPPLER, J G Region 3, Office of Director 3pp 21873 360 24X Fiche 50-315, 84/01/18, 8401230367

R Periodic operating reports & related correspondence

8401120398 Monthly operating rept for Nov 1983 W/831215 ltr
MIGHT, A, SVENSSON, B A, PEAK, G J Indiana & Michigan Electric Co 83/11/30 Office of Resource Management, Director 11pp 21791 096 24X Fiche 50-315, 83/11/30, 8401120398

8401270446 Monthly operating rept for Dec 1983 W/840113 ltr
GILLET, W T, SVENSSON, B A, SMITH, W G Indiana & Michigan Electric Co 83/12/31 NRC - No Detailed Affiliation Given 9pp 21980 241 24X Fiche 50-315, 83/12/31, 8401270446

S Reportable occurrences, LERs & related correspondence

8401030678 NPDES noncompliance notification on 831102, steam generator blowdown suspended solid samples not taken Sys operated on normal running flash tank on 831103 when daily sampling resumed Ltr dtd 831123 to State of MI encl
SMITH, W G Indiana & Michigan Electric Co 83/12/13 KEPPLER, J G Region 3, Office of Director 2pp 21724 112 24X Fiche: 50-315, 83/12/13, 8401030678

DOCKETED ITEMS

8401040340 Updated LER 83-072/03X-1 on 830801, during B & C leak rate test several containment valves showed excessive leakage. Caused by dirt & scale deposit on seating surface, erosion of valve seats & incomplete weld. Valves cleaned W/831216 ltr PALMER, R A, SMITH, W G Indiana & Michigan Electric Co 83/12/16 KEPLER, J G Region 3, Office of Director 3pp 21704 357 24X Fiche 50-315, 83/12/16, 8401040340

8401050441 RD on 831270, discovered that action statement in Tech Spec Table 3 3-13 not met. Samples required for weekly analysis not continuously collected w/auxiliary sampling equipment. Followup rept will be submitted within 14 days. SMITH, W G Indiana & Michigan Electric Co 83/12/20 KEPLER, J G Region 3, Office of Director 1p 21729 338 24X Fiche 50-315, 83/12/20, 8401050441

8401040323 Updated LER 83-073/03X-1 on 830726, min average ice weight of sample ice condenser baskets less than 1.220 lb per basket. Caused by natural sublimation. Ice mass fully reconditioned to optimize ice density W/831221 ltr PALMER, R A, SMITH, W G Indiana & Michigan Electric Co 83/12/21 KEPLER, J G Region 3, Office of Director 4pp 21705 011 24X Fiche 50-315, 83/12/21, 8401040323

8401050636 LER 83-119/03L-0 on 831123, reservoir & half of retaining clamp for snubber 1-GRC-S594 found detached from snubber. Caused by loosening of clamp fasteners & vibration. New snubber tested & installed W/831222 ltr FLAUG, W J, SMITH, W G Indiana & Michigan Electric Co 83/12/22 KEPLER, J G Region 3, Office of Director 2pp 21726 077 24X Fiche 50-315, 83/12/22, 8401050636

8401060305 Forwards updated LER 83-090/03X-1 & LER 83-120/03L-0 SMITH, W G Indiana & Michigan Electric Co 83/12/29 KEPLER, J G Region 3, Office of Director 1p 21742 347 24X Fiche 50-315, 83/12/29, 8401060305

--8401060311 Updated LER 83-090/03X-1 on 830825, west centrifugal charging pump min flow to three most conservative branch lines below min allowable rate of 345 gpm. Rotating assembly replaced. RISCHLING, J L Indiana & Michigan Electric Co 83/12/29 Region 3, Office of Director 1p 21742 348 24X Fiche 50-315, 83/12/29, 8401060311

--8401060315 LER 83-120/03L-0 on 831203, Fire Door 471 (control rod drive room access door), would not latch properly. Caused by latch & strike plate misalignment. Strike plate adjusted. PIERCE, R H Indiana & Michigan Electric Co 83/12/29 Region 3, Office of Director 1p 21742 349 24X Fiche 50-315, 83/12/29, 8401060315

1401100340 LER 83-121/01T-0 on 831219, discovered that continuous charcoal & particulate samples not obtained. Caused by inadequate procedures. Auxiliary sampling equipment utilized W/840103 ltr RISCHLING, J L, SMITH, W G Indiana & Michigan Electric Co 84/01/03 KEPLER, J G Region 3, Office of Director 2pp 21764 046 24X Fiche 50-315, 84/01/03, 8401100340

8401130177 LER 83-122/03L-0 on 831212, four ice condenser intermediate deck doors found frozen shut. Caused by ice accumulation due to leaking drain lines on air handlers 4-2A, 4-4A & 1-5B. Ice removed W/840104 ltr FLAUG, W J, SMITH, W G Indiana & Michigan Electric Co 84/01/04 KEPLER, J G Region 3, Office of Director 2pp 21802 030 24X Fiche 50-315, 84/01/04, 8401130177

1401130281 NPDES noncompliance notification on 831210, circulating water sys flow & temp not recorded. Caused by operator failure to energize recording instrumentation. Instructions developed requiring energizing instruments. MENGE, R C Indiana & Michigan Electric Co 84/01/04 KEPLER, J G Region 3, Office of Director 2pp 21801 113 24X Fiche 50-315, 84/01/04, 8401130281

401130336 NPDES noncompliance notification steam generator blowdown samples for total suspended solids, iron & copper not taken in Nov. Caused by personnel error. Sampling procedures reviewed w/technician. SMITH, W G Indiana & Michigan Electric Co 84/01/06 KEPLER, J G Region 3, Office of Director 2pp 21798 298 24X Fiche 50-315, 84/01/06, 8401130336

401130349 NPDES noncompliance notification on 831209, discovered that turbine room sump discharge pH meter failed. Repairs made & meter returned to svc on 831212. Meter failed again on 831215. SMITH, W G Indiana & Michigan Electric Co 84/01/06 KEPLER, J G Region 3, Office of Director 2pp 21798 280 24X Fiche 50-315, 84/01/06, 8401130349

8401190371 Forwards LERs 83-123/03L-0 & 83-124/03L-0 SMITH, W G Indiana & Michigan Electric Co 84/01/10 KEPLER, J G Region 3, Office of Director 1p 21850 072 24X Fiche 50-315, 84/01/10, 8401190371

--8401190374 LER 83-123/03L-0 on 831216, during replacement of mirror insulation of PORV, cable for acoustic valve monitor accelerometer SV-456 cut. New cable installed. PALMER, R A Indiana & Michigan Electric Co 84/01/10 Region 3, Office of Director 1p 21850 073 24X Fiche 50-315, 84/01/10, 8401190374

--8401190375 LER 83-124/03L-0 on 831217, fire detection sys alarm for Zone 14 in auxiliary bldg received in control room. Cause unknown. New detector, mfg by Pyratronic, installed. PALMER, R A Indiana & Michigan Electric Co 84/01/10 Region 3, Office of Director 1p 21850 074 24X Fiche 50-315, 84/01/10, 8401190375

8401240063 NPDES noncompliance notification on 831218, steam generator blowdown flash tank sampling for pH & total suspended solids not performed. Cause not stated. SMITH, W G Indiana & Michigan Electric Co 84/01/17 KEPLER, J G Region 3, Office of Director 2pp 21912 332 24X Fiche 50-315, 84/01/17, 8401240063

8401240167 LER 83-125/03L-0 on 831212, one safety-related fire door intentionally made inoperable to perform corrective maint on door frame. Renovation project includes 89 fire doors. Tentative completion date is late 1984 W/840117 ltr BURKE, B A, SMITH, W G Indiana & Michigan Electric Co 84/01/17 KEPLER, J G Region 3, Office of Director 3pp 21910 299 24X Fiche 50-315, 84/01/17, 8401240167

8401310301 NPDES noncompliance notification on 831229, turbine room sump discharge pH meter malfunction discovered. During repair, automatic feature isolated & pump-out to absorption pond initiated only after manual sampling of pH. SMITH, W G Indiana & Michigan Electric Co SMITH, W G American Electric Power Co, Inc 84/01/23 KEPLER, J G Region 3, Office of Director 2pp 22017 356 24X Fiche 50-315, 84/01/23, 8401310301

8401310406 Forwards LERs 83-126/03L-0 & 83-127/03L-0 SMITH, W G Indiana & Michigan Electric Co 84/01/23 KEPLER, J G Region 3, Office of Director 1p 22018 334 24X Fiche 50-315, 84/01/23, 8401310406

--8401310409 LER 83-126/03L-0 on 831230, RCS average temp DNB parameter of 370 5 F exceeded for two short periods of time. Caused by operator holding turbine control valve closed to gather turbine control data. Alarm setpoint lowered. MURPHY, C E Indiana & Michigan Electric Co 84/01/23 Region 3, Office of Director 1p 22018 335 24X Fiche 50-315, 84/01/23, 8401310409

--8401310414 LER 83-127/03L-0 on 831223, Fire Door 519 found partially open. Caused by personnel attempting to use door. Positive lock mechanism fabricated & installed. FLAUG, W J Indiana & Michigan Electric Co 84/01/23 Region 3, Office of Director 1p 22018 336 24X Fiche 50-315, 84/01/23, 8401310414

8401300242 Forwards LERs 83-128/03L-0, 83-129/03L-0 & 83-130/03L-0 SMITH, W G Indiana & Michigan Electric Co 84/01/24 KEPLER, J G Region 3, Office of Director 1p 22062 098 24X Fiche 50-315, 84/01/24, 8401300242

--8401300243 LER 83-128/03L-0 on 831226, during performance of diesel generator AB operability test, diesel generator tripped on apparent overspeed condition. Caused by loose ground wire associated w/electronic tachometer circuit. PALMER, R A Indiana & Michigan Electric Co 84/01/24 Region 3, Office of Director 1p 22062 099 24X Fiche 50-315, 84/01/24, 8401300243

--8401300245 LER 83-129/03L-0 on 831228, during normal operation, Fire Door 471 would not fully close & latch. Caused by latch plate being misaligned w/latch bolt of active leaf. Latch plate aligned & door closers adjusted. FLAUG, W J Indiana & Michigan Electric Co 84/01/24 Region 3, Office of Director 1p 22062 101 24X Fiche 50-315, 84/01/24, 8401300245

--8401300248 LER 83-130/03L-0 on 831230, during normal operations, air lost discovered on steam generator blowdown sample containment isolation valve 4 (DCR-304). Caused by degraded O-ring inside valve operator O-ring replaced. PALMER, R A Indiana & Michigan Electric Co 84/01/24 Region 3, Office of Director 1p 22027 333 24X Fiche 50-315, 84/01/24, 8401300248

DOCKETED ITEMS

145

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8401040193 Forwards Rev 1 to "Program Plan Rept for Detailed Control Room Design Review for Indiana & Michigan Electric Co, DC Cook Units 1 & 2 to NRC " Rept defines overall process by which plan will be implemented
ALEXICH, M P Indiana & Michigan Electric Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21703 018
24X Fiche 50-315, 83/12/29, 8401040193

--8401040196 Rev 1 to "Program Plan Rept for Detailed Control Room Design Review for Indiana & Michigan Electric Co, DC Cook Units 1 & 2 to NRC "
* American Electric Power Service Corp * Westinghouse Electric Corp * Canyon Research Corp 83/12/02 180pp 21703 020 24X
Fiche 50-315, 83/12/29, 8401040193

8401230525 Notices of FEMA radiological emergency preparedness program meetings on 840112 & 13 in Chicago, IL Emergency preparedness & prompt alert & notification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 21878 217 24X Fiche 50-315, 84/01/05, 8401230525

8401160257 Ack receipt of F Arsenault 831212 ltr requesting approval of proposed course of fire for semiautomatic rifle
Recommendations & request forwarded to NMSB for response
AXELSON, W L Region 3, Office of Director 84/01/12 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 1p 21834 231 24X Fiche 50-315, 84/01/12, 8401160257

8401240406 Forwards revised Pages 5-5 & 5-6 & Figure 5 1 2 of modified amended security plan Pages & Figure withheld
(ref 10CR73 21)
ALEXICH, M P Indiana & Michigan Electric Co 84/01/12
KEPPLER, J G Region 3, Office of Director 1p 21920 140 24X
Fiche 50-315, 84/01/12, 8401240406

8401250127 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21959 059 24X Fiche 50-315, 84/01/18, 8401250127

--8401250130 Public version of Change Sheet 1 to Rev 0 to Emergency Plan Implementing Procedure PHP 2081 EPP 029, "Initial Core Damage Assessment "
TOWNLEY, E Indiana & Michigan Electric Co 83/12/22 8pp
21959 060 24X Fiche 50-315, 84/01/18, 8401250127

8401260242 Releases public version of rev to emergency plan procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21985 302 24X Fiche 50-315, 84/01/20, 8401260242

--8401260244 Public version of Rev 4 to Emergency Plan Procedure PHP 2080 EPP, 001, "Emergency Plan Activation & Condition Classification " W/840106 ltr & receipt form
MURPHY, C E, TOWNLEY, E L Indiana & Michigan Electric Co 84/01/06 Region 3, Office of Director 39pp 21985, 303 24X
Fiche 50-315, 84/01/20, 8401260242

J Insurance & indemnity information

8401060044 Forwards Endorsements 58 & 59 to NELIA Policy NF-204, Endorsements 47 & 48 to MAELU Policy MF-79, Endorsement 4 to NELIA Certificates N-45 & N-64 & Endorsement 4 to MAELU Certificates M-45 & M-64
BUCKLES, J A Marsh & McLennan, Inc 83/12/22 SALTZMAN, J
Assistant Director for State & License Relations 9pp 21739 227
24X Fiche 50-315, 83/12/22, 8401060044

P Operating license stage documents & correspondence

8401100166 Forwards Amends 78 & 59 to Licenses DPR-58 & DPR-74, respectively & safety evaluation Amends revise Tech Specs re DHR capability & refueling water cavity level
WIGGINTON, D L Operating Reactors Branch 1 83/11/22 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 21768 284 24X Fiche 50-315, 83/11/22, 8401100166

--8401100171 Amends 78 & 59 to Licenses DPR-58 & DPR-74 respectively, revising DHR capability & refueling water cavity level
VARQA, S A Operating Reactors Branch 1 83/11/22 36pp
21768 286 24X Fiche 50-315, 83/11/22, 8401100166

--8401100179 Safety evaluation supporting Amends 78 & 59 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/11/23 3pp
21768 322 24X Fiche 50-315, 83/11/22, 8401100166

8401030304 Forwards safety evaluation re Westinghouse Owners Group study on potential for voiding in RCS during anticipated transients, per TMI Action Item 11 K 2 17 Void will not result in unacceptable consequences during transients
VARQA, S A Operating Reactors Branch 1 83/12/16 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 9pp 21493 341 24X Fiche 50-315, 83/12/16, 8401030304

8401030167 Grants extension to 840123 for implementing Tech Spec changes associated w/Amends 78 & 59 to Licenses DPR-58 & DHR-74, respectively, re DHR capability & refueling cavity water level
VARQA, S A Operating Reactors Branch 1 83/12/22 DOLAN, J
Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 21495 249 24X Fiche 50-315, 83/12/22, 8401030167

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130292 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators " Maint of preheat & prelubrication eliminates engine stresses caused by cold starts Fast start engine stress mitigated only by reducing frequency of starts
ALEXICH, M P Indiana & Michigan Electric Co 84/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21801 130
24X Fiche 50-315, 84/01/06, 8401130292

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues "
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401200076 Forwards minutes of 830913 meeting w/American Electric Power Svc Corp in Bethesda, MD re proposed resolution of numerous environ qualification deficiencies identified by Franklin Research Ctr, per 831024 request
ALEXICH, M P Indiana & Michigan Electric Co 84/01/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 26pp 21864 290
24X Fiche 50-315, 84/01/17, 8401200076

8401250028 Application for amend to Licenses DPR-58 & DPR-74, revising Tech Specs re RCS vents, per NUREG-0937, Item 11 D 1 Proposed specs modeled as suggested in Generic Ltr 83-37
ALEXICH, M P Indiana & Michigan Electric Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21935 227
24X Fiche 50-315, 84/01/20, 8401250028

--8401250033 Proposed Tech Specs re RCS vents
* Indiana & Michigan Electric Co 84/01/20 11pp 21935 229
24X Fiche 50-315, 84/01/20, 8401250028

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 109pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bays " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

DOCKETED ITEMS

- 8401190408 Forwards IE Insp Repts 50-315/83-19 & 50-316/83-20 on 831021-1210 & notice of violation
SHAFER, W D Region 3, Office of Director 83/12/28 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 2pp 21849 329 24X Fiche 50-315, 83/12/28, 8401190408
- 8401190410 Notice of violation from insp on 831021-1210
SHAFER, W D Region 3, Office of Director 83/12/28 3pp
21849 331 24X Fiche 50-315, 83/12/28, 8401190408
- 8401190412 IE Insp Repts 50-315/83-19 & 50-316/83-20 on 831021-1210
Violations noted diesel generator day tank level column
valving error, explosive mixture action requirement not met &
inoperable containment air recirculation sys
SWANSON, E R, DUBRY, N E, HELLER, J K Region 3, Office of
Director 83/12/28 13pp 21849 334 24X Fiche 50-315, 83/12/28,
8401190408
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093
- 8401040102 Confirmatory action ltr re 831227 telcon concerning 83117
confirmatory action ltr Schedule for corrective actions due
by 840120
KEPPLER, J Q Region 3, Office of Director 83/12/30 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 1p 21703 265 24X Fiche 50-315, 83/12/30, 8401040102
- 8401120227 Forwards IE Insp Repts 50-315/83-18 & 50-316/83-19 on
830627-0701 & 1018-20 & notice of violation
SPESSARD, R L Division of Engineering 83/12/30 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 2pp 21794 088 24X Fiche 50-315, 83/12/30, 8401120227
- 8401120238 Notice of violation from insp on 830627-0701 & 1018-20
SPESSARD, R L Division of Engineering 83/12/30 3pp
21794 090 24X Fiche 50-315, 83/12/30, 8401120227
- 8401120255 IE Insp Repts 50-315/83-18 & 50-316/83-19 on 830627-0701 &
1018-20 Violation noted failure of nuclear safety & design
review committee to review QA audit findings, nonreportable
plant condition reports & NRC insp findings
FARRELL, R E, HOLZNER, M H, HUNTER, D R Region 3, Office of
Director 83/12/30 8pp 21794 093 24X Fiche 50-315, 83/12/30,
8401120227
- 8401100407 Confirms 840131 IE mgt meeting at Region III ofcs to discuss
status of regulatory performance improvement program, per
831222 discussion
NORELIOUS, C E Division of Project & Resident Programs 84/01/05
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 1p 21762 296 24X
Fiche 50-315, 84/01/05, 8401100407
- 401120232 Confirms 840109 mgt meeting in Glen Ellyn, IL to discuss
draft response to NRC 83117 confirmatory action ltr re
committee activities & engineering design verification
NORELIOUS, C E Division of Project & Resident Programs 84/01/06
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 1p 21793 307 24X
Fiche 50-315, 84/01/06, 8401120232
- 8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104
- 8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107
- 8401260078 Forwards IE Insp Repts 50-315/83-22 & 50-316/83-23 on
831220-23 & notice of violation
HIND, J A Division of Radiological & Materials Safety Programs
84/01/11 DOLAN, J E American Electric Power Service Corp
DOLAN, J E Indiana & Michigan Electric Co 2pp 21957 110 24X
Fiche 50-315, 84/01/11, 8401260078
- 8401260084 Notice of violation from insp on 831220-23
HIND, J A Division of Radiological & Materials Safety Programs
84/01/11 1p 21957 112 24X Fiche 50-315, 84/01/11, 8401260078
- 8401260090 IE Insp Repts 50-315/83-22 & 50-316/83-23 on 831220-23
Noncompliance noted failure to sample & analyze dissolved
oxygen at least once per 72 h
ROZAK, S, SLAWINSKI, W J, SCHUMACHER, M Region 3, Office of
Director 84/01/11 6pp 21957 113 24X Fiche 50-315, 84/01/11,
8401260078
- 8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- 8401230367 Ack receipt of 840110 ltr informing NRC of steps taken to
correct noncompliance noted in IE Insp Repts 50-315/83-16
& 50-315/83-17
SHAFER, W D Region 3, Office of Director 84/01/18 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan
Electric Co 1p 21873 359 24X Fiche 50-315, 84/01/18, 8401230367
- 8401230374 Responds to NRC 831123 ltr re noncompliance noted in IE Insp
Repts 50-315/83-16 & 50-316/83-17 Corrective actions
personnel counseled re proper movement of remaining concrete
shield blocks
ALEXICH, M P Indiana & Michigan Electric Co 84/01/10
KEPPLER, J Q Region 3, Office of Director 3pp 21873 360 24X
Fiche 50-315, 84/01/18, 8401230367
- R Periodic operating reports & related correspondence
- 8401120412 Monthly operating rept for Nov 1983 W/831215 ltr
MIGHT, A, SVENSSON, B A, PEAR, Q J Indiana & Michigan Electric Co
83/11/30 Office of Resource Management, Director 12pp
21791 183 24X Fiche 50-316, 83/11/30, 8401120412
- 8401270477 Monthly operating rept for Dec 1983 W/840113 ltr
OLLETT, W T, SVENSSON, B A, SMITH, W Q Indiana & Michigan Electric
Co 83/12/31 NRC - No Detailed Affiliation Given 7pp
21981 172 24X Fiche 50-316, 83/12/31, 8401270477
- S Reportable occurrences, LERs & related correspondence
- 8401230319 Describes actions during 831015 unscheduled outage Source
of primary to secondary leakage in steam generators 21, 22 &
23 Listed tubes mechanically plugged by Westinghouse Primary
manway reopened & tubesheet visually examined
SMITH, W Q Indiana & Michigan Electric Co 83/12/12 KEPPLER, J Q
Region 3, Office of Director 4pp 21883 317 24X
Fiche 50-316, 83/12/12, 8401230319
- 8401030678 NPDES noncompliance notification on 831102, steam generator
blowdown suspended solid samples not taken Sys operated on
normal running flash tank on 831103 when daily sampling
resumed ltr dtd 831123 to State of MI encl
SMITH, W Q Indiana & Michigan Electric Co 83/12/13 KEPPLER, J Q
Region 3, Office of Director 2pp 21724 112 24X
Fiche 50-315, 83/12/13, 8401030678
- 8401060434 Forwards LERs 83-114/03L-O & 83-115/03L-O
SMITH, W Q Indiana & Michigan Electric Co 83/12/16 KEPPLER, J Q
Region 3, Office of Director 1p 21740 267 24X
Fiche 50-316, 83/12/16, 8401060434
- 8401060437 LER 83-114/03L-O on 831118, carbon dioxide isolation switch
for cable penetration tunnel area found in isolated
position No personnel in area Responsible person not
identified Design change pursued
SVENSSON, B A Indiana & Michigan Electric Co 83/12/16 Region
3, Office of Director 2pp 21740 268 24X Fiche 50-316,
83/12/16, 8401060434
- 8401060440 LER 83-115/03L-O on 831122, turbine & reactor trip occurred
at approx 30% power from steam generator high-high level
Caused by overfeeding due to feed pump leakoff closure &
starting Hotwell pump due to inadequate main feed flow
KRAUSE, D F Indiana & Michigan Electric Co 83/12/16 Region
3, Office of Director 2pp 21740 270 24X Fiche 50-316,
83/12/16, 8401060434

8401040355 Forwards LERs 83-114/03L-0 & 83-117/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/12/21 KEPLER, J G
Region 3, Office of Director 1p 21707 350 24X
Fiche 50-316, 83/12/21, 8401040355

--8401040362 LER 83-117/03L-0 on 831123, steam generator 1 blowdown sample
isolation valve DCR-301 tripped closed on high alarm from
blowdown radiation monitor R-19 Caused by leakage due to
flat spots on two O-rings in valve actuator
PALMER, R A Indiana & Michigan Electric Co 83/12/21 Region 3,
Office of Director 1p 21707 351 24X Fiche 50-316, 83/12/21,
8401040355

--8401040367 LER 83-116/03L-0 on 831128, 30 & 1202, lower containment outer
personnel air lock door exceeded seal leakage limits No
cause indicated Outer door seals replaced & adjustments made
to door frame clamps
PALMER, R A Indiana & Michigan Electric Co 83/12/21 Region 3,
Office of Director 1p 21707 352 24X Fiche 50-316, 83/12/21,
8401040355

8401060425 Forwards LERs 83-118/03L-0, 83-119/03L-0 & 83-120/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/12/29 KEPLER, J G
Region 3, Office of Director 1p 21740 351 24X
Fiche 50-316, 83/12/29, 8401060425

--8401060428 LER 83-118/03L-0 on 831205, CD battery room Fire Door 461
would not latch properly Caused by burr on strike plate
interfering w/latch & lack of adjustment Burr removed &
closure adjusted
PIEHL, R H Indiana & Michigan Electric Co 83/12/29 Region 3,
Office of Director 1p 21740 352 24X Fiche 50-316, 83/12/29,
8401060425

--8401060430 LER 83-119/03L-0 on 831130, hydrogen analyzer could not be
calibr Caused by instrument drift Local panel meters
recalibr
RISCHLING, J L Indiana & Michigan Electric Co 83/12/29
Region 3, Office of Director 1p 21740 353 24X
Fiche 50-316, 83/12/29, 8401060425

--8401060435 LER 83-120/03L-0, on 831206, chart paper for containment sump
flow monitoring recorder 2-C8-001 would not advance Cause
not stated Recorder repaired Design change submitted
KRAUSE, D F Indiana & Michigan Electric Co 83/12/29 Region 3,
Office of Director 1p 21740 354 24X Fiche 50-316, 83/12/29,
8401060425

8401130331 Forwards updated LER 82-016/03X-1 & LERs 83-121/03L-0 &
83-122/03L-0
SMITH, W G Indiana & Michigan Electric Co 84/01/04 KEPLER, J G
Region 3, Office of Director 1p 21798 269 24X
Fiche: 50-316, 84/01/04, 8401130331

--8401130337 Updated LER 82-016/03X-1 on 810719, pinhole leak discovered
on suction strainer for west containment spray (CTS) pump
Caused by fatigue Pinhole removed by grinding & rewelding
KRAUSE, D F Indiana & Michigan Electric Co 84/01/04 Region 3,
Office of Director 2pp 21798 270 24X Fiche 50-316,
84/01/04, 8401130331

--8401130345 LER 83-121/03L-0 on 831209, Fire Door 472 in 4 kV room found
occasionally stuck in full open position Caused by paint
buildup on floor High spot ground down & middle & lower door
hinges shimmed
PIEHL, R H Indiana & Michigan Electric Co 84/01/04 Region 3,
Office of Director 1p 21798 272 24X Fiche 50-316, 84/01/04,
8401130331

--8401130353 LER 83-122/03L-0 on 831210, during surveillance test on EBF
Pan 2-HV-AEB-1, suspicious odor noted Cause undetermined
Coupling reengaged & screws tightened
PIEHL, R H Indiana & Michigan Electric Co 84/01/04 Region 3,
Office of Director 1p 21798 273 24X Fiche 50-316, 84/01/04,
8401130331

8401130336 NPDES noncompliance notification steam generator blowdown
samples for total suspended solids, iron & copper not taken
in Nov Caused by personnel error Sampling procedures
reviewed w/technician
SMITH, W G Indiana & Michigan Electric Co 84/01/06 KEPLER, J G
Region 3, Office of Director 2pp 21798 298 24X
Fiche: 50-316, 84/01/06, 8401130336

8401130349 NPDES noncompliance notification on 831209, discovered that
turbine room sump discharge pH meter failed Repairs made
& meter returned to svc on 831212, Meter failed again on
831215.
SMITH, W G Indiana & Michigan Electric Co 84/01/06 KEPLER, J G
Region 3, Office of Director, ZUGGER, P D Minnesota, State of
2pp. 21798 280. 24X Fiche 50-316, 84/01/06, 8401130349

8401240183 Forwards LER 83-123/03L-0 & LER 83-111/03X-1
SMITH, W G Indiana & Michigan Electric Co 84/01/17 KEPLER, J G
Region 3, Office of Director 1p 21908 307 24X
Fiche 50-316, 84/01/17, 8401240183

--8401240191 LER 83-123/03L-0 on 831220, output from bistable 2FB-512B
fluctuated at trip & reset points Cause not stated Bistable
replaced
PALMER, R A Indiana & Michigan Electric Co 84/01/17 Region 3,
Office of Director 1p 21908 308 24X Fiche 50-316, 84/01/17,
8401240183

--8401240202 LER 83-111/03X-1 on 831221, safety-related fire door made
inoperable to perform corrective maint on door frame During
maint, door latch broke Caused by renovation of B4 fire
doors Fire watches posted
BURKE, B A Indiana & Michigan Electric Co 84/01/17 Region 3,
Office of Director 2pp 21908 309 24X Fiche 50-316, 84/01/17,
8401240183

8401300195 Forwards LERs 83-052/03X-1 & 83-081/03X-1
SMITH, W G Indiana & Michigan Electric Co 84/01/18 KEPLER, J G
Region 3, Office of Director 1p 21995 310 24X
Fiche 50-316, 84/01/18, 8401300195

--8401300198 Updated LER 83-052/03X-1 on 830623, during normal operation,
reactor trip occurred as result of failure in 120-volt ac
vital bus inverter Caused by capacitor C-2 failure due to
high operating temps Capacitor & fuse replaced
PALMER, R A Indiana & Michigan Electric Co 84/01/18 Region 3,
Office of Director 1p 21995 311 24X Fiche 50-316, 84/01/18,
8401300195

--8401300201 Updated LER 83-081/03X-1 on 830822 & 23, during normal
operation, reactor trips occurred as result of failures of
120-volt ac vital bus inverter Caused by operating temps
above rated design temps Forced air cooling installed
PALMER, R A Indiana & Michigan Electric Co 84/01/18 Region 3,
Office of Director 2pp 21995 312 24X Fiche 50-316,
84/01/18, 8401300195

8401310050 LER 83-124/03L-0 on 831224, during surveillance test of power
range drawer, control power fuse blew Cause not determined
Power range drawer recalibr W/840123 ltr
KRAUSE, D F, SMITH, W G Indiana & Michigan Electric Co 84/01/23
KEPLER, J G Region 3, Office of Director 2pp 22022 061 24X
Fiche 50-316, 84/01/23, 8401310050

8401310301 NPDES noncompliance notification on 831229, turbine room sump
discharge pH meter malfunction discovered During repair,
automatic feature isolated & pump-out to absorption pond
initiated only after manual sampling of pH
SMITH, W G Indiana & Michigan Electric Co SMITH, W G American
Electric Power Co, Inc 84/01/23 KEPLER, J G Region 3, Office
of Director 2pp 22017 356 24X Fiche 50-316, 84/01/23, 8401310301

8401300257 LER 83-125/03L-0 on 831229, output from flux penalty module
2NY-441 found drifting in conservative direction Cause not
stated Flux penalty module calibr & returned to svc
W/840124 ltr
PALMER, R A, SMITH, W G Indiana & Michigan Electric Co 84/01/24
KEPLER, J G Region 3, Office of Director 2pp 21998 320 24X
Fiche 50-316, 84/01/24, 8401300257

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
F Security, medical, emergency & fire protection plans

8401050093 Releases public version of revised emergency plan
implementation procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 254 24X Fiche 50-317, 83/12/28,
8401050093

--8401050098 Forwards public version of revised emergency plan
implementation procedures, including Procedures ERPIP 4 3 1
re offsite gamma radiation & mobile air sample surveys &
ERPIP 4 3 2 re personnel contamination monitoring
USI, V Baltimore Gas & Electric Co 83/11/09 Office of
Nuclear Reactor Regulation, Director 1p 21736 255 24X
Fiche: 50-317, 83/12/28, 8401050093

--8401050101 Public version of revised emergency plan implementation
procedures, including Procedures ERPIP 4 3 1 re offsite
gamma radiation & mobile air sample surveys & ERPIP 4 3 2 re
personnel contamination monitoring
RUSSELL, L B Baltimore Gas & Electric Co 83/11/01 44pp
21736 257 24X Fiche 50-317, 83/12/28, 8401050093

DOCKETED ITEMS

B401090412 Releases public version of revised emergency response plan implementing procedure
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21743 118 24X Fiche 50-317, 83/12/28, 8401050412

--B401050417 Public version of Rev 10, Change 1, to Emergency Response Plan Implementing Procedure ERPIP 3 1, "Immediate Action Procedures" W/831130 ltr
 RUSSELL, L B, WALL, G F, USI, V Baltimore Gas & Electric Co 83/11/16 Region 1, Office of Director 21pp 21743 119 24X
 Fiche 50-317, 83/12/28, 8401050412

B401060027 Releases public version of revised emergency response plan
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21748 157 24X Fiche 50-317, 83/12/28, 8401060027

--B401060032 Public version of Rev 4 to emergency response plan W/831206 ltr & receipt form
 USI, V Baltimore Gas & Electric Co 83/09/28 DENTON, H R NRC - No Detailed Affiliation Given 200pp 21748 158 24X
 Fiche 50-317, 83/12/28, 8401060032

B401060264 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21748 348 24X Fiche 50-317, 83/12/28, 8401060264

--B401060266 Public version of Change 1 to Rev 9 to Emergency Plan Implementing Procedure ERPIP 4 3 1, "Onsite Personnel Protection/Accountability & Evacuation"
 RUSSELL, L B Baltimore Gas & Electric Co 83/10/26 6pp 21748 349 24X Fiche 50-317, 83/12/28, 8401060264

B401060270 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21755 184 24X Fiche 50-317, 83/12/28, 8401060270

--B401060274 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 4 3 3 re liquid effluent sampling & analysis & Procedures ERPIP 4 3 1 & ERPIP 4 3 2 Receipt form encl
 USI, V Baltimore Gas & Electric Co 83/11/21 Office of Nuclear Reactor Regulation, Director 2pp 21755 185 24X
 Fiche 50-317, 83/12/28, 8401060270

B401060278 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 4 3 3 re liquid effluent sampling & analysis & Procedures ERPIP 4 3 1 & ERPIP 4 3 2
 RUSSELL, L B Baltimore Gas & Electric Co 83/11/16 13pp 21755 187 24X Fiche 50-317, 83/12/28, 8401060270

01100493 Forwards integrated schedule in bar-chart format per Suppl 1 to NUREG-0737, describing emergency response capability upgrades
 ASH, R F Baltimore Gas & Electric Co 83/12/30 MILLER, J R Operating Reactors Branch 3 18pp 21743 067 24X
 Fiche 50-317, 83/12/30, 8401100493

B401190092 Forwards comments on 830901 detailed control room design review program plan per Suppl 1 to NUREG-0737
 MILLER, J R Operating Reactors Branch 3 83/12/30 LUNDVALL, A E Baltimore Gas & Electric Co 14pp 21870 266 24X
 Fiche 50-317, 83/12/30, 8401190092

101180246 Forwards exercise reports for 820928 small-scale & 830914 full-scale exercise of offsite radiological emergency preparedness plans for Calvert Cliffs Nuclear Power Station
 KRIMM, R W Federal Emergency Management Agency 84/01/06 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21844 022 24X Fiche 50-317, 84/01/06, 8401180246

B401180256 Evaluation of Calvert Cliffs 830914 full-scale exercise for offsite radiological emergency preparedness plans for facilities
 * Federal Emergency Management Agency 83/10/13 43pp 21844 023 24X Fiche 50-317, 84/01/06, 8401180246

B401180263 Evaluation of Calvert Cliffs small-scale exercise for offsite radiological emergency preparedness plans
 * Federal Emergency Management Agency 82/09/28 13pp 21844 067 24X Fiche 50-317, 84/01/06, 8401180246

B401240280 Forwards IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on 831128-1202 No violations noted
 MARTIN, T T Division of Engineering & Technical Programs 84/01/09 BOYMAKER, N J Baltimore Gas & Electric Co 2pp 21907 341 24X
 Fiche 50-317, 84/01/09, 8401240280

B401300352 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/26 Document
 Management Branch 1p 22005 346 24X Fiche 50-317, 84/01/26, 8401300352

--B401300355 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 1 re emergency classification of offsite agencies & ERPIP 4 1 2 re site emergency coordinator checklist
 USI, V Baltimore Gas & Electric Co 84/01/11 Director's Office, Office of Inspection and Enforcement 1p 22005 347 24X
 Fiche 50-317, 84/01/26, 8401300352

--B401300358 Public version of revised emergency plan implementing procedures, including Procedure ERPIP 3 1 re emergency classification of offsite agencies & ERPIP 4 1 2 re site emergency coordinator checklist
 RUSSELL, L B Baltimore Gas & Electric Co 83/12/16 14pp 22005 348 24X Fiche 50-317, 84/01/26, 8401300352

J Insurance & indemnity information

B401200140 Forwards Endorsements 55 & 22 to NELIA Policies NF-216 & NF-348, respectively, Endorsement 44 to MAELU Policy NF-76 & Endorsements 4 to MAELU Certificates M-52, M-53 to Master Policy 1
 YORK, W G Baltimore Gas & Electric Co 84/01/13 DINITZ, I Assistant Director for State & License Relations 6pp 21866 190 24X Fiche 50-317, 84/01/13, 8401200140

P Operating license stage documents & correspondence

B401180240 Resubmits Section 1B of updated FSAR in response to 10CFR50.54 requirement that licensees submit to appropriate regional ofc. current description of QA program being implemented for inclusion in SAR No changes made
 DOUGLASS, R H Baltimore Gas & Electric Co 83/06/17 NAPUDA, G Region 1, Office of Director 51pp 21842 083 24X
 Fiche 50-317, 83/06/17, 8401180240

B401030318 Forwards LASL draft, "TRAC Analyses of Potential Overcooling Transients at Calvert Cliffs-1 for Pressurized Thermal Shock Risk Assessment Preliminary Summary"
 JOHNSON, C Reactor Risk Branch 83/12/23 WOODS, R Generic Issues Branch 2pp 21695 259 24X Fiche 50-317, 83/12/23, 8401030318

--B401030323 Draft "TRAC Analysis of Potential Overcooling Transients at Calvert Cliffs-1 for Pressurized Thermal Shock Risk Assessment Preliminary Summary"
 KOENIG, J E, SPRIGGS, G D, SMITH, R C Los Alamos Scientific Laboratory 83/12/13 NRC - No Detailed Affiliation Given. 69pp 21695 261 24X Fiche 50-317, 83/12/23, 8401030318

B401100127 Forwards Amends 69 & 70 to Licenses DPR-53 & DPR-69, respectively & safety evaluation Amends revise Tech Specs to clarify operability requirements for containment purge isolation valves & basis for combustible gas control sys
 JAFFE, D H Operating Reactors Branch 3 83/12/30 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21768 238 24X
 Fiche 50-317, 83/12/30, 8401100127

--B401100130 Amends 69 & 70 to Licenses DPR-53 & DPR-69, respectively, revising Tech Specs to clarify operability requirements for containment purge isolation valves & basis for combustible gas control sys
 MILLER, J R Operating Reactors Branch 3 83/12/30 23pp 21768 240 24X Fiche 50-317, 83/12/30, 8401100127

--B401100131 Safety evaluation supporting Amends 69 & 70 to Licenses DPR-53 & DPR-69, respectively
 * Office of Nuclear Reactor Regulation, Director 83/12/30 5pp 21768 279 24X Fiche 50-317, 83/12/30, 8401100127

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for CLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related," Svc list encl.
 EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
 Fiche 50-000, 84/01/05, 8401050382

DOCKETED ITEMS

149

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Bhaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

8401040423 Forwards IE Insp Repts 50-317/83-29 & 50-318/83-29 on 831017-21 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/12/19
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21708 141 24X
Fiche 50-317, 83/12/19, 8401040423

--8401040427 Notice of violation from insp on 831017-21
* Region I, Office of Director 83/12/07 1p 21708 143 24X
Fiche 50-317, 83/12/19, 8401040423

--8401040430 IE Insp Repts 50-317/83-29 & 50-318/83-29 on 831017-21
Noncompliance noted failure to implement procedures re staff working hours for radiation chemistry technicians engaged in safety-related work
CDLLINS, D J, SHANBAK, M M Region I, Office of Director
83/12/09 5pp 21708 144 24X Fiche 50-317, 83/12/19, 8401040423

8401100170 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-26 & 50-318/83-26
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21760 172 24X
Fiche 50-317, 83/12/23, 8401100170

--8401100176 Responds to NRC 831109 ltr re violations noted in IE Insp Repts 50-317/83-26 & 50-318/83-26 Corrective actions
Surveillance Test Procedure STP O-7-1 re svc water inlet valve revised per Operating Instruction 15
LUNDVALL, A E Baltimore Gas & Electric Co 83/12/06 MARTIN, T T
Division of Engineering & Technical Programs 2pp 21760 174
24X Fiche 50-317, 83/12/23, 8401100170

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp, 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp, 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401130249 Ack receipt of 831031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-21 & 50-318/83-21
STAROSTECKI, R Division of Project & Resident Programs 84/01/09
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21800 326 24X
Fiche 50-317, 84/01/09, 8401130249

--8401130253 Responds to NRC 831003 ltr re violations noted in IE Insp Repts 50-317/83-21 & 50-318/83-21 Corrective actions, chemistry technicians counseled on importance of logging all analytical results & notifying personnel in timely manner
LUNDVALL, A E Baltimore Gas & Electric Co 83/10/31
STAROSTECKI, R Division of Project & Resident Programs 2pp
21800 328, 24X Fiche 50-317, 84/01/09, 8401130249

8401240280 Forwards IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on 831128-1202 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/09
BOMMAKER, N J Baltimore Gas & Electric Co 2pp 21909 341 24X
Fiche 50-317, 84/01/09, 8401240280

--8401240295 IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on 831128-1202 No violations noted Major areas inspected
security organization, testing & maint & security sys power supply Safeguards info deleted (ref 10CFR73 21)
BAILEY, R J, GDDY, A T Region I, Office of Director 84/01/06
5pp 21909 343 24X Fiche 50-317, 84/01/09, 8401240280

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401240274 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-28 & 50-318/83-28
MARTIN, T T Division of Engineering & Technical Programs 84/01/19
LUNDVALL, A E Baltimore Gas & Electric Co 1p 21909 355 24X
Fiche 50-317, 84/01/19, 8401240274

--8401240277 Responds to NRC 831130 ltr re violations noted in IE Insp Repts 50-317/83-28 & 50-318/83-28 Corrective actions
radiation safety procedures re radwaste packaging revised to comply w/DOE & NRC regulations & personnel retrained
LUNDVALL, A E Baltimore Gas & Electric Co 83/12/20 MURLEY, T E
Region I, Office of Director 2pp 21909 356 24X
Fiche 50-317, 84/01/19, 8401240274

R Periodic operating reports & related correspondence

8312290397 "Nonroutine Radiological Environ Operation Rept. for Period Ending Oct 1983"
FUHRMAN, G R Baltimore Gas & Electric Co 83/11/28 Region I, Office of Director 2pp 21660 226 24X Fiche 50-317, 83/11/28, 8312290397

8401250158 Monthly operating repts for Dec 1983 W/840113 ltr
LOTITO, E L Baltimore Gas & Electric Co 83/12/31 11pp
21937 062 24X Fiche 50-317, 83/12/31, 8401250158

8401240403 Forwards rept of changes, tests & experiments completed on facilities under provisions of 10CFR50 59 Safety evaluation summary also encl
LUNDVALL, A E Baltimore Gas & Electric Co 84/01/03 MURLEY, T E
Region I, Office of Director 7pp 21915 253 24X
Fiche 50-317, 84/01/03, 8401240403

S Reportable occurrences, LERs & related correspondence

8312290397 "Nonroutine Radiological Environ Operation Rept. for Period Ending Oct 1983"
FUHRMAN, G R Baltimore Gas & Electric Co 83/11/28 Region I, Office of Director 2pp 21660 226 24X Fiche 50-317, 83/11/28, 8312290397

DOCKETED ITEMS

8401030268 Updated LER 83-032/03X-1 on 830523, containment isolation signal logic module B would not actuate Caused by defective electronic logic components Module replaced, tested & returned to svc W/831209 ltr
BASCO, L F, RUSSELL, L B Baltimore Gas & Electric Co 83/12/09
MURLEY, T E Region 1, Office of Director 2pp 21681 174 24X
Fiche 50-317, 83/12/09, 8401030268

8401160081 LER 83-066/04T-0 on 831031, oyster samples collected during Oct 1983 showed Ag-110m to be 70 +/- 8 pCi/kg Caused by natural tendency of oysters to bioconcentrate environ silver W/831221 ltr
VOGEL, A M, RUSSELL, L B Baltimore Gas & Electric Co 83/12/19
MURLEY, T E Region 1, Office of Director 2pp 21815 193 24X
Fiche 50-317, 83/12/19, 8401160081

8401160067 Updated LER 83-055/03X-1 on 831001, while performing tests during shutdown operations, three main steam safety valves failed to lift at required setpoint Valves disassembled, inspected & repaired W/831221 ltr
JUNOE, M A, PAVIS, O S, RUSSELL, L B Baltimore Gas & Electric Co 83/12/21
MURLEY, T E Region 1, Office of Director 2pp 21813 266 24X
Fiche 50-317, 83/12/21, 8401160067

8401160093 LER 83-066/03L-0 on 831201, during surveillance test procedure, excessive leak rate past containment personnel air lock inner door discovered Caused by degraded gasket Gasket & groove cleaned & lubricated W/831222 ltr
JUNOE, M A, LYONS, W T, RUSSELL, L B Baltimore Gas & Electric Co 83/12/22
MURLEY, T E Region 1, Office of Director 2pp 21821 181 24X
Fiche 50-317, 83/12/22, 8401160093

8401260281 LER 83-070/03L-0 on 831202, pressurizer level decreased to 130 inches On 831210 pressurizer level decreased to 128 inches RCS temp swing of 10 degrees not uncommon during normal startup operations W/831222 ltr
JUNOE, M A, RUSSELL, L B Baltimore Gas & Electric Co 83/12/22
MURLEY, T E Region 1, Office of Director 2pp 21755 211 24X
Fiche 50-317, 83/12/22, 8401260281

8401130212 LER 83-062/03L-0 on 831129, post-accident monitoring instrumentation channel X found inoperable Caused by leaking variable leg drain valve on pressurizer level transmitter Bonnet & plug assembly replaced W/831229 ltr
PORTER, R J, SNYDER, J, RUSSELL, L B Baltimore Gas & Electric Co 83/12/29
MURLEY, T E Region 1, Office of Director 2pp 21801 142 24X
Fiche 50-317, 83/12/29, 8401130212

8401160126 LER 83-063/03L-0 on 831130, while starting up, safety injection tank 11B found inoperable due to level transmitter being out of calibr Caused by erroneous removal of static pressure offset adjustment W/831229 ltr
PORTER, R J, ANDROSIAK, R, RUSSELL, L B Baltimore Gas & Electric Co 83/12/29
MURLEY, T E Region 1, Office of Director 3pp 21821 152 24X
Fiche 50-317, 83/12/29, 8401160126

8401270281 LER 83-067/03L-0 on 831204, during preventative maint on ECCS pump room air cooler 12, saltwater inlet control valve 1-CV-5173 would not open Caused by worn & damaged mechanical linkage Actuator repaired W/831230 ltr
JUNOE, M, MAHON, C R, RUSSELL, L B Baltimore Gas & Electric Co 83/12/30
MURLEY, T E Region 1, Office of Director 3pp 21976 010 24X
Fiche 50-317, 83/12/30, 8401270281

8401270059 LER 83-073/03L-0 on 831214, excessive leak rate past containment personnel air lock outer door discovered Caused by degradation of gaskets & misalignment of door New gaskets installed & door closure mechanism adjusted W/840105 ltr
JUNOE, M, LYONS, W, RUSSELL, L B Baltimore Gas & Electric Co 84/01/05
MURLEY, T E Region 1, Office of Director 3pp 21979 153 24X
Fiche 50-317, 84/01/05, 8401270059

8401270137 LER 83-071/03L-0 on 831210, pressurizer pressure decreased to 2,180 psia Pressure switch in static liquid cooling sys failed, causing turbine runback Caused by loose screw holding switch actuator to Bourdon tube Screw replaced W/840109 ltr
JUNOE, M A, BASCO, L F, RUSSELL, L B Baltimore Gas & Electric Co 84/01/09
MURLEY, T E Region 1, Office of Director 2pp 21982 052 24X
Fiche 50-317, 84/01/09, 8401270137

V Operator Examinations

8401190326 Forwards operator licensing exam schedule, in response to 831221 Generic Ltr 83-40
LUNDVALL, A E Baltimore Gas & Electric Co 84/01/16 EISENHUT, D G
Division of Licensing 2pp 21850 353 24X
Fiche 50-317, 84/01/16, 8401190326

DOCKET 30-316 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8401050093 Releases public version of revised emergency plan implementation procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 254 24X
Fiche 50-317, 83/12/28, 8401050093

--8401050098 Forwards public version of revised emergency plan implementation procedures, including Procedures ERPIP 4 3 1 re offsite gamma radiation & mobile air sample surveys & ERPIP 4 3 2 re personnel contamination monitoring
USI, V Baltimore Gas & Electric Co 83/11/09 Office of Nuclear Reactor Regulation, Director 1p 21736 255 24X
Fiche 50-317, 83/12/28, 8401050093

--8401050101 Public version of revised emergency plan implementation procedures, including Procedures ERPIP 4 3 1 re offsite gamma radiation & mobile air sample surveys & ERPIP 4 3 2 re personnel contamination monitoring
RUSSELL, L B Baltimore Gas & Electric Co 83/11/01 44pp
21736 257 24X
Fiche 50-317, 83/12/28, 8401050093

8401050412 Releases public version of revised emergency response plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 118 24X
Fiche 50-317, 83/12/28, 8401050412

--8401050417 Public version of Rev 10, Change 1, to Emergency Response P Implementing Procedure ERPIP 3 1, "Immediate Action Procedures" W/831130 ltr
RUSSELL, L B, WALL, G F, USI, V Baltimore Gas & Electric Co 83/11/16 Region 1, Office of Director 21pp 21743 119 24X
Fiche 50-317, 83/12/28, 8401050412

8401060027 Releases public version of revised emergency response plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21748 157 24X
Fiche 50-317, 83/12/28, 8401060027

--8401060032 Public version of Rev 4 to emergency response plan W/8312 ltr & receipt form
USI, V Baltimore Gas & Electric Co 83/09/28 DENTON, H R NRC
No Detailed Affiliation Given 200pp 21748 158 24X
Fiche 50-317, 83/12/28, 8401060027

8401060264 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21748 348 24X
Fiche 50-317, 83/12/28, 8401060264

--8401060266 Public version of Change 1 to Rev 9 to Emergency Plan Implementing Procedure ERPIP 4 5 1, "Onsite Personnel Protection, Accountability & Evacuation"
RUSSELL, L B Baltimore Gas & Electric Co 83/10/26 6pp
21748 349 24X
Fiche 50-317, 83/12/28, 8401060264

8401060270 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21755 184 24X
Fiche 50-317, 83/12/28, 8401060270

--8401060274 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 4 3 3 re liquid effluent sampling & analysis & Procedures ERPIP 4 3 1 & ERPIP 4 3 2 Receipt Form encl.
USI, V Baltimore Gas & Electric Co 83/11/21 Office of Nuclear Reactor Regulation, Director 2pp 21755 185 24X
Fiche 50-317, 83/12/28, 8401060270

--8401060278 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 4 3 3 re liquid effluent sampling & analysis & Procedures ERPIP 4 3 1 & ERPIP 4 3 2
RUSSELL, L B Baltimore Gas & Electric Co 83/11/16 13pp,
21755 187 24X
Fiche 50-317, 83/12/28, 8401060270

8401100483 Forwards integrated schedule in bar-chart format per Supp 1 to NUREG-0737, describing emergency response capability upgrades
ASH, R F Baltimore Gas & Electric Co 83/12/30 MILLER, J R
Operating Reactors Branch 3 18pp 21763 067 24X
Fiche 50-317, 83/12/30, 8401100483

DOCKETED ITEMS

151

B401190092 Forwards comments on B30901 detailed control room design review program plan per Suppl 1 to NUREG-0737
MILLER, J R Operating Reactors Branch 3 83/12/30 LUNDVALL, A E
Baltimore Gas & Electric Co 14pp 21870 246 24X
Fiche 50-317, 83/12/30, B401190092

B401180246 Forwards exercise repts for B20928 small-scale & B30914 full-scale exercise of offsite radiological emergency preparedness plans for Calvert Cliffs Nuclear Power Station
KRIMM, R W Federal Emergency Management Agency 84/01/06
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 2pp 21844 022 24X Fiche 50-317, 84/01/06, B401180246

--B401180256 Evaluation of Calvert Cliffs B30914 full-scale exercise for offsite radiological emergency preparedness plans for facilities
* Federal Emergency Management Agency 83/10/13 43pp
21844 023 24X Fiche 50-317, 84/01/06, B401180246

--B401180263 Evaluation of Calvert Cliffs small-scale exercise for offsite radiological emergency preparedness plans
* Federal Emergency Management Agency 83/09/28 13pp
21844 067 24X Fiche 50-317, 84/01/06, B401180246

B401240280 Forwards IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on B31128-1202 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/09
BOWMAKER, N J Baltimore Gas & Electric Co 2pp 21909 341 24X
Fiche: 50-317, 84/01/09, B401240280

--B401240295 IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on B31128-1202 No violations noted Major areas inspected security organization, testing & maint & security sys power supply Safeguards info deleted (ref 10CFR73.21)
BAILEY, R J Region 1, Office of Director 84/01/06 5pp
21909 343 24X Fiche 50-317, 84/01/09, B401240280

B401300352 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/26, Document Management Branch 1p 22005 346 24X Fiche 50-317, 84/01/26, B401300352

--B401300355 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 3 1 re emergency classification of offsite agencies & ERPIP 4 1 2 re site emergency coordinator checklist
USIV, V Baltimore Gas & Electric Co 84/01/11 Director's Office, Office of Inspection and Enforcement 1p 22005 347 24X
Fiche: 50-317, 84/01/26, B401300352

--B401300358 Public version of revised emergency plan implementing procedures, including Procedure ERPIP 3 1 re emergency classification of offsite agencies & ERPIP 4 1 2 re site emergency coordinator checklist
RUSSELL, L B Baltimore Gas & Electric Co 83/12/16 14pp, 22005 348 24X Fiche 50-317, 84/01/26, B401300352

J Insurance & indemnity information

B401200160 Forwards Endorsements 55 & 22 to NELIA Policies NF-216 & NF-348, respectively, Endorsement 44 to MAELU Policy MF-76 & Endorsements 4 to MAELU Certificates M-52, M-53 to Master Policy 1.
YORK, M O Baltimore Gas & Electric Co 84/01/13, DINITZ, I Assistant Director for State & License Relations 8pp 21866 190 24X Fiche: 50-317, 84/01/13, B401200160

P Operating license stage documents & correspondence

B401180240 Resubmits Section 1B of updated FSAR in response to 10CFR50.54 requirement that licensees submit, to appropriate regional ofc, current description of QA program being implemented for inclusion in SAR No changes made
DOUGLASS, R M Baltimore Gas & Electric Co, 83/06/17 NAPUDA, G Region 1, Office of Director 5pp 21842 083, 24X
Fiche: 50-317, 83/06/17, B401180240

B401100127 Forwards Amends 89 & 70 to Licenses DPR-53 & DPR-69, respectively & safety evaluation. Amends revise Tech Specs to clarify operability requirements for containment purge isolation valves & basis for combustible gas control sys
JAFFE, D H Operating Reactors Branch 3 83/12/30 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21768 238 24X
Fiche: 50-317, 83/12/30, B401100127

--B401100130 Amends 89 & 70 to Licenses DPR-53 & DPR-69, respectively, revising Tech Specs to clarify operability requirements for containment purge isolation valves & basis for combustible gas control sys
MILLER, J R Operating Reactors Branch 3 83/12/30 23pp
21768 240 24X Fiche 50-317, 83/12/30, B401100127

--B401100131 Safety evaluation supporting Amends 89 & 70 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/30 5pp
21768 279 24X Fiche 50-317, 83/12/30, B401100127

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche: 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401040423 Forwards IE Insp Repts 50-317/83-29 & 50-318/83-29 on B31017-21 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/12/19 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21708 141 24X
Fiche 50-317, 83/12/19, B401040423

--B401040427 Notice of violation from insp on B31017-21
* Region 1, Office of Director 83/12/07 1p 21708 143 24X
Fiche 50-317, 83/12/19, B401040423

--B401040430 IE Insp Repts 50-317/83-29 & 50-318/83-29 on B31017-21 Noncompliance noted Failure to implement procedures re staff working hours for radiation chemistry technicians engaged in safety-related work
COLLINS, D J, SHANBARY, M M Region 1, Office of Director 83/12/09 5pp 21708 144 24X Fiche 50-317, 83/12/19, B401040423

B401100170 Ack receipt of B31206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-26 & 50-318/83-26
MARTIN, T T Division of Engineering & Technical Programs 83/12/23 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21760 172 24X
Fiche 50-317, 83/12/23, B401100170

--B401100176 Responds to NRC B31109 ltr re violations noted in IE Insp Repts 50-317/83-26 & 50-318/83-26 Corrective actions
Surveillance Test Procedure STP 0-7-1 re svc water inlet valve revised per Operating Instruction 15.
LUNDVALL, A E Baltimore Gas & Electric Co 83/12/06 MARTIN, T T Division of Engineering & Technical Programs 2pp 21760 174, 24X Fiche 50-317, 83/12/23, B401100170

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
BEYDUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche: 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche: 50-000, 83/12/30, B312120093

DOCKETED ITEMS

B401130249 Ack receipt of B31031 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-21 & 50-318/83-21
STARDSTECKI, R Division of Project & Resident Programs B4/01/09
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 21800 326 24X
Fiche 50-317, B4/01/09, B401130249

--B401130253 Responds to NRC B31003 ltr re violations noted in IE Insp Repts 50-317/83-21 & 50-318/83-21 Corrective actions chemistry technicians counseled on importance of logging all analytical results & notifying personnel in timely manner
LUNDVALL, A E Baltimore Gas & Electric Co B3/10/31
STARDSTECKI, R Division of Project & Resident Programs 2pp 21800 328 24X Fiche 50-317, B4/01/09, B401130249

B401240280 Forwards IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on B31128-1202 No violations noted
MARTIN, T T Division of Engineering & Technical Programs B4/01/09
BQIMAKER, N J Baltimore Gas & Electric Co 2pp 21909 341 24X
Fiche 50-317, B4/01/09, B401240280

--B401240295 IE Safeguards Insp Repts 50-317/83-33 & 50-318/83-33 on B31128-1202 No violations noted Major areas inspected security organization, testing & maint & security sys power supply Safeguards info deleted (ref IOCFR73 21)
BAYLEY, R J, GDDY, A T Region 1, Office of Director B4/01/06
5pp 21909 343 24X Fiche 50-317, B4/01/09, B401240280

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B401240274 Ack receipt of B31220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-28 & 50-318/83-28
MARTIN, T T Division of Engineering & Technical Programs B4/01/19
LUNDVALL, A E Baltimore Gas & Electric Co 1p 21909 355 24X
Fiche 50-317, B4/01/19, B401240274

--B401240277 Responds to NRC B31130 ltr re violations noted in IE Insp Repts 50-317/83-28 & 50-318/83-28 Corrective actions radiation safety procedures re radwaste packaging revised to comply w/DOT & NRC regulations & personnel retrained
LUNDVALL, A E Baltimore Gas & Electric Co B3/12/20 MURLEY, T E
Region 1, Office of Director 2pp 21909 356 24X
Fiche 50-317, B4/01/19, B401240274

I Periodic operating reports & related correspondence

B312290397 "Nonroutine Radiological Environ Operation Rept, for Period Ending Oct 1983"
FUHRMAN, O R Baltimore Gas & Electric Co B3/11/28 Region 1, Office of Director 2pp 21660 226 24X Fiche 50-317, B3/11/28, B312290397

B401250158 Monthly operating repts for Dec 1983 W/B40113 ltr
LOTIHO, E L Baltimore Gas & Electric Co B3/12/31 11pp
21937 062 24X Fiche 50-317, B3/12/31, B401250158

B401240403 Forwards rept of changes, tests & experiments completed on facilities under provisions of IOCFR50.59 Safety evaluation summary also encl
LUNDVALL, A E Baltimore Gas & Electric Co B4/01/03 MURLEY, T E
Region 1, Office of Director 7pp 21915 253 24X
Fiche 50-317, B4/01/03, B401240403

S Reportable occurrences, LERs & related correspondence

B312290397 "Nonroutine Radiological Environ Operation Rept, for Period Ending Oct 1983"
FUHRMAN, O R Baltimore Gas & Electric Co B3/11/28 Region 1, Office of Director 2pp 21660 226 24X Fiche 50-317, B3/11/28, B312290397

B401030186 LER B3-063/03L-0 on B31102, containment particulate & gaseous monitor skid isolation valve inadvertently shut Caused by close proximity to containment sample valve Locking device attached to prevent closure W/B31209 ltr
JUNGE, M A, CARLEON, J, RUSSELL, L B Baltimore Gas & Electric Co B3/12/09 MURLEY, T E Region 1, Office of Director 2pp 21683 049 24X Fiche 50-318, B3/12/09, B401030186

B401160171 LER B3-065/03L-0 on B31202 & 10, erratic metroscope alarms & indications for CEA 57 & 4 identified failed reed switch position transmitter stacks Root cause under investigation to determine corrective actions W/B31222 ltr
PIERINGER, P A, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B3/12/22 MURLEY, T E Region 1, Office of Director 2pp 21815 337 24X Fiche 50-318, B3/12/22, B401160171

B401270065 LER B3-070/03L-0 on B31125, pressure level decreased to 116 inches while loading main turbine Caused by RCS temp swings Change to pressurizer program in progress W/B31222 ltr
JUNGE, M A, RUSSELL, L B Baltimore Gas & Electric Co B3/12/22 MURLEY, T E Region 1, Office of Director 2pp 21981 361 24X Fiche 50-318, B3/12/22, B401270065

B401160087 LER B3-068/03L-0 on B31217, dose equivalent I-131 determined to be 1.413 uCi per g Caused by depressurization shock associated w/shutdown Sys purified utilizing ion exchanger No addl corrective action necessary W/B31227 ltr
PORTER, R J, RUSSELL, L B Baltimore Gas & Electric Co B3/12/29 MURLEY, T E Region 1, Office of Director 5pp 21815 195 24X Fiche 50-318, B3/12/29, B401160087

B401160131 LER B3-069/01T-0 on B31219, during return to full power operation, reed switch position indication lost for all control element assemblies due to high voltage condition on metroscope power supplies Power replaced W/B31227 ltr
PIERINGER, P A, CRUNKLETON, J, RUSSELL, L B Baltimore Gas & Electric Co B3/12/29 MURLEY, T E Region 1, Office of Director 2pp 21815 008 24X Fiche 50-318, B3/12/29, B401160131

B401270334 LER B3-067/03L-0 on B31208, during normal operation, w/charging pump 22 out of svc, charging pump 23 discharge relief valve lifted Caused by damaged disc Disc replaced, W/B40105 ltr
JUNGE, M A, REID, K A, RUSSELL, L B Baltimore Gas & Electric Co B4/01/06 MURLEY, T E Region 1, Office of Director 2pp 21976 321 24X Fiche 50-318, B4/01/06, B401270334

B401270086 LER B3-075/03L-0 on B31210, intermittent failure in metroscope CEA position indication sys caused spurious CEA motion inhibit & CEA group out-of-sequence alarms Cause unknown CMI feature retained via mod W/B40109 ltr
PIERINGER, P A, RAYNOR, J W, RUSSELL, L B Baltimore Gas & Electric Co B4/01/09 MURLEY, T E Region 1, Office of Director 2pp 21982 114 24X Fiche 50-318, B4/01/09, B401270086

V Operator Examinations

B401190326 Forwards operator licensing exam schedule, in response to B31221 Generic Ltr B3-40
LUNDVALL, A E Baltimore Gas & Electric Co B4/01/16 EISENHUT, D O
Division of Licensing 2pp 21850 353 24X Fiche 50-317, B4/01/16, B401190326

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents, App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records B3/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X
Fiche 50-000, B3/11/02, B401250163

--B401250185 Discusses how SECY-82-111 unravels NRC emergency preparedness requirements, per author B21103 memo Table III A 1-2-2 not changed in any way by SECY-82-111 Responses to listed questions requested
OILINSKY, V Commissioners B2/11/18 Commissioners 2pp 21958 004 24X Fiche 50-000, B3/11/02, B401250163

DOCKETED ITEMS

153

8401030234 Forwards IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 & notice of violation
MURLEY, T E Region 1, Office of Director 83/12/14 CLARK, F R
General Public Utilities - GPU Service Corp 3pp 21682 279 24X
Fiche 50-289, 83/12/14, 8401030234

--8401030237 Notice of violation from insp on 830911
MURLEY, T E Region 1, Office of Director 83/12/14 1p
21682 282 24X Fiche 50-289, 83/12/14, 8401030234

--8401030241 IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 Violation noted drafts containing
safeguards info left unattended on desk in unlocked security
storage container
MURLEY, T E Region 1, Office of Director 83/12/14 2pp
21682 283 24X Fiche 50-289, 83/12/14, 8401030234

8401050033 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21735 133 24X Fiche 50-320, 83/12/27,
8401050033

--8401050037 Public version of revised emergency plan implementing
procedures, including Procedures 1054 1 re unusual event,
1054 2 re alert & 1054 3 re site emergency
BRADY, J A STANGE, S J General Public Utilities - GPU Service
Corp 83/11/08 150pp 21735 134 24X Fiche 50-320, 83/12/27,
8401050033

8401050039 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21732 192 24X Fiche 50-320, 83/12/27,
8401050039

--8401050044 Forwards public version of revised emergency plan
implementing procedures, including Procedures 1055 re
emergency preparedness drills, 1054 1 re unusual event &
1054 2 re alert Receipt form encl
NASH, B General Public Utilities - GPU Service Corp 83/11/09
POINDEXTER, T C TH1 Program Office 1p 21732 193 24X
Fiche 50-320, 83/12/27, 8401050039

--8401050049 Public version of revised emergency plan implementing
procedures, including Procedures 1055 re emergency
preparedness drills, 1054 1 re unusual event & 1054 2 re
alert
BRADY, J A STANGE, S J General Public Utilities - GPU Service
Corp 83/11/03 151pp 21732 195 24X Fiche 50-320, 83/12/27,
8401050039

8401060103 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21747 039 24X Fiche 50-320, 83/12/27,
8401060103

--8401060111 Public version of revised emergency plan implementing
procedures, including Procedures 1054 27 re activation of
emergency operations facility & 1054 33 re sampling, analysis
& evaluation of liquid samples
BROWN, N BRADY, J A STANGE, S J General Public Utilities - GPU
Service Corp 83/11/21 80pp 21747 040 24X
Fiche 50-320, 83/12/27, 8401060103

8401130323 Ack receipt of 831014 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-289/83-18 &
50-320/83-10 Corrective actions re min number of fire
brigade members at site acceptable
MARTIN, T T Division of Engineering & Technical Programs 84/01/05
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
21801 328 24X Fiche 50-289, 84/01/05, 8401130323

8401310137 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22037 231 24X Fiche 50-320, 84/01/18,
8401310137

--8401310219 Public version of Rev 8 to Emergency Plan Implementing
Procedures 1054 A, "Add'l Assistance & Notification" & Rev 5
to Procedure 1054 B, "Callout of Onsite & Offsite Duty
Roster Personnel"
BEAVER, J R STANGE, S J BRADY, J A General Public Utilities -
GPU Service Corp 83/11/01 36pp 22037 232 24X
Fiche: 50-320, 84/01/18, 8401310137

8401260213 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21971 350 24X Fiche 50-320, 84/01/20,
8401260213

--8401260217 Public version of Rev 2 to Emergency Plan Implementing
Procedure 1054 3b, "Emergency Assembly Area"
LEWIS, S Metropolitan Edison Co 83/12/27 10pp 21971 351
24X Fiche 50-320, 84/01/20, 8401260213

8401260234 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21992 153 24X Fiche 50-320, 84/01/20,
8401260234

--8401260238 Public version of Rev 2 to Emergency Plan Implementing
Procedure 1054 3c, "Activation of Annex to Emergency
Operations Facility" & Rev 5 to Procedure 1051, "Emergency
Preparedness Drills"
NELSON, M A TROFFER, Q J Metropolitan Edison Co
83/12/20 32pp 21992 154 24X Fiche 50-320, 84/01/20, 8401260234

8401260378 Releases public version of temporary change notice to
emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 281 24X Fiche 50-320, 84/01/20,
8401260378

--8401260401 Public version of temporary change notice to Rev 5 to
Emergency Plan Implementing Procedure 1054 B, "Callout of
Onsite & Offsite Duty Roster Personnel"
BEAVER, J MILLER, A General Public Utilities - GPU Service Corp
83/12/21 18pp 21959 282 24X Fiche 50-320, 84/01/20, 8401260378

8401300365 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/26 Document
Management Branch 1p 22005 316 24X Fiche 50-320, 84/01/26,
8401300365

--8401300367 Public version of Rev 4 to Emergency Plan Implementing
Procedure 1054 3, "Site Emergency"
* Metropolitan Edison Co 84/01/26 29pp 22005 317 24X
Fiche 50-320, 84/01/26, 8401300365

G Adjudicatory correspondence

8401090353 Corrects apparent misunderstanding re prior meeting w/Kuhns
concerning resignation Util mat deserves high marks for
efforts to keep company solvent & maintain unrestricted &
unbroken svc to all customers
ALLGOOD, I J National Systems, Inc 84/01/03 OILINSKY, V
Commissioners 3pp 21754 083 24X Fiche 50-289, 84/01/03,
8401090353

H General correspondence

8401300078 Requests removal of EQ Wallace from future correspondence &
svc copy lists for TH1 Program Ofc generated documents
WETHMORE, J S General Public Utilities - GPU Service Corp 84/01/12
BARRETT, L H TH1 Program Office 1p 21999 166 24X
Fiche 50-289, 84/01/12, 8401300078

8401310220 Supports NRC judgment re proposed cleanup plans Continued
delay unnecessary & presents economic penalty on general
public.
FURSE, R K Affiliation Unknown 84/01/25 SNYDER, B J TH1 Program
Office 2pp 22021 339 24X Fiche 50-320, 84/01/25, 8401310220

J Insurance & indemnity information

8401030198 Forwards Endorsements 67, 68 & 69 to NELIA Policy NF-220 &
Endorsements 58 & 59 to MAELU Policy MF-73 w/o Endorsement
67
GERETY, H F General Public Utilities - GPU Service Corp 83/12/14
SALTZMAN, J Office of Nuclear Reactor Regulation, Director 6pp
21683 083 24X Fiche 50-289, 83/12/14, 8401030198

8401260005 Forwards Endorsement 3 to NELIA Binders N-56 & N-65
GERETY, H F General Public Utilities - GPU Service Corp 84/01/16
SALTZMAN, J Office of Nuclear Reactor Regulation, Director 3pp
21956 345 24X Fiche 50-289, 84/01/16, 8401260005

8401300308 Forwards Endorsement 70 to NELIA Policy NF-220 &
Endorsement 60 to MAELU Policy MF-73
GERETY, H F General Public Utilities - GPU Service Corp 84/01/24
SALTZMAN, J Office of Nuclear Reactor Regulation, Director 3pp
21996 338 24X Fiche 50-289, 84/01/24, 8401300308

DOCKETED ITEMS

P Operating license stage documents & correspondence

- 8401270427 SAFETY EVALUATION AND ENVIRONMENTAL ASSESSMENT, THREE MILE ISLAND NUCLEAR STATION, UNIT NO. 2 Docket No. 50-320
(Metropolitan Edison Company, Jersey Central Power and Light Company, and Pennsylvania Electric Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0647
80/02/28 24pp 22002 246 24X Fiche 50-320, 80/02/28, 8401270427
- 8401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies
Supporting ltrs encl
CALSOYAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, 83/10/10, 8401050027
- 8401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015
- 8206110014 Informs of status of util ability to provide addl senior reactor operator on shift by 820701 per requirements of TMI Item I A 1.3, "Shift Manning Requirements"
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-219 82/06/01 4pp 21944 235 24X
Fiche 50-000, 83/10/18, 8401250015
- 8209200347 Informs of current status of NRC efforts re psychological stress associated w/TMI restart Natl Inst of Mental Health is reviewing proposed psychological survey
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-346 82/08/19 2pp 21966 030 24X
Fiche 50-000, 83/10/18, 8401250015
- 8301070155 Informs Commission of status of psychological stress survey proposal to predict stress resulting from restart of TMI-1 & reanalyses of three studies of psychological stress caused by accident & aftermath at TMI-2
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-500 82/12/27 6pp 21967 216 24X
Fiche 50-000, 83/10/18, 8401250015
- 8401250311 Informs of status of staff effort re psychological stress associated w/TMI-1 restart
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-346A 82/09/13 2pp 21966 032 24X
Fiche 50-000, 83/10/18, 8401250015
- 8401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies NRC has no records subj to request Utilis not required to submit insurance rating to NRC
FELTON, J M Division of Rules and Records 83/10/25 CALSOYAS, C D Affiliation Unknown 1p 21736 236 24X Fiche 50-000, 83/10/25, 8401050043
- 8401230001 Further response to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests App A info partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/07 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 3pp 21930 322 24X
Fiche 50-289, 83/11/07, 8401230001
- 8401230015 Requests investigation of Hartman allegations of leak rate falsification at TMI-2, per DL Jensen 830517 ltr indicating no bar to NRC proceeding w/independent investigations
PALLADINO, N J Commissioners 83/11/07 HAYES, B Office of Investigation 1p 21930 334 24X Fiche 50-320, 83/11/07, 8401230015
- 8401230036 Discusses propriety of NRC civil investigation into Hartman allegation concurrent w/DOJ criminal investigation of same
Nontensored version
CUMMINGS, J J Office of Inspector & Auditor 83/05/31
JENSEN, D L Justice, Dept of 3pp 21930 343 24X
Fiche 50-289, 83/11/07, 8401230001
- 8401260302 Forwards responses to 831017 request re Rev 2 to QA plan
Encl updated quality classification list issued 830701 as part of Procedure 4000-ENG-7313 01 Reg Guides 1 37 & 1 39 will be revised to clarify position
KANGA, B K General Public Utilities - GPU Service Corp 83/12/22
SNYDER, B J TMI Program Office 15pp 21935 158 24X
Fiche 50-320, 83/12/22, 8401260302
- 101190135 Submits review of proposed plan for makeup & purification demineralizer resin sampling Plan acceptable
BARRETT, L H TMI Program Office 83/12/23 KANGA, B K General Public Utilities - GPU Service Corp 2pp 21871 021 24X
Fiche 50-320, 83/12/23, 8401190135
- 8401040335 Forwards plan & schedule to recover Tech Spec-required components such that required surveillance can be performed, per 830930 commitment Plan lists areas in auxiliary & fuel handling bldg for which ALARA exemptions taken
KANGA, B K General Public Utilities - GPU Service Corp 83/12/23
SNYDER, B J TMI Program Office 5pp 21704 344 24X
Fiche 50-320, 83/12/30, 8401040335
- 8401090613 PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO DECONTAMINATION AND DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979 ACCIDENT, THREE MILE ISLAND NUCLEAR STATION, UNIT 2 Docket No. 50-320
* TMI Program Office NUREG-0683 501 DRFT 83/12/31 50pp
21767 160 24X Fiche 50-320, 83/12/31, 8401090613
- 8401260068 ANSWERS TO QUESTIONS ABOUT UPDATED ESTIMATES OF OCCUPATIONAL RADIATION DOSES AT THREE MILE ISLAND, UNIT 2 Docket No. 50-320
* TMI Program Office NUREG-1060 83/12/31 21pp 21971 263
24X Fiche 50-320, 83/12/31, 8401260068
- 8401190105 Forwards response to proposed rev to Fuel Pool A refurbishment SER Proposed rev & continued refurbishment activities acceptable
KANGA, B K TMI Program Office 84/01/04 BARRETT, L H General Public Utilities - GPU Service Corp 2pp 21870 232 24X
Fiche 50-320, 84/01/04, 8401190105
- 8401250433 Advises that Section 3.3 to annual technical evaluation re for once-through steam generator layout recirculation sys should be revised Technical evaluation rept acceptable, subj to stated comment Proposed corrective action requested
BARRETT, L H TMI Program Office 84/01/04 KANGA, B K General Public Utilities - GPU Service Corp 2pp 21949 026 24X
Fiche 50-320, 84/01/04, 8401250433
- 8401090382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401090382
- 8401170515 Advises that util actions taken in response to NRC 801222 ltr & Generic Ltr 81-07 re control of heavy loads satisfy requirements
SNYDER, B J TMI Program Office 84/01/05 KANGA, B K General Public Utilities - GPU Service Corp 3pp 21847 132 24X
Fiche 50-320, 84/01/05, 8401170515
- 8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221
- 8401170174 Submits response to 831216 telcon requesting info re Senat Specter question on total number of GPU employees now applied to TMI-1, who were Met Ed employees, having any involvement w/operation of TMI-2 prior to Mar 1979
CLARK, P R General Public Utilities - GPU Service Corp 84/01/11
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21834 139 24X Fiche 50-289, 84/01/11, 8401170174
- 8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084
- 8401190226 Forwards comments resulting from review of Tech Spec Change Requests 39, 41 & 43 & recovery operations plan Change Requests 19, 20 & 22 Comments must be addressed before reviews can be completed
SNYDER, B J TMI Program Office 84/01/13 KANGA, B K General Public Utilities - GPU Service Corp 5pp 21870 204 24X
Fiche 50-320, 84/01/13, 8401190226
- 8401250279 Forwards "TMI-2 Rept Mgt & Safety Allegations Vol I Introduction, Summary & Conclusions" & "Vol IV Allegations of Safety Deficiencies & Poor Mgt"
CLARK, P R General Public Utilities - GPU Service Corp 84/01/16
DENTON, H R Office of Nuclear Reactor Regulation, Director 23pp 21941 349 24X Fiche 50-320, 84/01/16, 8401250279
- 8401250284 "TMI-2 Rept Mgt & Safety Allegations, Vol I Introduction, Summary & Conclusions"
STIER, E H General Public Utilities - GPU Service Corp 83/11/16 100pp 21942 013 24X Fiche 50-320, 84/01/16, 8401250279

--B401250267 TMI-2 Rept Mgt & Safety Allegations Vol IV Allegations of Safety Deficiencies & Poor Mgt
STIER, E. H. General Public Utilities - GPU Service Corp 83/11/16
403pp. 21942 104 24X Fiche 50-320,84/01/16,8401250277

Q Inspection reports, IE Bulletins & correspondence

8401030234 Forwards IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 & notice of violation
MURLEY, T. E. Region 1, Office of Director 83/12/14 CLARK, P. R.
General Public Utilities - GPU Service Corp 3pp 21682 279 24X
Fiche 50-289,83/12/14,8401030234

--B401030237 Notice of violation from insp on 830911
MURLEY, T. E. Region 1, Office of Director 83/12/14 1p
21682 282 24X Fiche 50-289,83/12/14,8401030234

--B401030241 IE Enforcement Conference Repts 50-289/83-104 & 50-320/83-104 on 831205 Violation noted drafts containing safeguards info left unattended on desk in unlocked security storage container
MURLEY, T. E., GODY, A. T. Region 1, Office of Director 83/12/14
2pp 21682 283 24X Fiche 50-289,83/12/14,8401030234

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp 21731 164 24X Fiche 50-000,83/12/28,8312120090

8401100393 Ack receipt of 831202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-15
BARRETT, L. H. TMI Program Office 83/12/28 KANGA, B. K. General Public Utilities - GPU Service Corp 1p. 21762 231 24X
Fiche 50-320,83/12/28,8401100393

--B401100398 Responds to NRC 831102 ltr re violations noted in IE Insp Rept 50-320/83-15 Corrective actions personnel involved w/procedure writing advised to be more explicit in written instructions & procedures re crane movement
KANGA, B. K. General Public Utilities - GPU Service Corp 83/12/02
MURLEY, T. E. Region 1, Office of Director 2pp 21762 232 24X
Fiche 50-320,83/12/28,8401100393

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp. 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401100334 Ack receipt of 830902,09 & 1107 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-08 NRC amend of order effective 831101 revised various mgt personnel responsibilities
BARRETT, L. H. TMI Program Office 84/01/03 KANGA, B. K. General Public Utilities - GPU Service Corp 2pp 21763 333 24X
Fiche 50-320,84/01/03,8401100334

--B401100354 Responds to NRC 830803 ltr re violations noted in IE Insp Rept 50-320/83-08 Corrective actions Procedures 1054 33 & 4301-W-2 re reactor coolant samples & storage batteries will be completed on 831014 & 0930, respectively
KANGA, B. K. General Public Utilities - GPU Service Corp 83/09/09
MURLEY, T. E. Region 1, Office of Director 3pp. 21763 340 24X
Fiche 50-320,84/01/03,8401100334

--B401100363 Clarifies statements in NRC 831025 ltr re IE Insp Rept 50-320/83-08 Implementation of 830919 amend to order no longer requires depth of involvement by site operations director
KANGA, B. K. General Public Utilities - GPU Service Corp 83/11/07
STAROSTECKI, R. Division of Project & Resident Programs 1p
21763 343 24X Fiche 50-320,84/01/03,8401100334

8401100323 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-18 & 50-320/83-10 Corrective actions re min number of fire brigade members at site acceptable
MARTIN, T. T. Division of Engineering & Technical Programs 84/01/05
MURILL, H. D. General Public Utilities - GPU Service Corp 2pp
21801 328 24X Fiche 50-289,84/01/05,8401100323

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp. 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401170397 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-16
BARRETT, L. H. TMI Program Office 84/01/12 KANGA, B. K. General Public Utilities - GPU Service Corp 1p 21828 331 24X
Fiche 50-320,84/01/12,8401170397

--B401170401 Responds to NRC 831109 ltr re violations noted in IE Insp Rept 50-320/83-16 Corrective actions addl instruction given to appropriate personnel to ensure radiological procedural controls will be followed
KANGA, B. K. General Public Utilities - GPU Service Corp 83/12/09
MURLEY, T. E. Region 1, Office of Director 5pp 21828 332 24X
Fiche 50-320,84/01/12,8401170397

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp. 21937 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401180017 Forwards TMI Program Ofc weekly status rept for wk of 840107
BARRETT, L. H. TMI Program Office 84/01/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 22pp 21848 268 24X Fiche 50-320,84/01/09,8401180017

8401300123 Estimated quantities of solid waste as result of ongoing containment decontamination for period ending 831231
KANGA, B. K. General Public Utilities - GPU Service Corp 84/01/23
SNYDER, B. J. TMI Program Office 2pp 21999 094 24X
Fiche 50-320,84/01/23,8401300123

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs
GRABER, L. D. NUS Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000,83/10/07,8401050064

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records 83/11/02 O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge 5pp 21937 357 24X
Fiche 50-000,83/11/02,8401250163

--B401250283 Submits responses to questions raised re I-131 airborne releases during plant accident Estimates of releases use actual effluent radiation readings & sample analyses during emergency conditions
DIRCKS, W. Office of the Executive Director for Operations 81/01/28 BRADFORD, P. Commissioners 3pp 21938 325 24X
Fiche 50-000,83/11/02,8401250163

8401030129 Updated LER 82-020/D1X-1 on 820603, determined recent over flow of auxiliary bldg pump caused by influx of rainwater from borated water storage tank recirculation pump encl
Spec limit Caused by sticking, broken linkage in vortex damper Linkage will be replaced W/831212 ltr
CHAPLIN, S. D., KANGA, B. K. General Public Utilities - GPU Service Corp 83/12/09 MURLEY, T. E. Region 1, Office of Director 6pp
21683 127 24X Fiche 50-320,83/12/09,8401030129

8401030135 LER 83-060/03L-0 on 831110 & 22, auxiliary bldg exhaust fans AH-E-8C/D cycled periodically, decreasing flowrate below Tech Spec limit Caused by sticking, broken linkage in vortex damper Linkage will be replaced W/831212 ltr
SWARTZWELDER, B., KANGA, B. K. General Public Utilities - GPU Service Corp. 83/12/12 MURLEY, T. E. Region 1, Office of Director 2pp
21680 324 24X Fiche 50-320,83/12/12,8401030135

DOCKETED ITEMS

8401160195 LER 83-053/99X-0 on 830628, two mechanical seismic restraint snubbers on decay heat auxiliary spray line would not respond to in-place exercising. Snubber failure probably caused by excessive loading. Snubbers replaced W/831222 ltr GULD, T L, KANGA, B K General Public Utilities - GPU Service Corp 83/12/22 MURLEY, T E Region 1, Office of Director 3pp 21808 300 24X Fiche 50-320, 83/12/22, 8401160195

8401240074 LER 83-062/03L-0 on 831201, low flow conditions found in auxiliary bldg ventilation sys Cause traced to supply fan trip in Unit 1 fuel handling bldg ventilation sys Unit 1 control room notified W/831229 ltr CHAPLIN, S D, KANGA, B K General Public Utilities - GPU Service Corp 83/12/29 MURLEY, T E Region 1, Office of Director 4pp 21912 311 24X Fiche 50-320, 83/12/29, 8401240074

8401250279 Forwards "TMI-2 Rept Mgt & Safety Allegations Vol I Introduction, Summary & Conclusions" & "Vol IV Allegations of Safety Deficiencies & Poor Mgt" CLARK, P R General Public Utilities - GPU Service Corp 84/01/16 BENTON, H R Office of Nuclear Reactor Regulation, Director 25pp 21941 349 24X Fiche 50-320, 84/01/16, 8401250279

--8401250287 "TMI-2 Rept Mgt & Safety Allegations Vol IV Allegations of Safety Deficiencies & Poor Mgt" BIER, E H General Public Utilities - GPU Service Corp. 83/11/16 403pp 21942 104 24X Fiche 50-320, 84/01/16, 8401250279

T Hearing transcripts on non-antitrust matters

8401310163 Transcript of 831208 hearing in Harrisburg, PA re decontamination of TMI-2 Pp 1-91 Supporting documentation encl * Advisory Council for Decontamination of TMI Unit 2 83/12/08 150pp 22034 181 24X Fiche 50-320, 83/12/08, 8401310163

U Congressional/Executive Correspondence

8401230001 Further response to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests App A info partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/11/07 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 3pp 21930 322 24X Fiche 50-289, 83/11/07, 8401230001

--8401230011 Requests explanation of conflict between NJ Palladino 830325 testimony & DL Jensen 830517 ltr re NRC investigation into allegations that leak rate calculations at TMI-2 improperly conducted prior to accident UDALL, M K House of Rep, Interior & Insular Affairs 83/09/23 PALLADINO, N J Commissioners 1p 21930 333 24X Fiche 50-289, 83/11/07, 8401230001

8401230026 Responds to 830523 request for explanation of conflict between NJ Palladino 830325 testimony & DL Jensen 830517 ltr re propriety of NRC investigation into allegations that leak rate calculations at TMI-2 improperly conducted PALLADINO, N J Commissioners 83/07/14 UDALL, M K House of Rep, Interior & Insular Affairs 3pp 21930 337 24X Fiche 50-289, 83/11/07, 8401230001

01110327 Declines invitation to participate in restart hearing Meeting to be held on 840110 will evaluate alternatives for addressing mgt integrity, not reach decision re restart. PALLADINO, N J Commissioners 83/12/15 SPECTER, A Senate 2pp 21793 008 24X Fiche 50-289, 83/12/08, 840110327

--8401110328 Requests delay in administrative proceedings re Unit 1 operation until conclusion of util criminal misconduct trial Schedule conflict re witness testimony at both proceedings possible JENSEN, D L Justice, Dept of 83/12/14 PALLADINO, N J Commissioners 2pp 21793 010 24X Fiche 50-289, 83/12/08, 840110327

110244 Forwards response to 830929 request for answers to questions, util review of draft IE rept re Unit 2 accident (NUREG-0600) PALLADINO, N J Commissioners 83/12/09 UDALL, M K House of Rep Interior & Insular Affairs 3pp 21793 028 24X Fiche 50-320, 83/12/09, 840110244

10110247 Forwards "Rept on Comparison of NUREG-0600 to 790715 Draft" for review All changes to rept proper & no impropriety associated w/release of rept Investigation unwarranted STELLO, V Regional Operations & Generic Requirements 83/09/16 PALLADINO, N J Commissioners 11pp 21793 033 24X Fiche 50-320, 83/12/09, 840110244

--840110250 Forwards draft IE investigation rept re 790328 accident Review for proprietary info requested ORTER, B H Region 1, Office of Director 79/07/16 ARNOLD, R C Metropolitan Edison Co 2pp 21795 044 24X Fiche 50-320, 83/12/09, 840110244

--840110255 Advises that IE investigation rept re nuclear accident on 790328-30 contains no proprietary info STELLO, V Office of Inspection & Enforcement, Office of the Director 79/09/01 HERBEIN, J G Metropolitan Edison Co 1p 21795 046 24X Fiche 50-320, 83/12/09, 840110244

--840110258 Ack receipt of V Stello 830916 memo re release of NUREG-0600 in draft form No further internal inquiry required PALLADINO, N J Commissioners 83/10/04 DIRCKS, W J Office of the Executive Director for Operations 1p 21795 047 24X Fiche 50-320, 83/12/09, 840110244

--840110264 Questions why draft IE rept re accident (NUREG-0600) sent to util for comments PALLADINO, N J Commissioners 83/09/29 UDALL, M K House of Rep, Interior & Insular Affairs 2pp 21795 048 24X Fiche 50-320, 83/12/09, 840110244

8401170518 Provides addl info re items raised during 831216 hearing in Harrisburg, PA Issues include Hartman allegations (TMI-2 leak rate falsification), TMI-1 leak rate falsification, GPU vs B&W lawsuit & Paris et al allegations BENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/30 SPECTER, A Senate 2pp 21844 362 24X Fiche 50-320, 83/12/30, 8401170518

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8401050621 Forwards IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted DANCE, H C Division of Project & Resident Programs 83/12/09 KELLY, R J Georgia Power Co 2pp 21726 062 24X Fiche 50-321, 83/12/09, 8401050621

--8401050633 IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted Major areas inspected plant tours, plant operations review, Tech Spec compliance, physical protection, refueling activity & spent fuel pool activity MATHIS, J L, KRUG, H Region 2, Office of Director JAFFE, F Division of Engineering & Operational Programs 83/12/06 5pp 21726 064 24X Fiche 50-321, 83/12/09, 8401050621

8401060446 Discusses Jan & Feb 1983 revs to radiological emergency plan Revs meet applicable planning stds of 10CFR50 Outstanding issues identified in IE Insp Repts 50-321/83-19 & 50-366/83-19 DANCE, H C Division of Project & Resident Programs 83/12/30 KELLY, R J Georgia Power Co 2pp 21740 089 24X Fiche 50-321, 83/12/30, 8401060446

8401240285 Expresses appreciation for util effort in investigation & subsequent arrest & terminations in response to recent bomb threats O'REILLY, J P Region 2, Office of Director 84/01/13 KELLY, R J Georgia Power Co 1p 21909 340 24X Fiche 50-321, 84/01/13, 8401240285

8401240379 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/83-30 LEWIS, R C Division of Project & Resident Programs 84/01/13 KELLY, R J Georgia Power Co 1p 21909 149 24X Fiche 50-321, 84/01/13, 8401240379

--8401240391 Notice of violation from insp on 831001-31 * Region 2, Office of Director 83/12/08 1p 21909 155 24X Fiche 50-321, 84/01/13, 8401240379

--8401240397 IE Insp Repts 50-321/83-30 & 50-366/83-32 on 831001-31 Noncompliance noted Failure to establish required fire watches CALENJAK, R V, HOLMES-RAY, P Region 2, Office of Director PANCIERA, V W Division of Project & Resident Programs 83/12/07 6pp 21909 156 24X Fiche 50-321, 84/01/13, 8401240379

8401240099 Releases public version of revised emergency plan implementing procedures. FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21932 232 24X Fiche 50-321, 84/01/18, 8401240099

DOCKETED ITEMS

157

--B401240102 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8035 re pulmonary function screening program & HNP-8016 re shipment of radioactive matl
NIX, H C Georgia Power Co 83/12/05 Office of Nuclear Reactor Regulation, Director 1p 21932 233 24X Fiche 50-321, 84/01/18, B401240097

--B401240106 Public version of revised emergency plan implementing procedures, including Procedures HNP-8035 re pulmonary function screening program & HNP-8016 re shipment of radioactive matl
ROGERS, W. H., GREENE, T., NIX, H C Georgia Power Co 83/12/07 133pp 21932 234 24X Fiche 50-321, 84/01/18, B401240097

B401260056 Releases public version of revised site emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21989 256 24X Fiche 50-321, 84/01/18, B401260056

--B401260059 Public version of Rev 5 to site emergency plan W/831108 memo & receipt form
OLLINGER, W H., GUCHA, L T Georgia Power Co 83/11/08 Office of Nuclear Reactor Regulation, Director 48pp 21989 257 24X Fiche 50-321, 84/01/18, B401260056

B401310315 Submits info documenting addl considerations of projected phased improvement in fire protection & mitigating factors for areas unmodified during extended implementation period
Tentative completion dates for App R mods encl
BECKHAM, J T Georgia Power Co 84/01/24 STOLZ, J F Operating Reactors Branch 4 3pp 22026 281 24X Fiche 50-321, 84/01/24, B401310315

J Insurance & indemnity information

B401050269 Forwards Endorsement 84 to NELIA Policy NF-215 & Endorsement 69 to MAELU Policy MF-78
FIELDER, J Marsh & McLennan, Inc 83/12/27 BALTZMAN, J Assistant Director for State & License Relations 3pp 21727 169 24X Fiche: 50-321, 83/12/27, B401050269

P Operating license stage documents & correspondence

B312200076 Forwards Amend 96 to License DPR-57 & safety evaluation Amend re/reflects changes to core design associated w/replacement of leaking fuel assemblies & extends allowable fuel burnup limit
RINENBARK, G Operating Reactors Branch 4 83/12/06 BECKHAM, J T Georgia Power Co 3pp 21590 108 24X Fiche 50-321, 83/12/06, B312200076

--B312200086 Amend 96 to License DPR-57, modifying Tech Specs to reflect changes to core design associated w/replacement of leaking fuel assemblies & extending allowable fuel burnup limit from 30 Gwd/t to 40 Gwd/t
STOLZ, J F Operating Reactors Branch 4 83/12/06 12pp 21590 111 24X Fiche 50-321, 83/12/06, B312200076

--B312200089 Safety evaluation supporting Amend 96 to License DPR-57
* Office of Nuclear Reactor Regulation, Director 83/12/06 3pp 21590 123 24X Fiche 50-321, 83/12/06, B312200076

B401060260 Summarizes 831209 meeting in Atlanta, GA re proposed organizational changes
O'REILLY, J P Region 2, Office of Director, 83/12/15 KELLY, R J Georgia Power Co 1p 21740 139 24X Fiche 50-321, 83/12/15, B401060260

B401130346 Forwards addl info re 831214 ltr requesting substitution of longer valves for scram discharge val vent & drain valve closure times Closure times proposed in 831214 ltr do not meet acceptance criteria in SER
GUCHA, L T Georgia Power Co 83/12/22 STOLZ, J F Operating Reactors Branch 4 3pp 21798 277 24X Fiche 50-321, 83/12/22, B401130346

B401100019 Notification of 840111 meeting w/util in Bethesda, MD to discuss util request for extension for completion of NUREG-0737, Item II B 3, "Post-Accident Sampling Sys"
RIVENBARK, G Operating Reactors Branch 4 84/01/04 STOLZ, J F Operating Reactors Branch 4 2pp 21776 058 24X Fiche 50-321, 84/01/04, B401100019

B401190551 Informs that NRC accepted OE small break LOCA model for use in satisfying TMI Action Item II K 3 30 on 831213, using model in facility LOCA analysis if info incorrect, requests act.
STOLZ, J F. Operating Reactors Branch 1 84/01/04 BECKHAM, J T Georgia Power Co. 2pp 21861 191 24X Fiche 50-321, 84/01/04, B401190551.

B401260083 Forwards Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively & safety evaluation Amends revise Tech Specs to add limiting condition for operation & surveillance requirements for scram discharge val vent & drain valves
STOLZ, J F Operating Reactors Branch 4 84/01/04 BECKHAM, J T Georgia Power Co 2pp 21990 158 24X Fiche 50-321, 84/01/04, B401260083

--B401260086 Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively, revising Tech Specs to add limiting condition for operation & surveillance requirements for scram discharge val vent & drain valves
STOLZ, J F Operating Reactors Branch 4 84/01/04 25pp 21990 162 24X Fiche 50-321, 84/01/04, B401260083

--B401260091 Safety evaluation supporting Amends 97 & 34 to Licenses DPR-57 & NPF-5
* Office of Nuclear Reactor Regulation, Director 84/01/04 117pp 21990 187 24X Fiche 50-321, 84/01/04, B401260083

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401170172 Submits info on diesel generator quick starts & opinion of effect on reliability Record of diesel cold starts for 1983 summarized, in response to NRC 831216 request
GUCHA, L T Georgia Power Co 84/01/09 STOLZ, J F Operating Reactors Branch 4 3pp 21834 136 24X Fiche 50-321, 84/01/09, B401170172

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401310047 Forwards safety evaluations confirming satisfactory resolution of Generic Item B-24 issues & NUREG-0737, Item II E 4 2 re containment vent & purging & valve operability
Tech Specs proposed in 1983 ltrs to be handled separately
STOLZ, J F Operating Reactors Branch 4 84/01/16 BECKHAM, J T Georgia Power Co 3pp 22032 342 24X Fiche 50-321, 84/01/16, B401310047

--B401310052 Safety evaluation concluding util demonstrated operability of containment purge & vent valves Valves will close against buildup of containment pressure in event of DBA/LOCA when valves limited to opening angles of 30 degrees or less
* NRC - No Detailed Affiliation Given 84/01/16 5pp 22032 045 24X Fiche 50-321, 84/01/16, B401310047

--B401310056 Safety evaluation suppl on containment/purge vent sys
Acceptable approach provided to modify standby gas treatment sys to withstand pressure increase resulting from LOCA
* NRC - No Detailed Affiliation Given 84/01/16 3pp 22032 350 24X Fiche 50-321, 84/01/16, B401310047

--B401310063 Safety evaluation accepting util evaluation of radiological consequences of LOCA during purging
* NRC - No Detailed Affiliation Given 84/01/16 2pp 22032 353 24X Fiche 50-321, 84/01/16, B401310047

B401300030 Forwards "App B, Comparison of Special Lifting Device Design to ANSI N14 6-1978," per 830729 response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants"
BECKHAM, J T Georgia Power Co 84/01/23 STOLZ, J F Operating Reactors Branch 4 15pp 21999 248 24X Fiche 50-321, 84/01/23, B401300030

B401310309 Application to amend License NPF-5, supporting mods associated w/installation of GE analog transmitter trip sys Encl proprietary Rev 1 to NEDE-22154-1, "Analog Trip Sys for Engineered Safeguards Sensor Trip Inputs" withheld
BECKHAM, J T Georgia Power Co. 84/01/23 STOLZ, J F Operating Reactors Branch 4 3pp 22021 001 24X Fiche 50-321, 84/01/23, B401310309

DOCKETED ITEMS

--B401310314 "Proposed Plant Mods To Be Incorporated Into Analog Transmitter Trip Scram Design " GE affidavit for withholding NEDE 22154-1, "Analog Trip Sys for Engineered Safeguard Sensor Trip Inputs," encl
Georgia Power Co 83/08/19 109pp 22021 004 24X
Fiche 50-321,84/01/23,8401310309

B401310123 Forwards description of current criteria for meeting NUREG-0737, Item 11 B 3, "Post-Accident Sampling Capability " Schedule for completing remaining tasks encl Extension until 840601 requested to complete item
GUCHAR, L T Georgia Power Co 84/01/26 STOLZ, J F Operating Reactors Branch 4 21pp 22022 040 24X Fiche 50-321,84/01/26, 8401310123

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTDM, J H Division of Rules and Records 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Troubridge Ip 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060150

B312050488 Responds to concern raised by NRC during site insps on 820302-05 & 14-19 (ref IE Insp Repts 50-321/82-08 & 50-366/82-08) re IE Bulletin 80-08 Problems nonexistent re radiography of flued head penetrations
GUCHAR, L T Georgia Power Co 83/11/18 O'REILLY, J P Region 2, Office of Director 2pp 21381 074 24X Fiche 50-321, 83/11/18, 8312050488

B312070443 Responds to 830812 allegation that NRC lacked legal jurisdiction to issue 830713 notice of violation Notice of violation valid since until improperly disposed of licensed mail by transfer to unauthorized recipient
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/11/25 KELLY, R J Georgia Power Co 3pp 21418 330 24X Fiche 50-321, 83/11/25, 8312070443

B401050621 Forwards IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/09 KELLY, R J Georgia Power Co 2pp 21724 062 24X
Fiche 50-321, 83/12/09, 8401050621

--B401050633 IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted Major areas inspected, plant tours, plant operations review, Tech Spec compliance, physical protection, refueling activity & spent fuel pool activity
MATHIS, J L, KRUG, H Region 2 Office of Director JAFE, F Division of Engineering & Operational Programs, 83/12/04 5pp 21726 064 24X Fiche 50-321, 83/12/09, 8401050633

B401090195 Forwards IE Insp Repts 50-321/83-33 & 50-366/83-35 on 831129-1201 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/16 KELLY, R J Georgia Power Co 2pp 21749 216 24X
Fiche 50-321, 83/12/16, 8401090195

--B401090201 IE Insp Repts 50-321/83-33 & 50-366/83-35 on 831129-1201 No violations noted Major areas inspected nuclear welding, recirculation sys piping replacement & previous insp findings
CROWLEY, B R Region 2, Office of Director, BLAKE, J J Division of Engineering & Operational Programs 83/12/14 8pp 21749 218 24X Fiche 50-321, 83/12/16, 8401090195

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B401060446 Discusses Jan & Feb 1983 revs to radiological emergency plan Revs meet applicable planning stds of 10CFR50
Outstanding issues identified in IE Insp Repts 50-321/83-19 & 50-366/83-19
DANCE, H C Division of Project & Resident Programs 83/12/30 KELLY, R J Georgia Power Co 8pp 21740 089 24X
Fiche 50-321, 83/12/30, 8401060446

B401190411 Informs that inservice insp plan for Unit 1 will be provided to site personnel tentatively by mid-Feb 1984 inservice insp plans for 1984 Unit 2 main recirculation sys piping replacement outage finalized
GUCHAR, L T Georgia Power Co 84/01/09 STOLZ, J F Operating Reactors Branch 4 2pp 21850 093 24X Fiche 50-321, 84/01/09, 8401190411

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

B401240379 Ack receipt of B40106 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/83-30
LEWIS, R C Division of Project & Resident Programs 84/01/13 KELLY, R J Georgia Power Co Ip 21909 149 24X
Fiche 50-321, 84/01/13, 8401240379

--B401240384 Responds to NRC 831208 ltr re violations noted in IE Insp Rept 50-321/83-30 Corrective actions personnel counseled on importance of writing deviation repts in timely manner
New deviation rept procedure written
GUCHAR, L T Georgia Power Co 84/01/06 O'REILLY, J P Region 2, Office of Director 3pp 21907 150 24X Fiche 50-321, 84/01/13, 8401240379

--B401240388 Forwards IE Insp Repts 50-321/83-30 & 50-366/83-32 on 831001-31 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/12/08 KELLY, R J Georgia Power Co 2pp 21909 153 24X
Fiche 50-321, 84/01/13, 8401240379

--B401240391 Notice of violation from insp on 831001-31
Region 2, Office of Director 83/12/08 Ip 21909 155 24X
Fiche 50-321, 84/01/13, 8401240379

--B401240397 IE Insp Repts 50-321/83-30 & 50-366/83-32 on 831001-31 Noncompliance noted failure to establish required fire watches
CLENEN, R V, HOLMES-RAY, P Region 2, Office of Director PANCIERA, V M Division of Project & Resident Programs 83/12/07 4pp 21907 156 24X Fiche 50-321, 84/01/13, 8401240379

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

B401130330 Monthly operating repts for Dec 1983 W/840110 ltr
RAFEEDIE, D P, NIX, H C Georgia Power Co 83/12/31 Director's Office, Office of Inspection and Enforcement 17pp 21801 171 24X
Fiche 50-321, 83/12/31, 8401130330

S Reportable occurrences, LERs & related correspondence

B401030112 LER 83-115/OIT-0 on 831206, AE personnel determined that four sets of reactor water cleanup temp thermocouples inoperable & two other sets inoperable, as installed caused by improper drawings Thermocouple switched W/831216 ltr
TIPPS, B B, NIX, H C Georgia Power Co 83/12/16 O'REILLY, J P Region 2, Office of Director 4pp 21683 162 24X
Fiche 50-321, 83/12/16, 8401030112

DOCKETED ITEMS

8401030193 LER 83-072/03L-O on 831121, during reactor bldg vent radiation & arm sys calibr Procedure HNP-1-3114, control room radiation sensors 241-N0154A & B found out of tolerance Caused by setpoint drift Sensors adjusted W/831216 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/12/16 O'REILLY, J P
Region 2, Office of Director App 21683 075 24X
Fiche 50-321, 83/12/16, 8401030193

8401040168 LER 83-114/03L-O on 831209, surveillance personnel noted that mechanical overspeed trip mechanism for RCIC turbine actuated above rated speed Caused by setpoint drift
Mechanism recalibr W/831222 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director App 21702 012 24X
Fiche 50-321, 83/12/22, 8401040168

8401040334 LER 83-120/03L-O on 831209, during performance of control of transient combustibles (Procedure HNP-599), personnel noted Fire Door IL48-C22 would not close completely Caused by component failure due to normal wear W/831222 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director App 21705 071 24X
Fiche 50-321, 83/12/22, 8401040334

8401040336 LER 83-116/03L-O on 831202, links K96A & N determined open at steam condensing mode flow control valve IE11-F053A Cause unknown Links closed Operation verified W/831222 ltr
TIPPS, S B , NIX, H C Georgia Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director App 21704 349 24X
Fiche 50-321, 83/12/22, 8401040336

8401060311 LER 83-117/03L-O on 831203, while preparing to run diesel generator IC (1R43-S001C), valve IP41-F401B discovered closed. Caused by personnel error Valve repaired W/831230 ltr
TIPPS, S B , NIX, H C Georgia Power Co. 83/12/30 O'REILLY, J P
Region 2, Office of Director App 21739 353 24X
Fiche 50-321, 83/12/30, 8401060311

8401030399 PND-11-84-001 on 840103, bomb threats received at facility Searches revealed no bomb FBI, media & info assessment team notified
MCQUIRE, D R , TDBIN, W J Region 2, Office of Director 84/01/03
lp. 21731 124 24X Fiche 50-321, 84/01/03, 8401030399

8401300259 LER 83-124/03L-O on 831215, transverse in-core probe B detector cable could not be withdrawn Caused by drive cable binding in indexing tube Detector B drive cable & indexing tube section replaced W/840113 ltr
TIPPS, S B , NIX, H C Georgia Power Co 84/01/13 O'REILLY, J P
Region 2, Office of Director App 21998 322 24X
Fiche 50-321, 84/01/13, 8401300259

8401300268 LER 83-113/03L-O on 831220, surveillance personnel noted reactor bldg exhaust vent radiation monitors ID11-K609 A, B & C inoperable. Caused by monitors ID11-K609 A, B & C out of calibr. Monitors recalibr W/840113 ltr
TIPPS, S B , NIX, H C Georgia Power Co 84/01/13 O'REILLY, J P
Region 2, Office of Director App 21995 193 24X
Fiche 50-321, 84/01/13, 8401300268

8401300293 RD 1984-001 on 840103, plant received bomb threat. Appropriate emergency procedure initiated, controlled search begun & unnecessary personnel evacuated. No bomb found
NIX, H C Georgia Power Co 84/01/18 O'REILLY, J P Region 2, Office of Director App 21994 360 24X Fiche 50-321, 84/01/18, 8401300293

8401310393 LER 83-122/03L-O on 831228, during HPCI quick start Procedure HNP-1-3316, HPCI had erratic response & was tripped Caused by failed ramp generator signal converter unit Converter replaced, W/840124 ltr
TIPPS, S B , NIX, H C Georgia Power Co. 84/01/24 O'REILLY, J P
Region 2, Office of Director App 22018 351 24X
Fiche 50-321, 84/01/24, 8401310393

8401310394 LER 83-126/03L-O on 831229, during performance of HPCI steam line pressure instrument FTC procedure, HPCI A, B, C & D switches actuated below requirements Caused by setpoint drift Switches recalibr W/840124 ltr
TIPPS, S B , NIX, H C Georgia Power Co 84/01/24 O'REILLY, J P
Region 2, Office of Director App 22018 001 24X
Fiche 50-321, 84/01/24, 8401310394

V. Operator Examinations

8401060499 Forwards "Power Plant Exam Results Summary Sheet," delineating results of exams administered during wks of 830926 & 1010 Failure rates higher than industry norms
W/s encl

DANKE, H C Division of Project & Resident Programs, 83/12/08
KELLY, R J Georgia Power Co lp 21739 345 24X
Fiche 50-321, 83/12/08, 8401060499

8401240242 Confirms 840103 telcon arrangements for 840111 meeting to discuss significant failure rates on recent reactor operator & instructor certification exams
O'REILLY, J P Region 2, Office of Director 84/01/11 KELLY, R J
Georgia Power Co lp 21920 242 24X Fiche 50-321, 84/01/11, 8401240242

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8401040617 FOIA request for documents made available under B Hafner FOIA Request 83-386, for list of inaccessible sys in containment considered to be safety-related for facility
EARLEY, A F Hunton & Williams 83/10/03 FELTON, J M Division of Rules and Records lp 21714 203 24X Fiche 50-322, 83/10/03, 8401040617

8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831127 ltr re standby diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director For Licensing 19pp 22034 358 24X
Fiche 50-000, 83/12/16, 8312200154

8401050505 Forwards completed NRC facility staffing questionnaire Info provided by telecopy on 831213
SMITH, J L Long Island Lighting Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director App 21726 013 24X
Fiche 50-322, 83/12/21, 8401050505

8312120101 Board Notification 83-187 provides info re possible interaction of main steam lines w/main feedwater at DWRs
Subj being studied on expedited basis Commissioners will be notified when review completed
EISENHUT, D O Division of Licensing 83/12/27 PALLADINO, N , QILINSKY, V , ROBERTS, J Commissioners App 21725 260 24X
Fiche 50-000, 83/12/27, 8312120101

--8312190346 Recommends that board notification be made for listed facilities re potential for interaction of nonseismic feedwater lines w/seismic Category I main steam lines
MATTHEW, R Division of Systems Integration (post 811005)
VOLLMER, R Division of Engineering 83/12/06 EISENHUT, D O Division of Licensing 2pp 21725 266 24X Fiche 50-000, 83/12/27, 8312120101

840110555 Forwards TM Novak 831227 request to Mississippi Power & Light Co for addl info re emergency diesel generators mfg by Transamerica Delaval, Inc Plant-specific answers requested
SCHWENCKER, A Licensing Branch 2 83/12/29 POLLOCK, M B Long Island Lighting Co 3pp 21795 332 24X Fiche 50-322, 83/12/29, 840110555

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification program has position is that NRC environ qualification program has problems
EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Syc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

840110240 Forwards "Shoreham Diesel Generator Recovery Program," & summary Owners of similar diesel generator units in nuclear env have formed owners group
MCCAFFREY, B R , HILLIGAN, M H , YOUNGLING, E J Long Island Lighting Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 21770 237 24X Fiche 50-322, 84/01/06, 840110240

--840110245 "Shoreham Diesel Generator Recovery Program"
MULLER, A R Long Island Lighting Co 83/11/22 935pp
21770 272 24X Fiche 50-322, 84/01/06, 840110240

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Syc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

DOCKETED ITEMS

8401240107 Submits technical guidance & methodology for conducting rebuilt emergency diesel generator overload testing per Rev 1 to Reg Guide 1.106 Preoperational test program must demonstrate full-load-carrying capability
MCCAFFREY, B R Long Island Lighting Co 84/01/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21912 288
24X Fiche 50-322, 84/01/16, 8401240107

8401240388 Forwards "Field Test of Emergency Diesel Generator 101" Data used by Failure Analysis Assoc in investigation of crankshaft failure on diesel generator 102
MCCAFFREY, B R Long Island Lighting Co 84/01/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21916 059
24X Fiche 50-322, 84/01/16, 8401240388

--8401240393 "Field Test of Emergency Diesel Generator 101" BERCEL, E J, HALL, J R Stone & Webster Engineering Corp 83/10/31 167pp 21916 061 24X Fiche 50-322, 84/01/16, 8401240393

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
MANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

E NRC Safety Evaluation Report (SER): supply & correspondence

8401240411 Forwards "List of Active Safety Related Equipment at Qualification Level," per SER Issue B, "Dynamic Qualification" & util 831123 commitment
MCCAFFREY, B R Long Island Lighting Co 84/01/17, DENTON, H R
Office of Nuclear Reactor Regulation, Director 53pp 21918 334
24X Fiche 50-322, 84/01/17, 8401240411

F Security, medical, emergency & fire protection plans

8401090229 "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants" Certificate of Svc encl Related correspondence
* Federal Emergency Management Agency 83/09/30 60pp 21732 135
24X Fiche 50-322, 83/09/30, 8401090229

8401040567 Ack receipt of 831122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-322/83-32
STAROSTECKI, R Division of Project & Resident Programs 83/12/21
POLLOCK, M S Long Island Lighting Co 2pp 21706 305 24X
Fiche 50-322, 83/12/21, 8401040567

--8401040574 Forwards response to NRC 831027 ltr re violations noted in IE Safeguards Insp Rept 50-322/83-32 Corrective actions withheld (ref 10CFR73.21)
POLLOCK, M S Long Island Lighting Co 83/11/22 STAROSTECKI, R
Division of Project & Resident Programs 5pp 21706 307 24X
Fiche 50-322, 83/12/21, 8401040567

8401030332 Releases public version of emergency plan & revised emergency preparedness implementing procedures
FELTON, J M Division of Rules and Records, 83/12/27 Document
Management Branch 1p 21697 318 24X Fiche 50-322, 83/12/27, 8401030332

--8401030337 Forwards public version of emergency plan & revised emergency preparedness implementing procedures, including Procedures EPIP 1-1 re unusual event, EPIP 1-2 re alert & EPIP 1-3 re site area emergency
SMITH, J L Long Island Lighting Co 83/11/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21697 316
24X Fiche 50-322, 83/12/27, 8401030332

--8401030339 Public version of Rev 5 to emergency plan
* Long Island Lighting Co 83/11/30 210pp 21697:318 24X
Fiche 50-322, 83/12/27, 8401030332

--8401030341 Public version of revised emergency preparedness implementing procedures, including Procedures EPIP 1-1 re unusual event, EPIP 1-2 re alert & EPIP 1-3 re site area emergency
* Long Island Lighting Co 83/11/15 700pp 21698 176 24X
Fiche 50-322, 83/12/27, 8401030332

8401040014 Releases public version of revised local offsite radiological emergency response plan & revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records, 83/12/27 Document
Management Branch 1p 21709 001 24X Fiche 50-322, 83/12/27, 8401040014

--8401040015 Forwards public version of Rev 2 to local offsite radiological emergency response plan & Rev 12 to emergency plan implementing procedures
POLLOCK, M S Long Island Lighting Co 83/11/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 21709 002
24X Fiche 50-322, 83/12/27, 8401040014

--8401040018 Public version of Rev 2 to local offsite radiological emergency response plan
* Long Island Lighting Co 83/11/07 311pp 21709 013 24X
Fiche 50-322, 83/12/27, 8401040014

--8401040020 Public version of revised emergency plan implementing procedures, including Procedures OPIP 2 1 1 re position definitions, OPIP 3 3 4 re route alert driver procedure & OPIP 3 5 1 re downwind surveying
* Long Island Lighting Co 83/10/24 512pp 21709 324 24X
Fiche 50-322, 83/12/27, 8401040014

8401050124 Releases public version of revised App A of local offsite radiological emergency response plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 264 24X Fiche 50-322, 83/12/28, 8401050124

--8401050128 Forwards public version of Rev 2 pages to App A of local offsite radiological emergency response plan
POLLOCK, M S Long Island Lighting Co 83/11/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 21743 265
24X Fiche 50-322, 83/12/28, 8401050124

--8401050132 Public version of Rev 2 pages to App A of local offsite radiological emergency response plan
* Long Island Lighting Co 83/10/18 6pp 21743 270 24X
Fiche 50-322, 83/12/28, 8401050124

8401040135 Forwards EL Jordan 831228 ltr to RW Krimm (FEMA) re emergency planning
BORDENICK, B M Hearing Branch 3 83/12/27 LAURENSON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 5pp 21702 071 24X Fiche 50-322, 83/12/27, 8401040135

8401090338 Requests interim relief from provisions of Page 2-3 of fire hazards analysis rept Manual assistance sometimes required to ensure fire damper reopening after closure
MCCAFFREY, B R Long Island Lighting Co 84/01/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21754 107
24X Fiche 50-322, 84/01/04, 8401090338

8401190345 Forwards IE Insp Rept 50-322/83-40 on 831212-15 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/06
POLLOCK, M S Long Island Lighting Co 2pp 21850 322 24X
Fiche 50-322, 84/01/06, 8401190345

--8401190349 IE Insp Rept 50-322/83-40 on 831212-15 No noncompliance noted Major areas inspected, proposed physical security plan, including security organization, locks, key & combinations & training & qualification plan
BAILEY, R J, GDDY, A T Region 1, Office of Director 84/01/06 3pp 21850 324 24X Fiche 50-322, 84/01/06, 8401190345

8401180189 Informs that FEMA has confirmed receipt of revised transition plan & revised NUREG-0694 cross-reference for facility
KRIMM, R W Federal Emergency Management Agency 84/01/13
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21844 081 24X Fiche 50-322, 84/01/13, 8401180189

8401250244 Forwards IE 840111 memo to FEMA responding to FEMA 831222 ltr outlining conditions for expedited review of Revs 2 & 3 to util transition plan
BORDENICK, B M Hearing Branch 3 84/01/16 LAURENSON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 6pp 21941 342 24X Fiche 50-322, 84/01/16, 8401250244

8401250147 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21982 230 24X Fiche 50-322, 84/01/20, 8401250147

--8401250151 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1-6 re evacuations, EPIP 1-7 re personnel accountability & EPIP 1-15 re security during emergencies
SMITH, J L Long Island Lighting Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21982 232
24X Fiche 50-322, 84/01/20, 8401250147

DOCKETED ITEMS

16

--B401250155 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1-6 re evacuations, EPIP 1-7 re personnel accountability & EPIP 1-15 re security during emergencies
* Long Island Lighting Co 83/12/07 66pp 21982 234 24X Fiche 50-322,84/01/20,8401250147

O Adjudicatory correspondence

B401050229 "Std Guide for Evaluation of Alert & Notification Sys for Nuclear Power Plants " Certificate of Svc encl Related correspondence
* Federal Emergency Management Agency 83/09/30 60pp 21732 135 24X Fiche 50-322,83/09/30,8401050229

B401090359 Requests prompt distribution of collated LILCO transition plan to regional assistance committee members by B40103 & forwards suggested matrix for util identification of page changes affected by each rev Certificate of Svc encl
KRIMM, R W Federal Emergency Management Agency 83/12/22
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 21754 066 24X Fiche 50-322,83/12/22, B401090359

B401030148 Request for ASLB reconsideration of emergency planning schedule Date for submission of revised Group II contentions should be pacing item for Group II summary disposition motions & testimony Certificate of Svc encl
LETSCHE, K Suffolk County, NY LETSCHE, K Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/12/28 Atomic Safety and Licensing Board Panel 11pp 21683 210 24X Fiche 50-322,83/12/28, B401030148

B401040135 Forwards EL Jordan B31228 ltr to RW Krimm (FEMA) re emergency planning
BORDENICK, B M Hearing Branch 3 83/12/29 LAURENSEN, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 5pp 21702 071 24X Fiche 50-322,83/12/29,8401040135

B401050202 Reply to Suffolk County B31228 request for ASLB reconsideration of emergency planning schedule Schedule for litigation of Group II issues should be extended Certificate of Svc encl
DOUGHERTY, J B Shoreham Opponents Coalition 83/12/29 Atomic Safety and Licensing Board Panel 3pp 21727 244 24X Fiche 50-322,83/12/29,8401050202

B401050231 Requests that ASLB schedule conference of parties, at earliest convenience, in light of filings on util request to set schedule
EARLEY, A E Hunton & Williams EARLEY, A E Long Island Lighting Co 83/12/29 BRENNER, L Atomic Safety and Licensing Board Panel 1p 21728 272 24X Fiche 50-322,83/12/29,8401050231

B401050320 Preliminary response to Suffolk County B31228 request for ASLB reconsideration of emergency planning schedule re conference deemed warranted, B31230 meeting date recommended
IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams 83/12/29 Atomic Safety and Licensing Board Panel 1p 21726-359 24X Fiche 50-322,83/12/29,8401050320

B401060370 Affidavit of DO Bridenbaugh on Suffolk County Contention II re passive mechanical valve failure Certificate of Svc encl
BRIDENBAUGH, D MHB Technical Associates 83/12/29 11pp 21741 098 24X Fiche 50-322,83/12/29,8401060370

B401040132 Forwards affidavit of R Caruso in response to LILCO B31128 response to ASLB order contained in partial initial decision re detection of passive mechanical valve failures W/o encl
REPKA, D A Hearing Branch 3 83/12/30 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 21702 069 24X Fiche 50-322,83/12/30,8401040132

B401060386 Joint motion for adjustment of schedule for remaining litigation of emergency planning issues due to filing of Rev 3 to emergency plan Certificate of Svc encl
IRWIN, D P Long Island Lighting Co LANPHER, L C Suffolk County, NY 84/01/03 Atomic Safety and Licensing Board Panel 7pp 21741:113 24X Fiche 50-322,84/01/03,8401060386

B401060276 Order confirming schedule for supplemental diesel generator contentions
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/04 2pp 21741:179 24X Fiche 50-322,84/01/04,8401060276

B401060362 Requests that GC Crotty & B Wiles be added to emergency planning svc list LL Swartz should be deleted from svc list
LAURENSEN, J A Atomic Safety and Licensing Board Panel 84/01/04 Docketing & Services Branch 1p 21741 109 24X Fiche: 50-322,84/01/04,8401060362

B401100147 Notice of appearance in proceeding
FALZONE, R R Long Island Lighting Co FALZONE, R R Hunton & Williams 84/01/04 1p 21759 361 24X Fiche 50-322,84/01/04, B401100147

B401090271 Order directing continued effort to resolve & further consider check valve testing & RHR loads issues Joint repts will be discussed at B40222 conference
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/05 Long Island Lighting Co 3pp 21754 225 24X Fiche 50-322,84/01/05,8401090271

B401100153 Informs that facility will be physically ready to load fuel in Mar 1984 Litigation on diesel generators will not be completed before Summer 1984 Util will do everything to expedite process
REVELEY, W T Harmon & Weiss REVELEY, W T Long Island Lighting Co 84/01/05 BRENNER, L, FERGUSON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 21760 209 24X Fiche 50-322,84/01/05, B401100153

B401100206 Motion to strike listed ref in Suffolk County B31223 brief Incorporation by ref impermissible Certificate of Svc encl
REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams 84/01/05 Atomic Safety and Licensing Appeal Panel 6pp 21760 210 24X Fiche 50-322,84/01/05,8401100206

B401100144 Order directing Suffolk County to respond by B40112 to applicant motion to strike portions of county brief supporting exceptions to ASLB B30921 partial initial decision
TOMPkins, B A Atomic Safety and Licensing Appeal Panel 84/01/06 Suffolk County, NY 2pp 21760 031 24X Fiche 50-322,84/01/06, B401100144

B401120311 Informs that LILCO reft on diesel generator recovery program sent under separate cover to Judges Morris & Ferguson, MRC & Suffolk County
EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 84/01/09 BRENNER, L Atomic Safety and Licensing Board Panel 1p 21792 140 24X Fiche 50-322,84/01/09,8401120311

B401160212 Request for leave to file out of time motion to strike LJ Campa testimony on Contentions 25 C & 25 D re role conflict & effect on early dismissals from schools Certificate of Svc encl
MCCLLESKEY, E B Long Island Lighting Co MCCLLESKEY, E B Hunton & Williams 84/01/11 Atomic Safety and Licensing Board Panel 25pp 21815 118 24X Fiche 50-322,84/01/11,8401160212

B401160244 Response opposing LILCO B40105 motion to strike certain refs in brief Refs do not constitute improper attempt to incorporate portions of earlier briefs Certificate of Svc encl
OILMARTIN, D J Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/11 Atomic Safety and Licensing Appeal Panel 10pp 21814 182 24X Fiche 50-322,84/01/11,8401160244

B401130112 Order denying applicant motion to strike certain refs in Suffolk County brief & accepting Suffolk County amendments to brief
SHENMAKER, C J Atomic Safety and Licensing Appeal Panel 84/01/12 Long Island Lighting Co 1p 21802 344 24X Fiche 50-322,84/01/12,8401130112

B401170229 Notice of appearance in proceeding Certificate of Svc encl
SCHEIDT, D J Suffolk County, NY SCHEIDT, D J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/12 4pp 21833 324 24X Fiche 50-322,84/01/12,8401170229

B401170276 Proposed emergency planning contentions modified to reflect Rev 3 of LILCO transition plan
* Suffolk County, NY * Shoreham Opponents Coalition * North Shore Committee Against Nuclear & Thermal Pollution 84/01/12 Atomic Safety and Licensing Board Panel 242pp 21830 001 24X Fiche 50-322,84/01/12,8401170276

--B401170278 Memorandum explaining format & reasons for proposed modified emergency planning contentions Certificate of Svc encl
LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/12 32pp 21830 211 24X Fiche 50-322,84/01/12,8401170278

B401250250 Response supporting w/mods LILCO motion to strike certain refs in Suffolk County brief in support of exceptions to ASLB B30921 partial initial decision Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 84/01/12 Atomic Safety and Licensing Appeal Panel 6pp 21944 124 24X Fiche 50-322,84/01/12, B401250250

DOCKETED ITEMS

B401170150 Forwards notice of appearance for FG Palomino for B40117 hearing on emergency preparedness Certificate of Svc encl CUOMO, M M New York, State of 84/01/13 LAURENSEN, J A Atomic Safety and Licensing Board Panel 4pp 21833 333 24X Fiche 50-322, 84/01/13, B401170150

B401180198 Responds to counsel comments at B40104 conference re State of NY intended participation in emergency planning proceeding Special Counsel, FG Palomino, will represent Governor at resumed B40117 hearings CUOMO, M M New York, State of 84/01/13 LAURENSEN, J A Atomic Safety and Licensing Board Panel 1p 21841 318 24X Fiche 50-322, 84/01/13, B401180198

B401180206 Order denying motion to strike portions of inspector RC Roberts, et al, testimony on Contentions 65 & 23 H & granting in part, motion to strike portions of Suffolk County testimony on traffic issues as incompetent LAURENSEN, J A Atomic Safety and Licensing Board Panel 84/01/16 Long Island Lighting Co 13pp 21844 152 24X Fiche 50-322, 84/01/16, B401180206

B401180269 Amended direct testimony of RC Roberts, JL Monteith, P McGuire, MJ Turano & J Michel on emergency planning Contentions 65 & 23 H re evacuation time estimates & emergency planning zone access control ROBERTS, R C, MONTEITH, J L, MCGUIRE, P Suffolk County, NY 84/01/16 239pp 21843 001 24X Fiche 50-322, 84/01/16, B401180269

--B401180288 Motion for leave to file listed amended & supplemental testimony on certain Group I issues Certificate of Svc encl LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/16 Atomic Safety and Licensing Board Panel 26pp 21843 214 24X Fiche 50-322, 84/01/16, B401180288

B401190167 Motion to admit supplemental testimony of MC Cordaro, JA Weismantle & EB Lieberman on Phase II emergency planning Contentions 23 D & 65 for good cause IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams 84/01/16 Atomic Safety and Licensing Board Panel 7pp 21850 209 24X Fiche 50-322, 84/01/16, B401190167

--B401190170 Supplemental testimony of MC Cordaro, JA Weismantle & EB Lieberman on Phase II emergency planning Contentions 23 D & 65 Certificate of Svc encl CORDARO, M C, WEISMANTLE, J A, LIEBERMAN, E B Long Island Lighting Co 84/01/16 71pp 21850 216 24X Fiche 50-322, 84/01/16, B401190170

B401190180 Status rept on automatic depressurization sys logic mod Engineering & matl procurement on schedule & mod implementation will be completed prior to fuel load Certificate of Svc encl EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 84/01/16 4pp 21851 287 24X Fiche 50-322, 84/01/16, B401190180

B401190185 Designation of listed contentions for summary disposition On B40112 intervenors filed proposed emergency planning contentions, modified to reflect Rev 3 of LILCO plan Certificate of Svc encl MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/01/16 4pp 21851 291 24X Fiche 50-322, 84/01/16, B401190185

B401200132 Response opposing applicant request for leave to file, out of time, motion to strike LJ Campa B31118 testimony on Contentions 25 C & 25 D Motion contains no showing of good cause Certificate of Svc encl LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/16 Atomic Safety and Licensing Board Panel 10pp 21865 285 24X Fiche 50-322, 84/01/16, B401200132

B401250244 Forwards IE B40111 memo to FEMA responding to FEMA B31222 ltr outlining conditions for expedited review of Revs 2 & 3 to util transition plan BORDENICK, B M Hearing Branch 3 84/01/16 LAURENSEN, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 6pp 21941 342 24X Fiche 50-322, 84/01/16, B401250244

B401240289 Designation of contentions involving DOE as to which county reserves right to file for summary disposition Certificate of Svc encl BIRKENHEIER, J Suffolk County, NY BIRKENHEIER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/17 4pp 21909 266 24X Fiche 50-322, 84/01/17, B401240289

B401260184 Forwards amended designation of contentions involving DOE as to which county reserves right to file for summary disposition Second page inadvertently omitted from original submittal Related correspondence BIRKENHEIER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips BIRKENHEIER, J Suffolk County, NY 84/01/17 LAURENSEN, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 1p 21956 107 24X Fiche 50-322, 84/01/17, B401260184

--B401260189 Amended designation of contentions involving DOE as to which county reserves right to file for summary disposition Certificate of Svc encl BIRKENHEIER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips BIRKENHEIER, J Suffolk County, NY 84/01/17 5pp 21956 108 24X Fiche 50-322, 84/01/17, B401260189

B401240249 Objections to Suffolk County B40112 proposed emergency planning contentions modified to reflect Rev 3 of county transition plan Certificate of Svc encl MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/01/19 Atomic Safety and Licensing Board Panel 28pp 21910 146 24X Fiche 50-322, 84/01/19, B401240249

B401250167 Advises that future documents served on Suffolk County atty should be sent to listed address Related correspondence BIRKENHEIER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips BIRKENHEIER, J Suffolk County, NY 84/01/19 NRC - No Detailed Affiliation Given 1p 21938 189 24X Fiche 50-322, 84/01/19, B401250167

B401250360 Objections to Suffolk County B40112 revised emergency planning Contentions 15 E & 66 D Contentions should stand as previously admitted Certificate of Svc encl REPKA, D A Hearing Branch 3 84/01/19 Atomic Safety and Licensing Board Panel 7pp 21943 188 24X Fiche 50-322, 84/01/19, B401250360

B401240305 Amended order, granting in part & denying in part, NRC & applicant B31128 motions to strike certain portions of SC Saegert direct testimony submitted by Suffolk County LAURENSEN, J A Atomic Safety and Licensing Board Panel 84/01/23 Long Island Lighting Co 13pp 21909 246 24X Fiche 50-322, 84/01/23, B401240305

B401310140 Notice of appearance in proceeding Certificate of Svc encl ZAHNLEUTER, R J New York, State of 84/01/25 4pp 22022 072 24X Fiche 50-322, 84/01/25, B401310140

B401310305 Proposal for resolving legal authority issues of Contention 1-10 Contentions should be decided by ASLB not state court Legal authority issues should be addressed in Group II Findings Certificate of Svc encl CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams 84/01/26 9pp 22018 116 24X Fiche 50-322, 84/01/26, B401310305

B401310284 Motion to admit supplemental diesel generator contentions re reliability & adequacy Unexecuted affidavits of SO Christensen & GD Eley encl DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/27 Atomic Safety and Licensing Board Panel 70pp 22014 222 24X Fiche 50-322, 84/01/27, B401310284

--B401310285 Addendum to motion to admit supplemental diesel generator contentions Certificate of Svc encl DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/01/27 Atomic Safety and Licensing Board Panel 91pp 22014 322 24X Fiche 50-322, 84/01/27, B401310285

H General correspondence

B401120339 Notifies that BR McCaffrey has assumed responsibilities for regulatory compliance matters, effective B40103 MUEHLER, W J Long Island Lighting Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21792 023 24X Fiche 50-322, 84/01/05, B401120339

P Operating license stage documents & correspondence

B401050382 Generic ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

DOCKETED ITEMS

16

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401030259 Forwards IE Insp Rept 50-322/83-39 on 831205-09 No violations noted Allegations re concrete voids & drywell floor rebar unsubstantiated
STAROSTECKI, R Division of Project & Resident Programs 83/12/14 POLLOCK, M S Long Island Lighting Co 2pp 21680 305 24X
Fiche 50-322, 83/12/14, 8401030259

--8401030262 IE Insp Rept 50-322/83-39 on 831205-09 No noncompliance noted Major areas inspected voids in reactor vessel pedestal & drywell floor concrete, improper installation of backing rings & inadequate insp by equipment suppliers
BATEMAN, W H, MCCABE, E C Region 1, Office of Director 83/12/14 13pp 21680 307 24X Fiche 50-322, 83/12/14, 8401030259

8401030269 Forwards IE Insp Rept 50-322/83-35 on 831017-1127 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 83/12/14 POLLOCK, M S Long Island Lighting Co 15pp 21681 176 24X
Fiche 50-322, 83/12/14, 8401030269

--8401030273 IE Insp Rept 50-322/83-35 on 831017-1127 No violations noted Major areas inspected emergency diesel crankshaft failures, circuit breaker latch failures, simulator training exams & TMI action items
PETRONE, C, SHEDLOSKEY, J T Region 1, Office of Director MCCABE, E C Division of Project & Resident Programs 83/12/12 13pp 21681 178 24X Fiche 50-322, 83/12/14, 8401030269

8401040369 Ack receipt of 831122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-322/83-32
STAROSTECKI, R Division of Project & Resident Programs 83/12/21 POLLOCK, M S Long Island Lighting Co 2pp 21706 305 24X
Fiche 50-322, 83/12/21, 8401040369

--8401040574 Forwards response to NRC 831027 ltr re violations noted in IE Safeguards Insp Rept 50-322/83-32 Corrective actions withheld (ref 10CFR73.21)
POLLOCK, M S Long Island Lighting Co 83/11/22 STAROSTECKI, R Division of Project & Resident Programs 5pp 21706 307 24X
Fiche 50-322, 83/12/21, 8401040369

8401100322 Forwards IE Insp Rept 50-322/83-34 on 831115-18 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 83/12/21 POLLOCK, M S Long Island Lighting Co 2pp 21762 128 24X
Fiche 50-322, 83/12/21, 8401100322

--8401100331 IE Insp Rept 50-322/83-34 on 831115-18 No violations noted Major areas inspected allegations re design methods & adequacy, design change process as applied to hangers & supports & suspected deliberate damage to instrumentation
KELLY, E H, MCCABE, E C Region 1, Office of Director 83/12/20 22pp, 21762.130 24X Fiche 50-322, 83/12/21, 8401100322

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp, 21731:166 24X Fiche 50-000, 83/12/28, 8312120090.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401180214 Forwards IE Insp Rept 50-322/83-27 on 831031-1104 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/01/05 POLLOCK, M S Long Island Lighting Co 2pp 21844 198 24X
Fiche 50-322, 84/01/05, 8401180214

--8401180218 IE Insp Rept 50-322/83-27 on 831031-1104 No violations observed Major areas inspected licensee action on previous insp findings, preoperational test program, including test program status & implementation & test procedures
NICHOLS, H H, BETTENHAUSEN, L Region 1, Office of Director 84/01/04 11pp 21844 200 24X Fiche 50-322, 84/01/05, 8401180214

8401190345 Forwards IE Insp Rept 50-322/83-40 on 831212-15 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/06 POLLOCK, M S Long Island Lighting Co 2pp 21850 322 24X
Fiche 50-322, 84/01/06, 8401190345

--8401190349 IE Insp Rept 50-322/83-40 on 831212-15 No noncompliance noted Major areas inspected proposed physical security plan, including security organization, locks, key & combinations & training & qualification plan
BAILEY, R J, GODY, A T Region 1, Office of Director 84/01/06 3pp 21850 324 24X Fiche 50-322, 84/01/06, 8401190345

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generator
CARUSO, R Licensing Branch 2 84/01/17 SCHWENGER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

S Reportable occurrences, LERs & related correspondence

8401030239 Final deficiency rept re matl in connecting rod bearings Initially reported on 831014 Failure Analysis Assoc rept analyzing replacement connecting rod bearings & fatigue life prediction encl
SMITH, J L Long Island Lighting Co 83/12/16 MURLEY, T E Region 1, Office of Director 3pp 21680 329 24X Fiche 50-322, 83/12/16, 8401030239

--8401030243 "Analysis of Replacement Connecting Rod Bearings Emergency Diesel Generators, Fatigue Life Prediction, Shoreham Nuclear Power Station"
* Failure Analysis Associates FAAN-83-12-7 83/12/15 11pp 21680 333 24X Fiche 50-322, 83/12/16, 8401030239

8401030318 PNO-I-84-001 on 831230, emergency diesel generator 101 shut down manually due to loud noise Insp revealed rocker arm hold down bolts on cylinder subcover had come loose, causing rocker arm assembly to strike other components
KELLY, E, PETRONE, C, ESELGROTH, P Region 1, Office of Director 84/01/03 1p 21726 358 24X Fiche 50-322, 84/01/03, 8401030318

8401190389 PNO-I-84-001A on 831230, emergency diesel generator 101 rocker arm hold-down bolts on cylinder 3 failed Caused by unterqued bolts during preassembly procedure Assembly procedures reviewed & subcovers to be replaced by 840104
KELLY, E, PETRONE, C, ESELGROTH, P Region 1, Office of Director 84/01/04 1p 21849 321 24X Fiche 50-322, 84/01/04, 8401190389

DOCKETED ITEMS

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utilis notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X
Fiche 50-000, 84/01/09, 8401170186

T Hearing transcripts on non-antitrust matters

8401100195 Transcript of 840104 conference of counsel in Washington, DC Pg 2, 195-2, 232
* Atomic Safety and Licensing Board Panel 84/01/04 47pp
21760 267 24X Fiche 50-322, 84/01/04, 8401100195

8401180269 Amended direct testimony of RC Roberts, JL Monteith, P McGuire, MJ Turano & J Michel on emergency planning
Contentions 65 & 23 H re evacuation time estimates & emergency planning time access control
ROBERTS, R C, MONTEITH, J L, MCGUIRE, P Suffolk County, NY 84/01/16 239pp 21843 001 24X Fiche 50-322, 84/01/16, 8401180269

--8401180274 Supplemental direct testimony of G Jeffers & AR Rossi re Contentions 25 C & 25 D
JEFFERS, G, ROSSI, A R Suffolk County, NY 84/01/16 5pp
21843 193 24X Fiche 50-322, 84/01/16, 8401180269

--8401180277 Supplemental direct testimony of RW Petrillat on Contentions 25 C & 25 D re role conflict
PETRILLAT, R W Suffolk County, NY 84/01/16 4pp 21843 190
24X Fiche 50-322, 84/01/16, 8401180269

--8401180281 Supplemental direct testimony of LJ Campo on emergency planning Contentions 25 C & 25 D re role conflict addressed in Rev 3 of LILCO plan
CAMP, L J Suffolk County, NY 84/01/16 6pp 21843 194 24X
Fiche 50-322, 84/01/16, 8401180269

--8401180284 Supplemental direct testimony of BW Pigozzi on Contention 65 re evacuation time estimates
PIGOZZI, B W Suffolk County, NY 84/01/16 14pp 21843 200
24X Fiche 50-322, 84/01/16, 8401180269

--8401180288 Motion for leave to file listed amended & supplemental testimony on certain Group 1 issues Certificate of Svc encl
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hall, Christopher & Phillips 84/01/16 Atomic Safety and Licensing Board Panel 26pp 21843 214 24X
Fiche 50-322, 84/01/16, 8401180269

8401190167 Motion to admit supplemental testimony of MC Cordaro, JA Weismantle & ED Lieberman on Phase II emergency planning
Contentions 23 D & 65 for good cause
IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams 84/01/16 Atomic Safety and Licensing Board Panel 7pp
21850 209 24X Fiche 50-322, 84/01/16, 8401190167

--8401190170 Supplemental testimony of MC Cordaro, JA Weismantle & ED Lieberman on Phase II emergency planning Contentions 23 D & 65 Certificate of Svc encl
CORDARO, M C, WEISMANTLE, J A, LIEBERMAN, E B Long Island Lighting Co 84/01/16 71pp 21850 216 24X Fiche 50-322, 84/01/16, 8401190167

8401200099 Supplemental direct testimony of NJ Muto & JT Smith on Contention 25 re role conflict addressed in Rev 3 to LILCO emergency plan Certificate of Svc encl
MUTO, N J, SMITH, J T Suffolk County, NY 84/01/17 6pp
21866 343 24X Fiche 50-322, 84/01/17, 8401200099

8401240279 Transcript of 840117 emergency planning hearing in Riverhead, NY Pg 2, 233-2, 392 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/17 673pp
21906 001 24X Fiche 50-322, 84/01/17, 8401240279

8401230036 Transcript of 840118 hearing in Riverhead, NY Pg 2, 393-2, 545
* Atomic Safety and Licensing Board Panel 84/01/18 152pp
21885 021 24X Fiche 50-322, 84/01/18, 8401230036

8401240383 Transcript of 840119 emergency planning hearing in Riverhead, NY Pg 2, 546-2, 771
* Atomic Safety and Licensing Board Panel 84/01/19 229pp
21916 231 24X Fiche 50-322, 84/01/19, 8401240383

8401240416 Transcript of 840120 emergency planning hearing in Riverhead, NY Pg 2, 772-2, 894 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/20 484pp
21918 196 24X Fiche 50-322, 84/01/20, 8401240416

8401270408 Transcript of 840124 hearing in Riverhead, NY Pg 2, 895-3, 068
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/24 437pp
21974 001 24X Fiche 50-322, 84/01/24, 8401270408

8401300204 Transcript of 840125 emergency planning hearing in Riverhead, NY Pg 3, 069-3, 284 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/25 296pp
21977 001 24X Fiche 50-322, 84/01/25, 8401300204

8401310253 Transcript of 840126 hearing in Riverhead, NY Pg 3, 285-3, 504
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/26 295pp
22019 001 24X Fiche 50-322, 84/01/26, 8401310253

8401310001 Transcript of 840127 hearing in Riverhead, NY Pg 3, 505-3, 676
* Atomic Safety and Licensing Board Panel 84/01/27 175pp
22024 250 24X Fiche 50-322, 84/01/27, 8401310001

U Congressional/Executive Correspondence

8401110176 Forwards constituent R Giallorenzo B30829 ltr re transportation problems on Route 25A in Suffolk County which would result in event of evacuation of area around facility
Comments should be included in record of proceeding
CARNEY, W House of Rep 84/01/04 LAURENSEN, J A Atomic Safety and Licensing Board Panel 3pp 21772 310 24X
Fiche 50-322, 84/01/04, 8401110176

V Operator Examinations

8401240548 Forwards operator licensing exam schedule through May 1987, in response to Generic Ltr B3-40
MCCAFFREY, B R Long Island Lighting Co 84/01/16 DECKHAM, D NRC - No Detailed Affiliation Given 3pp 21907 329 24X
Fiche 50-322, 84/01/16, 8401240548

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies.
Supporting ltrs encl
CALEDOYAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, 83/10/10, 8401050027

8401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015

--8203120423 Recommends approval of proposed AD determination re seismic design errors Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations SECY-82-081 82/02/25 81pp 21961 065 24X
Fiche 50-000, 83/10/18, 8401250015

--8204220364 Recommends that Commission accept Fitzgerald & Rothchild conclusions re employment of Newark to work on matters re facility
BICKWIT, L Office of the General Counsel SECY-82-152 82/04/12 4pp 21962 319 24X Fiche 50-000, 83/10/18, 8401250015

--8209160068 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations SECY-82-352 82/08/20 37pp 21966 035 24X
Fiche 50-000, 83/10/18, 8401250015

8401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies NRC has no records subj to request Utilis not required to submit insurance rating to NRC
FELTON, J M Division of Rules and Records 83/10/25 CALEDOYAS, C D Affiliation Unknown 1p 21736 236 24X Fiche 50-000, 83/10/25, 8401050043

8401040567 Forwards rev to proposed change to FAR Chapter 17 re QA organization Submittal incorporates comments made during B31025 meeting w/NRC Class III Fee for review encl
SCHUYLER, J O Pacific Gas & Electric Co 83/12/02 MARTIN, J B Region 5, Office of Director 51pp 21714 102 24X
Fiche 50-275, 83/12/02, 8401040567

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21973 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21937 267 24X Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8312120125 Board Notification 84-009 Forwards info re H Hudson, former vendor GA inspector, 831114 allegations concerning deviations from Pullman Power Products weld procedures & major breakdowns in util contract specs & GA programs
EISENHUT, D O Division of Licensing 84/01/16 PALLADINO, N J, GILINSKY, V, ROBERTS, T Commissioners 3pp 21940 229 24X Fiche 50-275, 84/01/16, 8312120125

--8401250217 Alleges deviations from Pullman Power Products weld procedure codes & util contract spec GA & welding requirements at facilities Related info encl
HUDSON, H Affiliation Unknown 83/11/14 GILINSKY, V Commissioners 264pp 21940 232 24X Fiche 50-275, 84/01/16, 8312120125

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crisis & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

8401240134 Provides Westinghouse Owners Group revised completion schedules for resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps." Revised emergency response guidelines will be completed by 830731
SCHUYLER, J O Pacific Gas & Electric Co 84/01/19 EISENHUT, D O Division of Licensing 2pp 21910 291 24X Fiche 50-275, 84/01/19, 8401240134

8401260192 Forwards addl info re performance testing of relief & safety valves per NUREG-0737, Item II D 1, "Relief & Safety Valves"
SCHUYLER, J O Pacific Gas & Electric Co 84/01/23 KNIGHTON, O W Licensing Branch 3 16pp 21936 167 24X Fiche 50-275, 84/01/23, 8401260192

E NRC Safety Evaluation Report (SER), supplc & correspondence

8401090163 Forwards SSER 20 final draft re items to be resolved prior to Step 2 (criticality & low power testing). Concurrence requested w/o encl
EISENHUT, D O Division of Licensing 83/12/22 MATTSON, R Division of Systems Integration (post 811005) VOLLMER, R Division of Engineering 1p 21757 216 24X Fiche 50-275, 83/12/22, 8401090163

8312120095 Board Notification 83-192, forwards EDO 831223 memo & SSER 20 (NUREG-0675) re authorization for criticality & low power testing
EISENHUT, D O Division of Licensing 83/12/29 Atomic Safety and Licensing Appeal Panel, 2pp 21740 272 24X Fiche: 50-275, 83/12/29, 8312120095

--8401030397 Forwards SSER 20 on criticality/low power authorization re design verification program issues flowing from IDVP/ITP requiring satisfactory resolution resolved
DICKS, W Office of the Executive Director for Operations, 83/12/23 PALLADINO, N C Commissioners, 61pp 21740 274 24X Fiche 50-275, 83/12/29, 8312120095

8401170143 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 AND 50-323 (Pacific Gas and Electric Company)
* Division of Licensing NUREG-0675 S21 83/12/31 275pp Available at NRC \$7 00 21839 001 24X Fiche 50-275, 83/12/31, 8401170143

8401260071 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 AND 50-323 (Pacific Gas and Electric Company)
* Division of Licensing NUREG-0675 S20 83/12/31 30pp 21971 198 24X Fiche 50-275, 83/12/31, 8401260071

8401190144 Forwards SSER 20 (NUREG-0676) w/o encl
KNIGHTON, O W Licensing Branch 3 84/01/04 SCHUYLER, J O Pacific Gas & Electric Co 4pp 21871 006 24X Fiche 50-275, 84/01/04, 8401190144

8401250486 Forwards SSER 21 (NUREG-0675) Suppl provides info on status of staff review of allegations & concerns about design, const & operation w/o encl
KNIGHTON, O W Licensing Branch 3 84/01/11 SCHUYLER, J O Pacific Gas & Electric Co 4pp 21948 347 24X Fiche 50-275, 84/01/11, 8401250486

8401260218 Provides basis for not plugging Row 1 steam generator tubes, in response to SSER 9 open item Observed leakage rates low & stable Tubes will leak rather than burst
SCHUYLER, J O Pacific Gas & Electric Co 84/01/23 EISENHUT, D O Division of Licensing 4pp 21956 260 24X Fiche 50-275, 84/01/23, 8401260218

F Security, medical, emergency & fire protection plans

8401240410 Forwards Attachments A, B & C to Rev 11 to security plan Attachments withheld (ref 10CFR73 21)
SCHUYLER, J O Pacific Gas & Electric Co 84/01/11 MARTIN, J B Region 5, Office of Director 1p 21920 139 24X Fiche 50-275, 84/01/11, 8401240410

8401240134 Provides Westinghouse Owners Group revised completion schedules for resolution of TMI Action Item II K 3 S, "Automatic Trip of Reactor Coolant Pumps." Revised emergency response guidelines will be completed by 830731
SCHUYLER, J O Pacific Gas & Electric Co 84/01/19 EISENHUT, D O Division of Licensing 2pp 21910 291 24X Fiche 50-275, 84/01/19, 8401240134

G Adjudicatory correspondence

8401040205 Advises that util asserted failure to disclose 1977 NSC audit rept of Pullman Power Products being considered as petition for enforcement action, per ALAB-736 request
CHANDLER, L J Hearing Branch 2 83/12/29 MOORE, T S, DUCK, J H, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 2pp 21701 204 24X Fiche 50-275, 83/12/29, 8401040205

8401050221 Errata to 831223 proposed findings of fact & conclusions of law re design GA Certificate of Svc encl
HAVIAN, E R Joint Intervenor - Diablo Canyon HAVIAN, E R Center for Law in the Public Interest 83/12/27 4pp 21728 185 24X Fiche 50-275, 83/12/29, 8401050221

8401100137 Response to Joint Intervenor's & Governor Dukmejian 831223 proposed findings of fact & conclusions of law re design GA Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 84/01/04 43pp 21761 077 24X Fiche 50-275, 84/01/04, 8401100137

8401120286 Proposed findings of fact & conclusions of law authorizing issuance of full-power OLs for Units 1 & 2 & extending License DPR-76 per 820803 & 830817 requests Certificate of Svc encl
MCORREIN, H J Hearing Branch 1 CHANDLER, L J Hearing Branch 2 84/01/04 73pp 21793 001 24X Fiche 50-275, 84/01/04, 8401120286

8401100159 Requests Commission 840117 briefing on concerns requiring further review prior to NRC recommendation re low power licensing be rescheduled after House Subcommittee 840124 hearing
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor - Diablo Canyon 84/01/06 PALLADINO, N, GILINSKY, V, ROBERTS, T Commissioners 2pp 21740 361 24X Fiche: 50-275, 84/01/06, 8401100159

DOCKETED ITEMS

840110183 Forwards errata to SECY-84-001, "Mod of Commission Memorandum & Order re Operation of Diablo Canyon Nuclear Power Plant," consisting of Encl 1, inadvertently omitted from original submittal
CHILK, S J Office of the Secretary of the Commission 84/01/09
PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 1p
21772 338 24X Fiche 50-275, 84/01/09, 840110183

8401160204 Petition for Commission review of ALAB-756 & for reversal of ASLAB denial of motion to reopen record re const QA Certificate of Svc encl
REYNOLDS, J R Joint Intervenor - Diablo Canyon REYNOLDS, J R
Center for Law in the Public Interest 84/01/09 Commissioners
22pp 21815 143 24X Fiche 50-275, 84/01/09, 8401160204

8401170249 Petition for Commission review of ALAB-756 re denial of Governor Deukmejian motion to reopen record on const QA issue Certificate of Svc encl
STRUMWASSER, M California, State of 84/01/09 Commissioners
19pp 21832 226 24X Fiche 50-275, 84/01/09, 8401170249

8401160242 Confirms 840109 telcon wherein NRC extended deadline for filing petition re review of ALAB-756 until 840111
VAN DE KAMP, J, STRUMWASSER, M California, State of 84/01/10
CHILK, S J Atomic Safety and Licensing Appeal Panel 1p
21814 096 24X Fiche 50-275, 84/01/10, 8401160242

8401180235 Requests NRC complete three listed steps to determine validity of allegations re potential safety problems before authorizing plant operation
O'CONNELL, J California, State of 84/01/11 PALLADINO, N
Commissioners 2pp 21844 096 24X Fiche 50-275, 84/01/11, 8401180235

8401180187 Comments on Commission consideration of low power license investigation of all allegations re poor const, safety & QC recommended
HART, G K California, State of 84/01/12 PALLADINO, N
Commissioners 2pp 21840 348 24X Fiche 50-275, 84/01/12, 8401180187

8401180210 Recommends authorization of NRC investigation of QA/QC breakdown, independent audit of design review & independent comprehensive QA reinsp of all safety-related hardware
CHACON, P R California, State of 84/01/12 PALLADINO, N
Commissioners 2pp 21842 361 24X Fiche 50-275, 84/01/12, 8401180210

8401170243 Advises that Governor Deukmejian supports until request for authority to operate at Modes 3 & 4 No safety hazards presented by precriticality operation Testing can provide valuable info re operation of plant
STRUMWASSER, M California, State of 84/01/13 PALLADINO, N
Commissioners 1p 21832 241 24X Fiche 50-275, 84/01/13, 8401170243

8401170236 Order CLI-84-1, denying Joint Intervenor's request for stay of fuel loading & precriticality testing at facility
Commissioner Gilinsky separate views encl
CHILK, S J Office of the Secretary of the Commission 84/01/16
3pp 21831 359 24X Fiche 50-275, 84/01/16, 8401170236

8401250235 Confirms 840116 discussion wherein Secretary Chilk granted leave to all parties to file answers to Joint Intervenor's & Governor Deukmejian petitions for review of ALAB-756 by 840126
CHANDLER, L J Hearing Branch 2 84/01/16 CHILK, S J Office of the Secretary of the Commission 2pp 21944 130 24X
Fiche 50-275, 84/01/16, 8401250235

8401230435 Renews 830915 request that Commission briefing scheduled for 840215 re reinstatement of suspended low power license be held in San Luis Obispo, CA
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R
Joint Intervenor - Diablo Canyon 84/01/17 PALLADINO, N,
GILINSKY, V, ROBERTS, T Commissioners 2pp 21882 144 24X
Fiche 50-275, 84/01/17, 8401230435

8401300214 Answer in opposition to Governor Deukmejian & Joint Intervenor's 840109 petition for review of ALAB-756 re const QA Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co * Norton, Burke, Berry & French 84/01/26 Commissioners 46pp 21995 238 24X
Fiche 50-275, 84/01/26, 8401300214

8401300314 Answer to Governor Deukmejian 840109 petition for review of ALAB-756 re const QA ASLAB assessment of applicability of App B correct Petition should be denied Certificate of Svc encl
NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 84/01/26 Commissioners 14pp 21994 172, 24X
Fiche 50-275, 84/01/26, 8401300314

8401310267 Responds to 840117 request that briefing on reinstatement of low power license be held in San Luis Obispo, CA Request denied Briefing will convene on 840210 in Washington, DC
CHILK, S J Office of the Secretary of the Commission 84/01/30
REYNOLDS, J R Center for Law in the Public Interest 1p
22020 342 24X Fiche 50-275, 84/01/30, 8401310267

H General correspondence

8401050294 Requests info re events at facility & questions plant operation
OLESEN, M Affiliation Unknown 83/12/28 NRC - No Detailed
Affiliation Given 1p 21728 309 24X Fiche 50-275, 83/12/28, 8401050294

8401170316 Requests that LM Gustafson replace DH Davis on mailing lists Related correspondence
GUSTAFSON, L M Pacific Gas & Electric Co 84/01/13 CHILK, S J
Office of the Secretary of the Commission 1p 21833 286 24X
Fiche 50-275, 84/01/13, 8401170316

I Advisory Committee on Reactor Safeguards reports & correspondence

8401250193 Informs of ACRS 840118-19 meeting findings that plant mode to Unit 1 resulting from design verification program restored design margins to levels existing at time of ACRS 780714 rept
FRALRY, R F ACRS - Advisory Committee on Reactor Safeguards
84/01/23 PALLADINO, N Commissioners 1p 21937 109 24X
Fiche 50-275, 84/01/23, 8401250193

J Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 093 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

G Reportable occurrences, LERs & related correspondence

8401120422 PNO-V-84-002 on 840102, NRC resident inspector observed media repts of 2.5 to 2.7 magnitude earthquake reportedly occurring seven miles from facility. Plant seismic instrumentation not triggered by event.
* Region 5, Office of Director 84/01/03 1p 21791 021 24X
Fiche: 50-275, 84/01/03, 8401120422

8401160234 Final deficiency rept re containment spray initiation timing. Timer setting for starting of containment spray pump changed from original FSAR Table 8-3-4 value to value of 26 s & 22 s for pumps 1 & 2, respectively.
SCHUYLER, J O Pacific Gas & Electric Co 84/01/09 MARTIN, J D
Region 5, Office of Director 1p 21814 217 24X
Fiche: 50-275, 84/01/09, 8401160234

T Hearing transcripts on non-antitrust matters

8312120112 Board Notification 84-005 forwards NRC transcript of 831215 meeting in Bethesda, MD & intervenor 831216 & 1214 ltrs re Miami Valley Power Project 2 204 petition for reconsideration of ASLB 830915 order.
EISENHUT, D G Division of Licensing 84/01/10 PALLADINO, N J
OILINSKY, V, ROBERTS, T Commissioners 5pp 21928 003 24X
Fiche: 50-000, 84/01/10, 8312120112

--8401230612 Transcript of 831215 meeting w/uttl in Bethesda, MD
* Commissioners 83/12/15 210pp 21928 014 24X
Fiche: 50-000, 84/01/10, 8312120112

8401170297 Corrections to transcript of 831031-1121 hearings re design QA Certificate of Svc encl.
CRANE, P A Pacific Gas & Electric Co 84/01/11 23pp 21832 327
24X Fiche: 50-275, 84/01/11, 8401170297

8401260004 Transcript of 840112 affirmation/discussion & vote re request for stay of fuel loading at Diablo Canyon & 10CFR1 in Washington, DC. Pp 1-3 Supporting documentation encl.
* Commissioners 84/01/12 7pp 21989 351 24X
Fiche: 50-275, 84/01/12, 8401260004

8401250088 Transcript of ACRS Subcommittee on Diablo Canyon 840119 hearing in Los Angeles, CA. Pp 1-243 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 84/01/19
288pp, 21935 246 24X Fiche: 50-275, 84/01/19, 8401250088

U Congressional/Executive Correspondence

8401310168 Forwards rept addressing issues raised in 831101 ltr re NRC handling of drafts of QA case studies, in particular Diablo Canyon. Commission has concluded no further investigation necessary.
PALLADINO, N J Commissioners 84/01/09 MARKEY, E J House of Rep, Interior & Insular Affairs 1p 22032 001 24X
Fiche: 50-275, 84/01/09, 8401310168

--8401310169 "Rept on Review of Issues Raised by Congressman Markey Ltr of 831101,"
DIRCKS, W J Office of the Executive Director for Operations, 84/01/09 200pp 22032 002 24X Fiche: 50-275, 84/01/09, 8401310168

--8401310172 Raises concerns re NRC handling of drafts of QA case studies.
MARKEY, E J House of Rep, Interior & Insular Affairs 83/11/01 PALLADINO, N J Commissioners 13pp 22032 281 24X
Fiche: 50-275, 84/01/09, 8401310168

8401240220 Discusses allegations by util workers re poor const QC & unsafe bldg practices. NRC should perform complete review of util/Bechtel design review & reinsp of plant safety features by outside, independent authority.
IBENBERG, P California, State of 84/01/12 PALLADINO, N J Commissioners 1p 21910 303 24X Fiche: 50-275, 84/01/12, 8401240220

8401230432 Recommends fair public hearing & thorough investigation of all credible allegations re potential safety problems at facility.
BRONZAN, B California, State of 84/01/17 PALLADINO, N J Commissioners 1p 21882 324 24X Fiche: 50-275, 84/01/17, 8401230432

8401240199 Urges extraordinary steps be taken to investigate all allegations of inadequacy in QA program in order to allay public concern about safety of opening facility.
ROSENTHAL, H California, State of 84/01/17 PALLADINO, N J Commissioners 2pp 21909 220 24X Fiche: 50-275, 84/01/17, 8401240199

8401240208 Requests NRC require independent design review audit, comprehensive QC reinsp of plant & investigation of root of apparent overwhelming problems before authorization of operation.
HAYDEN, T California, State of 84/01/17 PALLADINO, N J Commissioners 2pp 21908 262 24X Fiche: 50-275, 84/01/17, 8401240208

8401240232 Urges careful investigation into alleged safety problems & violations prior to licensing.
PETRIS, N C California, State of 84/01/17 PALLADINO, N J Commissioners 1p 21910 183 24X Fiche: 50-275, 84/01/17, 8401240232

8401240086 Urges full investigation of allegations of potential safety problems be undertaken before granting util license to operate.
BATES, T H California, State of 84/01/18 PALLADINO, N J Commissioners 2pp 21912 350 24X Fiche: 50-275, 84/01/18, 8401240086

8401240269 Urges serious allegations re QA/QC be investigated prior to plant operation.
BROWN, W L California, State of 84/01/18 PALLADINO, N J Commissioners 1p, 21909 362 24X Fiche: 50-275, 84/01/18, 8401240269

8401230399 Requests NRC authorize complete investigation into causes of QA/QC breakdown, authorize independent audit of util/Bechtel design review & authorize comprehensive QC reinsp of all safety-related hardware.
WATERS, M California, State of 84/01/19 PALLADINO, N J Commissioners 2pp 21879 150 24X Fiche: 50-275, 84/01/19, 8401230399

8401240227 Recommends complete investigation into causes of QA/QC breakdown, independent audit of design review & comprehensive independent QC insp of all safety-related hardware.
KLEBS, J California, State of 84/01/19 PALLADINO, N J Commissioners 2pp 21910 178 24X Fiche: 50-275, 84/01/19, 8401240227

8401240493 Requests NRC investigation of allegations re QC/QA breakdown, possible mgt coverup of problems & worker harassment. Investigation should be completed before authorizing plant operation.
VASCONELO, J California, State of 84/01/19 PALLADINO, N J Commissioners 2pp 21920 097 24X Fiche: 50-275, 84/01/19, 8401240493

8401270226 Suggests completion of IE investigation re causes of QA/QC breakdown, independent audit of util/Bechtel design review & comprehensive QC reinsp of all safety-related hardware by independent body before authorizing operation.
FARR, S California, State of 84/01/23 PALLADINO, N J Commissioners 2pp 21976 336 24X Fiche: 50-275, 84/01/23, 8401270226

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8401050481 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32. Implementation of corrective actions will be examined during future insps.
LEWIS, R C Division of Project & Resident Programs 83/12/19 UTLEY, E E Carolina Power & Light Co 1p 21726 021 24X
Fiche: 50-324, 83/12/19, 8401050481

--8401050490 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32. Corrective actions real-time training provided to operating shift personnel re Operating Instruction 01-13.
HOWE, P W Carolina Power & Light Co 83/12/07 O'REILLY, J P Region 2, Office of Director 2pp 21726 022 24X
Fiche: 50-324, 83/12/19, 8401050481

--8401050514 Notice of violation from insp on 830815-0923.
* Region 2, Office of Director 83/11/07 1p 21726 026 24X
Fiche: 50-324, 83/12/19, 8401050481

--8401050525 IE Insp Repts 50-324/83-32 & 50-325/83-32 on 830815-0923. Violation noted: Failure to implement Operating Instruction 01-13 re valve & electrical lineup verification.
MYERS, D O, GARNER, L W Region 2, Office of Director BEMIS, P R Division of Project & Resident Programs 83/10/23 9pp, 21726 027 24X Fiche: 50-324, 83/12/19, 8401050481

DOCKETED ITEMS

B401300037 Forwards evaluation of methodology used in evaluation of associated circuits for post-fire shutdown analysis. If util cannot comply w/guidance provided, notification requested. Proposal acceptable.
VASSALLO, D B Operating Reactors Branch 2 83/12/21 UTLEY, E E
Carolina Power & Light Co 5pp 22006 353 24X
Fiche 50-324, 83/12/21, B401300037

B401060132 Releases public version of revised emergency plan procedure & emergency response plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21745 249 24X Fiche 50-324, 83/12/27, B401060132

--B401060140 Forwards public version of Rev 4 to Emergency Plan Procedure PEP-04 3, "Performance of Training, Exercises & Drills" & Rev 11 to emergency response plan
ZIMMERMAN, S R Carolina Power & Light Co 83/11/18
O'REILLY, J P Region 2, Office of Director 1p 21745 250 24X
Fiche 50-324, 83/12/27, B401060132

--B401060145 Public version of Rev 4 to Emergency Plan Procedure PEP-04 3, "Performance of Training, Exercises & Drills"
TOLER, W R, BOYER, L E Carolina Power & Light Co 83/10/27
10pp 21745 251 24X Fiche 50-324, 83/12/27, B401060132

--B401060151 Public version of Rev 11 to emergency response plan
TOLER, W R, BOYER, L E Carolina Power & Light Co 83/10/27
50pp 21745 261 24X Fiche 50-324, 83/12/27, B401060132

B401190021 Notification of B40116 meeting w/util in Bethesda, MD to discuss progress rept on fire protection, including alternate shutdown sys, cable routing, suppression sys, reactor bldg fire areas, diesel generator bldg & exemptions
MACKAY, S D Operating Reactors Branch 2 84/01/05 VASSALLO, D B
Operating Reactors Branch 2 2pp 21870 310 24X
Fiche 50-324, 84/01/05, B401190021

B401260267 Notification of B40216 meeting w/util in Bethesda, MD to discuss progress rept on fire protection, alternate shutdown sys, guidelines for alternate safe shutdown & overall completion schedule
MACKAY, S D Operating Reactors Branch 2 84/01/20 VASSALLO, D B
Operating Reactors Branch 2 1p 21987 337 24X
Fiche 50-324, 84/01/20, B401260267

B401260274 Notification of B40202 meeting w/util in Bethesda, MD to discuss fire protection, alternate shutdown & associated exemptions
MACKAY, S D Operating Reactors Branch 2 84/01/20 VASSALLO, D B
Operating Reactors Branch 2 1p 21982 360 24X
Fiche 50-324, 84/01/20, B401260274

J Insurance & indemnity information

B401200024 Forwards Endorsement 51 to NELIA Policy NF-218
BARHAM, C D Carolina Power & Light Co 84/01/13 SALTZMAN, J D
Office of Nuclear Reactor Regulation, Director 2pp 21864 354
24X Fiche 50-324, 84/01/13, B401200024

B401200192 Forwards Endorsement 44 to MAELU Policy MF-80
BARHAM, C D Carolina Power & Light Co 84/01/13 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 2pp 21863 338
24X Fiche 50-324, 84/01/13, B401200192

B401260023 Forwards Endorsement 4 to MAELU Certificates M-54 & M-55
BARHAM, C D Carolina Power & Light Co 84/01/13 SALTZMAN, J
Office of Nuclear Reactor Regulation, Director 3pp 21956 303
24X Fiche 50-324, 84/01/13, B401260023

B401260210 Forwards Endorsement 4 to NELIA Certificates N-54 & N-55
BARHAM, C D Carolina Power & Light Co 84/01/13 SALTZMAN, J NRC
- No Detailed Affiliation Given 3pp 21956 297 24X
Fiche 50-324, 84/01/13, B401260210

P Operating license stage documents & correspondence

B401040468 Application for amend to License DPR-62, revising Tech Spec 4 B 2 3 2 re surveillance requirements for 125-volt battery
W/ four oversize drawings. Aperture cards are available in PDR
HOWE, P W Carolina Power & Light Co 83/12/07 VASSALLO, D B
Operating Reactors Branch 2 33pp 21723 317 24X
Fiche 50-324, 83/12/07, B401040468

--B401040315 Rev 6 to "RCIC Sys Description SD-16," Vol II
* Carolina Power & Light Co 83/10/12 63pp 21723 354 24X
Fiche 50-324, 83/12/07, B401040468

--B401040519 Rev 5 to "Sys Description SD-19, HPCI Sys," Vol II
* Carolina Power & Light Co 83/10/12 48pp 21724 055 24X
Fiche 50-324, 83/12/07, B401040468

--B401040527 Proposed changes to Tech Spec 4 B 2 3 2 re surveillance requirements for 125-volt battery
* Carolina Power & Light Co 83/10/12 1p 21724 102 24X
Fiche 50-324, 83/12/07, B401040468

B401050029 Forwards Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively, safety evaluation, notice of issuance & availability & EIA Amends allow increase in spent fuel storage capacity to max of 3,946 assemblies
GROTHENHUIS, M Operating Reactors Branch 2 83/12/15 UTLEY, E E
Carolina Power & Light Co 2pp 21735 284 24X
Fiche 50-324, 83/12/15, B401050029

--B401050034 Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively, allowing increase in spent fuel storage capacity to max of 3,946 assemblies
VASSALLO, D B Operating Reactors Branch 2 83/12/15 8pp,
21735 286 24X Fiche 50-324, 83/12/15, B401050029

--B401050041 Safety evaluation supporting Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/15
14pp 21735 294 24X Fiche 50-324, 83/12/15, B401050029

--B401050048 EIA supporting Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively
* NRC - No Detailed Affiliation Given 83/12/15 11pp
21735 308 24X Fiche 50-324, 83/12/15, B401050029

--B401050057 Notice of issuance & availability & negative declaration of Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively.
VASSALLO, D B Operating Reactors Branch 2 83/12/15 2pp
21735 319 24X Fiche: 50-324, 83/12/15, B401050029

B401160464 Forwards generic evaluation of radiological consequences of accidents while purging or venting at power. Generic review applicable to Facility Response to B31201 ltr will be last part of review
VASSALLO, D B Operating Reactors Branch 2 83/12/22 UTLEY, E E
Carolina Power & Light Co 4pp 21824 295 24X
Fiche 50-324, 83/12/22, B401160464

B401230602 Forwards Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively & safety evaluation. Amends authorize changes to implement requirements of App I, establish new limiting conditions for operation & revise environ programs
VASSALLO, D B Operating Reactors Branch 2 83/12/27 UTLEY, E E
Carolina Power & Light Co 2pp 21905 047 24X
Fiche 50-324, 83/12/27, B401230602

--B401230615 Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively, authorizing changes to implement requirements of App I, establishing new limiting conditions for operation & revising environ monitoring programs
VASSALLO, D B Operating Reactors Branch 2 83/12/27 247pp
21905 049 24X Fiche 50-324, 83/12/27, B401230602

--B401230626 Safety evaluation supporting Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/27 6pp
21905 296 24X Fiche: 50-324, 83/12/27, B401230602

--B304070498 "Radiological Effluent Tech Spec Implementation (A,2): Carolina Power & Light Co, Brunswick Steam Electric Plant Units 1 & 2," technical evaluation rept
CHEN, S, PANDEY, F Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-85/86 83/03/29 CONGEL, F, WILLIS, C
NRC - No Detailed Affiliation Given 34pp 21905 302 24X
Fiche 50-324, 83/12/27, B401230602

B401200016 Forwards Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively & safety evaluation. Amends add limiting conditions for operation & surveillance requirements for reactor protection sys electrical power supplies
VASSALLO, D B Operating Reactors Branch 2 83/12/28 UTLEY, E E
Carolina Power & Light Co 14pp, 21871 119 24X
Fiche 50-324, 83/12/28, B401200016

--B401200020 Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively, adding limiting conditions for operation & surveillance requirements for reactor protection sys electrical power supplies
VASSALLO, D B Operating Reactors Branch 2 83/12/28 7pp
21871 121 24X Fiche 50-324, 83/12/28, B401200016

DOCKETED ITEMS

169

- B401200026 Safety evaluation supporting Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/28 2pp
21871 131 24X Fiche 50-324, 83/12/28, B401200016
- B401050198 Suppl to B10728 & B21210 applications for amends to Licenses DPR-71 & DPR-62, incorporating corporate & plant organizational changes
HOWE, P W Carolina Power & Light Co 83/12/29 VASSALLO, D B
Operating Reactors Branch 2 26pp 21730 001 24X
Fiche 50-324, 83/12/29, B401050198
- B401050219 Proposed Tech Specs re changes to administrative controls
* Carolina Power & Light Co 83/12/29 78pp 21730 030 24X
Fiche 50-324, 83/12/29, B401050198
- B401270537 Forwards exemption from certain requirements of 10CFR50 44 (c) re combustible gas control
EISENHUT, D G Division of Licensing 83/12/29 UTLEY, E E
Carolina Power & Light Co 2pp 22000 343 24X
Fiche 50-324, 83/12/29, B401270537
- B401270541 Exemption from requirements of 10CFR50 44(c) re combustible gas control Means for controlling combustible gas for interim operation through B40630 acceptable
EISENHUT, D G Division of Licensing 83/12/29 Carolina Power & Light Co 4pp 22000 345 24X Fiche 50-324, 83/12/29, B401270537
- B401110192 Requests remittance of addl fee for review of B30929 application for amend to License DPR-62 requesting extension of completion date for mod to effgas sys
MILLER, W O License Fee Management Branch 83/12/30 UTLEY, E E
Carolina Power & Light Co 1p 21795 126 24X
Fiche 50-324, 83/12/30, B401110192
- B401200128 Forwards Amend 90 to License DPR-62 & safety evaluation Amend revises surveillance test requirement for station electrical battery 2A-2
ORDTENHUIS, M Operating Reactors Branch 2 83/12/31 UTLEY, E E
Carolina Power & Light Co 2pp 21872 151 24X
Fiche 50-324, 83/12/31, B401200128
- B401200131 Amend 90 to License DPR-62, revising surveillance test requirement for station electrical battery 2A-2
VASSALLO, D B Licensing Branch 2 83/12/31 4pp 21872 153 24X Fiche 50-324, 83/12/31, B401200128
- B401200134 Safety evaluation supporting Amend 90 to License DPR-62
* Office of Nuclear Reactor Regulation, Director 83/12/31 3pp 21872 157 24X Fiche 50-324, 83/12/31, B401200128
- B401130230 Forwards proprietary & nonproprietary response to NRC B31101 request for addl info, amending topical repts re BWR steady-state analysis methods Affidavit requesting proprietary info be withheld (ref 10CFR2 750) encl
ZIMMERMAN, S R Carolina Power & Light Co 84/01/03 VASSALLO, D B
Operating Reactors Branch 2 13pp 21801 001 24X
Fiche 50-324, 84/01/03, B401130230
- B401130237 Amend 1 to Topical Rept NF-1583, 01-1, "Description & Validation of Steady-State Analysis Methods for BWRs,"
N/nine oversize figures Aperture cards are available in PDR.
GITNICK, B J Carolina Power & Light Co NF-1583, 01-1, 83/12/22 32pp 21801 014 24X Fiche 50-324, 84/01/03, B401130230
- B401130266 Nonproprietary Amend 1 to Topical Rept NF-1583 02-1, "Methods of Record LWR Fuel Assembly Burnup Code."
GITNICK, B J Carolina Power & Light Co NF-1583 02-1 (NP) 83/12/22 40pp 21801 047 24X Fiche 50-324, 84/01/03, B401130230
- B401130283 Nonproprietary Amend 1 to Topical Rept NF-1583 03-1, "Methods of PRESTO-B Three-Dimensional BWR Core Simulation Code."
GITNICK, B J Carolina Power & Light Co NF-1583 03-1 (NP) 83/12/23 26pp 21801 087 24X Fiche 50-324, 84/01/03, B401130230
- B401100283 Forwards Rev B to Training Instruction, Vol I TI-200, "Plant Operator Retraining Program" for approval. Rev describes use of simulator for retraining
HOWE, P W Carolina Power & Light Co 84/01/04 VASSALLO, D B
Operating Reactors Branch 2 2pp 21758 226 24X
Fiche 50-324, 84/01/04, B401100283
- B401100289 Rev B to Training Instruction TI-200, Vol I, "Plant Operator Retraining Program"
HOPKINS, P C, CHA, J W Carolina Power & Light Co 83/11/22 13pp 21758 228 24X Fiche 50-324, 84/01/04, B401100283
- B401200118 Notifies of completion of TMI Action Items II K 3 30 & II K 3 31 based on NRC B31213 acceptance of OE small break LOCA model For use in plant analysis Requests confirmation of model use
VASSALLO, D Operating Reactors Branch 1 84/01/04 UTLEY, E E
Carolina Power & Light Co 2pp 21872 173 24X
Fiche 50-324, 84/01/04, B401200118
- B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382
- B401100373 Describes util method for complying w/draft implementation guidelines for 10CFR61 Impell Corp WASTETRAK computer program will be utilized for waste classification
CUTTER, A B Carolina Power & Light Co 84/01/05 EISENHUT, D G
Division of Licensing 1p 21763 290 24X Fiche 50-000, 84/01/05, B401100373
- B401190020 Notification of B40202 meeting w/util in Bethesda, MD to discuss status of equipment environ qualification Agenda encl
ORDTENHUIS, M Operating Reactors Branch 2 84/01/05 VASSALLO, D B
Operating Reactors Branch 2 3pp 21870 311 24X
Fiche 50-324, 84/01/05, B401190020
- B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221
- B401200232 Responds to FOIA request for correspondence between NRC & util re facility in Southport, NC Forwards App A documents
FELTON, J M Division of Rules and Records 84/01/06 BELEW, R H
Star-News Newspapers, Wilmington, NC 2pp 21887 286 24X
Fiche 50-324, 84/01/06, B401200232
- B401200234 FOIA request for NRC recent order requiring util to meet testing requirements at Southport generating plant or take unit out of operation & correspondence requiring util to meet safety studs per Reg Guide 1.118
BELEW, R H Star-News Newspapers, Wilmington, NC 83/12/07 NRC
No Detailed Affiliation Given 2pp 21887 288 24X
Fiche 50-324, 84/01/06, B401200232
- B401230048 Forwards intergranular stress corrosion cracking insp order confirming shutdown of plant
VASSALLO, D B Operating Reactors Branch 2 83/08/26 UTLEY, E E
Carolina Power & Light Co 2pp 21887 290 24X
Fiche 50-324, 84/01/06, B4012300232
- B401170431 Application to amend License DPR-62, postponing one full flow test of core spray pumps until primary containment suppression chamber restored to operational condition
HOWE, P W Carolina Power & Light Co 84/01/10 VASSALLO, D B
Operating Reactors Branch 2 5pp 21827 143 24X
Fiche 50-324, 84/01/10, B401170431
- B401170433 Proposed Tech Specs re core spray surveillance interval extension
* Carolina Power & Light Co 84/01/10 2pp 21827 146 24X
Fiche 50-324, 84/01/10, B401170431
- B401250446 Forwards Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively & safety evaluation Amends change Tech Specs to provide limited flexibility in scheduling containment leak testing surveillance consistent w/planned outages
ORDTENHUIS, M Operating Reactors Branch 4 84/01/11 UTLEY, E E
Carolina Power & Light Co 2pp 21949 006 24X
Fiche 50-324, 84/01/11, B401250446
- B401250450 Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively, changing Tech Specs to provide limited flexibility in scheduling containment leak testing surveillance consistent w/planned outages
VASSALLO, D B Operating Reactors Branch 2 84/01/11 14pp 21949 008 24X Fiche 50-324, 84/01/11, B401250446
- B401250458 Safety evaluation supporting Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/11 2pp 21949 022 24X Fiche 50-324, 84/01/11, B401250446

DOCKETED ITEMS

- 8401170181 Informs that util will not be able to respond to draft technical evaluation rept open items re control of heavy loads within recommended time frame Responses to open items will be provided by 840203
ZIMMERMAN, S R Carolina Power & Light Co 84/01/12 VASSALLO, D B Operating Reactors Branch 2 1p 21834 152 24X
Fiche 50-324, 84/01/12, 8401170181
- 8401170245 Responds to 831216 request for addl info re fast cold starts of diesel generators per Generic Ltr 83-41 Diesel generators not subj to fast cold starts as described Total number of diesel generator starts from 821201-831130 listed
ZIMMERMAN, S R Carolina Power & Light Co 84/01/12 EISENHUT, D O Division of Licensing 3pp 21832 242 24X Fiche 50-324, 84/01/12, 8401170245
- 8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084
- 8401250261 Forwards addl fee for Amend 86 to License DPR-62, in response to NRC 831230 request
CUTTER, A B Carolina Power & Light Co 84/01/19 MILLER, W O License Fee Management Branch 2pp 21943 236 24X
Fiche 50-324, 84/01/19 8401250261
- Q Inspection reports, IE Bulletins & correspondence
- 8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Petts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040
- 8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040
- 8401050454 Forwards IE Insp Repts 50-324/83-38 & 50-325/83-38 on 831103-04 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/01 UTLEY, E E Carolina Power & Light Co 2pp 21730 143 24X
Fiche 50-324, 83/12/01, 8401050454
- 8401050457 IE Insp Repts 50-324/83-38 & 50-325/83-38 on 831103-04 No violations noted Major areas inspected respiratory protection & external exposure control
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/30 3pp 21730 145 24X Fiche 50-324, 83/12/01, 8401050457
- 8401050378 Forwards IE Insp Repts 50-324/83-39 & 50-325/83-39 on 831015-1115 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/06 UTLEY, E E Carolina Power & Light Co 2pp 21731 001 24X
Fiche 50-324, 83/12/06, 8401050378
- 8401050380 IE Insp Repts 50-324/83-39 & 50-325/83-39 on 831015-1115 No violations noted Major areas inspected surveillance, maint, operational safety verification, ESF walkdown, in-office LER review & independent insp
MYERS, D O, GARNER, L W Region 2, Office of Director BEMIS, P R Division of Project & Resident Programs 83/12/05 8pp 21731 003 24X Fiche 50-324, 83/12/06, 8401050378
- 8401050336 Forwards IE Insp Repts 50-324/83-36 & 50-325/83-36 on 831114-18 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/08 UTLEY, E E Carolina Power & Light Co 2pp 21727 145 24X
Fiche 50-324, 83/12/08, 8401050336
- 8401050338 IE Insp Repts 50-324/83-36 & 50-325/83-36 on 831114-18 No noncompliance noted Major areas inspected areas of IE Bulletin 83-02 re inservice insp work & recirculation sys piping repair welding
COLEY, J L Region 2, Office of Director BLAKE, J J Division of Emergency Preparedness & Materials Safety 83/12/06 4pp 21727 147 24X Fiche 50-324, 83/12/08, 8401050336
- 8401050478 Suppls 830608 response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators Periodic testing of valves incorporated into Procedure MI-10-5211 Initial insps completed 831112 Item closed
HOWE, P W Carolina Power & Light Co 83/12/13 O'REILLY, J P Region 2, Office of Director 1p 21730 125 24X
Fiche 50-324, 83/12/13, 8401050478
- 8401090131 Forwards IE Insp Repts 50-324/83-40 & 50-325/83-40 on 831114-18 No violation noted
VERRELLI, D M Division of Project & Resident Programs 83/12/14 UTLEY, E E Carolina Power & Light Co 2pp 21750 320 24X
Fiche 50-324, 83/12/14, 8401090131
- 8401090138 IE Insp Repts 50-324/83-40 & 50-325/83-40 on 831114-18 No violation noted Major areas inspected respiratory protection, external dose control, HEPA & charcoal filter testing, receipt of radioactive mat'l & radwaste generation.
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/12/12 5pp 21750 322 24X Fiche 50-324, 83/12/14, 8401090131
- 8401050481 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32 Implementation of corrective actions will be examined during future insps
LEWIS, R C Division of Project & Resident Programs 83/12/19 UTLEY, E E Carolina Power & Light Co 1p 21726 021 24X
Fiche 50-324, 83/12/19, 8401050481
- 8401050490 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32 Corrective actions real-time training provided to operating shift personnel re Operating Instruction OI-13
HOWE, P W Carolina Power & Light Co 83/12/07 O'REILLY, J P Region 2, Office of Director 2pp 21726 022 24X
Fiche 50-324, 83/12/19, 8401050481
- 8401050510 Forwards IE Insp Repts 50-324/83-32 & 50-325/83-32 on 830815-0923 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07, UTLEY, E E Carolina Power & Light Co 2pp 21726 024 24X
Fiche 50-324, 83/12/19, 8401050481
- 8401050514 Notice of violation from insp on 830815-0923
* Region 2, Office of Director 83/11/07 1p 21726 026 24X
Fiche 50-324, 83/12/19, 8401050481
- 8401050525 IE Insp Repts 50-324/83-32 & 50-325/83-32 on 830815-0923 Violation noted failure to implement Operating Instruction OI-13 re valve & electrical lineup verification
MYERS, D O, GARNER, L W Region 2, Office of Director BEMIS, P R Division of Project & Resident Programs 83/10/25 9pp 21726 027 24X Fiche 50-324, 83/12/19, 8401050481
- 8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- 8401060424 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-34 & 50-325/83-34
VERRELLI, D M Division of Project & Resident Programs 83/12/29, UTLEY, E E Carolina Power & Light Co 1p 21741 063 24X
Fiche 50-324, 83/12/29, 8401060424
- 8401060426 Responds to NRC 831111 ltr re violations noted in IE Insp Repts 50-324/83-34 & 50-325/83-34 Corrective actions as-built guidelines will be incorporated into engineering support unit by 840115
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P Region 2, Office of Director 3pp 21741 064 24X
Fiche 50-324, 83/12/29, 8401060424
- 8401060427 Forwards IE Insp Repts 50-324/83-34 & 50-325/83-34 on 830915-1015 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/11/21 UTLEY, E E Carolina Power & Light Co 10pp 21741 067 24X
Fiche 50-324, 83/12/29, 8401060424
- 8401060429 Notice of violation from insp on 830915-1015.
* Region 2, Office of Director 83/11/21 1p 21741 069 24X
Fiche 50-324, 83/12/29, 8401060424.
- 8401060432 IE Insp Repts 50-324/83-34 & 50-325/83-34 on 830915-1015 Noncompliance noted failure to establish document control procedures for Drawing FP9527-80D17-2, Sheet 8, Rev A
MYERS, D O, GARNER, L W, BEMIS, P R Region 2, Office of Director 83/11/18 7pp 21741 070 24X Fiche 50-324, 83/12/29, 8401060424
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

DOCKETED ITEMS

171

B401240490 Ack receipt of B30923 & 1207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23
O'REILLY, J P Region 2, Office of Director 84/01/06 UTLEY, E E
Carolina Power & Light Co 1p 21920 083 24X
Fiche 50-324, 84/01/06, B401240490

--B401240498 Suppls B30923 response to NRC B30825 ltr re violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 Corrective actions procedure to ensure reverts to certificates of compliance identified implemented on B31018
DIETZ, C R Carolina Power & Light Co 83/12/07 O'REILLY, J P
Region 2, Office of Director 1p 21920 084 24X
Fiche 50-324, 84/01/06, B401240490

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 033 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/14 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/14, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401250172 Annual rept of changes, tests & experiments for 1982, per 10CFR50.59 W/B31027 ltr
DIETZ, C R Carolina Power & Light Co 82/12/31 O'REILLY, J P
Region 2, Office of Director 367pp 21937 162 24X
Fiche 50-324, 82/12/31, B401250172

B401030248 Nonroutine 30-day Radiological Environ Event Rept 2-SR-83-32 re gamma analysis results of bottom sediment sample Co-60 activity increased by factor of 10 above MDA
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21681 006 24X
Fiche 50-324, 83/12/22, B401030248

B401110233 Monthly operating repts for Dec 1983 W/B40104 ltr HARRISON, F J, DIETZ, C R Carolina Power & Light Co 83/12/31
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 10pp 21772 313 24X Fiche 50-324, 83/12/31, B401110233

B Reportable occurrences, LERs & related correspondence

B401030248 Nonroutine 30-day Radiological Environ Event Rept 2-SR-83-32 re gamma analysis results of bottom sediment sample Co-60 activity increased by factor of 10 above MDA
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21681 006 24X
Fiche 50-324, 83/12/22, B401030248

B401030271 LER B3-097/017-0 on B31212, during IE Bulletin B3-02 testing, crack indications identified in 19 of 131 welds caused by intergranular stress corrosion cracking Eight welds repaired Remaining indications acceptable, W/B31222 ltr PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/12/22
O'REILLY, J P Region 2, Office of Director 3pp 21681 275 24X
Fiche 50-324, 83/12/22, B401030271

B401100161 RD on B31122, limiting conditions for operation implemented when Fire Doors 112, 117, 103, 105, 108 & 123 declared inoperable. Caused by high differential air pressure preventing automatic self-closure
DIETZ, C R Carolina Power & Light Co 83/12/29 O'REILLY, J P
Region 2, Office of Director, 1p 21761 001, 24X
Fiche: 50-324, 83/12/29, B401100161

B401120380 EN-B4-002 on B40109, notice of violation & proposed imposition of civil penalty of \$40,000 to be issued Action based on violations of fire protection requirements Notice includes citation for matl false statement
CRAIG, J, AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/01/09 1p 21791 017 24X Fiche 50-324, 84/01/09, B401120380

B401240003 RD 2-SR-83-35 bottom sediment sample gamma analysis collected on B31201 detected abnormal Co-60 concentration Sampling frequency increased to monthly to closely monitor Co-60 activity
DIETZ, C R Carolina Power & Light Co 84/01/12 O'REILLY, J P
Region 2, Office of Director 2pp 21912 300 24X
Fiche 50-324, 84/01/12, B401240003

B401240166 RD 2-SR-83-33 on B31206, specified 7-day time frame for limiting condition for operation exceeded during performance of 125-volt battery capacity test Test conducted w/control bldg Fire Doors 108 & 114 open Fire watch maintained
DIETZ, C R Carolina Power & Light Co 84/01/12 O'REILLY, J P
Region 2, Office of Director 1p 21910 296 24X
Fiche 50-324, 84/01/12, B401240166

B401230406 Informs of revised schedule for submission of cause of RO-2-B3-75 re fire penetration designs Current status investigation to be completed by B40131
DIETZ, C R Carolina Power & Light Co 84/01/13 O'REILLY, J P
Region 2, Office of Director 1p 21879 122 24X
Fiche 50-324, 84/01/13, B401230406

B401240070 LER B3-092/03L-0 on B31219, accumulator leak detection instruments 2-C12-LS-129-42-11, 46-35, 50-19 & 18-03 failed to respond to applied test input Caused by instrument failure Instrument replaced W/B40116 ltr
PASTVA, M J, DIETZ, C R Carolina Power & Light Co 84/01/16 O'REILLY, J P Region 2, Office of Director 2pp 21913 214 24X
Fiche 50-324, 84/01/16, B401240070

X Onsite Storage of Low Level Waste

B401130335 Confirms B31214 telcon w/PH Lohaus re errors found in Paragraph A1 55(a)(7) of 10CFR61 statement on waste form classification Util interpretation of paragraph stated
ZIMMERMAN, S R Carolina Power & Light Co 84/01/09 EISENHUT, D G Division of Licensing 1p 21801 201 24X Fiche 50-000, 84/01/09, B401130335

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

B401030481 Ack receipt of B31207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32 Implementation of corrective actions will be examined during future insps
LEWIS, R C Division of Project & Resident Programs 83/12/19
UTLEY, E E Carolina Power & Light Co 1p 21726 021 24X
Fiche 50-324, 83/12/19, B401030481

--B401030490 Responds to NRC B31107 ltr re violations noted in IE Insp Repts 50-324/83-32 & 50-325/83-32 Corrective actions real-time training provided to operating shift personnel re Operating Instruction OI-13
HOWE, P W Carolina Power & Light Co 83/12/07 O'REILLY, J P
Region 2, Office of Director 2pp 21726 022 24X
Fiche 50-324, 83/12/19, B401030481

--B401030514 Notice of violation from insp on B30815-0923
* Region 2, Office of Director 83/11/07 1p 21726 026 24X
Fiche 50-324, 83/12/19, B401030481

--B401030525 IE Insp Repts 50-324/83-32 & 50-325/83-32 on B30815-0923 Violation noted Failure to implement Operating Instruction OI-13 re valve & electrical lineup verification
MYERS, D O Region 2, Office of Director 83/10/25 9pp 21726 027 24X Fiche 50-324, 83/12/19, B401030481

B401300037 Forwards evaluation of methodology used in evaluation of associated circuits for post-fire shutdown analysis If util cannot comply w/guidance provided, notification requested
Proposal acceptable
VASSALLO, D B Operating Reactors Branch 2 83/12/21 UTLEY, E E
Carolina Power & Light Co 5pp 22006 333 24X
Fiche 50-324, 83/12/21, B401300037

B401060132 Releases public version of revised emergency plan procedure & emergency response plan
FELTON, J M Division of Rules and Records 83/12/27 Document Management Branch 1p 21743 249 24X Fiche 50-324, 83/12/27, B401060132

DOCKETED ITEMS

0140 Forwards public version of Rev 4 to Emergency Plan Procedure PEP-04 3, "Performance of Training Exercises & 1a" & Rev 11 to emergency response plan
 IERMAN, S R Carolina Power & Light Co 83/11/18
 ILLY, J P Region 2, Office of Director 1p 21745 250 24X
 50-324, 83/12/27, 8401060132

0145 Public version of Rev 4 to Emergency Plan Procedure -04 3, "Performance of Training Exercises & Drills"
 R.W.R., BOYER, L.E. Carolina Power & Light Co 83/10/27
 21745 251 24X Fiche 50-324, 83/12/27, 8401060132

0151 Public version of Rev 11 to emergency response plan
 R.W.R., BOYER, L.E. Carolina Power & Light Co 83/10/27
 21745 261 24X Fiche 50-324, 83/12/27, 8401060132

221 Notification of 840116 meeting w/util in Bethesda, MD to progress rept on fire protection, including alternate sun sys, cable routing, suppression sys, reactor bldg fire diesel generator bldg & exemptions
 V.B.D. Operating Reactors Branch 2 84/01/05 VASSALLO, D B
 50-324, 84/01/05, 8401190021

267 Notification of 840216 meeting w/util in Bethesda, MD to progress rept on fire protection, alternate shutdown guidelines for alternate safe shutdown & overall station schedule
 V.B.D. Operating Reactors Branch 2 84/01/20 VASSALLO, D B
 50-324, 84/01/20, 8401260267

274 Notification of 840202 meeting w/util in Bethesda, MD to progress rept on fire protection, alternate shutdown & associated conditions
 V.B.D. Operating Reactors Branch 2 84/01/20 VASSALLO, D B
 50-324, 84/01/20, 8401260274

 rance & indemnity information

024 Forwards Endorsement 51 to NELIA Policy NF-218
 M.C.D. Carolina Power & Light Co 84/01/13 SALTZMAN, J D
 e of Nuclear Reactor Regulation, Director 2pp 21864 354
 50-324, 84/01/13, 8401200024

192 Forwards Endorsement 44 to MAELU Policy MF-80
 M.C.D. Carolina Power & Light Co 84/01/13 SALTZMAN, J
 e of Nuclear Reactor Regulation, Director 2pp 21863 358
 50-324, 84/01/13, 8401200192

023 Forwards Endorsement 4 to MAELU Certificates M-54 & M-55
 M.C.D. Carolina Power & Light Co 84/01/13 SALTZMAN, J
 e of Nuclear Reactor Regulation, Director 3pp 21956 303
 50-324, 84/01/13, 8401260023

210 Forwards Endorsement 4 to NELIA Certificates N-54 & N-55
 M.C.D. Carolina Power & Light Co 84/01/13 SALTZMAN, J. NRC
 Detailed Affiliation Given 3pp 21956 257 24X
 50-324, 84/01/13, 8401260210

 ating license stage documents & correspondence

029 Forwards Amends 61 & 87 to Licenses DPR-71 & DPR-62, ctively, safety evaluation, notice of issuance & ability & EIA Amends allow increase in spent fuel ge capacity to max of 3,946 assemblies
 NHUIS, M Operating Reactors Branch 2 83/12/15 UTLEY, E E
 ina Power & Light Co 2pp 21735 284 24X
 50-324, 83/12/15, 8401050029

50034 Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively, owing increase in spent fuel storage capacity to max of 46 assemblies
 SALLQ, D B Operating Reactors Branch 2 83/12/15 8pp
 35 286 24X Fiche 50-324, 83/12/15, 8401050029

50041 Safety evaluation supporting Amends 61 & 87 to Licenses -71 & DPR-62, respectively.
 Office of Nuclear Reactor Regulation, Director 83/12/15
 p 21735 294 24X Fiche 50-324, 83/12/15, 8401050029

50048 EIA supporting Amends 61 & 87 to Licenses DPR-71 & DPR-62, pectively
 NRC - No Detailed Affiliation Given 83/12/15 11pp
 35 308 24X Fiche 50-324, 83/12/15, 8401050029.

--8401050057 Notice of issuance & availability & negative declaration of Amends 61 & 87 to Licenses DPR-71 & DPR-62, respectively
 VASSALLO, D B Operating Reactors Branch 2 83/12/15 2pp
 21735 319 24X Fiche 50-324, 83/12/15, 8401050029

8401160464 Forwards generic evaluation of radiological consequences of accidents while purging or venting at power Generic review applicable to facility Response to 831201 ltr will be last part of review
 VASSALLO, D B Operating Reactors Branch 2 83/12/22 UTLEY, E E
 Carolina Power & Light Co 4pp 21824 295 24X
 Fiche 50-324, 83/12/22, 8401160464

8401230402 Forwards Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively & safety evaluation Amends authorize changes to implement requirements of App I, establish new limiting conditions for operation & revise environ programs
 VASSALLO, D B Operating Reactors Branch 2 83/12/27 UTLEY, E E
 Carolina Power & Light Co 2pp 21905 047 24X
 Fiche 50-324, 83/12/27, 8401230602

--8401230615 Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively, authorizing changes to implement requirements of App I, establishing new limiting conditions for operation & revising environ monitoring programs
 VASSALLO, D B Operating Reactors Branch 2 83/12/27 247pp
 21905 047 24X Fiche 50-324, 83/12/27, 8401230602

--8401230626 Safety evaluation supporting Amends 62 & 88 to Licenses DPR-71 & DPR-62, respectively
 * Office of Nuclear Reactor Regulation, Director 83/12/27 6pp
 21905 276 24X Fiche 50-324, 83/12/27, 8401230602

--8404070498 "Radiological Effluent Tech Spec Implementation (A, 2), Carolina Power & Light Co Brunswick Steam Electric Plant Units 1 & 2," technical evaluation rept
 CHEN, B. PANDEY, F. Franklin Institute/Franklin Research Center
 NRC-03-81-120 TER-C5504-85/86 83/03/29 CONGEL, F., WILLIS, C
 NRC - No Detailed Affiliation Given 34pp 21905 302 24X
 Fiche 50-324, 83/12/27, 8401230602

8401200016 Forwards Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively & safety evaluation Amends add limiting conditions for operation & surveillance requirements for reactor protection sys electrical power supplies
 VASSALLO, D B Operating Reactors Branch 2 83/12/28 UTLEY, E E
 Carolina Power & Light Co 14pp 21871 119 24X
 Fiche 50-324, 83/12/28, 8401200016

--8401200020 Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively, adding limiting conditions for operation & surveillance requirements for reactor protection sys electrical power supplies
 VASSALLO, D B Operating Reactors Branch 2 83/12/28 9pp
 21871 121 24X Fiche 50-324, 83/12/28, 8401200016

--8401200026 Safety evaluation supporting Amends 64 & 89 to Licenses DPR-71 & DPR-62, respectively
 * Office of Nuclear Reactor Regulation, Director 83/12/28 2pp
 21871 131 24X Fiche 50-324, 83/12/28, 8401200016

8401260246 Forwards Amend 63 to License DPR-71 & safety evaluation Amend deletes requirements for seismic snubbers on removed control rod drive return line piping
 GROTEHUIS, M Operating Reactors Branch 2 83/12/28 UTLEY, E E
 Carolina Power & Light Co 2pp 21992 075 24X
 Fiche 50-325, 83/12/28, 8401260246

--8401260255 Amend 63 to License DPR-71, deleting requirements for seismic snubbers on removed control rod drive return line piping & adding requirements re operability, response time & surveillance of instrumentation
 VASSALLO, D B Operating Reactors Branch 2 83/12/28 16pp
 21992 077 24X Fiche 50-325, 83/12/28, 8401260246

--8401260261 Safety evaluation supporting Amend 63 to License DPR-71
 * Office of Nuclear Reactor Regulation, Director 83/12/28 4pp
 21992 073 24X Fiche 50-325, 83/12/28, 8401260246

8401050198 Suppl to 810728 & 821210 applications for amends to Licenses DPR-71 & DPR-62, incorporating corporate & plant organizational changes
 HOWE, P W Carolina Power & Light Co 83/12/29 VASSALLO, D B
 Operating Reactors Branch 2 26pp 21730 001 24X
 Fiche 50-324, 83/12/29, 8401050198

--8401050219 Proposed Tech Specs re changes to administrative controls
 * Carolina Power & Light Co 83/12/29 78pp 21730:030 24X
 Fiche 50-324, 83/12/29, 8401050198

DOCKETED ITEMS

173

B401270537 Forwards exemption from certain requirements of 10CFR50.44 (c) re combustible gas control
EISENHUT, D G Division of Licensing 83/12/29 UTLEY, E E
Carolina Power & Light Co 2pp 22000 343 24X
Fiche: 50-324, 83/12/29, B401270537

--B401270541 Exemption from requirements of 10CFR50.44(c) re combustible gas control Means for controlling combustible gas for interim operation through B40630 acceptable
EISENHUT, D G Division of Licensing 83/12/29 Carolina Power & Light Co 4pp 22000 343 24X Fiche 50-324, 83/12/29, B401270537

B401130250 Forwards proprietary & nonproprietary response to NRC B31101 request for addl info, amending topical repts re BWR steady-state analysis methods Affidavit requesting proprietary info be withheld (ref 10CFR2 790) encl
ZIMMERMAN, S R Carolina Power & Light Co 84/01/03 VASSALLO, D B Operating Reactors Branch 2 13pp 21801 001 24X
Fiche 50-324, 84/01/03, B401130250

--B401130257 Amend 1 to Topical Rept NF-1583 01-1, "Description & Validation of Steady-State Analysis Methods for BWRs"
W/nine oversize figures Aperture cards are available in PDR
QITNICK, B J Carolina Power & Light Co NF-1583 01-1 83/12/22 32pp 21801 014 24X Fiche 50-324, 84/01/03, B401130250

--B401130246 Nonproprietary Amend 1 to Topical Rept NF-1583 02-1, "Methods of Record LWR Fuel Assembly Burnup Code"
QITNICK, B J Carolina Power & Light Co NF-1583 02-1 (NP) 83/12/22 40pp 21801 047 24X Fiche 50-324, 84/01/03, B401130250

--B401130283 Nonproprietary Amend 1 to Topical Rept NF-1583 03-1, "Methods of PRESTD-D Three-Dimensional, BWR Core Simulation Code"
QITNICK, B J Carolina Power & Light Co NF-1583 03-1 (NP) 83/12/23 26pp 21801 087 24X Fiche 50-324, 84/01/03, B401130250

B401100283 Forwards Rev B to Training Instruction, Vol I TI-200, "Plant Operator Retraining Program" for approval Rev describes use of simulator for retraining
HOWE, P W Carolina Power & Light Co 84/01/04 VASSALLO, D B Operating Reactors Branch 2 2pp 21758 226 24X
Fiche 50-324, 84/01/04, B401100283

--B401100289 Rev B to Training Instruction TI-200, Vol I, "Plant Operator Retraining Program"
HOPKINS, P C, CHA, J W Carolina Power & Light Co 83/11/22 13pp 21758 226 24X Fiche 50-324, 84/01/04, B401100283

B401200118 Notifies of completion of TMI Action Items II K 3 30 & II, K 3, 31 based on NRC B31213 acceptance of GE small break LOCA model for use in plant analysis Requests confirmation of model use
VASSALLO, D B Operating Reactors Branch 1 84/01/04 UTLEY, E E Carolina Power & Light Co 2pp 21872 173 24X
Fiche 50-324, 84/01/04, B401200118

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401100373 Describes util method for complying w/draft implementation guidelines for 10CFR61 Impell Corp WASTETRAK computer program will be utilized for waste classification
CUTTER, A B Carolina Power & Light Co 84/01/05 EISENHUT, D G Division of Licensing 1p 21763 290 24X Fiche 50-000, 84/01/05, B401100373

B401190020 Notification of B40202 meeting w/util in Bethesda, MD to discuss status of equipment environ qualification Agenda encl
GROTHENHUIS, M Operating Reactors Branch 2 84/01/05 VASSALLO, D B Operating Reactors Branch 2 3pp 21870 311 24X
Fiche: 50-324, 84/01/05, B401190020

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche: 50-000, 84/01/06, B401090221

B401200232 Responds to FOIA request for correspondence between NRC & util re facility in Southport, NC Forwards App A documents.
FELTON, J M Division of Rules and Records 84/01/06 BELEW, R H Star-News Newspapers, Wilmington, NC 2pp 21887 286 24X
Fiche 50-324, 84/01/06, B401200232

--B401200234 FOIA request for NRC recent order requiring util to meet testing requirements at Southport generating plant or take unit out of operation & correspondence requiring util to meet safety stds per Reg Guide 1.118
BELEW, R H Star-News Newspapers, Wilmington, NC 83/12/07 NRC
- No Detailed Affiliation Given 2pp 21887 286 24X
Fiche 50-324, 84/01/06, B401200232

--B401230048 Forwards intergranular stress corrosion cracking insp order confirming shutdown of plant
VASSALLO, D B Operating Reactors Branch 2 83/08/26 UTLEY, E E Carolina Power & Light Co 2pp 21887 290 24X
Fiche 50-324, 84/01/06, B401200232

B401250446 Forwards Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively & safety evaluation Amends change Tech Specs to provide limited flexibility in scheduling containment leak testing surveillance consistent w/planned outages
GROTHENHUIS, M Operating Reactors Branch 4 84/01/11 UTLEY, E E Carolina Power & Light Co 2pp 21949 006 24X
Fiche 50-324, 84/01/11, B401250446

--B401250450 Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively, changing Tech Specs to provide limited flexibility in scheduling containment leak testing surveillance consistent w/planned outages
VASSALLO, D B Operating Reactors Branch 2 84/01/11 14pp 21949 008 24X Fiche 50-324, 84/01/11, B401250446

--B401250458 Safety evaluation supporting Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/11 2pp 21949 022 24X Fiche 50-324, 84/01/11, B401250446

B401170181 Informs that util will not be able to respond to draft technical evaluation rept open items re control of heavy loads within recommended time Frame Responses to open items will be provided by B40203
ZIMMERMAN, S R Carolina Power & Light Co 84/01/12 VASSALLO, D B Operating Reactors Branch 2 1p 21834 152 24X
Fiche 50-324, 84/01/12, B401170181

B401170245 Responds to B31216 request for addl info re fast cold starts of diesel generators, per Generic Ltr B3-41 Diesel generators not subj to fast cold starts as described Total number of diesel generator starts from B21201-B31130 listed
ZIMMERMAN, S R Carolina Power & Light Co 84/01/12 EISENHUT, D G Division of Licensing 3pp 21832 242 24X Fiche 50-324, 84/01/12, B401170245

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

0 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 103pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401050454 Forwards IE Insp Repts 50-324/83-38 & 50-325/83-38 on B31103-04 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/01 UTLEY, E E Carolina Power & Light Co 2pp 21730 143 24X
Fiche 50-324, 83/12/01, B401050454

--B401050457 IE Insp Repts 50-324/83-38 & 50-325/83-38 on B31103-04 No violations noted Major areas inspected respiratory protection & external exposure control
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/30 5pp 21730 145 24X Fiche 50-324, 83/12/01, B401050454

B401050378 Forwards IE Insp Repts 50-324/83-39 & 50-325/83-39 on B31019-1115 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/06 UTLEY, E E Carolina Power & Light Co 2pp 21731 001 24X
Fiche 50-324, 83/12/06, B401050378

DOCKETED ITEMS

- B401050380 IE Insp Repts 50-324/83-39 & 50-325/83-39 on 831015-1115 No violations noted Major areas inspected surveillance, maint, operational safety verification, ESF walkdown, in-office LER review & independent insp
MYERS, D O, GARNER, L W Region 2, Office of Director BEMIS, P R
Division of Project & Resident Programs 83/12/05 8pp
21731 003 24X Fiche 50-324, 83/12/06, B401050378
- B401050336 Forwards IE Insp Repts 50-324/83-36 & 50-325/83-36 on 831114-18 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/08
UTLEY, E E Carolina Power & Light Co 2pp 21727 145 24X
Fiche 50-324, 83/12/08, B401050336
- B401050338 IE Insp Repts 50-324/83-36 & 50-325/83-36 on 831114-18 No noncompliance noted Major areas inspected areas of IE
Bulletin 83-02 re inservice insp work & recirculation sys
piping repair welding
COLEY, J L Region 2, Office of Director BLAKE, J J Division of
Emergency Preparedness & Materials Safety 83/12/06 4pp
21727 147 24X Fiche 50-324, 83/12/08, B401050336
- B401050478 Suppls 830608 response to IE Bulletin 83-03 re check valve
failures in raw water cooling sys of diesel generators
Periodic testing of valves incorporated into Procedure
HI-10-521 Initial insps completed 831113 Item closed
HOWE, P W Carolina Power & Light Co 83/12/13 O'REILLY, J P
Region 2, Office of Director 1p 21730 125 24X
Fiche 50-324, 83/12/13, B401050478
- B401050131 Forwards IE Insp Repts 50-324/83-40 & 50-325/83-40 on 831114-18 No violation noted
VERRELLI, D M Division of Project & Resident Programs 83/12/14
UTLEY, E E Carolina Power & Light Co 2pp 21750 320 24X
Fiche 50-324, 83/12/14, B401050131
- B401050138 IE Insp Repts 50-324/83-40 & 50-325/83-40 on 831114-18 No violation noted Major areas inspected respiratory
protection, external dose control, HEPA & charcoal filter
testing, receipt of radioactive matl & radwaste generation
ALBRIGHT, R W Region 2, Office of Director BARR, K P Division
of Engineering & Operational Programs 83/12/12 5pp 21750 322
24X Fiche 50-324, 83/12/14, B401050131
- B401050481 Ack receipt of 831207 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-324/83-32 &
50-325/83-32 Implementation of corrective actions will be
examined during future insps
LEWIS, R C Division of Project & Resident Programs 83/12/19
UTLEY, E E Carolina Power & Light Co 1p 21726 021 24X
Fiche 50-324, 83/12/19, B401050481
- B401050490 Responds to NRC 831107 ltr re violations noted in IE Insp
Repts 50-324/83-32 & 50-325/83-32 Corrective actions real-
time training provided to operating shift personnel re
Operating Instruction DI-13
HOWE, P W Carolina Power & Light Co 83/12/07 O'REILLY, J P
Region 2, Office of Director 2pp 21726 022 24X
Fiche 50-324, 83/12/19, B401050481
- B401050510 Forwards IE Insp Repts 50-324/83-32 & 50-325/83-32 on 830815-0923 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07
UTLEY, E E Carolina Power & Light Co 2pp 21726 024 24X
Fiche 50-324, 83/12/19, B401050481
- B401050514 Notice of violation from insp on 830815-0923
* Region 2, Office of Director 83/11/07 1p 21726 026 24X
Fiche 50-324, 83/12/19, B401050481
- B401050525 IE Insp Repts 50-324/83-32 & 50-325/83-32 on 830815-0923
Violation noted, failure to implement Operating Instruction
OI-13 re valve & electrical lineup verification
MYERS, D O, GARNER, L W Region 2, Office of Director BEMIS, P R
Division of Project & Resident Programs 83/10/25 9pp
21726 027 24X Fiche 50-324, 83/12/19, B401050481
- B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090
- B401060424 Ack receipt of 831222 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-324/83-34 &
50-325/83-34
VERRELLI, D M Division of Project & Resident Programs 83/12/29
UTLEY, E E Carolina Power & Light Co 1p 21741 063 24X
Fiche 50-324, 83/12/29, B401060424
- B401060426 Responds to NRC 831111 ltr re violations noted in IE Insp
Repts 50-324/83-34 & 50-325/83-34 Corrective actions
as-built guidelines will be incorporated into engineering
support unit by 840115
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21741 064 24X
Fiche 50-324, 83/12/29, B401060424
- B401060427 Forwards IE Insp Repts 50-324/83-34 & 50-325/83-34 on 830915-1015 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/11/21
UTLEY, E E Carolina Power & Light Co 10pp 21741 067 24X
Fiche 50-324, 83/12/29, B401060424
- B401060429 Notice of violation from insp on 830915-1015
* Region 2, Office of Director 83/11/21 1p 21741 069 24X
Fiche 50-324, 83/12/29, B401060424
- B401060432 IE Insp Repts 50-324/83-34 & 50-325/83-34 on 830915-1015
Noncompliance noted failure to establish document control
procedures for Drawing FP9527-50017-2, Sheet B, Rev A
MYERS, D O, GARNER, L W, BEMIS, P R Region 2, Office of Director
83/11/18 7pp 21741 070 24X Fiche 50-324, 83/12/29, B401060424
- B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093
- B401240490 Ack receipt of 830923 & 1207 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-324/83-23 & 50-325/83-23
O'REILLY, J P Region 2, Office of Director 84/01/06 UTLEY, E E
Carolina Power & Light Co 1p 21920 083 24X
Fiche 50-324, 84/01/06, B401240490
- B401240498 Suppls 830923 response to NRC 830825 ltr re violations noted
in IE Insp Repts 50-324/83-23 & 50-325/83-23 Corrective
actions procedure to ensure revs to certificates of
compliance identified implemented on 831018
DIETZ, C R Carolina Power & Light Co 83/12/07 O'REILLY, J P,
Region 2, Office of Director 1p 21920 084 24X
Fiche 50-324, 84/01/06, B401240490
- B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104
- B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107
- B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114
- B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators." Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116
- B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117
- R Periodic operating reports & related correspondence
- B401250172 Annual rept of changes, tests & experiments for 1982, per
10CFR50.59 W/B31027 ltr
DIETZ, C R Carolina Power & Light Co 82/12/31 O'REILLY, J P
Region 2, Office of Director 367pp 21937 162 24X
Fiche 50-324, 82/12/31, B401250172
- B401030248 Nonroutine 30-day Radiological Environ Event Rept 2-SR-83-32
re gamma analysis results of bottom sediment sample Co-60
activity increased by factor of 10 above MDA
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21681 006 24X
Fiche 50-324, 83/12/22, B401030248

DOCKETED ITEMS

175

B40110233 Monthly operating repts for Dec 1983 W/840104 ltr
HARRISON, F., DIETZ, C R Carolina Power & Light Co 83/12/31
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 10pp 21772 313 24X Fiche 50-324, 83/12/31,
B40110233

S Reportable occurrences, LERs & related correspondence

B401030145 LER 83-057/03L-0 on 831119, primary containment multipoint
temp recorder 1-CAC-TR-1258 showed temp indications, but
printed erratically Caused by dirty electrical contacts in
recorder control board timing relay W/831219 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/19
O'REILLY, J P Region 2, Office of Director 2pp 21683 208 24X
Fiche 50-325, 83/12/19, B401030145

B401030257 LER 83-054/03L-0 on 831119, routine surveillance revealed
that Div I primary containment atmosphere oxygen/hydrogen
analyzer not showing expected decrease in oxygen
concentration Caused by worn seals W/831219 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/19
O'REILLY, J P Region 2, Office of Director 2pp 21680 360 24X
Fiche 50-325, 83/12/19, B401030257

B401030062 LER 83-059/03L-0 on 831122, RHR svc water pump 1C tripped
immediately after starting Cause unknown Pump suction
aligned to svc water conventional header No further action
planned. W/831221 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/21
O'REILLY, J P Region 2, Office of Director 2pp 21683 099 24X
Fiche 50-325, 83/12/21, B401030062

B401030190 LER 83-052/03L-0 on 831122, while performing operability
test, control room indicators CAC-LI-2601-1 & LI-4177 &
remote shutdown panel CAC-LI-3342 showed level indication -
2 1/2 inches Caused by cracked open drain valve W/831222 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/22
O'REILLY, J P Region 2, Office of Director 3pp 21683 072 24X
Fiche 50-325, 83/12/22, B401030190

B401030248 Nonroutine 30-day Radiological Environ Event Rpt 2-BR-83-32
re gamma analysis results of bottom sediment sample Co-60
activity increased by factor of 10 above MDA.
DIETZ, C R Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21681 006 24X
Fiche 50-324, 83/12/22, B401030248

B401030327 LER 83-056/03L-0 on 831127, control board position indication
problems identified in control rods 14-19, 22-03 & 38-31
Caused by defective position indication probe connectors or
reed switches in subj rods W/831222 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/22
O'REILLY, J P Region 2, Office of Director 2pp 21680 139 24X
Fiche 50-325, 83/12/22, B401030327

B401040315 LER 83-061/03L-0 on 831127, reactor power intermediate-range
monitor C51-IRM-K601H determined inoperable due to downscale
indications Caused by signal preamplifier low/high range
gain of K601H out of adjustment W/831227 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/27
O'REILLY, J P Region 2, Office of Director 2pp 21708 031 24X
Fiche 50-325, 83/12/27, B401040315

B401050438 LER 83-055/03L-0 on 831129, reactor water sample outboard
primary containment isolation valve B32-F020 discovered not
fully closed w/valve pneumatic operator Caused by actuator
spring out of adjustment Spring replaced W/831229 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/29
O'REILLY, J P Region 2, Office of Director 2pp 21729 339 24X
Fiche 50-325, 83/12/29, B401050438

B401060361 LER 83-063/03L-0 on 831203, reactor water cleanup sys
differential flow indicator 1-031-R615 displayed erroneous
flow indication Spurious leak hi-hi alarm annunciated on
831207, Caused by trapped air in sensing lines. W/831230 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 83/12/30
O'REILLY, J P Region 2, Office of Director 3pp 21741 163 24X
Fiche 50-325, 83/12/30, B401060361

B401130255 LER 83-062/03L-0 on 831206, exhaust ventilation radiation
high instrument 1-D12-RM-N010B actuated at setpoint of
13 m/h. Caused by instrument setpoint drift. Adjustments
made W/840105 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 84/01/05
O'REILLY, J P Region 2, Office of Director 3pp 21800 330 24X
Fiche 50-325, 84/01/05, B401130255

B401170132 Updated LER 83-045/03L-1 on 830919, inboard PCIV E51-F007
steam supply to RCIC sys would not completely reopen,
indicating dual open-close position Caused by loose
limb torque motor operator spring pack W/840109 ltr
ALLEN, M T., DIETZ, C R Carolina Power & Light Co 84/01/09
O'REILLY, J P Region 2, Office of Director 3pp 21833 357 24X
Fiche 50-325, 84/01/09, B401170132

B401230283 LER 83-050/03L-0 on 831212, RHR sys flow indication signal
converter 1-C11-FY-333B could not be calibr due to
fluctuating instrument output signal Caused by cold solder
joint Solder joint repaired W/840111 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 84/01/11
O'REILLY, J P Region 2, Office of Director 2pp 21884 201 24X
Fiche 50-325, 84/01/11, B401230283

B401240003 RD 2-BR-83-36 bottom sediment sample gamma analysis
collected on 831201 detected abnormal Co-60 concentration
Sampling frequency increased to monthly to closely monitor
Co-60 activity
DIETZ, C R Carolina Power & Light Co 84/01/12 O'REILLY, J P
Region 2, Office of Director 2pp 21912 300 24X
Fiche 50-324, 84/01/12, B401240003

B401230406 Informs of revised schedule for submission of cause of
RO-2-B3-95 re fire penetration designs Current status
investigation to be completed by 840131
DIETZ, C R Carolina Power & Light Co 84/01/13 O'REILLY, J P
Region 2, Office of Director 1p 21879 122 24X
Fiche 50-324, 84/01/13, B401230406

B401240019 LER 83-060/03L-0 on 831217, remote shutdown panel
C32-PI-3332 showed pressure of 860 psi while redundant
control room instrumentation showed expected pressure of
790 psi Caused by failed electrical capacitor W/840116 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 84/01/16
O'REILLY, J P Region 2, Office of Director 3pp 21912 294 24X
Fiche 50-325, 84/01/16, B401240019

B401260019 LER 83-064/03L-0 on 831228, square root integrator
016-FYQ-K603 functioned out of calibr tolerance Caused by
instrument drift of FYQ-K603 square root transmitter (SIT)
card SIT card adjusted W/840117 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 84/01/17
O'REILLY, J P Region 2, Office of Director 2pp 21956 310 24X
Fiche 50-325, 84/01/17, B401260019

B401260039 LER 83-030/03L-0 on 831221, measured specific gravity of
pilot cell for Div I battery 1A-1 found below Tech Spec min
Caused by battery not being fully charged Battery recharged
& surveillance procedures revised W/840117 ltr
PASTVA, M J., DIETZ, C R Carolina Power & Light Co 84/01/17
O'REILLY, J P Region 2, Office of Director 2pp 21956 360 24X
Fiche 50-325, 84/01/17, B401260039

B401260351 RO on 831212, double Fire Door 110 declared inoperable
because of encountered high differential air pressure across
door, preventing automatic self-closure Plant engineer
requested to evaluate problem
DIETZ, C R Carolina Power & Light Co 84/01/18 O'REILLY, J P
Region 2, Office of Director 1p 21955 157 24X
Fiche 50-325, 84/01/18, B401260351

X Onsite Storage of Low Level Waste

B401130335 Confirms 831214 telcon w/PH Lohaus re errors found in
Paragraph 41 55(a)(7) of 10CFR61 statement on waste form
classification Util interpretation of paragraph stated
ZIMMERMAN, S R Carolina Power & Light Co 84/01/09 EISENHUT, D G
Division of Licensing 1p 21801 201 24X Fiche 50-000, 84/01/09,
B401130335

DOCKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES REACTOR

Q Inspection Reports, IE Bulletins & correspondence

B401300253 Forwards IE Insp Rpt 50-326/83-01 on 831207-09 & notice of
violation
SCARAND, R A Division of Radiological Safety & Safeguards Program
84/01/18 LILLYMAN, W J California, Univ of, Irvine, CA 2pp
21998 300 24X Fiche 50-326, 84/01/18, B401300253

--B401300255 Notice of violation from insp on 831207-09
WENSLAWSKI, F A Region 3, Office of Director 84/01/18 1p
21998 302 24X Fiche 50-326, 84/01/18, B401300255

--B401300258 IE Insp Rpt 50-326/83-01 on 831207-09 Noncompliance noted
failure to conduct Tech Spec Reactor Operations Committee
quarterly meeting
GILLIS, M., WENSLAWSKI, F A Region 3, Office of Director
84/01/12 7pp 21998 303 24X Fiche 50-326, 84/01/18, B401300258

DOCKETED ITEMS

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8401060077 Releases public version of revised radiological emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21747 120 24X Fiche 50-327, 83/12/28,
8401060077

--8401060101 Public version of Rev 5 to radiological emergency plan w/
831216 ltr
MILLS, L M Tennessee Valley Authority 83/12/06 O'REILLY, J P
Region 2, Office of Director 7pp 21747 121 24X
Fiche 50-327, 83/12/28, 8401060077

8401240522 Forwards rev to physical security plan Rev withheld (ref
10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/12/30 O'REILLY, J P
Region 2, Office of Director 1p 21718 142 24X
Fiche 50-327, 83/12/30, 8401240522

8401050346 Forwards IE Safeguards Insp Repts 50-327/83-30 &
50-328/83-30 on 831128-1208 No violations noted
VERRELLI, D M Division of Project & Resident Programs 84/01/03
PARRIS, H G Tennessee Valley Authority 2pp 21729 251 24X
Fiche 50-327, 84/01/03, 8401050346

--8401050352 IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on
831128-1208 No noncompliance noted Major areas inspected
alleged improper security practices re escort procedures
Details withheld (ref 10CFR2 790 & 10CFR73 21)
MOORE, D E Region 2, Office of Director MCGUIRE, D R Division
of Emergency Preparedness & Materials Safety 83/12/29 1p
21729 253 24X Fiche 50-327, 84/01/03, 8401050346

8401090372 Forwards safety analysis for safety parameter display sys
per 830415 commitment re Generic Ltr 82-33, Suppl 1 to
NUREG-0737, "Requirements for Emergency Response
Capability" Verification & Validation plan encl
MILLS, L M Tennessee Valley Authority 84/01/04 ADENSAH, E
Licensing Branch 4 20pp 21750 279 24X Fiche 50-327, 84/01/04,
8401090372

8401170215 Ack receipt of 831018 ltr re 830815 rev to security
personnel training & qualification plan Change inconsistent
w/10CFR50 54 provisions Commitments in previously approved
plan must be followed Encl withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/10
PARRIS, H G Tennessee Valley Authority 2pp 21833 290 24X
Fiche 50-327, 84/01/10, 8401170215

8401310126 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22026 351 24X Fiche 50-327, 84/01/18,
8401310126

--8401310135 Forwards public version of revised Emergency Plan
Implementing Procedures SGN-IP-6 re activation of technical
support ctr & SGN-IP-1 re emergency plan classification
logic
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 1p 22026 352 24X
Fiche 50-327, 84/01/18, 8401310126

--8401310147 Public version of revised Emergency Plan Implementing
Procedures SGN-IP-6 re activation of technical support ctr
& SGN-IP-1 re emergency plan classification logic
FORTENBERRY, R , OSBORNE, J D , NIBLES, L M Tennessee Valley
Authority 83/12/16 7pp 22026 353 24X Fiche 50-327, 84/01/18,
8401310126

8401250110 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 079 24X Fiche 50-000, 84/01/20,
8401250110

--8401250118 Forwards public version of revised emergency plan
implementing procedures, including Procedure MSEC IP-6,
"Emergency Preparedness" & DNEC-IP-7, "Procedure for
Performance of Assessment Team Function"
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080
24X Fiche 50-000, 84/01/20, 8401250110

--8401250126 Public version of revised emergency plan implementing
procedures, including Procedures MSEC IP-6, "Emergency
Preparedness" & DNEC-IP-7, "Procedure for Performance of
Assessment Team Function"
MAXWELL, R D Tennessee Valley Authority 83/11/10 34pp
21959 081 24X Fiche 50-000, 84/01/20, 8401250110

H General correspondence

8401040304 Designates MP Schmierback, RJ Johnson & DM McCarthy as
acting officials during author absence
BRUCH, A Tennessee Valley Authority 83/12/29 MARLAR, J
Environmental Protection Agency 1p 21707 299 24X
Fiche 50-327, 83/12/29, 8401040304

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II
KAMMER, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I
PARRIS, H G Tennessee Valley Authority 84/01/12 75pp
21865 002 24X Fiche 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II
PARRIS, H G Tennessee Valley Authority 84/01/12 96pp
21865 077 24X Fiche 50-000, 84/01/12, 8401200194

O Advisory Committee on Reactor Safeguards reports & correspondence

8401310513 Submits observations & opinions re hydrogen control in ice
condenser containment of Sequoyah reactor, based on
evaluation of info gathered
SCHOTT, G L Los Alamos Scientific Laboratory SCHOTT, G L ACRS -
Advisory Committee on Reactor Safeguards 81/05/07 MARK, J C ACRS -
Advisory Committee on Reactor Safeguards 7pp 22036 345 24X
Fiche 50-327, 81/05/07, 8401310513

8401130361 Summary of ACRS Sequoyah Subcommittee 821207 meeting w/YVA,
NRR & RES re proposed hydrogen control sys
+ ACRS - Advisory Committee on Reactor Safeguards 83/01/17
ACRS - Advisory Committee on Reactor Safeguards 19pp 21817 305
24X Fiche 50-327, 83/01/17, 8401130361

P Operating license stage documents & correspondence

8401040384 Requests continued relief from surveillance requirement for
testing containment penetration protective fuses until NRC
review of proposed Tech Specs completed NSHC involved
MILLS, L M Tennessee Valley Authority 83/12/29 ADENSAH, E
Licensing Branch 4 2pp 21706 278 24X Fiche 50-327, 83/12/29,
8401040384

8401190495 Advises of decision to refund fees associated w/830525
application for Tech Spec changes re onsite power
distribution sys, as application withdrawn
MILLER, W D License Fee Management Branch 84/01/04 PARRIS, H G
Tennessee Valley Authority 2pp 21861 346 24X
Fiche 50-327, 84/01/04, 8401190495

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs
& holders of CPs for power reactors re NRC use of terms:
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power
authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

840110004 Forwards supplemental response to TMI Action Item II K 3.5
re automatic trip of reactor coolant pumps Delays occurred
in release of Westinghouse rept re justification for
manual reactor coolant pump trip
MILLS, L M Tennessee Valley Authority 84/01/06 ADENSAH, E
Licensing Branch 4 3pp 21772 216 24X Fiche 50-327, 84/01/06,
840110004

DOCKETED ITEMS

17

8401170250 Forwards revised response to Criterion II B re 831123 proposed license amend allowing completion of mod for post-accident sampling, per NUREG-0737, Item II B 3 Isolation valves backed by Class IE power
MILLS, L M Tennessee Valley Authority 84/01/09 ADENSAM, A E Licensing Branch 4 2pp 21832 224 24X Fiche 50-327, 84/01/09, 8401170250

8401170423 Suppl 831123 application to amend Licenses DPR-77 & DPR-79, allowing completion of post-accident sampling mod per NUREG-0737, Item II B 3 Expeditions review of application requested to allow mod during Feb 1984 refueling outage
MILLS, L M Tennessee Valley Authority 84/01/10 ADENSAM, E Licensing Branch 4 2pp 21829 221 24X Fiche 50-327, 84/01/10, 8401170423

8401170400 Forwards response to Generic Ltr 83-41 re fast cold starts of diesel generators Encl table for Browns Ferry shows times surveillance testing, maint activities & actual demand caused diesel generators to start
MILLS, L M Tennessee Valley Authority 84/01/11 EISENHUT, D G Division of Licensing 3pp 21829 216 24X Fiche 50-000, 84/01/11, 8401170400

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl.
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/15 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/15, 8312120114

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310217 Forwards peaking factor limit rept for Cycle 3 operations Appropriate W(2) functions, when applied to power distribution under equilibrium conditions, demonstrate that LOCA conditions & 10CFR50.46 ECCS acceptance criteria met
MILLS, L M Tennessee Valley Authority 84/01/24 BERLINGER, C H Core Performance Branch 8pp 22021 331 24X Fiche 50-327, 84/01/24, 8401310217

8401310413 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs as result of mods to satisfy requirements of NUREG-0737, Items II B 1.11 F 1.11 F 1.3, 1.1 F 1.4 & 1.1 F 2 & diesel generator testing
MILLS, L M Tennessee Valley Authority 84/01/25 ADENSAM, E Licensing Branch 4 2pp 22019 316 24X Fiche 50-327, 84/01/25, 8401310413

--8401310425 Proposed Tech Spec changes as result of mods to satisfy requirements of NUREG-0737, Items II B 1.11 F 1.11 F 1.3, 1.1 F 1.4 & 1.1 F 2 & diesel generator testing
* Tennessee Valley Authority 84/01/25 30pp 22019 318 24X Fiche 50-327, 84/01/25, 8401310413

8401310369 Suppl to 831024 application for amend to Licenses DPR-77 & DPR-79, consisting of Tech Spec change revising allowable value to plus or minus 30 s for diesel generator start & load shed timer
KAMMER, D B Tennessee Valley Authority 84/01/26 ADENSAM, E Licensing Branch 4 1p 22018 398 24X Fiche 50-327, 84/01/26, 8401310369

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR.
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Traubridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401090267 Forwards IE Insp Repts 50-327/83-28 & 50-328/83-28 on 831114-18. No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/15 PARRIS, H Q Tennessee Valley Authority 2pp 21754 228 24X Fiche 50-327, 83/12/15, 8401090267

--8401090277 IE Insp Repts 50-327/83-28 & 50-328/83-28 on 831114-18. No violations noted Major areas inspected health physics organization, instruments & equipment, external & internal exposures, posting, radiation surveys & waste shipments
PEERY, W W Region 2, Office of Director PARRIS, H Q Division of Engineering & Operational Programs 83/12/13 7pp 21754 230 24X Fiche 50-327, 83/12/15, 8401090267

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21926 060 24X Fiche 50-000, 83/12/30, 8312120093

8401050346 Forwards IF Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on 831128-1208. No violations noted
VERRELLI, D M Division of Project & Resident Programs 84/01/03 PARRIS, H Q Tennessee Valley Authority 2pp 21729 251 24X Fiche 50-327, 84/01/03, 8401050346

--8401050352 IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on 831128-1208. No noncompliance noted Major areas inspected alleged improper security practices re escort procedures Details withheld (ref 10CFR2.790 & 10CFR73.21)
MODRE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/12/29 1p 21729 253 24X Fiche 50-327, 84/01/03, 8401050346

8401240485 Confirms 840116 enforcement conference at site to discuss recent trend of personnel error violations, per 831222 & 840104 telcons Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 84/01/06 PARRIS, H Q Tennessee Valley Authority 3pp 21918 172 24X Fiche 50-327, 84/01/06, 8401240485

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 123pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

R Periodic operating reports & related correspondence

8401120257 Monthly operating repts for Nov 1983 W/831215 ltr
MASON, C C Tennessee Valley Authority 83/11/30 Office of Resource Management, Director 24pp 21794 103 24X Fiche 50-327, 83/11/30, 8401120257

8401270481 Monthly operating repts for Dec 1983 W/840113 ltr
MASON, C C EDDINGS, H Q DUPREE, D C Tennessee Valley Authority 83/12/31 Office of Resource Management, Director 26pp 21981 315 24X Fiche 50-327, 83/12/31, 8401270481

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050064

8401050075 Responds to FOIA request for 27 LERs Forwards three listed LERs Remaining LERs unavailable in NRC records sys, canceled, or never issued
FELTON, J M Division of Rules and Records 83/10/25 GRABER, L D NUS Corp 1p 21736 343 24X Fiche 50-000, 83/10/25, 8401050075

DOCKETED ITEMS

B401030247 LER 83-177/03L-0 on 831122, diesel generator 2A-A declared inoperable due to failure to trip on demand during relay testing Cause of failure of differential relay 87A unknown Relay replaced W/831221 ltr
ROGERS, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/12/21 O'REILLY, J P Region 2, Office of Director 2pp
21691 004 24X Fiche 50-327, 83/12/21, 8401030247

B401030071 LER 83-176/03L-0 on 831124, one steam generator flow channel 1-FT-1-28A declared inoperable due to reading high Cause unknown Transmitter returned to Barton for review & repair W/831232 ltr
ROGERS, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/12/22 O'REILLY, J P Region 2, Office of Director 2pp
21693 201 24X Fiche 50-327, 83/12/22, 8401030071

B401050422 LER 83-175/03L-0 on 831124, refueling water storage tank level channel found out of Tech Spec tolerance Caused by instrument drift Transmitter recalibr W/831228 ltr
ROGERS, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority
83/12/28 O'REILLY, J P Region 2, Office of Director 2pp
21731 053 24X Fiche 50-327, 83/12/28, 8401050422

B401120336 LER 83-183/03L-0 on 831202, during stroke testing of one turbine-driven auxiliary feedwater pump, steam supply valve 1-FCV-1-18 failed to meet surveillance requirements Caused by geared limit switch failure W/831230 ltr
HARDING, M R , GREEN, H J Tennessee Valley Authority 83/12/30
O'REILLY, J P Region 2, Office of Director 2pp 21792 143 24X
Fiche 50-327, 83/12/30, 8401120336

B401120202 LER 83-178/03L-0 on 831206, waste gas decay tank Q found w/oxygen concentration 2.2%, exceeding 2% limit Cause unknown Nitrogen added to reduce concentration W/840104 ltr
KIRK, G B , HARDING, M R , COFFEY, J A Tennessee Valley Authority
84/01/04 O'REILLY, J P Region 2, Office of Director 2pp
21792 236 24X Fiche 50-327, 84/01/04, 8401120202

B401120235 LER 83-180/03L-0 on 831206, thermal overload devices on several motor-operated valves failed trip check test Caused by improperly sized thermal overload heaters Overloads replaced & satisfactorily tested W/840104 ltr
DUGGAN, G E , HARDING, M R , COFFEY, J A Tennessee Valley Authority
84/01/04 O'REILLY, J P Region 2, Office of Director 3pp
21793 308 24X Fiche 50-327, 84/01/04, 8401120235

B401120356 LER 83-182/03L-0 on 831206, essential raw cooling water pump JA time delay relay ST-1A failed SI-220 1, "Load Sequence Timer Functional Test " Caused by instrument drift Relay adjusted & returned to svc W/840104 ltr
KIRK, G B , HARDING, M R , COFFEY, J A Tennessee Valley Authority
84/01/04 O'REILLY, J P Region 2, Office of Director 2pp
21791 353 24X Fiche 50-327, 84/01/04, 8401120356

401130278 LER 83-186/03L-0 on 831209, diesel generator 1A-A tripped on high crankcase pressure Caused by improperly torqued wrist pin bolts on cylinder 8 Diesel repaired Affected parts sent to General Motors Electromotive Div for insp W/840106 ltr
COFFEY, J A Tennessee Valley Authority 84/01/06 O'REILLY, J P
Region 2, Office of Director 3pp 21800 356 24X
Fiche 50-327, 84/01/06, 8401130278

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B401060097 Releases public version of revised radiological emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21747 120 24X Fiche 50-327, 83/12/28,
8401060097

-B401060101 Public version of Rev 5 to radiological emergency plan W/831216 ltr
MILLS, L M Tennessee Valley Authority 83/12/06 O'REILLY, J P
Region 2, Office of Director 7pp 21747 121 24X
Fiche 50-327, 83/12/28, 8401060097

101240522 Forwards rev to physical security plan withheld (ref 10CFR73 21)
MILLS, L M Tennessee Valley Authority 83/12/30 O'REILLY, J P
Region 2, Office of Director 1p 21918 142 24X
Fiche 50-327, 83/12/30, 8401240522

101050346 Forwards IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on 831128-1208 No violations noted
VERRELL, D M Division of Project & Resident Programs 84/01/03
PARRIS, H G Tennessee Valley Authority 2pp, 21729 251 24X
Fiche 50-327, 84/01/03, 8401050346

--B401050352 IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on 831128-1208 No noncompliance noted Major areas inspected alleged improper security practices re escort procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
MORRE, D E Region 2, Office of Director 83/12/29 1p
21729 253 24X Fiche 50-327, 84/01/03, 8401050346

B401090372 Forwards safety analysis for safety parameter display sys per 830415 commitment re Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability " Verification & validation plan encl
MILLS, L M Tennessee Valley Authority 84/01/04 ADENBAM, E
Licensing Branch 4 20pp 21750 279 24X Fiche 50-327, 84/01/04,
8401090372

B401170215 Ack receipt of 831018 ltr re 830815 rev to security personnel training & qualification plan Change inconsistent w/10CFR50 54 provisions Commitments in previously approved plan must be followed Encl withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/10
PARRIS, H G Tennessee Valley Authority 2pp 21833 290 24X
Fiche 50-327, 84/01/10, 8401170215

B401310126 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22026 351 24X Fiche 50-327, 84/01/18,
8401310126

--B401310135 Forwards public version of revised Emergency Plan implementing procedures SQN-IP-6 re activation of technical support ctr & SQN-IP-1 re emergency plan classification logic
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 1p 22026 352 24X
Fiche 50-327, 84/01/18, 8401310126

--B401310147 Public version of revised Emergency Plan implementing procedures SQN-IP-6 re activation of technical support ctr & SQN-IP-1 re emergency plan classification logic
FORTENDERRY, R , GSBORNE, J D , NOBLES, L M Tennessee Valley
Authority 83/12/16 7pp 22026 353 24X Fiche 50-327, 84/01/18,
8401310126

B401250110 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21759 079 24X Fiche 50-000, 84/01/20,
8401250110

--B401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure MSECC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function "
MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080
24X Fiche 50-000, 84/01/20, 8401250110

--B401250126 Public version of revised emergency plan implementing procedures, including Procedures MSECC IP-6, "Emergency Preparedness" & DNPEC-IP-7, "Procedure for Performance of Assessment Team Function "
MAXWELL, R B Tennessee Valley Authority 83/11/10 34pp
21959 081 24X Fiche 50-000, 84/01/20, 8401250110

H General correspondence

B401040504 Designates MP Schmierback, RJ Johnson & DM McCarthy as acting officials during author absence
BRUCH, A Tennessee Valley Authority 83/12/29 HARLAR, J
Environmental Protection Agency 1p 21707 299 24X
Fiche 50-327, 83/12/29, 8401040504

I Financial information

B401200194 Forwards Annual Financial Rept 1982, Vols I & II.
KAMMER, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000, 84/01/12, 8401200194

--B401200197 Annual Financial Rept 1982, Vol I
PARRIS, H G Tennessee Valley Authority 84/01/12 75pp,
21865 002 24X Fiche 50-000, 84/01/12, 8401200194

--B401200206 Annual Financial Rept 1982, Vol II
PARRIS, H G Tennessee Valley Authority 84/01/12 96pp
21865 077 24X Fiche 50-000, 84/01/12, 8401200194

B Advisory Committee on Reactor Safeguards reports & correspondence

B401310513 Submits observations & opinions re hydrogen control in ice condenser containment of Sequoyah reactor, based on evaluation of info gathered
SCHOTT, O L Los Alamos Scientific Laboratory SCHOTT, O L ACRS - Advisory Committee on Reactor Safeguards 81/05/07 MARK, J C ACRS - Advisory Committee on Reactor Safeguards 7pp 22036 345 24X Fiche 50-327,81/05/07,B401310513

B401130361 Summary of ACRS Sequoyah Subcommittee 821207 meeting w/TVA, NRS & REG re proposed hydrogen control sys
* ACRS - Advisory Committee on Reactor Safeguards 83/01/17
ACRS - Advisory Committee on Reactor Safeguards 19pp 21817 305 24X Fiche 50-327,83/01/17,B401130361

P Operating license stage documents & correspondence

B401040384 Requests continued relief from surveillance requirement for testing containment penetration protective fuses until NRC review of proposed Tech Specs completed NSHC involved
MILLS, L M Tennessee Valley Authority 83/12/29 ADENSAM, E Licensing Branch 4 2pp 21706 278 24X Fiche 50-327,83/12/29, B401040384

B401190495 Advises of decision to refund fees associated w/B30525 application for Tech Spec changes re onsite power distribution sys, as application withdrawn
MILLER, W D License Fee Management Branch 84/01/04 PARRIS, H G Tennessee Valley Authority 2pp 21861 346 24X Fiche 50-327,84/01/04,B401190495

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000,84/01/05,B401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000,84/01/06,B401090221

B401110004 Forwards supplemental response to TMI Action Item II K 3 5 re automatic trip of reactor coolant pumps Delays occurred in release of Westinghouse rept re justification for manual reactor coolant pump trip
MILLS, L M Tennessee Valley Authority 84/01/06 ADENSAM, E Licensing Branch 4 3pp 21772 216 24X Fiche 50-327,84/01/06, B401110004

B401170250 Forwards revised response to Criterion II B re B31123 proposed license amend allowing completion of mod for post-accident sampling, per NUREG-0737, Item II B 3 Isolation valves backed by Class IE power
MILLS, L M Tennessee Valley Authority 84/01/09 ADENSAM, A E Licensing Branch 4 2pp 21832 224 24X Fiche 50-327,84/01/09, B401170250

B401170423 Supple B31123 application to amend Licenses DPR-77 & DPR-79, allowing completion of post-accident sampling mod per NUREG-0737, Item II B 3 Expedient review of application requested to allow mod during Feb 1984 refueling outage
MILLS, L M Tennessee Valley Authority 84/01/10 ADENSAM, E Licensing Branch 4 2pp 21829 221 24X Fiche 50-327,84/01/10, B401170423

B401170400 Forwards response to Generic Ltr 83-41 re fast cold starts of diesel generators Encl table for Browns Ferry shows times surveillance testing, maint activities & actual demand caused diesel generators to start
MILLS, L M Tennessee Valley Authority 84/01/11 EISENHUT, D O Division of Licensing 5pp 21829 216 24X Fiche 50-000,84/01/11, B401170400

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000,84/01/13,B401130084

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000,84/01/16,B312120114

B401310413 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs as result of mods to satisfy requirements of NUREG-0737, Items II B 1, II F 1, II F 1 3, II F 1 4 & II F 2 & diesel generator testing
MILLS, L M Tennessee Valley Authority 84/01/25 ADENSAM, E Licensing Branch 4 2pp 22019 316 24X Fiche 50-327,84/01/25, B401310413

--B401310425 Proposed Tech Spec changes as result of mods to satisfy requirements of NUREG-0737, Items II B 1, II F 1, II F 1 3, II F 1 4 & II F 2 & diesel generator testing
* Tennessee Valley Authority 84/01/25 30pp 22019 318 24X Fiche 50-327,84/01/25,B401310413

B401310369 Suppl to B31024 application for amend to Licenses DPR-77 & DPR-79, consisting of Tech Spec change revising allowable value to plus or minus 30 s for diesel generator start & load shed timer
HAMMER, D S Tennessee Valley Authority 84/01/26 ADENSAM, E Licensing Branch 4 1p 22018 358 24X Fiche 50-327,84/01/26, B401310369

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000,83/10/20,B401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20, B401060040

B401090267 Forwards IE Insp Repts 50-327/83-28 & 50-328/83-28 on B31114-18 No violations noted
VERRELL, D M Division of Project & Resident Programs 83/12/15 PARRIS, H G Tennessee Valley Authority 2pp 21754 228 24X Fiche 50-327,83/12/15,B401090267

--B401090277 IE Insp Repts 50-327/83-28 & 50-328/83-28 on B31114-18 No violations noted Major areas inspected: health physics organization, instruments & equipment, external & internal exposures, posting, radiation surveys & waste shipments
PEERY, W W Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/12/13 7pp 21754 230 24X Fiche 50-327,83/12/15, B401090267

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,B312120093

B401050346 Forwards IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on B31128-1208 No violations noted
VERRELL, D M Division of Project & Resident Programs 84/01/03 PARRIS, H G Tennessee Valley Authority 2pp 21729 251 24X Fiche 50-327,84/01/03,B401050346

--B401050352 IE Safeguards Insp Repts 50-327/83-30 & 50-328/83-30 on B31128-1208 No noncompliance noted Major areas inspected alleged improper security practices re escort procedures Details withheld (ref 10CFR2 790 & 10CFR73 21)
MOORE, D E Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/12/29 1p 21729 253 24X Fiche 50-327,84/01/03,B401050346

B401240485 Confirms B40116 enforcement conference at site to discuss recent trend of personnel error violations, per B31222 & B40104 telcons Proposed meeting agenda encl
O'REILLY, J P Region 2, Office of Director 84/01/06 PARRIS, H G Tennessee Valley Authority 3pp 21918 172 24X Fiche 50-327,84/01/06,B401240485

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,B312120104

DOCKETED ITEMS

012120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

012120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

012120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

Periodic operating reports & related correspondence

001120257 Monthly operating repts for Nov 1983 W/831215 ltr
MASON, C C Tennessee Valley Authority 83/11/30 Office of Resource Management, Director 24pp 21794 103 24X Fiche 50-327,83/11/30,8401120257

001270481 Monthly operating repts for Dec 1983 W/840113 ltr
MASON, C C, EDDINGS, M O, DUPREE, D C Tennessee Valley Authority 83/12/31 Office of Resource Management, Director 24pp 21981 315 24X Fiche 50-327,83/12/31,8401270481

Reportable occurrences, LERs & related correspondence

001050064 FOIA request for 27 listed LERs
GRABER, L D NUG Corp 83/10/07 Division of Rules and Records 2pp 21736 343 24X Fiche 50-000,83/10/07,8401050064

001040436 LER 83-179/03L-0 on 831203, during performance of SI-699 2, "Monthly Equipment Rotation," centrifugal charging pump 20-B failed to start Caused by broken microswitch
Microswitch replaced W/831228 ltr
KIRK, G B, HARDING, M R, GREEN, H J Tennessee Valley Authority 83/12/28 O'REILLY, J P Region 2, Office of Director 2pp 21708 084 24X Fiche 50-328,83/12/28,8401040436

01050651 LER 83-172/03L-0 on 831130, steam generator blowdown containment isolation valve 2-FCV-1-182 failed to close on demand Caused by valve limit switch misadjustment Switch adjusted & returned to svc on 831130 W/831228 ltr
KIRK, G B, HARDING, M R, GREEN, H J Tennessee Valley Authority 83/12/28 O'REILLY, J P Region 2, Office of Director 2pp 21724 267 24X Fiche 50-328,83/12/28,8401050651

001120386 LER 83-181/01T-0 on 831223, 120-volt ac vital inverter taken out of svc for instrument power board check & not returned to svc within 24 h Caused by personnel error W/840105 ltr
COFFEY, J A Tennessee Valley Authority 84/01/05 O'REILLY, J P Region 2, Office of Director 3pp 21791 318 24X Fiche 50-328,84/01/05,8401120386

001120328 LER 83-171/03L-0 on 831206, diesel generator 1A-A declared inoperable when remote speed control failed to operate properly Caused by bad winding in potentiometer drive motor Motor replaced & generator returned to svc W/840105 ltr
COOPER, M R, HARDING, M R, GREEN, H J Tennessee Valley Authority 84/01/06 O'REILLY, J P Region 2, Office of Director 2pp 21794 150 24X Fiche 50-328,84/01/06,8401120328

001120383 LER 83-185/03L-0 on 831207, glycol containment isolation valve 2-FCV-61-97 would not clear open limit switch Caused by improperly tightened bolt on limit switch mounting bracket Bolt tightened & switch adjusted W/840105 ltr
KIRK, G B, GREEN, H J Tennessee Valley Authority 84/01/06 O'REILLY, J P Region 2, Office of Director 2pp 21791 200 24X Fiche 50-328,84/01/06,8401120383

001130093 LER 83-190/03L-0 on 831211, RCB subcooling margin monitor declared inoperable due to loss of P-250 computer Computer halt caused by programmatic error Monitor returned to svc W/840104 ltr
COFFEY, J A Tennessee Valley Authority 84/01/06 O'REILLY, J P Region 2, Office of Director 2pp 21802 242 24X Fiche 50-328,84/01/06,8401130093

001170198 LER 83-184/03L-0 on 831212, lower containment personnel airlock outer door would not close Caused by failure of three cam follower bearings in mechanical linkage due to normal wear Cam follower bearings replaced W/840110 ltr
KIRK, G B, HARDING, M R, COFFEY, J A Tennessee Valley Authority 84/01/10 O'REILLY, J P Region 2, Office of Director 2pp 21831 318 24X Fiche 50-328,84/01/10,8401170198

8401260038 LER 83-188/03L-0 on 831221, during attempted load of diesel generator 1A-1, load dropped instantly to zero Caused by loose & dirty cannon plug connector on engine 1 governor Connector cleaned W/840119 ltr
DUGGIN, O E, HARDING, M R, COFFEY, J A Tennessee Valley Authority 84/01/19 O'REILLY, J P Region 2, Office of Director 2pp 21956 358 24X Fiche 50-328,84/01/19,8401260038

8401260321 LER 83-189/03L-0 on 831224, while in Mode 1, feedwater flow channel 2-FT-3-90 declared inoperable due to frozen sense line Caused by extreme low outside temp & blown fuse in heat trace circuit Fuse replaced W/840119 ltr
ROGERS, M R, HARDING, M R, COFFEY, J A Tennessee Valley Authority 84/01/19 O'REILLY, J P Region 2, Office of Director 2pp 21955 196 24X Fiche 50-328,84/01/19,8401260321

DOCKET 50-327 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8401170052 Partial response to FOIA request for 42 categories of documents Forwards listed documents Documents also available in PRR Review of addl records suby to request in progress
FELTON, J M Division of Rules and Records 83/10/03 HOLLY, S C Union of Concerned Scientists 1p 21846 163 24X Fiche 50-329,83/10/03,8401170052

--8203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NURE0-0660, Item II E 5.1, design sensitivity of B&W reactors Lists of NURE0-0667 recommendations reviewed & NRC evaluation encl
HATTSO, R Division of Systems Integration (post 811005) 82/02/26 HANAUER, S Division of Safety Technology 23pp 21846 227 24X Fiche 50-329,83/10/03,8401170052

8401250015 Partial response to FOIA request for all 1982 BECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000,83/10/18,8401250015

--8209160068 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations BECY-82-352 82/08/20 37pp 21966 035 24X Fiche 50-000,83/10/18,8401250015

8401040044 Responds to FOIA request for records re rereview of structural adequacy of diesel generator bldg at facilities subsequent to May testimony of R Landsman in ASLB proceeding
FELTON, J M Division of Rules and Records 83/10/27 GARDE, B P Government Accountability Project 3pp 21714 289 24X Fiche 50-329,83/10/27,8401040044

--8310280277 Forwards initial response to RB Landsman concerns on structural integrity of diesel generator bldg, as prepared during 830728 working meeting w/consultants J Matra & O Harstead
RINALDI, F Structural & Geotechnical Engineering Branch 83/10/21 KUO, P T Structural & Geotechnical Engineering Branch 10pp 21714 299 24X Fiche 50-329,83/10/27,8401040044

--8401040052 "Review Comments of J Kane, Diesel Generator Bldg Concerns at Midland"
KANE, J NRC - No Detailed Affiliation Given 83/10/27 5pp 21714 294 24X Fiche 50-329,83/10/27,8401040044

8401100246 Forwards corrected version of hold point 011 reported in 831114 weekly rept
BARANOW, S W Stone & Webster, Inc 83/11/17 KEPLER, J O Region 3, Office of Director 3pp 21759 225 24X Fiche 50-329,83/11/17,8401100246

8401170175 Confirms transmittal of listed PQCI &/or changes & procedures
EWERT, G F Consumers Power Co 83/11/21 BARANOW, S Stone & Webster, Inc 1p 21834 141 24X Fiche 50-329,83/11/21,8401170175

8401170164 Confirms transmittal of three computer printouts w/info on MP0AD (balance of plant) inspector records Prints include training, exams, performance demos & certifications
BOTIMER, L A Consumers Power Co 83/11/29 BARANOW, S Stone & Webster Engineering Corp 1p 21834 114 24X Fiche 50-329,83/11/29,8401170164

8401050369 Confirms transmittal of Rev 6 to C-1 31 control log for wk ending 831118 to B&W
EWERT, G F Consumers Power Co 83/11/30 BARANOW, S Stone & Webster, Inc 1p 21731 094 24X Fiche 50-329,83/11/30,8401050369

DOCKETED ITEMS

181

- 8401050434 Confirms transmittal of MPQAD Manual, F-2M
EWERT, O F Consumers Power Co 83/12/01 BARANOW, S Stone &
Webster, Inc 1p 21730 287 24X Fiche 50-329, 83/12/01, 8401050434
- 8401170167 Confirms transmittal of three computer printouts w/info on
MPQAD (balance of plant) inspector records Prints include
training, exams, performance demos & certifications
BOTIMER, L A, EWERT, O F Consumers Power Co 83/12/04 BARANOW, S
Stone & Webster, Inc 1p 21834 134 24X Fiche 50-329, 83/12/04,
8401170167.
- 8312200154 Forwards response to nine Users Group questions presented at
831130 meeting & forwarded by R Caruso 831129 ltr re standby
diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M
Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, 83/12/16, 8312200154
- 8401120273 Confirms transmittal of all controlled copies of PQCI &
changes Future rev or updates will be transmitted
EWERT, O F Consumers Power Co 83/12/16 BARANOW, S Stone &
Webster, Inc 1p 21792 162 24X Fiche 50-329, 83/12/16, 8401120273
- 8401170171 Confirms transmittal of listed Bechtel field procedures
EWERT, O F Consumers Power Co 83/12/21 BARANOW, S Stone &
Webster, Inc 1p 21834 135 24X Fiche 50-329, 83/12/21, 8401170171
- 8401050341 Presents schedule of activities for audit re lifting recent
FCR/FCN stop work orders Clear definition of packages &
schedule for audit will be provided by 831230
GUAMME, D L Consumers Power Co 83/12/22 BARANOW, S W Stone &
Webster, Inc 7pp 21727 160 24X Fiche 50-329, 83/12/22,
8401050341
- 8401050347 Requests reauthorization for remedial soils work, Items
165053050 re excavating Pier CT1 & 155053050 re excavating
Pier CT12, in accordance w/work authorization procedure
GUAMME, D L Consumers Power Co 83/12/22 HARRISON, J J Region 3,
Office of Director 1p 21729 254 24X Fiche 50-329, 83/12/22,
8401050347
- 8401050371 Forwards Bechtel 831219 ltr in response to issue re
bypassing of QC hold points Ack requested if response
acceptable
GUAMME, D L Consumers Power Co. 83/12/22 BARANOW, S W Stone &
Webster, Inc Bpp 21731 095 24X Fiche 50-329, 83/12/22,
8401050371
- 8401050647 Comments on NRC-suggested interim actions/guidelines for
maint of auxiliary bldg elevation to be employed until
840104-06 meeting to discuss upward movements & jacking of
reserve capacity loads
MOONEY, J A Consumers Power Co 83/12/22 HARRISON, J J Region 3,
Office of Director App 21735 354 24X Fiche 50-329, 83/12/22,
8401050647.
- 8401040379 Notifies of 840104 meeting w/util, NRC & Bechtel in Ann
Arbor, MI to discuss status of confirmed items & findings re
independent design & const verification program Agenda encl
LEVIN, H A TERA Corp 83/12/27 KEPLER, J G Region 3, Office of
Director, EISENHUT, D G Division of Licensing COOK, J W,
Consumers Power Co. 5pp 21706 237 24X Fiche 50-329, 83/12/27,
8401040379.
- 8401090791 Summary of 831129-30 meetings w/util & Mark Technologies
Corp re seismic portion of spatial sys interaction program
Viewgraphs encl.
HODD, D. Licensing Branch 4 83/12/27. Licensing Branch 4 44pp
21764; 248. 24X Fiche 50-329, 83/12/27, 8401090791
- 8401050393 Forwards S&W 831222 ltr re results of review of Bechtel
const training records Records for listed nonmanual
personnel satisfactory
GUAMME, D L Consumers Power Co. 83/12/28 HIERZER, O A Bechtel
Corp. App 21731 120 24X Fiche 50-329, 83/12/28, 8401050393
- 8401060343 Informs that all architectural stations ready to be
audited by S&W for vendor drawings & all remaining design/
spec exception items, per 831228 discussions
GUAMME, D L Carolina Power & Light Co 83/12/28 BARANOW, S W
Stone & Webster, Inc. 1p 21741; 177 24X Fiche 50-329, 83/12/28,
8401060343
- 8401100384 Notifies of weekly distribution for listed MPQAD personnel
printouts covering inspector training & personnel forms
EWERT, O F, BOTIMER, L A Consumers Power Co 83/12/28 BARANOW, S
Stone & Webster Engineering Corp. 1p. 21764, 001 24X
Fiche: 50-329, 83/12/28, 8401100384
- 8401100286 Advises that MPQAD audit of Civil Stations 8, 10, 13, 24 & 64
completed & ready for S&W final audit w/successful
audit completion, stop work on soils activities will be
lifted
GUAMME, D L Consumers Power Co 83/12/29 BARANOW, S W Stone &
Webster, Inc 1p 21758 242 24X Fiche 50-329, 83/12/29, 8401100286
- 8401100379 Forwards proposed list of work for Jan 1984 & supplemental
work activity list for Feb 1984 for remedial soils work
Review & authorization requested
GUAMME, D L Consumers Power Co 83/12/29 HARRISON, J J Region 3,
Office of Director 13pp 21764 002 24X Fiche 50-329, 83/12/29,
8401100379
- 8401130102 Forwards TM Novak ltr to JP McLaughy re series of
questions on emergency diesel generators mfg by
Transamerica Delaval, Inc Response may be submitted by ref to
owners group or plant-specific repts w/o encl
ADENBAM, E G Licensing Branch 4 83/12/29 COOK, J W Consumers
Power Co 1p 21821 124 24X Fiche 50-329, 83/12/29, 8401130102
- 8401100237 Advises that civil stations ready to be audited for vendor
drawings, design drawings & specs
GUAMME, D L Consumers Power Co 83/12/30 BARANOW, S W Stone &
Webster, Inc 1p 21759 185 24X Fiche 50-329, 83/12/30, 8401100237
- 8401100357 Advises that drawing review proposed cannot presently be
performed due to incomplete mechanical drawing register
GUAMME, D L Consumers Power Co 83/12/30 BARANOW, S W Stone &
Webster, Inc 1p 21764 104 24X Fiche 50-329, 83/12/30, 8401100357
- 8401120387 Forwards 831229 ltr from Bechtel re five unsatisfactory
training level assignments identified in NIR-008 Scheduled
date for completing review of entire matrix & issuing new
rev will be mid-Jan 1984
GUAMME, D L Consumers Power Co 84/01/03 BARANOW, S W Stone &
Webster, Inc 3pp 21791 321 24X Fiche 50-329, 84/01/03,
8401120387
- 8401060281 Forwards "Midland Independent Design & Const Verification
Program Structural Evaluation of Diesel Generator Bldg "
LEVIN, H A TERA Corp 84/01/04 EISENHUT, D G Division of
Licensing KEPLER, J G Region 3, Office of Director COOK, J W
Consumers Power Co 2pp 21741 291 24X Fiche, 50-329, 84/01/04,
8401060281
- 8401060294 "Midland Independent Design & Const Verification Program
Structural Evaluation of Diesel Generator Bldg "
LEVIN, H A TERA Corp 84/01/04 46pp 21741 294 24X
Fiche 50-329, 84/01/04, 8401060281
- 8401060464 Lists critical work activities authorized for Jan 1984
HARRISON, J J Region 3, Office of Director 84/01/04 GUAMME, D L
Consumers Power Co 2pp 21739 357 24X Fiche 50-329, 84/01/04,
8401060464
- 8401120206 Confirms transmittal of listed stop work orders
EWERT, O F Consumers Power Co 84/01/04 BARANOW, S Stone &
Webster, Inc 1p 21792 240 24X Fiche 50-329, 84/01/04, 8401120206
- 8401120274 Forwards listed MPQAD quality action requests corresponding
to S&W nonconformance identification repts
GUAMME, D L Consumers Power Co 84/01/04 BARANOW, S W Stone &
Webster, Inc 15pp 21794 001 24X Fiche 50-329, 84/01/04,
8401120274
- 8401120339 Forwards "Structural Evaluation of Midland Diesel Generator
Bldg Assessment of Structural Performance Capability &
Serviceability as Potentially Affected by Settlement Induced
Cracking " Significant cracking not anticipated
LEVIN, H A TERA Corp 84/01/04 KEPLER, J G Region 3, Office of
Director COOK, J W Consumers Power Co EISENHUT, D G Division of
Licensing 3pp 21793 171 24X Fiche 50-329, 84/01/04, 8401120339
- 8401120351 "Structural Evaluation of Midland Diesel Generator Bldg
Assessment of Structural Performance Capability &
Serviceability as Potentially Affected by Settlement Induced
Cracking "
* TERA Corp 84/01/04 47pp 21793 174 24X
Fiche: 50-329, 84/01/04, 8401120339
- 8401120426 Notifies of placement on weekly distribution for printouts
of summary of inspector training, personnel forms & item
complete forms
BOTIMER, L A Consumers Power Co 84/01/04 BARANOW, S Stone &
Webster Engineering Corp 1p 21791 039 24X Fiche 50-329,
84/01/04, 8401120426

DOCKETED ITEMS

8312120108 Board Notification B4-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

8401160145 Forwards Bechtel response to Observations 036 & 038 re control of proposed field changes & checklists assuring consistency during status assessment & hanger installation, respectively
QUAMME, D L Consumers Power Co 84/01/05 BARANOW, S W Stone & Webster, Inc 11pp 21815 315 24X Fiche 50-329, 84/01/05, 8401160145

8401190281 Forwards IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 2pp 21850 301 24X Fiche 50-329, 84/01/05, 8401190281

--8401190291 Comments on concerns expressed in 831014 telcon re solution cavities under plant structures, lack of dynamic earthquake analysis & cooling pond during cavity collapse No further action necessary
CARDONE, T, KIMBALL, J Geosciences Branch 83/10/28 JACKSON, R E Geosciences Branch 4pp 21850 309 24X Fiche 50-329, 84/01/05, 8401190281

8401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401100210 Forwards IE Mtg Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted
WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W Consumers Power Co 2pp 21788 001 24X Fiche 50-329, 84/01/06, 8401100210

--8401100224 Forwards third-party assessment 831208 meeting minutes Meeting covered remedial soils & const completion programs
LUCKB, A S Stone & Webster, Inc 83/12/15 HARRISON, J J Region 3, Office of Director 28pp 21758 007 24X Fiche 50-329, 84/01/06, 8401100210

8401160036 Forwards Const Implementation Overview 038 Checklist developed by Bechtel for status assessments of Rev 1 to Procedure FPM-7 000, "Mechanical Sys Status & Completion," lacks procedure attributes
KARR, J E Stone & Webster, Inc 84/01/06 QUAMME, D L Consumers Power Co 2pp 21815 208 24X Fiche 50-329, 84/01/06, 8401160036

8401160096 Forwards open Const Implementation Overview Items/Hold Point Notifications 041, 042 & 043 for action/info Installation work on emergency diesel generators may be affected by evaluation of Phase III activities
BARANOW, S W Stone & Webster, Inc 84/01/06 QUAMME, D L Duke Power Co 6pp 21815 277 24X Fiche 50-329, 84/01/06, 8401160096

8401170369 Forwards open CID item/hold point notifications, Items 041, 042 & 043 Phase III evaluation results re document control & applicant corrective action plan info request
BARANOW, S W Stone & Webster, Inc 84/01/06 QUAMME, D L Consumers Power Co 8pp 21828 215 24X Fiche 50-329, 84/01/06, 8401170369

8401190424 Forwards const implementation overview/hold point notification for Phase III resolution re civil discipline - soils for appropriate action
BARANOW, S W Stone & Webster, Inc 84/01/10 QUAMME, D L Consumers Power Co 4pp 21849 289 24X Fiche 50-329, 84/01/10, 8401190424

8401190329 Requests authorization to proceed w/Work Authorization Procedure 142530000 re preparation of auxiliary bldg roof as required for crack survey
MOONEY, J A Consumers Power Co 84/01/11 HARRISON, J J Region 3, Office of Director 1p 21850 357 24X Fiche 50-329, 84/01/11, 8401190329

8401190335 Forwards list of const personnel completing training requirements to commence status assessment
QUAMME, D L Consumers Power Co 84/01/11 BARANOW, S W Stone & Webster, Inc 4pp 21851 266 24X Fiche 50-329, 84/01/11, 8401190335

8401230146 Forwards list of Bechtel const personnel who completed training requirements to commence status assessment
EH Pillsbury should be contacted to initiate individual audit requirements
QUAMME, D L Consumers Power Co 84/01/11 BARANOW, S W Stone & Webster, Inc 4pp 21884 352 24X Fiche 50-329, 84/01/11, 8401230146

8401230169 Authorizes start of remedial soils activities identified in encl scheduled for Jan 1984
COOK, R J Region 3, Office of Director 84/01/11 QUAMME, D L Consumers Power Co 3pp 21884 122 24X Fiche 50-329, 84/01/11, 8401230169

8401230356 Forwards list of Bechtel const personnel who have completed training requirements to commence status assessment
QUAMME, D L Consumers Power Co 84/01/12 BARANOW, S W Stone & Webster, Inc 10pp 21873 344 24X Fiche 50-329, 84/01/12, 8401230356

8401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401230309 Forwards 840112 list of Bechtel const personnel trained to commence status assessment & replacement list dtd 840109 inadvertently detached from 840112 transmittal
* Consumers Power Co 84/01/13 Stone & Webster, Inc 10pp 21878 221 24X Fiche 50-329, 84/01/13, 8401230309

8401240501 Transmits actions which have or will be taken to address concerns identified in mgt corrective action Request/Rept DAT-1 & SW Const Implementation Overview Item 043 Discussion on document control actions also encl
QUAMME, D L Consumers Power Co 84/01/16 BARANOW, S W Stone & Webster, Inc 10pp 21917 105 24X Fiche 50-329, 84/01/16, 8401240501

8401240610 Forwards affidavits & resumes for JP Oliveira & BA Metros, assigned to independent assessment team
LUCKB, A S Stone & Webster Engineering Corp 84/01/16 HARRISON, J J Region 3, Office of Director 5pp 21909 215 24X Fiche 50-329, 84/01/16, 8401240610

8312120133 Supplemental Board Notification B4-010 forwards info re diesel generator bldg safety issues in facility DM/CL proceeding JP Matra, of Naval Surface Weapons Ctr, meeting notes encl
NOVAK, T H Assistant Director for Licensing 84/01/17 BECHHOEFER, C J HARBOR, J J LOWAN, F Atomic Safety and Licensing Board Panel 7pp 21940 201 24X Fiche 50-329, 84/01/17, 8312120133

8401270336 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNOH, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270336

8401230158 Forwards resumes & statements of independence for M Holley, D Segal, P Streeter, H Lambert, J L Chameau & Q Reimers for insertion in GA program, App C in accordance w/independent design & const verification program.
LEVIN, H A TERA Corp 84/01/18 KEPLER, J Q Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 25pp 21875 273 24X Fiche 50-329, 84/01/18, 8401230158

8401270370 Advises that results of sampling insp of encl const training records satisfactory Personnel listed cleared to perform status assessment NFR 006 closed out w/o encl.
KARR, J E Stone & Webster, Inc 84/01/18 QUAMME, D L Consumers Power Co 1p 21976 042 24X Fiche 50-329, 84/01/18, 8401270370

8401310136 Forwards closed const implementation overview Items 036 & 038 re control of field proposed changes
KARR, J E Stone & Webster, Inc 84/01/18 QUAMME, D L Consumers Power Co 6pp 22022 101 24X Fiche 50-329, 84/01/18, 8401310136

8401310336 Forwards list of open const implementation overview Items 45, 46 & 48
KARR, J E Stone & Webster, Inc 84/01/18 QUAMME, D L Consumers Power Co 5pp 22020 356 24X Fiche 50-329, 84/01/18, 8401310336

DOCKETED ITEMS

183

8401270291 Forwards list dtd 840117 of Bechtel personnel trained to commence status assessment
* Consumers Power Co 84/01/19 Stone & Webster, Inc 2pp
21976 055 24X Fiche 50-329, 84/01/19, 8401270291

8401270349 Notifies that response to 840110 ltr will be delayed until 4 to 8 wks after mechanical stop work lifted Delay due to util concern to properly assess results of stop work review process
QUAMME, D L Carolina Power & Light Co 84/01/19 BARANOW, B W Stone & Webster, Inc 1p 21981 008 24X Fiche 50-329, 84/01/19, 8401270349

8401270353 Forwards Audit Finding Rept M01-345-2-04F re storage requirements of QA div generated QA records
* Consumers Power Co 84/01/19 Stone & Webster, Inc 4pp
21976 018 24X Fiche 50-329, 84/01/19, 8401270353

8401270367 Requests reauthorization for listed remedial soils work which has passed or will pass 90-day authorization limit
QUAMME, D L Consumers Power Co 84/01/19 HARRISON, J J Region 3, Office of Director 1p 21976 224 24X Fiche 50-329, 84/01/19, 8401270367

8401270470 Forwards monthly open item status rpt, per D Browns request, w/o encl
* Consumers Power Co 84/01/19 Stone & Webster, Inc 1p
21981 298 24X Fiche 50-329, 84/01/19, 8401270470

8401270498 Forwards closed Const Implementation Overview 012 Phase I & II complete for FCR/FCN review & Phase III completed for Soils Stations B, 10, 13, 24 & 44 Requirements for lifting Stop Work Order 38 satisfied
KARR, J E Stone & Webster, Inc 84/01/19 QUAMME, D L Consumers Power Co 2pp 21980 133 24X Fiche 50-329, 84/01/19, 8401270498

8401230489 Forwards summary of 840104 meeting w/util & Bechtel in Ann Arbor, MI re independent design & const verification program List of attendees & agenda encl
LEVIN, H A TERA Corp 84/01/20 EISENHUT, D G Division of Licensing KEPLER, J Q Region 3, Office of Director COOK, J W Consumers Power Co 17pp 21882 097 24X Fiche 50-329, 84/01/20, 8401230489

8401240535 Authorizes listed critical work activities for Jan 1984
HARRISON, J J Region 3, Office of Director 84/01/20 QUAMME, D L Consumers Power Co 1p 21907 326 24X Fiche 50-329, 84/01/20, 8401240535

--8401240542 Requests reauthorization for listed activities that passed 90-day authorization limit
QUAMME, D L Consumers Power Co 84/01/19 HARRISON, J J Region 3, Office of Director 2pp 21907 327 24X Fiche 50-329, 84/01/20, 8401240542

8401270494 Requests authorization to proceed w/remedial soils work, per work Authorization Procedure 142550100 re removal of concrete surface for crack measurements
QUAMME, D L Consumers Power Co 84/01/20 HARRISON, J J Region 3, Office of Director 1p 21980 132 24X Fiche 50-329, 84/01/20, 8401270494

8401310014 Forwards I&C FCR/FCN register & General Spec FCR/FCN register w/o encl
JOHNSON, D Consumers Power Co 84/01/20 Stone & Webster, Inc 1p 22023 341 24X Fiche 50-329, 84/01/20, 8401310014

8401310143 Forwards matrix displaying Phase I, II & III audit status Open target dates for instrumentation, electrical & mechanical disciplines requested
* Consumers Power Co 84/01/20 Stone & Webster, Inc 4pp
22022 076 24X Fiche 50-329, 84/01/20, 8401310143

8401310213 Advises that as result of 840120 partial release of Stop Work Order FSW-41 for civil & architectural documents, Bechtel released for status assessment for Modules 340, 102, 120, 410 & 800.
QUAMME, D L Consumers Power Co 84/01/20 HIERZER, G A Bechtel Corp 13pp 22021 294 24X Fiche 50-329, 84/01/20, 8401310213

8401310327 Notifies of 840201 sixth status review meeting w/util & Bechtel in Ann Arbor, MI to discuss independent design & const verification program Agenda encl
LEVIN, H A TERA Corp 84/01/20 KEPLER, J Q Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 5pp 22026 276 24X Fiche 50-329, 84/01/20, 8401310327

8401310379 Forwards 840119 list of Bechtel personnel trained to commence status assessment
* Consumers Power Co 84/01/20 Stone & Webster, Inc 2pp
22012 355 24X Fiche 50-329, 84/01/20, 8401310379

8401310293 Forwards closed const implementation overview Items 42, 44 & Hold Points 13 & 14 notifications
KARR, J E Stone & Webster, Inc 84/01/23 QUAMME, D L Consumers Power Co 5pp 22020 271 24X Fiche 50-329, 84/01/23, 8401310293

8401300159 Authorizes work on Activity 142550100 re removal of concrete surface for crack measurements
HARRISON, J J Region 3, Office of Director 84/01/24 QUAMME, D L Consumers Power Co 2pp 21996 267 24X Fiche 50-329, 84/01/24, 8401300159

F Security, medical, emergency & fire protection plans

8401050026 Releases public version of State of MI emergency preparedness plan
FELTON, J M Division of Rules and Records 83/12/27 Document Management Branch 1p 21734 001 24X Fiche 50-329, 83/12/27, 8401050026

--8401050031 Public version of State of MI emergency preparedness plan w/831104 ltr
BLANCHARD, J J, HOUGH, O L Michigan, State of 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 491pp 21734 002 24X Fiche 50-329, 83/12/27, 8401050026

8401230270 Notifies of FEMA 840112-13 meetings in Chicago, IL re radiological emergency preparedness program to develop final FY84/FY85 emergency preparedness exercise schedule & prompt alert notification certification schedule
PAPERIELLO, C J Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 4pp 21884 207 24X Fiche 50-000, 84/01/05, 8401230270

8401250099 Releases public version of revised controlled copyholder list
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21939 158 24X Fiche 50-000, 84/01/18, 8401250099

--8401250102 Public version of Rev 4 to controlled copyholder list of general of ctr/emergency operations facility emergency implementing procedures
* Consumers Power Co 83/11/10 Office of Nuclear Reactor Regulation, Director 7pp 21939 159 24X Fiche 50-000, 84/01/18, 8401250099

G Adjudicatory correspondence

8401030179 Order extending time until 840118 for Commission to act to review Director's Decision DD-83-16
CHILK, S J Office of the Secretary of the Commission 83/12/29 Commissioners 1p 21681 323 24X Fiche 50-329, 83/12/29, 8401030179

8401090366 Forwards replies to NRC 831115 & Stamiris 831216 findings on remedial soils issues, per ASD 830929 order
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co 84/01/03 BECHHOEFER Atomic Safety and Licensing Board Panel 1p 21753 300 24X Fiche 50-329, 84/01/03, 8401090366

--8401090375 Reply opposing Stamiris 831216 proposed findings of fact & conclusions of law on remedial soils issues QA implementation of remedial work issues should be addressed separately from technical adequacy issues
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 84/01/06 15pp 21753 301 24X Fiche 50-329, 84/01/03, 8401090366

--8401090384 Reply to NRC 831115 findings of fact & conclusions of law on remedial soils issues Certificate of Bvc encl
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 84/01/03 13pp 21753 316 24X Fiche 50-329, 84/01/03, 8401090366

8401250090 Forwards 840112 Director's Decision DD-84-2, supplementing Director's Decision DD-83-16 which granted BP Garde 10CFR2 206 request for audit of util mgt
WILCOVE, M N Hearing Branch 2 84/01/13 BECHHOEFER, C , COHAN, F P , HARBOR, J Atomic Safety and Licensing Board Panel 17pp 21934 172 24X Fiche 50-329, 84/01/13, 8401250090

8401200116 Order extending time until 840127 for Commission to act to review Director's Decision DD-83-16
CHILK, S J Office of the Secretary of the Commission 84/01/18 Commissioners 1p 21866 360 24X Fiche 50-329, 84/01/18, 8401200116

DOCKETED ITEMS

B401240073 Forwards util preliminary pretrial statement filed in State of MI Circuit Court for County of Midland Statement sent in fulfillment of obligation to keep ASLD informed of developments relevant to proceeding
STEFTEL, P P Isham, Lincoln & Beale 84/01/19 BECHHDEFER, C.
COWAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel
7pp 21912 280 24X Fiche 50-329, 84/01/19, 8401240073

B401300238 Summarizes 840116 telcon w/L Rome re relatively few enforcement fines levied on util & enforcement action to be taken based on hearing findings that util violated NRC order
JDOBSTEN, J Commissioners 84/01/19 Commissioners 1p
21998 362 24X Fiche 50-329, 84/01/19, 8401300238

B401270384 Request for leave to file encl corrected copies of applicant 831209 memorandum in opposition to appeal of Govt Accountability Project Table of contents & table of authorities inadvertently omitted Certificate of Svc encl
STEINDEL, S H Consumers Power Co STEINDEL, S H Isham, Lincoln & Beale 84/01/23 Atomic Safety and Licensing Appeal Panel 4pp
21976 165 24X Fiche 50-329, 84/01/23, 8401270384

--B401270391 Memorandum in opposition to Govt Accountability Project deponent 831021 appeal ASLB rulings do not constitute abuse of discretion & should be sustained Deponents should be ordered to appear per subpoenas Certificate of Svc encl
PROCTOR, S D Consumers Power Co PROCTOR, S D Isham, Lincoln & Beale 83/12/09 Atomic Safety and Licensing Appeal Panel.
5pp 21976 169 24X Fiche 50-329, 84/01/23, 8401270384

B401270371 Notice of appearance in proceeding Certificate of Svc encl
STEINDEL, S H Consumers Power Co STEINDEL, S H Isham, Lincoln & Beale 84/01/24 3pp 21976 225 24X Fiche 50-329, 84/01/24, 8401270371

B401300191 Order extending time until 840210 for Commission to act to review Director's Decisions 80-83-16 & 80-84-2
CHILK, S J Office of the Secretary of the Commission 84/01/27
Commissioners 1p 21997 349 24X Fiche 50-329, 84/01/27, 8401300191

4 Inspection reports, IE Bulletins & correspondence

B401230621 FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response
WINSLOW, R Wall Street Journal 83/09/28 NRC - No Detailed Affiliation Given 1p 21905 336 24X Fiche: 50-329, 83/09/28, 8401230621

101060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p. 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--B401060190 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

B401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response
Forwards App A documents Review of addl records in progress
FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21903 337 24X Fiche 50-329, 83/11/01, 8401230630

B12070139 Recommends that the Board be notified re reported settlement in diesel generator bldg Related interim deficiency rept submitted on 780929 & insp conducted on 781024-27 to examine details of problem [Encl 7810060283]
THORNBURG, H D Division of Reactor Construction Inspection 78/11/09 OMER, G C Executive Officer for Operations Support 1p. 21903 339 24X Fiche 50-329, 83/11/01, 8401230630

7908070022 Forward comments & recommendation resulting from review of Region 3 enforcement package dtd 790403 on facility settlement problems Four matl false statement identified out of five Expects imposition of civil penalties
THORNBURG, H D Division of Reactor Construction Inspection, 79/06/13 THOMPSON, D Executive Officer for Operations Support 2pp 21905 341 24X Fiche 50-329, 83/11/01, 8401230630.

/912140299 Comments on action needed for 790423 enforcement package re matl false statement in FSAR
THORNBURG, H D Division of Reactor Construction Inspection, 79/09/27 OMER, G C Executive Officer for Operations Support 2pp 21905 344 24X Fiche 50-329, 83/11/01, 8401230630

--B4002120130 Forwards info re order to modify CP including matl false statement consideration
THORNBURG, H D Division of Reactor Construction Inspection 80/01/03 FORTUNA, R Office of Inspector & Auditor 4pp
21905 348 24X Fiche 50-329, 83/11/01, 8401230630

--B401230639 Discusses IE investigation re FSAR submittals Several incorrect statements re soil foundation appear to reflect matl false statements
SINCLAIR, J R Office of Inspector & Auditor 79/03/20 Office of Inspector & Auditor 1p 21905 340 24X Fiche 50-329, 83/11/01, 8401230630

--B401230644 Discusses status of IE investigation re FSAR submittals
SINCLAIR, J R Office of Inspector & Auditor 79/06/26 Office of Inspector & Auditor 1p 21905 343 24X Fiche 50-329, 83/11/01, 8401230630

--B401230651 Discusses enforcement action re diesel generator bldg & plant fill areas, per 790403 memo to HD Thornburg Item 1 considered matl false statement Four items should be treated as items of noncompliance
OMER, G C Executive Officer for Operations Support 79/10/04
KEPPLER, J O Region 3, Chicago, Office of the Director 2pp 21905 346 24X Fiche 50-329, 83/11/01, 8401230630

B401050350 Forwards J Christy 831121 & 1206 memos re reinsp of 500 large bore hangers
GUAMME, D L Consumers Power Co 83/12/22 BARANOW, S W Stone & Webster, Inc 4pp 21729 255 24X Fiche 50-329, 83/12/22, 8401050350

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

B401050544 Responds to IE Bulletin 83-08, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co (HTPC)," per 830810 commitment No HTPC pumps used in safety-related sys at facilities HTPC spare parts purchased
HOWELL, S H Consumers Power Co 83/12/28 KEPPLER, J O Region 3, Office of Director 5pp 21726 054 24X Fiche 50-329, 83/12/28, 8401050544

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B401060496 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-23 & 50-330/83-24
WARNICK, R F Region 3, Office of Director 84/01/04 COOK, J W Consumers Power Co 2pp 21739 339 24X Fiche 50-329, 84/01/04, 8401060496

--B401060500 Responds to NRC 831117 ltr re violations noted in IE Insp Repts 50-329/83-23 & 50-330/83-24 Corrective actions Nonconformance Rept GAR 88-00024 re omission of calibr stickers on hydraulic meters initiated
COOK, J W Consumers Power Co, 83/12/20 KEPPLER, J O Region 3, Office of Director 4pp 21739 341 24X Fiche 50-329, 84/01/04, 8401060496

B401190281 Forwards IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 2pp 21850 301 24X Fiche 50-329, 84/01/05, 8401190281

--B401190286 IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 Noncompliance noted Major areas inspected previously identified items, remedial soil work activities, allegations & document control stop work order
HARRISON, J J, BURGESS, B L, COOK, R J Region 3, Office of Director 84/01/04 6pp 21850 303 24X Fiche 50-329, 84/01/05, 8401190281

--B401190291 Comments on concerns expressed in 831014 telcon re settlement cavities under plant structures, lack of dynamic earthquake analysis & cooling pond during cavity collapse. No further action necessary
CARDONE, T, KINBALL, J Geosciences Branch 83/10/28
JACKSON, R E Geosciences Branch 4pp 21850 309 24X Fiche 50-329, 84/01/05, 8401190281

8401100210 Forwards IE Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted
 WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W
 Consumers Power Co 2pp 21758 001 24X Fiche 50-329, 84/01/06, 8401100210

--8401100221 IE Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted subcontractor used procedure w/hold indicated, incomplete entry of crack monitoring data & MPQAF group insp repts not submitted promptly
 GARDNER, R. N., HARRISON, J J Region 3, Office of Director 84/01/06 App 21758 003 24X Fiche 50-329, 84/01/06, 8401100210

--8401100224 Forwards third-party assessment 831208 meeting minutes Meeting covered remedial soils & const completion programs
 LUCKS, A S Stone & Webster, Inc 83/12/15 HARRISON, J J Region 3, Office of Director 28pp 21758 007 24X Fiche 50-329, 84/01/06, 8401100210

--8401100228 Forwards Independent Assessment of Underpinning Weekly Rept 59 for 831030-1105 Minutes of daily meetings between assessment team & site engineering, const & GA personnel encl
 LUCKS, A S Stone & Webster, Inc 83/11/09 COOK, R NRC ~ No Detailed Affiliation Given 50pp 21758 036 24X Fiche 50-329, 84/01/06, 8401100210

--8401100234 Forwards Const Implementation Overview Rept 21 for 831031-1104 Evaluations of const completion program activities, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/08 KEPPLER, J O Region 3, Office of Director 14pp 21758 086 24X Fiche 50-329, 84/01/06, 8401100210

--8401100238 Forwards Const Implementation Overview Rept 22 for 831107-11 Evaluations of const completion program activities & matrices of observations, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/14 KEPPLER, J O Region 3, Office of Director 15pp 21758 100 24X Fiche 50-329, 84/01/06, 8401100210

--8401100257 Forwards Const Implementation Overview Rept 23 for 831114-18 Evaluations of const completion program activities & matrices of observation, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/22 KEPPLER, J O Region 3, Office of Director 16pp 21758 117 24X Fiche 50-329, 84/01/06, 8401100210

--8401100261 Forwards Const Implementation Overview Rept 24 for 831121-23 Evaluations of const completion activities & matrices of observations, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/29 KEPPLER, J O Region 3, Office of Director 12pp 21758 133 24X Fiche 50-329, 84/01/06, 8401100210

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401190368 Requests info for scheduling verification activities & developing sampling plans for hanger reinsp program
 BARANOW, S W Stone & Webster, Inc 84/01/10 QUAMME, D L Consumers Power Co 4pp 21850 158 24X Fiche 50-329, 84/01/10, 8401190368

8401200077 Forwards confirmatory order re plan for independent appraisal of mgt organization re excavation of soil matl & fireline relocation activities w/o prior NRC approval.
 DEYOUNG, R Director's Office, Office of Inspection and Enforcement 84/01/12 SELBY, J D Consumers Power Co 2pp 21872.177 24X Fiche 50-329, 84/01/12, 8401200077

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
 CARUSO, R Licensing Branch 2 84/01/17 SCHMENCER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401050156 Forwards ALAB-104 monthly rept for Nov 1983
 COOK, J W Consumers Power Co 83/12/27 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1833pp 21718 284 24X Fiche 50-329, 83/12/27, 8401050156

8401160124 Forwards const implementation overview weekly Rept 28 for 831219-23 Rept includes summary of open items, nonconformance identification repts & hold points
 BARANOW, S W Stone & Webster, Inc 83/12/28 KEPPLER, J O Region 3, Office of Director 11pp 21821 155 24X Fiche 50-329, 83/12/28, 8401160124

8401160079 Forwards Rept 29 for const implementation overview for period 831226-30
 BARANOW, S W Stone & Webster, Inc 84/01/04 KEPPLER, J O Region 3, Office of Director 10pp 21821 191 24X Fiche 50-329, 84/01/04, 8401160079

8401100210 Forwards IF Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted
 WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W Consumers Power Co 2pp 21758 001 24X Fiche 50-329, 84/01/06, 8401100210

--8401100228 Forwards Independent Assessment of Underpinning Weekly Rept 59 for 831030-1105 Minutes of daily meetings between assessment team & site engineering, const & GA personnel encl
 LUCKS, A S Stone & Webster, Inc 83/11/09 COOK, R NRC ~ No Detailed Affiliation Given 50pp 21758 036 24X Fiche 50-329, 84/01/06, 8401100210

--8401100234 Forwards Const Implementation Overview Rept 21 for 831031-1104 Evaluations of const completion program activities, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/08 KEPPLER, J O Region 3, Office of Director 14pp 21758 086 24X Fiche 50-329, 84/01/06, 8401100210

--8401100238 Forwards Const Implementation Overview Rept 22 for 831107-11 Evaluations of const completion program activities & matrices of observations, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/14 KEPPLER, J O Region 3, Office of Director 15pp 21758 100 24X Fiche 50-329, 84/01/06, 8401100210

--8401100257 Forwards Const Implementation Overview Rept 23 for 831114-18 Evaluations of const completion program activities & matrices of observation, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/22 KEPPLER, J O Region 3, Office of Director 16pp 21758 117 24X Fiche 50-329, 84/01/06, 8401100210

--8401100261 Forwards Const Implementation Overview Rept 24 for 831121-23 Evaluations of const completion activities & matrices of observations, nonconformance identification repts & hold points encl
 BARANOW, S W Stone & Webster, Inc 83/11/29 KEPPLER, J O Region 3, Office of Director 12pp 21758 133 24X Fiche 50-329, 84/01/06, 8401100210

8401190348 Forwards Const Implementation Overview Weekly Repts 27 & 28 for Items 39 & 40 Drawing A-213 added to file Resampling conducted
 BARANOW, S W Stone & Webster, Inc 84/01/10 QUAMME, D L Consumers Power Co 3pp 21850 327 24X Fiche 50-329, 84/01/10, 8401190348

DOCKETED ITEMS

B401230340 Forwards const implementation overview Weekly Rept 30 for B40103-06 Rept includes summary of open items, nonconformance identification rept & hold points
BARANOW, S W Stone & Webster, Inc B4/01/11 KEPLER, J G Region 3, Office of Director 12pp 21883 215 24X Fiche 50-329, B4/01/11, B401230340

B401170380 Forwards "Midland Independent Design & Const Verification Program," Monthly Status Rept 8 for Dec 1983
LEVIN, H A TERA Corp B4/01/13 KEPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 3pp 21829 001 24X Fiche 50-329, B4/01/13, B401170380

--B401170385 "Midland Independent Design & Const Verification Program," Monthly Status Rept 8 for Dec 1983
DUBOHERTY, F A, TULODIESKI, D B, LEVIN, H A TERA Corp B3/12/31 3Bpp 21829 004 24X Fiche 50-329, B4/01/13, B401170380

B401230493 Forwards monthly status rept for Dec 1983
WARNICK, R F Region 3, Office of Director B4/01/18 KEPLER, J G Region 3, Office of Director 1p 21882 093 24X Fiche 50-329, B4/01/18, B401230493

--B401230497 Forwards monthly status rept for Dec 1983
COOK, R J Region 3, Office of Director B4/01/12 WARNICK, R F Region 3, Office of Director 2pp 21882 094 24X Fiche 50-329, B4/01/18, B401230493

B401270252 Requests transmittal of weekly repts to LPDR, Grace Dow Memorial Library in Midland, MI Repts should also be furnished to NRC & util
HARRISON, J J Region 3, Office of Director B4/01/25 AMORUSO, P LUCK, S EG&O, Inc 2pp 21982 182 24X Fiche 50-329, B4/01/25, B401270252

B401310026 Forwards Dec 1983 monthly rept in accordance w/condition of Memorandum & Order ALAB-106, dtd 730323 & Amend 1 to CPPR-B1 & CPPR-82
COOK, J W Consumers Power Co B4/01/25 CEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1, B6Bpp 22007 001 24X Fiche 50-329, B4/01/25, B401310026

B Reportable occurrences, LERs & related correspondence

B401100315 Forwards nonconformance identification rept re civil review Phase III re inconsistent quality distribution for design drawings & specs for appropriate action
BARANOW, S W Stone & Webster Engineering Corp B3/01/03 GUAMME, D L Consumers Power Co 3pp 21763 284 24X Fiche 50-329, B3/01/03, B401100315

B401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response
FELTON, J M Division of Rules and Records B3/11/01 WINSLOW, R Wall Street Journal 2pp 21905 337 24X Fiche 50-329, B3/11/01, B401230630

B401040200 Fifth interim Deficiency Rept B3-01 re loose locking clips in instrument cabinets No change in status of item since B30930 ltr due to hold placed on all Q work at site Next rept by B40330
COOK, J W Consumers Power Co B3/12/23 KEPLER, J G Region 3, Office of Director 3pp 21701 195 24X Fiche 50-329, B3/12/23, B401040200

B401040461 Interim deficiency rept re reactor bldg spray piping supports Pipe hanger testing completed Remaining activities still progressing Next rept expected by B40330
COOK, J W Consumers Power Co B3/12/23 KEPLER, J G Region 3, Office of Director 2pp 21707 341 24X Fiche 50-329, B3/12/23, B401040461

B401040508 Interim potential deficiency rept re safety-related electrical equipment not meeting project requirements Site overinsps will be conducted on 66 purchase orders Next rept expected by B40330
COOK, J W Consumers Power Co B3/12/23 KEPLER, J G Region 3, Office of Director 3pp 21705 335 24X Fiche 50-329, B3/12/23, B401040508

B401160124 Forwards const implementation overview weekly Rept 28 for B31219-23 Rept includes summary of open items, nonconformance identification repts & hold points
BARANOW, S W Stone & Webster, Inc B3/12/28 KEPLER, J G Region 3, Office of Director 11pp 21821 155 24X Fiche 50-329, B3/12/28, B401160124

B401040216 Informs of completion of review of listed corrective actions taken re identified crack monitoring sys deficiencies
Corrective actions satisfactory
HARRISON, J J Region 3, Office of Director B3/12/29 MOONEY, J Consumers Power Co 2pp 21701 291 24X Fiche 50-329, B3/12/29, B401040216

B401100002 Forwards CID NIR 011 re architectural review, Phase III, FCR/FCN Midland CIG drawing Stations 51 & 59 Two retired drawings identified w/o proper notation
BARANOW, S W Stone & Webster, Inc B4/01/03 GUAMME, D L Consumers Power Co 2pp 21761 208 24X Fiche 50-329, B4/01/03, B401100002

B401100465 Forwards CID Nonconformance Identification Rept (NIR) 012 re FSK drawing discrepancy w/Bechtel master composite register & design drawings & spec inconsistent w/quantity distribution requirements
BARANOW, S W Stone & Webster, Inc B4/01/03 GUAMME, D L Consumers Power Co 3pp 21761 288 24X Fiche 50-329, B4/01/03, B401100465

B401160090 Forwards Quality Action Request R8-00106 generated by QA dept to track QUAIL program deficiencies identified in NIR-012
GUAMME, D L Consumers Power Co B4/01/05 BARANOW, S W Stone & Webster, Inc 3pp 21821 183 24X Fiche 50-329, B4/01/05, B401160090

B401130280 EN-B4-001 confirmatory order will be issued on or about B40112 Order confirms commitment & requires util to submit plan for independent appraisal of site & corporate mgt organizations & functions
KLINGLER, O, AXELRAD, J Director's Office, Office of Inspection and Enforcement B4/01/06 1p 21798 360 24X Fiche 50-329, B4/01/06, B401130280

B401170212 Interim Deficiency Rept B3-11 #1 re potentially defective capstan springs in Pacific Scientific mechanical shock arresters Initially reported on B31207 Investigation continuing Next rept will be submitted by B40316
COOK, J W Consumers Power Co B4/01/06 KEPLER, J G Region 3, Office of Director 18pp 21832 281 24X Fiche 50-329, B4/01/06, B401170212

B401170430 Interim deficiency rept re inconsistent processing & review of field change request/field change notices against project design documents Initially reported on B31211 Review program established Next rept expected B40210
COOK, J W Consumers Power Co B4/01/06 KEPLER, J G Region 3, Office of Director 9pp 21827 148 24X Fiche 50-329, B4/01/06, B401170430

B401170447 Interim deficiency rept re ITT Grinnell mechanical snubber assemblies Initially reported on B31209 All Figure 306 & 30n snubbers will be evaluated, repaired or replaced Next rept expected by B40323
COOK, J W Consumers Power Co B4/01/06 KEPLER, J G Region 2, Office of Director 7pp 21827 091 24X Fiche 50-329, B4/01/06, B401170447

B401170184 Interim Deficiency Rept B3-03 #3 re cracking of core support structure bolting ASME SA 453 Grade 660 (A-286) bolts will be replaced w/fasteners fabricated from listed matls Next rept by B40330
COOK, J W Consumers Power Co B4/01/09 KEPLER, J G Region 3, Office of Director 4pp 21831 346 24X Fiche 50-329, B4/01/09, B401170184

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Util notified
BOYER, R E Transamerica Delaval, Inc B4/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000, B4/01/09, B401170186

B401190378 Forwards nonconformance identification rept On B31214, discovered that potential exists for Field Change Request C-1926 to be misapplied to Drawings C-358 & C-479 Addl field change request resolution sheet issued
BARANOW, S W Stone & Webster, Inc B4/01/10 GUAMME, D L Consumers Power Co 6pp 21850 131 24X Fiche 50-329, B4/01/10, B401190378

B401190397 Forwards B31211 nonconformance identification rept Drawing A-213 missing during sample insp of controlled architectural drawings Entire lot of drawings rejected Missing drawing added to stick drawing acceptable
BARANOW, S W Stone & Webster, Inc B4/01/10 GUAMME, D L Consumers Power Co 2pp 21849 347 24X Fiche 50-329, B4/01/10, B401190397

8401190402 Interim deficiency rept re broken/cracked puffer piston rods in Model 5 Hk breakers mfg by Brown-Beverl Initially reported on 831213 Safety evaluation performed Nonconformance rept issued Next rept by 840330
COOK, J W Consumers Power Co 84/01/12 KEPLER, J G Region 3, Office of Director 14pp 21850 101 24X Fiche 50-329, 84/01/12, 8401190402

8401230331 Interim deficiency rept re differential settlement between diesel generator structure & pedestal Initially reported on 831214 Interim or final rept will be submitted by 840420
COOK, J W Consumers Power Co 84/01/13 KEPLER, J G Region 3, Office of Director 5pp 21884 232 24X Fiche 50-329, 84/01/13, 8401230331

8401230344 Interim deficiency rept re attachment of non-Q/nonseismic piping to component cooling water sys Initially reported on 831216 Interim or final rept will be submitted by 840420
COOK, J W Consumers Power Co 84/01/16 KEPLER, J G Region 3, Office of Director 6pp 21882 346 24X Fiche 50-329, 84/01/16, 8401230344

8401240509 Forwards, for review for closure of NIR-0012, GA Requests GAR-RB-00106 & GAR-RB-00109 re deficiencies at Stations B & IO, respectively
Consumers Power Co 84/01/17 Stone & Webster, Inc 23pp 21917 117 24X Fiche 50-329, 84/01/17, 8401240509

V. Operator Examinations

8401230253 Forwards updated estimated schedule for nuclear instructor program & operator & instructor licensing programs through FY87, per Generic Ltr 83-40
BORDINE, T C Consumers Power Co 84/01/16 EISENHUT, D G Division of Licensing 6pp 21884 290 24X Fiche 50-000, 84/01/16, 8401230253

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8401170052 Partial response to FOIA request for 42 categories of documents Forwards listed documents Documents also available in PDR, Review of addl records subj to request in progress
FELTON, J M Division of Rules and Records 83/10/03 SHOLLY, B C Union of Concerned Scientists 1p 21846 163 24X Fiche 50-329, 83/10/03, 8401170052

--8203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NUREG-0660, Item 1F E 5 1, design sensitivity of B&W reactors Lists of NUREG-0667 recommendations reviewed & NRC evaluation encl
HATTSON, R Division of Systems Integration (post 811005) 82/02/26 HANAUER, S Division of Safety Technology 25pp 21846:227 24X Fiche 50-329, 83/10/03, 8401170052

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000, 83/10/18, 8401250015

--8209160068 Informs Commission of NRC initiatives to improve GA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations SECY-82-352, 82/08/20 37pp 21966 035 24X Fiche 50-000, 83/10/18, 8401250015

8401040044 Responds to FOIA request for records re review of structural adequacy of diesel generator bldg at facilities subsequent to May testimony of R Landsman in ASLB proceeding
FELTON, J M Division of Rules and Records 83/10/27 GARDE, B P Government Accountability Project 3pp 21714 289 24X Fiche 50-329, 83/10/27, 8401040044

--8310280277 Forwards initial response to RB Landsman concerns on structural integrity of diesel generator bldg, as prepared during 830728 working meeting w/consultants J Matra & G Harstead
RINALDI, F. Structural & Geotechnical Engineering Branch 83/10/21 KUD, P. T Structural & Geotechnical Engineering Branch 10pp 21714:299 24X Fiche 50-329, 83/10/27, 8401040044

--8401040052 "Review Comments of J Kane, Diesel Generator Bldg Concerns at Midland,"
KANE, J NRC - No Detailed Affiliation Given 83/10/27 5pp 21714 294 24X Fiche 50-329, 83/10/27, 8401040044

8401100246 Forwards corrected version of hold point 011 reported in 831114 weekly rept
BARANOW, S W Stone & Webster, Inc 83/11/17 KEPLER, J G Region 3, Office of Director 3pp 21759 225 24X Fiche 50-329, 83/11/17, 8401100246

8401170175 Confirms transmittal of listed PQCI &/or changes & procedures
EWERT, G F Consumers Power Co 83/11/21 BARANOW, S Stone & Webster, Inc 1p 21834 141 24X Fiche 50-329, 83/11/21, 8401170175

8401170164 Confirms transmittal of three computer printouts w/info on MPQAD (balance of plant) inspector records Prints include training, exams, performance demos & certifications
BOTIMER, L A Consumers Power Co 83/11/29 BARANOW, S Stone & Webster Engineering Corp 1p 21834 114 24X Fiche 50-329, 83/11/29, 8401170164

8401050369 Confirms transmittal of Rev 6 to C-1 31 control log for wk ending 831118 to S&W
EWERT, G F Consumers Power Co 83/11/30 BARANOW, S Stone & Webster, Inc 1p 21731 094 24X Fiche 50-329, 83/11/30, 8401050369

8401050434 Confirms transmittal of MPQAD Manual, F-2M
EWERT, G F Consumers Power Co 83/12/01 BARANOW, S Stone & Webster, Inc 1p 21730 289 24X Fiche 50-329, 83/12/01, 8401050434

8401170167 Confirms transmittal of three computer printouts w/info on MPQAD (balance of plant) inspector records Prints include training, exams, performance demos & certifications
BOTIMER, L A, EWERT, G F Consumers Power Co 83/12/06 BARANOW, S Stone & Webster, Inc 1p 21834 134 24X Fiche 50-329, 83/12/06, 8401170167

8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C B Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22054 358 24X Fiche 50-000, 83/12/16, 8312200154

8401120273 Confirms transmittal of all controlled copies of PQCI & changes Future rev or updates will be transmitted
EWERT, G F Consumers Power Co 83/12/16 BARANOW, S Stone & Webster, Inc 1p 21792 162 24X Fiche 50-329, 83/12/16, 8401120273

8401170171 Confirms transmittal of listed Bechtel field procedures
EWERT, G F Consumers Power Co 83/12/21 BARANOW, S Stone & Webster, Inc 1p 21834 135 24X Fiche 50-329, 83/12/21, 8401170171

8401050341 Presents schedule of activities for audit re lifting recent FCR/FCN stop work orders Clear definition of packages & schedule for audit will be provided by 831230
GUAMME, D L Consumers Power Co 83/12/22 BARANOW, S W Stone & Webster, Inc 7pp 21727 160 24X Fiche 50-329, 83/12/22, 8401050341

8401050347 Requests reauthorization for remedial soils work, Items 165053050 re excavating Pier CT1 & 155053050 re excavating Pier CT12, in accordance w/work authorization procedure
GUAMME, D L Consumers Power Co 83/12/22 HARRISON, J J Region 3, Office of Director 1p 21729 254 24X Fiche 50-329, 83/12/22, 8401050347

8401050371 Forwards Bechtel 831219 ltr in response to issue re bypassing of GC hold points Ack requested if response acceptable
GUAMME, D L Consumers Power Co 83/12/22 BARANOW, S W Stone & Webster, Inc 8pp 21731 095 24X Fiche 50-329, 83/12/22, 8401050371

8401050647 Comments on NRC-suggested interim actions/guidelines for maint of auxiliary bldg elevation to be employed until 840104-06 meeting to discuss upward movements & jacking of reserve capacity loads
MORNEY, J A Consumers Power Co 83/12/22 HARRISON, J J Region 3, Office of Director 4pp 21735 354 24X Fiche 50-329, 83/12/22, 8401050647

8401040379 Notifies of 840104 meeting w/util, NRC & Bechtel in Ann Arbor, MI to discuss status of confirmed items & findings re independent design & const verification program Agenda encl
LEVIN, H A TERA Corp 83/12/27 KEPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 3pp 21706 237 24X Fiche 50-329, 83/12/27, 8401040379

8401090791 Summary of 831129-30 meetings w/util & Mark Technologies Corp re seismic portion of spatial sys interaction program Viewgraphs encl
HODD, D Licensing Branch 4 83/12/27 Licensing Branch 4 44pp 21764 248 24X Fiche 50-329, 83/12/27, 8401090791

DOCKETED ITEMS

3 Forwards S&W 831222 ltr re results of review of Bechtel training records Records for listed nonmanual
1 satisfactory
1 L Consumers Power Co 83/12/28 HIERZER, G A Bechtel
1pp 21731 120 24X Fiche 50-329, 83/12/28, 8401050393

1 Informs that all architectural stations ready to be by S&W for vendor drawings & all remaining design/option items, per 831228 discussions
1 L Carolina Power & Light Co 83/12/28 BARANDOW, S W Webster, Inc 1p 21741 177 24X Fiche 50-329, 83/12/28, 8401100286

Notifies of weekly distribution for listed MPOAD personnel s covering inspector training & personnel forms
F, BOTIMER, L A Consumers Power Co 83/12/28 BARANDOW, S Webster Engineering Corp 1p 21764 001 24X
-329, 83/12/28, 8401100384

Advices that MPOAD audit of Civil Stations 8, 10, 13, 24 & 64 d & ready for S&W final audit W/successful completion, stop work on soils activities will be

L Consumers Power Co 83/12/29 BARANDOW, S W Stone & Inc 1p 21758 242 24X Fiche 50-329, 83/12/29, 8401100286

Forwards proposed list of work for Jan 1984 & supplemental iverty list for Feb 1984 for remedial soils work authorization requested

L Consumers Power Co 83/12/29 HARRISON, J J Region 3, f Director 13pp 21764 002 24X Fiche 50-329, 83/12/29, 8401100310

Forwards TM Novak ltr to JP McCaughy re series of s on emergency diesel generators mfg by rica Delaval, Inc Response may be submitted by ref to group or plant-specific repts W/o encl
E G Licensing Branch 4 83/12/29 COOK, J W Consumers 1p 21821 124 24X Fiche 50-329, 83/12/29, 8401130102

Advices that civil stations ready to be audited for vendor design drawings & specs
L Consumers Power Co 83/12/30 BARANDOW, S W Stone & Inc 1p 21759 185 24X Fiche 50-329, 83/12/30, 8401100237

Advices that drawing review proposed cannot presently be f due to incomplete mechanical drawing register
L Consumers Power Co 83/12/30 BARANDOW, S W, Stone & Inc 1p 21764 104 24X Fiche 50-329, 83/12/30, 8401100357

Forwards 831229 ltr from Bechtel re five unsatisfactory level assignments identified in NIR-008 Scheduled completing review of entire matrix & issuing new be mid-Jan 1984
L Consumers Power Co 84/01/03 BARANDOW, S W Stone & Inc 3pp 21791 321 24X Fiche 50-329, 84/01/03, 8401100237

Forwards "Midland Independent Design & Const Verification Structural Evaluation of Diesel Generator Bldg "
1 TERA Corp 84/01/04 EISENHUT, D G Division of 1 KEPLER, J G Region 3, Office of Director COOK, J W Power Co 2pp 21741 291 24X Fiche 50-329, 84/01/04, 8401100210

4 "Midland Independent Design & Const Verification Program al Evaluation of Diesel Generator Bldg "
1 A TERA Corp 84/01/04 46pp 21741 294 24X
0-329, 84/01/04, 8401060281

Lists critical work activities authorized for Jan 1984
J J Region 3, Office of Director 84/01/04 GUAMME, D L Power Co 2pp 21739 357 24X Fiche 50-329, 84/01/04, 8401100310

Confirms transmittal of listed stop work orders
Consumers Power Co 84/01/04 BARANDOW, S Stone & Inc 1p 21792 240 24X Fiche 50-329, 84/01/04, 8401102006

Forwards listed MPOAD quality action requests corresponding nonconformance identification repts
L Consumers Power Co 84/01/04 BARANDOW, S W Stone & Inc 15pp 21794 001 24X Fiche 50-329, 84/01/04, 8401100310

Forwards "Structural Evaluation of Midland Diesel Generator sment of Structural Performance Capability & ility as Potentially Affected by Settlement Induced " Significant cracking not anticipated
TERA Corp 84/01/04 KEPLER, J G Region 3, Office of COOK, J W Consumers Power Co EISENHUT, D G, Division of 3pp 21793 171, 24X Fiche: 50-329, 84/01/04, 8401100339

--8401120351 "Structural Evaluation of Midland Diesel Generator Bldg Assessment of Structural Performance Capability & Serviceability as Potentially Affected by Settlement Induced Cracking "
* TERA Corp 84/01/04 47pp 21793 174 24X
Fiche 50-329, 84/01/04, 8401120339

8401120426 Notifies of placement on weekly distribution for printouts of summary of inspector training, personnel forms & item complete forms
BOTIMER, L A Consumers Power Co 84/01/04 BARANDOW, S Stone & Webster Engineering Corp 1p 21791 037 24X Fiche 50-329, 84/01/04, 8401120426

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21793 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401160145 Forwards Bechtel response to Observations 036 & 038 re control of proposed field changes & checklists assuring consistency during status assessment & hanger installation, respectively
GUAMME, D L Consumers Power Co 84/01/05 BARANDOW, S W, Stone & Webster, Inc 11pp 21815 315 24X Fiche 50-329, 84/01/05, 8401160145

8401190281 Forwards IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 2pp 21850 301 24X Fiche 50-329, 84/01/05, 8401190281

--8401190291 Comments on concerns expressed in 831014 telcon re solution cavities under plant structures, lack of dynamic earthquake analysis & cooling pond during cavity collapse No further action necessary
CARDONE, T J, KIMBALL, J Geosciences Branch 83/10/28 JACKSON, R E Geosciences Branch 4pp 21850 309 24X
Fiche 50-329, 84/01/05, 8401190281

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401100210 Forwards IE Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831028 Violation noted
WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W Consumers Power Co 2pp 21758 001 24X Fiche 50-329, 84/01/06, 8401100210

--8401100224 Forwards third-party assessment 831208 meeting minutes Meeting covered remedial soils & const completion programs
LUCKS, A S Stone & Webster, Inc 83/12/15 HARRISON, J J Region 3, Office of Director 28pp 21758 007 24X
Fiche 50-329, 84/01/06, 8401100210

8401160036 Forwards Const Implementation Overview 038 Checklist developed by Bechtel for status assessments of Rev 1 to Procedure FPM-7 000, "Mechanical Sys Status & Completion, " lacks procedure attributes
KARR, J E Stone & Webster, Inc 84/01/06 GUAMME, D L Consumers Power Co 2pp 21815 208 24X Fiche 50-329, 84/01/06, 8401160036

8401160096 Forwards open Const Implementation Overview Items/Hold Point Notifications 041, 042 & 043 for action/info Installation work on emergency diesel generators may be affected by evaluation of Phase III activities
BARANDOW, S W Stone & Webster, Inc 84/01/06 GUAMME, D L, Duke Power Co 8pp 21815 277 24X Fiche 50-329, 84/01/06, 8401160096

8401170369 Forwards open CIO item/hold point notifications, Items 041, 042 & 043 Phase III evaluation results re document control & applicant corrective action plan info request
BARANDOW, S W Stone & Webster, Inc 84/01/06 GUAMME, D L Consumers Power Co 8pp 21828 215 24X Fiche 50-329, 84/01/06, 8401170369

190424 Forwards const implementation overview/hold point
ification for Phase III resolution re civil discipline -
ils for appropriate action
RANDW, S W Stone & Webster, Inc 84/01/10 GUAMME, D L
Consumers Power Co 4pp 21849 289 24X Fiche 50-329, 84/01/10,
01190424

190329 Requests authorization to proceed w/Work Authorization
cedure 142550000 re preparation of auxiliary bldg roof as
quired for crack survey
ONEY, J A Consumers Power Co 84/01/11 HARRISON, J J Region 3,
fice of Director 1p 21850 357 24X Fiche 50-329, 84/01/11,
01190329

190335 Forwards list of const personnel completing training
quirements to commence status assessment
AMME, D L Consumers Power Co 84/01/11 BARANDW, S W Stone &
bster, Inc 4pp 21851 266 24X Fiche 50-329, 84/01/11,
01190335

230146 Forwards list of Bechtel const personnel who completed
aining requirements to commence status assessment
Pillsbury should be contacted to initiate individual
dit requirements
AMME, D L Consumers Power Co 84/01/11 BARANDW, S W Stone &
bster, Inc 4pp 21884 352 24X Fiche 50-329, 84/01/11,
01230146

230169 Authorizes start of remedial soils activities identified in
cl scheduled for Jan 1984
JKR, R J Region 3, Office of Director 84/01/11 GUAMME, D L
Consumers Power Co 3pp 21884 122 24X Fiche 50-329, 84/01/11,
01230169

230356 Forwards list of Bechtel const personnel who have completed
ining requirements to commence status assessment
AMME, D L Consumers Power Co 84/01/12 BARANDW, S W Stone &
bster, Inc 10pp 21873 344 24X Fiche 50-329, 84/01/12,
01230356

130084 Generic Ltr 84-03 to all licensees of operating reactors.
licants for QLS & holders of CPs re availability of
IEQ-0933, "Prioritization of Generic Safety Issues"
1st encl.
EINHUT, D O Division of Licensing 84/01/13 Consolidated
son Co of New York, Inc 18pp 21946 174 24X
he: 50-000, 84/01/13, 8401130084

130509 Forwards 840112 list of Bechtel const personnel trained to
mmence status assessment & replacement list dtd 840109
idventently detached from 840112 transmittal
Consumers Power Co 84/01/13 Stone & Webster, Inc 10pp
178 221. 24X Fiche 50-329, 84/01/13, 8401230509

140501 Transmits actions which have or will be taken to address
cerns identified in mgt corrective action Request/Rept
-1 & S&W Const Implementation Overview Item 043
ussion on document control actions also encl
AMME, D L Consumers Power Co 84/01/16 BARANDW, S W Stone &
bster, Inc 10pp 21917 105 24X Fiche 50-329, 84/01/16,
01240501.

40610 Forwards affidavits & resumes for JP Oliveira & BA Metros.
to independent assessment team
KB, A S Stone & Webster Engineering Corp 84/01/16
RIBON, J J Region 3, Office of Director 5pp 21909 215 24X
he: 50-329, 84/01/16, 8401240610

20133 Supplemental Board Notification 84-010 forwards info re
sel generator bldg safety issues in facility OM/OX.
ceding JP Matra, of Naval Surface Weapons Ctr. meeting
as encl
AK, T. M Assistant Director for Licensing 84/01/17
HHOEFER, C, HARBOR, J, LOWAN, F Atomic Safety and Licensing
rd Panel 7pp 21940 201 24X Fiche 50-329, 84/01/17, 8312120133

70536 Notification of 840126 meeting w/OL applicants in Bethesda.
to discuss limited operational experience on operating
us & development of acceptable experience profile for
plants
NDN, J. Division of Licensing, 84/01/17 Division of
ensing, 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

30158 Forwards resumes & statements of independence for M Holley,
agail, P Streeter, H Lambert, J L Chameau & O Reimers for
rtion in QA program. App C in accordance w/independent
ign & const verification program
IN, H A TERA Corp 84/01/18 KEPLER, J O Region 3, Office of
ector EISENHUT, D O Division of Licensing CODK, J W,
umers Power Co 25pp 21875, 273 24X Fiche 50-329, 84/01/18,
1230158

8401270370 Advises that results of sampling insp of encl const training
records satisfactory Personnel listed cleared to perform
status assessment NIR 006 closed out W/o encl
KARR, J E Stone & Webster, Inc 84/01/18 GUAMME, D L Consumers
Power Co 1p 21976 042 24X Fiche 50-329, 84/01/18, 8401270370

8401310136 Forwards closed const implementation overview Items 036 &
038 re control of field proposed changes
KARR, J E Stone & Webster, Inc 84/01/18 GUAMME, D L Consumers
Power Co 6pp 22022 101 24X Fiche 50-329, 84/01/18, 8401310136

8401310336 Forwards list of open const implementation overview Items
45, 46 & 48
KARR, J E Stone & Webster, Inc 84/01/18 GUAMME, D L Consumers
Power Co 5pp 22020 336 24X Fiche 50-329, 84/01/18, 8401310336

8401270291 Forwards list dtd 840117 of Bechtel personnel trained to
commence status assessment
* Consumers Power Co 84/01/19 Stone & Webster, Inc 2pp
21974 055 24X Fiche 50-329, 84/01/19, 8401270291

8401270349 Notifies that response to 840110 ltr will be delayed until
4 to 8 wks after mechanical stop work lifted Delay due to
util concern to properly assess results of stop work review
process
GUAMME, D L Carolina Power & Light Co 84/01/19 BARANDW, S W
Stone & Webster, Inc 1p 21981 008 24X Fiche 50-329, 84/01/19,
8401270349

8401270353 Forwards Audit Finding Rept M01-345-2-04F re storage
requirements of QA div generated QA records
* Consumers Power Co 84/01/19 Stone & Webster, Inc 4pp
21976 018 24X Fiche 50-329, 84/01/19, 8401270353

8401270367 Requests reauthorization for listed remedial soils work
which has passed or will pass 90-day authorization limit
GUAMME, D L Consumers Power Co 84/01/19 HARRISON, J J Region 3,
Office of Director 1p 21976 224 24X Fiche 50-329, 84/01/19,
8401270367

8401270470 Forwards monthly open item status rept, per D Browns
request W/o encl
* Consumers Power Co 84/01/19 Stone & Webster, Inc 1p
21981 298 24X Fiche 50-329, 84/01/19, 8401270470

8401270498 Forwards closed Const Implementation Overview 012 Phase I &
II complete for FCR/FCN review & Phase III completed for
Soils Stations 8, 10, 13, 24 & 64 Requirements for lifting
Stop Work Order 38 satisfied
KARR, J E Stone & Webster, Inc 84/01/19 GUAMME, D L Consumers
Power Co 2pp 21980 133 24X Fiche 50-329, 84/01/19, 8401270498

8401230489 Forwards summary of 840104 meeting w/util & Bechtel in Ann
Arbor, MI re independent design & const verification program
List of attendees & agenda encl
LEVIN, H A TERA Corp 84/01/20 EISENHUT, D O Division of
Licensing KEPLER, J O Region 3, Office of Director CODK, J W
Consumers Power Co 17pp 21882 097 24X Fiche 50-329, 84/01/20,
8401230489

8401240535 Authorizes listed critical work activities for Jan 1984
HARRISON, J J Region 3, Office of Director 84/01/20 GUAMME, D L
Consumers Power Co 1p 21907 326 24X Fiche 50-329, 84/01/20,
8401240535

--8401240542 Requests reauthorization for listed activities that passed
90-day authorization limit
GUAMME, D L Consumers Power Co 84/01/19 HARRISON, J J Region
3, Office of Director 2pp 21907 327 24X Fiche 50-329,
84/01/20, 8401240535

8401270494 Requests authorization to proceed w/remedial soils work, per
work Authorization Procedure 142550100 re removal of
concrete surface for crack measurements
GUAMME, D L Consumers Power Co 84/01/20 HARRISON, J J Region 3,
Office of Director 1p 21980 132 24X Fiche 50-329, 84/01/20,
8401270494

8401310014 Forwards I&C FCR/FCN register & General Spec FCR/FCN
register W/o encls
JOHNSON, D Consumers Power Co 84/01/20 Stone & Webster, Inc
1p 22023 341 24X Fiche 50-329, 84/01/20, 8401310014

8401310143 Forwards matrix displaying Phase I, II & III audit status
Open target dates for instrumentation, electrical &
mechanical disciplines requested
* Consumers Power Co 84/01/20 Stone & Webster, Inc 4pp
22022 076 24X Fiche 50-329, 84/01/20, 8401310143

DOCKETED ITEMS

8401310213 Advises that as result of 840120 partial release of Stop Work Order FSW-41 for civil & architectural documents. Bechtel released for status assessment for Modules 340, 102, 120, 410 & B00
QUAHME, D L Consumers Power Co 84/01/20 HIERZER, G A Bechtel Corp 15pp 22021 294 24X Fiche 50-329, 84/01/20, 8401310213

8401310327 Notifies of 840201 sixth status review meeting w/uttl & Bechtel in Ann Arbor, MI to discuss independent design & const verification program Agenda encl
LEVIN, H A TERA Corp 84/01/20 WEPPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 5pp 22026 276 24X Fiche 50-329, 84/01/20, 8401310327

8401310379 Forwards 840119 list of Bechtel personnel trained to commence status assessment
* Consumers Power Co 84/01/20 Stone & Webster, Inc 2pp 22012 355 24X Fiche 50-329, 84/01/20, 8401310379

8401310293 Forwards closed const implementation overview Items 42, 44 * Hold Points 13 & 14 notifications
KARR, J C Stone & Webster, Inc 84/01/23 QUAHME, D L Consumers Power Co 5pp 22020 271 24X Fiche 50-329, 84/01/23, 8401310293

8401300159 Authorizes work on Activity 142550100 re removal of concrete surface for crack measurements
HARRISON, J J Region 3, Office of Director 84/01/24 QUAHME, D L Consumers Power Co 2pp 21996 267 24X Fiche 50-329, 84/01/24, 8401300159

F Security, medical, emergency & fire protection plans

8401050026 Releases public version of State of MI emergency preparedness plan
FELTON, J M Division of Rules and Records 83/12/27 Document Management Branch 1p 21734 001 24X Fiche 50-329, 83/12/27, 8401050026

--8401050031 Public version of State of MI emergency preparedness plan W/831104 ltr
BLANCHARD, J J, HOUGH, G L Michigan, State of 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 49pp 21734 002 24X Fiche 50-329, 83/12/27, 8401050031

8401230270 Notifies of FEMA 840112-13 meetings in Chicago, IL re radiological emergency preparedness program to develop final FY84/FY85 emergency preparedness exercise schedule & prompt alert notification certification schedule
PAPERICLLO, C J Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 4pp 21884 207 24X Fiche 50-000, 84/01/05, 8401230270

8401250099 Releases public version of revised controlled copyholder list
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21759 158 24X Fiche 50-000, 84/01/18, 8401250099

--8401250102 Public version of Rev 4 to controlled copyholder list of general ofc ctr/emergency operations facility emergency implementing procedures
* Consumers Power Co 83/11/10 Office of Nuclear Reactor Regulation, Director 7pp 21959 159 24X Fiche 50-000, 84/01/10, 8401250099

Adjudicatory correspondence

01030179 Order extending time until 840118 for Commission to act to review Director's Decision DD-83-16
CHILK, S J Office of the Secretary of the Commission 83/12/29 Commissioners 1p 21681 323 24X Fiche 50-329, 83/12/29, 8401030179

8401090366 Forwards replies to NRC 831115 & Stamiris 831216 findings on remedial soils issues, per ASLB 830929 order
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co 84/01/03 BECHHOEFER Atomic Safety and Licensing Board Panel 1p 21733 300 24X Fiche 50-329, 84/01/03, 8401090366

--8401090375 Reply opposing Stamiris 831216 proposed findings of fact & conclusions of law on remedial soils issues GA implementation of remedial work issues should be addressed separately from technical adequacy issues
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 84/01/06 15pp 21753 301 24X Fiche 50-329, 84/01/03, 8401090366

--8401090384 Reply to NRC 831115 findings of fact & conclusions of law on remedial soils issues Certificate of Svc encl
STEPTOE, P P Consumers Power Co STEPTOE, P P Isham, Lincoln & Beale 84/01/03 13pp 21733 316 24X Fiche 50-329, 84/01/03, 8401090366

8401250090 Forwards 840112 Director's Decision DD-84-2, supplementing Director's Decision DD-83-16 which granted BP Garde 10CFR2 206 request for audit of util mgt
WILCOVE, M N Hearing Branch 2 84/01/13 BECHHOEFER, C , COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 17pp 21936 172 24X Fiche 50-329, 84/01/13, 8401250090

8401200116 Order extending time until 840127 for Commission to act to review Director's Decision DD-83-16
CHILK, S J Office of the Secretary of the Commission 84/01/18 Commissioners 1p 21866 360 24X Fiche 50-329, 84/01/18, 8401200116

8401240073 Forwards util preliminary pretrial statement filed in State of MI Circuit Court for County of Midland Statement sent in fulfillment of obligation to keep ASLB informed of developments relevant to proceeding
STEPTOE, P P Isham, Lincoln & Beale 84/01/19 BECHHOEFER, C , COHAN, F P, HARBOUR, J Atomic Safety and Licensing Board Panel 7pp 21912 280 24X Fiche 50-329, 84/01/19, 8401240073

8401300238 Summarizes 840116 telcon w/L Romo re relatively few enforcement fines levied on util & enforcement action to be taken based on hearing findings that util violated NRC order
JODSTEN, J Commissioners 84/01/17 Commissioners 1p 21998 362 24X Fiche 50-329, 84/01/19, 8401300238

8401270384 Request for leave to file encl corrected copies of applicant 831209 memorandum in opposition to appeal of Govt Accountability Project Table of contents & table of authorities inadvertently omitted Certificate of Svc encl
STEINDEL, S H Consumers Power Co STEINDEL, S H Isham, Lincoln & Beale 84/01/23 Atomic Safety and Licensing Appeal Panel 4pp 21976 165 24X Fiche 50-329, 84/01/23, 8401270384

--8401270391 Memorandum in opposition to Govt Accountability Project deponent 831021 appeal ASLB rulings do not constitute abuse of discretion & should be sustained Deponents should be ordered to appear per subpoenas Certificate of Svc encl
PROCTOR, S D Consumers Power Co PROCTOR, S D Isham, Lincoln & Beale 83/12/09 Atomic Safety and Licensing Appeal Panel 55pp 21976 169 24X Fiche 50-329, 84/01/23, 8401270384

8401270371 Notice of appearance in proceeding Certificate of Svc encl
STEINDEL, S H Consumers Power Co STEINDEL, S H Isham, Lincoln & Beale 84/01/24 3pp 21976 225 24X Fiche 50-329, 84/01/24, 8401270371

8401300191 Order extending time until 840210 for Commission to act to review Director's Decisions DD-83-16 & DD-84-2
CHILK, S J Office of the Secretary of the Commission 84/01/27 Commissioners 1p 21997 349 24X Fiche 50-329, 84/01/27, 8401300191

G Inspection reports, IE Bulletins & correspondence

8401230621 FOIA request for IE B00103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response
WINSLOW, R Wall Street Journal 83/09/28 NRC - No Detailed Affiliation Given 1p 21905 336 24X Fiche 50-329, 83/09/28, 8401230621

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401230630 Partial response to FOIA request for IE B00103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addl records in progress
FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21905 337 24X Fiche 50-329, 83/11/01, 8401230630

- 7812070139 Recommends that the Board be notified re reported settlement in diesel generator bldg Related interim deficiency rept submitted on 780929 & insp conducted on 781024-27 to examine details of problem [Encl 78100602853]
THORNBERG, H D Division of Reactor Construction Inspection
78/11/09 GOWER, G C Executive Officer for Operations Support
1p 21905 339 24X Fiche 50-329, 83/11/01, 8401230630
- 7908070022 Forward comments & recommendation resulting from review of Region 3 enforcement package dtd 790403 on facility settlement problems Four matl false statement identified out of five Expects imposition of civil penalties
THORNBERG, H D Division of Reactor Construction Inspection
79/06/13 THOMPSON, D Executive Officer for Operations Support
2pp 21905 341 24X Fiche 50-329, 83/11/01, 8401230630
- 7912140299 Comments on action needed for 790423 enforcement package re matl false statement in FSAR
THORNBERG, H D Division of Reactor Construction Inspection
79/09/27 GOWER, G C Executive Officer for Operations Support
2pp 21905 344 24X Fiche 50-329, 83/11/01, 8401230630
- 8002120130 Forwards info re order to modify CP including matl false statement consideration
THORNBERG, H D Division of Reactor Construction Inspection
80/01/03 FORTUNA, R Office of Inspector & Auditor 4pp
21905 348 24X Fiche 50-329, 83/11/01, 8401230630
- 8401230639 Discusses IE investigation re FSAR submittals Several incorrect statements re soil foundation appear to reflect matl false statements
SINCLAIR, J R Office of Inspector & Auditor 79/03/20 Office of Inspector & Auditor 1p 21905 340 24X Fiche 50-329, 83/11/01, 8401230630
- 8401230644 Discusses status of IE investigation re FSAR submittals
SINCLAIR, J R Office of Inspector & Auditor 79/06/26 Office of Inspector & Auditor 1p 21905 343 24X Fiche 50-329, 83/11/01, 8401230630
- 8401230651 Discusses enforcement action re diesel generator bldg & plant fill areas, per 790403 memo to HD Thornburg Item 1 considered matl false statement Four items should be treated as items of noncompliance
GOWER, G C Executive Officer for Operations Support 79/10/04
KEPPLER, J O Region 3, Chicago, Office of the Director 2pp
21905:346 24X Fiche 50-329, 83/11/01, 8401230630
- 8401050350 Forwards J Christy 831121 & 1206 memos re reinsp of 500 large bore hangers
QUAHME, D L Consumers Power Co 83/12/22 BARANOW, B W Stone & Webster, Inc 4pp 21729 255 24X Fiche 50-329, 83/12/22, 8401050350
- 8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- 8401050544 Responds to IE Bulletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co (HTPC)," per 830810 commitment No HTPC pumps used in safety-related sys at facilities HTPC spare parts purchased
HOWELL, B H Consumers Power Co 83/12/28 KEPPLER, J O Region 3, Office of Director 5pp 21726 054 24X Fiche 50-329, 83/12/28, 8401050544
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093
- 8401060496 Ack receipt of 831220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-23 & 50-330/83-24
WARNICK, R F Region 3, Office of Director 84/01/04 COOK, J W Consumers Power Co, 2pp 21739 339 24X Fiche 50-329, 84/01/04, 8401060496
- 8401060500 Responds to NRC 831117 ltr re violations noted in IE Insp Repts 50-329/83-23 & 50-330/83-24 Corrective actions Nonconformance Rept GAR 85-00024 re omission of calibr stickers on hydraulic meters initiated.
COOK, J W Consumers Power Co 83/12/20 KEPPLER, J O Region 3, Office of Director 4pp 21739.341 24X Fiche 50-329, 84/01/04, 8401060496.
- 8401190281 Forwards IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 No noncompliance noted
WARNICK, R F Region 3, Office of Director 84/01/05 COOK, J W Consumers Power Co 2pp 21850 301 24X Fiche 50-329, 84/01/05, 8401190281
- 8401190286 IE Insp Repts 50-329/83-21 & 50-330/83-22 on 831021-1120 No noncompliance noted Major areas inspected previously identified items, remedial soil work activities, allegations & document control stop work order
HARRISON, J J, DURGESE, B L, COOK, R J Region 3, Office of Director 84/01/04 6pp 21850 303 24X Fiche 50-329, 84/01/05, 8401190281
- 8401100210 Forwards IE Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted
WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W Consumers Power Co 2pp 21758 001 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100221 IE Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted subcontractor used procedure w/hold indicated, incomplete entry of crack monitoring data & MPDAP group insp repts not submitted promptly
GARDNER, R N, HARRISON, J J Region 3, Office of Director 84/01/06 4pp 21758 003 24X Fiche 50-329, 84/01/06, 8401100210
- 8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 053 24X Fiche 50-000, 84/01/10, 8312120104
- 8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107
- 8401190368 Requests info for scheduling verification activities & developing sampling plans for hanger reinsp program
BARANOW, B W Stone & Webster, Inc 84/01/10 QUAHME, D L Consumers Power Co 4pp 21850 158 24X Fiche 50-329, 84/01/10, 8401190368
- 8401200077 Forwards confirmatory order re plan for independent appraisal of mgt organization re excavation of soil matl & fireline relocation activities w/o prior NRC approval
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/12 SELBY, J D Consumers Power Co 2pp 21872 197 24X Fiche 50-329, 84/01/12, 8401200077
- 8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114
- 8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUBO, R Licensing Branch 2 84/01/17 SCHWENGER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- R Periodic operating reports & related correspondence
- 8401050156 Forwards ALAB-106 monthly rept for Nov 1983
COOK, J W Consumers Power Co 83/12/27 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 183pp 21718 284 24X Fiche 50-329, 83/12/27, 8401050156
- 8401160124 Forwards const implementation overview weekly Rept 28 for 831219-23 Rept includes summary of open items, nonconformance identification reports & hold points
BARANOW, B W Stone & Webster, Inc 83/12/28 KEPPLER, J O Region 3, Office of Director 11pp 21821 155 24X Fiche 50-329, 83/12/28, 8401160124

DOCKETED ITEMS

- 8401160079 Forwards Rept 29 for const implementation overview for period 831226-30
BARANOW, S W Stone & Webster, Inc 84/01/04 KEPLER, J G Region 3, Office of Director 10pp 21821 191 24X Fiche 50-329, 84/01/04, 8401160079
- 8401100210 Forwards IF Mgt Meeting Repts 50-329/83-25 & 50-330/83-26 on 831208 Violation noted
WARNICK, R F Region 3, Office of Director 84/01/06 COOK, T W Consumers Power Co 2pp 21758 001 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100228 Forwards Independent Assessment of Underpinning Weekly Rept 59 for 831030-1105 Minutes of daily meetings between assessment team & site engineering, const & QA personnel encl
LUCK, B S Stone & Webster, Inc 83/11/09 COOK, R NRC - No Detailed Affiliation Given 30pp 21758 036 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100234 Forwards Const Implementation Overview Rept 21 for 831031-1104 Evaluations of const completion program activities, nonconformance identification repts & hold points encl
BARANOW, S W Stone & Webster, Inc 83/11/08 KEPLER, J G Region 3, Office of Director 14pp 21758 086 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100238 Forwards Const Implementation Overview Rept 22 for 831107-11 Evaluations of const completion program activities & matrices of observations, nonconformance identification repts & hold points encl
BARANOW, S W Stone & Webster, Inc 83/11/14 KEPLER, J G Region 3, Office of Director 15pp 21758 100 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100257 Forwards Const Implementation Overview Rept 23 for 831114-18 Evaluations of const completion program activities & matrices of observation, nonconformance identification repts & hold points encl
BARANOW, S W Stone & Webster, Inc 83/11/22 KEPLER, J G Region 3, Office of Director 16pp 21758 117 24X Fiche 50-329, 84/01/06, 8401100210
- 8401100261 Forwards Const Implementation Overview Rept 24 for 831121-23 Evaluations of const completion activities & matrices of observations, nonconformance identification repts & hold points encl
BARANOW, S W Stone & Webster, Inc 83/11/29 KEPLER, J G Region 3, Office of Director 12pp 21758 133 24X Fiche 50-329, 84/01/06, 8401100210
- 401190348 Forwards Const Implementation Overview Weekly Repts 27 & 28 for Items 39 & 40 Drawing A-213 added to file Resampling conducted
BARANOW, S W Stone & Webster, Inc 84/01/10 GUAMME, D L Consumers Power Co 3pp 21850 327 24X Fiche 50-329, 84/01/10, 8401190348
- 8401230340 Forwards const implementation overview Weekly Rept 30 for 840103-06 Rept includes summary of open items, nonconformance identification repts & hold points
BARANOW, S W Stone & Webster, Inc 84/01/11 KEPLER, J G Region 3, Office of Director 12pp 21883 215 24X Fiche 50-329, 84/01/11, 8401230340
- 8401170380 Forwards "Midland Independent Design & Const Verification Program," Monthly Status Rept B for Dec 1983
LEVIN, H A TERA Corp 84/01/13 KEPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 3pp 21829 001 24X Fiche 50-329, 84/01/13, 8401170380
- 8401170385 "Midland Independent Design & Const Verification Program," Monthly Status Rept B for Dec 1983
DOUGHERTY, F A, TULODIESKI, D B, LEVIN, H A TERA Corp 83/12/31 38pp 21829 004 24X Fiche 50-329, 84/01/13, 8401170380
- 401230493 Forwards monthly status rept for Dec 1983
WARNICK, R F Region 3, Office of Director 84/01/18 KEPLER, J G Region 3, Office of Director 1p 21882 093 24X Fiche 50-329, 84/01/18, 8401230493
- 8401230497 Forwards monthly status rept for Dec 1983
COOK, R J Region 3, Office of Director 84/01/12 WARNICK, R F Region 3, Office of Director 2pp 21882 094 24X Fiche 50-329, 84/01/18, 8401230493
- 1401270252 Requests transmittal of weekly repts to LPDR, Grace Dow Memorial Library in Midland, MI Repts should also be furnished to NRC & util
HARRISON, J J Region 3, Office of Director 84/01/25 ANDRUSO, P LUCK, B E&O, Inc 2pp 21782 182 24X Fiche 50-329, 84/01/25, 8401270252
- 8401310026 Forwards Dec 1983 monthly rept in accordance w/condition of Memorandum & Order ALAD-106, dtd 730323 & Amend 1 to CRR-81 & CRR-82
COOK, J W Consumers Power Co 84/01/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1,868pp 22007 001 24X Fiche 50-329, 84/01/25, 8401310026
- 9 Reportable occurrences, LERs & related correspondence
- 8401100315 Forwards nonconformance identification rept re civil review Phase III re inconsistent quality distribution for design drawings & specs for appropriate action
BARANOW, S W Stone & Webster Engineering Corp 83/01/03 GUAMME, D L Consumers Power Co 3pp 21763 284 24X Fiche 50-329, 83/01/03, 8401100315
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response
FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21905 337 24X Fiche 50-329, 83/11/01, 8401230630
- 8401040200 Fifth interim Deficiency Rept 83-01 re loose locking clips in instrument cabinets No change in status of item since 830930 ltr due to hold placed on all Q work at site Next rept by 840330
COOK, J W Consumers Power Co 83/12/23 KEPLER, J G Region 3, Office of Director 3pp 21701 195 24X Fiche 50-329, 83/12/23, 8401040200
- 8401040461 Interim deficiency rept re reactor bldg spray piping supports Pipe hanger testing completed Remaining activities still progressing Next rept expected by 840330
COOK, J W Consumers Power Co 83/12/23 KEPLER, J G Region 3, Office of Director 2pp 21707 341 24X Fiche 50-329, 83/12/23, 8401040461
- 8401040508 Interim potential deficiency rept re safety-related electrical equipment not meeting project requirements Site overinsps will be conducted on 66 purchase orders Next rept expected by 840330
COOK, J W Consumers Power Co 83/12/23 KEPLER, J G Region 3, Office of Director 3pp 21705 335 24X Fiche 50-329, 83/12/23, 8401040508
- 8401160124 Forwards const implementation overview weekly Rept 28 for 831217-23 Rept includes summary of open items, nonconformance identification repts & hold points
BARANOW, S W Stone & Webster, Inc 83/12/28 KEPLER, J G Region 3, Office of Director 11pp 21821 155 24X Fiche 50-329, 83/12/28, 8401160124
- 8401040216 Informa of completion of review of listed corrective actions taken re identified crack monitoring sys deficiencies
HARRISON, J J Region 3, Office of Director 83/12/29 MOONEY, J Consumers Power Co 2pp 21701 291 24X Fiche 50-329, 83/12/29, 8401040216
- 8401100002 Forwards CIO NIR 011 re architectural review, Phase III, FCR/FCN Midland CIO drawing Stations 51 & 59 Two retired drawings identified w/o proper notation
BARANOW, S W Stone & Webster, Inc 84/01/03 GUAMME, D L Consumers Power Co 2pp 21761 208 24X Fiche 50-329, 84/01/03, 8401100002
- 8401100465 Forwards CIO Nonconformance Identification Rept (NIR) 012 re FSK drawing discrepancy w/Bechtel master composite register & design drawings & spec inconsistent w/quantity distribution requirements
BARANOW, S W Stone & Webster, Inc 84/01/03 GUAMME, D L Consumers Power Co 3pp 21761 288 24X Fiche 50-329, 84/01/03, 8401100465
- 8401160090 Forwards Quality Action Request RB-00106 generated by BA dept to track QAAIL program deficiencies identified in NIR-012
GUAMME, D L Consumers Power Co 84/01/05 BARANOW, S W Stone & Webster, Inc 3pp 21821 183 24X Fiche 50-329, 84/01/05, 8401160090
- 8401130280 EN-84-001 confirmatory order will be issued on or about 840112 Order confirms commitment & requires util to submit plan for independent appraisal of site & corporate mgt organizations & functions
KLINLER, Q, AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/01/06 1p 21798 360, 24X Fiche 50-329, 84/01/06, 8401130280

8401170212 Interim Deficiency Rept 83-11 #1 re potentially defective capstan springs in Pacific Scientific mechanical shock arrestors Initially reported on 831207 Investigation continuing Next rept will be submitted by 840316
CDDK, J W Consumers Power Co 84/01/06 KEPLER, J G Region 3, Office of Director 18pp 21832 281 24X Fiche 50-329, 84/01/06, 8401170212

8401170430 Interim deficiency rept re inconsistent processing & review of field change request/field change notices against project design documents Initially reported on 831121 Review program established Next rept expected 840210
CDDK, J W Consumers Power Co 84/01/06 KEPLER, J G Region 3, Office of Director 9pp 21827 148 24X Fiche 50-329, 84/01/06, 8401170430

8401170447 Interim deficiency rept re ITT Grinnell mechanical snubber assemblies Initially reported on 831209 All Figure 306 & 30n snubbers will be evaluated, repaired or replaced Next rept expected by 840323
CDDK, J W Consumers Power Co 84/01/06 KEPLER, J G Region 2, Office of Director 7pp 21827 091 24X Fiche 50-329, 84/01/06, 8401170447

8401170184 Interim Deficiency Rept 83-03 #3 re cracking of core support structure bailing ASME SA 453 Grade 660 (A-286) bolts will be replaced w/fasteners fabricated from listed matls Next rept by 840330
CDDK, J W Consumers Power Co 84/01/09 KEPLER, J G Region 3, Office of Director App 21831 346 24X Fiche 50-329, 84/01/09, 8401170184

8401170185 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utilis notified BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 267 24X Fiche 50-000, 84/01/09, 8401170185

8401190378 Forwards nonconformance identification rept On 831214, discovered that potential exists for Field Change Request C-1526 to be misapplied to Drawings C-398 & C-479 Addl Field change request resolution sheet issued
BARANOW, S W Stone & Webster, Inc 84/01/10 GUANNE, D L Consumers Power Co App 21850 131 24X Fiche 50-329, 84/01/10, 8401190378

8401190397 Forwards 831211 nonconformance identification rept Drawing A-213 missing during sample insp of controlled architectural drawings Entire lot of drawings rejected Missing drawing added to stick drawing acceptable
BARANOW, S W Stone & Webster, Inc 84/01/10 GUANNE, D L Consumers Power Co 2pp 21849 347 24X Fiche 50-329, 84/01/10, 8401190397

8401190402 Interim deficiency rept re broken/cracked puffer piston rods in Model 5 Hk breakers mfg by Brown-Boveri Initially reported on 831213 Safety evaluation performed Nonconformance rept issued Next rept by 840330
CDDK, J W Consumers Power Co 84/01/12 KEPLER, J G Region 3, Office of Director 14pp 21850 101 24X Fiche 50-329, 84/01/12, 8401190402

8401230331 Interim deficiency rept re differential settlement between diesel generator structure & pedestal Initially reported on 831214 Interim or final rept will be submitted by 840420
CDDK, J W Consumers Power Co 84/01/13 KEPLER, J G Region 3, Office of Director 5pp 21884 232 24X Fiche 50-329, 84/01/13, 8401230331

8401230344 Interim deficiency rept re attachment of non-Q/nonseismic piping to component cooling water sys Initially reported on 831216 Interim or final rept will be submitted by 840420
CDDK, J W Consumers Power Co 84/01/16 KEPLER, J G Region 3, Office of Director 6pp 21882 346 24X Fiche 50-329, 84/01/16, 8401230344

8401240509 Forwards, for review for closure of NIR-0012, QA Requests GAR-RS-00106 & GAR-RS-00109 re deficiencies at Stations B & 10, respectively
* Consumers Power Co 84/01/17 Stone & Webster, Inc 23pp, 21917: 117 24X Fiche 50-329, 84/01/17, 8401240509

V Operator Examinations

8401230253 Forwards updated estimated schedule for nuclear instructor program & operator & instructor licensing programs through FY87, per Generic Ltr 83-40
BORDINE, T C Consumers Power Co 84/01/16 EISENHUT, D G Division of Licensing 6pp 21884 290 24X Fiche 50-000, 84/01/16, 8401230253

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

8401170527 Forwards exemption from certain requirements of 10CFR50.48 10CFR50, App R re fire protection & safety evaluation accepting licensee 820622, 830110 & 0215 exemption requests VASSALLO, D B Operating Reactors Branch 2 83/12/19 LIU, L Iowa Electric Light & Power Co 2pp 21847 074 24X Fiche 50-331, 83/12/19, 8401170527

--8401170530 Exemptions from requirements of Section III G of 10CFR50 App R re fire protection of reactor bldg southwest corner, turbine bldg water treatment condensate pump area & Fire Zones 2-A, 2-B, 3-A, 4-A & 16-F
EISENHUT, D G Division of Licensing 83/12/19 Iowa Electric Light & Power Co 12pp 21847 076 24X Fiche 50-331, 83/12/19, 8401170527

--8401170531 Safety evaluation granting licensee 820622, 830110 & 0215 requests for exemptions from requirements of 10CFR50, App R
EBERLY, R Office of Nuclear Reactor Regulation, Director 83/12/19 19pp 21847 088 24X Fiche 50-331, 83/12/19, 8401170527

8312290259 Forwards changes to security plan Changes withheld (ref 10CFR73.21)
MCAUGHY, R W Iowa Electric Light & Power Co 83/12/21 KEPLER, J G Region 3, Office of Director 1p 21658 220 24X Fiche 50-331, 83/12/21, 8312290259

8401090265 Forwards safety parameter display sys implementation plan & SAR, per NUREG-0737, Suppl 1 requirements Sys installation does not require Tech Spec change
MCAUGHY, R W Iowa Electric Light & Power Co 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21754 238 24X Fiche 50-331, 84/01/03, 8401090265

--8401090275 "Safety Parameter Display Sys Implementation Plan for Duane Arnold Energy Ctr"
* Iowa Electric Light & Power Co 83/12/30 21pp 21754 239 24X Fiche 50-331, 84/01/03, 8401090265

--8401090280 "Duane Arnold Energy Ctr Safety Parameter Display Sys SAR"
* Iowa Electric Light & Power Co 83/12/30 44pp 21754 260 24X Fiche 50-331, 84/01/03, 8401090265

8401130289 Ack receipt of 831221 ltr transmitting changes to facility modified amended security plan Changes consistent w/provisions of 10CFR50.54(p) & acceptable
AXELSON, W L Region 3, Office of Director 84/01/07 LIU, L Iowa Electric Light & Power Co App 21801 122 24X Fiche 50-331, 84/01/09, 8401130289

8401160140 Confirms plans for 840113 enforcement conference in Glen Ellyn, IL to discuss circumstances surrounding recent security events
MORELIUS, C E Division of Project & Resident Programs 84/01/10 LIU, L Iowa Electric Light & Power Co 1p 21815 326 24X Fiche 50-331, 84/01/10, 8401160140

8401180219 Forwards modified, amended security plan changes Changes withheld (ref 10CFR73.21)
MCAUGHY, R W Iowa Electric Light & Power Co 84/01/12 KEPLER, J G Region 3, Office of Director 1p 21844 214 24X Fiche 50-331, 84/01/12, 8401180219

8401270461 Forwards IG Insp Rept 50-331/83-17 on 831101-1230 No noncompliance noted
SHAFFER, W D Region 3, Office of Director 84/01/16 LIU, L Iowa Electric Light & Power Co 2pp 21980 279 24X Fiche 50-331, 84/01/16, 8401270461

--8401270469 IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance or deviations identified Major areas inspected licensee actions on previous insp findings, operational safety, maint, surveillance, plant trips & IE bulletins & circulars
CLANDY, L S, WALKER, R D Region 3, Office of Director 84/01/16 12pp 21980 281 24X Fiche 50-331, 84/01/16, 8401270461

8401250058 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21947 108 24X Fiche 50-331, 84/01/18, 8401250058

DOCKETED ITEMS

--B401250059 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP-6.3, "Maint of Emergency Equipment & Supplies" w/831129 transmittal & receipt form
 * Iowa Electric Light & Power Co 83/11/29 Office of Nuclear Reactor Regulation, Director 4pp 21947 109 24X
 Fiche 50-331,84/01/18,8401250058

Operating license stage documents & correspondence

8401160003 Requests commitment that 6-month test frequency & testing within 72 h after purge/vent sys usage during normal operation comply w/NRC guidelines Response due in 30 days
 VASSALLO, D B Operating Reactors Branch 2 83/12/22 LIU, L Iowa Electric Light & Power Co 2pp 21821 341 24X
 Fiche 50-331,83/12/22,8401160003

8401300023 Informs that TMI Action Items II K 3 30 & II K 3 31 completed, based on NRC 831213 acceptance of GE small break LOCA model Requests confirmation as to model use
 VASSALLO, D B Operating Reactors Branch 2 83/12/28 LIU, L Iowa Electric Light & Power Co 2pp 22027 029 24X
 Fiche 50-331,83/12/28,8401300023

8401170501 Forwards SER & conclusions re review of consequences of hypothetical LOCA while containment in purge mode & reactor at full power operation issue resolved for facility
 VASSALLO, D B Operating Reactors Branch 2 83/12/29 LIU, L Iowa Electric Light & Power Co 2pp 21847 156 24X
 Fiche 50-331,83/12/29,8401170501

--8401170504 Safety evaluation supporting previous SER conclusions re radiological consequences of LOCA during containment purge
 * Office of Nuclear Reactor Regulation, Director 83/12/29 2pp 21847 158 24X Fiche 50-331,83/12/29,8401170501

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
 EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc 16pp 21946 190 24X
 Fiche 50-000,84/01/05,8401050382

8401190014 Notification of 840207 meeting w/util & Bechtel in Bethesda, MD to resolve outstanding issues re environ qualification of electrical equipment
 THADANI, M C Operating Reactors Branch 2 84/01/05 VASSALLO, D B Operating Reactors Branch 2 1p 21870 314 24X
 Fiche 50-331,84/01/05,8401190014

01090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
 Svc list encl
 EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co. of New York, Inc 18pp 21957 267 24X
 Fiche 50-000,84/01/06,8401090221

01250294 Forwards Rev 5 to inservice testing program for pumps & valves Response to SER dtd 830926 re pending relief requests, also encl
 MCGAUGHY, R W Iowa Electric Light & Power Co 84/01/12 DENTON, H Office of Nuclear Reactor Regulation, Director 8pp 21943 321 24X Fiche 50-331,84/01/12,8401250294

--8401250296 Rev 5 to inservice testing program for pumps & valves
 YOUNG, K Iowa Electric Light & Power Co 83/12/23 145pp 21943 329 24X Fiche 50-331,84/01/12,8401250294

01130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of URG-0933, "Prioritization of Generic Safety Issues" Svc list encl
 EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X
 Fiche 50-000,84/01/13,8401130084

1240228 Forwards proposed agenda for 840207 meeting to discuss status of util program for environ qualification of electrical equipment & schedule for completion of any open action items
 MCGAUGHY, R W Iowa Electric Light & Power Co 84/01/18 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 21910 180 24X Fiche 50-331,84/01/18,8401240228

1240196 Forwards response to NRC 831130 request for addl info re REQ-0737, Item II R 3 concerning post-accident sampling
 s Boron analysis will be performed per Procedure PASAP 3 4 ing carminic acid analysis method
 MCGAUGHY, R W Iowa Electric Light & Power Co 84/01/19 DENTON, H Office of Nuclear Reactor Regulation, Director 6pp 21910 325 24X Fiche 50-331,84/01/19,8401240196

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
 Notebook also available in PDR
 FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
 Fiche 50-000,83/10/20,8401060040

--8401060150 List of SALP results during 1982
 * Director's Office, Office of Inspection and Enforcement 83/10/20 109pp 21744 004 24X Fiche 50-000,83/10/20,8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401100302 Ack receipt of 831216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/83-16
 SHAFER, W D Region 3, Office of Director 84/01/05 LIU, L Iowa Electric Light & Power Co 1p 21759 161 24X
 Fiche 50-331,84/01/05,8401100302

--8401100305 Responds to NRC 831117 ltr re violations noted in IE Insp Rept 50-331/83-16 Corrective actions increased emphasis directed to ensure attention to details re review of surveillance test procedures
 MCGAUGHY, R W Iowa Electric Light & Power Co 83/12/16 KEPLER, J G Region 3, Office of Director 3pp 21759 162 24X
 Fiche 50-331,84/01/05,8401100302

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 093 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401160140 Confirms plans for 840113 enforcement conference in Glen Ellyn, IL to discuss circumstances surrounding recent security events
 NORELUS, C E Division of Project & Resident Programs 84/01/10 LIU, L Iowa Electric Light & Power Co 1p 21815 326 24X
 Fiche 50-331,84/01/10,8401160140

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8401270461 Forwards IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance noted
 SHAFER, W D Region 3, Office of Director 84/01/16 LIU, L Iowa Electric Light & Power Co 2pp 21980 279 24X
 Fiche 50-331,84/01/16,8401270461

--8401270469 IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance of deviations identified Major areas inspected licensee actions on previous insp findings, operational safety, maint, surveillance, plant trips & IE bulletins & circulars
 CLARDY, L S, WALKER, R D Region 3, Office of Director 84/01/16 12pp 21980 281 24X Fiche 50-331,84/01/16,8401270461

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401230506 Confirms 840130 meeting in Glen Ellyn, IL to discuss status of regulatory improvement program
NORRELIUS, C E Division of Project & Resident Programs 84/01/18
LIU, L Iowa Electric Light & Power Co 1p 21878 231 24X
Fiche 50-331, 84/01/18, 8401230506

8401310024 Confirms 840109 telcon agreement that next 120-month inservice insp interval commences on 851101 Next 120-month inservice testing/insp interval will commence on 850201
MCQAUGHY, R W Iowa Electric Light & Power Co 84/01/24 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 22023 351 24X
Fiche 50-331, 84/01/24, 8401310024

R Periodic operating reports & related correspondence

8401180117 Monthly operating rept for Dec 1983 W/840113 ltr
ANDERSEN, M, MINECK, D L Iowa Electric Light & Power Co 83/12/31
Director's Office, Office of Inspection and Enforcement 7pp
21842 001 24X Fiche 50-331, 83/12/31, 8401180117

S Reportable occurrences, LERs & related correspondence

8401050451 LER 83-044/03L-0 on 831128, during normal operation, surveillance test of containment atmosphere dilution sys revealed pressure regulator PCV-4323A & B malfunctions Caused by worn O-rings & seats W/831228 ltr
HAMEL, D B, MINECK, D L Iowa Electric Light & Power Co 83/12/28
KEPPLER, J G Region 3, Office of Director 2pp 21730 208 24X
Fiche 50-331, 83/12/28, 8401050451

8401050466 LER 83-043/03L-0 on 831128, while performing daily instrument test, Torus B level transmitter functioned erratically Caused by corrosion & dirt building on internal amphenol connector Transmitter cleaned & recalibr W/831228 ltr
HARRIS, M S, MINECK, D L Iowa Electric Light & Power Co 83/12/28
KEPPLER, J G Region 3, Office of Director 2pp 21730 141 24X
Fiche 50-331, 83/12/28, 8401050466

8401050566 LER 83-046/03L-0 on 831201, reactor protection sys electric assembly B2 failed to trip output breaker at required frequency Caused by setpoint drift Test results will be monitored W/831231 ltr
HARRIS, M S, MINECK, D L Iowa Electric Light & Power Co 83/12/31
KEPPLER, J G Region 3, Office of Director 2pp 21725 235 24X
Fiche 50-331, 83/12/31, 8401050566

8401120423 LER 83-045/03L-0 on 831205, sys A 24-volt dc trouble alarm received HI-hi alarms from process rad monitors A & automatic initiation of standby gas treatment sys A also received Caused by loose card in charger W/840104 ltr
HARRIS, M S, MINECK, D L Iowa Electric Light & Power Co 84/01/04
KEPPLER, J G Region 3, Office of Director 3pp 21791 022 24X
Fiche 50-331, 84/01/04, 8401120423

8401270461 Forwards IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance noted
SHAFER, W D Region 3, Office of Director 84/01/16 LIU, L Iowa
Electric Light & Power Co 2pp 21980 279 24X
Fiche 50-331, 84/01/16, 8401270461

--8401270467 IE Insp Rept 50-331/83-17 on 831101-1230, No noncompliance or deviations identified. Major areas inspected licensee actions on previous insp findings, operational safety, maint, surveillance, plant trips & IE bulletins & circulars
CLARDY, L S, WALKER, R D Region 3, Office of Director 84/01/16
12pp 21980 281 24X Fiche 50-331, 84/01/16, 8401270461

8401270504 LER 83-047/03L-0 on 831220, ASME inservice test revealed 15.2 s closing of inboard steam line drain valve MO-4423, exceeding 15 s max. Cause not determined MO-4423 stroke time adjusted & returned to svc during shutdown W/840119 ltr
HAMEL, D B, MINECK, D L Iowa Electric Light & Power Co 84/01/19
KEPPLER, J G Region 3, Office of Director 2pp 21981 351 24X
Fiche 50-331, 84/01/19, 8401270504

V Operator Examinations

8401270486 Informs that written & oral operator & senior operator exams scheduled for wk of 840326 Requirements for conducting exams encl. Applications should be submitted 60 days prior to first exam
SPESSARD, R L Division of Engineering 84/01/25 LIU, L Iowa
Electric Light & Power Co 3pp 21981 295 24X
Fiche 50-331, 84/01/25, 8401270486

DOCKET 50-332 BARNWELL REPROCESSING PLANT

A Application/construction stage documents & correspondence

8401070066 Forwards application to amend State of SC Radioactive Matls License 144 & 831209 ltr to DOE summarizing current status of shutdown activities
BUCKHAM, J A Allied General Nuclear Services 83/12/13 ROUSE, L C
NRC - No Detailed Affiliation Given 6pp 21766 320 24X
Fiche 50-332, 83/12/13, 8401070066

--8401070083 Rev 1, to "Allied-General Nuclear Svcs Barnwell Nuclear Fuel Plant Decommissioning Plan "
* Allied General Nuclear Services 83/10/31 46pp 21766 326
24X Fiche 50-332, 83/12/13, 8401070066

G Inspection reports, IE Bulletins & correspondence

8401060407 Responds to IE Bulletin 83-07 & 83-07 Suppl 1, "Apparently Fraudulent Products Sold by Ray Miller, Inc " No subj matl installed at facility Matl in stock identified, isolated & tagged
BUCKHAM, J A Allied General Nuclear Services 83/12/13
O'REILLY, J P Region 2, Office of Director 3pp 21741 001 24X
Fiche 50-332, 83/12/13, 8401060407

8401060506 Responds to IE Bulletin 83-07 & 83-07, Suppl 1, "Apparently Fraudulent Products Sold by Ray Miller, Inc " No subj matl installed in safety-related sys at facility
BUCKHAM, J A Allied General Nuclear Services 83/12/14
O'REILLY, J P Region 2, Office of Director 3pp 21739 336 24X
Fiche 50-332, 83/12/14, 8401060506

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8401004460 Forwards IE Safeguards Insp Rept 50-333/83-26 on 831107-10 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
MCNIELL, C A Power Authority of the State of New York 2pp
21761 342 24X Fiche 50-333, 83/12/23, 8401004460

--8401004470 IE Safeguards Insp Rept 50-333/83-26 on 831107-10 No violations noted Major areas inspected security plan & implementing procedures, security organization, security program audit, records & repts & testing
DUNLAP, J M, GDDY, A T Region 1, Office of Director 83/12/21
5pp 21761 344 24X Fiche 50-333, 83/12/23, 8401004460

8401300209 Responds to 840109 ltr forwarding correspondence from Croton-Harmon School District in Croton-on-Hudson, NY re Westchester County evacuation plan for school children in event of facility accident FEMA already responded
KRIMM, R W Federal Emergency Management Agency 84/01/24
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21994 001 24X Fiche 50-000, 84/01/24, 8401300209

--8401300213 Forwards post-exercise assessment of 830928 exercise of radiological emergency preparedness plans of State of NY & Oswego County
KRIMM, R W Federal Emergency Management Agency 84/01/23
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21994 002 24X
Fiche 50-000, 84/01/24, 8401300209

--8401300219 Post-exercise assessment of exercise of State of NY & Oswego County radiological emergency plans
PETRONE, F P Federal Emergency Management Agency 82/10/29
62pp 21994 110 24X Fiche 50-000, 84/01/24, 8401300209

J Insurance & indemnity information

8401050287 Forwards Endorsement 68 to NELIA Policy NF-208, Endorsement 58 to MAELU Policy MF-77 & Endorsement 4 to NELIA Policies N-47 & N-7 & MAELU Policies M-47 & M-7
GOLDEN, M P Marsh & McLennan, Inc 83/12/28 SALTZMAN, J
Assistant Director for State & License Relations 7pp 21726 334
24X Fiche 50-000, 83/12/28, 8401050287

DOCKETED ITEMS

ing license stage documents & correspondence

Forwards safety evaluation & notice of granting of partial relief from ASME Section XI re inservice testing
 ents Relief granted & alternate testing imposed for 50727
 D B Operating Reactors Branch 2 83/12/05 BAYNE, J P
 thority of the State of New York 3pp 21848 218 24X
 -333,83/12/05,8401180043

48 Safety evaluation accepting 780901,800213 & 830318 requests
 relief from ASME Section XI re inservice testing
 ements
 ice of Nuclear Reactor Regulation, Director 83/12/05
 21848 221 24X Fiche 50-333,83/12/05,8401180043

52 Notice of granting of relief from ASME Section XI re
 ice testing requirements
 LO, D B Operating Reactors Branch 2 83/12/05 2pp
 263 24X Fiche 50-333,83/12/05,8401180043

Withdraws 830330 application for amend to License DPR-59,
 ing original Cycle 3 min critical power ratio limits
 ing Figures 3 1-2a,b & c as result of new fuel loaded
 e 6 Requests refund of amend fee
 P Power Authority of the State of New York 83/12/13
 D B Operating Reactors Branch 2 2pp 21844 099 24X
 -333,83/12/13,8401180241

Notifies that TMI Action Items II K 3 30 & II K 3 31
 per NRC 831213 acceptance of GE small break LOCA
 ans & schedule for completion of items requested
 0 days of receipt of ltr if info incorrect
 D Operating Reactors Branch 2 83/12/28 BAYNE, J P
 thority of the State of New York 2pp 21702 062 24X
 -333,83/12/28,8401230548

Notifies that TMI Action Items II K 3 30 & II K 3 31
 per NRC 831213 acceptance of GE small break LOCA
 ans & schedule for completion of items requested
 0 days of receipt of ltr if info incorrect
 D Operating Reactors Branch 2 83/12/28 BAYNE, J P
 thority of the State of New York 2pp 21702 062 24X
 -333,83/12/28,8401230548

Inform of delayed installation of mod to post-accident
 sys, per NUREG-0737, Item II B 3 2, due to postponed
 delivery Delay not in violation of 830314
 copy order
 P Power Authority of the State of New York 83/12/29
 D B Operating Reactors Branch 2 2pp 21980 239 24X
 -333,83/12/29,8401270440

Generic Ltr 84-01 to all holders of OLs; applicants for OLs
 of CPs for power reactors re NRC use of terms,
 at to safety" & "safety-related " Svc list encl
 D G Division of Licensing 84/01/05 Consolidated
 of New York, Inc 18pp 21946 190 24X
 000,84/01/05,8401050382

Generic Ltr 84-02 to all applicants for OLs & full power
 tions re notice of meeting on facility staffing
 encl
 D G Division of Licensing 84/01/06 Consolidated
 of New York, Inc 18pp 21957 267 24X
 000,84/01/06,8401090221.

Generic Ltr 84-03 to all licensees of operating reactors,
 s for OLs & holders of CPs re availability of
 3, "Prioritization of Generic Safety Issues "
 encl
 D G Division of Licensing 84/01/13 Consolidated
 of New York, Inc 18pp 21946 174 24X
 000,84/01/13,8401130084

Submits table listing diesel generator fast cold starts for
 1201 per Generic Ltr 83-41 Some scoring identified
 er walls & upper valve train components during
 outage maint
 P Power Authority of the State of New York 84/01/18,
 D B Operating Reactors Branch 2 2pp 21884:218 24X
 333,84/01/18,8401230255

Forwards fee for 831228 application for changes to Tech
 partial-arc to full-arc turbine control
 Power Authority of the State of New York 84/01/23
 D Office of Administration 1p 21935 193 24X
 333,84/01/23,8401260311

8401270222 Forwards application for amend to License DPR-59, changing
 Tech Specs to permit isolation of containment atmosphere
 monitoring sys during operation of post-accident sampling
 sys
 BAYNE, J P Power Authority of the State of New York 84/01/23
 VASSALLO, D B Operating Reactors Branch 2 2pp 21973 343 24X
 Fiche 50-333,84/01/23,8401270222

--8401270224 Application for amend to License DPR-59, changing Tech Specs
 to permit isolation of containment atmosphere monitoring sys
 during operation of post-accident sampling sys
 BAYNE, J P Power Authority of the State of New York 84/01/23
 1p 21973 345 24X Fiche 50-333,84/01/23,8401270222

--8401270227 Proposed Tech Spec changes re isolation of containment
 atmosphere monitoring sys during operation of post-accident
 sampling sys
 * Power Authority of the State of New York 84/01/23 5pp
 21973 346 24X Fiche 50-333,84/01/23,8401270222

8401300163 Requests scheduler exemption from requirements of 10CFR50 54
 (m) from 840120-850601 Exemption would remove one of two
 senior reactor operators from shift duty to participate in
 reactor operator training
 BAYNE, J P Power Authority of the State of New York 84/01/26
 VASSALLO, D B Operating Reactors Branch 2 3pp 21999 117 24X
 Fiche 50-333,84/01/26,8401300163

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results
 during 1982 Forwards IE notebook tabulating requested info.
 Notebook also available in PDR
 FELTON, J M Division of Rules and Records 83/10/20 ZAHLE, R E
 Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
 Fiche 50-000,83/10/20,8401060040

--8401060150 List of SAMP results during 1982
 * Director's Office, Office of Inspection and Enforcement,
 83/10/20 109pp 21744 004 24X Fiche 50-000,83/10/20,
 8401060040

8401040401 Forwards IE Insp Rept 50-333/83-27 on 831008-1106 & notice
 of violation
 STAROSTECKI, R Division of Project & Resident Programs 83/12/19
 MCNEILL, C A Power Authority of the State of New York 2pp,
 21707 072 24X Fiche 50-333,83/12/19,8401040401

--8401040403 Notice of violation from insp on 831008-1106.
 * Region 1, Office of Director 83/12/19 1p 21707,074 24X
 Fiche 50-333,83/12/19,8401040401

--8401040405 IE Insp Rept 50-333/83-27 on 831008-1106 Noncompliance
 noted failure to submit LER re inoperable safety-related
 snubber
 DOERFLEIN, L T Region 1, Office of Director COLLINS, S. J.
 Division of Project & Resident Programs 83/12/15 10pp
 21707 075 24X Fiche 50-333,83/12/19,8401040401.

8401100460 Forwards IF Safeguards Insp Rept 50-333/83-26 on 831107-10
 No violations noted
 MARTIN, T T Division of Engineering & Technical Programs, 83/12/23
 MCNEILL, C A Power Authority of the State of New York 2pp
 21761,342 24X Fiche 50-333,83/12/23,8401100460

--8401100470 IE Safeguards Insp Rept 50-333/83-26 on 831107-10 No
 violations noted Major areas inspected security plan &
 implementing procedures, security organization, security
 program audit, records & repts & testing
 DUNLAP, J M, GODDY, A T Region 1, Office of Director 83/12/21
 5pp, 21761 344 24X Fiche 50-333,83/12/23,8401100460.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
 W/Undervoltage Trip Feature in Use in Safety-Related
 Applications Other Than Reactor Trip Sys " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
 Brown Boveri Electric Type 5HK Breakers " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/12/30 Consolidated Edison Co. of New
 York, Inc 127pp, 21826 060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
 Voltage Levels Lower Than Analyzed " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/10 Consolidated Edison Co. of New
 York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

DOCKETED ITEMS

197

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401300247 Forwards status of commitment to reconfirm adequacy of main steam line support H29-351 & independent third-party review of support adequacy Util developing long-term pipe support insp & evaluation program
BAYNE, J P Power Authority of the State of New York 84/01/20
DENTON, H R. Office of Nuclear Reactor Regulation, Director 6pp 21995 203 24X Fiche 50-333,84/01/20,8401300247

R Periodic operating reports & related correspondence

8401130274 Monthly operating rept for Dec 1983 W/840109 ltr
COOK, J. J. MCNEILL, C A Power Authority of the State of New York
83/12/31, Director's Office, Office of Inspection and Enforcement 9pp 21801 157 24X Fiche 50-333,83/12/31,8401130274

S Reportable occurrences, LERs & related correspondence

8401120214 Discusses investigation of allegations re pipe support deficiencies Evaluation performed by United Engineers & Constructors consists of review of B&W analytical methodology, procedures & calculation packages
BAYNE, J P Power Authority of the State of New York 83/11/17
VASSALLO, D B Operating Reactors Branch 2 2pp 21792 254 24X Fiche: 50-333,83/11/17,8401120214

8401030235 LER 83-059/04T-0 on 831129,periphyton exceeded 10 times control sample for Co-60 Caused by bioaccumulation factor for element.No radiation dose to man expected W/831208 ltr
SALINI, J A , MCNEILL, C A. Power Authority of the State of New York
83/12/09 MURLEY, T E Region 1, Office of Director 4pp 21682 328 24X Fiche 50-333,83/12/09,8401030235

8401120242 Discusses potential pipe support nonconformance.All affected supports operable,able to withstand all normal & seismic loads & acceptable w/o mod All evaluations should be completed by 831227
BAYNE, J. P Power Authority of the State of New York 83/12/19
VASSALLO, D B Operating Reactors Branch 2 2pp 21793 292 24X Fiche 50-333,83/12/19,8401120242

8401160182 LER 83-058/03L-0, on 831128,during surveillance testing on HPCI turbine steam line high flow instrument 23-DP18-77, setpoint found w/less than 106 inches of water required Caused by instrument drift Setpoint adjusted W/831221 ltr
KEITH, H , MCNEILL, C A Power Authority of the State of New York
83/12/21 MURLEY, T E Region 1, Office of Director 2pp 21813 286, 24X Fiche 50-333,83/12/21,8401160182

8401160032 LER 83-061/03L-0 on 831130,during Surveillance Test F-ST-2R, RHR svc water pump P-1C,mfg by Allis-Chalmers,ran w/high vibration.Pump declared inoperable Cause not stated Bearing sleeve, suction bell & line shaft replaced W/831222 ltr
WESSE, R., MCNEILL, C A Power Authority of the State of New York
83/12/22, MURLEY, T E Region 1, Office of Director 3pp 21815 059 24X Fiche 50-333,83/12/22,8401160032

8401130359 LER 83-060/03L-0, on 831130,incorrect motor actuator installed on RHR suppression pool outboard isolation valve 10MOV-39B during maint activities Replacement valve actuator being procured,W/831228 ltr
WALZ, V. M., MCNEILL, C A Power Authority of the State of New York
83/12/28 MURLEY, T E Region 1, Office of Director 3pp 21800 313 24X Fiche 50-333,83/12/28,8401130359

8401160098 LER 83-062/03L-0 on 831203,during surveillance testing, calibr span on scram discharge val level transmitter 03-DPT-231-H found out of spec Caused by improperly sloped test vent tube Calibr span adjusted W/831227 ltr
KEITH, H , MCNEILL, C A Power Authority of the State of New York
83/12/27 MURLEY, T E Region 1, Office of Director 3pp 21821 217 24X Fiche 50-333,83/12/27,8401160098

8401270139 LER 83-041/04T-0 on 831228,mollusk samples exceeded 10 times control sample for Mn-54 Caused by high release of Mn-54 via liquid effluent,producing high concentration factor in mollusks Release within Tech Spec limits W/840106 ltr
SOLINI, J A , GORMAN, B , MCNEILL, C A Power Authority of the State of New York
84/01/06 MURLEY, T E Region 1, Office of Director 4pp 21982 057 24X Fiche 50-333,84/01/06,8401270139

8401270303 LER 83-064/03L-0 on 831220,while conducting surveillance testing on reactor low & high water level switches 02-3-L19-101D, setpoint found less conservative than Tech Spec Caused by setpoint drift W/840106 ltr
KEITH, H N , MCNEILL, C A Power Authority of the State of New York
84/01/06 MURLEY, T E Region 1, Office of Director 2pp 21975 354 24X Fiche 50-333,84/01/06,8401270303

8401270429 LER 83-063/03L-0 on 831215,during normal operation,LPCI independent power supply A tripped Cause undetermined Power supply returned to svc W/840106 ltr
RUDDY, D , MCNEILL, C A Power Authority of the State of New York
84/01/06 MURLEY, T Region 1, Office of Director 3pp 21980 236 24X Fiche 50-333,84/01/06,8401270429

8401300247 Forwards status of commitment to reconfirm adequacy of main steam line support H29-351 & independent third-party review of support adequacy Util developing long-term pipe support insp & evaluation program
BAYNE, J P Power Authority of the State of New York 84/01/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 21995 203 24X Fiche 50-333,84/01/20,8401300247

DOCKET 80-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401100199 Forwards IE Insp Rept 50-334/83-26 on 831024-28 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
CAREY, J J Duquesne Light Co 2pp 21760 235 24X Fiche 50-334,83/12/23,8401100199

--8401100203 IE Insp Rept 50-334/83-26 on 831024-28 No violations noted
Major areas inspected fire protection/prevention program, including program administration & organization & administrative control of combustibles & ignition sources
PULLANI, S V , ANDERSON, C J Region 1, Office of Director
83/12/01 10pp 21760 237 24X Fiche 50-334,83/12/23,8401100199

8401170495 Forwards NRC comments on detailed control room design review program plan submitted in response to Generic Ltr 83-28 (NUREG-0797, Suppl 1) In-progress audit should be scheduled during last 7 months of 1984
VAROAS, S A Operating Reactors Branch 1 84/01/04 CAREY, J J Duquesne Light Co 15pp 21847 160 24X Fiche 50-334,84/01/04,8401170495

8401180129 Documents 840109 telcon re App R to 10CFR50,Section III L 2 concerning wide-range core exit thermocouples as acceptable alternative to wide-range TH loop resistance temp devices for relative process monitoring capability
CAREY, J J Duquesne Light Co 84/01/12 VAROAS, S A Operating Reactors Branch 1 3pp 21841 345 24X Fiche 50-334,84/01/12,8401180129

8401310037 Forwards IE Insp Rept 50-334/83-29 on 831129-1231 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs, 84/01/16
CAREY, J J Duquesne Light Co 2pp 22024 013 24X Fiche 50-334,84/01/16,8401310037

--8401310037 Notice of violation from insp on 831129-1231.
* Region 1, Office of Director 84/01/16 2pp 22024 015 24X Fiche. 50-334,84/01/16,8401310037

--8401310042 IE Insp Rept 50-334/83-29 on 831129-1231 Noncompliance noted failure to perform inservice insp required stroke tests of selected valves & failure to specify limiting conditions for ESF loss of power relay surveillance tests
TROBOKSKI, W M , TRIPP, L E Region 1, Office of Director
84/01/11 13pp 22024 017 24X Fiche 50-334,84/01/16,8401310037

DOCKETED ITEMS

8401310109 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22028 095 24X Fiche 50-334,84/01/20,
8401310109

--8401310115 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP/IP 1-2 re unusual event, EPP/IP 1-3 re alert & EPP/IP 1-4 re site area emergency Transmittal form encl
MILLER, D J Duquesne Light Co 83/12/04 NRC - No Detailed
Affiliation Given 2pp 22028 096 24X Fiche 50-334,84/01/20,
8401310109

--8401310122 Public version of revised emergency plan implementing procedures, including Procedures EPP/IP 1-2 re unusual event, EPP/IP 1-3 re alert & EPP/IP 1-4 re site area emergency
LACEY, W S Duquesne Light Co 83/11/30 200pp. 22028 098 24X
Fiche 50-334,84/01/20,8401310109

J Insurance & indemnity information

8401200043 Forwards Amend 7 to Indemnity Agreement B-73, per 831208 request
CAREY, J J Duquesne Light Co 84/01/12 SALTZMAN, J Assistant
Director for State & Licensee Relations 2pp. 21867 027 24X
Fiche 50-334,84/01/12,8401200043

P Operating license stage documents & correspondence

8401120172 Forwards Amend 75 to License DPR-66 & safety evaluation Amend changes Tech Specs to clarify onsite ac power distribution configuration
TAM, P S Operating Reactors Branch 1 83/12/13 CAREY, J J
Duquesne Light Co 3pp 21805:004 24X Fiche 50-334,83/12/13,
8401120172

--8401120176 Amend 75 to License DPR-66, changing Tech Specs to clarify onsite ac power distribution configuration
VARGA, S A Operating Reactors Branch 1 83/12/13 5pp.
21805 007 24X Fiche 50-334,83/12/13,8401120172

--8401120179 Safety evaluation supporting Amend 75 to License DPR-66
* Office of Nuclear Reactor Regulation, Director 83/12/13 4pp
21805 012 24X Fiche 50-334,83/12/13,8401120172

-8401120186 Forwards evaluation re Tech Spec change request on onsite ac power distribution sys. Change acceptable
RUBENSTEIN, L S Assistant Director for Core & Plant Systems
83/11/10 LAINAS, G C Assistant Director for Operating Reactors
4pp 21805 016 24X Fiche 50-334,83/12/13,8401120172

11090769 Forwards concerns re review of 830325 & 0421 responses to Generic Ltr B2-28, "Inadequate Core Cooling Instrumentation Sys " Approach acceptable Core exist thermocouple design per THI Item II F 2 unacceptable
VARQA, S A Operating Reactors Branch 1 83/12/16 CAREY, J J
Duquesne Light Co 1pp 21767 049 24X Fiche 50-334,83/12/16,
8401090769

8401190313 Forwards SER on THI Item II K 2.17, "Potential for Voiding in RCS During Transients," for Westinghouse reactors
Specific plant steam void analyses acceptable Action completed
VARQA, S A Operating Reactors Branch 1 83/12/19 CAREY, J J
Duquesne Light Co 1pp 21870 029 24X Fiche 50-334,83/12/19,
8401190313

01040501 Forwards "Cycle 4 Startup Physics Test Rept " Rept provides technical summary of plant startup testing program
Comparisons made to predicted design values & applicable Tech Spec requirements
LACEY, W S Duquesne Light Co 83/12/23 VARQA, S A Operating
Reactors Branch 1 2pp 21707 146 24X Fiche 50-334,83/12/23,
8401040501

8401040503 "Cycle 4 Startup Physics Test Rept "
* Duquesne Light Co 83/09/30 5pp 21707 148. 24X
Fiche 50-334,83/12/23,8401040501

31050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D O Division of Licensing 84/01/05. Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X
Fiche 50-000,84/01/05,8401050382

8401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,8401090221

8401160178 Responds to Generic Ltr B3-41 Eight diesel generator fast starts noted during Dec 1982 - Nov 1983 due to excessive equipment cycling on breakers, relay contacts & shaft driven components & increased mechanical wear on bearings
CAREY, J J Duquesne Light Co 84/01/06 EISENHUT, D O Division of
Licensing 2pp 21815 350 24X Fiche 50-334,84/01/06,8401160178

8401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-D933, "Prioritization of Generic Safety Issues "
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement.
83/10/20 105pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401120405 Forwards monthly operating rept for Nov 1983 Results of third refueling steam generator tube insp also encl
CAREY, J J Duquesne Light Co 83/12/08 Office of Resource
Management, Director 1p 21791 127 24X Fiche 50-334,83/12/08,
8401120405

8401040077 Forwards notice of granting relief from ASME Section XI requirements for certain RHR sys welds per 830517 request
VARQA, S A Operating Reactors Branch 1 83/12/15 CAREY, J
Duquesne Light Co 4pp 21711 311 24X Fiche 50-334,83/12/15,
8401040077

--8401040084 Notice of granting relief from ASME Section XI inservice insp requirements for certain RHR sys welds
VARQA, S A Operating Reactors Branch 1 83/12/15 2pp
21711 315 24X Fiche 50-334,83/12/15,8401040077

8401040163 Forwards IE Insp Rept 50-334/83-24 on 831017-21. No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/15
CAREY, J J Duquesne Light Co 2pp 21702 001 24X
Fiche:50-334,83/12/15,8401040163

--8401040167 IE Insp Rept 50-334/83-24 on 831017-21 No noncompliance noted Major areas inspected testing program, prescritical tests, zero power physics tests & power ascension tests.
WEN, P C, BETTENHAUSEN, L Region 1, Office of Director 83/12/19
9pp 21702 003 24X Fiche 50-334,83/12/15,8401040163

8401120413 Forwards proprietary inservice insp rept for June & Sept 1983 Rept details exam of ASME Class 1,2 & 3 components & piping in accordance w/Section XI of ASME Boiler & Pressure Vessel Code Rept withheld
CAREY, J J Duquesne Light Co 83/12/16, MURLEY, T E Region 1,
Office of Director 2pp 21791 069 24X Fiche 50-334,83/12/16,
8401120413

8401100199 Forwards IE Insp Rept 50-334/83-26 on 831024-28 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
CAREY, J J Duquesne Light Co 2pp 21760 235 24X
Fiche 50-334,83/12/23,8401100199

--8401100203 IE Insp Rept 50-334/83-26 on 831024-28 No violations noted Major areas inspected fire protection/prevention program, including program administration & organization & administrative control of combustibles & ignition sources
PULLANI, S V, ANDERSON, C J Region 1, Office of Director
83/12/01 10pp 21760 237 24X Fiche 50-334,83/12/23,8401100199

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYDUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp 21731:166 24X Fiche 50-000,83/12/28,8312120090

DOCKETED ITEMS

199

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401180221 Forwards IE Insp Rept 50-334/83-28 on 831101-04 No violations observed
MARTIN, T T Division of Engineering & Technical Programs 84/01/05
CAREY, J J Duquesne Light Co 2pp 21844 215 24X
Fiche 50-334,84/01/05,8401180221

--8401180224 IE Insp Rept 50-334/83-28 on 831101-04 No violations observed Major areas inspected licensee training & qualification training program, including licensed & nonlicensed training
DISSSETT, P , CAPHTON, D L Region 1, Office of Director 83/12/29
6pp 21844 217 24X Fiche 50-334,84/01/05,8401180221

8401190377 Forwards IE Enforcement Conference Rept 50-334/83-27 on 831011 & notice of violation
MURLEY, T E Region 1, Office of Director 84/01/06 CAREY, J J Duquesne Light Co 3pp 21850 137 24X Fiche 50-334,84/01/06,8401190377

---8401190379 Notice of violation from insp on 830816-0912 & 22-23
* Region 1, Office of Director 84/01/06 3pp 21850 140 24X
Fiche 50-334,84/01/06,8401190377

--8401190382 IE Enforcement Conference Rept 50-334/83-27 on 831011 Major areas discussed inoperable RHR sys & inoperable reactor plant river water subsystem
TRIPP, L E , KEIMIG, R R Division of Project & Resident Programs 83/10/28 App 21850 143 24X Fiche 50-334,84/01/06,8401190377

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000,84/01/16,8312120114

8401310037 Forwards IE Insp Rept 50-334/83-29 on 831129-1231 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/01/16
CAREY, J J Duquesne Light Co 2pp 22024 013 24X
Fiche 50-334,84/01/16,8401310037

--8401310039 Notice of violation from insp on 831129-1231
* Region 1, Office of Director 84/01/16 2pp 22024 015 24X
Fiche 50-334,84/01/16,8401310037

--8401310042 IE Insp Rept 50-334/83-29 on 831129-1231 Noncompliance noted failure to perform inservice insp required stroke tests of selected valves & failure to specify limiting conditions for ESF loss of power relay surveillance tests
TROSKOSKI, W M , TRIPP, L E Region 1, Office of Director 84/01/16 13pp 22024 017 24X Fiche 50-334,84/01/16,8401310037

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401120405 Forwards monthly operating rept for Nov 1983 Results of third refueling steam generator tube insp also encl
CAREY, J J Duquesne Light Co 83/12/08 Office of Resource Management, Director 1p 21791 127 24X Fiche 50-334,83/12/08,8401120405

--8401120407 Monthly operating rept for Nov 1983
HOLTZ, J L Duquesne Light Co 83/12/08 9pp 21791 128 24X
Fiche 50-334,83/12/08,8401120405

8401120413 Forwards proprietary inservice insp rept for June & Sept 1983 Rept details exam of ASME Class 1,2 & 3 components & piping in accordance w/Section XI of ASME Boiler & Pressure Vessel Code Rept withheld
CAREY, J J Duquesne Light Co 83/12/16 MURLEY, T E Region 1, Office of Director 2pp 21791 069 24X Fiche 50-334,83/12/16,8401120413

8401040469 "NPDES Monthly Rept for Nov 1983 " W/831227 ltr
FEITKNECHT, C Duquesne Light Co 83/12/28 REID, R W Operating Reactors Branch 4 17pp 21707 110 24X Fiche 50-334,83/12/28,8401040469

8401270228 Monthly operating rept for Dec 1983 W/840110 ltr
HOLTZ, J L , CAREY, J J Duquesne Light Co 83/12/31 Office of Resource Management, Director 6pp 21793 352 24X
Fiche 50-334,83/12/31,8401270228

8401310295 NPDES discharge monitoring rept for Dec 1983 W/840121 ltr
FEITKNECHT, C Duquesne Light Co 83/12/31 REID, R W Operating Reactors Branch 4 27pp 22020 276 24X Fiche 50-334,83/12/31,8401310295

S Reportable occurrences, LERs & related correspondence

8401030240 LER 83-036/03L-0 on 831104, reactor coolant pump thermal barrier CCR isolation valves TV-CC-107A,B & C not stroked as outlined in inservice insp program After 1980 inservice insp rev, valves inadvertently omitted W/831203 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 83/12/03 MURLEY, T E Region 1, Office of Director 4pp 21680 344 24X
Fiche 50-334,83/12/03,8401030240

8401120228 LER 83-038/03L-0 on 831123, during maint Surveillance Procedure 2.04, rate trip time constant found below Tech Spec min Caused by instrument drift Time constant adjusted to 2.2 s W/831223 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 83/12/23 MURLEY, T E Region 1, Office of Director 4pp 21793 296 24X
Fiche 50-334,83/12/23,8401120228

8401120313 LER 83-039/03L-0 on 831126, level channel L-RC460 failed channel check (4% deviation between level channels) Caused by packing leak on instrument valve Internals of instrument valves replaced & ref leg refilled W/831223 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 83/12/23 MURLEY, T E Region 1, Office of Director 4pp 21794 152 24X
Fiche 50-334,83/12/23,8401120313

8401270148 LER 83-040/03L-0 on 831213, chemical addition pump discharge valve MOV-05-1048 failed to close electrically as required by Tech Spec 3 & 2.3 Caused by faulty torque switch Compression spring replaced W/840130 ltr
DRUGA, R J , LACEY, W S Duquesne Light Co 84/01/10 MURLEY, T E Region 1, Office of Director 4pp 21982 063 24X
Fiche 50-334,84/01/10,8401270148

V Operator Examinations

8401200073 Forwards projected schedule through 1987 for prospective licensing exams in response to Generic Ltr 83-40 Data has been outlined by month, util class & expected mix of license
CAREY, J J Duquesne Light Co 84/01/13 EISENHUT, D G Division of Licensing 4pp 21867 015 24X Fiche 50-334,84/01/13,8401200073

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8401190168 Notifies of review of 821221 submittal re habitability & location of emergency operations facility Facility complies w/requirements of Table 1 of Suppl 1 to NUREG-0737
MILLER, J R Operating Reactors Branch 3 83/12/15 WILLIAMS, J W Florida Power & Light Co 2pp 21861 362 24X
Fiche 50-335,83/12/15,8401190168

8401060439 Confirms 831212 telcon request to observe federal field exercise at facilities Primary assignment will be to observe medical drill Handwritten rept to be submitted prior to leaving site
HUFFMAN, G N Region 2, Office of Director 83/12/21 RICKS, R C Oak Ridge National Laboratory 1p 21740 088 24X
Fiche 50-335,83/12/21,8401060439

DOCKETED ITEMS

8401060014 Releases public version of revised administrative procedures indices
 FELTON, J M Division of Rules and Records 83/12/28 Document
 Management Branch 1p 21755 290 24X Fiche 50-335, 83/12/28,
 8401060014

-8401060020 Forwards public version of revised administrative procedures indices, including chemistry procedures index, general maint procedures index, health physics reporting procedures index & offnormal/emergency operating index
 KOZLOWSKI, G Florida Power & Light Co 83/11/17 Director's
 Office, Office of Inspection and Enforcement 1p 21753 291 24X
 Fiche 50-335, 83/12/28, 8401060014

8401060025 Public version of revised administrative procedures indices, including chemistry procedures index, general maint procedures index, health physics reporting procedures index & offnormal/emergency operating procedures index
 * Florida Power & Light Co 83/11/30 27pp 21755 292 24X
 Fiche 50-335, 83/12/28, 8401060014

01040265 Forwards evaluation rept on existing accident monitoring instrumentation & control sys. in conjunction w/Suppl 1 to NUREG-0737 & requirements of Rev 3 to Reg Guide 1.97
 WILLIAMS, J W Florida Power & Light Co 83/12/30 EISENHUT, D G
 Division of Licensing 1p 21703 268 24X Fiche 50-335, 83/12/30,
 8401040265

8401040272 "Engineering Evaluation of Instrumentation Sys for Rev 3 to Reg Guide 1.97, St Lucie Plant Unit 1"
 * Florida Power & Light Co 83/11/30 70pp 21703 269 24X
 Fiche 50-335, 83/12/30, 8401040265

01240415 Forwards addl info re fire protection in response to 831027 concerns Cold shutdown can be achieved within 72 h w/loss of offsite power Plant operators trained for loss of pressurizer heater events
 WILLIAMS, J W Florida Power & Light Co 84/01/19 EISENHUT, D G
 Division of Licensing 3pp 21916 024 24X Fiche 50-335, 84/01/19,
 8401240415

31260260 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Records 84/01/20 Document
 Management Branch 1p 21990 344 24X Fiche 50-000, 84/01/20,
 8401260260

8401260265 Public version of revised Emergency Plan Implementing Procedure 1301, "Emergency Roster - Offsite Emergency Organization" W/831227 ltr
 WILLIAMS, J W, JOHNSON, H D Florida Power & Light Co 83/12/15
 O'REILLY, J P Region 2, Office of Director 11pp 21990 345
 24X Fiche 50-000, 84/01/20, 8401260260

Operating license stage documents & correspondence

1050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs holders of CPs for power reactors re NRC use of terms, important to safety" & "safety-related" Svc list encl
 EISENHUT, D G Division of Licensing 84/01/05 Consolidated
 Edison Co of New York, Inc 16pp 21946 190 24X
 Fiche 50-000, 84/01/05, 8401050382

1090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing vc list encl
 EISENHUT, D G Division of Licensing 84/01/06 Consolidated
 Edison Co of New York, Inc 18pp 21957 267 24X
 Fiche 50-000, 84/01/06, 8401090221

1170517 Confirms telcon w/R Stevens scheduling 840208-09 meetings to discuss open items in Franklin Research Ctr technical valuation repts re environ qualification of electrical equipment
 MILLER, J R Operating Reactors Branch 3 84/01/09 WILLIAMS, J W
 Florida Power & Light Co 2pp 21847 115 24X
 Fiche 50-000, 84/01/09, 8401170517

1130159 Forwards proprietary draft "Integrity & Stability of Internals Conclusions & Findings," per 830419 & 1214 commitments in response to NRC 830426 request Rept withheld ref 10CFR9.5(41)
 WILLIAMS, J W Florida Power & Light Co 84/01/11 MILLER, J R
 Operating Reactors Branch 3, 7pp 21802 080 24X
 Fiche 50-335, 84/01/11, 8401130159

130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NRC-0933, "Prioritization of Generic Safety Issues" vc list encl
 EISENHUT, D G Division of Licensing 84/01/13 Consolidated
 Edison Co of New York, Inc 18pp 21946 174 24X
 Fiche 50-000, 84/01/13, 8401130084

8401200158 Forwards license amend fees, per 840110 ltr
 WILLIAMS, J W Florida Power & Light Co 84/01/16 EISENHUT, D G
 Division of Licensing 1p 21866 158 24X Fiche 50-335, 84/01/16,
 8401200158

8401240088 Advises that diesel generators do not undergo type of fast cold starts discussed in Generic Ltr 83-41 because of prelubrication of turbocharger bearings & brief idle period prior to loading Dec 1982 - Nov 1983 quick starts listed
 WILLIAMS, J W Florida Power & Light Co 84/01/17 EISENHUT, D G
 Division of Licensing 2pp 21912 352 24X Fiche 50-335, 84/01/17,
 8401240088

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
 FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
 Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
 Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
 * Director's Office, Office of Inspection and Enforcement
 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
 8401060040

8401060431 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for Jul 1982 - June 1983
 O'REILLY, J P Region 2, Office of Director 83/12/15
 WILLIAMS, J W Florida Power & Light Co 3pp 21740-001 24X
 Fiche 50-000, 83/12/15, 8401060431

--8401060442 Forwards SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
 LEWIS, R C Division of Project & Resident Programs 83/10/14
 UHRIG, R E Florida Power & Light Co 2pp 21740 004, 24X
 Fiche 50-000, 83/12/15, 8401060431

--8401060452 SALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 & 50-389/83-61 for period Jul 1982 - June 1983
 * Region 2, Office of Director 83/10/14 49pp 21740 006, 24X
 Fiche 50-000, 83/12/15, 8401060431

8401090208 Forwards IE Insp Repts 50-335/83-38 & 50-389/83-66 on 831121-23 No violations noted
 DANCE, H C Division of Project & Resident Programs 83/12/15
 WILLIAMS, J W Florida Power & Light Co 2pp 21754 013 24X
 Fiche 50-335, 83/12/15, 8401090208

--8401090244 IE Insp Repts 50-335/83-38 & 50-389/83-66 on 831121-23 No violations noted Major areas inspected pipe support baseplates (IE Bulletin 79-02) & designs using concrete expansion anchors (IE Bulletin 79-14)
 ANQ, W P Region 2, Office of Director BLAKE, J J Division of
 Engineering & Operational Programs 83/12/12 6pp 21754.015
 24X Fiche 50-335, 83/12/15, 8401090208

8401090246 Forwards IE Insp Repts 50-335/83-40 & 50-389/83-69 on 831128-1202 No violations noted
 DANCE, H C Division of Project & Resident Programs 83/12/15
 WILLIAMS, J W Florida Power & Light Co 2pp 21754 021 24X
 Fiche 50-335, 83/12/15, 8401090246

--8401090252 IE Insp Repts 50-335/83-40 & 50-389/83-69 on 831128-1202 No violations noted Major areas inspected health physics organization & personnel qualifications, training, exposure controls, posting, labeling & control of radioactive matl
 WRAY, J R Region 2, Office of Director BARR, K P Division of
 Engineering & Operational Programs 83/12/14 7pp 21754:023
 24X Fiche 50-335, 83/12/15, 8401090246

8401240438 Forwards IE Insp Repts 50-335/83-35 & 50-389/83-63 on 831011-1110 No violations noted
 DANCE, H C Division of Project & Resident Programs 83/12/22
 WILLIAMS, J W Florida Power & Light Co 2pp 21919 332 24X
 Fiche 50-335, 83/12/22, 8401240438

--8401240447 IE Insp Repts 50-335/83-35 & 50-389/83-63 on 831011-1110 No violations noted Major areas inspected maint & surveillance observation, plant operations, IE bulletins & circulars & LERs
 ELROD, S A Division of Project & Resident Programs, 818B, H E
 Region 2, Office of Director 83/12/22 6pp 21919 334 24X
 Fiche 50-335, 83/12/22, 8401240438

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

DOCKETED ITEMS

201

8401050379 Ack receipt of 831202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-29 & 50-389/83-56
DANCE, H C Division of Project & Resident Programs 83/12/28
WILLIAMS, J W Florida Power & Light Co 1p 21731 019 24X
Fiche 50-335, 83/12/28, 8401050379

--8401050384 Responds to NRC 831104 ltr re violations noted in IE Insp Repts 50-335/83-29 & 50-389/83-56 Corrective actions 1983 requalification program revised to include refresher training on Procedure AP 001022, "In-Plant Equipment"
WILLIAMS, J W Florida Power & Light Co 83/12/02 O'NEILLY, J P Region 2, Office of Director 2pp 21731 020 24X
Fiche 50-335, 83/12/28, 8401050379

--8401050387 Forwards IE Insp Repts 50-335/83-29 & 50-389/83-56 on 830811-0910 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/11/02
WILLIAMS, J W Florida Power & Light Co 2pp 21731 022 24X
Fiche: 50-335, 83/12/28, 8401050379

--8401050389 Notice of violation from insp on 830811-0910
* Region 2, Office of Director 83/11/02 2pp 21731 024 24X
Fiche 50-335, 83/12/28, 8401050379

--8401050394 IE Insp Repts 50-335/83-29 & 50-389/83-56 on 830811-0910 Violation noted failure to implement operational safety verification procedures re valves V-2145 & V-2155
ELROD, S A, BIBB, H E Region 2, Office of Director LANDIS, K Division of Project & Resident Programs 83/11/03 7pp
21731 026 24X Fiche 50-335, 83/12/28, 8401050379

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 12pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc. 12pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc. 12pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc. 12pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 11pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 12pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R. Periodic operating reports & related correspondence

8401120363 Monthly operating repts for Nov 1983 W/831215 ltr
GRANT, N.W., WILLIAMS, J W Florida Power & Light Co 83/11/30
Division of Data Automation & Management Information 17pp
21791 330 24X Fiche 50-000, 83/11/30, 8401120363

8401270459 Monthly operating repts for Dec 1983 W/840116 ltr
GRANT, N.W., WILLIAMS, J W Florida Power & Light Co. 83/12/31
Office of Resource Management, Director 17pp 21980 026 24X
Fiche. 50-000, 83/12/31, 8401270459

S. Reportable occurrences, LERs & related correspondence

8401130459 Summary of 831110 meeting w/utills & C-E re failure to perform mechanical analysis dealing w/thermal shield support structure failure & resulting core barrel damage Viewgraphs & list of attendees encl
BELL, S D E Operating Reactors Branch 3 84/01/05 Operating Reactors Branch 3 57pp 21820 176 24X Fiche 50-335, 84/01/05, 8401130459

V. Operator Examinations

8401060457 Informs that in order to meet schedule for 840213 operator senior operator licensing written & oral exams, ref matl from approved list in Encl 1 must be received by 840106 W/o encl
DANCE, H C Division of Project & Resident Programs 83/12/15
UHRIG, R E Florida Power & Light Co 2pp 21740 203 24X
Fiche 50-335, 83/12/15, 8401060457

8401190358 Requests extension of 4 months of annual exam requirement for 1983 for operator requalification, per 10CFR55, App A
Delay in preparing program due to commitment to initial startup activities for Unit 2
WILLIAMS, J W Florida Power & Light Co 84/01/10 EISENHUT, D O Division of Licensing 2pp 21850 189 24X Fiche 50-335, 84/01/10, 8401190358

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X
Fiche 50-000, 83/11/02, 8401250163

--8305260352 Urges discussion on licensee disregard for NRC guidance re location of permanent & backup emergency operations facilities, per W Dircks 821227 memo Requests explanation re Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners 83/01/06 Commissioners 2pp 21958 001 24X Fiche 50-000, 83/11/02, 8401250163

--8305260362 Responds to Commissioner Gilinsky 830106 comments on 821227 memo re implementation of emergency response facilities guidance Requested explanations re Waterford, San Onofre & Millstone plans provided
DIRCKS, W J Office of the Executive Director for Operations 83/02/15 PALLADINO, N Commissioners 2pp 21958 303 24X
Fiche 50-000, 83/11/02, 8401250163

8401090132 Forwards status of current plans for implementation of provisions of Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability," transmitted by Generic Ltr 82-33
COUNCIL, W G Connecticut Yankee Atomic Power Co COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/11/28 EISENHUT, D O Division of Licensing 23pp 21749 170 24X Fiche 50-000, 83/11/28, 8401090132

8312300203 Forwards list of dates acceptable to util per confirmatory orders re integrated implementation schedules for Suppl 1 to NUREG-0737, Generic Ltr 82-33, "Requirements for Emergency Response Capability"
COUNCIL, W G Connecticut Yankee Atomic Power Co. COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNCIL, W G Northeast Utilities 83/12/20 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 21673 114 24X Fiche 50-000, 83/12/20, 8312300203

8401180237 Forwards IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21842 339 24X Fiche 50-245, 84/01/03, 8401180237

--8401180249 IE Insp Repts 50-245/83-21 & 50-336/83-29 on 831113-1217 No violations noted Major areas inspected evaluations of plant operations, equipment alignments & readiness, radiation protection, physical security & fire protection
LIPINSKI, D R Region 1, Office of Director 83/12/30 14pp, 21842 341 24X Fiche 50-245, 84/01/03, 8401180237

8401180204 Forwards Rev 2 to suitability, training & qualification plan Rev withheld (ref 10CFR73.21 & 2.790)
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W G Northeast Utilities 84/01/10
MURLEY, T E Region 1, Office of Director 1p 21842 360 24X
Fiche 50-245, 84/01/10, 8401180204

8401180266 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
COUNCIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21843 249 24X Fiche 50-245, 84/01/10, 8401180266

DOCKETED ITEMS

--B401180270 Responds to NRC B31107 ltr re violations noted in IE Insp Repts 50-245/B3-16 & 50-336/B3-23 Corrective actions withheld (ref 10CFR73.21)
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/06 MARTIN, T T Division of Engineering & Technical Programs 2pp 21843 251 24X Fiche 50-245, B4/01/10, B401180266

B401260320 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records B4/01/20 Document Management Branch 1p 21989 359 24X Fiche 50-245, B4/01/20, B401260320

--B401260324 Public version of Change 2 to Rev 4 to Emergency Plan Implementing Procedure OP 2501, "Incident Assessment & Classification - Unit 2" W/B31229 ltr
COUNSIL, W G, OPEKA, J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/22 EISENHUT, D G Division of Licensing 2pp 21989 360 24X Fiche 50-245, B4/01/20, B401260320

J Insurance & indemnity information

B401130130 Forwards Endorsement 5 to NELIA Certificates N-15 & N-16 & Endorsement 5 to MAELU Certificates M-15 & M-16
SINISI, J M Marsh & McLennan, Inc 83/12/27 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 21802 237 24X Fiche 50-000, B3/12/27, B401130130

B401230477 Forwards Endorsements 90 & 91 to NELIA Policy NF-173 & Endorsements B1 & B2 to MAELU Policy MF-32
SINISI, J M Marsh & McLennan, Inc B4/01/12 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 21882 153 24X Fiche 50-000, B4/01/12, B401230477

F Operating license stage documents & correspondence

B401170329 Forwards final rept providing basis for return to power operation based on results of thermal shield damage recovery program Core support barrel insps completed B31030 W/o stated rept
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/12 MILLER, J R Operating Reactors Branch 3 3pp 21829 328 24X Fiche 50-336, B3/12/12, B401170329

B401170435 Discusses steam generator tube rupture reassessment for Cycle & operation Radiological doses will be increased as result of lower reset pressure Releases expected to be significantly below 10CFR100 criteria
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/12 MILLER, J R Operating Reactors Branch 3 7pp 21827 136 24X Fiche 50-336, B3/12/12, B401170435

B401170105 Approves request for withholding Westinghouse proprietary matl contained in B30603, 0818 & 1117 submittals re steam generator tube sleeving, in accordance w/Westinghouse B30524 application for withholding per 10CFR2.790
MILLER, J R Operating Reactors Branch 3 83/12/23 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 21839 342 24X Fiche 50-336, B3/12/23, B401170105

401160147 Provides addl info re results of fracture mechanics evaluation of flaw tolerance for core support barrel No unreviewed safety question results from mod to remove thermal shield
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/28 MILLER, J R Operating Reactors Branch 3 6pp 21815 266 24X Fiche 50-336, B3/12/28, B401160147

401110173 Forwards Amend B9 to License DPR-65 & proprietary & nonproprietary versions of safety evaluation Amend allows repair of degraded steam generator tubes by installing metal sleeves Proprietary version withheld
HEITNER, K L Operating Reactors Branch 3 83/12/30 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 21774 282 24X Fiche 50-336, B3/12/30, B401110173

--B401110186 Amend B9 to License DPR-65, allowing repair of degraded steam generator tubes by installing metal sleeves in addition to plugging
MILLER, J R Operating Reactors Branch 3 83/12/30 10pp 21774 286 24X Fiche 50-336, B3/12/30, B401110173

--B401110194 Safety evaluation supporting Amend B9 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 83/12/30 21PP 21774 296 24X Fiche 50-336, B3/12/30, B401110173

B401120175 Forwards safety evaluation & Amend 90 to License DPR-65 re non-LQCA transient & accident analyses for Cycle 6 reload
Confirmatory items remain outstanding Submittal requested in 60 days W/o encl
HEITNER, K L Operating Reactors Branch 3 83/12/30 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp, 21804 361 24X Fiche 50-336, B3/12/30, B401120175

B401170379 Advises that results of C-E Owners Group program & completion dates for operator training/emergency operating procedure revs per NUREG-0737, item II K 3 5 will be submitted by B40501
COUNSIL, W G, SEAR, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities, 83/12/30 EISENHUT, D G Division of Licensing 1p 21828 281 24X Fiche 50-336, B3/12/30, B401170379

B401270360 "Thermal Shield Damage Recovery Program, Final Rept"
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/31 163pp 21979 223 24X Fiche 50-336, B3/12/31, B401270360

B401200163 Application for amend to License DPR-65, revising pressure-temp limits & max heatup rate for RCS
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/01/04 MILLER, J R Operating Reactors Branch 3 3pp 21866 212 24X Fiche 50-336, B4/01/04, B401200163

--B401200165 Proposed Tech Specs revising pressure-temp limits & max heatup rate for RCS
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/01/04 9pp 21866 215 24X Fiche 50-336, B4/01/04, B401200163

--B401200168 "Post-Irradiation Evaluation of Reactor Vessel Surveillance Capsule W-97"
BYRNE, S T, KOZLO, J J, JACQUES, R C Combustion Engineering, Inc TR-N-MCM-008 82/04/30 117pp 21866 223 24X Fiche 50-336, B4/01/04, B401200163

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/03 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, B4/01/03, B401050382

B401070221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21937 267 24X Fiche 50-000, B4/01/06, B401070221

B401200164 Forwards revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual" W/o encl.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities Service Co (subs of Northeast Utilities) 84/01/09 EISENHUT, D G Division of Licensing 2pp 21866 341 24X Fiche 50-000, B4/01/09, B401200164

B401230178 Informs that equipment installed in fulfillment of NUREG-0737, Items II F 1.1 & II F 1.2 declared operational in mid-Dec 1983 Tech Specs required by Generic Ltr B3-37 being prepared
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/01/10, CRUTCHFIELD, D Operating Reactors Branch 5 MILLER, J R Operating Reactors Branch 3 2pp 21884 174 24X Fiche 50-245, B4/01/10, B401230178

B401160221 Forwards summary of three BNL contracts re study of occupational dose reduction at nuclear power plants
CRUTCHFIELD, D Operating Reactors Branch 5 84/01/12 COUNSIL, W G Connecticut Yankee Atomic Power Co 7pp 21808 309 24X Fiche 50-000, B4/01/12, B401160221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, B4/01/13, B401130084

B401310023 Informs that util QA-verified B31212 reanalysis of steam generator tube rupture event Reported results remain valid.
Verification completed prior to startup for Cycle 6
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/01/17 MILLER, J R Operating Reactors Branch 3 1p 22024 035 24X Fiche 50-336, B4/01/17, B401310023

8401230151 Notification of 841010-11 meetings w/uttl in Bethesda, MD to discuss & resolve outstanding environ qualification issues
SHEA, J J Operating Reactors Branch 5 84/01/20 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 21864 316 24X
Fiche 50-000, 84/01/20, 8401230151

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

8401170329 Forwards final rept providing basis for return to power operation based on results of thermal shield damage recovery program Core support barrel insps completed 831030 W/o stated rept
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/12
MILLER, J R Operating Reactors Branch 3 3pp 21829 328 24X
Fiche 50-336, 83/12/12, 8401170329

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Braun Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401180237 Forwards IE Insp Repts 50-245/83-21 & 50-336/83-27 on 831113-1217 No violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21842 339 24X Fiche 50-245, 84/01/03, 8401180237

--8401180249 IE Insp Repts 50-245/83-21 & 50-336/83-27 on 831113-1217 No violations noted Major areas inspected evaluations of plant operations, equipment alignments & readiness, radiation protection, physical security & fire protection
LIPINSKI, D R Region 1, Office of Director ELSASSER, T C Division of Project & Resident Programs 83/12/30 14pp 21842 341 24X Fiche 50-245, 84/01/03, 8401180237

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401180266 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21843 249 24X Fiche 50-245, 84/01/10, 8401180266

--8401180270 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-245/83-16 & 50-336/83-23 Corrective actions withheld (ref 10CFR73.21)
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/12/06
MARTIN, T T Division of Engineering & Technical Programs 2pp 21843 231 24X Fiche 50-245, 84/01/10, 8401180266

8401260300 Forwards IE Insp Rept 50-336/83-24 on 831019-21 No violation noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21956 003 24X Fiche 50-336, 84/01/10, 8401260300

--8401260309 IE Insp Rept 50-336/83-24 on 831019-21 No violation noted
Major areas inspected photographs, videotapes, analyses & exam of selected records re recently identified fuel problems
BETTENHAUSEN, L Region 1, Office of Director BETTENHAUSEN, L Division of Engineering & Technical Programs 83/12/19 13pp 21956 005
24X Fiche 50-336, 84/01/10, 8401260300

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IF Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120196 Monthly operating rept for Nov 1983 W/831215 ltr
GIBSON, J, MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/11/30
NRC - No Detailed Affiliation Given 4pp 21792 248 24X
Fiche 50-336, 83/11/30, 8401120196

8401270457 Monthly operating rept for Dec 1983 W/840113 ltr
GIBSON, J, MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/12/31
Office of Resource Management, Director 6pp 21980 262 24X
Fiche 50-336, 83/12/31, 8401270457

S Reportable occurrences, LERs & related correspondence

8312300176 LER 83-030/01T-0 on 831205, fuel movement took place in spent fuel pool, while credit taken for facility encl Bldg B
filtration sys (EDFS) EDFS inoperable due to installation of temporary wall not seismically qualified W/831216 ltr
BRINKMAN, S, MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/12/16
MURLEY, T E Region 1, Office of Director 2pp 21673 025 24X
Fiche 50-336, 83/12/16, 8312300176

8401120312 RO 50-336/83-31 during seismic analysis on svc water sys, discovered heavy vs std wall pipe installed Hanger loading analyses indicated five undersized hangers Further info will be provided in 14-day rept
HERBERT, R J, MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/12/23
MURLEY, T E Region 1, Office of Director 1p 21792 041 24X
Fiche 50-336, 83/12/23, 8401120312

8401040183 Updated LER 82-043/03X-1 on 821102, during power ascension, broken hydraulic snubber stud discovered & traced to hanger 490001 on main steam lead to high pressure turbine Caused by constant high vibration W/831227 ltr
STADNICK, S, MROCZKA, E J Northeast Utilities MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/12/27 MURLEY, T E Region 1, Office of Director 2pp 21701 349 24X Fiche 50-336, 83/12/27, 8401040183

8401100352 LER 83-031/01T-0 on 831222, discovered that Schedule 40 vs std wall pipe installed in portions of svc water sys Caused by matl unavailability Stress analysis updated & four hangers modified W/840105 ltr
FILLBURN, T, HERBERT, R J Northeast Nuclear Energy Co (subs of Northeast Utilities) HERBERT, R J Northeast Utilities 84/01/05
NRC - No Detailed Affiliation Given 3pp 21764 031 24X
Fiche 50-336, 84/01/05, 8401100352

8401170251 LER 83-032/03L-0 on 831214, during loss of normal power test on facility Z1, diesel generator 12U started but failed to sequence on emergency loads Caused by lack of breaker permissive inputs Connection resoldered W/840111 ltr
DUFFY, B, MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E J Northeast Utilities 84/01/11
NRC - No Detailed Affiliation Given 2pp 21827 128 24X
Fiche 50-336, 84/01/11, 8401170251

DOCKETED ITEMS

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8401050555 Ack receipt of B3118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-18 & 50-339/83-18
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 1p 21735 340 24X
Fiche 50-338, 83/12/15, 8401050555

--8401050622 IE Insp Repts 50-338/83-18 & 50-339/83-18 on 830706-0805
Violation noted: failure to follow procedures in radiation protection area & lockup relays not functionally checked
BHYMLOCK, M B, LUEHMANN, J G Region 2, Office of Director
LANDIS, K Division of Project & Resident Programs 83/10/18
7pp. 21735 347 24X Fiche 50-338, 83/12/15, 8401050555

8401240301 Forwards corrected pages to security program, per B3116 ltr
Pages withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/12/19 MCQUIRE, D R
Division of Emergency Preparedness & Materials Safety 1p
21909:265 24X Fiche 50-338, 83/12/19, 8401240301

8401030344 Releases public version of revised corporate emergency response plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch. 1p 21687 083 24X Fiche 50-000, 83/12/27, 8401030344

--8401030347 Public version of revised corporate emergency response plan
STEWART, W L Virginia Electric & Power Co 83/11/23,
O'REILLY, J P Region 2, Office of Director. 73pp 21687, 086
24X Fiche 50-000, 83/12/27, 8401030344

8401030353 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch. 1p 21688 129 24X Fiche 50-338, 83/12/27, 8401030353

--8401030357 Public version of Rev 4 to emergency plan, W/831214 ltr
Tech Spec to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/11/21
O'REILLY, J P Region 2, Office of Director 477pp 21688 002
24X Fiche 50-338, 83/12/27, 8401030353

8401040424 Application for amend to Licenses NPF-4 & DFR-7, revising
Tech Spec to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21708 113 24X
Fiche 50-338, 83/12/27, 8401040424

--8401040429 Proposed Tech Specs re addition of new fire protection sys
* Virginia Electric & Power Co 83/12/27 7pp 21708 115 24X
Fiche 50-338, 83/12/27, 8401040424

8401050110 Releases public version of Rev 5 to emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch. 1p 21743 302. 24X Fiche 50-338, 83/12/28, 8401050110

--8401050114 Public version of Rev 5 to emergency plan, W/831117 ltr
& revised effective page listing
STEWART, W L Virginia Electric & Power Co 83/10/26
O'REILLY, J P Region 2, Office of Director 40pp 21743 303
24X Fiche 50-338, 83/12/28, 8401050110

8401060048 Forwards 10CFR170 fees for fire protection reviews &
approvals, per 831206 request
STEWART, W L Virginia Electric & Power Co 83/12/30 MILLER, W O
License Fee Management Branch. 1p 21739 226. 24X
Fiche 50-338, 83/12/30, 8401060048

8401100307 Ack receipt of revised physical security plan dtd 830920,
per 831006 submittal Portions of revs inconsistent w/
provisions of 10CFR50 54 & must not be implemented Encl
detailing inconsistent changes withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/05
STEWART, W L Virginia Electric & Power Co. 3pp. 21759, 166. 24X
Fiche: 50-338, 84/01/05, 8401100307

8401170408 Forwards exercise rept of 830618 joint exercise of offsite
radiological emergency preparedness plans for facilities.
KRIMM, R W Federal Emergency Management Agency. 84/01/09
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 33pp 21828, 225 24X Fiche: 50-338,
84/01/09, 8401170408.

8401300080 Advises that location of backup & primary emergency
operation facilities acceptable, in response to 820408, 1206.
830414 & 0506 ltrs
EISENHUT, D O Division of Licensing 84/01/13 STEWART, W L
Virginia Electric & Power Co 2pp 22006 316 24X
Fiche 50-000, 84/01/13, 8401300080

8401200102 Notification of 840127 meeting w/utl1 & S&W in Bethesda, Md
to discuss planned mods & schedules resulting from preaudit
& reevaluation of App R effort
ENGLE, L B Operating Reactors Branch 3 84/01/17 MILLER, J R
Operating Reactors Branch 3 3pp 21932 214 24X
Fiche 50-000, 84/01/17, 8401200102

8401260253 Releases public version of revised emergency plan.
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21992 144 24X Fiche 50-338, 84/01/18,
8401260253

--8401260257 Public version of Rev 7 to emergency plan W/831227 ltr
PAXTON, Q J, STEWART, W L Virginia Electric & Power Co 83/12/
O'REILLY, J P Region 2, Office of Director 8pp 21992 145
24X Fiche 50-338, 84/01/18, 8401260253

8401300090 Forwards results of 830829-0902 regulatory effectiveness
review, including vital area validation Comments requested
by 840127 Encl withheld
THOMAS, C O Standardization & Special Projects Branch 84/01/19
PARR, D D Auxiliary Systems Branch CLAYTON, B H Procedures &
Systems Review Branch 1p 22006 161 24X Fiche 50-338, 84/01/19
8401300090

8401260201 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21971 334 24X Fiche 50-338, 84/01/20,
8401260201

--8401260205 Public version of Rev 5 to Emergency Plan Implementing
Procedure EPIP-3 04, "Activation of Emergency Operation
Facility," W/840104 ltr
STEWART, W L Virginia Electric & Power Co 83/12/21
O'REILLY, J P Region 2, Office of Director 15pp 21971 335
24X Fiche 50-338, 84/01/20, 8401260201

8401300178 Extends completion date for implementation of emergency
operating procedures to 840115 per Generic Ltr 82-33
(NUREG-0737, Suppl 1)
STEWART, W L Virginia Electric & Power Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21997 357 24X
Fiche 50-338, 84/01/20, 8401300178

8401300115 Ack receipt of 831106 & 1219 ltrs, transmitting Rev 11 to
physical security plan Rev 11 acceptable
LEWIS, R C Division of Project & Resident Programs 84/01/24
STEWART, W L Virginia Electric & Power Co 3pp 21999 225 24X
Fiche 50-338, 84/01/24, 8401300115

H General correspondence

8401040445 Submits change of address for Old Dominion Electric
Cooperative
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21708 092 24X
Fiche 50-338, 83/12/27, 8401040445

J Insurance & indemnity information

8401060296 Forwards Amend B to Indemnity Agreement B-80, verifying
partial sale of facility to Old Dominion Electric
Cooperative
STEWART, W L Virginia Electric & Power Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Licensing Branch 3 2pp 21742 350 24X Fiche 50-338, 83/12/30,
8401060296

8401300264 Endorsements to MAELU & NELIA policies, including
Endorsement 4 to Policies M-28, N-28, M-27 & N-27, Endorsement
6 to M-70, N-70, M-63 & N-63, Endorsement 34 to MF-57,
Endorsement 71 to NF-186 & Endorsement 33 to MF-96
* Nuclear Energy Liability Insurance Association * Mutual Atomic
Energy Liability Underwriters 84/01/03 16pp 21998 344 24X
Fiche 50-000, 84/01/03, 8401300264

P Operating license stage documents & correspondence

8401090162 Forwards request for addl info to continue review of submittals re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." Response schedule requested in 30 days
VARGA, S A Operating Reactors Branch 1 83/12/16 STEWART, W L
Virginia Electric & Power Co Bpp 21757 217 24X
Fiche 50-000, 83/12/16, 8401090162

8401040424 Application for amend to Licenses NPF-4 & DPR-7, revising Tech Spec to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21708 113 24X
Fiche 50-338, 83/12/27, 8401040424

---8401040429 Proposed Tech Specs re addition of new fire protection sys
* Virginia Electric & Power Co 83/12/27 7pp 21708 115 24X
Fiche 50-338, 83/12/27, 8401040424

8401040229 Informs of completed evaluation of safety & relief valve discharge piping, per NUREG-0737, Item II D 1 2 Util will proceed w/final engineering & required mods based on retention of safety valve loop seals
STEWART, W L Virginia Electric & Power Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 21701 188 24X Fiche 50-338, 83/12/29, 8401040229

8401040520 Forwards proprietary response to request for further clarification of addl info provided in util 831206 ltr re proposed spent fuel capacity expansion Affidavit requesting info be withheld (ref 10CFR2 790) encl
STEWART, W L Virginia Electric & Power Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 21707 271 24X
Fiche 50-338, 83/12/29, 8401040520

8401090500 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs re reactor trip sys interlock setpoint P-7 to indicate 10% full load turbine impulse chamber pressure instead of thermal power equivalent
STEWART, W L Virginia Electric & Power Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 4pp 21753 107 24X
Fiche 50-338, 83/12/30, 8401090500

---8401090501 Proposed Tech Spec Table 3 3-1, "Reactor Trip Sys Interlocks"
* Virginia Electric & Power Co 83/12/30 6pp 21753 111 24X
Fiche 50-338, 83/12/30, 8401090500

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401240225 Responds to Generic Ltr 83-41 re premature diesel engine degradation caused by starts w/rapid acceleration loading w/o prelubrication & warmup Diesel generators have undergone design changes to alleviate fast cold starts
STEWART, W L Virginia Electric & Power Co 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 2pp 21910 174 24X Fiche 50-338, 84/01/18, 8401240225

8401300090 Forwards results of 830829-0902 regulatory effectiveness review, including vital area validation Comments requested by 840127 Encl withheld
THOMAS, C O Standardization & Special Projects Branch 84/01/19
PARR, D D Auxiliary Systems Branch CLAYTON, D H Procedures & Systems Review Branch 1p 22006 161 24X Fiche 50-338, 84/01/19, 8401300090

8401270268 Provides status rpt of progress on resolving ODC 17 analysis re rerating of motor operated valves & plan for further work as committed to in 831014 ltr Verified valve torque requirements obtained for all valves
STEWART, W L Virginia Electric & Power Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 3pp 21976 161 24X
Fiche 50-338, 84/01/20, 8401270268

8401310210 Cancels 831118 application for amend to Licenses NPF-4 & NPF-7, revising Tech Specs on quadrant power tilt ratio
STEWART, W L Virginia Electric & Power Co 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 1p 22021 349 24X
Fiche 50-338, 84/01/23, 8401310210

8401310402 Application to cancel 820628 proposed Tech Spec changes re RCG leakage detection sys, per 840117 discussion between JH Leberstien & LB Engle
STEWART, W L Virginia Electric & Power Co 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 1p 22018 342 24X
Fiche 50-338, 84/01/23, 8401310402

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

---8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401060475 Confirms 831114 telcon re 831208 mgt meeting at plant site re results of BALP program BALP board assessment will be forwarded approx 1 wk prior to meeting Agenda encl
O'REILLY, J P Region 2, Office of Director 83/12/01 STEWART, W L
Virginia Electric & Power Co 2pp 21740 265 24X
Fiche 50-338, 83/12/01, 8401060475

8401050557 Ack receipt of 831123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-17 & 50-339/83-17
DANCE, H C Division of Project & Resident Programs 83/12/14
STEWART, W L Virginia Electric & Power Co 1p 21726 123 24X
Fiche 50-338, 83/12/14, 8401050557

---8401050575 Responds to NRC 831028 ltr re violations noted in IE Insp Repts 50-338/83-17 & 50-339/83-17 Corrective actions extraneous unidentifiable mats from technical support ctr & barricades stiffened
STEWART, W L Virginia Electric & Power Co 83/11/23
O'REILLY, J P Region 2, Office of Director 3pp 21726 124 24X
Fiche 50-338, 83/12/14, 8401050557

---8401050588 Forwards IE Insp Repts 50-338/83-17 & 50-339/83-17 on 830611-0705 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/10/28
STEWART, W L Virginia Electric & Power Co 2pp 21726 127 24X
Fiche 50-338, 83/12/14, 8401050557

---8401050598 Notice of violation from insp on 830611-0705
* Region 2, Office of Director 83/10/28 1p 21726 129 24X
Fiche 50-338, 83/12/14, 8401050557

---8401050614 IE Insp Repts 50-338/83-17 & 50-339/83-17 on 830611-0705 Violation noted failure to identify & control Category 1 mat in technical support ctr
SHYLOCK, M B, LUEHMANN, J G, JENISON, K M Region 2, Office of Director 83/10/27 Bpp 21726 130 24X Fiche 50-338, 83/12/14, 8401050557

8401050555 Ack receipt of 831118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-18 & 50-339/83-18
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 1p 21735 340 24X
Fiche 50-338, 83/12/15, 8401050555

---8401050579 Responds to NRC 831019 ltr re violations noted in IE Insp Repts 50-338/83-18 & 50-339/83-18 Corrective actions: Checklist Procedure EMP-P-RT-208 revised; personnel counseled in adherence to procedures & surveillance increased
STEWART, W L Virginia Electric & Power Co 83/11/18, O'REILLY, J P Region 2, Office of Director 3pp 21735 341 24X
Fiche: 50-338, 83/12/15, 8401050555

DOCKETED ITEMS

- B401050594 Forwards IE Insp Repts 50-338/83-18 & 50-339/83-18 on 830706-0805 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/10/19
STEWART, W L Virginia Electric & Power Co 2pp 21735 344 24X
Fiche 50-338, 83/12/15, 8401050595
- B401050605 Notice of violation from Insp on 830706-0805
* Region 2, Office of Director 83/10/19 1p 21735 346 24X
Fiche 50-338, 83/12/15, 8401050595
- B401050622 IE Insp Repts 50-338/83-18 & 50-339/83-18 on 830706-0805
Violation noted failure to follow procedures in radiation protection area & lockup relays not functionally checked
SHYMLOCK, M B, LUEHMAN, J G Region 2, Office of Director
LANDIS, K Division of Project & Resident Programs 83/10/18
7pp 21735 347 24X Fiche 50-338, 83/12/15, 8401050595
- B401090041 Forwards IE Insp Repts 50-338/83-24 & 50-339/83-24 on 830906-1005 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 2pp 21754 001 24X
Fiche 50-338, 83/12/15, 8401090041
- B401090056 IE Insp Repts 50-338/83-24 & 50-339/83-24 on 830906-1005 No violations noted
Major areas inspected surveillance, safety sys walkdowns, LERS, procurement, maint activities, Category I matl storage & design changes
SHYMLOCK, M B, LUEHMAN, J G, JENISON, K Region 2, Office of Director 83/12/15 10pp 21754 003 24X Fiche 50-338, 83/12/15, 8401090041
- B401050482 Ack receipt of 831118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-13 & 50-339/83-13
LEWIS, R C Division of Project & Resident Programs 83/12/20
STEWART, W L Virginia Electric & Power Co 1p 21725 340 24X
Fiche 50-338, 83/12/20, 8401050482
- B401050496 Responds to NRC 831020 ltr re violations noted in IE Insp Repts 50-338/83-13 & 50-339/83-13 Corrective actions
intermediate range neutron flux trip setpoint modified & procedure revised to include visual verification
STEWART, W L Virginia Electric & Power Co 83/11/18
O'REILLY, J P Region 2, Office of Director 5pp 21725 341 24X
Fiche 50-338, 83/12/20, 8401050482
- B401050508 Forwards IE Insp Repts 50-338/83-13 & 50-339/83-13 on 830506-0610 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/20
STEWART, W L Virginia Electric & Power Co 2pp 21725 346 24X
Fiche 50-338, 83/12/20, 8401050482
- B401050519 Notice of violation from Insp on 830506-0610
* Region 2, Office of Director 83/12/20 2pp 21725 348 24X
Fiche 50-338, 83/12/20, 8401050482
- B401050539 IE Insp Repts 50-338/83-13 & 50-339/83-13 on 830506-0610
Violation noted failure to implement written procedures for discharge & inlet valves & failure to set neutron flux trip setpoints properly
SHYMLOCK, M B, LUEHMAN, J G, JENISON, K M Region 2, Office of Director 83/10/14 8pp 21725 350 24X Fiche 50-338, 83/12/20, 8401050482
- B401240551 Forwards IE Insp Repts 50-338/83-27 & 50-339/83-27 on 831006-1205 No violations or deviations noted
DANCE, H C Division of Project & Resident Programs 83/12/23
STEWART, W L Virginia Electric & Power Co 2pp 21920 022 24X
Fiche 50-338, 83/12/23, 8401240551
- B401240553 IE Insp Repts 50-338/83-27 & 50-339/83-27 on 831006-1205 No violations or deviations noted
Major areas inspected cold water protection, identified items, LERS, surveillance & maint
SHYMLOCK, M B, LUEHMAN, J G Region 2, Office of Director
ELROD, S A Division of Project & Resident Programs 83/12/22
7pp 21920 024 24X Fiche 50-338, 83/12/23, 8401240551
- B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093
- B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104
- B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107
- B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114
- B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License " Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116
- B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- R Periodic operating reports & related correspondence
- B401120233 Monthly operating repts for Nov 1983 W/831214 ltr
LEE, J N, STEWART, W L Virginia Electric & Power Co 83/11/30
HALLER, N M Office of Resource Management, Director 13pp 21794 127 24X Fiche 50-338, 83/11/30, 8401120233
- B401270484 Monthly operating repts for Dec 1983 W/840113 ltr
LEE, J N, STEWART, W L Virginia Electric & Power Co 83/12/31 HALLER, N M NRC - No Detailed Affiliation Given 14pp 21781 158 24X
Fiche 50-338, 83/12/31, 8401270484
- S Reportable occurrences, LERS & related correspondence
- B401040549 LER 83-084/03L-0 on 831202, fire door between clean charge room & auxiliary bldg would not latch automatically Caused by loose & missing screws on door hinges Screws tightened & missing screws replaced W/831221 ltr
HARELL, E W Virginia Electric & Power Co 83/12/21 O'REILLY, J P Region 2, Office of Director 2pp 21706 314 24X
Fiche 50-338, 83/12/21, 8401040549
- B401120293 Informs of 831228 oil sheen discovered on Lake Anna Caused by rain washing oil off waste oil drums Oil boom & absorbent pads used to contain & clean up spill Oil drum storage facility const in progress
TAYLOR, J A Virginia Electric & Power Co 83/12/29 CHEWNING, R B Virginia, Commonwealth of, 1p 21792 302 24X
Fiche 50-338, 83/12/29, 8401120293
- B401050548 LER 83-086/03L-0 on 831209, w/unit at 100% power, open penetration discovered in fire wall between motor driven auxiliary feedwater pump room & steam driven auxiliary feedwater pump room Wall not included in test W/831230 ltr
HARELL, E W Virginia Electric & Power Co 83/12/30 O'REILLY, J P Region 2, Office of Director 2pp 21726 092 24X
Fiche 50-338, 83/12/30, 8401050548
- B401230021 LER 83-085/03L-0 on 831220, discovered thermal power containment pressure channel IV drifting & causing intermittent alarms Possibly caused by dirt in feedback coil Transmitter cleaned W/840111 ltr
HARELL, E W Virginia Electric & Power Co 84/01/11 O'REILLY, J P Region 2, Office of Director 3pp 21884 185 24X
Fiche 50-338, 84/01/11, 8401230021
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- B401050555 Ack receipt of 831118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-18 & 50-339/83-18
DANCE, H C Division of Project & Resident Programs 83/12/15
STEWART, W L Virginia Electric & Power Co 1p 21735 340 24X
Fiche 50-338, 83/12/15, 8401050555

DOCKETED ITEMS

207

--B401050622 IE Insp Repts 50-338/83-18 & 50-339/83-18 on 830706-0805
Violation noted failure to follow procedures in radiation
protection area & lockup relays not functionally checked
SMYLMLOCK, M B Region 2, Office of Director 83/10/18 7pp
21739 347 24X Fiche 50-338, 83/12/15, 8401050555

B401240301 Forwards corrected pages to security program, per 831116 ltr
Pages withheld (ref 10CFR73 21)
STEWART, W L Virginia Electric & Power Co 83/12/19 MCQUIRE, D R
Division of Emergency Preparedness & Materials Safety 1p
21909 265 24X Fiche 50-338, 83/12/19, 8401240301

B401030344 Releases public version of revised corporate emergency
response plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21687 083 24X Fiche 50-000, 83/12/27,
8401030344

--B401030347 Public version of revised corporate emergency response plan
STEWART, W L Virginia Electric & Power Co 83/11/23
O'REILLY, J P Region 2, Office of Director 73pp 21687 084
24X Fiche 50-000, 83/12/27, 8401030344

B401030353 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21688 129 24X Fiche 50-338, 83/12/27,
8401030353

--B401030357 Public version of Rev 4 to emergency plan W/831214 ltr
STEWART, W L Virginia Electric & Power Co 83/11/21
O'REILLY, J P Region 2, Office of Director 477pp 21688 002
24X Fiche 50-338, 83/12/27, 8401030353

B401040424 Application for amend to Licenses NPF-4 & DPR-7, revising
Tech Spec to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21708 113
24X Fiche 50-338, 83/12/27, 8401040424

--B401040429 Proposed Tech Specs re addition of new fire protection sys
& Virginia Electric & Power Co 83/12/27 7pp 21708 113 24X
Fiche 50-338, 83/12/27, 8401040424

B401050110 Releases public version of Rev 5 to emergency plan
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21743 302 24X Fiche 50-338, 83/12/28,
8401050110

--B401050114 Public version of Rev 5 to emergency plan W/831117 ltr
& revised effective page listing
STEWART, W L Virginia Electric & Power Co 83/10/26
O'REILLY, J P Region 2, Office of Director 40pp 21743 303
24X Fiche 50-338, 83/12/28, 8401050110

B401060048 Forwards 10CFR170 fees for fire protection reviews &
approvals, per 831206 request
STEWART, W L Virginia Electric & Power Co 83/12/30 MILLER, M O
License Fee Management Branch 1p 21739 226 24X
Fiche 50-338, 83/12/30, 8401060048

B401100307 Ack receipt of revised physical security plan dtd 830920,
per 831006 submittal Portions of revs inconsistent w/
provisions of 10CFR50.54 & must not be implemented Encl
detailing inconsistent changes withheld (ref 10CFR73 21)
LEWIS, R C Division of Project & Resident Programs 84/01/05
STEWART, W L Virginia Electric & Power Co 3pp 21759 166 24X
Fiche 50-338, 84/01/05, 8401100307

B401170408 Forwards exercise rept of 830618 joint exercise of offsite
radiological emergency preparedness plans for facilities
KRAMER, R W Federal Emergency Management Agency 84/01/09
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 33pp 21628 225 24X Fiche 50-338,
84/01/09, 8401170408

B401300080 Advises that location of backup & primary emergency
operation facilities acceptable in response to 820408, 1206,
830414 & 0506 ltrs
EISENHUT, D O Division of Licensing 84/01/13 STEWART, W L
Virginia Electric & Power Co 2pp 22006 316 24X
Fiche 50-000, 84/01/13, 8401300080

B401200102 Notification of 840127 meeting w/util & S&W in Bethesda, MD
to discuss planned mods & schedules resulting from preaudit
& reevaluation of App R effort
ENGLE, L D Operating Reactors Branch 3 84/01/17, MILLER, J R
Operating Reactors Branch 3 3pp 21932 214 24X
Fiche 50-000, 84/01/17, 8401200102

B401260253 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21992 144 24X Fiche 50-338, 84/01/18,
8401260253

--B401260257 Public version of Rev 7 to emergency plan W/831227 ltr
FAXTON, Q J, STEWART, W L Virginia Electric & Power Co 83/12/14
O'REILLY, J P Region 2, Office of Director 8pp 21992 145
24X Fiche 50-338, 84/01/18, 8401260253

B401300090 Forwards results of 830829-0902 regulatory effectiveness
review, including vital area validation Comments requested
by 840127 Encl withheld
THOMAS, C D Standardization & Special Projects Branch 84/01/19
PARR, Q D Auxiliary Systems Branch 1p 22006 161 24X
Fiche 50-338, 84/01/19, 8401300090

B401260201 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21971 334 24X Fiche 50-338, 84/01/20,
8401260201

--B401260205 Public version of Rev 5 to Emergency Plan Implementing
Procedure EPIP-3 04, "Activation of Emergency Operation
Facility" W/840104 ltr
STEWART, W L Virginia Electric & Power Co 83/12/21
O'REILLY, J P Region 2, Office of Director 15pp 21971 335
24X Fiche 50-338, 84/01/20, 8401260201

B401300178 Extends completion date for implementation of emergency
operating procedures to 840115 per Generic Ltr 82-33
(NUREG-0737, Suppl 1)
STEWART, W L Virginia Electric & Power Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21997 357 24X
Fiche 50-338, 84/01/20, 8401300178

B401300115 Ack receipt of 831106 & 1219 ltrs, transmitting Rev 11 to
physical security plan Rev 11 acceptable
LEWIS, R C Division of Project & Resident Programs 84/01/24
STEWART, W L Virginia Electric & Power Co 3pp 21999 225 24X
Fiche 50-338, 84/01/24, 8401300115

H General correspondence

B401040445 Submits change of address for Old Dominion Electric
Cooperative
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21708 092 24X
Fiche 50-338, 83/12/27, 8401040445

J Insurance & indemnity information

B401300264 Endorsements to MAELU & NELIA policies, including
Endorsement 4 to Policies M-28, N-28, M-27 & N-27, Endorsement
6 to M-70, N-70, M-63 & N-63, Endorsement 84 to MF-57,
Endorsement 71 to NF-186 & Endorsement 35 to MF-96
* Nuclear Energy Liability Insurance Association 84/01/03 16pp
21998 344 24X Fiche 50-000, 84/01/03, 8401300264

B401040296 Forwards Amend B to Indemnity Agreement B-80, verifying
partial sale of facility to Old Dominion Electric
Cooperative
STEWART, W L Virginia Electric & Power Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Licensing Branch 3 2pp 21742 350 24X Fiche 50-338, 83/12/30,
8401040296

P Operating license stage documents & correspondence

B401090162 Forwards request for addl info to continue review of
submittals re NUREG-0737, Item II B 3, "Post-Accident
Sampling Sys" Response schedule requested in 30 days
VARGA, B A Operating Reactors Branch 1 83/12/16, STEWART, W L
Virginia Electric & Power Co 8pp 21757 217 24X
Fiche 50-000, 83/12/16, 8401090162

B401040424 Application for amend to Licenses NPF-4 & DPR-7, revising
Tech Spec to reflect addition of new fire protection sys
STEWART, W L Virginia Electric & Power Co 83/12/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, J R
Operating Reactors Branch 3 2pp 21708 113 24X
Fiche 50-338, 83/12/27, 8401040424

--B401040429 Proposed Tech Specs re addition of new fire protection sys
& Virginia Electric & Power Co 83/12/27 7pp, 21708 113 24X
Fiche 50-338, 83/12/27, 8401040424

DOCKETED ITEMS

B401040520 Forwards proprietary response to request for further clarification of add'l info provided in util 831204 ltr re proposed spent fuel capacity expansion Affidavit requesting info be withheld (ref 10CFR2 790) encl
 STEWART, W L Virginia Electric & Power Co 83/12/29 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 3pp 21707 271 24X
 Fiche: 50-338, 83/12/29, B401040520

B401090500 Application to amend Licenses NPF-4 & NPF-7, revising Tech Specs re reactor trip sys interlock setpoint P-7 to indicate 10X full load turbine impulse chamber pressure instead of thermal power equivalent
 STEWART, W L Virginia Electric & Power Co 83/12/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 4pp 21753 107 24X
 Fiche: 50-338, 83/12/30, B401090500

--B401090501 Proposed Tech Spec Table 3 3-1, "Reactor Trip Sys Interlocks"
 * Virginia Electric & Power Co 83/12/30 6pp 21753 111 24X
 Fiche: 50-338, 83/12/30, B401090500

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms: "important to safety" & "safety-related." Svc list encl
 EISENHUT, D O Division of Licensing 84/01/05 Consolidated
 Edison Co of New York, Inc. 18pp 21946 190 24X
 Fiche: 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
 Svc list encl
 EISENHUT, D O Division of Licensing 84/01/06 Consolidated
 Edison Co of New York, Inc. 18pp 21957 267 24X
 Fiche: 50-000, 84/01/06, B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
 Svc list encl
 EISENHUT, D O Division of Licensing 84/01/13 Consolidated
 Edison Co of New York, Inc. 18pp 21946 174 24X
 Fiche: 50-000, 84/01/13, B401130084

B401240223 Responds to Generic Ltr B3-41 re premature diesel engine degradation caused by starts w/rapid acceleration loading
 w/o prelubrication & warmup Diesel generators have undergone design changes to alleviate fast cold starts.
 STEWART, W L Virginia Electric & Power Co 84/01/18 DENTON, H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D O
 Division of Licensing 2pp 21910 174 24X Fiche: 50-338, 84/01/18, B401240223

B401300090 Forwards results of B30829-0902 regulatory effectiveness review, including vital area validation Comments requested by B40127. Encl withheld
 THOMAS, C O Standardization & Special Projects Branch 84/01/19
 PARR, D D Auxiliary Systems Branch CLAYTON, B H Procedures & Systems Review Branch 1p 22006 161 24X Fiche: 50-338, 84/01/19, B401300090

B401270268 Provides status rept of progress on resolving QDC 17 analysis re rotating of motor operated valves & plan for further work as committed to in B31014 ltr Verified valve torque requirements obtained for all valves
 STEWART, W L Virginia Electric & Power Co 84/01/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 3pp 21976 161 24X
 Fiche: 50-338, 84/01/20, B401270268

B401310210 Cancels B31118 application for amend to Licenses NPF-4 & NPF-7, revising Tech Specs on quadrant power tilt ratio.
 STEWART, W L Virginia Electric & Power Co 84/01/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 1p 22021 349 24X
 Fiche: 50-338, 84/01/23, B401310210

B401310402 Application to cancel B20628 proposed Tech Spec changes re RCS leakage detection sys, per B40117 discussion between JH Labersien & LB Engle
 STEWART, W L Virginia Electric & Power Co 84/01/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 1p 22018 342 24X
 Fiche: 50-338, 84/01/23, B401310402

Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR.
 FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E, Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
 Fiche: 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
 * Director's Office, Office of Inspection and Enforcement
 83/10/20 105pp 21744 004 24X Fiche: 50-000, 83/10/20, B401060040

B401060475 Confirms B31114 telcon re B31208 mgt meeting at plant site re results of BALP program BALP board assessment will be forwarded approx 1 wk prior to meeting Agenda encl
 O'REILLY, J P Region 2, Office of Director 83/12/01 STEWART, W L
 Virginia Electric & Power Co 2pp 21740 265 24X
 Fiche: 50-338, 83/12/01, B401060475

B401050557 Ack receipt of B31123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/B3-17 & 50-339/B3-17
 DANCE, H C Division of Project & Resident Programs 83/12/14
 STEWART, W L Virginia Electric & Power Co 1p 21726 123 24X
 Fiche: 50-338, 83/12/14, B401050557

--B401050575 Responds to NRC B31028 ltr re violations noted in IE Insp Repts 50-338/B3-17 & 50-339/B3-17 Corrective actions: extraneous unidentifiable mats from technical support ctr & barricades stiffened
 STEWART, W L Virginia Electric & Power Co 83/11/23
 O'REILLY, J P Region 2, Office of Director 3pp 21726 124 24X
 Fiche: 50-338, 83/12/14, B401050575

--B401050588 Forwards IE Insp Repts 50-338/B3-17 & 50-339/B3-17 on B30611-0705 & notice of violation
 DANCE, H C Division of Project & Resident Programs 83/10/28
 STEWART, W L Virginia Electric & Power Co 2pp 21726 127 24X
 Fiche: 50-338, 83/12/14, B401050557

--B401050598 Notice of violation from insp on B30611-0705
 * Region 2, Office of Director 83/10/28 1p 21726 129 24X
 Fiche: 50-338, 83/12/14, B401050557

--B401050614 IE Insp Repts 50-338/B3-17 & 50-339/B3-17 on B30611-0705
 Violation noted failure to identify & control Category I matl in technical support ctr
 SHYMLOCK, M B, LUEHMANN, J O, JENISON, K M Region 2, Office of Director 83/10/27 8pp 21726 130 24X Fiche: 50-338, 83/12/14, B401050557

B401050555 Ack receipt of B31118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/B3-18 & 50-339/B3-18
 DANCE, H C Division of Project & Resident Programs 83/12/15
 STEWART, W L Virginia Electric & Power Co 1p 21735 340 24X
 Fiche: 50-338, 83/12/15, B401050555

--B401050577 Responds to NRC B31019 ltr re violations noted in IE Insp Repts 50-338/B3-18 & 50-339/B3-18 Corrective actions: Checklist Procedure EMP-P-R-208 revised, personnel counseled in adherence to procedures & surveillance increased
 STEWART, W L Virginia Electric & Power Co 83/11/18
 O'REILLY, J P Region 2, Office of Director 3pp 21735 341 24X
 Fiche: 50-338, 83/12/15, B401050555

--B401050594 Forwards IE Insp Repts 50-338/B3-18 & 50-339/B3-18 on B30706-0805 & notice of violation
 DANCE, H C Division of Project & Resident Programs 83/10/19
 STEWART, W L Virginia Electric & Power Co 2pp 21735 344 24X
 Fiche: 50-338, 83/12/15, B401050555

--B401050605 Notice of violation from insp on B30706-0805
 * Region 2, Office of Director 83/10/19 1p 21735 346 24X
 Fiche: 50-338, 83/12/15, B401050555

--B401050622 IE Insp Repts 50-338/B3-18 & 50-339/B3-18 on B30706-0805
 Violation noted failure to follow procedures in radiation protection area & lockup relays not functionally checked
 SHYMLOCK, M B, LUEHMANN, J O Region 2, Office of Director
 LANDIS, K Division of Project & Resident Programs 83/10/18
 7pp 21735 347 24X Fiche: 50-338, 83/12/15, B401050555

B401090041 Forwards IE Insp Repts 50-338/B3-24 & 50-339/B3-24 on B30906-1003 No violations noted
 DANCE, H C Division of Project & Resident Programs 83/12/15
 STEWART, W L Virginia Electric & Power Co 2pp 21754 001 24X
 Fiche: 50-338, 83/12/15, B401090041

--B401090056 IE Insp Repts 50-338/B3-24 & 50-339/B3-24 on B30906-1003 No violations noted Major areas inspected surveillance, safety sys walkdowns, LERs, procurement, maint activities, Category I matl storage & design changes
 SHYMLOCK, M B, LUEHMANN, J O, JENISON, K Region 2, Office of Director 83/12/15 10pp 21754 003 24X Fiche: 50-338, 83/12/15, B401090041

DOCKETED ITEMS

209

8401030482 Ack receipt of 831118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-13 & 50-339/83-13
LEWIS, R C Division of Project & Resident Programs 83/12/20
STEWART, W L Virginia Electric & Power Co 1p 21725 340 24X
Fiche 50-338, 83/12/20, 8401030482

--8401030496 Responds to NRC 831020 ltr re violations noted in IE Insp Repts 50-338/83-13 & 50-339/83-13 Corrective actions intermediate range neutron flux trip setpoint modified & procedure revised to include visual verification
STEWART, W L Virginia Electric & Power Co 83/11/18
O'REILLY, J P Region 2, Office of Director 3pp 21725 341 24X
Fiche 50-338, 83/12/20, 8401030482

--8401030508 Forwards IE Insp Repts 50-338/83-13 & 50-339/83-13 on 830506-0610 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/20
STEWART, W L Virginia Electric & Power Co 2pp 21725 346 24X
Fiche 50-338, 83/12/20, 8401030482

--8401030519 Notice of violation from insp on 830506-0610
* Region 2, Office of Director 83/12/20 2pp 21725 348 24X
Fiche 50-338, 83/12/20, 8401030482

--8401030539 IE Insp Repts 50-338/83-13 & 50-339/83-13 on 830506-0610 Violation noted failure to implement written procedures for discharge & inlet valves & failure to set neutron flux trip setpoints properly
SHYLOCK, M B, LUEHMAN, J O, JENISON, K M Region 2, Office of Director 83/10/14 8pp 21725 350 24X Fiche 50-338, 83/12/20, 8401030482

8401240551 Forwards IE Insp Repts 50-338/83-27 & 50-339/83-27 on 831006-1205 No violations or deviations noted
DANCE, H C Division of Project & Resident Programs 83/12/23
STEWART, W L Virginia Electric & Power Co 2pp 21920 022 24X
Fiche 50-338, 83/12/23, 8401240551

--8401240553 IE Insp Repts 50-338/83-27 & 50-339/83-27 on 831006-1205 No violations or deviations noted Major areas inspected cold water protection, identified items, LERs, surveillance & maint
SHYLOCK, M B, LUEHMAN, J O Region 2, Office of Director
ELROD, S A Division of Project & Resident Programs 83/12/22 7pp 21920 024 24X Fiche 50-338, 83/12/23, 8401240551

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 033, 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp, 21826 184, 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957, 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp, 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp, 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120253 Monthly operating repts for Nov 1983 W/831214 ltr
LEE, J N, STEWART, W L Virginia Electric & Power Co 83/11/30
HALLER, N M Office of Resource Management, Director 15pp
21794 127 24X Fiche 50-338, 83/11/30, 8401120253

8401270484 Monthly operating repts for Dec 1983 W/840113 ltr
LEE, J N Virginia Electric & Power Co 83/12/31 HALLER, N M NRC
- No Detailed Affiliation Given 14pp 21981 158 24X
Fiche 50-338, 83/12/31, 8401270484

S Reportable occurrences, LERs & related correspondence

8401040365 LER 83-079/03L-0 on 831211, pressurizer level indication channel II LI-2460 failed low Caused by failure of power supply card LI-2460 Card replaced & channel caliber satisfactorily W/831221 ltr
HARRELL, E W Virginia Electric & Power Co 83/12/21 O'REILLY, J P
Region 2, Office of Director 2pp 21706 182 24X
Fiche 50-339, 83/12/21, 8401040365

8401120293 Informs of 831228 oil sheen discovered on Lake Anna Caused by rain washing oil off waste oil drums Oil boom & absorbent pads used to contain & clean up spill Oil drum storage facility const in progress
TAYLOR, J A Virginia Electric & Power Co 83/12/29 CHEWNING, R B
Virginia, Commonwealth of, 1p 21792 302 24X
Fiche 50-338, 83/12/29, 8401120293

8401130010 LER 83-072/03L-0 on 831205, low head safety injection pump containment suction valve MDV-2860A failed to open fully during surveillance testing Caused by placement of electrical cord on valve stem extension W/840104 ltr
HARRELL, E W Virginia Electric & Power Co 84/01/04 O'REILLY, J P
Region 2, Office of Director 4pp 21802 350 24X
Fiche 50-339, 84/01/04, 8401130010

8401260006 LER 83-080/03L-0 on 831221, individual rod position indicator for rod C-09 deviated from group demand position by greater than 12 steps Caused by instrument drift Channel properly recaliber & returned to svc W/840118 ltr
HARRELL, E W Virginia Electric & Power Co 84/01/18 O'REILLY, J P
Region 2, Office of Director 2pp 21956 343 24X
Fiche 50-339, 84/01/18, 8401260006

8401260015 LER 83-074/03L-0 on 831227, outer personnel hatch door determined to have unacceptable leak rate Caused by dirt buildup on seal Seal cleaned, relubricated & tested satisfactorily W/840118 ltr
HARRELL, E W Virginia Electric & Power Co 84/01/18 O'REILLY, J P
Region 2, Office of Director 2pp 21956 317 24X
Fiche 50-339, 84/01/18, 8401260015

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8401230330 Informs that Rev 1 to Preoperational Test C1108-001 re rod worth minimizer sys will be initiated on or about 831230 Draft procedure provided for chief of test program section & P Byron, NRC resident inspector
AODBT, F E Detroit Edison Co 83/12/20 KONKLIN, J E Region 3, Office of Director 1p 21882 357 24X Fiche 50-341, 83/12/20, 8401230330

8312120101 Board Notification 83-187 provides info re possible interaction of main steam lines w/main feedwater at BHRs. Subj being studied on expedited basis Commissioners will be notified when review completed
ETSENHUT, D O Division of Licensing 83/12/27, FALLADINO, N J, GILINIKY, V, ROBERTS, T Commissioners 6pp, 21726 260 24X
Fiche 50-000, 83/12/27, 8312120101

8401090199 Forwards Certificate of Svc re Amend 52 to amended & substituted application for DL
HATHAWAY, O M Detroit Edison Co 83/12/29 Office of Nuclear Reactor Regulation, Director 3pp 21750, 327 24X
Fiche 50-341, 83/12/29, 8401090199

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
ETSENHUT, D O Division of Licensing, 84/01/05 Consolidated Edison Co of New York, Inc 16pp, 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

DOCKETED ITEMS

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT, D. O. Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc. 18pp. 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl.
EISENHUT, D. O. Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc. 18pp. 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401230394 Submits addl info re harsh environ safety-related electrical equipment, per NRC request. Info includes evaluation of FSAR Chapter 15 re DBE & NUREG-0737 & NUREG-0598 associated equipment
TAUBER, H. Detroit Edison Co. 84/01/16 YOUNGBLOOD, B. J. Licensing Branch 1 37pp. 21879 082 24X Fiche 50-341, 84/01/16, 8401230394

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing 1p 22000 349. 24X Fiche 50-000, 84/01/17, 8401270536

F Security, medical, emergency & fire protection plans

8401190247 Forwards updated proposed safeguards license condition & updated SER input resulting from review of complete rev to security plans
MIRACIA, F. J. Assistant Director for Safety Assessment 83/12/30
NOVAK, T. M. Assistant Director for Licensing. 1p 21870 162 24X
Fiche 50-341, 83/12/30, 8401190247

8401230417 Advises that FEMA will host 840112 & 13 radiological emergency preparedness program meetings in Chicago, IL. Emergency preparedness & prompt alert & notification certification schedules will be developed
PAPERIELLO, C. J. Region 3, Office of Director 84/01/05. WELLS, D. A. Detroit Edison Co. 3pp 21890 359 24X Fiche 50-341, 84/01/05, 8401230417

8401310319 Responds to NRC 831207 ltr re qualifications of WV Lipton, radiation protection manager WV Lipton qualifications, educ & experience fully comply w/guidelines of Reg Guide 1.8 Resume encl
JENB, W. H. Detroit Edison Co. 84/01/19 YOUNGBLOOD, B. J. Licensing Branch 1 4pp. 22026, 333. 24X Fiche 50-341, 84/01/19, 8401310319

8401300371 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 84/01/26 Document Management Branch. 1p. 22004-001 24X Fiche 50-341, 84/01/26, 8401300371.

--8401300376 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-101 re classification of emergencies, EP-102 re unusual event & EP-103 re alert
JENB, W. H. Detroit Edison Co. 84/01/16 YOUNGBLOOD, B. J. Licensing Branch 1 2pp 22004 002. 24X Fiche 50-341, 84/01/16, 8401300371.

--8401300381 Public version of revised emergency plan implementing procedures, including Procedures EP-101 re classification of emergencies, EP-102 re unusual event & EP-103 re alert.
RANDAZZO, T. Detroit Edison Co. 83/12/01 379pp. 22004-004 24X
Fiche 50-341, 84/01/26, 8401300371.

J Insurance & indemnity information

8401060255 Forwards MAELU & NELIA Secondary Financial Protection Certificates N-94 & N-94, respectively.
HATHAWAY, G. H. Detroit Edison Co. 84/01/03 DINITZ, I. Office of Nuclear Reactor Regulation, Director. 13pp. 21741, 044. 24X
Fiche: 50-341, 84/01/03, 8401060255

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J. M. Division of Rules and Records. 83/10/20. ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge 1p. 21744 003. 24X
Fiche: 50-000, 83/10/20, 8401060040.

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8312190222 Ack receipt of 831201 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-21
SPESSARD, R. L. Region 3, Office of Director 83/12/09 WELLS, D. A. Detroit Edison Co. 1p 21561 347 24X Fiche 50-341, 83/12/09, 8312190222

--8312190225 Responds to NRC 831021 ltr re violations noted in IE Insp Rept 50-341/83-21 Corrective actions generic retesting on Charger 2A1-1 will be performed by 831230 Maint instruction revised to include balancing
WELLS, D. A. Detroit Edison Co. 83/12/01 SPESSARD, R. L. Region 3, Office of Director 7pp 21561 348 24X Fiche 50-341, 83/12/09, 8312190222

8401100001 Forwards IE Insp Rept 50-341/83-29 on 831001-1130 & notice of violation
KNOPF, R. C. Region 3, Office of Director 83/12/22 WELLS, D. A. Detroit Edison Co. 2pp 21761 210 24X Fiche 50-341, 83/12/22, 8401100001

--8401100003 Notice of violation from Insp on 831001-1130.
KNOPF, R. C. Region 3, Office of Director 83/12/22 2pp 21761 212 24X Fiche 50-341, 83/12/22, 8401100001

--8401100005 IE Insp Rept 50-341/83-29 on 831001-1130 Noncompliance noted use of inactive QA procedure, failure to mark area designated for storage & inadequate drainage in storage areas
BYRON, P. M., PARKER, M. E., KONKLIN, J. E. Region 3, Office of Director 83/12/19 11pp. 21761 214 24X Fiche 50-341, 83/12/22, 8401100001

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUN, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp. 21731:166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401160267 Ack receipt of 840103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-25
STREETER, J. F. Division of Engineering 84/01/12 WELLS, D. A. Detroit Edison Co. 1p. 21813 303 24X Fiche 50-341, 84/01/12, 8401160267

--8401160271 Responds to NRC 831202 re violations noted in IE Insp Rept 50-341/83-25 Corrective actions test change notice will be issued to PRET C3202 001 to perform required testing of remote shutdown panel & reactor pressure indication
JENB, W. H. Detroit Edison Co. 84/01/03 STREETER, J. F. Division of Engineering 3pp 21813 306 24X Fiche 50-341, 84/01/12, 8401160267.

8401160274 Ack receipt of 831219 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-20
NORELUS, C. E. Division of Project & Resident Programs 84/01/12 WELLS, D. A. Detroit Edison Co. 1p 21813 315 24X
Fiche: 50-341, 84/01/12, 8401160274

--8401160277 Responds to NRC 831104 ltr re violations noted in IE Insp Rept 50-341/83-20 Corrective actions three procedures re mail control/warehousing & actions taken by procurement QA regarding receiving insp revised
WELLS, D. A. Detroit Edison Co. 83/12/19. NORELUS, C. E. Division of Project & Resident Programs 31pp 21813:316 24X
Fiche: 50-341, 84/01/12, 8401160274

DOCKETED ITEMS

211

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401300301 Responds to violations noted in IE Insp Rept 50-341/83-29
Corrective actions nuclear operations interfacing Procedure
11 000 02, "Updating Part V of POM Index" written &
includes controls to assure listed info correct
WELLS, D A Detroit Edison Co 84/01/23 KNDP, R C Division of
Project & Resident Programs 6pp 21996 346 24X
Fiche 50-341, 84/01/23, 8401300301

S Reportable occurrences, LERs & related correspondence

8401050450 Interim deficiency rept, Item 87, re possible ITE circuit
breaker failures Initially reported on 830304 Replacement
solid state trip devices received Mod request issued to
allow work on replacements Work will be completed June 1984
WELLS, D A Detroit Edison Co 83/12/16 KEPLER, J O Region 3,
Office of Director 3pp 21730 137 24X Fiche 50-341, 83/12/16,
8401050450

8401050405 Interim deficiency rept, Item 61 re undersized battery cables
used w/motor operated valves & switchgear Initially reported
on 830312 Sixty-four design change notices issued to make
necessary changes to cables
WELLS, D A Detroit Edison Co 83/12/22 KEPLER, J O Region 3,
Office of Director 2pp 21731 128 24X Fiche 50-341, 83/12/22,
8401050405

8401050409 Interim deficiency rept, Item 91 re ITE 4,160-volt breaker
puffer piston shaft possibly developing cracks Initially
reported on 830321 Replacement shafts will be installed upon
receipt
WELLS, D A Detroit Edison Co 83/12/22 KEPLER, J O Region 3,
Office of Director 2pp 21731 131 24X Fiche 50-341, 83/12/22,
8401050409

8401050625 Interim Deficiency Rept 107 re RHR pump B & D impellers
w/linear indications, set screws for wear rings in pump bowl
missing & excessive wear on wear rings & hydrostatic bearing
wear ring Initially reported on 831121 GE analysis underway
WELLS, D A Detroit Edison Co, 83/12/22 KEPLER, J O Region 3,
Office of Director 2pp 21726 103 24X Fiche 50-341, 83/12/22,
8401050625

8401300298 Interim deficiency rept, Item 108 re RHR 4,160-volt
switchgear installation records Initially reported on
831216 Latest design drawings depicting installation
configuration will be reviewed against installation records
WELLS, D A Detroit Edison Co 84/01/16 KEPLER, J O Region 3,
Office of Director 3pp 21996 354 24X Fiche 50-341, 84/01/16,
8401300298

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency
operation facilities Forwards App B documents App A & B
documents available in PDR App C documents entirely withheld
(ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X
Fiche 50-000, 83/11/02, 8401250163

--8304020457 Requests Commission review NRC disapproval of primary
emergency operations facility w/no habitability features
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-199 83/05/20 7pp 21958 183 24X
Fiche 50-000, 83/11/02, 8401250163

--8401250192 Notifies that emergency operations facility for plant paper
(SECY-83-199) before Commission as negative consent paper
Agrees w/NRC disapproval of license proposal
ABSELYTINE, J K Commissioners. 83/06/07 CHILK, S J Office of
the Secretary of the Commission 1p 21958 015 24X
Fiche 50-000, 83/11/02, 8401250163

8401040565 Forwards evaluation of Amend 3 to radiological emergency
plan Actions taken to resolve deficiencies requested within
30 days
NORDERHAUO, L R Region 3, Office of Director 83/12/28
WITHERS, B D Portland General Electric Co 21pp 21707 250 24X
Fiche 50-344, 83/12/28, 8401040565

8401050035 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21732 346 24X Fiche 50-344, 83/12/28,
8401050035

--8401050050 Forwards public version of revised Emergency Plan
Implementing Procedures EP-B 22, "Emergency Operations
Facility Security Representative" & EP-9, "Operation of
Operational Support Ctrs "
PUZEY, A M Portland General Electric Co 83/12/12 CLARK, R A
Office of Nuclear Reactor Regulation, Director 2pp 21732 347
24X Fiche 50-344, 83/12/28, 8401050035

--8401050058 Public version of revised Emergency Plan Implementing
Procedures EP-B 22, "Emergency Operations Facility Security
Representative" & EP-9, "Operation of Operational Support
Ctrs "
* Portland General Electric Co 83/12/02 14pp 21732 350 24X
Fiche 50-344, 83/12/28, 8401050035

8401180061 Forwards addendum to 831005, "Exercise of Offsite
Radiological Emergency Preparedness Plans " All deficiencies
resolved but one Addendum showing status of deficiencies in
four past joint exercises encl
KRIMM, R W Federal Emergency Management Agency 84/01/06,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 21842 070 24X Fiche 50-344, 84/01/06,
8401180061

--8401180071 Addendum to 831005, "Exercise of Offsite Radiological
Emergency Preparedness Plans " Status of deficiencies for
four past joint exercises encl
* Federal Emergency Management Agency 83/11/08 12pp
21842 071. 24X Fiche 50-344, 84/01/06, 8401180061

8401240495 Forwards Rev 7 to physical security plan Rev withheld
(ref 10CFR73 21)
WITHERS, B D Portland General Electric Co 84/01/12, MARTIN, J B
Region 3, Office of Director 2pp 21907 344 24X
Fiche 50-344, 84/01/12, 8401240495

G Adjudicatory correspondence

840110234 Petition of State of OR Energy Facility Siting Council & OR
DOE for leave to intervene & request for hearing re addl
spent fuel storage Certificate of Svc encl
PERRY, W Oregon, State of 84/01/04 Commissioners. 3pp,
21780 304 24X Fiche 50-344, 84/01/04, 840110234.

8401100197 Request for hearing & petition for leave to intervene re
util 830801 & 1031 requests for amend to License NPF-1 to
increase storage capacity of spent fuel pool & to increase
authorized enrichment of fuel Certificate of Svc encl
ROSLIE, E Coalition for Safe Power, 84/01/05 Commissioners
9pp 21760 332 24X Fiche 50-344, 84/01/05, 8401100197

840110211 Notice of ASLB constitution IW Smith, Chairman & RA Morris &
OH Paris, members
COTTER, D P Atomic Safety and Licensing Board Panel. 84/01/09
2pp 21772 358 24X Fiche 50-344, 84/01/09, 840110211

8401240306 Response to Coalition for Safe Power request for hearing &
petition for leave to intervene Ruling should be withheld
until at least one sufficient contention is submitted
JOHNSON, R W Portland General Electric Co 84/01/20 Atomic
Safety and Licensing Board Panel 2pp 21909 231 24X
Fiche 50-344, 84/01/20, 8401240306

--8401240310 Response to State of OR request for hearing & petition for
leave to intervene State has standing to participate in
hearing Certificate of Svc & notice of appearance encl
JOHNSON, R W Portland General Electric Co 84/01/20 Atomic
Safety and Licensing Board Panel. 4pp 21909 233 24X
Fiche 50-344, 84/01/20, 8401240306

P Operating license stage documents & correspondence

8401050027 FOIA request for info re whether facilities rated for
earthquakes by Lloyd's of London or other rating agencies
Supporting ltrs encl
CALSDYAS, C D Affiliation Unknown 83/10/10 NRC - No Detailed
Affiliation Given 4pp 21736 232 24X Fiche 50-000, 83/10/10,
8401050027

DOCKETED ITEMS

B401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies. NRC has no records subj to request Utilis not required to submit insurance ratings to NRC
 FELTON, J. M. Division of Rules and Records 83/10/25 CALSOYAS, C. D.
 Affiliation Unknown 1p. 21736 236 24X Fiche 50-000, 83/10/25, 8401050043

B40110196 Forwards Amend B4 to License NPF-1 & safety evaluation Amend changes offsite & onsite organization charts in Tech Specs
 TRAMMELL, C. M. Operating Reactors Branch 3 83/12/27 WITHERS, B. D.
 Portland General Electric Co. 2pp 21795 117 24X
 Fiche 50-344, 83/12/27, 840110196

--B40110198 Amend B4 to License NPF-1, changing offsite & onsite organization charts in Tech Specs
 MILLER, J. R. Operating Reactors Branch 3 83/12/27 5pp
 21779 119 24X Fiche 50-344, 83/12/27, 840110198

--B40110201 Safety evaluation supporting Amend B4 to License NPF-1
 * Office of Nuclear Reactor Regulation, Director 83/12/27 2pp
 21795 124 24X Fiche 50-344, 83/12/27, 840110196

B401030106 License Change Application 97 for amend to License NPF-1, permitting qualified individuals to function in dual role of senior reactor operator & shift technical advisor
 WITHERS, B. D. Portland General Electric Co. 83/12/28 MILLER, J. R.
 Operating Reactors Branch 3 7pp 21683: 117 24X
 Fiche: 50-344, 83/12/28, 8401030106

--B401030113 Proposed Tech Spec Table 6 2-1, "Min Shift Crew Composition."
 * Portland General Electric Co. 83/12/28 1p. 21683. 124 24X
 Fiche 50-344, 83/12/28, 8401030106.

B401040587 Discusses 831129 request to extend implementation schedule for NUREG-0737, Items II.F.1.1 & II.F.1.2 from 831231 until startup from 1984 refueling outage. Interim procedures described in 800102 & 0423 ltrs remain in effect.
 WITHERS, B. D. Portland General Electric Co. 83/12/29 EISENHUT, D. O.
 Division of Licensing 2pp. 21705 355 24X Fiche 50-344, 83/12/29, 8401040587.

B401190112 Notification of 840327 meeting w/util in Bethesda, MD to discuss all outstanding equipment qualification issues.
 TRAMMELL, C. M. Operating Reactors Branch 3 83/12/29 MILLER, J. R.
 Operating Reactors Branch 3 2pp. 21871. 040 24X
 Fiche: 50-344, 83/12/29, 8401190112

B401050530 Forwards responses to request for addl info re proposed spent fuel storage capacity increase. Affidavit encl.
 Proprietary calculations withheld
 WITHERS, B. D. Portland General Electric Co. 83/12/30 MILLER, J. R.
 Operating Reactors Branch 3 4pp 21725. 255 24X
 Fiche: 50-344, 83/12/30, 8401050530

B401190128 Forwards safety evaluation re TMI Action Item II K 2 17, "Voiding in RCS." Item resolved
 MILLER, J. R. Operating Reactors Branch 3 84/01/03 WITHERS, B. D.
 Portland General Electric Co. 3pp. 21870 001 24X
 Fiche: 50-344, 84/01/03, 8401190128

B401190145 Requests remittance of Class III fee for review of 830524 application issued as Amend B4 to License NPF-1 re entering Mode 2 & 3 for testing pressurizer safety valve & MBIVs
 DIOGUE, R. M. License Fee Management Branch. 84/01/04 WITHERS, B. D.
 Portland General Electric Co. 1p 21871:009 24X
 Fiche: 50-344, 84/01/04, 8401190145.

B401060382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl.
 EISENHUT, D. O. Division of Licensing 84/01/05 Consolidated
 Edison Co. of New York, Inc. 18pp. 21946: 190 24X
 Fiche: 50-000, 84/01/05, 8401060382

B401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing.
 Svc list encl.
 EISENHUT, D. O. Division of Licensing. 84/01/06 Consolidated
 Edison Co. of New York, Inc. 18pp. 21957: 267. 24X
 Fiche: 50-000, 84/01/06, 8401090221.

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues."
 Svc list encl.
 EISENHUT, D. O. Division of Licensing. 84/01/13 Consolidated
 Edison Co. of New York, Inc. 18pp. 21946: 174. 24X
 Fiche: 50-000, 84/01/13, 8401130084.

B401240118 Informs that addl mods & heavy loads procedure revs required, per 820122 ltr Redundant upper travel limit switch installation on main & auxiliary hooks for turbine & fuel bldgs & containment polar cranes completed per NUREG-0612
 WITHERS, B. D. Portland General Electric Co. 84/01/18 EISENHUT, D. O.
 Division of Licensing. 1p 21912 287 24X Fiche 50-344, 84/01/18, 8401240118

B401240144 Forwards response to 831110 request for addl info re flow testing for spray additive tank in order to complete review of License Change Application 95 Check valve 2-QCB-9 flow tested as part of inservice testing program
 WITHERS, B. D. Portland General Electric Co. 84/01/18 MILLER, J. R.
 Operating Reactors Branch 3 3pp 21910 276 24X
 Fiche 50-344, 84/01/18, 8401240144

B401270431 Forwards Application 98 for amend to License NPF-1, revising boron concentration requirements for boron injection tank
 WITHERS, B. D. Portland General Electric Co. 84/01/23 MILLER, J. R.
 Operating Reactors Branch 3 1p 21980 328 24X
 Fiche: 50-344, 84/01/23, 8401270431

--B401270434 Application 98 for amend to License NPF-1, revising boron concentration requirements for boron injection tank
 WITHERS, B. D. Portland General Electric Co. 84/01/23 8pp
 21980 329 24X Fiche 50-344, 84/01/23, 8401270431

--B401270437 Proposed Tech Spec 3/4 5 4, revising boron concentration requirements for boron injection tank
 * Portland General Electric Co. 84/01/23 3pp 21980 337 24X
 Fiche 50-344, 84/01/23, 8401270431

B401270346 Forwards Rev O to Procedure 12-1-B3, "Purge & Vent Valve Operability Qualification Analysis." New hydrogen vent valves will be installed during forthcoming refueling outage
 WITHERS, B. D. Portland General Electric Co. 84/01/24 MILLER, J. R.
 Operating Reactors Branch 3 1p 21975 137 24X
 Fiche 50-344, 84/01/24, 8401270346

--B401270350 Rev O to Procedure 12-1-B3, "Purge & Vent Valve Operability Qualification Analysis."
 NONDAHL, S. M., KRUEGER, J. E. CLOW Corp. 83/12/30 117pp.
 21975 138 24X Fiche: 50-344, 84/01/24, 8401270346

B401310087 Forwards Change Application 99 to License NPF-1, revising reactor vessel matl irradiation surveillance schedule to include addl containment isolation valves & revising refs to peak containment pressures
 WITHERS, B. D. Portland General Electric Co. 84/01/27 MILLER, J. R.
 Operating Reactors Branch 3 1p 22022 001 24X
 Fiche: 50-344, 84/01/27, 8401310087

--B401310093 Change Application 99 to License NPF-1, revising reactor vessel matl irradiation surveillance schedules to include addl containment isolation valves & revising refs to peak containment pressures
 WITHERS, B. D. Portland General Electric Co. 84/01/27. 11pp
 22022. 002 24X Fiche: 50-344, 84/01/27, 8401310087

--B401310097 Proposed Tech Specs revising reactor vessel matl irradiation surveillance schedules to include addl containment isolation valves & revising refs to peak containment pressures
 * Portland General Electric Co. 84/01/27 7pp 22022 013 24X
 Fiche: 50-344, 84/01/27, 8401310087

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info
 Notebook also available in PDR
 FELTON, J. M. Division of Rules and Records 83/10/20 ZAHLER, R. E.
 Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
 Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of BALP results during 1982
 * Director's Office, Office of Inspection and Enforcement.
 83/10/20. 134pp 21744: 004 24X Fiche 50-000, 83/10/20, 8401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co. of New York, Inc.
 124pp 21731. 166. 24X Fiche 50-000, 83/12/28, B312120090.

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc.
 127pp. 21826 040. 24X Fiche: 50-000, 83/12/30, B312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8401310441 Replies to allegation that member of insp team lacked objectivity in discovery of deficiency, as alleged in 831028 response to notice of violation & proposed imposition of civil penalty. Allegation unsubstantiated.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/17 WITHERS, B D Portland General Electric Co
Ip 22036 339 24X Fiche 50-344,84/01/17,8401310441

--8401310445 Responds to concerns presented in util 831028 response to notice of violation. No specific action cited by util as evidence of lack of objectivity.
WHITNEY, L E Division of QA, Safeguards & Inspection Programs (Post 830103) 83/11/29 PARTLOW, J Q Division of QA, Safeguards & Inspection Programs (Post 830103) 3pp 22036 340 24X Fiche 50-344,84/01/17,8401310441

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401240392 Informs of intention to revert to requirements of 1974 edition of ASME Boiler & Pressure Vessel Code (w/Summer 1975 addenda) for conducting sys pressure tests since relief from using VT-2 qualified examiners not granted.
WITHERS, B D Portland General Electric Co 84/01/18 MILLER, J R Operating Reactors Branch 3 2pp 21907 361 24X Fiche: 50-344,84/01/18,8401240392

R Periodic operating reports & related correspondence

8401120416 Monthly operating rept for Nov 1983 W/831209 1tr
HAMMEYER, D J, YUNDT, C P Portland General Electric Co 83/11/30
Office of Resource Management, Director 6pp 21791 168 24X Fiche: 50-344,83/11/30,8401120416

8401270476 Monthly operating rept for Dec 1983 W/840109 1tr
NICHOLSON, W O, YUNDT, C P Portland General Electric Co 83/12/31
Office of Resource Management, Director 6pp 21981 307 24X Fiche: 50-344,83/12/31,8401270476

S Reportable occurrences, LERs & related correspondence

8401120321 LER 83-018/03L-O, on 831126, reactor coolant drain tank outlet containment isolation valve CV-4006 did not close within 10 s. Caused by slow depressurization through air solenoid valve operating mechanism W/831222 1tr
BAIR, G O, YUNDT, C P Portland General Electric Co. 83/12/22
MARTIN, J B Region 3, Office of Director 3pp 21792 137 24X Fiche: 50-344,83/12/22,8401120321

8401120408 LER 83-017/03L-O, on 831123, during audit of plant operational test records, found that Periodic Operating Test POT-2-3DB not run for Aug 1983. Caused by personnel error in computer scheduling. Personnel advised of procedures. W/831222 1tr.
BAIR, G O, YUNDT, C P Portland General Electric Co 83/12/22
MARTIN, J B Region 3, Office of Director 3pp 21791 138 24X Fiche 50-344,83/12/22,8401120408

8401140252 LER 83-020/03L-O, on 831207, train A RHR pump failed to restart from control room, resulting in operation w/less than min number of operable pumps. Caused by loose mounting bolts on circuit breaker position switch W/840105 1tr.
BAIR, G O, YUNDT, C P Portland General Electric Co. 84/01/05
MARTIN, J B Region 3, Office of Director, 3pp. 21814.201 24X Fiche 50-344,84/01/05,8401140252

8401160304 LER 83-019/03L-O on 831208, containment spray containment isolation valve MD-2053A & sodium hydroxide spray additive valve MD-2056A failed to meet inservice testing valve travel time criteria W/840105 1tr
BAIR, G O, YUNDT, C P Portland General Electric Co 84/01/05
MARTIN, J B Region 3, Office of Director 3pp 21814 078 24X Fiche 50-344,84/01/05,8401160304

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities. Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21937 357 24X Fiche 50-000,83/11/02,8401250163

--8306030404 Requests Commission review approval for exception to location of backup emergency operations facility beyond 20 miles from plant.
DIRKSB, W J, Office of the Executive Director for Operations, BECY-83-191, 83/05/18 8pp. 21938 105 24X Fiche: 50-000,83/11/02,8401250163

8401050121 Releases public version of Rev 194 to emergency plan supporting procedures rev index
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21743 276 24X Fiche 50-346,83/12/28,8401050121

--8401050126 Public version of Rev 194 to emergency plan supporting procedures rev index W/831129 1tr & receipt form.
* Toledo Edison Co 83/11/30 NRC - No Detailed Affiliation Given. 3pp 21743 277 24X Fiche 50-346,83/12/28,8401050121

8401060082 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21747 131 24X Fiche 50-346,83/12/28,8401060082

--8401060086 Forwards public version of revised emergency plan implementing procedures, including Procedures EI 1300 00 re station response to emergencies, EI 1300 02 re unusual event & EI 1300 03 re alert
* Toledo Edison Co. 83/12/02 NRC - No Detailed Affiliation Given 1p 21747 132 24X Fiche 50-346,83/12/28,8401060082

8401060091 Public version of revised emergency plan implementing procedures, including Procedures EI 1300 00 re station response to emergencies, EI 1300 02 re unusual event & EI 1300 03 re alert.
REED, G J, WELLS, C E, MURRAY, T D Toledo Edison Co. 83/11/30 67pp 21747 133 24X Fiche: 50-346,83/12/28,8401060082

8401050275 Forwards calculation performed in support of 830930 App R to 10CFR50 exemption request. Evaluation simulated fire test requirements of NFPA 251 & demonstrated ability of door to withstand 25 minute fire.
CROUSE, R P Toledo Edison Co 83/12/30 STOLZ, J F Operating Reactors Branch 4 6pp 21727 175 24X Fiche: 50-346,83/12/30,8401050275

8401160013 Confirms understanding reached at 831208 meeting re proposed schedules for resolution of issues identified during 830725-28 App R fire protection audit. Proposed schedules acceptable
STOLZ, J F Operating Reactors Branch 4. 84/01/03 CROUSE, R P Toledo Edison Co 2pp 21821 357 24X Fiche 50-346,84/01/03,8401160013

8401190100 Notification of 840125 meeting w/util in Bethesda, MD to discuss progress & adequacy of licensee approach to resolve Tasks 1-8 of 830725-28 App R fire protection audit.
DEAGAZIO, A Operating Reactors Branch 4 84/01/04 STOLZ, J F Operating Reactors Branch 4. 2pp 21870 237 24X Fiche 50-346,84/01/04,8401190100

8401230129 Notifies of FEMA radiological emergency preparedness 840112-13 program meetings at Ramada Inn, O'Hare Motel to develop Final FY84/85 emergency preparedness exercise & prompt alert & notification certification schedules.
PAPERIELLO, G J, Region 3, Office of Director 84/01/05
CROUSE, R P, Toledo Edison Co. 3pp 21877 359 24X Fiche: 50-346,84/01/05,8401230129

DOCKETED ITEMS

B401230035 Forwards Amend 65 to License NPF-3 & safety evaluation Amend modifies Tech Spec 3.7.10 re fire barrier penetrations to be consistent w/current Tech Specs for B&W plants
DEAGAZIO, A.W. Operating Reactors Branch 4 84/01/12 CROUSE, R.D. Toledo Edison Co. 3pp 21930 350 24X Fiche 50-346, 84/01/12, 8401230035

--B401230040 Amend 65 to License NPF-3, modifying Tech Spec 3.7.10 re fire barrier penetrations to be consistent w/current Tech Specs for B&W plants
STOLZ, J.F. Operating Reactors Branch 4 84/01/12 6pp 21930-353 24X Fiche 50-346, 84/01/12, 8401230035

--B401230045 Safety evaluation supporting Amend 65 to License NPF-3
* Office of Nuclear Reactor Regulation, Director. 84/01/12 2pp 21930-359 24X Fiche 50-346, 84/01/12, 8401230035

B401230650 Releases public version of rev to emergency plan
FELTON, J.M. Division of Rules and Records 84/01/18 Document Management Branch 1p 21926 304 24X Fiche 50-346, 84/01/18, 8401230650.

--B401230654 Public version of Rev 7 to emergency plan. W/831209 transmittal sheet
MURRAY, T.D. Toledo Edison Co. 83/11/30. Region 3, Office of Director. 318pp 21926-306 24X Fiche 50-346, 84/01/18, 8401230650

B401250014 Releases public version of revised emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records 84/01/18 Document Management Branch 1p 21948 104 24X Fiche 50-346, 84/01/18, 8401250014

--B401250018 Public version of Rev 15 to Emergency Plan Implementing Procedure HP 1602.01, "External Personnel Radiation Exposure Monitoring." W/831221 ltr, receipt form & Rev 15 to index.
MURRAY, T.D. Toledo Edison Co. 83/12/08 NRC - No Detailed Affiliation Given 15pp 21948-105 24X Fiche 50-346, 84/01/18, 8401250014.

B401260376 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records 84/01/18. Document Management Branch 1p. 21992 186 24X Fiche 50-346, 84/01/18, 8401260376

--B401260379 Forwards public version of revised emergency plan implementing procedures, including Procedures EI 1300.01 re emergency plan activation, EI 1300.04 re site area emergency & EI 1300.05 re general emergency. Receipt form encl.
* Toledo Edison Co. 83/12/15. NRC - No Detailed Affiliation Given. 1p 21992:187 24X Fiche 50-346, 84/01/18, 8401260376.

--B401260384 Public version of revised emergency plan implementing procedures, including Procedures EI 1300.01 re emergency plan activation, EI 1300.04 re site area emergency & EI 1300.05 re general emergency.
REED, D.J., WELLS, C.E., BEYER, B.R. Toledo Edison Co. 83/12/02 112pp 21992:188 24X Fiche 50-346, 84/01/18, 8401260376.

B401310065 Releases public version of temporary change to emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records 84/01/18 Document Management Branch 1p 22028 357 24X Fiche 50-346, 84/01/18, 8401310065

--B401310070 Public version of Temporary Change T-7553 to Emergency Plan Implementing Procedure EI 1300.04, "Operations Support Ctr Activation." W/831103 ltr & Rev 33 to rev index
MURRAY, T.D., DOWNING, Q. Toledo Edison Co. 83/11/30 NRC - No Detailed Affiliation Given. 3pp 22028-360 24X Fiche 50-346, 84/01/18, 8401310065.

B401240649 Releases public version of revised emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records 84/01/20. Document Management Branch 1p. 21948-168 24X Fiche 50-346, 84/01/20, 8401240649.

--B401240650 Public version of revised Emergency Plan Implementing Procedure HP-1602.01, "External Personnel Radiation Exposure Monitoring."
* Toledo Edison Co. 83/12/08. 26pp. 21948:169. 24X Fiche 50-346, 84/01/20, 8401240649.

B401260229 Releases public version of rev to emergency plan supporting procedures rev index
FELTON, J.M. Division of Rules and Records 84/01/20 Document Management Branch 1p. 21982-357 24X Fiche 50-346, 84/01/20, 8401260229.

--B401260233 Public version of Rev 197 to emergency plan supporting procedures rev index W/831228 transmittal & receipt form
* Toledo Edison Co. 83/12/31 2pp 21982 358 24X Fiche 50-346, 84/01/20, 8401260229

B401300330 Releases public version of emergency plan supporting procedures
FELTON, J.M. Division of Rules and Records 84/01/25 Document Management Branch 1p. 22005 300 24X Fiche 50-346, 84/01/25, 8401300330

--B401300333 Public version of Rev 30 to Administrative Memo 41, "Emergency Duty Officer & Other Emergency Duties" & Rev 3 to Administrative Procedure AD 1827 04, "Overexposure/Internal Contamination."
DOVEL, C.J., GREEN, W., BRIDEN, D.W. Toledo Edison Co. 84/01/06 NRC - No Detailed Affiliation Given 13pp 22005 301 24X Fiche 50-346, 84/01/25, 8401300330

J Insurance & indemnity information

B401060242 Forwards Endorsements 45-46 & 35-36 to NELIA & MAELU Policies NF-235 & MF-92, respectively Also forwards Endorsement 4 to NELIA Certificate N-61 & MAELU Certificate M-61
GOLDEN, M.P. Marsh & McLennan, Inc. 83/12/23 SALTZMAN, J. Assistant Director for State & Licensee Relations 7pp 21740-132 24X Fiche 50-346, 83/12/23, 8401060242

P Operating license stage documents & correspondence

B401040138 Clarifies NRC views on general structure of regulatory enhancement program Meeting will be held in Jan 1984 to discuss program.
NORELIUS, C.E. Division of Project & Resident Programs 83/12/23 CROUSE, R.P. Toledo Edison Co. 2pp 21702 359 24X Fiche 50-346, 83/12/23, 8401040138.

B401040566 Addresses 10CFR61 program implementation status. Gamma spectroscopy will be used to measure certain radionuclides to which scaling factors will be applied to quantify radionuclides not directly measured
CROUSE, R.P. Toledo Edison Co. 83/12/27 STOLZ, J.F. Operating Reactors Branch 4 1p. 21707 361 24X Fiche 50-346, 83/12/27, 8401040566

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D.O. Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc. 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D.O. Division of Licensing 84/01/06 Consolidated Edison Co. of New York, Inc. 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

B401120346 Confirms B40110 meeting in Glen Ellyn, IL to discuss proposed comprehensive enhancement program.
NORELIUS, C.E. Division of Project & Resident Programs 84/01/06 CROUSE, R. Toledo Edison Co. 1p 21792 175 24X Fiche 50-346, 84/01/06, 8401120346

B401130343 Summary of 831213 meeting w/NRR & util in Bethesda, MD re remaining deficiencies in Franklin Research Ctr technical evaluation re equipment qualification agenda Justifications for continued operation reviewed
GAUTAM, A.S. Region 3, Office of Director 84/01/06 WILLIAMS, C.O. Region 3, Office of Director. 26pp 21798 241 24X Fiche 50-346, 84/01/06, 8401130343

B401230483 Responds to Generic Ltr 83-41 re fast cold start surveillance testing of diesel generators Tech Specs require surveillance testing 13 times per yr.
CROUSE, R.P. Toledo Edison Co. 84/01/11 EISENHUT, D.O. Division of Licensing 2pp. 21882-163 24X Fiche 50-346, 84/01/11, 8401230483

B401230035 Forwards Amend 65 to License NPF-3 & safety evaluation. Amend modifies Tech Spec 3.7.10 re fire barrier penetrations to be consistent w/current Tech Specs for B&W plants
DEAGAZIO, A.W. Operating Reactors Branch 4 84/01/12 CROUSE, R.D. Toledo Edison Co. 3pp 21930 350 24X Fiche 50-346, 84/01/12, 8401230035

--B401230040 Amend 65 to License NPF-3, modifying Tech Spec 3.7.10 re fire barrier penetrations to be consistent w/current Tech Specs for B&W plants.
STOLZ, J.F. Operating Reactors Branch 4 84/01/12 6pp 21930:353. 24X Fiche 50-346, 84/01/12, 8401230035

--8401230045 Safety evaluation supporting Amend 65 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 84/01/12 2pp
21930 359 24X Fiche 50-346,84/01/12,8401230035

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLS & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

8401270390 Forwards application for amend to License NPF-3 Amend
deletes requirement for containment recirculating fans
CROUSE, R P Toledo Edison Co 84/01/14 STOLZ, J F Operating
Reactors Branch 4 2pp 21981 046 24X Fiche 50-346,84/01/14,
8401270390

--8401270394 Application for amend to License NPF-3, deleting requirement
for containment recirculating fans SER encl
CROUSE, R P Toledo Edison Co 84/01/14 6pp 21981 048 24X
Fiche 50-346,84/01/14,8401270390

8401190331 Provides addl info supporting 840114 request for emergency
amend to License NPF-3, changing Tech Specs to delete
requirement for containment recirculation sys Reformatted
significant hazards consideration encl
CROUSE, R P Toledo Edison Co 84/01/17 STOLZ, J F Operating
Reactors Branch 4 6pp 21850 331 24X Fiche 50-346,84/01/17,
8401190331

8401270293 Forwards draft integrated living schedule program plan for
review Application for amend to License NPF-3 incorporating
plan will be submitted upon resolution of comments
CROUSE, R P Toledo Edison Co 84/01/20 STOLZ, J F Operating
Reactors Branch 4, 3pp 21978 308 24X Fiche 50-346,84/01/20,
8401270293

--8401270297 Draft integrated living schedule program plan
* Toledo Edison Co 84/01/20 14pp 21978 311 24X
Fiche 50-346,84/01/20,8401270293

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J W Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement.
83/10/20 105pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401190380 Forwards IE Insp Rept 50-346/83-20 on 830913-1118 & notices
of violation & deviation
SHAHER, W D Region 3, Office of Director 83/12/07 CROUSE, R P
Toledo Edison Co 2pp 21849 300 24X Fiche 50-346,83/12/07,
8401190380

--8401190381 Notice of violation from insp on 830913-1118.
SHAHER, W D Region 3, Office of Director, 83/12/07, 2pp.
21849.302 24X Fiche 50-346,83/12/07,8401190380

--8401190383 Notice of deviation from insp on 830913-1118.
SHAHER, W D, Region 3, Office of Director 83/12/07, 1p
21849.304 24X Fiche 50-346,83/12/07,8401190380

--8401190386 IE Insp Rept 50-346/83-20 on 830913-1118 Violations &
deviation noted, failure to rept inoperable safety sys, return
to operability procedures not met & drawings not updated
following work completion
ROGERS, W O., JORDAN, M., JACKMAN, N Region 3, Office of Director
83/12/07, 16pp, 21849 305 24X Fiche 50-346,83/12/07,8401190380.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and
Enforcement, 83/12/28, Consolidated Edison Co of New York, Inc
124pp, 21731 166 24X Fiche 50-000,83/12/28,8312120090.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/12/30 Consolidated Edison Co. of New
York, Inc 127pp, 21826.060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104.

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators" Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116.

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401240316 Ack receipt of 840113 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-346/83-19
SHAHER, W D Region 3, Office of Director 84/01/20 CROUSE, R P
Toledo Edison Co 1p 21920 354 24X Fiche 50-346,84/01/20,
8401240316

--8401240327 Responds to NRC 831216 ltr re violations noted in IE Insp
Rept 50-346/83-19 Corrective actions mgt level training
oversight committee established to monitor all QA
activities
CROUSE, R P Toledo Edison Co 84/01/13 NORELIUS, C.E Division
of Project & Resident Programs 3pp 21920 355 24X
Fiche 50-346,84/01/20,8401240316

8401240474 Ack receipt of 840104 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-346/83-20
SHAHER, W D Region 3, Office of Director 84/01/20, CROUSE, R P
Toledo Edison Co 1p 21907 314 24X Fiche 50-346,84/01/20,
8401240474.

--8401240479 Responds to NRC 831207 ltr re violations noted in IE Insp
Rept 50-346/83-20 Corrective actions temporary mod to
ST5031 04, containment radiation monitor input to safety
features actuation signal refueling period calibr, rewritten.
CROUSE, R P Toledo Edison Co 84/01/06 NORELIUS, C.E. Division
of Project & Resident Programs 4pp 21907.315 24X
Fiche 50-346,84/01/20,8401240474

R Periodic operating reports & related correspondence

8401120322 Monthly operating rept for Nov 1983 W/831209 ltr
BARBOUR, B., MURRAY, T.D. Toledo Edison Co 83/11/30 HALLER, N
Office of Resource Management, Director 6pp 21794 144 24X
Fiche 50-346,83/11/30,8401120322

8401170178 NPDEB discharge monitoring rept for Dec 1983 W/840111 ltr.
MURRAY, T D Toledo Edison Co 83/12/31 Ohio, State of. 10pp.
21834.142 24X Fiche 50-346,83/12/31,8401170178.

8401170196 Monthly operating rept for Dec 1983 W/840110 ltr.
BARBOUR, B., MURRAY, T.D. Toledo Edison Co. 83/12/31 HALLER, N
Division of Data Automation & Management Information, 24p
21831.294, 24X Fiche 50-346,83/12/31,8401170196

8401170205 "Wastewater Rept, Dec 1983." W/840111 ltr.
MURRAY, T D Toledo Edison Co. 83/12/31 Ohio, State of. 9pp
21831.328 24X Fiche 50-346,83/12/31,8401170205.

S Reportable occurrences, LERs & related correspondence

8401040390 LER 83-065/03L-0 on 831117, Channel 1 essential conduit
3B609A-1-1/2 inch inadequately supported for approx 30 ft
Caused by original const installation error. Addl supports
installed by 830909 W/831216 ltr
BONNER, N., MURRAY, T.D. Toledo Edison Co. 83/12/16. KEPPLER, J O.
Region 3, Office of Director 4pp 21708.058 24X
Fiche 50-346,83/12/16,8401040390

DOCKETED ITEMS

8401040317 LER 83-066/03L-0 on 831120, neutron flux detector power range NI-5 took step change in flux downward by 2X & imbalance changed from -4% to -14%, resulting in flux/delta flux/flow trip of reactor protection sys channel 2 W/831220 ltr. BLUNK, Q., MURRAY, T D Toledo Edison Co 83/12/20 KEPPLER, J Q Region 3, Office of Director 3pp 21708 149 24X Fiche 50-346, 83/12/20, 8401040317

8401040358 LER 83-066/03L-0 on 831124, operator discovered fire dampers 10B5, 10B4 & 1111 not monitored Caused by personnel error Personnel failed to rept for work resulting in lack of coverage Individual moved to central area W/831222 ltr EBERSOLE, R., MURRAY, T D Toledo Edison Co 83/12/22 KEPPLER, J Region 3, Office of Director 3pp 21706 133 24X Fiche 50-346, 83/12/22, 8401040358

8401060494 LER 83-068/03L-0 on 831129, rod 7-12 dropped to 0% withdrawn Asymmetrical condition caused integrated control sys to run back to 60% Caused by opening motor programmer phase Fuse CC Fuse replaced W/831229 ltr BHARTZ, J., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21740 183 24X Fiche 50-346, 83/12/29, 8401060494

8401060509 LER 83-069/03L-0 on 831130, Fire Barrier Doors 320, 321, 322, 323, 427, 428, 215, 601 & 603 identified as having non-upper level hardware attachments Caused by design/fabrication error Personnel reviewing corrective actions W/831229 ltr. HART, T., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21739 350 24X Fiche 50-346, 83/12/29, 8401060509

8401160227 Updated LER 83-067/03X-1 on 831124, discovered fire dampers 10B5, 10B4 & 1111 not continuously monitored Caused by lack of adequate personnel coverage Individual moved to area where all dampers can be seen W/831229 ltr EBERSOLE, R., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21813 108 24X Fiche 50-346, 83/12/29, 8401160227

8401160259 Revised LER 82-045/03X-2 on 820904 & 1203, operator observed auxiliary feedwater (AFW) pump 1-1 suction valve FW786 closed for no apparent reason Valve immediately reopened W/831229 ltr LONG, J W., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 4pp 21814 356 24X Fiche 50-346, 83/12/29, 8401160259

8401160299 Revised LER 83-053/03X-1 on 821018, alarm trip received on steam & feedwater rupture control sys channel 2 due to failure of steam generator instrument channel 2 power supply Failure caused power supply trip W/831229 ltr. YARGER, K., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21814 343 24X Fiche 50-346, 83/12/29, 8401160299

8401160325 Revised LER 83-018/03X-1 on 830417, safety features actuation sys channel 4 radiation monitor RE2007 read 0.15 mR/h Containment radiation monitor declared inoperable Caused by equipment failure Detector replaced W/831229 ltr. IBLEY, T., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21814 093 24X Fiche 50-346, 83/12/29, 8401160325

8401160330 Revised LER 81-061/03X-2 on 811003 & 20, absolute position indication on group 4, rod 7 became erratic, fluctuating 5-10% of full range Caused by loss of electrical penetration module signal Module replaced W/831229 ltr UEBBING, R., MURRAY, T D Toledo Edison Co 83/12/29 KEPPLER, J Q Region 3, Office of Director 3pp 21814 224 24X Fiche 50-346, 83/12/29, 8401160330

8401160338 Revised LER 83-057/03X-1 on 831015, auxiliary feedwater pump turbine 2 tripped immediately following start Caused by sticky linkage. Trip linkage cycling will be included w/ Surveillance Test ST 5071.04 W/831230 ltr. THOMPSON, T., MURRAY, T D Toledo Edison Co 83/12/30 KEPPLER, J Q Region 3, Office of Director 3pp 21813 283 24X Fiche 50-346, 83/12/30, 8401160338

8401130393 PNO-III-83-002 on 840108, reactor tripped automatically due to neutron flux imbalance in reactor core Caused by axial power shaping rods automatically inserting Reactor in hot shutdown until Region III concurs in resolution. JORDAN, M., JACKIN, I., SHAFFER, W. Region 3, Office of Director 84/01/10. 1p. 21798 341 24X Fiche 50-346, 84/01/10, 8401130393.

8401190331 LER 83-070/03L-0 on 831210, analysis of RCS sample indicated 0.20 ppm chloride, exceeding Tech Spec min Caused by purification demineralizer 1-1 being exhausted on chlorides Demineralizer 1-2 placed in svc W/840110 ltr BRIDEN, D. W., MURRAY, T D Toledo Edison Co 84/01/10 KEPPLER, J Q Region 3, Office of Director 4pp. 21851 259 24X Fiche 50-346, 84/01/10, 8401190331.

8401190406 LER 83-071/03L-0 on 831205, control room operators received sequence inhibit alarm & discovered diamond control panel in manual. Caused by fault in motor power return SCR gate drive circuit W/840110 ltr BHARTZ, J., MURRAY, T D Toledo Edison Co 84/01/10 KEPPLER, J Q Region 3, Office of Director 3pp 21850 098 24X Fiche 50-346, 84/01/10, 8401190406

8401270483 Revised LER 82-045/03X-3 on 820904 & 1203, auxiliary feedwater pump 1-1 suction valve FW786 closed for no apparent reason Cause Unknown Control circuit investigated Valve reopened LONG, J W., MURRAY, T D Toledo Edison Co 84/01/16 KEPPLER, J Q Region 3, Office of Director 4pp 21981 343 24X Fiche 50-346, 84/01/16, 8401270483

8401300009 LER 83-072/03L-0 on 831217, 120-volt ac essential bus V1, reactor protection sys channel 1 & safety features actuation sys channel 1 deenergized Caused by personnel error Personnel counseled W/840116 ltr RICHTER, L., MURRAY, T D Toledo Edison Co 84/01/16 KEPPLER, J Q Region 3, Office of Director 7pp 21999 233 24X Fiche 50-346, 84/01/16, 8401300009

8401300187 LER 83-073/03L-0 on 831219, containment air sample return valve CV9011E failed to close electrically Cause unknown Valve cycled three times smoothly w/normal running currents Operator & starter checked W/840118 ltr LONG, J W., MURRAY, T D Toledo Edison Co 84/01/18 KEPPLER, J Q Region 3, Office of Director 3pp 21997 346 24X Fiche 50-346, 84/01/18, 8401300187

8401300295 LER 83-074/03L-0 on 831224, operators received borated water storage tank high fail alarm for safety features actuation sys channel 1 Caused by improperly installed heat trace on transmitter piping Procedure modified W/840123 ltr IBLEY, T., MURRAY, T D Toledo Edison Co 84/01/24 KEPPLER, J Q Region 3, Office of Director 3pp 21996 357 24X Fiche 50-346, 84/01/24, 8401300295

V. Operator Examinations

8401270401 Advises that operator/senior operator licensing written exams scheduled for 840317 & oral exams scheduled for 840328 & 29. All listed info should be submitted 60 days prior to first exams. SPEBBARD, R L Division of Engineering 84/01/19 CROUSE, R P. Toledo Edison Co 4pp 21976 247 24X Fiche 50-346, 84/01/19, 8401270401

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8401050445 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 VERRELLI, D M Division of Project & Resident Programs 83/12/20 McDONALD, R P Alabama Power Co 1p 21730 214 24X Fiche 50-348, 83/12/20, 8401050445

--8401050448 Responds to NRC 830909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions, mgt directive issued reemphasizing that fire protection program reevaluation considered on same basis as FSAR CLAYTON, F L Alabama Power Co 83/12/09. VERRELLI, D M Division of Project & Resident Programs 67pp. 21730 215 24X Fiche 50-348, 83/12/20, 8401050448

8401060408 Forwards IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-18 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/12/21 McDONALD, R P Alabama Power Co 2pp 21741 083 24X Fiche 50-348, 83/12/21, 8401060408

--8401060410 IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-18. No noncompliance noted Major areas inspected: emergency preparedness. STODDART, P Q Region 2, Office of Director JENKINS, O R. Division of Emergency Preparedness & Materials Safety. 83/12/08 8pp. 21741 085 24X Fiche 50-348, 83/12/21, 8401060410

8401060436 Confirms 840112 mgt meeting w/util in Atlanta, GA to discuss 10CFR50, App R fire protection requirements Proposed agenda encl LEWIS, R C Division of Project & Resident Programs 83/12/22 McDONALD, R P Alabama Power Co 2pp 21740 156 24X Fiche 50-348, 83/12/22, 8401060436

DOCKETED ITEMS

217

B401030371 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21694 001 24X Fiche 50-348, 83/12/27,
B401030371

--B401030374 Public version of Rev B to emergency plan W/831213 ltr
HUDBPETH, J B Alabama Power Co 83/12/07 Office of Nuclear
Reactor Regulation, Director 600pp 21694 002 24X
Fiche 50-348, 83/12/27, B401030371

B401060115 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21746 082 24X Fiche 50-348, 83/12/27,
B401060115

--B401060121 Forwards public version of revised emergency plan
implementing procedures, including Procedures 00-EIP-114 re
news release coordination & distribution & 00-EIP-134 re
corporate emergency plan training
HUDD, C H Alabama Power Co 83/11/21 Document Management
Branch 2pp 21746 083 24X Fiche 50-348, 83/12/27, B401060115

--B401060126 Public version of revised emergency plan implementing
procedures, including Procedures 00-EIP-114 re news release
coordination & distribution & 00-EIP-134 re corporate
emergency plan training
MCGOWAN, J W Alabama Power Co 83/11/21 100pp 21746 085 24X
Fiche: 50-348, 83/12/27, B401060115

B401100167 Ack receipt of 831116 ltr re emergency exercise scheduled
for site during Feb 1984 Planned exercise & objectives
reviewed & discussed Addl comments will be made by telephone
to McCracken
VERRELL, J D M Division of Project & Resident Programs 84/01/04
MCGOWAN, J W Alabama Power Co 1p 21760 171 24X
Fiche: 50-348, 84/01/04, B401100167

B401190444 Forwards Amends 39 & 29 to Licenses NPF-2 & NPF-B,
respectively Amends require audit of emergency preparedness
program at least once per 12 months (per Generic Ltr 82-17)
REEVES, E A Operating Reactors Branch 1 84/01/06 CLAYTON, F L
Alabama Power Co 3pp 21857 357 24X Fiche 50-348, 84/01/06,
B401190444

--B401190451 Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively,
requiring audit of emergency preparedness program at least
once per 12 months (per Generic Ltr 82-17)
VARDA, S A Operating Reactors Branch 1 84/01/06 6pp
21837:360 24X Fiche 50-348, 84/01/06, B401190444

--B401190460 Safety evaluation supporting Amends 39 & 29 to Licenses
NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/06 2pp
21858.006 24X Fiche 50-348, 84/01/06, B401190444,

B401200284 Releases public version of addition to emergency plan rev
FELTON, J M Division of Rules and Records 84/01/17 Document
Management Branch 1p 21890 361 24X Fiche: 50-348, 84/01/17,
B401200284

--B401200288 Public version of addition to Rev 5 to emergency plan
entitled, "Region II Suppl to NUREG-0845,"
* Alabama Power Co 83/10/31 164pp 21890 362 24X
Fiche: 50-348, 84/01/17, B401200284

B401250002 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/17 Document
Management Branch 1p 21948 218 24X Fiche: 50-348, 84/01/17,
B401250002

--B401250003 Public version of Rev 13 to Emergency Plan Implementing
Procedure FNP-O-EIP-O, "Radiation Exposure Estimation &
Classification of Emergencies " W/840104 ltr,
HUDBPETH, J B Alabama Power Co 84/01/03 Document Management
Branch 119pp, 21948, 219 24X Fiche 50-348, 84/01/17, B401250002

B401260181 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p, 21971:290 24X Fiche: 50-348, 84/01/18,
B401260181.

--B401260185 Public version of Rev 3 to Emergency Plan Implementing
Procedure 00-EIP-112, "Emergency Mobile Communications,"
W/831215 ltr
MCGOWAN, J W, HUDD, C H Alabama Power Co, 83/12/15, NRC - No
Detailed Affiliation Given 9pp 21971:292 24X
Fiche 50-348, 84/01/18, B401260181.

B401260266 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21992 316 24X Fiche 50-348, 84/01/18,
B401260266

--B401260270 Public version of Rev 8 to Emergency Plan Implementing
Procedure FNP-O-EIP-15, "Emergency Drills " W/831228 ltr &
receipt form
HUDBPETH, J B Alabama Power Co 83/12/22 Office of Nuclear
Reactor Regulation, Director 9pp 21992 317 24X
Fiche 50-348, 84/01/18, B401260266

B401240624 Releases public version of figures to revised emergency
plan administrative procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21944 347 24X Fiche 50-348, 84/01/20,
B401240624

--B401240627 Public version of figures to Rev 13 to Emergency Plan
Administrative Procedure FNP-O-EIP-9 re relative dose rate
plume boundary W/840105 & 06 ltrs
HUDBPETH, J B Alabama Power Co 84/01/05 Office of Nuclear
Reactor Regulation, Director 12pp 21944 348 24X
Fiche 50-348, 84/01/20, B401240624

B401240630 Releases public version of emergency plan implementing
procedure
FELTON, J M Division of Rules and Records 84/01/20, Document
Management Branch 1p, 21944 335, 24X Fiche 50-348, 84/01/20,
B401240630

--B401240632 Public version of Rev 2 to Emergency Plan Implementing
Procedure 00-EIP-132, "Emergency Plan Drills & Exercises "
W/830103 ltr
MCGOWAN, J W Alabama Power Co 84/01/03 NRC - No Detailed
Affiliation Given 11pp 21944 336 24X Fiche: 50-348, 84/01/20,
B401240630

B401240638 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/20, Document
Management Branch 1p 21944 218 24X Fiche 50-348, 84/01/20,
B401240638

--B401240642 Forwards public version of Rev 1 to Emergency Plan
Implementing Procedures 00-EIP-119, "Relocation of Emergency
Operations Facility (EOF) Functions to Alternate EOF" &
00-EIP-116, "Emergency Operations Facility Shift Turnover "
HUDD, C H Alabama Power Co 84/01/12 NRC - No Detailed
Affiliation Given 1p 21944 219 24X Fiche 50-348, 84/01/20,
B401240638

--B401240645 Public version of Rev 1 to Emergency Plan Implementing
Procedures 00-EIP-119, "Relocation of Emergency Operations
Facility (EOF) Functions to Alternate EOF" & 00-EIP-116,
"Emergency Operations Facility Shift Turnover "
MCGOWAN, J W Alabama Power Co, 84/01/12 31pp 21944, 220 24X
Fiche 50-348, 84/01/20, B401240638

B401260296 Releases public version of revised emergency plan
implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21992 118, 24X Fiche 50-348, 84/01/20,
B401260296

--B401260299 Public version of Rev 7 to Emergency Plan Implementing
Procedure FNP-O-EIP-26, "Offsite Notification " W/840101 ltr
& receipt form.
HUDBPETH, J B Alabama Power Co 83/12/21, Document Management
Branch 25pp 21992, 119 24X Fiche 50-348, 84/01/20, B401260296.

B401260330 Releases public version of rev to emergency plan
implementing procedure
FELTON, J M Division of Rules and Records, 84/01/20 Document
Management Branch 1p 21992 097 24X Fiche: 50-348, 84/01/20,
B401260330

--B401260334 Public version of Rev 1 to Emergency Plan Implementing
Procedure 00-EIP-101, "Corporate Emergency Organization "
W/830104 ltr & receipt form
MCGOWAN, J W, Alabama Power Co 84/01/04 Document Management
Branch 20pp, 21992, 117 24X Fiche 50-348, 84/01/20, B401260330

B401310229 Releases public version of revised emergency plan
implementing procedures
FELTON, J M, Division of Rules and Records, 84/01/20, Document
Management Branch 1p, 22037:151 24X Fiche, 50-348, 84/01/20,
B401310229

DOCKETED ITEMS

--8401310236 Forwards public version of Rev 2 to Emergency Plan Implementing procedure 00-EIP-117 re emergency operations facility administrative support & Rev 3 to Procedure 00-EIP-131 re emergency operations ctr
MUDD, C. H. Alabama Power Co 84/01/05 Document Management Branch 1p, 22037 152. 24X Fiche 50-348, 84/01/20, 8401310229

--8401310240 Public version of Rev 2 to Emergency Plan Implementing Procedure 00-EIP-117 re emergency operations facility administrative support & Rev 3 to Procedure 00-EIP-131 re emergency operations ctr.
MCQUHAN, J. W. Alabama Power Co 84/01/05. 36pp 22037 154. 24X Fiche 50-348, 84/01/20, 8401310229

P. Operating license stage documents & correspondence

8401060238 Notification of 840110 meeting w/util in Bethesda, MD to discuss proposed Tech Spec change on inoperable control rods proposed in util 831010 ltr
REEVES, E. A. Operating Reactors Branch 1 83/12/28. VARQA, S. A. Operating Reactors Branch 1 2pp 21753 150 24X Fiche 50-348, 83/12/28, 8401060238.

8401130026 Forwards Amends 38 & 28 to Licenses NPF-2 & NPF-B, respectively & safety evaluation. Amends change Tech Specs to incorporate overtime limitations in Generic Ltr 82-12 per TH1 Action Item I A.1.3.
REEVES, E. A. Operating Reactors Branch 1. 83/12/30 CLAYTON, F. L. Alabama Power Co 2pp 21821 004. 24X Fiche 50-348, 83/12/30, 8401130026.

--8401130030 Amends 38 & 28 to Licenses NPF-2 & NPF-B, respectively, changing Tech Specs to incorporate overtime limitations in Generic Ltr 82-12 per TH1 Action Item I A.1.3
VARQA, S. A. Operating Reactors Branch 1. 83/12/30 5pp 21821 006. 24X Fiche 50-348, 83/12/30, 8401130026

--8401130038 Safety evaluation supporting Amends 38 & 28 to Licenses NPF-2 & NPF-B, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/12/30 2pp 21821 014. 24X Fiche 50-348, 83/12/30, 8401130026

8401180080 Requests addl info re river water sys & diesel generator testing, per 821220 OL amend request. Response should be provided within 45 days of ltr receipt
VARQA, S. A. Operating Reactors Branch 1. 84/01/04 CLAYTON, F. L. Alabama Power Co. 4pp. 21848 214 24X Fiche 50-348, 84/01/04, 8401180080.

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D. G. Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc. 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382.

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Bvc list encl.
EISENHUT, D. G. Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc. 18pp. 21957 247 24X Fiche 50-000, 84/01/06, 8401090221.

8401160084 Forwards response to 831216 Generic Ltr 83-41 re cold starts of diesel generators Fast cold starts exacerbate bearing wear due to lack of prelubrication Fast cold starts should be avoided, except for emergencies.
CLAYTON, F. L. Alabama Power Co. 84/01/06 EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director 2pp 21815 065 24X Fiche 50-348, 84/01/06, 8401160084

8401190444 Forwards Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively. Amends require audit of emergency preparedness program at least once per 12 months (per Generic Ltr 82-17).
REEVES, E. A. Operating Reactors Branch 1. 84/01/06 CLAYTON, F. L. Alabama Power Co 3pp. 21857 337 24X Fiche 50-348, 84/01/06, 8401190444.

--8401190451 Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively, requiring audit of emergency preparedness program at least once per 12 months (per Generic Ltr 82-17).
VARQA, S. A. Operating Reactors Branch 1. 84/01/06. 5pp 21857 360. 24X Fiche 50-348, 84/01/06, 8401190444.

--8401190460 Safety evaluation supporting Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/06. 2pp 21858 006. 24X Fiche 50-348, 84/01/06, 8401190444.

8401190261 Forwards Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends delete applicability of Tech Spec Table 3 3-3 re safety injection signal & correct Multi-Plant Action Item B-32
REEVES, E. A. Operating Reactors Branch 1 84/01/09 CLAYTON, F. L. Alabama Power Co 4pp 21870 079 24X Fiche 50-348, 84/01/09, 8401190261

--8401190268 Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively, deleting applicability of footnote for Item 1 e in Table 3 3-3 re safety injection signal & correcting Multi-Plant Item B-32 re blocked safety injection signal
VARQA, S. A. Operating Reactors Branch 1 84/01/09 8pp 21870 083 24X Fiche 50-348, 84/01/09, 8401190261

--8401190276 Safety evaluation supporting Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director 84/01/09 2pp 21870 091 24X Fiche 50-348, 84/01/09, 8401190261

8401130448 Notification of 840120 meeting w/util in Bethesda, MD to discuss proposed Tech Spec change re inoperable control rods
REEVES, E. A. Operating Reactors Branch 1. 84/01/10 VARQA, S. A. Operating Reactors Branch 1 3pp 21819 342 24X Fiche 50-348, 84/01/10, 8401130448

8401200030 Forwards Amend 31 to License NPF-B & safety evaluation Amend deletes eight nonsafety-related hydraulic snubbers from Tech Spec Table 3 7-4a
REEVES, E. A. Operating Reactors Branch 1 84/01/10 CLAYTON, F. L. Alabama Power Co 4pp 21871 108 24X Fiche 50-348, 84/01/10, 8401200030

--8401200032 Amend 31 to License NPF-B, deleting eight nonsafety-related hydraulic snubbers from Tech Spec Table 3 7-4a
VARQA, S. A. Operating Reactors Branch 1 84/01/10 5pp 21871 112 24X Fiche 50-348, 84/01/10, 8401200030

--8401200034 Safety evaluation supporting Amend 31 to License NPF-B
* Office of Nuclear Reactor Regulation, Director 84/01/10 2pp 21871 117 24X Fiche 50-348, 84/01/10, 8401200030

8401300021 Forwards BER re util responses to NUREG-0737, Item II K 2 17, "Potential for Voiding in RCS during Transients" Voids generated in RCS during anticipated transients accounted for in present analysis models.
VARQA, S. A. Operating Reactors Branch 1 84/01/10 CLAYTON, F. L. Alabama Power Co 10pp 22027 306 24X Fiche 50-348, 84/01/10, 8401300021

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Bvc list encl
EISENHUT, D. G. Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc. 18pp. 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401170235 Requests exemption from 10CFR20, App A, to allow credit for radiolysis protection factor in employing MSA 46620 QMR-I canister Limitations in use of canister listed Test results, proposed test protocol & QA sampling plan encl
CLAYTON, F. L. Alabama Power Co. 84/01/13. VARQA, S. A. Office of Nuclear Reactor Regulation, Director 4pp 21831 353 24X Fiche 50-348, 84/01/13, 8401170235

Q. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J. H. Division of Rules and Records. 83/10/20. ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement. 83/10/20 103pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040.

8401050560 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-26 & 50-364/83-24
LEWIS, R. C. Division of Project & Resident Programs 83/12/16 McDONALD, R. P. Alabama Power Co. 1p 21724 270 24X Fiche 50-348, 83/12/16, 8401050560

DOCKETED ITEMS

219

--8401050606 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-348/83-26 & 50-364/83-24 Corrective actions Procedure FNP-O-AP-16 revised to require locking device be removed prior to verifying open position of locked valve
CLAYTON, F L Alabama Power Co 83/12/07 LEWIS, R C Division of Project & Resident Programs 3pp 21724 271 24X
Fiche 50-348, 83/12/16, 8401050606

--8401050611 Forwards IE Insp Repts 50-348/83-26 & 50-364/83-24 on 830911-1010 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07
MCDONALD, R P Alabama Power Co 2pp 21724 274 24X
Fiche 50-348, 83/12/16, 8401050611

--8401050616 Notice of violation from Insp on 830911-1010
* Region 2, Office of Director 83/11/07 1p 21724 276 24X
Fiche 50-348, 83/12/16, 8401050616

--8401050626 IE Insp Repts 50-348/83-26 & 50-364/83-24 on 830911-1010
Violation noted containment spray loop 2A eductor supply valve locked in closed position while Unit 2 in cold shutdown
BRADFORD, W H, RULAND, W H, CANTRELL, F S Region 2, Office of Director 83/11/03 13pp 21724 277 24X Fiche 50-348, 83/12/16, 8401050626

8401050445 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19
VERRELLI, D M Division of Project & Resident Programs 83/12/20
MCDONALD, R P Alabama Power Co 1p 21730 214 24X
Fiche 50-348, 83/12/20, 8401050445

--8401050448 Responds to NRC 830909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions mgt directive issued reemphasizing that fire protection program reevaluation considered on same basis as FSAR
CLAYTON, F L Alabama Power Co 83/12/09, VERRELLI, D M Division of Project & Resident Programs 6pp 21730 215 24X
Fiche 50-348, 83/12/20, 8401050448

8401060408 Forwards IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/12/21
MCDONALD, R P Alabama Power Co 2pp 21741 083 24X
Fiche 50-348, 83/12/21, 8401060408

--8401060410 IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-18 No noncompliance noted Major areas inspected emergency preparedness
STODDART, P O Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/12/08, 8pp 21741 085 24X Fiche 50-348, 83/12/21, 8401060410

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp, 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401240598 Forwards IE Insp Repts 50-348/83-30 & 50-364/83-28 on 831111-1210 No violations or deviations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/29
MCDONALD, R P Alabama Power Co 2pp 21909 197 24X
Fiche 50-348, 83/12/29, 8401240598

--8401240606 IE Insp Repts 50-348/83-30 & 50-364/83-28 on 831111-1210 No violations or deviations noted Major areas inspected: plant status, monthly surveillance observation, monthly maint observation & operational safety verification
BRADFORD, W H, RULAND, W H Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs, 83/12/28 9pp, 21909 199 24X Fiche 50-348, 83/12/29, 8401240598

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060, 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184, 24X Fiche 50-000, 84/01/10, 8312120107

8401240558 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-29 & 50-364/83-27
LEWIS, R C Division of Project & Resident Programs 84/01/11
MCDONALD, R P Alabama Power Co 1p 21909 104 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240565 Responds to NRC 831207 ltr re violations noted in IE Insp Repts 50-348/83-29 & 50-364/83-27 Corrective actions personnel counseled to adhere to plant procedures & monitor cooldown limits closely
CLAYTON, F L Alabama Power Co 84/01/06 LEWIS, R C Region 2, Office of Director 3pp 21909 107 24X Fiche 50-348, 84/01/11, 8401240558

--8401240567 Forwards IE Insp Repts 50-348/83-29 & 50-364/83-27 on 831011-1110 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/12/07
MCDONALD, R P Alabama Power Co 2pp 21909 110, 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240571 Notice of violation from Insp on 831011-1110
* Region 2, Office of Director 83/12/07 1p, 21909 112 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240580 IE Insp Repts 50-348/83-29 & 50-364/83-27 on 831011-1110
Violation noted, heaters not tested & humidity sensors which turn heaters on & off not verified operable & Tech Spec limit exceeded for RCS cooldown rate
BRADFORD, W H, RULAND, W H Region 2, Office of Director CANTRELL, F S, Division of Project & Resident Programs 83/12/06 12pp 21909 113 24X Fiche 50-348, 84/01/11, 8401240558.

8312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18, Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18, Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401270125 Forwards revised pages to inservice Insp program, Attachment 1 to Class I table & Notes 14, 15 & 16 to Class II table, per EA Reaves 840120 request Encls do not constitute request for addl relief.
CLAYTON, F L Alabama Power Co 84/01/23 VAROA, B A Office of Nuclear Reactor Regulation, Director 10pp 21982 032 24X
Fiche 50-348, 84/01/23, 8401270125.

R Periodic operating reports & related correspondence

8401170191 Monthly operating rpt for Dec 1983 W/840115 ltr
HAIRSTON, W Q, CLAYTON, F L Alabama Power Co 83/12/31, Division of Data Automation & Management Information, 6pp 21833 301, 24X
Fiche 50-348, 83/12/31, 8401170191

S Reportable occurrences, LERs & related correspondence

8401040123 Forwards LERs 83-080/03L-0, 83-081/03L-0 & 83-082/03L-0
CLAYTON, F L Alabama Power Co 83/12/22, Region 2, Office of Director 1p, 21702 057, 24X Fiche 50-348, 83/12/22, 8401040123.

--8401040131 LER 83-080/03L-0 on 831125, spent fuel storage area radiation monitor R-5 declared inoperable due to erroneous indication
Caused by loose connection, Connection repaired
HAIRSTON, W Q, Alabama Power Co 83/12/22 Region 2, Office of Director 1p, 21702 058 24X Fiche 50-348, 83/12/22, 8401040123.

--8401040136 LER 83-081/03L-0, on 831201, river water pump 4 declared inoperable due to broken lower pump bearing lube water supply line Caused by failed fitting between line & pump
Fitting replaced
HAIRSTON, W Q, Alabama Power Co, 83/12/22 Region 2, Office of Director 1p 21702 059 24X Fiche 50-348, 83/12/22, 8401040123.

--8401040140 LER 83-082/03L-0 on 831202, specific gravity on auxiliary bldg train A battery cell 40 found low, Cause undetermined, Affected cell recharged
HAIRSTON, W Q, Alabama Power Co, 83/12/22, Region 2, Office of Director 1p 21702 060 24X Fiche 50-348, 83/12/22, 8401040123

DOCKETED ITEMS

8401040157 LER 83-086/03L-0 on 831122, instrumentation channel associated w/reactor coolant pump C bus undervoltage declared inoperable due to low trip setpoint. Caused by relay drifting out of tolerance. Relay adjusted w/831222 ltr.
HAIRSTON, W O., CLAYTON, F. L. Alabama Power Co 83/12/22 Region 2, Office of Director 2pp 21702 093 24X Fiche 50-348, 83/12/22, 8401040157

8401040359 RO. on 831224, fire protection tank A & B levels fell to approx 232,000 gallons each due to extreme cold, causing cooling tower IC fire protection sys to fail. On 831226, tank levels found below min due to personnel error.
HAIRSTON, W O., Alabama Power Co 83/12/27 O'REILLY, J P Region 2, Office of Director 1p 21706 151 24X Fiche 50-348, 83/12/27, 8401040359

8401060465 Forwards LERs 83-084/03L-0, 83-087/03L-0, 83-088/03L-0 & 83-063/03L-0
CLAYTON, F. L. Alabama Power Co 83/12/27 Region 2, Office of Director 1p 21740 055 24X Fiche 50-348, 83/12/27, 8401060465

--8401060469 LER 83-084/03L-0 on 831204, motor driven auxiliary feed pump 1A declared inoperable due to valve GIN23V002A (MDAPP) discharge check valve leaking. Caused by one missing & one worn hinge pin bushing. Hinge bushings replaced.
HAIRSTON, W O., Alabama Power Co 83/12/27 Region 2, Office of Director 6pp 21740 056 24X Fiche 50-348, 83/12/27, 8401060465

--8401060473 LER 83-087/03L-0 on 831203, train A chlorine detector declared inoperable when dampers HV-3624 & HV-362B failed to close on receipt of simulated high chlorine signal. Caused by failure of solenoid valves. Valves replaced.
HAIRSTON, W O., Alabama Power Co 83/12/27 Region 2, Office of Director 3pp 21740 062 24X Fiche 50-348, 83/12/27, 8401060465

--8401060481 LER 83-088/03L-0 on 831112, train B emergency air cleanup sys declared inoperable when damper HV-3629 failed to close on receipt of simulated high radiation signal. Caused by failure of damper solenoid valve. Valve repaired.
HAIRSTON, W O., Alabama Power Co 83/12/27 Region 2, Office of Director 3pp 21740 065 24X Fiche 50-348, 83/12/27, 8401060465

--8401060489 LER 83-063/03L-0 on 831206, instrumentation channel associated w/level indicator LI-4075A (refueling water storage tank) declared inoperable due to erroneous high indication. Caused by transmitter box leak. Cover repaired.
HAIRSTON, W O., Alabama Power Co 83/12/27 Region 2, Office of Director 3pp 21740 068 24X Fiche 50-348, 83/12/27, 8401060465

8401100390 Forwards LERs 83-083/03L-0 & 83-085/03L-0.
CLAYTON, F. L. Alabama Power Co 83/12/30 Region 2, Office of Director 1p 21762 227 24X Fiche 50-348, 83/12/30, 8401100390

--8401100395 LER 83-083/03L-0 on 831206, during Auxiliary Bldg Battery Quarterly Verification FNP-1-STP-16 7 not performed within allowed time. Sys declared inoperable. Caused by personnel error. No cause found re improper valve stroking.
HAIRSTON, W O., Alabama Power Co 83/12/30 Region 2, Office of Director 1p 21762 228 24X Fiche 50-348, 83/12/30, 8401100390

--8401100403 LER 83-085/03L-0 on 831204, Containment Spray Sys Valve Inservice Tests FNP-1-STP-16 7 not performed within allowed time. Sys declared inoperable. Caused by personnel error. No cause found re improper valve stroking.
HAIRSTON, W O., Alabama Power Co 83/12/30 Region 2, Office of Director 2pp 21762 229 24X Fiche 50-348, 83/12/30, 8401100390

8401240263 Forwards LERs 83-089/03L-0 & 83-064/03L-0
CLAYTON, F. L. Alabama Power Co 84/01/13 Region 2, Office of Director 1p 21910 027 24X Fiche 50-348, 84/01/13, 8401240263

--8401240267 LER 83-089/03L-0 on 831215, radiation monitor R-11 declared inoperable due to improper valve lineup. Caused by personnel error. Valve lineup corrected.
HAIRSTON, W O., Alabama Power Co 84/01/13 Region 2, Office of Director 2pp 21910 028 24X Fiche 50-348, 84/01/13, 8401240263

--8401240275 LER 83-064/03L-0 on 831214, instrumentation channel associated w/flow indicator FI-474 declared inoperable due to drifting out of tolerance. Cause unknown. Steam generator 2A FT-474 loop calibr & functional test conducted.
HAIRSTON, W O., Alabama Power Co 84/01/13 Region 2, Office of Director 6pp 21910 030 24X Fiche 50-348, 84/01/13, 8401240263

8401300287 Forwards LERs 83-090/03L-0, 83-091/03L-0, 83-092/03L-0, 83-065/03L-0 & 83-066/03L-0
CLAYTON, F. L. Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21997 301 24X Fiche 50-348, 84/01/20, 8401300287

--8401300291 LER 83-090/03L-0 on 831224, radiation monitors R-11 & R12 declared inoperable when vacuum pump tripped. Caused by flow rate set too high. Method for adjusting flow rate revised & monitors returned to svc.
HAIRSTON, W O., Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21997 302 24X Fiche 50-348, 84/01/20, 8401300287

--8401300294 LER 83-091/03L-0 on 831226, radiation monitor R-5 declared inoperable due to erroneous indication. Caused by faulty connection. Connection repaired & monitor declared operable.
HAIRSTON, W O., Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21997 303 24X Fiche 50-348, 84/01/20, 8401300287

--8401300297 LER 83-092/03L-0 on 831225, instrumentation channel associated w/pressure transmitter PT-494 declared inoperable. Caused by localized freezing in sensing lines due to cold weather. Lines thawed out.
HAIRSTON, W O., Alabama Power Co 84/01/20 Region 2, Office of Director 2pp 21997 304 24X Fiche 50-348, 84/01/20, 8401300287

--8401300303 LER 83-065/03L-0 on 831227, instrumentation channel associated w/temp indicator TI-432B declared inoperable. Caused by drift of lead/lag card. Gain Card replaced & channel declared operable.
HAIRSTON, W O., Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21997 306 24X Fiche 50-348, 84/01/20, 8401300287

--8401300306 LER 83-066/03L-0 on 831231, instrumentation channel associated w/flow transmitter FT-476 declared inoperable. Caused by drift of square root extraction card. Card replaced & channel returned to svc.
HAIRSTON, W O., Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21997 307 24X Fiche 50-348, 84/01/20, 8401300287

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8401030321 Forwards request for addl info re environ qualification program. License application should be amended to comply w/ encl requirements. Info requested by 831230.
SCHWENCER, A. Licensing Branch 2 83/12/19 BAUER, E O Philadelphia Electric Co 3pp 21693 310 24X Fiche 50-352, 83/12/19, 8401030321

8401040065 Notification of 840106 meeting w/util in Bethesda, MD to discuss applicant analysis of tornado missiles for utility.
CAMPAONONE, M. Licensing Branch 2 83/12/23 SCHWENCER, A Licensing Branch 2 4pp 21711 326 24X Fiche 50-352, 83/12/23, 8401040065

8401190142 Notification of cancellation of 840106 meeting w/util in Bethesda, MD to discuss analysis of tornado missiles for UHS.
CAMPAONONE, M. J. Licensing Branch 2 83/12/23 SCHWENCER, A Licensing Branch 2 4pp 21871 010 24X Fiche 50-352, 83/12/23, 8401190142

8401040091 Forwards Procedure LIM-UT-1, Rev 1, "Reg Guide 1.150 Method for Compliance," per commitment at 830831 meeting to provide description of qualification of OE ultrasonic test process for reactor pressure vessel insp.
KEMPER, J. B. Philadelphia Electric Co 83/12/28 EISENHUT, D O Division of Licensing 2pp 21703 210 24X Fiche 50-352, 83/12/28, 8401040091

--8401040095 Rev 1 to Procedure LIM-UT-1, "Reg Guide 1.150 Method for Compliance."
FORSYTHE, F., MILLER, W F General Electric Co 83/10/11 7pp 21703 212 24X Fiche 50-352, 83/12/28, 8401040091

840110162 Notification of 840117-20 meetings w/util at site to perform audits of equipment by NRC pump & valve operability review team & seismic qualification review team.
KINTNER, L. L. Licensing Branch 1 83/12/28 SCHWENCER, A Licensing Branch 2 4pp 21795 216 24X Fiche 50-352, 83/12/28, 840110162

8401090334 Amend 60 to OL application, consisting of Rev 7 to emergency plan (PDR Category F), Rev 27 to PSAR (PDR Category K), Rev 16 to environ rept - OL stage (PDR Category C) & Rev 4 to mechanical equipment environ qualification rept.
BRADLEY, E. J. Philadelphia Electric Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21781 001 24X Fiche 50-352, 83/12/30, 8401090334

--840110313 Rev 4 to "Mechanical Equipment Environ Qualification Rept Limerick Generating Station Unit 1," Vols 1-4.
SEXTON, D E., LARSEN, C., KUMAR, P A Quadrex Corp. QUAD-1-83-016 R04 83/12/12 2771pp 21783 069 24X Fiche 50-352, 83/12/30, 8401090334

B401110477 Responds to B31214 ltr re late notification of NRC B31129 meeting w/uttl & erroneous separation of dockets
SCHWENCER, A Licensing Branch 2 83/12/30 SUGARMAN, R J Sugarmen
& Denuworth 1p 21795 352 24X Fiche 50-352, 83/12/30, B401110477

B312120108 Board Notification B4-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J
Commissioners 2pp 21793 324 24X Fiche 50-000, 84/01/05, B312120108

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21757 267 24X
Fiche: 50-000, 84/01/06, B401090221

B401130170 Requests clarification of Kemper B31227 ltr to NRC re completion of const & possible fuel loading date
SUGARMAN, R J Sugarmen & Denuworth 84/01/09 EISENHUT, D G
Division of Licensing 2pp 21802 038 24X Fiche 50-352, 84/01/09, B401130170.

B401200171 Requests plans, within 30 days, re assurance that plant designed & constructed in accordance w/regulations & SAR commitments, per design verification program
EISENHUT, D G Division of Licensing 84/01/10 BAUER, E G
Philadelphia Electric Co 3pp 21871 274 24X
Fiche 50-352, 84/01/10, B401200171

--B312270199 Forwards draft ltrs to uttl's requesting addl assurances from applicants for OL that design process used in const complies w/regulations & licensing commitments IE recommended actions listed
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 21871 277, 24X Fiche 50-352, 84/01/10, B401200171

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0973, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, B401130084

B401230024 Forwards responses to Environ Qualification Section B31219 request for addl info Responses will be included in Rev 1 to environ qualification rept scheduled for submittal in Apr 1984
KEMPER, J S Philadelphia Electric Co, 84/01/16 SCHWENCER, A
Licensing Branch 2 52pp 21886 117 24X Fiche 50-352, 84/01/16, B401230024

--B401230028 Rev 1 to "Drywell Temp Response to Small Steam Break, Realistic Environ Qualification Envelope"
NGUYEN, D V, JONES, D D General Electric Co, 83/11/18 12pp
21897-274 24X Fiche 50-352, 84/01/16, B401230024.

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
MANNON, J. Division of Licensing 84/01/17 Division of Licensing, 1p, 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401240244 Forwards marked-up proposed Tech Specs, per FSAR Section 16.2 & offsite dose calculation manual w/o encl
DALTROFF, E L Philadelphia Electric Co, 84/01/19, SCHWENCER, A
Licensing Branch 2, 2pp 21910 136 24X Fiche 50-352, 84/01/19, B401240244

B401240456 Forwards marked-up proposed Tech Spec, replacing certain time frames w/annotation "later" in several specs & Rev 0 to "Offsite Dose Calculation Manual"
DALTROFF, E L Philadelphia Electric Co, 84/01/19, SCHWENCER, A
Licensing Branch 2, 645pp 21913 233 24X Fiche 50-352, 84/01/19, B401240456.

--B401240460 Rev 0 to "Offsite Dose Calculation Manual"
* Philadelphia Electric Co 83/12/31 34pp 21913, 144 24X
Fiche 50-352, 84/01/19, B401240456

C Utility Environmental Report (ER), amends & correspondence

B401090334 Forwards Rev 16 to environ rept - OL stage
BRADLEY, E J Philadelphia Electric Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21781 001
24X Fiche 50-352, 83/12/30, B401090334

--B401110308 Rev 16 to environ rept
* Philadelphia Electric Co 83/12/31 14pp 21783 056 24X
Fiche 50-352, 83/12/30, B401090334

B401300226 Forwards affidavit of svc re distribution of Rev 27 to FSAR & Rev 16 to environ rept, per 810706 ltr
BRADLEY, E J Philadelphia Electric Co 84/01/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 22062 129
24X Fiche 50-352, 84/01/25, B401300226

B401310395 Advises that goat farm established in area since agricultural land use data presented in environ rept - OL stage compiled. Draft page changes to environ rept - OL stage encl Rev scheduled for Feb 1984
KEMPER, J S Philadelphia Electric Co 84/01/25 SCHWENCER, A
Licensing Branch 2 14pp 22018 005, 24X Fiche 50-352, 84/01/25, B401310395

D NRC Draft/Final Environmental Statements, suppl & correspondence

B401030297 Forwards Suppl 1 to DES & FR notice of availability. After receipt of comments, DES will be prepared w/o DES
SCHWENCER, A Licensing Branch 2 83/12/16 PERRIN, S
Environmental Protection Agency 2pp 21693 350 24X
Fiche 50-352, 83/12/16, B401030297

--B401030301 Notice of availability of Suppl 1 to DES
SCHWENCER, A Licensing Branch 2 83/12/16, 2pp 21693 352 24X
Fiche 50-352, 83/12/16, B401030297

B401030309 Forwards Suppl 1 to DES (NUREG-0974) for review & comment Response requested in 45 days w/o encl
SCHWENCER, A Licensing Branch 2 83/12/16, WOOD, J, M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 4pp 21693 337 24X Fiche 50-352, 83/12/16, B401030309

B401040057 Forwards FR notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2 83/12/16 DAVIS, J, F Affiliation Unknown CHERRY, M Cherry, M M /Cherry, Flynn & Kanter 1p 21711 330 24X Fiche 50-352, 83/12/16, B401040057

--B401040064 Notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2, 83/12/16, 3pp, 21711 331 24X
Fiche 50-352, 83/12/16, B401040057.

B401110370 Forwards FR notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2 83/12/16, BAUER, E G
Philadelphia Electric Co 3pp 21794 293, 24X
Fiche 50-352, 83/12/16, B401110370

B401060482 Forwards DES for facilities. Further comments to NRC requested within 3 wks w/o encl
HAGER, G W Maryland, State of 83/12/20 PYERS, C, BACHS, H, FREDERICK, L Maryland, State of 1p, 21740, 202 24X
Fiche 50-352, 83/12/20, B401060482

B401260061 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF LIMERICK GENERATING STATION, UNITS 1 AND 2 Docket Nos. 50-352 And 50-353 (Philadelphia Electric Company)
* Division of Licensing NUREG-0974 801, 83/12/31 157pp, 21970 001, 24X Fiche 50-352, 83/12/31, B401260061.

B401160263 Advises that Suppl 1 to DES reviewed No substantive comments made.
BARBIERI, N J Army, Dept. of, Corps of Engineers, 84/01/09, SCHWENCER, A, Licensing Branch 2 1p, 21813 301 24X
Fiche 50-352, 84/01/09, B401160263

E NRC Safety Evaluation Report (SER), suppl & correspondence

B401100034 Forwards BSER 1 (NUREG-0991) w/o encl.
SCHWENCER, A Licensing Branch 2 83/12/13, BAUER, E G, Philadelphia Electric Co 4pp 21777, 175, 24X
Fiche 50-352, 83/12/13, B401100034.

B401030177 Summary of 830930 meeting w/uttl & OE in King of Prussia, PA re Instrumentation & Control Sys Branch SER issue on plant instrument setpoints.
MARTIN, R, E Licensing Branch 2 83/12/19 Licensing Branch 2 6pp 21695, 242, 24X Fiche 50-352, 83/12/19, B401030177

DOCKETED ITEMS

8401090796 Summary of 831213 meeting w/uttl, Bechtel, BNL & Professional Loss Control, Inc re util submittals on two open SER Fire protection items Viewgraphs encl
KINTNER, L Licensing Branch 1 83/12/23 Licensing Branch 1
44pp 21768:001 24X Fiche 50-352, 84/01/04, 8401090796

8401090477 Forwards repts re means for assuring fire protection for structural steel in lieu of strict application of protective coating, per 831213 request & SER (NUREG-0991)
KEMPER, J S Philadelphia Electric Co 84/01/04 SCHWENCER, A
Licensing Branch 2 28pp 21752 248 24X Fiche 50-352, 84/01/04, 8401090477

--8401090485 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Sump Room 115, Fire Area 39 "
* Professional Loss Control, Inc. 83/12/20 5pp 21752 235
24X Fiche 50-352, 84/01/04, 8401090477

--8401090490 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Corridor Room 118, Fire Area 39 "
* Professional Loss Control, Inc. 83/12/20 3pp. 21752 260
24X Fiche 50-352, 84/01/04, 8401090477

--8401090494 "Structural Steel Analysis for Limerick Generating Station, Reactor Bldg Elevation 198-Ft Pipe Tunnel Room 202, Fire Area 76 "
* Professional Loss Control, Inc. 83/12/20 3pp 21752 263
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090599 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 201-Ft Cooling Water HX Area Room 207, Fire Area 41. "
* Professional Loss Control, Inc. 83/12/20 10pp 21752 266
24X Fiche: 50-352, 84/01/04, 8401090477.

--8401090609 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 201-Ft Safeguard Sys Access Room 200, Fire Area 48A "
* Professional Loss Control, Inc. 83/12/20 15pp 21752 276.
24X Fiche 50-352, 84/01/04, 8401090477.

--8401090619 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Corridor Room 605, Fire Area 48A. "
* Professional Loss Control, Inc. 83/12/20 4pp 21752 291
24X Fiche 50-352, 84/01/04, 8401090477

--8401090631 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft West Chiller Equipment Room, Room 258, Fire Area 11. "
* Professional Loss Control, Inc. 83/12/20 5pp 21753 069
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090632 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Laydown Area Room 601, Fire Area 48A. "
* Professional Loss Control, Inc. 83/12/20 4pp 21752 295
24X Fiche 50-352, 84/01/04, 8401090477.

--8401090636 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Redwaste Pipe Tunnel, Fire Area 115. "
* Professional Loss Control, Inc. 83/12/20 3pp 21753:074
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090637 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft RHR HX & Pump Room - Room 102, Fire Area 32. "
* Professional Loss Control, Inc. 83/12/20 7pp 21753:006
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090638 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Laydown Area Room 602, Fire Area 48A. "
* Professional Loss Control, Inc. 83/12/20. 4pp 21752:299
24X Fiche. 50-352, 84/01/04, 8401090477

--8401090641 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Recombiner Access Area Room 259, Fire Area 1N. "
* Professional Loss Control, Inc. 83/12/20 3pp. 21753:077
24X Fiche: 50-352, 84/01/04, 8401090477.

--8401090642 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 114, Fire Area 37. "
* Professional Loss Control, Inc. 83/12/20. 5pp 21753:013
24X Fiche. 50-352, 84/01/04, 8401090477.

--8401090646 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Recirculation Filter Compartments Room 618, Fire Areas 31A & 31B. "
* Professional Loss Control, Inc. 83/12/20 3pp 21752 303
24X Fiche 50-352, 84/01/04, 8401090477

--8401090650 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 113, Fire Area 36. "
* Professional Loss Control, Inc. 83/12/20 5pp 21753 018
24X Fiche 50-352, 84/01/04, 8401090477

--8401090654 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Exhaust Fan Room, Room 615, Fire Area 30A. "
* Professional Loss Control, Inc. 83/12/20 3pp 21752 306
24X Fiche 50-352, 84/01/04, 8401090477

--8401090657 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Receiving Tank Room 163, Fire Area 19. "
* Professional Loss Control, Inc. 83/12/20 4pp 21753 080
24X Fiche 50-352, 84/01/04, 8401090477

--8401090658 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft RHR HX & Pump Room - Room 103, Fire Area 31. "
* Professional Loss Control, Inc. 83/12/20 7pp 21753 023
24X Fiche 50-352, 84/01/04, 8401090477

--8401090661 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 164, Fire Area 1A. "
* Professional Loss Control, Inc. 83/12/20 3pp 21753 084
24X Fiche 50-352, 84/01/04, 8401090477

--8401090665 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Reactor Vent Supply Fan Room, Room 407, Fire Area 49. "
* Professional Loss Control, Inc. 83/12/20 4pp. 21752.309
24X Fiche 50-352, 84/01/04, 8401090477

--8401090666 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg RCIC Pump Room 108, Fire Area 33. "
* Professional Loss Control, Inc. 83/12/20 9pp 21753.030
24X Fiche 50-352, 84/01/04, 8401090477

--8401090668 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Diesel Generator Encl Elevation 217-Ft Diesel Generator Cell 1A, Fire Area 79. "
* Professional Loss Control, Inc. 83/12/20 4pp 21753 087
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090671 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 304-Ft Fan Room, Fire Zone 27. "
* Professional Loss Control, Inc. 83/12/20 8pp 21753:091
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090672 "Structural Steel Analysis for Limerick Generating Station, Units 1 & 2 Control Structure Elevation 217-Ft Switchgear Area, Fire Area 2. "
* Professional Loss Control, Inc. 83/11/01 17pp 21752.327
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090674 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 110, Fire Area 35. "
* Professional Loss Control, Inc. 83/12/20 5pp 21753 039
24X Fiche 50-352, 84/01/04, 8401090477

--8401090675 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Equipment Compartment Exhaust Filter Room 616 & 617, Fire Areas 30B & 30C. "
* Professional Loss Control, Inc. 83/12/20 3pp 21752 313
24X Fiche: 50-352, 84/01/04, 8401090477

--8401090677 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 217-Ft General Floor Area, Fire Area 44. "
* Professional Loss Control, Inc. 83/11/01 7pp 21752 344
24X Fiche 50-352, 84/01/04, 8401090477

--8401090679 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg, Elevation 253-Ft General Floor Area, Fire Area 45A. "
* Professional Loss Control, Inc. 83/11/01 6pp 21752 351
24X Fiche: 50-352, 84/01/04, 8401090477

--B401090681 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Corridor - Room 111, Fire Area 40 "
* Professional Loss Control, Inc 83/12/20 3pp 21753 055
24X Fiche 50-352,84/01/04, B401090477

--B401090684 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Pump Rooms, Rooms 161, 162 & 163, Fire Area 1J "
* Professional Loss Control, Inc 83/12/20 4pp 21753 044
24X Fiche 50-352,84/01/04, B401090477

--B401090687 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Access Area Room 629, Fire Area 28A "
* Professional Loss Control, Inc 83/12/20 3pp 21752 316
24X Fiche 50-352,84/01/04, B401090477

--B401090688 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft HPCI Pump & Turbine Room - Room 109, Fire Area 34 "
* Professional Loss Control, Inc 83/12/20 5pp 21753 038
24X Fiche 50-352,84/01/04, B401090477

--B401090691 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 166, Fire Area 1B "
* Professional Loss Control, Inc 83/12/20 4pp 21753 048
24X Fiche 50-352,84/01/04, B401090477

--B401090692 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 217-Ft Safeguard Sys Area Room 309, Fire Area 43 "
* Professional Loss Control, Inc 83/12/20 4pp 21753 063
24X Fiche 50-352,84/01/04, B401090477

--B401090695 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Filter Compartment Room 624, Fire Area 28B "
* Professional Loss Control, Inc 83/12/20 3pp 21752 319
24X Fiche 50-352,84/01/04, B401090477

--B401090698 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 253-Ft Main Steam & Feedwater Pipe Tunnel, Fire Zone 46 "
* Professional Loss Control, Inc 83/12/20 3pp 21753 052
24X Fiche 50-352,84/01/04, B401090477

--B401090701 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft East Chiller Equipment Room, Room 263, Fire Area 1M "
* Professional Loss Control, Inc 83/12/20 5pp 21752 322
24X Fiche 50-352,84/01/04, B401090477

F. Security, medical, emergency & fire protection plans

B401090796 Summary of 831213 meeting w/util, Bechtel, BN, & Professional Loss Control, Inc re util submittals on two open SER fire protection items Viewgraphs encl
KINTNER, L. Licensing Branch 1 83/12/23 Licensing Branch 1
44pp 21768 001 24X Fiche 50-352,83/12/23, B401090796

B401090334 Forwards Rev 7 to emergency plan
BRADLEY, E J Philadelphia Electric Co 83/12/30 DENTON, H R,
Office of Nuclear Reactor Regulation, Director 3pp. 21781 001
24X Fiche 50-352,83/12/30, B401090334

--B401090348 Rev 7 to emergency plan
* Philadelphia Electric Co 83/12/31 229pp 21781 005 24X
Fiche 50-352,83/12/30, B401090334

B401090477 Forwards repts re means for assuring fire protection for structural steel in lieu of strict application of protective coating, per 831213 request & SER (NUREG-0991)
MEMPER, J B Philadelphia Electric Co 84/01/04 SCHWENGER, A
Licensing Branch 2 28pp 21752 248 24X Fiche 50-352,84/01/04, B401090477

--B401090485 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Bump Room 115, Fire Area 3J "
* Professional Loss Control, Inc 83/12/20 5pp 21752 255
24X Fiche 50-352,84/01/04, B401090477

--B401090490 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Corridor Room 118, Fire Area 3J "
* Professional Loss Control, Inc 83/12/20 3pp 21752 260
24X Fiche 50-352,84/01/04, B401090477

--B401090494 "Structural Steel Analysis for Limerick Generating Station, Reactor Bldg Elevation 198-Ft Pipe Tunnel Room 202, Fire Area 76 "
* Professional Loss Control, Inc 83/12/20 3pp 21752 263
24X Fiche 50-352,84/01/04, B401090477

--B401090599 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 201-Ft Cooling Water HX Area Room 207, Fire Area 41 "
* Professional Loss Control, Inc 83/12/20 10pp 21752 266
24X Fiche 50-352,84/01/04, B401090477

--B401090609 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 201-Ft Safeguard Sys Access Room 200, Fire Area 42A "
* Professional Loss Control, Inc 83/12/20 15pp 21752 276
24X Fiche 50-352,84/01/04, B401090477

--B401090619 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Corridor Room 605, Fire Area 48A "
* Professional Loss Control, Inc 83/12/20 4pp 21752 291
24X Fiche 50-352,84/01/04, B401090477

--B401090631 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft West Chiller Equipment Room, Room 258, Fire Area 11 "
* Professional Loss Control, Inc 83/12/20 5pp 21753 069
24X Fiche 50-352,84/01/04, B401090477

--B401090632 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Laydown Area Room 601, Fire Area 48A "
* Professional Loss Control, Inc 83/12/20 4pp 21752 295
24X Fiche 50-352,84/01/04, B401090477

--B401090636 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Radwaste Pipe Tunnel, Fire Area 115 "
* Professional Loss Control, Inc 83/12/20 3pp 21753 074
24X Fiche 50-352,84/01/04, B401090477

--B401090637 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft RHR HX & Pump Room - Room 102, Fire Area 32 "
* Professional Loss Control, Inc 83/12/20 7pp 21753 006
24X Fiche 50-352,84/01/04, B401090477

--B401090638 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Laydown Area Room 602, Fire Area 48A "
* Professional Loss Control, Inc 83/12/20 4pp 21752 299
24X Fiche 50-352,84/01/04, B401090477

--B401090641 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Recombiner Access Area Room 259, Fire Area 1N "
* Professional Loss Control, Inc 83/12/20 3pp 21753 077
24X Fiche 50-352,84/01/04, B401090477

--B401090642 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 114, Fire Area 37 "
* Professional Loss Control, Inc 83/12/20 5pp 21753 013
24X Fiche 50-352,84/01/04, B401090477

--B401090646 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Recirculation Filter Compartments Room 618, Fire Areas 31A & 31B "
* Professional Loss Control, Inc 83/12/20 3pp. 21752 303.
24X Fiche 50-352,84/01/04, B401090477

--B401090650 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 113, Fire Area 36 "
* Professional Loss Control, Inc 83/12/20 5pp 21753 018.
24X Fiche 50-352,84/01/04, B401090477

--B401090654 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Exhaust Fan Room, Room 613, Fire Area 50A "
* Professional Loss Control, Inc 83/12/20 3pp. 21752 306.
24X Fiche 50-352,84/01/04, B401090477

--B401090657 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Receiving Tank Room 163, Fire Area 1D "
* Professional Loss Control, Inc 83/12/20 4pp 21753 080
24X Fiche 50-352,84/01/04, B401090477

DOCKETED ITEMS

- B401090658 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft RHR HX & Pump Room - Room 103, Fire Area 31 "
* Professional Loss Control, Inc 83/12/20 7pp 21753 023
24X Fiche 50-352, 84/01/04, B401090477
- B401090661 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 164, Fire Area 1A "
* Professional Loss Control, Inc. 83/12/20 3pp. 21753:084
24X Fiche 50-352, 84/01/04, B401090477
- B401090665 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 313-Ft Reactor Vent Supply Fan Room, Room 607, Fire Area 49 "
* Professional Loss Control, Inc 83/12/20. 4pp 21752 309
24X Fiche: 50-352, 84/01/04, B401090477
- B401090666 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg RCIC Pump Room 108, Fire Area 33."
* Professional Loss Control, Inc 83/12/20 9pp 21753 030
24X Fiche: 50-352, 84/01/04, B401090477.
- B401090668 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Diesel Generator Encl Elevation 217-Ft Diesel Generator Cell 1A, Fire Area 79 "
* Professional Loss Control, Inc 83/12/20 4pp. 21753.087
24X Fiche: 50-352, 84/01/04, B401090477.
- B401090671 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 304-Ft Fan Room, Fire Zone 27 "
* Professional Loss Control, Inc 83/12/20 8pp 21753 091.
24X Fiche: 50-352, 84/01/04, B401090477
- B401090672 "Structural Steel Analysis for Limerick Generating Station, Units 1 & 2 Control Structure Elevation 217-Ft Switchgear Area, Fire Area 2."
* Professional Loss Control, Inc 83/11/01 17pp 21752 327
24X Fiche: 50-352, 84/01/04, B401090477
- B401090674 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Core Spray Pump Room 110, Fire Area 35."
* Professional Loss Control, Inc 83/12/20 5pp 21753 039
24X Fiche 50-352, 84/01/04, B401090477
- 01090675 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 331-Ft Equipment Compartment Exhaust Filter Room 616 & 617, Fire Areas 50B & 50C "
* Professional Loss Control, Inc 83/12/20 3pp 21752:313
24X Fiche 50-352, 84/01/04, B401090477
- 3401090677 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 217-Ft General Floor Area, Fire Area 44."
* Professional Loss Control, Inc 83/11/01. 7pp 21752 344
24X Fiche: 50-352, 84/01/04, B401090477
- B401090679 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg, Elevation 253-Ft General Floor Area, Fire Area 45A."
* Professional Loss Control, Inc 83/11/01 8pp 21752 351.
24X Fiche: 50-352, 84/01/04, B401090477
- 1090681 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft Corridor - Room 111, Fire Area 40."
* Professional Loss Control, Inc 83/12/20 3pp 21753.055
24X Fiche: 50-352, 84/01/04, B401090477
- 401090684 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Pump Rooms, Rooms 161, 162 & 163, Fire Area 1J "
* Professional Loss Control, Inc. 83/12/20 4pp 21753:044.
24X Fiche: 50-352, 84/01/04, B401090477.
- 1401090687 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Access Area Room 625, Fire Area 28A "
* Professional Loss Control, Inc. 83/12/20. 3pp. 21752:316.
24X Fiche: 50-352, 84/01/04, B401090477.
- B401090688 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 177-Ft MFCI Pump & Turbine Room - Room 109, Fire Area 34."
* Professional Loss Control, Inc. 83/12/20. 3pp. 21753 058
24X Fiche: 50-352, 84/01/04, B401090477
- B401090691 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 166, Fire Area 1B "
* Professional Loss Control, Inc 83/12/20 4pp 21753 048
24X Fiche: 50-352, 84/01/04, B401090477
- B401090692 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 217-Ft Safeguard Sys Area Room 309, Fire Area 43 "
* Professional Loss Control, Inc 83/12/20 6pp 21753 063
24X Fiche: 50-352, 84/01/04, B401090477
- B401090695 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Filter Compartment Room 624, Fire Area 28B "
* Professional Loss Control, Inc 83/12/20 3pp 21752 319
24X Fiche 50-352, 84/01/04, B401090477
- B401090698 "Structural Steel Analysis for Limerick Generating Station, Unit 1 Reactor Bldg Elevation 253-Ft Main Steam & Feedwater Pipe Tunnel, Fire Zone 46 "
* Professional Loss Control, Inc 83/12/20 3pp 21753 052
24X Fiche 50-352, 84/01/04, B401090477
- B401090701 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft East Chiller Equipment Room, Room 263, Fire Area 1M "
* Professional Loss Control, Inc 83/12/20 5pp 21752 322
24X Fiche 50-352, 84/01/04, B401090477
- B401190445 Forwards repts on structural steel fire resistance, requested at 831213 meeting w/NRC Results of analysis for three remaining plant areas containing safe shutdown equipment & exposed structural steel areas also encl
KEMPER, J S Philadelphia Electric Co 84/01/13 SCHWENGER, A
Licensing Branch 2 18pp 21849 175 24X Fiche 50-352, 84/01/13, B401190445
- B401190452 "Structural Steel Analysis for Limerick Generating Station Unit 1 Reactor Bldg, El 352-Ft, Refueling Floor, Fire Area 78A "
* Professional Loss Control, Inc 83/12/20 3pp 21849 193
24X Fiche 50-352, 84/01/13, B401190445
- B401190457 "Structural Steel Analysis for Limerick Generating Station Unit 1 Turbine Bldg, El 239-Ft, Feedwater Heater Room, Fire Area 88B "
* Professional Loss Control, Inc 84/01/04 7pp 21849 196
24X Fiche 50-352, 84/01/13, B401190445
- B401190462 "Structural Steel Analysis for Limerick Generating Station Unit 1 Turbine Bldg, El 295-Ft 3 Inches, Pipe Chase Svc Room 523 "
* Professional Loss Control, Inc 84/01/04 6pp 21849 203
24X Fiche 50-352, 84/01/13, B401190445
- B401190466 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 251 Ft, RHR Svc Water Valve Compartment, Fire Area 122E "
* Professional Loss Control, Inc 83/12/20 4pp 21849 209
24X Fiche 50-352, 84/01/13, B401190445
- B401190475 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 168 Ft, Essential Svc Water & RHR Svc Water Pump Area, Fire Area 122A "
* Professional Loss Control, Inc 83/12/20 3pp 21849 213
24X Fiche 50-352, 84/01/13, B401190445
- B401190478 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 251 Ft, Essential Svc Water & RHR Svc Water Pump Area, Fire Area 122C "
* Professional Loss Control, Inc 83/12/20 3pp 21849 216
24X Fiche: 50-352, 84/01/13, B401190445
- B401190483 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 248 Ft, Access Hatch Area, Fire Area 122D "
* Professional Loss Control, Inc 83/12/20 3pp 21849 219
24X Fiche: 50-352, 84/01/13, B401190445
- B401190486 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 237 Ft, RHR Svc Water Pipeway, Fire Area 122 F "
* Professional Loss Control, Inc 83/12/20 3pp 21849 222
24X Fiche: 50-352, 84/01/13, B401190445
- B401190489 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 237 Ft, Wet Pit, Fire Area 122B "
* Professional Loss Control, Inc 83/12/20 3pp 21849 225.
24X Fiche: 50-352, 84/01/13, B401190445

8401250234 Forwards procedures generation package per NUREG-0737, Suppl 1, Section 7 Encl withheld (ref 10CFR2 790)
DALTRUFF, S L Philadelphia Electric Co 84/01/19 SCHNENCER, A
Licensing Branch 2 5pp 21941 337 24X Fiche 50-352, 84/01/19,
8401250234

9 Adjudicatory correspondence

8401050268 Forwards State of PA Emergency Mgt Agency ltrs sent to Counties of Berks, Chester & Montgomery re public meetings on offsite emergency preparedness W/o encls Related correspondence
FERKIN, Z O Pennsylvania, Commonwealth of, 83/12/28 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 21727 167 24X Fiche 50-352, 83/12/28, 8401050268

8401060290 Answers to fifth set of interrogatories on QA/welding Contention Certificate of Svc encl
KEMPER, J B, WETTERHAHN, M Philadelphia Electric Co WETTERHAHN, M Conner & Wetterhahn 83/12/28 Air and Water Pollution Patrol 11pp 21741 280 24X Fiche 50-352, 83/12/28, 8401060290

8401060337 Answers to fourth set of interrogatories re QA welding Contention, constituting Discovery 18
KEMPER, J B, CORCORAN, J M Philadelphia Electric Co 83/12/28 Air and Water Pollution Patrol 17pp 21740 115 24X Fiche 50-352, 83/12/28, 8401060337

8401040295 Forwards util comments on Del-Aware request under 10CFR2 206 & answer to Del-Aware request for admission of new late-filed contentions in OL proceeding
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/12/29 BENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 21705 015 24X Fiche 50-352, 83/12/29, 8401040295

--8401040300 Answer opposing Del-Aware Unlimited, Inc request for admission of new, late-filed Contentions V-30, V-31, V-32 & V-33 Motion should be denied as reworded version of contentions previously rejected Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/12/29 Atomic Safety and Licensing Board Panel 27pp 21705 032 24X Fiche 50-352, 83/12/29, 8401040295

840110312 Forwards Air & Water Pollution Patrol ltr to Judges Brenner, Cole & Morris & sixth, seventh & eighth requests for interrogatories re Contention VI-1 Certificate of Svc encl Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/02 Atomic Safety and Licensing Board Panel 1p 21772 274 24X Fiche 50-352, 84/01/02, 840110312

--840110316 Informs that repts on addl deficiencies re welding & welder qualifications not received from Applicant Applicant causing time delays
ROMANO, F R Air and Water Pollution Patrol 84/01/02 BRENNER, L, COLE, R, MORRIS, P Atomic Safety and Licensing Board Panel 2pp 21772 275 24X Fiche 50-352, 84/01/02, 840110312

--840110319 Sixth request for interrogatories on Contention VI-1 re welding QA/QC
ROMANO, F R Air and Water Pollution Patrol 84/01/02 CONNER, T B Philadelphia Electric Co 1p 21772 277 24X Fiche 50-352, 84/01/02, 840110312

--840110321 Seventh request for interrogatories on Contention VI-1 re welding infractions
ROMANO, F R Air and Water Pollution Patrol 84/01/02 CONNER, T B Philadelphia Electric Co 1p 21772 278 24X Fiche 50-352, 84/01/02, 840110312

--840110322 Eighth request for interrogatories on Contention VI-1 re audit repts
ROMANO, F R Air and Water Pollution Patrol 84/01/02 2pp 21772, 279, 24X Fiche 50-352, 84/01/02, 840110312

8401050248 Order denying Friends of the Earth & Del-Aware 831214 request to bar JH Lavery & law firm of Conner & Wetterhahn from representing applicant before ASLB Intervenor arguments not convincing
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/03 Friends of the Earth 3pp 21729 146 24X Fiche 50-352, 84/01/03, 8401050248

8401060297 Forwards responses to Air & Water Pollution Patrol fourth request re Contention VI-1 interrogatories & fifth request for info W/o encls
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 84/01/03 ROMANO, F R Air and Water Pollution Patrol 2pp 21741 355 24X Fiche 50-352, 84/01/03, 8401060297

8401090256 Confirms 840105 telcon re response to util first set of interrogatories & request for production of documents to Air & Water Pollution Patrol on Contention II-1 Related correspondence
WETTERHAHN, M J Conner & Wetterhahn 84/01/05 ROMANO, F Romano, F 1p 21754 037 24X Fiche 50-352, 84/01/05, 8401090256

8401120200 Response opposing Del-Aware 831216 motion to admit four late-filed contentions Jurisdiction lies w/ASLB Intervenor has not met burden to reopen record or admit late-filed contentions Notice of appearance & Certificate of Svc encl
WILCOVE, M N Hearing Branch 2 84/01/05 Atomic Safety and Licensing Board Panel 23pp 21792 213 24X Fiche 50-352, 84/01/05, 8401120200

8401100145 Rept re involvement of util mgt in assuring quality of welding at Facility Rept submitted per ASLB memorandum & order confirming rulings made at 831028 prehearing conference Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co 84/01/06 53pp 21760 034 24X Fiche 50-352, 84/01/06, 8401100145

840110238 Initial interrogatories & request for production of documents on Contention I-42 Response by 840203 requested Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/01/09 Limerick Ecology Action 6pp 21772 281 24X Fiche 50-352, 84/01/09, 840110238

8401130078 Forwards Del-Aware Unlimited petition to reopen & for reconsideration, to set aside prior orders & to take other action filed before Delaware River Basin Commission on 820902 Petition referenced in applicant 831229 answer
RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co 84/01/09 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 7pp 21802 322 24X Fiche 50-352, 84/01/09, 8401130078

8401130122 First set of interrogatories & request for production of documents on Contention I-42 Certificate of Svc encl Related correspondence
RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn 84/01/10 Limerick Ecology Action 13pp 21802 087 24X Fiche 50-352, 84/01/10, 8401130122

8401160202 Motion to reconsider or to certify ASLB 840103 order re M Lavery participation in proceeding Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Demworth 84/01/11 Atomic Safety and Licensing Board Panel 6pp 21809 350 24X Fiche 50-352, 84/01/11, 8401160202

8401260142 Forwards answers to applicant first set of interrogatories & request for production of documents on Contention VI-1 & tenth request for info re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/11 Atomic Safety and Licensing Board Panel 1p 21956 113 24X Fiche 50-352, 84/01/11, 8401260142

--8401260149 Response to tenth request for info re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/10 Philadelphia Electric Co 1p 21956 114 24X Fiche 50-352, 84/01/11, 8401260142

--8401260153 Answers to first set of interrogatories & request for production of documents on Contentions VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/06 Philadelphia Electric Co 3pp 21956 115 24X Fiche 50-352, 84/01/11, 8401260142

--8401260163 Forwards eleventh & twelfth interrogatories re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/14, Atomic Safety and Licensing Board Panel 1p 21956 120 24X Fiche 50-352, 84/01/11, 8401260142

--8401260168 Eleventh interrogatory re Contention VI-1 (QA/QC) Details pertinent to safety-related pipe failures due to freeze induced bursts requested
ROMANO, F R Air and Water Pollution Patrol 84/01/14, Philadelphia Electric Co 1p 21956 121 24X Fiche 50-352, 84/01/11, 8401260142

--8401260172 Twelfth interrogatory re Contention VI-1 (QA/QC) Documents, logs & repts on all safety-related welds requested
ROMANO, F R Air and Water Pollution Patrol 84/01/14, Philadelphia Electric Co 2pp 21956 122 24X Fiche 50-352, 84/01/11, 8401260142

DOCKETED ITEMS

- 8401180192 Request to submit late-filed Contentions V-35 & V-36 or to reopen record re inadequate amount of water to operate cooling water sys Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Denworth 84/01/12 Commissioners 6pp 21841:312 24X
Fiche 50-352, 84/01/12, 8401180192
- 8401180183 Second set of interrogatories & request for production of documents on Contention VI-1 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/01/13 Air and Water Pollution Patrol 5pp
21841 348 24X Fiche 50-352, 84/01/13, 8401180183
- 8401230170 Forwards correspondence between DS Bonds of GAO & J Ray of ACRB re NRC use of PRA
WRIGHT, M A Hearing Branch 2 84/01/13 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 20pp
21938 169 24X Fiche 50-352, 84/01/13, 8401230170
- 8401190301 Forwards radiological emergency response plans for schools & health care facilities within emergency planning zone
Correspondence w/institutions involved in review will be forwarded. W/o encl Related correspondence.
BRADLEY, E J Philadelphia Electric Co 84/01/16 ZITZER, P Limerick Ecology Action 2pp 21850 316. 24X Fiche 50-352, 84/01/16, 8401190301
- 8401190195 Confirms telcon request for proposed Contention V-34 & attachments not received w/840111 ltr.
CONNER, T B Conner & Wetterhahn. CONNER, T B Philadelphia Electric Co 84/01/17 SUGARMAN, R J Sugarman & Denworth 1p 21850 337.
24X Fiche: 50-352, 84/01/17, 8401190195.
- 8401200095 Advises that blank magnetic tape being sent under separate cover for transfer of data assumptions used in CRAC analysis for facility
BUSH, M M Philadelphia, PA 84/01/17 VOGLER, B H Office of the Executive Legal Director 1p 21866 349 24X Fiche 50-352, 84/01/17, 8401200095
- 8401240146 Requests communication re final meeting scheduled for 840126 in Philadelphia, PA to discuss onsite emergency planning contentions
CONNER, T B Conner & Wetterhahn. CONNER, T B Philadelphia Electric Co 84/01/19 BUSH, M M Philadelphia, PA ZITZER, P Limerick Ecology Action 2pp. 21910 272. 24X Fiche. 50-352, 84/01/19, 8401240146
- 8401240091 Forwards proposed order confirming rulings made on record of 840112 evidentiary hearing. All parties save Friends of the Earth concur in order. W/o encl. Related correspondence
WETTERHAHN, M J Conner & Wetterhahn. WETTERHAHN, M J Philadelphia Electric Co 84/01/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel. 1p 21912 347 24X
Fiche 50-352, 84/01/20, 8401240091
- 01240137 Order confirming schedule for proposed findings on Contention V-4
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/20. 2pp
21908 354 24X Fiche 50-352, 84/01/20, 8401240137
- 01240174 Answer opposing, in every aspect, Intervenor Lewis 831227 motion for reconsideration of ASLB decision granting utility motion for summary disposition of Contention I-62 re pressurized thermal shock instructions unfounded.
WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M J Conner & Wetterhahn. 84/01/20 Atomic Safety and Licensing Board Panel 11pp 21908 280 24X Fiche 50-352, 84/01/20, 8401240174.
- 8401240181 Transmittal of CM Ferrell, EH Markee & JM Campe supplemental cross-examination plan Certificate of Svc encl.
WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M J Conner & Wetterhahn 84/01/20 6pp. 21908 291. 24X
Fiche 50-352, 84/01/20, 8401240174
- 8401240240 Order confirming 840111 & 12 rulings that offsite emergency planning contentions must be coordinated & received by 840131. Courtesy notification encl.
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/20 Pennsylvania, Commonwealth of, 6pp 21910 115. 24X
Fiche: 50-352, 84/01/20, 8401240240
- 8401240322 Preliminary set of initial interrogatories & request for production of documents re onsite emergency planning contentions. Certificate of Svc encl
CONNER, T B Philadelphia Electric Co. CONNER, T B Conner & Wetterhahn. 84/01/20 Limerick Ecology Action. 6pp. 21920 348. 24X Fiche. 50-352, 84/01/20, 8401240322.
- 8401260159 Amended notice of appearance in proceeding Certificate of Svc encl.
LOVE, A R Love, A R 84/01/20 3pp. 21956 034. 24X
Fiche: 50-352, 84/01/20, 8401260159.
- 8401270203 Advises that City of Philadelphia will meet w/Commonwealth of PA representatives on 840126 to discuss listed areas of concern Meeting w/util suggested prior to meeting w/state Related correspondence
SMOLEN, H Philadelphia, PA 84/01/23 CONNER, T B Conner & Wetterhahn 2pp 21982 134 24X Fiche 50-352, 84/01/23, 8401270203
- 8401300211 Answer in opposition to Del-Aware Unlimited, Inc request to reopen & admit new late-filed Contentions V-35 & V-36 Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 84/01/25 Atomic Safety and Licensing Board Panel 26pp 21995 230 24X Fiche 50-352, 84/01/25, 8401300211
- 8401310320 Answers to Del-Aware Unlimited 840111 motion for reconsideration or certification of ASLB 840103 order denying request to bar participation of applicant counsel Motion should be denied Certificate of Svc encl
CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 84/01/25 Atomic Safety and Licensing Board Panel 8pp. 22026 229 24X Fiche 50-352, 84/01/25, 8401310320
- 8401310328 Forwards motion for extension of discovery time based on new info & comments on applicant second set of interrogatories Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/26 Atomic Safety and Licensing Board Panel 1p 22021 279 24X
Fiche 50-352, 84/01/26, 8401310328
- 8401310333 Motion for extension of discovery time based on new info & to permit disinterested individual on site
ROMANO, F R Air and Water Pollution Patrol 84/01/26 Atomic Safety and Licensing Board Panel 2pp 22021 280 24X
Fiche: 50-352, 84/01/26, 8401310328
- 8401310337 Comments on applicant second set of interrogatories & forwards two motions for extension of discovery w/o encls
ROMANO, F R Air and Water Pollution Patrol 84/01/26 CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 1p 22021 282 24X Fiche 50-352, 84/01/26, 8401310328
- 8401310297 Forwards limited appearance ltr for svc to proceeding parties
LANE, V M Atomic Safety and Licensing Board Panel 84/01/27 CLEMENTS, W L Docketing & Services Branch 1p 22020 361 24X
Fiche 50-352, 84/01/27, 8401310297
- 8401310306 Submits limited appearance statement requesting OL not be issued due to lack of evacuation plan
* Affiliation Unknown 83/09/15 MORRIS, P Atomic Safety and Licensing Board Panel 1p 22020 362 24X Fiche 50-352, 84/01/27, 8401310297
- 8401310151 Notice of 840305 prehearing conference & 840306 evidentiary hearing re admissibility of proposed offsite emergency planning contentions.
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/30 2pp
22022 111 24X Fiche 50-352, 84/01/30, 8401310151
- 8401310227 Memorandum & order denying Del-Aware 840111 motion to reconsider or to certify ASLB 840103 memorandum & order denying requests to bar participation of counsel for applicant
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/30 3pp
22021 205 24X Fiche 50-352, 84/01/30, 8401310227.
- H General correspondence
- 8401040372 Expresses concern re 840801 fuel loading date since insufficient time allowed to obtain replacement parts per IE Bulletin 83-06
LEWIS, M I Lewis, M 83/12/30, EISENHUT, D Division of Licensing 2pp 21706 336 24X Fiche. 50-352, 83/12/30, 8401040372
- 8401170489 Responds to 831123 ltr re review of every safety-related weld at facility. Although violations identified, none have been severe or numerous enough to warrant requiring review of every safety-related weld.
MURLEV, T E Region 1, Office of Director 84/01/03 ROMANO, F R Air and Water Pollution Patrol 6pp 21844 261 24X
Fiche 50-352, 84/01/03, 8401170489
- 8401100292 Forwards Board of Supervisors of Limerick Township change of address
SCHWENGER, D H Limerick, PA 84/01/04 SCHWENGER, A Licensing Branch 2, 2pp 21759 198 24X Fiche 50-352, 84/01/04, 8401100292

DOCKETED ITEMS

227

8401170406 Responds to 831214 ltr re supplemental cooling water availability & FOIA request FOIA request will be handled in separate response Supplemental cooling sys not included in insp program
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
SUGARMAN, R J Sugarman & Denworth 4pp 21828 290 24X
Fiche 50-352, 84/01/10, 8401170406

K Utility Final Safety Analysis Report (FSAR) & amends

8401090334 Forwards Rev 27 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21781 001
24X Fiche 50-352, 83/12/30, 8401090334

--8401110303 Rev 27 to FSAR
* Philadelphia Electric Co 83/12/31 542pp 21781 234 24X
Fiche 50-352, 83/12/30, 8401090334

8401300226 Forwards affidavit of svc re distribution of Rev 27 to FSAR & Rev 16 to environ rept, per 810706 ltr
BRADLEY, E J Philadelphia Electric Co 84/01/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 22062 129
24X Fiche 50-352, 84/01/25, 8401300226

D Advisory Committee on Reactor Safeguards reports & correspondence

8401130127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee 821103 meeting w/NRR & BNL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PRA Viewgraphs encl
* ACRS - Advisory Committee on Reactor Safeguards 82/12/06
ACRS - Advisory Committee on Reactor Safeguards 38pp 21820 237
24X Fiche 50-000, 82/12/06, 8401130127

8401160399 Summary of ACRS Subcommittee on Limerick Generating Station 831007-08 meetings w/util in Pottstown, PA re review of OL application
* ACRS - Advisory Committee on Reactor Safeguards 84/01/11
ACRS - Advisory Committee on Reactor Safeguards 31pp 21823 284
24X Fiche 50-352, 84/01/11, 8401160399

8401250170 Forwards correspondence between DS Bonde of GAO & J Ray of ACRS re NRC use of PRA
WRIGHT, N A Hearing Branch 2 84/01/13 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 20pp 21798 169 24X Fiche 50-352, 84/01/13, 8401250170

G Inspection reports, IE Bulletins & correspondence

8401040040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J H Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401040040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060150

8401040198 Grants 90-day extension to respond to IE Bulletin 83-06 re nonconforming mats supplied by Tube-Line Corp, per 831117 request
STAROSTECKI, R Division of Project & Resident Programs 83/12/22
KEMPER, J S Philadelphia Electric Co 1p 21702 089 24X
Fiche 50-352, 83/12/22, 8401040198

8401100365 Forwards IE Insp Rept 50-352/83-21 on 831129-1202, No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
KEMPER, J S Philadelphia Electric Co 2pp 21763 311 24X
Fiche 50-352, 83/12/23, 8401100365

--8401100372 IE Insp Rept 50-352/83-21 on 831129-1202 No violations noted Major areas inspected preservice insp activities, including program review, procedure review & observation of work in progress
MCBREARTY, R A, DURR, J P Region 1, Office of Director 83/12/23
3pp 21763 313, 24X Fiche 50-352, 83/12/23, 8401100365

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers w/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401180193 Forwards IE Insp Rept 50-352/83-17 on 831031-1104 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/01/05
KEMPER, J S Philadelphia Electric Co 2pp 21841 319 24X
Fiche 50-352, 84/01/05, 8401180193

--8401180197 Notice of violation from insp on 831031-1104
* Region 1, Office of Director 84/01/05 1p 21841 321 24X
Fiche 50-352, 84/01/05, 8401180193

--8401180201 IE Insp Rept 50-352/83-17 on 831031-1104 Violation noted Failure to translate design requirements to specs, drawings, procedures & instructions for standby liquid control sys
EAPEN, P K, PRELL, J A, CAPHTON, D L Region 1, Office of Director 84/01/04 8pp 21841 322 24X Fiche 50-352, 84/01/05, 8401180193

8401180242 Forwards IE Insp Rept 50-352/83-16 on 831031-1107 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/05
KEMPER, J S Philadelphia Electric Co 2pp 21844 001 24X
Fiche 50-352, 84/01/05, 8401180242

--8401180248 IE Insp Rept 50-352/83-16 on 831031-1107 No violations noted Major areas inspected installation & QA/QC documentation for containment penetrations, piping installation & structural steel welding
NARROW, L Region 1, Office of Director DURR, J P Division of Engineering & Technical Programs 83/12/30 4pp 21844 003 24X
Fiche 50-352, 84/01/05, 8401180242

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 129pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401240504 Forwards IE Insp Rept 50-352/83-18 on 831102-08, 14 & 15 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
KEMPER, J S Philadelphia Electric Co 2pp 21907 349 24X
Fiche 50-352, 84/01/10, 8401240504

--8401240510 IE Insp Rept 50-352/83-18 on 831102-08, 14 & 15 No violations noted Major areas inspected previous insp findings, preoperational test procedure review, local leak rate test procedure review & test witnessing
BRIGGS, L, VITO, D, BETTENHAUSEN, L Region 1, Office of Director 84/01/09 6pp 21907 351 24X Fiche 50-352, 84/01/10, 8401240504

8401240596 Forwards IE Insp Repts 50-352/83-19 & 50-353/83-07 on 831017-1130 & notice of violation Requests response to concerns raised during 831202 meeting w/Bechtel re QA & GC be incorporated in response to notice of violation
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
KEMPER, J S Philadelphia Electric Co 2pp 21909 132 24X
Fiche 50-352, 84/01/10, 8401240596

--8401240600 Notice of violation from insp on 831017-1130
* Region 1, Office of Director 84/01/10 2pp 21909 134, 24X
Fiche 50-352, 84/01/10, 8401240596

--8401240604 IE Insp Repts 50-352/83-19 & 50-353/83-07 on 831017-1130 Violations noted failure to adequately control work on turned-over sys & failure to adequately inspect two pipe hanger installations.
CHAUDHARY, S K, WIGGINS, J T, CONNER, E L Region 1, Office of Director 84/01/04 13pp 21909 136, 24X Fiche 50-352, 84/01/10, 8401240596

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401310377 Forwards IE Insp Repts 50-352/83-23 & 50-353/83-08 on 831201-31 No violation noted.
STAROSTECKI, R Division of Project & Resident Programs 84/01/16
KEMPER, J S Philadelphia Electric Co 2pp 22012 308, 24X
Fiche 50-352, 84/01/16, 8401310377

DOCKETED ITEMS

--8401310384 IE Insp Repts 50-352/83-23 & 50-353/83-08 on 831201-31 No violation noted Major areas inspected followup on previous findings, plant tour, preoperational test procedure review & preoperation test witnessing
CHAUDHARY, S K, WIGGINS, J T, CONNER, E L Region 1, Office of Director 84/01/16 13pp 22012 310 24X Fiche 50-352, 84/01/16, 8401310377

8312120116 IE Info Notice 84-03, "Compliance w/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl.

JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl

JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

B Reportable occurrences, LERs & related correspondence

8401260239 Interim potential significant Deficiency Rept 94 re improperly mated auxiliary contacts on Westinghouse dc motor control ctrs. Initially reported on 831115 Survey of contacts incomplete Next rept will be submitted by 840203.
KEMPER, J S Philadelphia Electric Co 83/12/16 MURLEY, T E Region 1, Office of Director 1p 21955 208 24X Fiche 50-352, 83/12/16, 8401260239

8401260303 Interim significant Deficiency Rept BDR 120 re electro-hydraulic HVAC valve actuators supplied by Paul Munroe Hydraulics, Inc. Initially reported on 831122 Actuators returned to vendor for overhaul. Final rept due in 9 months
KEMPER, J S Philadelphia Electric Co 83/12/22 MURLEY, T E Region 1, Office of Director 2pp 21955 139 24X Fiche 50-352, 83/12/22, 8401260303

1260372 Interim significant Deficiency Rept BDR 107 re defective contact relays. Initially reported on 831129 Relays undergoing analysis & testing Next rept expected by 840330
KEMPER, J S Philadelphia Electric Co 83/12/28 MURLEY, T E Region 1, Office of Director 3pp 21955 119 24X Fiche 50-352, 83/12/28, 8401260372

1230189 Final significant Deficiency Rept BDR 85 re potential defect in reactor water cleanup sys isolation valve control circuit Initially reported on 830912 Condition not design QA or hardware deficiency & not reportable per 10CFR50.55(e).
KEMPER, J S Philadelphia Electric Co 84/01/03 MURLEY, T E Region 1, Office of Director 2pp 21884 158 24X Fiche 50-352, 84/01/03, 8401230189

8401270215 Final significant Deficiency Rept BDR 108 re Brown Boveri 480-volt solid state trip devices. Initially reported on 831205. All defective devices w/silicon-controlled rectifiers will be returned to manufacturer for repairs
KEMPER, J S Philadelphia Electric Co 84/01/04 MURLEY, T E Region 1, Office of Director 3pp 21979 148 24X Fiche 50-352, 84/01/04, 8401270215

hearing transcripts on non-antitrust matters

1120213 Transcript of 840109 hearing in Philadelphia, PA Pp 5, 916-1024.
* Atomic Safety and Licensing Board Panel 84/01/09 108pp 21791 207 24X Fiche 50-352, 84/01/09, 8401120213

11130309 Transcript of 840110 hearing in Philadelphia, PA Pp 6, 029-1, 214.
* Atomic Safety and Licensing Board Panel 84/01/10 225pp 11800 001 24X Fiche 50-352, 84/01/10, 8401130309

11160004 Transcript of 840111 hearing in Philadelphia, PA Pp 6, 215-6, 434.
* Atomic Safety and Licensing Board Panel 84/01/11 262pp 21808 038 24X Fiche 50-352, 84/01/11, 8401160004

01180007 Transcript of 840112 hearing in Philadelphia, PA Pp 6, 435-6, 434.
* Atomic Safety and Licensing Board Panel 84/01/12 232pp 21840 001 24X Fiche 50-352, 84/01/12, 8401180007

1401180005 Transcript of 840113 hearing in Philadelphia, PA Pp 6, 654-6, 795 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 84/01/13 150pp 21841 001 24X Fiche 50-352, 84/01/13, 8401180005

8401250154 Supplemental testimony of CM Farrell, EH Marice & KM Campe re Friends of the Earth Contentions V-3a & V-3b Certificate of Svc encl
FERRELL, C M, MARKEE, E H, CAMPE, K M NRC - No Detailed Affiliation Given 84/01/16 166pp 21936 224 24X Fiche 50-352, 84/01/16, 8401250154

8401200021 Transcript of 840117 hearing in Philadelphia, PA Pp 6, 795-4, 915
* Atomic Safety and Licensing Board Panel 84/01/17 268pp 21864 001 24X Fiche 50-352, 84/01/17, 8401200021

8401230385 Transcript of 840118 hearing in Philadelphia, PA Pp 6, 916-7, 122
* Atomic Safety and Licensing Board Panel 84/01/18 200pp 21873 088 24X Fiche 50-352, 84/01/18, 8401230385

8401260333 Transcript of 840123 hearing in Philadelphia, PA Pp 7, 123 - 7, 226 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/23 121pp 21955 241 24X Fiche 50-352, 84/01/23, 8401260333

8401270091 Transcript of 840124 hearing in Philadelphia, PA Pp 7, 227-7, 413
* Atomic Safety and Licensing Board Panel 84/01/24 186pp 21973 040 24X Fiche 50-352, 84/01/24, 8401270091

8401270206 Transcript of 840125 hearing in Philadelphia, PA Pp 7, 417-7, 564
* Atomic Safety and Licensing Board Panel 84/01/25 147pp 21972 101 24X Fiche 50-352, 84/01/25, 8401270206

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

8401090772 Grants 831110 request for time extension to 840415 for submission of formal 120-day response to Generic Ltr 83-28, "Clarification of Required Actions Based on Generic Implications of Salem ATWS Events"
SCHWENCER, A Licensing Branch 2 83/12/15 BAUER, E O Philadelphia Electric Co 3pp 21767 060 24X Fiche 50-353, 83/12/15, 8401090772

8401030321 Forwards request for addl info re environ qualification program License application should be amended to comply w/ encl requirements Info requested by 831230
SCHWENCER, A Licensing Branch 2 83/12/19 BAUER, E O Philadelphia Electric Co 3pp 21693 310 24X Fiche 50-352, 83/12/19, 8401030321

8401040065 Notification of 840106 meeting w/util in Bethesda, MD to discuss applicant analysis of tornado missiles for utility
CAMPAGNONE, M Licensing Branch 2 83/12/23 SCHWENCER, A Licensing Branch 2 4pp 21711 326 24X Fiche 50-352, 83/12/23, 8401040065

8401190142 Notification of cancellation of 840106 meeting w/util in Bethesda, MD to discuss analysis of tornado missiles for UHS
CAMPAGNONE, M J Licensing Branch 2 83/12/23 SCHWENCER, A Licensing Branch 2 4pp 21871 010 24X Fiche 50-352, 83/12/23, 8401190142

8401040091 Forwards Procedure LIM UT-1, Rev 1, "Reg Guide 1.150 Method for Compliance," per commitment at 830831 meeting to provide description of qualification of DE ultrasonic test process for reactor pressure vessel insp
KEMPER, J S Philadelphia Electric Co 83/12/28 EISENHUT, D O Division of Licensing 2pp 21703 210 24X Fiche 50-352, 83/12/28, 8401040091

8401110162 Notification of 840117-20 meetings w/util at site to perform audits of equipment by NRC pump & valve operability review team & seismic qualification review team
KINTNER, L L Licensing Branch 1 83/12/28 SCHWENCER, A Licensing Branch 2 4pp 21795 216 24X Fiche 50-352, 83/12/28, 8401110162

8401090334 Amend 60 to OL application, consisting of Rev 7 to emergency plan (PDR Category F), Rev 27 to FSAR (PDR Category K), Rev 16 to environ rept - OL stage (PDR Category C) & Rev 4 to mechanical equipment environ qualification rept
BRADLEY, E J Philadelphia Electric Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21781 001 24X Fiche 50-352, 83/12/30, 8401090334

8401110477 Responds to 831214 ltr re late notification of NRC 831129 meeting w/util & erroneous separation of dockets
SCHWENCER, A Licensing Branch 2 83/12/30 SUGARMAN, R J Sugarmann & Denworth 1p 21795 352 24X Fiche 50-352, 83/12/30, 8401110477

DOCKETED ITEMS

229

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401230024 Forwards responses to Environ Qualification Section 831219 request for addl info Responses will be included in Rev 1 to environ qualification rept scheduled for submittal in Apr 1984
KEMPER, J S Philadelphia Electric Co 84/01/16 SCHWENCER, A Licensing Branch 2 529pp 21886 117 24X Fiche 50-352, 84/01/16, 8401230024

--8401230028 Rev 1 to "Drywell Temp Response to Small Steam Break, Realistic Environ Qualification Envelope"
NGUYEN, D V, JONES, D D General Electric Co 83/11/18 12pp 21887 274 24X Fiche 50-352, 84/01/16, 8401230024

C Utility Environmental Report (ER), amends & correspondence

8401090334 Forwards Rev 16 to environ rept - DL stage
BRADLEY, E J Philadelphia Electric Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21781 001 24X Fiche 50-352, 83/12/30, 8401090334

--8401103008 Rev 16 to environ rept
* Philadelphia Electric Co 83/12/31 14pp 21783 056 24X Fiche 50-352, 83/12/30, 8401090334

8401300226 Forwards affidavit of svc re distribution of Rev 27 to FSAR & Rev 16 to environ rept, per 810706 ltr
BRADLEY, E J Philadelphia Electric Co 84/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22062, 129, 24X Fiche 50-352, 84/01/25, 8401300226

8401310395 Advises that goat farm established in area since agricultural land use data presented in environ rept - DL stage compiled Draft page changes to environ rept - DL stage encl Rev scheduled for Feb 1984
KEMPER, J S Philadelphia Electric Co 84/01/25 SCHWENCER, A Licensing Branch 2 14pp 22018 005 24X Fiche 50-352, 84/01/25, 8401310395

D NRC Draft/Final Environmental Statements, suppl & correspondence

8401030297 Forwards Suppl 1 to DES & FR notice of availability After receipt of comments, DES will be prepared w/o DES
SCHWENCER, A Licensing Branch 2 83/12/16 PERRIN, S Environmental Protection Agency 2pp 21693 350, 24X Fiche 50-352, 83/12/16, 8401030297

--8401030301 Notice of availability of Suppl 1 to DES
SCHWENCER, A Licensing Branch 2 83/12/16 2pp 21693, 352 24X Fiche 50-352, 83/12/16, 8401030297

8401030309 Forwards Suppl 1 to DES (NUREG-0974) for review & comment. Response requested in 45 days w/o encl.
SCHWENCER, A Licensing Branch 2 83/12/16 WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration App. 21693 337 24X Fiche 50-352, 83/12/16, 8401030309

8401040057 Forwards FR notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2 83/12/16 DAVIS, J F Affiliation Unknown CHERRY, M Cherry, M M /Cherry, Flynn & Kanter ip. 21711, 330 24X Fiche 50-352, 83/12/16, 8401040057

--8401040064 Notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2 83/12/16 3pp 21711-331 24X Fiche 50-352, 83/12/16, 8401040057

8401103070 Forwards FR notice of availability of Suppl 1 to DES (NUREG-0974)
SCHWENCER, A Licensing Branch 2 83/12/16 BAUER, E O Philadelphia Electric Co 3pp 21794 293 24X Fiche 50-352, 83/12/16, 8401103070

8401060482 Forwards DES for facilities Further comments to NRC requested within 3 wks w/o encl
HAGER, O W Maryland, State of 83/12/20 PYERS, C, SACHS, H, FREDERICK, L Maryland, State of 1p 21740 202 24X Fiche 50-352, 83/12/20, 8401060482

8401260061 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF LIMERICK GENERATING STATION, UNITS 1 AND 2 Docket Nos 50-352 And 50-353 (Philadelphia Electric Company)
* Division of Licensing NUREG-0974 801 83/12/31 157pp 21990 001 24X Fiche 50-352, 83/12/31, 8401260061

8401160263 Advises that Suppl 1 to DES reviewed No substantive comments made
BARBIER, N J Army, Dept of, Corps of Engineers 84/01/09 SCHWENCER, A Licensing Branch 2 1p 21813 301 24X Fiche 50-352, 84/01/09, 8401160263

E NRC Safety Evaluation Report (SER), suppl & correspondence

8401100034 Forwards 8SER 1 (NUREG-0991) w/o encl
SCHWENCER, A Licensing Branch 2 83/12/13 BAUER, E O Philadelphia Electric Co 4pp 21777 175 24X Fiche 50-352, 83/12/13, 8401100034

8401030177 Summary of 830930 meeting w/util & QE in King of Prussia, PA re Instrumentation & Control Sys Branch SER issue on plant instrument endpoints
MARTIN, R E Licensing Branch 2 83/12/19 Licensing Branch 2 6pp 21695 242 24X Fiche 50-352, 83/12/19, 8401030177

8401090796 Summary of 831213 meeting w/util, Bechtel, BNL & Professional Loss Control, Inc re util submittals on two open SER fire protection items Viewgraphs encl
KINTNER, L Licensing Branch 1, 83/12/23 Licensing Branch 1 44pp 21768 001 24X Fiche 50-352, 83/12/23, 8401090796

8401090477 Forwards repts re means for assuring fire protection for structural steel in lieu of strict application of protective coating, per 831213 request & SER (NUREG-0991).
KEMPER, J S Philadelphia Electric Co 84/01/04, SCHWENCER, A, Licensing Branch 2 28pp 21752 248 24X Fiche 50-352, 84/01/04, 8401090477

--8401090494 "Structural Steel Analysis for Limerick Generating Station, Reactor Bldg Elevation 198-Ft Pipe Tunnel Room 202, Fire Area 76"
* Professional Loss Control, Inc 83/12/20 3pp 21752, 263, 24X Fiche 50-352, 84/01/04, 8401090477

F Security, medical, emergency & fire protection plans

8401090796 Summary of 831213 meeting w/util, Bechtel, BNL & Professional Loss Control, Inc re util submittals on two open SER fire protection items Viewgraphs encl
KINTNER, L Licensing Branch 1, 83/12/23 Licensing Branch 1 44pp 21768 001 24X Fiche 50-352, 83/12/23, 8401090796

8401090334 Forwards Rev 7 to emergency plan
BRADLEY, E J Philadelphia Electric Co 83/12/30, DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21781:001 24X Fiche 50-352, 83/12/30, 8401090334

--8401090348 Rev 7 to emergency plan
* Philadelphia Electric Co, 83/12/31 229pp, 21781:005 24X Fiche 50-352, 83/12/30, 8401090334

8401090477 Forwards repts re means for assuring fire protection for structural steel in lieu of strict application of protective coating, per 831213 request & SER (NUREG-0991).
KEMPER, J S Philadelphia Electric Co, 84/01/04, SCHWENCER, A, Licensing Branch 2, 28pp 21752 248 24X Fiche 50-352, 84/01/04, 8401090477

--8401090494 "Structural Steel Analysis for Limerick Generating Station, Reactor Bldg Elevation 198-Ft Pipe Tunnel Room 202, Fire Area 76"
* Professional Loss Control, Inc 83/12/20 3pp 21752:263 24X Fiche 50-352, 84/01/04, 8401090477

DOCKETED ITEMS

- B401090431 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft West Chiller Equipment Room, Room 238, Fire Area 11 "
* Professional Loss Control, Inc 83/12/20 5pp 21753 067
24X Fiche 50-352, 84/01/04, B401090477
- B401090434 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Radwaste Pipe Tunnel, Fire Area 115 "
* Professional Loss Control, Inc 83/12/20 3pp 21753 074
24X Fiche 50-352, 84/01/04, B401090477
- B401090441 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft Recombiner Access Area Room 239, Fire Area 1N "
* Professional Loss Control, Inc 83/12/20 3pp 21753 077
24X Fiche 50-352, 84/01/04, B401090477.
- B401090457 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Receiving Tank Room 163, Fire Area 10 "
* Professional Loss Control, Inc 83/12/20 4pp 21753 080
24X Fiche 50-352, 84/01/04, B401090477
- B401090461 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 164, Fire Area 1A "
* Professional Loss Control, Inc 83/12/20 3pp 21753 084
24X Fiche 50-352, 84/01/04, B401090477
- B401090471 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 304-Ft Fan Room, Fire Zone 27, "
* Professional Loss Control, Inc. 83/12/20 8pp 21753.091.
24X Fiche 50-352, 84/01/04, B401090477.
- B401090472 "Structural Steel Analysis for Limerick Generating Station, Units 1 & 2 Control Structure Elevation 217-Ft Switchgear Area, Fire Area 2, "
* Professional Loss Control, Inc. 83/11/01. 17pp. 21752 327
24X Fiche 50-352, 84/01/04, B401090477
- B401090484 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Backwash Pump Rooms, Rooms 161, 162 & 163, Fire Area 1J "
* Professional Loss Control, Inc. 83/12/20 4pp 21753 044
24X Fiche 50-352, 84/01/04, B401090477
- B401090487 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Access Area Room 623, Fire Area 28A "
* Professional Loss Control, Inc. 83/12/20 3pp 21752 316
24X Fiche 50-352, 84/01/04, B401090477
- B401090491 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 180-Ft Corridor 166, Fire Area 1B, "
* Professional Loss Control, Inc 83/12/20 4pp 21753 048.
24X Fiche: 50-352, 84/01/04, B401090477.
- B401090495 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 332-Ft Standby Gas Treatment Sys Filter Compartment Room 624, Fire Area 28B, "
* Professional Loss Control, Inc. 83/12/20 3pp. 21752 319
24X Fiche: 50-352, 84/01/04, B401090477
- B401090701 "Structural Steel Analysis for Limerick Generating Station, Control Structure Elevation 200-Ft East Chiller Equipment Room, Room 263, Fire Area 1M, "
* Professional Loss Control, Inc 83/12/20. 5pp. 21752 322
24X Fiche: 50-352, 84/01/04, B401090477
- B401190445 Forwards repts on structural steel fire resistance, requested at 831213 meeting w/NRC Results of analysis for three remaining plant areas containing safe shutdown equipment & exposed structural steel areas also encl
KEMPER, J B Philadelphia Electric Co. 84/01/13 SCHWENGER, A, Licensing Branch 2 18pp 21849 175 24X Fiche 50-352, 84/01/13, B401190445
- B401190446 "Structural Steel Analysis for Limerick Generating Station, Spray Pond Pump Structure, El 231 Ft, RHR Svc Water Valve Compartment, Fire Area 122E, "
* Professional Loss Control, Inc 83/12/20. 4pp 21849 209
24X Fiche. 50-352, 84/01/13, B401190445.
- B401190475 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 168 Ft, Essential Svc Water & RHR Svc Water Pump Area, Fire Area 122A,
* Professional Loss Control, Inc. 83/12/20 3pp. 21849 213
24X Fiche 50-352, 84/01/13, B401190445.
- B401190478 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 231 Ft, Essential Svc Water & RHR Svc Water Pump Area, Fire Area 122C
* Professional Loss Control, Inc 83/12/20 3pp 21849 216
24X Fiche. 50-352, 84/01/13, B401190445
- B401190483 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 268 Ft, Access Hatch Area, Fire Area 122D "
* Professional Loss Control, Inc 83/12/20 3pp 21849 219
24X Fiche 50-352, 84/01/13, B401190445
- B401190486 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 237 Ft, RHR Svc Water Pipeway, Fire Area 122 F "
* Professional Loss Control, Inc 83/12/20 3pp 21849 222
24X Fiche 50-352, 84/01/13, B401190445
- B401190489 "Structural Steel Analysis for Limerick Generating Station Spray Pond Pump Structure, El 237 Ft, Wet Pit, Fire Area 122B "
* Professional Loss Control, Inc 83/12/20 3pp 21849 225
24X Fiche 50-352, 84/01/13, B401190445
- B401250234 Forwards procedures generation package per NUREG-0737, Suppl 1, Section 7 Encl withheld (ref 10CFR2 790)
DALTRUFF, S L Philadelphia Electric Co 84/01/19 SCHWENGER, A Licensing Branch 2 5pp 21741 337 24X Fiche 50-352, 84/01/19, B401250234
- Q Adjudicatory correspondence
- B401050268 Forwards State of PA Emergency Mgt Agency ltrs sent to Counties of Berks, Chester & Montgomery re public meetings on offsite emergency preparedness w/o encls Related correspondence
FERKIN, Z Q Pennsylvania, Commonwealth of, 83/12/28 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 21727 167 24X Fiche 50-352, 83/12/28, B401050268
- B401060290 Answers to fifth set of interrogatories on GA/welding contention Certificate of Svc encl
KEMPER, J S, WETTERHAHN, M Philadelphia Electric Co WETTERHAHN, M Conner & Wetterhahn 83/12/28 Air and Water Pollution Patrol 11pp 21741 280 24X Fiche 50-352, 83/12/28, B401060290
- B401060357 Answers to fourth set of interrogatories re GA welding contention, constituting Discovery 18
KEMPER, J S, CORCORAN, J M Philadelphia Electric Co 83/12/28 Air and Water Pollution Patrol 17pp 21740 115 24X Fiche 50-352, 83/12/28, B401060357
- B401040295 Forwards util comments on Del-Aware request under 10CFR2 206 & answer to Del-Aware request for admission of new late-filed contentions in DL proceeding
CONNOR, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 21705 015 24X Fiche 50-352, 83/12/29, B401040295
- B401040300 Answer opposing Del-Aware Unlimited, Inc request for admission of new, late-filed Contentions V-30, V-31, V-32 & V-33 Motion should be denied as reworded version of contentions previously rejected Certificate of Svc encl
CONNOR, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/12/29 Atomic Safety and Licensing Board Panel 27pp 21705 032 24X Fiche 50-352, 83/12/29, B401040295
- B401110312 Forwards Air & Water Pollution Patrol ltr to Judges Brenner, Cole & Morris & sixth, seventh & eighth requests for interrogatories re Contention VI-1 Certificate of Svc encl Related correspondence.
ROMANO, F R Air and Water Pollution Patrol 84/01/02, Atomic Safety and Licensing Board Panel 1p 21772 274 24X Fiche 50-352, 84/01/02, B401110312
- B401110316 Informs that repts on addl deficiencies re welding & welder qualifications not received from applicant Applicant causing time delays
ROMANO, F R Air and Water Pollution Patrol 84/01/02 BRENNER, L, COLE, R, MORRIS, P Atomic Safety and Licensing Board Panel 2pp 21772 275 24X Fiche 50-352, 84/01/02, B401110312
- B401110319 Sixth request for interrogatories on Contention VI-1 re welding GA/GC
ROMANO, F R Air and Water Pollution Patrol 84/01/02 CONNER, T B Philadelphia Electric Co 1p 21772 277 24X Fiche 50-352, 84/01/02, B401110312

DOCKETED ITEMS

231

--840110321 Seventh request for interrogatories on Contention VI-1 re welding infractions
ROMANO, F R Air and Water Pollution Patrol 84/01/02
CONNER, T B Philadelphia Electric Co 1p 21772 278 24X
Fiche 50-352, 84/01/02, 840110312

--840110322 Eighth request for interrogatories on Contention VI-1 re audit repts
ROMANO, F R Air and Water Pollution Patrol 84/01/02 2pp
21772 279 24X Fiche 50-352, 84/01/02, 840110312

8401050248 Order denying Friends of the Earth & Del-Aware 831214 request to bar JH Lavery & law firm of Conner & Wetterhahn from representing applicant before ASLB Intervenor arguments not convincing
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/03
Friends of the Earth 3pp 21729 146 24X Fiche 50-352, 84/01/03, 8401050248

8401060297 Forwards responses to Air & Water Pollution Patrol fourth request re Contention VI-1 interrogatories & fifth request for info w/o encls
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 84/01/03 ROMANO, F R Air and Water Pollution Patrol 2pp 21741 355 24X Fiche 50-352, 84/01/03, 8401060297

8401090256 Confirms 840105 telcon re response to util first set of interrogatories & request for production of documents to Air & Water Pollution Patrol on Contention II-I Related correspondence
WETTERHAHN, M J Conner & Wetterhahn 84/01/05 ROMANO, F Romano, F 1p 21754 037 24X Fiche 50-352, 84/01/05, 8401090256

8401120200 Response opposing Del-Aware 831216 motion to admit four late-filed contentions Jurisdiction lies w/ASLB Intervenor has not met burden to reopen record or admit late-filed contentions Notice of appearance & Certificate of Svc encl
HILCOVE, M N Hearing Branch 2 84/01/05 Atomic Safety and Licensing Board Panel 23pp 21792 213 24X Fiche 50-352, 84/01/05, 8401120200

8401100145 Rept re involvement of util mgt in assuring quality of welding at facility Rept submitted per ASLB memorandum & order confirming rulings made at 831028 prehearing conference Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co 84/01/06 53pp
21760 034 24X Fiche 50-352, 84/01/06, 8401100145

8401110238 Initial interrogatories & request for production of documents on Contention I-42 Response by 840203 requested Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/01/09 Limerick Ecology Action 6pp 21772 281 24X Fiche 50-352, 84/01/09, 8401110238

8401130078 Forwards Del-Aware Unlimited petition to reopen & for reconsideration, to set aside prior orders & to take other action filed before Delaware River Basin Commission on 820902 Petition referenced in applicant 831227 answer
RADER, R M Conner & Wetterhahn RADER, R M Philadelphia Electric Co 84/01/09 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 9pp 21802 322 24X Fiche 50-352, 84/01/09, 8401130078

8401130122 First set of interrogatories & request for production of documents on Contention I-42 Certificate of Svc encl Related correspondence
RADER, R M Philadelphia Electric Co RADER, R M Conner & Wetterhahn 84/01/10 Limerick Ecology Action 13pp 21802 087 24X Fiche 50-352, 84/01/10, 8401130122

8401160202 Motion to reconsider or to certify ASLB 840103 order re M Lavery participation in proceeding Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Denworth 84/01/11 Atomic Safety and Licensing Board Panel 8pp 21809 350 24X Fiche 50-352, 84/01/11, 8401160202

8401260142 Forwards answers to applicant first set of interrogatories & request for production of documents on Contention VI-1 & tenth request for info re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/11 Atomic Safety and Licensing Board Panel 1p 21956 113 24X Fiche 50-352, 84/01/11, 8401260142

--8401260149 Response to tenth request for info re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/10 Philadelphia Electric Co 1p 21956 114 24X Fiche 50-352, 84/01/11, 8401260142

--8401260153 Answers to first set of interrogatories & request for production of documents on Contentions VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/06 Philadelphia Electric Co 5pp 21956 113 24X Fiche 50-352, 84/01/11, 8401260142

--8401260143 Forwards eleventh & twelfth interrogatories re Contention VI-1 Related correspondence
ROMANO, F R Air and Water Pollution Patrol 84/01/14 Atomic Safety and Licensing Board Panel 1p 21956 120 24X Fiche 50-352, 84/01/11, 8401260142

--8401260168 Eleventh interrogatory re Contention VI-1 (8A/8C) Details pertinent to safety-related pipe failures due to freeze induced bursts requested
ROMANO, F R Air and Water Pollution Patrol 84/01/14 Philadelphia Electric Co 1p 21956 121 24X Fiche 50-352, 84/01/11, 8401260142

--8401260172 Twelfth interrogatory re Contention VI-1 (8A/8C) Documents, logs & repts on all safety-related welds requested
ROMANO, F R Air and Water Pollution Patrol 84/01/14 Philadelphia Electric Co 2pp 21956 122 24X Fiche 50-352, 84/01/11, 8401260142

8401180192 Request to submit late-filed Contentions V-35 & V-36 or to reopen record re inadequate amount of water to operate cooling water sys Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman & Denworth 84/01/12 Commissioners 6pp 21841 312 24X Fiche 50-352, 84/01/12, 8401180192

8401180183 Second set of interrogatories & request for production of documents on Contention VI-1 Certificate of Svc encl
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/01/13 Air and Water Pollution Patrol 5pp 21841 348 24X Fiche 50-352, 84/01/13, 8401180183

8401250170 Forwards correspondence between DB Bonde of QAO & J Ray of ACRS re NRC use of PRA
WRIGHT, N A Hearing Branch 2 84/01/13 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 20pp 21938 169 24X Fiche 50-352, 84/01/13, 8401250170

8401190301 Forwards radiological emergency response plans for schools & health care facilities within emergency planning zone Correspondence w/institutions involved in review will be forwarded w/o encl Related correspondence
BRADLEY, E J Philadelphia Electric Co 84/01/16 ZITZER, P Limerick Ecology Action 2pp 21850 316 24X Fiche 50-352, 84/01/16, 8401190301

8401190195 Confirms telcon request for proposed Contention V-34 & attachments not received w/840111 ltr
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 84/01/17 SUGARMAN, R J Sugarman & Denworth 1p 21850 337 24X Fiche 50-352, 84/01/17, 8401190195

8401200095 Advises that blank magnetic tape being sent under separate cover for transfer of data assumptions used in CRAC analysis for facility
BUSH, M W Philadelphia, PA 84/01/17 VOGLER, B H Office of the Executive Legal Director 1p 21866 349 24X Fiche 50-352, 84/01/17, 8401200095

8401240146 Requests communication re final meeting scheduled for 840126 in Philadelphia, PA to discuss onsite emergency planning contentions
CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 84/01/19 BUSH, M W Philadelphia, PA ZITZER, P Limerick Ecology Action 2pp 21910 272 24X Fiche 50-352, 84/01/19, 8401240146

8401240091 Forwards proposed order confirming rulings made on record of 840112 evidentiary hearing. All parties save Friends of the Earth concur in order w/o encl Related correspondence
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 84/01/20 BRENNER, L, MORRIS, P A, COLE, R F Atomic Safety and Licensing Board Panel 1p 21912 349 24X Fiche 50-352, 84/01/20, 8401240091

8401240157 Order confirming schedule for proposed findings on Contention V-4
BRENNER, L Atomic Safety and Licensing Board Panel 84/01/20 2pp 21908 354 24X Fiche 50-352, 84/01/20, 8401240157

DOCKETED ITEMS

B401240174 Answer opposing, in every aspect, Intervenor Lewis B31227 motion for reconsideration of ASLB decision granting until motion for summary disposition of Contention I-62 re pressurized thermal shock. Insinuations unfounded
WETTERHAHN, M. J. Philadelphia Electric Co WETTERHAHN, M. J. Conner & Wetterhahn B4/01/20 Atomic Safety and Licensing Board Panel
11pp 21908 280 24X Fiche 50-352, B4/01/20, B401240174

--B401240181 Transmittal of CM Ferrell, EH Markee & KM Campe supplemental cross-examination plan Certificate of Svc encl
WETTERHAHN, M. J. Philadelphia Electric Co WETTERHAHN, M. J. Conner & Wetterhahn B4/01/20 App. 21908 291 24X
Fiche 50-352, B4/01/20, B401240174

B401240240 Order confirming B40111 & 12 rulings that offsite emergency planning contentions must be coordinated & received by B40131 Courtesy notification encl
BRENNER, L. Atomic Safety and Licensing Board Panel B4/01/20 Pennsylvania, Commonwealth of, 6pp 21910 115 24X
Fiche: 50-352, B4/01/20, B401240240

B401240322 Preliminary set of initial interrogatories & request for production of documents re onsite emergency planning contentions Certificate of Svc encl
CONNER, T. B. Philadelphia Electric Co CONNER, T. B. Conner & Wetterhahn B4/01/20 Limerick Ecology Action 6pp 21920 348 24X Fiche 50-352, B4/01/20, B401240322

B401260157 Amended notice of appearance in proceeding Certificate of Svc encl.
LOVE, A. R. Love, A. R. B4/01/20 3pp 21956:034 24X
Fiche 50-352, B4/01/20, B401260157.

B401270203 Advises that City of Philadelphia will meet w/Commonwealth of PA representatives on B40126 to discuss listed areas of concern Meeting w/Util suggested prior to meeting w/State. Related correspondence
SMOLEN, H. Philadelphia, PA B4/01/23 CONNER, T. B. Conner & Wetterhahn 2pp. 21982.134 24X Fiche: 50-352, B4/01/23, B401270203

B401300211 Answer in opposition to Del-Aware Unlimited, Inc request to reopen & admit new late-filed Contentions V-35 & V-36 Certificate of Svc encl.
CONNER, T. B. Philadelphia Electric Co. CONNER, T. B. Conner & Wetterhahn B4/01/25 Atomic Safety and Licensing Board Panel 2ppp 21995.230 24X Fiche, 50-352, B4/01/25, B401300211

B401310320 Answers to Del-Aware Unlimited B40111 motion for reconsideration or certification of ASLB B40103 order denying request to bar participation of applicant counsel. Motion should be denied. Certificate of Svc encl
CONNER, T. B. Philadelphia Electric Co CONNER, T. B. Conner & Wetterhahn, B4/01/25 Atomic Safety and Licensing Board Panel 8pp. 22026:229 24X Fiche: 50-352, B4/01/25, B401310320.

B401310328 Forwards motion for extension of discovery time based on new info & comments on applicant second set of interrogatories. Related correspondence
ROMANO, F. R. Air and Water Pollution Patrol B4/01/26. Atomic Safety and Licensing Board Panel 1p. 22021 279 24X
Fiche: 50-352, B4/01/26, B401310328.

B401310333 Motion for extension of discovery time based on new info & to permit disinterested individual on site.
ROMANO, F. R. Air and Water Pollution Patrol B4/01/26 Atomic Safety and Licensing Board Panel 2pp. 22021:280. 24X
Fiche: 50-352, B4/01/26, B401310328

B401310337 Comments on applicant second set of interrogatories & forwards two motions for extension of discovery w/o encls.
ROMANO, F. R. Air and Water Pollution Patrol. B4/01/26
CONNER, T. B. Conner & Wetterhahn CONNER, T. B. Philadelphia Electric Co. 1p. 22021:282. 24X Fiche, 50-352, B4/01/26, B401310328

01310297 Forwards limited appearance ltr for svc to proceeding parties.
LANE, V. M. Atomic Safety and Licensing Board Panel. B4/01/27
CLEMENTS, M. L. Docketing & Services Branch 1p 22020.361. 24X
Fiche: 50-352, B4/01/27, B401310297.

--B401310306 Submits limited appearance statement requesting OL not be issued due to lack of evacuation plan.
* Affiliation Unknown. B3/09/15 MORRIS, P. Atomic Safety and Licensing Board Panel 1p. 22020.362. 24X Fiche, 50-352, B4/01/27, B401310297

D1310151 Notice of B40305 prehearing conference & B40306 evidentiary hearing re admissibility of proposed offsite emergency planning contentions.
BRENNER, L. Atomic Safety and Licensing Board Panel B4/01/30. 2pp 22022:111. 24X Fiche: 50-352, B4/01/30, B401310151.

B401310227 Memorandum & order denying Del-Aware B40111 motion to reconsider or to certify ASLB B40103 memorandum & order denying requests to bar participation of counsel for applicant
BRENNER, L. Atomic Safety and Licensing Board Panel B4/01/30 3pp 22021:205 24X Fiche 50-352, B4/01/30, B401310227

H General correspondence

B401040372 Expresses concern re B40801 fuel loading date since insufficient time allowed to obtain replacement parts per IE Bulletin B3-06
LEWIS, M. J. Lewis, M. B3/12/30 EISENHUT, D. Division of Licensing 2pp 21706 336 24X Fiche 50-352, B3/12/30, B401040372

B401170489 Responds to B31123 ltr re review of every safety-related weld at facility Although violations identified, none have been severe or numerous enough to warrant requiring review of every safety-related weld
MURLEY, T. E. Region 1, Office of Director B4/01/03 ROMANO, F. R. Air and Water Pollution Patrol 6pp 21844 261 24X
Fiche 50-352, B4/01/03, B401170489

B401100292 Forwards Board of Supervisors of Limerick Township change of address
BOHMAN, B. H. Limerick, PA B4/01/04 SCHWENCER, A. Licensing Branch 2 2pp. 21759 198 24X Fiche 50-352, B4/01/04, B401100292

B401170406 Responds to B31214 ltr re supplemental cooling water availability & FOIA request FOIA request will be handled in separate response Supplemental cooling sys not included in insp program
STAROSTECKI, R. Division of Project & Resident Programs B4/01/10 SUGARMAN, R. J. Sugarman & Denuorth 4pp 21828 290 24X
Fiche: 50-352, B4/01/10, B401170406

K Utility Final Safety Analysis Report (FSAR) & amends

B401090334 Forwards Rev 27 to FSAR
BRADLEY, E. J. Philadelphia Electric Co B3/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 21781.001 24X Fiche 50-352, B3/12/30, B401090334

--B401110303 Rev 27 to FSAR.
* Philadelphia Electric Co B3/12/31 542pp 21781 234 24X
Fiche: 50-352, B3/12/30, B401090334

B401300226 Forwards affidavit of svc re distribution of Rev 27 to FSAR & Rev 16 to environ rept, per B10706 ltr
BRADLEY, E. J. Philadelphia Electric Co B4/01/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 22062 129 24X Fiche 50-352, B4/01/25, B401300226

O. Advisory Committee on Reactor Safeguards reports & correspondence

B401130127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee B21103 meeting w/MRR & BNL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PRA Viewgraphs encl.
* ACRS - Advisory Committee on Reactor Safeguards B2/12/06
ACRS - Advisory Committee on Reactor Safeguards 38pp 21820:237 24X Fiche: 50-000, B2/12/06, B401130127

B401160397 Summary of ACRS Subcommittee on Limerick Generating Station B31007-08 meetings w/Util in Pottstown, PA re review of OL application.
* ACRS - Advisory Committee on Reactor Safeguards. B4/01/11.
ACRS - Advisory Committee on Reactor Safeguards. 31pp. 21823 286 24X Fiche 50-352, B4/01/11, B401160397

B401250170 Forwards correspondence between DS Bonds of GAO & J Ray of ACRS re NRC use of PRA.
WRIGHT, N. A. Hearing Branch 2. B4/01/13 BRENNER, L. Atomic Safety and Licensing Board Panel 20pp 21938 169 24X
Fiche, 50-352, B4/01/13, B401250170

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J. M. Division of Rules and Records B3/10/20 ZAHNER, R. E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003. 24X
Fiche: 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement. B3/10/20 134pp. 21744.004 24X Fiche 50-000, B3/10/20, B401060040.

DOCKETED ITEMS

233

401040198 Grants 90-day extension to respond to IE Bulletin 83-06 re nonconforming mats supplied by Tube-Line Corp. per 83117 request
STARDSTECKI, R Division of Project & Resident Programs 83/12/22
KEMPER, J S Philadelphia Electric Co 1p 21702 089 24X
Fiche 50-352, 83/12/22, 8401040198

312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

401240596 Forwards IE Insp Repts 50-352/83-19 & 50-353/83-07 on 831017-1130 & notice of violation Requests response to concerns raised during 831202 meeting w/Bechtel re QA & QC be incorporated in response to notice of violation
STARDSTECKI, R Division of Project & Resident Programs 84/01/10
KEMPER, J S Philadelphia Electric Co 2pp 21909 132 24X
Fiche 50-352, 84/01/10, 8401240596

401240604 IE Insp Repts 50-352/83-19 & 50-353/83-07 on 831017-1130 Violations noted failure to adequately control work on turned-over sys & failure to adequately inspect two pipe hanger installations
CHAUDHARY, S K, WIGGINS, J T, CONNER, E L Region 1, Office of Director 84/01/04 13pp 21909 136 24X Fiche 50-352, 84/01/10, 8401240596

312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

401310377 Forwards IE Insp Repts 50-352/83-23 & 50-353/83-08 on 831201-31 No violation noted
STARDSTECKI, R Division of Project & Resident Programs 84/01/16
KEMPER, J S Philadelphia Electric Co 2pp 22012 308 24X
Fiche 50-352, 84/01/16, 8401310377

401310384 IE Insp Repts 50-352/83-23 & 50-353/83-08 on 831201-31 No violation noted Major areas inspected followup on previous findings, plant tour, preoperational test procedure review & preoperation test witnessing.
CHAUDHARY, S K, WIGGINS, J T, CONNER, E L Region 1, Office of Director 84/01/16 13pp 22012 310 24X Fiche 50-352, 84/01/16, 8401310377

312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

Reportable occurrences, LERs & related correspondence

401240239 Interim potential significant Deficiency Rept 94 re improperly mated auxiliary contacts on Westinghouse dc motor control ctrs Initially reported on 831115 Survey of contacts incomplete Next rept will be submitted by 840203
KEMPER, J S Philadelphia Electric Co 83/12/16
Region 1, Office of Director 1p 21955 208 24X
Fiche 50-352, 83/12/16, 8401240239

8401240303 Interim significant Deficiency Rept SDR 120 re electro-hydraulic HVAC valve actuators supplied by Paul Munroe Hydraulics, Inc Initially reported on 831122 Actuators returned to vendor for overhaul Final rept due in 9 months
KEMPER, J S Philadelphia Electric Co 83/12/22
Region 1, Office of Director 2pp 21955 139 24X
Fiche 50-352, 83/12/22, 8401240303

8401240372 Interim significant Deficiency Rept SDR 107 re defective Agastat relays Initially reported on 831129 Relays undergoing analysis & testing Next rept expected by 840330
KEMPER, J S Philadelphia Electric Co 83/12/28
Region 1, Office of Director 3pp 21955 119 24X
Fiche 50-352, 83/12/28, 8401240372

8401230189 Final significant Deficiency Rept SDR 85 re potential defect in reactor water cleanup sys isolation valve control circuit Initially reported on 830912 Condition not design, QA or hardware deficiency & not reportable per 10CFR50.55(a)
KEMPER, J S Philadelphia Electric Co 84/01/03
Region 1, Office of Director 2pp 21884 158 24X
Fiche: 50-352, 84/01/03, 8401230189

8401270215 Final significant Deficiency Rept SDR 108 re Brown Boveri 480-volt solid state trip devices Initially reported on 831205 All defective devices w/silicon-controlled rectifiers will be returned to manufacturer for repairs.
KEMPER, J S Philadelphia Electric Co 84/01/04
Region 1, Office of Director 3pp 21979 148 24X
Fiche 50-352, 84/01/04, 8401270215

8401300133 PNO-1-84-008 on 840124, util announced delay in completing Unit 2 due to PUC of PA ruling based on determination of no need for addl power
BAURACK, CONNER Region 1, Office of Director 84/01/24 1p
21998 286 24X Fiche 50-353, 84/01/24, 8401300133

T Hearing transcripts on non-antitrust matters

8401120213 Transcript of 840109 hearing in Philadelphia, PA Pp 5, 916-6, 024
* Atomic Safety and Licensing Board Panel 84/01/09 108pp.
21791 207 24X Fiche 50-352, 84/01/09, 8401120213

8401130309 Transcript of 840110 hearing in Philadelphia, PA Pp 6, 025-6, 214.
* Atomic Safety and Licensing Board Panel 84/01/10 225pp.
21800 001 24X Fiche 50-352, 84/01/10, 8401130309

8401160004 Transcript of 840111 hearing in Philadelphia, PA Pp 6, 434
* Atomic Safety and Licensing Board Panel 84/01/11 262pp
21808 038 24X Fiche 50-352, 84/01/11, 8401160004

8401180007 Transcript of 840112 hearing in Philadelphia, PA Pp 6, 435-6, 653
* Atomic Safety and Licensing Board Panel 84/01/12 232pp.
21840 001 24X Fiche 50-352, 84/01/12, 8401180007

8401180005 Transcript of 840113 hearing in Philadelphia, PA Pp 6, 694-6, 795 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/13 150pp
21841 001 24X Fiche 50-352, 84/01/13, 8401180005

8401250154 Supplemental testimony of CM Farrell, EH Markee & KM Campe re Friends of the Earth Contentions V-3a & V-3b, Certificate of Svc encl
FERRELL, C M, MARKEE, E H, CAMPE, K M NRC - No Detailed Affiliation Given 84/01/16 166pp. 21936 224 24X Fiche 50-352, 84/01/16, 8401250154

8401200021 Transcript of 840117 hearing in Philadelphia, PA Pp 6, 796-6, 915
* Atomic Safety and Licensing Board Panel 84/01/17 268pp
21864 001 24X Fiche 50-352, 84/01/17, 8401200021

8401230385 Transcript of 840118 hearing in Philadelphia, PA Pp 6, 916-7, 122
* Atomic Safety and Licensing Board Panel 84/01/18 200pp.
21873 088 24X Fiche 50-352, 84/01/18, 8401230385

8401240333 Transcript of 840123 hearing in Philadelphia, PA Pp 7, 123 - 7, 226 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 84/01/23 121pp
21955 241 24X Fiche 50-352, 84/01/23, 8401240333

8401270091 Transcript of 840124 hearing in Philadelphia, PA Pp 7, 227-7, 413
* Atomic Safety and Licensing Board Panel 84/01/24 184pp.
21973 040 24X Fiche 50-352, 84/01/24, 8401270091

DOCKETED ITEMS

B401270204 Transcript of B40125 hearing in Philadelphia, PA Pp 7, 417-7, 564.
 * Atomic Safety and Licensing Board Panel B4/01/25 147pp
 21972 101 24X Fiche 50-354, B4/01/25, B401270206

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B401060412 Forwards completed facility staffing survey per D Wagner B31206 request.
 MITTL, R L Public Service Electric & Gas Co of New Jersey.
 B3/12/19 SCHWENCER, A Licensing Branch 2 7pp 21741 037 24X
 Fiche 50-354, B3/12/19, B401060412

B401060486 Forwards "Monitoring of LNO & Liquid Petroleum Gas Shipping & Const Activities on Delaware River"
 MITTL, R L Public Service Electric & Gas Co. of New Jersey
 B3/12/27 SCHWENCER, A. Licensing Branch 2 2pp 21740 160 24X
 Fiche 50-354, B3/12/27, B401060486

--B401060493 "Monitoring of LNO & Liquid Petroleum Shipping & Const Activities on Delaware River"
 * Public Service Electric & Gas Co of New Jersey B3/12/31
 18pp 21740. 162 24X Fiche 50-354, B3/12/27, B401060486.

B401170323 Forwards "Salt Deposition from Hope Creek Cooling Towers & Potential Effect of Salt on Crops & Livestock," per DH Wagner request.
 MITTL, R L Public Service Electric & Gas Co of New Jersey
 B4/01/03 SCHWENCER, A. Licensing Branch 2 1p. 21829. 299 24X
 Fiche 50-354, B4/01/03, B401170323

--B401170327 "Salt Deposition from Hope Creek Cooling Towers & Potential Effect of Salt on Crops & Livestock," final rept
 LONDREB, E J. New Jersey, State of B0/09/16. 21pp. 21829 300
 24X Fiche. 50-354, B4/01/03, B401170323

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Bvc list encl
 EISENHUT, D. O. Division of Licensing B4/01/05 Consolidated
 Edison Co. of New York, Inc 16pp 21946 190. 24X
 Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
 Bvc list encl
 EISENHUT, D. O. Division of Licensing B4/01/06 Consolidated
 Edison Co. of New York, Inc 18pp 21937:267 24X
 Fiche: 50-000, B4/01/06, B401090221.

B401170413 Forwards ASME Code rept re overpressure protection, in response to OL safety review request for addl info, Question 440 3
 MITTL, R L. Public Service Electric & Gas Co of New Jersey
 B4/01/06. SCHWENCER, A. Licensing Branch 2 1p 21828 314. 24X
 Fiche 50-354, B4/01/06, B401170413

--B401170420 Rev O to "Overpressure Protection Rept"
 MATA, M., NAZARENO, E., IKEMOTO, F M General Electric Co. 23A1411
 R00. B3/01/28 14pp. 21828 315 24X Fiche: 50-354, B4/01/06, B401170413

--B401170426 Rev O to "Overpressure Protection Rept"
 MATA, M., GARCIA, J., NAZARENO, E General Electric Co DC23A1411
 R00. B3/01/28. 2pp. 21828-329 24X Fiche: 50-354, B4/01/06, B401170413

B401120317 Forwards Pritchard-Carpenter Oct 1972 rept on Newbold Island & rept on thermal discharge, per J Cho B40109 request
 RADER, R M Conner & Wetterhahn RADER, R M Public Service Electric & Gas Co of New Jersey B4/01/10 ROSENTHAL, A. S., GUTCHY, R L., MOORE, T. S. Atomic Safety and Licensing Appeal Panel 17pp.
 21792 116 24X Fiche: 50-354, B4/01/10, B401120317

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
 Bvc list encl.
 EISENHUT, D. O. Division of Licensing. B4/01/13 Consolidated
 Edison Co of New York, Inc 18pp 21946: 174 24X
 Fiche: 50-000, B4/01/13, B401130084

B401270535 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
 HANNON, J. Division of Licensing. B4/01/17 Division of Licensing 1p 22000. 349. 24X Fiche: 50-000, B4/01/17, B401270536

O Adjudicatory correspondence

B401060279 Preliminary set of initial interrogatories & request for production of documents Certificate of Bvc encl
 CONNER, T B Public Service Electric & Gas Co of New Jersey
 CONNER, T B Conner & Wetterhahn B4/01/03 Delaware, State of
 5pp 21741 181 24X Fiche 50-354, B4/01/03, B401060279

B401100136 Certifies svc of applicant preliminary set of initial interrogatories & request for production of documents to public advocate & State of DE on B40103
 CONNER, T B Public Service Electric & Gas Co of New Jersey
 CONNER, T B Conner & Wetterhahn B4/01/03 2pp 21761 075 24X
 Fiche 50-354, B4/01/03, B401100136

B401100225 Confirms that initial depositions of witnesses re Contention 4 will be taken on B40113 in Washington, DC Related correspondence
 RADER, R M Conner & Wetterhahn RADER, R M Public Service Electric & Gas Co of New Jersey B4/01/06 DELANEY, C Delaware, State of
 POTTER, R W New Jersey, State of 1p 21759 246 24X
 Fiche 50-354, B4/01/06, B401100225

B40110208 Advises of Superior Court of NJ, Appellate Div. B31219 order denying Ofc of Public Advocate B31201 motion for summary disposition of util challenge to Public Advocate statutory authority to intervene in proceeding.
 CONNER, T B Conner & Wetterhahn CONNER, T B Public Service Electric & Gas Co of New Jersey B4/01/09. MILLER, M E., CARPENTER, J. H., MORRIS, P A Atomic Safety and Licensing Board Panel
 2pp 21772 347. 24X Fiche 50-354, B4/01/09, B40110208

B40110210 Response to ASLAB B31228 order re recusal motion by State of NJ Ofc of Public Advocate Replacement of ASLAB member Carpenter urged Certificate of Bvc encl
 CONNER, T B Public Service Electric & Gas Co of New Jersey
 CONNER, T B Conner & Wetterhahn B4/01/09 Atomic Safety and Licensing Appeal Panel 7pp 21772 349 24X Fiche: 50-354, B4/01/09, B40110210

B401120317 Forwards Pritchard-Carpenter Oct 1972 rept on Newbold Island & rept on thermal discharge, per J Cho B40109 request
 RADER, R M Conner & Wetterhahn RADER, R M Public Service Electric & Gas Co of New Jersey B4/01/10 ROSENTHAL, A. S., GUTCHY, R L., MOORE, T. S. Atomic Safety and Licensing Appeal Panel 17pp
 21792 116 24X Fiche: 50-354, B4/01/10, B401120317.

B401250159 Response opposing Public Advocate of State of NJ B31118 request for recusal of Judge Carpenter Judge Carpenter did not abuse discretion by not recusing himself Certificate of Bvc encl
 DEMEY, L S Hearing Branch 3 B4/01/13 Atomic Safety and Licensing Appeal Panel 33pp 21937:030 24X Fiche 50-354, B4/01/13, B401250159

B401260183 Response to preliminary set of initial interrogatories & request for production of documents re Contentions 1-4. Certificate of Bvc encl Related correspondence.
 RENIB, B New Jersey, State of B4/01/18 Public Service Electric & Gas Co of New Jersey 6pp 21956 101 24X Fiche 50-354, B4/01/18, B401260183

B401240328 First set of interrogatories & request for production of documents re Contentions 1, 2, 3 & 4 Certificate of Bvc encl
 CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn. B4/01/20 New Jersey, State of 12pp 21920 324 24X Fiche. 50-354, B4/01/20, B401240328

B401270294 Requests that State of NJ witnesses review & execute deposition transcript sent on B40116, per B40113 agreement. Related correspondence
 RADER, R M Conner & Wetterhahn RADER, R M Public Service Electric & Gas Co of New Jersey B4/01/24 DELANEY, C, POTTER, R. W New Jersey, State of 1p. 21976 074 24X Fiche. 50-354, B4/01/24, B401270294

B401260209 Memorandum & Order ALAB-759, directing that Judge Carpenter recuse himself from proceeding & that another ABLB panel member be appointed to serve in proceeding.
 BHOENAKER, C J Atomic Safety and Licensing Appeal Panel B4/01/25
 CARPENTER, J. H. Atomic Safety and Licensing Board Panel 23pp
 21956. 234 24X Fiche 50-354, B4/01/25, B401260209

O Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
 FELTON, J M Division of Rules and Records B3/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744:003. 24X
 Fiche: 50-000, B3/10/20, B401060040

DOCKETED ITEMS

235

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
w/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Braun Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401240307 Forwards IE Insp Rept 50-354/83-14 on 830919-30 & notice
of violation
MARTIN, T J Division of Engineering & Technical Programs 84/01/10
MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp
21908 022 24X Fiche 50-354,84/01/10,8401240307

--8401240309 Notice of violation from insp on 830919-30
* Region 1, Office of Director 84/01/10 3pp 21908 024 24X
Fiche 50-354,84/01/10,8401240307

--8401240313 IE Insp Rept 50-354/83-14 on 830919-30 Violations noted
failure of QC insp to identify nonconformance of three cable
raceway supports w/project specs
RICHARDS, B, OREGO, H, PRELL, J Region 1, Office of Director
84/01/08 61pp 21908 027 24X Fiche 50-354,84/01/10,8401240307

8312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance w/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E,
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060130 List of SALP results during 1982,
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 BECY papers
Forwards App A documents. Remaining documents under review.
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000,83/10/18,8401250015.

--8207230670 Informs of T Devine (Govt Accountability Project) 820709
ltr responding to Chairman question at 820616 meeting &
requesting investigation of alleged util false statements
BICKWIT, L Office of the General Counsel BECY-82-297 82/07/15
97pp 21965 226 24X Fiche 50-000,83/10/18,8401250015

--820716006B Informs Commission of NRC initiatives to improve GA in
nuclear project design & const Approval requested to revise
NRC statutory authority to permit implementation of
representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-352 82/08/20 37pp 21966 035 24X
Fiche 50-000,83/10/18,8401250015

--8401250164 Discusses T Devine FOIA Appeal (82-A-1C) re DIA facility
rept Authorizes secretary to sign & dispatch attached ltr
denying appeal
BICKWIT, L Office of the General Counsel BECY-82-082 82/03/01.
20pp 21961 147 24X Fiche 50-000,83/10/18,8401250015

8401030213 Forwards completed facility staffing questionnaire, per NRC
831206 submittal. Eleven reactor operators & 35 senior
reactor operators assigned to shift work
WILLIAMS, J Cincinnati Gas & Electric Co 83/12/16 DENTON, H
Office of Nuclear Reactor Regulation, Director. 5pp 21682 309
24X Fiche 50-358,83/12/16,8401030213

8312120101 Board Notification 83-187 provides info re possible
interaction of main steam lines w/main feedwater at BHRs
Subj being studied on expedited basis Commissioners will be
notified when review completed
EISENHUT, D O Division of Licensing 83/12/27 PALLADINO, N J,
GILINSKY, V, ROBERTS, T Commissioners 6pp 21725 260 24X
Fiche 50-000,83/12/27,8312120101

--8312190346 Recommends that board notification be made for listed
facilities re potential for interaction of nonseismic
feedwater lines w/seismic Category I main steam lines
MATTSOON, R Division of Systems Integration (post 811003)
VOLLMER, R Division of Engineering 83/12/06 EISENHUT, D O
Division of Licensing 2pp 21725 266 24X Fiche 50-000,
83/12/27,8312120101

8312120094 Board Notification 83-197 forwards NRC 831216 decisions
(Director's Decision 83-19) re util actions under Commission
821112 order to show cause & order immediately suspending
const
EISENHUT, D O Division of Licensing 83/12/29 PALLADINO, N J,
GILINSKY, V, ROBERTS, T, M Commissioners 2pp. 21680 226 24X
Fiche 50-358,83/12/29,8312120094

--8401030290 Notice of issuance of Director's Decision 83-19 under
10CFR2 206 Decision denies T Devine 830525 petition for
certain Commission actions re facility
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/16 1p 21680 247 24X Fiche 50-358,
83/12/29,8312120094

8401060376 Notification of 840113 meeting w/util in Bethesda, MD to
discuss preliminary independent design review program &
submittal of final rept
KINTNER, L L Licensing Branch 1 83/12/29 YOUNGBLOOD, B J,
Licensing Branch 1 4pp 21755 180 24X Fiche 50-358,83/12/29,
8401060376

8401050603 Responds to 831206 ltr re layoff of 300 members of document
review staff w/o exit interviews Interviews performed w/327
of 401 employees
KEPLER, J O Region 3, Office of Director 84/01/03 Miami
Valley Power Project 2pp 21726 107 24X Fiche 50-358,84/01/03,
8401050603

--8401050609 Requests info on implications of layoffs of 300 document
review staff w/o conducting exit interviews.
ANDERSON, R, AMADON, P, DEVINE, T Miami Valley Power Project
83/12/06 KEPLER, J O Region 3, Office of Director. 1p
21726 109 24X Fiche 50-358,84/01/03,8401050603

8401190179 Forwards "Continuation of Const Plan," in response to
Commission 821112 order suspending const
EISENHUT, D O Division of Licensing 84/01/03 LIEBERMAN, J,
Regional Operations & Enforcement Division PARTLOW, J G, Division
of QA, Safeguards & Inspection Programs (Post 830103) THOMPSON, H L
Division of Human Factors Safety 2pp 21867 048. 24X
Fiche 50-358,84/01/03,8401190179

--8401190182 "Continuation of Const Plan "
* Cincinnati Gas & Electric Co 83/12/31. 246pp 21867 050.
24X Fiche 50-358,84/01/03,8401190179

DOCKETED ITEMS

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N J
Commissioners. 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401310085 Approves request for withholding "Safety Parameter Display Sys for Zimmer Nuclear Station Unit 1," from public disclosure pursuant to 10CFR2.790
YOUNGBLOOD, B J. Licensing Branch 1 84/01/05 WILLIAMS, J
Cincinnati Gas & Electric Co. App 22028 291 24X
Fiche 50-358, 84/01/05, 8401310085

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401160220 Forwards Rev 2 to Vols 1 & 2 of "Environ Qualification Rpt for Class IE Equipment" & Vol 1 of "Environ Qualification Rpt for Mechanical Equipment"
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/06 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 21810 001.
24X Fiche 50-358, 84/01/06, 8401160220

--8401160224 Rev 2 to Vols 1 & 2 of "Environ Qualification Rpt for Class IE Equipment."
* Cincinnati Gas & Electric Co 84/01/06 96pp 21810 004
24X Fiche 50-358, 84/01/06, 8401160220

--8401160228 Vol 1 of "Environ Qualification Rpt for Mechanical Equipment"
* Stone & Webster Engineering Corp. 83/12/09. 398pp 21812 245.
24X Fiche 50-358, 84/01/06, 8401160220.

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0939, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174. 24X
Fiche 50-000, 84/01/13, 8401130084.

8401180209 Ack receipt of util "Continuation of Const Plan," required per NRC 8312112 order to show cause & order immediately suspending const. Written comments from public should be received in Region III by 840210
KEPPLER, J O Region 3, Office of Director 84/01/13 WILLIAMS, J
Cincinnati Gas & Electric Co. App 21844 082. 24X
Fiche 50-358, 84/01/13, 8401180209.

8401190454 Forwards resumes for principal positions noted on organization chart in Section IV of Ebasco 831205 proposal re independent auditor for plan to verify const.
MAZD, B. R. Ebasco Services, Inc (subs of Enserch Corp) 84/01/13.
KEPPLER, J O. Region 3, Office of Director. 30pp. 21849 251. 24X
Fiche 50-358, 84/01/13, 8401190454

8401180113 Requests NRC approval of Teledyne Engineering Svcs as independent design review (IDR) contractor Teledyne proposal forwarded Criteria used during evaluation & presentation matl from NRC 840113 meeting encl.
WILLIAMS, J. Cincinnati Gas & Electric Co 84/01/16. EISENHUT, D O.
Division of Licensing. App 21841.151. 24X Fiche: 50-358, 84/01/16, 8401180113.

--8401180123 Technical Proposal PR-6194, "Independent Design Review of Zimmer Nuclear Power Station"
* Teledyne Engineering Services. 83/10/10 125pp. 21841.159.
24X Fiche: 50-358, 84/01/16, 8401180113

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing. 84/01/17. Division of Licensing. 1p. 22000.349. 24X Fiche: 50-000, 84/01/17, 8401270536

8401230192 Forwards protocol governing communications between util & independent auditor of plan to verify quality of const for facility Monthly progress meetings will be held
KEPPLER, J O Region 3, Office of Director 84/01/18 WILLIAMS, J
Cincinnati Gas & Electric Co 3pp 21884 153 24X
Fiche 50-358, 84/01/18, 8401230192

8312120127 Board Notification 84-012 forwards IE Directors's Decision DD-84-3 explaining reasons for denial of Miami Valley Power Project 831214 petition to reopen hearing for admission of eight proposed contentions re GA
EISENHUT, D O Division of Licensing 84/01/19 PALLADINO, N J.
GILINSKY, V., ROBERTS, T M Commissioners 3pp 21955 103 24X
Fiche 50-358, 84/01/19, 8312120127

8401300125 Informs that Training Directive ZPM-TR 101 & master training plan developed for NRC review
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/19 KEPPLER, J O
Region 3, Office of Director 2pp 21999 096 24X
Fiche 50-358, 84/01/19, 8401300125

8401270460 Forwards personnel resumes inadvertently omitted from 840113 ltr re independent auditor for plan to verify const
MAZD, B R Ebasco Services, Inc (subs of Enserch Corp) 84/01/20
KEPPLER, J O Region 3, Office of Director App 21980 273 24X
Fiche: 50-358, 84/01/20, 8401270460

8401310214 Requests completion of pending actions on 831216 plan to verify quality of const. to closeout outstanding items in 831112 order to show cause & order immediately suspending const
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/24 KEPPLER, J O
Region 3, Office of Director 1p 22021 343 24X
Fiche 50-358, 84/01/24, 8401310214

F Security, medical, emergency & fire protection plans

8401230236 Notifies of FEMA 840112-13 radiological emergency preparedness program meetings to develop final FY84 & FY85 emergency preparedness exercise & prompt alert & notification certification schedules, respectively
PAPERIELLO, C J Region 3, Office of Director 84/01/04
WILLIAMS, J. Cincinnati Gas & Electric Co 4pp. 21884 191 24X
Fiche: 50-358, 84/01/04, 8401230236

G Adjudicatory correspondence

8401050282 Proposed issues & prospective witnesses supporting Miami Valley Power Project proposed contentions re GA character & competence Certificate of Svc encl
DEVINE, T. Miami Valley Power Project 83/12/31 59pp 21726 275
24X Fiche: 50-358, 83/12/31, 8401050282

840110204 Notice of ASLB reconstitution JH Frye, Chairman & FF Hooper & GA Linsenberger, members
COTTER, B P. Atomic Safety and Licensing Board Panel 84/01/09
2pp. 21772 345 24X Fiche: 50-358, 84/01/09, 840110204

8312120112 Board Notification 84-005, forwards NRC transcript of 831215 meeting in Bethesda, MD & intervenor 831216 & 1214 ltrs re Miami Valley Power Project 2 206 petition for reconsideration of ASLB 830915 order
EISENHUT, D O Division of Licensing 84/01/10 PALLADINO, N,
GILINSKY, V., ROBERTS, T Commissioners 5pp. 21928 003 24X
Fiche: 50-000, 84/01/10, 8312120112

--8401230589 Informs of release of info highly relevant to Miami Valley Power Project 831214 2. 206 petition for reconsideration of ASLB ruling re IDVP. Review of 831215 transcript requested prior to decision
DEVINE, T., GARDE, B Government Accountability Project DEVINE, T
Miami Valley Power Project 83/12/16 PALLADINO, N., GILINSKY, V.,
ABBELETTINE, J. Commissioners 3pp 21928.008. 24X
Fiche 50-000, 84/01/10, 8312120112

--8401230600 Petition per 10CFR2 206 to defer judgment or decision on proposed course of action for completion of facility until suppl created for record of J Keppler 831215 briefing. W/o encl
DEVINE, T Government Accountability Project DEVINE, T. Miami Valley Power Project 83/12/14 PALLADINO, N., GILINSKY, V.,
ABBELETTINE, J Commissioners 3pp 21928 011 24X
Fiche 50-000, 84/01/10, 8312120112

--8401230612 Transcript of 831215 meeting w/util in Bethesda, MD
* Commissioners 83/12/15. 210pp 21928.014 24X
Fiche: 50-000, 84/01/10, 8312120112

B401120239 Order extending time until B40125 for Commission to act to review Director's Decision DD-B3-19
CHILK, B J Office of the Secretary of the Commission B4/01/10
PALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 1p
21793 311 24X Fiche 50-358, B4/01/10, B401120239

B401160209 Advises that Cincinnati City Council adopted Vice-Mayor M Spencer encl motion before council opposing limited public participation at B40111 meeting between NRC & util
POSEY, W W Cincinnati, OH B4/01/10 ROBERTS, T M Commissioners 2pp
21815 356 24X Fiche 50-358, B4/01/10, B401160209

B401180245 Forwards packet of newspaper articles re facility Packet acts as chronological summary of major events during 14 months prior to B31201
SUITZ, J B Cincinnati, OH B4/01/10 BERNTHAL, F Commissioners 96pp
21842 134 24X Fiche 50-358, B4/01/10, B401180245

B401230390 Submits partial response to util plan to verify quality of const for facility Counsel for Miami Valley Power Project decision not to attend B40111 public meeting clarified Related info encl
DEVINE, T Government Accountability Project DEVINE, T Miami Valley Power Project B4/01/11 KEPLER, J Region 3, Office of Director 11pp 21872 211 24X Fiche 50-358, B4/01/11, B401230390

--B401230396 Transcript of JB McCarten B30607 interview in Great Lakes, IL Pp 1-164 Supporting documentation encl Info deleted
Atomic Safety and Licensing Board Panel B3/06/07 169pp
21872 281 24X Fiche 50-358, B4/01/11, B401230396

B401190183 Forwards Director's Decision DD-B4-3, denying Miami Valley Power Project B31214 request to defer action on util proposed course of action
DEVYUNG, R C Director's Office, Office of Inspection and Enforcement B4/01/13 DEVINE, T Miami Valley Power Project 2pp
21861 197 24X Fiche 50-358, B4/01/13, B401190183

--B401190197 Director's Decision DD-B4-3, denying Miami Valley Power Project B31214 request to defer action on util proposed course of action All concerns raised in petition considered in NRC review
DEVYUNG, R C Director's Office, Office of Inspection and Enforcement B4/01/13 9pp 21861 199 24X Fiche 50-358, B4/01/13, B401190183

--B401190203 Notice of issuance & availability of Director's Decision B4-3
DEVYUNG, R C Director's Office, Office of Inspection and Enforcement B4/01/13 1p 21861 208 24X Fiche 50-358, B4/01/13, B401190183

B401190295 Response opposing Miami Valley Power Project B31231 proposed issues & support for contentions re GA issues not specific or litigable Certificate of Svc encl
CONNER, T B Cincinnati Gas & Electric Co CONNER, T B Conner & Hetherhahn B4/01/16 Atomic Safety and Licensing Appeal Panel, 24pp. 21890 277. 24X Fiche 50-358, B4/01/16, B401190295

B401310419 Forwards B40124 telegram appealing dismissal of J E Abson claim against HJ Kaiser Co, per Dept of Labor B40120 ruling
MOONEY, D J Paxton & Seasongood B4/01/24 FIERST, O A Labor, Dept. of 2pp 22018 337 24X Fiche 50-358, B4/01/24, B401310419

B401270300 Order extending time until B40208 for Commission to act to review Director's Decision DD-B3-19
CHILK, B J Office of the Secretary of the Commission B4/01/25 Commissioners 1p 21776 078 24X Fiche 50-358, B4/01/25, B401270300

H General correspondence

B401260226 Forwards Council of City of Cincinnati Resolution R/18-1984 which expresses dissatisfaction over NRC failure to require third-party independent review of facility
POSEY, W W Cincinnati, OH B4/01/13 PALLADINO, N, Commissioners 2pp 21756 124 24X Fiche 50-358, B4/01/13, B401260226

G Inspection reports, IE Bulletins & correspondence

B401160445 FOIA request for draft or final Hoyt investigation rept re facility
LEONITTO, J CBS News, CBS, Inc B3/10/12 FELTON, J M Division of Rules and Records 1p 21824 270 24X Fiche 50-358, B3/10/12, B401160445

B401250015 Partial response to FOIA request for all 1982 BECY papers, Forwards App A documents Remaining documents under review.
FELTON, J M Division of Rules and Records B3/10/18 WEISS, E R Union of Concerned Scientists. 3pp 21760 005 24X Fiche: 50-000, B3/10/18, B401250015

--B401250267 Discusses T Applegate vs NRC (B2-1829) case re allegations that NRC improperly withheld documents & failed to identify others in response to B1123 request for records concerning B18007 OIA rept on IE investigation at facility
SLAGWIE, E L Office of the General Counsel BECY-B2-285 B2/07/06 6pp 21765 026 24X Fiche 50-000, B3/10/18, B401250015

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401160446 Responds to FOIA request for Hoyt rept Release of Hoyt rept currently before Commission No info available at present time
FELTON, J M Division of Rules and Records, B3/10/28 LEONITTO, J CBS News, CBS, Inc 1p 21824 271 24X Fiche 50-358, B3/10/28, B401160446

B401100051 Forwards IE Insp Rept 50-358/B3-19 on B31001-1104 No noncompliance noted
WARNICK, R F Region 3, Office of Director B3/12/23 WILLIAMS, J, Cincinnati Gas & Electric Co, 2pp 21761 172 24X Fiche 50-358, B3/12/23, B401100051

--B401100054 IE Insp Rept 50-358/B3-19 on B31001-1104 No noncompliance noted. Major areas inspected licensee action on previous insp findings & const deficiency repts, independent insp efforts & followup on quality confirmation program tasks
GHYNN, T P, NIGHTINGALE, E, HILL, W M Region 3, Office of Director B3/12/23 16pp 21761 174 24X Fiche 50-358, B3/12/23, B401100051

B401100056 Forwards IE Insp Rept 50-358/B3-24 on B31105-1205. No noncompliance noted
WARNICK, R F Region 3, Office of Director B3/12/23 WILLIAMS, J, Cincinnati Gas & Electric Co, 2pp 21761 149 24X Fiche 50-358, B3/12/23, B401100056

--B401100059 IE Insp Rept 50-358/B3-24 on B31105-1205 No noncompliance noted. Major areas inspected licensee action on previous insp findings, nonconformance rept review, quality confirmation program task status & review of exit interview program
GHYNN, T P, NIGHTINGALE, E, HILL, W M Region 3, Office of Director B3/12/23 21pp. 21761 151 24X Fiche 50-358, B3/12/23, B401100056

B401100188 Forwards IE Insp Rept 50-358/B3-27 on B31205-16 No noncompliance noted
WARNICK, R F Region 3, Office of Director B3/12/23 WILLIAMS, J, Cincinnati Gas & Electric Co, 2pp 21760 136. 24X Fiche 50-358, B3/12/23, B401100188

--B401100194 IE Insp Rept 50-358/B3-27 on B31205-16 No noncompliance noted. Major areas inspected, 10 CFR 50.55(a) items, IE bulletins & circulars & actions on previously identified items
SHEBEL, HUT, C., ELBERGAS, V J, GHYNN, T P Region 3, Office of Director, B3/12/23. 10pp 21760 138 24X Fiche 50-358, B3/12/23, B401100188

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEVYUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co. of New York, Inc. 124pp. 21731 166 24X Fiche 50-000, B3/12/28, B312120090.

B401030419 Responds to IE Bulletin B3-06, "Nonconforming Metals Supplied by Tube-Line Corp Facilities at Long Island City, NY/Houston, TX & Coral Stream, IL." No subj matl used in safety-related sys Approx 15 manhours expended in review
WILLIAMS, J Cincinnati Gas & Electric Co B3/12/28 KEPLER, J. C. Region 3, Office of Director 2pp. 21731 051 24X Fiche 50-358, B3/12/28, B401030419

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). B3/12/30. Consolidated Edison Co. of New York, Inc. 127pp. 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/10. Consolidated Edison Co. of New York, Inc. 125pp 21746 053. 24X Fiche: 50-000, B4/01/10, B312120104.

DOCKETED ITEMS

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826.184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/16 Consolidated Edison Co of New
York, Inc 127pp. 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401240539 Forwards Natl Board of Boiler & Pressure Vessel Inspectors
Interim Rept 18 covering Natl Board Audit Team activities at
facility for Dec 1983 Concurs w/recommendations Task NBT-4
closed
YOST, R A Ohio, State of 84/01/17 WILLIAMS, J Cincinnati Gas &
Electric Co. 4pp. 21920 031 24X Fiche 50-358, 84/01/17, 8401240539

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18 Consolidated Edison Co. of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18 Consolidated Edison Co. of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401040017 Forwards Zimmer monthly status rept for Nov 1983
DIRCKS, W J Office of the Executive Director for Operations
83/12/27. PALLADINO, N J. Commissioners 5pp 21708 320 24X
Fiche 50-358, 83/12/27, 8401040017

--8401040022 Forwards Nov monthly status rept for quality confirmation
program, per 821230 ltr
WILLIAMS, J. Cincinnati Gas & Electric Co 83/12/14 KEPLER, J O
Region 3, Office of Director. 4pp 21708 325 24X
Fiche 50-358, 83/12/27, 8401040017

--8401040026 "Quality Confirmation Program," monthly status rept for Nov
1983.
" Cincinnati Gas & Electric Co 83/12/08 30pp 21708 329 24X
Fiche 50-358, 83/12/27, 8401040017

--8401040031 Forwards "Quality Confirmation Program," monthly status rept
for Nov 1983
KEPLER, J O Region 3, Office of Director. 83/12/23 DIRCKS, W J.
Office of the Executive Director for Operations 1p 21708 359
24X Fiche: 50-358, 83/12/27, 8401040017.

8401170194 Forwards "Quality Confirmation Program," monthly rept for
Dec 1983, per RF Warnick 821230 ltr
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/10 KEPLER, J O
Region 3, Office of Director. 2pp 21831 175. 24X
Fiche: 50-358, 84/01/10, 8401170194

--8401170206 "Quality Confirmation Program," monthly rept for Dec 1983
" Cincinnati Gas & Electric Co 84/01/05 32pp 21831 177 24X
Fiche. 50-358, 84/01/10, 8401170194

8401240539 Forwards Natl Board of Boiler & Pressure Vessel Inspectors
Interim Rept 18 covering Natl Board Audit Team activities at
facility for Dec 1983 Concurs w/recommendations. Task NBT-4
closed.
YOST, R A Ohio, State of. 84/01/17 WILLIAMS, J. Cincinnati Gas &
Electric Co 4pp. 21920. 031. 24X Fiche. 50-358, 84/01/17, 8401240539

8401300085 Forwards Zimmer monthly status rept for Dec 1983.
DIRCKS, W J Office of the Executive Director for Operations.
84/01/20. PALLADINO Commissioners 4pp 22006 272 24X
Fiche. 50-358, 84/01/20, 8401300085

S. Reportable occurrences, LERs & related correspondence

8401190435 Final deficiency rept, Item B-17 re design of main steam
tunnel & auxiliary bldg masonry walls Initially reported on
831020 Condition determined not reportable per
10CFR50.55(e).
WILLIAMS, J Cincinnati Gas & Electric Co. 83/01/10. KEPLER, J O
Region 3, Office of Director. 2pp. 21849:249 24X
Fiche: 50-358, 83/01/10, 8401190435

8312070216 Interim deficiency rept, Item E-37 re Brown Boveri 125-volt
dc control device failure on 6 9 kV & 4 16 kV switchgear
Initially reported on 830202 Insp & adjustment of applicable
circuit breakers continuing
WILLIAMS, J Cincinnati Gas & Electric Co 83/11/29 KEPLER, J O
Region 3, Office of Director 2pp 21426 079 24X
Fiche 50-358, 83/11/29, 8312070216

8401050328 Interim Deficiency Rept B-10 re masonry wall const Initially
reported on 830513 Reinsp & corrective action program will
be selected per course of action approved by NRC on 831216
WILLIAMS, J Cincinnati Gas & Electric Co 83/12/27 KEPLER, J O
Region 3, Office of Director 2pp 21725 282 24X
Fiche 50-358, 83/12/27, 8401050328

8401050391 Interim deficiency rept, Item G-12 re failure to follow
procedure for insp of GA/GC rework/repair activities
Initially reported on 830909 Hardware will be inspected to
validate design drawings Procedures under development
WILLIAMS, J Cincinnati Gas & Electric Co 83/12/28 KEPLER, J O
Region 3, Office of Director 2pp 21726 119 24X
Fiche 50-358, 83/12/28, 8401050391

8401100383 Interim deficiency rept, Item M-46 re turning vane failures
in essential HVAC sys Initially reported on 820510 Design
mods completed Adequacy of vanes less than 30 inches wide in
elbows will be verified
WILLIAMS, J Cincinnati Gas & Electric Co. 83/12/29 KEPLER, J O
Region 3, Office of Director 2pp 21763 361 24X
Fiche 50-358, 83/12/29, 8401100383

8401120365 Interim deficiency rept, Item M-32 re incomplete hydraulic
analysis of control rod drive piping Verification of
installed hardware will be completed under plan to verify
quality of const submitted 831216
WILLIAMS, J Cincinnati Gas & Electric Co 83/12/29. KEPLER, J O
Region 3, Office of Director 2pp 21792 021 24X
Fiche 50-358, 83/12/29, 8401120365

8401100294 Interim deficiency rept, Item E-30 re lack of installation
insp of non-Class 1E cables in panels Initially reported on
821027 Analysis identified 575 deviations requiring rework
Final rept will be submitted upon completion
WILLIAMS, J Cincinnati Gas & Electric Co 83/12/30 KEPLER, J O
Region 3, Office of Director 3pp 21798 202 24X
Fiche 50-358, 83/12/30, 8401100294

8401120390 Interim deficiency rept, Item G-14 re control of design
specs Initially reported on 831013 Measures to ensure that
approved specs issued as controlled documents in progress
Final rept will be submitted upon completion of activities
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/03 KEPLER, J O
Region 3, Office of Director 2pp 21791 078 24X
Fiche 50-358, 84/01/03, 8401120390

8401170444 Final deficiency rept, Item E-53 re switchgear wiring diagram
discrepancies Initially reported on 830922 All discrepancies
resolved Deficiencies not reportable under 10CFR50.55(e)
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/10 KEPLER, J O
Region 3, Office of Director 4pp 21827 098 24X
Fiche 50-358, 84/01/10, 8401170444

8401190318 Interim deficiency rept, Item M-67 re lack of procedural
qualifications for pipe bends Initially reported on 821109
Post-qualification program completed for 35 bends Corrective
action program will be conducted
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/10 KEPLER, J O
Region 3, Office of Director 2pp 21830 351 24X
Fiche. 50-358, 84/01/10, 8401190318

8401230393 Interim deficiency rept, Item E-50 re annunciator sys
replacement light bulbs Dimmer rheostats for lamp circuits
in main control room annunciator sys will be bypassed to
minimize line resistance & maximize short circuit current
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/16 KEPLER, J O
Region 3, Office of Director 2pp 21879 120 24X
Fiche. 50-358, 84/01/16, 8401230393

8401300155 Interim deficiency rept, Item M-104 re qualifications of
energy absorbing matl used in design & const of high energy
pipe whip restraints. Initially reported on 831219 Test
procedure development in process Next rept due by 840401
WILLIAMS, J Cincinnati Gas & Electric Co 84/01/17 KEPLER, J O
Region 3, Office of Director 2pp 21977 359 24X
Fiche: 50-358, 84/01/17, 8401300155

8401300143 PNO-III-84-008 on 840121, licensee announced that facility
will be converted to coal-fired plant rather than nuclear
plant. Facility expected to be operational in 1991
FORNEY, W J, WARNICK, R Region 3, Office of Director 84/01/23. 1p
21998, 262 24X Fiche 50-358, 84/01/23, 8401300143

DOCKETED ITEMS

239

T Hearing transcripts on non-antitrust matters

B401230370 Submits partial response to util plan to verify quality of const for facility Counsel for Miami Valley Power Project decision not to attend B40111 public meeting clarified Related info encl
DEVINE, T Government Accountability Project DEVINE, T Miami Valley Power Project B4/01/11 KEPLER, J Region 3, Office of Director 1pp 21872 211 24X Fiche 50-358, B4/01/11, B401230370

--B401230396 Transcript of JB McCarten B30607 interview in Great Lakes, IL Pp 1-164 Supporting documentation encl Info deleted
* Atomic Safety and Licensing Board Panel B3/06/07 169pp 21872 281 24X Fiche 50-358, B4/01/11, B401230396

B401230475 Transcript of B40111 hearing in Cincinnati, OH re review of util proposed plan for verification of quality of const Pp 1-193
* NRC - No Detailed Affiliation Given B4/01/11 193pp 21877 134 24X Fiche 50-358, B4/01/11, B401230475

V Operator Examinations

B401040292 Notifies that WT Oott & RW Link will attend B40111 meeting to discuss scheduling problems w/NRC exam process
CRUDEN, D S Cincinnati Gas & Electric Co B3/12/14 SPESGARD, R L Region 3, Office of Director 1p 21701 309 24X Fiche 50-358, B3/12/14, B401040292

B401300129 Requests written concurrence for training activities, as outlined Facility site directives & master training plan for all site training will be provided to Region III, per B31028 ltr
WILLIAMS, J Cincinnati Gas & Electric Co B4/01/19 KEPLER, J G Region 3, Office of Director 2pp 21999 089 24X Fiche 50-358, B4/01/19, B401300129

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records B3/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 4pp 21957 357 24X Fiche 50-000, B3/11/02, B401250163

--B309260392 Urges discussion on licensee disregard for NRC guidance re location of permanent & backup emergency operations facilities, per W Dircks B21227 memo Requests explanation re Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners B3/01/06 Commissioners 2pp 21958 001 24X Fiche 50-000, B3/11/02, B401250163

--B309260362 Responds to Commissioner Gilinsky B30106 comments on B21227 memo re implementation of emergency response facilities guidance Requested explanations re Waterford, San Onofre & Millstone plans provided
DIRCKS, W J Office of the Executive Director for Operations B3/02/15 PALLADINO, N Commissioners 2pp 21958 303 24X Fiche 50-000, B3/11/02, B401250163

B40110001B Forwards detailed discussion of violations noted during wk of B30926 re safe shutdown capability described in 10CFR50, App R Encl further describes corrective actions outlined in B31019 response Fire protection program review under way
MEDFORD, M O Southern California Edison Co B4/01/06 KNIGHTON, O W Licensing Branch 3 10pp 21761 120 24X Fiche 50-361, B3/01/06, B40110001B

B401180254 Provides current status of emergency operations facility ventilation sys mod & action necessary to address in-leakage Plan to review training & educ ctr encl
MEDFORD, M O Southern California Edison Co B4/01/09 EISENHUT, D G Division of Licensing 3pp 21844 101 24X Fiche 50-206, B4/01/09, B401180254

B401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/B3-24, 50-361/B3-39 & 50-362/B3-38 on B31205-09 No violation noted
NORDERHAUG, L R Region 5, Office of Director B4/01/12 MCCARTHY, C J Southern California Edison Co 2pp 21999 142 24X Fiche 50-206, B4/01/12, B401300183

--B401300188 IE Emergency Preparedness Insp Repts 50-206/B3-24, 50-361/B3-39 & 50-362/B3-38 on B31205-09 No violation noted Major areas inspected emergency detection & classification & protective action decisionmaking
NORTH, H S Region 5, Office of Director B4/01/11 18pp 21999 144 24X Fiche 50-206, B4/01/12, B401300183

B401240382 Forwards Addendum I to physical security plan, describing temporary change to south protected area barrier Addendum withheld (ref 10CFR73.21)
HAYNES, J G Southern California Edison Co B4/01/13 MARTIN, J B Region 5, Office of Director 2pp 21916 229 24X Fiche 50-206, B4/01/13, B401240382

B401230487 Forwards comments on draft facility attachment re US/IAEA safeguards agreement for application of IAEA safeguards Responses to IAEA design info questionnaire Items 38 & 43 also encl
MEDFORD, M O Southern California Edison Co B4/01/17 KNIGHTON, O W Licensing Branch 3 77pp 21886 039 24X Fiche 50-361, B4/01/17, B401230487

B401250183 Requests exemption from requirement for state & local participation in B40229 annual emergency exercise per 10CFR50, App E requirements State & local govts participated in three annual exercises in 1981, 1982 & on B30323
BASKIN, K P Southern California Edison Co B4/01/19 EISENHUT, D G Division of Licensing 2pp 21935 210 24X Fiche 50-206, B4/01/19, B401250183

H General correspondence

B401240172 Requests all IE bulletin, info notices & other correspondence be addressed to KP Baskin, KP Baskin B40103 ltr advising of recent organizational changes encl
FRANKLIN, D A Southern California Edison Co B4/01/12 DEYOUNG, R Office of Nuclear Reactor Regulation, Director 1p 21908.276 24X Fiche 50-206, B4/01/12, B401240172

--B401240179 Advises of recent organizational changes within util Util in process of preparing appropriate changes to licensing documentation to reflect changes for submittal in near future
BASKIN, K P Southern California Edison Co B4/01/03 MARTIN, J B Region 5, Office of Director 3pp 21908.277 24X Fiche 50-206, B4/01/12, B401240172

F Operating license stage documents & correspondence

B401260363 Discusses status of items outlined in util B30311 ltr re Unit 2 startup & readiness of Unit 3 for initial criticality
GULLD, W R Southern California Edison Co B3/08/19 MARTIN, J B Region 5, Office of Director 3pp 21936 018 24X Fiche 50-361, B3/08/19, B401260363

B309120493 Informs that NRR evaluation of reactor trip breaker problems completed, per B30314 request Review & licensee corrective actions documented in B30502 SER
EISENHUT, D G Division of Licensing B3/08/31 CREWS, J L Division of Resident Reactor Project & Engineering Programs 1p 21957 135 24X Fiche 50-361, B3/08/31, B309120493

B401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies Supporting ltr encl
CALBOYAB, C D Affiliation Unknown B3/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, B3/10/10, B401050027

B401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies NRC has no records subj to request Utilis not required to submit insurance rating to NRC
FELTON, J M Division of Rules and Records B3/10/25 CALBOYAB, C D Affiliation Unknown 1p 21736 235 24X Fiche 50-000, B3/10/25, B401050043

B312190111 Discusses demonstration at site planned for B31210 & 11. Util will not interfere w/rally, provided demonstrators do not attempt to violate security perimeter
ROOD, H Licensing Branch 3 B3/12/09 NOVAK, T M Assistant Director for Licensing 1p 21573 200 24X Fiche 50-361, B3/12/09, B312190111

B401050634 Application to amend Licensee NPF-10 & NPF-15, revising Tech Specs re containment ventilation sys Proposed change increases current limit of 1,000 h to 3,000 h per yr on use of B-inch containment purge sys
MEDFORD, M O Southern California Edison Co B4/01/03 KNIGHTON, O W Licensing Branch 3 5pp 21724 134 24X Fiche 50-361, B4/01/03, B401050634

--B401050639 Proposed Tech Specs re containment ventilation sys
* Southern California Edison Co B3/05/16 5pp 21724.139 24X Fiche 50-361, B4/01/03, B401050634

DOCKETED ITEMS

- 8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382
- 8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957, 267 24X
Fiche 50-000, 84/01/06, 8401090221
- 8401100067 Advises that Cycle 2 fuel performance calculations, using FATES-3 code, will be completed prior to end of Cycle 1 for Unit 2, per License Condition 6 Detailed reevaluation of fission gas release for Cycle 1 unnecessary
MEDFORD, M O Southern California Edison Co. 84/01/06
KNIGHTON, O W Licensing Branch 3, 2pp. 21761 147 24X
Fiche 50-361, 84/01/06, 8401100067
- 8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues."
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174. 24X
Fiche 50-000, 84/01/13, 8401130084
- 8401270266 Forwards Amend Applications 23 & 9 to Licenses NPF-10 & NPF-15, respectively, revising Tech Spec 3/4 3.2 re ESF actuation instrumentation to require testing of certain relays at 6-month intervals. Amend Fee encl.
BASKIN, K P Southern California Edison Co. 84/01/25. DENTON, H R. Office of Nuclear Reactor Regulation, Director 4pp 21979 157 24X
Fiche 50-361, 84/01/25, 8401270266
- 8401270270 Amend Applications 23 & 9 to Licenses NPF-10 & NPF-15, respectively, revising Tech Spec 3/4 3.2 re ESF actuation instrumentation to require testing of certain relays at 6-month intervals
BASKIN, K P Southern California Edison Co. 84/01/25 14pp 21979-161. 24X Fiche: 50-361, 84/01/25, 8401270266.
- 8401270274 Proposed changes to Tech Spec 3/4 3.2 re ESF actuation sys instrumentation to require testing of certain relays at 6-month intervals
* Southern California Edison Co 84/01/25. 48pp 21979, 175 24X Fiche: 50-361, 84/01/25, 8401270266
- G. Inspection reports, IE Bulletins & correspondence**
- 8401100018 Forwards detailed discussion of violations noted during wk of 830926 re safe shutdown capability described in 10CFR50, App R Encl further describes corrective actions outlined in 831019 response Fire protection program review under way
MEDFORD, M O, Southern California Edison Co. 84/01/06.
KNIGHTON, O W, Licensing Branch 3 10pp. 21761 120 24X
Fiche: 50-361, 83/01/06, 8401100018.
- 8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info, Notebook also available in PDR
FELTON, J M, Division of Rules and Records 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Trowbridge, Ip 21744:003 24X
Fiche: 50-000, 83/10/20, 8401060040
- 8401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement 83/10/20. 134pp 21744:004. 24X Fiche: 50-000, 83/10/20, 8401060040.
- 8401040590 Forwards preservice exam repts for Aug 1977 to Dec 1982 Submittal includes info re completed repairs or replacements of items from completion of ASME Section III work to 831114.
W/o encl
CURRAN, J M Southern California Edison Co. 83/11/21 MARTIN, J B, Region 5, Office of Director, Ip. 21706:286. 24X
Fiche: 50-361, 83/11/21, 8401040590.
- 8401030174 Confirms 831207 telcon re administrative error in 831129 response to notice of violation identified in IE Insp Repts 50-361/83-35 & 50-362/83-33. Safe shutdown circuit effort will be completed by 831222, not 831207.
HAYNES, J O, Southern California Edison Co. 83/12/12. MARTIN, J B, Region 5, Office of Director, Ip 21681.330 24X
Fiche: 50-361, 83/12/12, 8401030174.
- 8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl.
BEYOUNG, R C, Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826.060 24X Fiche 50-000, 83/12/30, 8312120093
- 8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104
- 8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche: 50-000, 84/01/10, 8312120107
- 8401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/83-24, 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
NORDEHAUS, L R, Region 5, Office of Director 84/01/12
MCCARTHY, C B Southern California Edison Co 2pp 21999 142 24X
Fiche 50-206, 84/01/12, 8401300183
- 8401300188 IE Emergency Preparedness Insp Repts 50-206/83-24, 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
Major areas inspected emergency detection & classification & protective action decisionmaking
NORTH, H S, TEMPLE, G M, SCHUSTER, M D, Region 5, Office of Director 84/01/11 13pp 21999 144 24X Fiche 50-206, 84/01/12, 8401300183
- 8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957.142 24X Fiche 50-000, 84/01/16, 8312120114
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl.
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp. 22000-001 24X Fiche 50-000, 84/01/18, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- 8401300142 Forwards IE Insp Repts 50-206/83-25, 50-361/83-40 & 50-362/83-37 on 831029-1209 No noncompliance noted
BISHOP, T W, Division of Resident Reactor Project & Engineering Programs, 84/01/19 MCCARTHY, C B Southern California Edison Co 2pp. 21998 263 24X Fiche 50-206, 84/01/19, 8401300142
- 8401300151 IE Insp Repts 50-206/83-25, 50-361/83-40 & 50-362/83-37 on 831029-1209, No noncompliance noted Major areas inspected, operations program & Unit 3 startup test program
CHAFFEE, A E, D'ANGELO, A, STEWART, J P, Region 5, Office of Director, 84/01/19, 10pp. 21998 265 24X Fiche 50-206, 84/01/19, 8401300142
- 8401300158 Forwards IE Insp Repts 50-206/83-27, 50-361/83-42 & 50-362/83-41 on 831227-28 No noncompliance noted.
WENSLAWSKI, F A, Region 5, Office of Director 84/01/19, MCCARTHY, C B Southern California Edison Co. 2pp 21999 111 24X
Fiche: 50-206, 84/01/19, 8401300158
- 8401300160 IE Insp Repts 50-206/83-27, 50-361/83-42 & 50-362/83-41 on 831227-28 No noncompliance noted Major areas inspected power ascension test program & licensee actions re release of matl contaminated w/low levels of radioactivity
YUHAS, O P, WENSLAWSKI, F A, Region 5, Office of Director, 84/01/19 4pp 21999-113 24X Fiche: 50-206, 84/01/19, 8401300158
- R Periodic operating reports & related correspondence**
- 8401120263 Monthly operating repts for Nov 1983 W/831215 ltr
MORRIS, C A, HAYNES, J O Southern California Edison Co. 83/11/30
Office of Resource Management, Director, 12pp 21792 145 24X
Fiche: 50-361, 83/11/30, 8401120263

DOCKETED ITEMS

241

8401270231 Monthly operating repts for Dec 1983 W/B40116 ltr
MORRIS, C A ; HAYNES, J G Southern California Edison Co 83/12/31
Division of Data Automation & Management Information 12pp
21976 338 24X Fiche 50-361,83/12/31,8401270231

S Reportable occurrences, LERs & related correspondence

8401040301 RD on 831123, review indicated that five fire hazard analysis
license amends & 33 nonconformance repts not maintained
Compensatory fire watches established for inoperable
fire-rated assemblies
HAYNES, J G Southern California Edison Co 83/12/07 MARTIN, J B
Region 5, Office of Director 2pp 21703 078 24X
Fiche 50-361,83/12/07,8401040301

8401030287 LER 83-151/03L-0 on 831114, w/unit in Mode 1, reactor manually
tripped due to unexpected pressurizer pressure & level
decrease Caused by operator opening emergency boration
valve 2HW-9247 Training program revamped W/B31215 ltr
HAYNES, J G Southern California Edison Co 83/12/15 MARTIN, J B
Region 5, Office of Director 4pp 21680 109 24X
Fiche 50-361,83/12/15,8401030287

8401040474 RD during Nov surveillance, listed fire doors found
inoperable Caused by latching mechanism & closure
mechanism failures & doors blocked open for const startup &
maint activities Design change packages developed
HAYNES, J G Southern California Edison Co 83/12/15 MARTIN, J B
Region 5, Office of Director 3pp 21714 031. 24X
Fiche 50-361,83/12/15,8401040474

8401040316 LER 83-147/03L-0 on 831121, train A control room fan failed
to start automatically on toxic gas isolation sys signal
Caused by spurious failure of relay in Unit 2 power source
Fan aligned to Unit 3 power source W/B31219 ltr
HAYNES, J G Southern California Edison Co 83/12/19 MARTIN, J B
Region 5, Office of Director 3pp 21708 033. 24X
Fiche 50-361,83/12/19,8401040316

8401120205 RD 83-146 on 831223, safety injection tanks (SITs) 007 & 010
exceeded nitrogen pressure limit of 625 psig while SIT 009
in process of being filled Caused by inleakage of borated
water through fill valves
HAYNES, J G Southern California Edison Co 83/12/27 MARTIN, J B
Region 5, Office of Director 2pp 21792 238 24X
Fiche 50-361,83/12/27,8401120205

8401160210 LER 83-144/03L-0 on 831202 & 22, excessive oxygen
concentration occurred 11 times for short durations in
waste gas holdup sys Cause undetermined W/B40103 ltr
HAYNES, J G Southern California Edison Co 84/01/03. MARTIN, J B
Region 5, Office of Director 3pp 21815 102 24X
Fiche 50-361,84/01/03,8401160210.

8401160198 LER 83-153/13X-0 on 831204, during surveillance testing,
undervoltage trip devices of reactor trip breakers 1 & 4
exhibited scattered & unacceptable response times. Reactor
trip breakers replaced W/B40104 ltr
HAYNES, J G Southern California Edison Co 84/01/04 MARTIN, J B
Region 5, Office of Director 4pp 21815 114 24X
Fiche 50-361,84/01/04,8401160198

8401160206 LER 83-107/03L-0 on 831205, w/unit in Mode 5, Zone 17 diesel
generator bldg preaction flame detector 2BSH8974 alarmed
& could not be reset Caused by faulty component on circuit
card Fire watch in effect W/B40106 ltr
HAYNES, J G Southern California Edison Co 84/01/06 MARTIN, J B
Region 5, Office of Director 3pp 21808 332 24X
Fiche 50-361,84/01/06,8401160206

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by
Lovejoy Coupling & installed by Transamerica Delaval, on
shafts in overspeed governor fuel transfer pump drive. Insp
of hubs in listed facilities recommended Utilis notified
BOYER, R. E Transamerica Delaval, Inc 84/01/09 Director's
Office, Office of Inspection and Enforcement 3pp 21828 269. 24X
Fiche 50-000,84/01/09,8401170186

8401260365 LER 83-152/03L-0 on 831213, while in Mode 4, remote shutdown
barometer 2A1-02038 found inoperable Caused by failed
display Display unit replaced W/B40112 ltr
HAYNES, J G Southern California Edison Co 84/01/12 MARTIN, J B
Region 5, Office of Director 3pp. 21935. 127 24X
Fiche 50-361,84/01/12,8401260365

8401260264 RD, on 840111, approx 23 NCRs identifying cable tray fire
wraps, UHF cable wrap, fire wall seismic joints & spray/
sprinkler sys determined not in full compliance w/fire
hazards analysis Damage due to subsequent activities.
HAYNES, J G Southern California Edison Co. 84/01/13 MARTIN, J B
Region 5, Office of Director 2pp 21935 209 24X
Fiche 50-361,84/01/13,8401260264

8401260361 LER 83-092/03L-0 on 831218, containment airborne radiation
monitor rendered inoperable when sample pump motor breaker
tripped Caused by insufficient margin between motor
operating current & thermal overload setpoint W/B40113 ltr
HAYNES, J G Southern California Edison Co 84/01/13 MARTIN, J B
Region 5, Office of Director 3pp 21955 148 24X
Fiche 50-361,84/01/13,8401260361

8401260074 LER 83-154/03L-0 on 831211, during Mode 5 outage, channel A
pressurizer level transmitter 2LT-0110-1 found inoperable
during performance of 18-month calibr Caused by empty ref
leg Leg filled W/B40116 ltr
HAYNES, J G Southern California Edison Co. 84/01/16 MARTIN, J B
Region 5, Office of Director 3pp 21957 004. 24X
Fiche 50-361,84/01/16,8401260074

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8401100018 Forwards detailed discussion of violations noted during wk
of 830926 re safe shutdown capability described in 10CFR50,
App R Encl Further describes corrective actions outlined in
830119 response Fire protection program review under way.
MEDFORD, M O Southern California Edison Co. 84/01/06
KNIGHTON, G W Licensing Branch 3 10pp 21761 120 24X
Fiche 50-361,83/01/06,8401100018

8401250163 Further response to FOIA request for documents re emergency
operation facilities Forwards App B documents App A & B
documents available in PDR App C documents entirely withheld
(ref FOIA Exemption 3)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X
Fiche 50-000,83/11/02,8401250163

--8305260382 Urges discussion on licensee disregard for NRC guidance
re location of permanent & backup emergency operations
facilities, per W Dircks 821227 memo Requests explanation re
Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners 83/01/06 Commissioners 2pp
21958 001 24X Fiche 50-000,83/11/02,8401250163.

--8305260362 Responds to Commissioner Gilinsky 830106 comments on 821227
memo re implementation of emergency response facilities
guidance Requested explanations re Waterford, San Onofre &
Millstone plans provided
DIRCKS, W J Office of the Executive Director for Operations.
83/02/15 PALLADINO, N Commissioners 2pp 21958 303. 24X
Fiche 50-000,83/11/02,8401250163

8401180254 Provides current status of emergency operations facility
ventilation sys mod & action necessary to address
in-leakage Plan to review training & educ ctr encl.
MEDFORD, M O Southern California Edison Co 84/01/09
EISENHUT, D O Division of Licensing 3pp 21844. 101 24X
Fiche 50-206,84/01/09,8401180254

8401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/83-24,
50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
NORDERHAUG, L R Region 5, Office of Director. 84/01/12
MCCARTHY, C B Southern California Edison Co 2pp. 21999 142 24X
Fiche 50-206,84/01/12,8401300183

--8401300188 IE Emergency Preparedness Insp Repts 50-206/83-24,
50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
Major areas inspected emergency detection & classification &
protective action decisionmaking.
NORTH, H S Region 5, Office of Director. 84/01/11. 15pp.
21999 144 24X Fiche. 50-206,84/01/12,8401300183.

8401240382 Forwards Addendum I to physical security plan, describing
temporary change to south protected area barrier. Addendum
withheld (ref 10CFR73 21).
HAYNES, J G Southern California Edison Co. 84/01/13 MARTIN, J B
Region 5, Office of Director 2pp. 21916 229 24X
Fiche 50-206,84/01/13,8401240382

8401250183 Requests exemption from requirement for state & local
participation in 840229 annual emergency exercise per
10CFR50, App E requirements. State & local govts participated
in three annual exercises in 1981, 1982 & on 830323
BASKIN, K P Southern California Edison Co 84/01/19. EISENHUT, D. O
Division of Licensing. 2pp 21935 210. 24X Fiche. 50-206,84/01/19,
8401250183

DOCKETED ITEMS

H General correspondence

B401240172 Requests all IE bulletins, info notices & other correspondence be addressed to KP Baskin KP Baskin B40103 ltr advising of recent organizational changes encl FRANKLIN, D A Southern California Edison Co B4/01/12 DEYOUNG, R Office of Nuclear Reactor Regulation, Director 1p 21908 276 24X Fiche 50-206, B4/01/12, B401240172

--B401240179 Advises of recent organizational changes within Util in process of preparing appropriate changes to licensing documentation to reflect changes for submittal in near future BASKIN, K P Southern California Edison Co B4/01/03 MARTIN, J B Region 5, Office of Director 3pp 21908 277 24X Fiche 50-206, B4/01/12, B401240172

P. Operating license stage documents & correspondence

B401260363 Discusses status of items outlined in Util B30311 ltr re Unit 2 startup & readiness of Unit 3 for initial criticality GOULD, W R Southern California Edison Co B3/08/19 MARTIN, J B Region 5, Office of Director 3pp 21956 018 24X Fiche 50-361, B3/08/19, B401260363

B309120493 Informs that NRR evaluation of reactor trip breaker problems completed, per B30314 request Review & licensee corrective actions documented in B30302 SER EISENHUT, D G Division of Licensing B3/08/31 CREWS, J L Division of Resident Reactor Project & Engineering Programs 1p 21957 135 24X Fiche 50-361, B3/08/31, B309120493

B401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies Supporting ltrs encl CALBOYAS, C D Affiliation Unknown B3/10/10 NRC - No Detailed Affiliation Given 4pp 21736 232 24X Fiche 50-000, B3/10/10, B401050027

B401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies. NRC has no records subj to request Utilis not required to submit insurance rating to NRC FELTON, J M Division of Rules and Records B3/10/25 CALBOYAS, C D Affiliation Unknown 1p 21736 236 24X Fiche 50-000, B3/10/25, B401050043

B401190108 Forwards notice of consideration of issuance of amend to License NPF-1B & proposed NSHC determination & opportunity for hearing re B30125, 0714 & 0923 submittals on fuel bowing DNBR calculation changes to Tech Specs RODD, H Licensing Branch 3 B3/12/15 BASKIN, K P Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 21871 032 24X Fiche 50-362, B3/12/15, B401190108

--B401190113 Notice of consideration of issuance of amend to License NPF-1B & proposed NSHC determination & opportunity for hearing re DNBR calculations of fuel rod bowing NSHC available in Central Files KNIGHTON, Q W Licensing Branch 3 B3/12/15 7pp 21871 035 24X Fiche 50-362, B3/12/15, B401190108

01180018 Forwards certification of pollution control facilities, in response to B31117 request DENTON, H R Office of Nuclear Reactor Regulation, Director B3/12/30 CHANDLER, D E California, State of 3pp 21847 349 24X Fiche 50-362, B3/12/30, B401180018

B401180023 Certification of pollution control facilities, DENTON, H R Office of Nuclear Reactor Regulation, Director B3/12/30 10pp 21847 352 24X Fiche 50-362, B3/12/30, B401180018

01260087 Forwards certification of pollution control facilities, DENTON, H R Office of Nuclear Reactor Regulation, Director B3/12/30 CHANDLER, D E California, State of 4pp 21990 337 24X Fiche 50-362, B3/12/30, B401260087

-B401260093 Certification of exam of financing application & application listing facilities under const or to be constructed at plant Such facilities in furtherance of purpose or controlling pollutants or contaminants in air & water, DENTON, H R Office of Nuclear Reactor Regulation, Director B3/12/30 1p 21990 340 24X Fiche 50-362, B3/12/30, B401260087

401050634 Application to amend Licenses NPF-10 & NPF-15, revising Tech Specs re containment ventilation sys. Proposed change increases current limit of 1,000 h to 3,000 h per yr on use of 8-inch containment purge sys MEDFORD, M O Southern California Edison Co B4/01/03 KNIGHTON, Q W Licensing Branch 3 3pp 21724 134 24X Fiche 50-361, B4/01/03, B401050634

--B401050639 Proposed Tech Specs re containment ventilation sys * Southern California Edison Co B3/05/16 5pp 21724 139 24X Fiche 50-361, B4/01/03, B401050634

B401050382 Generic Ltr B4-01 to all holders of ULs, applicants for ULs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl EISENHUT, D G Division of Licensing B4/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for ULs & full power authorizations re notice of meeting on facility staffing Svc list encl EISENHUT, D G Division of Licensing B4/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, B4/01/06, B401090221

B401100067 Advises that Cycle 2 fuel performance calculations, using FATES-3 code, will be completed prior to end of Cycle 1 for Unit 2, per License Condition 6 Detailed reevaluation of fission gas release for Cycle 1 unnecessary MEDFORD, M O Southern California Edison Co B4/01/06 KNIGHTON, Q W Licensing Branch 3 2pp 21761 147 24X Fiche 50-361, B4/01/06, B401100067

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for ULs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl EISENHUT, D G Division of Licensing B4/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, B4/01/13, B401130084

B401270266 Forwards Amend Applications 23 & 9 to Licenses NPF-10 & NPF-15, respectively, revising Tech Spec 3/4 3 2 re ESF actuation instrumentation to require testing of certain relays at 6-month intervals Amend fee encl BASKIN, K P Southern California Edison Co B4/01/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 21979 137 24X Fiche 50-361, B4/01/25, B401270266

--B401270270 Amend Applications 23 & 9 to Licenses NPF-10 & NPF-15, respectively, revising Tech Spec 3/4 3 2 re ESF actuation instrumentation to require testing of certain relays at 6-month intervals BASKIN, K P Southern California Edison Co B4/01/25 14pp 21979 161 24X Fiche 50-361, B4/01/25, B401270266

--B401270274 Proposed changes to Tech Spec 3/4 3 2 re ESF actuation sys instrumentation to require testing of certain relays at 6-month intervals * Southern California Edison Co B4/01/25 48pp 21979 175 24X Fiche 50-361, B4/01/25, B401270266

B401270376 Forwards "Leakage Reduction Program Test Results," demonstrating licensee compliance w/requirements of NUREG-0737, Item III, D 1 1 Procedure requiring sys walkdown written MEDFORD, M O Southern California Edison Co B4/01/25 KNIGHTON, Q W Licensing Branch 3 2pp 21976 022 24X Fiche 50-362, B4/01/25, B401270376

--B401270381 "Leakage Reduction Program Test Results" * Southern California Edison Co B4/01/25 15pp 21976 024 24X Fiche 50-362, B4/01/25, B401270376

G Inspection reports, IE Bulletins & correspondence

B401100018 Forwards detailed discussion of violations noted during wt of B30926 re safe shutdown capability described in 10CFR50, App R, Encl further describes corrective actions outlined in B31019 response Fire protection program review under way MEDFORD, M O Southern California Edison Co B4/01/06 KNIGHTON, Q W Licensing Branch 3 10pp 21761 120 24X Fiche 50-361, B3/01/06, B401100018

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR, FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982 * Director's Office, Office of Inspection and Enforcement B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

DOCKETED ITEMS

243

8401040590 Forwards preservice exam repts for Aug 1977 to Dec 1982
 Submittal includes info re completed repairs or replacements
 of items from completion of ASME Section III work to 831114
 W/a encls
 CURRAN, J M Southern California Edison Co 83/11/21 MARTIN, J B
 Region 5, Office of Director 1p 21706 286 24X
 Fiche 50-361,83/11/21,8401040590

8401030174 Confirms 831207 telcon re administrative error in 831129
 response to notice of violation identified in IE Insp Repts
 50-361/83-35 & 50-362/83-33 Safe shutdown circuit effort
 will be completed by 831222, not 831207
 HAYNES, J G Southern California Edison Co 83/12/12 MARTIN, J B
 Region 5, Office of Director 1p 21681 330 24X
 Fiche 50-361,83/12/12,8401030174

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
 W/Undervoltage Trip Feature in Use in Safety-Related
 Applications Other Than Reactor Trip Sys " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
 Brown Boveri Electric Type 5HK Breakers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/12/30 Consolidated Edison Co of New
 York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401100367 Responds to notice of violation & proposed imposition of
 civil penalty based on violations noted in IE Insp Repts
 50-206/83-21, 50-361/83-33 & 50-362/83-31 Addl training
 included in operator requalification program
 GASKIN, K P Southern California Edison Co 84/01/06 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement 9pp
 21764.090 24X Fiche 50-362,84/01/06,8401100367

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
 Voltage Levels Lower Than Analyzed " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/10 Consolidated Edison Co of New
 York, Inc 129pp 21946.053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
 Breeches " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/10 Consolidated Edison Co of New
 York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401230051 Ack receipt of 840106 ltr & check in amount of \$40,000 in
 payment for civil penalties proposed on 831208 Corrective
 actions described will be examined during future insp
 AXELRAD, J A Enforcement Staff 84/01/10 MCCARTHY, C B Southern
 California Edison Co 2pp 21905 354 24X Fiche 50-362,84/01/10,
 8401230051

8401300183 Forwards IE Emergency Preparedness Insp Repts 50-206/83-24,
 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
 NORBERHAUG, L R Region 5, Office of Director 84/01/12
 MCCARTHY, C B Southern California Edison Co 2pp 21999 142 24X
 Fiche: 50-206,84/01/12,8401300183

--8401300188 IE Emergency Preparedness Insp Repts 50-206/83-24,
 50-361/83-39 & 50-362/83-38 on 831205-09 No violation noted
 Major areas inspected emergency detection & classification &
 protective action decisionmaking
 NORTH, H S, TEMPLE, O M, SCHUSTER, M D Region 5, Office of
 Director 84/01/11 15pp 21999 144 24X Fiche 50-206,84/01/12,
 8401300188

8312120114 IE Info Notice 84-05, "Exercise Frequency," Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/16 Consolidated Edison Co of New
 York, Inc 127pp 21957.142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
 Notification of Disability by Licensed Operators." Svc list
 encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/18 Consolidated Edison Co of New
 York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
 Valves Used Only During Cold Shutdowns," Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/01/18 Consolidated Edison Co of New
 York, Inc 120pp 22000.041 24X Fiche 50-000,84/01/18,8312120117

8401300142 Forwards IE Insp Repts 50-206/83-25, 50-361/83-40 &
 50-362/83-39 on 831029-1209, No noncompliance noted
 BISHOP, T W Division of Resident, Reactor Project & Engineering
 Programs 84/01/19 MCCARTHY, C B Southern California Edison Co.
 2pp. 21998.263. 24X Fiche: 50-206,84/01/19,8401300142

--8401300151 IE Insp Repts 50-206/83-25, 50-361/83-40 & 50-362/83-39 on
 831029-1209 No noncompliance noted Major areas inspected
 operations program & Unit 3 startup test program
 CHAFFEE, A E, D'ANGELO, A, STEWART, J P Region 5, Office of
 Director 84/01/19 10pp 21998 265 24X Fiche 50-206,84/01/19,
 8401300142

8401300158 Forwards IE Insp Repts 50-206/83-27, 50-361/83-42 &
 50-362/83-41 on 831227-28 No noncompliance noted
 WENSLAWSKI, F A Region 5, Office of Director 84/01/19
 MCCARTHY, C B Southern California Edison Co 2pp 21999 111 24X
 Fiche 50-206,84/01/19,8401300158

--8401300160 IE Insp Repts 50-206/83-27, 50-361/83-42 & 50-362/83-41 on
 831227-28, No noncompliance noted Major areas inspected
 power ascension test program & licensee actions re release
 of matl contaminated w/low levels of radioactivity
 YUHAS, Q P, WENSLAWSKI, F A Region 5, Office of Director
 84/01/19 4pp 21999.113 24X Fiche 50-206,84/01/19,8401300158

R Periodic operating reports & related correspondence

8401120263 Monthly operating repts for Nov 1983 W/831215 ltr.
 MORRIS, C A, HAYNES, J G Southern California Edison Co 83/11/30
 Office of Resource Management, Director 12pp 21792 143 24X
 Fiche 50-361,83/11/30,8401120263.

8401270231 Monthly operating repts for Dec 1983 W/840116 ltr
 MORRIS, C A, HAYNES, J G Southern California Edison Co 83/12/31
 Division of Data Automation & Management Information 12pp.
 21976 338 24X Fiche 50-361,83/12/31,8401270231

B Reportable occurrences, LERs & related correspondence

8401040301 RD: on 831123, review indicated that five fire hazard analysis
 license amends & 33 nonconformance repts not maintained
 Compensatory fire watches established for inoperable
 fire-rated assemblies
 HAYNES, J G Southern California Edison Co 83/12/07 MARTIN, J B
 Region 5, Office of Director 2pp 21705 078 24X
 Fiche: 50-361,83/12/07,8401040301

8401040187 LER 83-09B/03L-0 on 831108, qualified safety parameter
 display sys Channel A observed continuously cycling through
 pages of display & channel declared inoperable Caused by
 loose circuit board Loose board reseated W/831208 ltr
 HAYNES, J G Southern California Edison Co 83/12/08 MARTIN, J B
 Region 5, Office of Director 3pp 21702 079 24X
 Fiche 50-362,83/12/08,8401040187

8401040302 LER 83-109/03L-0 on 831111, qualified safety parameter
 display sys channel A began intermittently failing &
 declared inoperable. Caused by failed power supply to plasma
 display Power supply replaced W/831212 ltr
 HAYNES, J G Southern California Edison Co 83/12/12 MARTIN, J B
 Region 5, Office of Director 3pp 21705 080 24X
 Fiche 50-362,83/12/12,8401040302

8401040307 LER 83-102/03L-0 on 831116, channel A of post-LOCA hydrogen
 monitor failed & declared inoperable Caused by shorted
 capacitor in circuit board resulting in blown fuse. Circuit
 board & fuse replaced W/831215 ltr
 HAYNES, J G Southern California Edison Co 83/12/15 MARTIN, J B
 Region 5, Office of Director 3pp 21708 009 24X
 Fiche 50-362,83/12/15,8401040307

8401040474 RD: during Nov surveillance, listed fire doors found
 inoperable Caused by latching mechanism & closure
 mechanism failures & doors blocked open for const startup &
 maint activities Design change packages developed.
 HAYNES, J G Southern California Edison Co 83/12/15 MARTIN, J B
 Region 5, Office of Director 5pp 21714.031 24X
 Fiche 50-361,83/12/15,8401040474

8401040306 LER 83-105/03L-0 on 831117 & 29, mini-purge exhaust
 containment isolation valve 3HV9825 failed to close within
 max isolation time Caused by imbalance between opening air
 supply pressure & closing spring tension W/831216 ltr
 HAYNES, J G Southern California Edison Co 83/12/16 MARTIN, J B
 Region 5, Office of Director 3pp 21708.105 24X
 Fiche 50-362,83/12/16,8401040306.

8401040343 LER 83-100/03L-0 on 831116, w/util in Mode 1, containment
 airborne monitor 3RI-7804C found in constant alarm state
 Caused by containment radioactivity increasing to greater
 than setpoints New setpoints implemented W/831219 ltr
 HAYNES, J G Southern California Edison Co 83/12/19 MARTIN, J B
 Region 5, Office of Director 1p. 21706 210 24X
 Fiche: 50-362,83/12/19,8401040343

DOCKETED ITEMS

8401040386 LER 83-106/03L-0 on 831117, Surveillance Test 3023-3-3 6 indicated that DNBR margin not within allowable limits. Caused by conservatism inherent in procedure. Acceptable DNBR margin verified within 1 h W/831219 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/19 MARTIN, J. B. Region 5, Office of Director 4pp 21708-046 24X. Fiche 50-362, 83/12/19, 8401040386

8401120219 LER 83-108/03L-0 on 831123, qualified safety parameter display sys (GSPDS) channel A failed & declared inoperable. Caused by interference in plasma display unit due to ground loops. Grounding configuration modified W/831222 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/22 MARTIN, J. B. Region 5, Office of Director 3pp 21792 257 24X. Fiche 50-362, 83/12/22, 8401120219

8401120237 LER 83-083/03L-0 on 831123, diesel generator 30003 tripped & could not be restarted. Caused by blown air-start sys air compressor head gaskets replaced W/831223 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/23 MARTIN, J. B. Region 5, Office of Director 3pp 21793 330 24X. Fiche 50-362, 83/12/23, 8401120237

8401120256 LER 83-107/03L-0 on 831124, component cooling water outlet valve 3HV-6367 failed to open fully, rendering train A containment emergency cooling unit 3E-401 inoperable. Caused by premature opening of torque switch W/831223 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/23 MARTIN, J. B. Region 5, Office of Director 3pp 21793 283 24X. Fiche 50-362, 83/12/23, 8401120256

8401120248 LER 83-104/03L-0 on 831205, high auxiliary feedwater (AFW) flow rate erroneously indicated when no flow existed. Steam generator E-069 AFW flow rate channel declared inoperable. Caused by loose voltage converter terminal W/831230 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/30 MARTIN, J. B. Region 5, Office of Director 3pp 21793 270 24X. Fiche 50-362, 83/12/30, 8401120248

8401160294 LER 83-112/03L-0 on 831130, regulating group & control element assemblies exceeded time allowed below long-term steady-state insertion limit. Caused by need to control axial shape index oscillations W/831230 ltr. HAYNES, J. Q. Southern California Edison Co. 83/12/30 MARTIN, J. B. Region 5, Office of Director 3pp 21814:346 24X. Fiche 50-362, 83/12/30, 8401160294

8401160276 LER 83-117/03L-0 on 831202, control element assembly 64 slipped 10 inches. Caused by faulty IC chip on rod timer card. Timer card replaced W/840103 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/03 MARTIN, J. B. Region 5, Office of Director 3pp 21813 331 24X. Fiche 50-362, 84/01/03, 8401160276

8401160300 LER 83-110/03L-0 on 831202 & 22, sub j control element assemblies slipped & became misaligned from other assemblies in group. Caused by sluggish operation of assemblies, causing upper & lower grippers to sequence improperly W/840103 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/03 MARTIN, J. B. Region 5, Office of Director 3pp 21813 290 24X. Fiche 50-362, 84/01/03, 8401160300

8401160223 PNO-V-84-001 on 840101, unplanned gaseous releases occurred, causing plant vent stack to alarm. Release caused by draining 20 gallons of water from charging sys to floor drain. Release estimated to be 80 Ci mixed noble gases. YUHAS, G.; WENSLAWSKI, F. Region 5, Office of Director 84/01/04, 1p. 21813 358 24X. Fiche 50-362, 84/01/04, 8401160223

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended. Utils notified, BOYER, R. E. Transamerica Delaval, Inc. 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X. Fiche 50-000, 84/01/09, 8401170186

101260225 LER 83-113/03L-0 on 831210, control element assembly calculator 2 failed. Caused by faulty central processing unit Board replaced W/840109 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/09 MARTIN, J. B. Region 5, Office of Director 3pp 21756 289 24X. Fiche 50-362, 84/01/09, 8401260225

401260016 LER 83-115/03L-0 on 831214, core protection calculator channel C local power density trip & DNBR received in control room. Caused by failed module card. Card replaced & order written to troubleshoot & repair card. W/840113 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/13 MARTIN, J. B. Region 5, Office of Director 3pp 21756:314 24X. Fiche 50-362, 84/01/13, 8401260016

8401260264 RD on 840111, approx 23 NCRs identifying cable tray fire wraps, UHF cable wrap, fire wall seismic joints & spray/sprinkler sys determined not in full compliance w/fire hazards analysis. Damage due to subsequent activities. HAYNES, J. Q. Southern California Edison Co. 84/01/13 MARTIN, J. B. Region 5, Office of Director 2pp 21755 209 24X. Fiche 50-361, 84/01/13, 8401260264

8401260298 LER 83-120/03L-0 on 831222, while in Mode 1, both main feedwater pumps tripped due to low suction pressure. Caused by high water demand on condensate storage tank 3T-121 by auxiliary feedwater sys. Review underway W/840113 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/13 MARTIN, J. B. Region 5, Office of Director 3pp 21755 136 24X. Fiche 50-362, 84/01/13, 8401260298

8401260073 LER 83-114/03L-0 on 831215, nitrogen cover pressure in safety injection tank 3T-007 discovered below min. Caused by excessive draining resulting from sampling technique which allows sampling outside containment W/840116 ltr. HAYNES, J. Q. Southern California Edison Co. 84/01/16 MARTIN, J. B. Region 5, Office of Director 3pp 21757 117 24X. Fiche 50-362, 84/01/16, 8401260073

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8401030445 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19. VERRELLI, D. M. Division of Project & Resident Programs 83/12/20. McDONALD, R. P. Alabama Power Co. 1p. 21730 214 24X. Fiche 50-348, 83/12/20, 8401030445

--8401030448 Responds to NRC 830907 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19. Corrective actions mgt directive issued reemphasizing that fire protection program reevaluation considered on same basis as FSAR. CLAYTON, F. L. Alabama Power Co. 83/12/09. VERRELLI, D. M. Division of Project & Resident Programs. 67pp 21730 218 24X. Fiche 50-348, 83/12/20, 8401030448

8401060408 Forwards IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-1B No noncompliance noted. VERRELLI, D. M. Division of Project & Resident Programs 83/12/21. McDONALD, R. P. Alabama Power Co. 2pp 21741 083 24X. Fiche 50-348, 83/12/21, 8401060408

--8401060410 IE Insp Repts 50-348/83-28 & 50-364/83-26 on 831114-1B No noncompliance noted. Major areas inspected emergency preparedness. STODDART, P. O. Region 2, Office of Director 83/12/08 8pp 21741 083 24X. Fiche 50-348, 83/12/21, 8401060408

8401060436 Confirms 840112 mgt meeting w/util in Atlanta, GA to discuss 10CFR50, App R fire protection requirements. Proposed agenda encl. LEWIS, R. C. Division of Project & Resident Programs 83/12/22. McDONALD, R. P. Alabama Power Co. 2pp 21740 156 24X. Fiche 50-348, 83/12/22, 8401060436

8401030371 Releases public version of revised emergency plan. FELTON, J. M. Division of Rules and Records 83/12/27. Document Management Branch 1p 21694 001 24X. Fiche 50-348, 83/12/27, 8401030371

--8401030374 Public version of Rev B to emergency plan, W/831213 ltr. HUDSPETH, J. B. Alabama Power Co. 83/12/07. Office of Nuclear Reactor Regulation, Director 600pp 21694 002 24X. Fiche 50-348, 83/12/27, 8401030371

8401060115 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records 83/12/27. Document Management Branch 1p. 21746 082 24X. Fiche 50-348, 83/12/27, 8401060115

--8401060121 Forwards public version of revised emergency plan implementing procedures, including Procedures 80-EIP-114 re news release coordination & distribution & 80-EIP-134 re corporate emergency plan training. MUDD, C. H. Alabama Power Co. 83/11/21. Document Management Branch. 2pp 21746 083 24X. Fiche 50-348, 83/12/27, 8401060115

--8401060126 Public version of revised emergency plan implementing procedures, including Procedures 80-EIP-114 re news release coordination & distribution & 80-EIP-134 re corporate emergency plan training. MCDONALD, J. W. Alabama Power Co. 83/11/21 100pp. 21746 085 24X. Fiche 50-348, 83/12/27, 8401060115

DOCKETED ITEMS

248

B401100167 Ack receipt of B31116 ltr re emergency exercise scheduled for site during Feb 1984 Planned exercise & objectives reviewed & discussed Addl comments will be made by telephone to McCracken
VERRELL, D. M. Division of Project & Resident Programs B4/01/04
MCDONALD, R. P. Alabama Power Co. 1p 21760 171 24X
Fiche 50-348, B4/01/04, B401100167

B401190444 Forwards Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively Amends require audit of emergency preparedness program at least once per 12 months (per Generic Ltr 82-17)
REEVES, E. A. Operating Reactors Branch 1 B4/01/06 CLAYTON, F. L.
Alabama Power Co. 3pp 21857 357 24X Fiche 50-348, B4/01/06, B401190444

--B401190451 Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively, requiring audit of emergency preparedness program at least once per 12 months (per Generic Ltr 82-17)
VARGA, B. A. Operating Reactors Branch 1 B4/01/06 Bpp.
21858 001 24X Fiche 50-348, B4/01/06, B401190444

--B401190460 Safety evaluation supporting Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director B4/01/06 2pp
21858 006 24X Fiche 50-348, B4/01/06, B401190444

B401200284 Releases public version of addition to emergency plan rev
FELTON, J. M. Division of Rules and Records B4/01/17 Document
Management Branch 1p 21890 361 24X Fiche 50-348, B4/01/17, B401200284

--B401200288 Public version of addition to Rev 5 to emergency plan entitled, "Region II Suppl to NUREG-0845"
* Alabama Power Co. 83/10/31 164pp 21890 362 24X
Fiche 50-348, B4/01/17, B401200284

B401250002 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B4/01/17. Document
Management Branch 1p 21948 218 24X Fiche 50-348, B4/01/17, B401250002

--B401250003 Public version of Rev 13 to Emergency Plan Implementing Procedure FNP-0-EIP-0, "Radiation Exposure Estimation & Classification of Emergencies" W/B40104 ltr
HUDBETH, J. B. Alabama Power Co. B4/01/03 Document Management
Branch 119pp 21948 219 24X Fiche 50-348, B4/01/17, B401250002

B401260181 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B4/01/18 Document
Management Branch 1p 21971, 290 24X Fiche 50-348, B4/01/18, B401260181

--B401260185 Public version of Rev 3 to Emergency Plan Implementing Procedure QO-EIP-112, "Emergency Mobile Communications," W/B31215 ltr
MCDOWAN, J. W., MUDD, C. H. Alabama Power Co. 83/12/15 NRC - No
Detailed Affiliation Given 9pp 21971 292 24X
Fiche 50-348, B4/01/18, B401260181

B401260266 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B4/01/18 Document
Management Branch 1p 21992 316 24X Fiche 50-348, B4/01/18, B401260266

--B401260270 Public version of Rev 8 to Emergency Plan Implementing Procedure FNP-0-EIP-15, "Emergency Drills" W/B31228 ltr & receipt form
HUDBETH, J. B. Alabama Power Co. 83/12/22 Office of Nuclear
Reactor Regulation, Director 9pp 21992 317 24X
Fiche: 50-348, B4/01/18, B401260266

B401240624 Releases public version of figures to revised emergency plan administrative procedure
FELTON, J. M. Division of Rules and Records B4/01/20. Document
Management Branch. 1p. 21944, 347 24X Fiche 50-348, B4/01/20, B401240624

--B401240627 Public version of figures to Rev 13 to Emergency Plan Administrative Procedure FNP-0-EIP-9 re relative dose rate plume boundary W/B40105 & 06 ltrs
HUDBETH, J. B. Alabama Power Co. B4/01/05 Office of Nuclear
Reactor Regulation, Director 12pp 21944, 348 24X
Fiche 50-348, B4/01/20, B401240624

B401240630 Releases public version of emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B4/01/20 Document
Management Branch 1p 21944 335 24X Fiche 50-348, B4/01/20, B401240630

--B401240632 Public version of Rev 2 to Emergency Plan Implementing Procedure QO-EIP-132, "Emergency Plan Drills & Exercises" W/B30103 ltr
MCDOWAN, J. W. Alabama Power Co. B4/01/03 NRC - No Detailed
Affiliation Given 11pp 21944 336 24X Fiche 50-348, B4/01/20, B401240630

B401240638 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records B4/01/20 Document
Management Branch 1p 21944 218 24X Fiche 50-348, B4/01/20, B401240638

--B401240642 Forwards public version of Rev 1 to Emergency Plan Implementing Procedures QO-EIP-119, "Relocation of Emergency Operations Facility (EOF) Functions to Alternate EOF" & QO-EIP-116, "Emergency Operations Facility Shift Turnover"
MUDD, C. H. Alabama Power Co. B4/01/12 NRC - No Detailed
Affiliation Given 1p 21944 219 24X Fiche: 50-348, B4/01/20, B401240638

--B401240645 Public version of Rev 1 to Emergency Plan Implementing Procedures QO-EIP-119, "Relocation of Emergency Operations Facility (EOF) Functions to Alternate EOF" & QO-EIP-116, "Emergency Operations Facility Shift Turnover"
MCDOWAN, J. W. Alabama Power Co. B4/01/12 31pp 21944, 220 24X
Fiche 50-348, B4/01/20, B401240638

B401260296 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records B4/01/20. Document
Management Branch. 1p 21992 118 24X Fiche 50-348, B4/01/20, B401260296

--B401260299 Public version of Rev 7 to Emergency Plan Implementing Procedure FNP-0-EIP-26, "Offsite Notification" W/B40101 ltr & receipt form
HUDBETH, J. B. Alabama Power Co. 83/12/21 Document Management
Branch 25pp 21992: 119, 24X Fiche 50-348, B4/01/20, B401260296

B401260330 Releases public version of rev to emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records. B4/01/20 Document
Management Branch. 1p 21992: 097 24X Fiche 50-348, B4/01/20, B401260330.

--B401260334 Public version of Rev 1 to Emergency Plan Implementing Procedure QO-EIP-101, "Corporate Emergency Organization" W/B30104 ltr & receipt form
MCDOWAN, J. W. Alabama Power Co. B4/01/04. Document Management
Branch 20pp 21992, 117. 24X Fiche: 50-348, B4/01/20, B401260330.

B401310229 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records B4/01/20. Document
Management Branch 1p 22037: 151 24X Fiche, 50-348, B4/01/20, B401310229

--B401310236 Forwards public version of Rev 2 to Emergency Plan Implementing procedure QO-EIP-117 re emergency operations facility administrative support & Rev 3 to Procedure QO-EIP-131 re emergency operations ctr.
MUDD, C. H. Alabama Power Co. B4/01/05. Document Management
Branch 1p 22037, 152 24X Fiche, 50-348, B4/01/20, B401310229.

--B401310240 Public version of Rev 2 to Emergency Plan Implementing Procedure QO-EIP-117 re emergency operations facility administrative support & Rev 3 to Procedure QO-EIP-131 re emergency operations ctr.
MCDOWAN, J. W. Alabama Power Co. B4/01/05 36pp, 22037 154. 24X
Fiche, 50-348, B4/01/20, B401310229

P Operating license stage documents & correspondence

B401060238 Notification of B40110 meeting w/util in Bethesda, MD to discuss proposed Tech Spec change on inoperable control rods proposed in util B31010 ltr
REEVES, E. A. Operating Reactors Branch 1. 83/12/28. VARGA, B. A.
Operating Reactors Branch 1. 2pp 21755: 150. 24X
Fiche, 50-348, 83/12/28, B401060238

B401130026 Forwards Amends 38 & 28 to Licenses NPF-2 & NPF-B, respectively & safety evaluation, Amends change Tech Specs to incorporate overtime limitations in Generic Ltr 82-12 per TMI Action Item I A 1.3
REEVES, E. A. Operating Reactors Branch 1 83/12/30. CLAYTON, F. L.
Alabama Power Co. 2pp. 21821-004 24X Fiche: 50-348, 83/12/30, B401130026.

DOCKETED ITEMS

--B401130030 Amends 3B & 2B to Licenses NPF-2 & NPF-B, respectively, changing Tech Specs to incorporate overtime limitations in Generic Ltr B2-12 per TMI Action Item 1 A 1.3
VARQA, B A Operating Reactors Branch 1 83/12/30 8pp
21821 006 24X Fiche 50-348, 83/12/30, B401130026

--B401130038 Safety evaluation supporting Amends 3B & 2B to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director 83/12/30 2pp
21821 014 24X Fiche 50-348, 83/12/30, B401130026

B401180080 Requests addl info re river water sys & diesel generator testing, per B21220 DL amend request Response should be provided within 45 days of ltr receipt
VARQA, B A Operating Reactors Branch 1 84/01/04 CLAYTON, F L
Alabama Power Co App 21848 214 24X Fiche 50-348, 84/01/04, B401180080

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Bvc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche: 50-000, 84/01/06, B401090221

B401160084 Forwards response to B31216 Generic Ltr B3-41 re cold starts of diesel generators Fast cold starts exacerbate bearing wear due to lack of prelubrication Fast cold starts should be avoided, except for emergencies
CLAYTON, F L Alabama Power Co 84/01/06 EISENHUT, D O Office of Nuclear Reactor Regulation, Director. 2pp 21815 055 24X
Fiche: 50-348, 84/01/06, B401160084

B401190444 Forwards Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively Amends require audit of emergency preparedness program at least once per 12 months (per Generic Ltr B2-17)
REEVES, E A Operating Reactors Branch 1 84/01/06 CLAYTON, F L
Alabama Power Co 3pp 21837 357 24X Fiche 50-348, 84/01/06, B401190444

--B401190451 Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively, requiring audit of emergency preparedness program at least once per 12 months (per Generic Ltr B2-17)
VARQA, B A Operating Reactors Branch 1 84/01/06 8pp
21837: 360 24X Fiche: 50-348, 84/01/06, B401190444.

-B401190460 Safety evaluation supporting Amends 39 & 29 to Licenses NPF-2 & NPF-B, respectively
* Office of Nuclear Reactor Regulation, Director. 84/01/06 2pp
21838 006 24X Fiche: 50-348, 84/01/06, B401190444

B401190261 Forwards Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively & safety evaluation Amends delete applicability of Tech Spec Table 3.3-3 re safety injection signal & correct Multi-Plant Action Item B-32
REEVES, E A Operating Reactors Branch 1 84/01/09 CLAYTON, F L
Alabama Power Co. App 21870 079 24X Fiche: 50-348, 84/01/09, B401190261.

--B401190268 Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively, deleting applicability of footnote to Item 1.5 in Table 3.3-3 re safety injection signal & correcting Multi-Plant Item B-32 re blocked safety injection signal
VARQA, B A Operating Reactors Branch 1. 84/01/09 8pp.
21870 083 24X Fiche 50-348, 84/01/09, B401190261.

--B401190276 Safety evaluation supporting Amends 40 & 30 to Licenses NPF-2 & NPF-B, respectively.
* Office of Nuclear Reactor Regulation, Director 84/01/09 2pp
21870 091 24X Fiche: 50-348, 84/01/09, B401190261

B401130448 Notification of B40120 meeting w/util in Bethesda, MD to discuss proposed Tech Spec change re inoperable control rods
REEVES, E A Operating Reactors Branch 1 84/01/10. VARQA, B A
Operating Reactors Branch 1 3pp 21819 342. 24X
Fiche: 50-348, 84/01/10, B401130448

B401300021 Forwards BER re util responses to NUREG-0737, Item II K.2.17, "Potential for Voiding in RCB during Transients" Voids generated in RCB during anticipated transients accounted for in present analysis models.
VARQA, B A Operating Reactors Branch 1. 84/01/10 CLAYTON, F L
Alabama Power Co 10pp. 22027.306. 24X Fiche: 50-348, 84/01/10, B401300021.

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0737, "Prioritization of Generic Safety Issues" Bvc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

0 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp. 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401050560 Ack receipt of B31207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-26 & 50-364/83-24
LEWIS, R C Division of Project & Resident Programs 83/12/16.
MCDONALD, R P Alabama Power Co 1p 21724 270 24X
Fiche 50-348, 83/12/16, B401050560

--B401050606 Responds to NRC B31107 ltr re violations noted in IE Insp Repts 50-348/83-26 & 50-364/83-24 Corrective actions
Procedure FNP-C-AP-16 revised to require locking device be removed prior to verifying open position of locked valve
CLAYTON, F L Alabama Power Co 83/12/07. LEWIS, R C Division of Project & Resident Programs 3pp 21724 271 24X
Fiche 50-348, 83/12/16, B401050560

--B401050611 Forwards IE Insp Repts 50-348/83-26 & 50-364/83-24 on B30911-1010 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07
MCDONALD, R P Alabama Power Co 2pp 21724 274 24X
Fiche 50-348, 83/12/16, B401050560

--B401050616 Notice of violation from insp on B30911-1010
* Region 2, Office of Director 83/11/07 1p 21724 276 24X
Fiche 50-348, 83/12/16, B401050560

--B401050626 IE Insp Repts 50-348/83-26 & 50-364/83-24 on B30911-1010
Violation noted containment spray loop 2A eductor supply valve locked in closed position while Unit 2 in cold shutdown
BRADFORD, W H, RULAND, W H, CANTRELL, F B Region 2, Office of Director 83/11/03 13pp 21724 277 24X Fiche 50-348, 83/12/16, B401050560

B401050448 Ack receipt of B31209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19
VERRELLI, D M Division of Project & Resident Programs 83/12/20
MCDONALD, R P Alabama Power Co 1p 21730 214 24X
Fiche: 50-348, 83/12/20, B401050448

--B401050448 Responds to NRC B30909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions mgt
directive issued reemphasizing that fire protection program reevaluation considered on same basis as FSAR
CLAYTON, F L Alabama Power Co 83/12/09 VERRELLI, D M Division of Project & Resident Programs 67pp 21730 215 24X
Fiche: 50-348, 83/12/20, B401050448

B401060408 Forwards IE Insp Repts 50-348/83-28 & 50-364/83-26 on B31114-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/12/21
MCDONALD, R P Alabama Power Co 2pp 21741 083 24X
Fiche 50-348, 83/12/21, B401060408

--B401060410 IE Insp Repts 50-348/83-28 & 50-364/83-26 on B31114-18 No noncompliance noted. Major areas inspected emergency preparedness.
STODDART, P G Region 2, Office of Director JENKINS, O R
Division of Emergency Preparedness & Materials Safety 83/12/08
8pp 21741 085. 24X Fiche: 50-348, 83/12/21, B401060408

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Bvc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 83/12/28 Consolidated Edison Co of New York, Inc
124pp. 21731 166. 24X Fiche 50-000, 83/12/28, B312120090

DOCKETED ITEMS

24

8401240598 Forwards IE Insp Repts 50-348/83-30 & 50-344/83-28 on 831111-1210 No violations or deviations noted
VERRELL, D M Division of Project & Resident Programs 83/12/29
MCDONALD, R P Alabama Power Co 2pp 21909 197 24X
Fiche 50-348, 83/12/29, 8401240598

--8401240606 IE Insp Repts 50-348/83-30 & 50-344/83-28 on 831111-1210 No violations or deviations noted Major areas inspected plant status, monthly surveillance observation, monthly maint observation & operational safety verification
BRADFORD, W H, RULAND, W H Region 2, Office of Director
CANTRELL, F S Division of Project & Resident Programs 83/12/28
9pp 21909 199 24X Fiche 50-348, 83/12/29, 8401240598

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401240558 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-29 & 50-364/83-27
LEWIS, R C Division of Project & Resident Programs 84/01/11
MCDONALD, R P Alabama Power Co 1p 21909 106 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240565 Responds to NRC 831207 ltr re violations noted in IE Insp Repts 50-348/83-29 & 50-364/83-27 Corrective actions personnel counseled to adhere to plant procedures & monitor cooldown limits closely
CLAYTON, F L Alabama Power Co 84/01/06 LEWIS, R C Region 2, Office of Director 3pp 21909 107 24X Fiche 50-348, 84/01/11, 8401240558

--8401240567 Forwards IE Insp Repts 50-348/83-29 & 50-364/83-27 on 831011-1110 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/12/07
MCDONALD, R P Alabama Power Co 2pp 21909 110 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240571 Notice of violation from insp on 831011-1110, * Region 2, Office of Director 83/12/07 1p 21909 112. 24X
Fiche 50-348, 84/01/11, 8401240558

--8401240580 IE Insp Repts 50-348/83-29 & 50-364/83-27 on 831011-1110 Violation noted, heaters not tested & humidity sensors which turn heaters on & off not verified operable & Tech Spec limit exceeded for RCS cooldown rate
BRADFORD, W H, RULAND, W H Region 2, Office of Director
CANTRELL, F S Division of Project & Resident Programs 83/12/06
12pp 21909 113 24X Fiche 50-348, 84/01/11, 8401240558

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance w/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117.

R. Periodic operating reports & related correspondence

8401170197 Monthly operating rept for Dec 1983 W/840115 ltr
HAIRSTON, W O, CLAYTON, F L Alabama Power Co. 83/12/31 Office
of Resource Management, Director 7pp 21831-232 24X
Fiche 50-364, 83/12/31, 8401170197

S Reportable occurrences, LERs & related correspondence

8401030123 LER 83-062/03L-0 on 831121, inverter 2D declared inoperable due to failed capacitor Caused by component failure.
Capacitor replaced W/831220 ltr
HAIRSTON, W O, CLAYTON, F L Alabama Power Co 83/12/20. Region 2, Office of Director 2pp 21683 133 24X Fiche 50-364, 83/12/20, 8401030123

8401040359 RO on 831224, fire protection tank A & B levels fell to approx 232,000 gallons each due to extreme cold, causing cooling tower 1C fire protection sys to fail On 831226, tank levels found below min due to personnel error
HAIRSTON, W O Alabama Power Co 83/12/27 O'REILLY, J P Region 2, Office of Director 1p 21706 151 24X Fiche 50-348, 83/12/27, 8401040359

8401060465 Forwards LERs 83-084/03L-0, 83-087/03L-0, 83-088/03L-0 & 83-063/03L-0.
CLAYTON, F L Alabama Power Co 83/12/27 Region 2, Office of Director 1p 21740 055 24X Fiche 50-348, 83/12/27, 8401060465

--8401060489 LER 83-063/03L-0 on 831206, instrumentation channel associated w/level indicator LI-4075A (refueling water storage tank) declared inoperable due to erroneous high indication Caused by transmitter box leak Cover repaired
HAIRSTON, W O Alabama Power Co 83/12/27 Region 2, Office of Director 3pp 21740 068 24X Fiche 50-348, 83/12/27, 8401060465

8401240263 Forwards LERs 83-089/03L-0 & 83-064/03L-0
CLAYTON, F L Alabama Power Co 84/01/13 Region 2, Office of Director 1p 21910 027 24X Fiche 50-348, 84/01/13, 8401240263

--8401240275 LER 83-064/03L-0 on 831214, instrumentation channel associated w/flow indicator FI-474 declared inoperable due to drifting out of tolerance Cause unknown Steam generator 2A FI-474 loop calibr & functional test conducted
HAIRSTON, W O Alabama Power Co 84/01/13 Region 2, Office of Director 3pp 21910 030 24X Fiche 50-348, 84/01/13, 8401240263

8401300287 Forwards LERs 83-090/03L-0, 83-091/03L-0, 83-092/03L-0, 83-065/03L-0 & 83-066/03L-0
CLAYTON, F L Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21977 301 24X Fiche 50-348, 84/01/20, 8401300287

--8401300303 LER 83-065/03L-0 on 831227, instrumentation channel associated w/temp indicator TI-432D declared inoperable Caused by drift of lead/lag card gain Card replaced & channel declared operable
HAIRSTON, W O Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21977 306 24X Fiche 50-348, 84/01/20, 8401300287

--8401300306 LER 83-066/03L-0 on 831231, instrumentation channel associated w/flow transmitter FT-476 declared inoperable Caused by drift of square root extraction card Card replaced & channel returned to svc
HAIRSTON, W O Alabama Power Co 84/01/20 Region 2, Office of Director 1p 21977-307 24X Fiche 50-348, 84/01/20, 8401300287

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8401050621 Forwards IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/09
KELLY, R J Georgia Power Co 2pp 21726 062. 24X
Fiche 50-321, 83/12/09, 8401050621.

--8401050633 IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted Major areas inspected: plant tours, plant operations review, Tech Spec compliance, physical protection, refueling activity & spent fuel pool activity
MATHIS, J L Region 2, Office of Director 83/12/06 5pp
21726 064. 24X Fiche 50-321, 83/12/09, 8401050621

8401060446 Discusses Jan & Feb 1983 revs to radiological emergency plan Revs meet applicable planning stds of 10CFR50
Outstanding issues identified in IE Insp Repts 50-321/83-19 & 50-366/83-19
DANCE, H C Division of Project & Resident Programs 83/12/30
KELLY, R J Georgia Power Co. 2pp 21740:089. 24X
Fiche 50-321, 83/12/30, 8401060446

8401240285 Expresses appreciation for util effort in investigation & subsequent arrest & terminations in response to recent bomb threats.
O'REILLY, J P Region 2, Office of Director 84/01/13 KELLY, R J
Georgia Power Co 1p. 21909 340. 24X Fiche: 50-321, 84/01/13, 8401240285.

DOCKETED ITEMS

8401240379 Ack receipt of 840106 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/83-30
LEWIS, R C Division of Project & Resident Programs 84/01/13
KELLY, R J Georgia Power Co 1p 21909 149 24X
Fiche 50-321,84/01/13,8401240379

--8401240377 IE Insp Repts 50-321/83-30 & 50-366/83-32 on 831001-31
Noncompliance noted failure to establish required fire
watches
CRLINJAK, R V. Region 2, Office of Director. 83/12/07. 4pp
21909 156 24X Fiche 50-321,84/01/13,8401240379

8401240099 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21932 232 24X Fiche 50-321,84/01/18,
8401240099

--8401240102 Forwards public version of revised emergency plan
implementing procedures, including Procedures HNP-8035 re
pulmonary function screening program & HNP-8016 re shipment
of radioactive matl.
NIX, H C Georgia Power Co 83/12/05 Office of Nuclear Reactor
Regulation, Director. 1p. 21932 233 24X Fiche 50-321,84/01/18,
8401240099

--8401240106 Public version of revised emergency plan implementing
procedures, including Procedures HNP-8035 re pulmonary
function screening program & HNP-8016 re shipment of
radioactive matl.
ROEDER, W H, GREENE, T J, NIX, H C Georgia Power Co 83/12/07
133pp. 21932 234. 24X Fiche 50-321,84/01/18,8401240099.

8401260056 Releases public version of revised site emergency plan
FELTON, J M Division of Rules and Records. 84/01/18 Document
Management Branch 1p 21989 255 24X Fiche 50-321,84/01/18,
8401260056

--8401260059 Public version of Rev 5 to site emergency plan W/83108
memo & receipt form
OLLINGER, W H, QUICHA, L T Georgia Power Co. 83/11/08 Office
of Nuclear Reactor Regulation, Director. 48pp. 21989 257 24X
Fiche 50-321,84/01/18,8401260056.

8401310315 Submits info documenting addl considerations of projected
phased improvement in fire protection & mitigating factors
for areas unmodified during extended implementation period.
Tentative completion dates for App R mods encl.
BECKHAM, J T Georgia Power Co 84/01/24. BTOLZ, J F. Operating
Reactors Branch 4 3pp. 22026 281 24X Fiche: 50-321,84/01/24,
8401310315

1. Insurance & indemnity information

8401050269 Forwards Endorsement 84 to NELIA Policy NF-215 & Endorsement
69 to HAELO Policy NF-78.
FIELDER, J. Marsh & McLennan, Inc. 83/12/27. SALTZMAN, J Assistant
Director for State & License Relations. 3pp. 21727 168 24X
Fiche: 50-321,83/12/27,8401050269

1. Operating license stage documents & correspondence

101060260 Summarizes 831209 meeting in Atlanta, GA re proposed
organizational changes
O'REILLY, J P. Region 2, Office of Director 83/12/15 KELLY, R J
Georgia Power Co. 1p 21740 139 24X Fiche: 50-321,83/12/15,
8401060260.

101040347 Application for amend to License NPF-5, allowing operation of
traversing in-core probe for 31 effective full power days w/
one or more sys probes inoperable
HEAD, O F Georgia Power Co. 83/12/21 BTOLZ, J F Operating
Reactors Branch 4. 2pp. 21706 136 24X Fiche: 50-366,83/12/21,
8401040347.

7401040349 Proposed Tech Spec re conditions for operation of traversing
in-core probe sys to allow operation for 31 effective
full power days w/one or more probes inoperable.
* Georgia Power Co. 83/12/21. 4pp. 21706 136 24X
Fiche: 50-366,83/12/21,8401040347.

1130340 Forwards response to NRC questions re radiological aspects
recirculation pipe replacement project raised during
206 telcon. Job description draft encl
MA, L T. Georgia Power Co. 83/12/27. BTOLZ, J F. Operating
Reactors Branch 4. 13pp 21798 285 24X Fiche: 50-366,83/12/27,
1130340.

8401100019 Notification of 840111 meeting w/util in Bethesda, MD to
discuss util request for extension for completion of
NUREG-0737, Item II B 3, "Post-Accident Sampling Sys"
RIVENBARK, G Operating Reactors Branch 4 84/01/04 STOLZ, J F
Operating Reactors Branch 4 2pp 21776 058 24X
Fiche 50-321,84/01/04,8401100019

8401190351 Informs that NRC accepted OE small break LDCA model for use
in satisfying TH1 Action Item II K 3 30 on 831213, using
model in facility LDCA analysis If info incorrect, requests
ack.
BTOLZ, J F Operating Reactors Branch 1 84/01/04 BECKHAM, J T
Georgia Power Co 2pp 21861 191 24X Fiche 50-321,84/01/04,
8401190351

8401260083 Forwards Amends 97 & 34 to Licenses DPR-57 & NPF-5,
respectively & safety evaluation Amends revise Tech Specs to
add limiting condition for operation & surveillance
requirements for scram discharge vol vent & drain valves
BTOLZ, J F Operating Reactors Branch 4 84/01/04 BECKHAM, J T
Georgia Power Co 2pp 21990 158 24X Fiche 50-321,84/01/04,
8401260083

--8401260086 Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively,
revising Tech Specs to add limiting condition for operation
& surveillance requirements for scram discharge vol vent
& drain valves
STOLZ, J F Operating Reactors Branch 4 84/01/04 25pp.
21990 162 24X Fiche 50-321,84/01/04,8401260083

--8401260091 Safety evaluation supporting Amends 97 & 34 to Licenses
DPR-57 & NPF-5
* Office of Nuclear Reactor Regulation, Director 84/01/04.
117pp 21990 187. 24X Fiche 50-321,84/01/04,8401260083

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing. 84/01/05 Consolidated
Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche: 50-000,84/01/05,8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,8401090221

840130179 Confirms 840105 telcons w/NRC re recent developments
concerning plans to replace recirculation sys piping
Scheduled shutdown delayed for wk or later date in Jan, due
to delay in fabrication of piping
QUICHA, L T. Georgia Power Co 84/01/06 BTOLZ, J F. Operating
Reactors Branch 4 2pp 21801 361 24X Fiche 50-366,84/01/06,
840130179

8401130357 Notifies of equipment qualification problems which could
result in request for extension of 10CFR50.49 rulemaking
deadline
QUICHA, L T Georgia Power Co 84/01/06 BTOLZ, J F. Operating
Reactors Branch 4 2pp 21800 316 24X Fiche 50-366,84/01/06,
8401130357.

8401200136 Approves licensee 831005 request to extend implementation
date for scram discharge vol mods from 831231 to prior to
restart following Jan 1984 shutdown to replace recirculation
sys piping.
EISENHUT, D G Division of Licensing 84/01/06 BECKHAM, J T
Georgia Power Co 2pp. 21872 137 24X Fiche 50-366,84/01/06,
8401200136

8401170172 Submits info on diesel generator quick starts & opinion of
effect on reliability Record of diesel cold starts for
1983 summarized, in response to NRC 831216 request
QUICHA, L T. Georgia Power Co 84/01/09 BTOLZ, J F. Operating
Reactors Branch 4 3pp 21834 136 24X Fiche 50-321,84/01/09,
8401170172

8401130084 Generic Ltr 84-03 to all licensees of operating reactors;
applicants for OLs & holders of CPs re availability of
NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl.
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche: 50-000,84/01/13,8401130084

8401310047 Forwards safety evaluations confirming satisfactory
resolution of Generic Item B-24 issues & NUREG-0737, Item
II, E 4 2 re containment vent & purging & valve operability.
Tech Specs proposed in 1983 ltrs to be handled separately.
BTOLZ, J F Operating Reactors Branch 4 84/01/16 BECKHAM, J T
Georgia Power Co. 3pp 22032 342 24X Fiche: 50-321,84/01/16,
8401310047

DOCKETED ITEMS

249

--B401310052 Safety evaluation concluding util demonstrated operability of containment purge & vent valves Valves will close against buildup of containment pressure in event of DBA/LOCA when valves limited to opening angles of 90 degrees or less
* NRC - No Detailed Affiliation Given 84/01/16 5pp
22032 345 24X Fiche 50-321,84/01/16,8401310047

--B401310056 Safety evaluation suppl on containment/purge vent sys Acceptable approach provided to modify standby gas treatment sys to withstand pressure increase resulting from LOCA
* NRC - No Detailed Affiliation Given 84/01/16 3pp
22032 350 24X Fiche 50-321,84/01/16,8401310047

--B401310063 Safety evaluation accepting util evaluation of radiological consequences of LOCA during purging
* NRC - No Detailed Affiliation Given 84/01/16 2pp
22032 353 24X Fiche 50-321,84/01/16,8401310047

B401300030 Forwards "App B, Comparison of Special Lifting Device Design to ANSI N14 6-1978," per B30729 response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants"
BECKHAM, J T Georgia Power Co 84/01/23 STOLZ, J F Operating Reactors Branch 4 15pp 21799 248 24X Fiche 50-321,84/01/23, 8401300030

B401310309 Application to amend License NPF-5, supporting mods associated w/installation of GE analog transmitter trip sys Encl proprietary Rev 1 to NEDE-22154-1, "Analog Trip Sys for Engineered Safeguards Sensor Trip Inputs" withheld
BECKHAM, J T Georgia Power Co 84/01/23 STOLZ, J F Operating Reactors Branch 4 3pp 22021 001 24X Fiche 50-321,84/01/23, 8401310309

--B401310314 "Proposed Plant Mods To Be Incorporated Into Analog Transmitter Trip Scram Design" GE affidavit for withholding NEDE 22154-1, "Analog Trip Sys for Engineered Safeguard Sensor Trip Inputs," encl
* Georgia Power Co 83/08/19 109pp 22021 004 24X Fiche 50-321,84/01/23,8401310309

B401310123 Forwards description of current criteria for meeting NUREG-0737, Item II B 3, "Post-Accident Sampling Capability" Schedule for completing remaining tasks encl Extension until 840601 requested to complete item
GUCWA, L T Georgia Power Co 84/01/26 STOLZ, J F Operating Reactors Branch 4 21pp 22022 040 24X Fiche 50-321,84/01/26, 8401310123

B Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge lp 21744 003 24X Fiche: 50-000, 83/10/20, 8401060040

--B401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040.

B312050488 Responds to concern raised by NRC during site insps on 820302-05 & 14-19 (ref IE Insp Repts 50-321/82-08 & 50-366/82-08) re IE Bulletin 80-08 Problems nonexistent re radiography of fluid head penetrations
GUCWA, L T Georgia Power Co 83/11/18 O'REILLY, J P Region 2, Office of Director 2pp 21381 076 24X Fiche 50-321,83/11/18, 8312050488

B312070443 Responds to 830812 allegation that NRC lacked legal jurisdiction to issue B30713 notice of violation Notice of violation valid since util improperly disposed of licensed mail by transfer to unauthorized recipient
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/11/25 KELLY, R J Georgia Power Co 3pp 21418 330 24X Fiche 50-321,83/11/25,8312070443

B401050621 Forwards IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18. No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/09 KELLY, R J Georgia Power Co 2pp 21726 062 24X Fiche: 50-321,83/12/09,8401050621

--B401050633 IE Insp Repts 50-321/83-31 & 50-366/83-33 on 831114-18 No violations noted Major areas inspected: plant tours, plant operations review, Tech Spec compliance, physical protection, refueling activity & spent fuel pool activity
MATHIEB, J L, KRUG, H Region 2, Office of Director, JAPE, F. Division of Engineering & Operational Programs 83/12/06 5pp 21726 064 24X Fiche: 50-321,83/12/09,8401050631.

B401090195 Forwards IE Insp Repts 50-321/83-33 & 50-366/83-35 on 831129-1201 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/16 KELLY, R J Georgia Power Co 2pp 21749 216 24X Fiche: 50-321,83/12/16,8401090195

--B401090201 IE Insp Repts 50-321/83-33 & 50-366/83-35 on 831129-1201 No violations noted Major areas inspected nuclear welding, recirculation sys piping replacement & previous insp findings
CROWLEY, B R Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/12/14 8pp 21749 218 24X Fiche 50-321,83/12/16,8401090195

B40110546 Discusses IE Insp Rept 50-366/83-23 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P Region 2, Office of Director 83/12/27 KELLY, R J Georgia Power Co 3pp 21795 340 24X Fiche 50-366,83/12/27, 840110546

--B40110552 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted procedures for control rod manipulations improperly implemented & rod worth minimizer not verified by second person
O'REILLY, J P Region 2, Office of Director 83/12/27 3pp 21795 343 24X Fiche 50-366,83/12/27,840110546

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche: 50-000,83/12/28,8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp. 21826 060 24X Fiche 50-000,83/12/30,8312120093

B401060446 Discusses Jan & Feb 1983 revs to radiological emergency plan, Revs meet applicable planning stds of 10CFR50 Outstanding issues identified in IE Insp Repts 50-321/83-19 & 50-366/83-19
DANCE, H C Division of Project & Resident Programs 83/12/30, KELLY, R J Georgia Power Co 2pp 21740 089 24X Fiche: 50-321,83/12/30,8401060446

B401250165 Forwards corrected page to NRC ltr transmitting notice of violation & proposed imposition of civil penalty arising from IE Insp Rept 50-366/83-23 Original ltr contained extraneous sentence
O'REILLY, J P Region 2, Office of Director 84/01/06 KELLY, R J Georgia Power Co 4pp 21959 026 24X Fiche 50-366,84/01/06, 8401250165

B401190411 Informs that inservice insp plan for Unit 1 will be provided to site personnel tentatively by mid-Feb 1984. Inservice insp plans for 1984 Unit 2 main recirculation sys piping replacement outage finalized
GUCWA, L T Georgia Power Co 84/01/09 STOLZ, J F. Operating Reactors Branch 4 2pp 21850 093 24X Fiche: 50-321,84/01/09, 8401190411

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 093 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp. 21826 184 24X Fiche: 50-000,84/01/10,8312120107.

B401240579 Ack receipt of 840104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/83-30
LEWIS, R C Division of Project & Resident Programs 84/01/13, KELLY, R J Georgia Power Co lp 21909 149 24X Fiche: 50-321,84/01/13,8401240579

--B401240588 Forwards IE Insp Repts 50-321/83-30 & 50-366/83-32 on 831001-31 & notice of violation.
LEWIS, R C Division of Project & Resident Programs 83/12/08 KELLY, R J Georgia Power Co 2pp 21909 153 24X Fiche 50-321,84/01/13,8401240579.

DOCKETED ITEMS

--B401240597 IE Insp Repts 50-321/83-30 & 50-366/83-32 on B31001-31
Noncompliance noted failure to establish required fire
watches
CRLENJAK, R V, HOLMES-RAY, P Region 2, Office of Director
PANCIERA, V W Division of Project & Resident Programs B3/12/07
6pp 21909 136 24X Fiche 50-321,84/01/13, B401240597

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) B4/01/16 Consolidated Edison Co. of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) B4/01/18 Consolidated Edison Co. of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) B4/01/18 Consolidated Edison Co. of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18, B312120117

R Periodic operating reports & related correspondence

B401130330 Monthly operating repts for Dec 1983 W/B40110 1tr
RAFFEDIE, D P, NIX, H C Georgia Power Co B3/12/31 Director's
Office, Office of Inspection and Enforcement. 17pp 21801 171 24X
Fiche 50-321,83/12/31, B401130330

S Reportable occurrences, LERs & related correspondence

B401050399 PNO-II-84-001 on B40103, bomb threats received at facility
Searches revealed no bomb FBI, media & info assessment
team notified
MCQUIRE, D R, TOBIN, W J Region 2, Office of Director B4/01/03
1p 21731 124 24X Fiche 50-321,84/01/03, B401050399

B401030116 LER 83-131/03L-0 on B31119, false low pressure alarm received
in main control room for control rod scram accumulator
hydraulic unit 2C11-18-27 Caused by setpoint drift Pressure
switch recalibr W/B31216 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/16 O'REILLY, J P
Region 2, Office of Director App 21683 158 24X
Fiche 50-366,83/12/16, B401030116

B401030242 LER 83-138/03L-0 on B31206, diesel generator 2C(2R43-8001C)
could not be shut down w/local or control room stop switch
Caused by loose governor shutdown solenoid due to engine
vibration Solenoid repositioned W/B31216 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/16 O'REILLY, J P
Region 2, Office of Director App 21682 285 24X
Fiche 50-366,83/12/16, B401030242

B401040230 LER 83-141/03L-0 on B31208, during MSIV closure instrument
functional test, valve 2C71-K3D failed to deenergize Caused
by corroded limit switch Switch cleaned W/B31222 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/22 O'REILLY, J P
Region 2, Office of Director App 21701:164 24X
Fiche 50-366,83/12/22, B401040230

B401040344 LER 83-142/03L-0 on B31208, during performance of MSIV
leakage control sys operability procedure, MSIV B leakage
control sys isolation valve failed to complete full
operating cycle. Caused by short in motor W/B31222 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/22 O'REILLY, J P
Region 2, Office of Director App 21706:324 24X
Fiche 50-366,83/12/22, B401040344

B401050638 Informs of mod to previous commitment re operation of
facility beyond CY83 w/o completing corrective action on
pipe whip issue described in LER 50-366/283-46 Facility will
continue to operate into Jan 1984
GUCHALL, T Georgia Power Co B3/12/22 O'REILLY, J P Region 2,
Office of Director 2pp 21725 191 24X Fiche 50-366,83/12/22,
B401050638

101170345 RD 50-366/83-46 on B30623, certain pipe whip restraints
reported not installed Commitment made at B30928 meeting
not to operate beyond end of CY83 w/o completion of
corrective action extended into Jan 1984
GUCHALL, T Georgia Power Co B3/12/22, O'REILLY, J P Region 2,
Office of Director 2pp 21831 141, 24X Fiche 50-366,83/12/22,
1401170345

B401060371 LER 83-134/03L-0 on B31127 & 1204, drywell hydrogen &
oxygen analyzer B noted inoperable Cause of first event
unknown Second event due to failure of sys sample pump &
leaking pipe fittings Pump & leaks repaired W/B31227 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/27 O'REILLY, J P
Region 2, Office of Director App 21741 158 24X
Fiche 50-366,83/12/27, B401060371

B401060415 Updated LER 78-026/03X-1 on 780825, mechanical penetrations
in oil room floor & in wall of 600-volt switchgear room 2D
found w/o fire penetration seals Caused by personnel
determining seals unnecessary Seals installed W/B31227 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/27 O'REILLY, J P
Region 2, Office of Director App 21741 033 24X
Fiche 50-366,83/12/27, B401060415

B401060461 LER 83-132/03L-0 on B31211, during Procedure HNP-7408, primary
containment noble gas monitor 2D11-K633 noted inoperable,
contrary to Tech Spec 3 4 3 1 Caused by component failure
due to setpoint drift Monitor recalibr W/B31230 1tr
TIPPS, S B, NIX, H C Georgia Power Co B3/12/30 O'REILLY, J P
Region 2, Office of Director App 21740 205 24X
Fiche 50-366,83/12/30, B401060461

B401230263 LER 83-148/03L-0 on B31208, personnel determined that
continuous fire watch not implemented within 1 h when Fire
Door 2L48-2R53 determined inoperable. Caused by personnel
error & component failure. Fire door adjusted W/B40107 1tr
TIPPS, S B, NIX, H C Georgia Power Co B4/01/07 O'REILLY, J P
Region 2, Office of Director App 21884 203 24X
Fiche 50-366,84/01/07, B401230263

B401230012 LER 83-135/03L-0 on B31212, during high reactor pressure
instrumentation FT&C Procedure HNP-R-3001, reactor vessel C
steam high dome pressure switch 2B21-NO23C out of calibr
Caused by setpoint drift Switch recalibr W/B40111 1tr
TIPPS, S B, NIX, H C Georgia Power Co B4/01/11, O'REILLY, J P
Region 2, Office of Director App 21884 296 24X
Fiche 50-366,84/01/11, B401230012

B401230201 LER 83-136/03L-0 on B31213, standby gas treatment fan 2B
tripped & would not restart. Caused by component failure
Fan motor starter replaced W/B40112 1tr
TIPPS, S B, NIX, H C Georgia Power Co B4/01/12, O'REILLY, J P
Region 2, Office of Director App 21877 355 24X
Fiche 50-366,84/01/12, B401230201

B401230362 LER 83-129/03L-0 on B31213, during QA audit, diesel generator
testing not scheduled on staggered test basis. Caused by
personnel error Diesel generators surveillance scheduled
per staggered requirement W/B40112 1tr.
TIPPS, S B, NIX, H C Georgia Power Co. B4/01/12, O'REILLY, J P
Region 2, Office of Director App. 21884:269 24X
Fiche 50-366,84/01/12, B401230362

B401300262 LER 83-137/03L-0 on B31221 & 22, personnel determined safety
relief valve tailpipe temp recorder 2B21-R614 inoperable.
Caused by failed chart drive motor & failed chart drive
idler gear Replacement parts installed W/B40113 1tr.
TIPPS, S B, NIX, H C Georgia Power Co B4/01/13 O'REILLY, J P
Region 2, Office of Director App. 21998 336 24X
Fiche 50-366,84/01/13, B401300262

B401300312 LER 83-139/03L-0 on B31214, position of vacuum breaker
2T48-F323C could not be confirmed due to blown position
indicator light fuse 2T48-F1 Caused by shorted valve
position switch. Switch & fuse replaced. W/B40113 1tr
TIPPS, S B, NIX, H C Georgia Power Co. B4/01/13, O'REILLY, J P.
Region 2, Office of Director App. 21996:326 24X
Fiche 50-366,84/01/13, B401300312

B401300327 LER 83-144/03L-0 on B31219, plant personnel determined
primary containment hydrogen recombiner 2T49-B002A would not
heat up Caused by sticking heater control relay contacts.
Sticking relay contacts freed. W/B40113 1tr.
TIPPS, S B, NIX, H C Georgia Power Co. B4/01/13, O'REILLY, J P.
Region 2, Office of Director App. 21996:296 24X
Fiche 50-366,84/01/13, B401300327.

B401310398 LER 83-143/03L-0 on B31225, plant svc water valve 2F41-F316C
isolated, stopping flow to turbine bldg. Caused by ice in
differential pressure cell of differential pressure switch.
Ice thawed & circuit breaker turned on W/B40124 1tr
TIPPS, S B, NIX, H C Georgia Power Co B4/01/24 O'REILLY, J P.
Region 2, Office of Director App 22018:347 24X
Fiche 50-366,84/01/24, B401310398

B401310400 LER 83-140/03L-0 on B31225, low nitrogen pressure alarm
received on control rod scram accumulators 2C11-18-43 &
2C11-26-43. Cause unknown Accumulators serviced w/nitrogen
& returned to svc. W/B40124 1tr
TIPPS, S B, NIX, H C Georgia Power Co. B4/01/24, O'REILLY, J P.
Region 2, Office of Director App 22018, 343. 24X
Fiche 50-366,84/01/24, B401310400

DOCKETED ITEMS

251

V Operator Examinations

B401060499 Forwards "Power Plant Exam Results Summary Sheet," delineating results of exams administered during wks of 830926 & 1010 Failure rates higher than industry norms W/o encl
DANCE, H C Division of Project & Resident Programs 83/12/08
KELLY, R J Georgia Power Co ip 21739 345 24X
Fiche: 50-321, 83/12/08, B401060499

B401240242 Confirms B40103 telcon arrangements for B40111 meeting to discuss significant failure rates on recent reactor operator & instructor certification exams
O'REILLY, J P Region 2, Office of Director 84/01/11 KELLY, R J
Georgia Power Co ip 21920 242 24X Fiche 50-321, B4/01/11,
B401240242

DOCKET 50-367 BAILLY GENERATING STATION

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge ip 21744 003 24X
Fiche: 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp, 21744 004 24X Fiche 50-000, 83/10/20,
B401060040

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

B401270066 Forwards IE Safeguards Insp Repts 50-313/83-23 & 50-368/83-23 on 830822-26 & notice of violation IE insp repts withheld (ref 10CFR73.21)
AGLIARDI, J E Region 4, Office of Director 83/12/20
GRIFFIN, J M Arkansas Power & Light Co 2pp 21982 001 24X
Fiche: 50-313, 83/12/20, B401270066

--B401270072 Notice of violation from insp on 830822-26 Violation noted: two of four explosive detectors did not meet 95% accuracy criterion & switch over to secondary emergency security power supply did not operate.
* Region 4, Office of Director 83/12/20 2pp 21982 003 24X
Fiche: 50-313, 83/12/20, B401270066.

B401060181 Releases public version of revised emergency plan.
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch ip 21744 185 24X Fiche 50-313, 83/12/28,
B401060181.

--B401060186 Public version of Rev 9 to emergency plan W/831212 ltr & revised table of contents
MARSHALL, J R Arkansas Power & Light Co 83/11/30 COLLINS, J T
Region 4, Office of Director 91pp, 21744 186 24X
Fiche: 50-313, 83/12/28, B401060181

B401170377 Clarifies NRC approval of util exemption request for emergency planning exercises at facility Reduction of exercises will result in higher quality performance & improvement in exercises which are held
MARSHALL, J R Arkansas Power & Light Co, 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 21828 339
24X Fiche 50-313, 83/12/30, B401170377.

B401170259 Ack receipt of 831215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25.
AGLIARDI, J E, Division of Resident, Reactor Project & Engineering Programs, 84/01/10 GRIFFIN, J M Arkansas Power & Light Co ip 21830 353 24X Fiche: 50-313, 84/01/10, B401170259

--B401170264 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 Corrective actions memo issued providing clarification of documentation requirements & fire watch training program revised
MARSHALL, J R Arkansas Power & Light Co 83/12/15
AGLIARDI, J E, Division of Resident, Reactor Project & Engineering Programs 5pp, 21830, 354 24X Fiche: 50-313, 84/01/10, B401170259

B401170331 Forwards amended Attachments 10 9 & 55 & of IAEA design info questionnaire returned by 830822, reflecting minor mod to procedure for receipt & storage of fresh fuel Replacement of affected pages requested
MARSHALL, J R Arkansas Power & Light Co 84/01/12 EISENHUT, D O
Division of Licensing 4pp 21829 346 24X Fiche 50-368, B4/01/12,
B401170331

B401240182 Forwards documentation supporting 831230 request for exemption from requirement for full-scale emergency planning exercise in 1984, per Region IV emergency planning staff request
MARSHALL, J R Arkansas Power & Light Co 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 21908 303
24X Fiche 50-313, 84/01/18, B401240182

B401250057 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch ip 21947 151 24X Fiche: 50-313, 84/01/18,
B401250057

--B401250060 Public version of Rev 0 to Emergency Plan Implementing Procedure 1903 34, "Administration of Potassium Iodide," W/831122 transmittal & receipt form
LEVINE, J M Arkansas Power & Light Co 83/11/22 14pp
21947 152 24X Fiche 50-313, 84/01/18, B401250057.

B401250081 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch ip 21946 311 24X Fiche 50-313, 84/01/18,
B401250081

--B401250085 Public version of Rev 8 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equipment" & Rev 4 to Procedure 1903 61, "Communications Equipment Tests" W/831110 transmittal & receipt form
LEVINE, J M, BAKER, D Arkansas Power & Light Co 83/11/09 5pp
21946 312 24X Fiche 50-313, 84/01/18, B401250081

B401260024 Releases public version of amended nuclear contingency plan & revised nuclear contingency plan procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch ip 21990 301 24X Fiche 50-313, 84/01/18,
B401260024

--B401260027 Forwards public version of Amend 3 to nuclear contingency plan & revised nuclear contingency plan procedures, including Procedures 2 re notifications & 7 re response guides/checklists
MARSHALL, J R, Arkansas Power & Light Co 83/12/12 EISENHUT, D O
Office of Nuclear Reactor Regulation, Director ip 21990 302
24X Fiche 50-313, 84/01/18, B401260024

--B401260029 Public version of Amend 3 to nuclear contingency plan * Arkansas Power & Light Co 83/11/30 5pp 21990 303 24X
Fiche 50-313, 84/01/18, B401260024

--B401260032 Public version of revised nuclear contingency plan procedures, including Procedures 1 re assignment of personnel to emergency response organization, 2 re notifications & 7 re response guides/checklists
GIFF, J M Arkansas Power & Light Co 83/12/04, 29pp 21990 308,
24X Fiche 50-313, 84/01/18, B401260024

B401260245 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch ip 21971 361 24X Fiche: 50-313, 84/01/18,
B401260245

--B401260251 Public version of Rev 6 to Emergency Plan Implementing Procedure 1903 22, "Fire or Explosion" W/831229 receipt form
LEVINE, J M Arkansas Power & Light Co 83/12/29 NRC - No
Detailed Affiliation Given, 3pp 21987 359 24X
Fiche 50-313, 84/01/18, B401260245

B401260301 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20, Document
Management Branch ip 21990 356 24X Fiche: 50-313, 84/01/20,
B401260301

--B401260305 Public version of Rev 5 to Emergency Plan Implementing Procedure 1903 31, "Exclusion Area Evacuation" W/831228 receipt form.
LEVINE, J M Arkansas Power & Light Co, 83/12/22 NRC - No
Detailed Affiliation Given 7pp, 21990 357, 24X
Fiche 50-313, 84/01/20, B401260301

DOCKETED ITEMS

8401260312 Releases public version of revised nuclear contingency plan & procedures
FELTON, J M Division of Rules and Records. 84/01/20 Document
Management Branch. 1p 21990 341 24X Fiche 50-313, 84/01/20,
8401260312

--8401260316 Forwards public version of Amend 3 to nuclear contingency plan, Rev 3 to Nuclear Contingency Plan Procedures 1, 2, 3 & 7 & Rev 2 to Procedure 9 W/o encl
MARSHALL, J R Arkansas Power & Light Co 83/12/12 COLLINS, J T
Region 4, Office of Director 1p 21990 342 24X
Fiche 50-313, 84/01/20, 8401260312

8401310458 Releases public versions of revs to util nuclear contingency plan & implementing Procedures 1, 2, 3, 7 & 9
FELTON, J M Division of Rules and Records. 84/01/20 Document
Management Branch. 1p 22036 306 24X Fiche 50-313, 84/01/20,
8401310458

--8401310460 Forwards revs to nuclear contingency plan & implementing Procedures 1, 2, 3, 7 & 9, W/o encl
MARSHALL, J R Arkansas Power & Light Co 83/12/15 COLLINS, J T
Region 4, Office of Director 1p 22036 307 24X
Fiche 50-313, 84/01/20, 8401310458

8401300167 Comments on 830921 draft "Safeguards Agreement Under NPT Between USA & IAEA Subsidiary Arrangements," intended to be implemented through facility license amend Markup copy of agreement encl
GRIFFIN, J M Arkansas Power & Light Co 84/01/23 MILLER, J R
Operating Reactors Branch 3 25pp. 21976 242. 24X
Fiche 50-368, 84/01/23, 8401300167

8401300361 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records. 84/01/26 Document
Management Branch. 1p 22006:001 24X Fiche 50-313, 84/01/26,
8401300361

--8401300364 Public version of revised emergency plan implementing procedures, including Procedure 1903 32 re area evacuation & 1903 44 re duties of emergency recovery team W/840112 transmittal & receipt form
LEVINE, J M Arkansas Power & Light Co 84/01/11 NRC - No
Detailed Affiliation Given. 24pp. 22006:002 24X
Fiche 50-313, 84/01/26, 8401300361

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licenseses charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds
REYNOLDS, N S South Carolina Electric & Gas Co REYNOLDS, N S
Texas Utilities Generating Co 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp. 21919 361. 24X Fiche 50-000, 84/01/19,
8401240335.

Operating license stage documents & correspondence

8401040270 Forwards CEN-261(A), "Arkansas Nuclear One, Unit 2, Cycle 4 Shoulder Gap Evaluation," in order to complete response to concerns expressed in NRC 830608 ltr
MARSHALL, J R Arkansas Power & Light Co 83/12/16 OGLIARDO, J E
Division of Resident, Reactor Project & Engineering Programs. 1p
21701:327. 24X Fiche 50-368, 83/12/16, 8401040270

--8401040275 "Arkansas Nuclear One, Unit 2, Cycle 4 Shoulder Gap Evaluation."
* Combustion Engineering, Inc. CEN-261(A). 83/11/30. 7pp.
21701.328. 24X Fiche: 50-368, 83/12/16, 8401040270

8401040541 Informs that core damage estimate procedure will be developed as result of review to satisfy NUREG-0737, Item II, B. 3 re post-accident sampling sys & address concerns raised in 830714 & 1031 ltrs. Schedule expected by 840131.
MARSHALL, J R Arkansas Power & Light Co 83/12/27. STOLZ, J F
Operating Reactors Branch 4. MILLER, J R. Operating Reactors Branch 3. 1p 21706:323 24X Fiche 50-313, 83/12/27, 8401040541.

8401050577 Forwards proprietary & nonproprietary, "Digital Simulation of C-E NSSS," Proprietary rept withheld (ref 10CFR2 790).
MARSHALL, J R Arkansas Power & Light Co 83/12/27 MILLER, J R
Operating Reactors Branch 3 3pp. 21724:290 24X
Fiche: 50-368, 83/12/27, 8401050577

--8401050584 Nonproprietary "Digital Simulation of C-E NSSS."
* Combustion Engineering, Inc. 82/01/05. 256pp. 21724.295. 24X
Fiche: 50-368, 83/12/27, 8401050577.

8401170190 Discusses 830927 Tech Spec change request re remote shutdown instrumentation. Requested change would delete instrument ranges specified in Table 3 3-9 Deleted info will be included in Chapter 7 of updated FEAR
GRIFFIN, J M Arkansas Power & Light Co 83/12/30 MILLER, J R
Operating Reactors Branch 3 2pp 21833 299 24X
Fiche 50-368, 83/12/30, 8401170190

8401180062 Informs that remote shutdown instrumentation range info requested for deletion from Tech Spec Table 3 3-9 will be included in Chapter 7 of 1984 rev to SAR
GRIFFIN, J M Arkansas Power & Light Co 83/12/30 MILLER, J R
Operating Reactors Branch 3 2pp 21841 361 24X
Fiche 50-368, 83/12/30, 8401180062

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401120424 Forwards responses to 831118 telcon re proposed rev to Tech Spec 3 3 3 2 to require at least one tilt estimate at each central three axial levels
GRIFFIN, J M Arkansas Power & Light Co 84/01/06 MILLER, J R
Operating Reactors Branch 3 10pp 21791 027 24X
Fiche 50-368, 84/01/06, 8401120424

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, 8401130084

8401230402 Provides results of analyses of isotopic activity used by Radiological & Environ Sciences Lab in preparation of unknown liquid sample. Official documentation of analyses will appear in next confirmatory measurements insp rept.
OGLIARDO, J E Region 4, Office of Director 84/01/16
GRIFFIN, J M Arkansas Power & Light Co 2pp 21879:153 24X
Fiche: 50-313, 84/01/16, 8401230402

8401310312 Submits addl info re proposed sealed source leak testing Tech Specs, in response to NRC 831108 request
MARSHALL, J R Arkansas Power & Light Co 84/01/20 STOLZ, J F
Operating Reactors Branch 4 MILLER, J R. Operating Reactors Branch 3 8pp 22026 300 24X Fiche 50-313, 84/01/20, 8401310312

8401270420 Advises that RP Denise will become new Director, Div of Resident, Reactor Project Engineering Programs, effective 840122.
COLLINS, J T. Region 4, Office of Director 84/01/23 GRIFFIN, J M
Arkansas Power & Light Co. 1p 21981 154. 24X
Fiche 50-313, 84/01/23, 8401270420

8401300186 Advises that response to Generic Ltr 83-37 re Tech Spec changes for 11 NUREG-0737 items will not be completed until 840319, due to lengthy Unit 2 outage
MARSHALL, J R Arkansas Power & Light Co. 84/01/23. STOLZ, J F.
Operating Reactors Branch 4 MILLER, J R. Operating Reactors Branch 3 1p. 21957:345 24X Fiche 50-313, 84/01/23, 8401300186

8401310237 Advises that core damage estimate methodology will be completed by 850131, per NUREG-0737, Item II B 3 "Post-Accident Sampling Sys" Estimate used for informational purposes only
MARSHALL, J R. Arkansas Power & Light Co 84/01/24. STOLZ, J F
Operating Reactors Branch 4. MILLER, J R. Operating Reactors Branch 3 1p. 22021 159 24X Fiche 50-313, 84/01/24, 8401310237

G Inspection reports, IE Bulletins & correspondence

840130332 Ack receipt of 830722 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-313/83-10 & 50-368/83-10
SEIDLE, W C Region 4, Office of Director. 83/08/02. GRIFFIN, J M
Arkansas Power & Light Co. 1p 21801.188 24X
Fiche: 50-313, 83/08/02, 840130332.

DOCKETED ITEMS

25

--B401130339 Responds to NRC B30615 ltr re violations noted in IE Insp Repts 50-313/B3-10 & 50-368/B3-10 Corrective actions Procedure 1622 017, "Operation of Control Point," will be issued on 830930
MARSHALL, J R Arkansas Power & Light Co 83/07/22 SEIDLE, W C
Region 4, Office of Director 5pp 21801 189 24X
Fiche 50-313, B3/08/02, B401130332

B401270505 Responds to violations noted in IE Insp Repts 50-313/B3-20 & 50-368/B3-20 Corrective actions personnel collecting milk samples will notify analytical lab staff when samples obtained from local dairies
MARSHALL, J R Arkansas Power & Light Co 83/10/09 SEIDLE, W C
Region 4, Office of Director 3pp 21981 348 24X
Fiche 50-313, B3/10/09, B401270505

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 105pp 21744.004 24X Fiche 50-000, B3/10/20,
B401060040

B401040444 Ack receipt of B30920 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/B3-17 & 50-368/B3-17 Addl info requested within 30 days
GAOLIARD, J E Region 4, Office of Director 83/10/27
GRIFFIN, J M Arkansas Power & Light Co 1p 21708 087 24X
Fiche 50-313, B3/10/27, B401040444

--B401040452 Responds to NRC B30819 ltr re violations noted in IE Insp Repts 50-313/B3-17 & 50-368/B3-17 Corrective actions Energy Supply Procedure (ESP) 202 reviewed & revised to comply w/ AP&L-TOP-1A, effective 830701
MARSHALL, J R Arkansas Power & Light Co 83/09/20 SEIDLE, W C
Region 4, Office of Director 4pp 21708 088 24X
Fiche: 50-313, B3/10/27, B401040444

B401040107 Forwards BALP Repts 50-313/B3-22 & 50-368/B3-22 for Jul 1982 - June 1983
COLLINS, J T Region 4, Office of Director 83/11/28 GRIFFIN, J M
Arkansas Power & Light Co 4pp 21701 221 24X
Fiche 50-313, B3/11/28, B401040107

--B401040111 BALP Repts 50-313/B3-22 & 50-368/B3-22 for Jul 1982 - June 1983
JOHNSON, W D, SEIDLE, W C Region 4, Office of Director 83/09/15
48pp 21701 227 24X Fiche 50-313, B3/11/28, B401040107

--B308090279 Evaluates LERs for BALP input for Jul 1982 - June 1983 Some LERs should have been updated to identify final corrective action when corrective actions different from actions postulated in original LER
SEYFRIT, K V Reactor Operations Analysis Branch 83/07/28
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 5pp 21701 278 24X Fiche 50-313, B3/11/28, B401040107

--B401040212 Responds to NRC B30929 ltr re findings of BALP Repts 50-313/B3-22 & 50-368/B3-22 Unqualified spare part replaced.
MARSHALL, J R Arkansas Power & Light Co 83/11/03,
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 5pp 21701 283 24X Fiche 50-313, B3/11/28, B401040107

B401170350 Forwards Rockbestos Co QA program insp rept, identifying one violation & 11 noncompliances for info & action Ack of rept receipt requested. W/o encl
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 83/11/29 GRIFFIN, J M Arkansas Power & Light Co, 2pp 21829 344 24X Fiche 50-313, B3/11/29, B401170350

B401270046 Forwards IE Safeguards Insp Repts 50-313/B3-23 & 50-368/B3-23 on B30922-26 & notice of violation IE insp repts withheld (ref 10CFR73 21)
GAOLIARD, J E Region 4, Office of Director, 83/12/20
GRIFFIN, J M Arkansas Power & Light Co 2pp 21982 001 24X
Fiche 50-313, B3/12/20, B401270046

--B401270072 Notice of violation from insp on B30822-26 Violation noted: two of four explosive detectors did not meet 95% accuracy criterion & switch over to secondary emergency security power supply did not operate
* Region 4, Office of Director, 83/12/20 2pp 21982 003 24X
Fiche 50-313, B3/12/20, B401270046

B401230492 Requests extension of response date to B40207 to respond to B31209 notice of deviation
MARSHALL, J R Arkansas Power & Light Co 83/12/22 GAOIARD, J E
Division of Resident, Reactor Project & Engineering Programs 1p
21880 362 24X Fiche 50-313, B3/12/22, B401230492

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 033 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401170241 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/B3-17 & 50-368/B3-17
GAOLIARD, J E Region 4, Office of Director 84/01/10
GRIFFIN, J M Arkansas Power & Light Co 1p 21827 156 24X
Fiche 50-313, B4/01/10, B401170241

--B401170487 Responds to NRC B30819 & 1027 ltrs re violations noted in IE Insp Repts 50-313/B3-17 & 50-368/B3-17 Corrective actions Rev B to Energy Supply Procedure 202, "Design Process," now includes necessary documentation
MARSHALL, J R Arkansas Power & Light Co 83/12/16,
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 4pp 21827 157 24X Fiche 50-313, B4/01/10, B401170241

B401170259 Ack receipt of B31215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/B3-23 & 50-368/B3-23
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 84/01/10 GRIFFIN, J M Arkansas Power & Light Co, 1p 21830 353 24X Fiche 50-313, B4/01/10, B401170259

--B401170264 Responds to NRC B31024 ltr re violations noted in IE Insp Repts 50-313/B3-23 & 50-368/B3-23 Corrective actions memo issued providing clarification of documentation requirements & fire watch training program revised
MARSHALL, J R Arkansas Power & Light Co 83/12/15,
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 5pp 21830 354 24X Fiche 50-313, B4/01/10, B401170259

B401170351 Forwards amended Attachments 10 9 & 55.6 of IAEA design info questionnaire returned by B30822, reflecting minor mod to procedure for receipt & storage of fresh fuel Replacement of affected pages requested
MARSHALL, J R Arkansas Power & Light Co 84/01/12 EISENHUT, D Q
Division of Licensing 4pp 21829 346 24X Fiche 50-368, B4/01/12, B401170351.

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103), 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103), 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B401270097 Grants B31222 request to extend response date to B31209 notice of deviation until B40207
GAOLIARD, J E Division of Resident, Reactor Project & Engineering Programs 84/01/20 GRIFFIN, J M Arkansas Power & Light Co, 1p, 21973 361 24X Fiche 50-313, B4/01/20, B401270097.

DOCKETED ITEMS

B401270269 Forwards Rockbestos Co QA Program Insp Repts 99900277/83-02 & 99900277/83-04 for action. Significance of reported findings & act of rept receipt requested W/o encl
 QAOLIARDO, J E Region 4, Office of Director 84/01/20
 GRIFFIN, J M Arkansas Power & Light Co 2pp 21976 111 24X
 Fiche 50-313, 84/01/20, B401270269

B401270432 Forwards QA Program Insp Rept 99900400/83-01 identifying Vendor Program Branch concerns Evaluation of findings re quality & acceptability of product or svc requested W/o encl
 QAOLIARDO, J E Region 4, Office of Director 84/01/20
 GRIFFIN, J M Arkansas Power & Light Co 2pp 21981 217 24X
 Fiche 50-313, 84/01/20, B401270432

R Periodic operating reports & related correspondence

B401120418 Monthly operating rept for Nov 1983 W/831215 1tr
 BRAHLETT, L B, MARSHALL, J R Arkansas Power & Light Co 83/11/30.
 BASSETT, H S Division of Data Automation & Management Information
 7pp 21791 174 24X Fiche 50-368, 83/11/30, B401120418

B401270402 Monthly operating rept for Dec 1983 W/840113 1tr
 BRAHLETT, L B, MARSHALL, J R Arkansas Power & Light Co 83/12/31
 BASSETT, H S Office of Resource Management, Director 7pp
 21976 262 24X Fiche 50-368, 83/12/31, B401270402

S Reportable occurrences, LERs & related correspondence

B401030291 Revised LER 83-045/03X-4 on 830916-1123, fire protection deficiencies identified Cause & corrective actions listed W/831216 1tr.
 ROGERS, P., MARSHALL, J R Arkansas Power & Light Co 83/12/16
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs. 18pp 21680 119 24X Fiche 50-368, 83/12/16, B401030291

B401030120 Updated LER 83-045/03X-5 on 830916-1123, review revealed listed fire protection deficiencies Cause not stated.
 Complete fire protection sys walkdown insp in progress
 Roving fire insp program established W/831220 1tr
 ROGERS, P., MARSHALL, J R Arkansas Power & Light Co 83/12/20
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs. 19pp 21683 135 24X Fiche 50-368, 83/12/20, B401030120

1100368 LER 83-049/01T-0 on 831212, due to procedural & personnel errors identified in station battery surveillance
 requirements, review of addl surveillances conducted Addl test inadequacies discovered W/831226 1tr
 JOGBURN, T H, MARSHALL, J R Arkansas Power & Light Co 83/12/26
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 3pp 21764 017 24X Fiche 50-368, 83/12/26, B401100368

101100342 Revised LER 83-045/03X-4 on 830916, discovered listed fire protection deficiencies Causes & corrective actions listed
 Integrated program developed to provide assurance that fire sys maintained, as required W/831229 1tr
 ROGERS, P., MARSHALL, J R Arkansas Power & Light Co 83/12/29
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 20pp 21764 068 24X Fiche 50-368, 83/12/29, B401100342

101230473 Revised LER 83-045/03X-7 on 830916-1214, five barrier deficiencies identified, Causes & corrective actions listed in encl Interim controls placed on const activities to assure restoration of fire sys W/840106 1tr
 ROGERS, P., MARSHALL, J R Arkansas Power & Light Co 84/01/06
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs. 21pp. 21882 192 24X Fiche 50-368, 84/01/06, B401230473

101230234 Revised LER 82-031/01X-1: on 821010, while in Mode 6, insp of emergency feedwater pump turbine steam supply check valve 2MS-39B revealed broken & missing disc stud. Caused by vibration fatigue Valve replaced W/840109 1tr
 MADE, P. B., MARSHALL, J R. Arkansas Power & Light Co. 84/01/09
 QAOLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 2pp. 21883 360 24X Fiche 50-368, 84/01/09, B401230234

NET 50-369 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 1
 Security, medical, emergency & fire protection plans

70414 Forwards IE Safeguards Insp Repts 50-369/83-29 & 370/83-36 on 830725-29 & notice of violation, Description safeguards mgt sys corrective actions requested, Notice of action & rept details withheld (ref 10CFR73 21).
 REILLY, J P Region 2, Office of Director 83/11/28 TUCKER, H B Duke Power Co 3pp. 21828 310 24X Fiche 50-369, 83/11/28, 1170414

--B401170424 IE Safeguards Insp Rept 50-369/83-29 & 50-370/83-36 on 830725-29 Violation noted inadequate vital area barrier Details withheld (ref 10CFR73 21)
 TILLMAN, A Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/10/03 1p.
 21828 313 24X Fiche 50-369, 83/11/28, B401170414

B401050486 Forwards IE Insp Repts 50-369/83-43 & 50-370/83-50 on 831031-1102 No violations noted
 DANCE, H C Division of Project & Resident Programs 83/12/02
 TUCKER, H B Duke Power Co 2pp 21730 111 24X
 Fiche 50-369, 83/12/02, B401050486

--B401050492 IE Insp Repts 50-369/83-43 & 50-370/83-50 on 831031-1102 No violations noted Major areas inspected emergency preparedness exercise
 CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/12/01 10pp
 21730 113 24X Fiche 50-369, 83/12/02, B401050486

B401090311 Advises that portions of in-core thermocouple sys outside containment will not be upgraded by 831231, per license condition Request to amend condition to reflect date consistent w/NUREG-0737, Suppl 1 will be submitted by 840113
 TUCKER, H B Duke Power Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4. 1p 21754 201 24X Fiche 50-369, 83/12/30, B401090311

B401170484 Forwards exemption from requirements of 10CFR50, App E re annual emergency preparedness exercise, in response to 830309 & 1010 requests No exemption from 10CFR50 47 required
 EISENHUT, D O Division of Licensing 84/01/06 TUCKER, H B Duke Power Co 6pp 21844 271 24X Fiche 50-000, 84/01/06, B401170484

--B401170491 Exemption from requirements of App E to 10CFR50 re annual emergency preparedness exercise & provisions for training & exercising of licensee employees, including headquarters support personnel in radiation emergency matters
 EISENHUT, D O Division of Licensing 84/01/06 Duke Power Co 3pp 21844 277 24X Fiche 50-000, 84/01/06, B401170484

B401200186 Application for amend to License NPF-9, extending required implementation date for outside-containment portion of in-core thermocouple sys upgrade, per NUREG-0737, Item II F 2, "Inadequate Core Cooling Instruments," & Suppl 1 to NUREG
 TUCKER, H B Duke Power Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 3pp 21864 335 24X Fiche 50-369, 84/01/12, B401200186

B401170373 Ack receipt of 831221 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36
 O'REILLY, J P Region 2, Office of Director 84/01/13 TUCKER, H B Duke Power Co 1p 21828 279. 24X Fiche 50-369, 84/01/13, B401170373

--B401170381 Responds to NRC 831128 1tr re violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36 Corrective actions withheld (ref 10CFR73 21)
 TUCKER, H B Duke Power Co 83/12/21 O'REILLY, J P Region 2, Office of Director 1p 21828 280 24X Fiche 50-369, 84/01/13, B401170373

B401310018 Forwards Rev 18 to security plan Rev withheld (ref 10CFR73 21)
 TUCKER, H B Duke Power Co. 84/01/16 O'REILLY, J P Region 2, Office of Director. 1p 22023 342 24X Fiche 50-369, 84/01/16, B401310018

B401310071 Releases public version of rev to emergency plan
 FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch. 1p. 22032 294. 24X Fiche 50-369, 84/01/18, B401310071

--B401310075 Public version of Rev 12 to emergency plan W/831212 1tr
 MCINTOSH, H D., TUCKER, H B Duke Power Co 83/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 33pp 22032 295. 24X Fiche 50-369, 84/01/18, B401310071

H General correspondence

B401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Bvc lists should be revised accordingly.
 REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds. 84/01/19
 CLEMENTS, W L Docketing & Services Branch 2pp. 21719 361. 24X Fiche 50-000, 84/01/19, B401240335

DOCKETED ITEMS

255

I. Financial information

B401100385 Forwards addl info re 1983-85 financial forecast, per
IP Dinit: B3107 request Projected figures for yr ended
831231 unavailable
TUCKER, H B Duke Power Co 84/01/04 DENTON, H R Office of
Nuclear Reactor Regulation, Director 3pp 21763 137 24X
Fiche 50-000, 84/01/04, 8401100385

P. Operating license stage documents & correspondence

B312050590 Application for amend to Licenses NPF-9 & NPF-17, changing
surveillance requirements for diesel fuel oil in Tech Spec
4 B 1.1 2
TUCKER, H B Duke Power Co 83/11/18 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch
4 3pp 21379 327 24X Fiche 50-369, 83/11/18, 8312050590

--B312050595 Proposed Tech Spec changes re surveillance requirements for
emergency diesel fuel oil sys
+ Duke Power Co 83/09/23 23pp 21379 330 24X
Fiche 50-369, 83/11/18, 8312050590

--B312050598 "Surveillance Requirements for Emergency Diesel Fuel Oil Sys
in Nuclear Power Plants," prepared for SNUPPS
STRAUSS, K H Strauss, K H 83/09/23 23pp 21379 340 24X
Fiche 50-369, 83/11/18, 8312050590

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 16pp 21957 267 24X
Fiche: 50-000, 84/01/06, 8401090221

B401190431 Responds to Generic Ltr 83-41 re possible effects of
fast cold starts on diesel generators Diesel generators
not sub to fast cold starts due to design features
TUCKER, H B Duke Power Co 84/01/09 DENTON, H R Office of
Nuclear Reactor Regulation, Director 1p 21849 228 24X
Fiche: 50-369, 84/01/09, 8401190431

B401200186 Application for amend to License NPF-9, extending required
implementation date for outside-containment portion of
in-core thermocouple sys upgrade, per NUREG-0737, Item II F 2,
"Inadequate Core Cooling Instruments," & Suppl 1 to NUREG
TUCKER, H B Duke Power Co 84/01/12 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSA, E O Licensing Branch
4 8pp 21864 335 24X Fiche 50-369, 84/01/12, 8401200186

B401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401230440 Submits design Mod M0-110B which adds one mechanical snubber
& deletes one hydraulic snubber in steam generator blowdown
sys Rev to Tech Spec 3 7 B will be submitted w/license amend
request
TUCKER, H B Duke Power Co 84/01/13 O'REILLY, J P Region 2,
Office of Director 1p 21880 341 24X Fiche 50-369, 84/01/13,
8401230440

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E
Bhaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
+ Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060150

B401170414 Forwards IE Safeguards Insp Repts 50-369/83-29 &
50-370/83-36 on 830725-29 & notice of violation Description
of safeguards mgt sys corrective actions requested Notice of
violation & rept details withheld (ref 10CFR73 21).
O'REILLY, J P Region 2, Office of Director 83/11/28 TUCKER, H B
Duke Power Co 3pp 21828 310 24X Fiche 50-369, 83/11/28,
8401170414

--B401170424 IE Safeguards Insp Rept 50-369/83-29 & 50-370/83-36 on
830725-29 Violation noted inadequate vital area barrier
Details withheld (ref 10CFR73 21)
TILLMAN, A Region 2, Office of Director MCQUIRE, D R Division
of Emergency Preparedness & Materials Safety 83/10/03 1p
21828 313 24X Fiche 50-369, 83/11/28, 8401170414

B401050486 Forwards IE Insp Repts 50-369/83-43 & 50-370/83-50 on
831031-1102 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/02
TUCKER, H B Duke Power Co 2pp 21730 111 24X
Fiche 50-369, 83/12/02, 8401050486

--B401050492 IE Insp Repts 50-369/83-43 & 50-370/83-50 on 831031-1102 No
violations noted Major areas inspected emergency
preparedness exercise
CLINE, W E Region 2, Office of Director JENKINS, O R Division
of Emergency Preparedness & Materials Safety 83/12/01 10pp
21730 113 24X Fiche 50-369, 83/12/02, 8401050486

B401050327 Forwards IE Insp Repts 50-369/83-41 & 50-370/83-48 on
831031-1102 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/05
TUCKER, H B Duke Power Co 2pp 21727 140 24X
Fiche 50-369, 83/12/05, 8401050327

--B401050335 IE Insp Repts 50-369/83-41 & 50-370/83-48 on 831031-1102 No
violations noted Major areas inspected: reactor coolant
chemistry, external exposure control & posting, labeling &
control
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division
of Engineering & Operational Programs 83/12/05 3pp 21727 142
24X Fiche 50-369, 83/12/05, 8401050327

B401050545 Forwards IE Insp Repts 50-369/83-42 & 50-370/83-49 on
830920-1030 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/06
TUCKER, H B Duke Power Co 2pp 21725 311 24X
Fiche 50-369, 83/12/06, 8401050545

--B401050562 IE Insp Repts 50-369/83-42 & 50-370/83-49 on 830920-1030 No
violations noted Major areas inspected operations safety
verification, maint activity, surveillance testing &
licensee event followup
ORDERS, W, PIERSON, R Region 2, Office of Director BROWNLEE, V L
Division of Project & Resident Programs 83/12/05 7pp
21725 313 24X Fiche 50-369, 83/12/06, 8401050545

B401090099 Forwards IE Insp Repts 50-369/83-44 & 50-370/83-51 on
831031-1120 No violation noted
DANCE, H C Division of Project & Resident Programs 83/12/15
TUCKER, H B Duke Power Co 2pp 21753 236 24X
Fiche 50-369, 83/12/15, 8401090099

--B401090104 IE Insp Repts 50-369/83-44 & 50-370/83-51 on 831031-1120 No
violation noted Major areas inspected operations safety
verification, surveillance testing & maint activities
ORDERS, W, PIERSON, R Region 2, Office of Director BROWNLEE, V L
Division of Project & Resident Programs 83/12/13 4pp
21753 238 24X Fiche 50-369, 83/12/15, 8401090099

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Under-voltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl
BEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 3HK Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

DOCKETED ITEMS

- 8401240319 Ack receipt of 831014 & 1222 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39
LEWIS, R. C. Division of Project & Resident Programs 84/01/12
TUCKER, H. B. Duke Power Co. 1p 21913 234 24X
Fiche 50-369, 84/01/12, 8401240319
- 8401240325 Suppls response to violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Corrective actions required documents posted in const portal on way to station radiation control zone
TUCKER, H. B. Duke Power Co. 83/12/22 O'REILLY, J. P. Region 2, Office of Director 2pp 21913 235 24X Fiche 50-369, 84/01/12, 8401240319
- 8401240348 Act receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Response to violation re bulletin boards in const portal evaluated during 831031-1102 insp
LEWIS, R. C. Division of Project & Resident Programs 83/12/07
TUCKER, H. B. Duke Power Co. 2pp 21913 237 24X
Fiche 50-369, 84/01/12, 8401240319
- 8401240354 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39
DANCE, H. C. Division of Project & Resident Programs 83/11/08
TUCKER, H. B. Duke Power Co. 1p 21913 239 24X
Fiche 50-369, 84/01/12, 8401240319
- 8401240367 Response to violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Corrective actions procedure changes implemented re radioactive matl shipments
TUCKER, H. B. Duke Power Co. 83/10/14 O'REILLY, J. P. Region 2, Office of Director 3pp 21913 240. 24X Fiche 50-369, 84/01/12, 8401240319
- 8401240371 Forwards IE Insp Repts 50-369/83-32 & 50-370/83-39 on 830808-12 & notice of violation
DANCE, H. C. Division of Project & Resident Programs 83/09/16
TUCKER, H. B. Duke Power Co. 2pp 21913 243 24X
Fiche 50-369, 84/01/12, 8401240319
- 8401240373 Notice of violation from insp on 830808-12
a Region 2, Office of Director 83/09/16 2pp 21913 245 24X
Fiche 50-369, 84/01/12, 8401240319
- 8401240380 IE Insp Repts 50-369/83-32 & 50-370/83-39 on 830808-12 Violations noted failure of radioactive matl shipping personnel to obtain revised procedure prior to 830701-0808 shipments & failure to post documents per 10CFR19.11
ALBRIGHT, R. H. Region 2, Office of Director BARR, K. P. Division of Engineering & Operational Programs 83/09/09 4pp 21913 247 24X Fiche 50-369, 84/01/12, 8401240319
- 8401170373 Ack receipt of 831221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36
O'REILLY, J. P. Region 2, Office of Director 84/01/13 TUCKER, H. B. Duke Power Co. 1p 21828 279 24X Fiche 50-369, 84/01/13, 8401170373
- 8401170381 Responds to NRC 831128 ltr re violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36 Corrective actions withheld (ref 10CFR73.21)
TUCKER, H. B. Duke Power Co. 83/12/21 O'REILLY, J. P. Region 2, Office of Director 1p 21828 280 24X Fiche 50-369, 84/01/13, 8401170373
- 8312120114 IE Info Notice 84-03, "Exercise Frequency," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21937 142. 24X Fiche 50-000, 84/01/16, 8312120114
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, 84/01/16, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 120pp 22000 041. 24X Fiche 50-000, 84/01/16, 8312120117
- R Periodic operating reports & related correspondence
- 8401200014 Monthly operating repts for Dec 1983 W/840113 ltr
REAVIS, J. A., TUCKER, H. B. Duke Power Co. 83/12/31 Director's Office, Office of Inspection and Enforcement 7pp 21864 281 24X
Fiche 50-369, 83/12/31, 8401200014
- S Reportable occurrences, LERs & related correspondence
- 8312200514 LER 83-106/03L-0 on 831025, invalid fire alarm for Fire Detection Zone 152 received in control room which would not reset Caused by corroded circuitry board of one ionization type detector Detector replaced W/831209 ltr
ORDERS, W. T., TUCKER, H. B. Duke Power Co. 83/12/09 O'REILLY, J. P. Region 2, Office of Director 2pp 21584 029 24X
Fiche 50-369, 83/12/09, 8312200514
- 8401040328 LER 83-111/03L-0 on 831117, detector voltage removed from source range detectors for channels N-31 & N-32, rendering channels inoperable Caused by personnel error & unclear procedure Detector voltage restored W/831216 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/16 O'REILLY, J. P. Region 2, Office of Director 2pp 21705 059 24X
Fiche 50-369, 83/12/16, 8401040328
- 8401040332 LER 83-112/03L-0 on 831121, fire protection Zone EFA 150 declared inoperable when trouble alarm would not reset Cause of trouble alarm actuation not determined Fire detectors in zone cleaned, checked & adjusted W/831221 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/21 O'REILLY, J. P. Region 2, Office of Director 2pp 21707 102 24X
Fiche 50-369, 83/12/21, 8401040332
- 8401040133 LER 83-113/03L-0 on 831124, trouble alarm for fire detection Zone EFA 162 received & would not reset Caused by moisture accumulation in detector base, resulting in corrosion Water source undetermined Detector replaced, W/831222 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/22 O'REILLY, J. P. Region 2, Office of Director 2pp 21702 034 24X
Fiche 50-369, 83/12/22, 8401040133
- 8401120226 LER 83-114/03L-0 on 831128, diesel generator load sequencer 1B declared inoperable, Caused by component malfunction Sequencer test satisfactorily completed after adjusting timers W/831228 ltr.
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/28 O'REILLY, J. P. Region 2, Office of Director 2pp 21793 335 24X
Fiche 50-369, 83/12/28, 8401120226
- 8401120217 RO 369/83-115 on 831129, degradation of annulus ventilation sys occurred Required info not yet available, Complete rept will be submitted by 840113
TUCKER, H. B. Duke Power Co. 83/12/29 O'REILLY, J. P. Region 2, Office of Director 1p 21792 256. 24X Fiche 50-369, 83/12/29, 8401120217
- 8401120376 LER 83-116/03L on 831202, invalid fire alarm for Fire Detection Zone EFA 40 (control room) received Alarm would not reset, Caused by dust & dirt accumulation Detector cleaned & adjusted W/831229 ltr
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/29 O'REILLY, J. P. Region 2, Office of Director 2pp 21792 013. 24X
Fiche 50-369, 83/12/29, 8401120376
- 8401130069 Updated LER 83-052/03X-1 on 830707, 10, 15 & 16, several fire detection zones declared inoperable due to invalid alarms Caused by bent contact on detector, dirt accumulation & detector base corrosion W/831230 ltr
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/30 O'REILLY, J. P. Region 2, Office of Director 2pp 21802 346 24X
Fiche 50-369, 83/12/30, 8401130069.
- 8401240130 Updated LER 83-061/03X-1, on 830719, while in Mode 3, radiation monitor EMF-17 was in alarm due to increase in general background activity Caused by receipt of spent fuel from Dconee Trip setpoints set higher W/831230 ltr
NARDOCI, P. B., TUCKER, H. B. Duke Power Co. 83/12/30 O'REILLY, J. P. Region 2, Office of Director 2pp 21913 143. 24X
Fiche 50-369, 83/12/30, 8401240130.
- 8401240480 Advises that mods to inadequate fire barriers between electrical penetration rooms in auxiliary bldg, described in 830928 ltr re ROs 369/83-72 & 370/83-44, rescheduled for completion by 840701.
TUCKER, H. B. Duke Power Co. 84/01/04 O'REILLY, J. P. Region 2, Office of Director 1p 21920 061 24X Fiche 50-369, 84/01/04, 8401240480.

DOCKETED ITEMS

257

B401240008 RD 369/83-117 on B31209, control rod insertion limits exceeded Tech Specs Investigation & rept preparation incomplete Rept will be submitted by B40120
TUCKER, H B Duke Power Co 84/01/06 O'REILLY, J P Region 2, Office of Director 1p 21912 309 24X Fiche 50-369, 84/01/06, B401240008

B401240119 LER B3-118/03L-0 on B31206 & 08, fire alarm for Fire Detection Zone EPA77 received & would not reset Cause of B31206 event was water accumulation in one detector Cause of B31208 event undetermined Detectors replaced W/B40106 ltr NARDCCI, P B., TUCKER, H B Duke Power Co 84/01/06 O'REILLY, J P Region 2, Office of Director 2pp 21913 208 24X Fiche 50-369, 84/01/06, B401240119

B401240270 Submits responses to NRC questions re util proposal to undertake Nelson Electric duties per Part 21 Proposal to apply only to purchases for new requirements, mod work & procurement of replacement parts after B30531
TUCKER, H B Duke Power Co 84/01/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q, Licensing Branch 4 6pp 21920 193 24X Fiche 50-000, 84/01/13, B401240270

--B401240297 Procedure NPM7, "Procedure for Reporting of Defects of Noncompliance on Nuclear Orders "
* Duke Power Co 84/01/13 11pp 21920 199 24X Fiche 50-000, 84/01/13, B401240290

--B401240302 Rev 6 to Procedure GA-121, "NRC Reporting Requirements "
HENRY, W D Duke Power Co 82/10/25 8pp 21920 212 24X Fiche 50-000, 84/01/13, B401240290

--B401240312 Rev 9 to Procedure PR-290, "NRC Reporting Requirements "
HENRY, W D Duke Power Co 83/09/27 9pp 21920 220 24X Fiche 50-000, 84/01/13, B401240290

--B401240324 Rev 6 to Procedure R-5, "NRC Reporting Requirements "
HENRY, W D Duke Power Co 82/10/25 10pp 21920 229 24X Fiche 50-000, 84/01/13, B401240290

B401260160 LER B3-119/03L-0 on B31214, invalid fire alarm for Fire Detection Zone EFA 76 received & alarm would not reset Caused by corrosion & dirt inside detector base Fire watch established Detector & base replaced W/B40113 ltr NARDCCI, P B., TUCKER, H B Duke Power Co 84/01/13 O'REILLY, J P Region 2, Office of Director 2pp 21956 037 24X Fiche 50-369, 84/01/13, B401260160

V Operator Examinations

B401240136 Forwards response to B31221 Generic Ltr B3-40 re operator licensing exam schedule List of operator exams scheduled for FY84, B5, B6 & B7 encl
TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director BECKHAM, D Operator Licensing Branch 2pp 21910 289 24X Fiche 50-369, 84/01/17, B401240136

DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

B401170414 Forwards IE Safeguards Insp Repts 50-369/83-29 & 50-370/83-36 on B30725-29 & notice of violation Description of safeguards mgt sys corrective actions requested Notice of violation & rept details withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/11/28 TUCKER, H B Duke Power Co 3pp 21828 310 24X Fiche 50-369, 83/11/28, B401170414

--B401170424 IE Safeguards Insp Rept 50-369/83-29 & 50-370/83-36 on B30725-29, Violation noted inadequate vital area barrier Details withheld (ref 10CFR73 21)
TILLMAN, A Region 2, Office of Director 83/10/03 1p, 21828 313 24X Fiche 50-369, 83/11/28, B401170414

B401050486 Forwards IE Insp Repts 50-369/83-43 & 50-370/83-50 on B31031-1102 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/02 TUCKER, H B Duke Power Co, 2pp 21730, 111 24X Fiche 50-369, 83/12/02, B401050486

--B401050492 IE Insp Repts 50-369/83-43 & 50-370/83-50 on B31031-1102 No violations noted Major areas inspected: emergency preparedness exercise
CLINE, W E Region 2, Office of Director 83/12/01, 10pp, 21730 113 24X Fiche 50-369, 83/12/02, B401050486

B401170484 Forwards exemption from requirements of 10CFR50, App E re annual emergency preparedness exercise, in response to B30309 & 1010 requests No exemption from 10CFR50 47 required
EISENHUT, D Q Division of Licensing 84/01/06 TUCKER, H B Duke Power Co 6pp 21844 271 24X Fiche 50-000, 84/01/06, B401170484

--B401170491 Exemption from requirements of App E to 10CFR50 re annual emergency preparedness exercise & provisions for training & exercising of licensee employees, including headquarters support personnel in radiation emergency matters
EISENHUT, D Q Division of Licensing 84/01/06 Duke Power Co, 9pp 21844 277 24X Fiche 50-000, 84/01/06, B401170484

B401170373 Ack receipt of B31221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36
O'REILLY, J P Region 2, Office of Director 84/01/13 TUCKER, H B Duke Power Co 1p 21828 279 24X Fiche 50-369, 84/01/13, B401170373

--B401170381 Responds to NRC B31128 ltr re violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36 Corrective actions withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/12/21 O'REILLY, J P Region 2, Office of Director 1p 21828 280, 24X Fiche 50-369, 84/01/13, B401170373

B401310018 Forwards Rev 18 to security plan, Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 84/01/16 O'REILLY, J P Region 2, Office of Director 1p 22023, 342 24X Fiche 50-369, 84/01/16, B401310018

B401310071 Releases public version of rev to emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 22032 294 24X Fiche 50-369, 84/01/18, B401310071

--B401310075 Public version of Rev 12 to emergency plan, W/B31212 ltr, MCINTOSH, M D., TUCKER, H B Duke Power Co 83/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q, Licensing Branch 4 33pp 22032 295 24X Fiche 50-369, 84/01/18, B401310071

H General correspondence

B401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000, 84/01/19, B401240335

P Operating license stage documents & correspondence

B312050590 Application for amend to Licenses NPF-9 & NPF-17, changing surveillance requirements for diesel fuel oil in Tech Spec 4 B 1 1 2
TUCKER, H B Duke Power Co 83/11/18 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q, Licensing Branch 4 3pp 21379 327, 24X Fiche 50-369, 83/11/18, B312050590

--B312050595 Proposed Tech Spec changes re surveillance requirements for emergency diesel fuel oil sys
* Duke Power Co 83/09/23 23pp, 21379 330 24X Fiche 50-369, 83/11/18, B312050590

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related," Svc list encl
EISENHUT, D Q Division of Licensing 84/01/05, Consolidated Edison Co of New York, Inc 16pp 21946, 190, 24X Fiche 50-000, 84/01/05, B401050382

B401050221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D Q, Division of Licensing 84/01/06, Consolidated Edison Co of New York, Inc, 18pp 21957, 267, 24X Fiche 50-000, 84/01/06, B401050221

B401190431 Responds to Generic Ltr B3-41 re possible effects of fast cold starts on diesel generators, Diesel generators not sub to fast cold starts due to design features
TUCKER, H B Duke Power Co, 84/01/09, DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p 21849, 228, 24X Fiche 50-369, 84/01/09, B401190431

DOCKETED ITEMS

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,8401130084

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000,83/10/20,8401060040

--8401060130 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401170414 Forwards IE Safeguards Insp Repts 50-369/83-29 & 50-370/83-36 on 830725-29 & notice of violation. Description of safeguards mgt sys corrective actions requested Notice of violation & rpt details withheld (ref 10CFR73 21)
O'REILLY, J P Region 2, Office of Director 83/11/28 TUCKER, H B Duke Power Co 3pp 21828 310 24X Fiche 50-369,83/11/28, 8401170414

--8401170424 IE Safeguards Insp Rept 50-369/83-29 & 50-370/83-36 on 830725-29 Violation noted inadequate vital area barrier Details withheld (ref 10CFR73 21)
TILLMAN, A Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/10/03 1p 21828 313 24X Fiche 50-369,83/11/28,8401170414

8401050486 Forwards IE Insp Repts 50-369/83-43 & 50-370/83-50 on 831031-1102 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/02 TUCKER, H B Duke Power Co 2pp 21730 111 24X
Fiche 50-369,83/12/02,8401050486

8401050492 IE Insp Repts 50-369/83-43 & 50-370/83-50 on 831031-1102 No violations noted Major areas inspected emergency preparedness exercise
CLINE, W E Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Safety 83/12/01 10pp 21730 113 24X Fiche 50-369,83/12/02,8401050486

8401050327 Forwards IE Insp Repts 50-369/83-41 & 50-370/83-48 on 831031-1102 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/05 TUCKER, H B Duke Power Co 2pp 21727 140 24X
Fiche 50-369,83/12/05,8401050327

8401050335 IE Insp Repts 50-369/83-41 & 50-370/83-48 on 831031-1102 No violations noted Major areas inspected reactor coolant chemistry, external exposure control & posting, labeling & control
ALBRIGHT, R H Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/12/05 3pp 21727 142 24X Fiche 50-369,83/12/05,8401050327

8401050345 Forwards IE Insp Repts 50-369/83-42 & 50-370/83-49 on 830920-1030 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/06 TUCKER, H B Duke Power Co 2pp 21725 311 24X
Fiche 50-369,83/12/06,8401050345

--8401050362 IE Insp Repts 50-369/83-42 & 50-370/83-49 on 830920-1030 No violations noted Major areas inspected operations safety verification, maint activity, surveillance testing & licensee event followup.
ORDERS, W, PIERSON, R Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/12/05 7pp 21725 313 24X Fiche 50-369,83/12/06,8401050345

8401090099 Forwards IE Insp Repts 50-369/83-44 & 50-370/83-51 on 831031-1120 No violation noted.
DANCE, H C Division of Project & Resident Programs 83/12/15 TUCKER, H B Duke Power Co 2pp 21753 236 24X
Fiche 50-369,83/12/15,8401090099

--8401090104 IE Insp Repts 50-369/83-44 & 50-370/83-51 on 831031-1120 No violation noted Major areas inspected operations safety verification, surveillance testing & maint activities
ORDERS, W, PIERSON, R Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/12/15 4pp 21753 238 24X Fiche 50-369,83/12/15,8401090099

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

8401240319 Ack receipt of 831014 & 1222 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39
LEWIS, R C Division of Project & Resident Programs 84/01/12 TUCKER, H B Duke Power Co 1p 21913 234 24X
Fiche 50-369,84/01/12,8401240319

--8401240325 Suppls response to violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Corrective actions required documents posted in const portal on way to station radiation control zone
TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P Region 2, Office of Director 2pp 21913 235 24X Fiche 50-369,84/01/12, 8401240319

--8401240348 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Response to violation re bulletin boards in const portal evaluated during 831031-1102 insp
LEWIS, R C Division of Project & Resident Programs 83/12/07 TUCKER, H B Duke Power Co 2pp 21913 237 24X
Fiche 50-369,84/01/12,8401240319

--8401240354 Ack receipt of 831014 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39
DANCE, H C Division of Project & Resident Programs 83/11/08 TUCKER, H B Duke Power Co 1p 21913 239 24X
Fiche 50-369,84/01/12,8401240319

--8401240367 Responds to violations noted in IE Insp Repts 50-369/83-32 & 50-370/83-39 Corrective actions procedure changes implemented re radioactive matl shipments
TUCKER, H B Duke Power Co 83/10/14 O'REILLY, J P Region 2, Office of Director 3pp 21913 240 24X Fiche 50-369,84/01/12, 8401240319

--8401240371 Forwards IE Insp Repts 50-369/83-32 & 50-370/83-39 on 830808-12 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/09/16 TUCKER, H B Duke Power Co 2pp 21913 243 24X
Fiche 50-369,84/01/12,8401240319

--8401240373 Notice of violation from insp on 830808-12
* Region 2, Office of Director 83/09/16 2pp 21913 245 24X
Fiche 50-369,84/01/12,8401240319

--8401240380 IE Insp Repts 50-369/83-32 & 50-370/83-39 on 830808-12 Violations noted failure of radioactive matl shipping personnel to obtain revised procedure prior to 830701-0808 shipments & failure to post documents per 10CFR19.11
ALBRIGHT, R H Region 3, Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/09 6pp 21913 247 24X Fiche 50-369,84/01/12,8401240319

8401170373 Ack receipt of 831221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36
O'REILLY, J P Region 2, Office of Director 84/01/13 TUCKER, H B Duke Power Co 1p 21828 279 24X Fiche 50-369,84/01/13, 8401170373

--8401170381 Responds to NRC 831128 ltr re violations noted in IE Insp Repts 50-369/83-29 & 50-370/83-36 Corrective actions withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/12/21 O'REILLY, J P Region 2, Office of Director 1p 21828 280 24X Fiche 50-369,84/01/13, 8401170373

DOCKETED ITEMS

259

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401200014 Monthly operating repts for Dec 1983 W/B40113 ltr
REAVIS, J A , TUCKER, H B Duke Power Co 83/12/31 Director's
Office, Office of Inspection and Enforcement 9pp 21864 281 24X
Fiche 50-369, 83/12/31, B401200014

S Reportable occurrences, LERs & related correspondence

B401040354 LER B3-079/03L-O on B31114, while in Mode 1, pressurizer level instrumentation channel II indicated greater than 44 higher than other channels. Caused by component failure New fittings installed W/B31220 ltr
NARDCCI, P B , ORDERS, W T Duke Power Co 83/12/20 O'REILLY, J P
Region 2, Office of Director 2pp 21706 213 24X
Fiche 50-370, 83/12/20, B401040354

B401040410 LER B3-078/03L-O on B31120, during attempt to perform airlock operability test, remote control unit for lower containment airlock leak rate monitor indicated loss of programming data. Data reentered W/B31220 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 83/12/20 O'REILLY, J P
Region 2, Office of Director 2pp 21703 360 24X
Fiche 50-370, 83/12/20, B401040410

B401040311 LER B3-082/03L-O on B31126, surveillance test on ice condenser intermediate deck door not performed Door declared inoperable. Caused by operator error Test performed satisfactorily on B31128 W/B31222 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21708 021 24X
Fiche 50-370, 83/12/22, B401040311

B401040935 LER B3-081/03L-O on B31125, fire alarm for fire detection Zone EFA 1B8 received in control room & would not reset EFA 1B8 declared inoperable. Caused by dirt accumulation in one ionization type detector Detector replaced W/B31222 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21705 349 24X
Fiche 50-370, 83/12/22, B401040935

B401040562 LER B3-080/03L-O on B31122, during investigation of high sump level alarm, RCS valve 2NC-568 found leaking between body & diaphragm. Caused by loosened valve bonnet Valve disassembled & valve diaphragm replaced W/B31222 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21706 312 24X
Fiche 50-370, 83/12/22, B401040562

B401120375 LER B3-083/03L-O on B31130, during performance of ice condenser refrigeration sys valve stroke timing quarterly test, valve 2NF-22B failed to meet closure time of 15 s. Caused by component malfunction Valve cycled, W/B31229 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 83/12/29 O'REILLY, J P
Region 2, Office of Director 2pp 21792 011 24X
Fiche 50-370, 83/12/29, B401120375

B401240480 Advises that mods to inadequate fire barriers between electrical penetration rooms in auxiliary bldg, described in B30928 ltr re RDs 369/83-72 & 370/83-44, rescheduled for completion by B40701
TUCKER, H B Duke Power Co 84/01/04 O'REILLY, J P Region 2,
Office of Director 1p 21920 061 24X Fiche 50-369, 84/01/04, B401240480

B401240287 LER B3-084/03L-O on B31206, during performance of chemical & vol control sys valve stroke timing test, valve 2NV-B42A, C failed to close within required closure time. Caused by failed electrical contact W/B40103 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 84/01/05 O'REILLY, J P
Region 2, Office of Director 2pp 21909 332 24X
Fiche 50-370, 84/01/05, B401240287

B401240594 LER B3-085/03L-O on B31208, makeup frequency to vol control tank increased & containment & equipment sump 2A pumped out several times, indicating leakage problem. Caused by component malfunction Sample line isolated W/B40106 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 84/01/06 O'REILLY, J P
Region 2, Office of Director 2pp 21909 171 24X
Fiche 50-370, 84/01/06, B401240594

B401240105 LER B3-086/03L-O on B31212 & 13, invalid fire alarm for Fire Detection Zone 107 received & would not reset. Caused by broken ionization chamber mounting pins Detector replaced W/B40111 ltr
NARDCCI, P B Duke Power Co 84/01/11 O'REILLY, J P Region 2,
Office of Director 2pp 21913 154 24X Fiche 50-370, 84/01/11, B401240105

B401240282 Updated final Significant Deficiency Rept SD-370/B2-06 re evaluation of ITT Barton Class IE transmitters exhibiting thermal nonrepeatability. Safety analyses involving protection functions using transmitters conservative
TUCKER, H B Duke Power Co 84/01/11 O'REILLY, J P Region 2,
Office of Director 3pp 21909 348 24X Fiche 50-370, 84/01/11, B401240282

B401240290 Submits responses to NRC questions re util proposal to undertake Nelson Electric duties per Part 21 Proposal to apply only to purchases for new requirements, mod work & procurement of replacement parts after B30531
TUCKER, H B Duke Power Co 84/01/13 DENTON, H R Office of
Nuclear Reactor Regulation, Director ADENSAH, E G. Licensing Branch
4 2pp 21920 193 24X Fiche 50-000, 84/01/13, B401240290

--B401240297 Procedure NPM7, "Procedure for Reporting of Defects of Noncompliance on Nuclear Drifts "
* Duke Power Co 84/01/13 11pp 21920 199 24X
Fiche 50-000, 84/01/13, B401240290

--B401240302 Rev 4 to Procedure QA-121, "NRC Reporting Requirements "
HENRY, W D Duke Power Co 82/10/25 8pp 21920 212 24X
Fiche 50-000, 84/01/13, B401240290

--B401240312 Rev 9 to Procedure PR-290, "NRC Reporting Requirements. "
HENRY, W D Duke Power Co 83/09/27 9pp 21920 220 24X
Fiche 50-000, 84/01/13, B401240290

--B401240324 Rev 4 to Procedure R-5, "NRC Reporting Requirements "
HENRY, W D Duke Power Co 82/10/25 10pp 21920 229 24X
Fiche 50-000, 84/01/13, B401240290

B401240437 LER B3-087/03L-O on B31215, while in Mode 1, during monthly functional test containment hydrogen analyzer calibrator, analyzer 2B could not be satisfactorily calibr. Caused by faulty connection on amplifier control card W/B40113 ltr
NARDCCI, P B , TUCKER, H B Duke Power Co 84/01/13 O'REILLY, J P
Region 2, Office of Director 2pp 21915 188 24X
Fiche 50-370, 84/01/13, B401240437

V Operator Examinations

B401240136 Forwards response to B31221 Generic Ltr B3-40 re operator licensing exam schedule List of operator exams scheduled for FY84: 85, 86 & 87 encl
TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of
Nuclear Reactor Regulation, Director BECKHAM, D Operator Licensing
Branch 2pp 21910 289 24X Fiche 50-369, 84/01/17, B401240136

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

E NRC Safety Evaluation Report (SER), supp's & correspondence

B401030444 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF LA
SALLE COUNTY STATION, UNITS 1 AND 2 Docket Nos 50-373 And
50-374 (Commonwealth Edison Company)
* Division of Licensing NUREG-0519 B07 83/12/31 64pp
21692 134 24X Fiche 50-373, 83/12/31, B401030444

F Security, medical, emergency & fire protection plans

B401050055 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21742 352 24X Fiche 50-373, 83/12/28, B401050055

--B401050063 Public version of Rev 2 to Emergency Plan Implementing Procedure L2P-1360-2, "Use of Potassium Iodide (KI) as Thyroid Blocking Agent " W/B31203 ltr & revised index.
* Commonwealth Edison Co 83/11/17, Office of Nuclear Reactor
Regulation, Director 15pp. 21742: 353 24X Fiche 50-373, 83/12/28, B401050055

DOCKETED ITEMS

8401060434 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21755 154 24X Fiche 50-373, 83/12/28, 8401060234

--8401060259 Public version of Rev 2 to Emergency Plan Implementing Procedure LZF-1200-4, "Classification of Liquid Release"
Revised index encl
* Commonwealth Edison Co 83/11/04 10pp 21755 155 24X
Fiche 50-373, 83/12/28, 8401060234

8401190163 Responds to 830930 ltr re Rev 15 to security plan. Plans consistent w/provisions of 10CFR30.34(p) & acceptable
SCHWENCER, A Licensing Branch 2 83/12/30 FARRAR, D L
Commonwealth Edison Co 2pp 21870 351 24X Fiche 50-373, 83/12/30, 8401190163

8401230491 Notification of 840112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C
Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, 8401230491

8401180163 Forwards "Part I Exercise Final Rept, LaSalle Nuclear Power Station Joint Radiological Emergency Exercise"
Deficiencies did not detract from capability to protect public Approval 350 will remain in effect
KRIMM, R W Federal Emergency Management Agency 84/01/06
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 21840 312 24X Fiche 50-373, 84/01/06, 8401180163

--8401180174 "Part I Exercise Final Rept, LaSalle Nuclear Power Station Joint Radiological Emergency Exercise"
* Federal Emergency Management Agency, 83/07/12 30pp
21840 318 24X Fiche 50-373, 84/01/06, 8401180163.

01250309 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21952 184 24X Fiche 50-373, 84/01/18, 8401250309

8401250312 Forwards public version of revised emergency plan implementing procedures, including Procedures LZF-1200-5 re generating station emergency procedure guidelines for offsite protective actions & LZF-1310-1 re notifications
HOLYOAK, R H Commonwealth Edison Co 83/10/25 Office of Nuclear Reactor Regulation, Director 7pp 21952 185 24X
Fiche 50-373, 84/01/18, 8401250309

- 8401250314 Public version of revised emergency plan implementing procedures, including Procedures LZF-1200-5 re generating station emergency procedure guidelines for offsite protective actions & LZF-1310-1 re notifications
* Commonwealth Edison Co 84/10/17 74pp 21952 193 24X
Fiche 50-373, 84/01/18, 8401250309

/1310054 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 22029 289 24X Fiche 50-373, 84/01/18, 8401310054.

-8401310058 Forwards public version of revised Emergency Procedures LZF-1330-21, "Determination of Reactor Coolant Chloride... Sampling Sys" & LZF-1330-25, "Sampling of Reactor Coolant at High Radiation Sample Sys." Receipt form encl
* Commonwealth Edison Co 83/12/23 Office of Nuclear Reactor Regulation, Director, 1p 22029 290, 24X Fiche 50-373, 84/01/18, 8401310054

8401310064 Public version of revised Emergency Procedures LZF-1330-21, "Determination of Reactor Coolant Chloride Sampling Sys" & LZF-1330-25, "Sampling of Reactor Coolant at High Radiation Sample Sys"
* Commonwealth Edison Co 83/11/21 55pp 22029 292, 24X
Fiche 50-373, 84/01/18, 8401310054

01260293 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p, 21992 296 24X Fiche: 50-373, 84/01/20, 01260293.

01260297 Public version of Rev 3 to Emergency Plan Implementing Procedure LZF-1210-1, "Hazardous Matl Incidents Reporting"
LAWLESS, F. Commonwealth Edison Co 83/12/29 12pp 21992 297, 24X Fiche 50-373, 84/01/20, 8401260293

G Adjudicatory correspondence

8401100466 Addendum to petition for emergency relief per 10CFR2.205 re integrated leak rate testing All documentation re integrated leak rate tests must be made public
OGGOL, E M Affiliation Unknown 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21761 286 24X
Fiche 50-000, 84/01/06, 8401100466

8401170322 Submits Joint Intervenor's opposition to util applications to permit hot sys testing (Modes 3 & 4) & low power operation Design & const deficiencies should be corrected before add'l licensing authority granted
REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenor - Diablo Canyon 84/01/13 PALLADINO, N, GILINKBY, V, ROBERTS, T Commissioners 11pp 21831 159 24X
Fiche 50-275, 84/01/13, 8401170322

J Insurance & indemnity information

8401060534 Unexecuted Amend 4 to Indemnity Agreement B-84
SALTZMAN, J Assistant Director for State & Licensee Relations 83/12/16 3pp 21755 131 24X Fiche 50-373, 83/12/16, 8401060534

8401090504 Forwards Amend 4 to Indemnity Agreement B-84
OSTER, J Commonwealth Edison Co 84/01/03 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 21780 360 24X
Fiche 50-373, 84/01/03, 8401090504

8401200141 Forwards Endorsement 4 to NELIA Certificates N-1, 2, 3, 29, 30, 42, 43 & 71 & MAELU Certificates M-1, 2, 3, 29, 30, 42-43 & 71
OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant Director for State & Licensee Relations 17pp 21865 332 24X
Fiche 50-000, 84/01/09, 8401200141

8401200184 Forwards listed endorsements to NELIA Policies NF-43, 187, 201, 253 & 277 & MAELU Policies MF-22, 54, 64 & 104
OSTER, J Commonwealth Edison Co 84/01/09 SALTZMAN, J Assistant Director for State & Licensee Relations 19pp 21863 232 24X
Fiche 50-000, 84/01/09, 8401200184

P Operating license stage documents & correspondence

8401110165 Notification of 840104 meeting w/Z Raytblatt in Bethesda, MD to discuss integrated leak rate testing
BOURNIA, A Licensing Branch 2 83/12/27 SCHWENCER, A Licensing Branch 2 3pp 21794 360 24X Fiche 50-373, 83/12/27, 8401110165

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation will vary at each facility
SWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, 8401030229

8401060271 Application for emergency change to Tech Specs re control rod drive coupling & control rod operability Change allows mode changes w/affected control rod inserted & disarmed
SCHROEDER, C W Commonwealth Edison Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21741 269 24X Fiche 50-373, 84/01/04, 8401060271

--8401060288 Proposed Tech Specs for control rod operability, changing applicability of Spec 3 O 4 provisions Significant hazards consideration encl
* Commonwealth Edison Co, 84/01/04 6pp 21741 274 24X
Fiche 50-373, 84/01/04, 8401060271

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPEs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp, 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090142 Application for amend to License NPF-11, documenting 840104 handwritten emergency change to Tech Spec on control rod drive coupling & control rod operability.
SCHROEDER, C W Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director, 4pp, 21749 203 24X Fiche 50-373, 84/01/05, 8401090142

--8401090145 Proposed Tech Specs re control rod drive coupling & control rod operability Significant hazards consideration encl.
* Commonwealth Edison Co, 84/01/05 9pp 21749 207 24X
Fiche 50-373, 84/01/05, 8401090142

DOCKETED ITEMS

261

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D Q Division of Licensing B4/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, B4/01/06, B401090221

B401170523 Confirms B40104 telephone authorization re changes to Tech Spec Paragraphs 3 i 3 i 1 & 3 i 3 i 6, requested by B40104 ltr
Formal license amend, safety evaluation & FR notice being processed
NGVAK, T M Assistant Director for Licensing B4/01/09 FARRAR, D L
Commonwealth Edison Co 2pp 21844 358 24X Fiche 50-373,
B4/01/09, B401170523

B401170339 Responds to Generic Ltr B3-41, "Fast Cold Starts of Diesel Generators." Prelubrication w/some warning provided, therefore, generators not subjected to cold starts
BARNES, P L Commonwealth Edison Co B4/01/10 EISENHUT, D Q
Division of Licensing 1p 21829 341 24X Fiche 50-000, B4/01/10, B401170339

B401230288 Retransmits CW Schroeder B31201 ltr to HR Denton correcting typographical error re multiple failure concerns Potential radiological insult associated w/special scenario event trivial w/respect to 10CFR100 guidelines
SCHROEDER, C W Commonwealth Edison Co B4/01/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21882 325
24X Fiche 50-373, B4/01/11, B401230288

B401230338 Modifies wording in request for change to Tech Specs re diesel generator fast starts performed at least once per 184 days in surveillance testing All other starts shall be preceded by engine prelube period
SCHROEDER, C W Commonwealth Edison Co B4/01/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21878 234
24X Fiche 50-373, B4/01/11, B401230338

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D Q Division of Licensing B4/01/13 Consolidated
Edison Co of New York, Inc 18pp 21746 174 24X
Fiche 50-000, B4/01/13, B401130084

B401230424 Application for amend to License NPF-11, revising Tech Specs to reflect changes incorporated into Unit 2 Tech Specs on B31216 Class II amend fee encl
SCHROEDER, C W Commonwealth Edison Co B4/01/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21878 001
24X Fiche 50-373, B4/01/13, B401230424

--B401230433 Proposed Tech Specs reflecting changes incorporated into Unit 2 Tech Specs approved on B31216
* Commonwealth Edison Co B4/01/13 212pp 21878 003 24X
Fiche 50-373, B4/01/13, B401230424

B401260200 Summary of B40104 meeting w/Z Reutblatt of EXTRAN, Inc re available data base for 10CFR50, App J containment integrated leak tests at facility, per EM 0001 B31129 petitions
SCHWENGER, A Operating Reactors Branch 2, B4/01/17 Operating
Reactors Branch 2 5pp 21971 324 24X Fiche 50-373, B4/01/17, B401260200

G Inspection reports, IE Bulletins & correspondence

B401230149 Requests mitigation of civil penalty proposed in B30809 notice of violation Contention that previous noncompliance items should have identified potential for violation appears in error
REED, C Commonwealth Edison Co B3/09/06 KEPLER, J G Region 3,
Office of Director 2pp 21885, 003 24X Fiche 50-373, B3/09/06, B401230149

B401230233 Responds to notice of violation & proposed imposition of civil penalty re mispositioned breaker isolation valve in suppression pool to drywell vacuum Double verification of safety-related equipment lineup instituted
REED, C Commonwealth Edison Co B3/09/06 KEPLER, J G Region 3,
Office of Director 14pp, 21884 063 24X Fiche 50-373, B3/09/06, B401230233

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHNER, R E
Shaw, Pittman, Petts & Trowbridge 1p 21744 003 24X
Fiche 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401040533 Suppls response to IE Bulletin B3-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
BARNES, P L Commonwealth Edison Co B3/12/20 KEPLER, J G Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, B3/12/20, B401040533

B401040268 Ack receipt of B31214 ltr informing NRC of actions taken in response to B31128 confirmatory action ltr re ethylene-propylene soft seats on feedwater check valves Actions will be examined during future insp
SPESSARD, R L Division of Engineering B3/12/27 REED, C
Commonwealth Edison Co 1p 21701 335 24X Fiche 50-373, B3/12/27, B401040268

--B401040278 Responds to B31128 confirmatory action ltr re ethylene-propylene soft seats on inboard 24-inch feedwater check valves Actions A-D fulfilled Current status on Action E provided
SCHROEDER, C W Commonwealth Edison Co B3/12/14 KEPLER, J G Region 3, Office of Director 13pp 21701 336 24X
Fiche 50-373, B3/12/27, B401040268

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B401060231 Ack receipt of B31220 ltr & check in amount of \$40,000 as payment of civil penalty imposed by B31130 order
AXELRAD, J A Director's Office, Office of Inspection and Enforcement B3/12/30 O'CONNOR, J J Commonwealth Edison Co 2pp 21758 167 24X Fiche 50-373, B3/12/30, B401060231

B401270359 Forwards IE Insp Repts 50-373/B3-49 & 50-374/B3-52 on B31118-1216 & notice of violation
SHAFFER, W D Region 3, Office of Director B4/01/04 REED, C,
Commonwealth Edison Co 2pp 21775 325 24X Fiche 50-373, B4/01/06, B401270359

--B401270361 Notice of violation from insp on B31118-1216
SHAFFER, W D Region 3, Office of Director B4/01/06 2pp,
21775, 327 24X Fiche 50-373, B4/01/06, B401270359

--B401270366 IE Insp Repts 50-373/B3-49 & 50-374/B3-52 on B31118-1216 Noncompliance noted failure to perform surveillance test, inadequate review of post-mod testing requirements & Tech Spec violations
GULDEMOND, W Q, GUTHRIE, S C, EVANS, C D Region 3, Office of Director B4/01/04 22pp, 21775 329 24X Fiche 50-373, B4/01/06, B401270359

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 125pp 21746 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co of New York, Inc 122pp, 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401230285 Ack receipt of B40105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/B3-48, NORELUB, C E Division of Project & Resident Programs B4/01/13, REED, C, Commonwealth Edison Co 1p 21884:279, 24X
Fiche 50-373, B4/01/13, B401230285

--B401230294 Responds to NRC B31206 ltr re violations noted in IE Insp Rept 50-373/B3-48, Corrective actions: drywell pneumatic sys suction downstream isolation valve IN001B repositioned & equipment attendants trained on proper valve operation.
FARRAR, D L Commonwealth Edison Co B4/01/05 KEPLER, J G Region 3, Office of Director 5pp 21884, 280 24X
Fiche 50-373, B4/01/13, B401230285

DOCKETED ITEMS

8401230315 Act receipt of 831222 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-50 & 50-374/83-53 Justification for restart of Unit 1 & continued operation through first cycle acceptable NORELIOUS, C E Division of Project & Resident Programs 84/01/13 REED, C Commonwealth Edison Co 2pp 21883 151 24X Fiche 50-373, 84/01/13, 8401230315

--8401230334 Suppls 831222 response to NRC, per 831223 telcon, re violations noted in IE Insp Rept 50-373/83-50 Addl info re adequacy of visual insp techniques to determine condition of cables at higher elevations of drywell provided SCHROEDER, C W Commonwealth Edison Co 83/12/27 KEPLER, J O Region 3, Office of Director 2pp 21883 153 24X Fiche 50-373, 84/01/13, 8401230315

--8401230339 Forwards "Rept on Unit 1 High Drywell Temp," as committed to during 831121 meeting & documented in IE Insp Repts 50-373/83-50 & 50-374/83-53 Drywell heating problem in context of short-term fixes addressed SCHROEDER, C W Commonwealth Edison Co 83/12/22 KEPLER, J O Region 3, Office of Director 2pp 21883 155 24X Fiche 50-373, 84/01/13, 8401230315

--8401230342 "Rept on Unit 1 High Drywell Temp" * Commonwealth Edison Co 83/12/22 23pp 21883 157 24X Fiche 50-373, 84/01/13, 8401230315

8401230351 Act receipt of 840105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-42 & 50-374/83-46 NORELIOUS, C E Division of Project & Resident Programs 84/01/13 REED, C Commonwealth Edison Co 1p 21884 253 24X Fiche 50-373, 84/01/13, 8401230351

--8401230372 Responds to NRC 831206 ltr re violations noted in IE Insp Repts 50-373/83-42 & 50-374/83-46 Corrective actions: jumper authorized & installed on safety-related buses from Unit 2 undervoltage auxiliary transformer FARRAR, D L Commonwealth Edison Co 84/01/05 KEPLER, J O Region 3, Office of Director 5pp 21884 254 24X Fiche 50-373, 84/01/13, 8401230351

01300022 Forwards IE Insp Repts 50-373/83-51 & 50-374/83-50 on 831102-1215 & notice of violation STREETER, J F Region 3, Office of Director 84/01/13 REED, C Commonwealth Edison Co 2pp 21999 240 24X Fiche 50-373, 84/01/13, 8401300022

8401300024 Notice of violation from insp on 831102-1215 STREETER, J F Region 3, Office of Director 84/01/13 1p 21999 242 24X Fiche 50-373, 84/01/13, 8401300022

--8401300026 IE Insp Repts 50-373/83-51 & 50-374/83-50 on 831102-1215 Noncompliance noted failure to follow procedures during secondary containment integrity test LANKEBURY, R D, REYES, L A, STREETER, J F Region 3, Office of Director 84/01/14 5pp 21999 243 24X Fiche 50-373, 84/01/13, 8401300022

120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering (response Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

11230273 Act receipt of 840103 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-373/83-46 & 50-374/83-39 STREETER, J F Region 3, Office of Director 84/01/16 REED, C Commonwealth Edison Co 1p 21884 285 24X Fiche 50-373, 84/01/16, 8401230273

401230306 Responds to NRC 831116 ltr re open items noted in IE Insp Repts 50-373/83-46 & 50-374/83-39 Corrective actions sys operational analysis dept test procedures will be enhanced to delineate min documentation requirements, FARRAR, D L Commonwealth Edison Co 84/01/03 KEPLER, J O Region 3, Office of Director 4pp 21884 286 24X Fiche 50-373, 84/01/16, 8401230273

120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Cification of Disability by Licensed Operators" Svc list

JAN, E L Division of Emergency Preparedness & Engineering (response Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

17 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valve Used Only During Cold Shutdowns" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering (response Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120215 Monthly operating rept for Nov 1983 W/831209 ltr LIN, D L, DIEDERICH, G J Commonwealth Edison Co 83/11/30 NRC - No Detailed Affiliation Given 24pp 21794 025 24X Fiche 50-373, 83/11/30, 8401120215

8401170402 Monthly operating rept for Dec 1983 W/840105 ltr LIN, D L, DIEDERICH, G J Commonwealth Edison Co 83/12/31 NRC - No Detailed Affiliation Given 15pp 21828 295 24X Fiche 50-373, 83/12/31, 8401170402

S Reportable occurrences, LERs & related correspondence

8401130290 LER 83-148/03L-0 on 831118 bus 142V deenergized & switchgear 136X equipment failed to loadshed Caused by main sensing contact welding closed Contact separated & burnished W/831216 ltr HIETALA, J J, DIEDERICH, G J Commonwealth Edison Co 83/12/16 KEPLER, J O Region 3, Office of Director 3pp 21801 124 24X Fiche 50-373, 83/12/16, 8401130290

8401060268 LER 83-149/03L-0 on 831207, setpoint for reactor low water level switch 1821-N024C exceeded Tech Spec value Cause could not be determined Switch immediately recalibr W/831220 ltr LINTAKAS, A, DIEDERICH, G J Commonwealth Edison Co 83/12/20 KEPLER, J O Region 3, Office of Director 3pp 21740 149 24X Fiche 50-373, 83/12/20, 8401060268

8401050437 LER 83-150/01T-0 on 831212, Trip Function 3 a & 4 a for "Detector Not Full In" test not performed Caused by faulty technique to identify requirements New procedures will be written to satisfy requirements W/831222 ltr WELSH, D J, DIEDERICH, G J Commonwealth Edison Co 83/12/23 KEPLER, J O Region 3, Office of Director 4pp 21729 341 24X Fiche 50-373, 83/12/23, 8401050437

8401130341 LER 83-151/03L-0 on 831128, Functional Test L16-NR-02, required for Operating Conditions 2-5 due 831125 not performed until 831128 Caused by personnel error Stronger emphasis on surveillance program implemented W/831223 ltr WELSH, D J, DIEDERICH, G J Commonwealth Edison Co 83/12/23 KEPLER, J O Region 3, Office of Director 3pp 21798 282 24X Fiche 50-373, 83/12/23, 8401130341

8401060404 LER 83-152/03L-0 on 831130, shutdown cooling inboard isolation valve IE12-F009 exceeded allowable leakage limit Caused by bottom seat ring sealing surface not adequately flat Ring machined to assure flatness W/831230 ltr DUB, R, DIEDERICH, G J Commonwealth Edison Co 83/12/30 KEPLER, J O Region 3, Office of Director 3pp 21740 355 24X Fiche 50-373, 83/12/30, 8401060404

8401160261 LER 83-153/01T-0 on 831227, OA diesel fire pump damaged due to reverse rotation Caused by wood block keeping OA diesel fire pump discharge check valve open, causing pump & attached engine to rotate backwards W/840110 ltr POSTER, J, DIEDERICH, G J Commonwealth Edison Co 84/01/10 KEPLER, J O Region 3, Office of Director 5pp 21814 177 24X Fiche 50-373, 84/01/10, 8401160261

8401230404 LER 83-154/03L-0 on 831214, while performing LES-EH-01, reactor protection sys limit switch 1C71-N006E, for turbine stop valve 2, found out of spec Caused by loose set screw coupling limit switch to actuating arm W/840110 ltr TOKARZ, J, DIEDERICH, G J Commonwealth Edison Co 84/01/10 KEPLER, J O Region 3, Office of Director 4pp 21879 129 24X Fiche 50-373, 84/01/10, 8401230404

8401230258 PNO-111-84-007, on 840116, flexible metallic joint in steam exhaust sys from turbine ruptured, causing loss of vacuum in condenser & reactor shutdown Repairs to flexible metallic joint to take 2-3 days MADISON, A, SHAFER, W Region 3, Office of Director 84/01/05 1p 21883 362 24X Fiche 50-373, 84/01/17, 8401230258

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crisis & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

E NRC Safety Evaluation Report (SER), supp's & correspondence

B401030446 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF LA SALLE COUNTY STATION, UNITS 1 AND 2 Docket Nos 50-373 And 50-374 (Commonwealth Edison Company)
* Division of Licensing NUREG-0519 507 83/12/31 64pp 21692 134 24X Fiche 50-373, 83/12/31, B401030446

F Security, medical, emergency & fire protection plans

B401050055 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21742 352 24X Fiche 50-373, 83/12/28, B401050055

--B401050063 Public version of Rev 2 to Emergency Plan Implementing Procedure LFP-1260-2, "Use of Potassium Iodide (KI) as Thyroid Blocking Agent" w/831203 ltr & revised index
* Commonwealth Edison Co 83/11/17 Office of Nuclear Reactor Regulation, Director 15pp 21742 353 24X Fiche 50-373, 83/12/28, B401050055

B401060234 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/12/28 Document Management Branch 1p 21755 154 24X Fiche 50-373, 83/12/28, B401060234

--B401060259 Public version of Rev 2 to Emergency Plan Implementing Procedure LFP-1200-4, "Classification of Liquid Release" Revised index encl
* Commonwealth Edison Co 83/11/04 10pp 21755 155 24X Fiche 50-373, 83/12/28, B401060234

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation will vary at each facility
SHARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X Fiche 50-000, 83/12/29, B401030229

B401190163 Responds to 830930 ltr re Rev 15 to security plan Plans consistent w/provisions of 10CFR50 54(p) & acceptable
SCHWENGER, A Licensing Branch 2 83/12/30 FARRAR, D L Commonwealth Edison Co 2pp 21870 351 24X Fiche 50-373, 83/12/30, B401190163

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche: 50-000, 84/01/05, B401230491

B401180163 Forwards "Part I Exercise Final Rept, LaSalle Nuclear Power Station Joint Radiological Emergency Exercise"
Deficiencies did not detract from capability to protect public Approval 350 will remain in effect
KRIMM, R W Federal Emergency Management Agency 84/01/06 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 21840 312 24X Fiche 50-373, 84/01/06, B401180163

--B401180174 "Part I Exercise Final Rept, LaSalle Nuclear Power Station Joint Radiological Emergency Exercise"
* Federal Emergency Management Agency, 83/07/12 30pp, 21840 318 24X Fiche 50-373, 84/01/06, B401180163

B401250309 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21952 184 24X Fiche 50-373, 84/01/18, B401250309

--B401250312 Forwards public version of revised emergency plan implementing procedures, including Procedures LFP-1200-5 re generating station emergency procedure guidelines for offsite protective actions & LFP-1310-1 re notifications.
HOLYOAK, R H Commonwealth Edison Co 83/10/25 Office of Nuclear Reactor Regulation, Director 7pp 21952 185 24X Fiche 50-373, 84/01/18, B401250309

--B401250314 Public version of revised emergency plan implementing procedures, including Procedures LFP-1200-5 re generating station emergency procedure guidelines for offsite protective actions & LFP-1310-1 re notifications
* Commonwealth Edison Co 84/10/17 74pp 21952 193 24X Fiche 50-373, 84/01/18, B401250309

B401310054 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 22029 289 24X Fiche 50-373, 84/01/18, B401310054

--B401310058 Forwards public version of revised Emergency Procedures LFP-1330-21, "Determination of Reactor Coolant Chloride Sampling Sys" & LFP-1330-25, "Sampling of Reactor Coolant at High Radiation Sample Sys" Receipt form encl
* Commonwealth Edison Co 83/12/23 Office of Nuclear Reactor Regulation, Director 1p 22029 290 24X Fiche 50-373, 84/01/18, B401310054

--B401310064 Public version of revised Emergency Procedures LFP-1330-21, "Determination of Reactor Coolant Chloride Sampling Sys" & LFP-1330-25, "Sampling of Reactor Coolant at High Radiation Sample Sys"
* Commonwealth Edison Co 83/11/21 55pp 22029 292 24X Fiche 50-373, 84/01/18, B401310054

B401260293 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21992 296 24X Fiche 50-373, 84/01/20, B401260293

--B401260297 Public version of Rev 3 to Emergency Plan Implementing Procedure LFP-1210-1, "Hazardous Matl Incidents Reporting"
LAWLESS, F Commonwealth Edison Co 83/12/29 12pp 21992 297 24X Fiche 50-373, 84/01/20, B401260293

G Adjudicatory correspondence

B401100466 Addendum to petition for emergency relief per 10CFR2 206 re integrated leak rate testing All documentation re integrated leak rate tests must be made public
OQQOL, E M Affiliation Unknown 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21761 286 24X Fiche 50-000, 84/01/06, B401100466

J. Insurance & indemnity information

B401060534 Unexecuted Amend 4 to Indemnity Agreement B-84
BALTZMAN, J Assistant Director for State & Licensee Relations 83/12/16 3pp, 21755 131 24X Fiche 50-373, 83/12/16, B401060534

B401190003 Forwards License NPF-1B, notice of issuance & Amend 4 to Indemnity Agreement B-84 Operation restricted to power levels not to exceed 5% of full power pending Commission approval W/o Suppl 7 to SER.
EISENHUT, D O Division of Licensing 83/12/16 FARRAR, D L Commonwealth Edison Co 3pp 21870 327 24X Fiche 50-374, 83/12/16, B401190003

B401090037 Requests change in annual indemnity fee for License NPF-1B Power level of 5% achieved.
DINITZ, I Assistant Director for State & Licensee Relations 83/12/30 PUGLIESE, A NRC - No Detailed Affiliation Given 1p 21757 282 24X Fiche 50-374, 83/12/30, B401090037

B401090504 Forwards Amend 4 to Indemnity Agreement B-84
OSTER, J Commonwealth Edison Co 84/01/03 BALTZMAN, J Assistant Director for State & Licensee Relations 2pp, 21750 340 24X Fiche 50-373, 84/01/03, B401090504

P Operating license stage documents & correspondence

B401190003 Forwards License NPF-1B, notice of issuance & Amend 4 to Indemnity Agreement B-84 Operation restricted to power levels not to exceed 5% of full power pending Commission approval W/o Suppl 7 to SER
EISENHUT, D O Division of Licensing 83/12/16 FARRAR, D L Commonwealth Edison Co 3pp 21870 327 24X Fiche: 50-374, 83/12/16, B401190003

--B401190004 License NPF-1B for facility.
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/16 16pp 21870 330 24X Fiche 50-374, 83/12/16, B401190003

DOCKETED ITEMS

--B401190005 Notice of issuance of License NPF-1B Authorization to operate beyond 5% full power will require specific Commission approval
SCHWENGER, A. Licensing Branch 2 83/12/16 3pp 21870 346 24X
Fiche 50-374, 83/12/16, B401190003

B401110165 Notification of B40104 meeting w/ Z Reytblatt in Bethesda, MD to discuss integrated leak rate testing
BOURNIA, A. Licensing Branch 2 83/12/27 SCHWENGER, A. Licensing Branch 2 3pp 21794 360 24X Fiche 50-373, 83/12/27, B401110163

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT, D. O. Division of Licensing. 84/01/06 Consolidated Edison Co. of New York, Inc. 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401170339 Responds to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators." Prelubrication w/ some warming provided, therefore, generators not subjected to cold starts
BARNES, P. L. Commonwealth Edison Co. 84/01/10 EISENHUT, D. O. Division of Licensing 1p 21829 341 24X Fiche 50-000, 84/01/10, B401170339

B401230288 Retransmits CW Schroeder 831201 ltr to MR Denton correcting typographical error re multiple failure concerns Potential radiological insult associated w/ special scenario event trivial w/ respect to 10CFR100 guidelines.
SCHROEDER, C. W. Commonwealth Edison Co. 84/01/11, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 21882 325 24X Fiche 50-373, 84/01/11, B401230288

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl.
EISENHUT, D. O. Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc. 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

11260200 Summary of B40104 meeting w/ Z Reytblatt of EXTRAN, Inc re available data base for 10CFR50, App J containment integrated leak tests at facility, per EM Regol 831129 petitions
SCHWENGER, A. Operating Reactors Branch 2 84/01/17 Operating Reactors Branch 2 5pp 21971 324, 24X Fiche 50-373, 84/01/17, 101260200

Inspection reports, IE Bulletins & correspondence

31060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR.
FELTON, J. M. Division of Rules and Records 83/10/20 ZAHNER, R. E. Shaw, Pittman, Potts & Trowbridge. 1p. 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

- B401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004. 24X Fiche 50-000, 83/10/20, B401060040.

1040333 Supply response to IE Bulletin 83-06 re nonconforming mats applied by Tube-Line Corp. Training held to emphasize review of purchase documents re receipt, insp & visual item verification per purchase order requirements
JARNES, P. L. Commonwealth Edison Co. 83/12/20, KEPPLER, J. Q. Region 3, Office of Director. 3pp, 21714:036. 24X Fiche 50-000, 83/12/20, B401040333

401040268 Ack receipt of 831214 ltr informing NRC of actions taken in response to 831128 confirmatory action ltr re ethylene-propylene soft seats on feedwater check valves Actions will be examined during future insp.
SPESBARD, R. L. Division of Engineering. 83/12/27 REED, C. Commonwealth Edison Co. 1p. 21701 333. 24X Fiche 50-373, 83/12/27, B401040268

-B401040278 Responds to 831128 confirmatory action ltr re ethylene-propylene soft seats on inboard 24-inch feedwater check valves, Actions A-D Fulfilled Current status on Action E provided.
SCHROEDER, C. W. Commonwealth Edison Co. 83/12/14, KEPPLER, J. Q. Region 3, Office of Director. 13pp, 21701:336. 24X Fiche: 50-373, 83/12/27, B401040268.

112120090 IE Bulletin 83-08, "Electrical Circuit Breakers / Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bys." Svc list encl.
JEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co. of New York, Inc. 24pp. 21731:166. 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401270359 Forwards IE Insp Repts 50-373/83-49 & 50-374/83-52 on 831118-1216 & notice of violation
SHAHER, W. D. Region 3, Office of Director 84/01/06 REED, C. Commonwealth Edison Co. 2pp 21975 325 24X Fiche 50-373, 84/01/06, B401270359

--B401270366 IE Insp Repts 50-373/83-49 & 50-374/83-52 on 831118-1216 Noncompliance noted failure to perform surveillance test, inadequate review of post-mod testing requirements & Tech Spec violations
GULDEMOND, W. O., GUTHRIE, B. C., EVANS, C. D. Region 3, Office of Director 84/01/04 22pp 21975 329 24X Fiche 50-373, 84/01/06, B401270359

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401230315 Ack receipt of 831222 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-50 & 50-374/83-53 Justification for restart of Unit 1 & continued operation through first cycle acceptable
NORELIUS, C. E. Division of Project & Resident Programs. 84/01/13 REED, C. Commonwealth Edison Co. 2pp 21883 151 24X
Fiche 50-373, 84/01/13, B401230315

B401230351 Ack receipt of B40109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-42 & 50-374/83-48
NORELIUS, C. E. Division of Project & Resident Programs. 84/01/13 REED, C. Commonwealth Edison Co. 1p 21884 253 24X
Fiche 50-373, 84/01/13, B401230351

--B401230372 Responds to NRC 831206 ltr re violations noted in IE Insp Repts 50-373/83-42 & 50-374/83-46 Corrective actions jumper authorized & installed on safety-related buses from Unit 2 undervoltage auxiliary transformer
FARRAR, D. L. Commonwealth Edison Co. 84/01/05 KEPPLER, J. Q. Region 3, Office of Director. 5pp 21884 254 24X
Fiche 50-373, 84/01/13, B401230391

B401300022 Forwards IE Insp Repts 50-373/83-51 & 50-374/83-50 on 831102-1215 & notice of violation.
STREETER, J. F. Region 3, Office of Director 84/01/13 REED, C. Commonwealth Edison Co. 2pp 21999 240 24X Fiche 50-373, 84/01/13, B401300022.

--B401300024 Notice of violation from insp on 831102-1215
STREETER, J. F. Region 3, Office of Director 84/01/13 1p 21999 242 24X Fiche 50-373, 84/01/13, B401300022

--B401300026 IE Insp Repts 50-373/83-51 & 50-374/83-50 on 831102-1215 Noncompliance noted failure to follow procedures during secondary containment integrity test
LANKSBURY, R. D., REYES, L. A., STREETER, J. F. Region 3, Office of Director 84/01/14 5pp 21999 243 24X Fiche 50-373, 84/01/13, B401300022

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp. 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B401230273 Ack receipt of B40103 ltr informing NRC of steps taken to correct open items noted in IE Insp Repts 50-373/83-46 & 50-374/83-39
STREETER, J. F. Region 3, Office of Director 84/01/16 REED, C. Commonwealth Edison Co. 1p 21884 285 24X Fiche 50-373, 84/01/16, B401230273

--B401230306 Responds to NRC 831116 ltr re open items noted in IE Insp Repts 50-373/83-46 & 50-374/83-39 Corrective actions, sys operational analysis dept test procedures will be enhanced to delineate min documentation requirements
FARRAR, D. L. Commonwealth Edison Co. 84/01/03 KEPPLER, J. Q. Region 3, Office of Director 4pp 21884 286 24X
Fiche, 50-373, 84/01/16, B401230273

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R. Periodic operating reports & related correspondence

8401090097 TECHNICAL SPECIFICATIONS FOR LASALLE COUNTY STATION, UNIT NO 2 Docket No 50-374 (Commonwealth Edison Company)
HOFFMAN, D R Division of Licensing NUREG-1013 83/12/31 484pp 21765 001 24X Fiche 50-374,83/12/31,8401090097

S Reportable occurrences, LERs & related correspondence

8401050413 Final deficiency rept re defective GE HMA relays Initially reported on 830805 Two relays found to have insufficient armature clearance Adjustments made
SCHROEDER, C W Commonwealth Edison Co 83/12/22 KEPLER, J O Region 3, Office of Director 1p 21731 046 24X Fiche 50-374,83/12/22,8401050413

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A. Application/construction stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X Fiche: 50-000,83/10/18,8401250015

--8204220376 Forwards info re sua sponta issue, whether addl primary sys depressurization capability should be added to plant design
MALBOCH, M O Office of the General Counsel SECY-82-160 82/04/19 80pp 21963 075 24X Fiche 50-000,83/10/18,8401250015

--8206300371 Discusses Carole Bernstein suit seeking injunction to enjoin NRC from considering granting OL to LAPL Motion planned to dismiss suit for lack of jurisdiction & finality failure to exhaust administrative remedies
SHULMAN, H J Office of the General Counsel SECY-82-263 82/06/24 2pp 21964 313 24X Fiche 50-000,83/10/18,8401250015

8401040252 Outlines procedures for reporting info promptly to region by using given telephone numbers for ofc & outside-of-ofc hours Util urged to use numbers
COLLINS, J T Region 4, Office of Director 83/12/19 LEDDICK, R S Louisiana Power & Light Co 2pp 21701 172 24X Fiche 50-382,83/12/19,8401040252

8401040210 Informs of redesign of component cooling water sys to cure concerns of Generic Ltr 83-10A re TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps" & of inadvertent safety injection actuation signal
COOK, K W Louisiana Power & Light Co 83/12/29 KNIGHTON, G W Licensing Branch 3 App 21701 217 24X Fiche 50-382,83/12/29,8401040210

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000,84/01/05,8312120108

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl.
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000,84/01/05,8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche: 50-000,84/01/06,8401090221

8401130326 Notification of 840117 significant licensee meeting in Arlington, TX to discuss matters re licensing of facility
* Region 4, Office of Director 84/01/06 Region 4, Office of Director 1p 21801 333 24X Fiche 50-382,84/01/06,8401130326

8401270551 Notification of 840117 meeting w/util, ERASCO & C-E in Bethesda, MD to discuss emergency feedwater sys control design
WILSON, J H Licensing Branch 3 84/01/09 KNIGHTON, G W Licensing Branch 3 3pp 22000 340 24X Fiche 50-382,84/01/09,8401270551

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000,84/01/13,8401130084

8401300082 Forwards request for clarification re response to NRC inquiry team rept on GA concerns Response required by 840215
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/16 CAIN, J M Louisiana Power & Light Co 5pp 22006 311 24X Fiche 50-382,84/01/16,8401300082

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANCON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000,84/01/17,8401270536

8401270041 Announces that R Denise will become Director, Div of Resident, Reactor Project & Engineering Programs, effective 840122
COLLINS, J T Region 4, Office of Director 84/01/23 LEDDICK, R S Louisiana Power & Light Co 1p 21982 020 24X Fiche 50-382,84/01/23,8401270041

8401270130 Notification of 840201 significant licensee meeting w/util in Arlington, TX to discuss matters re licensing
* Region 4, Office of Director 84/01/24 Region 4, Office of Director 1p 21982 045 24X Fiche 50-382,84/01/24,8401270130

E NRC Safety Evaluation Report (BER), supp's & correspondence

8401230421 Lists corrections to SSER 2, Section 22, Item II, B re capability for post-accident sampling On-line boron analysis provided
COOK, K W Louisiana Power & Light Co 84/01/18 KNIGHTON, G W Licensing Branch 3 1p 21880 347, 24X Fiche 50-382,84/01/18,8401230421

8401310325 Forwards description of various actions & procedural requirements used to implement commitment re scheduled maint program to monitor leakage & reduce detected leakage outside containment, per BER & NUREG-0737, Item III D 1 i.
COOK, K W Louisiana Power & Light Co 84/01/26 KNIGHTON, G W Licensing Branch 3 5pp 22020 329 24X Fiche 50-382,84/01/26,8401310325

r Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02, O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X Fiche: 50-000,83/11/02,8401250163

--8202020366 Forwards Central Files version of layout of interim emergency operations & backup facilities Communications & dose assessment capabilities for backup facility listed.
MAURIN, L V Louisiana Power & Light Co 82/01/28 TEDESCO, R L Assistant Director for Licensing 12pp 21958 241, 24X Fiche 50-000,83/11/02,8401250163

--8305260352 Urges discussion on licensee disregard for NRC guidance re location of permanent & backup emergency operations facilities, per W Dirks 821227 memo Requests explanation re Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners 83/01/06 Commissioners, 2pp 21958 001 24X Fiche: 50-000,83/11/02,8401250163

DOCKETED ITEMS

--B305260362 Responds to Commissioner Gilinsky B30106 comments on B21227 memo re implementation of emergency response facilities guidance Requested explanations re Waterford, San Onofre & Millstone plans provided
DIRCKS, W J Office of the Executive Director for Operations
B3/02/13 FALLADING, N Commissioners 2pp 21958 303 24X
Fiche 50-000, B3/11/02, B401250163

--B306210319 Requests Commission review of staff approval for exception to location of backup emergency operations facility beyond 20-mile limit
DIRCKS, W J Office of the Executive Director for Operations
BECY-B3-205 B3/09/26 8pp 21958 232 24X
Fiche 50-000, B3/11/02, B401250163

B401040631 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records B3/12/27 Document
Management Branch 1p 21714 321 24X Fiche 50-382, B3/12/27, B401040631

--B401040632 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-2-020 re contaminated injured/ill personnel, EP-2-032 re monitoring & decontamination & EP-2-081 re search & rescue
COOK, K W Louisiana Power & Light Co B3/10/24 Document
Management Branch 3pp 21714 322 24X Fiche 50-382, B3/12/27, B401040631

--B401040633 Public version of revised emergency plan implementing procedures, including Procedures EP-2-020 re contaminated injured/ill personnel, EP-2-032 re monitoring & decontamination & EP-2-081 re search & rescue
* Louisiana Power & Light Co B3/10/04 300pp 21714 325 24X
Fiche 50-382, B3/12/27, B401040631

B401270263 Forwards SALP Rept 50-382/B3-28 for Jul 1982 - June 1983
COLLINB, J T Region 4, Office of Director B4/01/04 LEDDICK, R B
Louisiana Power & Light Co 2pp 21980 044 24X
Fiche 50-382, B4/01/04, B401270263

--B401270282 SALP Rept 50-382/B3-28 for Jul 1982 - June 1983
CROSSMAN, W A, MADSEN, G L Region 4, Office of Director
B3/10/11 36pp 21980 048 24X Fiche 50-382, B4/01/04, B401270263

--B401270318 Forwards input to safeguards licensing portion of IE SALP review for Jul 1982 - June 1983
MCCORKLE, Q W Power Reactor Safeguards Licensing Branch
B3/08/02 BROWN, Q D Region 4, Office of Director 2pp
21980 089 24X Fiche 50-382, B4/01/04, B401270263

--B401270331 Forwards comments on SALP Rept 50-382/B3-28 for Jul 1982 - June 1983 Independent evaluation of concrete base mat conducted
LEDDICK, R B Louisiana Power & Light Co B3/11/18 JOHNSON, E
Region 4, Office of Director 27pp 21980 092 24X
Fiche 50-382, B4/01/04, B401270263

B401200046 Forwards Rev 3 to safeguards contingency plan Rev withheld
COOK, K W Louisiana Power & Light Co B4/01/12 Office of
Nuclear Reactor Regulation, Director 1p 21867 026 24X
Fiche 50-382, B4/01/12, B401200046

B401200303 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records B4/01/17 Document
Management Branch 1p 21889 183 24X Fiche 50-382, B4/01/17, B401200303

--B401200308 Public version of Rev 3 to emergency plan W/undated ltr
COOK, K W Louisiana Power & Light Co B4/01/11 Office of
Nuclear Reactor Regulation, Director 53pp 21889 186 24X
Fiche 50-382, B4/01/17, B401200303

B401300305 Requests review of encl safety info booklet Distribution to public scheduled for early Mar 1984 W/two oversize charts.
Aperture cards are available in PDR
COOK, K W Louisiana Power & Light Co B4/01/25 KNIGHTON, O W
Licensing Branch 3 3pp 21995 102 24X Fiche 50-382, B4/01/25, B401300305

3 Adjudicatory correspondence

101180227 Answer opposing Joint Intervenor's B31212 amended & supplemental motion to reopen Contention 22 & request for public hearing. Certificate of Svc encl.
CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw, Pittman, Potts & Toubridge B4/01/13 Atomic Safety and Licensing Appeal Panel 43pp 21842 290 24X Fiche 50-382, B4/01/13, B401180227

--B401180231 Affidavit of TF Gerrets re allegations of missing & phony QA documentation & forged signatures on safety insps
GERRETS, T F Louisiana Power & Light Co B4/01/12 3pp
21842 335 24X Fiche 50-382, B4/01/13, B401180227

B401250202 Motion for extension of time until B40224 to respond to Joint Intervenor's B31212 amended & supplemental motion to reopen Contention 22 Addl time needed to review Gambit magazine on const deficiencies W/Certificate of Svc
TURK, S E Hearing Branch 1 B4/01/17 Atomic Safety and Licensing Appeal Panel 7pp 21943 177 24X Fiche 50-382, B4/01/17, B401250202

B401200124 Order extending time until B40221 for Commission to act to review ALAB-753
CHILK, S J Office of the Secretary of the Commission B4/01/18 Commissioners 1p 21866 362 24X Fiche 50-382, B4/01/18, B401200124

B401200127 Order granting NRC motion for 5-wk extension in which to respond to Joint Intervenor's B31212 amended & supplemental motion to reopen Contention 22
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel B4/01/18 Office of the Executive Legal Director 2pp 21863 361 24X
Fiche 50-382, B4/01/18, B401200127

K Utility Final Safety Analysis Report (FSAR) & amends

B401180172 Forwards Amend 34 to FSAR consisting of revised Chapters 13, 14 & 17, reflecting changes in organization & policy & emergency feedwater sys Final amend to FSAR expected prior to post-OL update required by 10CFR50.71
LEDDICK, R B Louisiana Power & Light Co B4/01/13 Office of Nuclear Reactor Regulation, Director 6pp 21898 008 24X
Fiche 50-382, B4/01/13, B401180172

--B401180175 Amend 34 to FSAR
* Louisiana Power & Light Co B4/01/31 118pp 21898 014 24X
Fiche 50-382, B4/01/13, B401180172

B401230363 Certifies svc of updated Amend 34 to FSAR on B40117
EGAN, K Louisiana Power & Light Co B4/01/17 1p 21884 259 24X
Fiche 50-382, B4/01/17, B401230363

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E Shaw, Pittman, Potts & Toubridge 1p 21744 003 24X
Fiche 50-000, B3/10/20, B401060040

--B401060130 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401040145 Forwards FS Ints, Rept 50-382/B3-31 on B31031-1103 No noncompliance noted.
JOHNSON, E H Region 4, Office of Director B3/11/29 LEDDICK, R B Louisiana Power & Light Co 2pp 21702 040 24X
Fiche 50-382, B3/11/29, B401040145

--B401040152 IE Insp Rept 50-382/B3-31 on B31031-1103 No noncompliance noted Major areas inspected significant const deficiency repts
OILBERT, L D, JOHNSON, W B, CROSSMAN, W A Region 4, Office of Director B3/11/23 3pp 21702 042 24X Fiche 50-382, B3/11/29, B401040145

B401170256 Forwards QA Program Insp Rept 99900702/B3-03 for info & evaluation Ack requested W/o encl
JOHNSON, E H Region 4, Office of Director B3/11/29 LEDDICK, R B Louisiana Power & Light Co 1p 21832 121 24X
Fiche 50-382, B3/11/29, B401170256

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090

B312120093 IE Info Notice B3-B4, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B3103) B3/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

DOCKETED ITEMS

267

B401270263 Forwards SALP Rept 50-382/83-28 for Jul 1982 - June 1983
COLLINS, J T Region 4, Office of Director 84/01/04 LEDDICK, R S
Louisiana Power & Light Co 2pp 21980 044 24X
Fiche 50-382, 84/01/04, B401270263

--B401270276 Forwards SALP Rept 50-382/83-28 for Jul 1982 - June 1983
Comments due by 831107
MADSEN, G L Region 4, Office of Director 83/10/11 LEDDICK, R S
Louisiana Power & Light Co 2pp 21980 046 24X
Fiche 50-382, 84/01/04, B401270263

--B401270282 SALP Rept 50-382/83-28 for Jul 1982 - June 1983
CROSSMAN, W A, MADSEN, G L Region 4, Office of Director
83/10/11 36pp 21980 048 24X Fiche 50-382, 84/01/04, B401270263

--B401270318 Forwards input to safeguards licensing portion of IE SALP
review for Jul 1982 - June 1983
MCCORMACK, G W Power Reactor Safeguards Licensing Branch
83/08/02 BROWN, G D Region 4, Office of Director 2pp
21980 089 24X Fiche 50-382, 84/01/04, B401270263

--B401270327 Requests extension until 831117 to respond to SALP Rept
50-382/83-28 for Jul 1982 - June 1983
GERRETS, T F Louisiana Power & Light Co 83/10/31 JOHNSON, E
Region 4, Office of Director 1p 21980 091 24X
Fiche 50-382, 84/01/04, B401270263

--B401270331 Forwards comments on SALP Rept 50-382/83-28 for Jul 1982 -
June 1983 Independent evaluation of concrete base mat
conducted
LEDDICK, R S Louisiana Power & Light Co 83/11/18 JOHNSON, E
Region 4, Office of Director 27pp 21980 092 24X
Fiche 50-382, 84/01/04, B401270263

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

S Reportable occurrences, LERs & related correspondence

B401240505 Forwards supplemental rept to summary rept for QA
engineering task force review of installed structures/
components Info based on followup audit which revealed
deficient conditions
LEDDICK, R S Louisiana Power & Light Co 83/11/21 COLLINS, J T
Region 4, Office of Director 7pp 21920 069 24X
Fiche: 50-382, 83/11/21, B401240505

B401030067 Fifth interim significant const Deficiency Rept B1 re
exceeding shelf life on cable splice & termination tape
Supporting documentation & disposition of out of date matl
being verified Final rept will be submitted by 840113
GERRETS, T F Louisiana Power & Light Co 83/12/15 COLLINS, J T
Region 4, Office of Director 2pp 21683 206 24X
Fiche 50-382, 83/12/15, B401030067

B401030232 Second interim significant Const Deficiency Rept 92, "HPSI
Sys Performance " HPSI pump A stage channel rings 5,7 & 8
found out of spec & machined to within spec Next rept by
840201
GERRETS, T F Louisiana Power & Light Co 83/12/15 COLLINS, J T
Region 4, Office of Director 2pp 21682 336 24X
Fiche: 50-382, 83/12/15, B401030232

B401100282 Final rept of significant const Deficiency B1 re shelf life
exceeded on cable splice & termination tape Initially
reported on 831215 All warehoused Okonite tape & cement past
shelf life expiration date tagged for disposal
GERRETS, T F Louisiana Power & Light Co 83/12/20 COLLINS, J T
Region 4, Office of Director 3pp 21738 207 24X
Fiche 50-382, 83/12/20, B401100282

B401130247 Final significant const Deficiency Rept 71 re inadequate
review of condition identification & work authorization
forms for reportability QA procedures revised
GERRETS, T F Louisiana Power & Light Co 83/12/20 COLLINS, J T
Region 4, Office of Director 4pp 21800 322 24X
Fiche 50-382, 83/12/20, B401130247

B401100184 Final rept of potentially reportable Deficiency 130 re
possible loss of annulus vacuum control in shield bldg
ventilation sys motor operated valves Initially reported on
831115 Item not reportable under 10CFR50.55(e)
GERRETS, T F Louisiana Power & Light Co 83/12/21 COLLINS, J T
Region 4, Office of Director 2pp 21760 343 24X
Fiche 50-382, 83/12/21, B401100184

B401100266 Final rept of significant const Deficiency 77 re inadequate
containment purge valve closure time & flow rates Initially
reported on 831013 Second solenoid valve added to each
containment purge & vent valve
GERRETS, T F Louisiana Power & Light Co 83/12/21 COLLINS, J T
Region 4, Office of Director 3pp 21759 202 24X
Fiche 50-382, 83/12/21, B401100266

B401130282 Fifth interim rept re Significant Const Deficiency 78,
"American Bridge Structural Steel Deficiencies " Final rept
will be delayed until 840131 due to continuing verification
of supporting documentation
GERRETS, T F Louisiana Power & Light Co 83/12/23 COLLINS, J T
Region 4, Office of Director 2pp 21801 115 24X
Fiche 50-382, 83/12/23, B401130282

B401130316 Final significant const Deficiency Rept B9 re OE AK50/AK30
switchgear breakers camshaft bearings retaining rings OE
provided modified procedure Nonconformance Rept W3-6766
initiated to track deficiency
GERRETS, T F Louisiana Power & Light Co 84/01/03 COLLINS, J T
Region 4, Office of Director 3pp 21798 309 24X
Fiche 50-382, 84/01/03, B401130316

B401170199 Final significant const Deficiency Rept B2 re bent control
element assembly (CEA) rods All CEAs returned to C-E for
evaluation/repair Results of subsequent visual insp & drag
test acceptable
GERRETS, T F Louisiana Power & Light Co 84/01/05 COLLINS, J T
Region 4, Office of Director 3pp 21832 247 24X
Fiche 50-382, 84/01/05, B401170199

B401170201 Final significant const Deficiency Rept B4 re tube track
welding Welds identified as being deficient will perform
design function. No rework required
GERRETS, T F Louisiana Power & Light Co 84/01/05 COLLINS, J T
Region 4, Office of Director 3pp 21831 320 24X
Fiche 50-382, 84/01/05, B401170201

B401230223 First interim significant Deficiency Rept 95 re failure of
HPSI pumps to start Shaft bearings shimmed & binding
eliminated OE evaluating possible design deficiency Next
rept will be submitted by 840224
GERRETS, T F Louisiana Power & Light Co 84/01/05 COLLINS, J T
Region 4, Office of Director 3pp 21884 083 24X
Fiche 50-382, 84/01/05, B401230223

B401230348 Third interim significant const Deficiency Rept B3 re heat
tracing design defects identified during functional testing
Corrective action scheduled for completion in mid-Feb 1984.
Final rept will be submitted on 840302
GERRETS, T F Louisiana Power & Light Co 84/01/09 COLLINS, J T
Region 4, Office of Director 2pp 21882 358 24X
Fiche 50-382, 84/01/09, B401230348

B401240550 Final rept re Significant Const Deficiency 91 concerning OE
AKR-30/AKR-50 circuit breakers failing to close on command.
Initially reported on 831116 All potentially improperly heat
treated parts & defective switches replaced
GERRETS, T F Louisiana Power & Light Co 84/01/09 COLLINS, J T
Region 4, Office of Director 3pp 21920 038 24X
Fiche: 50-382, 84/01/09, B401240550.

B401230530 Final deficiency Rept 137 re controlled ventilation area
sys doors Deficiency did not involve inadequate or
unapproved matl. Incident not considered reportable per
10CFR50.55(e)
GERRETS, T F Louisiana Power & Light Co 84/01/10 COLLINS, J T
Region 4, Office of Director 2pp 21878 215 24X
Fiche 50-382, 84/01/10, B401230530

DOCKETED ITEMS

B401240094 First interim rept re Significant Const Deficiency 96, "Failure of Chemical & Vol Control Sys Pump Train A to Start on Safety Injection Activation Signal" Relays returned to Electro Switch Co. Next rept by B40302
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/11 COLLINS, J. T
 Region 4, Office of Director 3pp 21913 147 24X
 Fiche 50-382, 84/01/11, B401240094

B401240128 Final Deficiency Rept 136 re improper actuation of containment purge valves Initially reported on 831208 Further evaluation indicates condition not reportable per 10CFR50.55(e)
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/11 COLLINS, J. T
 Region 4, Office of Director 2pp 21913 182 24X
 Fiche 50-382, 84/01/11, B401240128

B401240453 Final Deficiency Rept 135 re reactor auxiliary bldg controlled ventilation area wiring Initially reported on 831207 Wiring corrected by test engineers & sys satisfactorily tested Control wiring diagrams updated
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/11 COLLINS, J. T
 Region 4, Office of Director 2pp 21908 169 24X
 Fiche 50-382, 84/01/11, B401240453

B401240469 Final Deficiency Rept 132 re diesel generator A lube oil sys Initially reported on 831205 Further evaluation indicates condition not reportable per 10CFR50.55(e).
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/11 COLLINS, J. T
 Region 4, Office of Director 2pp 21908 175 24X
 Fiche 50-382, 84/01/11, B401240469

B401270076 Third interim Deficiency Rept 80 re unsatisfactory stroking of emergency feedwater pump turbine steam shut-off valves Valves reinstalled, electrical svc being installed & testing scheduled for late Feb 1984 Next rept by B40309
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/16 COLLINS, J. T
 Region 4, Office of Director 2pp 21982 008 24X
 Fiche 50-382, 84/01/16, B401270076

B401270071 Sixth interim significant const Deficiency Rept 60 re turnover documentation & inadequate hanger weld problems Documentation review still in progress Final rept will be submitted on 840316
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/17 COLLINS, J. T
 Region 4, Office of Director 2pp 21982 006 24X
 Fiche 50-382, 84/01/17, B401270071

B401270500 Final Deficiency Rept PRD 139 re linear indications in reactor coolant pump support beams Initially reported on 831216 Condition erroneously identified Deficiency not reportable Under 10CFR50.55(e)
 GERRETS, T. F. Louisiana Power & Light Co. 84/01/17 COLLINS, J. T
 Region 4, Office of Director 2pp 21980 119 24X
 Fiche 50-382, 84/01/17, B401270500

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

NRC Safety Evaluation Report (SER), supp's & correspondence

1050266 Forwards 10CFR50.59 rept summarizing safety evaluations approved from 820717-1231. Rept format for responding to SER items described.
 KENYON, B. D. Pennsylvania Power & Light Co. 83/12/27 MURLEY, T. E.
 Region 1, Office of Director 132pp. 21727 001 24X
 Fiche 50-387, 83/12/27, B401050266

B401160215 Forwards portions of GE rept, "Seismic Qualification Reevaluation of Class IE Equipment, Susquehanna Steam Electric Station Units 1 & 2," addressing level switch dynamic qualification as referenced in BSER 3.
 CURTIS, N. W. Pennsylvania Power & Light Co. 84/01/10 SCHWENCER, A
 Licensing Branch 2 16pp 21808 316 24X Fiche 50-387, 84/01/10, B401160215

Security, medical, emergency & fire protection plans

81250389 Reviews scheduling info for detailed description of conformance to Reg Guide 1.87, Rev 2 re emergency response capability, submitted in response to Generic Ltr 82-33 Util provided explicit commitment except for items in encl.
 SCHWENCER, A. Licensing Branch 2 83/12/30 CURTIS, N. W.
 Pennsylvania Power & Light Co. 2pp. 21948 016 24X
 Fiche 50-387, 83/12/30, B401250389

--8312230302 "Conformance to Reg Guide 1.97, Susquehanna Steam Electric Station, Units 1 & 2."
 UDY, A. C. EQ&O, Inc. FIN A-6483. 83/09/30. NRC - No Detailed Affiliation Given. 11pp. 21948 018 24X Fiche 50-387, 83/12/30, B401250388

B401180251 Forwards 1E Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 & notice of violation, App A & B
 STAROBITECKI, R. Division of Project & Resident Programs 84/01/04
 KENYON, B. D. Pennsylvania Power & Light Co. 2pp 21843 342 24X
 Fiche 50-387, 84/01/04, B401180251

--B401180257 Notice of violation from insp on 831003-1106 Safeguards info deleted (ref 10CFR73 21)
 * Region 1, Office of Director 84/01/04 2pp 21843 344 24X
 Fiche 50-387, 84/01/04, B401180251

--B401180268 1E Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 Violations noted FSAR not updated at completion of Unit 1 const Required 31-day surveillance not performed on valve 157-014 Safeguards info deleted (ref 10CFR73 21)
 RHODAS, G. PLISCO, L. Region 1, Office of Director MCCABE, E. C.
 Division of Project & Resident Programs 83/11/18 18pp
 21843 346 24X Fiche 50-387, 84/01/04, B401180251

B401230418 Responds to Generic Ltr 82-33 re safety parameter display sys completion Difficulties encountered w/testing & installation of sys per Suppl 1 to NUREG-0737 Achieving 840131 operational date doubtful
 CURTIS, N. W. Pennsylvania Power & Light Co. 84/01/18 SCHWENCER, A
 Licensing Branch 2 2pp 21877 347 24X Fiche 50-387, 84/01/18, B401230418

B401250027 Releases public version of revised emergency plan implementing procedure
 FELTON, J. M. Division of Rules and Records 84/01/18 Document
 Management Branch 1p 21948 029 24X Fiche 50-387, 84/01/18, B401250027

--B401250031 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-015, "Emergency Access" W/831219 ltr & revised table of contents
 KEISER, H. Pennsylvania Power & Light Co. 83/12/18 SCHWENCER, A
 NRC - No Detailed Affiliation Given. 9pp 21948 030 24X
 Fiche 50-387, 84/01/18, B401250027

B401250035 Releases public version of revised emergency plan implementing procedure
 FELTON, J. M. Division of Rules and Records 84/01/18 Document
 Management Branch 1p 21947 332 24X Fiche 50-387, 84/01/18, B401250035

--B401250039 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-103, "Review, Update, Control & Distribution of Emergency Plan & Implementing Procedures" W/831111 ltr, receipt form & Rev 12 to index
 KEISER, H. Pennsylvania Power & Light Co. 83/11/11 SCHWENCER, A
 NRC - No Detailed Affiliation Given 28pp 21947 333 24X
 Fiche 50-387, 84/01/18, B401250035

B401260147 Releases public version of temporary change to emergency plan implementing procedure
 FELTON, J. M. Division of Rules and Records 84/01/18 Document
 Management Branch 1p 21959 351 24X Fiche 50-387, 84/01/18, B401260147

--B401260152 Public version of Temporary Change 1-83-1366 to Rev 2 to Emergency Plan Implementing Procedure EP-IP-007, "Personnel Assembly & Accountability" W/831109 transmittal & receipt form
 BOQUETTI, V. Pennsylvania Power & Light Co. 83/11/03 SCHWENCER, A
 NRC - No Detailed Affiliation Given 6pp 21959 352 24X
 Fiche 50-387, 84/01/18, B401260147

B401310111 Releases public version of revised emergency plan implementing procedure
 FELTON, J. M. Division of Rules and Records 84/01/18 Document
 Management Branch 1p 22028 069 24X Fiche 50-387, 84/01/18, B401310111

--B401310117 Public version of Rev 0 to Emergency Plan Implementing Procedure EP-IP-022, "Shift Turnover During Emergency" W/831220 ltr, receipt form & Rev 31 to table of contents
 KEISER, H. Pennsylvania Power & Light Co. 83/12/20 SCHWENCER, A
 NRC - No Detailed Affiliation Given 24pp 22028 070 24X
 Fiche 50-387, 84/01/18, B401310111

B401240631 Releases public version of revised emergency plan implementing procedures
 FELTON, J. M. Division of Rules and Records 84/01/20 Document
 Management Branch 1p 21944 251 24X Fiche 50-387, 84/01/20, B401240631

--B401240635 Public version of revised emergency plan implementing procedures, including Procedures EP-IP-047 re post-accident sampling sys (PASS) large liquid/dissolved gas sample & EP-IP-046 re PASS iodine/particulate sample
VNUK, L K, DEEBLER, R C Pennsylvania Power & Light Co 83/12/23
SCHWENCER, NRC - No Detailed Affiliation Given 82pp 21944 252
24X Fiche 50-387, 84/01/20, 8401240631

B401260407 Releases public version of revs to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 249 24X Fiche 50-387, 84/01/20,
8401260407

--B401260413 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EP-IP-034, "Reactor Bldg Sample Station Emergency Sampling" & Rev 2 to EP-IP-42, "In-Plant & Emergency Operations Preparation" Receipt form encl
* Pennsylvania Power & Light Co 84/01/06 SCHWENCER, A NRC -
No Detailed Affiliation Given 1p 21959 250 24X
Fiche 50-387, 84/01/20, 8401260407

--B401260422 Public version of Rev 3 to Emergency Plan Implementing Procedure EP-IP-034, "Reactor Bldg Sample Station Emergency Sampling," & Rev 2 to EP-IP-42, "In-Plant & Emergency Operations Facility Chemistry Lab Preparation"
* Pennsylvania Power & Light Co 84/01/06 26pp 21959:251
24X Fiche 50-387, 84/01/20, 8401260407

B401270301 Requests exemption from 10CFR50, App E requirement for state & local govt full offsite participation in emergency planning exercise
CURTIS, N W Pennsylvania Power & Light Co 84/01/23 SCHWENCER, A
Licensing Branch 2 1p 21975 333 24X Fiche 50-387, 84/01/23,
8401270301

H General correspondence

B401240141 Informs that WJ Stewart designated as sewage treatment plant operator & PA LeManager designated alternate in accordance w/Title 25, Chapter 305 2d(3) of PA code
FIELD, J S Pennsylvania Power & Light Co 84/01/12 KOVAL, P J
Pennsylvania, Commonwealth of, 1p 21910 287 24X
Fiche 50-387, 84/01/12, 8401240141

F. Operating license stage documents & correspondence

B401050266 Forwards 10CFR50 59 rept summarizing safety evaluations approved from 820717-1231 Rept format for responding to SER items described
KENYON, B D Pennsylvania Power & Light Co 83/12/27 MURLEY, T E
Region 1, Office of Director 132pp 21727 001 24X
Fiche 50-387, 83/12/27, 8401050266

B401050282 Informs that Susquehanna Riverlands Recreation Area potable water supply shut down for winter & will not reopen until late Mar or early Apr 1984 No bacteriological samples will be collected during Fourth Quarter 1983
FIELD, J S Pennsylvania Power & Light Co 83/12/29
WHITCRAFT, P K Environmental Protection Agency 2pp 21741 186
24X Fiche 50-387, 83/12/29, 8401050282

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

B401090396 Forwards application for Amend 36 to License NPF-14, changing Tech Spec 4 & 5.1 C to clarify surveillance procedures necessary for operation of standby gas treatment sys for three-zone & two-zone operation
CURTIS, N W Pennsylvania Power & Light Co 84/01/05 SCHWENCER, A
Licensing Branch 2 2pp 21750 314 24X Fiche 50-387, 84/01/05,
8401090396

--B401090407 Application for Amend 36 to License NPF-14 changing Tech Spec 4 & 5.1 C to clarify surveillance procedures necessary for operation of standby gas treatment sys
CURTIS, N W Pennsylvania Power & Light Co 84/01/05 1p
21750 316 24X Fiche 50-387, 84/01/05, 8401090396

--B401090417 Proposed Tech Spec re clarification of surveillance procedures necessary for operation of standby gas treatment sys
* Pennsylvania Power & Light Co 84/01/05, 3pp 21750 317 24X
Fiche 50-387, 84/01/05, 8401090396

B401100252 Informs that requested info re diesel generator cold starts, per Generic Ltr B3-41, inapplicable, since 125 F cooling water & 125 F lubricating oil circulate through diesels to increase reliability & prevent cold start damage
CURTIS, N W Pennsylvania Power & Light Co 84/01/05 EISENHUT, D G
Division of Licensing 1p 21759 224 24X Fiche 50-387, 84/01/05,
8401100252

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

B401160101 Discusses equipment qualification of Target Rock Corp solenoid valves Interim operation justified History, status of qualification & justification submitted Valve testing will be completed by 840531
CURTIS, N W Pennsylvania Power & Light Co 84/01/11 SCHWENCER, A
Licensing Branch 2 3pp 21815 210 24X Fiche 50-387, 84/01/11,
8401160101

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing, 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401240435 Supports BWR Owners Group B10921 final position on TMI Item 11 K 3 25 Byron Jackson pump seals adequate to meet suby item requirements Pump seal cooling water supply mode unnecessary
CURTIS, N W Pennsylvania Power & Light Co 84/01/19 SCHWENCER, A
Licensing Branch 2, 1p. 21915 242 24X Fiche 50-387, 84/01/19,
8401240435

B401250131 Rev 2 to application for Amend 36 to License NPF-14 re drawdown time for surveillance tests, deleting 30 s time delay in starting second steam generator fan
CURTIS, N W Pennsylvania Power & Light Co, 84/01/21 SCHWENCER, A
Licensing Branch 2 3pp 21936 189 24X Fiche 50-387, 84/01/21,
8401250131

--B401250132 Proposed Tech Spec changes re new drawdown time for surveillance tests, deleting 30 s time delay in starting second steam generator fan
* Pennsylvania Power & Light Co 84/01/21, 19pp 21936 192
24X Fiche 50-387, 84/01/21, 8401250131

B401310359 Endorses BWR Owners Group "Response to NRC Request for Addl Info on Scram Discharge Piping" Equipment qualification for NUREG-0803 not required, based on listed average dose levels for scram discharge vol over plant life
CURTIS, N W Pennsylvania Power & Light Co 84/01/27 SCHWENCER, A
Licensing Branch 2 1p. 22026 254 24X Fiche 50-387, 84/01/27,
8401310359

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records, 83/10/20 ZAHLER, R.E.
Shaw, Pittman, Potts & Trowbridge 1p 21744 003, 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060130 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004, 24X Fiche 50-000, 83/10/20,
8401060040

B401100227 Forwards IE Insp Rept 50-387/83-17 on 831017-21 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/12/22
KENYON, B D Pennsylvania Power & Light Co, 3pp 21759 228, 24X
Fiche 50-387, 83/12/22, 8401100227

--B401100233 Notice of violation from Insp on 831017-21
* Region 1, Office of Director 83/12/22, 1p. 21759 234 24X
Fiche 50-387, 83/12/22, 8401100227

--B401100241 IE Insp Rept 50-387/83-17 on 831017-21 Violation noted: during 830905-1019, weekly iodine samples of reactor bldg 779-ft elevation not taken
NIMITZ, R L, BARR, K, BICEHOUSE, H J. Region 1, Office of Director
83/12/19 14pp 21759 232 24X Fiche 50-387, 83/12/22,
8401100227

DOCKETED ITEMS

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731:166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826:060 24X Fiche 50-000, 83/12/30, B312120093

B401180251 Forwards IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 & notice of violation, App A & B STAROSTECKI, R. Division of Project & Resident Programs 84/01/04 KENYON, B. D. Pennsylvania Power & Light Co. 2pp 21843:342 24X Fiche: 50-387, 84/01/04, B401180251.

--B401180257 Notice of violation from insp on 831003-1106 Safeguards info deleted (ref 10CFR73 21)
* Region 1, Office of Director 84/01/04 2pp 21843:344 24X Fiche 50-387, 84/01/04, B401180251

--B401180268 IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 Violations noted: FSAR not updated at completion of Unit 1 const. Required 31-day surveillance not performed on valve 157-014. Safeguards info deleted (ref 10CFR73 21) RHOADS, Q., PLISCO, L. Region 1, Office of Director. MCCABE, E. C. Division of Project & Resident Programs 83/11/18 18pp 21843:346. 24X Fiche 50-387, 84/01/04, B401180251

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp 21746:053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826:184 24X Fiche 50-000, 84/01/10, B312120107

B401230163 Confirms plans for NRC B40120 site visit to review facility status & readiness for two-unit operation STAROSTECKI, R. Division of Project & Resident Programs. 84/01/13 KENYON, B. D. Pennsylvania Power & Light Co. 1p 21884:351 24X Fiche: 50-387, 84/01/13, B401230163.

B401260166 Forwards IE Enforcement Conference Rept 50-387/83-24 on 831213 No noncompliance noted. STAROSTECKI, R. Division of Project & Resident Programs 84/01/13. KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 21956:063 24X Fiche: 50-387, 84/01/13, B401260166.

B401260177 IE Enforcement Conference Rept 50-387/83-24 on 831213 No noncompliance noted Major areas discussed: events involving inoperability of both trains of main condenser offgas treatment sys/explosive gas monitoring sys. PLISCO, L. R. Region 1, Office of Director KELLY, E. M. Division of Project & Resident Programs 84/01/06. 12pp 21956:065. 24X Fiche: 50-387, 84/01/13, B401260166.

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21757:142 24X Fiche: 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18. Consolidated Edison Co. of New York, Inc. 118pp. 22000:001 24X Fiche: 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp. 22000:041. 24X Fiche 50-000, 84/01/18, B312120117

R. Periodic operating reports & related correspondence

B401120327 Monthly operating rept for Nov 1983, W/831215 ltr. KUCZYNSKI, L. A., KENYON, B. D. Pennsylvania Power & Light Co. 83/11/30. BEEBE, M. R. Management Information Branch 6pp. 21792:201. 24X Fiche: 50-387, 83/11/30, B401120327

B401060319 Forwards NPDES discharge monitoring rept for Nov 1983 Outfall discharge parameters summarized FIELDS, J. S. Pennsylvania Power & Light Co. 83/12/29 Pennsylvania, Commonwealth of. 1p 21742:337 24X Fiche 50-387, 83/12/29, B401060319

--B401060324 NPDES discharge monitoring rept for Nov 1983 KEISER, H. Pennsylvania Power & Light Co. 83/11/30 9pp 21742:338 24X Fiche 50-387, 83/12/29, B401060319

B401170291 Monthly operating rept for Dec 1983 W/840112 ltr KUCZYNSKI, L. A., KENYON, B. D. Pennsylvania Power & Light Co. 83/12/31 BEEBE, M. R. Division of Data Automation & Management Information 26pp 21832:301 24X Fiche 50-387, 83/12/31, B401170291

B401310346 "NPDES Monitoring Rept, Dec 1983" FIELDS, J. S. Pennsylvania Power & Light Co. 83/12/31 Pennsylvania, Commonwealth of. 11pp 22021:350 24X Fiche 50-387, 83/12/31, B401310346

B401170338 Drinking water monitoring rept for Dec 1983 FIELDS, J. S. Pennsylvania Power & Light Co. 84/01/10 Environmental Protection Agency 2pp 21829:339 24X Fiche 50-387, 84/01/10, B401170338

S Reportable occurrences, LERs & related correspondence

B401030202 Final deficiency & Part 21 repts re final design of OE 7700 Series 250-volt dc control ctrs Plant operating procedures revised to include methods of clearing obstructions as provided by OE & exam & reforming of draw out contacts CURTIS, N. W. Pennsylvania Power & Light Co. 83/12/03 MURLEY, T. E. Region 1, Office of Director 4pp 21683:087 24X Fiche 50-387, 83/12/03, B401030202

B401030184 LER 83-161/01P-0 on 831210, RCS temp allowed to increase to approx 150 F while in Operational Condition 5 (refueling) Condition corrected & temp maintained at 140 F KEISER, H. W. Pennsylvania Power & Light Co. 83/12/12 MURLEY, T. E. Region 1, Office of Director 1p 21681:320 24X Fiche 50-387, 83/12/12, B401030184

B401130258 LER 83-163/03L-0 on 831120, repeated emergency outside air intake high radiation alarms occurred contrary to Tech Specs Caused by failure of OM tube Tube replaced, calibr. retested & channel returned to svc W/831219 ltr WILKS, B. L., KEISER, H. W. Pennsylvania Power & Light Co. 83/12/19 MURLEY, T. E. Region 1, Office of Director 2pp 21800:337 24X Fiche: 50-387, 83/12/19, B401130258

B401130145 LER 83-160/03L-0 on 831121, while returning deuterium/oxygen analyzer to svc, drywell oxygen concentration determined 0.1% greater than Tech Spec 3.6 & 4.1 limit Caused by faulty indication from analyzer Investigation ongoing W/831221 ltr KUCZYNSKI, L. A., KEISER, H. W. Pennsylvania Power & Light Co. 83/12/21 MURLEY, T. E. Region 1, Office of Director 3pp 21802:233 24X Fiche 50-387, 83/12/21, B401130145

B401120260 LER 83-159/03L-0 on 831126, dual indication received when valve BV-15736A placed in closed position Caused by infrequent valve operation Cycling frequency will be increased if necessary W/831222 ltr WILKS, B. L., KEISER, H. W. Pennsylvania Power & Light Co. 83/12/22 MURLEY, T. E. Region 1, Office of Director 3pp 21794:156 24X Fiche 50-387, 83/12/22, B401120260.

B401120320 LER 83-164/01P-0 control rod drive inserted & lines withdrawn Clamps used to restrict movement of lines will require work to ensure motion restricted in three directions Fourteen-day followup rept forthcoming KEISER, H. W. Pennsylvania Power & Light Co. 83/12/22 MURLEY, T. E. Region 1, Office of Director 1p 21772:362 24X Fiche: 50-387, 83/12/22, B401120320

B401130279 LER 83-161/01T-0 on 831209, during refueling, RCS temp allowed to exceed 140 F Shutdown cooling sys operable & in svc Caused by flawed procedures Reactor coolant temp not recorded while in Operational Condition 5 W/831222 ltr TODD, J. T., KEISER, H. W. Pennsylvania Power & Light Co. 83/12/22. MURLEY, T. E. Region 1, Office of Director 3pp 21800:357 24X Fiche 50-387, 83/12/22, B401130279.

B401260221 LER 83-162/03L-0 on 831128, RHR B svc water motor operated valve HV11210B would not operate in open direction for suppression pool cooling Caused by failure of auxiliary contact in circuit breaker valves W/831228 ltr WILKS, B. L., KEISER, H. W. Pennsylvania Power & Light Co. 83/12/28 MURLEY, T. E. Region 1, Office of Director 2pp 21956:281. 24X Fiche: 50-387, 83/12/28, B401260221

8401260276 LER 83-166/03L-0 on 831229, during surveillance testing, LIS 14221D setpoint found to be out of calibr. Caused by setpoint drift LIS recalibr & limiting conditions for operation cleared in 1 h W/831229 ltr
WILKS, B L, KEISER, H W Pennsylvania Power & Light Co 83/12/29
MURLEY, T E Region 1, Office of Director 2pp 21953 134 24X
Fiche 50-387, 83/12/29, 8401260276

8401160155 LER 83-164/01T-0 on 831221, test results indicated 3-way clamps on control rod drive insert & withdrawal lines may be unable to withstand worst case axial waterhammer loads Addl testing considered W/840103 ltr
WILKS, B L, KEISER, H W Pennsylvania Power & Light Co 84/01/03
MURLEY, T E Region 1, Office of Director 2pp 21813 299 24X
Fiche 50-387, 84/01/03, 8401160155

8401270185 LER 83-168/03L-0 on 831209, alarms/indication/records for sample flow rate of standby gas treatment vent radiation monitor lost Caused by failed microprocessor Microprocessor replaced W/840106 ltr
WILKS, B L, KEISER, H W Pennsylvania Power & Light Co 84/01/06
MURLEY, T E Region 1, Office of Director 4pp 21982 087 24X
Fiche 50-387, 84/01/06, 8401270185

8401270335 LER 83-167/03L-0 on 831208, while performing 4 kV bus undervoltage channel calibr, loss of voltage relays associated w/engineered safeguard sys buses A & C had trip setpoints of 17 volts Settings adjusted W/840106 ltr
WILKS, B L, KEISER, H W Pennsylvania Power & Light Co 84/01/06
MURLEY, T E Region 1, Office of Director 3pp 21981 009 24X
Fiche 50-387, 84/01/06, 8401270335

8401270017 LER 83-169/03L-0 on 831213, shutdown cooling suction inboard & outboard isolation valves closed following loss of power to primary containment isolation sys (PCIS) Caused by unintentional actuation of PCIS W/840112 ltr
KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 84/01/12
MURLEY, T E Region 1, Office of Director 2pp 21982 021 24X
Fiche 50-387, 84/01/12, 8401270017

8401270128 LER 83-170/03L-0 on 831213, charcoal filters in train A of control room emergency outside air supply sys did not satisfy test specs during freon leak test Caused by insufficient charcoal in charcoal filter W/840112 ltr
WILKS, B L, KEISER, H W Pennsylvania Power & Light Co 84/01/12
MURLEY, T E Region 1, Office of Director 2pp 21982 043 24X
Fiche 50-387, 84/01/12, 8401270128

8401190347 PNO-I-84-004 on 840114, while performing monthly surveillance testing of emergency diesel generator D crankcase explosion occurred Event under investigation Piston & liner being replaced
PLISCO, L, MCCABE, E Region 1, Office of Director 84/01/16 1p.
21850 319 24X
Fiche 50-387, 84/01/16, 8401190347

8401270079 LER 83-171/03L-0 on 831217, both reactor water cleanup sys high dp channel calibr switches had as-found trip settings greater than Tech Spec requirements One switch out-of-calibr due to bellows failure Other switch recalibr W/840116 ltr
KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 84/01/16
MURLEY, T E Region 1, Office of Director 2pp 21982 010 24X
Fiche 50-387, 84/01/16, 8401270079

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

8401030144 Submits interim operation justification for equipment not qualified for scram discharge vol break environ. per NUREG-0803 Util endorses BWR Owners Group PRA, NEDO-22209
CURTIS, N W Pennsylvania Power & Light Co 83/12/27, SCHWENCER, A
Licensing Branch 2 4pp. 21682 273 24X
Fiche 50-388, 83/12/27, 8401030144

8401040142 Forwards test abstracts added to FSAR, Section 14.2, for review Info will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 83/12/29, SCHWENCER, A
Licensing Branch 2 17pp 21703 001 24X
Fiche 50-388, 83/12/29, 8401040142

8401060267 Submits updated info re spent cleaning & testing solution discharges into site erosion ponds After Mar 1984, discharges will go into station radwaste sys, eliminating possible radioactive contamination to environ
FIELEB, J S Pennsylvania Power & Light Co 83/12/29 KOVAL, P J
Pennsylvania, Commonwealth of, 4pp 21753 026 24X
Fiche 50-388, 83/12/29, 8401060267.

8401090511 Advises that qualification of all installed harsh environ Reg Guide 1.97 Category I or II equipment completed, per Util 831113 position Util approval of documentation complete, except for ex-core neutron monitoring sys
CURTIS, N W Pennsylvania Power & Light Co 83/12/30, SCHWENCER, A
Licensing Branch 2 2pp 21753 105 24X
Fiche 50-388, 83/12/30, 8401090511

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090367 Responds to NRC request for info re Target Rock solenoid valves & York/Relliance DX refrigeration unit Refrigeration unit water regulating valve will be replaced prior to fuel load W/updated component work sheets
CURTIS, N W Pennsylvania Power & Light Co 84/01/05, SCHWENCER, A
Licensing Branch 2 4pp 21754 046 24X
Fiche 50-388, 84/01/05, 8401090367

8401100252 Informs that requested info re diesel generator cold starts, per Generic Ltr 83-41, inapplicable, since 125 F cooling water & 125 F lubricating oil circulate through diesels to increase reliability & prevent cold start damage
CURTIS, N W Pennsylvania Power & Light Co 84/01/05, EISENHUT, D G
Division of Licensing 1p. 21759 224 24X
Fiche 50-387, 84/01/05, 8401100252

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221.

8401190216 Notification of Significant Licensee Meeting 84-07 on 840120 w/Util in Berwick, PA to discuss preparations for Unit 2 operation
PLISCO, L R Region 1, Office of Director 84/01/06, Region 1,
Office of Director 2pp 21870 230 24X
Fiche 50-388, 84/01/06, 8401190216

8401160101 Discusses equipment qualification of Target Rock Corp solenoid valves interm operation justified, history, status of qualification & justification submitted Valve testing will be completed by 840531
CURTIS, N W Pennsylvania Power & Light Co 84/01/11, SCHWENCER, A
Licensing Branch 2 3pp. 21815 210 24X
Fiche 50-387, 84/01/11, 8401160101

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp. 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084.

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANRAN, J Division of Licensing 84/01/17 Division of
Licensing 1p. 22000 349 24X
Fiche 50-000, 84/01/17, 8401270536

8401240435 Supports BWR Owners Group 810921 final position on TMI Item II K 3.25 Byron Jackson pump seals adequate to meet subj item requirements Pump seal cooling water supply mode unnecessary
CURTIS, N W Pennsylvania Power & Light Co 84/01/19, SCHWENCER, A
Licensing Branch 2 1p 21913 242 24X
Fiche 50-387, 84/01/19, 8401240435

8401300217 Forwards revised FSAR Section 14.2 Revs will be incorporated in next FSAR amend
CURTIS, N W Pennsylvania Power & Light Co 84/01/25, SCHWENCER, A
Licensing Branch 2 8pp 21995 302 24X
Fiche 50-388, 84/01/25, 8401300217

8401310359 Endorses BWR Owners Group "Response to NRC Request for Addl Info on Scram Discharge Piping" Equipment qualification for NUREG-0803 not required, based on listed average dose levels for scram discharge vol over plant life
CURTIS, N W Pennsylvania Power & Light Co 84/01/27, SCHWENCER, A
Licensing Branch 2 1p 22026 254 24X
Fiche 50-387, 84/01/27, 8401310359.

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), supp's & correspondence

8401160215 Forwards portions of GE rept. "Seismic Qualification Reevaluation of Class IE Equipment, Susquehanna Steam Electric Station Units 1 & 2," addressing level switch dynamic qualification as referenced in SSER 3
CURTIS, N.W. Pennsylvania Power & Light Co. 84/01/10 SCHWENCER, A
Licensing Branch 2 16pp. 21808 316 24X Fiche 50-387, 84/01/10.
8401160215

F Security, medical, emergency & fire protection plans

8401250388 Reviews scheduling info for detailed description of conformance to Reg Guide 1.87, Rev 2 re emergency response capability, submitted in response to Generic Ltr 82-33 Util provided explicit commitment except for items in encl
SCHWENCER, A. Licensing Branch 2 83/12/30. CURTIS, N.W.
Pennsylvania Power & Light Co. 2pp 21948 016 24X
Fiche 50-387, 83/12/30, 8401250388

--84012230302 "Conformance to Reg Guide 1.97, Susquehanna Steam Electric Station, Units 1 & 2"
UDY, A.C. EQ&O, Inc. FIN A-64B3 83/09/30 NRC - No Detailed Affiliation Given 11pp. 21948 018. 24X Fiche 50-387, 83/12/30, 8401250388

8401180251 Forwards IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 & notice of violation, App A & B
STAROSTECKI, R. Division of Project & Resident Programs 84/01/04
KENYON, B.D. Pennsylvania Power & Light Co. 2pp 21843 342. 24X
Fiche 50-387, 84/01/04, 8401180251

--8401180268 IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106
Violations noted. FSAR not updated at completion of Unit 1
const Required 31-day surveillance not performed on valve
157-014 Safeguards info deleted (ref 10CFR73.21)
RHOADS, O. Region 1, Office of Director 83/11/18 18pp
21843 346. 24X Fiche 50-387, 84/01/04, 8401180251

8401230418 Responds to Generic Ltr 82-33 re safety parameter display sys completion. Difficulties encountered w/testing & installation of sys per Suppl 1 to NUREG-0737 Achieving
840131 operational data doubtful
CURTIS, N.W. Pennsylvania Power & Light Co. 84/01/18. SCHWENCER, A
Licensing Branch 2 2pp 21877 347 24X Fiche 50-387, 84/01/18,
8401230418

8401250027 Releases public version of revised emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records 84/01/18 Document
Management Branch 1p 21948 029. 24X Fiche 50-387, 84/01/18,
8401250027

--8401250031 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-015, "Emergency Access" W/831219 1tr & revised table of contents
KEISER, H. Pennsylvania Power & Light Co. 83/12/18 SCHWENCER, A
NRC - No Detailed Affiliation Given 9pp. 21948 030. 24X
Fiche 50-387, 84/01/18, 8401250027

8401250035 Releases public version of revised emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records. 84/01/18 Document
Management Branch 1p 21947 332 24X Fiche 50-387, 84/01/18,
8401250035.

--8401250039 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-103, "Review, Update, Control & Distribution of Emergency Plan & Implementing Procedures" W/831111 1tr, receipt form & Rev 12 to index
KEISER, H. Pennsylvania Power & Light Co. 83/11/11 SCHWENCER, A
NRC - No Detailed Affiliation Given 28pp 21947 333. 24X
Fiche 50-387, 84/01/18, 8401250035.

8401260147 Releases public version of temporary change to emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records. 84/01/18. Document
Management Branch. 1p. 21939 351. 24X Fiche 50-387, 84/01/18,
8401260147

--8401260152 Public version of Temporary Change 1-83-1366 to Rev 2 to Emergency Plan Implementing Procedure EP-IP-007, "Personnel Assembly & Accountability" W/831109 transmittal & receipt form.
BOGGETT, V. Pennsylvania Power & Light Co. 83/11/03 SCHWENCER, A
NRC - No Detailed Affiliation Given. 6pp. 21959 352. 24X
Fiche 50-387, 84/01/18, 8401260147.

8401310111 Releases public version of revised emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records 84/01/18 Document
Management Branch 1p 22028 069 24X Fiche 50-387, 84/01/18,
8401310111

--8401310117 Public version of Rev 0 to Emergency Plan Implementing Procedure EP-IP-022, "Shift Turnover During Emergency" W/831220 1tr, receipt form & Rev 31 to table of contents
KEISER, H. Pennsylvania Power & Light Co. 83/12/20 SCHWENCER, A
NRC - No Detailed Affiliation Given 24pp 22028 070 24X
Fiche 50-387, 84/01/18, 8401310111

8401240631 Releases public version of revised emergency plan implementing procedures
FELTON, J.M. Division of Rules and Records 84/01/20 Document
Management Branch 1p 21944 251 24X Fiche 50-387, 84/01/20,
8401240631

--8401240635 Public version of revised emergency plan implementing procedures, including Procedures EP-IP-047 re post-accident sampling sys (PASS) large liquid/dissolved gas sample & EP-IP-046 re PASS iodine/particulate sample
VNUK, L.K., DOEBLER, R.C. Pennsylvania Power & Light Co. 83/12/23
SCHWENCER, NRC - No Detailed Affiliation Given 82pp 21944 252
24X Fiche 50-387, 84/01/20, 8401240631

8401260407 Releases public version of revs to emergency plan implementing procedures
FELTON, J.M. Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 249 24X Fiche 50-387, 84/01/20,
8401260407

--8401260413 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EP-IP-034, "Reactor Bldg Sample Station Emergency Sampling" & Rev 2 to EP-IP-42, "In-Plant & Emergency Operations Preparation" Receipt form encl
* Pennsylvania Power & Light Co. 84/01/06 SCHWENCER, A NRC -
No Detailed Affiliation Given 1p 21959 250 24X
Fiche 50-387, 84/01/20, 8401260407

--8401260422 Public version of Rev 3 to Emergency Plan Implementing Procedure EP-IP-034, "Reactor Bldg Sample Station Emergency Sampling" & Rev 2 to EP-IP-42, "In-Plant & Emergency Operations Facility Chemistry Lab Preparation"
* Pennsylvania Power & Light Co. 84/01/06 26pp 21959 251
24X Fiche 50-387, 84/01/20, 8401260407

8401270301 Requests exemption from 10CFR50, App E requirement for state & local govt full offsite participation in emergency planning exercise
CURTIS, N.W. Pennsylvania Power & Light Co. 84/01/23 SCHWENCER, A
Licensing Branch 2 1p 21975 353 24X Fiche 50-387, 84/01/23,
8401270301

H General correspondence

8401240141 Informs that WJ Stewart designated as sewage treatment plant operator & PA LeHenger designated alternate in accordance w/Title 25, Chapter 305 2d(3) of PA code
FIELDS, J.S. Pennsylvania Power & Light Co. 84/01/12 KOVAL, P.J.
Pennsylvania, Commonwealth of, 1p 21910 287 24X
Fiche 50-387, 84/01/12, 8401240141

P Operating license stage documents & correspondence

8401060282 Informs that Susquehanna Riverlands Recreation Area potable water supply shut down for winter & will not reopen until late Mar or early Apr 1984 No bacteriological samples will be collected during Fourth Quarter 1983
FIELDS, J.S. Pennsylvania Power & Light Co. 83/12/29
WHITCRAFT, P.K. Environmental Protection Agency 2pp 21741 186
24X Fiche 50-387, 83/12/29, 8401060282

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J.M. Division of Rules and Records 83/10/20 ZAHNER, R.E.
Shaw, Pittman, Potts & Trowbridge 1p. 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp. 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

DOCKETED ITEMS

273

8401100376 Forwards IE Insp Rept 50-388/83-29 on 831128-1201 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
KENYON, B D Pennsylvania Power & Light Co 2pp 21763 117 24X
Fiche 50-388, 83/12/23, 8401100376

--8401100387 IE Insp Rept 50-388/83-29 on 831128-1201 No violations noted Major areas inspected status of outstanding items
NARROW, L J, DURR, J P Region 1, Office of Director 83/12/23
5pp 21763 117 24X Fiche 50-388, 83/12/23, 8401100376

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401180251 Forwards IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 & notice of violation, App A & B
STAROSTECKI, R Division of Project & Resident Programs 84/01/04
KENYON, B D Pennsylvania Power & Light Co 2pp 21843 342 24X
Fiche 50-387, 84/01/04, 8401180251

--8401180268 IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1106 Violations noted FSAR not updated at completion of Unit 1 const Required 31-day surveillance not performed on valve 157-014 Safeguards info deleted (ref 10CFR73.21)
RHODAS, G J, PLISCO, L Region 1, Office of Director MCCABE, E C Division of Project & Resident Programs 83/11/18 18pp 21843 346 24X Fiche 50-387, 84/01/04, 8401180251

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 093 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401230163 Confirms plans for NRC 840120 site visit to review facility status & readiness for two-unit operation
STAROSTECKI, R Division of Project & Resident Programs 84/01/13
KENYON, B D Pennsylvania Power & Light Co 1p 21884 351 24X
Fiche: 50-387, 84/01/13, 8401230163

8401260196 Forwards IE Insp Rept 50-388/83-18 on 831004-27 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/13
KENYON, B D Pennsylvania Power & Light Co 2pp 21956 143 24X
Fiche: 50-388, 84/01/13, 8401260196

--8401260204 IE Insp Rept 50-388/83-18 on 831004-07, 17-21 & 25-27 No noncompliance noted Major areas inspected test program implementation, test procedure review & verification & test results evaluation & witnessing
NICHOLAS, H H, BETTENHAUSEN, L Region 1, Office of Director 83/12/20 15pp 21956 143 24X Fiche: 50-388, 84/01/13, 8401260196.

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401060319 Forwards NPDES discharge monitoring rept for Nov 1983
Outfall discharge parameters summarized
FIELDB, J S Pennsylvania Power & Light Co 83/12/29
Pennsylvania, Commonwealth of, 1p 21742 337 24X
Fiche 50-387, 83/12/29, 8401060319

--8401060324 NPDES discharge monitoring rept for Nov 1983
KEISER, H Pennsylvania Power & Light Co. 83/11/30 9pp
21742 338 24X Fiche 50-387, 83/12/29, 8401060319

8401310346 "NPDES Monitoring Rept, Dec 1983 "
FIELDB, J S Pennsylvania Power & Light Co 83/12/31
Pennsylvania, Commonwealth of, 11pp 22021 350 24X
Fiche 50-387, 83/12/31, 8401310346

8401170338 Drinking water monitoring rept for Dec 1983
FIELDB, J S Pennsylvania Power & Light Co 84/01/10
Environmental Protection Agency 2pp 21829 339 24X
Fiche 50-387, 84/01/10, 8401170338

S Reportable occurrences, LERs & related correspondence

8401260323 Interim deficiency rept re improper relief valve settings & design pressures & temps found in HPCI, RCIC, RHR, core spray & essential svc water sys Initially reported on 831118. Hydrotests performed Also reported per Part 21
CURTIS, N W Pennsylvania Power & Light Co 83/12/20. MURLEY, T E Region 1, Office of Director 9pp 21955 198 24X
Fiche 50-388, 83/12/20, 8401260323

8401160151 Final deficiency rept re cracks in Pacific Scientific PBA-1 & PBA-3 snubber capstan springs. Caused by improper spring forming. Snubbers will be corrected prior to completion of first refueling outage Also reported per Part 21
CURTIS, N W Pennsylvania Power & Light Co 83/12/27 MURLEY, T E Region 1, Office of Director, 5pp 21815 327 24X
Fiche 50-388, 83/12/27, 8401160151

8401160165 Interim deficiency rept re electrical sys separation in multiple div pull & junction boxes One box identified containing redundant channel C & D circuits insufficiently separated by approved barrier
CURTIS, N W Pennsylvania Power & Light Co 83/12/27 MURLEY, T E Region 1, Office of Director, 3pp 21815 003 24X
Fiche 50-388, 83/12/27, 8401160165

8401160094 Interim deficiency rept re Bechtel failure to accomplish design verification of safety-related power & control cables Bechtel completed & documented required cable length verification & calculations
CURTIS, N W Pennsylvania Power & Light Co. 83/12/30. MURLEY, T E Region 1, Office of Director, 5pp 21815 200 24X
Fiche 50-388, 83/12/30, 8401160094.

8401160158 Final deficiency rept re isolation of nitrogen makeup sys Permanent mod consists of rerouting drywell & wetwell nitrogen makeup lines to spare penetrations Divisionalized isolation valves will be installed
CURTIS, N W Pennsylvania Power & Light Co. 83/12/30 MURLEY, T E Region 1, Office of Director 4pp 21815 272 24X
Fiche 50-388, 83/12/30, 8401160158

8401270210 Final deficiency rept re standby gas treatment sys (SGTS) performance not as described in FSAR FSAR change prepared to indicate SGTS may be required to maintain secondary containment integrity
CURTIS, N W Pennsylvania Power & Light Co 84/01/09 MURLEY, T E Region 1, Office of Director 6pp 21979 142 24X
Fiche: 50-388, 84/01/09, 8401270210

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8401190168 Notification of review of 821221 submittal re habitability & location of emergency operations facility Facility complies w/requirements of Table 1 of Suppl 1 to NUREG-0737
MILLER, J R Operating Reactors Branch 3, 83/12/15. WILLIAMS, J W Florida Power & Light Co 2pp 21861 362 24X
Fiche 50-335, 83/12/15, 8401190168

8401060439 Confirms 831212 telcon request to observe federal field exercise at facilities. Primary assignment will be to observe medical drill Handwritten rept to be submitted prior to leaving site
HUFFMAN, G N Region 2, Office of Director. 83/12/21. RICKS, R C Oak Ridge National Laboratory, 1p 21740.088 24X
Fiche: 50-335, 83/12/21, 8401060439

DOCKETED ITEMS

8401040538 Forwards Rev 2 to fire hazard analysis
WILLIAMS, J W Florida Power & Light Co 83/12/27 EISENHUT, D G
Division of Licensing 1p 21714 039 24X Fiche 50-389, 83/12/27,
8401040538

--8401040543 Rev 2 to fire hazards analysis W/10 oversize drawings
Aperture cards are available in PDR
* Florida Power & Light Co 83/12/27 62pp 21714 040 24X
Fiche: 50-389, 83/12/27, 8401040538

8401060014 Releases public version of revised administrative procedures
indices
FELTON, J M. Division of Rules and Records. 83/12/28 Document
Management Branch 1p 21755 290. 24X Fiche 50-335, 83/12/28,
8401060014

--8401060020 Forwards public version of revised administrative procedures
indices, including chemistry procedures index, general maint
procedures index, health physics reporting procedures index
& offnormal/emergency operating index.
KOLZOWSKI, O Florida Power & Light Co 83/11/17 Director's
Office, Office of Inspection and Enforcement 1p 21755:291 24X
Fiche 50-335, 83/12/28, 8401060014

--8401060025 Public version of revised administrative procedures indices,
including chemistry procedures index, general maint
procedures index, health physics reporting procedures index
& offnormal/emergency operating procedures index
* Florida Power & Light Co 83/11/30 27pp. 21755.292 24X
Fiche 50-335, 83/12/28, 8401060014

8401260135 Releases public version of revised emergency plan
implementing procedures.
FELTON, J M Division of Rules and Records. 84/01/18 Document
Management Branch 1p 21982 313 24X Fiche 50-389, 84/01/18,
8401260135.

--8401260140 Forwards public version of revised Emergency Plan
Implementing Procedures 2-0250031, "Boron Concentration
Control Offnormal" & 2-0410030, "HPBI - Offnormal
Operation."
WETHY, C M Florida Power & Light Co. 83/11/07. Director's
Office, Office of Inspection and Enforcement 1p 21982 314. 24X
Fiche 50-389, 84/01/18, 8401260135.

--8401260145 Public version of revised Emergency Plan Implementing
Procedures 2-0250031, "Boron Concentration Control
Offnormal" & 2-0410030, "HPBI - Offnormal Operation."
WETHY, C M Florida Power & Light Co 83/11/03 12pp 21982 315
24X Fiche. 50-389, 84/01/18, 8401260135

8401260260 Releases public version of revised emergency plan
implementing procedure.
FELTON, J M. Division of Rules and Records. 84/01/20 Document
Management Branch. 1p 21990.344 24X Fiche. 50-000, 84/01/20,
8401260260

8401260265 Public version of revised Emergency Plan Implementing
Procedure 1301, "Emergency Roster - Offsite Emergency
Organization" W/831229 ltr
WILLIAMS, J W Florida Power & Light Co 83/12/15 O'REILLY, J P
Region 2, Office of Director 1pp 21990.345 24X
Fiche: 50-000, 84/01/20, 8401260260

01310060 Releases public version of revised emergency plan offnormal
& emergency operating procedures
FELTON, J M Division of Rules and Records. 84/01/20 Document
Management Branch. 1p. 22035 072 24X Fiche 50-389, 84/01/20,
8401310060

--8401310069 Forwards public version of Rev 7 to Emergency Operating
Procedure 2-0030141 re control room inaccessibility & Rev 1
to Offnormal Operating Procedure 2-1560030 re primary water
sys.
WETHY, C M. Florida Power & Light Co 83/12/14. Director's
Office, Office of Inspection and Enforcement. 1p. 22035 073. 24X
Fiche. 50-389, 84/01/20, 8401310060

8401310080 Public version of Rev 7 to Emergency Operating Procedure
2-0030141 re control room inaccessibility & Rev 1 to
Offnormal Operating Procedure 2-1560030 re primary water
sys.
* Florida Power & Light Co. 83/12/13 46pp. 22035:075 24X
Fiche: 50-389, 84/01/20, 8401310060

101300373 Releases public version of revised offnormal & emergency
operating procedures.
FELTON, J M Division of Rules and Records. 84/01/25 Document
Management Branch 1p. 22003:206. 24X Fiche: 50-389, 84/01/25,
101300373

--8401300379 Forwards public version of revised offnormal & emergency
operating procedures, including Procedures 2-2100030 re oil
spill emergencies, 2-0120035 re pressurizer pressure & level
& 2-0120032 re excessive RCS activity
WETHY, C M Florida Power & Light Co 84/01/13 Director's
Office, Office of Inspection and Enforcement 2pp 22003 207
24X Fiche 50-389, 84/01/25, 8401300373

--8401300383 Public version of revised offnormal & emergency operating
procedures, including Procedures 2-2100030 re oil spill
emergencies, 2-0120035 re pressurizer pressure & level &
2-0120032 re excessive RCS activity
KOLZOWSKI, O Florida Power & Light Co 84/01/06 131pp
22003 209 24X Fiche 50-389, 84/01/25, 8401300373

O Advisory Committee on Reactor Safeguards reports & correspondence

8401160392 Summary of ACRS Subcommittee on St Lucie 2 811030-31
meetings in West Palm Beach, FL re review of OL application
* ACRS - Advisory Committee on Reactor Safeguards 81/12/16
ACRS - Advisory Committee on Reactor Safeguards 20pp 21823 317
24X Fiche. 50-389, 81/12/16, 8401160392

P Operating license stage documents & correspondence

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946:190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 16pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0733, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G. Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401200158 Forwards license amend fees, per 840110 ltr
WILLIAMS, J W Florida Power & Light Co 84/01/16 EISENHUT, D G
Division of Licensing 1p 21866 158 24X Fiche 50-335, 84/01/16,
8401200158

8401240088 Advises that diesel generators do not undergo type of fast
cold starts discussed in Generic Ltr 83-41 because of
prelubrication of turbocharger bearings & brief idle period
prior to loading Dec 1982 - Nov 1983 quick starts listed
WILLIAMS, J W Florida Power & Light Co 84/01/17 EISENHUT, D G
Division of Licensing 2pp. 21912.352 24X Fiche 50-335, 84/01/17,
8401240088

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records. 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge. 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040.

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744.004 24X Fiche 50-000, 83/10/20,
8401060040

8401060431 Forwards BALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33
& 50-389/83-61 for Jul 1982 - June 1983
O'REILLY, J P Region 2, Office of Director 83/12/15,
WILLIAMS, J W Florida Power & Light Co 3pp 21740 001 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060442 Forwards BALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 &
50-389/83-61 for period Jul 1982 - June 1983
LEWIS, R C. Division of Project & Resident Programs. 83/10/14
UHRIG, R E Florida Power & Light Co 2pp 21740 004 24X
Fiche 50-000, 83/12/15, 8401060431

--8401060452 BALP Repts 50-250/83-33, 50-251/83-33, 50-335/83-33 &
50-389/83-61 for period Jul 1982 - June 1983
* Region 2, Office of Director 83/10/14 49pp 21740.006 24X
Fiche. 50-000, 83/12/15, 8401060431.

DOCKETED ITEMS

275

8401090208 Forwards IE Insp Repts 50-335/83-38 & 50-389/83-66 on 83121-23 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/15
WILLIAMS, J W Florida Power & Light Co 2pp 21754 013 24X
Fiche 50-335, 83/12/15, 8401090208

--8401090244 IE Insp Repts 50-335/83-38 & 50-389/83-66 on 83121-23 No violations noted Major areas inspected pipe support baseplates (IE Bulletin 79-02) & designs using concrete expansion anchors (IE Bulletin 79-14)
AND, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/12/12 6pp 21754 015 24X
Fiche 50-335, 83/12/15, 8401090208

8401090246 Forwards IE Insp Repts 50-335/83-40 & 50-389/83-69 on 83128-1202 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/15
WILLIAMS, J W Florida Power & Light Co 2pp 21754 021 24X
Fiche 50-335, 83/12/15, 8401090246

--8401090252 IE Insp Repts 50-335/83-40 & 50-389/83-69 on 83128-1202 No violations noted Major areas inspected health physics organization & personnel qualifications, training, exposure controls, posting, labeling & control of radioactive matl
WRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/12/14 7pp 21754 023 24X
Fiche 50-335, 83/12/15, 8401090246

8401050218 Reviews 83123 response to 831019 notice of deviation in IE Insp Rept 50-389/83-57 Deviations will be reevaluated during 840104-06 insp
LEWIS, R C Division of Project & Resident Programs 83/12/19
WILLIAMS, J W Florida Power & Light Co 1p 21728 184 24X
Fiche: 50-389, 83/12/19, 8401050218

8401240438 Forwards IE Insp Repts 50-335/83-35 & 50-389/83-63 on 831011-1110 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/22
WILLIAMS, J W Florida Power & Light Co 2pp 21919 332 24X
Fiche: 50-335, 83/12/22, 8401240438

--8401240447 IE Insp Repts 50-335/83-35 & 50-389/83-63 on 831011-1110 No violations noted Major areas inspected maint & surveillance observation, plant operations, IE bulletins & circulars & LERs
ELROD, S A Division of Project & Resident Programs BIRB, H E Region 2, Office of Director 83/12/22 6pp 21919 334 24X
Fiche 50-335, 83/12/22, 8401240438

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 12pp 21731 166 24X
Fiche 50-000, 83/12/28, 8312120090

8401050377 Ack receipt of 831202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-29 & 50-389/83-56
DANCE, H C Division of Project & Resident Programs 83/12/28
WILLIAMS, J W Florida Power & Light Co 1p 21731 019 24X
Fiche 50-335, 83/12/28, 8401050377

--8401050384 Responds to NRC 831104 ltr re violations noted in IE Insp Repts 50-335/83-29 & 50-389/83-56 Corrective actions 1983 requalification program revised to include refresher training on Procedure AP 0010122, "In-Plant Equipment
WILLIAMS, J W Florida Power & Light Co 83/12/02 O'REILLY, J P Region 2, Office of Director 2pp 21731 020 24X
Fiche 50-335, 83/12/28, 8401050377

--8401050387 Forwards IE Insp Repts 50-335/83-29 & 50-389/83-56 on 830811-0910 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/11/02
WILLIAMS, J W Florida Power & Light Co 2pp 21731 022 24X
Fiche: 50-335, 83/12/28, 8401050377

--8401050389 Notice of violation from insp on 830811-0910
* Region 2, Office of Director 83/11/02. 2pp 21731.024. 24X
Fiche: 50-335, 83/12/28, 8401050377

--8401050394 IE Insp Repts 50-335/83-29 & 50-389/83-56 on 830811-0910 Violation noted failure to implement operational safety verification procedures re valves V-2145 & V-2155
ELROD, S A, BIRB, H E Region 2, Office of Director LANDIS, K. Division of Project & Resident Programs 83/11/03 7pp. 21731 026 24X
Fiche 50-335, 83/12/28, 8401050377

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 12pp 21826 060 24X
Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X
Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X
Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X
Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X
Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041. 24X
Fiche 50-000, 84/01/18, 8312120117

R Periodic operating reports & related correspondence

8401120363 Monthly operating repts for Nov 1983 W/831215 ltr.
GRANT, N W Florida Power & Light Co 83/11/30. Division of Data Automation & Management Information 17pp 21791 330 24X
Fiche 50-000, 83/11/30, 8401120363

8401270459 Monthly operating repts for Dec 1983 W/840116 ltr.
GRANT, N W Florida Power & Light Co 83/12/31 Office of Resource Management, Director 17pp 21980 026 24X
Fiche 50-000, 83/12/31, 8401270459

S Reportable occurrences, LERs & related correspondence

8401050064 FOIA request for 27 listed LERs.
GRABER, L D NUS Corp 83/10/07 Division of Rules and Records. 2pp. 21736.343 24X
Fiche: 50-000, 83/10/07, 8401050064

8401030072 LER 83-074/03L-0 on 831123, during normal full-power operation, both plant data processing computer & backup failed Cause of first computer failure unknown. Backup computer failed due to program error W/831222 ltr
WEST, D., WILLIAMS, J W Florida Power & Light Co 83/12/22 O'REILLY, J P Region 2, Office of Director. 2pp 21683 199. 24X
Fiche 50-389, 83/12/22, 8401030072

8401040420 LER 83-075/03L-0, on 831124, while at 100% power, fire doors found open Doors open primarily during const Continuous fire patrol instituted W/831227 ltr
MC LAUGHLIN, L., WILLIAMS, J W Florida Power & Light Co 83/12/27 O'REILLY, J P Region 2, Office of Director 2pp 21706 207 24X
Fiche 50-389, 83/12/27, 8401040420

8401120326 LER 83-076/03L-0 on 831202, while at 100% power, fire detection sys failed for 3 h Caused by defective transceiver card Honeywell card replaced W/840103 ltr
MC LAUGHLIN, L., WILLIAMS, J W Florida Power & Light Co. 84/01/03 O'REILLY, J P Region 2, Office of Director. 2pp. 21792.141. 24X
Fiche 50-389, 84/01/03, 8401120326

8401260094 LER 83-077/03L-0 on 831221, diesel generator 2D failed to start within 10 s & fuel oil day tank failed to automatically fill above 30% level Cause for slow start not determined Tank holding relay module replaced W/840120 ltr
MC LAUGHLIN, L., WILLIAMS, J W Florida Power & Light Co 84/01/20 O'REILLY, J P Region 2, Office of Director 2pp 21957 019 24X
Fiche: 50-389, 84/01/20, 8401260094.

8401300292 PNO-IX-84-005, on 840125, special emergency drill temporarily suspended due to discovery of plastic bottle at radiation control point exterior to vital areas, w/handwritten label, "Danger Nitroglycerine." Event determined to be hoax
TOBIN, W. J., MCGUIRE, D R Region 2, Office of Director 84/01/25 2pp 21795.357. 24X
Fiche 50-389, 84/01/25, 8401300292

DOCKETED ITEMS

V Operator Examinations

B401060457 Informs that in order to meet schedule for B40213 operator & senior operator licensing written & oral exams, ref matl from approved list in Encl 1 must be received by B40106 W/O encl 1
DANCE, H C Division of Project & Resident Programs 83/12/15
UHRIO, R E. Florida Power & Light Co 2pp 21740 203 24X
Fiche 50-335, 83/12/15, B401060457

B401190398 Requests extension of 4 months of annual exam requirement for 1983 for operator requalification, per 10CFR55, App A
Delay in preparing program due to commitment to initial startup activities for Unit 2
WILLIAMS, J W Florida Power & Light Co 84/01/10 EISENHUT, D G
Division of Licensing 2pp 21850 189 24X Fiche 50-335, 84/01/10,
B401190398

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1A Application/construction stage documents & correspondence

B401090432 Responds to 831028 request for addl info re NUREG-0737, Item II F 2, concerning installation & preoperational testing of reactor vessel level instrumentation sys (RVLIS) RVLIS will be installed & tested prior to fuel load
MILLS, L M Tennessee Valley Authority 84/01/04 ADENSAM, E
Licensing Branch 4 12pp 21750 302 24X Fiche 50-390, 84/01/04,
B401090432

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401100299 Advises that safety-related mechanical equipment environ qualification evaluation will be submitted on B40305
Submittal will include evaluation results, summary of corrective actions & justification for interim operation
MILLS, L M Tennessee Valley Authority 84/01/05 ADENSAM, E
Licensing Branch 4 1p 21738 158 24X Fiche 50-390, 84/01/05,
B401100299

B401100882 Forwards addl info in response to Generic Ltr B3-10C re automatic trip of reactor coolant pumps Westinghouse Owners Group expects to submit generic rept justifying manual reactor coolant pump trip by B40301
MILLS, L M Tennessee Valley Authority 84/01/05 ADENSAM, E
Licensing Branch 4 2pp 21772 238 24X Fiche 50-390, 84/01/05,
B401100882

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21937 267 24X
Fiche 50-000, 84/01/06, B401090221

B401160413 Summary of 831220 meeting w/util in Bethesda, MD re exemption request from NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation"
KENYON, T J Licensing Branch 4 84/01/09 Licensing Branch 4
9pp 21821 254 24X Fiche 50-390, 84/01/09, B401160413

B401170224 Forwards addl info in support of util position on compliance to QDC-51, per 831028 request NUREG-0577 NDT (+57F) statistically generated bounding valve based on 90% confidence.
MILLS, L M Tennessee Valley Authority 84/01/09 ADENSAM, E
Licensing Branch 4 9pp 21833 314 24X Fiche 50-390, 84/01/09,
B401170224

B401170252 Forwards addl info clarifying items 1 b, 2, a, 2 b, 2 c, 5, 9, 11, 21 & 22 of equipment qualification program
MILLS, L M Tennessee Valley Authority 84/01/11, ADENSAM, E
Licensing Branch 4. 104pp 21832 001. 24X Fiche 50-390, 84/01/11,
B401170252

B401180262 Forwards justification for not providing intermittent prelubrication of upper portions of diesel engines, in response to NRC informal question on 831202
MILLS, L M Tennessee Valley Authority 84/01/12, ADENSAM, E
Licensing Branch 4. 2pp 21843, 325 24X Fiche 50-390, 84/01/12,
B401180262

B401190307 Forwards util response to NRC & Corps of Engineers concerns re slope stability, amended FBAR matl which reflects remedial action & rept entitled "Site-Specific Top-of-Ground Motion for ERCW Pipeline W/Response to NRC Staff Concerns"
KAMMER, D S Tennessee Valley Authority 84/01/12 ADENSAM, E
Licensing Branch 4 62pp 21851 084 24X Fiche 50-390, 84/01/12,
B401190307

--B401190309 "Site-Specific Top-of-Ground Motion for ERCW Pipeline W/Response to NRC Staff Concerns"
* Woodward-Clyde Consultants, Inc 83/09/23 113pp 21851 147
24X Fiche 50-390, 84/01/12, B401190309

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401200083 Forwards addl info on equipment qualification program, per B40110 telcon Info consists of lists of Class C equipment & of equipment inside containment subjected to post-LOCA submergence & verification of 1 h time margin
MILLS, L M Tennessee Valley Authority 84/01/17 ADENSAM, E
Licensing Branch 4 45pp 21863 309 24X Fiche 50-390, 84/01/17,
B401200083

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profiles for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing
1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401270088 Informs that expected fuel load dates for facilities delayed due to insufficient net hanger installation rate needed to support preoperational testing Fuel load expected by B40401 for Unit 1 & 831201 for Unit 2
MILLS, L M Tennessee Valley Authority 84/01/23 ADENSAM, E
Licensing Branch 4 1p 21982 012 24X Fiche 50-390, 84/01/23,
B401270088

B401310017 Forwards request for exemption to install high-range noble gas monitors on auxiliary bldg vent as required by NUREG-0737, Item II F 1 Provisions for initiating isolation & measuring release meet intent of NUREG-0737
MILLS, L M Tennessee Valley Authority 84/01/24 ADENSAM, E
Licensing Branch 4 8pp 22024 037 24X Fiche 50-390, 84/01/24,
B401310017

E NRC Safety Evaluation Report (SER), supplis & correspondence

B401170332 Forwards updated status rept of SER, App D items concerning control room mods, per 831108 commitment
MILLS, L M Tennessee Valley Authority 84/01/10 ADENSAM, E
Licensing Branch 4 8pp 21829 331 24X Fiche 50-390, 84/01/10,
B401170332

B401240258 Forwards util understanding of Power Sys Branch SER item status resulting from 831027 & 1101 telcons, util statement & NRC actions resulting from telcons & statement of compliance w/License Conditions 13 through 17
MILLS, L M Tennessee Valley Authority 84/01/17 ADENSAM, E
Licensing Branch 4 17pp 21910 010 24X Fiche 50-390, 84/01/17,
B401240258

F Security, medical, emergency & fire protection plans

B401090498 Forwards IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/12
PARRIS, H G Tennessee Valley Authority 2pp 21753 117 24X
Fiche 50-390, 83/12/12, B401090498

--B401090502 IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted Major areas inspected const fire protection GA program.
MILLER, W H. Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/12/07 2pp 21753 119
24X Fiche 50-390, 83/12/12, B401090498

B401110048 Forwards supplemental response to Suppl 1 to NUREG-0737 (Generic Ltr B2-33) re safety parameter display sys. Implementation approval not required prior to Unit 1 fuel load date.
MILLS, L M Tennessee Valley Authority 84/01/05 ADENSAM, E
Licensing Branch 4 9pp 21772 229 24X Fiche 50-390, 84/01/05,
B401110048

8401240317 Ack receipt of 831209 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-390/B2-29 & 50-391/B2-26 Rev to Procedure WDN-QC1 1 39 will require documentation of independent verification insps
LEWIS, R C Division of Project & Resident Programs 84/01/05
PARRIS, H O Tennessee Valley Authority 2pp 21932 130 24X
Fiche 50-390, 84/01/05, 8401240317

--8401240323 Suppl response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/B2-29 & 50-391/B2-26 Corrective actions
Fire protection QA program drawings will be reviewed & deficiencies corrected through drawing revs
HILLS, L M Tennessee Valley Authority 83/12/09 O'REILLY, J P
Region 2, Office of Director 33pp 21932 132 24X
Fiche 50-390, 84/01/05, 8401240317

8401160111 Forwards list of oversize drawings showing vital area designations List withheld (ref 10CFR73 21)
HILLS, L M Tennessee Valley Authority 84/01/09 ADENBAM, E
Licensing Branch 4 1p 21821 213 24X Fiche 50-390, 84/01/09,
8401160111

8401170332 Forwards updated status rept of SER, App D items concerning control room mods, per 831108 commitment
HILLS, L M Tennessee Valley Authority 84/01/10 ADENBAM, E
Licensing Branch 4 8pp 21829 331 24X Fiche 50-390, 84/01/10,
8401170332

8401170303 Notifies of current status of milestone schedule for prompt notification sys Fixed sirens installed Deficiencies identified currently being corrected Mobile siren routes identified Sys expected to be operational by 840401
KAHMER, D S Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 1p 21833 215 24X Fiche 50-390, 84/01/12,
8401170303

8401180156 Forwards revised "TVA Compliance W/App A to Branch Technical Position 9 5-1, 'Guidelines for Fire Protection for Nuclear Power Plants Docketed Prior to 740701 "' Rev result of recent TVA review of fire protection program
HILLS, L M Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 1p 21840 233 24X Fiche 50-390, 84/01/12,
8401180156

--8401180164 Revised "TVA Compliance W/App A to Branch Technical Position 9 5-1, 'Guidelines for Fire Protection for Nuclear Power Plants Docketed Prior to 740701 "'
* Tennessee Valley Authority 84/01/12 72pp 21840 234 24X
Fiche 50-390, 84/01/12, 8401180156

8401250121 Forwards comments on security plan re designation of vital equipment Response required within 30 days of receipt of ltr Comments withheld (ref 10CFR73 21)
PARRIS, H O Tennessee Valley Authority 84/01/13 ADENBAM, E
Licensing Branch 4 1p 21936 210 24X Fiche 50-390, 84/01/13,
8401250121

8401250319 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document
Management Branch 1p 21957 325 24X Fiche 50-390, 84/01/18,
8401250319

--8401250321 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure IP-6, "Activation of Technical Support Ctr" & Rev 1 to IP-10, "Medical Emergency Procedure"
HILLS, L M Tennessee Valley Authority 83/11/14 O'REILLY, J P
Region 2, Office of Director 1p 21957 326 24X
Fiche 50-390, 84/01/18, 8401250319

--8401250324 Public version of Rev 2 to Emergency Plan Implementing Procedure IP-6, "Activation of Technical Support Ctr" & Rev 1 to IP-10, "Medical Emergency Procedure"
MCERSCHELL, R P, DELK, W S, JONES, M K Tennessee Valley Authority 83/11/07 30pp 21957 328 24X Fiche 50-390, 84/01/18,
8401250319

8401240268 Informs that listed mods to fire alarm & detection circuits will be completed by 840402 for Unit 1 & 850401 for Unit 2, per NRC 830831 ltr
HILLS, L M Tennessee Valley Authority 84/01/19, ADENBAM, E
Licensing Branch 4 1p 21920 239 24X Fiche 50-390, 84/01/19,
8401240268

8401250110 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21959 077 24X Fiche 50-000, 84/01/20,
8401250110

--8401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure MSEC IP-6, "Emergency Preparedness" & DMPEC-IP-7, "Procedure for Performance of Assessment Team Function"
HILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21959 080
24X Fiche 50-000, 84/01/20, 8401250110

--8401250126 Public version of revised emergency plan implementing procedures, including Procedures MSEC IP-6, "Emergency Preparedness" & DMPEC-IP-7, "Procedure for Performance of Assessment Team Function"
MAXWELL, R B Tennessee Valley Authority 83/11/10 34pp 21959 081 24X Fiche 50-000, 84/01/20, 8401250110

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II
KAHMER, D S Tennessee Valley Authority 84/01/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21865:001 24X
Fiche 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I
PARRIS, H O Tennessee Valley Authority 84/01/12 75pp 21865 002 24X Fiche 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II
PARRIS, H O Tennessee Valley Authority 84/01/12 96pp 21865 077 24X Fiche 50-000, 84/01/12, 8401200194

K Utility Final Safety Analysis Report (FSAR) & amends

8401110130 Forwards Amend 49 to FSAR
HILLS, L M Tennessee Valley Authority 84/01/06 ADENBAM, E
Licensing Branch 4 1p 21773 001 24X Fiche 50-390, 84/01/06,
8401110130

--8401110132 Amend 49 to FSAR
* Tennessee Valley Authority 84/01/06 591pp 21773 002 24X
Fiche 50-390, 84/01/06, 8401110130

8401300304 Forwards suppl to FSAR Amend 49, containing pages inadvertently omitted during printing
KAHMER, D S Tennessee Valley Authority 84/01/26 ADENBAM, E
Licensing Branch 4 1p 21996 341 24X Fiche 50-390, 84/01/26,
8401300304

--8401300307 Supplemental pages to Amend 49 to FSAR
* Tennessee Valley Authority 84/01/26 4pp 21996 342 24X
Fiche 50-390, 84/01/26, 8401300304

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

8401090498 Forwards IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/12 PARRIS, H O Tennessee Valley Authority 2pp 21753 117 24X
Fiche 50-390, 83/12/12, 8401090498

--8401090502 IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted Major areas inspected const fire protection QA program
MILLER, W H Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/12/07 2pp 21753:119 24X Fiche 50-390, 83/12/12, 8401090498

8401090478 Forwards IE Insp Repts 50-390/83-48 & 50-391/83-37 on 831024-1126 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/16 PARRIS, H O Tennessee Valley Authority 2pp 21753 139 24X
Fiche 50-390, 83/12/16, 8401090478

DOCKETED ITEMS

- B401090480 IE Insp Repts 50-390/83-48 & 50-391/83-37 on 831024-1126 No violations noted Major areas inspected inspector open items. Independent insp effort, review of licensee identified items & soil liquefaction barrier installation
SHAW, W B , HOLLAND, W E Region 2, Office of Director JULIAN, C A
Division of Project & Resident Programs 83/12/15 17pp
21753 141 24X Fiche 50-390, 83/12/16, 8401090478
- B401090103 Forwards IE Insp Repts 50-390/83-50 & 50-391/83-39 on 831128-1202 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/20
PARRIS, H G Tennessee Valley Authority 2pp 21753 197 24X
Fiche 50-390, 83/12/20, 8401090103
- B401090109 IE Insp Repts 50-390/83-50 & 50-391/83-39 on 831128-1202 No violations noted Major areas inspected preoperational test witnessing, preoperational test results review & followup on previously identified findings
THOMAS, M Region 2, Office of Director JAFFE, F Division of Engineering & Operational Programs 83/12/20 App 21753 199
24X Fiche 50-390, 83/12/20, 8401090103
- B401050515 Ack receipt of 830705 & 0824 ltrs informing NRC of steps taken to correct violations in IE Insp Repts 50-390/83-14 & 50-391/83-10 Violation noted in IE Insp Rept 50-390/83-14 rescinded following careful consideration
LEWIS, R C Division of Project & Resident Programs 83/12/21
PARRIS, H G Tennessee Valley Authority 1p 21725 321 24X
Fiche 50-390, 83/12/21, 8401050515
- B401050523 Responds to NRC 830601 ltr re violations noted in IE Insp Repts 50-390/83-14 & 50-391/83-10 Response suppls 830705 ltr Violation in IE Insp Rept 50-390/83-14 re personnel correctly performing QC insp denied
MILLS, L M Tennessee Valley Authority 83/08/24 O'REILLY, J P
Region 2, Office of Director 3pp 21725 322 24X
Fiche 50-390, 83/12/21, 8401050515
- B401050529 Responds to NRC 830601 ltr re violations noted in IE Insp Repts 50-390/83-14 & 50-391/83-10 Violation in IE Insp Rept 50-390/83-14 denied & support 1068-1-68-336 reworked per IE Bulletin 79-14
MILLS, L M Tennessee Valley Authority 83/07/05 O'REILLY, J P
Region 2, Office of Director 3pp 21725 325 24X
Fiche 50-390, 83/12/21, 8401050515
- B401050537 Forwards IE Insp Repts 50-390/83-14 & 50-391/83-14 on 830426-29 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/06/01
PARRIS, H G Tennessee Valley Authority 2pp 21725 330 24X
Fiche 50-390, 83/12/21, 8401050515
- B401050541 Notice of violation from insp on 830426-29
* Region 2, Office of Director 83/06/01 1p 21725 332 24X
Fiche 50-390, 83/12/21, 8401050515
- B401050546 IE Insp Repts 50-390/83-14 & 50-391/83-10 on 830426-29. Violation noted failure to follow valve installation & hanger weld insp procedures, per IE Bulletin 79-14
LIU, W C Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/03/23 7pp 21725 333
24X Fiche 50-390, 83/12/21, 8401050515
- B401050571 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-41 & 50-391/83-30
VERRELLI, D M Division of Project & Resident Programs 83/12/21
PARRIS, H G Tennessee Valley Authority 1p 21726 147 24X
Fiche 50-390, 83/12/21, 8401050571
- B401050582 Responds to NRC 831020 ltr re violations noted in IE Insp Repts 50-390/83-41 & 50-391/83-30 Corrective actions documentation corrected to indicate correct proctor curves & Procedure WBNP-QCP-2 01 will be revised by 840201
MILLS, L M Tennessee Valley Authority 83/12/06, O'REILLY, J P
Region 2, Office of Director App 21726 148 24X
Fiche 50-390, 83/12/21, 8401050571
- B401050587 Forwards IE Insp Repts 50-390/83-41 & 50-391/83-30 on 830927-30 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/10/20
PARRIS, H G Tennessee Valley Authority 2pp 21726 152 24X
Fiche 50-390, 83/12/21, 8401050571
- B401050596 Notice of violation from insp on 830927-30
* Region 2, Office of Director 83/10/20 2pp 21726 154 24X
Fiche 50-390, 83/12/21, 8401050571
- B401050610 IE Insp Repts 50-390/83-41 & 50-391/83-30 on 830927-30 Violations noted failure to follow QC instructions on earthfill testing for underground barriers for potential soil liquefaction
HARRIS, J R Region 2, Office of Director CONLON, T E Division of Project & Resident Programs 83/10/17 3pp 21726 156 24X
Fiche 50-390, 83/12/21, 8401050571
- B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- B401060441 Ack receipt of 831110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-35 & 50-391/83-24
LEWIS, R C Division of Project & Resident Programs 83/12/29
PARRIS, H G Tennessee Valley Authority 1p 21740 091 24X
Fiche 50-390, 83/12/29, 8401060441
- B401060445 Responds to NRC 831014 ltr re violations noted in IE Insp Repts 50-390/83-35 & 50-391/83-24 Corrective actions undersize weld on hanger 1003B-1-03B-3 repaired to comply w/current drawing requirements
MILLS, L M Tennessee Valley Authority 83/11/10 O'REILLY, J P
Region 2, Office of Director 2pp 21740 092 24X
Fiche 50-390, 83/12/29, 8401060441
- B401060448 Forwards IE Insp Repts 50-390/83-35 & 50-391/83-24 on 830912-16 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/14
PARRIS, H G Tennessee Valley Authority 2pp 21740 093 24X
Fiche 50-390, 83/12/29, 8401060441
- B401060470 Notice of violation from insp on 830912-16
* Region 2, Office of Director 83/10/14 1p 21740 097 24X
Fiche 50-390, 83/12/29, 8401060441
- B401060478 IE Insp Repts 50-390/83-35 & 50-391/83-24 on 830912-16 Noncompliance noted QC inspectors failed to detect undersize weld, lack of double nuts on pipe clamps & wrong size base plates & concrete anchor on hangers
ANG, W P., LIU, W C, YORK, J W Region 2, Office of Director
83/10/06 10pp 21740 098 24X Fiche 50-390, 83/12/29, 8401060441
- B401060449 Ack receipt of 830726 & 0817 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-17 & 50-391/83-13
LEWIS, R C Division of Project & Resident Programs 83/12/29
PARRIS, H G Tennessee Valley Authority 1p 21740 335 24X
Fiche 50-390, 83/12/29, 8401060449
- B401060453 Revises 830726 response to NRC 830627 ltr re violations noted in IE Insp Repts 50-390/83-17 & 50-391/83-13 Support 2072-72-QCS-R10 inadvertently listed as 2072-72-R19 in corrective actions dtd 830726
MILLS, L M Tennessee Valley Authority 83/08/17 O'REILLY, J P
Region 2, Office of Director 1p 21740 336 24X
Fiche 50-390, 83/12/29, 8401060449
- B401060455 Responds to 830627 ltr re violations noted in IE Insp Repts 50-390/83-17 & 50-391/83-13 Corrective actions, shock arrester to accommodate pipe thermal movement & stiffener plate oversized weld & orientation deficiencies documented
KAMMER, D S Tennessee Valley Authority 83/07/26 O'REILLY, J P
Region 2, Office of Director App 21740 337 24X
Fiche 50-390, 83/12/29, 8401060449
- B401060458 Forwards IE Insp Repts 50-390/83-17 & 50-391/83-13 on 830523-26 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/06/27
PARRIS, H G Tennessee Valley Authority 2pp 21740 341 24X
Fiche 50-390, 83/12/29, 8401060449
- B401060462 IE Insp Repts 50-390/83-17 & 50-391/83-13 on 830523-26 Noncompliance noted: failure to follow procedure on hanger/snubber insp & to follow fabrication & insp procedures for hanger/snubber installation
LIU, W C Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/06/22 6pp 21740 343
24X Fiche 50-390, 83/12/29, 8401060449
- B401060460 Notice of violation from insp on 830523-26
* Region 2, Office of Director 83/06/27 2pp 21740 343 24X
Fiche 50-390, 83/12/29, 8401060449
- B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

DOCKETED ITEMS

279

8401240524 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-46 & 50-391/83-35 Implementation of corrective actions will be examined during future insps
LEWIS, R C Division of Project & Resident Programs 84/01/04
PARRIS, H G Tennessee Valley Authority 1p 21918 143 24X
Fiche 50-390, 84/01/04, 8401240524

--8401240536 Responds to NRC 831122 ltr re violations noted in IE Insp Repts 50-390/83-46 & 50-391/83-35 Corrective actions future entries into primary side of steam generators will be monitored by const personnel
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21918 144 24X
Fiche 50-390, 84/01/04, 8401240524

--8401240541 Forwards IE Insp Repts 50-390/83-46 & 50-391/83-35 on 830926-1022 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/22
PARRIS, H G Tennessee Valley Authority 2pp 21918 147 24X
Fiche 50-390, 84/01/04, 8401240524

--8401240544 Notice of violation from insp on 830926-1022
* Region 2, Office of Director 83/11/22 2pp 21918 149 24X
Fiche 50-390, 84/01/04, 8401240524

--8401240549 IE Insp Repts 50-390/83-46 & 50-391/83-35 on 830926-1022
Violation noted failure to protect against foreign matter contamination of sys & components in reactor bldg & safety injection pump Room 20-B
HEATHERLY, T L, SWAN, W B Region 2, Office of Director
JULIAN, C A Division of Project & Resident Programs 83/11/22
1pp 21918 151 24X Fiche 50-390, 84/01/04, 8401240524

8401240317 Ack receipt of 831207 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Rev to Procedure WBN-QC1 1 37 will require documentation of independent verification insps
LEWIS, R C Division of Project & Resident Programs 84/01/05
PARRIS, H G Tennessee Valley Authority 2pp 21932 130 24X
Fiche 50-390, 84/01/05, 8401240317

--8401240323 Suppl response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Corrective actions fire protection QA program drawings will be reviewed & deficiencies corrected through drawing revs
MILLS, L M Tennessee Valley Authority 83/12/09 O'REILLY, J P
Region 2, Office of Director 3pp 21932 132 24X
Fiche 50-390, 84/01/05, 8401240317

--8401240327 Rev 6 to Procedure WBNP-6C1-1 25, "Control of As-Constructed Drawings"
EDISON, R D Tennessee Valley Authority 83/09/02 13pp
21932 165 24X Fiche 50-390, 84/01/05, 8401240317.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401240586 Ack receipt of 831223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-40 & 50-391/83-29
LEWIS, R C Division of Project & Resident Programs 84/01/16
PARRIS, H G Tennessee Valley Authority 1p 21909 177 24X
Fiche 50-390, 84/01/16, 8401240586

--8401240593 Responds to NRC 831019 ltr re violations noted in IE Insp Repts 50-390/83-40 & 50-391/83-29 Corrective actions test engineers retrained on requirements for preoperational testing Violation re cable separation denied as stated
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P
Region 2, Office of Director 4pp 21909 178 24X
Fiche 50-390, 84/01/16, 8401240586

--8401240601 Forwards IE Insp Repts 50-390/83-40 & 50-391/83-29 on 830822-0921 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/19
PARRIS, H G Tennessee Valley Authority 2pp 21909, 184 24X
Fiche 50-390, 84/01/16, 8401240586

--8401240603 Notice of violation from insp on 830822-0921
LEWIS, R C Division of Project & Resident Programs 83/10/19
2pp 21909 186 24X Fiche 50-390, 84/01/16, 8401240586

--8401240608 IE Insp Repts 50-390/83-40 & 50-391/83-29 on 830822-0921
Violations noted failure to establish & execute separation requirement insp program & failure to transcribe design basis requirements
HEATHERLY, T L, SWAN, W B Region 2, Office of Director JULIAN, C
Division of Project & Resident Programs 83/10/14 9pp
21909 188 24X Fiche 50-390, 84/01/16, 8401240586

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

S Reportable occurrences, LERs & related correspondence

8401030137 Final deficiency rept re broken pin carrier plates on essential raw cooling water (ERCW) motors supplied by Siemens-Allis Initially reported on 830824 Parts for eight ERCW motors to be installed Also reportable per 10CFR21
MILLS, L M Tennessee Valley Authority 83/12/19 O'REILLY, J P
Region 2, Office of Director 3pp 21692 256 24X
Fiche 50-390, 83/12/19, 8401030137

8401030108 Final Deficiency Rept NCR W-132-P re QA program for control of fuses Initially reported on 830815 Fuse installation by const personnel substantially correct Item no longer reportable per 10CFR50.55(e)
MILLS, L M Tennessee Valley Authority 83/12/21 O'REILLY, J P
Region 2, Office of Director 3pp 21683 125 24X
Fiche 50-390, 83/12/21, 8401030108

8401030231 First interim deficiency rept re control room pressurization boundary loss through floor & equipment drains Initially reported on 831121 Engineering change notice issued & review of sys drawings initiated
MILLS, L M Tennessee Valley Authority 83/12/21 O'REILLY, J P
Region 2, Office of Director 3pp 21682 338 24X
Fiche 50-390, 83/12/21, 8401030231

8401040242 Final deficiency rept re routing of radioactive & nonradioactive sys instrument lines Initially reported on 830729 Instrument drain lines will be disconnected from closed drain sys by 840202
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21701 147 24X
Fiche 50-390, 83/12/22, 8401040242

8401040299 Final deficiency rept re spacing & clearance of sprinkler heads on high pressure fire protection sys Initially reported on 830331 Caused by lack of understanding by design & const personnel Walkdown of sprinkler sys conducted
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21705 075 24X
Fiche 50-390, 83/12/22, 8401040299

8401040389 Final deficiency rept for Unit 1 & fourth interim deficiency rept for Unit 2 re incorrect insulation weights used in piping analysis Initially reported on 820825 Next rept for Unit 2 by 841231 Not reportable for Unit 1
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21705 311 24X
Fiche 50-390, 83/12/22, 8401040389

8401040596 Second interim deficiency rept re loading on diesel generator for LOCA & blackout causing unacceptable frequency transient Initially reported on 831007 Next rept to be submitted by 840208
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 2pp 21706 287 24X
Fiche 50-390, 83/12/22, 8401040596

8401040303 Supplemental final deficiency rept re generic defect in design review Initially reported on 811215 Issuance of Engineering Procedures 3 57 & 3 58 expected by 840101
MILLS, L M Tennessee Valley Authority 83/12/23 O'REILLY, J P
Region 2, Office of Director 1p 21707 100 24X
Fiche 50-000, 83/12/23, 8401040303

DOCKETED ITEMS

B401040406 Supplemental final deficiency rept re design review process interface coordination activity Initially reported on B40717 Engineering Procedures 3 57 & 3 58 will be issued by B40101
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 1p 21703 362 24X
Fiche: 50-000,83/12/23,B401040406

B401050406 Supplemental interim deficiency rept re lack of isolation capability for air intakes for post-accident sampling facility Initially reported on B30517. Corrective action will be completed by B40203
MILLS,L.M. Tennessee Valley Authority 83/12/27 O'REILLY,J.P.
Region 2, Office of Director 1p 21731 130 24X
Fiche: 50-390,83/12/27,B401050406

B401100345 Final deficiency rept for Unit 1 & eighth interim rept for Unit 2 re foam seals in mechanical pipe sleeves Initially reported on B11204. Foam seal stiffness found to be insignificant. Next rept by B40619.
MILLS,L.M. Tennessee Valley Authority. 84/01/03 O'REILLY,J.P.
Region 2, Office of Director. 2pp. 21763 344 24X
Fiche: 50-390,84/01/03,B401100345

B401120277 Final deficiency rept for Unit 1 & third interim rept for Unit 2 re inaccurate results from ANCHOR computer program Initially reported on B30329 Program modified. Next rept for Unit 2 will be submitted by B40715
MILLS,L.M. Tennessee Valley Authority 84/01/04 O'REILLY,J.P.
Region 2, Office of Director 2pp 21792 260 24X
Fiche: 50-390,84/01/04,B401120277

B401120367 Third interim deficiency rept re pump motors supplied w/o seismic analysis or operability demonstrated Initially reported on B30428. Pumps & motors certified structurally adequate by Westinghouse. Next rept by B41222
MILLS,L.M. Tennessee Valley Authority 84/01/04 O'REILLY,J.P.
Region 2, Office of Director. 2pp 21791:358 24X
Fiche: 50-390,84/01/04,B401120367

B401130365 Final deficiency rept re setpoint program for overpressure mitigating sys. Initially reported on B20521 New setpoints will be provided on B40131 by Westinghouse Also reportable under Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/06 O'REILLY,J.P.
Region 2, Office of Director 3pp. 21799 357 24X
Fiche: 50-390,84/01/06,B401130365

B401170001 Final deficiency rept re pressurizer level transmitters mfg by ITT Barton w/caliber span inadequate for level process range Initially reported on B30629 Transmitters will be adjusted & reinstalled by B40220 Also reported per Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/09 O'REILLY,J.P.
Region 2, Office of Director 3pp 21834 111. 24X
Fiche: 50-390,84/01/09,B401170001.

B401170265 Final deficiency rept re automatic transfer of supply for 6.9 kV shutdown boards in event generator trip signal does not reset after transfer. Initially reported on B31216. Time delay relays added to generator trip auxiliary relays
MILLS,L.M. Tennessee Valley Authority 84/01/09 O'REILLY,J.P.
Region 2, Office of Director. 2pp 21830 359 24X
Fiche: 50-390,84/01/09,B401170265

B401170365 Seventh interim deficiency rept re incorrect analysis of thermal range Initially reported on B10222 Design revs continuing. Next rept for Unit 2 will be submitted on or about B50216
MILLS,L.M. Tennessee Valley Authority 84/01/09 O'REILLY,J.P.
Region 2, Office of Director 1p 21828.278. 24X
Fiche: 50-390,84/01/09,B401170365

B401240486 Supplemental final deficiency rept re high pressure fire protection piping water danger to shutdown board transformers after earthquake Initially reported on B30616 Engineering Change Notices 3837 & 4282 written
MILLS,L.M. Tennessee Valley Authority. 84/01/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 21920 080 24X
Fiche: 50-390,84/01/11,B401240486

B401240494 Revised final deficiency rept re incorrect use of Category (I/L) supports on pipes near water chillers. Initially reported on B30117. Design spray shield installed above & around main control room water chillers A-A & B-B
MILLS,L.M. Tennessee Valley Authority. 84/01/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp 21920.099. 24X
Fiche: 50-390,84/01/11,B401240494.

B401240545 First deficiency rept re live loads not considered in design of concrete partition walls. Initially reported on B31213. Program established to determine which walls will require structural restraints Next rept expected by B40301.
MILLS,L.M. Tennessee Valley Authority. 84/01/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 21920 035 24X
Fiche: 50-390,84/01/11,B401240545

B401240024 Final deficiency rept re leaking containment is valves. Initially reported on B30817 Line valves disassembled, cleaned &/or flushed Add'l high velocity flow performed on affected lines
MILLS,L.M. Tennessee Valley Authority 84/01/16 O'REILLY,J.P.
Region 2, Office of Director 2pp 21913 211 24X
Fiche: 50-390,84/01/16,B401240024

B401260009 Final deficiency rept re discrepancies between as-analyzed configurations Initially reported on B20910. Tests performed on Category I 2 1/2-inch safety-related piping & Category I piping dynamically analyzed by computer
MILLS,L.M. Tennessee Valley Authority 84/01/18 O'REILLY,J.P.
Region 2, Office of Director 3pp 21956 337 24X
Fiche: 50-390,84/01/18,B401260009

B401260045 Final Deficiency Repts NCR WBN NEB B329 & NCR WBN NEB re low air flow rates for safety-related exhaust fans Initially reported on B31107 General cleanup performed & fans tested
MILLS,L.M. Tennessee Valley Authority. 84/01/19 O'REILLY,J.P.
Region 2, Office of Director 4pp 21957 122 24X
Fiche: 50-390,84/01/19,B401260045

B401300136 Second interim Deficiency Rept NCR WBN WBP B335 re room pressurization boundary loss through floor & equipment drain Initially reported on B31121 Proposed piping support changes unsuitable Next rept due by B40217.
MILLS,L.M. Tennessee Valley Authority 84/01/24 O'REILLY,J.P.
Region 2, Office of Director 1p 2199B 283 24X
Fiche: 50-390,84/01/24,B401300136

B401300276 Third interim deficiency rept re diesel generator bearing Initially reported on B30627. Actions to prevent recurrence under investigation Next rept will be submitted by B40302 Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/24 O'REILLY,J.P.
Region 2, Office of Director 4pp 21995 353 24X
Fiche: 50-390,84/01/24,B401300276

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

B401090432 Responds to B31028 request for add'l info re NUREG 0737, Item II F 1, concerning installation & preoperational testing of reactor vessel level instrumentation sys (RVLS) RVLS will be installed & tested prior to fuel load
MILLS,L.M. Tennessee Valley Authority 84/01/04 ADENBAM E
Licensing Branch 4. 12pp 21750 302 24X Fiche: 50-390 B4 01 04
B401090432

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT,D O Division of Licensing. 84/01/03 Consolidated
Edison Co of New York, Inc 18pp. 21946:190 24X
Fiche: 50-000,84/01/03,B401050382

B401100299 Advises that safety-related mechanical equipment qualification evaluation will be submitted on B40303
Submittal will include evaluation results, summary of corrective actions & justification for interim operation
MILLS,L.M. Tennessee Valley Authority. 84/01/03 ADENBAM E
Licensing Branch 4 1p 21798 198 24X Fiche: 50-390,84/01/03
B401100299

B401110082 Forwards add'l info in response to Generic Ltr B3 10- re automatic trip of reactor coolant pumps Westinghouse Owners Group expects to submit generic rept justifying manual reactor coolant pump trip by B40301.
MILLS,L.M. Tennessee Valley Authority 84/01/03 ADENBAM E
Licensing Branch 4 2pp 21772.238 24X Fiche: 50-390,84/01/03
B401110082

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT,D O Division of Licensing. 84/01/04 Consolidated
Edison Co of New York, Inc. 18pp 21957 267 24X
Fiche: 50-000,84/01/04,B401090221

B401160413 Summary of B31220 meeting w/UTII in Bethesda, MD re response request from NUREG-0737, Item II F 1, "Add'l Accident Monitoring Instrumentation "
KENYON,T.J Licensing Branch 4. 84/01/09. Licensing Branch 4
2pp 21821.254. 24X Fiche: 50-390,84/01/09,B401160413

DOCKETED ITEMS

281

8401170224 Forwards addl info in support of util position on compliance to GDC-51, per 831028 request NUREG-0577 NDT (157F) statistically generated bounding valve based on 90% confidence
MILLS, L. M. Tennessee Valley Authority 84/01/09 ADENBAM, E
Licensing Branch 4 9pp 21833 314 24X Fiche 50-390, 84/01/09,
8401170224

8401170252 Forwards addl info clarifying Items 1 b.2 a.2 b.2 c.5.9.11, 21 & 22 of equipment qualification program
MILLS, L. M. Tennessee Valley Authority 84/01/11 ADENBAM, E
Licensing Branch 4 104pp 21832 001 24X Fiche 50-390, 84/01/11,
8401170252

8401180262 Forwards justification for not providing intermittent prelubrication of upper portions of diesel engines, in response to NRC informal question on 831202
MILLS, L. M. Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 2pp 21843 325 24X Fiche 50-390, 84/01/12,
8401180262

8401190307 Forwards util response to NRC & Corps of Engineers concerns re slope stability, amended FSAR matl which reflects remedial action & rept entitled "Site-Specific Top-of-Ground Motion for ERCH Pipeline W/Response to NRC Staff Concerns"
KAMMER, D. S. Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 62pp 21891 084 24X Fiche 50-390, 84/01/12,
8401190307

--**8401190307** "Site-Specific Top-of-Ground Motion for ERCH Pipeline W/Response to NRC Staff Concerns"
* Woodward-Clyde Consultants, Inc 83/09/23 113pp 21891 147 24X Fiche 50-390, 84/01/12, 8401190307

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
SVC list encl
EISENHUT, D. O. Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401200083 Forwards addl info on equipment qualification program, per 840110 telcon info consists of lists of Class C equipment & of equipment inside containment subjected to post-LOCA submergence & verification of 1 h time margin
MILLS, L. M. Tennessee Valley Authority 84/01/17 ADENBAM, E
Licensing Branch 4 45pp 21863 309 24X Fiche 50-390, 84/01/17,
8401200083

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HAMMON, J. Division of Licensing 84/01/17 Division of
Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

8401270088 Informs that expected fuel load dates for facilities delayed due to insufficient net hanger installation rate needed to support preoperational testing Fuel load expected by 840601 for Unit 1 & 851201 for Unit 2
MILLS, L. M. Tennessee Valley Authority 84/01/23 ADENBAM, E
Licensing Branch 4 1p 21962 012 24X Fiche 50-390, 84/01/23,
8401270088

8401310017 Forwards request for exemption to install high-range noble gas monitors on auxiliary bldg vent as required by NUREG-0737, Item II F.1 Provisions for initiating isolation & measuring release meet intent of NUREG-0737
MILLS, L. M. Tennessee Valley Authority 84/01/24 ADENBAM, E
Licensing Branch 4 8pp 22024 037 24X Fiche 50-390, 84/01/24,
8401310017

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8401170332 Forwards updated status rept of SER, App D items concerning control room mods, per 831108 commitment
MILLS, L. M. Tennessee Valley Authority 84/01/10 ADENBAM, E
Licensing Branch 4 8pp 21829 331 24X Fiche 50-390, 84/01/10,
8401170332

8401240258 Forwards util understanding of Power Sys Branch SER item status resulting from 831027 & 1101 telcons, util statement & NRC actions resulting from telcons & statement of compliance w/License Conditions 13 through 17
MILLS, L. M. Tennessee Valley Authority 84/01/17 ADENBAM, E
Licensing Branch 4 17pp 21910 010 24X Fiche 50-390, 84/01/17,
8401240258

F Security, medical, emergency & fire protection plans

8401090498 Forwards IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted
VERRELLI, D. H. Division of Project & Resident Programs 83/12/12
PARRIS, H. G. Tennessee Valley Authority 2pp 21753 117 24X
Fiche 50-390, 83/12/12, 8401090498

--**8401090502** IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted Major areas inspected const fire protection QA program
MILLER, W. H. Region 2, Office of Director 83/12/07 2pp 21753 119 24X Fiche 50-390, 83/12/12, 8401090498

8401100048 Forwards supplemental response to Suppl 1 to NUREG-0737 (Generic Ltr 82-33) re safety parameter display sys Implementation approval not required prior to Unit 1 fuel load date
MILLS, L. M. Tennessee Valley Authority 84/01/05 ADENBAM, E
Licensing Branch 4 9pp 21772 229 24X Fiche 50-390, 84/01/05,
8401100048

8401240317 Ack receipt of 831207 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Rev to Procedure WBN-001 1 39 will require documentation of independent verification insps
LEWIS, R. C. Division of Project & Resident Programs 84/01/05
PARRIS, H. G. Tennessee Valley Authority 2pp 21932 130 24X
Fiche 50-390, 84/01/05, 8401240317

--**8401240323** Suppl's response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Corrective actions fire protection QA program drawings will be reviewed & deficiencies corrected through drawing revs
MILLS, L. M. Tennessee Valley Authority 83/12/09 O'REILLY, J. P.
Region 2, Office of Director 33pp 21932 132 24X
Fiche 50-390, 84/01/05, 8401240317

8401160111 Forwards list of oversize drawings showing vital area designations list withheld (ref 10CFR73.21)
MILLS, L. M. Tennessee Valley Authority 84/01/09 ADENBAM, E
Licensing Branch 4 1p 21821 213 24X Fiche 50-390, 84/01/09,
8401160111

8401170332 Forwards updated status rept of SER, App D items concerning control room mods, per 831108 commitment
MILLS, L. M. Tennessee Valley Authority 84/01/10 ADENBAM, E
Licensing Branch 4 8pp 21829 331 24X Fiche 50-390, 84/01/10,
8401170332

8401170303 Notices of current status of milestone schedule for prompt notification sys Fixed sirens installed Deficiencies identified currently being corrected Mobile siren routes identified Sys expected to be operational by 840401
KAMMER, D. S. Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 1p 21833 215 24X Fiche 50-390, 84/01/12,
8401170303

8401180156 Forwards revised "TVA Compliance W/App A to Branch Technical Position 9 5-1, 'Guidelines for Fire Protection for Nuclear Power Plants Docketed Prior to 760701'" Rev result of recent TVA review of fire protection program
MILLS, L. M. Tennessee Valley Authority 84/01/12 ADENBAM, E
Licensing Branch 4 1p 21840 233 24X Fiche 50-390, 84/01/12,
8401180156

--**8401180164** Revised "TVA Compliance W/App A to Branch Technical Position 9 5-1, 'Guidelines for Fire Protection for Nuclear Power Plants Docketed Prior to 760701'"
* Tennessee Valley Authority 84/01/12 72pp 21840, 234 24X
Fiche 50-390, 84/01/12, 8401180156

8401250121 Forwards comments on security plan re designation of vital equipment Response required within 30 days of receipt of ltr Comments withheld (ref 10CFR73.21)
PARRIS, H. G. Tennessee Valley Authority 84/01/13 ADENBAM, E
Licensing Branch 4 1p 21936 210 24X Fiche 50-390, 84/01/13,
8401250121

8401250319 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 84/01/18 Document
Management Branch 1p 21957 325 24X Fiche 50-390, 84/01/18,
8401250319

--**8401250321** Forwards public version of Rev 2 to Emergency Plan Implementing Procedure IP-6, "Activation of Technical Support Ctr" & Rev 1 to IP-10, "Medical Emergency Procedure"
MILLS, L. M. Tennessee Valley Authority 83/11/14 O'REILLY, J. P.
Region 2, Office of Director 1p 21957, 326 24X
Fiche 50-390, 84/01/18, 8401250319

DOCKETED ITEMS

--8401250324 Public version of Rev 2 to Emergency Plan Implementing Procedure IP-6, "Activation of Technical Support Ctr" & Rev 1 to IP-10, "Medical Emergency Procedure" MOERSCHHELL, R P, DELK, W S, JONES, M K Tennessee Valley Authority 83/11/07 30pp 21957 32B 24X Fiche 50-390, 84/01/18, 8401250319

8401240268 Informs that listed mods to fire alarm & detection circuits will be completed by 840402 for Unit 1 & 850401 for Unit 2, per NRC 830831 ltr MILLS, L M Tennessee Valley Authority 84/01/19 ADENSAM, E Licensing Branch 4 1p 21920 239 24X Fiche 50-390, 84/01/19, 8401240268

8401250110 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21959 079 24X Fiche 50-000, 84/01/20, 8401250110

--8401250118 Forwards public version of revised emergency plan implementing procedures, including Procedure MSEC IP-6, "Emergency Preparedness" & DNEC-IP-7, "Procedure for Performance of Assessment Team Function." MILLS, L M Tennessee Valley Authority 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21959 080 24X Fiche 50-000, 84/01/20, 8401250110

--8401250126 Public version of revised emergency plan implementing procedures, including Procedures MSEC IP-6, "Emergency Preparedness" & DNEC-IP-7, "Procedure for Performance of Assessment Team Function" MAXWELL, R B Tennessee Valley Authority 83/11/10 34pp 21959 081 24X Fiche 50-000, 84/01/20, 8401250110,

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II KAMMER, D B Tennessee Valley Authority 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X Fiche 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I PARRIS, H O Tennessee Valley Authority 84/01/12 75pp 21865 002 24X Fiche 50-000, 84/01/12, 8401200194,

--8401200206 Annual Financial Rept 1982, Vol II PARRIS, H O Tennessee Valley Authority 84/01/12 96pp 21865 077 24X Fiche 50-000, 84/01/12, 8401200194,

K. Utility Final Safety Analysis Report (FSAR) & amends

8401101030 Forwards Amend 49 to FSAR MILLS, L M Tennessee Valley Authority 84/01/06 ADENSAM, E Licensing Branch 4 1p 21773 001. 24X Fiche 50-390, 84/01/06, 8401101030

--8401101032 Amend 49 to FSAR * Tennessee Valley Authority, 84/01/06 591pp 21773.002 24X Fiche 50-390, 84/01/06, 8401101030

8401300304 Forwards suppl to FSAR Amend 49, containing pages inadvertently omitted during printing KAMMER, D B Tennessee Valley Authority 84/01/26 ADENSAM, E Licensing Branch 4 1p. 21996 341. 24X Fiche 50-390, 84/01/26, 8401300304,

--8401300307 Supplemental pages to Amend 49 to FSAR * Tennessee Valley Authority 84/01/26. 4pp. 21996 342 24X Fiche 50-390, 84/01/26, 8401300304,

Q. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR FELTON, J M Division of Rules and Records, 83/10/20 ZAHLE, R E Shaw, Pittman, Potts & Trowbridge 1p 21744.003, 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982 * Director's Office, Office of Inspection and Enforcement 83/10/20 134pp. 21744 004. 24X Fiche 50-000, 83/10/20, 8401060040

8401090498 Forwards IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted VERRELLI, D M Division of Project & Resident Programs 83/12/12 PARRIS, H O Tennessee Valley Authority 2pp 21753 117 24X Fiche 50-390, 83/12/12, 8401090498

--8401090502 IE Insp Repts 50-390/83-47 & 50-391/83-36 on 831116 No violations noted Major areas inspected const fire protection GA program MILLER, W H Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs 83/12/07 2pp 21753 119 24X Fiche 50-390, 83/12/12, 8401090498

8401090478 Forwards IE Insp Repts 50-390/83-48 & 50-391/83-37 on 831024-1126 No violations noted VERRELLI, D M Division of Project & Resident Programs 83/12/16 PARRIS, H O Tennessee Valley Authority 2pp 21753 139 24X Fiche 50-390, 83/12/16, 8401090478

--8401090480 IE Insp Repts 50-390/83-48 & 50-391/83-37 on 831024-1126 No violations noted Major areas inspected inspector open items, independent insp effort, review of licensee identified items & soil liquefaction barrier installation SWAN, W B, HOLLAND, W E Region 2, Office of Director, JULIAN, C A Division of Project & Resident Programs 83/12/15 17pp 21753 141 24X Fiche 50-390, 83/12/16, 8401090478

8401090103 Forwards IE Insp Repts 50-390/83-50 & 50-391/83-39 on 831128-1202 No violations noted VERRELLI, D M Division of Project & Resident Programs 83/12/20 PARRIS, H O Tennessee Valley Authority 2pp 21753 197 24X Fiche 50-390, 83/12/20, 8401090103

--8401090109 IE Insp Repts 50-390/83-50 & 50-391/83-39 on 831128-1202 No violations noted Major areas inspected preoperational test witnessing, preoperational test results review & followup on previously identified findings THOMAS, M Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/12/20 4pp 21753 199 24X Fiche 50-390, 83/12/20, 8401090103

8401050515 Ack receipt of 830705 & 0824 ltrs informing NRC of steps taken to correct violations in IE Insp Repts 50-390/83-14 & 50-391/83-10. Violation noted in IE Insp Rept 50-390/83-14 rescinded following careful consideration. LEWIS, R C Division of Project & Resident Programs 83/12/21 PARRIS, H O Tennessee Valley Authority. 1p 21725 321 24X Fiche 50-390, 83/12/21, 8401050515

--8401050523 Responds to NRC 830601 ltr re violations noted in IE Insp Repts 50-390/83-14 & 50-391/83-10 Response supple 830705 ltr Violation in IE Insp Rept 50-390/83-14 re personnel correctly performing GC insp denied MILLS, L M Tennessee Valley Authority 83/08/24 O'REILLY, J P Region 2, Office of Director 3pp 21725 322 24X Fiche 50-390, 83/12/21, 8401050515

--8401050529 Responds to NRC 830601 ltr re violations noted in IE Insp Repts 50-390/83-14 & 50-391/83-10. Violation in IE Insp Rept 50-390/83-14 denied & support 106B-1-6B-336 reworked per IE Bulletin 79-14 MILLS, L M Tennessee Valley Authority 83/07/05 O'REILLY, J P Region 2, Office of Director 3pp 21725 325 24X Fiche 50-390, 83/12/21, 8401050515

--8401050537 Forwards IE Insp Repts 50-390/83-14 & 50-391/83-14 on 830426-29 & notice of violation LEWIS, R C Division of Project & Resident Programs 83/06/01 PARRIS, H O Tennessee Valley Authority 2pp 21725 330 24X Fiche 50-390, 83/12/21, 8401050515

--8401050546 IE Insp Repts 50-390/83-14 & 50-391/83-10 on 830426-29 Violation noted, failure to follow valve installation & hanger used insp procedures, per IE Bulletin 79-14, LIU, W C Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/05/25 7pp 21725 333 24X Fiche 50-390, 83/12/21, 8401050515

8401050571 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-41 & 50-391/83-30 VERRELLI, D M Division of Project & Resident Programs 83/12/21 PARRIS, H O Tennessee Valley Authority 1p. 21726 147 24X Fiche 50-390, 83/12/21, 8401050571

--8401050582 Responds to NRC 831020 ltr re violations noted in IE Insp Repts 50-390/83-41 & 50-391/83-30 Corrective actions documentation corrected to indicate correct reactor curves & Procedure WBNP-GCP-2 01 will be revised by 840201 MILLS, L M Tennessee Valley Authority 83/12/06 O'REILLY, J P Region 2, Office of Director 4pp 21726 148 24X Fiche 50-390, 83/12/21, 8401050571

DOCKETED ITEMS

283

--B401050587 Forwards IE Insp Repts 50-390/83-41 & 50-391/83-30 on 830927-30 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/10/20
PARRIS, H G Tennessee Valley Authority 2pp 21726 152 24X
Fiche 50-390, 83/12/21, 8401050571

--B401050596 Notice of violation from insp on 830927-30
* Region 2, Office of Director 83/10/20 2pp 21726 154 24X
Fiche 50-390, 83/12/21, 8401050571

--B401050610 IE Insp Repts 50-390/83-41 & 50-391/83-30 on 830927-30
Violations noted failure to follow QC instructions on
earthfill testing for underground barriers for potential
soil liquefaction
HARRIS, J R Region 2, Office of Director CONLON, T E Division
of Project & Resident Programs 83/10/17 5pp 21726 156 24X
Fiche 50-390, 83/12/21, 8401050571

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
H/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEYQUNG, R C Director's Office, Office of Inspection and
Enforcement. 83/12/28 Consolidated Edison Co of New York, Inc
124pp. 21731 165 24X Fiche 50-000, 83/12/28, 8312120090

B401060441 Ack receipt of 831110 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-390/83-35 &
50-391/83-24
LEWIS, R C Division of Project & Resident Programs 83/12/29
PARRIS, H G Tennessee Valley Authority 1p 21740 091 24X
Fiche 50-390, 83/12/29, 8401060441

--B401060445 Responds to NRC 831014 ltr re violations noted in IE Insp
Repts 50-390/83-35 & 50-391/83-24 Corrective actions
undersize weld on hanger 10030-1-030-3 repaired to comply
w/current drawing requirements
MILLS, L M Tennessee Valley Authority 83/11/10 O'REILLY, J P
Region 2, Office of Director 2pp 21740 092 24X
Fiche 50-390, 83/12/29, 8401060441

--B401060448 Forwards IE Insp Repts 50-390/83-35 & 50-391/83-24 on
830912-16 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/14
PARRIS, H G Tennessee Valley Authority 2pp 21740 095 24X
Fiche 50-390, 83/12/29, 8401060441

--B401060478 IE Insp Repts 50-390/83-35 & 50-391/83-24 on 830912-16
Noncompliance noted QC inspectors failed to detect undersize
weld, lack of double nuts on pipe clamps & wrong size base
plates & concrete anchor on hangers
AYO, W P, LIU, W C, YORK, J W Region 2, Office of Director
83/10/06 10pp 21740 098 24X Fiche 50-390, 83/12/29, 8401060441

B401060449 Ack receipt of 830726 & 0817 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Repts
50-390/83-17 & 50-391/83-13
LEWIS, R C Division of Project & Resident Programs. 83/12/29
PARRIS, H G Tennessee Valley Authority 1p 21740 335 24X
Fiche 50-390, 83/12/29, 8401060449

--B401060453 Revises 830726 response to NRC 830627 ltr re violations
noted in IE Insp Repts 50-390/83-17 & 50-391/83-13
Support 2072-72-268-R10 inadvertently listed as 2072-72-R19
in corrective actions dtd 830726
MILLS, L M Tennessee Valley Authority 83/08/17, O'REILLY, J P
Region 2, Office of Director 1p 21740 336 24X
Fiche 50-390, 83/12/29, 8401060449

--B401060455 Responds to 830627 ltr re violations noted in IE Insp Repts
50-390/83-17 & 50-391/83-13 Corrective actions shock
arrestor to accommodate pipe thermal movement & stiffener
plate oversized weld & orientation deficiencies documented.
KAMMER, B S Tennessee Valley Authority 83/07/26 O'REILLY, J P
Region 2, Office of Director 4pp 21740 337 24X
Fiche 50-390, 83/12/29, 8401060449

--B401060458 Forwards IE Insp Repts 50-390/83-17 & 50-391/83-13 on
830523-26 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/06/27
PARRIS, H G Tennessee Valley Authority 2pp 21740 341 24X
Fiche 50-390, 83/12/29, 8401060449

--B401060462 IE Insp Repts 50-390/83-17 & 50-391/83-13 on 830523-26
Noncompliance noted failure to follow procedure on hanger/
snubber insp & to follow fabrication & insp procedures for
hanger/snubber installation
LIU, W C Region 2, Office of Director BLAKE, J J Division of
Engineering & Operational Programs 83/06/22 6pp 21740 345
24X Fiche 50-390, 83/12/29, 8401060449

--B401060460 Notice of violation from insp on 830523-26
* Region 2, Office of Director 83/06/27 2pp 21740 343, 24X
Fiche 50-390, 83/12/29, 8401060449

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B401240524 Ack receipt of 831222 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-390/83-46 &
50-391/83-35 Implementation of corrective actions will be
examined during future insps
LEWIS, R C Division of Project & Resident Programs 84/01/04
PARRIS, H G Tennessee Valley Authority 1p 21918 143 24X
Fiche 50-390, 84/01/04, 8401240524

--B401240536 Responds to NRC 831122 ltr re violations noted in IE Insp
Repts 50-390/83-46 & 50-391/83-35 Corrective actions future
entries into primary side of steam generators will be
monitored by const personnel
MILLS, L M Tennessee Valley Authority 83/12/22 O'REILLY, J P
Region 2, Office of Director 3pp 21918 144 24X
Fiche 50-390, 84/01/04, 8401240524

--B401240541 Forwards IE Insp Repts 50-390/83-46 & 50-391/83-35 on
830926-1022 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/22
PARRIS, H G Tennessee Valley Authority 2pp 21918 147 24X
Fiche 50-390, 84/01/04, 8401240524

--B401240544 Notice of violation from insp on 830926-1022
* Region 2, Office of Director 83/11/22 2pp 21918 149 24X
Fiche 50-390, 84/01/04, 8401240524

--B401240549 IE Insp Repts 50-390/83-46 & 50-391/83-35 on 830926-1022
Violation noted failure to protect against foreign matter
contamination of sys & components in reactor bldg & safety
injection pump room 20-B
HEATHERLY, T L, SHAN, W B Region 2, Office of Director
JULIAN, C A Division of Project & Resident Programs 83/11/22,
11pp 21918 151 24X Fiche 50-390, 84/01/04, 8401240524

B401240317 Ack receipt of 831209 ltr informing NRC of steps taken to
correct deviations noted in IE Insp Repts 50-390/82-29 &
50-391/82-26 Rev to Procedure WBN-GCI 1 39 will require
documentation of independent verification insps
LEWIS, R C Division of Project & Resident Programs 84/01/05
PARRIS, H G Tennessee Valley Authority 2pp 21932 130 24X
Fiche 50-390, 84/01/05, 8401240317

--B401240323 Suppls response to NRC 820827 ltr re deviations noted in IE
Insp Repts 50-390/82-29 & 50-391/82-26 Corrective actions
fire protection GA program drawings will be reviewed &
deficiencies corrected through drawing revs
MILLS, L M Tennessee Valley Authority 83/12/09 O'REILLY, J P
Region 2, Office of Director 33pp 21932 132 24X
Fiche 50-390, 84/01/05, 8401240317

--B401240329 Rev & to Procedure WBNF-GCI-1 23, "Control of As-Constructed
Drawings "
EDISON, R D Tennessee Valley Authority 83/09/02 13pp
21932 165 24X Fiche 50-390, 84/01/05, 8401240317

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21746 053 24X Fiche 50-000, 84/01/10, 8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 164 24X Fiche 50-000, 84/01/10, 8312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

B401240586 Ack receipt of 831223 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-390/83-40 &
50-391/83-29
LEWIS, R C Division of Project & Resident Programs. 84/01/16
PARRIS, H G Tennessee Valley Authority 1p 21909 177 24X
Fiche 50-390, 84/01/16, 8401240586

--B401240593 Responds to NRC 831019 ltr re violations noted in IE Insp
Repts 50-390/83-40 & 50-391/83-29 Corrective actions test
engineers retrained on requirements for preoperational
testing Violation re cable separation denied as stated.
MILLS, L M Tennessee Valley Authority 83/12/23, O'REILLY, J P
Region 2, Office of Director 6pp 21909 178 24X
Fiche 50-390, 84/01/16, 8401240586

DOCKETED ITEMS

- 8401240601 Forwards IE Insp Repts 50-390/83-40 & 50-391/83-29 on 830822-0921 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/10/19
FARRIS, H. Q. Tennessee Valley Authority 2pp 21909 184 24X
Fiche 50-390, 84/01/16, 8401240586
- 8401240603 Notice of violation from Insp on 830822-0921
LEWIS, R. C. Division of Project & Resident Programs 83/10/19
2pp 21909 186 24X Fiche 50-390, 84/01/16, 8401240586
- 8401240608 IE Insp Repts 50-390/83-40 & 50-391/83-29 on 830822-0921
Violations noted failure to establish & execute separation
requirements Insp program & failure to transcribe design
basis requirements
HEATHERLY, T. L., SHAN, W. B. Region 2, Office of Director JULIAN, C.
Division of Project & Resident Programs 83/10/19 7pp
21909 188 24X Fiche 50-390, 84/01/16, 8401240586.
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18 Consolidated Edison Co. of New
York, Inc 118pp 22000.001 24X Fiche 50-000, 84/01/18, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18 Consolidated Edison Co. of New
York, Inc 120pp. 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- B Reportable occurrences, LERs & related correspondence**
- 8401030137 Final deficiency rept re broken pin carrier plates on
essential raw cooling water (ERCW) motors supplied by
Siemens-Allis. Initially reported on 830824 Parts for eight
ERCW motors to be installed Also reportable per 10CFR21.
MILLS, L. M. Tennessee Valley Authority 83/12/19. O'REILLY, J. P.
Region 2, Office of Director. 2pp 21682 256 24X
Fiche 50-390, 83/12/19, 8401030137
- 8401030108 Final Deficiency Rept NCR W-132-F re GA program for control
of fuses Initially reported on 830815 Fuse installation by
const personnel substantially correct Item no longer
reportable per 10CFR50.35(e)
MILLS, L. M. Tennessee Valley Authority 83/12/21 O'REILLY, J. P.
Region 2, Office of Director. 2pp. 21683 125 24X
Fiche 50-390, 83/12/21, 8401030108
- 8401030231 First interim deficiency rept re control room pressurization
boundary loss through floor & equipment drains. Initially
reported on 831121 Engineering change notice issued & review
of sys drawings initiated
MILLS, L. M. Tennessee Valley Authority. 83/12/21 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21682 338 24X
Fiche 50-390, 83/12/21, 8401030231.
- 8401040242 Final deficiency rept re routing of radioactive &
nonradioactive sys instrument lines Initially reported on
830729. Instrument drain lines will be disconnected from
closed drain sys by 840202
MILLS, L. M. Tennessee Valley Authority. 83/12/22 O'REILLY, J. P.
Region 2, Office of Director. 3pp. 21701 147 24X
Fiche 50-390, 83/12/22, 8401040242
- 101040299 Final deficiency rept re spacing & clearance of sprinkler
heads on high pressure fire protection sys Initially
reported on 830331 Caused by lack of understanding by design
& const personnel. Walkdown of sprinkler sys conducted
MILLS, L. M. Tennessee Valley Authority 83/12/22 O'REILLY, J. P.
Region 2, Office of Director. 3pp. 21705.075 24X
Fiche 50-390, 83/12/22, 8401040299.
- 8401040589 Final deficiency rept for Unit 1 & fourth interim deficiency
rept for Unit 2 re incorrect insulation weights used in
piping analysis Initially reported on 830823 Next rept for
Unit 2 by 841231. Not reportable for Unit 1
MILLS, L. M. Tennessee Valley Authority 83/12/22. O'REILLY, J. P.
Region 2, Office of Director 2pp 21705-311. 24X
Fiche 50-390, 83/12/22, 8401040589.
- 401040596 Second interim deficiency rept re loading on diesel
generator for LOCA & blackout causing unacceptable frequency
transient Initially reported on 831007. Next rept to be
submitted by 840206
MILLS, L. M. Tennessee Valley Authority. 83/12/22 O'REILLY, J. P.
Region 2, Office of Director. 2pp. 21706:287 24X
Fiche 50-390, 83/12/22, 8401040596
- 8401040303 Supplemental final deficiency rept re design & safety
design review Initially reported on 811215 Issued by
Engineering Procedures 3 57 & 3 58 expected by 841117
MILLS, L. M. Tennessee Valley Authority 83/12/23
Region 2, Office of Director 1p 21707 100 24X
Fiche 50-000, 83/12/23, 8401040303
- 8401040406 Supplemental final deficiency rept re design & safety
interface coordination activity Initially reported on
810717 Engineering Procedures 3 57 & 3 58 will be issued by
840101
MILLS, L. M. Tennessee Valley Authority 83/12/23
Region 2, Office of Director 1p 21703 362 24X
Fiche 50-000, 83/12/23, 8401040406
- 8401050406 Supplemental interim deficiency rept re design & safety
capability for air intakes for post-accident sampling
facility Initially reported on 830517 Corrective action
will be completed by 840203
MILLS, L. M. Tennessee Valley Authority 83/12/27
Region 2, Office of Director 1p 21731 130 24X
Fiche 50-390, 83/12/27, 8401050406
- 8401100345 Final deficiency rept for Unit 1 & eighth interim
Unit 2 re foam seals in mechanical pipe sleeves Initially
reported on 811204 Foam seal stiffness found to be
insignificant Next rept by 840619
MILLS, L. M. Tennessee Valley Authority 84/01/03
Region 2, Office of Director 2pp 21763 344 24X
Fiche 50-390, 84/01/03, 8401100345
- 8401120277 Final deficiency rept for Unit 1 & third interim
Unit 2 re inaccurate results from ANCHOR computer program
Initially reported on 830329 Program modified Next rept for
Unit 2 will be submitted by 840715
MILLS, L. M. Tennessee Valley Authority 84/01/04
Region 2, Office of Director 2pp. 21792 260 24X
Fiche 50-390, 84/01/04, 8401120277
- 8401120367 Third interim deficiency rept re pump motors supplied on
seismic analysis or operability demonstrated Initially
reported on 830428 Pumps & motors certified structurally
adequate by Westinghouse Next rept by 841222
MILLS, L. M. Tennessee Valley Authority 84/01/04
Region 2, Office of Director 2pp 21791 358 24X
Fiche 50-390, 84/01/04, 8401120367
- 8401170265 Final deficiency rept re automatic transfer of supply
6.9 kV shutdown boards in event generator trip signal does
not reset after transfer Initially reported on 831215 Time
delay relays added to generator trip auxiliary relays
MILLS, L. M. Tennessee Valley Authority 84/01/09
Region 2, Office of Director. 2pp 21830 359 24X
Fiche 50-390, 84/01/09, 8401170265
- 8401170365 Seventh interim deficiency rept re incorrect analysis
thermal range Initially reported on 810222 Design review
continuing Next rept for Unit 2 will be submitted on or
about 830216
MILLS, L. M. Tennessee Valley Authority 84/01/09 O'REILLY, J. P.
Region 2, Office of Director 1p 21828 278 24X
Fiche 50-390, 84/01/09, 8401170365
- 8401240486 Supplemental final deficiency rept re high pressure
protection piping water danger to shutdown board
transformers after earthquake. Initially reported on 830616
Engineering Change Notices 3837 & 4282 written
MILLS, L. M. Tennessee Valley Authority 84/01/11 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21920 080 24X
Fiche 50-390, 84/01/11, 8401240486
- 8401240545 First deficiency rept re live loads not considered in
design of concrete partition walls Initially reported on 831213
Program established to determine which walls will require
structural restraints. Next rept expected by 840301
MILLS, L. M. Tennessee Valley Authority 84/01/11 O'REILLY, J. P.
Region 2, Office of Director 2pp 21920 035 24X
Fiche 50-390, 84/01/11, 8401240545.
- 8401260165 Final deficiency rept re postulated accident shutdown
more than one steam generator Initially reported on 821015
Availability of pump A assumed by isolating pump from
faulted steam generator emergency operating instructions
MILLS, L. M. Tennessee Valley Authority 84/01/17 O'REILLY, J. P.
Region 2, Office of Director 2pp 21956 060 24X
Fiche 50-391, 84/01/17, 8401260165
- 8401260045 Final Deficiency Repts NCR WBN NEB 8329 & NCR WBN NEB 8330
re low air flow rates for safety-related exhaust fans
Initially reported on 831107 General cleanup performed &
fans tested
MILLS, L. M. Tennessee Valley Authority 84/01/19 O'REILLY, J. P.
Region 2, Office of Director 2pp. 21957 122 24X
Fiche 50-390, 84/01/19, 8401260045

DOCKETED ITEMS

285

B401300136 Second interim Deficiency Rept NCR WBN WBP B335 re control room pressurization boundary loss through floor & equipment drain Initially reported on B31121 Proposed piping support changes unsuitable Next rept due by B40217
MILLS,L M Tennessee Valley Authority B4/01/24 O'REILLY,J P Region 2, Office of Director 1p 21978 283 24X
Fiche 50-390,B4/01/24,B401300136

B401300276 Third interim deficiency rept re diesel generator rear bearing Initially reported on B30627 Actions to prevent recurrence under investigation Next rept will be submitted by B40302 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority B4/01/24 O'REILLY,J P Region 2, Office of Director 4pp 21975 383 24X
Fiche 50-390,B4/01/24,B401300276

DOCKET 50-395 VIROIL C SUMMER NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records B3/11/02 O'NEILL,J H Shaw, Pittman, Potts & Trowbridge 6pp 21977 357 24X
Fiche 50-000,B3/11/02,B401250163

--B301060498 Discusses status of implementation of emergency operations facilities in response to Secretary B21126 memo re possible vote on full power OL Supporting documentation encl
DIRCKS,W J Office of the Executive Director for Operations B2/12/27 PALLADINO,N Commissioners 7pp 21958 305 24X
Fiche 50-000,B3/11/02,B401250163

--B303110415 Requests Commission disapprove exception for backup emergency operations facility for plant
DIRCKS,W J Office of the Executive Director for Operations SECY-B3-085 B3/02/28 9pp 21958 016 24X
Fiche 50-000,B3/11/02,B401250163

--B401250185 Discusses how SECY-B2-111 unravels NRC emergency preparedness requirements, per author B21103 memo Table III, A 1 2-2 not changed in any way by SECY-B2-111 Responses to listed questions requested
GILINSKY,V Commissioners B2/11/18 Commissioners 2pp 21958 004 24X Fiche 50-000,B3/11/02,B401250163

B401240360 Forwards IE Insp Rept 50-395/B3-36 on B31128-1204 No violations noted
VERRELLI,D M Division of Project & Resident Programs B3/12/22 DIXON,O W South Carolina Electric & Gas Co 2pp 21920 244 24X
Fiche 50-395,B3/12/22,B401240360

--B401240364 IE Insp Rept 50-395/B3-36 on B31128-1204 No violations noted Major areas inspected followup on LERs, maint & surveillance activities, physical protection, Tech Spec compliance & util actions on previous insp findings
NEUFELT,G M Region 2, Office of Director CANTRELL,F B Division of Project & Resident Programs B3/12/20 6pp 21920 246 24X Fiche 50-395,B3/12/22,B401240360

B401030207 Discusses safety parameter display sys status & schedule Significant mods will be required by Westinghouse to resolve sys software problems Sys will be fully operational no later than Dec 1985
DIXON,O W South Carolina Electric & Gas Co B3/12/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 21682 295 24X Fiche 50-395,B3/12/28,B401030207

B401050107 Releases public version of revised emergency plan implementing procedure
FELTON,J M Division of Rules and Records B3/12/28 Document Management Branch 1p 21743 343 24X Fiche 50-395,B3/12/28,B401050107

--B401050111 Public version of Rev 3 to Emergency Plan Implementing Procedure EPP-020, "Emergency Personnel Exposure Control" Revised table of contents encl
COUNTS,M BRADHAM,A S South Carolina Electric & Gas Co B3/11/14 9pp 21743 344 24X Fiche 50-395,B3/12/28,B401050107

B401250315 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records B4/01/18 Document Management Branch 1p 21932 267 24X Fiche 50-395,B4/01/18,B401250315

--B401250316 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-002 re communication & notification, EPP-005 re offsite dose calculations & EPP-015 re natural emergencies
DIXON,O W South Carolina Electric & Gas Co B3/11/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 21932 268 24X Fiche 50-395,B4/01/18,B401250315

--B401250318 Public version of revised emergency plan implementing procedures, including Procedures EPP-002 re communication & notification, EPP-005 re offsite dose calculations & EPP-015 re natural emergency
COUNTS,M South Carolina Electric & Gas Co B3/11/10 70pp 21932 270 24X Fiche 50-395,B4/01/18,B401250315

B401260034 Releases public version of revised radiation emergency plan
FELTON,J M Division of Rules and Records B4/01/18 Document Management Branch 1p 21989 311 24X Fiche 50-395,B4/01/18,B401260034

--B401260036 Public version of Rev 11 to Radiation Emergency Plan EP-100 W/B31109 ltr
DIXON,O W BEALE,K E South Carolina Electric & Gas Co B3/11/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 37pp 21989 312 24X Fiche 50-395,B4/01/18,B401260034

B401260335 Requests exemption from requirement of 10CFR50, App E, IV 1 a re state & local govt participation in util B40321 limited emergency preparedness exercise
DIXON,O W South Carolina Electric & Gas Co B4/01/18 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 21933 141 24X Fiche 50-395,B4/01/18,B401260335

H General correspondence

B401240335 Informs that firm name of counsel for applicants/licenses changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds B4/01/19 CLEMENTS,W L Docketing & Services Branch 2pp 21919 361 24X
Fiche 50-000,B4/01/19,B401240335

P Operating license stage documents & correspondence

B401120440 Forwards Amend 19 to License NPF-12, safety evaluation & NBHC Amend corrects administrative errors in Tech Specs involving typographical errors & incorrect plotting of rod bow penalty curve data NBHC available in Central Files
ADENSBAM,E G Licensing Branch 4 B3/12/23 DIXON,O W South Carolina Electric & Gas Co 2pp 21803 222 24X
Fiche 50-395,B3/12/23,B401120440

--B401120443 Amend 19 to License NPF-12, correcting administrative errors in Tech Specs involving typographical errors & incorrect plotting of rod bow penalty curve data
ADENSBAM,E G Licensing Branch 4 B3/12/23 10pp 21803 225 24X Fiche 50-395,B3/12/23,B401120440

--B401120445 Safety evaluation supporting Amend 19 to License NPF-12 * Office of Nuclear Reactor Regulation, Director B3/12/23 2pp 21803 236 24X Fiche 50-395,B3/12/23,B401120440

B401040593 Forwards draft "Licensing Rept on High Density Spent Fuel Racks for VC Summer Nuclear Station," Tech Spec change requests will be forwarded in early Jan 1984 New racks should be fully installed & ready for use by B40901
DIXON,O W South Carolina Electric & Gas Co B3/12/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 21703 112 24X Fiche 50-395,B3/12/28,B401040593

--B401040597 Draft "Licensing Rept on High Density Spent Fuel Racks for VC Summer Nuclear Station" * South Carolina Electric & Gas Co B3/12/31 182pp 21703 114 24X Fiche 50-395,B3/12/28,B401040593

B401050382 Generic ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT,D G Division of Licensing B4/01/03 Consolidated Edison Co of New York, Inc. 16pp 21946 190 24X
Fiche 50-000,B4/01/03,B401050382

B401190538 Forwards Amend 20 to License NPF-12 & safety evaluation, Amend changes Tech Specs to add requirements for condensate demineralizer backwash effluent line monitoring
ADENSBAM,E G Licensing Branch 4 B4/01/03 DIXON,O W South Carolina Electric & Gas Co 3pp 21861 321 24X
Fiche 50-395,B4/01/03,B401190538

DOCKETED ITEMS

--B401190542 Amend 20 to License NPF-12, changing Tech Specs to add requirements for condensate demineralizer backwash effluent line monitoring
ADENSAM, E O Licensing Branch 4 84/01/05. 9pp 21861 324 24X
Fiche 50-395, 84/01/05, 8401190538

--B401190544 Safety evaluation supporting Amend 20 to License NPF-12
* Licensing Branch 4 84/01/05 2pp. 21861 333 24X
Fiche 50-395, 84/01/05, 8401190538

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc. 18pp 21957 267 24X
Fiche: 50-000, 84/01/06, 8401090221

B401100444 Responds to request for addl info for justification of 72 h feedwater isolation valve inoperable time limit as presented in 831116 application for amend to Tech Specs Feedwater pump trip & feedwater control valve provide added protection
DIXON, O W South Carolina Electric & Gas Co 84/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp 21762.087
24X Fiche: 50-395, 84/01/06, 8401100444

B401120371 Submits response to Generic Ltr 83-41, "Fast Cold Starts of Diesel Generators " Colt recommends starting & continuous running procedure Number of fast cold starts for 821201-831201 listed
DIXON, O W South Carolina Electric & Gas Co. 84/01/06 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 2pp. 21791 348
24X Fiche 50-395, 84/01/06, 8401120371

B401160419 Notification of B40109 meeting w/utl in Bethesda, MD to discuss licensee low temp overpressurization protection sys (License Condition 2C(10)).
HOPKINS, J B. Licensing Branch 4 84/01/09 ADENSAM, E O Licensing Branch 4. 3pp 21821 294 24X Fiche 50-395, 84/01/09, 8401160419.

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl.
EISENHUT, D O. Division of Licensing 84/01/13 Consolidated
Edison Co. of New York, Inc. 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, 8401130084.

B401240138 Application to amend License NPF-12, revising Tech Specs re combustible gas control, per Generic Ltr 83-37 Tech Specs for reactor vessel head vent valves meet NUREG-0737, Item II B.1 requirements
DIXON, O W South Carolina Electric & Gas Co. 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 3pp 21913-230
24X Fiche 50-395, 84/01/18, 8401240138

--B401240143 Proposed Tech Spec 3/4 & 5 re combustible gas control.
* South Carolina Electric & Gas Co 84/01/18 1p 21913 233
24X Fiche 50-395, 84/01/18, 8401240138

240557 Application to amend License NPF-12, revising Tech Spec ble 3 B-1, "Containment Penetration Conductor Protective vice Test Setpoint Criteria," to provide for addition of inadvertently omitted breakers.
DIXON, O W South Carolina Electric & Gas Co 84/01/18. DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp 21920.017.
X Fiche: 50-395, 84/01/18, 8401240557.

1401240563 Proposed Tech Spec Table 3 B-1, "Containment Penetration Conductor Overcurrent Protective Device Test Setpoint Criteria "
* South Carolina Electric & Gas Co 84/01/18. 1p. 21920.019
24X Fiche: 50-395, 84/01/18, 8401240557

310206 Forwards final "Licensing Rept on New Fuel Storage Racks " & tied-up Tech Specs re high density spent fuel storage rks. NBHC appropriate based on rept & 10CFR50.92
DIXON, O W South Carolina Electric & Gas Co. 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 41pp. 22020.001
X Fiche: 50-395, 84/01/23, 8401310206

01310209 "Licensing Rept on New Fuel Storage Racks "
* Southern California Edison Co 83/12/31. 190pp. 22020 042
24X Fiche: 50-395, 84/01/23, 8401310206

0005 Responds to B40123 request for info re 831116 application amend to License NPF-12. Valves mentioned in request main feedwater isolation valves 1611A, 1611B & 1611C.
DIXON, O W South Carolina Electric & Gas Co 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 1p 22024:030
Fiche: 50-395, 84/01/23, 8401310005

3 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060040

B401050499 Forwards IE Insp Rept 50-395/83-33 on 831003-07 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/01
DIXON, O W South Carolina Electric & Gas Co 2pp 21726 007 24X
Fiche: 50-395, 83/12/01, 8401050499

--B401050506 IE Insp Rept 50-395/83-33 on 831003-07 No violations noted
Major areas inspected: health physics organizational changes, internal audits of health physics program, training, procedural changes & instruments & equipment
PEERY, W W Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/29 4pp 21726 009
24X Fiche 50-395, 83/12/01, 8401050499

B401090255 Forwards IE Insp Rept 50-395/83-35 on 831129-1202 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/15
DIXON, O W South Carolina Electric & Gas Co 2pp 21754 030 24X
Fiche: 50-395, 83/12/15, 8401090255

--B401090262 IE Insp Rept 50-395/83-35 on 831129-1202, No noncompliance noted Major areas inspected review of completed startup & surveillance tests
BURNETT, P T Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/12/13 5pp 21754 032
24X Fiche 50-395, 83/12/15, 8401090255

B401240360 Forwards IE Insp Rept 50-395/83-36 on 831128-1204 No violations noted.
VERRELLI, D M Division of Project & Resident Programs 83/12/22
DIXON, O W South Carolina Electric & Gas Co 2pp 21920 244 24X
Fiche: 50-395, 83/12/22, 8401240360

--B401240364 IE Insp Rept 50-395/83-36 on 831128-1204 No violations noted Major areas inspected followup on LERs, maint & surveillance activities, physical protection, Tech Spec compliance & util actions on previous insp findings
NEWFELT, G M Region 2, Office of Director CANTRELL, F S
Division of Project & Resident Programs 83/12/20 4pp
21920.246 24X Fiche 50-395, 83/12/22, 8401240360

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp. 21731 166 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

B401040378 Suggests installation of steam generator insp ports to monitor denting on Model D-3 unnecessary Visual denting through insp port would occur long after denting would be detectable in lower tube support plate region
DIXON, O W South Carolina Electric & Gas Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp 21704 296
24X Fiche 50-395, 83/12/30, 8401040378

B401240390 Notifies that util 831104 commitment to establish addl procedural controls to correct inadequacies in drawing control program cited in IE Insp Rept 50-395/83-27 delayed by plant outage Procedures will be submitted 840131.
DIXON, O W South Carolina Electric & Gas Co 83/12/30
D'REILL, J P Region 2, Office of Director. 1p. 21920.359 24X
Fiche: 50-395, 83/12/30, 8401240390

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co of New York, Inc. 125pp 21946 053. 24X Fiche: 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401240326 Ack receipt of 840105 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-34
VERRELLI, D M Division of Project & Resident Programs 84/01/11
DIXON, O W South Carolina Electric & Gas Co 1p 21920 335 24X Fiche 50-395, 84/01/11, 8401240326

--8401240331 Responds to NRC 831206 ltr re violations noted in IE Insp Rept 50-395/83-34 Corrective actions diesel generator local control panel alarm response procedures will be issued by 840115
DIXON, O W South Carolina Electric & Gas Co 84/01/05
O'REILLY, J P Region 2, Office of Director 2pp 21920 337 24X Fiche 50-395, 84/01/11, 8401240331

--8401240336 Forwards IE Insp Rept 50-395/83-34 on 831114-19 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/12/06
DIXON, O W South Carolina Electric & Gas Co 2pp 21920 339 24X Fiche 50-395, 84/01/11, 8401240336

--8401240343 Notice of violation from insp on 831114-19
w Region 2, Office of Director 83/12/06 1p 21920 341 24X Fiche 50-395, 84/01/11, 8401240343

--8401240359 IE Insp Rept 50-395/83-34 on 831114-19 Violation noted each annunciator on diesel generator local control panel did not have applicable, component-specific procedure
RULAND, W H Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/12/05 6pp 21920 342 24X Fiche 50-395, 84/01/11, 8401240359

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310022 Forwards info re Model D-3 steam generator insp in Apr 1983, per 831227 request Results of eddy current exam, manifold visual insp, tube vibration monitoring & inlet pressure monitoring summarized
DIXON, O W South Carolina Electric & Gas Co 84/01/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22023 346 24X Fiche 50-395, 84/01/27, 8401310022

R Periodic operating reports & related correspondence

8401120279 Forwards monthly operating rept for Nov 1983 & revised attachments to Aug, Sept & Oct 1983 repts
DIXON, O W South Carolina Electric & Gas Co 83/12/14 BARRY, L W Office of Resource Management, Director 1p 21792 163 24X Fiche 50-395, 83/12/14, 8401120279

--8401120283 Monthly operating rept for Nov 1983.
LOIGNON, G A South Carolina Electric & Gas Co 83/11/30 4pp 21792 164 24X Fiche 50-395, 83/12/14, 8401120279

--8401120285 Corrected Attachment II to monthly operating rept for Aug 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/08/31 2pp 21792 168 24X Fiche 50-395, 83/12/14, 8401120279

--8401120290 Corrected Attachment II to monthly operating rept for Sept 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/09/30 1p 21792 170 24X Fiche 50-395, 83/12/14, 8401120279

--8401120295 Corrected Attachment II to monthly operating rept for Oct 1983
LOIGNON, G A South Carolina Electric & Gas Co 83/10/31, 1p 21792 171 24X Fiche 50-395, 83/12/14, 8401120279

8401270377 Forwards monthly operating rept for Dec 1983 & revised monthly operating repts for Apr-Nov 1983
DIXON, O W South Carolina Electric & Gas Co 84/01/13 BARRY, L W Office of Resource Management, Director 1p 21796 228 24X Fiche 50-395, 84/01/13, 8401270377

--8401270379 Monthly operating rept for Dec 1983
LOIGNON, G A South Carolina Electric & Gas Co 83/12/31 7pp 21796 229 24X Fiche 50-395, 84/01/13, 8401270377

--8401270382 Revised monthly operating rept for Apr 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/04/30 2pp 21796 236 24X Fiche 50-395, 84/01/13, 8401270377

--8401270383 Revised monthly operating rept for May 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/05/31 2pp 21796 238 24X Fiche 50-395, 84/01/13, 8401270377

--8401270385 Revised monthly operating rept for June 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/06/30 1p 21796 240 24X Fiche 50-395, 84/01/13, 8401270377

--8401270387 Revised monthly operating rept for Jul 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/07/31 1p 21796 241 24X Fiche 50-395, 84/01/13, 8401270377

--8401270388 Revised monthly operating rept for Aug 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/08/31 1p 21796 242 24X Fiche 50-395, 84/01/13, 8401270377

--8401270389 Revised monthly operating rept for Sept 1983
TAYLOR, G J South Carolina Electric & Gas Co 83/09/30 1p 21796 243 24X Fiche 50-395, 84/01/13, 8401270377

--8401270392 Revised monthly operating rept for Oct 1983
LOIGNON, G A South Carolina Electric & Gas Co 83/10/31 1p 21796 244 24X Fiche 50-395, 84/01/13, 8401270377

--8401270393 Revised monthly operating rept for Nov 1983
LOIGNON, G A South Carolina Electric & Gas Co 83/11/30 1p 21796 245 24X Fiche 50-395, 84/01/13, 8401270377

8 Reportable occurrences, LERs & related correspondence

8401040399 LER 83-134/03L-0 on 831124, inner door of personnel hatch declared inoperable Caused by broken cam follower Door secured from inside containment & subsequently repaired W/831220 ltr
BOUKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/12/20 O'REILLY, J P Region 2, Office of Director 3pp 21707 085 24X Fiche 50-395, 83/12/20, 8401040399

8401040542 LER 83-133/03L-0 on 831123, boron injection tank (BIT) inadvertently diluted to 19,700 ppm while performing surveillance testing Caused by lifting of relief valve XVR-8925 Boron concentration restored W/831222 ltr
BOUKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/12/22 O'REILLY, J P Region 2, Office of Director 3pp 21705 351 24X Fiche 50-395, 83/12/22, 8401040542

8401050410 LER 83-136/03L-0 on 831112, vital instrumentation panel APN-5901 transferred to alternate power to accommodate mods to normal power source W/Train A RHR sys in svc, suction valve closed Caused by dead bus transfer W/831227 ltr
FIELDS, H C, DIXON, O W South Carolina Electric & Gas Co 83/12/27 O'REILLY, J P Region 2, Office of Director 3pp 21730 358 24X Fiche 50-395, 83/12/27, 8401050410

8401050443 LER 83-137/03L-0 on 831212, boric acid tank level indicator found out of calibr Caused by instrument drift Transmitter calibr No addl corrective action other than preventive maint & testing required W/831227 ltr
BOUKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/12/27 O'REILLY, J P Region 2, Office of Director 2pp 21730 135 24X Fiche 50-395, 83/12/27, 8401050443

8401050597 LER 83-135/03L-0 on 831201, supports RHH-134, 135 & 137 in RHR sys declared inoperable Cause under investigation Supports repaired, tested & declared operable W/831227 ltr
BOUKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co 83/12/27 O'REILLY, J P Region 2, Office of Director 2pp 21726 105 24X Fiche 50-395, 83/12/27, 8401050597

8401120357 RO on 831205, during surveillance testing, four tendons had lift off forces not exceeding 95% of base value Caused by redistribution of force along curved tendons set up during original stressing
DIXON, O W South Carolina Electric & Gas Co 84/01/04, O'REILLY, J P Region 2, Office of Director 3pp 21791 327 24X Fiche 50-395, 84/01/04, 8401120357

DOCKETED ITEMS

8401120410 LER 83-138/03L-0 on 831205 & 09, w/plant in Mode 5, GC personnel identified one frozen snubber & several rotated pipe clamps during hanger/snubber insp of feedwater & steam generator blowdown sys W/840104 ltr
FIELDS, H C, DIXON, D W South Carolina Electric & Gas Co 84/01/04
O'REILLY, J P Region 2, Office of Director 2pp 21791 145 24X
Fiche 50-395, 84/01/04, 8401120410

8401170209 LER 83-140/01Y-0 on 831224, instrument lines for refueling water storage tank level transmitters froze. Caused by abnormally cold temps. Heat applied to transmitters. Heat trace setpoint mods to be completed by 840120 W/840106 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co 84/01/06
O'REILLY, J P Region 2, Office of Director 3pp 21831 337 24X
Fiche 50-395, 84/01/06, 8401170209

8401240387 LER 83-139/03L-0 on 831214, remote info acquisition cabinet 12 tripped, causing intermediate bldg sprinkler sys to go into alarm mode. Caused by water entering panel & shorting out electronic cards. Cards replaced W/840109 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co 84/01/09
O'REILLY, J P Region 2, Office of Director 2pp 21916 057 24X
Fiche 50-395, 84/01/09, 8401240387

8401240123 LER 83-141/03L-0 on 831215, while in Mode 2, snubbers MSH-324 & MSH-325 declared inoperable. Caused by transient in 32-inch main steam line which induced B50 lb load in 4-inch line. Snubbers replaced W/840112 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co 84/01/12
O'REILLY, J P Region 2, Office of Director 2pp 21912 339 24X
Fiche 50-395, 84/01/12, 8401240123

8401240132 LER 83-142/03L-0 on 831216, identified leakage from RCS determined to be 10.4 gpm, exceeding Tech Spec limit. Caused by excessive leakage from seal 2 on reactor coolant pump C & packing leaks W/840113 ltr
MCKINNEY, C J, DIXON, D W South Carolina Electric & Gas Co 84/01/13
O'REILLY, J P Region 2, Office of Director 2pp 21912 291 24X
Fiche 50-395, 84/01/13, 8401240132

8401230398 Deficiency rept re broken strand wires on auxiliary switch mounted on OE air magnetic circuit breakers. Investigation determined defect not reportable per IOCFR21
SIMPSON, J W General Electric Co 84/01/17
DEYDUNG, R Director's Office, Office of Inspection and Enforcement 2pp 21880 354 24X
Fiche 50-395, 84/01/17, 8401230398

8401260081 Updated LER 83-076/03X-1 on 830707, pressurizer PORV PCV-444B-RC would not fully stroke when operated from main control board. Caused by low operating pressure. Regulator for PCV-444B-RC replaced W/840118 ltr
KOLB, L E, DIXON, D W South Carolina Electric & Gas Co 84/01/18
O'REILLY, J P Region 2, Office of Director 2pp 21957:017 24X
Fiche 50-395, 84/01/18, 8401260081

8401260022 LER 83-144/03L-0 on 831223, during normal operation, erratic behavior from power range nuclear instrument NT-42 necessitated quadrant power tilt ratio measurement. Cause unknown. Bistables placed in trip W/840120 ltr
FIELDS, H C, DIXON, D W South Carolina Electric & Gas Co 84/01/20
O'REILLY, J P Region 2, Office of Director 4pp 21956 306 24X
Fiche 50-395, 84/01/20, 8401260022

8401300241 LER 83-143/03L-0 on 831224, while in Mode 1, indication for condensate storage tank level transmitter LT-3621 failed high because of frozen instrument lines. Caused by abnormally cold temp. Heat trace setpoints increased. W/840123 ltr
BOUKNIGHT, R J, DIXON, D W South Carolina Electric & Gas Co 84/01/23
O'REILLY, J P Region 2, Office of Director 2pp 22062 096 24X
Fiche 50-395, 84/01/23, 8401300241

V. Operator Examinations

8401060501 Requests addl info by 831230 for operator requalification exams scheduled for 840202-03, per M Williams & T Morris telcon. Encl lists mail requested.
VERRELLI, D M, Division of Project & Resident Programs, 84/01/03
DIXON, D W South Carolina Electric & Gas Co App. 21739:346 24X
Fiche 50-395, 84/01/03, 8401060501

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8401030424 Responds to five issues raised by Coalition for Safe Power 2 204 petition dtd 831014 requesting NRC institute show cause proceedings to determine whether CP should be revoked. Request denied based on extensive review.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/20, ROSEB, E Coalition for Safe Power 7pp 21695:342 24X
Fiche 50-397, 83/12/20, 8401030424

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
HANNON, J Division of Licensing 84/01/17
Division of Licensing 1p 22000 349 24X
Fiche 50-000, 84/01/17, 8401270536

E NRC Safety Evaluation Report (SER), suppl's & correspondence

8401190090 Forwards SSER 4 (NUREG-0892) W/o encl
SCHWENCER, A Licensing Branch 2 83/12/29
SORENSEN, G C Washington Public Power Supply System 2pp 21870 252 24X
Fiche 50-397, 83/12/29, 8401190090

8401040036 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WPPSS NUCLEAR PROJECT NO 2 Docket No 50-397 (Washington Public Power Supply System)
* Division of Licensing NUREG-0892 804 83/12/31 142pp 21711 116 24X
Fiche 50-397, 83/12/31, 8401040036

8401300075 Informs that based on review of environ qualification files, equipment listed in App 3-B of SER (NUREG-0892) qualified for interim operations per 830916 & 1205 submittals.
SORENSEN, G C Washington Public Power Supply System 84/01/10
SCHWENCER, A Licensing Branch 4 2pp 21999 164 24X
Fiche 50-397, 84/01/10, 8401300075

8401240162 Suggests rev to SSER 4, NUREG-0892 Backup emergency operations facility (EOF) located 9.5 miles from plant. Facility should be referred to as location rather than backup EOF.
SORENSEN, G C Washington Public Power Supply System 84/01/19
SCHWENCER, A Licensing Branch 2 2pp 21910 294 24X
Fiche 50-397, 84/01/19, 8401240162

8401300062 Confirms completion of pipeline mounted equipment g value comparison program, in response to SSER 4, Section 3.10.1 & operator licensing item 2 C(5)(b). Uncompleted plant mods scheduled for completion prior to exceeding 5% power.
SORENSEN, G C Washington Public Power Supply System 84/01/23
SCHWENCER, A Licensing Branch 2 1p 21999 159 24X
Fiche 50-397, 84/01/23, 8401300062

8401310376 Advises that plant mods re final as-built stress reconciliation will be completed by 840131, per util 830616 & 0328 ltrs re hydrodynamic loads outside containment. Response resolves NUREG-0892, SER, Confirmatory Item 4.
SORENSEN, G C Washington Public Power Supply System 84/01/24
SCHWENCER, A Licensing Branch 2 3pp 22012:352 24X
Fiche 50-397, 84/01/24, 8401310376

F Security, medical, emergency & fire protection plans

8401050003 Releases public version of radiological emergency response plan.
FELTON, J M Division of Rules and Records 83/12/27
Document Management Branch, 1p 21733 001 24X
Fiche 50-397, 83/12/27, 8401050003

--8401050005 Public version of DOE, Richland Operations Ofc radiological emergency response plan W/831111 ltr.
FRELING, A G Energy, Dept of SORESEN, G C Washington Public Power Supply System 82/01/11
SCHWENCER, A Licensing Branch 2 353pp 21733 002 24X
Fiche 50-397, 83/12/27, 8401050005

8401200018 Forwards IE Insp Rept 50-397/83-55 on 831114-18. No noncompliance noted.
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/05
SORENSEN, G C Washington Public Power Supply System 2pp 21864 325 24X
Fiche 50-397, 84/01/05, 8401200018

--8401200022 IE Insp Rept 50-397/83-55 on 831114-18. No noncompliance noted. Major areas inspected: fire protection for associated nonsafety circuits.
SCDMN, K, PATE, R Region 5, Office of Director, 84/01/04 9pp 21864:327 24X
Fiche 50-397, 84/01/04, 8401200022

8401240162 Suggests rev to SSER 4, NUREG-0892 Backup emergency operations facility (EOF) located 9.5 miles from plant. Facility should be referred to as location rather than backup EOF.
SORENSEN, G C Washington Public Power Supply System 84/01/19
SCHWENCER, A Licensing Branch 2 2pp 21910 294 24X
Fiche 50-397, 84/01/19, 8401240162

8401310131 Forwards description of plant support facility & radiological programs instruction manual index, per 831131 request. Info will be included in rev to FBAR.
SORENSEN, G C Washington Public Power Supply System 84/01/24
SCHWENCER, A Licensing Branch 2 19pp 22022 080 24X
Fiche 50-397, 84/01/24, 8401310131

DOCKETED ITEMS

289

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REVOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds 84/01/19
CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X
Fiche 50-000, 84/01/19, 8401240335

J Insurance & indemnity information

8401060615 Unexecuted Amend 1 to Indemnity Agreement B-94
SALTZMAN, J Assistant Director for State & Licensee Relations
83/12/20 4pp 21755 115 24X Fiche 50-397, 83/12/20, 8401060615

8401090085 Requests change in annual indemnity fee for OL issuance
Power level of 57 reached
DINITZ, J Assistant Director for State & Licensee Relations
83/12/30 PUBLISE, A S Division of Accounting 1p 21757 264
24X Fiche 50-397, 83/12/30, 8401090085

8401110001 Forwards Endorsements 9-12 to NELIA Policy NF-270
ASHBURN, D J Marsh & McLennan, Inc 84/01/06 SALTZMAN, J
Assistant Director for State & Licensee Relations 3pp 21772 246
24X Fiche 50-397, 84/01/06, 8401110001

8401200069 Forwards declaration page to MAELU Policy NF-110
ASHBURN, D J Marsh & McLennan, Inc 84/01/10 SALTZMAN, J
Assistant Director for State & Licensee Relations 2pp 21867 019
24X Fiche 50-397, 84/01/10, 8401200069

8401180217 Forwards executed Amend 1 to Indemnity Agreement B-94,
deleting Items 2a & 3 re amount of financial protection &
license numbers & substituting Item 4 re site description
w/11sted change & amend to Item 5
SORENSEN, O C Washington Public Power Supply System 84/01/11
EISENHUT, D G Division of Licensing 4pp 21844 007 24X
Fiche 50-397, 84/01/11, 8401180217

8401200056 Forwards Endorsements 1 & 2 to NELIA Certificate N-91 &
Endorsements 1 & 2 to MAELU Certificate M-91
ASHBURN, D J Marsh & McLennan, Inc 84/01/11 SALTZMAN, J
Assistant Director for State & Licensee Relations 3pp 21867 021
24X Fiche 50-397, 84/01/11, 8401200056

P Operating license stage documents & correspondence

8401040307 Forwards seismic & operability qualification package for
containment purge & vent valves W/o encl
SORENSEN, O C Washington Public Power Supply System 83/12/19
SCHWENCER, A Licensing Branch 2 1p 21707 298 24X
Fiche 50-397, 83/12/19, 8401040307

8401170560 Forwards License NPF-21 for facility, environ protection
plan & Tech Specs (NUREG-1009) Pending Commission approval,
operation restricted to power levels not in excess of 5% of
full power Assessment of effect of license duration encl
EISENHUT, D G Division of Licensing 83/12/20 MAZUR, D W
Washington Public Power Supply System 9pp 21845 001 24X
Fiche 50-397, 83/12/20, 8401170560

8401170561 License NPF-21 for facility Tech Specs (NUREG-1009) encl
DENTON, H R Office of Nuclear Reactor Regulation, Director,
83/12/20 497pp 21845 010 24X Fiche 50-397, 83/12/20,
8401170560

8401170562 Environ protection plan (nonradiological)
* NRC - No Detailed Affiliation Given 83/12/20 13pp
21846 147 24X Fiche 50-397, 83/12/20, 8401170560

8401170563 Notice of issuance & availability of License NPF-21
SCHWENCER, A Licensing Branch 2 83/12/20 3pp 21846 160 24X
Fiche 50-397, 83/12/20, 8401170560

8401030270 Forwards proprietary claim filed w/Pittsburgh Des Moines
Steel Co representing costs incurred by util in repair &
replacement of work under contract, per 831220 conversation
Claim withheld (ref 10CFR2 790)
SORENSEN, O C Washington Public Power Supply System 83/12/22
EISENHUT, D G Division of Licensing 2pp 21861 285 24X
Fiche 50-397, 83/12/22, 8401030270

8401160477 TECHNICAL SPECIFICATIONS FOR WPPSS NUCLEAR PROJECT NO 2.
Docket No 50-397 (Washington Public Power Supply System)
HOFFMAN, D R Division of Licensing NUREG-1009 83/12/31 475pp
Available at NRC \$9 50 21824 299 24X Fiche 50-397, 83/12/31,
8401160477

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401160069 Confirms 831209 telcon re OE coupled piping & RHR HX
analysis results Analysis indicated increase in up loads
Original washer plate design adequate RHR addendum to
"Design Reverification Program," encl
SORENSEN, O C Washington Public Power Supply System 84/01/06
SCHWENCER, A Licensing Branch 2 2pp 21815 012 24X
Fiche 50-397, 84/01/06, 8401160069

8401160072 RHR addendum to "Design Verification Program"
DOUCHEY, D D Washington Public Power Supply System 83/12/30
37pp 21815 014 24X Fiche 50-397, 84/01/06, 8401160069

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401300066 Advises that, due to contract w/Chem Nuclear Sys, Inc to
process wet, solid radwaste, preoperational test for Waste
Concentrators PT 33 O-B will be suspended indefinitely
SORENSEN, O C Washington Public Power Supply System 84/01/17
SCHWENCER, A Licensing Branch 2 1p 21999 160 24X
Fiche 50-397, 84/01/17, 8401300066

8401300166 Advises that radiosensitive subcomponents in REA-8R-37
replaced, per util B31215 commitment & Reg Guide 1 97 re
equipment qualification
SORENSEN, O C Washington Public Power Supply System 84/01/18
SCHWENCER, A Licensing Branch 2 1p 21999 120 24X
Fiche 50-397, 84/01/18, 8401300166

8401300235 Application to amend License NPF-21, revising Tech Specs to
reflect reporting requirements of 10CFR50 73
SORENSEN, O C Washington Public Power Supply System 84/01/20
SCHWENCER, A Licensing Branch 2 1p 22062 065 24X
Fiche 50-397, 84/01/20, 8401300235

8401300236 Proposed Tech Specs reflecting reporting requirements of
10CFR50 73
* Washington Public Power Supply System 84/01/20 13pp
22062 066 24X Fiche 50-397, 84/01/20, 8401300235

8401310027 Application for amend to License NPF-21, revising Tech Specs
re intermediate-range noble gas activity monitor, LPCI sys
injection permissive, containment isolation for fluid sys &
diesel engine warmup period
SORENSEN, O C Washington Public Power Supply System 84/01/20,
SCHWENCER, A Licensing Branch 2 5pp 22023 354 24X
Fiche 50-397, 84/01/20, 8401310027

8401310028 Proposed Tech Specs re intermediate-range noble gas activity
monitor, LPCI sys injection permissive, containment isolation
for fluid sys & diesel engine warmup period
* Washington Public Power Supply System 84/01/20 10pp
22023 359 24X Fiche 50-397, 84/01/20, 8401310027

8401310021 Advises that program plan for detailed control room design
review will be submitted by 840220 Summary status of human
engineering deficiencies to be corrected prior to exceeding
5% rated thermal power submitted
SORENSEN, O C Washington Public Power Supply System 84/01/24
SCHWENCER, A Licensing Branch 2 2pp 22023 344 24X
Fiche 50-397, 84/01/24, 8401310021

8401310215 Informs that preoperational & acceptance tests scheduled to
be completed by 840301, before exceeding 5% power
Post-Accident Sampling Sys PT 106 O-E also scheduled to be
complete by 840301 Chemical waste processing test suspended,
SORENSEN, O C Washington Public Power Supply System 84/01/24
SCHWENCER, A Licensing Branch 2 1p 22021 160 24X
Fiche 50-397, 84/01/24, 8401310215

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge Ip 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982
e Director's Office, Office of Inspection and Enforcement.
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401030253 Act receipt of 831121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-14
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/12/21 SORENSEN, Q C Washington Public Power Supply System Ip 21681 157 24X Fiche 50-397, 83/12/21, 8401030253

--8401030254 Responds to NRC 830603 ltr re violations noted in IE Insp Rept 50-397/83-14 Corrective actions sampling plan developed to provide 95% confidence level that less than 5% defects exist in sample lot
SORENSEN, Q C Washington Public Power Supply System 83/11/21 MARTIN, J B Region 5, Office of Director 4pp 21681 158 24X Fiche 50-397, 83/12/21, 8401030253

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 165 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5MK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21824 060 24X Fiche 50-000, 83/12/30, 8312120093

8401200018 Forwards IE Insp Rept 50-397/83-55 on 831114-18 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/05 SORENSEN, Q C Washington Public Power Supply System 2pp 21864 325 24X Fiche 50-397, 84/01/05, 8401200018

--8401200022 IE Insp Rept 50-397/83-55 on 831114-18 No noncompliance noted Major areas inspected fire protection for associated nonsafety circuits
SCAMM, K., PATE, R Region 5, Office of Director 84/01/04 9pp 21864 327 24X Fiche 50-397, 84/01/05, 8401200018

8401200027 Forwards IE Insp Rept 50-397/83-59 on 831114-18 & 1205-08 No noncompliance noted.
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/05 SORENSEN, Q C Washington Public Power Supply System 2pp 21864 336 24X Fiche 50-397, 84/01/05, 8401200027

--8401200028 IE Insp Rept 50-397/83-59 on 831114-18 & 1205-08. No noncompliance noted Major areas inspected preoperational test results, followup items, TMI (NUREG-0737) activities, bulletins & circulars
WILLET, D J, DODDS, R Y Region 5, Office of Director 83/12/16 5pp 21864 358 24X Fiche 50-397, 84/01/05, 8401200027

8401200191 Forwards IE Insp Rept 50-397/83-56 on 831111-1216 No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/05 SORENSEN, Q C Washington Public Power Supply System 2pp 21863 284 24X Fiche 50-397, 84/01/05, 8401200191

--8401200193 IE Insp Rept 50-397/83-56 on 831111-1216. No noncompliance noted Major areas inspected const & preoperational testing activities, including licensee action on previous enforcement, unresolved & followup items.
DODDS, R Y, HATST, D P, BURDOIN, J F Region 5, Office of Director 84/01/05 21pp 21398 161 24X Fiche 50-397, 84/01/05, 8401200191

8401200072 Forwards IE Insp Rept 50-397/83-54 on 831103-1204. No noncompliance noted
BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/01/06 SORENSEN, Q C Washington Public Power Supply System 2pp 21865 171 24X Fiche 50-397, 84/01/06, 8401200072

8401200074 IE Insp Rept 50-397/83-54 on 831103-1204 No noncompliance noted Major areas inspected const quality reverification activities, status of previous insp findings & plant completion status.
TOTH, A D, DODDS, R Y Region 5, Office of Director 83/12/27 29pp 21865 173 24X Fiche 50-397, 84/01/06, 8401200072

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

B Reportable occurrences, LERs & related correspondence

8401040310 Final deficiency rept, Condition 302 re mode covering HPCS second level undervoltage protection producing potential conditions for HPCS pump to fail to start on valid initiation signal Design revised
SORENSEN, Q C Washington Public Power Supply System 83/12/09 MARTIN, J B Region 5, Office of Director 3pp 21708 110 24X Fiche 50-397, 83/12/09, 8401040310

8401040333 Final deficiency rept, Condition 306 re recombiner scrubber drainage impaired by design configuration of connections for water loop seal & process blower on recombiner skid Initially reported on 831215 Also reported per Part 21
SORENSEN, Q C Washington Public Power Supply System 83/12/16 MARTIN, J B Region 5, Office of Director 3pp 21705 068 24X Fiche 50-397, 83/12/16, 8401040333

8401040318 Revised final deficiency rept, Condition 260 re insufficient flow to HKs in standby svc water loops A & B B&R evaluating design error Also reported per Part 21
SORENSEN, Q C Washington Public Power Supply System 83/12/20 MARTIN, J B Region 5, Office of Director 3pp 21708 152 24X Fiche 50-397, 83/12/20, 8401040318

8401040379 Final deficiency rept, Condition 307 re Target Rock isolation valve B2H-002 on loop B not closing when deenergized Initially reported on 831219 Twelve valves disassembled, readjusted & reinstalled under vendor supervision
SORENSEN, Q C Washington Public Power Supply System 83/12/20 MARTIN, J B Region 5, Office of Director 3pp 21707 097 24X Fiche 50-397, 83/12/20, 8401040379

8401260072 LER 83-001/03L-0 on 831225 while loading first fuel bundle, rod block protective interlock lost caused by misinterpretation of Tech Spec intent Calibr & surveillance procedures changed 4/840109 ltr
REIS, M P, MARTIN, J B Washington Public Power Supply System 84/01/09 MARTIN, J B Region 5, Office of Director 3pp 21997 001 24X Fiche 50-397, 84/01/09, 8401260072

U Congressional/Executive Correspondence

8401190493 Responds to 830928 ltr posing questions re apparently improper release of draft documents to applicant by NRC inspector
FALLADINO, N J Commissioners 83/12/21 WEAVER, J House of Rep Interior & Insular Affairs 72pp 21857 207 24X Fiche 50-397, 83/12/21, 8401190493

--8401190497 Requests response to questions re apparently improper release of draft documents to applicant by NRC inspector also requested
WEAVER, J House of Rep Interior & Insular Affairs 83/09/28 FALLADINO, N J Commissioners 2pp 21857 355 24X Fiche 50-397, 83/12/21, 8401190493

DOCKETED ITEMS

291

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22034 358 24X
Fiche 50-000, 83/12/16, B312200154

B312120108 Board Notification B4-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, B312120108

B401050382 Generic Ltr B4-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401230007 Forwards revised "Mgt Capability Rept"
UTLEY, E E Carolina Power & Light Co 84/01/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21885 176 24X Fiche 50-400, 84/01/10, B401230007

--B401230009 Revised "Mgt Capability Rept"
* Carolina Power & Light Co 84/01/10 89pp 21885 178 24X
Fiche 50-400, 84/01/10, B401230007

B401270521 Notification of B40119 meeting w/util in Bethesda, MD to discuss design of alternate shutdown sys in event that control room unavailable
BUCKLEY, B C Licensing Branch 3 84/01/10 KNIGHTON, G W Licensing Branch 3 4pp 22000 358 24X Fiche 50-400, 84/01/10, B401270521

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401300184 Requests photographic matl re aerial radiological monitoring sys aerial survey, per B40118 telcon
CUTTER, A B Carolina Power & Light Co 84/01/24 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 21997 336 24X Fiche 50-400, 84/01/24, B401300184

D NRC Draft/Final Environmental Statements, suppl & correspondence

B401270555 Forwards errata to FEB Page 5-35 US population dose from exposure to radioactivity attributed to normal annual operation changed to be consistent w/correction to App D, Corrections to population densities converted to metric sys
KNIGHTON, G W Licensing Branch 3 84/01/12 UTLEY, E E Carolina Power & Light Co 5pp 22000 335 24X Fiche 50-400, 84/01/12, B401270555

F Security, medical, emergency & fire protection plans

B401050388 Ack receipt of B31209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/B3-29 & 50-401/B3-29
LEWIS, R C Division of Project & Resident Programs 83/12/22 UTLEY, E E Carolina Power & Light Co 1p 21731 105 24X
Fiche 50-400, 83/12/22, B401050388

--B401050392 Forwards IE Insp Repts 50-400/B3-29 & 50-401/B3-29 on B30920-1020 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/10 UTLEY, E E Carolina Power & Light Co 2pp 21731 109 24X
Fiche 50-400, 83/12/22, B401050388

--B401050395 Notice of violation from insp on B30920-1020
* Region 2, Office of Director 83/11/10 1p 21731 111 24X
Fiche 50-400, 83/12/22, B401050388

--B401050398 IE Insp Repts 50-400/B3-29 & 50-401/B3-29 on B30920-1020 Noncompliance noted failure to control fastening matl in fire protection & radwaste sys
MAXWELL, G F, PREVATTE, R L Region 2, Office of Director BENIS, P R Division of Project & Resident Programs 83/11/09, 8pp 21731 112 24X Fiche 50-400, 83/12/22, B401050388

B401050305 Forwards "Evacuation Time Estimates for Plume Exposure Pathway Emergency Planning Zone"
MCDOUFFIE, M A Carolina Power & Light Co 83/12/29 EISENHUT, D G Division of Licensing 1p 21726 161 24X Fiche 50-400, 83/12/29, B401050305

--B401050309 "Evacuation Time Estimates for Plume Exposure Pathway Emergency Planning Zone"
WATSON, J J, WELLS, R K, MARIMPIETRI, A HMM Associates, Inc 83/10/31 108pp 21726 162 24X Fiche 50-400, 83/12/29, B401050305

0 Adjudicatory correspondence

B401050209 Forwards addl documents cited in opposition to summary disposition of Contention 8F1
EDDLEMAN, W Eddleman, W 83/12/19 Atomic Safety and Licensing Board Panel 138pp 21727 343 24X Fiche 50-400, 83/12/19, B401050209

B401040122 Forwards SER W/a encl
BARTH, C A Hearing Branch 1, 83/12/29 KELLEY, J L, CARPENTER, J H, BRIGHT, G D Atomic Safety and Licensing Board Panel 1p 21702 056 24X Fiche 50-400, 83/12/29, B401040122

B401050304 Reply to ASLB B31130 questions on Eddleman Contention 64(f) re spent fuel shipping cask pressure relief valve
Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/12/29 7pp 21729 075 24X
Fiche 50-400, 83/12/29, B401050304

B401040118 Response to ASLB B31130 order re spent fuel shipping casks
Both questions answered in negative Certificate of Svc encl
BARTH, C A Hearing Branch 1 83/12/30 9pp 21703 225 24X
Fiche 50-400, 83/12/30, B401040118

B401060280 Motion to resume discovery on Joint Contentions I & VII re environ safety Filing of discovery requests by B40315 & responding to requests by B40416 recommended Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 84/01/03 Atomic Safety and Licensing Board Panel 7pp 21739 159 24X Fiche 50-400, 84/01/03, B401060280

B401060318 Confirms availability of draft offsite emergency response plans by mid-Feb 1984 Comprehensive schedule for emergency preparedness issues should not be amended until plans received Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co BAXTER, T A North Carolina Municipal Power Agencies 84/01/03 KELLEY, J L, BRIGHT, G D, CARPENTER, J H Atomic Safety and Licensing Board Panel 4pp 21740 152 24X
Fiche 50-400, 84/01/03, B401060318

B401090335 Response to summary disposition on Eddleman Contention 132 re safety parameter display sys Certificate of Svc encl
EDDLEMAN, W Eddleman, W 84/01/03 BRIGHT, G D, CARPENTER, J H, KELLEY, J L Atomic Safety and Licensing Board Panel, 2pp 21754 110 24X Fiche 50-400, 84/01/03, B401090335

--B401090346 Filing of new Contentions 169, 170, 171 & 172 re inadequate safety parameter display sys design
EDDLEMAN, W Eddleman, W 84/01/03 Atomic Safety and Licensing Board Panel 2pp 21754 112 24X Fiche 50-400, 84/01/03, B401090335

B401120337 Forwards affidavit of QA Schwenk Affidavit should be attached to NRC B31228 response in support of applicant motion for summary disposition of Chapel Hill Anti-Nuclear Group Effort Contention 44 & Eddleman Contention 132
BARTH, C A Hearing Branch 1 84/01/04 KELLEY, J L, CARPENTER, J H, BRIGHT, G D Atomic Safety and Licensing Board Panel 1p 21792 208 24X Fiche 50-400, 84/01/04, B401120337

DOCKETED ITEMS

--B401120342 Affidavit of GA Schwenk in support of summary disposition of Chapel Hill Anti-Nuclear Group Effort Contention 44 & Eddieleman Contention 132
SCHWENK, G A Core Performance Branch B4/01/04 4pp. 21792 209
24X Fiche: 50-400, B4/01/04, B401120337

B401100217 Revised response to Interrogatory 15AA(2d)-19(h) on Eddieleman Contention 15AA re cost of shutdown. Certificate of Svc encl Related correspondence
HOLLAR, D E Carolina Power & Light Co HOLLAR, D E Shaw, Pittman, Potts & Trowbridge B4/01/06 EDDLEMAN, W Eddieleman, W 3pp
21759 274 24X Fiche 50-400, B4/01/06, B401100217

B40110214 Motion for summary disposition of Joint Intervenor's Contention IV re TLDs. No genuine issue of matl fact exists & applicant entitled to favorable decision
ANDERSON, P H Shaw, Pittman, Potts & Trowbridge ANDERSON, P H Carolina Power & Light Co B4/01/09 Atomic Safety and Licensing Board Panel. 14pp. 21774-242 24X Fiche 50-400, B4/01/09, B40110214.

--B40110218 Affidavit of SA Browne re issues of TLD accuracy & real-time monitoring capability. Prof qualifications encl
BROWNE, B A Carolina Power & Light Co B4/01/04 19pp.
21774:256 24X Fiche: 50-400, B4/01/09, B40110214

--B40110224 Statement of matl facts as to which there is no genuine issue supporting motion for summary disposition of Joint Intervenor's Contention IV re TLDs. Certificate of Svc encl.
ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman, Potts & Trowbridge B4/01/09 Atomic Safety and Licensing Board Panel 7pp 21774 275. 24X Fiche 50-400, B4/01/09, B40110214.

B401170233 Motion for protective order to prevent public disclosure of info sought by W Eddieleman discovery requests.
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge. B4/01/13 Atomic Safety and Licensing Board Panel 11pp. 21831 260. 24X Fiche: 50-400, B4/01/13, B401170233

--B401170237 Affidavit of AR Pannill re privacy of employee records, supporting util request for protective order covering W Eddieleman interrogatories
PANNILL, A R Carolina Power & Light Co PANNILL, A R Daniel International (subs. of Fluor Corp.) B4/01/13 2pp. 21831-271
24X Fiche 50-400, B4/01/13, B401170233

--B401170239 Affidavit of JJ Schroeder supporting util request for protective order covering discovery request for info on employee records Proposed protective order & Certificate of Svc encl
SCHROEDER, J J Carolina Power & Light Co SCHROEDER, J J Daniel International (subs. of Fluor Corp.) B4/01/11 12pp 21831.273
24X Fiche. 50-400, B4/01/13, B401170233

B401170302 Supplemental response to general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc encl.
BAXTER, T A. Carolina Power & Light Co. BAXTER, T A. Shaw, Pittman, Potts & Trowbridge, B4/01/13. EDDLEMAN, W Eddieleman, W 7pp
21833.208. 24X Fiche 50-400, B4/01/13, B401170302.

B401250161 Forwards NRC response in support of applicant motion for summary disposition of Chapel Hill Anti-Nuclear Group Effort Contention 44 & Eddieleman Contention 132
MOORE, J. E. Hearing Branch 1 B4/01/13 KELLEY, J. L., BRIGHT, G O, CARPENTER, J. H Atomic Safety and Licensing Board Panel. 1p.
21937:145 24X Fiche: 50-400, B4/01/13, B401250161

B401230438 Motion for further deferral of parts of Contention 107 re unresolved safety issues SER inadequacies cannot be answered until SER received. Certificate of Svc encl.
EDDLEMAN, W Eddieleman, W. B4/01/17 Atomic Safety and Licensing Board Panel. 2pp 21880 329 24X Fiche. 50-400, B4/01/17, B401230438

--B401230443 New contentions & amended deferred contentions, in response to NRC SER.
EDDLEMAN, W Eddieleman, W B4/01/17. Atomic Safety and Licensing Board Panel 10pp 21880 331. 24X Fiche: 50-400, B4/01/17, B401230438.

1230391 Motion for summary disposition of Eddieleman Contention 65 re Daniel Intl history of faulty const No genuine issue of matl fact exists & applicant entitled to favorable decision.
BAXTER, T A Carolina Power & Light Co BAXTER, T A. Shaw, Pittman, Potts & Trowbridge. B4/01/18 Atomic Safety and Licensing Board Panel. 16pp 21873.298. 24X Fiche: 50-400, B4/01/18, B401230391.

--B401230395 Statement of matl facts as to which there is no genuine issue, in support of motion for summary disposition of Eddieleman Contention 65
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/18 Atomic Safety and Licensing Board Panel 3pp 21873 314 24X Fiche. 50-400, B4/01/18, B401230391

--B401230397 Affidavit of RM Parsons supporting applicant motion for summary disposition of Eddieleman Contention 65 Soniscopes exam of concrete containment structure unnecessary Prof qualifications & Certificate of Svc encl
PARSONS, R M Carolina Power & Light Co B4/01/17 19pp
21873 317 24X Fiche 50-400, B4/01/18, B401230391

B401230466 Forwards revised affidavit of AR Pannill, correcting minor typographical errors in B40113 affidavit filed w/applicant motion for protective order
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co B4/01/18 KELLEY, J. L., BRIGHT, G O, CARPENTER, J. H Atomic Safety and Licensing Board Panel 3pp
21882 167 24X Fiche 50-400, B4/01/18, B401230466

--B401230468 Corrected affidavit of AR Pannill re access to craft employment records of welders who installed facility pipe hangers
PANNILL, A R Carolina Power & Light Co PANNILL, A R Daniel International (subs. of Fluor Corp.) B4/01/13 2pp 21882 172
24X Fiche 50-400, B4/01/18, B401230466

B401260123 Response opposing Eddieleman Contentions 169-172 re safety parameter display sys Contentions wholly w/o basis, operate on faulty understanding of sys & should not be admitted Certificate of Svc encl
BAXTER, T A Consumers Power Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/23 Atomic Safety and Licensing Board Panel 14pp 21957 063 24X Fiche 50-400, B4/01/23, B401260123

B401270375 Response opposing applicant B40103 motion to resume discovery on Joint Contentions I & VII Response timely filed Discovery should resume by B40301 W/Certificate of Svc Related correspondence
READ, D F Joint Intervenor's - Shearon Harris B4/01/23 Atomic Safety and Licensing Board Panel 4pp 21976 113 24X Fiche. 50-400, B4/01/23, B401270375

B401260117 Interrogatories & request for production of documents re Eddieleman Contentions 9, 11 & 132C (II) Notice of appearance & Certificate of Svc encl
O'NEILL, T A Carolina Power & Light Co O'NEILL, T A Shaw, Pittman, Potts & Trowbridge B4/01/24 EDDLEMAN, W Eddieleman, W 23pp 21957 077 24X Fiche 50-400, B4/01/24, B401260117.

B401310262 Memorandum & order ruling on motions for summary disposition of Joint Contention II & Eddieleman Contentions 37B, 8F(1) & 8F(2) re health effects
KELLEY, J. L., CARPENTER, J. H., BRIGHT, G O Atomic Safety and Licensing Board Panel B4/01/27. Office of the Executive Legal Director 52pp 22021 227 24X Fiche: 50-400, B4/01/27, B401310262.

K. Utility Final Safety Analysis Report (FSAR) & amends

B401230470 Forwards Amend 11 to FSAR, consisting of miscellaneous technical changes, revised position on reg guides & editorial changes & revised pages incorporating hafnium control rods into plant design
MCDOUFFIE, M A Carolina Power & Light Co B4/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 21879:191
24X Fiche 50-400, B4/01/17, B401230470

--B401230474 Amend 11 to FSAR
* Carolina Power & Light Co B4/01/17 496pp 21879 193 24X Fiche 50-400, B4/01/17, B401230470.

B401310015 Informs of distribution of Amend 11 to FSAR individuals on attached distribution list
ZIMMERMAN, S R Carolina Power & Light Co B4/01/23 EISENHUT, D O Division of Licensing 4pp. 22024 046 24X Fiche: 50-400, B4/01/23, B401310015

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744.003 24X Fiche. 50-000, B3/10/20, B401060040

DOCKETED ITEMS

29

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 13pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

8401050488 Forwards IE Insp Repts 50-400/83-32 & 50-401/83-32 on
831107-10 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/06
UTLEY, E E Carolina Power & Light Co 2pp 21726 001 24X
Fiche 50-400,83/12/06,8401050488

--8401050504 IE Insp Repts 50-400/83-32 & 50-401/83-32 on 831107-10 No
violations noted Major areas inspected structural concrete
& soil compaction controls
HARRIS, J R, CONLON, T E Region 2, Office of Director 83/12/02
4pp 21726 003 24X Fiche 50-400,83/12/06,8401050488

8401050388 Ack receipt of 831209 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-400/83-29 &
50-401/83-29
LEWIS, R C Division of Project & Resident Programs 83/12/22
UTLEY, E E Carolina Power & Light Co 1p 21731 105 24X
Fiche 50-400,83/12/22,8401050388

--8401050390 Responds to NRC 831110 ltr re violations noted in IE Insp
Rept 50-400/83-29 Corrective actions "Q" bolts purchased
to eliminate need for distinguishing between "Q" bolts &
"non-Q" bolts
PARSONS, R M Carolina Power & Light Co 83/12/09 O'REILLY, J P
Region 2, Office of Director 3pp 21731 106 24X
Fiche 50-400,83/12/22,8401050388

--8401050392 Forwards IE Insp Repts 50-400/83-29 & 50-401/83-29 on
830920-1020 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/10
UTLEY, E E Carolina Power & Light Co 2pp 21731:109 24X
Fiche 50-400,83/12/22,8401050388

--8401050395 Notice of violation from insp on 830920-1020
* Region 2, Office of Director 83/11/10 1p 21731 111 24X
Fiche 50-400,83/12/22,8401050388

--8401050398 IE Insp Repts 50-400/83-29 & 50-401/83-29 on 830920-1020
Noncompliance noted failure to control fastening matl in
fire protection & radwaste sys
MAXWELL, O F, PREVATTE, R L Region 2, Office of Director
BEMIS, P R Division of Project & Resident Programs 83/11/09
8pp 21731 112 24X Fiche 50-400,83/12/22,8401050388

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp 21746 053 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp, 21826, 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21937 142 24X Fiche 50-000,84/01/16,8312120114

840130002B Notification of 840126 meeting w/utls & Transamerica
Delaval, Inc (TDI) in Bethesda, MD to discuss actions required
to address insp results & operating experience re TDI
emergency diesel generators
CARUSO, R. Licensing Branch 2, 84/01/17 SCHWENGER, A Licensing
Branch 2 21pp, 22027 009 24X Fiche 50-000,84/01/17,840130002B

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

R Periodic operating reports & related correspondence

8401310399 "Quarterly Data Rept Seismic Monitoring Program, Oct-Dec
1983 "
ZIMMERMAN, S R Carolina Power & Light Co 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 22012 360
24X Fiche 50-400,84/01/23,8401310399

8401310245 Forwards revised "Quarterly Data Rept, Seismic Monitoring
Program, Oct-Dec 1983 "
ZIMMERMAN, S R Carolina Power & Light Co 84/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 22018 327 24X
Fiche 50-400,84/01/26,8401310245

--8401310246 Revised "Quarterly Data Rept, Seismic Monitoring Program,
Oct-Dec 1983 "
* Carolina Power & Light Co 83/12/31 1p 22018 328 24X
Fiche 50-400,84/01/26,8401310245

S Reportable occurrences, LERs & related correspondence

8401050461 Second interim deficiency & Part 21 repts, Item 100 re solid
state protection sys supplied by Westinghouse Vendor
reviewing design prior to change recommendations Test
procedures revised Final rept by 841230
PARSONS, R M Carolina Power & Light Co 83/12/22 O'REILLY, J P
Region 2, Office of Director 4pp 21730 210 24X
Fiche 50-400,83/12/22,8401050461

8401050627 Final deficiency rept re Class IE cable in engine & panel
circuits failing IEEE 383 insulation flame test Transamerica
Delaval monitoring replacement Replacement expected by
840131
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/22
KEPPLER, J G Region 3, Office of Director 2pp 21726:075 24X
Fiche 50-400,83/12/22,8401050627

8401050470 Fourth interim deficiency rept, Item 117 re welding on
Siemens-Aluis & 9-kV switchgear breakers Initially reported
on 830211 All Class IE breakers returned to vendor Final
rept expected by 840229 Also reportable per Part 21
PARSONS, R M Carolina Power & Light Co 83/12/28 O'REILLY, J P
Region 2, Office of Director 4pp 21730 201 24X
Fiche 50-400,83/12/28,8401050470

8401060420 Fourth interim deficiency rept re potential failure of
Westinghouse gate valves to close under design conditions
Initially reported on 801128 Changes completed Final rept by
840301 Also reported per Part 21
PARSONS, R M Carolina Power & Light Co 83/12/29 O'REILLY, J P
Region 2, Office of Director 3pp 21741 004 24X
Fiche 50-400,83/12/29,8401060420

8401170006 Deficiency rept re bolts installed on seismic ductwork w/o
ASTM A-307 Grade A marking requirement Initially reported on
840105 Item evaluated & considered not reportable per
10CFR50.55(e) & Part 21
GHIANI, M J Carolina Power & Light Co 84/01/09 O'REILLY, J P
Region 2, Office of Director 1p 21827 130 24X
Fiche 50-400,84/01/09,8401170006

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by
Lovejoy Coupling & installed by Transamerica Delaval on
shafts in overspeed governor fuel transfer pump drive Insp
of hubs in listed facilities recommended Utls notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's
Office, Office of Inspection and Enforcement 5pp 21828 269 24X
Fiche 50-000,84/01/09,8401170186

8401240506 Third interim deficiency rept, Item 104 re welding for 480-
volt Class IE switchgear & seismically-designed 480-volt
non-Class IE switchgear from Brown-Boveri Electric Co
Initially reported on 830304 Defective welds repaired
PARSONS, R M Carolina Power & Light Co 84/01/11 O'REILLY, J P
Region 2, Office of Director 4pp 21920:057 24X
Fiche 50-400,84/01/11,8401240506

8401260354 Interim deficiency rept, Item 157 re failure of actuators
supplied by Ruskin Mfg Co to meet functional test
requirements of GH Bettis Co. Initially reported on 831221
Next rept by 840220 Also reported under Part 21
PARSONS, R M Carolina Power & Light Co 84/01/18 O'REILLY, J P
Region 2, Office of Director 1p 21935 207 24X
Fiche 50-400,84/01/18,8401260354

DOCKETED ITEMS

8401260103 Second interim deficiency rept, Item 112, re bolted structural steel connections w/flame cut bolt holes & undersized bolts Initially reported on 830426 Undersized bolts replaced All but three connections repaired Final rept by 840601 PARSONS, R M Carolina Power & Light Co 84/01/20 O'REILLY, J P Region 2, Office of Director 4pp 21937 100 24X Fiche 50-400, 84/01/20, 8401260103

8401260176 Second interim deficiency rept, Item 92 re bolted structural connections w/excessive gaps & ASTM A325 nuts on ASTM A490 bolts. Initially reported on 820702 Procedures revised to require insp for mating surface gaps during erection PARSONS, R M Carolina Power & Light Co 84/01/20 O'REILLY, J P Region 2, Office of Director 4pp 21936 087 24X Fiche 50-400, 84/01/20, 8401260176

8401260356 Second interim deficiency rept, Item 102 re grease in friction-type structural connections Initially reported on 830426 Site work & technical procedures revised. Final rept will be submitted by 840601 PARSONS, R M Carolina Power & Light Co 84/01/20 O'REILLY, J P Region 2, Office of Director 4pp 21935 220 24X Fiche 50-400, 84/01/20, 8401260356

T. Hearing transcripts on non-antitrust matters

8401090234 Transcript of ACRS Subcommittee on Shearon Harris 840103 meeting in Apex, NC Pp 1-189 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 84/01/03 375pp 21749 226 24X Fiche 50-400, 84/01/03, 8401090234

8401090082 Transcript of ACRS Subcommittee on Shearon Harris Nuclear Plant 840104 meeting in Apex, NC Pp 190-356 * ACRS - Advisory Committee on Reactor Safeguards 83/01/04 169pp 21749:001 24X Fiche 50-400, 84/01/04, 8401090082

8401160149 Transcript of ACRS 285th general meeting on 840112 in Washington, DC Pp 1-260 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 84/01/12 346pp. 21809:001 24X Fiche 50-400, 84/01/12, 8401160149

V. Operator Examinations

8401060352 Requests that facility furnish selected ref matl from approved encl list by 840120. Written exams scheduled for 840321. Applications for instructor certifications should be submitted 60 days prior to exam date VERRELL, J. D M. Division of Project & Resident Programs 84/01/03 UTLEY, E. E Carolina Power & Light Co 4pp 21741.167 24X Fiche 50-400, 84/01/03, 8401060352.

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

1. Application/construction stage documents & correspondence

1312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22054 39B 24X Fiche 50-000, 83/12/16, 8312200154

312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems. EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp. 21973 324 24X Fiche 50-000, 84/01/05, 8312120108

NRC Draft/Final Environmental Statements, supp's & correspondence

101270555 Forwards errata to FEB Page 5-35 US population dose from exposure to radioactivity attributed to normal annual operation changed to be consistent w/correction to App D Corrections to population densities converted to metric sys KNIGHTON, Q W Licensing Branch 3 84/01/12 UTLEY, E. E Carolina Power & Light Co. 5pp. 22000.335 24X Fiche 50-400, 84/01/12, 8401270555.

Security, medical, emergency & fire protection plans

01050305 Forwards "Evacuation Time Estimates for Plume Exposure Pathway Emergency Planning Zone." VODUFFIE, M A Carolina Power & Light Co 83/12/29 EISENHUT, D O Division of Licensing 1p. 21726 161. 24X Fiche 50-400, 83/12/29, 3401050305

--8401050309 "Evacuation Time Estimates for Plume Exposure Pathway Emergency Planning Zone " WATSON, J J, WELLS, R K, MARIMPIETRI, A HMM Associates, Inc 83/10/31 108pp 21726 162 24X Fiche 50-400, 83/12/29, 8401050309

G. Adjudicatory correspondence

8401050209 Forwards addl documents cited in opposition to summary disposition of Contention 8F1 EDDLEMAN, W Eddleman, W 83/12/19 Atomic Safety and Licensing Board Panel 138pp 21727 343 24X Fiche 50-400, 83/12/19, 8401050209

8401040122 Forwards SER W/o encl BARTH, C A Hearing Branch 1 83/12/29 KELLEY, J L, CARPENTER, J H, BRIGHT, G O Atomic Safety and Licensing Board Panel 1p 21702 056 24X Fiche 50-400, 83/12/29, 8401040122

8401050304 Reply to ASLB 831130 questions on Eddleman Contention 84(F) re spent fuel shipping cask pressure relief valve Certificate of Svc encl O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/12/29 7pp 21729 075 24X Fiche 50-400, 83/12/29, 8401050304

8401040118 Response to ASLB 831130 order re spent fuel shipping casks Both questions answered in negative Certificate of Svc encl BARTH, C A Hearing Branch 1 83/12/30 9pp 21703 225 24X Fiche 50-400, 83/12/30, 8401040118

8401060280 Motion to resume discovery on Joint Contentions I & VII re environ safety Filing of discovery requests by 840315 & responding to requests by 840416 recommended Certificate of Svc encl BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 84/01/03 Atomic Safety and Licensing Board Panel 7pp 21739 159 24X Fiche 50-400, 84/01/03, 8401060280

8401060318 Confirms availability of draft offsite emergency response plans by mid-Feb 1984 Comprehensive schedule for emergency preparedness issues should not be amended until plans received Svc list encl BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co BAXTER, T A North Carolina Municipal Power Agencies 84/01/03 KELLEY, J L, BRIGHT, G O, CARPENTER, J H Atomic Safety and Licensing Board Panel 4pp 21740 152 24X Fiche 50-400, 84/01/03, 8401060318

8401120337 Forwards affidavit of GA Schwenk Affidavit should be attached to NRC 831228 response in support of applicant motion for summary disposition of Chapel Hill Anti-Nuclear Group Effort Contention 44 & Eddleman Contention 132 BARTH, C A Hearing Branch 1 84/01/04 KELLEY, J L, CARPENTER, J H, BRIGHT, G O Atomic Safety and Licensing Board Panel 1p 21792 208 24X Fiche 50-400, 84/01/04, 8401120337

--8401120342 Affidavit of GA Schwenk in support of summary disposition of Chapel Hill Anti-Nuclear Group Effort Contention 44 & Eddleman Contention 132 SCHWENK, G A Core Performance Branch 84/01/04 4pp 21792 209 24X Fiche 50-400, 84/01/04, 8401120337

8401100217 Revised response to Interrogatory 15AA(2d)-19(h) on Eddleman Contention 15AA re cost of shutdown Certificate of Svc encl Related correspondence HOLLAR, D E Carolina Power & Light Co HOLLAR, D E Shaw, Pittman, Potts & Trowbridge 84/01/06 EDDLEMAN, W Eddleman, W 5pp 21759 274 24X Fiche 50-400, 84/01/06, 8401100217

8401100214 Motion for summary disposition of Joint Intervenor's Contention IV re TLDs No genuine issue of matl fact exists & applicant entitled to favorable decision ANDERSON, P H Shaw, Pittman, Potts & Trowbridge ANDERSON, P H Carolina Power & Light Co 84/01/09 Atomic Safety and Licensing Board Panel 14pp 21774 242 24X Fiche 50-400, 84/01/09, 8401100214.

--8401100218 Affidavit of SA Browne re issues of TLD accuracy & real-time monitoring capability Prof qualifications encl BROWNE, S A Carolina Power & Light Co 84/01/04 19pp 21774 256 24X Fiche 50-400, 84/01/09, 8401100214

--8401100224 Statement of matl facts as to which there is no genuine issue supporting motion for summary disposition of Joint Intervenor's Contention IV re TLDs Certificate of Svc encl ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 84/01/09 Atomic Safety and Licensing Board Panel 7pp 21774 275 24X Fiche 50-400, 84/01/09, 8401100214

B401170233 Motion for protective order to prevent public disclosure of info sought by W Eddleman discovery requests
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/13 Atomic Safety and Licensing Board Panel 11pp 21831 260 24X Fiche 50-400, B4/01/13, B401170233

--B401170237 Affidavit of AR Pannill re privacy of employee records, supporting util request for protective order covering W Eddleman interrogatories
PANNILL, A R Carolina Power & Light Co PANNILL, A R Daniel International (subs of Fluor Corp) B4/01/13 2pp 21831 271 24X Fiche 50-400, B4/01/13, B401170233

--B401170239 Affidavit of JJ Schroeder supporting util request for protective order covering discovery request for info on employee records Proposed protective order & Certificate of Svc encl
SCHROEDER, J J Carolina Power & Light Co SCHROEDER, J J Daniel International (subs of Fluor Corp) B4/01/11 12pp 21831 273 24X Fiche 50-400, B4/01/13, B401170233

B401170302 Supplemental response to general interrogatories & Interrogatories on Contentions 41 & 65 Certificate of Svc encl
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/13 EDDLEMAN, W Eddleman, W 7pp 21833 208 24X Fiche 50-400, B4/01/13, B401170302

B401250161 Forwards NRC response in support of applicant motion for summary disposition of Chaple Hill Anti-Nuclear Group Effort Contention 44 & Eddleman Contention 132
MOORE, J E Hearing Branch 1 B4/01/13 KELLEY, J L, BRIGHT, G O, CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 21937 145 24X Fiche 50-400, B4/01/13, B401250161

B401230391 Motion for summary disposition of Eddleman Contention 65 re Daniel Intl history of faulty const No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/18 Atomic Safety and Licensing Board Panel 16pp 21873 298 24X Fiche 50-400, B4/01/18, B401230391

--B401230395 Statement of matl facts as to which there is no genuine issue, in support of motion for summary disposition of Eddleman Contention 65
BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/18 Atomic Safety and Licensing Board Panel 3pp 21873 314 24X Fiche 50-400, B4/01/18, B401230391

--B401230397 Affidavit of RM Parsons supporting applicant motion for summary disposition of Eddleman Contention 65 Soniscope exam of concrete containment structure unnecessary Prof qualifications & Certificate of Svc encl
PARSONS, R M Carolina Power & Light Co B4/01/17 19pp 21873 317 24X Fiche 50-400, B4/01/18, B401230391

B401230466 Forwards revised affidavit of AR Pannill, correcting minor typographical errors in B40113 affidavit filed w/applicant motion for protective order
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Carolina Power & Light Co B4/01/18 KELLEY, J L, BRIGHT, G O, CARPENTER, J H Atomic Safety and Licensing Board Panel 3pp 21882 169 24X Fiche 50-400, B4/01/18, B401230466

--B401230468 Corrected affidavit of AR Pannill re access to craft employment records of welders who installed facility pipe hangers.
PANNILL, A R Carolina Power & Light Co PANNILL, A R Daniel International (subs of Fluor Corp) B4/01/13 2pp 21882 172 24X Fiche 50-400, B4/01/18, B401230466

B401260123 Response opposing Eddleman Contentions 169-172 re safety parameter display sys Contentions wholly w/o basis, operate on faulty understanding of sys & should not be admitted Certificate of Svc encl
BAXTER, T A Consumers Power Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge B4/01/23 Atomic Safety and Licensing Board Panel 14pp 21937 063 24X Fiche 50-400, B4/01/23, B401260123

B401270375 Response opposing applicant B40103 motion to resume discovery on Joint Contentions I & VII Response timely filed Discovery should resume by B40301 W/Certificate of Svc Related correspondence
READ, D F Joint Intervenor - Shearon Harris B4/01/23 Atomic Safety and Licensing Board Panel 4pp 21976 113 24X Fiche: 50-400, B4/01/23, B401270375

B401260117 Interrogatories & request for production of documents re Eddleman Contentions 9, 11 & 132C (II) Notice of appearance & Certificate of Svc encl
O'NEILL, T A Carolina Power & Light Co O'NEILL, T A Shaw, Pittman, Potts & Trowbridge B4/01/24 EDDLEMAN, W Eddleman, W 23pp 21957 077 24X Fiche 50-400, B4/01/24, B401260117

B401310262 Memorandum & order ruling on motions for summary disposition of Joint Contention II & Eddleman Contentions 37B, 8F(1) & 8F(2) re health effects
KELLEY, J L, CARPENTER, J H, BRIGHT, G O Atomic Safety and Licensing Board Panel B4/01/27 Office of the Executive Legal Director 52pp 22021 227 24X Fiche 50-400, B4/01/27, B401310262

0 Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records B3/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, B3/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement B3/10/20 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040

B401050488 Forwards IE Insp Repts 50-400/B3-32 & 50-401/B3-32 on B31107-10 No violations noted.
VERRELLI, D M Division of Project & Resident Programs B3/12/06 UTLEY, E E Carolina Power & Light Co 2pp 21726 001 24X Fiche 50-400, B3/12/06, B401050488

--B401050504 IE Insp Repts 50-400/B3-32 & 50-401/B3-32 on B31107-10 No violations noted. Major areas inspected structural concrete & soil compaction controls.
HARRIS, J R, CONLON, T E Region 2, Office of Director. B3/12/02 4pp 21726 003 24X Fiche 50-400, B3/12/06, B401050488

B401050388 Ack receipt of B31209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/B3-29 & 50-401/B3-29
LEWIS, R C Division of Project & Resident Programs B3/12/22 UTLEY, E E Carolina Power & Light Co 1p. 21731 105 24X Fiche 50-400, B3/12/22, B401050388

--B401050392 Forwards IE Insp Repts 50-400/B3-29 & 50-401/B3-29 on B30920-1020 & notice of violation
LEWIS, R C Division of Project & Resident Programs B3/11/10. UTLEY, E E Carolina Power & Light Co 2pp 21731 109 24X Fiche 50-400, B3/12/22, B401050388

--B401050398 IE Insp Repts 50-400/B3-29 & 50-401/B3-29 on B30920-1020 Noncompliance noted: failure to control fastening matl in fire protection & radwaste sys
MAXWELL, G F, PREVATTE, R L Region 2, Office of Director. BEMIS, P R Division of Project & Resident Programs B3/11/09 8pp 21731 112 24X Fiche 50-400, B3/12/22, B401050388

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement B3/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, B3/12/28, B312120090.

B312120093 IE Info Notice B3-B4, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, B3/12/30, B312120093

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401300028 Notification of B40126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R Licensing Branch 2 B4/01/17. SCHWENGER, A, Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, B4/01/17, B401300028

B Reportable occurrences, LERs & related correspondence

B401060420 Fourth interim deficiency rept re potential failure of Westinghouse gate valves to close under design conditions Initially reported on B01128. Changes completed Final rept by B40301 Also reported per Part 21
PARSONS, R M Carolina Power & Light Co B3/12/29. O'REILLY, J P Region 2, Office of Director. 9pp 21741:004 24X Fiche 50-400, B3/12/29, B401060420

DOCKETED ITEMS

8401170186 Part 21 rept re loose flexible coupling drive hubs.mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000, 84/01/09, 8401170186

T Hearing transcripts on non-antitrust matters

8401090234 Transcript of ACRS Subcommittee on Shearon Harris 840103 meeting in Apex, NC Pp 1-189 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/03 375pp 21749 226 24X Fiche 50-400, 84/01/03, 8401090234

8401090082 Transcript of ACRS Subcommittee on Shearon Harris Nuclear Plant 840104 meeting in Apex, NC Pp 190-356
* ACRS - Advisory Committee on Reactor Safeguards 83/01/04 169pp 21749 001 24X Fiche 50-400, 84/01/04, 8401090082

8401160149 Transcript of ACRS 285th general meeting on 840112 in Washington, DC Pp 1-260 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/12 345pp 21809 001 24X Fiche 50-400, 84/01/12, 8401160149

V Operator Examinations

8401060352 Requests that facility furnish selected ref matl from approved encl list by 840120 Written exams scheduled for 840321 Applications for instructor certifications should be submitted 60 days prior to exam date
VERRELLI, D M Division of Project & Resident Programs 84/01/03, UTLEY, E E Carolina Power & Light Co 4pp 21741 167 24X Fiche 50-400, 84/01/03, 8401060352

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

S Reportable occurrences, LERs & related correspondence

8401170186 Part 21 rept re loose flexible coupling drive hubs.mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp, 21828 269 24X Fiche 50-000, 84/01/09, 8401170186

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

S Reportable occurrences, LERs & related correspondence

8401170186 Part 21 rept re loose flexible coupling drive hubs.mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000, 84/01/09, 8401170186

DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8401240443 Forwards IE Insp Rept 50-406/83-01 on 831214-15 No violation noted.
LEWIS, R C Division of Project & Resident Programs 83/12/28
HARRIS, V O Tuskegee Institute, Tuskegee Institute, AL 1p 21920 137 24X Fiche 50-406, 83/12/28, 8401240443

--8401240452 IE Insp Rept 50-406/83-01 on 831214-15 No violations noted Major areas inspected documentation & verification to assure no nuclear fuel present Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL, B L Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/12/27 1p 21920 138 24X Fiche 50-406, 83/12/28, 8401240443

G Inspection reports, IE Bulletins & correspondence

8401240443 Forwards IE Insp Rept 50-406/83-01 on 831214-15 No violation noted
LEWIS, R C Division of Project & Resident Programs 83/12/28
HARRIS, V O Tuskegee Institute, Tuskegee Institute, AL 1p 21920 137 24X Fiche 50-406, 83/12/28, 8401240443

--8401240452 IE Insp Rept 50-406/83-01 on 831214-15 No violations noted Major areas inspected documentation & verification to assure no nuclear fuel present Details withheld (ref 10CFR2 790 & 10CFR73 21)
HALL, B L Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/12/27 1p 21920 138 24X Fiche 50-406, 83/12/28, 8401240443

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

V Operator Examinations

8401300111 Requests withdrawal of OL applications for B Vaseghi & Bonabian Students wish to improve knowledge of NRC regulations before taking exam
SANDQUIST, O M Utah, Univ of, Salt Lake City, UT 84/01/23
Office of Nuclear Reactor Regulation, Director 1p 21999 109 24X Fiche 50-407, 84/01/23, 8401300111

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8401190360 Forwards IE Insp Rept 50-409/83-20 on 831206-07 No noncompliance noted Response to encl exercise weaknesses requested within 30 days
PAPERIELLO, C J Region 3, Office of Director 83/12/15
LINDER, F W Dairyland Power Cooperative 3pp 21850 179 24X Fiche 50-409, 83/12/15, 8401190360

--8401190364 IE Insp Rept 50-409/83-20 on 831206-07 No noncompliance noted Major areas inspected; emergency preparedness exercise
SNELL, W, PATTERSON, J, KERS, L Region 3, Office of Director 83/12/16 7pp 21850 182 24X Fiche 50-409, 83/12/15, 8401190360

8401230326 Notifies that FEMA will host radiological emergency preparedness program meetings on 840112 & 13 at Ramada Inn, D'Hane Motel Util emergency preparedness planners requested to attend 840112 afternoon session Agenda encl
PAPERIELLO, C J Region 3, Office of Director 84/01/05
LINDER, F W Dairyland Power Cooperative 3pp 21864 229 24X Fiche 50-409, 84/01/05, 8401230326

8401250012 Releases public version of revised emergency plan procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21952 155 24X Fiche 50-409, 84/01/18, 8401250012

--8401250364 Forwards public version of Issue 12 to Emergency Plan Procedure EPP-2, "Organization & Operations During Emergencies" & Issue 2 to EPP-14, "Emergency Plan Training"
LINDER, F W Dairyland Power Cooperative 83/12/08 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21952 156 24X Fiche 50-409, 84/01/18, 8401250012

--8401250369 Public version of Issue 12 to Emergency Plan Procedure EPP-2, "Organization & Operations During Emergencies" & Issue 2 to EPP-14, "Emergency Plan Training"
* Dairyland Power Cooperative 83/12/05 26pp 21952 150 24X Fiche 50-409, 84/01/18, 8401250012

8401260014 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21989 358 24X Fiche 50-409, 84/01/18, 8401260014

--8401260017 Forwards public version of Issue 4 to Emergency Plan Implementing Procedure EPP-5, "Estimate of Offsite Dose" & Issue 1 to Procedure EPP-12, "Personnel Decontamination Procedure"
LINDER, F W Dairyland Power Cooperative 83/11/10 CRUTCHFIELD, D Operating Reactors Branch 5 1p 21992 004 24X Fiche 50-409, 84/01/18, 8401260014

--8401260021 Public version of Issue 4 to Emergency Plan Implementing Procedure EPP-5, "Estimate of Offsite Dose" & Issue 1 to Procedure EPP-12, "Personnel Decontamination Procedure"
SHAFFER, P W Dairyland Power Cooperative 83/10/24 49pp 21992 006 24X Fiche 50-409, 84/01/18, 8401260014

8401300007 Forwards IE Safeguards Insp Rept 50-409/84-01 on 840109-13 No noncompliance noted
AXELSON, W L Region 3, Office of Director 84/01/24 LINDER, F W Dairyland Power Cooperative 2pp 21999 230 24X Fiche 50-409, 84/01/24, 8401300007

DOCKETED ITEMS

297

--B401300008 IE Safeguards Insp Rept 50-409/84-01 on 840109-13 No noncompliance noted Major areas inspected security organization, security program audit, testing & maint & physical barriers Details withheld (ref 10CFR73.21)
BELANGER, J. L., CREED, J. R. Region 3, Office of Director 84/01/24
1p 21999 232 24X Fiche 50-409, 84/01/24, 8401300007

P Operating license stage documents & correspondence

B401030201 Forwards "Repair of 1B Forced Circulation Pump Discharge Valve Bypass Line Weld, 92A " No pipings or fittings replaced Insp conducted per NUREG-0313
LINDER, F. Dairyland Power Cooperative 83/12/21 NRC - No Detailed Affiliation Given 2pp 21682 297 24X
Fiche 50-409, 83/12/21, 8401030201

--B401030206 "Repair of 1B Forced Circulation Pump Discharge Valve Bypass Line Weld, 92A "
TOWSLEY, H. A. Dairyland Power Cooperative LAC-TR-120 83/12/31
6pp 21682 299 24X Fiche 50-409, 83/12/21, 8401030201

B401130207 Responds to request for review of certain differences between current guidelines for new reactor const & original const stds, per SEP integrated plant safety assessment (NUREG-0827) Summary of proposed actions encl
LINDER, F. Dairyland Power Cooperative 83/12/29 CRUTCHFIELD, D. Operating Reactors Branch 5 153pp 21799 001 24X
Fiche 50-409, 83/12/29, 8401130207

B401030303 Forwards exemption from licensed operator staffing rule in response to 830825 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/12/30 LINDER, F. Dairyland Power Cooperative 2pp 21729 049 24X
Fiche 50-409, 83/12/30, 8401030303

--B401050310 Exemption from requirements of 10CFR50.54 re licensed operator staffing
EISENHUT, D. G. Division of Licensing 84/01/01 Dairyland Power Cooperative 4pp 21729 071 24X Fiche 50-409, 83/12/30, 8401050303

B401100011 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators Engine block heaters installed on emergency diesel generators to maintain engines & lubricating oil at 100 F.
LINDER, F. Dairyland Power Cooperative 84/01/03 EISENHUT, D. G. Division of Licensing 2pp 21761 199 24X Fiche 50-409, 84/01/03, 8401100011

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D. G. Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc. 16pp 21746 190 24X
Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D. G. Division of Licensing 84/01/06, Consolidated Edison Co. of New York, Inc. 18pp 21957.267 24X
Fiche 50-000, 84/01/06, 8401090221

B401170202 Forwards response to 831103 ltr re NUREG-0737, Item II B.3. "Post-Accident Sampling Sys " Radionuclide concentrations will be accomplished by using Geil detector in conjunction w/ND5600 computer.
LINDER, F. Dairyland Power Cooperative 84/01/10 CRUTCHFIELD, D. Operating Reactors Branch 5 5pp 21831.323 24X
Fiche 50-409, 84/01/10, 8401170202

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl.
EISENHUT, D. G. Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc. 18pp. 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401250103 Revised application for amend to License DFR-45, adding Tech Spec Sections 4/5.3 & 4/5.4, "Radioactive Effluents" & "Radiological Environ Monitoring," respectively
LINDER, F. Dairyland Power Cooperative. 84/01/19 CRUTCHFIELD, D. Operating Reactors Branch 5 8pp 21937.076 24X
Fiche 50-409, 84/01/19, 8401250103

--B401250114 Proposed Tech Spec Sections 4/5.3 & 4/5.4, "Radioactive Effluents" & "Radiological Environ Monitoring," respectively
* Dairyland Power Cooperative 84/01/19. 22pp. 21937 084 24X
Fiche 50-409, 84/01/19, 8401250103

B401300264 Forwards "Vibration & Stress Analysis of Forced Circulation Pump Discharge Rotoport Valve Bypass Line "
LINDER, F. Dairyland Power Cooperative 84/01/19 Division of Technical Information & Document Control 1p 21995 163 24X
Fiche 50-409, 84/01/19, 8401300264

--B401300269 "Vibration of Stress Analysis of Forced Circulation Pump Discharge Rotoport Valve Bypass Line "
LANGE, O. R. Dairyland Power Cooperative 84/01/16 31pp
21995 164 24X Fiche 50-409, 84/01/19, 8401300266

B401260001 Corrections to 840119 application for amend to License DPR-45, App I re radiological environ monitoring program info inadvertently omitted from original submittal
LINDER, F. Dairyland Power Cooperative 84/01/23 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 21956 352 24X
Fiche 50-409, 84/01/23, 8401260001

--B401260002 Proposed Tech Specs re radiological environ monitoring program
* Dairyland Power Cooperative 84/01/23 5pp 21956 353 24X
Fiche 50-409, 84/01/23, 8401260001

B401300173 Notification of 840216 meeting w/util in Bethesda, MD to discuss & resolve all outstanding environ qualification issues
DUDLEY, R. F. Operating Reactors Branch 5. 84/01/26 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 21999 131 24X
Fiche 50-409, 84/01/26, 8401300173

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FDIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/20 ZAHNER, R. E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp. 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

B401190360 Forwards IE Insp Rept 50-409/83-20 on 831206-07 No noncompliance noted Response to encl exercise weaknesses requested within 30 days
PAPERIELLO, G. J. Region 3, Office of Director 83/12/15, LINDER, F. W. Dairyland Power Cooperative 3pp 21850 179 24X
Fiche 50-409, 83/12/15, 8401190360

--B401190364 IE Insp Rept 50-409/83-20 on 831206-07 No noncompliance noted Major areas inspected emergency preparedness exercise.
SNELL, W., PATTERSON, J., KERBL, Region 3, Office of Director. 83/12/16 7pp 21850 182 24X Fiche 50-409, 83/12/15, 8401190360

B401030201 Forwards "Repair of 1B Forced Circulation Pump Discharge Valve Bypass Line Weld, 92A " No pipings or fittings replaced Insp conducted per NUREG-0313
LINDER, F. Dairyland Power Cooperative 83/12/21 NRC - No Detailed Affiliation Given 2pp 21682 297 24X
Fiche 50-409, 83/12/21, 8401030201

--B401030206 "Repair of 1B Forced Circulation Pump Discharge Valve Bypass Line Weld, 92A "
TOWSLEY, H. A. Dairyland Power Cooperative LAC-TR-120 83/12/31.
6pp 21682 299 24X Fiche 50-409, 83/12/21, 8401030201

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

B401120379 Forwards IE Insp Rept 50-409/83-21 on 831213. No noncompliance noted
LITTLE, W. B. Region 3, Office of Director. 83/12/28 LINDER, F. W. Dairyland Power Cooperative 2pp 21792 001 24X
Fiche 50-409, 83/12/28, 8401120379.

--B401120382 IE Insp Rept 50-409/83-21 on 831213 No noncompliance noted Major areas inspected: review of inservice insp procedures, work activities, NDE personnel certifications & data, previous insp findings & IE bulletin activities
WARD, X. D., DANIELSON, D. H. Region 3, Office of Director 83/12/27 8pp 21792.003. 24X Fiche 50-409, 83/12/28, 8401120379

DOCKETED ITEMS

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc. 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

8401100344 Ack receipt of 831114 & 1219 ltrs informing NRC of steps
taken to correct violations noted in IE Insp Rept
50-409/83-13
SPESSARD, R L Division of Emergency Preparedness & Operational
Support 84/01/04 LINDER, F W Dairyland Power Cooperative 1p
21763 346 24X Fiche 50-409,84/01/04,8401100344

--8401100358 Forwards responses to NRC 831017 ltr re violations noted in
IE Insp Rept 50-409/83-13 Corrective actions memo issued
stressing importance of filling blanks on surveillance
sheets Data sheets being modified
LINDER, F Dairyland Power Cooperative 83/11/14 SPESSARD, R L
Division of Emergency Preparedness & Operational Support 6pp
21763 347 24X Fiche 50-409,84/01/04,8401100344

--8401100369 Submits supplemental response to NRC 831017 ltr re
violations noted in IE Insp Rept 50-409/83-13 Addl training
planned to stress importance of quality, commitments &
implementation of QA program & recordkeeping
LINDER, F Dairyland Power Cooperative 83/12/19 SPESSARD, R L
Division of Emergency Preparedness & Operational Support. 2pp
21763 353 24X Fiche 50-409,84/01/04,8401100344.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 125pp. 21946 033 24X Fiche 50-000,84/01/10,8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp. 21826 184 24X Fiche 50-000,84/01/10,8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001. 24X Fiche 50-000,84/01/18,8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc. 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

8401240299 Ack receipt of 831222 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-409/83-18
PAPERIELLO, C J Region 3, Office of Director 84/01/20
LINDER, F W Dairyland Power Cooperative 1p 21909 259 24X
Fiche 50-409,84/01/20,8401240299

--8401240303 Responds to NRC 831130 ltr re violations noted in IE Insp
Rept 50-409/83-18 Corrective actions, larger self-absorption
correction factor for Xe-133 81 keV photo peak will be
incorporated into new calibr procedure nearing completion
LINDER, F. Dairyland Power Cooperative 83/12/22. HIND, J A
Region 3, Office of Director 3pp. 21909 260 24X
Fiche. 50-409,84/01/20,8401240299

8401300007 Forwards IE Safeguards Insp Rept 50-409/84-01 on 840109-13
No noncompliance noted.
AXELSON, W L Region 3, Office of Director. 84/01/24. LINDER, F W
Dairyland Power Cooperative. 2pp. 21999 230 24X
Fiche. 50-409,84/01/24,8401300007.

--8401300008 IE Safeguards Insp Rept 50-409/84-01 on 840109-13 No
noncompliance noted Major areas inspected: security
organization, security program audit, testing & maint &
physical barriers Details withheld (ref 10CFR73 21)
BELANGER, J L., CREED, J R Region 3, Office of Director 84/01/24
1p. 21999 232 24X Fiche: 50-409,84/01/24,8401300007.

8310221 Ack receipt of 840103 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-409/83-19
PAPERIELLO, C J Region 3, Office of Director 84/01/27
LINDER, F W Dairyland Power Cooperative 1p. 22021 288 24X
Fiche: 50-409,84/01/27,8401310221

--8401310224 Responds to NRC 831208 ltr re violations noted in IE Insp
Rept 50-409/83-19 Corrective actions personnel instructed in
radiological protection procedures & radiological occurrence
rept log record will be developed
LINDER, F Dairyland Power Cooperative 84/01/03 PAPERIELLO, C J
Region 3, Office of Director 3pp 22021 289 24X
Fiche 50-409,84/01/27,8401310221

R Periodic operating reports & related correspondence

8401120381 Monthly operating rept for Nov 1983 W/831206 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative 83/11/30
NRC - No Detailed Affiliation Given 10pp 21791 190 24X
Fiche 50-409,83/11/30,8401120381

8401060480 Forwards results of Sr-89 & 90 analyses of stack particulate
filters & liquid waste composites for 1982 & part of 1983 &
results of gross beta & 3H 3,000-gallon waste sample tank
split samples for Nov 1983
SHAFER, P W Dairyland Power Cooperative 83/12/03 SCHUMACHER, H C
Region 3, Office of Director 1p 21740 186 24X
Fiche 50-409,83/12/30,8401060480

--8401060484 Results of gross beta & 3H analyses of 3,000-gallon waste
sample tank split samples for Nov 1983
* Energy, Dept of 83/11/30 6pp 21740 187 24X
Fiche 50-409,83/12/30,8401060480

--8401060488 Results of Sr-89 & 90 analyses of stack particulate
filters & liquid waste composites for 1982 & part of 1983
ZIBUNG, R Dairyland Power Cooperative 83/08/26 6pp
21740 188 24X Fiche 50-409,83/12/30,8401060480

8401160270 Monthly operating rept for Dec 1983 W/840109 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative 83/12/31
NRC - No Detailed Affiliation Given 14pp 21814 152 24X
Fiche 50-409,83/12/31,8401160270

S Reportable occurrences, LERs & related correspondence

8401230183 Forwards modified Table 3 to 830803 response to confirmation
action ltr re 830716 event Table provides summary of stress
analysis results Ltr documents previous answers re stress to
reactor vessel & seal inject sys
LINDER, F Dairyland Power Cooperative 83/11/16 KEPLER, J Q
Region 3, Office of Director 3pp 21884 169 24X
Fiche 50-409,83/11/16,8401230183

8401050646 LER 83-012/01L-0 on 831130, through weld crack detected at
seal weld joining forced circulation pump discharge valve
bypass line 12 to valve body Caused by fault in original
weld Weld will be repaired W/831213 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative 83/12/13
KEPLER, J Q Region 3, Office of Director 4pp 21725 196 24X
Fiche 50-409,83/12/13,8401050646

8401060261 LER 83-009/03L-0 on 831130, 480-volt bus 1A main feed
breaker 432 MIA tripped Caused by problem w/breaker static
trip device magnetic actuator Magnetic actuator replaced &
new model on order W/831229 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative 83/12/29
KEPLER, J Q Region 3, Office of Director 7pp 21740 140 24X
Fiche 50-409,83/12/29,8401060261

8401130001 LER 83-011/03L-0 on 831209, high pressure svc water diesel
1B failed to start during surveillance test Cause not
stated Burned out starter replaced Old starter sent offsite
for insp & repair W/840103 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative. 84/01/03
KEPLER, J Q Region 3, Office of Director 3pp 21802 332 24X
Fiche. 50-409,84/01/03,8401130001.

8401130148 LER 83-010/03L-0 on 831205, during refueling outage, personnel
airlock inner door equalizing valve leaked air during Type
B leakage test Caused by tape in equalizing valve Tape
removed & valve ball & seat replaced W/840103 ltr
GOODMAN, L S, LINDER, F Dairyland Power Cooperative 84/01/03
KEPLER, J Q Region 3, Office of Director 3pp 21802 113 24X
Fiche: 50-409,84/01/03,8401130148

8401100190 PND-III-84-002 on 831129, offsite power circuit breaker
opened for no apparent cause Investigation determined
magnetic coupling became weak Allis Chalmers supplied
mod kits Made complete
JORDAN, H, SHAFER, W Region 3, Office of Director 84/01/04 1p
21760 150 24X Fiche 50-409,84/01/04,8401100190

DOCKETED ITEMS

299

B401160254 LER 83-013/03L-0 on 831212, one of two starter engagement solenoids on high pressure svc water diesel 1A failed. Starter continued cranking while off. Caused by solenoid contacts fusing together. Solenoid replaced W/B40106 ltr QDOBMAN, L S, LINDER, F Dairyland Power Cooperative 84/01/06. KEPLER, J G Region 3, Office of Director 3pp 21814 110 24X Fiche 50-409, 84/01/06, B401160254

V Operator Examinations

B401300316 Responds to Generic Ltr 83-40 survey re operator licensing exam schedules. Encl completed survey represents best estimate of schedule for FY84-87. LINDER, F Dairyland Power Cooperative 84/01/25 EISENHUT, D G Division of Licensing 2pp 21996 308 24X Fiche 50-409, 84/01/25, B401300316

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B401030417 Forwards updated distribution list for environ rept - OL stage, FSAR & general info. SCHWENCER, A Licensing Branch 2 83/12/13 RHODE, G K Niagara Mohawk Power Corp 5pp 21693 330 24X Fiche 50-410, 83/12/13, B401030417

B401040479 Responds to NRC 831121 ltr requesting addl info re Class IE bus interconnections. Response will be provided by B40330. MANGAN, C V Niagara Mohawk Power Corp 83/12/23 SCHWENCER, A Licensing Branch 2 1p 21707 203 24X Fiche 50-410, 83/12/23, B401040479

B401130458 Notification of B40112 meeting w/util in Bethesda, MD to discuss training. HAUGHEY, M Licensing Branch 2 84/01/03 SCHWENCER, A Licensing Branch 2 3pp 21820 234 24X Fiche 50-410, 84/01/03, B401130458

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" svc list encl. EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl. EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401190293 Summary of 831104 meeting w/util, S&W & GE in Bethesda, MD re power sys. HAUGHEY, M F Licensing Branch 2 84/01/09 Licensing Branch 2 3pp 21870 053 24X Fiche 50-410, 84/01/09, B401190293

B401190296 Summary of 831013 meeting w/util, Dames & Moore, S&W & Pennsylvania State Univ re util responses to NRC requests for info regarding geoscience issues. HAUGHEY, M F Licensing Branch 4 84/01/09 Licensing Branch 4 11pp 21870 042 24X Fiche 50-410, 84/01/09, B401190296

B401190224 Forwards list of safety issues applicable to Mark I & II BWR containments, as result of former GE sys engineer, J Humphrey, concerns. Response, in form of revised FSAR pages, due in 60 days. SCHWENCER, A Licensing Branch 2 84/01/10 RHODE, G K Niagara Mohawk Power Corp 11pp 21870 209 24X Fiche 50-410, 84/01/10, B401190224

B401200092 Summary of 830928 meeting w/util in Bethesda, MD re structural issues from OL review. HAUGHEY, M F Licensing Branch 2 84/01/12 Licensing Branch 2 11pp 21872 185 24X Fiche 50-410, 84/01/12, B401200092

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" svc list encl. EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401270561 Notification of B40118 meeting w/util & GE in Bethesda, MD to discuss documentation submitted for instrumentation & control. HAUGHEY, M F Licensing Branch 2 84/01/16 SCHWENCER, A Licensing Branch 2 3pp 21992 338 24X Fiche 50-410, 84/01/16, B401270561

B401310223 Summary of 831207 meeting w/util, S&W Engineering & GE re instrumentation & control sys. HAUGHEY, M F Licensing Branch 2 84/01/16 Licensing Branch 2 5pp 22021 125 24X Fiche 50-410, 84/01/16, B401310223

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants. HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401240100 Informs that incorrect date referenced in 831213 request for justification for proprietary status. Correct date should be 830125 vice 830124. MANN, S F Niagara Mohawk Power Corp 84/01/18 EISENHUT, D G Division of Licensing 1p 21912 362 24X Fiche 50-410, 84/01/18, B401240100

B401270092 Forwards info showing comparison of plant diesel generators w/generators of other units demonstrating similarity. Diesel generator 300 start test need not be conducted. Exclusion from testing for preoperational program requested. MANGAN, C V Niagara Mohawk Power Corp 84/01/23 SCHWENCER, A Licensing Branch 2 4pp 21982 136 24X Fiche 50-410, 84/01/23, B401270092

C Utility Environmental Report (ER), amends & correspondence

B401030417 Forwards updated distribution list for environ rept - OL stage, FSAR & general info. SCHWENCER, A Licensing Branch 2 83/12/13 RHODE, G K Niagara Mohawk Power Corp 5pp 21693 330 24X Fiche 50-410, 83/12/13, B401030417

B401040081 Forwards affidavit of distribution of Amend 7 to FSAR & Suppl 5 to environ rept to individuals on encl svc list. RHODE, G K Niagara Mohawk Power Corp 83/12/27 EISENHUT, D G Division of Licensing 5pp 21703 219 24X Fiche 50-410, 83/12/27, B401040081

K Utility Final Safety Analysis Report (FSAR) & amends

B312280405 Forwards 339 oversize drawings referenced in Section 1.7 of FSAR. Drawing updates originally forwarded on 830425 w/Amend 1 to FSAR. Document transmittal inventory also encl. Aperture cards are available in PDR. MANGAN, C V Niagara Mohawk Power Corp 83/12/16 SCHWENCER, A Licensing Branch 2 3pp 21649 242 24X Fiche 50-220, 83/12/16, B312280405

B401040081 Forwards affidavit of distribution of Amend 7 to FSAR & Suppl 5 to environ rept to individuals on encl svc list. RHODE, G K Niagara Mohawk Power Corp 83/12/27 EISENHUT, D G Division of Licensing 5pp 21703 219 24X Fiche 50-410, 83/12/27, B401040081

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR. FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

--B401060130 List of SALP results during 1982. * Director's Office, Office of Inspection and Enforcement 83/10/20, 134pp 21744, 004 24X Fiche 50-000, 83/10/20, B401060040

B401100370 Ack receipt of 830901 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/83-08. MARTIN, T T Division of Engineering & Technical Programs 83/12/23, RHODE, G K Niagara Mohawk Power Corp 2pp 21764 099 24X Fiche 50-410, 83/12/23, B401100370

--B401100381 Responds to NRC 830723 ltr re violations noted in IE Insp Rept 50-410/83-08. Corrective actions, S&W will revise Spac E0150 re clamps & wiring via engineering & design coordination rept by 830909. DISE, D P Niagara Mohawk Power Corp 83/09/01, STARDSTECKI, R Division of Project & Resident Programs 3pp 21764, 101 24X Fiche 50-410, 83/12/23, B401100370

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" svc list encl. DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

DOCKETED ITEMS

8401040493 Advises that response to Question F250 1 re submission of Preservice insp program plan will be provided for review by 840121
RHODE, G K Niagara Mohawk Power Corp 83/12/28 SCHWENGER, A
Licensing Branch 2 1p 21707 166 24X Fiche 50-410, 83/12/28, 8401040493

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401190370 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-410/1-83-005
STAROSTECKI, R Division of Project & Resident Programs 84/01/03
RHODE, G K Niagara Mohawk Power Corp. 1p. 21850 068 24X
Fiche: 50-410, 84/01/03, 8401190370

--8401190373 Responds to NRC 831013 ltr re violations noted in IE Investigation Rept 50-410/1-83-005. Corrective actions site personnel access to NRC will be reemphasized. Contract QA activities will be monitored.
DISE, D P Niagara Mohawk Power Corp 83/12/07, STAROSTECKI, R
Division of Project & Resident Programs 3pp 21850 069 24X
Fiche: 50-410, 84/01/03, 8401190370

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc. 125pp 21746.053. 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp. 21826 164 24X Fiche: 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp. 21957 142. 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc. 118pp 22000 001. 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000:041. 24X Fiche 50-000, 84/01/18, 8312120117

S. Reportable occurrences, LERs & related correspondence

8401030238 Final deficiency rept re failure of MSIV actuators during qualification testing initially reported on 831109
Deficiency does not exist since qualification tests part of vendor design development phase
MANNAN, C V Niagara Mohawk Power Corp. 83/12/09 STAROSTECKI, R
Division of Project & Resident Programs. 2pp 21882:277. 24X
Fiche 50-410, 83/12/09, 8401030238

8401130321 Interim deficiency rept re mechanical snubbers supplied by Pacific Scientific Co initially reported on 831117 Seven snubbers tested revealed broken capstan spring tang
Investigation ongoing Final rept by 840616
MANNAN, C V Niagara Mohawk Power Corp 83/12/16, STAROSTECKI, R
Division of Project & Resident Programs. 2pp. 21801.321 24X
Fiche. 50-410, 83/12/16, 8401130321

8401130349 Final deficiency rept re ITT Grinnell weld radiographs of T-quenchers & piping equal or greater than 1/2 inch.
Initially reported on 830119. Fifty-three welds found to have enhancements. 37 reradiographed & determined acceptable
MANNAN, C V Niagara Mohawk Power Corp. 83/12/19, STAROSTECKI, R.
Division of Project & Resident Programs 2pp 21798 274. 24X
Fiche: 50-410, 83/12/19, 8401130349.

8401140100 Interim deficiency rept re HEA relays mfg by GE initially reported on 831121. Investigation continuing to determine if relays supplied to facility Final rept will be submitted by 840731.
MANNAN, C V Niagara Mohawk Power Corp. 83/12/21, STAROSTECKI, R
Division of Project & Resident Programs. 3pp. 21821:173 24X
Fiche: 50-410, 83/12/21, 8401140100

8401270108 Interim deficiency rept re reactor bldg roof design
Initially reported on 831209 Investigation not yet complete
Final rept will be submitted by 840430
MANNAN, C V Niagara Mohawk Power Corp 84/01/09 STAROSTECKI, R
Division of Project & Resident Programs 2pp 21976 224 24X
Fiche. 50-410, 84/01/09, 8401270108

8401270449 Final deficiency rept re control bldg control & alarm room drywall partition walls not designed for seismic loads
Initially reported on 831208 Drywall partitions redesigned to withstand seismic loads
MANNAN, C V Niagara Mohawk Power Corp 84/01/09 STAROSTECKI, R
Division of Project & Resident Programs 2pp 21980 257 24X
Fiche 50-410, 84/01/09, 8401270449

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8401090137 Notification of 840103 meeting w/util in Bethesda MD to discuss review plans for Reg Guide 1.97 implementation rept
LAZD, L Licensing Branch 3 83/12/16 KNIGHTON, Q W Licensing Branch 3 4pp 21757 225 24X Fiche 50-412, 83/12/16, 8401090137

8401090154 Notification of 831219 meeting w/util in Bethesda MD to discuss mechanical equipment qualification program
LAZD, L Licensing Branch 3 83/12/19 KNIGHTON, Q W Licensing Branch 3 4pp 21757 229 24X Fiche 50-412, 83/12/19, 8401090154

8401060285 Forwards master computerized listing of seismic & stress qualification summary & status of safety-related equipment per response to FBAR acceptance review question, Encl 4. Item 5A re development of equipment list for PVDRT & SORT
WOOLEVER, E J Duquesne Light Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director KNIGHTON, Q W Licensing Branch 3 437pp 21737 001 24X Fiche 50-412, 83/12/29, 8401060285

8401120457 Notification of 840104 meeting w/util in Bethesda MD to discuss util QA program & staff requirements
LAZD, L Licensing Branch 3 84/01/03 KNIGHTON, Q W Licensing Branch 3 4pp 21804:097. 24X Fiche 50-412, 84/01/03, 8401120457

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl.
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382.

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re Notice of meeting on facility staffing
Svc list encl.
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp. 21957 267 24X
Fiche: 50-000, 84/01/06, 8401090221

8401250479 Forwards request for addl info re FBAR Sections 13.1 & 13.5.1 generated by Licensee Qualifications Branch Meeting requested to discuss requests & to schedule formal submission of responses
KNIGHTON, Q W Licensing Branch 3. 84/01/06 WOOLEVER, E J Duquesne Light Co 7pp 21948 331 24X Fiche 50-412, 84/01/06, 8401250479

8401130175 Responds to 831207 ltr transmitting facility staffing survey. Personnel in operating staff will meet qualifications defined in Section 4 of ANSI N18.1-1971. Specific info will be provided. Completed survey encl.
WOOLEVER, E J Duquesne Light Co 84/01/09 DENTON, H R Office of Nuclear Reactor Regulation, Director, KNIGHTON, Q W Licensing Branch 3 3pp 21802 044. 24X Fiche 50-412, 84/01/09, 8401130175

8401130084 Generic Ltr 84-03 to all licensees of operating reactors applicants for OLs & holders of CPs re availability of Svc list encl.
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc. 18pp. 21946:174 24X
Fiche: 50-000, 84/01/13, 8401130084.

8401180151 Forwards amended slides & diagrams utilized during 831214 meeting w/NRC re cable separation program Westinghouse design approach re separation within NSSS electrical panels found in FBAR Section 7.1.2.2.1.
WOOLEVER, E J Duquesne Light Co. 84/01/13, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 21849.006 24X
Fiche: 50-412, 84/01/13, 8401180151

8401240327 Forwards "Amends 1 & 2 to Failure Modes & Effects Analysis Nuclear Reactor Regulation, Director 3pp 21953:001 24X
Fiche: 50-412, 84/01/16, 8401240327.

DOCKETED ITEMS

30

--B401260331 "Amend 2 to Failure Modes & Effects Analysis "
* Stone & Webster Engineering Corp 84/01/31 26pp 21953 004
24X Fiche 50-412,84/01/16,8401260327

--B401260337 "Amend 1 to Failure Modes & Effects Analysis "
* Stone & Webster Engineering Corp 84/01/31 374pp 21953 030
24X Fiche 50-412,84/01/16,8401260327

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda,
MD to discuss limited operational experience on operating
crews & development of acceptable experience profile for
new plants
HANNON, J Division of Licensing 84/01/17 Division of
Licensing 1p 22000 349 24X Fiche 50-000,84/01/17,8401270536

B401300329 Forwards revised response to QA Branch questions Responses
scheduled to be submitted as part of Amend 4 to FSAR
WOOLEVER, E J Duquesne Light Co 84/01/24 KNIGHTON, G W
Licensing Branch 3 57pp 21993 267 24X Fiche 50-412,84/01/24,
8401300329

F. Security, medical, emergency & fire protection plans

B401310109 Releases public version of revised emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 22028 095 24X Fiche 50-334,84/01/20,
8401310109

--B401310115 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPP/IP 1-2 re
unusual event, EPP/IP 1-3 re alert & EPP/IP 1-4 re site area
emergency Transmittal Form encl
HILLER, D J Duquesne Light Co 83/12/04 NRC - No Detailed
Affiliation Given 2pp 22028 096 24X Fiche 50-334,84/01/20,
8401310109

--B401310122 Public version of revised emergency plan implementing
procedures, including Procedures EPP/IP 1-2 re unusual event,
EPP/IP 1-3 re alert & EPP/IP 1-4 re site area emergency
LACEY, W S Duquesne Light Co 83/11/30 200pp 22028 098 24X
Fiche 50-334,84/01/20,8401310109

B401300224 Forwards suppl to B31110 response to NRC request for addl
info re physical security plan info withheld (ref 10CFR73 21
& 10CFR2 790)
WOOLEVER, E J Duquesne Light Co 84/01/24 DENTON, H R Office of
Nuclear Reactor Regulation, Director 4pp 21998 312 24X
Fiche 50-412,84/01/24,8401300224

G. Adjudicatory correspondence

B401030153 Advises that Environ Coalition on Nuclear Power has not
shown appropriate standing & interest & has not set forth
admissible contentions in petition for leave to intervene
Petition should be denied Certificate of Svc encl
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J T
Duquesne Light Co, 83/12/28 MARQUILIES, M B, HILL, E E, PURDOM, P W
Atomic Safety and Licensing Board Panel 4pp 21681 346 24X
Fiche 50-412,83/12/28,8401030153

B401310248 Rept & order denying petitions to intervene & hold
adjudicatory hearing re DL application No basis in fact or
law exists for granting of hearing
MARQUILIES, M B Atomic Safety and Licensing Board Panel 84/01/27
Pennsylvania, Commonwealth of, 62pp 22018 263 24X
Fiche 50-412,84/01/27,8401310248

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results
during 1982. Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche: 50-000,83/10/20,8401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20,
8401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys." Svc list encl
DEYDUNG, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,8312120090,

B401040169 Forwards description of preservice insp program per B31205
commitment in Amend 4 to FSAR Program will include isometric
sketches identifying welds & supports or bolted connections
subj to exam in each piping sys
WOOLEVER, E J Duquesne Light Co 83/12/29 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 21701 361 24X
Fiche 50-412,83/12/29,8401040169

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HA Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co. of New
York, Inc 127pp 21826 060 24X Fiche 50-000,83/12/30,8312120093

B401100276 Act receipt of B31007 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-412/83-11
Concern re use of ASME Boiler & Pressure Vessel Code for
post-weld heat treatment described
STAROSTECKI, R Division of Project & Resident Programs 84/01/04,
WOOLEVER, E J Duquesne Light Co 2pp 21758 162 24X
Fiche 50-412,84/01/04,8401100276

--B401100296 Responds to NRC B30909 ltr re violations noted in IE Insp
Rept 50-412/83-11 Corrective actions: welds on spool MS-043-2
will be magnetic particle examined & furnace survey charts
provided to verify furnace temp
WOOLEVER, E J Duquesne Light Co 83/10/07 STAROSTECKI, R
Division of Project & Resident Programs 6pp 21758 164 24X
Fiche 50-412,84/01/04,8401100276

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 123pp 21946 033 24X Fiche 50-000,84/01/10,8312120104.

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107.

B401240308 Forwards IE Insp Rept 50-412/83-16 on B31121 & 22 No
violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
WOOLEVER, E J Duquesne Light Co 2pp 21909 224 24X
Fiche 50-412,84/01/10,8401240308

--B401240318 IE Insp Rept 50-412/83-16 on B31121-22. No violations
noted Major areas inspected activities re stainless steel
piping outside diameter weld buildup effects on corrosion
performance & safety-related pipe support welding
REYNOLDS, B D, DURR, J Region I, Office of Director 84/01/06
5pp 21909 226 24X Fiche 50-412,84/01/10,8401240308

B401260182 Forwards IE Insp Rept 50-412/83-14 on B31101-03, No
violation noted.
MARTIN, T T Division of Engineering & Technical Programs 84/01/13
WOOLEVER, E J Duquesne Light Co 2pp 21956 093 24X
Fiche 50-412,84/01/13,8401260182.

--B401260186 IE Insp Rept 50-412/83-14 on B31101-03, No violation noted
Major areas inspected activities re installation of safety-
related electrical/instrumentation equipment
FINKEL, A, ANDERSON, C J Region I, Office of Director, 83/12/16,
6pp 21956 095 24X Fiche 50-412,84/01/13,8401260182

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New
York, Inc 127pp 21957 142 24X Fiche 50-000,84/01/16,8312120114.

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators." Svc list
encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116.

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117.

DOCKETED ITEMS

V Operator Examinations

B401200073 Forwards projected schedule through 1987 for prospective licensing exams in response to Generic Ltr B3-40 Data has been outlined by month, until class & expected mix of license
 CAREY, J J Duquesne Light Co 84/01/13 EISENHUT, D O, Division of Licensing 4pp 21867 015 24X Fiche 50-334, 84/01/13, B401200073

DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1A Application/construction stage documents & correspondence

B401270123 Submits results of review of geologic & seismic data in FSAR Sections 2 5 1 through 2 5 3 & other related studies Site geologically acceptable & meets NRC requirements
 PLANNER, H N, NEWTON, C A Los Alamos Scientific Laboratory, 83/11/17 JACKSON, R E Geosciences Branch 4pp 21982 027 24X Fiche 50-413, 83/11/17, B401270123

B401060307 Expresses appreciation for assistance of State of SC, Dept of Health & Environ Control w/implementation of TLD direct radiation monitoring network Encl list of TLD station locations available in Central Files only.
 LEWIS, R C Division of Project & Resident Programs 83/11/29 TUCKER, H B Duke Power Co 2pp 21741 120 24X Fiche 50-413, 83/11/29, B401060307.

B312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants.
 MATHES, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp. 22034 358 24X Fiche 50-000, 83/12/16, B312200154

B401040234 Forwards facility staffing survey, per KN Jabbar 831206 request
 TUCKER, H B Duke Power Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4, 5pp 21701 183, 24X Fiche 50-413, 83/12/21, B401040234

B401130097 Forwards TM Novak ltr to JP McQuaghy re series of questions on emergency diesel generators mfg by Transamerica Delaval, Inc. Response may be submitted by ref to owners group or plant-specific repts w/o encl
 ADENSAH, E G Licensing Branch 4, 83/12/30 TUCKER, H B Duke Power Co 1p 21821 125 24X Fiche 50-413, 83/12/30, B401130097

B312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems.
 EISENHUT, D O, Division of Licensing 84/01/05 PALLADINO, N J Commissioners 2pp. 21993 324 24X Fiche 50-000, 84/01/05, B312120108

>1050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, 'important to safety' & 'safety-related' Svc list encl
 EISENHUT, D O, Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
 EISENHUT, D O, Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp. 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401170359 Forwards offsite dose calculation manual.
 TUCKER, H B Duke Power Co, 84/01/10 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4, 1p 21829 071 24X Fiche 50-413, 84/01/10, B401170359.

--B401170360 Offsite dose calculation manual
 * Duke Power Co, 84/01/10 32pp 21829 072 24X Fiche 50-413, 84/01/10, B401170359.

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
 EISENHUT, D O, Division of Licensing, 84/01/13, Consolidated Edison Co of New York, Inc 18pp. 21946 174, 24X Fiche 50-000, 84/01/13, B401130084.

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
 HANNON, J, Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401270194 Requests const completion data specified in CRR-116 be extended 8 months to 841101, supporting B40501 fuel load data
 TUCKER, H B Duke Power Co 84/01/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 21982 061 24X Fiche 50-413, 84/01/23, B401270194.

E NRC Safety Evaluation Report (SER), suppl & correspondence

B401240283 Forwards revised response to Question 430 110 re Confirmatory Item 3B of SER Section B 4 10, concerning 100% load reduction capability Problem w/voltage excursions following load rejections not indicated
 TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 21909 353 24X Fiche 50-413, 84/01/17, B401240283

B401270181 Responds to Open Item 16 in Section 13 3 of SSER 1 re emergency planning & meteorology, Sufficient staff & facilities available in crisis mgt ctr to respond in event of simultaneous emergencies at Catawba & McGuire
 TUCKER, H B Duke Power Co 84/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 21982 069 24X Fiche 50-413, 84/01/19, B401270181

B401310280 Forwards info requested at 830923 meeting re SER Open Item 4 on seismic qualification of equipment Info includes revised FSAR Table 3 10-1 & computer list of safety-related electronic equipment
 TUCKER, H B Duke Power Co, 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 83pp. 22015 214 24X Fiche 50-413, 84/01/20, B401310280

B401270254 Responds to open item in SER Section 13 5 1 3 re NUREG-0737, Item 1 A 1 i, "Shift Technical Advisor" On-shift staff will include shift engineer, fulfilling TMI item requirements Revised FSAR pages encl
 TUCKER, H B Duke Power Co 84/01/24 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 10pp 21982 184, 24X Fiche 50-413, 84/01/24, B401270254

F Security, medical, emergency & fire protection plans

B401250071 Forwards comments on vital areas described in physical security plan. Response should be submitted within 30 days of ltr receipt Comments withheld (ref 10CFR73 21)
 ADENSAH, E G Licensing Branch 4 84/01/10 TUCKER, H B Duke Power Co 1p. 21939 284 24X Fiche 50-413, 84/01/10, B401250071

B401250262 Responds to questions raised at meeting to arrange for informal discovery No NRC-FEMA communications re offsite emergency plans occurred, NRC will issue SER suppl containing comments on FEMA findings FEMA external correspondence encl
 JOHNSON, O E Hearing Branch 4 84/01/10 GUILD, R 17pp. 21944 190 24X Fiche 50-413, 84/01/10, B401250262

B401240171 Forwards two oversize drawings showing location of sprinkler heads in Unit 1 annulus Aperture cards are available in POR
 TUCKER, H B Duke Power Co 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4, 2pp 21910 251 24X Fiche 50-413, 84/01/17, B401240171

B401270181 Responds to Open Item 16 in Section 13 3 of SSER 1 re emergency planning & meteorology Sufficient staff & facilities available in crisis mgt ctr to respond in event of simultaneous emergencies at Catawba & McGuire
 TUCKER, H B Duke Power Co 84/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E G Licensing Branch 4 2pp 21982 069 24X Fiche 50-413, 84/01/19, B401270181

B401300231 Responds to B40123 telephone inquiry re termination date for discovery on emergency planning contentions All discovery must be completed by 840206, Copy of student emergency plan booklet encl. Related correspondence
 SHEARIN, R V Duke Power Co, 84/01/24, RILEY, J L Carolina Environmental Study Group 3pp 22062 139 24X Fiche 50-413, 84/01/24, B401300231

B401310308 Forwards IE Insp Rept 50-413/84-09 on B40103-06 No violations noted. Details withheld (ref 10CFR2 790 & 21)
 DANCE, H C, Division of Project & Resident Programs 84/01/27 TUCKER, H B Duke Power Co 2pp 22019 296, 24X Fiche 50-413, 84/01/27, B401310308

DOCKETED ITEMS

303

--8401310311 IE Insp Rept 50-413/84-09 on 840103-06 No noncompliance noted Major areas inspected SNM physical security storage plan & implementing procedures & security organization Details withheld (ref 10CFR2 790 & 73 21)
MOORE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/01/26 1p
22019-298 24X Fiche 50-413,84/01/27,8401310308

Q Adjudicatory correspondence

8401040195 Forwards 831221 ltr to util transmitting IE Insp Repts 50-413/83-33 & 50-414/83-40 re laminar indications in containment penetration sleeves
JOHNSON, G E Hearing Branch 4 83/12/29 KELLEY, J L, FOSTER, PURDOM, P W Atomic Safety and Licensing Board Panel 6pp
21702-082 24X Fiche 50-413,83/12/29,8401040195

8401050230 Memorandum & order denying util 831103 motion for reconsideration re revised emergency planning Contention II Denial should not be interpreted as active opposition to interlocutory review
KELLEY, J L Atomic Safety and Licensing Board Panel. 83/12/30. Duke Power Co 5pp 21728 273 24X Fiche 50-413,83/12/30, 8401050230

8401050253 Order confirming ASLB 831216 oral rulings closing record & setting schedule for filing proposed findings of fact, conclusions of law & proposed license conditions Record on Contentions 16, 18/44 & 17 closed on 831216
KELLEY, J L Atomic Safety and Licensing Board Panel 83/12/30 Duke Power Co. 5pp 21725 259 24X Fiche 50-413,83/12/30, 8401050253

8401050247 Response opposing Palmetto Alliance motions to direct certification of ASLB rulings on discovery re in camera witness testimony & to require that record remain open pending opportunity for discovery W/Certificate of Svc
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/01/03 Atomic Safety and Licensing Appeal Panel. 33pp 21729 111 24X Fiche 50-413,84/01/03,8401050247

8401120195 Forwards two ASLB orders addressing emergency planning contentions Encl suppl 830816 matl W/o encl
JOHNSON, G E Hearing Branch 4 84/01/04 PERRY, S Federal Emergency Management Agency 1p 21793 352 24X Fiche 50-413,84/01/04,8401120195

8401120216 Forwards NRC opposition to Palmetto Alliance motions for directed certification of ASLB denial of further discovery on in camera issues & of motion to hold record open Pleading should be treated per terms of 831101 order
JOHNSON, G E Hearing Branch 4 84/01/05 KELLEY, J L, PURDOM, P W, FOSTER, R F Atomic Safety and Licensing Board Panel 1p. 21791 204. 24X Fiche 50-413,84/01/05,8401120216

8401120224 Forwards NRC opposition to Palmetto Alliance motions for directed certification of ASLB denial of further discovery on in camera issues & of motion to hold record open Pleading should be treated per terms of 831101 order
JOHNSON, G E Hearing Branch 4 84/01/05 GUILD, R Guild, R GUILD, R Palmetto Alliance 1p 21793 261 24X Fiche: 50-413,84/01/05,8401120224

8401120252 Forwards staff opposition to Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold open record Pleading should be treated per terms of 831101 order W/o encl
JOHNSON, G E Hearing Branch 4 84/01/05 WILSON, R P. South Carolina, State of. 1p. 21793 282 24X Fiche 50-413,84/01/05, 8401120252

8401120310 Forwards ltr to ASLAB & NRC response opposing Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold record open W/o encls
JOHNSON, G E Operations & Administrative Division. 84/01/05 MCGARRY, J M Debevoise & Liberman 1p 21792 188 24X Fiche: 50-413,84/01/05,8401120310.

8401120315 Forwards NRC pleading in opposition to Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold record open. W/o encl
JOHNSON, G E Hearing Branch 4 84/01/05 ROSENTHAL, A S., WILBER, H A, MOORE, T. B. Atomic Safety and Licensing Appeal Panel 2pp. 21792 189. 24X Fiche: 50-413,84/01/05,8401120315.

8401120300 Responds to requests for documents re correspondence between FEMA & NRC on offsite plans & for SER suppl commenting on FEMA findings. Date not established for SSER issuance. W/o encl.
JOHNSON, G E. Regulations Division. 84/01/10 GUILD, R Guild, R 2pp. 21791 010. 24X Fiche: 50-413,84/01/10,8401120300.

8401250262 Responds to questions raised at meeting to arrange for informal discovery No NRC-FEMA communications re offsite emergency plans occurred NRC will issue SER suppl containing comments on FEMA findings FEMA external correspondence encl.
JOHNSON, G E Hearing Branch 4 84/01/10 GUILD, R Guild, R 17pp 21744 190 24X Fiche 50-413,84/01/10,8401250262.

--8401250272 Forwards emergency planning contentions admitted by ASLB on 830808 Portions of transcript which constitute rulings on contentions also encl W/o encl
JOHNSON, G E Hearing Branch 4 83/08/16 PERRY, S Federal Emergency Management Agency 1p 21744 207 24X Fiche 50-413,84/01/10,8401250262

8401160258 Petition for directed certification of ASLB 831230 denial of applicant motion to reconsider order revising & admitting emergency planning Contention II re size of emergency planning zone Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 84/01/12 Atomic Safety and Licensing Appeal Panel 38pp. 21814 114 24X Fiche 50-413,84/01/12,8401160258

8401250101 Forwards documentation re License SNM-1920 authorizing receipt & storage of new fuel in shipping containers at Unit 1 License does not relate to OL proceeding contention re storage of spent fuel from other util facilities
JOHNSON, G E Hearing Branch 4 84/01/12 KELLEY, J L, PURDOM, P W, FOSTER, R F Atomic Safety and Licensing Board Panel. 17pp 21940 208. 24X Fiche 50-413,84/01/12,8401250101

8401170268 Memorandum & order setting 840126 as starting date & Charlotte, NC as place for evidentiary hearing on five in camera matters listed in ASLB 831230 order.
KELLEY, J L Atomic Safety and Licensing Board Panel. 84/01/13 4pp 21831 001 24X Fiche: 50-413,84/01/13,8401170268

8401180222 Forwards pages of 830909 transcript relevant to applicant opposition to admission of intervenor late-filed contention re adequacy of diesel generator crankshaft. Intervenor late filing inexcusable
MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds MCGARRY, J M Duke Power Co 84/01/13 KELLEY, J L, PURDOM, P W, FOSTER, R F Atomic Safety and Licensing Board Panel 4pp 21844 223 24X Fiche 50-413,84/01/13,8401180222

--8401180228 Forwards attachments inadvertently omitted from 840112 motion for directed certification of ASLB 831230 ruling revising & admitting Contention II re emergency planning. Notice of appearance encl
CALVERT, M S Bishop, Liberman, Cook, Purcell & Reynolds CALVERT, M S Duke Power Co 84/01/13 ROSENTHAL, A S, MOORE, T B, WILBER, H A. Atomic Safety and Licensing Appeal Panel. 33pp 21844 227. 24X Fiche: 50-413,84/01/13,8401180222

8401180216 Forwards maps inadvertently omitted from 840112 motion for directed certification Maps provided to ASLAB members only. W/o encl
CALVERT, M S Bishop, L L CALVERT, M S Duke Power Co. 84/01/16. ROSENTHAL, A S., WILBER, H A, MOORE, T. B Atomic Safety and Licensing Appeal Panel 1p 21844 213 24X Fiche: 50-413,84/01/16,8401180216

8401190298 Informs that listed documents added to 840106 compilation of documents available for review Related correspondence
SHEARIN, R V Duke Power Co 84/01/16 GUILD, R Guild, R RIZEY, J L Carolina Environmental Study Group. GUILD, R Palmetto Alliance 1p. 21850 315 24X Fiche: 50-413,84/01/16,8401190298

8401240165 Forwards documents requested during 840116 visit to general ofcs W/o encl. Related correspondence
SHEARIN, R V Duke Power Co 84/01/17. LOWE, M Palmetto Alliance. 2pp 21910 297. 24X Fiche: 50-413,84/01/17,8401240165

8401260132 Response to first round of interrogatories & requests to produce re emergency planning Contentions 1,3,6-9,11,14,15 & 18 Certificate of Svc encl. Related correspondence.
RILEY, J L Carolina Environmental Study Group. RILEY, J L Palmetto Alliance RILEY, J L Riley, J L. 84/01/17. Duke Power Co. 7pp 21957 051. 24X Fiche: 50-413,84/01/17,8401260132

8401200144 Motion to bifurcate hearing & request for appointment of separate ASLB to rule on emergency plan contentions.
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/01/18 Atomic Safety and Licensing Board Panel 4pp. 21865 349. 24X Fiche 50-413,84/01/18,8401200144

--8401200146 Affidavit of WH Owen re current schedule for Unit 1 fuel loading & testing & power ascension phases Certificate of Svc encl
OWEN, W H Duke Power Co 84/01/18 4pp 21865 333. 24X Fiche 50-413,84/01/18,8401200144

DOCKETED ITEMS

8401240296 Advises of separate transmittal of requested documentation re lamination & foreman override Related correspondence.
CARR, A.V. Duke Power Co. 84/01/20 QUILD, R. Guild, R. 1p
21909 287 24X Fiche: 50-413, 84/01/20, 8401240296

---8401240300 Second round of interrogatories re Palmetto Alliance & Carolina Environ Study Group emergency planning Contentions 1, 3, 6-9, 11, 14, 15 & 18. Certificate of Svc encl. Related correspondence
MCQARRY, J.M. Duke Power Co. MCQARRY, J.M., Bishop, Liberman, Cook, Purcell & Reynolds 84/01/20 Carolina Environmental Study Group. 37pp 21909 290 24X Fiche: 50-413, 84/01/20, 8401240296

8401250194 Order postponing evidentiary hearing until 840130-31
KELLEY, J.L. Atomic Safety and Licensing Board Panel 84/01/20.
2pp. 21937 108 24X Fiche: 50-413, 84/01/20, 8401250194.

8401300231 Responds to 840123 telephone inquiry re termination date for discovery on emergency planning contentions All discovery must be completed by 840206 Copy of student emergency plan booklet encl. Related correspondence.
SHEARIN, R.V. Duke Power Co. 84/01/24. RILEY, J.L. Carolina Environmental Study Group. 8pp. 22062:139 24X
Fiche: 50-413, 84/01/24, 8401300231

8401300190 Motion for leave to file reply brief to applicant & NRC answers to Palmetto Alliance motion for directed certification of ASLB denial of discovery on newly admitted contentions.
CLEWETT, J. Palmetto Alliance. CLEWETT, J. Clewett, J. 84/01/25. Atomic Safety and Licensing Appeal Panel 2pp. 21996:220 24X
Fiche: 50-413, 84/01/25, 8401300190.

---8401300194 Brief in reply to applicant & NRC answers to Palmetto motion for directed certification of ASLB denial of discovery. Fair hearing should be held on newly admitted contentions
CLEWETT, J. Palmetto Alliance. CLEWETT, J. Clewett, J. 84/01/25 Atomic Safety and Licensing Appeal Panel. 8pp. 21996:222 24X
Fiche: 50-413, 84/01/25, 8401300190.

8401300197 Affidavit of HS Nunn in response to applicant suggestion of contrived testimony Certificate of Svc encl
NUNN, H.B. Palmetto Alliance. NUNN, H.B. Duke Power Co. 84/01/24
12pp. 21996:230 24X Fiche: 50-413, 84/01/25, 8401300190.

01310287 Requests Commission take action in DL hearings to enforce articulated policies re conduct of DL hearing. Commission should review views of chairman of ASLB & direct IE to apprise ASLB of findings & matl evidence.
* Government Accountability Project. 84/01/26 PALLADINO, N., OILINSKY, V., ABSELSTINE, J. Commissioners. 11pp. 22026:258 24X
Fiche: 50-413, 84/01/26, 8401310287.

8401310323 First round of interrogatories re Emergency Planning Contentions 1, 3, 6, 7, 8, 9, 11, 14, 15 & 18 Affirmation of Svc encl.
RILEY, J.L. Carolina Environmental Study Group. RILEY, J.L. Palmetto Alliance. 84/01/26 Duke Power Co. 23pp. 22020:306. 24X
Fiche: 50-413, 84/01/26, 8401310323.

8401310343 Forwards clear copy of WH Owen affidavit.
MCQARRY, J.M. Bishop, Liberman, Cook, Purcell & Reynolds 84/01/26. KELLEY, J.L., FOSTER, R.F., PURDOM, P.W. Atomic Safety and Licensing Board Panel. 1p. 22017:358. 24X Fiche: 50-413, 84/01/26, 8401310343

8401310339 Memorandum & order denying Palmetto Alliance motion for directed certification of ASLB 831213 oral ruling. Alliance fails to meet criteria for interlocutory review
BHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel 84/01/30. Palmetto Alliance. 2pp. 22019:352 24X Fiche: 50-413, 84/01/30, 8401310339.

H. General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Svc lists should be revised accordingly.
REYNOLDS, N.S. Bishop, Liberman, Cook, Purcell & Reynolds. REYNOLDS, N.S. Washington Public Power Supply System. 84/01/19. CLEMENTS, M.L. Docketing & Services Branch. 2pp. 21919:361. 24X
Fiche: 50-000, 84/01/19, 8401240335.

J. Insurance & indemnity information

8401100240 Forwards Endorsement 8 to NELIA Policy NF-281.
ROBBINS, J.O. Marsh & McLennan, Inc. 84/01/03. DINITZ, I. Assistant Director for State & Licensee Relations. 3pp. 21799:186. 24X
Fiche: 50-413, 84/01/03, 8401100240.

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J.M. Division of Rules and Records. 83/10/20. ZAHLER, R.E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

---8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp. 21744 004 24X Fiche 50-000, 83/10/20, 8401060040.

8401050665 Forwards IE Insp Repts 50-413/83-44 & 50-414/83-36 on 831115-18 No violations noted
DANCE, H.C. Division of Project & Resident Programs 83/12/09
TUCKER, H.B. Duke Power Co. 2pp 21724 144 24X
Fiche 50-413, 83/12/09, 8401050665

---8401050672 IE Insp Repts 50-413/83-44 & 50-414/83-36 on 831115-18 No violations noted Major areas inspected: spent fuel storage racks, records review, reactor vessel internals, review of QA implementing procedure & review of quality records
ECONOMOS, N. Region 2, Office of Director BLAKE, J.J. Division of Engineering & Operational Programs. 83/12/06 5pp 21724 146 24X Fiche 50-413, 83/12/09, 8401050665.

8401060471 Forwards final response to IE Bulletin 79-02, Rev 2 Util base plate flexibility accounted for in calculation of expansion anchor loads using conservative hand calculation method
TUCKER, H.B. Duke Power Co. 83/12/15. O'REILLY, J.P. Region 2, Office of Director. 5pp. 21740:258. 24X Fiche 50-413, 83/12/15, 8401060471

8401060301 Forwards IE Insp Repts 50-413/83-53 & 50-414/83-40 on 831206-09. No violations noted.
DANCE, H.C. Division of Project & Resident Programs. 83/12/21
TUCKER, H.B. Duke Power Co. 2pp 21741 357 24X
Fiche 50-413, 83/12/21, 8401060301

---8401060317 IE Insp Repts 50-413/83-53 & 50-414/83-40 on 831206-09. No violations noted Major areas inspected: containment penetrations, observation of work activities & review & evaluation of quality records.
ECONOMOS, N. Region 2, Office of Director BLAKE, J.J. Division of Engineering & Operational Programs 83/12/21. 4pp 21741:359. 24X Fiche 50-413, 83/12/21, 8401060301

8401060365 Informs of facilities needed to support NRC mobile lab onsite Lab used in routine insp program to verify util capability for analyzing radioactive effluents & to achieve & maintain comparable methods of analysis w/NRC
LEWIS, R.C. Division of Project & Resident Programs. 83/12/21
TUCKER, H.B. Duke Power Co. 1p 21741:162 24X
Fiche: 50-413, 83/12/21, 8401060365

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co. of New York, Inc 124pp 21731:166 24X Fiche: 50-000, 83/12/28, 8312120090

8401240607 Forwards IE Insp Rept 50-413/83-49 on 831205-09. No violations or deviations noted
DANCE, H.C. Division of Project & Resident Programs. 83/12/28. TUCKER, H.B. Duke Power Co. 2pp 21909:208 24X
Fiche: 50-413, 83/12/28, 8401240607.

---8401240613 IE Insp Rept 50-413/83-49 on 831205-09 No violations or deviations noted. Major areas inspected, integrated hot functional testing, preoperational test procedure review, inspector followup items & plant tour.
TAYLOR, P.A. Region 2, Office of Director. JAFFE, F. Division of Engineering & Operational Programs 83/12/23. 5pp 21909 210 24X Fiche: 50-413, 83/12/28, 8401240607

8401040195 Forwards 831221 ltr to util transmitting IE Insp Repts 50-413/83-53 & 50-414/83-40 re laminar indications in containment penetration sleeves.
JOHNSON, Q.E. Hearing Branch 4. 83/12/29. KELLEY, J.L., FOSTER, PURDOM, P.W. Atomic Safety and Licensing Board Panel 6pp. 21702:082. 24X Fiche: 50-413, 83/12/29, 8401040195.

8401060323 Ack receipt of IE Insp Repts 50-413/83-53 & 50-414/83-40 No proprietary info.
TUCKER, H.B. Duke Power Co. 83/12/29. O'REILLY, J.P. Region 2, Office of Director. 1p. 21742:329. 24X Fiche: 50-413, 83/12/29, 8401060323.

DOCKETED ITEMS

305

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401060401 Provides final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp. describing results of review of items identified in initial response dtd 831118 Elbows considered acceptable, as furnished
TUCKER, H. B. Duke Power Co. 83/12/30 O'REILLY, J. P. Region 2, Office of Director 2pp 21741 125 24X Fiche 50-413, 83/12/30, 8401060401

8401240351 Forwards IE Insp Rept 90-413/83-51 on 831205-07 No violations noted
DANCE, H. C. Division of Project & Resident Programs 83/12/30
TUCKER, H. B. Duke Power Co. 2pp 21920 293 24X
Fiche 50-413, 83/12/30, 8401240351

--8401240355 IE Insp Rept 90-413/83-51 on 831205-07 No violations noted
Major areas inspected design activities re self-initiated evaluation items, seismic analysis for as-built, safety-related piping sys & pipe support baseplate designs
AND, W. P. Region 2, Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 83/12/21 6pp 21920 295 24X Fiche 50-413, 83/12/30, 8401240351

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 129pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R. Licensing Branch 2 84/01/17 SCHWENGER, A. Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance w/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310308 Forwards IE Insp Rept 90-413/84-09 on 840103-06, No violations noted Details withheld (ref 10CFR2 790 & 21)
DANCE, H. C. Division of Project & Resident Programs. 84/01/27
TUCKER, H. B. Duke Power Co. 2pp 22019 296 24X
Fiche 50-413, 84/01/27, 8401310308

--8401310311 IE Insp Rept 90-413/84-09 on 840103-06 No noncompliance noted, Major areas inspected, SNM physical security storage plan & implementing procedures & security organization Details withheld (ref 10CFR2 790 & 73 21)
MCORE, D. E. Region 2, Office of Director, MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety 84/01/26 1p 22019 298 24X Fiche 50-413, 84/01/27, 8401310308

S Reportable occurrences, LERs & related correspondence

8401060417 Final Significant Deficiency Rept SD 413-414/79-02 re steam generator narrow-range level measurement errors, Ref leg will be insulated to minimize measurement errors due to ref leg heatup
TUCKER, H. B. Duke Power Co. 83/12/28, O'REILLY, J. P. Region 2, Office of Director, 7pp 21741 026 24X Fiche: 50-413, 83/12/28, 8401060417

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utills notified
BOYER, R. E. Transamerica Delaval, Inc. 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X
Fiche 50-000, 84/01/09, 8401170186

8401240290 Submits responses to NRC questions re util proposal to undertake Nelson Electric duties per Part 21 Proposal to apply only to purchases for new requirements, mod work & procurement of replacement parts after 830531
TUCKER, H. B. Duke Power Co. 84/01/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. Q. Licensing Branch 4 6pp 21920 193 24X Fiche 50-000, 84/01/13, 8401240290

--8401240297 Procedure NPM7, "Procedure for Reporting of Defects of Noncompliance on Nuclear Orders "
* Duke Power Co. 84/01/13 11pp 21920 199 24X
Fiche 50-000, 84/01/13, 8401240290

--8401240302 Rev 6 to Procedure QA-121, "NRC Reporting Requirements "
HENRY, W. D. Duke Power Co. 82/10/25 8pp 21920 212 24X
Fiche 50-000, 84/01/13, 8401240290

--8401240312 Rev 9 to Procedure PR-270, "NRC Reporting Requirements, "
HENRY, W. D. Duke Power Co. 83/09/27 9pp 21920 220 24X
Fiche 50-000, 84/01/13, 8401240290

--8401240324 Rev 6 to Procedure R-5, "NRC Reporting Requirements "
HENRY, W. D. Duke Power Co. 82/10/25 10pp 21920 229 24X
Fiche 50-000, 84/01/13, 8401240290

8401240389 Forwards final response to Significant Deficiency Rept SD 413-414/79-02 re steam generator narrow-range level measurement errors
TUCKER, H. B. Duke Power Co. 84/01/17, DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. Q. Licensing Branch 4 2pp 21915 243 24X Fiche 50-413, 84/01/17, 8401240389

--8401240404 Final Significant Deficiency Rept SD 413-414/79-02 re steam generator narrow-range level measurement errors, To minimize errors, installation of mirror insulation to be completed prior to testing
TUCKER, H. B. Duke Power Co. 84/01/17 O'REILLY, J. P. Region 2, Office of Director 7pp 21915 243 24X Fiche 50-413, 84/01/17, 8401240389

U Congressional/Executive Correspondence

8401100126 Responds to 831101 ltr expressing concerns re NRC efforts to pursue allegations of safety-related deficiencies at nuclear const sites Use of confidentiality formally incorporated into Opc of investigations procedures
FALLADINO, N. J. Commissioners 84/01/09 UDALL, M. K. House of Rep , Interior & Insular Affairs. 5pp 21761 067 24X
Fiche 50-413, 84/01/09, 8401100126

--8401100133 Expresses concern re Commission effort to pursue allegations of safety-related deficiencies at nuclear const sites, Advisory Committee for Review of Investigation Policy , rept failed to address grant of confidentiality
UDALL, M. K. House of Rep , Interior & Insular Affairs 83/11/01 FALLADINO, N. J. Commissioners. 2pp 21761 072 24X
Fiche: 50-413, 84/01/09, 8401100126

V Operator Examinations

8401060353 Requests submittal by 840104 of selected ref matl in approved list in Encl 1 to meet schedules for written & oral licensing exams scheduled for wk of 840305
DANCE, H. C. Division of Project & Resident Programs. 83/12/05
TUCKER, H. B. Duke Power Co. 4pp 21741 171 24X
Fiche 50-413, 83/12/05, 8401060353

DOCKET 50-414 CATANBA NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8401270123 Submits results of review of geologic & seismic data in FSAR Sections 2.5.1 through 2.5.3 & other related studies Site geologically acceptable & meets NRC requirements
PLANNER, H. N. NEWTON, C. A. Los Alamos Scientific Laboratory. 83/11/17, JACKSON, R. E. Geosciences Branch. 4pp 21982 027 24X
Fiche 50-413, 83/11/17, 8401270123

DOCKETED ITEMS

- 8401060307 Expresses appreciation for assistance of State of SC Dept of Health & Environ Control w/implementation of TLD direct radiation monitoring network Encl list of TLD station locations available in Central Files only
LEWIS, R C Division of Project & Resident Programs 83/11/29
TUCKER, H B Duke Power Co 2pp 21741 120 24X
Fiche 50-413, 83/11/29, 8401060307
- 8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHIAS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M
Assistant Director for Licensing 19pp 22034 358 24X
Fiche 50-000, 83/12/16, 8312200154
- 8401040234 Forwards facility staffing survey, per KN Jabbour 831206 request
TUCKER, H B Duke Power Co 83/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 5pp 21701 183 24X Fiche 50-413, 83/12/21, 8401040234
- 8401130097 Forwards TM Novak ltr to JP McLaughy re series of questions on emergency diesel generators mfg by Transamerica Delaval, Inc Response may be submitted by ref to owners group or plant-specific repts w/o encl
ADENSAM, E G Licensing Branch 4 83/12/30 TUCKER, H B. Duke Power Co. 1p. 21821 125 24X Fiche 50-413, 83/12/30, 8401130097
- 8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D O Division of Licensing 84/01/05 FALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108
- 8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382
- 8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Bvc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp. 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221
- 8401170359 Forwards offsite dose calculation manual
TUCKER, H B Duke Power Co. 84/01/10. DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 1p. 21829.071 24X Fiche: 50-413, 84/01/10, 8401170359.
- 8401170360 Offsite dose calculation manual.
* Duke Power Co 84/01/10. 32pp 21829.072 24X
Fiche. 50-413, 84/01/10, 8401170359
- 8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Bvc list encl
EISENHUT, D O Division of Licensing. 84/01/13 Consolidated Edison Co of New York, Inc 18pp. 21946 174 24X
Fiche: 50-000, 84/01/13, 8401130084
- 8401270536 Notification of 840126 meeting w/OL applicants in Bethesda. MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing. 1p 22000.349 24X Fiche 50-000, 84/01/17, 8401270536.
- E. NRC Safety Evaluation Report (SER), supplis & correspondence
- 8401240283 Forwards revised response to Question 430 110 re Confirmatory Item 38 of SER Section 8.4 10, concerning 100% load reduction capability Problem w/voltage excursions following load rejections not indicated.
TUCKER, H B. Duke Power Co 84/01/17. DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E G. Licensing Branch 4. 2pp. 21909.353. 24X Fiche: 50-413, 84/01/17, 8401240283.
- 8401270181 Responds to Open Item 16 in Section 13.3 of SSER 1 re emergency planning & meteorology. Sufficient staff & facilities available in crisis mgt ctr to respond in event of simultaneous emergencies at Catawba & McGuire.
TUCKER, H B Duke Power Co 84/01/19. DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4. 2pp. 21982.069. 24X Fiche: 50-413, 84/01/19, 8401270181
- 8401310280 Forwards info requested at 830923 meeting re SER Open Item 4 on seismic qualification of equipment Info includes revised FSAR Table 3.10-1 & computer list of safety-related electronic equipment
TUCKER, H B Duke Power Co 84/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 83pp 22015 214 24X Fiche 50-413, 84/01/20, 8401310280
- 8401270254 Responds to open item in SER Section 13.5 1.3 re NUREG-0737, Item I A 1.1, "Shift Technical Advisor" On-shift staff will include shift engineer, fulfilling TH1 item requirements
Revised FSAR pages encl
TUCKER, H B Duke Power Co 84/01/24. DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 10pp 21982 184 24X Fiche 50-413, 84/01/24, 8401270254
- F Security, medical, emergency & fire protection plans
- 8401250262 Responds to questions raised at meeting to arrange for informal discovery No NRC-FEMA communications re offsite emergency plans occurred NRC will issue SER suppl containing comments on FEMA findings FEMA external correspondence encl
JOHNSON, O E Hearing Branch 4 84/01/10 GUILD, R Guild, R 17pp 21944 190 24X Fiche 50-413, 84/01/10, 8401250262
- 8401240171 Forwards two oversize drawings showing location of sprinkler heads in Unit 1 annulus Aperture cards are available in PDR.
TUCKER, H B. Duke Power Co. 84/01/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 2pp 21910 251 24X Fiche 50-413, 84/01/17, 8401240171
- 8401270181 Responds to Open Item 16 in Section 13.3 of SSER 1 re emergency planning & meteorology Sufficient staff & facilities available in crisis mgt ctr to respond in event of simultaneous emergencies at Catawba & McGuire
TUCKER, H B. Duke Power Co 84/01/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21982 069. 24X
Fiche 50-413, 84/01/19, 8401270181
- 8401300231 Responds to 840123 telephone inquiry re termination date for discovery on emergency planning contentions All discovery must be completed by 840206 Copy of student emergency plan booklet encl Related correspondence
SHEARIN, R V. Duke Power Co 84/01/24 RILEY, J L Carolina Environmental Study Group. 8pp 22062 139. 24X
Fiche: 50-413, 84/01/24, 8401300231
- G Adjudicatory correspondence
- 8401040195 Forwards 831221 ltr to util transmitting IE Insp Repts 50-413/83-93 & 50-414/83-40 re laminar indications in containment penetration sleeves
JOHNSON, O E Hearing Branch 4 83/12/29. KELLEY, J L, FOSTER, FURDOM, P W Atomic Safety and Licensing Board Panel 6pp 21702 082. 24X Fiche: 50-413, 83/12/29, 8401040195
- 8401050230 Memorandum & order denying util 831103 motion for reconsideration re revised emergency planning Contention II Denial should not be interpreted as active opposition to interjectory review
KELLEY, J L Atomic Safety and Licensing Board Panel. 83/12/30 Duke Power Co. 5pp 21728 273 24X Fiche: 50-413, 83/12/30, 8401050230.
- 8401050233 Order confirming ASLB 831216 oral rulings closing record & setting schedule for filing proposed findings of fact, conclusions of law & proposed license conditions. Record on Contentions 16, 18/44 & 17 closed on 831216
KELLEY, J L Atomic Safety and Licensing Board Panel. 83/12/30 Duke Power Co 5pp. 21729 259. 24X Fiche: 50-413, 83/12/30, 8401050233.
- 8401050247 Response opposing Palmetto Alliance motions to direct certification of ASLB rulings on discovery re in camera witness testimony & to require that record remain open pending opportunity for discovery. W/Certificate of Bvc.
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds. 84/01/03. Atomic Safety and Licensing Appeal Panel 33pp 21729 111. 24X Fiche: 50-413, 84/01/03, 8401050247.
- 8401120193 Forwards two ASLB orders addressing emergency planning contentions Encl supplis 830816 matl. w/o encl
JOHNSON, O E Hearing Branch 4 84/01/04 PERRY, B. Federal Emergency Management Agency. 1p. 21793.352. 24X
Fiche: 50-413, 84/01/04, 8401120193
- 8401120216 Forwards NRC opposition to Palmetto Alliance motions for directed certification of ASLB denial of further discovery on in camera issues & of motion to hold record open. Pleading should be treated per terms of 831011 order.
JOHNSON, O E. Hearing Branch 4 84/01/05 KELLEY, J L, FURDOM, P W, FOSTER, R F. Atomic Safety and Licensing Board Panel 1p. 21791 204 24X Fiche. 50-413, 84/01/05, 8401120216

DOCKETED ITEMS

30

8401120224 Forwards NRC opposition to Palmetto Alliance motions for directed certification of ASLB denial of further discovery on in camera issues & of motion to hold record open Pleading should be treated per terms of 831101 order
JOHNSON, G E Hearing Branch 4 84/01/05 GUILD, R Guild, R
GUILD, R Palmetto Alliance 1p 21793 261 24X
Fiche 50-413, 84/01/05, 8401120224

8401120252 Forwards staff opposition to Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold open record Pleading should be treated per terms of 831101 order W/o encl
JOHNSON, G E Hearing Branch 4 84/01/05 WILSON, R P South Carolina, State of 1p 21793 282 24X Fiche 50-413, 84/01/05, 8401120252

8401120310 Forwards ltr to ASLB & NRC response opposing Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold record open W/o encl
JOHNSON, G E Operations & Administrative Division 84/01/05
MCGARRY, J M Debevoise & Liberman 1p 21792 188 24X
Fiche 50-413, 84/01/05, 8401120310

8401120315 Forwards NRC pleading in opposition to Palmetto Alliance motions for directed certification of ASLB ruling denying further discovery on in camera issues & to hold record open W/o encl
JOHNSON, G E Hearing Branch 4 84/01/05 ROSENTHAL, A S ,
WILBER, H A , MOORE, T B Atomic Safety and Licensing Appeal Panel 2pp 21792 189 24X Fiche 50-413, 84/01/05, 8401120315

8401120300 Responds to requests for documents re correspondence between FEMA & NRC on offsite plans & for BER suppl commenting on FEMA findings Date not established for BER issuance W/o encl
JOHNSON, G E Regulations Division 84/01/10 GUILD, R Guild, R 2pp 21791 010 24X Fiche 50-413, 84/01/10, 8401120300.

8401250262 Responds to questions raised at meeting to arrange for informal discovery No NRC-FEMA communications re offsite emergency plans occurred NRC will issue BER suppl containing comments on FEMA findings FEMA external correspondence encl
JOHNSON, G E Hearing Branch 4 84/01/10 GUILD, R Guild, R 17pp 21944 190 24X Fiche 50-413, 84/01/10, 8401250262

--8401250272 Forwards emergency planning contentions admitted by ASLB on 830808. Portions of transcript which constitute rulings on contentions also encl W/o encl
JOHNSON, G E Hearing Branch 4 83/08/16 PERRY, S Federal Emergency Management Agency 1p 21944 207 24X
Fiche 50-413, 84/01/10, 8401250262

8401160258 Petition for directed certification of ASLB 831230 denial of applicant motion to reconsider order revising & admitting emergency planning Contention 11 re size of emergency planning zone Certificate of Svc encl
MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 84/01/12 Atomic Safety and Licensing Appeal Panel 38pp 21814 114 24X Fiche 50-413, 84/01/12, 8401160258

8401250101 Forwards documentation re License SNM-1920 authorizing receipt & storage of new fuel in shipping containers at Unit 1 License does not relate to OL proceeding contention re storage of spent fuel from other unit facilities
JOHNSON, G E Hearing Branch 4 84/01/12 KELLEY, J L , PURDOM, P W ,
FOSTER, R F Atomic Safety and Licensing Board Panel 17pp 21940 208 24X Fiche 50-413, 84/01/12, 8401250101.

8401170268 Memorandum & order setting 840126 as starting date & Charlotte, NC as place for evidentiary hearing on five in camera matters listed in ASLB 831230 order
KELLEY, J L Atomic Safety and Licensing Board Panel 84/01/13, 4pp 21831 001 24X Fiche 50-413, 84/01/13, 8401170268

8401180222 Forwards pages of 830907 transcript relevant to applicant opposition to admission of intervenor late-filed contention re adequacy of diesel generator crankshaft. Intervenor late filing inexcusable.
MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds
MCGARRY, J M Duke Power Co 84/01/13 KELLEY, J L , PURDOM, P W ,
FOSTER, R F Atomic Safety and Licensing Board Panel 4pp 21844 223 24X Fiche 50-413, 84/01/13, 8401180222

--8401180228 Forwards attachments inadvertently omitted from 840112 motion for directed certification of ASLB 831230 ruling revising & admitting Contention 11 re emergency planning Notice of appearance encl
CALVERT, M S Bishop, Liberman, Cook, Purcell & Reynolds
CALVERT, M S Duke Power Co 84/01/13 ROSENTHAL, A S ,
MOORE, T B , WILBER, H A Atomic Safety and Licensing Appeal Panel, 33pp 21844 227 24X Fiche 50-413, 84/01/13, 8401180222

8401180216 Forwards maps inadvertently omitted from 840112 motion for directed certification Maps provided to ASLB members only W/o encl
CALVERT, M S Bishop, L L CALVERT, M S Duke Power Co 84/01/16
ROSENTHAL, A S , WILBER, H A , MOORE, T B Atomic Safety and Licensing Appeal Panel 1p 21844 213 24X Fiche 50-413, 84/01/16, 8401180216

8401190278 Informs that listed documents added to 840106 compilation of documents available for review Related correspondence
SHEARIN, R V Duke Power Co 84/01/16 GUILD, R Guild, R
RIZEY, J L Carolina Environmental Study Group GUILD, R Palmetto Alliance 1p 21850 315 24X Fiche 50-413, 84/01/16, 8401190278

8401240165 Forwards documents requested during 840116 visit to general ofcs W/o encl Related correspondence
SHEARIN, R V Duke Power Co 84/01/17 LOWE, M Palmetto Alliance 2pp 21910 297 24X Fiche 50-413, 84/01/17, 8401240165

8401260132 Response to first round of interrogatories & requests to produce re emergency planning Contentions 1, 3, 6-9, 11, 14, 15 & 18 Certificate of Svc encl Related correspondence
RILEY, J L Carolina Environmental Study Group RILEY, J L Palmetto Alliance RILEY, J L Riley, J L 84/01/17 Duke Power Co 7pp 21957 051 24X Fiche 50-413, 84/01/17, 8401260132

8401200144 Motion to bifurcate hearing & request for appointment of separate ASLB to rule on emergency plan contentions
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/01/18 Atomic Safety and Licensing Board Panel 4pp 21865 349 24X Fiche 50-413, 84/01/18, 8401200144.

--8401200146 Affidavit of WH Owen re current schedule for Unit 1 fuel loading & testing & power ascension phases Certificate of Svc encl
OWEN, W H Duke Power Co 84/01/18 4pp 21865 353 24X
Fiche 50-413, 84/01/18, 8401200144

8401240296 Advises of separate transmittal of requested documentation re lamination & foreman override. Related correspondence.
CARR, A V Duke Power Co 84/01/20 GUILD, R Guild, R 1p 21909 289 24X Fiche 50-413, 84/01/20, 8401240296

--8401240300 Second round of interrogatories re Palmetto Alliance & Carolina Environ Study Group emergency planning Contentions 1, 3, 6-9, 11, 14, 15 & 18. Certificate of Svc encl Related correspondence
MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/01/20 Carolina Environmental Study Group 37pp 21909 290 24X Fiche 50-413, 84/01/20, 8401240296

8401250194 Order postponing evidentiary hearing until 840130-31
KELLEY, J L Atomic Safety and Licensing Board Panel 84/01/20, 2pp 21937 108 24X Fiche 50-413, 84/01/20, 8401250194

8401300231 Responds to 840123 telephone inquiry re termination date for discovery on emergency planning contentions A71 discovery must be completed by 840206 Copy of student emergency plan booklet encl Related correspondence.
SHEARIN, R V Duke Power Co 84/01/24 RILEY, J L Carolina Environmental Study Group 8pp 22062 139 24X
Fiche 50-413, 84/01/24, 8401300231

8401300190 Motion for leave to file reply brief to applicant & NRC answers to Palmetto Alliance motion for directed certification of ASLB denial of discovery on newly admitted contentions
CLEWETT, J Palmetto Alliance CLEWETT, J Clewett, J 84/01/25 Atomic Safety and Licensing Appeal Panel 2pp 21996 220 24X
Fiche 50-413, 84/01/25, 8401300190

--8401300194 Brief in reply to applicant & NRC answers to Palmetto motion for directed certification of ASLB denial of discovery Fair hearing should be held on newly admitted contentions.
CLEWETT, J Palmetto Alliance CLEWETT, J Clewett, J 84/01/25 Atomic Safety and Licensing Appeal Panel 8pp 21996 222 24X
Fiche 50-413, 84/01/25, 8401300190

--8401300197 Affidavit of HB Nunn in response to applicant suggestion of contrived testimony Certificate of Svc encl
NUNN, H B Palmetto Alliance NUNN, H B Duke Power Co 84/01/24, 12pp 21996 230 24X Fiche 50-413, 84/01/25, 8401300190.

8401310287 Requests Commission take action in OL hearings to enforce articulated policies re conduct of OL hearing. Commission should review views of chairman of ASLB & direct IE to appraise ASLB of findings & metl evidence.
* Government Accountability Project 84/01/26 PALLADINO, N ,
GILINSKY, V , ABSELESTINE, J Commissioners 11pp 22026 258 24X
Fiche 50-413, 84/01/26, 8401310287

DOCKETED ITEMS

8401310323 First round of interrogatories re Emergency Planning Contentions 1,3,6,7,8,9,11,14,15 & 18 Affirmation of Svc encl
RILEY, J. L. Carolina Environmental Study Group RILEY, J. L. Palmetto Alliance 84/01/26 Duke Power Co 23pp 22020 306 24X
Fiche 50-413, 84/01/26, 8401310323

8401310343 Forwards clear copy of WH Owen affidavit
MCGARRY, J. M. Bishop, Liberman, Cook, Purcell & Reynolds 84/01/26 KELLEY, J. L., FOSTER, R. F., PURDOM, P. W. Atomic Safety and Licensing Board Panel 1p 22017 358 24X Fiche 50-413, 84/01/26, 8401310343

8401310339 Memorandum & order denying Palmetto Alliance motion for directed certification of ASLB 831213 oral ruling Alliance fails to meet criteria for interlocutory review
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 84/01/30 Palmetto Alliance 2pp 22019 352 24X Fiche 50-413, 84/01/30, 8401310339

M General correspondence

8401240335 Informs that firm name of counsel for applicants/licenseses charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N. B. Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS, N. B. Washington Public Power Supply System 84/01/19 CLEMENTS, W. L. Docketing & Services Branch 2pp 21919 361 24X
Fiche 50-000, 84/01/19, 8401240335

J Insurance & indemnity information

8401100240 Forwards Endorsement 8 to NELIA Policy NF-281
ROBBINS, J. O. Marsh & McLennan, Inc 84/01/03. DINITZ, I. Assistant Director for State & License Relations. 3pp. 21759 186 24X
Fiche 50-413, 84/01/03, 8401100240

Q. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/20. ZAHNER, R. E. Shaw, Pittman, Potts & Trowbridge 1p. 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

8401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004. 24X Fiche 50-000, 83/10/20, 8401060040.

8401090665 Forwards IE Insp Repts 30x413/83-44 & 50-414/83-36 on 831115-18. No violations noted
DANCE, H. C. Division of Project & Resident Programs 83/12/09 TUCKER, H. B. Duke Power Co 2pp 21724 144. 24X
Fiche 50-413, 83/12/09, 8401090665

8401050672 IE Insp Repts 50-413/83-44 & 50-414/83-36 on 831115-18 No violations noted Major areas inspected: spent fuel storage racks, records review, reactor vessel internals, review of QA implementing procedure & review of quality records
ECONOMOS, N. Region 2, Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 83/12/06. 5pp 21724 146. 24X Fiche 50-413, 83/12/09, 8401050672.

8401060471 Forwards final response to IE Bulletin 79-02, Rev 2 Util base plate flexibility accounted for in calculation of expansion anchor loads using conservative hand calculation method.
TUCKER, H. B. Duke Power Co. 83/12/15 O'REILLY, J. P. Region 2, Office of Director. 5pp 21740 258 24X Fiche 50-413, 83/12/15, 8401060471.

8401060301 Forwards IE Insp Repts 50-413/83-53 & 50-414/83-40 on 831206-09. No violations noted.
DANCE, H. C. Division of Project & Resident Programs 83/12/21. TUCKER, H. B. Duke Power Co. 2pp. 21741 357. 24X
Fiche 50-413, 83/12/21, 8401060301

8401060317 IE Insp Repts 50-413/83-53 & 50-414/83-40 on 831206-09. No violations noted. Major areas inspected: containment penetrations, observation of work activities & review & evaluation of quality records
ECONOMOS, N. Region 2, Office of Director. BLAKE, J. J. Division of Engineering & Operational Programs 83/12/21. 4pp 21741 359 24X Fiche 50-413, 83/12/21, 8401060317

8401060365 Informs of facilities needed to support NRC mobile lab onsite Lab used in routine insp program to verify util capability for analyzing radioactive effluents & to achieve & maintain comparable methods of analyses w/NRC
LEWIS, R. C. Division of Project & Resident Programs 83/12/21 TUCKER, H. B. Duke Power Co 1p 21741 162 24X
Fiche 50-413, 83/12/21, 8401060365

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401040195 Forwards 831221 ltr to util transmitting IE Insp Repts 50-413/83-53 & 50-414/83-40 re laminar indications in containment penetration sleeves
JOHNSON, O. E. Hearing Branch 4 83/12/29 KELLEY, J. L. Atomic Safety and Licensing Board Panel 6pp 21702 082 24X
Fiche 50-413, 83/12/29, 8401040195

8401060323 Ack receipt of IE Insp Repts 50-413/83-53 & 50-414/83-40 No proprietary info
TUCKER, H. B. Duke Power Co 83/12/29 O'REILLY, J. P. Region 2, Office of Director 1p 21742 329 24X Fiche 50-413, 83/12/29, 8401060323.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401060401 Provides final response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp, describing results of review of items identified in initial response dtd 831118. Elbows considered acceptable, as furnished
TUCKER, H. B. Duke Power Co 83/12/30 O'REILLY, J. P. Region 2, Office of Director 2pp 21741 125 24X Fiche 50-413, 83/12/30, 8401060401

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184. 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16. Consolidated Edison Co. of New York, Inc. 127pp 21957 142. 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utls & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R. Licensing Branch 2. 84/01/17. SCHWENGER, A. Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18. Consolidated Edison Co. of New York, Inc. 118pp 22000 001. 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns. " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18. Consolidated Edison Co. of New York, Inc. 120pp. 22000 041. 24X Fiche 50-000, 84/01/18, 8312120117

B Reportable occurrences, LERs & related correspondence

8401030160 Significant Deficiency Rept SD 414/83-17 re installation of special welding bosses instead of special welding boss restrictors. Initially reported on 831222. Special restrictors installed as required by design drawings
TUCKER, H. B. Duke Power Co 83/12/22 O'REILLY, J. P. Region 2, Office of Director. 3pp. 21682 360. 24X Fiche 50-414, 83/12/22, 8401030160.

DOCKETED ITEMS

309

B401060417 Final Significant Deficiency Rept BD 413-414/79-02 re steam generator narrow-range level measurement errors Ref leg will be insulated to minimize measurement errors due to ref leg heatup.
TUCKER, H. B. Duke Power Co 83/12/28 O'REILLY, J. P. Region 2, Office of Director 7pp 21741 026 24X Fiche 50-413, 83/12/28, B401060417

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified
BOYER, R. E. Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche 50-000, 84/01/09, B401170186

B401240400 Interim Deficiency Rept BD 413-414/80-03 re guide tube support pins Pins will be installed during reactor vessel internals assembly, beginning B40109 Completion expected by B40315.
TUCKER, H. B. Duke Power Co 84/01/11 O'REILLY, J. P. Region 2, Office of Director 1p 21915 232 24X Fiche 50-414, 84/01/11, B401240400

B401240290 Submits responses to NRC questions re util proposal to undertake Nelson Electric duties per Part 21 Proposal to apply only to purchases for new requirements, mod work & procurement of replacement parts after B30531
TUCKER, H. B. Duke Power Co 84/01/13 ADENSAM, E. O. Office of Nuclear Reactor Regulation, Director 6pp 21920 193 24X Fiche 50-000, 84/01/13, B401240290

--B401240297 Procedure NPM7, "Procedure for Reporting of Defects of Noncompliance on Nuclear Orders."
* Duke Power Co. 84/01/13 11pp 21920 199 24X Fiche 50-000, 84/01/13, B401240290

--B401240302 Rev 6 to Procedure QA-121, "NRC Reporting Requirements"
HENRY, W. G. Duke Power Co 82/10/25 8pp 21920 212 24X Fiche 50-000, 84/01/13, B401240290.

--B401240312 Rev 9 to Procedure PR-290, "NRC Reporting Requirements"
HENRY, W. G. Duke Power Co 83/09/27 9pp 21920, 220 24X Fiche: 50-000, 84/01/13, B401240290

--B401240324 Rev 4 to Procedure R-5, "NRC Reporting Requirements"
HENRY, W. G. Duke Power Co 82/10/25 10pp 21920 229, 24X Fiche: 50-000, 84/01/13, B401240290

B401240389 Forwards final response to Significant Deficiency Rept BD 413-414/79-02 re steam generator narrow-range level measurement errors
TUCKER, H. B. Duke Power Co 84/01/17 DEYTON, H. R. Office of Nuclear Reactor Regulation, Director, ADENSAM, E. O. Licensing Branch 4, 2pp, 21915 243 24X Fiche, 50-413, 84/01/17, B401240389

--B401240404 Final Significant Deficiency Rept BD 413-414/79-02 re steam generator narrow-range level measurement errors To minimize errors, installation of mirror insulation to be completed prior to testing
TUCKER, H. B. Duke Power Co 84/01/17, O'REILLY, J. P. Region 2, Office of Director 7pp 21915 243 24X Fiche: 50-413, 84/01/17, B401240389.

U Congressional/Executive Correspondence

B401100126 Responds to B31101 ltr expressing concerns re NRC efforts to pursue allegations of safety-related deficiencies at nuclear const sites Use of confidentiality formally incorporated into Ofc of Investigations procedures
PALLADINO, N. J. Commissioners 84/01/09 UDALL, M. K. House of Rep, Interior & Insular Affairs, 5pp 21761 067 24X Fiche: 50-413, 84/01/09, B401100126

--B401100133 Expresses concern re Commission effort to pursue allegations of safety-related deficiencies at nuclear const sites Advisory Committee for Review of Investigation Policy re:pt failed to address grant of confidentiality
UDALL, M. K. House of Rep, Interior & Insular Affairs, 83/11/01, PALLADINO, N. J. Commissioners, 2pp 21761 072 24X Fiche: 50-413, 84/01/09, B401100126

V. Operator Examinations

B401060353 Requests submittal by B40104 of selected ref matl in approved list in Encl 1 to meet schedules for written & oral licensing exams scheduled for wk of B40305
DANCE, H. C. Division of Project & Resident Programs, 83/12/05, TUCKER, H. B. Duke Power Co 4pp 21741 171 24X Fiche: 50-413, 83/12/05, B401060353

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing 1p, 22000:349 24X Fiche 50-000, 84/01/17, B401270536.

F Security, medical, emergency & fire protection plans

B401060483 Forwards IE Insp Rept 50-416/83-53 on B31031-1104 No Violations noted
VERRELLI, D. M. Division of Project & Resident Programs 83/12/02 RICHARD, J. B. Mississippi Power & Light Co 2pp, 21740 194 24X Fiche 50-416, 83/12/02, B401060483

--B401060491 IE Insp Rept 50-416/83-53 on B31031-1104 No violations noted Major areas inspected health physics organization, qualifications & experience of health physics personnel, radiation procedures, work permit & ALARA program.
KAHLE, J. B., WEDDINGTON, R. E. Region 2, Office of Director, BARR, K. P. Division of Engineering & Operational Programs, 83/11/30 6pp, 21740 196 24X Fiche 50-416, 83/12/02, B401060483.

B401060159 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 83/12/28 Document Management Branch 1p, 21745:039 24X Fiche, 50-416, 83/12/28, B401060159

--B401060165 Forwards public version of revised emergency plan implementing procedures, including Procedures 10-B-01-19 re personnel injury, 10-B-01-25 re onsite personnel response & 10-B-01-26 re offsite emergency response
MCQUAGHY, J. P. Mississippi Power & Light Co, 83/11/29 O'REILLY, J. P. Region 2, Office of Director 1p 21745.060, 24X Fiche: 50-416, 83/12/28, B401060159

--B401060171 Public version of revised emergency plan implementing procedures, including Procedures 10-B-01-19 re personnel injury, 10-B-01-25 re onsite personnel response & 10-B-01-26 re offsite emergency response
HURLEY, J., CROSS, J. S. Mississippi Power & Light Co 83/11/07, 62pp 21745 061 24X Fiche 50-416, 83/12/28, B401060159

B401260269 Releases public version of revised emergency plan.
FELTON, J. M. Division of Rules and Records 84/01/18, Document Management Branch 1p 21991 190 24X Fiche: 50-416, 84/01/18, B401260269

--B401260286 Public version of Rev B to emergency plan W/831219 ltr.
BENEDICT, P., DALE, L. F., HUTCHINSON, C. R. Mississippi Power & Light Co 83/11/21, 77pp 21991 191, 24X Fiche: 50-416, 84/01/18, B401260269

G Adjudicatory correspondence

B401090625 Forwards executed certificate re pollution control facilities, per B30916 request concerning resolution adopted B30610 by Board of Supervisors of Claiborne County, MO.
CASE, E. O. Office of Nuclear Reactor Regulation, Director 83/12/21 CONNER, T. B. Conner & Wetterhahn, 4pp, 21767 252, 24X Fiche: 50-416, 83/12/21, B401090625.

B401120233 Response to Jacksonians United for Livable Energy Policies (JULEP) B31211 amended request for adjudicatory hearing on Amend 10, JULEP should be admitted as party to proceeding Certificate of Bvc encl
WAGNER, M. E. Hearing Branch 4 84/01/03 Atomic Safety and Licensing Board Panel 7pp, 21794.049, 24X Fiche: 50-416, 84/01/03, B401120233

B401180212 Response to NRC & licensee answers to Jacksonians United for Livable Energy Policies B31117 petition to intervene & request for hearing & B31211 amended petition, Certificate of Bvc encl.
STEWART, C. A. Jacksonians United for Livable Energy Policies, 84/01/12, Atomic Safety and Licensing Board Panel, 20pp, 21844 178 24X Fiche, 50-416, 84/01/12, B401180212.

B401300122 Notice of appearance in proceeding, Certificate of Bvc encl
MCQUEEN, R. B. Mississippi Power & Light Co. MCQUEEN, R. B. Conner & Wetterhahn 84/01/24 3pp, 21799.091 24X Fiche: 50-416, 84/01/24, B401300122

DOCKETED ITEMS

H. General correspondence

8401100248 Requests correspondence presently addressed to JF Fager be changed to RT Lally
MACHADO, C K Middle South Services, Inc 84/01/05 NOVAK, T M
Division of Licensing 1p 21799 189 24X Fiche: 50-416, 84/01/05, 8401100248.

8401120191 Requests all correspondence currently being sent to JF Fager be sent to RT Lally at listed address
MACHADO, C K Middle South Services, Inc 84/01/05 CASE, E Q
Office of Nuclear Reactor Regulation, Director. 1p 21793 231 24X
Fiche: 50-416, 84/01/05, 8401120191

K. Utility Final Safety Analysis Report (FSAR) & Amends

8401060456 Forwards Affidavit of Svc on distribution of application for licenses, consisting of Amend 37 to FSAR
DALE, L F. Mississippi Power & Light Co 83/12/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21739 361
24X Fiche: 50-416, 83/12/28, 8401060456

P. Operating license stage documents & correspondence

8401030316 Forwards questionnaire on staffing for Unit 1. Response requested by 831230 Similar questionnaire telecopied to unit earlier for Unit 2
SCHMENCER, A. Licensing Branch 2 83/12/12 MCGOUGH, J P.
Mississippi Power & Light Co 4pp 21693 300 24X
Fiche: 50-416, 83/12/12, 8401030316

8312200154 Forwards response to nine Users Group questions presented at 831100 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C B Transamerica Delaval, Inc 83/12/16 NOVAK, T M
Assistant Director for Licensing 19pp 22054 358 24X
Fiche: 50-000, 83/12/16, 8312200154

8401060456 Forwards Affidavit of Svc on distribution of application for licenses, consisting of Amend 37 to FSAR.
DALE, L F. Mississippi Power & Light Co 83/12/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21739 361
24X Fiche: 50-416, 83/12/28, 8401060456

8401090544 Requests that encl TM Novak 831227 request for addl info re Transamerica Delaval emergency diesel generators be answered specifically
SCHMENCER, A. Licensing Branch 2 83/12/29 MCGOUGH, J P
Mississippi Power & Light Co 2pp 21757 244 24X
Fiche: 50-416, 83/12/29, 8401090544.

--8401060639 Forwards list of NRC questions re Delaval diesel generators Questions address generic concerns which could be effectively answered by Owners Group
NOVAK, T M. Assistant Director for Licensing 83/12/27
MCGOUGH, J P. Mississippi Power & Light Co 3pp 21795 327 24X
Fiche: 50-416, 83/12/29, 8401090544.

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O. Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche: 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D O. Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc. 18pp 21957 267 24X
Fiche: 50-000, 84/01/06, 8401090221.

8401100336 Forwards response to 831212 request for info re plant staffing & experience. Experience of personnel during const & preoperational phases offset lack of BWR operating experience
DALE, L F. Mississippi Power & Light Co 84/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 3pp 21764 112
24X Fiche: 50-416, 84/01/06, 8401100336.

8401100371 Forwards proprietary affidavit & figures referenced in util 840106 response to NRC questions re Agastat relays Encls withheld (ref 10CFR2.790).
DALE, L F. Mississippi Power & Light Co 84/01/06. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 2pp 21764 088.
24X Fiche: 50-416, 84/01/06, 8401100371.

8401100478 Endorses safety review committee on operational readiness review for 5% power Util mgt reviewed & approved rept w/one exception re diesel generator testing Exception outlined in encl.
MCGOUGH, J P. Mississippi Power & Light Co 84/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 21761 231
24X Fiche: 50-416, 84/01/06, 8401100478

8401130240 Forwards mds to FSAR Chapter 14 re startup test program Startup Test 25 on MBIV function testing requires specific change to FSAR Review & approval requested by 840127
DALE, L F. Mississippi Power & Light Co 84/01/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 21799 334
24X Fiche: 50-416, 84/01/11, 8401130240

8401170392 Advises that written documentation not received re NRC determination & associated explanations of state comments on certain issues identified in util applications for license amends covered by Tech Specs (NUREG-0926)
FUENTE, E B. Mississippi, State of 84/01/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 21844 260 24X
Fiche: 50-416, 84/01/12, 8401170392

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O. Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, 8401130084

8401270006 Responds to 831213 inquiry re Tech Specs for low power licensees GE STB used to develop util Tech Specs
DIRCKS, W J. Office of the Executive Director for Operations 84/01/13 OILINSKY, V. Commissioners 8pp 22003 005 24X
Fiche: 50-416, 84/01/13, 8401270006

--8401270010 Forwards Region II comments re util Tech Specs, per Oilinsy 831213 memo.
LEWIS, R C. Region 2, Office of Director 83/12/21 EISENHUT, D O
Division of Licensing 5pp 22003 013 24X
Fiche: 50-416, 84/01/13, 8401270006

--8401270013 Requests info re number of Tech Spec & associated surveillance changes, initial awareness & action, results of preoperational & low power tests & extent of Ofc of Internal Affairs involvement Response requested by 831221.
OILINSKY, V. Commissioners 83/12/13 DIRCKS, W J. Office of the Executive Director for Operations 1p 22003 019 24X
Fiche: 50-416, 84/01/13, 8401270006

8401200001 Application to amend License NPF-13, revising Tech Specs to reflect minor managerial position changes Fee remittance encl
MCGOUGH, J P. Mississippi Power & Light Co. 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 3pp 21867 001
24X Fiche: 50-416, 84/01/18, 8401200001

--8401200003 Proposed Tech Specs 6 S 1 2, 6 2 3 4 & Figure 6 2 2-1 reflecting minor managerial position changes
* Mississippi Power & Light Co 84/01/18. 4pp 21867 006 24X
Fiche: 50-416, 84/01/18, 8401200001

8401200157 Forwards responses to NRC 831229 request for addl info re Transamerica Delaval, Inc diesel generators employed at facilities. Insp program will be implemented on Div II diesel generator
DALE, L F. Mississippi Power & Light Co 84/01/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director 31pp 21866 159
24X Fiche: 50-416, 84/01/18, 8401200157

8401250023 Submits addl info on Agastat relays per 840106 ltr Results of effect of varying testing intervals for ECCB will be submitted by 840217 Relays expected to reach end-of-svc life approx mid-1985.
DALE, L F. Mississippi Power & Light Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21939 285
24X Fiche: 50-416, 84/01/20, 8401250023

8401250295 Submits info re knowledge & use of Taiwan Power Co Kuosheng Nuclear Station operating experience, in response to NRC informal request Startup test procedures & sys operating instructions changed as result of info exchange.
DALE, L F. Mississippi Power & Light Co 84/01/20. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 3pp 21944 219
24X Fiche: 50-416, 84/01/20, 8401250295

8401250290 Forwards first of several submittals intended to demonstrate justification for control room envelop inleakage higher than originally assumed in FSAR. Wind tunnel testing complete Results being evaluated
DALE, L F. Mississippi Power & Light Co 84/01/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 21943 223
24X Fiche: 50-416, 84/01/23, 8401250290

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SARP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SARP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 13pp 21744 004 24X Fiche 50-000, 83/10/20,
B401060040

B401060485 Forwards IE Insp Rept 50-416/83-53 on 831031-1104 No violations noted
VERRELL, D M Division of Project & Resident Programs 83/12/02
RICHARD, J B Mississippi Power & Light Co 2pp 21740 194 24X
Fiche 50-416, 83/12/02, B401060485

--B401060491 IE Insp Rept 50-416/83-53 on 831031-1104 No violations noted Major areas inspected health physics organization, qualifications & experience of health physics personnel, radiation procedures, work permit & ALARA program
KAHLE, J B, WEDDINGTON, R E Region 2, Office of Director
BARR, K P Division of Engineering & Operational Programs
83/11/30 6pp 21740 196 24X Fiche 50-416, 83/12/02, B401060485

B401090286 Forwards IE Insp Rept 50-416/83-52 on 831018-1115 No violations noted
VERRELL, D M Division of Project & Resident Programs 83/12/14
RICHARD, J B Mississippi Power & Light Co 2pp 21754 202 24X
Fiche 50-416, 83/12/14, B401090286

--B401090292 IE Insp Rept 50-416/83-52 on 831018-1115 No violations noted Major areas inspected, operational safety, maint & surveillance observation, EBF sys walkdown, RD, reactor trip, Part 21 repts & followup items
WAGNER, A Q, OARNER, L Region 2, Office of Director JULIAN, C A
Division of Project & Resident Programs 83/12/13 8pp
21754 204 24X Fiche 50-416, 83/12/14, B401090286

B401040103 Forwards notice of violation & proposed imposition of civil penalties in amount of \$12,000 as result of 830904 fire which damaged Div I diesel generator
O'REILLY, J P Region 2, Office of Director 83/12/21 RICHARD, J B
Mississippi Power & Light Co 3pp 21714 227 24X
Fiche 50-416, 83/12/21, B401040103

--B401040112 Notice of violation & proposed imposition of civil penalty in amount of \$12,000 Violation involved failure to conduct proper maint as result of 830904 fire in Div I diesel generator
O'REILLY, J P Region 2, Office of Director 83/12/21 4pp.
21714 230 24X Fiche 50-416, 83/12/21, B401040103

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B401090374 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-46
LEWIS, R C Division of Project & Resident Programs 84/01/03
RICHARD, J B Mississippi Power & Light Co 1p 21756 028 24X
Fiche 50-416, 84/01/03, B401090374

--B401090380 Responds to NRC B31107 ltr re violations noted in IE Insp Rept 50-416/83-46, Corrective actions: Surveillance Procedure 06-HE-1M&1-V-0001 revised & reissued as Rev 20 TCN 7 requiring valve alignment sketch incorporated
DALE, L F Mississippi Power & Light Co 83/12/07 O'REILLY, J P
Region 2, Office of Director 6pp 21756 029 24X
Fiche 50-416, 84/01/03, B401090374

--B401090385 Forwards IE Insp Rept 50-416/83-46 on 830906-09 & 13-16 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/11/07
RICHARD, J B Mississippi Power & Light Co 2pp. 21756. 035. 24X
Fiche: 50-416, 84/01/03, B401090374

--B401090389 Notice of violation from insp on 830906-09 & 13-16
* Region 2, Office of Director 83/11/07 1p 21756. 037 24X
Fiche: 50-416, 84/01/03, B401090374

--B401090394 IE Insp Rept 50-416/83-46 on 830906-09 & 13-16 Violation noted valve alignments not identified in local leak rate test procedure
WHITENER, H L Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/11/03 8pp 21756:038
24X Fiche 50-416, 84/01/03, B401090374

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401240214 Responds to 840107 ltr re training program insp & return to duty of three operators removed from shift assignment. Concurs w/actions based on continuing review of recertification program
O'REILLY, J P Region 2, Office of Director 84/01/13 RICHARD, J B
Mississippi Power & Light Co 1p 21908 264 24X
Fiche 50-416, 84/01/13, B401240214

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, B312120114

B401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R Licensing Branch 2 84/01/17 SCHWENGER, A Licensing Branch 2 21pp 22027.009 24X Fiche 50-000, 84/01/17, B401300028

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401270264 Monthly operating rept for Dec 1983 W/B40113 ltr.
GESARE, J Q, DALE, L F Mississippi Power & Light Co 83/12/31
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp. 21973 326 24X Fiche 50-416, 83/12/31, B401270264

S Reportable occurrences, LERs & related correspondence

B401030215 LER 83-185/03L-0 on 831201, while in cold shutdown, breaker 552-2105 from svc transformer #1 tripped, causing loss of power to Div I ESF bus & all balance-of-plant loads. Caused by shorted wires in breaker handswitch W/B31220 ltr
BYRD, R, DALE, L F Mississippi Power & Light Co 83/12/20
O'REILLY, J P Region 2, Office of Director 3pp. 21682:314 24X
Fiche 50-416, 83/12/20, B401030215

B401030220 Updated LER 83-130/03X-1, on 830829, shutdown cooling sys isolated twice when suction valve received isolation signals. First isolation caused by personnel error Second caused by use of alligator clips. W/B31220 ltr
BAILEY, J D, DALE, L F Mississippi Power & Light Co 83/12/20,
O'REILLY, J P Region 2, Office of Director 3pp. 21682.349. 24X
Fiche. 50-416, 83/12/20, B401030220

B401030083 LER 83-184/03L-0 on 831122, standby svc water pump A declared inoperable due to low cooling water flow through pump. Caused by sediment in supply/return line restricting cooling flow through pump A W/B31222 ltr
BAILEY, J D, DALE, L F Mississippi Power & Light Co. 83/12/22
O'REILLY, J P Region 2, Office of Director 3pp. 21683:193 24X
Fiche 50-416, 83/12/22, B401030083

B401030194 LER 83-187/03L-0 on 831122, technician filling reactor vessel level transmitter ref leg caused spike, resulting in Div I automatic actuations & injection by low pressure core spray pump & isolation of shutdown cooling. W/B31222 ltr
BYRD, R W, DALE, L F Mississippi Power & Light Co 83/12/22
O'REILLY, J P Region 2, Office of Director. 4pp. 21683.079. 24X
Fiche 50-416, 83/12/22, B401030194

DOCKETED ITEMS

8401030233 Updated LER 83-166/03X-1 on 831021, standby svc water cooling fan C003D tripped breaker 52-16804 Caused by defective trip device installed on breaker Breaker units inspected & modified trip units installed W/831222 ltr.
BYRD, R. W., DALE, L. F. Mississippi Power & Light Co. 83/12/22
O'REILLY, J. P. Region 2, Office of Director. App. 21682 332 24X
Fiche: 50-416, 83/12/22, 8401030233

8401060325 LER 83-183/03L-0 on 831123, control room standby fresh air unit B found w/flow rate in excess of Tech Spec limit. Caused by inadequate retest following maint work Damper limit switches readjusted W/831229 ltr.
BAILEY, J. D., DALE, L. F. Mississippi Power & Light Co. 83/12/29
O'REILLY, J. P. Region 2, Office of Director. App. 21742 333 24X
Fiche: 50-416, 83/12/29, 8401060325

8401060312 LER 83-188/03L-0 on 831201, loss of reactor protection sys bus B & shutdown cooling occurred when alternative power supply breaker tripped. Cause not determined. Investigation continuing. Updated retest expected by 840130 W/831230 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 83/12/30
O'REILLY, J. P. Region 2, Office of Director. App. 21742 327 24X
Fiche: 50-416, 83/12/30, 8401060312

8401060421 Updated LER 83-126/01X-2 on 830904, Div I diesel generator fuel line ruptured due to fatigue crack propagation Caused by rough mating surfaces of valve latch & clapper Fuel line supports added W/831230 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 83/12/30
O'REILLY, J. P. Region 2, Office of Director. App. 21741:013 24X
Fiche: 50-416, 83/12/30, 8401060421

8401060477 Updated RD 83-094/1 on 830926, Fire Door C0313 reported inoperable. Caused by heavy use. Parts to repair door ordered. Completion expected by 840228. Fire watch established.
DALE, L. F. Mississippi Power & Light Co. 83/12/30, O'REILLY, J. P. Region 2, Office of Director. App. 21740:263 24X
Fiche: 50-416, 83/12/30, 8401060477

8401120350 Interim Part 21 retest re failure of fuel oil mfg by Transamerica Delaval adjacent to main branch tee on Div I diesel generator. Initially reported on 831230 Fuel oil line support installed. Next retest by 840413
MCGAUGHY, J. P. Mississippi Power & Light Co. 84/01/03
O'REILLY, J. P. Region 2, Office of Director. App. 21792:027 24X
Fiche: 50-416, 84/01/03, 8401120350

8401100411 Forwards response to NRC 831013 request for addl info re Agastat relays. Agastat relay replacement program will be performed during current outage. Failure rate of relays within design considerations. Proprietary figures deleted.
DALE, L. F. Mississippi Power & Light Co. 84/01/06, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 18pp 21763:046 24X
Fiche: 50-416, 84/01/06, 8401100411

8401170186 Part 21 retest re loose flexible coupling drive hubs mfg by Lovejoy Coupling & installed by Transamerica Delaval on shafts in overgovernor fuel transfer pump drive Insp of hubs in listed facilities recommended. Utility notified.
BOYER, R. E. Transamerica Delaval, Inc. 84/01/09 Director's Office, Office of Inspection and Enforcement App. 21828:269 24X
Fiche: 50-000, 84/01/09, 8401170186

8401170376 Interim Deficiency Rept PRD-84/01 re incorrect installation of 30-volt dc 22 microfarad capacitor in solid state trip unit. Initially reported on 840105. Final retest by 840330 Also reported per Part 21.
MCGAUGHY, J. P. Mississippi Power & Light Co. 84/01/09
O'REILLY, J. P. Region 2, Office of Director. App. 21827:131 24X
Fiche: 50-416, 84/01/09, 8401170376

8401240385 RD 83-113/0 on 831202, fire-rated Door 1A201 to turbine bldg reported inoperable. Caused by damaged latching mechanism due to heavy use. Door restored on 831213.
DALE, L. F. Mississippi Power & Light Co. 84/01/09, O'REILLY, J. P. Region 2, Office of Director. App. 21920:360 24X
Fiche: 50-416, 84/01/09, 8401240385

8401240491 LER 83-189/03L-0 on 831207, breaker 152-1704 to Div 3 EBF bus tripped. Caused by broken current limiter resistor socket for breaker position indicating light. Testing frequency will be increased to 3 days. W/840110 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/10
O'REILLY, J. P. Region 2, Office of Director. App. 21907:339 24X
Fiche: 50-416, 84/01/10, 8401240491

8401240160 LER 83-191/03L-0 on 831217, standby fresh air unit A placed in isolated mode to meet Tech Spec action requirements due to planned Div 2 electrical outage on 831210. Caused by operator error. Procedures revised. W/840111 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/11
O'REILLY, J. P. Region 2, Office of Director. App. 21908:357 24X
Fiche: 50-416, 84/01/11, 8401240160

8401240450 Updated LER 83-116/03X-1 on 830809, during work on Div 12 load shedding panel, removal of temp jumpers caused partial LOCA/LOBP signal to occur. Caused by loosening of terminal screws resulting in loss of continuity W/840112 ltr.
DAUGHTERY, L. F., DALE, L. F. Mississippi Power & Light Co. 84/01/12
O'REILLY, J. P. Region 2, Office of Director. App. 21913:193 24X
Fiche: 50-416, 84/01/12, 8401240450

8401240455 Updated LER 83-121/03X-2 on 830817, M4-R4 contacts in Agastat relay 95X for motor operated valve IE22-F010 found failed in open state. Caused by contact between nylon movable contact arm & barrier strip on relay base W/840112 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/12
O'REILLY, J. P. Region 2, Office of Director. App. 21913:197 24X
Fiche: 50-416, 84/01/12, 8401240455

8401260018 LER 83-190/03L-0 on 831214, Div 2 isolation occurred, causing loss of shutdown cooling when pump suction valve F009 isolated. Cause under investigation. Shutdown cooling restored in 15 minutes. Update expected by 840229 W/840113 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/13
O'REILLY, J. P. Region 2, Office of Director. App. 21956:312 24X
Fiche: 50-416, 84/01/13, 8401260018

8401300179 Updated LER 83-136/03X-3 on 830830, diesel generator shut down when cylinder exhaust gaskets RB1 & LB5 failed & crack & 2 broken welds discovered on intercoolers Gasket failures caused by loose manifold bolts W/840113 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/13
O'REILLY, J. P. Region 2, Office of Director. App. 21999:138 24X
Fiche: 50-416, 84/01/13, 8401300179

8401260088 RD 83-114/0 on 831215, control room temp exceeded Tech Spec limit of 77 degrees F for period of more than 8 h. Max recorded temp was 80 degrees F. Availability or operability of equipment within area not affected.
DALE, L. F. Mississippi Power & Light Co. 84/01/16, O'REILLY, J. P. Region 2, Office of Director. App. 21957:108 24X
Fiche: 50-416, 84/01/16, 8401260088

8401260338 RD 83-113/0 on 831212, Fire Rated Door 1A301 from auxiliary bldg to turbine bldg would not close. Caused by heavy use damaging door closer. Door restored on 840111.
DALE, L. F. Mississippi Power & Light Co. 84/01/18, O'REILLY, J. P. Region 2, Office of Director. App. 21955:122 24X
Fiche: 50-416, 84/01/18, 8401260338

8401260031 Updated RD 83-095/1 on 830926, fire-rated penetrations AE330 & AE390 Found open. Caused by penetrations not being listed on penetration schedule. Wall not required & penetrations not required to be sealed. Drawings revised.
DALE, L. F. Mississippi Power & Light Co. 84/01/19, O'REILLY, J. P. Region 2, Office of Director. App. 21956:301 24X
Fiche: 50-416, 84/01/19, 8401260031

8401300175 Updated LER 83-111/03X-1 on 830730, amphenol type signal cable connector in control room panel disconnected. Caused by personnel error. Changes to administrative controls governing maint activities implemented W/840120 ltr.
DAUGHTERY, L. F., DALE, L. F. Mississippi Power & Light Co. 84/01/20
O'REILLY, J. P. Region 2, Office of Director. App. 21999:134 24X
Fiche: 50-416, 84/01/20, 8401300175

8401300234 Updated LER 83-146/03X-1 on 830918, while in cold shutdown, shutdown cooling loop pump B found tripped due to isolated suction valve. Caused by Channel C & Channel B isolation logic test switches placed in test position W/840120 ltr.
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/20, O'REILLY, J. P. Region 2, Office of Director. App. 22062:062 24X
Fiche: 50-416, 84/01/20, 8401300234

8401300239 Updated LER 83-117/03X-1 on 830812, during performance of test on Div I load shedding panel, output relays pulled, causing drywell purge compressor A to auto-start. Caused by lack of caution for auto-start in work authorization W/840120 ltr.
DAUGHTERY, L. F., DALE, L. F. Mississippi Power & Light Co. 84/01/20
O'REILLY, J. P. Region 2, Office of Director. App. 22062:088 24X
Fiche: 50-416, 84/01/20, 8401300239

8401300263 Updated LER 83-112/03X-1 on 830730, while troubleshooting N888/ECCS initiation circuitry re improper operation of E12F087B & F025B, partial LOCA occurred. Caused by error in work order changes underway W/840120 ltr.
DAUGHTERY, L. F., DALE, L. F. Mississippi Power & Light Co. 84/01/20
O'REILLY, J. P. Region 2, Office of Director. App. 21998:340 24X
Fiche: 50-416, 84/01/20, 8401300263

8401300284 Updated LER 83-090/01X-1 on 830722, inlet valve to reactor water cleanup sys nonregenerative HX discovered closed. Caused by valve isolation when relay removed during limiting safety sys setting troubleshooting. W/840120 ltr.
BYRD, R., DAUGHTERY, L. F., DALE, L. F. Mississippi Power & Light Co. 84/01/20
O'REILLY, J. P. Region 2, Office of Director. App. 21997:308 24X
Fiche: 50-416, 84/01/20, 8401300284

DOCKETED ITEMS

31

B401300220 LER 83-192/03L-0 on 831223, first shift failed to adequately perform 12 h channel check of Tech Spec 4.3.7.1-1.7. Caused by personnel error. Daily operating log being revised.
W/840123 ltr
BYRD, R., DALE, L. F. Mississippi Power & Light Co. 84/01/23
O'REILLY, J. P. Region 2, Office of Director. 2pp. 22062. 116. 24X
Fiche 50-416, 84/01/23, 8401300220

V Operator Examinations

B401240214 Responds to 840109 ltr re training program insp & return to duty of three operators removed from shift assignment. Concurs w/actions based on continuing review of recertification program.
O'REILLY, J. P. Region 2, Office of Director. 84/01/13. RICHARD, J. B. Mississippi Power & Light Co. 1p. 21908. 264. 24X
Fiche 50-416, 84/01/13, 8401240214

B401180079 Responds to Generic Ltr 83-40 re operation licensing exams. Anticipated operator licensing exam schedule for Unit 1 encl.
DALE, L. F. Mississippi Power & Light Co. 84/01/16. BECKHAM, D. H. Operator Licensing Branch. 3pp. 21841. 358. 24X
Fiche 50-416, 84/01/16, 8401180079

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B401030316 Forwards questionnaire on staffing for Unit 1. Response requested by 831230. Similar questionnaire telecopied to Unit 2 earlier for Unit 2.
SCHWENCER, A. Licensing Branch 2. 83/12/12. MCGAUGHY, J. P. Mississippi Power & Light Co. 4pp. 21693. 300. 24X
Fiche 50-416, 83/12/12, 8401030316

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants.
MATHEWS, C. B. Transamerica Delaval, Inc. 83/12/16. NOVAK, T. M. Assistant Director for Licensing. 17pp. 22034. 338. 24X
Fiche 50-000, 83/12/16, 8312200154

B401060456 Forwards Affidavit of Bvc on distribution of application for licenses, consisting of Amend 37 to FSAR.
DALE, L. F. Mississippi Power & Light Co. 83/12/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 21739. 361. 24X
Fiche 50-416, 83/12/28, 8401060456

B401090544 Requests that encl TM Novak 831227 request for addl info re Transamerica Delaval emergency diesel generators be answered specifically.
SCHWENCER, A. Licensing Branch 2. 83/12/29. MCGAUGHY, J. P. Mississippi Power & Light Co. 2pp. 21757. 244. 24X
Fiche 50-416, 83/12/29, 8401090544

B401060639 Forwards list of NRC questions re Delaval diesel generators. Questions address generic concerns which could be effectively answered by Owners Group.
NOVAK, T. M. Assistant Director for Licensing. 83/12/27. MCGAUGHY, J. P. Mississippi Power & Light Co. 5pp. 21795. 327. 24X
Fiche 50-416, 83/12/29, 8401090544

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Bvc list encl.
EISENHUT, D. O. Division of Licensing. 84/01/05. Consolidated. Edison Co. of New York, Inc. 16pp. 21946. 190. 24X
Fiche 50-000, 84/01/05, 8401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Bvc list encl.
EISENHUT, D. O. Division of Licensing. 84/01/06. Consolidated. Edison Co. of New York, Inc. 18pp. 21957. 267. 24X
Fiche 50-000, 84/01/06, 8401090221

B401100371 Forwards proprietary affidavit & figures referenced in Unit 2 B40106 response to NRC questions re Agastat relays. Encls withheld (ref 10CFR2.790).
DALE, L. F. Mississippi Power & Light Co. 84/01/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 21764. 088. 24X
Fiche 50-416, 84/01/06, 8401100371

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues," Bvc list encl.
EISENHUT, D. O. Division of Licensing. 84/01/13. Consolidated. Edison Co. of New York, Inc. 18pp. 21946. 174. 24X
Fiche 50-000, 84/01/13, 8401130084

B401200157 Forwards responses to NRC 831229 request for addl info re Transamerica Delaval, Inc. diesel generators employed at facilities. Insp program will be implemented on Div II diesel generator.
DALE, L. F. Mississippi Power & Light Co. 84/01/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 31pp. 21866. 159. 24X
Fiche 50-416, 84/01/18, 8401200157

B401250295 Submits info re knowledge & use of Taiwan Power Co Kuosheng Nuclear Station operating experience, in response to NRC informal request. Startup test procedures & sys operating instructions changed as result of info exchange.
DALE, L. F. Mississippi Power & Light Co. 84/01/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 21744. 215. 24X
Fiche 50-416, 84/01/20, 8401250295

B401250290 Forwards first of several submittals intended to demonstrate justification for control room enveloper inleakage higher than originally assumed in FSAR. Wind tunnel testing complete. Results being evaluated.
DALE, L. F. Mississippi Power & Light Co. 84/01/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 21943. 223. 24X
Fiche 50-416, 84/01/23, 8401250290

F Security, medical, emergency & fire protection plans

B401060159 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/12/28. Document Management Branch. 1p. 21745. 059. 24X
Fiche 50-416, 83/12/28, 8401060159

B401060165 Forwards public version of revised emergency plan implementing procedures, including Procedures 10-8-01-19 re personnel injury, 10-8-01-25 re onsite personnel response & 10-8-01-26 re offsite emergency response.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/11/29. O'REILLY, J. P. Region 2, Office of Director. 1p. 21745. 060. 24X
Fiche 50-416, 83/12/28, 8401060159

B401060171 Public version of revised emergency plan implementing procedures, including Procedures 10-8-01-19 re personnel injury, 10-8-01-25 re onsite personnel response & 10-8-01-26 re offsite emergency response.
HURLEY, J., CROSS, J. B. Mississippi Power & Light Co. 83/11/07. 62pp. 21745. 061. 24X
Fiche 50-416, 83/12/28, 8401060159

B401260269 Releases public version of revised emergency plan.
FELTON, J. M. Division of Rules and Records. 84/01/18. Document Management Branch. 1p. 21791. 190. 24X
Fiche 50-416, 84/01/18, 8401260269

B401260286 Public version of Rev 8 to emergency plan W/831219 ltr.
BENEDICT, P., DALE, L. F., HUTCHINSON, C. R. Mississippi Power & Light Co. 83/11/21. 77pp. 21791. 191. 24X
Fiche 50-416, 84/01/18, 8401260269

G Adjudicatory correspondence

B401180212 Response to NRC & licensee answers to Jacksonians United for Livable Energy Policies 831117 petition to intervene & request for hearing & 831211 amended petition. Certificate of Bvc encl.
BTEWART, C. A. Jacksonians United for Livable Energy Policies. 84/01/12. Atomic Safety and Licensing Board Panel. 20pp. 21844. 178. 24X
Fiche 50-416, 84/01/12, 8401180212

H General correspondence

B401100248 Requests correspondence presently addressed to JF Fager be changed to RT Lally.
MACHADO, C. K. Middle South Services, Inc. 84/01/05. NOVAK, T. M. Division of Licensing. 1p. 21759. 189. 24X
Fiche 50-416, 84/01/05, 8401100248

K Utility Final Safety Analysis Report (FSAR) & amendments

B401060456 Forwards Affidavit of Bvc on distribution of application for licenses, consisting of Amend 37 to FSAR.
DALE, L. F. Mississippi Power & Light Co. 83/12/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 21739. 361. 24X
Fiche 50-416, 83/12/28, 8401060456

DOCKETED ITEMS

G. Inspection Reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR
 FELTON, J.H. Division of Rules and Records. 83/10/20. ZAHLER, R.E. Shaw, Pittman, Potts & Trowbridge. 1p. 21744 003. 24X
 Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
 * Director's Office, Office of Inspection and Enforcement
 83/10/20. 134pp. 21744, 004. 24X. Fiche: 50-000, 83/10/20.
 B401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co. of New York, Inc. 124pp. 21731 166. 24X. Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/12/30. Consolidated Edison Co. of New York, Inc. 127pp. 21826 060. 24X. Fiche: 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Authorized." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/10. Consolidated Edison Co. of New York, Inc. 125pp. 21946 053. 24X. Fiche: 50-000, 84/01/10, B312120104.

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/10. Consolidated Edison Co. of New York, Inc. 122pp. 21826 164. 24X. Fiche: 50-000, 84/01/10, B312120107.

B401240214 Responds to B40109 ltr re training program insp & return to duty of three operators removed from shift assignment. Concurs w/actions based on continuing review of recertification program.
 O'REILLY, J.P. Region 2, Office of Director. 84/01/13. RICHARD, J.B. Mississippi Power & Light Co. 1p. 21908 264. 24X
 Fiche: 50-416, 84/01/13, B401240214

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/16. Consolidated Edison Co. of New York, Inc. 127pp. 21957 142. 24X. Fiche 50-000, 84/01/16, B312120114

B401300028 Notification of B40126 meeting w/utills & Transamerica Delaval, Inc. (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators.
 CARUSO, R. Licensing Branch 2. 84/01/17. SCHWENCER, A. Licensing Branch 2. 2pp. 22027, 009. 24X. Fiche 50-000, 84/01/17, B401300028

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/18. Consolidated Edison Co. of New York, Inc. 118pp. 22000, 001. 24X. Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/18. Consolidated Edison Co. of New York, Inc. 120pp. 22000, 041. 24X. Fiche 50-000, 84/01/18, B312120117.

H. Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended Utills notified.
 BOYER, R.E. Transamerica Delaval, Inc. 84/01/09. Director's Office, Office of Inspection and Enforcement. 3pp. 21828 269. 24X
 Fiche: 50-000, 84/01/09, B401170186

V. Operator Examinations

B401240214 Responds to B40109 ltr re training program insp & return to duty of three operators removed from shift assignment. Concurs w/actions based on continuing review of recertification program.
 O'REILLY, J.P. Region 2, Office of Director. 84/01/13. RICHARD, J.B. Mississippi Power & Light Co. 1p. 21908 264. 24X
 Fiche: 50-416, 84/01/13, B401240214

B401180079 Responds to Generic Ltr 83-40 re operation licensing areas. Anticipated operator licensing exam schedule for Unit 1 encl
 DALE, L.F. Mississippi Power & Light Co. 84/01/16. BECKHAM, D.H. Operator Licensing Branch. 3pp. 21841 358. 24X
 Fiche 50-416, 84/01/16, B401180079

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3A. Application/construction stage documents & correspondence

B401050273 Forwards addl geologic zone matrices prepared by R McGuire of Dames & Moore, per B31129 meeting request
 COUNSIL, W.G. Northeast Utilities Service Co. (subs. of Northeast Utilities). COUNSIL, W.G. Northeast Utilities. 83/12/14. YOUNGBLOOD, B.J. Licensing Branch 1. 7pp. 21727 225. 24X
 Fiche 50-423, 83/12/14, B401050273

B401050314 Forwards B&W viewgraphs used at B31129 presentation to Geosciences Branch entitled "Millstone Soil Amplification Shake Analyses, Unit 3"
 COUNSIL, W.G. Northeast Utilities Service Co. (subs. of Northeast Utilities). COUNSIL, W.G. Northeast Utilities. 83/12/14. YOUNGBLOOD, B.J. Licensing Branch 1. 57pp. 21729 280. 24X
 Fiche: 50-423, 83/12/14, B401050314

B401060468 Forwards addl info requested by NRC Siting Analysis Branch documenting State of CT Historic Preservation Officer comments on right-of-way development & mgt plan for facility 345-kV transmission line.
 COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.G. Northeast Utilities. 83/12/14. YOUNGBLOOD, B.J. Licensing Branch 1. 49pp. 21740 209. 24X
 Fiche 50-423, 83/12/14, B401060468

B401060045 Forwards response to Question 420.06 of B31003 ltr re accident monitoring instrumentation Response will appear in Amend 7 scheduled to be submitted by end of Feb 1984
 COUNSIL, W.G. SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.G. Northeast Utilities. 83/12/14. YOUNGBLOOD, B.J. Licensing Branch 1. 29pp. 21739 274. 24X
 Fiche 50-423, 83/12/14, B401060045

B401040613 Approves B31121 application to withhold "Seismology & Geology Studies Miramichi Area, New Brunswick & Central NH Vol I & II, Aug 1983" pursuant to 10CFR2.790
 YOUNGBLOOD, B.J. Licensing Branch 1. 83/12/23. COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 21714, 205. 24X. Fiche: 50-423, 83/12/23, B401040613

B401160176 Discusses revised GA program description of principle contractor Clarification of Section XVIII, Rev O of Aug 1973 program description & Section 19, Rev C of current GA program description requested
 MARTIN, T.T. Division of Engineering & Technical Programs. 83/12/23. COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 21815, 001. 24X. Fiche: 50-423, 83/12/23, B401160176

B401030098 Notification of B40105 meeting w/utill in Bethesda, MD to discuss New Brunswick Earthquake relation to site in support of util response to Safety Review Question 230.6
 DOOLITTLE, E.L. Licensing Branch 1. 83/12/28. YOUNGBLOOD, B.J. Licensing Branch 1. 3pp. 21695, 231. 24X. Fiche 50-423, 83/12/28, B401030098

B401100429 Advises that Weston Geophysical Corp rept, "Seismology & Geological Studies Miramichi Area, New Brunswick & Central NH" no longer treated as proprietary info due to limited commercial marketability
 COUNSIL, W.G. Northeast Utilities. 83/12/28. YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 21762, 168. 24X. Fiche: 50-423, 83/12/28, B401100429

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms: "important to safety" & "safety-related." Svc list encl
 EISENHUT, D.Q. Division of Licensing. 84/01/05. Consolidated Edison Co. of New York, Inc. 16pp. 21946, 190. 24X
 Fiche 50-000, 84/01/05, B401050382.

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl.
 EISENHUT, D.Q. Division of Licensing. 84/01/06. Consolidated Edison Co. of New York, Inc. 18pp. 21937 267. 24X
 Fiche: 50-000, 84/01/06, B401090221.

DOCKETED ITEMS

315

B40120364 Forwards proprietary response to questions raised at B31213 meeting re probabilistic safety study info withheld (ref 10CFR2 790)

COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 84/01/10
YOUNGBLOOD, B J Licensing Branch 1 2pp 21798 315 24X
Fiche 50-423, 84/01/10, B40120364

B401230323 Describes how approval & operation of facility will be consistent w/State of CT Coastal Mgt Program Consistency between CT Coastal Zone Plan & CT Plan of Conservation & Development also described

COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 84/01/10
YOUNGBLOOD, B J Licensing Branch 1 App 21883 207 24X
Fiche 50-423, 84/01/10, B401230323

B401200345 Notification of cancellation of Significant Licensee Meeting 84-05 on B40117 w/util in King of Prussia, PA to review

cable pulling techniques & acceptance criteria
WOODARD, C Region 1, Office of Director 84/01/12 DIRCKS, W J
Office of the Executive Director for Operations. STELL, V Regional
Operations & Generic Requirements DEYOUNG, R C Director's Office,
Office of Inspection and Enforcement 2pp 21872:088 24X
Fiche 50-423, 84/01/12, B401200345

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of

NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401300048 Forwards request for addl info to complete evaluation of application for DL as result of Containment Sys Branch FSAR

review Response to questions expected by B40515
YOUNGBLOOD, B J Licensing Branch 1 84/01/16 COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 25pp
22027 031. 24X Fiche 50-423, 84/01/16, B401300048

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating

crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of
Licensing 1p 22000, 349 24X Fiche 50-000, 84/01/17, B401270536

D NRC Draft/Final Environmental Statements, supp's & correspondence

B401190210 Forwards request for addl info resulting from NRC review of probabilistic safety study. Response should be submitted

within 30 days to support DEB issuance schedule
YOUNGBLOOD, B J Licensing Branch 1 84/01/06 COUNCIL, W O
Northeast Nuclear Energy Co (subs of Northeast Utilities) 30pp
21869 334 24X Fiche 50-423, 84/01/06, B401190210

F Security, medical, emergency & fire protection plans

B401090132 Forwards status of current plans for implementation of provisions of Suppl 1 to NUREG-0737, "Requirements for

Emergency Response Capability," transmitted by Generic Ltr 82-33
COUNCIL, W O Connecticut Yankee Atomic Power Co 83/11/28
EISENHUT, D G Division of Licensing 23pp 21749 170 24X
Fiche 50-000, 83/11/28, B401090132

B401230467 Submits revised integrated implementation schedule re Suppl 1 to NUREG-0737 requirements for emergency response

capability per Generic Ltr 82-33 Control room design review final rept scheduled for B41101
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O, BEARS, C F Northeast Utilities
84/01/11 YOUNGBLOOD, B J Licensing Branch 1. App 21877 021
24X Fiche 50-423, 84/01/11, B401230467

J Insurance & indemnity information

B401130130 Forwards Endorsement 5 to NELIA Certificates N-15 & N-16 & Endorsement 5 to MAELU Certificates M-15 & M-16.

BINIBI, J M Marsh & McLennan, Inc 83/12/27 SALTZHAN, J D
Assistant Director for State & Licensee Relations 5pp 21802, 237
24X Fiche 50-000, 83/12/27, B401130130

B401230477 Forwards Endorsements 90 & 91 to NELIA Policy NF-173 & Endorsements B1 & B2 to MAELU Policy NF-52

BINIBI, J M Marsh & McLennan, Inc 84/01/12 SALTZHAN, J D
Assistant Director for State & Licensee Relations 5pp 21882 153
24X Fiche 50-000, 84/01/12, B401230477

K Utility Final Safety Analysis Report (FSAR) & amends

B31280178 Forwards Amend 5 to FSAR & responses to selected requests for info, including revised responses to B30131, 0503 & 31

requests & responses to Series 640 questions submitted in B30829 ltr Amend incorporates revs/responses
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/11/29
YOUNGBLOOD, B J Licensing Branch 1 2pp 21409 001 24X
Fiche 50-423, 83/11/29, B31280178

--B312060402 Forwards Amend 5 to FSAR Completion of encl forms requested to verify receipt

SHAFFER, C J Northeast Utilities 83/11/29 DOOLITTLE, E A NRC
- No Detailed Affiliation Given 3pp 21409 004 24X
Fiche 50-423, 83/11/29, B31280178

--B312060403 Amend 5 to FSAR

* Northeast Utilities 83/11/30 387pp 21409 007 24X
Fiche 50-423, 83/11/29, B31280178

B401230175 Forwards Amend 6 to FSAR & revised responses to selected requests for addl info

COUNCIL, W O, BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 84/01/16
YOUNGBLOOD, B J Licensing Branch 1. 3pp. 21875 319 24X
Fiche 50-423, 84/01/16, B401230175

--B401230184 Amend 6 to FSAR

* Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/01/31 40pp 21875 322 24X Fiche 50-423, 84/01/16, B401230175

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info

Notebook also available in PDR
FELTON, J M Division of Rules and Records, 83/10/20. ZAHLER, R E.
Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982.

* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040.

B401100441 Forwards IE Insp Rept 50-423/83-16 on B30801-0917, No violations noted

STAROSTECKI, R Division of Project & Resident Programs, 83/12/21.
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21762 087 24X Fiche 50-423, 83/12/21, B401100441.

--B401100446 IE Insp Rept 50-423/83-16 on B30801-0917, No violations noted

Major areas inspected previous insp findings, preservice insp program, craft drawings review, radiographic film interpretation & probabilistic safety study meeting
REBELGHSKI, T. Region 1, Office of Director, ELASBER, T Division of Project & Resident Programs 83/12/21 App. 21762, 091. 24X
Fiche 50-423, 83/12/21, B401100441.

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related

Applications Other Than Reactor Trip Sys." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B401090279 Notification of Significant Licensee Meeting 84-05 on B40117 w/util in King of Prussia, PA to review cable pulling

techniques & acceptance criteria.
WOODARD, C Region 1, Office of Director 83/12/28 Region 1,
Office of Director 2pp. 21768:162 24X Fiche 50-423, 83/12/28, B401090279

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl.

JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30. Consolidated Edison Co. of New York, Inc 127pp. 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.

JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl.

JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp. 21826 184. 24X Fiche 50-000, 84/01/10, B312120107.

DOCKETED ITEMS

8401240467 Forwards IE Insp Rept 50-423/83-17 on 830918-1029 No violations noted
STARDSTECK, R Division of Project & Resident Programs 84/01/10
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21918 187 24X Fiche 50-423, 84/01/10, 8401240467

--8401240475 IE Insp Rept 50-423/83-17 on 830918-1029, No violations noted Major areas inspected licensee actions on previous insp findings, seismic analysis of piping sys w/overweight fittings, electric cable pulls & Category I cable splices
REBELOWSKI, T A Region 1, Office of Director ELSASSER, T Division of Project & Resident Programs 84/01/09 7pp 21918 189 24X Fiche 50-423, 84/01/10, 8401240467

8401240468 Forwards IE Insp Rept 50-423/83-18 on 830926-29 & notice of deviation
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
COUNCIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 21918 179 24X Fiche 50-423, 84/01/10, 8401240468

--8401240470 Notice of deviation from insp on 830926-29
* Region 1, Office of Director 84/01/10 1p 21918 177 24X Fiche 50-423, 84/01/10, 8401240468

--8401240472 IE Insp Rept 50-423/83-18 on 830926-29, Deviation noted. Failure to comply w/requirements of Reg Guide 1.75 for cable installation
FINKEL, A E, ANDERSON, C J Region 1, Office of Director 83/11/16 7pp 21918 178 24X Fiche 50-423, 84/01/10, 8401240468

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

S Reportable occurrences, LERs & related correspondence

8401160174 Final Significant Deficiency Rept SD-34 re interference & possible binding of ITT Grinnell mechanical snubbers Initially reported on 830408 B&W identified 233 snubber installations w/potential hardware interference
COUNCIL, W O, SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNCIL, W O Northeast Utilities 83/12/30
MURLEY, T E Region 1, Office of Director 2pp 21815 339 24X Fiche 50-423, 83/12/30, 8401160174

8401270208 Final significant Deficiency Rept SD-49 re possible cutting of magnetic latch leads in 480-volt switchgear Initially reported on 831214. Caused by slack left in leads when braiser wiring harnessed. Brown Boveri repairs made
COUNCIL, W O Northeast Utilities 84/01/13
MURLEY, T E Region 1, Office of Director 2pp 21822 116 24X Fiche 50-423, 84/01/13, 8401270208

I Operator Examinations

401030265 Forwards completed staffing level survey expected to be in place when OL issued. Anticipated yrs of experience for reactor operators at time of issuance noted.
COUNCIL, W O, SEARS, C F Northeast Utilities 83/12/16
YOUNGBLOOD, B J Licensing Branch 1 3pp 21728 304 24X Fiche 50-423, 83/12/16, 8401030265

DOCKET 50-424 VOOTLE ELECTRIC GENERATING PLANT

A Application/construction stage documents & correspondence

8401101089 Requests addl info re Transamerica Delaval emergency diesel generators. Owners group or plant-specific rept may be submitted to respond to specific questions
ADENBAM, E O Licensing Branch 4 83/12/19, FOSTER, D Georgia Power Co 1p 21793 127 24X Fiche 50-424, 83/12/19, 8401101089

8401060490 Forwards request for addl info re GA program Review of Suppl 10 to GA program dtd 831216 will be completed within 30 days
LEWIS, R C Division of Project & Resident Programs 83/12/30
KELLY, R J Georgia Power Co 3pp 21740 180 24X Fiche 50-424, 83/12/30, 8401060490

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21746 190 24X Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & Full power authorizations re notice of meeting on Facility staffing Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401170358 Provides info re facility control burn activities to eliminate potential fire conditions scheduled for Jan-Feb 1984. Activities will be supervised by util & State of GA Forestry Commission. Map of areas to be burned encl
FOSTER, D O Georgia Power Co 84/01/09 ADENBAM, E O Licensing Branch 4 3pp 21828 351 24X Fiche 50-424, 84/01/09, 8401170358

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

B. Utility Preliminary Safety Analysis Report, amends

8401230488 Forwards Suppl 10 to PSAR, Chapter 17, Responsibility for procurement transferred from Bechtel Power Corp to Southern Co Svcs Changes do not adversely affect GA program
FOSTER, D O Georgia Power Co 83/12/16 O'REILLY, J P Region 2, Office of Director 3pp 21877 025 24X Fiche 50-424, 83/12/16, 8401230488

--8401230495 Suppl 10 to PSAR, Chapter 17, * Georgia Power Co, 83/12/16 39pp 21877 028 24X Fiche 50-424, 83/12/16, 8401230488

C Utility Environmental Report (ER), amends & correspondence

8401170149 Advises that Dept of Commerce & Advisory Council on Historical Preservation removed from environ rept - OL stage distribution, certified in 831128 ltr to DQ Eisenhut
FOSTER, D O Georgia Power Co 84/01/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21827 126 24X Fiche 50-424, 84/01/10, 8401170149

F. Security, medical, emergency & fire protection plans

8401100023 Notification of 840118 meeting w/util in Waynesboro, GA to discuss applicant security & contingency plan in light of findings from NRC initial review
MILLER, M A Licensing Branch 4 83/12/29 ADENBAM, E O Licensing Branch 4 2pp 21776 036 24X Fiche 50-424, 83/12/29, 8401100023

G Adjudicatory correspondence

8401300096 Joint petition of Georgians Against Nuclear Energy for leave to intervene & request for hearing
TEPER, D C, STANGLER, C A Georgians Against Nuclear Energy 84/01/26 Atomic Safety and Licensing Board Panel 11pp 21999 171 24X Fiche 50-424, 84/01/26, 8401300096

--8401300100 Request that hearings be held in Atlanta, GA. Certificate of Svc encl
TEPER, D C, STANGLER, C A Georgians Against Nuclear Energy 84/01/26 Atomic Safety and Licensing Board Panel 2pp 21999 182 24X Fiche 50-424, 84/01/26, 8401300096

DOCKETED ITEMS

317

8401300321 Petition of Campaign for Prosperous Georgia for leave to intervene & request for hearing in Atlanta, GA re applications for OLS Affidavits, notice of appearance & Certificate of Svc encl
FOHLER, L. Affiliation Unknown 84/01/26 Atomic Safety and Licensing Board Panel 10pp 21993 347 24X Fiche 50-424, 84/01/26, 8401300321

8401310244 Petition of Consumers Util Counsel of GA for leave to intervene & request for hearing Certificate of Svc encl
DICHTER, J. R. Georgia, State of 84/01/26 Commissioners 6pp 22020 334 24X Fiche 50-424, 84/01/26, 8401310244

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/20 ZAHLER, R. E. Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, 8401060040

8401050660 Forwards IE Insp Repts 50-424/83-22 & 50-425/83-22 on 831001-1110 No violations noted
DANCE, H. C. Division of Project & Resident Programs 83/12/08 KELLY, R. J. Georgia Power Co. 2pp 21724 159 24X Fiche 50-424, 83/12/08, 8401050660

--8401050669 IE Insp Repts 50-424/83-22 & 50-425/83-22 on 831001-1110 No violations noted Major areas inspected equipment storage, concrete placement, welding, Category 1 backfill, crane lift tests & installation of electrical cables
SANDERS, W. F. Region 2, Office of Director PANCIERA, V. W. Division of Project & Resident Programs 83/12/07 4pp 21724 161 24X Fiche 50-424, 83/12/08, 8401050660

8401050259 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-16 & 50-425/83-16 Violation re installation of penetration assembly withdrawn
LEWIS, R. C. Division of Project & Resident Programs 83/12/22 KELLEY, R. J. Georgia Power Co. 2pp 21728 281 24X Fiche 50-424, 83/12/22, 8401050259

--8401050264 Responds to NRC 830831 ltr re violations noted in IE Insp Repts 50-424/83-16 & 50-425/83-16 Violation re weld radiography disputed
FOSTER, D. O. Georgia Power Co. 83/09/30 LEWIS, R. C. Region 2, Office of Director 2pp, 21728 283 24X Fiche 50-424, 83/12/22, 8401050259

--8401050267 Forwards IE Insp Repts 50-424/83-16 & 50-425/83-16 on 830809-12 & notice of violation
DANCE, H. C. Division of Project & Resident Programs 83/08/31 KELLY, R. J. Georgia Power Co. 2pp 21728 285 24X Fiche 50-424, 83/12/22, 8401050259

--8401050272 Notice of violation from insp on 830809-12
* Region 2, Office of Director 83/08/31 1p 21728 287 24X Fiche 50-424, 83/12/22, 8401050259

--8401050276 IE Insp Repts 50-424/83-16 & 50-425/83-16 on 830809-12 Violation noted, failure to establish adequate radiography procedure to control special processes.
KLEINBORGE, W. P. Region 2, Office of Director BLAKE, J. J. Division of Engineering & Operational Programs, 83/08/29 7pp, 21728 288 24X Fiche 50-424, 83/12/22, 8401050259

8401240084 Forwards IE Insp Repts 50-424/83-24 & 50-425/83-24 on 831129-1202 No violations noted
DANCE, H. C. Division of Project & Resident Programs, 83/12/22, KELLY, R. J. Georgia Power Co. 2pp 21912 343 24X Fiche 50-424, 83/12/22, 8401240084

--8401240089 IE Insp Repts 50-424/83-24 & 50-425/83-24 on 831129-1202 No violations noted Major areas inspected structural backfill, structural concrete & previously identified, unresolved & inspector followup items
CDLON, T. E. Division of Engineering & Operational Programs HARRIS, J. R. Region 2, Office of Director 83/12/21 4pp 21912 345 24X Fiche 50-424, 83/12/22, 8401240084

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEVOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 164 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401090426 Ack receipt of 831128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-424/83-15 Response meets requirements of 10CFR2.201.
LEWIS, R. C. Division of Project & Resident Programs 83/12/30 KELLY, R. J. Georgia Power Co. 1p, 21753 169 24X Fiche 50-424, 83/12/30, 8401090426

--8401090431 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-424/83-15 & 50-425/83-15 Corrective actions Pullman Power Products engineering & GA personnel admonished to review process sheets closely
FOSTER, D. O. Georgia Power Co. 83/11/28 LEWIS, R. C. Region 2, Office of Director 2pp 21753 170 24X Fiche 50-424, 83/12/30, 8401090426

--8401090437 Forwards IE Insp Repts 50-424/83-15 & 50-425/83-15 on 830927-30 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/10/24 KELLY, R. J. Georgia Power Co. 2pp 21753 172 24X Fiche 50-424, 83/12/30, 8401090426

--8401090439 Notice of violation from insp on 830927-30.
* Region 2, Office of Director 83/10/24 1p, 21753 174 24X Fiche 50-424, 83/12/30, 8401090426

--8401090446 IE Insp Repts 50-424/83-15 & 50-425/83-15 on 830927-30 Violation noted, failure to provide for code required penetrant exam for RCPB weld 119-M-05.
GIRARD, E. H. Region 2, Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 83/10/19 4pp, 21753 175 24X Fiche 50-424, 83/12/30, 8401090426

8401090464 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-18 & 50-425/83-18 Response meets requirements of 10CFR2.201
LEWIS, R. C. Division of Project & Resident Programs 83/12/30 KELLY, R. J. Georgia Power Co. 1p 21753 158 24X Fiche 50-424, 83/12/30, 8401090464

--8401090468 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-424/83-18 & 50-425/83-18 Corrective actions C-E discontinued practice of gritblasting close heads following liquid penetrant exam
FOSTER, D. O. Georgia Power Co. 83/12/14 LEWIS, R. C. Region 2, Office of Director 2pp, 21753 159 24X Fiche 50-424, 83/12/30, 8401090464

--8401090472 Forwards IE Insp Repts 50-424/83-18 & 50-425/83-18 on 830816-0930 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs 83/11/07, KELLY, R. J. Georgia Power Co. 2pp 21753 161 24X Fiche 50-424, 83/12/30, 8401090464

--8401090474 Notice of violation from insp on 830816-0930.
* Region 2, Office of Director, 83/11/07 1p, 21753 163 24X Fiche 50-424, 83/12/30, 8401090464

--8401090476 IE Insp Repts 50-424/83-18 & 50-425/83-18 on 830816-0930 Violation noted, adequate measures not established to assure NDT controlled & accomplished w/applicable codes.
SANDERS, W. F. Region 2, Office of Director PANCIERA, V. Division of Project & Resident Programs, 83/11/04 5pp, 21753 164 24X Fiche 50-424, 83/12/30, 8401090464

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 083 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

DOCKETED ITEMS

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B40130002B Notification of B40126 meeting w/utis & Transamerica
Delaval, Inc (TDI) in Bethesda, MD to discuss actions required
to address insp results & operating experience re TDI
emergency diesel generators
CARUSO, R Licensing Branch 2 B4/01/17, SCHWENCER, A Licensing
Branch 2 21pp 22027 009 24X Fiche 50-000, B4/01/17, B40130002B

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators " Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New
York, Inc 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co of New
York, Inc 120pp 22000 041 24X Fiche 50-000, B4/01/18, B312120117

B Reportable occurrences, LERs & related correspondence

B401130152 Deficiency rept re diesel generator governor drive coupling
supplied by Transamerica Delaval Initially reported on
B2102B. Flexible element of drive coupling will be replaced
Replacement parts will be installed by B30330
FOSTER, D O Georgia Power Co FOSTER, D O Southern Co Services,
Inc B2/12/14 O'REILLY, J P Region 2, Office of Director 2pp
21802 128 24X Fiche 50-424, B2/12/14, B401130152

B401170184 Part 21 rept re loose flexible coupling drive hubs, mfg by
Lovejoy Coupling & installed by Transamerica Delaval, on
shafts in overspeed governor fuel transfer pump drive insp
of hubs in listed facilities recommended Utis notified
BOYER, R E Transamerica Delaval, Inc. B4/01/09 Director's
Office, Office of Inspection and Enforcement 5pp 21828 269 24X
Fiche 50-000, B4/01/09, B401170184

B401230384 Interim deficiency rept re heat sink adhesive failures of
printed circuit cards & failure of NYC cards Initially
reported on B30601 Potential interaction of heat sinks
w/other sys not probable
FOSTER, D O Georgia Power Co B4/01/11 O'REILLY, J P Region 2,
Office of Director 8pp 21877 182 24X Fiche 50-424, B4/01/11,
B401230384

B401260069 Deficiency rept re control circuit electrical penetration
protection Initially reported on B31219 AE continuing
evaluation to determine potential effects on safety of
operation Results of evaluation expected by B40030
FOSTER, D O Georgia Power Co B4/01/18 O'REILLY, J P Region 2,
Office of Director 2pp 21957 126 24X Fiche 50-424, B4/01/18,
B401260069

DOCKET 50-425 V00TLE ELECTRIC GENERATING PLANT

A. Application/construction stage documents & correspondence

B312200134 Forwards response to nine Users Group questions presented at
B31130 meeting & forwarded by R Caruso B31129 ltr re standby
diesel generators at nuclear power plants.
MATHEWS, C B Transamerica Delaval, Inc. B3/12/16 NOVAK, T M
Assistant Director for Licensing 19pp 22054 358, 24X
Fiche 50-000, B3/12/16, B312200134

B401110189 Requests addl info re Transamerica Delaval emergency diesel
generators. Owners group or plant-specific rept may be
submitted to respond to specific questions.
ADENSAM, E O Licensing Branch 4 B3/12/19 FOSTER, D Georgia
Power Co. 1p 21795 127, 24X Fiche 50-424, B3/12/19, B401110189

11060490 Forwards request for addl info re GA program Review of Suppl
O to GA program did B31216 will be completed within 30
days.
EWIS, R C Division of Project & Resident Programs B3/12/30,
KELLY, R J Georgia Power Co. 3pp 21740 180 24X
Fiche 50-424, B3/12/30, B401060490

O1050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related." Svc list encl
EISENHUT, D O Division of Licensing B4/01/05, Consolidated
Edison Co of New York, Inc 16pp 21746 190, 24X
Fiche 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing B4/01/06 Consolidated
Edison Co of New York, Inc 18pp 21757 267 24X
Fiche 50-000, B4/01/06, B401090221

B401170358 Provides info re facility control burn activities to
eliminate potential fire conditions scheduled for Jan-Feb
1984 Activities will be supervised by util & State of GA
Forestry Commission Map of areas to be burned encl
FOSTER, D O Georgia Power Co B4/01/09 ADENSAM, E O Licensing
Branch 4 3pp 21828 351 24X Fiche 50-424, B4/01/09, B401170358

B401130084 Generic Ltr B4-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues "
Svc list encl
EISENHUT, D O Division of Licensing B4/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda,
MD to discuss limited operational experience on operating
crews & development of acceptable experience profile for
new plants
HANNOX, J Division of Licensing B4/01/17 Division of
Licensing 1p 22000 349 24X Fiche 50-000, B4/01/17, B401270536

B Utility Preliminary Safety Analysis Report, amends

B401230488 Forwards Suppl 10 to PSAR, Chapter 17 Responsibility for
procurement transferred from Bechtel Power Corp to Southern
Co Svcs Changes do not adversely affect GA program
FOSTER, D O Georgia Power Co B3/12/16 O'REILLY, J P Region 2,
Office of Director 3pp 21877 025 24X Fiche 50-424, B3/12/16,
B401230488

--B401230495 Suppl 10 to PSAR, Chapter 17
* Georgia Power Co B3/12/16 39pp 21877 028 24X
Fiche 50-424, B3/12/16, B401230488

C Utility Environmental Report (ER), amends & correspondence

B401170149 Advises that Dept of Commerce & Advisory Council on
Historical Preservation removed from environ rept - DL stage
distribution, certified in B31128 ltr to DQ Eisenhut
FOSTER, D O Georgia Power Co B4/01/10 DENTON, H R Office of
Nuclear Reactor Regulation, Director 2pp 21827 126 24X
Fiche 50-424, B4/01/10, B401170149

F Security, medical, emergency & fire protection plans

B401100023 Notification of B40118 meeting w/utis in Waynesboro, GA to
discuss applicant security & contingency plan in light of
findings from NRC initial review
MILLER, M A Licensing Branch 4 B3/12/29 ADENSAM, E O Licensing
Branch 4 2pp 21776 056 24X Fiche 50-424, B3/12/29, B401100023

G. Adjudicatory correspondence

B401300096 Joint petition of Georgians Against Nuclear Energy for
leave to intervene & request for hearing
TEPER, D C, STANGLER, C A Georgians Against Nuclear Energy
B4/01/26 Atomic Safety and Licensing Board Panel 11pp
21999 171 24X Fiche 50-424, B4/01/26, B401300096

--B401300100 Request that hearings be held in Atlanta, GA Certificate of
Svc encl
TEPER, D C, STANGLER, C A Georgians Against Nuclear Energy
B4/01/26 Atomic Safety and Licensing Board Panel 2pp
21999 182 24X Fiche 50-424, B4/01/26, B401300096

B401300321 Petition of Campaign for Prosperous Georgia for leave to
intervene & request for hearing in Atlanta, GA re
applications for OLs Affidavits, notice of appearance &
Certificate of Svc encl
FOHLER, L Affiliation Unknown B4/01/26 Atomic Safety and
Licensing Board Panel 10pp 21993 347, 24X Fiche 50-424, B4/01/26,
B401300321

B401310244 Petition of Consumers Util Council of GA for leave to
intervene & request for hearing Certificate of Svc encl
DICHTER, J R Georgia, State of B4/01/26 Commissioners 5pp
22020 334, 24X Fiche 50-424, B4/01/26, B401310244

DOCKETED ITEMS

319

☉ Inspection reports, IE Bulletins & correspondence

8401050040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401050040

--8401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20,
8401060150

8401050660 Forwards IE Insp Repts 50-424/83-22 & 50-425/83-22 on 831001-1110 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/08
KELLY, R J Georgia Power Co 2pp 21724 159 24X
Fiche 50-424, 83/12/08, 8401050660

--8401050668 IE Insp Repts 50-424/83-22 & 50-425/83-22 on 831001-1110 No violations noted Major areas inspected equipment storage, concrete placement, welding, Category 1 backfill, crane lift tests & installation of electrical cables
SANDERS, W F Region 2, Office of Director PANCIERA, V W Division of Project & Resident Programs 83/12/07 4pp 21724 161 24X Fiche 50-424, 83/12/08, 8401050660

8401050259 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-16 & 50-425/83-16 Violation re installation of penetration assembly withdrawn
LEWIS, R C Division of Project & Resident Programs 83/12/22
KELLY, R J Georgia Power Co 2pp 21728 281 24X
Fiche 50-424, 83/12/22, 8401050259

--8401050264 Responds to NRC 830831 ltr re violations noted in IE Insp Repts 50-424/83-16 & 50-425/83-16 Violation re weld radiography disputed
FOSTER, D O Georgia Power Co 83/09/30 LEWIS, R C Region 2, Office of Director 2pp 21728 283 24X Fiche 50-424, 83/12/22, 8401050264

--8401050267 Forwards IE Insp Repts 50-424/83-16 & 50-425/83-16 on 830809-12 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/08/31
KELLY, R J Georgia Power Co 2pp 21728 285 24X
Fiche 50-424, 83/12/22, 8401050267

--8401050272 Notice of violation from insp on 830809-12
* Region 2, Office of Director 83/08/31 1p 21728 287 24X
Fiche 50-424, 83/12/22, 8401050272

--8401050276 IE Insp Repts 50-424/83-16 & 50-425/83-16 on 830809-12 Violation noted Failure to establish adequate radiography procedure to control special processes
KLEINSORGE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/08/29 7pp 21728 288 24X Fiche 50-424, 83/12/22, 8401050276

8401240084 Forwards IE Insp Repts 50-424/83-24 & 50-425/83-24 on 831129-1202 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/22
KELLY, R J Georgia Power Co 2pp 21912 343 24X
Fiche 50-424, 83/12/22, 8401240084

--8401240089 IE Insp Repts 50-424/83-24 & 50-425/83-24 on 831129-1202 No violations noted Major areas inspected structural backfill, structural concrete & previously identified, unresolved & inspector followup items
CONLON, T E Division of Engineering & Operational Programs HARRIS, J R Region 2, Office of Director 83/12/21 4pp 21912 345 24X Fiche 50-424, 83/12/22, 8401240084

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21791 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHM Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401090426 Ack receipt of 831128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-424/83-15 Response meets requirements of 10CFR2 201
LEWIS, R C Division of Project & Resident Programs 83/12/30
KELLY, R J Georgia Power Co 1p 21753 169 24X
Fiche 50-424, 83/12/30, 8401090426

--8401090431 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-424/83-15 & 50-425/83-15 Corrective actions Pullman Power Products engineering & QA personnel admonished to review process sheets closely
FOSTER, D O Georgia Power Co 83/11/28 LEWIS, R C Region 2, Office of Director 2pp 21753 170 24X Fiche 50-424, 83/12/30, 8401090431

--8401090437 Forwards IE Insp Repts 50-424/83-15 & 50-425/83-15 on 830927-30 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/10/24
KELLY, R J Georgia Power Co 2pp 21753 172 24X
Fiche 50-424, 83/12/30, 8401090437

--8401090446 IE Insp Repts 50-424/83-15 & 50-425/83-15 on 830927-30 Violation noted Failure to provide for code required penetrant exam for RCPB weld 119-W-05
GIRARD, E H Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/10/19 6pp 21753 175 24X Fiche 50-424, 83/12/30, 8401090446

8401090464 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-424/83-18 & 50-425/83-18 Response meets requirements of 10CFR2 201
LEWIS, R C Division of Project & Resident Programs 83/12/30
KELLY, R J Georgia Power Co 1p 21753 158 24X
Fiche 50-424, 83/12/30, 8401090464

--8401090468 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 50-424/83-18 & 50-425/83-18 Corrective actions C-E discontinued practice of gritblasting close heads following liquid penetrant exam
FOSTER, D O Georgia Power Co 83/12/14 LEWIS, R C Region 2, Office of Director 2pp 21753 159 24X Fiche 50-424, 83/12/30, 8401090468

--8401090472 Forwards IE Insp Repts 50-424/83-18 & 50-425/83-18 on 830816-0930 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/11/07
KELLY, R J Georgia Power Co 2pp 21753 161 24X
Fiche 50-424, 83/12/30, 8401090472

--8401090474 Notice of violation from insp on 830816-0930
* Region 2, Office of Director 83/11/07 1p 21753 163 24X
Fiche 50-424, 83/12/30, 8401090474

--8401090476 IE Insp Repts 50-424/83-18 & 50-425/83-18 on 830816-0930 Violation noted adequate measures not established to assure NDT controlled & accomplished w/applicable codes
SANDERS, W F Region 2, Office of Director PANCIERA, V Division of Project & Resident Programs 83/11/04 5pp 21753 164 24X
Fiche 50-424, 83/12/30, 8401090476

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUBO, R Licensing Branch 2 84/01/17 SCHWENGER, A, Licensing Branch 2 2pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

DOCKETED ITEMS

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) B4/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000, 041 24X Fiche 50-000, B4/01/18, B312120117

B. Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended. Utilis notified
BOYER, R. E. Transamerica Delaval, Inc B4/01/09 Director's Office, Office of Inspection and Enforcement. 5pp. 21828:249. 24X Fiche. 50-000, B4/01/09, B401170186

B401260069 Deficiency rept re control circuit electrical penetration protection Initially reported on B31219 AE continuing evaluation to determine potential effects on safety of operation. Results of evaluation expected by B40330
FOSTER, D. O. Georgia Power Co. B4/01/18 O'REILLY, J. P. Region 2, Office of Director. 2pp 21957:126. 24X Fiche. 50-424, B4/01/18, B401260069

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B401250068 Releases public version of revised emergency plan.
FELTON, J. M. Division of Rules and Records. B4/01/18 Document Management Branch. 1p. 21947:019. 24X Fiche 50-433, B4/01/18, B401250068

--B401250070 Public version of revised emergency plan w/B31226 ltr
PROFIO, A. E. California, Univ. of, Santa Barbara, CA B3/12/20.
THOMAS, C. D. Standardization & Special Projects Branch. 21pp. 21947:020. 24X Fiche. 50-433, B4/01/18, B401250068.

DOCKET BFN-50-437 FLOATING NUCLEAR PLANT

A. Application/construction stage documents & correspondence

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl.
EISENHUT, D. O. Division of Licensing. B4/01/05 Consolidated Edison Co. of New York, Inc. 16pp 21946:190. 24X Fiche: 50-000, B4/01/05, B401050382.

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D. O. Division of Licensing. B4/01/06 Consolidated Edison Co. of New York, Inc. 18pp 21957:267. 24X Fiche: 50-000, B4/01/06, B401090221.

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl.
EISENHUT, D. O. Division of Licensing. B4/01/13 Consolidated Edison Co. of New York, Inc. 18pp. 21946:174. 24X Fiche: 50-000, B4/01/13, B401130084.

G. Inspection reports, IE Bulletins & correspondence

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bus." Svc list encl.
BEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. B3/12/28 Consolidated Edison Co. of New York, Inc. 12pp. 21731:166. 24X Fiche: 50-000, B3/12/28, B312120090.

B312120093 IE Info Notice B3-04, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/12/30. Consolidated Edison Co. of New York, Inc. 127pp. 21826:060 24X Fiche: 50-000, B3/12/30, B312120093

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/10. Consolidated Edison Co. of New York, Inc. 125pp. 21946:053 24X Fiche: 50-000, B4/01/10, B312120104.

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000, 041 24X Fiche 50-000, B4/01/18, B312120117

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C. B. Transamerica Delaval, Inc B3/12/16 NOVAK, T. H. Assistant Director for Licensing 19pp 22054 338 24X Fiche 50-000, B3/12/16, B312200154

B40110358 Request addl info re Transamerica Delaval emergency diesel generators. Owners group or plant-specific repts may be utilized to respond to specific questions
ADENSAH, E. O. Licensing Branch 4 B3/12/29 PARRIS, H. O. Tennessee Valley Authority 1p 21794.342 24X Fiche 50-438, B3/12/29, B40110358

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl.
EISENHUT, D. O. Division of Licensing B4/01/05 Consolidated Edison Co. of New York, Inc. 16pp. 21946 190 24X Fiche: 50-000, B4/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl.
EISENHUT, D. O. Division of Licensing B4/01/06 Consolidated Edison Co. of New York, Inc. 18pp 21957.267. 24X Fiche: 50-000, B4/01/06, B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl.
EISENHUT, D. O. Division of Licensing B4/01/13 Consolidated Edison Co. of New York, Inc. 18pp. 21946:174 24X Fiche: 50-000, B4/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
HANNON, J. Division of Licensing B4/01/17 Division of Licensing 1p. 22000.349. 24X Fiche 50-000, B4/01/17, B401270536

B401310366 Forwards schedule of commitments adjusted to new fuel load schedule, per util B31216 ltr. Appropriate date changes will appear in next FSAR amend
KAMMER, D. B. Tennessee Valley Authority B4/01/27. ADENSAH, E. Licensing Branch 4. 2pp 22015:031 24X Fiche 50-438, B4/01/27, B401310366

I. Financial information

B401200194 Forwards Annual Financial Rept 1982, Vols I & II.
KAMMER, D. B. Tennessee Valley Authority B4/01/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 21865:001. 24X Fiche: 50-000, B4/01/12, B401200194.

--B401200199 Annual Financial Rept 1982, Vol I
PARRIS, H. O. Tennessee Valley Authority B4/01/12. 75pp 21865:002. 24X Fiche. 50-000, B4/01/12, B401200194.

DOCKETED ITEMS

321

--B401200206 Annual Financial Rept 1982, Vol II
PARRIS, H Q Tennessee Valley Authority 84/01/12 76pp
21865.077 24X Fiche 50-000, 84/01/12, B401200194

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche: 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401050311 Forwards IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831114-18 No violations noted
VERRELLI, D M Division of Project & Resident Programs 83/12/05, Tennessee Valley Authority 2pp 21729 272 24X
Fiche 50-438, 83/12/05, B401050311

--B401050323 IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831114-18 No violations noted Major areas inspected, GA insp of licensee identified items, inspector followup items & Part 21 requirements
MCFARLAND, C R Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/12/02, 3pp 21729 274 24X Fiche 50-438, 83/12/05, B401050311

B401240569 Ack receipt of 830823, 24 & 1123 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-15 & 50-439/83-15
VERRELLI, D M Division of Project & Resident Programs 83/12/15, PARRIS, H Q Tennessee Valley Authority 1p 21907 001 24X
Fiche: 50-438, 83/12/15, B401240569

--B401240574 Responds to NRC 830930 telcon re violations noted in IE Insp Rept 50-438/83-15 Util denies alleged violation re switchgear frame welded assemblies No applicable welding code existed at contract award time
MILLS, L M Tennessee Valley Authority 83/11/23 O'REILLY, J P Region 2, Office of Director App 21907 002 24X
Fiche 50-438, 83/12/15, B401240569

--B401240583 Responds to NRC 830719 ltr re violations noted in IE Insp Repts 50-438/83-15 & 50-439/83-15 Corrective actions: correction of welds will be completed by 831101
MILLS, L M Tennessee Valley Authority, 83/08/24 O'REILLY, J P Region 2, Office of Director 5pp 21907 008, 24X
Fiche: 50-438, 83/12/15, B401240569

--B401240587 Forwards IE Insp Repts 50-438/83-15 & 50-439/83-15 on 830501-0610 & notice of violation App B & Rept Details 2 withheld (ref 10CFR73 21)
VERRELLI, D M Division of Project & Resident Programs 83/07/19 PARRIS, H Q Tennessee Valley Authority 2pp 21909 013 24X
Fiche 50-438, 83/12/15, B401240569

--B401240590 Notice of violation from insp on 830501-0610
* Region 2, Office of Director 83/07/19 2pp, 21909 015 24X
Fiche: 50-438, 83/12/15, B401240569

--B401240599 IE Insp Repts 50-438/83-15 & 50-439/83-15 on 830501-0610 Violations noted unacceptable ERCW intake switchgear panel welds & failure of vendor to perform welding in accordance w/drawings.
WILCOX, J B., FREDRICKSON, P Region 2, Office of Director QUICK, D R Division of Project & Resident Programs 83/07/15 12pp, 21909 017 24X Fiche: 50-438, 83/12/15, B401240569.

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/12/30 Consolidated Edison Co. of New York, Inc 124pp, 21731 166 24X Fiche: 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/12/30 Consolidated Edison Co. of New York, Inc 127pp, 21826 060 24X Fiche: 50-000, 83/12/30, B312120093.

B401090128 Ack receipt of B31221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-27 & 50-439/83-27,
VERRELLI, D M Division of Project & Resident Programs, 84/01/03, PARRIS, H Q Tennessee Valley Authority 1p 21749 189 24X
Fiche: 50-438, 84/01/03, B401090128

--B401090135 Forwards response to NRC 831123 ltr re violations noted in IE Insp Repts 50-438/83-27 & 50-439/83-27 Corrective actions training sessions will be conducted to reemphasize proper insp of clamp spacers & allowable tolerance
MILLS, L M Tennessee Valley Authority 83/12/21 O'REILLY, J P Region 2, Office of Director App 21749 190, 24X
Fiche 50-438, 84/01/03, B401090128

--B401090141 Forwards IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831018-21 & notice of violation
VERRELLI, D M Division of Project & Resident Programs, 83/11/23 PARRIS, H Q Tennessee Valley Authority 2pp 21749 194, 24X
Fiche 50-438, 84/01/03, B401090128

--B401090144 Notice of violation from insp on 831018-21
* Region 2, Office of Director 83/11/23 1p 21749 196 24X
Fiche 50-438, 84/01/03, B401090128

--B401090150 IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831018-21 Violation noted failure to follow procedure for hanger
insps
YORK, J W, LIU, W Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs, 83/11/22 6pp 21749 197 24X Fiche 50-438, 84/01/03, B401090128

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104.

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10, Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche: 50-000, 84/01/10, B312120107

B401240334 Ack receipt of B31228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-28 & 50-439/83-28
LEWIS, R C Division of Project & Resident Programs 84/01/13 PARRIS, H Q Tennessee Valley Authority, 1p 21920 279 24X
Fiche 50-438, 84/01/13, B401240334

--B401240339 Responds to NRC 831127 ltr re violations noted in IE Insp Repts 50-438/83-28 & 50-439/83-28 Corrective actions: memo emphasizing awareness of requirement that heaters remain energized issued & FSAR revised to reflect exception
MILLS, L M Tennessee Valley Authority 83/12/28 O'REILLY, J P Region 2, Office of Director 3pp 21920 280 24X
Fiche: 50-438, 84/01/13, B401240334.

--B401240341 Forwards IE Insp Repts 50-438/83-28 & 50-439/83-28 on 831025-28 & notices of violation & deviation
LEWIS, R C Division of Project & Resident Programs 83/11/29 PARRIS, H Q Tennessee Valley Authority 2pp, 21920 284 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240344 Notice of violation from insp on 831025-28
* Region 2, Office of Director 83/11/29 1p 21920 286, 24X
Fiche 50-438, 84/01/13, B401240334

--B401240347 Notice of deviation from insp on 831025-28.
* Region 2, Office of Director, 83/11/29 1p 21920 287, 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240352 IE Insp Repts 50-438/83-28 & 50-439/83-28 on 831025-28 Noncompliance noted: failure to maintain heat on ERCW pump motors & to submit FSAR rev in timely manner, per conceptual design requirement final rept.
HUNT, M D Region 2, Office of Director CONLON, T E Division of Engineering & Operational Programs, 83/11/16 5pp 21920 288, 24X Fiche: 50-438, 84/01/13, B401240334

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/16 Consolidated Edison Co. of New York, Inc 127pp, 21957 142 24X Fiche: 50-000, 84/01/16, B312120114

B401300028 Notification of B40126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators.
CARUSO, R. Licensing Branch 2 84/01/17, SCHWENGER, A Licensing Branch 2, 21pp, 22027 009 24X Fiche: 50-000, 84/01/17, B401300028.

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18, Consolidated Edison Co. of New York, Inc, 118pp 22000 001, 24X Fiche: 50-000, 84/01/18, B312120116

DOCKETED ITEMS

83120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New
York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 83120117

R Periodic operating reports & related correspondence

8401160156 Notifies that scheduled fuel load date for Unit 1 is Oct 1987 Any schedule change will be described in next appropriate quarterly update
MILLS, L. M. Tennessee Valley Authority 84/01/09 EISENHUT, D. O.
Division of Licensing, 1p 21815 360 24X Fiche 50-438, 84/01/09, 8401160156

S Reportable occurrences, IERs & related correspondence

8401030182 First interim deficiency rept re overtightened studs on Borg Warner gate valve motor operators. Initially reported on 831121. Vendor revising drawings. Next rept expected by 840328. Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 83/12/19, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21681 321, 24X
Fiche 50-438, 83/12/19, 8401030182

8401030303 Second interim deficiency rept re tornado depressurization. Initially reported on 830414. Reevaluation of compartment pressures due to tornado depressurization of common zone fuel handling area determined structural capacity adequate.
MILLS, L. M. Tennessee Valley Authority, 83/12/19, O'REILLY, J. P.
Region 2, Office of Director, 2pp, 21680 137 24X
Fiche 50-438, 83/12/19, 8401030303

8401030101 Final Deficiency Rept NCR 1887 re Lakeside Bridge & Steel deficient steam generator support bolts. Initially reported on 820723. Field Change Request M-3045 to require preload of 50% ultimate load prepared.
MILLS, L. M. Tennessee Valley Authority 83/12/21, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21683 115 24X
Fiche 50-438, 83/12/21, 8401030101

8401040339 Supplemental final deficiency rept re bonnet studs improperly torqued on DHR valves. Initially reported on 831222. Completion of corrective actions anticipated by 840116. Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 83/12/22, O'REILLY, J. P.
Region 2, Office of Director, 1p, 21707 393 24X
Fiche 50-438, 83/12/22, 8401040339

8401040303 Supplemental final deficiency rept re generic defect in design review. Initially reported on 831213. Issuance of Engineering Procedures 3 57 & 3 58 expected by 840101.
MILLS, L. M. Tennessee Valley Authority, 83/12/23, O'REILLY, J. P.
Region 2, Office of Director, 1p 21707 100, 24X
Fiche 50-000, 83/12/23, 8401040303

8401040312 Second interim deficiency rept re field cables not properly terminated in penetrations. Initially reported on 830614. Documented audit program will be implemented. Next rept will be submitted by 840801.
MILLS, L. M. Tennessee Valley Authority, 83/12/23, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21708 026 24X
Fiche 50-438, 83/12/23, 8401040312

8401040406 Supplemental final deficiency rept re design review process interface coordination activity. Initially reported on 830717. Engineering Procedures 3 57 & 3 58 will be issued by 840101.
MILLS, L. M. Tennessee Valley Authority 83/12/23, O'REILLY, J. P.
Region 2, Office of Director, 1p 21703 362 24X
Fiche 50-000, 83/12/23, 8401040406

8401040592 Final deficiency rept re QA test documentation on radiation monitoring equipment. Initially reported on 820824. Item not reportable under 10CFR50.55(e). No significant deficiency represented in design or construction breakdown in QA.
MILLS, L. M. Tennessee Valley Authority, 83/12/23, O'REILLY, J. P.
Region 2, Office of Director, 2pp, 21703 361 24X
Fiche 50-438, 83/12/23, 8401040592

8401040493 Second interim deficiency rept re design of auxiliary feedwater pump trip & throttle valve electrical circuits. Initially reported on 830719. Design revisions implemented by Engineering Change Notices 2372 & 2833. Next rept by 840402.
MILLS, L. M. Tennessee Valley Authority 83/12/27, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21707 300 24X
Fiche 50-438, 83/12/27, 8401040493

8401120223 Supplemental deficiency rept re potential deterioration of isoprene gaskets on standby diesel generators. Initially reported on 821217. Unit 2 corrective actions postponed until 870326. Unit 1 work complete. Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/05, O'REILLY, J. P.
Region 2, Office of Director, 1p 21793 260 24X
Fiche 50-438, 84/01/05, 8401120223

8401120289 Ninth interim deficiency rept re inconsistencies in pipe break LOCA analysis. Initially reported on 801121. Review of B&W alternate approaches to resolve problem in progress. Also reported per Part 21. Next rept by 840630.
MILLS, L. M. Tennessee Valley Authority 84/01/05, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21792 172 24X
Fiche 50-438, 84/01/05, 8401120289

8401130053 First interim deficiency rept re Transamerica Delaval, Inc 64 program. Initially reported on 831206. Final configuration for control cabinet indicates drawing Revs M, L & M not incorporated. Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/05, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21802 354 24X
Fiche 50-000, 84/01/05, 8401130053

8401130165 Tenth interim deficiency rept re B&W nonconservative analysis of neutron flux. Initially reported on 840103. B&W rept on analysis indicates results acceptable w/o mod to plant hardware or setpoint. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/06, O'REILLY, J. P.
Region 2, Office of Director, 1p 21802 032 24X
Fiche 50-438, 84/01/06, 8401130165

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended. Utilis notified.
BOYER, R. E. Transamerica Delaval, Inc 84/01/09, Director's
Office, Office of Inspection and Enforcement 3pp 21828 269 24X
Fiche 50-000, 84/01/09, 8401170186

8401170214 Third interim Deficiency Rept 83-02 re failure of air compressor motor. Initially reported on 821209. Cause under investigation. Engineering Change Notice 1916 approved to implement motor replacement. Next rept expected by 841003.
MILLS, L. M. Tennessee Valley Authority 84/01/09, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21831 342 24X
Fiche 50-438, 84/01/09, 8401170214

8401240168 First interim deficiency rept re failed OE trip breakers. Initially reported on 831214. Replacement of defective breakers in Unit 1, w/ two breakers from Unit 2, under consideration. Next rept will be submitted by 840508.
MILLS, L. M. Tennessee Valley Authority 84/01/11, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21910 331 24X
Fiche 50-438, 84/01/11, 8401240168

8401240482 Second interim deficiency rept re reactor bldg sump pH values by B&W. Initially reported on 830623. Util will perform analysis in attempt to show that sump pH outside recommended limits not detrimental to plant safety.
MILLS, L. M. Tennessee Valley Authority 84/01/12, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21920 078 24X
Fiche 50-438, 84/01/12, 8401240482

8401240605 Final deficiency rept re governor lube oil cooler on standby diesel generator. Initially reported on 820308. Coolers relocated to position below governors. Drawing number will be added to parts list. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/13, O'REILLY, J. P.
Region 2, Office of Director, 2pp 21909 173 24X
Fiche 50-438, 84/01/13, 8401240605

8401240097 Fifth interim Deficiency Rept NCR BLN BLP 8201 re temp of nitrogen supply. Initially reported on 820114. Procurement specs for nitrogen heaters & mechanical installation drawings issued. Next rept by 860829.
MILLS, L. M. Tennessee Valley Authority 84/01/13, O'REILLY, J. P.
Region 2, Office of Director, 2pp, 21913 150 24X
Fiche 50-438, 84/01/13, 8401240097

8401240149 Supplemental final deficiency rept re auxiliary bldg fuel handling zone ventilation fans. Initially reported on 810506. Necessary mode cannot be implemented until winter conditions subside. Corrective action will be completed by 840615.
MILLS, L. M. Tennessee Valley Authority 84/01/13, O'REILLY, J. P.
Region 2, Office of Director, 1p 21910 271 24X
Fiche 50-438, 84/01/13, 8401240149

8401240264 Final Deficiency Rept NCR 2162 re defective sequencer control cards from Consolidated Control Corp. Initially reported on 830112. Failed cards returned to vendor. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/13, O'REILLY, J. P.
Region 2, Office of Director, 3pp 21909 359, 24X
Fiche 50-438, 84/01/13, 8401240264

8401240342 Final Deficiency Rept NCR-2221 re Johnson Machine Works welds on auxiliary feedwater pump room doors Initially reported on 830210 Doors returned to manufacturer for reworking Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/13 O'REILLY, J. P.
Region 2, Office of Director 2pp 21920 303 24X
Fiche 50-438, 84/01/13, 8401240342

8401240085 Fourth interim deficiency rept re undersigned snubber on main feedwater piping in Valve Room B Initially reported on 821013 Piping reanalyses will include torsional components & effects on floor response spectra Next rept by 850419
MILLS, L. M. Tennessee Valley Authority 84/01/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 21912 354 24X
Fiche 50-438, 84/01/16, 8401240085

8401260012 Final deficiency rept re failure of design criteria to consider venting of high points in ERCW sys Initially reported on 820802 Deficiency no longer reportable under 10CFR50.55(e)
MILLS, L. M. Tennessee Valley Authority 84/01/18 O'REILLY, J. P.
Region 2, Office of Director 3pp 21956 319 24X
Fiche 50-438, 84/01/18, 8401260012

8401260171 Final interim deficiency rept re failure to incorporate increased support in ERCW sys Initially reported on 831222 Investigation of scope, cause & corrective action underway Next rept expected by 840427
MILLS, L. M. Tennessee Valley Authority 84/01/18 O'REILLY, J. P.
Region 2, Office of Director 2pp 21956 292 24X
Fiche 50-438, 84/01/18, 8401260171

8401260344 Suppl to final deficiency rept re uncontrolled parts for battery chargers from Power Conversion Products, Inc. Correct number is 91-3463, Nuclear power manual revised.
MILLS, L. M. Tennessee Valley Authority 84/01/18 O'REILLY, J. P.
Region 2, Office of Director 1p 21959 300 24X
Fiche 50-438, 84/01/18, 8401260344

8401260359 Final deficiency rept re shielded power cable bend radius Initially reported on 820806 Conduits being reworked in compliance w/expected 840420 completion date Cable 2KE-ECA5-86-B will be reworked & grommet installed by 840420
MILLS, L. M. Tennessee Valley Authority 84/01/19 O'REILLY, J. P.
Region 2, Office of Director 3pp 21954 044 24X
Fiche 50-438, 84/01/19, 8401260359

8401300246 Final deficiency rept re Delaval problem w/starting air valve assembly on standby diesels Initially reported on 821201 Capscrews replaced per approved procedure & drawings revised to reflect shorter length
MILLS, L. M. Tennessee Valley Authority 84/01/23 O'REILLY, J. P.
Region 2, Office of Director 2pp 21993 360 24X
Fiche 50-000, 84/01/23, 8401300246

8401300275 Supplemental deficiency rept re Lambda power module failures. Initially reported on 801218 ACZ6 capacitor substituted for C6 capacitor Corrective action & final rept by 840601. Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/23 O'REILLY, J. P.
Region 2, Office of Director 1p 21995 361 24X
Fiche 50-438, 84/01/23, 8401300275

8401300140 First interim Deficiency Rept NCR BLN BLP 8334 re time span for ABCO temp switch response Initially reported on 831227 TVA considering replacement of switches w/fast-acting ambient monitoring switches Next rept due by 840815
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director 2pp 21977 361 24X
Fiche 50-438, 84/01/25, 8401300140

8401300193 Final Deficiency Rept 83-19 for Unit 1 & 83-15 for Unit 2 re pressure drop across Valen 2 1/2-inch stop check valve. Initially reported on 830202 Disc drawings revised Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director 2pp 21977 380 24X
Fiche 50-438, 84/01/25, 8401300193

8401300300 Final deficiency rept re check valve leak in air start sys of standby diesel generators Initially reported on 820209. Defective valves modified by replacing disc assembly per conversion procedure. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director 2pp 21996 352 24X
Fiche 50-438, 84/01/25, 8401300300

8401300325 Second interim deficiency rept re separation of front covers from Bailey meter modules Initially reported on 831004. Next rept will be submitted by 840420 Util awaiting B&W response re disposition Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director 1p 21995 362 24X
Fiche 50-438, 84/01/25, 8401300325

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C. S. Transamerica Delaval, Inc 83/12/16 NOVAK, T. M.
Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, 83/12/16, 8312200154

8401103358 Request addl info re Transamerica Delaval emergency diesel generators Owners group or plant-specific repts may be utilized to respond to specific questions
ADENBAM, E. O. Licensing Branch 4 83/12/29. PARRIS, H. O. Tennessee Valley Authority 1p. 21794 342 24X Fiche 50-438, 83/12/29, 8401103358

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D. O. Division of Licensing 84/01/05. Consolidated
Edison Co. of New York, Inc 16pp. 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl
EISENHUT, D. O. Division of Licensing 84/01/06. Consolidated
Edison Co. of New York, Inc 18pp. 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D. O. Division of Licensing 84/01/13. Consolidated
Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

8401310366 Forwards schedule of commitments adjusted to new fuel load schedule, per util 831216 ltr Appropriate date changes will appear in next FBAR amend.
KAMMER, D. S. Tennessee Valley Authority 84/01/27. ADENBAM, E.
Licensing Branch 4 2pp. 22015 051. 24X Fiche 50-438, 84/01/27, 8401310366

I Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II.
KAMMER, D. S. Tennessee Valley Authority 84/01/12 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 21865 001 24X
Fiche 50-000, 84/01/12, 8401200194

--8401200197 Annual Financial Rept 1982, Vol I
PARRIS, H. O. Tennessee Valley Authority 84/01/12 75pp
21865 002 24X Fiche 50-000, 84/01/12, 8401200194.

--8401200206 Annual Financial Rept 1982, Vol II.
PARRIS, H. O. Tennessee Valley Authority 84/01/12 76pp.
21865 077 24X Fiche 50-000, 84/01/12, 8401200194

O. Inspection Reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in FDR.
FELTON, J. M. Division of Rules and Records 83/10/20 ZAHLER, R. E.
Shaw, Pittman, Potts & Trowbridge 1p. 21744:003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement.
83/10/20 134pp. 21744:004 24X Fiche 50-000, 83/10/20, 8401060040

8401050311 Forwards IE Insp Repts 50-438/83-29 & 50-439/83-29 on 831114-18. No violations noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/12/05.
PARRIS, H. O. Tennessee Valley Authority 2pp. 21729:272 24X
Fiche 50-438, 83/12/05, 8401050311.

DOCKETED ITEMS

--B401030223 IE Insp Repts 50-438/83-29 & 50-439/83-29 on 831114-18 No violations noted Major areas inspected QA Insp of licensee identified items, Inspector Followup items & Part 21 requirements.
MCFARLAND, C.R. Region 2, Office of Director. UPRIGHT, C.M. Division of Engineering & Operational Programs 83/12/02 3pp
21729-274 24X Fiche: 50-438, 83/12/05, B401030311

B401240369 Ack receipt of 830823, 24 & 1123 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-15 & 50-439/83-15
VERRELLI, D.M. Division of Project & Resident Programs 83/12/15
PARRIS, H.Q. Tennessee Valley Authority. 1p 21909 001 24X
Fiche: 50-438, 83/12/15, B401240369

--B401240383 Responds to NRC 830719 ltr re violations noted in IE Insp Repts 50-438/83-15 & 50-439/83-15 Corrective actions, correction of welds will be completed by 831101
MILLS, L.M. Tennessee Valley Authority. 83/08/24 O'REILLY, J.P. Region 2, Office of Director. 3pp 21909 008 24X
Fiche: 50-438, 83/12/15, B401240369

--B401240387 Forwards IE Insp Repts 50-438/83-15 & 50-439/83-15 on 830901-0610 & notice of violation App B & Rept Details 2 withheld (ref 10CFR73.21)
VERRELLI, D.M. Division of Project & Resident Programs 83/07/19
PARRIS, H.Q. Tennessee Valley Authority. 2pp 21909 013 24X
Fiche: 50-438, 83/12/15, B401240369

--B401240390 Notice of violation from insp on 830501-0610.
* Region 2, Office of Director 83/07/19 2pp 21909 015 24X
Fiche: 50-438, 83/12/15, B401240369.

--B401240399 IE Insp Repts 50-438/83-15 & 50-439/83-15 on 830501-0610 Violations noted. unacceptable ERCW intake switchgear panel welds & failure of vendor to perform welding in accordance w/drawings.
WILCOX, J.D., FREDRICKSON, P. Region 2, Office of Director. QUICK, D.R. Division of Project & Resident Programs 83/07/15.
12pp. 21909 017. 24X Fiche: 50-438, 83/12/15, B401240369

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp. 21731 166 24X Fiche: 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc 127pp. 21826 060 24X Fiche: 50-000, 83/12/30, B312120093

B401090128 Ack receipt of 831221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-27 & 50-439/83-27
VERRELLI, D.M. Division of Project & Resident Programs 84/01/03
PARRIS, H.Q. Tennessee Valley Authority 1p. 21749 189. 24X
Fiche: 50-438, 84/01/03, B401090128

--B401090135 Forwards response to NRC 831123 ltr re violations noted in IE Insp Repts 50-438/83-27 & 50-439/83-27. Corrective actions: training sessions will be conducted to reemphasize proper insp of clamp spacers & allowable tolerance
MILLS, L.M. Tennessee Valley Authority. 83/12/21 O'REILLY, J.P. Region 2, Office of Director. 4pp 21749 190. 24X
Fiche: 50-438, 84/01/03, B401090128

--B401090141 Forwards IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831018-21 & notice of violation
VERRELLI, D.M. Division of Project & Resident Programs 83/11/23
PARRIS, H.Q. Tennessee Valley Authority 2pp 21749 194. 24X
Fiche: 50-438, 84/01/03, B401090128

--B401090144 Notice of violation from insp on 831018-21.
* Region 2, Office of Director. 83/11/23. 1p. 21749 196. 24X
Fiche: 50-438, 84/01/03, B401090128

--B401090150 IE Insp Repts 50-438/83-27 & 50-439/83-27 on 831018-21. Violation noted: failure to follow procedure for hanger insps.
YORK, J.W., LIU, W. Region 2, Office of Director. BLAKE, J.J. Division of Engineering & Operational Programs. 83/11/22 4pp
21749 197 24X Fiche: 50-438, 84/01/03, B401090128

B12120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10. Consolidated Edison Co. of New York, Inc 125pp 21946 053. 24X Fiche: 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche: 50-000, 84/01/10, B312120107

B401240334 Ack receipt of 831228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-28 & 50-439/83-28
LEWIS, R.C. Division of Project & Resident Programs 84/01/13
PARRIS, H.Q. Tennessee Valley Authority 1p 21920 274 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240339 Responds to NRC 831129 ltr re violations noted in IE Insp Repts 50-438/83-28 & 50-439/83-28 Corrective actions memo emphasizing awareness of requirement that heaters remain energized issued & FBAR revised to reflect exception
MILLS, L.M. Tennessee Valley Authority 83/12/28 O'REILLY, J.P. Region 2, Office of Director 3pp 21920 280 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240341 Forwards IE Insp Repts 50-438/83-28 & 50-439/83-28 on 831025-28 & notices of violation & deviation
LEWIS, R.C. Division of Project & Resident Programs 83/11/29
PARRIS, H.Q. Tennessee Valley Authority 2pp 21920 284 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240347 Notice of deviation from insp on 831025-28
* Region 2, Office of Director 83/11/29 1p 21920 287 24X
Fiche: 50-438, 84/01/13, B401240334

--B401240352 IE Insp Repts 50-438/83-28 & 50-439/83-28 on 831025-28 Noncompliance noted Failure to maintain heat on ERCW pump motors & to submit FBAR rev in timely manner, per conceptual design requirement final rept
HUNT, M.D. Region 2, Office of Director CONLON, T.E. Division of Engineering & Operational Programs 83/11/16 5pp 21920 288 24X Fiche: 50-438, 84/01/13, B401240334

B312120114 IE Info Notice 84-03, "Exercise Frequency." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc 127pp. 21937 142 24X Fiche: 50-000, 84/01/16, B312120114

B401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R. Licensing Branch 2. 84/01/17 SCHWENGER, A. Licensing Branch 2 21pp 22027 009 24X Fiche: 50-000, 84/01/17, B401300028

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche: 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041. 24X Fiche: 50-000, 84/01/18, B312120117

R Periodic operating reports & related correspondence

B401160156 Notifies that scheduled fuel load date for Unit 1 is Oct 1987 Any schedule change will be described in next appropriate quarterly update.
MILLS, L.M. Tennessee Valley Authority 84/01/09 EISENHUT, D.O. Division of Licensing 1p 21815 360 24X Fiche: 50-438, 84/01/09, B401160156

B Reportable occurrences, LERs & related correspondence

B401030182 First interim deficiency rept re overtightened studs on Borg Warner gate valve motor operators Initially reported on 831121. Vendor revising drawings. Next rept expected by 840328 Also reported per Part 21
MILLS, L.M. Tennessee Valley Authority 83/12/19 O'REILLY, J.P. Region 2, Office of Director 2pp 21681 321 24X
Fiche: 50-438, 83/12/19, B401030182

B401030303 Second interim deficiency rept re tornado depressurization Initially reported on 830414. Reevaluation of compartment pressures due to tornado depressurization of common zone fuel handling area determined structural capacity adequate.
MILLS, L.M. Tennessee Valley Authority 83/12/19 O'REILLY, J.P. Region 2, Office of Director 2pp. 21680 137. 24X
Fiche: 50-438, 83/12/19, B401030303.

DOCKETED ITEMS

325

8401030306 Second interim deficiency rept re drawing discrepancy for in-core monitor sleeves Initially reported on 830405 B&W recommended until install sleeves in correct location Next rept will be submitted by 830123
MILLS,L.M. Tennessee Valley Authority 83/12/19 O'REILLY,J.P.
Region 2, Office of Director 2pp 21680 113 24X
Fiche 50-438,83/12/19,8401030306

8401030101 Final Deficiency Rept NCR 1887 re Lakeside Bridge & Steel deficient steam generator support bolts Initially reported on 820723 Field Change Request M-3045 to require preload of 50% ultimate load prepared
MILLS,L.M. Tennessee Valley Authority 83/12/21 O'REILLY,J.P.
Region 2, Office of Director 2pp 21683 115 24X
Fiche 50-438,83/12/21,8401030101

8401040339 Supplemental final deficiency rept re bonnet studs improperly torqued on DHR valves Initially reported on 811222 Completion of corrective actions anticipated by 840116 Also reported per Part 21
MILLS,L.M. Tennessee Valley Authority 83/12/22 O'REILLY,J.P.
Region 2, Office of Director 1p 21707 353 24X
Fiche 50-438,83/12/22,8401040339

8401040303 Supplemental final deficiency rept re generic defect in design review Initially reported on 811215 Issuance of Engineering Procedures 3 57 & 3 58 expected by 840101
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 1p 21707 100 24X
Fiche 50-000,83/12/23,8401040303

8401040312 Second interim deficiency rept re field cables not properly terminated in penetrations Initially reported on 830614 Documented audit program will be implemented Next rept will be submitted by 840801
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 2pp 21708 026 24X
Fiche 50-438,83/12/23,8401040312

8401040327 Final Deficiency Rept NCR 1986 re linear indications in Natl Valve & Mfg Co spool pieces Initially reported on 820924 All subassemblies containing identified matl inspected & repaired Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 2pp 21706 191 24X
Fiche 50-438,83/12/23,8401040327

8401040406 Supplemental final deficiency rept re design review process interface coordination activity Initially reported on 810717 Engineering Procedures 3 57 & 3 58 will be issued by 840101
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 1p 21703 362 24X
Fiche 50-000,83/12/23,8401040406

8401040592 Final deficiency rept re QA test documentation on radiation monitoring equipment Initially reported on 820824 Item not reportable under 10CFR50.55(e) No significant deficiency represented in design or const nor breakdown in QA
MILLS,L.M. Tennessee Valley Authority 83/12/23 O'REILLY,J.P.
Region 2, Office of Director 2pp 21705 361 24X
Fiche 50-438,83/12/23,8401040592

8401040493 Second interim deficiency rept re design of auxiliary feedwater pump trip & throttle valve electrical circuits. Initially reported on 830719 Design revs implemented by Engineering Change Notices 2372 & 2833 Next rept by 840402
MILLS,L.M. Tennessee Valley Authority 83/12/27 O'REILLY,J.P.
Region 2, Office of Director 2pp 21707 300, 24X
Fiche 50-438,83/12/27,8401040493

8401030581 First interim deficiency rept re Limitorque valve flooded in reactor bldg normal sump Initially reported on 831201 Valve motor cleaned & inspected Next rept expected by 840328
MILLS,L.M. Tennessee Valley Authority 83/12/27 O'REILLY,J.P.
Region 2, Office of Director 2pp 21726 121, 24X
Fiche 50-438,83/12/27,8401030581

8401120223 Supplemental deficiency rept re potential deterioration of isoprene gaskets on standby diesel generators Initially reported on 821217 Unit 2 corrective actions postponed until 870326 Unit 1 work complete Also reported per Part 21.
MILLS,L.M. Tennessee Valley Authority 84/01/05 O'REILLY,J.P.
Region 2, Office of Director 1p 21793 260, 24X
Fiche 50-438,84/01/05,8401120223

8401120289 Ninth interim deficiency rept re inconsistencies in pipe break LOCA analysis Initially reported on 801121 Review of B&W alternate approaches to resolve problem in progress. Also reported per Part 21 Next rept by 840530
MILLS,L.M. Tennessee Valley Authority 84/01/05 O'REILLY,J.P.
Region 2, Office of Director 2pp 21792 172, 24X
Fiche 50-438,84/01/05,8401120289

8401130053 First interim deficiency rept re Transamerica Delaval, Inc GA program Initially reported on 831205 Final configuration for control cabinet indicates drawing Revs K.L. & M not incorporated Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/05 O'REILLY,J.P.
Region 2, Office of Director 2pp 21802 354 24X
Fiche 50-000,84/01/05,8401130053

8401130165 Tenth interim deficiency rept re B&W nonconservative analysis of neutron flux. Initially reported on 840105 B&W rept on analysis indicates results acceptable w/o mod to plant hardware or setpoint Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/06 O'REILLY,J.P.
Region 2, Office of Director 1p 21802-032, 24X
Fiche 50-438,84/01/06,8401130165

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended. Util notified.
BOYER,R.E. Transamerica Delaval, Inc 84/01/09, Director's Office, Office of Inspection and Enforcement 5pp. 21828:269 24X
Fiche 50-000,84/01/09,8401170186

8401240168 First interim deficiency rept re failed OE trip breakers Initially reported on 831214 Replacement of defective breakers in Unit 1 w/ two breakers from Unit 2, under consideration Next rept will be submitted by 840508
MILLS,L.M. Tennessee Valley Authority 84/01/11 O'REILLY,J.P.
Region 2, Office of Director 2pp 21910 331 24X
Fiche 50-438,84/01/11,8401240168

8401240482 Second interim deficiency rept re reactor bldg sump pH values by B&W Initially reported on 830623 Util will perform analysis in attempt to show that sump pH outside recommended limits not detrimental to plant safety
MILLS,L.M. Tennessee Valley Authority 84/01/12 O'REILLY,J.P.
Region 2, Office of Director 2pp 21920:078 24X
Fiche 50-438,84/01/12,8401240482

8401240605 Final deficiency rept re governor lube oil cooler on standby diesel generator Initially reported on 820308 Coolers relocated to position below governors Drawing number will be added to parts list Also reportable per Part 21
MILLS,L.M. Tennessee Valley Authority 84/01/12 O'REILLY,J.P.
Region 2, Office of Director 2pp 21909 173, 24X
Fiche 50-438,84/01/12,8401240605

8401240097 Fifth interim Deficiency Rept NCR BLN BLP 8201 re temp of nitrogen supply Initially reported on 820114 Procurement specs for nitrogen heaters & mechanical installation drawings issued Next rept by 860829
MILLS,L.M. Tennessee Valley Authority 84/01/13 O'REILLY,J.P.
Region 2, Office of Director 2pp 21913 150, 24X
Fiche 50-438,84/01/13,8401240097

8401240149 Supplemental final deficiency rept re auxiliary bldg fuel handling zone ventilation fans Initially reported on 810506. Necessary mods cannot be implemented until winter conditions subside Corrective action will be completed by 840615
MILLS,L.M. Tennessee Valley Authority 84/01/13 O'REILLY,J.P.
Region 2, Office of Director 1p 21910 271 24X
Fiche 50-438,84/01/13,8401240149

8401240342 Final Deficiency Rept NCR-2221 re Johnson Machine Works welds on auxiliary feedwater pump room doors. Initially reported on 830210. Doors returned to manufacturer for reworking. Also reportable per Part 21.
MILLS,L.M. Tennessee Valley Authority 84/01/13 O'REILLY,J.P.
Region 2, Office of Director 2pp 21920 303, 24X
Fiche 50-438,84/01/13,8401240342

8401240085 Fourth interim deficiency rept re undersigned snubbers on main feedwater piping in Valve Room B Initially reported on 821013 Piping reanalyses will include torsional components & effects on floor response spectra Next rept by 830419.
MILLS,L.M. Tennessee Valley Authority 84/01/16 O'REILLY,J.P.
Region 2, Office of Director 2pp 21912:354 24X
Fiche 50-438,84/01/16,8401240085

8401260012 Final deficiency rept re failure of design criteria to consider venting of high points in ERCW sys Initially reported on 820802. Deficiency no longer reportable under 10CFR50.55(e)
MILLS,L.M. Tennessee Valley Authority 84/01/18 O'REILLY,J.P.
Region 2, Office of Director 2pp 21956:319 24X
Fiche 50-438,84/01/18,8401260012

8401260171 Final interim deficiency rept re failure to incorporate increased support in ERCW sys. Initially reported on 831222. Investigation of scope, cause & corrective action underway. Next rept expected by 840427.
MILLS,L.M. Tennessee Valley Authority 84/01/18 O'REILLY,J.P.
Region 2, Office of Director 2pp 21956:292, 24X
Fiche 50-438,84/01/18,8401260171

DOCKETED ITEMS

8401300246 Final deficiency rept re Delaval problem w/starting air valve assembly on standby diesel. Initially reported on 821201. Capscrews replaced per approved procedure & drawings revised to reflect shorter length.
MILLS, L. M. Tennessee Valley Authority 84/01/23 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21993 360 24X
Fiche: 50-000, 84/01/23, 8401300246

8401300275 Supplemental deficiency rept re Lambda power module failures initially reported on 801218 AC24 capacitor substituted for C6 capacitor. Corrective action & final rept by 840601. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/23 O'REILLY, J. P.
Region 2, Office of Director. 1p 21995 361 24X
Fiche 50-438, 84/01/23, 8401300275

8401300140 First interim deficiency Rept NCR BLN BLP 8334 re time span for ASCO temp switch response. Initially reported on 831227. TVA considering replacement of switches w/fast-acting ambient monitoring switches. Next rept due by 840815.
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21997 361 24X
Fiche 50-438, 84/01/25, 8401300140.

8401300193 Final Deficiency Rept 83-19 for Unit 1 & 83-15 for Unit 2 re pressure drop across Velan 2 1/2-inch stop check valve. Initially reported on 830202. Disc drawings revised. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21997 350 24X
Fiche 50-438, 84/01/25, 8401300193

8401300300 Final deficiency rept re check valve leak in air start sys of standby diesel generators. Initially reported on 820209. Defective valves modified by replacing disc assembly per conversion procedure. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director. 2pp 21996 352 24X
Fiche: 50-438, 84/01/25, 8401300300.

8401300325 Second interim deficiency rept re separation of front covers from Bailey meter modules. Initially reported on 831004. Next rept will be submitted by 840420. Util awaiting B&W response re disposition. Also reportable per Part 21.
MILLS, L. M. Tennessee Valley Authority 84/01/25 O'REILLY, J. P.
Region 2, Office of Director. 1p 21995 362 24X
Fiche: 50-438, 84/01/25, 8401300325

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8401160385 FOIA request for four categories of documents
HIATT, S. L. Ohio Citizens for Responsible Energy 83/09/27.
FELTON, J. M. Division of Rules and Records. 1p 21836 030 24X
Fiche: 50-440, 83/09/27, 8401160385.

8401170032 FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const
GANULIN, R. Ohio, State of 83/09/30 Office of Administration
2pp. 21837 001. 24X Fiche: 50-440, 83/09/30, 8401170032

8401170034 Responds to FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const
Forwards App A documents
FELTON, J. M. Division of Rules and Records 83/10/21 GANULIN, R.
Ohio, State of 3pp 21837 003 24X Fiche: 50-440, 83/10/21, 8401170034

--821180523 Recommends mgt level meeting w/util in Bethesda or caseload Forecast panel site visit prior to 821231, since some review areas may have licensing impact
NOVAK, T. M. Assistant Director for Licensing. 82/11/12
EISENHUT, D. O. Division of Licensing. 2pp. 21837 302. 24X
Fiche: 50-440, 83/10/21, 8401170034

--8401170036 Graph of preoperational & acceptance testing of facility components.
* Affiliation Unknown. 82/01/11. 3pp 21837 008. 24X
Fiche: 50-440, 83/10/21, 8401170034.

--8401170038 Discusses cancellation of 830321 Caseload Forecast Panel mgt meeting due to slip of fuel load to Dec 1984. Press release will be issued by util
STEFANO, J. J. Licensing Branch 1 83/03/08. NOVAK, T. M. Assistant Director for Licensing. 3pp. 21837 011. 24X
Fiche: 50-440, 83/10/21, 8401170034

--8401170042 Info re facility const Related info encl.
* Cleveland Electric Illuminating Co 83/10/21 50pp
21837 063. 24X Fiche: 50-440, 83/10/21, 8401170034

--8401170044 Handwritten notes re facility const
* Affiliation Unknown 81/10/07 5pp 21837 221 24X
Fiche 50-440, 83/10/21, 8401170034

--8401170048 Handwritten "Piping Status " Related info encl
* Affiliation Unknown 79/10/31 16pp 21837 233 24X
Fiche 50-440, 83/10/21, 8401170034

--8401170051 "Progress for Perry " Related info encl
* Affiliation Unknown 79/11/13 5pp 21837 256 24X
Fiche 50-440, 83/10/21, 8401170034

8401160390 Responds to FOIA request for four categories of documents
Forwards App A documents Request for documents released under FOIA Request 83-306 pending
FELTON, J. M. Division of Rules and Records 83/10/26 HIATT, S. L.
Ohio Citizens for Responsible Energy 3pp 21836 031 24X
Fiche 50-440, 83/10/26, 8401160390

8312200134 Forwards response to nine Users Group questions presented 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C. S. Transamerica Delaval, Inc 83/12/16 NOVAK, T. M.
Assistant Director for Licensing 17pp 22054 358 24X
Fiche 50-000, 83/12/16, 8312200134

8401190172 Requests addl info re Transamerica Delaval emergency diesel generators. Response may be submitted via owners group or plant-specific rept
YOUNGBLOOD, B. J. Licensing Branch 1 83/12/28 EDELMAN, M. R.
Cleveland Electric Illuminating Co. 2pp 21861 350 24X
Fiche 50-440, 83/12/28, 8401190172

8401100323 Forwards addl info per Equipment Qualification Branch Questions 270 ia, ic & B consisting of tables listing principal component, safety function & safety class
EDELMAN, M. R. Cleveland Electric Illuminating Co 84/01/04
YOUNGBLOOD, B. J. Licensing Branch 1 42pp 21764 155 24X
Fiche 50-440, 84/01/04, 8401100323

8401170308 Requests plans for assuring adequacy of design verification program & compliance w/SAR commitments. Response due in 60 days
EISENHUT, D. O. Division of Licensing 84/01/04 EDELMAN, M. R.
Cleveland Electric Illuminating Co 2pp 21847 150 24X
Fiche 50-440, 84/01/04, 8401170308

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification. Sandia position is that NRC environ qualification program has problems
EISENHUT, D. O. Division of Licensing 84/01/05 PALLADINO, N. J.
Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D. O. Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401170391 Forwards "Action Plan to Resolve Addl Containment Issues (Humphrey Concerns)," constituting final rept on Mark III containment sys issues. Detailed action plans & response submittal summaries encl
EDELMAN, M. R. Cleveland Electric Illuminating Co 84/01/05
YOUNGBLOOD, B. J. Licensing Branch 1 1p 21827 161 24X
Fiche 50-440, 84/01/05, 8401170391

--8401170396 "Action Plan to Resolve Addl Containment Issues (Humphrey Concerns)"
* Cleveland Electric Illuminating Co 83/12/29. 3pp 21827 162
24X Fiche 50-440, 84/01/05, 8401170391

--8401170403 "Perry Plant-Unique Pool Swell Encroachment Study " W/40 oversize figures. Aperture cards are available in PDR
* General Electric Co 83/07/13. 63pp 21827 165 24X
Fiche 50-440, 84/01/05, 8401170391

--8401170411 "Model Study of Perry Nuclear Power Plant Suppression Pool final technical rept W/90 oversize drawings. Aperture cards are available in PDR
* Gilbert/Commonwealth Cos 77/07/06 127pp 21827 229 24X
Fiche 50-440, 84/01/05, 8401170391.

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing. Svc list encl
EISENHUT, D. O. Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221.

DOCKETED ITEMS

327

B401130451 Notification of B40207 meeting w/util in Bethesda, MD to discuss plans for detailed control room design review
STEFANO, J J Licensing Branch 1 84/01/10 YOUNGBLOOD, B J
Licensing Branch 1 3pp 21819 339 24X Fiche 50-440, 84/01/10, 8401130451

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

E NRC Safety Evaluation Report (SER), suppls & correspondence

B401190220 Forwards NRC evaluation finding re BER Outstanding Issue 14, "Control Sys Failures," to be incorporated in next SSER
Evaluation partially resolves issue re effects of failures of power sources, sensors or sensor impulse lines
YOUNGBLOOD, B J Licensing Branch 1 84/01/10 EDELMAN, M R
Cleveland Electric Illuminating Co 8pp 21870 220 24X
Fiche 50-440, 84/01/10, 8401190220

F Security, medical, emergency & fire protection plans

B401050281 Forwards IE Insp Repts 50-440/83-36 & 30-19494/83-01 on B31206-09, No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/12/21
EDELMAN, M R Cleveland Electric Illuminating Co 2pp 21726 341
24X Fiche 50-440, 83/12/21, 8401050281

--B401050286 IE Insp Repts 50-440/83-36 & 30-19494/83-01 on B31206-09 No noncompliance noted Major areas inspected radiation protection program, including organization & staffing, training & health physics procedures
MILLER, D E, GREGER, L R Region 3, Office of Director 83/12/21
3pp 21726 343 24X Fiche 50-440, 83/12/21, 8401050286

B401230389 Notifies of B40112 & 13 radiological emergency preparedness program meetings in Chicago, IL to discuss final FY84/85 emergency preparedness exercise schedule & to develop prompt alert & notification certification schedules
PAPERIELLO, C J Region 3, Office of Director 84/01/05
EDELMAN, M R Cleveland Electric Illuminating Co 3pp 21878 236
24X Fiche 50-440, 84/01/05, 8401230389

B401170553 Forwards NRR comments on emergency action levels of emergency plan Comments should be incorporated into emergency classification & action level schema. Response requested within 5 days
YOUNGBLOOD, B J Licensing Branch 1 84/01/11 EDELMAN, M R
Cleveland Electric Illuminating Co 4pp 21844 323 24X
Fiche 50-440, 84/01/11, 8401170553

G Adjudicatory correspondence

B401100140 Tenth set of interrogatories on diesel generators Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/01/06
Office of the Executive Legal Director 3pp 21760 010 24X
Fiche 50-440, 83/01/06, 8401100140

B401060358 Response to util answer to NRC supplemental response to Ohio Citizens for Responsible Energy B31027 motion for admission & to resubmit proposed Contention 2 re diesel generator reliability Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/12/22
Atomic Safety and Licensing Board Panel 4pp 21741 079 24X
Fiche 50-440, 83/12/22, 8401060358

B401040126 Forwards statement of Sunflower Alliance contention & specific issues raised re adequacy of offsite emergency plans Affidavit in support of motion for summary disposition requested
WOODHEAD, C P Hearing Branch 4 83/12/29 PERRY, B Federal Emergency Management Agency 3pp 21702 061 24X
Fiche 50-440, 83/12/29, 8401040126

B40110159 Answer opposing Ohio Citizens for Responsible Energy B31208 amend to motion to reopen record on Comstock issues ASLB would be justified in dismissing amended motion as falling outside scope of Issues 3 & 7
GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge GLASSPIEGEL, H
Cleveland Electric Illuminating Co 84/01/06 Atomic Safety and Licensing Board Panel 12pp 21774 317 24X Fiche 50-440, 84/01/06, 840110159

--B401110164 Affidavit of SC Young re termination of Johnson Controls, Inc
QC Inspector R Wade Prof qualifications encl
YOUNG, S C Cleveland Electric Illuminating Co 84/01/06 23pp
21774 329 24X Fiche 50-440, 84/01/06, 8401110159

--B401110167 Affidavit of E Riley re termination of Johnson Controls, Inc
QC Inspector R Wade Certificate of Svc encl
RILEY, E Cleveland Electric Illuminating Co 84/01/06 10pp
21774 353 24X Fiche 50-440, 84/01/06, 8401110159

B401230225 Responds to B30917 ltr requesting Commission take action under 10CFR2 206 re facility. Request denied for reasons stated in encl Director's Decision DD-84-1.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/09 LODGE, T J Affiliation Unknown 3pp
21931 298 24X Fiche 50-440, 84/01/09, 8401230225

--B401230230 Director's Decision DD-84-1 denying request for investigation of const accident during attempted lift of steam separator from reactor vessel & evaluation of safety, structural & economic impacts
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/09 10pp 21931 301 24X
Fiche 50-440, 84/01/09, 8401230225

--B401230234 Notice of issuance of Director's Decision DD-84-1 under 10CFR2 206 denying S Bass & Sunflower Alliance request for util to open plant to insp re lifting accident
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/01/09 2pp 21931 311 24X
Fiche 50-440, 84/01/09, 8401230225

B401120421 Forwards affidavit of M Gilder, NRC resident inspector, re newspaper articles submitted by intervenor B31228 telcon W/o encl
WOODHEAD, C P Hearing Branch 4 84/01/10 BLOCH, P B, BRIGHT, O D, KLINE, J R Atomic Safety and Licensing Board Panel 1p 21791 020
24X Fiche 50-440, 84/01/10, 8401120421

B401170227 Order extending time until B40120 for Commission to act to review B3115 director's decision re Ohio Citizens for Responsible Energy request
CHILK, B J Office of the Secretary of the Commission 84/01/13
Commissioners 1p 21933 323 24X Fiche 50-440, 84/01/13, 8401170227

B401240333 Brief on regulations & guidance applicable to Issue 16 re reliability of Transamerica Delaval diesel generators Util must prove generator compliance w/NRC regulations & stds or replace generators. Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 84/01/16
Atomic Safety and Licensing Board Panel 16pp 21920 308 24X
Fiche 50-440, 84/01/16, 8401240333

B401230403 Memorandum & Order LBP-84-3, denying Ohio Citizens for Responsible Energy B31123 motion to reopen record on QA based on former Comstock inspector allegations of deficiencies in Facility QA program
BLOCH, P B, KLINE, J R, BRIGHT, O D Atomic Safety and Licensing Board Panel 84/01/20 Ohio Citizens for Responsible Energy 9pp 21879 155 24X Fiche 50-440, 84/01/20, 8401230403

B401240071 Confirms B40119 telcon wherein ASLB granted extension until B40127 to file applicant brief on NRC regulations & guidance applicable to Issue 16 Delay until B40203 to respond to Ohio Citizens for Responsible Energy interrogatories granted
SHIGER, M A Shaw, Pittman, Potts & Trowbridge SHIGER, M A
Cleveland Electric Illuminating Co 84/01/20 BLOCH, P B, KLINE, J R, BRIGHT, O D Atomic Safety and Licensing Board Panel 3pp 21912 315 24X Fiche 50-440, 84/01/20, 8401240071

B401240259 Order extending time until B40127 for Commission to act to review B3115 director's decision.
CHILK, B J Office of the Secretary of the Commission 84/01/20
Commissioners 1p 21910 002 24X Fiche 50-440, 84/01/20, 8401240259

B401300104 Order extending time until B40203 for Commission to act to review B3115 director's decision.
CHILK, B J Office of the Secretary of the Commission 84/01/27
Commissioners 1p 21999 184 24X Fiche 50-440, 84/01/27, 8401300104

DOCKETED ITEMS

8401310124 Brief on NRC regulations & guidance applicable to Issue 16 re reliability of four Transamerica Delaval diesel generators Certificate of Svc encl.
SHIGER, J. E. Shaw, Pittman, Potts & Trowbridge SHIGER, J. E.
Cleveland Electric Illuminating Co. 84/01/27 6pp 22022, 063 24X
Fiche: 50-440, 84/01/27, 8401310124

M. Antitrust correspondence

8401090370 Requests on behalf of City of Cleveland, OH, extension of 30 days to complete study of NRC analysis re facility DL antitrust review & provide response to directors findings
GOLDBERG, R. Goldberg, Fieldman & Letham, P. C. GOLDBERG, R.
Cleveland, OH 84/01/05 DENTON, H. R. Office of Nuclear Reactor
Regulation, Director. 1p. 21754 044. 24X Fiche 50-440, 84/01/05,
8401090370

O. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR.
FELTON, J. M. Division of Rules and Records. 83/10/20 ZAHNER, R. E.
Shaw, Pittman, Potts & Trowbridge 1p. 21744 003. 24X
Fiche: 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
Director's Office, Office of Inspection and Enforcement.
83/10/20. 134pp. 21744:004 24X Fiche: 50-000, 83/10/20,
8401060040

8401040277 Forwards IE Insp Repts 50-440/83-34 & 50-441/83-33 on 830901-1031 & notice of violation.
KNOP, R. C. Region 3, Office of Director. 83/12/12. EDELMAN, M. R.
Cleveland Electric Illuminating Co. 2pp. 21701:311. 24X
Fiche: 50-440, 83/12/12, 8401040277.

--8401040281 Notice of violation from insp on 830901-1031.
KNOP, R. C. Region 3, Office of Director. 83/12/12 2pp.
21701 313. 24X Fiche: 50-440, 83/12/12, 8401040277.

--8401040285 IE Insp Repts 50-440/83-34 & 50-441/83-33 on 830901-1031.
Noncompliance noted: failure to control handling of mat'l & equipment & failure to ensure that hoisting equipment not overloaded.
GILDNER, M. L., KONKLIN, J. E. Region 3, Office of Director.
83/12/12 5pp. 21701.315. 24X Fiche: 50-440, 83/12/12, 8401040277

8401050281 Forwards IE Insp Repts 50-440/83-34 & 30-19494/83-01 on 831206-09. No noncompliance noted
PAPERIELLO, C. J. Region 3, Office of Director. 83/12/21.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 21726:341
24X Fiche: 50-440, 83/12/21, 8401050281

--8401050286 IE Insp Repts 50-440/83-34 & 30-19494/83-01 on 831206-09 No noncompliance noted. Major areas inspected radiation protection program including organization & staffing, training & health physics procedures.
MILLER, D. E., GREGER, L. R. Region 3, Office of Director. 83/12/21.
5pp. 21726:343. 24X Fiche: 50-440, 83/12/21, 8401050281.

8401100401 Discusses IE Insp Repts 50-440/83-31 & 50-441/83-30 on 830822-0923 & forwards notice of violation.
NORELIUS, C. E. Division of Project & Resident Programs. 83/12/23.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 21762:153.
24X Fiche: 50-440, 83/12/23, 8401100401

--8401100416 Notice of violation from insp on 830822-0923. Violation noted: cable tray segments did not maintain required separation & seismic pipe supports/restraints not inspected per design requirements.
NORELIUS, C. E. Division of Project & Resident Programs. 83/12/23
5pp. 21762:153. 24X Fiche: 50-440, 83/12/23, 8401100401.

11230363 Forwards response to Const Appraisal Team Insp Repts 50-440/83-31 & 50-441/83-30 on 830822, 0902 & 12-23. Drywell wall designed & constructed to maintain airtight integrity or 40 yrs.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/23
KEPPLER, J. O. Region 3, Office of Director. 12pp. 21882:327. 24X
Fiche: 50-440, 83/12/23, 8401230363.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co. of New York, Inc.
124pp. 21731:166. 24X Fiche: 50-000, 83/12/28, 8312120090.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp. 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc. 122pp. 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp. 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R. Licensing Branch 2 84/01/17 SCHWENGER, A. Licensing Branch 2 21pp. 22027.009 24X Fiche: 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp. 22000 001 24X Fiche: 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp. 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401230295 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-34 & 50-441/83-33.
KNOP, R. C. Region 3, Office of Director. 84/01/18. EDELMAN, M. R. Cleveland Electric Illuminating Co. 1p. 21884:262. 24X
Fiche: 50-440, 84/01/18, 8401230295.

--8401230301 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-440/83-34 & 50-441/83-33 Corrective actions: polar crane rechecked w/certified cable, replacement strongback obtained & moisture separator assembly successfully removed
EDELMAN, M. R. Cleveland Electric Illuminating Co. 84/01/10
KNOP, R. C. Division of Project & Resident Programs. 3pp. 21884:263. 24X Fiche: 50-440, 84/01/18, 8401230295.

8401260141 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-35 & 50-441/83-34
LITTLE, W. S. Region 3, Office of Director. 84/01/20 EDELMAN, M. R. Cleveland Electric Illuminating Co. 1p. 21956 026 24X
Fiche: 50-440, 84/01/20, 8401260141

--8401260146 Responds to NRC 831214 ltr re violations noted in IE Insp Repts 50-440/83-35 & 50-441/83-34 Corrective actions: cables will be trained & supported to eliminate training radius violations & megger test will be performed.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 84/01/10.
LITTLE, W. S. Region 3, Office of Director. 3pp. 21956:027 24X
Fiche: 50-440, 84/01/20, 8401260141

B. Reportable occurrences, LERs & related correspondence

8401230280 Interim Deficiency Rept RDC 83(83) re shop welds on Power Piping Co safety-related pipe supports. Final rept delayed to 840130 to allow for determination of effects on supports & piping
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/14
KEPPLER, J. O. Region 3, Office of Director. 1p. 21884 214. 24X
Fiche: 50-440, 83/12/14, 8401230280

8401230375 Interim Deficiency Rept RDC 24(81) re lubricating oil sys defect in standby diesel generators. Installation of tubing for mod of turbocharger lubricating oil sys will be complete by Apr 1984 for Unit 1 & by Jul 1984 for Unit 2.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/15
KEPPLER, J. O. Region 3, Office of Director. 173pp. 21878 252. 24X
Fiche: 50-440, 83/12/15, 8401230375.

DOCKETED ITEMS

329

B401050326 Interim Deficiency Rept RDC 72(83) re cooling of RCIC room during LOCA Design mods will be completed by 840215 & implemented by 840531
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/21
KEPPLER, J G Region 3, Office of Director 1p 21726-360 24X
Fiche 50-440, 83/12/21, 8401050326

B401050446 Interim deficiency rept re starting air sys check valves supplied by Transamerica Delaval Initially reported on 830701 Mods could not be performed at Delaval facility Valves returned to manufacturer Final rept by 840131
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/21
KEPPLER, J G Region 3, Office of Director 1p 21729 337 24X
Fiche 50-440, 83/12/21, 8401050446

B401050509 Deficiency rept re restart of control room chiller following LOCA or loss of offsite power Design changes will be completed by 840331 & implementation completed by 840601
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/21
KEPPLER, J G Region 3, Office of Director 1p 21725 361 24X
Fiche 50-440, 83/12/21, 8401050509

B401050620 Updated final Deficiency Rept RDC 19(80) re stainless steel cladding inside containment Full suppression pool monitoring sys will be functional by 841101 for Unit 1
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/21
KEPPLER, J G Region 3, Office of Director 1p 21726 073 24X
Fiche 50-440, 83/12/21, 8401050620

B401050375 Supplemental final deficiency rept re rework associated w/ASME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc Unit 2 rework will not be completed until 840207 due to scheduling delays
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/22
KEPPLER, J G Region 3, Office of Director 1p 21731-103 24X
Fiche 50-440, 83/12/22, 8401050375

B401050402 Interim Deficiency Rept RDC 59(82) re governor drive coupling Governors returned from manufacturer for Unit 1 & rework completed Rework for Unit 2 delayed until 840501 to allow storage pending completion of other const work
EDELMAN, M R Cleveland Electric Illuminating Co 83/12/22
KEPPLER, J G Region 3, Office of Director 1p 21731 126 24X
Fiche 50-440, 83/12/22, 8401050402

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovjoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified.
BOYER, R E Transamerica Delaval, Inc. 84/01/09 Director's
Fiche 50-000, 84/01/09, 8401170186

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

B401170032 FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const.
QANULIN, R. Ohio, State of 83/09/30 Office of Administration
2pp. 21837 001 24X Fiche 50-440, 83/09/30, 8401170032

B401170034 Responds to FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const
Forward App A documents
FELTON, J. M. Division of Rules and Records 83/10/21 QANULIN, R
Ohio, State of. 3pp 21837 003 24X Fiche 50-440, 83/10/21, 8401170034

--B401180523 Recommends mgt level meeting w/util in Bethesda or caseload forecast panel site visit prior to 821231, since some review areas may have licensing impact
NOVAK, T M Assistant Director for Licensing 82/11/12
EISENHUT, D G Division of Licensing 2pp 21837, 302 24X
Fiche 50-440, 83/10/21, 8401170034

--B401170038 Discusses cancellation of 830321 Caseload Forecast Panel mgt meeting due to slip of fuel load to Dec 1984 Press release will be issued by util
STEFANO, J. J. Licensing Branch 1 83/03/08, NOVAK, T. M Assistant Director for Licensing 3pp 21837 011 24X
Fiche 50-440, 83/10/21, 8401170034

--B401170042 Info re facility const Related info encl
* Cleveland Electric Illuminating Co 83/10/21 50pp
21837: 063 24X Fiche 50-440, 83/10/21, 8401170034

--B401170044 Handwritten notes re facility const.
* Affiliation Unknown. 81/10/07 5pp. 21837 221 24X
Fiche 50-440, 83/10/21, 8401170034

--B401170048 Handwritten "Piping Status " Related info encl.
* Affiliation Unknown 79/10/31 16pp 21837 233 24X
Fiche 50-440, 83/10/21, 8401170034

--B401170051 "Progress for Perry." Related info encl
* Affiliation Unknown 79/11/13 5pp 21837 256 24X
Fiche 50-440, 83/10/21, 8401170034

B312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C B Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 17pp 22054-358 24X
Fiche 50-000, 83/12/16, 8312200154

B401190172 Requests addl info re Transamerica Delaval emergency diesel generators Response may be submitted via owners group or plant-specific rept
YOUNGBLOOD, B. J. Licensing Branch 1 83/12/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 21861 350 24X
Fiche 50-440, 83/12/28, 8401190172

B401100323 Forwards addl info per Equipment Qualification Branch Questions 270 la, ic & B consisting of tables listing principal component, safety function & safety class.
EDELMAN, M R. Cleveland Electric Illuminating Co 84/01/04 YOUNGBLOOD, B J Licensing Branch 1 42pp 21764 155 24X
Fiche 50-440, 84/01/04, 8401100323

B312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05. PALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D G Division of Licensing 84/01/05. Consolidated Edison Co of New York, Inc 16pp 21946:190. 24X
Fiche 50-000, 84/01/05, 8401050382

B401170391 Forwards "Action Plan to Resolve Addl Containment Issues (Humphrey Concerns)," constituting final rept on Mark III containment sys issues Detailed action plans & response submittal summaries encl.
EDELMAN, M R Cleveland Electric Illuminating Co, 84/01/05, YOUNGBLOOD, B J Licensing Branch 1 1p 21827 161 24X
Fiche 50-440, 84/01/05, 8401170391

--B401170396 "Action Plan to Resolve Addl Containment Issues (Humphrey Concerns)"
* Cleveland Electric Illuminating Co 83/12/29 3pp 21827 162 24X Fiche 50-440, 84/01/05, 8401170391

--B401170403 "Perry Plant-Unique Pool Swell Encroachment Study." W/four oversize figures Aperture cards are available in PDR
* General Electric Co 83/07/13 63pp 21827 165 24X
Fiche 50-440, 84/01/05, 8401170391

--B401170411 "Model Study of Perry Nuclear Power Plant Suppression Pool," final technical rept W/nine oversize drawings Aperture cards are available in PDR
* Gilbert/Commonwealth Cos 77/07/06, 127pp 21827-229 24X
Fiche 50-440, 84/01/05, 8401170391

B401090221 Generic Ltr 84-02 to all Applicants for DLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc. 18pp. 21957-267. 24X
Fiche 50-000, 84/01/06, 8401090221.

B401130451 Notification of 840207 meeting w/util in Bethesda, MD to discuss plans for detailed control room design review
STEFANO, J. J. Licensing Branch 1. 84/01/10, YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 21819, 339. 24X Fiche 50-440, 84/01/10, 8401130451.

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13. Consolidated Edison Co of New York, Inc 18pp. 21946, 174. 24X
Fiche 50-000, 84/01/13, 8401130084

DOCKETED ITEMS

E. NRC Safety Evaluation Report (SER), supp's & correspondence

8401190220 Forwards NRC evaluation finding re SER Outstanding Issue 14, "Control Sys Failures," to be incorporated in next SSER. Evaluation partially resolves issue re effects of failures of power sources, sensors or sensor impulse lines. YOUNGBLOOD, B. J. Licensing Branch 1. 84/01/10 EDELMAN, M. R. Cleveland Electric Illuminating Co. 8pp 21870 220 24X Fiche: 50-440, 84/01/10, 8401190220

Security, medical, emergency & fire protection plans

8401230389 Notifies of 840112 & 13 radiological emergency preparedness program meetings in Chicago, IL to discuss final FY84/85 emergency preparedness exercise schedule & to develop prompt alert & notification certification schedules. PAPERIELLO, C. J. Region 3, Office of Director 84/01/05 EDELMAN, M. R. Cleveland Electric Illuminating Co. 3pp. 21878-236 24X Fiche: 50-440, 84/01/05, 8401230389

840170353 Forwards NRC comments on emergency action levels of emergency plan comments should be incorporated into emergency classification & action level scheme. Response requested within 5 days. YOUNGBLOOD, B. J. Licensing Branch 1. 84/01/11 EDELMAN, M. R. Cleveland Electric Illuminating Co. 4pp. 21844 323 24X Fiche: 50-440, 84/01/11, 840170353.

Adjudicatory correspondence

840100140 Tenth set of interrogatories on diesel generators. Certificate of Svc encl. HIATT, B. L. Ohio Citizens for Responsible Energy. 83/01/06. Office of the Executive Legal Director 5pp 21760 010 24X Fiche: 50-440, 83/01/06, 840100140

84060358 Response to util answer to NRC supplemental response to Ohio Citizens for Responsible Energy 831027 motion for admission & to resubmit proposed Contention 2 re diesel generator reliability. Certificate of Svc encl. HIATT, B. L. Ohio Citizens for Responsible Energy 83/12/22 Atomic Safety and Licensing Board Panel 4pp 21741.079 24X Fiche: 50-440, 83/12/22, 8401060358

84040126 Forwards statement of Sunflower Alliance contention & specific issues raised re adequacy of offsite emergency plans. Affidavit in support of motion for summary disposition requested. JOONHEAD, G. P. Hearing Branch 4 83/12/29 PERRY, B. Federal Emergency Management Agency. 3pp 21702:061 24X Fiche: 50-440, 83/12/29, 8401040126.

840110159 Answer opposing Ohio Citizens for Responsible Energy 831208 motion to motion to reopen record on Comstock issues. ASLB could be justified in dismissing amended motion as falling outside scope of Issues 3 & 7. LABSPIEDEL, M. Shaw, Pittman, Potts & Trowbridge. LABSPIEDEL, M. Cleveland Electric Illuminating Co. 84/01/06 Atomic Safety and Licensing Board Panel. 12pp 21774-317. 24X Fiche: 50-440, 84/01/06, 840110159.

840110164 Affidavit of BC Young re termination of Johnson Controls, Inc QC Inspector R Wade. Certificate of Svc encl. YOUNG, B. C. Cleveland Electric Illuminating Co. 84/01/06. 23pp 21774-329 24X Fiche: 50-440, 84/01/06, 840110159.

840110167 Affidavit of E Riley re termination of Johnson Controls, Inc QC Inspector R Wade. Certificate of Svc encl. RILEY, E. Cleveland Electric Illuminating Co. 84/01/06. 10pp. 21774-353. 24X Fiche: 50-440, 84/01/06, 840110159.

84020421 Forwards affidavit of M Gilder, NRC resident inspector, re newspaper articles submitted by intervenor 831228 telcon w/o tel.

JOONHEAD, G. P. Hearing Branch 4. 84/01/10. BLOCH, P. B., BRIGHT, O. O., KLINE, J. R. Atomic Safety and Licensing Board Panel. 1p 21791 020 24X Fiche: 50-440, 84/01/10, 840120421

84070227 Order extending time until 840120 for Commission to act to review 831115 director's decision re Ohio Citizens for Responsible Energy request. CHILK, S. J. Office of the Secretary of the Commission. 84/01/13. Commissioners. 1p 21833.323. 24X Fiche: 50-440, 84/01/13, 84070227.

84030333 Brief on regulations & guidance applicable to Issue 16 re reliability of Transamerica Delaval diesel generators. Util to prove generator compliance w/NRC regulations & stds on place generators. Certificate of Svc encl. HIATT, B. L. Ohio Citizens for Responsible Energy. 84/01/16 Atomic Safety and Licensing Board Panel. 16pp 21920.308. 24X Fiche: 50-440, 84/01/16, 8401240333.

8401230403 Memorandum & Order LBP-84-3, denying Ohio Citizens for Responsible Energy 831123 motion to reopen record on GA based on former Comstock inspector allegations of deficiencies in Facility QA program. BLOCH, P. B., KLINE, J. R., BRIGHT, O. O. Atomic Safety and Licensing Board Panel 84/01/20 Ohio Citizens for Responsible Energy 9pp 21879 155 24X Fiche: 50-440, 84/01/20, 8401230403

8401240071 Confirms 840119 telcon wherein ASLB granted extension until 840127 to file applicant brief on NRC regulations & guidance applicable to Issue 16 Delay until 840208 to respond to Ohio Citizens for Responsible Energy interrogatories granted. SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. SWIGER, M. A. Cleveland Electric Illuminating Co. 84/01/20 BLOCH, P. B., KLINE, J. R., BRIGHT, O. O. Atomic Safety and Licensing Board Panel 3pp 21912 315 24X Fiche: 50-440, 84/01/20, 8401240071

8401240259 Order extending time until 840127 for Commission to act to review 831115 director's decision. CHILK, S. J. Office of the Secretary of the Commission 84/01/20 Commissioners. 1p 21910 002 24X Fiche: 50-440, 84/01/20, 8401240259

8401300104 Order extending time until 840203 for Commission to act to review 831115 director's decision. CHILK, S. J. Office of the Secretary of the Commission 84/01/27 Commissioners. 1p 21999 184 24X Fiche: 50-440, 84/01/27, 8401300104.

8401310124 Brief on NRC regulations & guidance applicable to Issue 16 re reliability of four Transamerica Delaval diesel generators. Certificate of Svc encl. SWIGER, J. E. Shaw, Pittman, Potts & Trowbridge. SWIGER, J. E. Cleveland Electric Illuminating Co. 84/01/27 6pp 22022 063 24X Fiche: 50-440, 84/01/27, 8401310124

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR. FELTON, J. M. Division of Rules and Records 83/10/20. ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge. 1p 21744 003 24X Fiche: 50-000, 83/10/20, 8401060040

--8401060150 List of SALP results during 1982 * Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744.004 24X Fiche: 50-000, 83/10/20, 8401060040.

8401040277 Forwards IE Insp Repts 50-440/83-34 & 50-441/83-33 on 830901-1031 & notice of violation. KNOPF, R. C. Region 3, Office of Director 83/12/12 EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp 21701-311 24X Fiche: 50-440, 83/12/12, 8401040277

--8401040285 IE Insp Repts 50-440/83-34 & 50-441/83-33 on 830901-1031 Noncompliance noted: failure to control handling of mail & equipment & failure to ensure that hoisting equipment not overloaded. GILDNER, M. L., KONKLIN, J. E. Region 3, Office of Director 83/12/12 5pp 21701:315 24X Fiche: 50-440, 83/12/12, 8401040277

8401100401 Discusses IE Insp Repts 50-440/83-31 & 50-441/83-30 on 830822-0923 & forwards notice of violation. NORELUS, C. E. Division of Project & Resident Programs 83/12/23 EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp 21762 153 24X Fiche: 50-440, 83/12/23, 8401100401.

--8401100416 Notice of violation from insp on 830822-0923 Violation noted: cable tray segments did not maintain required separation & seismic pipe supports/restraints not inspected per design requirements. NORELUS, C. E. Division of Project & Resident Programs 83/12/23 5pp. 21762.155 24X Fiche: 50-440, 83/12/23, 8401100401

8401230365 Forwards response to Const Appraisal Team Insp Repts 50-440/83-31 & 50-441/83-30 on 830822, 0902 & 12-23 Drywell wall designed & constructed to maintain leaktight integrity for 40 yrs. EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/23 KEPLER, J. G. Region 3, Office of Director. 12pp. 21882 327. 24X Fiche: 50-440, 83/12/23, 8401230365.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731-166 24X Fiche: 50-000, 83/12/28, 8312120090

DOCKETED ITEMS

331

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R. Licensing Branch 2 84/01/17 SCHWENGER, A. Licensing Branch 2. 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp. 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401230295 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-34 & 50-441/83-33
KNOPF, R. C. Region 3, Office of Director 84/01/18, EDELMAN, M. R. Cleveland Electric Illuminating Co 1p 21884:262 24X Fiche 50-440, 84/01/18, 8401230295

--8401230301 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-440/83-34 & 50-441/83-33 Corrective actions, polar crane recabled w/certified cable, replacement strongback obtained & moisture separator assembly successfully removed
EDELMAN, M. R. Cleveland Electric Illuminating Co. 84/01/10
KNOPF, R. C. Division of Project & Resident Programs 5pp 21884.263 24X Fiche 50-440, 84/01/18, 8401230295

8401260141 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-35 & 50-441/83-34
LITTLE, W. S. Region 3, Office of Director 84/01/20 EDELMAN, M. R. Cleveland Electric Illuminating Co 1p. 21956 026 24X Fiche 50-440, 84/01/20, 8401260141

--8401260146 Responds to NRC 831214 ltr re violations noted in IE Insp Repts 50-440/83-35 & 50-441/83-34 Corrective actions, cables will be trained & supported to eliminate training radius violations & megger test will be performed.
EDELMAN, M. R. Cleveland Electric Illuminating Co 84/01/10
LITTLE, W. S. Region 3, Office of Director 3pp 21956:027. 24X Fiche: 50-440, 84/01/20, 8401260141

B Reportable occurrences, LERs & related correspondence

8401230280 Interim Deficiency Rept RDC 83(83) re shop welds on Power Piping Co safety-related pipe supports. Final rept delayed to 840130 to allow for determination of effects on supports & piping.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/14
KEPPLER, J. G. Region 3, Office of Director. 1p. 21884 214. 24X Fiche 50-440, 83/12/14, 8401230280

8401230375 Interim Deficiency Rept RDC 24(81) re lubricating oil sys defect in standby diesel generators. Installation of tubing for mod of turbocharger lubricating oil sys will be complete by Apr 1984 for Unit 1 & by Jul 1984 for Unit 2
EDELMAN, M. R. Cleveland Electric Illuminating Co 83/12/15.
KEPPLER, J. G. Region 3, Office of Director 173pp 21878 232 24X Fiche 50-440, 83/12/15, 8401230375

8401030326 Interim Deficiency Rept RDC 72(83) re cooling of RCIC room during LOCA Design mods will be completed by 840215 & implemented by 840531.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/21
KEPPLER, J. G. Region 3, Office of Director 1p 21726 360 24X Fiche 50-440, 83/12/21, 8401030326

8401030446 Interim deficiency rept re starting air sys check valves, supplied by Transamerica Delaval Initially reported on 830701 Mods could not be performed at Delaval facility. Valves returned to manufacturer. Final rept by 840131
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/21
KEPPLER, J. G. Region 3, Office of Director 1p 21729 337 24X Fiche 50-440, 83/12/21, 8401030446

8401030509 Deficiency rept re restart of control room chiller following LOCA or loss of offsite power. Design changes will be completed by 840331 & implementation completed by 840601
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/12/21
KEPPLER, J. G. Region 3, Office of Director 1p. 21725 361 24X Fiche 50-440, 83/12/21, 8401030509

8401030620 Updated final Deficiency Rept RDC 19(80) re stainless steel cladding inside containment. Full suppression pool monitoring sys will be functional by 841101 for Unit 1.
EDELMAN, M. R. Cleveland Electric Illuminating Co 83/12/21
KEPPLER, J. G. Region 3, Office of Director. 1p 21726 073 24X Fiche 50-440, 83/12/21, 8401030620

8401030375 Supplemental final deficiency rept re rework associated w/ASME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc. Unit 2 rework will not be completed until 840207 due to scheduling delays
EDELMAN, M. R. Cleveland Electric Illuminating Co 83/12/22
KEPPLER, J. G. Region 3, Office of Director. 1p 21731.103 24X Fiche 50-440, 83/12/22, 8401030375

8401030402 Interim Deficiency Rept RDC 59(82) re governor drive coupling Governors returned from manufacturer for Unit 1 & rework completed. Rework for Unit 2 delayed until 840501 to allow storage pending completion of other const work
EDELMAN, M. R. Cleveland Electric Illuminating Co 83/12/22.
KEPPLER, J. G. Region 3, Office of Director. 1p 21731 126 24X Fiche 50-440, 83/12/22, 8401030402

8401030627 Final deficiency rept re Class IE cable in engine & panel circuits failing IEEE 383 insulation flame test. Transamerica Delaval monitoring replacement. Replacement expected by 840131
EDELMAN, M. R. Cleveland Electric Illuminating Co 83/12/22
KEPPLER, J. G. Region 3, Office of Director 2pp 21726:075 24X Fiche 50-440, 83/12/22, 8401030627.

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended. Utills notified
BOYER, R. E. Transamerica Delaval, Inc 84/01/09. Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X Fiche: 50-000, 84/01/09, 8401170186.

DOCKET 50-443 BEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8401230015 Partial response to FOIA request for all 1982 BECY papers. Forwards App A documents. Remaining documents under review
FELTON, J. M. Division of Rules and Records 83/10/18 WEISS, E. R. Union of Concerned Scientists 3pp. 21960 005. 24X Fiche 50-000, 83/10/18, 8401230015

--8203300068 Discusses 820222 brief re emergency preparedness at facilities
FITZGERALD, J. A. Office of the General Counsel, BECY-82-112. 82/03/16 33pp. 21962 096. 24X Fiche: 50-000, 83/10/18, 8401230015.

8312120108 Board Notification 84-004: notifies of Chairman Dec 1983 trip to Sandia re briefing an environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D. G. Division of Licensing 84/01/05. PALLADINO, N. J. Commissioners. 2pp 21993.024. 24X Fiche: 50-000, 84/01/05, 8312120108

8401030382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CRs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D. G. Division of Licensing. 84/01/05. Consolidated Edison Co. of New York, Inc. 14pp 21946:190. 24X Fiche: 50-000, 84/01/05, 8401030382.

DOCKETED ITEMS

B40110287 Forwards qualification status listing of active mechanical components located in harsh plant environs to allow NRC to select three items for which documentation of environ qualification will be requested
DEVINCENITIS, J. Yankee Atomic Electric Co. DEVINCENITIS, J. Public Service Co. of New Hampshire. B4/01/05. KNIGHTON, Q. W. Licensing Branch 3. 7pp. 21772.254. 24X Fiche: 50-443, B4/01/05, B40110287

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D. O. Division of Licensing. B4/01/06. Consolidated Edison Co. of New York, Inc. 18pp. 21957.267. 24X Fiche: 50-000, B4/01/06, B401090221.

B401170343 Advises that "Seismological & Geological Studies, Miramichi Area, New Brunswick & Central New Hampshire" reclassified nonproprietary
DEVINCENITIS, J. Yankee Atomic Electric Co. DEVINCENITIS, J. Public Service Co. of New Hampshire. B4/01/06. KNIGHTON, Q. W. Licensing Branch 3. 3pp. 21828.360. 24X Fiche: 50-443, B4/01/06, B401170343.

B401230343 Forwards revised response to Power Sys Branch Request for Addl Info RAI 430 B1 re quality & reliability of fuel oil for emergency diesel generator operation. Rev will be incorporated into future FSAR amend.
DEVINCENITIS, J. Yankee Atomic Electric Co. DEVINCENITIS, J. Public Service Co. of New Hampshire. B4/01/06. KNIGHTON, Q. W. Licensing Branch 3. 4pp. 21883.211. 24X Fiche: 50-443, B4/01/06, B401230343

B401260494 Discusses until 831219 commitment to provide safety-grade controls & actuators for steam generator atmospheric relief valves. Mat'l cost & lack of regulatory requirement preclude upgrading Nonsafety-grade actuators will be retained
NERBER, V. Licensing Branch 3. B4/01/12. Licensing Branch 3. 2pp. 21939.325. 24X Fiche: 50-443, B4/01/12, B401260494.

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D. O. Division of Licensing. B4/01/13. Consolidated Edison Co. of New York, Inc. 18pp. 21946.174. 24X Fiche: 50-000, B4/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
HANNON, J. Division of Licensing. B4/01/17. Division of Licensing. 1p. 22000.349. 24X Fiche: 50-000, B4/01/17, B401270536

E. NRC Safety Evaluation Report (SER), suppl & correspondence

B401100207 Forwards responses to Geosciences Branch Requests for Addl Info 230.3, 230.6, 230.7, 230.8 & 230.10 & SER Outstanding Issue 3 re seismology/geology w/two oversize figures. Aperture cards are available in PDR.
DEVINCENITIS, J. Yankee Atomic Electric Co. DEVINCENITIS, J. Public Service Co. of New Hampshire. B4/01/05. KNIGHTON, Q. W. Licensing Branch 3. 72pp. 21759.284. 24X Fiche: 50-443, B4/01/05, B401100207

F. Security, medical, emergency & fire protection plans

B401120400 Forwards summary of 831109 meeting w/util at King of Prussia, PA re emergency planning, preparedness & upcoming appraisals. Meeting provided addl info re status of activities for adequate emergency preparedness program
MARTIN, T. T. Division of Engineering & Technical Programs. 83/12/29. HARRISON, R. J. Public Service Co. of New Hampshire. 4pp. 21791.107. 24X Fiche: 50-443, 83/12/29, B401120400

260509 Forwards in-progress 830726-28 audit of detailed control room design review, per NUREG-0737, Suppl 1. Requirements listed except in sys function & task analysis areas & comparison of analysis results w/control room inventory.
KNIGHTON, Q. W. Licensing Branch 3. B4/01/12. HARRISON, R. J. Public Service Co. of New Hampshire. 3pp. 21759.166. 24X Fiche: 50-443, B4/01/12, B401260509.

B401260511 "Human Factors Engineering In-Progress Audit of Detailed Control Room Design Review for Public Svc of NH."
* Human Factors Engineering Branch. B4/01/04. 55pp. 21959.169. 24X Fiche: 50-443, B4/01/12, B401260509.

01230494 Forwards "Procedures Generation Package for Seabrook Station," in response to Generic Ltr B2-33 requirements re emergency operating procedures, Rev 1 to "Westinghouse Owners Group Emergency Response Guidelines," also encl.
DEVINCENITIS, J. Yankee Atomic Electric Co. DEVINCENITIS, J. Public Service Co. of New Hampshire. B4/01/17. KNIGHTON, Q. W. Licensing Branch 3. 3pp. 21874.005. 24X Fiche: 50-443, B4/01/17, B401230494.

--B401230500 "Procedures Generation Package for Seabrook Station"
* Public Service Co. of New Hampshire. B4/01/17. 27pp. 21874.008. 24X Fiche: 50-443, B4/01/17, B401230494

--B310070199 Requests detailed description of task analyses performed to support development of Westinghouse Owners Group emergency response guidelines (ERG) & program plan for verification/validation to be performed on ERGs, Rev 1
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/09/12. SHEPPARD, J. J. Westinghouse Operating Plants Owners Group. SHEPPARD, J. J. Carolina Power & Light Co. 2pp. 21874.038. 24X Fiche: 50-443, B4/01/17, B401230494

--B401230520 Rev 0 to "Seabrook Station Writers Guide for Emergency Response Procedures"
* Westinghouse Operating Plants Owners Group. 83/10/31. 277pp. 21874.242. 24X Fiche: 50-443, B4/01/17, B401230494

G. Adjudicatory correspondence

B401030136 Forwards motion to compel supplementary answers to State of NH atty general interrogatories on Contention NH-10 re control room design
QAD, R. K. Ropes & Gray. QAD, R. K. Public Service Co. of New Hampshire. 83/12/21. Office of the Secretary of the Commission. 1p. 21682.240. 24X Fiche: 50-443, 83/12/21, B401030136

--B401030141 Motion to compel supplementary answers to State of NH atty general interrogatories on Contention NH-10 re control room design Certificate of Svc encl
QAD, R. K. Public Service Co. of New Hampshire. QAD, R. K. Ropes & Gray. 83/12/21. Atomic Safety and Licensing Board Panel. 15pp. 21682.241. 24X Fiche: 50-443, 83/12/21, B401030136

B401030109 Response to Seacoast Anti-Pollution League memorandum in support of 830926 motion to dismiss OL application & petition for late-filed contention Motion should be denied & contention excluded Certificate of Svc encl.
DIGNAN, T. Q., QAD, R. K. Public Service Co. of New Hampshire. DIGNAN, T. Q. Ropes & Gray. 83/12/27. Atomic Safety and Licensing Board Panel. 6pp. 21683.166. 24X Fiche: 50-443, 83/12/27, B401030109

B401030150 Answer opposing Atty General Bellotti petition for Commission review of ALAB-749 re disqualification of Judge Hoyt. Certificate of Svc encl
QAD, R. K. Public Service Co. of New Hampshire. QAD, R. K. Ropes & Gray. 83/12/27. Commissioners. 6pp. 21681.352. 24X Fiche: 50-443, 83/12/27, B401030150

B401050207 Grants extension to B40105 to file & serve response to ALAB 831221 order.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/12/29. Ropes & Gray. 1p. 21727.253. 24X Fiche: 50-443, 83/12/29, B401050207

B401040114 Answer opposing State of MA atty general 831215 petition for Commission review of ALAB-749 Certificate of Svc encl
LEBBY, R. P., PATTERSON, W. F. Hearing Branch 3. 83/12/30. Commissioners. 16pp. 21703.235. 24X Fiche: 50-443, 83/12/30, B401040114.

B401120193 Response opposing Seacoast Anti-Pollution League 831214 memorandum in support of League 830926 motion to dismiss OL application & for late-filed contention Movant has no right to reply to own motion. Certificate of Svc encl.
PATTERSON, W. F., LEBBY, R. P. Hearing Branch 3. B4/01/03. Atomic Safety and Licensing Board Panel. 11pp. 21793.220. 24X Fiche: 50-443, B4/01/03, B401120193

B401090272 Forwards response to ASLB 831223 order re status of deferred contentions.
QAD, R. K. Ropes & Gray. QAD, R. K. Public Service Co. of New Hampshire. B4/01/04. Office of the Secretary of the Commission. 1p. 21754.212. 24X Fiche: 50-443, B4/01/04, B401090272

--B401090281 Memorandum in response to ASLB 831223 order re status of deferred contentions Acceptance of motion to compel supplementary answers to interrogatories recommended Certificate of Svc encl
QAD, R. K. Public Service Co. of New Hampshire. QAD, R. K. Ropes & Gray. B4/01/04. Atomic Safety and Licensing Board Panel. 12pp. 21754.213. 24X Fiche: 50-443, B4/01/04, B401090272.

B401100213 Answer to applicant 831221 motion to compel supplemental answers to Atty General of NH interrogatories. State will provide response to interrogatories II-2, II-7, II-8 & II-10 within 30 days. W/Certificate of Svc. Related correspondence.
LISBEE, Q. D. New Hampshire, State of. B4/01/06. Atomic Safety and Licensing Board Panel. 4pp. 21759.251. 24X Fiche: 50-443, B4/01/06, B401100213

DOCKETED ITEMS

333

B40110171 Petition for Commission review of ALAB-751 & ALAB-757 re disqualification of Judge Hoyt Allegations should be addressed specifically Assurance of trial fairness requested Certificate of Svc encl
CURRAN, D. JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 84/01/09 Commissioners 12pp
21772 298 24X Fiche 50-443,84/01/09,840110171

B401120210 Advises that NRC takes no position on applicant B31221 motion to compel supplementary answers to interrogatories from State of NH Atty General
PATTERSON, W F Hearing Branch 3 84/01/09 HOYT, H F, HARBOUR, J, LUEBKE, E A Atomic Safety and Licensing Board Panel 2pp
21793 350 24X Fiche 50-443,84/01/09,8401120210

B401170306 Memorandum & order denying Seacoast Anti-Pollution League motions to reply to responses to motion to dismiss CL application & for admission of late-filed contentions
HOYT, H F Atomic Safety and Licensing Board Panel 84/01/13
Seacoast Anti-Pollution League 10pp 21833 227 24X
Fiche 50-443,84/01/13,8401170306

B401250222 Requests remittance of check to cover costs of reproducing B30810 ltr & accompanying SER re NRC review of Westinghouse Owners Group generic design mods to provide automatic reactor trip sys actuation
PATTERSON, W F Hearing Branch 3 84/01/16 CURRAN, D Harmon & Weiss 1p 21943 147 24X Fiche 50-443,84/01/16,8401250222

B401200105 Requests that ASLB defer ruling on applicant motion for summary disposition re manual reactor trip testing
Stipulation of withdrawal of Contention I D 2 will be filed within 2 wks
CURRAN, D Harmon & Weiss CURRAN, D New England Coalition on Nuclear Pollution 84/01/17 HOYT, H F, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 21866 353 24X
Fiche 50-443,84/01/17,8401200105

B401230382 Answer opposing New England Coalition on Nuclear Pollution petition for review of ALAB-751 & ALAB-757 Motion untimely filed & provides no new basis for arguments already rejected Certificate of Svc encl
DIGNAN, T G, GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 84/01/17 Commissioners 7pp
21879 173 24X Fiche 50-443,84/01/17,8401230382

B401230423 Response opposing CT Div of Consumer Counsel & Seacoast Anti-Pollution League request to deny renewal of CP for Unit 2 Request should be dismissed Certificate of Svc encl
DIGNAN, T G, GAD, R K Seacoast Anti-Pollution League DIGNAN, T G Ropes & Gray 84/01/17 Commissioners 6pp 21880 348 24X
Fiche 50-443,84/01/17,8401230423

B401240250 Forwards RM Beckman ltr re amend to svc list for proceeding Future correspondence re Amesbury, MA Director of Civil Defense, should be sent to M Clark
BISBEE, G D New Hampshire, State of 84/01/18 Office of the Secretary of the Commission 2pp 21910, 144. 24X
Fiche 50-443,84/01/18,8401240250

B401250218 Answer in opposition to New England Coalition on Nuclear Pollution B40109 petition for Commission review of ALAB-751 & ALAB-757 Neither disqualifying extrajudicial bias nor pervasive bias shown Certificate of Svc encl
LESSY, R P Hearing Branch 3 84/01/19 Commissioners. 15pp
21943 148 24X Fiche 50-443,84/01/19,8401250218

B401260175 Decision ALAB-758, affirming ASLB B31115 order denying JF Doherty untimely petition for leave to intervene in CL proceeding Doherty argument already rejected by ASLB
SCHOENAKER, C J Atomic Safety and Licensing Appeal Panel 84/01/24
10pp 21956 077 24X Fiche 50-443,84/01/24,8401260175

B401260219 Order extending time until B40210 for Commission to act to review ALAB-748, ALAB-749, ALAB-751 & ALAB-757
CHILK, S J Office of the Secretary of the Commission. 84/01/25
Commissioners. 1p 21956, 264 24X Fiche 50-443,84/01/25, 8401260219

B401310279 Order directing parties to refrain from addressing verbal requests to ASLB & legal or administrative staff Only written pleadings should be submitted
HOYT, H F Atomic Safety and Licensing Board Panel 84/01/27 2pp
22014, 220 24X Fiche 50-443,84/01/27,8401310279

Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982, Forwards IE notebook tabulating requested info Notebook also available in PDR.
FELTON, J M Division of Rules and Records. 83/10/20. ZAHLER, R E Shaw, Pittman, Potts & Trowbridge. 1p 21744, 003. 24X
Fiche 50-000,83/10/20,8401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche 50-000,83/10/20, 8401060040

B401100320 Ack receipt of B31102 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-443/83-12 Basis for violation predicated on ultrasonic procedure required to be proven capable of detecting flaws in geometrics
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
HARRISON, R J Public Service Co of New Hampshire 2pp
21764 198 24X Fiche 50-443,83/12/23,8401100320

--B401100328 Responds to NRC B31005 ltr re violations noted in IE Insp Rept 50-443/83-12 Corrective actions Pullman-Higgins revised ultrasonic test rept documentation providing sufficient info to permit accurate duplication of insps
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/11/02 MARTIN, T T Division of Engineering & Technical Programs 3pp 21764 200 24X
Fiche 50-443,83/12/23,8401100320

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731.166 24X Fiche 50-000,83/12/28,8312120090.

B401120400 Forwards summary of B31109 meeting w/Util at King of Prussia, PA re emergency planning, preparedness & upcoming appraisals Meeting provided addl info re status of activities for adequate emergency preparedness program
MARTIN, T T. Division of Engineering & Technical Programs 83/12/29
HARRISON, R J Public Service Co of New Hampshire. 4pp
21791.107 24X Fiche 50-443,83/12/29,8401120400

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826.060 24X Fiche 50-000,83/12/30,8312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946.053 24X Fiche 50-000,84/01/10,8312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,8312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142. 24X Fiche 50-000,84/01/16,8312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103). 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000,84/01/18,8312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/18. Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000,84/01/18,8312120117

B401300283 Forwards IE Mgt Meeting Rept 50-443/84-06 on B40105
STAROSTECKI, R Division of Project & Resident Programs 84/01/23
HARRISON, R J Public Service Co. of New Hampshire 2pp. 21997, 312. 24X Fiche 50-443,84/01/23,8401300283

--B401300286 IE Mgt Meeting Rept 50-443/84-06 on B40105, Major areas discussed, cold license operator exams
GALLO, J, BEALL, J., DUDLEY, N. Region 1, Office of Director. 84/01/17 3pp 21997, 314. 24X Fiche 50-443,84/01/23,8401300283.

DOCKETED ITEMS

B. Reportable occurrences, LERs & related correspondence

8312200113 Interim deficiency rept re status of Pullman-Higgins reexam/reevaluation program relative to suspect NDEs performed by former employee Program complete except for detailed rept of results Rept expected by 840115
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/12/02 STAROSTECKI, R. Division of Project & Resident Programs 3pp 21574 088 24X Fiche 50-443, 83/12/02, 8312200113

8401030162 Part 21 rept re adequacy of svc water & circulating water pump house structure Caused by lack of proper consideration of shrinkage effects in design of compression members Mods will be completed by 840216
KREIDER, H. O. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 83/12/22 Director's Office, Office of Inspection and Enforcement 3pp 21680 326 24X Fiche 50-443, 83/12/22, 8401030162

T. Hearing transcripts on non-antitrust matters

8401170139 Forwards statement of concerns re evacuation & decontamination of individuals in restricted area
TYE, M. J. Tufts Univ., School of Medicine 84/01/09 Commissioners, Ip. 21833, 352, 24X Fiche: 50-443, 84/01/09, 8401170139

--8401170141 Testimony of MJ Tye re evacuation & decontamination of individuals in restricted area.
TYE, M. J. Tufts Univ., School of Medicine. 84/01/09, App 21833: 353, 24X Fiche 50-443, 84/01/09, 8401170139

V. Operator Examinations

8401300283 Forwards IE Mgt Meeting Rept 50-443/84-06 on 840105
STAROSTECKI, R. Division of Project & Resident Programs. 84/01/23 HARRISON, R. J. Public Service Co. of New Hampshire 2pp 21977 312 24X Fiche: 50-443, 84/01/23, 8401300283

--8401300286 IE Mgt Meeting Rept 50-443/84-06 on 840105 Major areas discussed cold license operator exams.
GALLO, R., BEALL, J., BUDLEY, N. Region 1, Office of Director. 84/01/17, 3pp 21977: 314, 24X Fiche: 50-443, 84/01/23, 8401300283

W. 50-444 SEABROOK NUCLEAR STATION, UNIT 2Location/construction stage documents & correspondence

015 Partial response to FOIA request for all 1982 BECY papers rds App A documents. Remaining documents under Review
W. J. M. Division of Rules and Records 83/10/18, WEISS, E. R. of Concerned Scientists, 3pp. 21960 005 24X :50-000, 83/10/18, 8401250015

1300068 Discusses 820222 brief re emergency preparedness at facilities
ITZBERALD, D. J. A. Office of the General Counsel BECY-82-112, 82/03/16, 33pp 21962: 096, 24X Fiche: 50-000, 83/10/18, 8401250015.

1120108 Board Notification 84-004 notifies of Chairman Dec 1983 rpt to Sandia re briefing on environ qualification. Sandia position is that NRC environ qualification program has problems
VENHUT, D. G. Division of Licensing. 84/01/05 PALLADINO, N. J. Commissioners, 2pp 21993: 324 24X Fiche: 50-000, 84/01/05, 120108

0382 Generic Ltr 84-01 to all holders of OLs applicants for OLs 1ders of CPs for power reactors re NRC use of terms: "important to safety" & "safety-related." Svc list encl
VENHUT, D. G. Division of Licensing 84/01/05 Consolidated on Co. of New York, Inc. 16pp 21946: 190, 24X :50-000, 84/01/05, 8401050382.

110287 Forwards qualification status listing of active mechanical components located in harsh plant environs to allow NRC to select three items for which documentation of environ qualification will be requested.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 84/01/05, KNIGHTON, O. W. Licensing mch 3, 7pp, 21772: 254, 24X Fiche: 50-443, 84/01/05, 840110287.

190221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
1st encl.
VENHUT, D. G. Division of Licensing 84/01/06, Consolidated on Co. of New York, Inc. 18pp, 21957: 267, 24X :50-000, 84/01/06, 8401090221

8401170343 Advises that "Seismological & Geological Studies, Miramichi Area, New Brunswick & Central New Hampshire" reclassified nonproprietary
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 84/01/06, KNIGHTON, O. W. Licensing Branch 3 3pp 21828 360 24X Fiche 50-443, 84/01/06, 8401170343

8401230343 Forwards revised response to Power Sys Branch Request for Addl Info RAI 430 B1 re quality & reliability of fuel oil for emergency diesel generator operation Rev will be incorporated into future FSAR amend
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 84/01/06, KNIGHTON, O. W. Licensing Branch 3 4pp 21883 211 24X Fiche 50-443, 84/01/06, 8401230343

8401260494 Discusses until 831219 commitment to provide safety-grade controls & actuators for steam generator atmospheric relief valves Matl cost & lack of regulatory requirement preclude upgrading Nonsafety-grade actuators will be retained
NERBER, V. Licensing Branch 3 84/01/12 Licensing Branch 3 2pp 21959 325 24X Fiche 50-443, 84/01/12, 8401260494

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D. G. Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc. 18pp 21946 174 24X Fiche: 50-000, 84/01/13, 8401130084

E. NRC Safety Evaluation Report (SER), suppl & correspondence

8401100207 Forwards responses to Geosciences Branch Requests for Addl Info 230 3, 230, 6, 230 8 & 230 10 & SER Outstanding Issue 3 re seismology/geology W/two oversize figures
Aperture cards are available in PDR
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 84/01/05, KNIGHTON, O. W. Licensing Branch 3 72pp 21759 284 24X Fiche 50-443, 84/01/05, 8401100207

F. Security, medical, emergency & fire protection plans

8401120400 Forwards summary of 831109 meeting w/util at King of Prussia, PA re emergency planning, preparedness & upcoming appraisals Meeting provided addl info re status of activities for adequate emergency preparedness program
MARTIN, T. T. Division of Engineering & Technical Programs 83/12/29 HARRISON, R. J. Public Service Co. of New Hampshire App 21791 107 24X Fiche: 50-443, 83/12/29, 8401120400

8401260509 Forwards in-progress 830726-28 audit of detailed control room design review, per NUREG-0737, Suppl 1. Requirements satisfied except in sys function & task analysis areas & comparison of analysis results w/control room inventory
KNIGHTON, O. W. Licensing Branch 3 84/01/12 HARRISON, R. J. Public Service Co. of New Hampshire 3pp 21759 166 24X Fiche 50-443, 84/01/12, 8401260509

--8401260511 "Human Factors Engineering In-Progress Audit of Detailed Control Room Design Review for Public Svc of NH"
Human Factors Engineering Branch 84/01/04, 55pp 21959: 169 24X Fiche: 50-443, 84/01/12, 8401260509

8401230494 Forwards "Procedures Generation Package for Seabrook Station," in response to Generic Ltr 82-33 requirements re emergency operating procedures, Rev 1 to "Westinghouse Owners Group Emergency Response Guidelines," also encl
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 84/01/17, KNIGHTON, O. W. Licensing Branch 3 3pp, 21874: 008 24X Fiche: 50-443, 84/01/17, 8401230494

--8401230500 "Procedures Generation Package for Seabrook Station"
Public Service Co. of New Hampshire 84/01/17 27pp, 21874: 008 24X Fiche: 50-443, 84/01/17, 8401230494

--8401230520 Rev 0 to "Seabrook Station Writers Guide for Emergency Response Procedures,"
Westinghouse Operating Plants Owners Group. 83/10/31 277pp 21874: 242, 24X Fiche: 50-443, 84/01/17, 8401230494.

G. Adjudicatory correspondence

8401030136 Forwards motion to compel supplementary answers to State of NH atty general interrogatories on Contention NH-10 re control room design.
GAD, R. K. Rogers & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/12/21, Office of the Secretary of the Commission Ip. 21682: 240, 24X Fiche: 50-443, 83/12/21, 8401030136.

--B401030141 Motion to compel supplementary answers to State of NH atty general interrogatories on Contention NH-10 re control room design Certificate of Svc encl
GAD,R.K. Public Service Co of New Hampshire GAD,R.K. Ropes & Gray 83/12/21 Atomic Safety and Licensing Board Panel 15pp
21682 241 24X Fiche 50-443,83/12/21,B401030136

B401030109 Response to Seacoast Anti-Pollution League memorandum in support of B30926 motion to dismiss DL application & petition for late-filed contention Motion should be denied & contention excluded Certificate of Svc encl
DIGNAN,T.G., GAD,R.K. Public Service Co of New Hampshire DIGNAN,T.G. Ropes & Gray 83/12/27 Atomic Safety and Licensing Board Panel 6pp 21683 166 24X Fiche 50-443,83/12/27,B401030109

B401030150 Answer opposing Atty General Belletti petition for Commission review of ALAB-749 re disqualification of Judge Hoyt Certificate of Svc encl
GAD,H.K. Public Service Co of New Hampshire GAD,R.K. Ropes & Gray 83/12/27 Commissioners 6pp 21681 352 24X Fiche 50-443,83/12/27,B401030150

B401050207 Grants extension to B40105 to file & serve response to ALAB B31221 order
HOYT,H.F. Atomic Safety and Licensing Board Panel 83/12/29 Ropes & Gray 1p 21727 293 24X Fiche 50-443,83/12/29,B401050207

B401040114 Answer opposing State of MA atty general B31215 petition for Commission review of ALAB-749 Certificate of Svc encl
LESSY,R.P., PATTERSON,W.F. Hearing Branch 3 83/12/30 Commissioners 16pp 21703 235 24X Fiche 50-443,83/12/30,B401040114

B401120193 Response opposing Seacoast Anti-Pollution League B31214 memorandum in support of League B30926 motion to dismiss DL application & for late-filed contention Movant has no right to reply to own motion Certificate of Svc encl
PATTERSON,W.F., LESSY,R.P. Hearing Branch 3 84/01/03 Atomic Safety and Licensing Board Panel 11pp 21793 220 24X Fiche 50-443,84/01/03,B401120193

B401090272 Forwards response to ASLB B31223 order re status of deferred contentions
GAD,R.K. Ropes & Gray GAD,R.K. Public Service Co of New Hampshire 84/01/04 Office of the Secretary of the Commission 1p 21754 212 24X Fiche 50-443,84/01/04,B401090272

--B401090281 Memorandum in response to ASLB B31223 order re status of deferred contentions Acceptance of motion to compel supplementary answers to interrogatories recommended Certificate of Svc encl
GAD,R.K. Public Service Co of New Hampshire GAD,R.K. Ropes & Gray 84/01/04 Atomic Safety and Licensing Board Panel 12pp 21754 213 24X Fiche 50-443,84/01/04,B401090272

B401100213 Answer to applicant B31221 motion to compel supplemental answers to Atty General of NH interrogatories State will provide response to Interrogatories II-2,II-7,II-B & II-10 within 30 days.W/Certificate of Svc Related correspondence
BIBBEE,O.D. New Hampshire, State of 84/01/06 Atomic Safety and Licensing Board Panel 4pp 21759 231 24X Fiche 50-443,84/01/06,B401100213

B401110171 Petition for Commission review of ALAB-751 & ALAB-757 re disqualification of Judge Hoyt Allegations should be addressed specifically Assurance of trial fairness requested.Certificate of Svc encl
CURRAN,D. JORDAN,W.B. New England Coalition on Nuclear Pollution. CURRAN,D. Harmon & Weiss 84/01/09 Commissioners 12pp, 21772 29B. 24X Fiche.50-443,84/01/09,B401110171

B401120210 Advises that NRC takes no position on applicant B31221 motion to compel supplementary answers to interrogatories from State of NH Atty General
PATTERSON,W.F. Hearing Branch 3 84/01/09 HOYT,H.F., HARBOUR,J., LUEBKE,E.A. Atomic Safety and Licensing Board Panel 2pp 21793 330. 24X Fiche 50-443,84/01/09,B401120210

B401170306 Memorandum & order denying Seacoast Anti-Pollution League motions to reply to responses to motion to dismiss DL application & for admission of late-filed contentions.
HOYT,H.F. Atomic Safety and Licensing Board Panel 84/01/13 Seacoast Anti-Pollution League 10pp 21833,227. 24X Fiche. 50-443,84/01/13,B401170306

B401250222 Requests remittance of check to cover costs of reproducing B30810 ltr & accompanying BER re NRC review of Westinghouse Owners Group generic design mods to provide automatic reactor trip sys actuation.
PATTERSON,W.F. Hearing Branch 3 84/01/16 CURRAN,D. Harmon & Weiss 1p 21943 147 24X Fiche 50-443,84/01/16,B401250222

B401200105 Requests that ASLB defer ruling on applicant motion for summary disposition re manual reactor trip testing
Stipulation of withdrawal of Contention I D.2 will be filed within 2 wks
CURRAN,D. Harmon & Weiss CURRAN,D. New England Coalition on Nuclear Pollution 84/01/17 HOYT,H.F., LUEBKE,E.A., HARBOUR,J. Atomic Safety and Licensing Board Panel 1p 21866 353 24X Fiche 50-443,84/01/17,B401200105

B401230382 Answer opposing New England Coalition on Nuclear Pollution petition for review of ALAB-751 & ALAB-757 Motion untimely filed & provides no new basis for arguments already rejected Certificate of Svc encl
DIGNAN,T.G., GAD,R.K. Public Service Co of New Hampshire DIGNAN,T.G. Ropes & Gray 84/01/17 Commissioners 7pp 21879 175 24X Fiche 50-443,84/01/17,B401230382

B401230423 Response opposing CT Div of Consumer Counsel & Seacoast Anti-Pollution League request to deny renewal of CP for Unit 2 Request should be dismissed Certificate of Svc encl
DIGNAN,T.G., GAD,R.K. Seacoast Anti-Pollution League DIGNAN,T.G. Ropes & Gray. 84/01/17 Commissioners 6pp 21880,348 24X Fiche 50-443,84/01/17,B401230423

B401240250 Forwards RM Beckman ltr re amend to svc list for proceeding Future correspondence re Amesbury,MA Director of Civil Defense,should be sent to M Clark
BIBBEE,O.D. New Hampshire, State of 84/01/18. Office of the Secretary of the Commission 2pp 21910 144 24X Fiche 50-443,84/01/18,B401240250

B401250218 Answer in opposition to New England Coalition on Nuclear Pollution B40109 petition for Commission review of ALAB-751 & ALAB-757 Neither disqualifying extrajudicial bias nor pervasive bias shown Certificate of Svc encl
LESSY,R.P. Hearing Branch 3 84/01/17 Commissioners. 15pp 21943 148 24X Fiche:50-443,84/01/17,B401250218

B401260175 Decision ALAB-758,affirming ASLB B31115 order denying JF Doherty untimely petition for leave to intervene in DL proceeding Doherty argument already rejected by ASLB
SHOENAKER,C.J. Atomic Safety and Licensing Appeal Panel 84/01/24 10pp. 21956 077 24X Fiche 50-443,84/01/24,B401260175.

B401260219 Order extending time until B40210 for Commission to act to review ALAB-748,ALAB-749, ALAB-751 & ALAB-757
CHILKOT,J. Office of the Secretary of the Commission. 84/01/25 Commissioners 1p 21956,264 24X Fiche 50-443,84/01/25,B401260219

B401310279 Order directing parties to refrain from addressing verbal requests to ASLB & legal or administrative staff. Only written pleadings should be submitted
HOYT,H.F. Atomic Safety and Licensing Board Panel. 84/01/27. 2pp 22014 220 24X Fiche 50-443,84/01/27,B401310279.

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON,J.M. Division of Rules and Records 83/10/20. ZAHLER,R.E. Shaw, Pittman, Potts & Trowbridge 1p 21744.003 24X Fiche. 50-000,83/10/20,B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744:004 24X Fiche 50-000,83/10/20,B401060040

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp. 21731:166 24X Fiche 50-000,83/12/28,B312120090,

B401120400 Forwards summary of B31109 meeting w/util at King of Prussia,PA re emergency planning,preparedness & upcoming appraisals Meeting provided addl info re status of activities for adequate emergency preparedness program.
MARTIN,T.T. Division of Engineering & Technical Programs 83/12/29. HARRISON,R.J. Public Service Co of New Hampshire. 4pp. 21791 107 24X Fiche. 50-443,83/12/29,B401120400.

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30. Consolidated Edison Co. of New York, Inc 127pp 21826.060. 24X Fiche 50-000,83/12/30,B312120093

DOCKETED ITEMS

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc. 123pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-03, "Exercise Frequency." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc. 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc. 118pp. 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc. 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

B. Reportable occurrences, LERs & related correspondence

8312200113 Interim deficiency rept re status of Pullman-Higgins
reexam/reevaluation program relative to suspect NDEs
performed by former employee Program complete except for
detailed rept of results Rept expected by 840115.
DEVINCENTIS, J Yankee Atomic Electric Co. DEVINCENTIS, J Public
Service Co. of New Hampshire 83/12/02 STAROSTECKI, R Division of
Project & Resident Programs. 3pp. 21574 088 24X
Fiche 50-443, 83/12/02, 8312200113.

8401030162 Part 21 rept re adequacy of svc water & circulating water
pump house structure. Caused by lack of proper consideration
of shrinkage effects in design of compression members. Mode
will be completed by 840216
KREIDER, H Q United Engineers & Constructors, Inc (subs of
Raytheon Co.). 83/12/22. Director's Office, Office of Inspection
and Enforcement. 3pp 21680 326 24X Fiche 50-443, 83/12/22,
8401030162

T. Hearing transcripts on non-antitrust matters

8401170139 Forwards statement of concerns re evacuation &
decontamination of individuals in restricted area
TYE, M J Tufts Univ, School of Medicine. 84/01/09
Commissioners 1p 21833 352 24X Fiche 50-443, 84/01/09,
8401170139

--8401170141 Testimony of MJ Tye re evacuation & decontamination of
individuals in restricted area
TYE, M J Tufts Univ, School of Medicine. 84/01/09 4pp.
21833 353 24X Fiche 50-443, 84/01/09, 8401170139.

DOCKET 50-443 COMANCHE PEAK STEAM ELECTRIC BTA, UNIT 1

A. Application/construction stage documents & correspondence

8401230515 Responds to 830722 ltr commenting on proposed methodology
for calibr of effluent radiation monitors. Two addl
functional check sources will be provided for RD-32 & RD-33
effluent detectors.
CLEMEN, B R Texas Utilities Generating Co 83/08/29 MADSEN, G L.
Region 4, Office of Director 1p. 21878 220. 24X
Fiche 50-443, 83/08/29, 8401230515

8312200154 Forwards response to nine Users Group questions presented at
831130 meeting & forwarded by R Caruso 831129 ltr re standby
diesel generators at nuclear power plants.
MATHEWS, C B Transamerica Delaval, Inc. 83/12/16. NOVAK, T M.
Assistant Director for Licensing. 19pp. 22054 358. 24X
Fiche 50-000, 83/12/16, 8312200154

401040239 Outlines procedures for reporting info promptly to region
by using given telephone numbers for ofc & outside-of-ofc
hours. Util urged to use numbers
COLLINS, J T Region 4, Office of Director. 83/12/19. GARY, R J
Texas Utilities Generating Co. 2pp 21701 154. 24X
Fiche 50-443, 83/12/19, 8401040239.

8401030205 Forwards revised pages from Chapter 17 I of FSAR, Amend 44,
reflecting QA program description change Rev does not
reduce util commitments nor QA program effectiveness
GARY, R J Texas Utilities Generating Co 83/12/22 COLLINS, J T
Region 4, Office of Director 6pp 21683 093 24X
Fiche 50-443, 83/12/22, 8401030205

8401050274 Agrees to submit amend to application for OL to reflect
amend to CPs by 840127, per NRC request
SCHMIDT, H C Texas Utilities Services, Inc 83/12/22.
YOUNGBLOOD, B J Division of Licensing 1p 21727 174 24X
Fiche 50-443, 83/12/22, 8401050274

8401060087 Forwards request for addl info re independent assessment
program rept for facility
PARTLOW, J Q Division of QA, Safeguards & Inspection Programs (Post
830103) 83/12/27 YOUNGBLOOD, B J Licensing Branch 1 2pp
21747 129 24X Fiche 50-443, 83/12/27, 8401060087

8401190111 Requests addl info re Transamerica Delaval emergency diesel
generators. Response may be submitted via owners group or
plant-specific rept
YOUNGBLOOD, B J Licensing Branch 1 83/12/28 GARY, R J Texas
Utilities Generating Co 2pp 21871 042 24X Fiche 50-443,
83/12/28, 8401190111

8401090210 Responds to 831223 request for supplemental info re
independent assessment program Manhour summary & resumes of
project personnel not included in program plan encl
WILLIAMS, N H Cygnus Energy Services 83/12/29 BURWELL, S NRC -
No Detailed Affiliation Given SCHMIDT, H Westinghouse Electric
Corp. 23pp 21750 331. 24X Fiche 50-443, 83/12/29, 8401090210

8401100394 Forwards addl info re TMI Item II F 2, "Instrumentation for
Detection of Inadequate Core Cooling" & justification for
proposed implementation schedule for heated junction
thermocouple sys
GARY, R J Texas Utilities Generating Co 84/01/03 YOUNGBLOOD, B J
Licensing Branch 1 37pp 21762 183 24X Fiche 50-443, 84/01/03,
8401100394

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983
trip to Sandia re briefing on environ qualification Sandia
position is that NRC environ qualification program has
problems.
EISENHUT, D Q Division of Licensing 84/01/05 PALLADINO, N J
Commissioners. 2pp 21993 324 24X Fiche 50-000, 84/01/05,
8312120108.

8401030382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related." Svc list encl
EISENHUT, D Q Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc. 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401030382

8401100349 Provides addl details & clarifications to 830913 ltr re
high/moderate energy pipe break analysis Local control
station relocated to prevent damage from flooding All high
energy lines designed to seismic Category 1 requirements
SCHMIDT, H C Texas Utilities Generating Co 84/01/05
YOUNGBLOOD, B J Licensing Branch 1 2pp 21764 109 24X
Fiche 50-443, 84/01/05, 8401100349

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D Q Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc. 18pp 21957 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401190140 Confirms 831223 telcon w/H Schmidt, N Williams, T Witting &
SB Burwell. SB Burwell requested addl info re independent
assessment program performed by Cygnus Reviews scheduled for
wk of 840116
YOUNGBLOOD, B J Licensing Branch 1 84/01/09 GARY, R J Texas
Utilities Generating Co. 3pp. 21871 014 24X Fiche 50-443,
84/01/09, 8401190140.

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for OLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues."
Svc list encl
EISENHUT, D Q Division of Licensing. 84/01/13 Consolidated
Edison Co. of New York, Inc. 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084.

8401250252 Forwards NRC 840109 ltr to util documenting 831223 telcon
wherein NRC requested addl info on Cygnus rept conclusions
Future correspondence will be forwarded
MIZUNO, S B Hearing Branch 1 84/01/13. BLOCH, P B, JORDAN, W H,
MCCOLLUM, K A Atomic Safety and Licensing Board Panel. 69pp
21943 231. 24X Fiche 50-443, 84/01/13, 8401250252

DOCKETED ITEMS

337

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNOON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, B4/01/17, B401270536

B401270409 Informs that RP Denise will replace J Gagliardo as Region IV Director, Div of Resident, Reactor Project & Engineering Programs, effective 840122
COLLINS, J T Region 4, Office of Director 84/01/23 GARY, R J Texas Utilities Generating Co 2pp 21981 057 24X Fiche 50-445, B4/01/23, B401270409

B401310330 Forwards proposed Amend 3 to OL application Amend reflects recent organizational changes previously approved by Amend 7 to CP
GARY, R J Texas Utilities Generating Co 84/01/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22020 236 24X Fiche 50-445, B4/01/26, B401310330

--B401310332 Proposed Amend 3 to OL application, reflecting recent organizational changes
* Texas Utilities Generating Co * Texas Municipal Power Agency
* Brazos Electric Power Cooperative, Inc 84/01/26 27pp 22020 238 24X Fiche 50-445, B4/01/26, B401310330

B401190008 Board Notification B4-017 forwards evaluation findings of possible impact of large earthquake associated w/Hears Fault
NOVAK, T M Assistant Director for Licensing 84/01/27 Atomic Safety and Licensing Board Panel 4pp 22018 047 24X Fiche 50-000, B4/01/27, B401190008

D NRC Draft/Final Environmental Statements, supp's & correspondence

B401270428 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNIT NOS 1 AND 2 Docket Nos 50-445 And 50-446 (Texas Utilities Generating Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0775 81/09/30 160pp 22001 143 24X Fiche 50-445, B1/09/30, B401270428

E NRC Safety Evaluation Report (SER), supp's & correspondence

B312090111 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket Nos 50-445 And 50-446 (Texas Utilities Generating Company, et al)
* Division of Licensing NUREG-0797 804, 83/11/30 65pp Available at NRC 84 23 21447 200 24X Fiche 50-445, B3/11/30, B312090111

F Security, medical, emergency & fire protection plans

B401300034 Forwards upgraded figures for physical security plan Figures withheld (ref 10CFR73 21)
GARY, R J Texas Utilities Generating Co, 84/01/23 DENTON, H Office of Nuclear Reactor Regulation, Director. 1p 21999, 263 24X Fiche: 50-445, B4/01/23, B401300034

G Adjudicatory correspondence

B401030126 Forwards two footnotes inadvertently omitted from B31223 response to util identification of issues & proposal to establish hearing schedule
ELLIS, J Citizens Association for Sound Energy 83/12/26, BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 21681 358 24X Fiche 50-445, B3/12/26, B401030126

--B401030133 Revised Pages 19 & 20 of B31223 response to util identification of issues & proposal to establish hearing schedule Two inadvertently omitted footnotes encl
* Citizens Association for Sound Energy, 83/12/26, Atomic Safety and Licensing Board Panel 2pp 21681 360, 24X Fiche 50-445, B3/12/26, B401030126.

B401030173 Answer supporting NRC B31213 motion to reopen record to admit JR Rajan Affidavit re stress calculations Affidavit should be admitted for limited purpose of supporting J Doyle statements Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/12/26, Atomic Safety and Licensing Board Panel 6pp, 21681 324, 24X Fiche: 50-445, B3/12/26, B401030173

B401030277 Memorandum & order responding to scheduling concerns & clarifying B31023 order re QA procedure
BLOCH, P B Atomic Safety and Licensing Board Panel 84/01/03 8pp 21727: 232 24X Fiche 50-445, B4/01/03, B401030277

B401040360 Memorializes B40102 conversation re extension of time to respond to ASLB B31228 memorandum & order due to death in family Responses to Item 6, Page 3, should be sent by B40109
ELLIS, J Citizens Association for Sound Energy 84/01/03 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 1p 21741 166 24X Fiche 50-445, B4/01/03, B401040360

B401120332 Forwards Region IV B31222 ltr transmitting notice of violation & proposed imposition of civil penalty & IE Insp Repts 50-445/B3-50 & 50-446/B3-24 re QC inspector intimidation w/o encls
MIZUNO, G S Hearing Branch 1 84/01/03 BLOCH, P B, MCCOLLUM, K A, JORDAN, W H Atomic Safety and Licensing Board Panel 1p 21792 207 24X Fiche 50-445, B4/01/03, B401120332

B401110302 Proposed schedule for next hearing session, tentatively scheduled to begin on B40207 Certificate of Svc encl
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds 84/01/09 5pp 21772 267 24X Fiche 50-445, B4/01/09, B401110302

B401120245 Notifies ASLB & parties that NRC will not be prepared to present direct testimony on matters at B40207 hearing session
MIZUNO, G S Hearing Branch 1 84/01/09 BLOCH, P B, MCCOLLUM, K A, JORDAN, W H Atomic Safety and Licensing Board Panel 1p, 21793 263 24X Fiche 50-445, B4/01/09, B401120245

B401130106 Proposed schedule for next hearing session, per ASLB B31228 order Hearing on open welding issues proposed for B40221-24 & 0227-0302, Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 84/01/09 11pp 21802 303 24X Fiche 50-445, B4/01/09, B401130106

B401250327 Advises that DELD will transmit any relevant investigation repts & accompanying affidavits to ASLB DELD will assist in determining relevant matl
CUNNINGHAM, G H Office of the Executive Legal Director, 84/01/12 HAYES, B D Office of Investigation 1p 21944 209 24X Fiche 50-445, B4/01/12, B401250327

B401170300 Motion for reconsideration of ASLB B31228 & B40103 memoranda & orders re procedures for "show-&-tell" site visit by witnesses to identify specific deficiencies & firing of QC Inspector Certificate of Svc encl.
ELLIS, J Citizens Association for Sound Energy 84/01/13 Atomic Safety and Licensing Board Panel 11pp 21832 350 24X Fiche 50-445, B4/01/13, B401170300.

B401230180 Advises that NRC will not file motions for reconsideration of ASLB B31228 memorandum & order (first scheduling order) & B40103 memorandum & order (second scheduling order) NRC response to intervenor B31223 filing to be submitted B40130
MIZUNO, G S Hearing Branch 1 84/01/13 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 2pp 21935 212 24X Fiche 50-445, B4/01/13, B401230180

B401250252 Forwards NRC B40109 ltr to util documenting B31223 telcon wherein NRC requested addl info on Cygna rept conclusions Future correspondence will be forwarded
MIZUNO, G S Hearing Branch 1 84/01/13 BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing Board Panel 69pp 21943 251 24X Fiche 50-445, B4/01/13, B401250252

B401190188 Clarification of B31223 response to applicant identification of issues & proposal to establish hearing schedule. Clarification not intended as summary of case. Certificate of Svc encl.
ELLIS, J Citizens Association for Sound Energy 84/01/16, 9pp 21851 295 24X Fiche 50-445, B4/01/16, B401190188

B401190283 Motion for reconsideration of ASLB B31228 memorandum & order re intervenor allegations on QA for pipe support design Applicant presented no citations that require rebuttal Summary of QA program & Certificate of Svc encl.
REYNOLDS, N S, HORIN, W A Texas Utilities Generating Co, REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds 84/01/17, Atomic Safety and Licensing Board Panel. 67pp 21850: 001, 24X Fiche 50-445, B4/01/17, B401190283

B401240204 Motion for reconsideration of ASLB B31228 memorandum & order re QA for design Cygna should be excluded from consideration as organization to conduct independent design review based on established ties w/util Certificate of Svc encl.
ELLIS, J Citizens Association for Sound Energy 84/01/17 Atomic Safety and Licensing Board Panel 6pp 21908 256 24X Fiche: 50-445, B4/01/17, B401240204

B401250177 Motion for reconsideration of ASLB B31228 memorandum & order re design QA Order should reflect staff position that 10CFR50, App B relevant to design Certificate of Svc encl
MIZUNO, G S Hearing Branch 1 84/01/17 Atomic Safety and Licensing Board Panel 6pp, 21937 118 24X Fiche 50-445, B4/01/17, B401250177

DOCKETED ITEMS

8401200148 Notice of evidentiary hearings in Feb - May 1983 in Fort Worth, TX re OL application
BLOGH, P B Atomic Safety and Licensing Board Panel 84/01/18 1p
21865 357. 24X Fiche 50-445, 84/01/18, 8401200148

8401300244 Answer opposing Citizens Assoc for Sound Energy (CASE) motion for reconsideration of scheduling orders ASLE should cease further efforts to allow CASE to conduct discovery through in situ insp Certificate of Svc encl
REYNOLDS, N B, MORIN, W. A. Texas Utilities Generating Co
REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds 84/01/26
Atomic Safety and Licensing Board Panel 11pp 22062 102 24X
Fiche 50-445, 84/01/26, 8401300244.

8401310222 Memorandum LBP-84-B on adequacy of records & sys of retrieving & utilizing const deficiency records Findings preliminary & may not be referenced as authority for filings or motions for reconsideration.
BLOGH, P B, JORDAN, M H, MCCOLLUM, K A. Atomic Safety and Licensing Board Panel 84/01/30 5pp 22021:283 24X Fiche 50-445, 84/01/30, 8401310222.

H. General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Svc lists should be revised accordingly.
REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds. 84/01/19.
CLEMENTS, W. L. Docketing & Services Branch 2pp. 21919:361. 24X
Fiche 50-000, 84/01/19, 8401240335

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982. Forwards IE notebook tabulating requested info Notebook also available in PDR.
FELTON, J. H. Division of Rules and Records 83/10/20 ZAHNER, R. E Shaw, Pittman, Potts & Trowbridge. 1p 21744:003. 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982.
* Director's Office, Office of Inspection and Enforcement.
83/10/20 134pp 21744:004. 24X Fiche 50-000, 83/10/20, 8401060040

8401040491 Forwards IE Insp Rept 50-445/83-38 on 830926-29. No violations noted
JOHNSON, E. H. Region 4, Office of Director 83/11/16 GARY, R. J Texas Utilities Generating Co. 2pp 21707:160. 24X
Fiche 50-445, 83/11/16, 8401040491.

--8401040499 IE Insp Rept 50-445/83-38 on 830926-29. No violations noted Major areas inspected: records & completed installation, safety-related instrumentation & review of nonconformance repts re instrumentation
BESS, J. E., MULLIKIN, R. P., HUNNICUTT, D. Region 4, Office of Director. 83/11/10. 4pp 21707:162 24X Fiche 50-445, 83/11/10, 8401040499

8401170384 Confirms extension of response to IE Bulletin 83-06 until 831230. Extension approved by 831117 telcon Review of purchase records identifying Tube-Line Corp matls not completed
GARY, R. J Texas Utilities Generating Co. 83/11/21 COLLINS, J. T Region 4, Office of Director. 1p. 21829:042. 24X
Fiche 50-445, 83/11/21, 8401170384.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731:166. 24X Fiche 50-000, 83/12/28, 8312120090.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30. Consolidated Edison Co. of New York, Inc. 127pp. 21826:060. 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946:053. 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10. Consolidated Edison Co. of New York, Inc. 122pp. 21826:184. 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957:142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utls & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSD, R Licensing Branch 2 84/01/17 SCHWENCER, A Licensing Branch 2 21pp 22027:009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000:001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000:041 24X Fiche 50-000, 84/01/18, 8312120117

8312120132 Board Notification 83-196 informs ASLB that NRC initiated special insp on 831107 into two allegations re facility coatings program insp should be completed by Mar 1984
NOVAK, T. H Assistant Director for Licensing 84/01/18 Atomic Safety and Licensing Board Panel. 2pp 21940:189 24X
Fiche 50-445, 84/01/18, 8312120132

8401270316 Forwards response to 831222 notice of violation & proposed imposition of civil penalty Requests enforcement action & proposed civil penalty be withdrawn since legal std NRC applied seems unclear
GARY, R. J Texas Utilities Generating Co 84/01/23 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement 33pp 21951:012. 24X Fiche 50-445, 84/01/23, 8401270316

B Reportable occurrences, LERs & related correspondence

8401100004 Deficiency Rept 8401-123 re Barton recommended calibr checks for Westinghouse supplied pressure transmitters Revised setpoint will be incorporated into equipment list for pressurizer pressure safety injection sys by 840601
GARY, R. J Texas Utilities Generating Co 83/12/28 JOHNSON, E. H Region 4, Office of Director 2pp 21761:206 24X
Fiche 50-445, 83/12/28, 8401100004

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utls notified
BOYER, R. E. Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement. 3pp. 21828:269 24X
Fiche 50-000, 84/01/09, 8401170186

8401270275 Interim Deficiency Rept 8401-124 re installation of chlorine sensors not conforming to QDC 4.5 & 19, FSAR commitments to Reg Guides 1.7B & 1.95 & NUREG-0737, Item III D 3.4. Sensor relocated & mods to provide adequate calibr instituted.
GARY, R. J Texas Utilities Generating Co 84/01/18 JOHNSON, E. H Region 4, Office of Director 3pp 21976:007 24X
Fiche 50-445, 84/01/18, 8401270275

8312120157 Board Notification 84-015 on 840116, licensee reported potential 10CFR50.55(a) deficiency re reinsp program for paint applied to inner wall of containment liner. Calibr data not properly applied as evaluation of test results
NOVAK, T. M Assistant Director for Licensing 84/01/23 Atomic Safety and Licensing Board Panel 2pp 21940:191 24X
Fiche 50-445, 84/01/23, 8312120157

--8401250237 Discusses proposed board notification re potential 10CFR50.55(a) rept on quality of coating applied to inner wall of containment liner before Oct 1981 Calibr data used in reinsp improperly applied
COLLINS, J. T. Region 4, Office of Director 84/01/18 EISENHUT, D. G Division of Licensing 2pp 21940:193. 24X
Fiche 50-445, 84/01/23, 8312120157

--8401250243 Submits addl info for proposed board notification on Contention 5 re failure to adhere to GA provisions in concrete work, mortar blocks, steel, fracture toughness; welding, insp & testing of matls
WESTERMAN, T. F Region 4, Office of Director. 84/01/06 EIDSON, O Office of Nuclear Reactor Regulation, Director 3pp. 21940:193 24X
Fiche 50-445, 84/01/23, 8312120157

DOCKETED ITEMS

339

3 Hearing transcripts on non-antitrust matters

B401160150 Transcript of B40112 conference call in Bethesda, MD
Pp 9, 207-9, 256
* Atomic Safety and Licensing Board Panel B4/01/12 50pp
21814, 264 24X Fiche 50-445, B4/01/12, B401160150

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

A Application/construction stage documents & correspondence

B401230515 Responds to B30722 ltr commenting on proposed methodology
for calibr of effluent radiation monitors Two addl
functional check sources will be provided for RD-52 & RD-33
effluent detectors
CLEHENTS, B R Texas Utilities Generating Co B3/08/29 MADSEN, G L
Region 4, Office of Director ip 21878 220 24X
Fiche 50-445, B3/08/29, B401230515

B312200154 Forwards response to nine Users Group questions presented at
B31130 meeting & forwarded by R Caruso B31129 ltr re standby
diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc B3/12/16 NOVAK, T M
Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, B3/12/16, B312200154

B401040239 Outlines procedures for reporting info promptly to region
by using given telephone numbers for ofc & outside-of-ofc
hours Util urged to use numbers
COLLINS, J T Region 4, Office of Director B3/12/19 GARY, R J
Texas Utilities Generating Co 2pp 21701 154 24X
Fiche 50-445, B3/12/19, B401040239

B401030205 Forwards revised pages from Chapter 17 1 of FSAR, Amend 44,
reflecting GA program description change Rev does not
reduce util commitments nor GA program effectiveness
GARY, R J Texas Utilities Generating Co B3/12/22 COLLINS, J T
Region 4, Office of Director 6pp 21683 093. 24X
Fiche, 50-445, B3/12/22, B401030205

B401050274 Agrees to submit amend to application for DL to reflect
amend to CPs by B40127, per NRC request
SCHMIDT, H C Texas Utilities Services, Inc B3/12/22
YOUNGBLOOD, B J Division of Licensing ip 21727 174 24X
Fiche 50-445, B3/12/22, B401050274

B401190111 Requests addl info re Transamerica Delaval emergency diesel
generators Response may be submitted via owners group or
plant-specific rept
YOUNGBLOOD, B J Licensing Branch 1 B3/12/28 GARY, R J Texas
Utilities Generating Co 2pp 21871 042 24X Fiche 50-445,
B3/12/28, B401190111

B401090210 Responds to B31223 request for supplemental info re
independent assessment program Manhour summary & resumes of
project personnel not included in program plan encl
WILLIAMS, N H Cygna Energy Services B3/12/29 BURWELL, S NRC -
No Detailed Appylation Given SCHMIDT, H Westinghouse Electric
Corp. 23pp 21750 331 24X Fiche 50-445, B3/12/29, B401090210

B401100394 Forwards addl info re TMI Item II F.2, "Instrumentation for
Detection of Inadequate Core Cooling" & justification for
proposed implementation schedule for heated junction
thermocouple sys
GARY, R J Texas Utilities Generating Co. B4/01/03 YOUNGBLOOD, B J
Licensing Branch 1 37pp 21762 183 24X Fiche 50-445, B4/01/03,
B401100394

B312120108 Board Notification B4-004 notifies of Chairman Dec 1983
trip to Sandia re briefing on environ qualification. Sandia
position is that NRC environ qualification program has
problems
EISENHUT, D O Division of Licensing B4/01/03 PALLADINO, N J
Commissioners 2pp, 21993 324 24X Fiche 50-000, B4/01/03,
B312120108

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs
& holders of CPs for power reactors re NRC use of terms,
"Important to safety" & "safety-related" Svc list encl.
EISENHUT, D O Division of Licensing B4/01/03 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, B4/01/03, B401050382

B401100349 Provides addl details & clarifications to B30913 ltr re
high/moderate energy pipe break analysis Local control
station relocated to prevent damage from flooding. All high
energy lines designed to seismic Category I requirements
SCHMIDT, H C Texas Utilities Generating Co B4/01/03
YOUNGBLOOD, J A Licensing Branch 1, 2pp, 21764; 109. 24X
Fiche 50-445, B4/01/03, B401100349

B401130084 Generic Ltr B4-03 to all licensees of operating reactors,
applicants for DLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing B4/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, B4/01/13, B401130084

B401250252 Forwards NRC B40109 ltr to util documenting B31223 telcon
wherein NRC requested addl info on Cygna rept conclusions
Future correspondence will be forwarded.
MIZUND, G S Hearing Branch 1 B4/01/13 BLOCH, P B Atomic Safety
& Licensing Board Panel 69pp 21943 281. 24X
Fiche 50-445, B4/01/13, B401250252

B401270336 Notification of B40126 meeting w/DL applicants in Bethesda,
MD to discuss limited operational experience on operating
crews & development of acceptable experience profile for
new plants
HANNON, J Division of Licensing B4/01/17 Division of
Licensing ip 22000 349 24X Fiche 50-000, B4/01/17, B401270336

B401270409 Informs that RP Denise will replace J Gagliardo as Region IV
Director, Div of Resident Reactor Project & Engineering
Programs, effective B40122
COLLINS, J T Region 4, Office of Director B4/01/23 GARY, R J
Texas Utilities Generating Co 2pp 21981 037 24X
Fiche 50-445, B4/01/23, B401270409

B401310330 Forwards proposed Amend 3 to DL application Amend reflects
recent organizational changes previously approved by Amend 7
to CP
GARY, R J Texas Utilities Generating Co. B4/01/26 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 22020 236
24X Fiche 50-445, B4/01/26, B401310330

--B401310332 Proposed Amend 3 to DL application, reflecting recent
organizational changes.
* Texas Utilities Generating Co * Texas Municipal Power Agency
* Brazos Electric Power Cooperative, Inc B4/01/26 27pp
22020 238 24X Fiche: 50-445, B4/01/26, B401310330

B401190008 Board Notification B4-017 forwards evaluation findings of
possible impact of large earthquake associated w/Heers
Fault
NOVAK, T M Assistant Director for Licensing B4/01/27 Atomic
Safety and Licensing Board Panel 4pp 22018 047 24X
Fiche 50-000, B4/01/27, B401190008

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing. B4/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, B4/01/06, B401090221

D NRC Draft/Final Environmental Statements, supp & correspondence

B401270428 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT NOS 1 AND 2
Docket Nos 50-445 And 50-446 (Texas Utilities Generating
Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0775
B1/09/30 160pp 22001 143. 24X Fiche: 50-445, B1/09/30, B401270428

E NRC Safety Evaluation Report (SER), supp & correspondence

B312090111 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF
COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 Docket
Nos 50-445 And 50-446 (Texas Utilities Generating Company,
et al)
* Division of Licensing NUREG-0797 B04 B3/11/30 65pp
Available at NRC. \$4.25 21447 200. 24X Fiche: 50-445, B3/11/30,
B312090111

F. Security, medical, emergency & fire protection plans

B401300034 Forwards upgraded figures for physical security plan Figures
withheld (ref 10CFR73.21)
GARY, R J Texas Utilities Generating Co B4/01/23, DENTON, H.
Office of Nuclear Reactor Regulation, Director. ip. 21999; 263. 24X
Fiche 50-445, B4/01/23, B401300034.

G Adjudicatory correspondence

B401030126 Forwards two footnotes inadvertently omitted from B31223
response to util identification of issues & proposal to
establish hearing schedule
ELLIS, J Citizens Association for Sound Energy B3/12/26.
BLOCH, P B, JORDAN, W H, MCCOLLUM, K A Atomic Safety and Licensing
Board Panel ip. 21681 358. 24X Fiche: 50-445, B3/12/26, B401030126.

DOCKETED ITEMS

--8401030133 Revised Pages 19 & 20 of 831223 response to util identification of issues & proposal to establish hearing schedule Two inadvertently omitted footnotes encl
* Citizens Association for Sound Energy 83/12/26 Atomic
Safety and Licensing Board Panel 2pp 21681 360 24X
Fiche 50-445, 83/12/26, 8401030134

8401030175 Answer supporting NRC 831213 motion to reopen record to admit JR Rajan affidavit re stress calculations. Affidavit should be admitted for limited purpose of supporting J Doyle statements Certificate of Svc encl
ELLIS, J. Citizens Association for Sound Energy. 83/12/26 Atomic
Safety and Licensing Board Panel 6pp. 21681 324 24X
Fiche 50-445, 83/12/26, 8401030175

8401030277 Memorandum & order responding to scheduling concerns & clarifying 831025 order re GA procedure
BLOCH, P. B. Atomic Safety and Licensing Board Panel 84/01/03. 8pp
21727. 232. 24X Fiche: 50-445, 84/01/03, 8401030277

8401060360 Memorializes 840102 conversation re extension of time to respond to ASLB 831228 memorandum & order due to death in Family. Responses to Item 6, Page 3, should be sent by 840109
ELLIS, J. Citizens Association for Sound Energy. 84/01/03
BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel 1p 21741: 166. 24X Fiche: 50-445, 84/01/03, 8401060360

8401120332 Forwards Region IV 831222 ltr transmitting notice of violation & proposed imposition of civil penalty & IE Insp
Reps 50-445/83-50 & 50-446/83-24 re QC inspector
Intimidation. W/o encl
MIZUNO, O. S. Hearing Branch 1. 84/01/03. BLOCH, P. B., MCCOLLUM, K. A., JORDAN, W. H. Atomic Safety and Licensing Board Panel 1p.
21792: 207. 24X Fiche: 50-445, 84/01/03, 8401120332.

8401110302 Proposed schedule for next hearing session tentatively scheduled to begin on 840207. Certificate of Svc encl
REYNOLDS, N. S. Texas Utilities Generating Co. REYNOLDS, N. S. Bishop, Liberman, Cook, Purcell & Reynolds. 84/01/09. 8pp. 21772: 267. 24X
Fiche: 50-445, 84/01/09, 8401110302

8401120245 Notifies ASLB & parties that NRC will not be prepared to present direct testimony on matters at 840207 hearing session.
MIZUNO, O. S. Hearing Branch 1. 84/01/09. BLOCH, P. B., MCCOLLUM, K. A., JORDAN, W. H. Atomic Safety and Licensing Board Panel. 1p.
21793: 263. 24X Fiche: 50-445, 84/01/09, 8401120245.

8401130106 Proposed schedule for next hearing session per ASLB 831228 order Hearing on open welding issues proposed for 840221-24 & 0227-0302 Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy 84/01/09. 11pp.
21802: 305. 24X Fiche: 50-445, 84/01/09, 8401130106

8401230327 Advises that CELD will transmit any relevant investigation reports & accompanying affidavits to ASLB. CELD will assist in determining relevant matl
CUNNINGHAM, G. H. Office of the Executive Legal Director. 84/01/12.
HAYES, S. B. Office of Investigation. 1p 21944 209. 24X
Fiche: 50-445, 84/01/12, 8401230327

8401170300 Motion for reconsideration of ASLB 831228 & 840103 memoranda & orders re procedures for "show-&-tell" site visit by witnesses to identify specific deficiencies & firing of QC inspector. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy 84/01/13. Atomic
Safety and Licensing Board Panel 11pp. 21832 350 24X
Fiche: 50-445, 84/01/13, 8401170300

8401250180 Advises that NRC will not file motions for reconsideration of ASLB 831228 memorandum & order (first scheduling order) & 840103 memorandum & order (second scheduling order). NRC response to intervenor 831223 filing to be submitted 840130.
MIZUNO, O. S. Hearing Branch 1. 84/01/13 BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel. 2pp.
21935: 212. 24X Fiche: 50-445, 84/01/13, 8401250180.

8401250252 Forwards NRC 840109 ltr to util documenting 831223 telcon wherein NRC requested addl info on Cygra rept conclusions. Future correspondence will be forwarded.
MIZUNO, O. S. Hearing Branch 1 84/01/13. BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel. 69pp.
21943. 251. 24X Fiche: 50-445, 84/01/13, 8401250252.

8401190188 Clarification of 831223 response to applicant identification of issues & proposal to establish hearing schedule Clarification not intended as summary of case. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 84/01/16 9pp.
21851: 295. 24X Fiche: 50-445, 84/01/16, 8401190188

8401190283 Motion for reconsideration of ASLB 831228 memorandum & order re intervenor allegations on GA for pipe support design Applicant presented no citations that require rebuttal Summary of GA program & Certificate of Svc encl
REYNOLDS, N. S., HORIN, W. A. Texas Utilities Generating Co. REYNOLDS, N. S. Bishop, Liberman, Cook, Purcell & Reynolds 84/01/17
Atomic Safety and Licensing Board Panel 67pp 21850 001 24X
Fiche: 50-445, 84/01/17, 8401190283

8401240204 Motion for reconsideration of ASLB 831228 memorandum & order re GA for design Cygra should be excluded from consideration as organization to conduct independent design review based on established ties w/ util Certificate of Svc encl
ELLIS, J. Citizens Association for Sound Energy. 84/01/17 Atomic
Safety and Licensing Board Panel 6pp 21908 256 24X
Fiche 50-445, 84/01/17, 8401240204

8401250177 Motion for reconsideration of ASLB 831228 memorandum & order re design GA Order should reflect staff position that 10CFR50, App B relevant to design Certificate of Svc encl
MIZUNO, O. S. Hearing Branch 1 84/01/17 Atomic Safety and Licensing Board Panel 6pp 21937 118 24X Fiche 50-445, 84/01/17, 8401250177

8401200148 Notice of evidentiary hearings in Feb - May 1983 in Fort Worth, TX re QL application
BLOCH, P. B. Atomic Safety and Licensing Board Panel 84/01/18 1p
21865: 357. 24X Fiche 50-445, 84/01/18, 8401200148

8401300244 Answer opposing Citizens Assoc for Sound Energy (CASE) motion for reconsideration of scheduling orders ASLB should cease further efforts to allow CASE to conduct discovery through in situ insp Certificate of Svc encl
REYNOLDS, N. S., HORIN, W. A. Texas Utilities Generating Co. REYNOLDS, N. S. Bishop, Liberman, Cook, Purcell & Reynolds 84/01/26
Atomic Safety and Licensing Board Panel 11pp 22062 102 24X
Fiche: 50-445, 84/01/26, 8401300244

8401310222 Memorandum LBP-84-B on adequacy of records & sys of retrieving & utilizing const deficiency records Findings preliminary & may not be referenced as authority for filings or motions for reconsideration
BLOCH, P. B., JORDAN, W. H., MCCOLLUM, K. A. Atomic Safety and Licensing Board Panel 84/01/30 8pp 22021 283 24X Fiche: 50-445, 84/01/30, 8401310222

H. General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds. Svc lists should be revised accordingly
REYNOLDS, N. S. Bishop, Liberman, Cook, Purcell & Reynolds 84/01/19
CLEMENS, W. L. Docketing & Services Branch 2pp 21919 361. 24X
Fiche: 50-000, 84/01/19, 8401240335

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/20 ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche: 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement
83/10/20 124pp 21744 004 24X Fiche: 50-000, 83/10/20, 8401060040

8401170384 Confirms extension of response to IE Bulletin 83-06 until 831230. Extension approved by 831117 telcon Review of purchase records identifying Tube-Line Corp matls not completed
GARV, R. J. Texas Utilities Generating Co 83/11/21 COLLINS, J. Y. Region 4, Office of Director 1p 21829 042. 24X
Fiche: 50-445, 83/11/21, 8401170384

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp. 21731: 166 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp. 21826: 060. 24X Fiche: 50-000, 83/12/30, 8312120093

DOCKETED ITEMS

341

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B401300028 Notification of B40126 meeting w/utls & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R Licensing Branch 2 84/01/17 SCHWENCER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, B401300028

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

B312120132 Board Notification B3-196 informs ASLB that NRC initiated special insp on B31107 into two allegations re facility coatings program Insp should be completed by Mar 1984.
NOVAK, T M Assistant Director for Licensing 84/01/18 Atomic Safety and Licensing Board Panel 2pp 21940 189 24X Fiche 50-445, 84/01/18, B312120132

B401270316 Forwards response to B31222 notice of violation & proposed imposition of civil penalty Requests enforcement action & proposed civil penalty be withdrawn since legal std NRC applied seems unclear
OARV, R J Texas Utilities Generating Co 84/01/23 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 33pp 21981 012 24X Fiche 50-445, 84/01/23, B401270316

S Reportable occurrences, LERS & related correspondence

B401100004 Deficiency Rept BDAR-123 re Barton recommended calibr checks for Westinghouse supplied pressure transmitters Revised setpoint will be incorporated into equipment list for pressurizer pressure safety injection sys by B40601
OARV, R J Texas Utilities Generating Co 83/12/28 JOHNSON, E H Region 4, Office of Director 2pp 21761 206 24X Fiche: 50-445, 83/12/28, B401100004

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended Utills notified.
B DYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828, 269, 24X Fiche 50-000, 84/01/09, B401170186

B401230410 Deficiency rept re linear indications in emergency diesel generator auxiliary skids Skids will be scrapped Replacement structures will be fabricated at jobsite per site engineering drawings by Sept 1984
OARV, R J Texas Utilities Generating Co 84/01/10, JOHNSON, E H Region 4, Office of Director 2pp 21880 342 24X Fiche: 50-446, 84/01/10, B401230410

B401270275 Interim Deficiency Rept BDAR-124 re installation of chlorine sensors not conforming to ODC 4.5 & 19.FSAR commitments to Reg Guides 1.78 & 1.93 & NUREG-0737, Item III D.3.4 Sensor relocated & mods to provide adequate calibr instituted.
OARV, R J Texas Utilities Generating Co 84/01/18, JOHNSON, E H Region 4, Office of Director 3pp 21976 007 24X Fiche: 50-445, 84/01/18, B401270275

B312120157 Board Notification B4-015, on B40116, licensee reported potential 10CFR50.55(a) deficiency re rainsp program for paint applied to inner wall of containment liner Calibr data not properly applied as evaluation of test results
NOVAK, T M Assistant Director for Licensing 84/01/23 Atomic Safety and Licensing Board Panel 2pp 21940.191 24X Fiche: 50-445, 84/01/23, B312120157.

--B401250243 Submits addl info for proposed board notification on Contention 3 re failure to adhere to QA provisions in concrete work, mortar blocks, steel fracture toughness, welding, insp & testing of matls
WESTERMAN, T F Region 4, Office of Director 84/01/06 EDISON, O Office of Nuclear Reactor Regulation, Director 6pp 21940 195 24X Fiche 50-445, 84/01/23, B312120157

T Hearing transcripts on non-antitrust matters

B401160150 Transcript of B40112 conference call in Bethesda, MD Pp 9, 207-9, 256
* Atomic Safety and Licensing Board Panel 84/01/12, 50pp 21814 264 24X Fiche: 50-445, 84/01/12, B401160150

DOCKET STN-50-447 QESSAR-23B

A Application/construction stage documents & correspondence

B401110265 Forwards proprietary draft "QESSAR II Seismic Event Uncertainty Analysis " Formal amend will be submitted in early 1984 Draft rept withheld (ref 10CFR2 790) Affidavit encl.
QUIRK, J F General Electric Co 83/12/29 EISENHUT, D G Division of Licensing, 5pp 21790 320, 24X Fiche 50-447, 83/12/29, B401110265

B401250030 Forwards, for approval, proposed QESSAR II severe accident review schedule Schedule includes consideration of external events in PRA & use of new source term SER issuance delayed until B40715
MIRAGLIA, F J Assistant Director for Safety Assessment 84/01/11 EISENHUT, D G, Division of Licensing 2pp 21947 361 24X Fiche 50-447, 84/01/11, B401250030

B401240523 Forwards proprietary info supporting QESSAR II seismic fragility analysis requested at B40109 & 10 meetings in San Jose, CA info withheld (ref 10CFR2 790)
QUIRK, J F General Electric Co 84/01/19 THOMAS, C O Standardization & Special Projects Branch 5pp, 21917, 100, 24X Fiche 50-447, 84/01/19, B401240523

B401300147 Forwards proprietary request for addl info re severe accident review of QESSAR II Request withheld
THOMAS, C O Standardization & Special Projects Branch 84/01/26 SHERWOOD, G O General Electric Co 1p 21999 167 24X Fiche 50-447, 84/01/26, B401300147

D. Advisory Committee on Reactor Safeguards reports & correspondence

B401160376 Summary of ACRB Air Sys Subcommittee B30923 meeting in Washington, DC re review of QESSAR II design relative to control room habitability & overview of QE BWR suppression pool scrubbing program
* ACRB - Advisory Committee on Reactor Safeguards 83/11/09, ACRB - Advisory Committee on Reactor Safeguards 16pp 21824 232 24X Fiche 50-447, 83/11/09, B401160376

DOCKET STN-50-454 BYRON STATION, UNIT 1

A. Application/construction stage documents & correspondence

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants.
MAYHEWS, C B Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22054:358 24X Fiche: 50-000, 83/12/16, B312200154

B401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR.
TRAMM, T R Commonwealth Edison Co, 83/12/20, DENTON, H R, Office of Nuclear Reactor Regulation, Director 8pp, 21751, 246 24X Fiche 50-000, 83/12/20, B401090223

B401030351 Advises that plans for interim operation of HVAC sys, described in B31027 ltr, acceptable
YOUNGBLOOD, B J Licensing Branch 1 83/12/22, FARRAR, D L, Commonwealth Edison Co 2pp, 21695, 340 24X Fiche, 50-454, 83/12/22, B401030351

B401100479 Requests issuance of OLs for full term of 40 yrs from date of issuance, per Atomic Energy Act & NEPA
TRAMM, T R Commonwealth Edison Co 83/12/28, DENTON, H R, Office of Nuclear Reactor Regulation, Director 5pp, 21761:233, 24X Fiche 50-000, 83/12/28, B401100479.

DOCKETED ITEMS

B401050346 Forwards applicant B31216 ltr re changes to Byron steam generators to minimize flow-induced vibration. Ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes.
GALLLO, J. Isham, Lincoln & Beale 83/12/30 SMITH, I W Atomic Safety and Licensing Board Panel 28pp 21731 066 24X
Fiche: 50-000, 83/12/30, B401050346

B401100311 Forwards list of safety-related mechanical equipment denoting environ qualification & explanation of qualification established for all balance-of-plant equipment on list except for eight valves
TRAHM, T R Commonwealth Edison Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 23pp 21738 243. 24X
Fiche: 50-000, 83/12/30, B401100311

B401100162 Forwards advance copy of revised response to FSAR Question 040.94 re emergency diesel generator vibration Response will be incorporated in next FSAR amend
TRAHM, T R Commonwealth Edison Co. 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 21760.165. 24X
Fiche 50-000, 84/01/03, B401100162

B401100362 Forwards revised temp limits for reactor vessel, per amend to App Q to 10CFR50. Only cooldown curves for Byron Unit 1 & Braidwood Unit 2 must be changed to incorporate new closure flange limitations
TRAHM, T.R. Commonwealth Edison Co 84/01/03 DENTON, H.R Office of Nuclear Reactor Regulation, Director. 4pp. 21763 357. 24X
Fiche 50-000, 84/01/03, B401100362.

B312120108 Board Notification B4-004, notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems.
EISENHUT, D.O Division of Licensing. 84/01/03 PALLADINO, N J, Commissioners. 2pp. 21793 324 24X Fiche 50-000, 84/01/03, 8312120108.

B401050382 Generic Ltr B4-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl.
EISENHUT, D.O. Division of Licensing 84/01/03 Consolidated Edison Co of New York, Inc 16pp 21746 190 24X
Fiche 50-000, 84/01/03, B401050382

B401100265 Submits supplemental info re periodic training for rad/chem technicians for post-accident sampling procedures Special retraining will be completed at least every 6 months
TRAHM, T.R Commonwealth Edison Co. 84/01/03, DENTON, H.R Office of Nuclear Reactor Regulation, Director. 2pp 21759; 200. 24X
Fiche: 50-000, 84/01/03, B401100265

B401100276 Submits addl info re emergency operating procedures used during initial operation Verification & validation of current emergency operating procedures completed during wk of 831226, utilizing 14 accident scenarios.
TRAHM, T.R. Commonwealth Edison Co. 84/01/03 DENTON, H.R Office of Nuclear Reactor Regulation, Director. 2pp 21772-252. 24X
Fiche: 50-454, 84/01/03, B401100276.

B401090221 Generic Ltr B4-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D.O Division of Licensing. 84/01/06 Consolidated Edison Co. of New York, Inc. 18pp. 21757 267. 24X
Fiche: 50-000, 84/01/06, B401090221.

B401100303 Forwards rpts to certain human engineering deficiencies contained in util B30809 ltr re control room preliminary design assessment along w/Suppl I & II in response to NUREG-0660 & Section 18 of SER, Byron BSR Item 17 closed.
SWARTZ, E.D Commonwealth Edison Co 84/01/06. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 28pp. 21799.305 24X
Fiche: 50-000, 84/01/06, B401100303.

B401160314 Advises of changes to plan for completion of some preoperational tests. Delays in completion of tests due to variety of design, delivery & installation problems. Listing of min sys for each milestone condition encl
TRAHM, T.R. Commonwealth Edison Co. 84/01/06. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 12pp. 21814.081. 24X
Fiche: 50-454, 84/01/06, B401160314.

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl
EISENHUT, D.O. Division of Licensing. 84/01/13. Consolidated Edison Co. of New York, Inc. 18pp. 21946:174. 24X
Fiche: 50-000, 84/01/13, B401130084

B401190350 Confirms B40119 meeting w/util at Region III ofc, Glen Ellyn, IL to discuss open items requiring resolution prior to fuel loading.
NORELIUS, C.E Division of Project & Resident Programs 84/01/13
REED, C Commonwealth Edison Co 1p 21890 330 24X
Fiche 50-454, 84/01/13, B401190350

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401240255 Forwards memo re B40117 meeting w/util Memo should be sent to parties in DL proceeding & placed in docket file
MANNING, W J Commissioners 84/01/20 CHILK, S J Office of the Secretary of the Commission 1p 21910 003 24X
Fiche 50-454, 84/01/20, B401240255

---B401240261 Summary of B40117 meeting w/util re DL proceeding.
MANNING, W J Commissioners 84/01/20 Commissioners 4pp 21910 004. 24X Fiche 50-454, 84/01/20, B401240255

B401250205 Summary of B40117 meeting w/Comm Ed re ASLB B40113 initial decision to deny application for DL on basis of inadequate GA
CUNNINGHAM, O H Office of the Executive Legal Director 84/01/20
DIRKS, W J., ROE, J W Office of the Executive Director for Operations. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 4pp. 21943 173 24X Fiche 50-454, 84/01/20, B401250205

E NRC Safety Evaluation Report (SER), supp's & correspondence

B312120186 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BYRON STATION, UNITS 1 & 2 Docket Nos STN 50-454 And STN 50-455 (Commonwealth Edison Company)
* Division of Licensing NUREG-0876 S03 83/11/30 31pp Available at NRC. #3 75. 21511 100 24X Fiche 50-454, 83/11/30, B312120186

B401100181 Forwards Tables CET-1 & CET-2 which provide point-by-point evaluation of inadequate core cooling instrumentation, per NUREG-0737, Item II, F 2 Info supp's B30208 response to Question 8 of NRC B21027 ltr SER Outstanding Item 9 closed
TRAHM, T R Commonwealth Edison Co. 83/12/27. DENTON, H R Office of Nuclear Reactor Regulation, Director. 6pp. 21760 345 24X
Fiche. 50-000, 83/12/27, B401100181

B401100193 Provides addl info re NUREG-0737, Item II K 3.1, "Isolation & Testing of Automatic PORV Isolation Sys." to close out SER Confirmatory Issue 28, Automatic PORV isolation unnecessary, based on Westinghouse Owners Group study
TRAHM, T.R. Commonwealth Edison Co. 83/12/27 DENTON, H.R Office of Nuclear Reactor Regulation, Director. 1p 21759 279 24X
Fiche. 50-000, 83/12/27, B401100193.

B401060180 Provides addl info re adequacy of pressurizer relief & safety valves Info closes confirmatory issue in Section 3 9.3 3 of SER Safety functions of safety & relief valve piping network for NUREG-0737, Item II D.1 satisfied.
TRAHM, T.R Commonwealth Edison Co. 83/12/30 DENTON, H.R Office of Nuclear Reactor Regulation, Director 3pp 21739.166. 24X
Fiche 50-000, 83/12/30, B401060180

B401060204 Forwards revised FSAR pages providing addl info re monitoring of leakage from sys outside containment, satisfying concern in NUREG-0737, Item III D.1.1 Info should close Byron SER Confirmatory Issue 28(a).
TRAHM, T.R Commonwealth Edison Co. 83/12/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 21739 169 24X
Fiche. 50-000, 83/12/30, B401060204

B401100433 Provides addl info re auxiliary bldg vent noble gas effluent monitors, to complete review of instrumentation as documented in Byron SER.
TRAHM, T.R Commonwealth Edison Co. 83/12/30. DENTON, H.R Office of Nuclear Reactor Regulation, Director 1p 21762 167. 24X
Fiche: 50-000, 83/12/30, B401100433.

B401100347 Provides justification for interim operation (JIO) for several items of electrical equipment for which environ testing will be incomplete at time of fuel load for Byron Unit 1. Review of JIO necessary to close SER Item 10
TRAHM, T.R. Commonwealth Edison Co 84/01/05. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 32pp 21764.034 24X
Fiche: 50-000, 84/01/05, B401100347

DOCKETED ITEMS

343

B401160260 Forwards addl info re accuracy & sensitivity of analytical procedures & online instrumentation to be used for post-accident analysis of reactor coolant info supports generic review of procedures in SER Section 9.3.2
TRAMM, T R Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 21814 170 24X
Fiche 50-454, 84/01/05, B401160260

B401190192 Forwards SER (NUREG-0876) for Byron in support of ACRS review of Braidwood SER W/o encl
NOVAK, T M Assistant Director for Licensing 84/01/05
ESERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 1p 21870 021 24X Fiche 50-454, 84/01/05, B401190192

B401130303 Forwards revs to certain human engineering deficiencies contained in util 830509 ltr re control room preliminary design assessment along w/Supplis I & II in response to NUREG-0660 & Section 18 of SER Byron BSR Item 17 closed
SWARTZ, E D Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 28pp 21799 305 24X
Fiche 50-000, 84/01/06, B401130303

F Security, medical, emergency & fire protection plans

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (VAV) plan & criteria for parameter selection Implementation will vary at each facility
SWARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 83/12/29, B401030229

B401060170 Forwards Rev 10 to security plan Rev addresses vitalization of essential svc water sys cooling towers Rev withheld (ref 10CFR73.21)
FARRAR, D L Commonwealth Edison Co 83/12/30 Office of Nuclear Reactor Regulation, Director 1p 21739 225 24X
Fiche 50-454, 83/12/30, B401060170

B401100428 Forwards IE Safeguards Insp Rept 50-454/83-59 on 831212-16 No noncompliance noted
AXELSON, W L Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 2pp 21762 160 24X Fiche 50-454, 84/01/05, B401100428

--B401100434 IE Safeguards Insp Rept 50-454/83-59 on 831212-16. No noncompliance noted Major areas inspected implementation of training & qualification plan for security force Details withheld (ref 10CFR73.21)
BELANGER, J L, STAPLETON, B W, CREED, J R Region 3, Office of Director 84/01/05 2pp 21762 162 24X Fiche 50-454, 84/01/05, B401100428

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at D'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed.
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, B401230491

B401260178 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21982 346 24X Fiche 50-454, 84/01/18, B401260178

B401250042 Releases public version of revised emergency plan procedures
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21947 320 24X Fiche 50-454, 84/01/20, B401250042

--B401250047 Public version of Rev 0 to Emergency Plan Implementing Procedure B2P 380-3, "Post-Accident Vent Stack Sampling of Wide-Range Gas Monitor" & Rev 0 to B2P 380-6, "Radiological Precautions for Sample Analysis"
* Commonwealth Edison Co 83/12/07 10pp 21947 321 24X
Fiche 50-454, 84/01/20, B401250042

B401260287 Releases public version of emergency plan implementing procedure.
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21992 310 24X Fiche 50-454, 84/01/20, B401260287

--B401260287 Public version of Rev 1 to Emergency Plan Implementing Procedure B2P 300-T8, "Checklist - Environ Monitoring Supplies"
* Commonwealth Edison Co 83/11/04 5pp 21992 311 24X
Fiche 50-454, 84/01/20, B401260287

B401260403 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document Management Branch 1p 21959 278 24X Fiche 50-454, 84/01/20, B401260403

--B401260407 Public version of Rev 2 to Emergency Plan Implementing Procedure B2P 300-T4, "Byron Station First Aid Kit Inventory"
* Commonwealth Edison Co 83/12/20 2pp 21959 279 24X
Fiche 50-454, 84/01/20, B401260403

Q Adjudicatory correspondence

B401040189 Forwards IE Insp Repts 50-454/83-39 & 50-455/83-29 re reinsp program discussed at 830808-12 hearings. W/o encl
RAWSON, R J Hearing Branch 4 83/12/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 21702 078 24X Fiche 50-454, 83/12/30, B401040189

B401050366 Forwards applicant 831216 ltr re changes to Byron steam generators to minimize flow-induced vibration ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
CALLD, J Isham, Lincoln & Seale, CALLD, J Consumers Power Co 83/12/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 28pp 21731 066 24X Fiche 50-000, 83/12/30, B401050366

B401120231 Forwards IE Insp Rept 50-454/83-37, per ASLB request to be provided w/all Region III insps performed as part of reinsp program.
YOUNG, M A Hearing Branch 4 84/01/05 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 16pp 21794 056 24X Fiche 50-454, 84/01/05, B401120231

B401100215 Response opposing intervenor motion to reopen record & for order imposing commitments re GA/QC issues Issues do not warrant reopening record
BECKER, B D Commonwealth Edison Co BECKER, B D, Isham, Lincoln & Seale 84/01/06 Atomic Safety and Licensing Board Panel 10pp 21739 255 24X Fiche 50-454, 84/01/06, B401100215

--B401100219 Affidavit of L DelGeorge re reinsp program. Certificate of Bvc encl
DELGEORGE, L Commonwealth Edison Co 84/01/06 6pp 21759 265 24X Fiche 50-454, 84/01/06, B401100215

B401100466 Addendum to petition for emergency relief per 10CFR2.206 re integrated leak rate testing. All documentation re integrated leak rate tests must be made public
OOGOL, E M Affiliation Unknown 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21761 286 24X
Fiche 50-000, 84/01/06, B401100466

B401250078 Forwards NRC response to intervenor motion to reopen record & for order imposing commitments & affidavit of DW Hayes & KA Connaughton
YOUNG, M A Hearing Branch 4 84/01/11 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 21939 258 24X Fiche 50-454, 84/01/11, B401250078

--B401250083 Response opposing intervenor motion to reopen record & order imposing commitments Three events upon which motion grounded do not support issuance of order requiring applicant & staff to honor commitments
YOUNG, M A Hearing Branch 4 84/01/11 Atomic Safety and Licensing Board Panel 13pp 21939 259 24X
Fiche 50-454, 84/01/11, B401250078

--B401250087 Affidavit of DW Hayes & KA Connaughton supporting NRC opposition to intervenor motion to reopen record on GA/QC issues & for order imposing commitments. Certificate of Bvc encl
HAYES, D W, CONNAUGHTON, K Division of Project & Resident Programs 84/01/10 12pp 21939 272 24X Fiche 50-454, 84/01/11, B401250078

B401230439 Initial Decision LWP-84-2, withholding authorization for OL because of failures in GA program
SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 84/01/13 417pp 21881 001 24X Fiche 50-454, 84/01/13, B401230439

B401250208 Forwards IE Insp Repts 50-454/83-37 & 50-455/83-40 of preoperational radiation protection program Repts may be relevant to Rockford League of Women Voters Contentions 42, 111 & 112 re ALARA
RAWSON, R J Hearing Branch 4 84/01/13 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 1p 21943 163 24X Fiche 50-454, 84/01/13, B401250208

DOCKETED ITEMS

8401300221 Forwards summary of 840117 meeting w/util re ASLB 840113 initial decision denying DL
CUNNINGHAM, G H. Office of the Executive Legal Director 84/01/20.
DIRCKS, W J. Office of the Executive Director for Operations
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 4pp. 22062:118 24X Fiche 50-454, 84/01/20, 8401300221

8401250201 Notice of appeal of ASLB 840113 Initial Decision LBP-84-2 Certificate of Svc encl.
MILLER, M I. Commonwealth Edison Co MILLER, M I Isham, Lincoln & Beale. 84/01/23 4pp. 21943:184 24X Fiche 50-454, 84/01/23, 8401250201

8401270378 Notice of appeal of ASLB 840113 initial decision Certificate of Svc encl.
WHICHER, J M. League of Women Voters of Rockford, IL WHICHER, J M DuKalb Area Alliance for Responsible Energy WHICHER, J M Safe Energy for New Haven. 84/01/23 3pp 21976:045 24X Fiche 50-454, 84/01/23, 8401270378

8401300202 Motion for expedited consideration of appeal of ASLB denial of DL Facility in final stages of const & will be ready for fuel load by 840315. Briefing schedule delineated
MILLER, M I. Commonwealth Edison Co. MILLER, M I Isham, Lincoln & Beale. 84/01/24. Atomic Safety and Licensing Appeal Panel 5pp. 21998:316. 24X Fiche: 50-454, 84/01/24, 8401300202

--8401300207 Affidavit of C Reed re const status & target fuel load dates
REED, C. Commonwealth Edison Co 84/01/24 4pp 21993:322. 24X Fiche: 50-454, 84/01/24, 8401300207

--8401300210 Affidavit of RL Heumann re costs of delay in startup & operation. Notice of appearance for PP Steptoe, notice of withdrawal of appearance for G Herrin, RO Fitzgibbons & P Murphy & Certificate of Svc encl.
HEUMANN, R L. Commonwealth Edison Co 84/01/24 11pp. 21995:326. 24X Fiche. 50-454, 84/01/24, 8401300210

8401300261 Motion for expedition of util appeal of 840113 Initial Decision LBP-84-2 re inadequate GA program ASLB should adopt intervenor proposed schedule which allows for full & fair briefing on expedited basis w/Certificate of Svc
WHICHER, J M. League of Women Voters of Rockford, IL WHICHER, J M DuKalb Area Alliance for Responsible Energy. WHICHER, J M Safe Energy for New Haven. 84/01/25 Atomic Safety and Licensing Appeal Panel. 5pp. 21998:331. 24X Fiche. 50-454, 84/01/25, 8401300261.

J. Insurance & indemnity information

8401200184 Forwards listed endorsements to NELIA Policies NF-43, 187, 201, 253 & 277 & MAELU Policies NF-22, 54, 64 & 104.
OSTER, J. Commonwealth Edison Co 84/01/09. SALTZMAN, J. Assistant Director for State & License Relations. 19pp 21863:232 24X Fiche: 50-000, 84/01/09, 8401200184.

K. Utility Final Safety Analysis Report (FSAR) & amends

8401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR.
TRAMM, T R. Commonwealth Edison Co. 83/12/20. DENTON, H R. Office of Nuclear Reactor Regulation, Director 8pp 21751:246 24X Fiche. 50-000, 83/12/20, 8401090223.

--8401090242 Amend 44 to FSAR
Commonwealth Edison Co. 83/12/31. 350pp. 21751:254 24X Fiche: 50-000, 83/12/20, 8401090223

M. Antitrust correspondence

8401090436 Forwards FR notice of finding of no significant antitrust changes & time for filing requests for reevaluation for publication.
REGAN, W H. Site Analysis Branch. 83/12/29. STUCKY, S W. Office of the Secretary of the Commission. 3pp. 21768:045. 24X Fiche: 50-454, 83/12/29, 8401090436.

--8401090442 Notice of finding of no significant antitrust changes & time for filing requests for reevaluation.
REGAN, W H. Site Analysis Branch. 83/12/29. 2pp. 21768:047. 24X Fiche: 50-454, 83/12/29, 8401090436

8401250326 Forwards FR notice & NRC review of finding no significant antitrust changes & time for filing requests for reevaluation.
REGAN, W H. Site Analysis Branch. 84/01/09. TRAMM, T R. Commonwealth Edison Co. 1p. 21957:282. 24X Fiche: 50-454, 84/01/09, 8401250326.

--8401250328 Notice of finding of no significant antitrust changes & time for filing of requests for reevaluation.
REGAN, W H. Site Analysis Branch 84/01/09 2pp. 21957:283 24X Fiche 50-454, 84/01/09, 8401250326

--8401250329 "Byron Station Unit 1 Significant Change Analysis"
NICHOLSON, P. Site Analysis Branch 84/01/09 39pp 21937:283 24X Fiche 50-454, 84/01/09, 8401250326

P. Operating license stage documents & correspondence

8401100455 Supplis 830422 response to Generic Ltr 83-10C & D. Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301
BARNES, P L. Commonwealth Edison Co 84/01/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 21761:284 24X Fiche 50-000, 84/01/04, 8401100455

Q. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M. Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p. 21744:003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744:004 24X Fiche. 50-000, 83/10/20, 8401060040

8401040533 Supplis response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements.
BARNES, P L. Commonwealth Edison Co. 83/12/20 KEPPLER, J G Region 3, Office of Director 3pp 21714:036. 24X Fiche: 50-000, 83/12/20, 8401040533

8401050418 Forwards IE Insp Repts 50-454/83-37 & 50-455/83-40 on 831128-1202. No noncompliance noted
PAPERTELLO, C J. Region 3, Office of Director 83/12/23 REED, C. Commonwealth Edison Co 2pp 21731:140 24X Fiche. 50-454, 83/12/23, 8401050418

--8401050421 IE Insp Repts 50-454/83-37 & 50-455/83-40 on 831128-1202 No noncompliance noted Major areas inspected: radiation protection procedures, respiratory protection program, NUREG-0737 items & preoperational sys demonstrations
HUTER, L J., GREGER, L R. Region 3, Office of Director 83/12/23 7pp 21731:142. 24X Fiche 50-454, 83/12/23, 8401050418.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers w/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731:166. 24X Fiche 50-000, 83/12/28, 8312120090

8401050296 Forwards IE Insp Repts 50-454/83-39 & 50-455/83-29 on 830808-1122 No noncompliance noted
LITTLE, W S. Region 3, Office of Director 83/12/28 REED, C. Commonwealth Edison Co 2pp. 21728:312. 24X Fiche: 50-454, 83/12/28, 8401050296

--8401050300 IE Insp Repts 50-454/83-39 & 50-455/83-29 on 830808-1122 No noncompliance noted Major areas inspected: previous insp findings, IE bulletins, allegations, safety-related components & structural & piping activities.
WARD, K D., CILIMBERO, R L., KEATING, D E. Region 3, Office of Director 83/12/28. 53pp. 21728:314 24X Fiche. 50-454, 83/12/28, 8401050296.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc. 127pp. 21826:060 24X Fiche. 50-000, 83/12/30, 8312120093

8401100275 Forwards response to unresolved items identified in Integrated Design Insp Rept 50-454/83-32 & addresses NRC conclusions presented in 830930 ltr
REED, C. Commonwealth Edison Co 83/12/30 DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 147pp 21758:270 24X Fiche: 50-454, 83/12/30, 8401100275

DOCKETED ITEMS

345

8401100428 Forwards IE Safeguards Insp Rept 50-454/83-59 on 831212-16 No noncompliance noted
AXELSON, W L Region 3, Office of Director 84/01/05 REED, C
Commonwealth Edison Co 2pp 21762 160 24X Fiche 50-454, 84/01/05, 8401100428

--8401100434 IE Safeguards Insp Rept 50-454/83-59 on 831212-16 No noncompliance noted Major areas inspected implementation of training & qualification plan for security force Details withheld (ref 10CFR73.21)
BELANGER, J L, STAPLETON, B W, CREED, J R Region 3, Office of Director 84/01/05 2pp 21762 162 24X Fiche 50-454, 84/01/05, 8401100428

8401120231 Forwards IE Insp Rept 50-454/83-37, per ASLB request to be provided w/all Region III insps performed as part of reinsp program
YOUNG, M A Hearing Branch 4 84/01/05 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 16pp 21794 036 24X Fiche 50-454, 84/01/05, 8401120231

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 12pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 12pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401170357 Forwards results of pump performance test & sys hydrostatic pressure test per requirements of IE Bulletin 83-05 re use of pumps & spare parts mfg by Hayward Tyler Pump Co.
BARNES, P L Commonwealth Edison Co 84/01/10 KEPLER, J Q Region 3, Office of Director 3pp 21828 348 24X Fiche 50-454, 84/01/10, 8401170357

8401190420 Provides supplemental response to IE Bulletin 83-05 re use of ASME nuclear code pumps & spare parts mfg by Hayward Tyler Pump Co Results of pump performance & hydrostatic pressure tests encl
BARNES, P L Commonwealth Edison Co 84/01/10 KEPLER, J Q Region 3, Office of Director 3pp 21850 090 24X Fiche 50-454, 84/01/10, 8401190420

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 12pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8401230303 Ack receipt of 840104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-454/83-53
STREETER, J F Region 3, Office of Director 84/01/17 REED, C
Commonwealth Edison Co. 1p 21883 333 24X Fiche 50-454, 84/01/17, 8401230303

--8401230310 Responds to NRC 831205 ltr re violations noted in IE Insp Rept 50-454/83-53 on 831108-10 & 15-23 Corrective actions
Hunter Corp QC & craft personnel will be retrained in requirements of SIP 4 000 re hardware removal forms
FARRAR, D L Commonwealth Edison Co 84/01/04 KEPLER, J Q Region 3, Office of Director 3pp 21883 334 24X Fiche 50-454, 84/01/17, 8401230303

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 11pp, 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 12pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401310386 Forwards IE Insp Repts 50-454/83-61 & 50-455/83-41 on 831101-1231 No noncompliance noted
KNOP, R C Region 3, Office of Director 84/01/20 REED, C.
Commonwealth Edison Co. 2pp 22018 025, 24X Fiche 50-454, 84/01/20, 8401310386

--8401310389 IE Insp Repts 50-454/83-61 & 50-455/83-41 on 831101-1231 No noncompliance noted Major areas inspected IE bulletin responses, preoperational test procedures, preoperational testing operations, new fuel receipt & storage
HINDS, J. M, CONNAUGHTON, K, HAYES, D W Region 3, Office of Director 84/01/20 16pp 22018 027 24X Fiche 50-454, 84/01/20, 8401310386

T Hearing transcripts on non-antitrust matters

8401120306 Memorandum & order accepting NRC proposed transcript corrections of 830808 & 0930
SMITH, I. W Atomic Safety and Licensing Board Panel 84/01/11 Office of the Executive Legal Director 1p 21792 115, 24X Fiche 50-454, 84/01/11, 8401120306

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

8401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR
TRAMM, T R Commonwealth Edison Co 83/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 21751 246 24X Fiche 50-000, 83/12/20, 8401090223

8401030351 Advises that plans for interim operation of HVAC sys, described in 831027 ltr, acceptable
YOUNGBLOOD, B Licensing Branch 1 83/12/22, FARRAR, D L Commonwealth Edison Co 2pp, 21693 340 24X Fiche 50-454, 83/12/22, 8401030351

8401100479 Requests issuance of OLs for full term of 40 yrs from date of issuance, per Atomic Energy Act & NEPA
TRAMM, T R Commonwealth Edison Co. 83/12/28 DENTON, H. R Office of Nuclear Reactor Regulation, Director 5pp 21761 233 24X Fiche 50-000, 83/12/28, 8401100479

8401050366 Forwards applicant 831216 ltr re changes to Byron steam generators to minimize flow-induced vibration ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
GALLLO, J. Isham, Lincoln & Seale 83/12/30 SMITH, I W. Atomic Safety and Licensing Board Panel. 28pp 21731 066 24X Fiche 50-000, 83/12/30, 8401050366

8401100311 Forwards list of safety-related mechanical equipment denoting environ qualification & explanation of qualification established for all balance-of-plant equipment on list except for eight valves
TRAMM, T. R. Commonwealth Edison Co 83/12/30 DENTON, H. R Office of Nuclear Reactor Regulation, Director 23pp 21758, 243 24X Fiche 50-000, 83/12/30, 8401100311

8401100162 Forwards advance copy of revised response to FSAR Question 040.94 re emergency diesel generator vibration Response will be incorporated in next FSAR amend
TRAMM, T. R. Commonwealth Edison Co 84/01/03 DENTON, H. R Office of Nuclear Reactor Regulation, Director. 3pp 21760 165 24X Fiche 50-000, 84/01/03, 8401100162

8401100362 Forwards revised temp limits for reactor vessel, per amend to App G to 10CFR50 Only cooldown curves for Byron Unit 1 & Braidwood Unit 2 must be changed to incorporate new closure flange limitations
TRAMM, T R Commonwealth Edison Co 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 21763, 357 24X Fiche 50-000, 84/01/03, 8401100362

8401100455 Suppls 830422 response to Generic Ltr 83-10C & D Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301.
BARNES, P L Commonwealth Edison Co 84/01/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p, 21761 284, 24X Fiche 50-000, 84/01/04, 8401100455

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification. Sandia position is that NRC environ qualification program has problems
EISENHUT, D Q Division of Licensing. 84/01/05, PALLADINO, N J Commissioners 2pp, 21793 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms: "important to safety" & "safety-related," Svc list encl.
EISENHUT, D. Q Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp, 21946 190, 24X Fiche 50-000, 84/01/05, 8401050382

8401100265 Submits supplemental info re periodic training for rad/chem technicians for post-accident sampling procedures Special retraining will be completed at least every 6 months.
TRAMM, T. R Commonwealth Edison Co. 84/01/05, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp, 21759 200, 24X Fiche 50-000, 84/01/05, 8401100265

DOCKETED ITEMS

840110276 Submits addl info re emergency operating procedures used during initial operation. Verification & validation of current emergency operating procedures completed during wk of 8/31/26, utilizing 14 accident scenarios.
TRAMM, T. R. Commonwealth Edison Co 84/01/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 21772 252 24X
Fiche 30-454, 84/01/03, 840110276

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Bvc list encl.
EISENHUT, D. O. Division of Licensing 84/01/06 Consolidated Edison Co. of New York, Inc 18pp. 21957 267 24X
Fiche: 30-000, 84/01/06, 8401090221

8401130303 Forwards revs to certain human engineering deficiencies contained in util 830509 ltr re control room preliminary design assessment along w/Supplis I & II in response to NUREG-0660 & Section 18 of SER. Byron SSER Item 17 closed
SWARTZ, E. D. Commonwealth Edison Co 84/01/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 28pp 21799 305 24X
Fiche: 30-000, 84/01/06, 8401130303

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Bvc list encl.
EISENHUT, D. O. Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174 24X
Fiche: 30-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profiles for new plants.
HAMMON, J. Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X
Fiche: 30-000, 84/01/17, 8401270536

8401240255 Forwards memo re 840117 meeting w/util. Memo should be sent to parties in OL proceeding & placed in docket file
MANNING, W. J. Commissioners 84/01/20 CHILK, B. J. Office of the Secretary of the Commission 1p 21910 003 24X
Fiche: 30-454, 84/01/20, 8401240255

--8401240261 Summary of 840117 meeting w/util re OL proceeding.
MANNING, W. J. Commissioners 84/01/20 Commissioners 4pp. 21910 004 24X
Fiche: 30-454, 84/01/20, 8401240255

1401250205 Summary of 840117 meeting w/Comm Ed re ASLB 840113 initial decision to deny application for OL on basis of inadequate SA.
CUNNINGHAM, G. H. Office of the Executive Legal Director 84/01/20. DIRCKS, W. J., ROE, J. W. Office of the Executive Director for Operations. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 4pp. 21943 173 24X
Fiche: 30-454, 84/01/20, 8401250205

E. NRC Safety Evaluation Report (SER), supplis & correspondence

8312120186 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BYRON STATION, UNITS 1 & 2 Docket Nos STN 30-454 And STN 30-455 (Commonwealth Edison Company)
* Division of Licensing. NUREG-0876 803. 83/11/30, 31pp. Available at NRC. \$3.75. 21511 100. 24X
Fiche 30-454, 83/11/30, 8312120186.

1401100181 Forwards Tables CET-1 & CET-2 which provide point-by-point evaluation of inadequate core cooling instrumentation, per NUREG-0737, Item II.F.2. Info supplis 830208 response to Question 8 of NRC 821027 ltr SER Outstanding Item 9 closed.
TRAMM, T. R. Commonwealth Edison Co. 83/12/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 21760 345. 24X
Fiche: 30-000, 83/12/27, 8401100181.

8401100193 Provides addl info re NUREG-0737, Item II.K.3 1, "Isolation & Testing of Automatic PORV Isolation Sys." to close out SER Confirmatory Issue 2B, Automatic PORV isolation unnecessary, based on Westinghouse Owners Group study.
TRAMM, T. R. Commonwealth Edison Co. 83/12/27. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 21759 279. 24X
Fiche: 30-000, 83/12/27, 8401100193.

8401060180 Provides addl info re adequacy of pressurizer relief & safety valves. Info closes confirmatory issue in Section 5.9.3.3 of SER Safety Functions of Safety & Relief Valve piping network for NUREG-0737, Item II.D.1 satisfied.
TRAMM, T. R. Commonwealth Edison Co. 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 21739 166. 24X
Fiche: 30-000, 83/12/30, 8401060180.

8401060204 Forwards revised FBAR pages providing addl info re monitoring of leakage from sys outside containment, satisfying concern in NUREG-0737, Item III D 1 1 Info should close Byron SER Confirmatory Issue 2B(a)
TRAMM, T. R. Commonwealth Edison Co 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 21739 169 24X
Fiche 30-000, 83/12/30, 8401060204

8401100433 Provides addl info re auxiliary bldg vent noble gas effluent monitors, to complete review of instrumentation as documented in Byron SER
TRAMM, T. R. Commonwealth Edison Co 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 21762 167 24X
Fiche 30-000, 83/12/30, 8401100433

8401100347 Provides justification for interim operation (JIO) for several items of electrical equipment for which environ testing will be incomplete at time of fuel load for Byron Unit 1 Review of JIO necessary to close SER Item 10
TRAMM, T. R. Commonwealth Edison Co 84/01/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 32pp 21764 034 24X
Fiche 30-000, 84/01/05, 8401100347

8401160260 Forwards addl info re accuracy & sensitivity of analytical procedures & online instrumentation to be used for post-accident analysis of reactor coolant info supports generic review of procedures in SER Section 9 3 2
TRAMM, T. R. Commonwealth Edison Co 84/01/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp 21814 170. 24X
Fiche: 30-454, 84/01/05, 8401160260

8401190192 Forwards SER (NUREG-0876) for Byron in support of ACRS review of Braidwood SER w/o encl
NOVAK, T. M. Assistant Director for Licensing 84/01/05 EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 1p 21870 021 24X
Fiche: 30-454, 84/01/05, 8401190192.

8401130303 Forwards revs to certain human engineering deficiencies contained in util 830509 ltr re control room preliminary design assessment along w/Supplis I & II in response to NUREG-0660 & Section 18 of SER Byron SSER Item 17 closed
SWARTZ, E. D. Commonwealth Edison Co 84/01/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 28pp 21799 305 24X
Fiche: 30-000, 84/01/06, 8401130303

F Security, medical, emergency & fire protection plans

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection Implementation will vary at each facility
SWARTZ, E. D. Commonwealth Edison Co 83/12/29 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche: 30-000, 83/12/29, 8401030229.

8401060170 Forwards Rev 10 to security plan Rev addresses vitalization of essential svc water sys cooling towers Rev withheld (ref 10CFR73.21)
FARRAR, D. L. Commonwealth Edison Co 83/12/30 Office of Nuclear Reactor Regulation, Director 1p. 21739 225 24X
Fiche 30-454, 83/12/30, 8401060170

8401230491 Notification of 840112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C. J. Region 3, Office of Director 84/01/05. REED, C. Commonwealth Edison Co 4pp 21874 001 24X
Fiche 30-000, 84/01/05, 8401230491.

8401260178 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 84/01/18 Document Management Branch. 1p 21982 346 24X
Fiche 30-454, 84/01/18, 8401260178.

8401250042 Releases public version of revised emergency plan procedures.
FELTON, J. M. Division of Rules and Records. 84/01/20. Document Management Branch 1p 21947 320 24X
Fiche: 30-454, 84/01/20, 8401250042.

--8401250047 Public version of Rev 0 to Emergency Plan Implementing Procedure BZP 380-3, "Post-Accident Vent Stack Sampling of Wide-Range Gas Monitor" & Rev 0 to BZP 380-6, "Radiological Precautions for Sample Analysis"
* Commonwealth Edison Co 83/12/07. 10pp 21947 321 24X
Fiche 30-454, 84/01/20, 8401250042

DOCKETED ITEMS

347

8401260287 Releases public version of emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21992 310 24X Fiche 50-454, 84/01/20, 8401260287

--8401260287 Public version of Rev 1 to Emergency Plan Implementing Procedure B2P 500-T8, "Checklist - Environ Monitoring Supplies"
* Commonwealth Edison Co 83/11/04 5pp 21992 311 24X
Fiche 50-454, 84/01/20, 8401260287

8401260403 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 84/01/20 Document
Management Branch 1p 21999 278 24X Fiche 50-454, 84/01/20, 8401260403

--8401260409 Public version of Rev 2 to Emergency Plan Implementing Procedure B2P 500-T4, "Byron Station First Aid Kit Inventory"
* Commonwealth Edison Co 83/12/20 2pp 21999 279 24X
Fiche 50-454, 84/01/20, 8401260409

0 Adjudicatory correspondence

8401040189 Forwards IE Insp Repts 50-454/83-39 & 50-455/83-29 re reinsp program discussed at 830808-12 hearings w/o encl
RAWSON, R J Hearing Branch 4 83/12/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 21702 078 24X Fiche 50-454, 83/12/30, 8401040189

8401050366 Forwards applicant 831216 ltr re changes to Byron steam generators to minimize flow-induced vibration Ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/12/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 28pp 21731 066 24X Fiche 50-000, 83/12/30, 8401050366

8401120231 Forwards IE Insp Rept 50-454/83-37, per ASLB request to be provided w/all Region III insps performed as part of reinsp program
YOUNG, M A Hearing Branch 4 84/01/05 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 16pp 21794 056 24X Fiche 50-454, 84/01/05, 8401120231

8401100215 Response opposing intervenor motion to reopen record & for order imposing commitments re QA/QC issues Issues do not warrant reopening record
BECKER, B D Commonwealth Edison Co BECKER, B D Isham, Lincoln & Beale 84/01/06 Atomic Safety and Licensing Board Panel 10pp. 21759 255 24X Fiche 50-454, 84/01/06, 8401100215

--8401100219 Affidavit of L DelGeorge re reinsp program Certificate of Bvc encl
DELGEORGE, L Commonwealth Edison Co 84/01/06 6pp 21759 265. 24X Fiche 50-454, 84/01/06, 8401100219

8401100466 Addendum to petition for emergency relief per 10CFR2.206 re integrated leak rate testing All documentation re integrated leak rate tests must be made public
ODGOL, E M Affiliation Unknown 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21761, 286 24X
Fiche: 50-000, 84/01/06, 8401100466

8401250078 Forwards NRC response to intervenor motion to reopen record & for order imposing commitments & affidavit of DW Hayes & KA Connaughton
YOUNG, M A Hearing Branch 4 84/01/11 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 21939 258 24X Fiche 50-454, 84/01/11, 8401250078

--8401250083 Response opposing intervenor motion to reopen record & order imposing commitments Three events upon which motion grounded do not support issuance of order requiring applicant & staff to honor commitments
YOUNG, M A Hearing Branch 4 84/01/11 Atomic Safety and Licensing Board Panel 13pp 21939 259 24X
Fiche 50-454, 84/01/11, 8401250078

--8401250087 Affidavit of DW Hayes & KA Connaughton supporting NRC opposition to intervenor motion to reopen record on QA/QC issues & for order imposing commitments Certificate of Bvc encl.
HAYES, D W, CONNAUGHTON, K Division of Project & Resident Programs 84/01/10 12pp. 21939 272 24X Fiche: 50-454, 84/01/11, 8401250078

8401230439 Initial Decision LBP-84-2, withholding authorization for OL because of failures in QA program
SMITH, I W, CALLIHAN, D, COLE, R F Atomic Safety and Licensing Board Panel 84/01/13 417pp 21881 001 24X Fiche 50-454, 84/01/13, 8401230439

8401250208 Forwards IE Insp Repts 50-454/83-57 & 50-455/83-40 of preoperational radiation protection program Repts may be relevant to Rockford League of Women Voters Contentions 42, 111 & 112 re ALARA
RAWSON, R J Hearing Branch 4 84/01/13 SMITH, I W, CALLIHAN, A D, COLE, R F Atomic Safety and Licensing Board Panel 1p 21943 163 24X Fiche 50-454, 84/01/13, 8401250208

8401300221 Forwards summary of 840117 meeting w/util re ASLB 840113 initial decision denying OL
CUNNINGHAM, G H Office of the Executive Legal Director 84/01/20 DIRKS, W J Office of the Executive Director for Operations DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 22062 118 24X Fiche 50-454, 84/01/20, 8401300221

8401250201 Notice of appeal of ASLB 840113 Initial Decision LBP-84-2 Certificate of Bvc encl
MILLER, M I Commonwealth Edison Co MILLER, M I Isham, Lincoln & Beale 84/01/23 4pp 21943 184 24X Fiche 50-454, 84/01/23, 8401250201

8401270378 Notice of appeal of ASLB 840113 initial decision Certificate of Bvc encl.
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Safe Energy for New Haven 84/01/23 3pp 21976 045 24X
Fiche 50-454, 84/01/23, 8401270378

8401300202 Motion for expedited consideration of appeal of ASLB denial of OL Facility in final stages of const & will be ready for fuel load by 840315 Briefing schedule delineated
MILLER, M I Commonwealth Edison Co MILLER, M I Isham, Lincoln & Beale 84/01/24 Atomic Safety and Licensing Appeal Panel 6pp 21995 316 24X Fiche 50-454, 84/01/24, 8401300202

--8401300207 Affidavit of C Reed re const status & target fuel load dates
REED, C Commonwealth Edison Co 84/01/24 4pp 21995 322 24X
Fiche 50-454, 84/01/24, 8401300202

--8401300210 Affidavit of RL Heumann re costs of delay in startup & operation Notice of appearance for PP Steptow, notice of withdrawal of appearance for G Herrin, RQ Fitzgibbons & R Murphy & Certificate of Bvc encl
HEUMANN, R L Commonwealth Edison Co 84/01/24 11pp. 21995 326 24X Fiche 50-454, 84/01/24, 8401300202.

8401300261 Motion for expedition of util appeal of 840113 Initial Decision LBP-84-2 re inadequate QA program ASLB should adopt intervenor proposed schedule which allows for full & fair briefing on expedited basis w/Certificate of Bvc.
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Safe Energy for New Haven. 84/01/25 Atomic Safety and Licensing Appeal Panel 5pp 21998 331 24X Fiche: 50-454, 84/01/25, 8401300261

K. Utility Final Safety Analysis Report (FSAR) & amends

8401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR
TRAMM, T R Commonwealth Edison Co 83/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 21751: 246 24X
Fiche 50-000, 83/12/20, 8401090223

--8401090242 Amend 44 to FSAR
* Commonwealth Edison Co. 83/12/31 350pp 21751. 254 24X
Fiche. 50-000, 83/12/20, 8401090223.

0 Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982, Forwards IE notebook tabulating requested info Notebook also available in PDR.
FELTON, J M Division of Rules and Records. 83/10/20. ZAHNER, R. E. Shaw, Pittman, Petts & Troubridge. 1p 21744: 003 24X
Fiche: 50-000, 83/10/20, 8401060040.

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744. 004. 24X Fiche. 50-000, 83/10/20, 8401060040

DOCKETED ITEMS

8401040533 Suppls response to IE Bulletin 83-06 re nonconforming mats supplied by Tube-Line Corp. Training held to emphasize review of purchase documents re receipt, insp & visual item verification per purchase order requirements
BARNES, P. L. Commonwealth Edison Co 83/12/20 KEPPLER, J. O. Region 3, Office of Director 3pp. 21714 036 24X Fiche 50-000, 83/12/20, 8401040533

8401050418 Forwards IE Insp Repts 50-454/83-57 & 50-455/83-40 on 831128-1202 No noncompliance noted
PAPERIELLO, C. J. Region 3, Office of Director 83/12/23. REED, C. Commonwealth Edison Co 2pp 21731 140 24X Fiche 50-454, 83/12/23, 8401050418

--8401050421 IE Insp Repts 50-454/83-57 & 50-455/83-40 on 831128-1202 No noncompliance noted Major areas inspected radiation protection procedures, respiratory protection program, NUREG-0737 items & preoperational sys demonstrations.
HUTER, L. J., GREGER, L. R. Region 3, Office of Director 83/12/23. 7pp. 21731 142 24X Fiche 50-454, 83/12/23, 8401050418

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090.

8401050296 Forwards IE Insp Repts 50-454/83-39 & 50-455/83-29 on 830808-1122 No noncompliance noted
LITTLE, W. B. Region 3, Office of Director 83/12/28 REED, C. Commonwealth Edison Co. 2pp 21728 312 24X Fiche 50-454, 83/12/28, 8401050296

--8401050300 IE Insp Repts 50-454/83-39 & 50-455/83-29 on 830808-1122 No noncompliance noted Major areas inspected previous insp findings, IE bulletins, allegations, safety-related components & structural & piping activities.
WARD, K. D., CLIMBERO, R. L., KEATING, D. E. Region 3, Office of Director 83/12/28 53pp. 21728 314 24X Fiche 50-454, 83/12/28, 8401050296.

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 040. 24X Fiche 50-000, 83/12/30, 8312120093

8401100275 Forwards response to unresolved items identified in Integrated Design Insp Rept 50-454/83-92 & addresses NRC conclusions presented in 830930 ltr
REED, C. Commonwealth Edison Co 83/12/30. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 147pp 21758 270. 24X Fiche 50-454, 83/12/30, 8401100275

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946.053. 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10. Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107.

8312120114 IE Info Notice 84-05, "Excessive Frequency." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16. Consolidated Edison Co. of New York, Inc. 127pp. 21957:142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp. 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp. 22000 041. 24X Fiche 50-000, 84/01/18, 8312120117.

8401310386 Forwards IE Insp Repts 50-454/83-61 & 50-455/83-41 on 831101-1231 No noncompliance noted
KNOP, R. C. Region 3, Office of Director. 84/01/20 REED, C. Commonwealth Edison Co 2pp. 22018.025. 24X Fiche 50-454, 84/01/20, 8401310386.

--8401310389 IE Insp Repts 50-454/83-61 & 50-455/83-41 on 831101-1231 No noncompliance noted Major areas inspected IE bulletin responses, preoperational test procedures, preoperational testing operations, new fuel receipt & storage
HINDS, J. M., CONNAUGHTON, K., HAYES, D. W. Region 3, Office of Director 84/01/20 16pp 22018 027 24X Fiche 50-454, 84/01/20, 8401310386

T Hearing transcripts on non-antitrust matters

8401120306 Memorandum & order accepting NRC proposed transcript corrections of 830808 & 0930
SMITH, I. W. Atomic Safety and Licensing Board Panel 84/01/11 Office of the Executive Legal Director 1p 21792 115 24X Fiche 50-454, 84/01/11, 8401120306

DOCKET BTN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FBAR
TRAHM, T. R. Commonwealth Edison Co 83/12/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 8pp 21751 246. 24X Fiche 50-000, 83/12/20, 8401090223

8401060416 Forwards Natl Register of Historic Places inventory - nomination form, identifying potential archeological site located onsite Site undisturbed by const.
SMARTZ, E. D. Commonwealth Edison Co 83/12/21 YOUNG, B. J. Licensing Branch 1. 5pp 21741 021 24X Fiche 50-456, 83/12/21, 8401060416

8401190322 Forwards transparencies presented at NRC 831220 enforcement conference re const & QA activities at facility
FARRAR, D. L. Commonwealth Edison Co 83/12/21 DAVIS, B. Region 3, Office of Director 1p 21851 001 24X Fiche 50-456, 83/12/21, 8401190322

8401100479 Requests issuance of OLs for full term of 40 yrs from date of issuance, per Atomic Energy Act & NEPA
TRAHM, T. R. Commonwealth Edison Co 83/12/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 21761 233. 24X Fiche 50-000, 83/12/28, 8401100479.

8401050366 Forwards applicant 831216 ltr re changes to Byron steam generators to minimize flow-induced vibration ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
GALL, J. Isham, Lincoln & Beale 83/12/30 SMITH, I. W. Atomic Safety and Licensing Board Panel 28pp 21731 066 24X Fiche 50-000, 83/12/30, 8401050366

8401100311 Forwards list of safety-related mechanical equipment denoting environ qualification & explanation of qualification established for all balance-of-plant equipment on list except for eight valves
TRAHM, T. R. Commonwealth Edison Co 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 25pp. 21758 243 24X Fiche 50-000, 83/12/30, 8401100311

8401100162 Forwards advance copy of revised response to FBAR Question 040 94 re emergency diesel generator vibration Response will be incorporated in next FBAR amend
TRAHM, T. R. Commonwealth Edison Co 84/01/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 21760 165 24X Fiche 50-000, 84/01/03, 8401100162.

8401100362 Forwards revised temp limits for reactor vessel, per amend to App G to 10CFR50 Only cooldown curves for Byron Unit 1 & Braidwood Unit 2 must be changed to incorporate new closure flange limitations
TRAHM, T. R. Commonwealth Edison Co 84/01/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 21763 337 24X Fiche 50-000, 84/01/03, 8401100362.

8401100455 Suppls 830422 response to Generic Ltr 83-10C & D Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301
BARNES, P. L. Commonwealth Edison Co 84/01/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 21761 284. 24X Fiche 50-000, 84/01/04, 8401100455

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D. G. Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc. 16pp. 21946.190 24X Fiche 50-000, 84/01/05, 8401050382

DOCKETED ITEMS

349

B401100265 Submits supplemental info re periodic training for rad/chem technicians for post-accident sampling procedures. Special retraining will be completed at least every 6 months.
TRAMM, T R Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21759 200 24X
Fiche: 50-000, 84/01/05, B401100265

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing.
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche: 50-000, 84/01/06, B401090221

B401130303 Forwards revs to certain human engineering deficiencies contained in util B30509 ltr re control room preliminary design assessment along w/Supple 1 & 11 in response to NUREG-0560 & Section 18 of SER Byron SSER Item 17 closed.
SHARTZ, E D Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 28pp 21797 305 24X
Fiche: 50-000, 84/01/06, B401130303

B401170160 Requests delay until B40315 for full ACRS committee meeting currently scheduled for Feb 1984 Subcommittee meetings could be held B40308-09 Delay required to resolve outstanding items, is acceptable to ACRS & would not affect ABLB hearing.
SHARTZ, E D Commonwealth Edison Co 84/01/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21834 133 24X
Fiche: 50-456, 84/01/12, B401170160

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues".
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants.
HANNOX, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

C Utility Environmental Report (ER), amends & correspondence

B401100380 Notifies that amends to environ rept - OL stage, submitted to NRC on B31215, distributed to agencies, officials & individuals, per 10CFR2.101.
SHARTZ, E D Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21764 015 24X
Fiche: 50-456, 84/01/05, B401100380

D NRC Draft/Final Environmental Statements, suppl's & correspondence

B401180120 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF BRAIDWOOD STATION UNITS 1 AND 2 Docket Nos STN 50-456 And STN 50-457 (Commonwealth Edison Company).
* Division of Licensing NUREG-1026 83/12/31 213pp, Available at NRC #6 50 21848 001 24X Fiche 50-456, 83/12/31, B401180120

B401190139 Forwards DER (NUREG-1026) W/o encl
YOUNGBLOOD, B J Licensing Branch 1 84/01/06 FARRAR, D L Commonwealth Edison Co 2pp 21871 017 24X Fiche 50-456, 84/01/06, B401190139

E NRC Safety Evaluation Report (SER), suppl's & correspondence

B401100181 Forwards Tables CET-1 & CET-2 which provide point-by-point evaluation of inadequate core cooling instrumentation, per NUREG-0737, Item II F 2 info suppl's B30208 response to Question B of NRC B21027 ltr SER Outstanding Item 9 closed.
TRAMM, T R Commonwealth Edison Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 21760 345 24X
Fiche: 50-000, 83/12/27, B401100181

B401100193 Provides addl info re NUREG-0737, Item II, K 3 i, "Isolation & Testing of Automatic PORV Isolation Sys." to close out SER Confirmatory Issue 28 Automatic PORV isolation unnecessary, based on Hestingshouse Owners Group study.
TRAMM, T R Commonwealth Edison Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21759, 279 24X
Fiche: 50-000, 83/12/27, B401100193

B401060180 Provides addl info re adequacy of pressurizer relief & safety valves info closes confirmatory issue in Section 3.9.3 of SER Safety Functions of safety & relief valve piping network for NUREG-0737, Item II, D i satisfied.
TRAMM, T R Commonwealth Edison Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21739, 166 24X
Fiche: 50-000, 83/12/30, B401060180

B401060204 Forwards revised FSAR pages providing addl info re monitoring of leakage from sys outside containment, satisfying concern in NUREG-0737, Item III D 1 i info should close Byron SER Confirmatory Issue 28(a).
TRAMM, T R Commonwealth Edison Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21739 169 24X
Fiche: 50-000, 83/12/30, B401060204

B401100433 Provides addl info re auxiliary bldg vent noble gas effluent monitors, to complete review of instrumentation as documented in Byron SER.
TRAMM, T R Commonwealth Edison Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21762 167 24X
Fiche: 50-000, 83/12/30, B401100433

B401100400 Forwards SER (NUREG-0876) W/o encl
NOVAK, T M Assistant Director for Licensing 83/12/30 RAY, J J ACRS - Advisory Committee on Reactor Safeguards 3pp 21794 309 24X Fiche 50-456, 83/12/30, B401100400

B401100347 Provides justification for interim operation (JIO) for several items of electrical equipment for which environ testing will be incomplete at time of fuel load for Byron Unit 1 Review of JIO necessary to close SER Item 10.
TRAMM, T R Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 21764 034 24X
Fiche: 50-000, 84/01/05, B401100347

F. Security, medical, emergency & fire protection plans

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection implementation will vary at each facility.
SHARTZ, E D Commonwealth Edison Co 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche: 50-000, 83/12/29, B401030229

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed.
PAPERIELLO, C J Region 3, Office of Director 84/01/05 REED, C. Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 84/01/05, B401230491

G Adjudicatory correspondence

B401050366 Forwards applicant B31216 ltr re changes to Byron steam generators to minimize flow-induced vibration. Ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes.
GALLLO, J Isham, Lincoln & Beale, GALLLO, J Consumers Power Co. 83/12/30 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 28pp 21731 066 24X Fiche 50-000, 83/12/30, B401050366

K Utility Final Safety Analysis Report (FSAR) & amends

B401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR.
TRAMM, T R Commonwealth Edison Co 83/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 21751 246 24X
Fiche: 50-000, 83/12/20, B401090223

--B401090242 Amend 44 to FSAR
* Commonwealth Edison Co 83/12/31 350pp 21751 254 24X
Fiche: 50-000, 83/12/20, B401090223

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR.
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche: 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744 004 24X Fiche: 50-000, 83/10/20, B401060040

B401040533 Suppl's response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements.
BARNES, P L Commonwealth Edison Co 83/12/20 KEPPLER, J O Region 3, Office of Director 3pp 21714 036 24X Fiche 50-000, 83/12/20, B401040533

DOCKETED ITEMS

8401050342 Forwards IE Insp Repts 50-456/83-19 & 50-457/83-18 on 831205-07 No noncompliance noted
PAPERIELLO, C J, Region 3, Office of Director. 83/12/23 REED, C
Commonwealth Edison Co 2pp 21729 244 24X Fiche 50-456, 83/12/23,
8401050342

--8401050343 IE Insp Repts 50-456/83-19 & 50-457/83-18 on 831205-07 No noncompliance noted Major areas inspected preoperational radiation protection program
GRANT, W B., GREGER, L R Region 3, Office of Director 83/12/23
4pp 21729 246 24X Fiche 50-456, 83/12/23, 8401050342

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp. 21731:166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060. 24X Fiche 50-000, 83/12/30, 8312120093.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp. 21946.053 24X Fiche: 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826:184 24X Fiche 50-000, 84/01/10, 8312120107

8401230426 Responds to Region III concerns re piping, HVAC & electrical areas, per 831220 meeting on recent insp findings. Overview of disputed issues & summary of util position encl
DELGEOORDE, L O Commonwealth Edison Co. 84/01/12 DAVIS, A B Region 3, Office of Director. 44pp 21882 242 24X
Fiche: 50-456, 84/01/12, 8401230426

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co of New York, Inc. 127pp 21937 142 24X Fiche: 50-000, 84/01/16, 8312120114.

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp. 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc. 120pp. 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A. Application/construction stage documents & correspondence

8401090223 Amend to application for CPs & OLs, consisting of Amend 44 to FSAR.
TRAMM, T R. Commonwealth Edison Co 83/12/20 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 8pp 21731 246 24X
Fiche: 50-000, 83/12/20, 8401090223.

8401060416 Forwards Natl Register of Historic Places inventory - nomination form, identifying potential archeological site located onsite. Site undisturbed by const
SWARTZ, E D. Commonwealth Edison Co. 83/12/21 YOUNGBLOOD, B J. Licensing Branch 1. 5pp. 21741 021 24X Fiche: 50-456, 83/12/21, 8401060416.

8401190322 Forwards transparencies presented at NRC 831220 enforcement conference re const & QA activities at facility.
FARRAN, D L Commonwealth Edison Co. 83/12/21. DAVIS, B. Region 3, Office of Director 1p. 21831.001. 24X Fiche: 50-456, 83/12/21, 8401190322.

8401100479 Requests issuance of OLs for full term of 40 yrs from date of issuance, per Atomic Energy Act & NEPA
TRAMM, T R. Commonwealth Edison Co. 83/12/28. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 5pp. 21761:233 24X
Fiche: 50-000, 83/12/28, 8401100479

8401050366 Forwards applicant 831216 ltr re changes to Byron steam generators to minimize flow-induced vibration ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
GALLD, J Isham, Lincoln & Beale 83/12/30 SMITH, I W Atomic Safety and Licensing Board Panel 28pp 21731 066 24X
Fiche 50-000, 83/12/30, 8401050366

8401100311 Forwards list of safety-related mechanical equipment denoting environ qualification & explanation of qualification established for all balance-of-plant equipment on list except for eight valves
TRAMM, T R Commonwealth Edison Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 25pp 21738 243 24X
Fiche 50-000, 83/12/30, 8401100311

8401100162 Forwards advance copy of revised response to FSAR Question 040 94 re emergency diesel generator vibration Response will be incorporated in next FSAR amend
TRAMM, T R Commonwealth Edison Co 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 21760 165 24X
Fiche: 50-000, 84/01/03, 8401100162

8401100362 Forwards revised temp limits for reactor vessel, per app 0 to 10CFR50 Only cooldown curves for Byron Unit 1 & Braidwood Unit 2 must be changed to incorporate new closure
TRAMM, T R Commonwealth Edison Co 84/01/03. DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 21763 357 24X
Fiche 50-000, 84/01/03, 8401100362

8401100455 Suppls 830422 response to Generic Ltr 83-10C & D Balance of response will be provided following receipt of Westinghouse Owners Group generic response, expected to be completed by 840301.
BARNES, P L Commonwealth Edison Co 84/01/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21761 284 24X
Fiche 50-000, 84/01/04, 8401100455

8401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc. 16pp 21946 190 24X
Fiche: 50-000, 84/01/05, 8401050382

8401100265 Submits supplemental info re periodic training for radiation technicians for post-accident sampling procedures Special retraining will be completed at least every 6 months
TRAMM, T R Commonwealth Edison Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21739 200 24X
Fiche 50-000, 84/01/05, 8401100265

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc. 18pp 21937 267 24X
Fiche 50-000, 84/01/06, 8401090221

8401130303 Forwards revs to certain human engineering deficiencies contained in util 830509 ltr re control room preliminary design assessment along w/Suppls I & II in response to NUREG-0660 & Section 18 of SER Byron SER Item 17 closed
SWARTZ, E D Commonwealth Edison Co 84/01/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 28pp 21799 305 24X
Fiche: 50-000, 84/01/06, 8401130303

8401170160 Requests delay until 840315 for full ACRS committee meeting currently scheduled for Feb 1984 Subcommittee meetings could be held 840308-09 Delay required to solve outstanding items. is acceptable to ACRS & would not affect ASLB hearing
SWARTZ, E D. Commonwealth Edison Co 84/01/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p. 21834 133 24X
Fiche 50-456, 84/01/12, 8401170160

8401130084 Generic Ltr 84-03 to all licensees of operating reactors: applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946:174 24X
Fiche: 50-000, 84/01/13, 8401130084.

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing 1p. 22000 349 24X Fiche: 50-000, 84/01/17, 8401270536

DOCKETED ITEMS

351

C Utility Environmental Report (ER), amends & correspondence

B401100380 Notifies that amends to environ rept - DL stage, submitted to NRC on 8/31/15, distributed to agencies, officials & individuals, per 10CFR2.101
SWARTZ, E D Commonwealth Edison Co 8/4/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21764 015 24X
Fiche 50-456, 8/4/01/05, B401100380

D NRC Draft/Final Environmental Statements, suppl's & correspondence

B401180120 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF BRAIDWOOD STATION UNITS 1 AND 2 Docket Nos STN 50-456 And STN 50-457 (Commonwealth Edison Company)
* Division of Licensing NUREG-1026 8/3/12/31 213pp Available at NRC \$6 50 21848 001 24X Fiche 50-456, 8/3/12/31, B401180120

B401190139 Forwards DES (NUREG-1026) W/o encl
YOUNGBLOOD, B J Licensing Branch 1 8/4/01/06 FARRAR, D L Commonwealth Edison Co 2pp 21871 017 24X Fiche 50-456, 8/4/01/06, B401190139

E NRC Safety Evaluation Report (SER), suppl's & correspondence

B401100181 Forwards Tables CET-1 & CET-2 which provide point-by-point evaluation of inadequate core cooling instrumentation, per NUREG-0737, Item II F 2 Info suppl's B30208 response to Question 8 of NRC B21027 ltr SER Outstanding Item 9 closed
TRAMM, T R Commonwealth Edison Co 8/3/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 21760 345 24X
Fiche 50-000, 8/3/12/27, B401100181

B401100193 Provides addl info re NUREG-0737, Item II K 3 i, "Isolation & Testing of Automatic PORV Isolation Sys," to close out SER Confirmatory Issue 28 Automatic PORV isolation unnecessary, based on Westinghouse Owners Group study
TRAMM, T R Commonwealth Edison Co 8/3/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21759 279 24X
Fiche 50-000, 8/3/12/27, B401100193

B401060180 Provides addl info re adequacy of pressurizer relief & safety valves, info closes confirmatory issue in Section 3 9 3 3 of SER Safety functions of safety & relief valve piping network for NUREG-0737, Item II D 1 satisfied
TRAMM, T R Commonwealth Edison Co 8/3/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21739 166 24X
Fiche 50-000, 8/3/12/30, B401060180

B401060204 Forwards revised FSAR pages providing addl info re monitoring of leakage from sys outside containment, satisfying concern in NUREG-0737, Item III D 1 i Info should close Byron SER Confirmatory Issue 28(a)
TRAMM, T R Commonwealth Edison Co 8/3/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21739 169 24X
Fiche 50-000, 8/3/12/30, B401060204

B401100433 Provides addl info re auxiliary bldg Vent noble gas effluent monitors, to complete review of instrumentation as documented in Byron SER
TRAMM, T R Commonwealth Edison Co 8/3/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21762 167 24X
Fiche 50-000, 8/3/12/30, B401100433

B401100400 Forwards SER (NUREG-0876) W/o encl.
NOVAK, Y M Assistant Director for Licensing 8/3/12/30 RAY, J J ACRS - Advisory Committee on Reactor Safeguards 3pp 21794 309, 24X Fiche 50-456, 8/3/12/30, B401100400

B401100347 Provides justification for interim operation (JIO) for several items of electrical equipment for which environ testing will be incomplete at time of fuel load for Byron Unit 1 Review of JIO necessary to close SER Item 10.
TRAMM, T R Commonwealth Edison Co 8/4/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 21764 034 24X
Fiche 50-000, 8/4/01/05, B401100347

Security, medical, emergency & fire protection plans

B401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection, implementation will vary at each facility
SWARTZ, E D Commonwealth Edison Co 8/3/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 21680 283 24X
Fiche 50-000, 8/3/12/29, B401030229

B401230491 Notification of B40112-13 FEMA radiological emergency preparedness program meetings at O'Hare Airport Emergency preparedness exercise & prompt alert & notification certification schedules will be developed
PAPERIELLO, C J Region 3, Office of Director 8/4/01/05 REED, C Commonwealth Edison Co 4pp 21874 001 24X Fiche 50-000, 8/4/01/05, B401230491

G Adjudicatory correspondence

B401050366 Forwards applicant B31216 ltr re changes to Byron steam generators to minimize flow-induced vibration Ltr addresses issues litigated under intervenor contentions challenging integrity of installed steam generator tubes
GALL, J J Isham, Lincoln & Deale 8/3/12/30 SMITH, I W Atomic Safety and Licensing Board Panel 28pp 21731 066 24X
Fiche 50-000, 8/3/12/30, B401050366

K Utility Final Safety Analysis Report (FSAR) & amends

B401090223 Amend to application for CPs & DLs, consisting of Amend 44 to FSAR
TRAMM, T R Commonwealth Edison Co 8/3/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 21751 246 24X
Fiche 50-000, 8/3/12/20, B401090223

--B401090242 Amend 44 to FSAR
* Commonwealth Edison Co 8/3/12/31 350pp 21751 254 24X
Fiche 50-000, 8/3/12/31, B401090242

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 8/3/10/20 ZAHNER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 8/3/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement, 8/3/10/20 134pp 21744 004 24X Fiche 50-000, 8/3/10/20, B401060150

B401040533 Suppl's response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Training held to emphasize review of purchase documents re receipt, insp & visual item verification, per purchase order requirements
BARNES, P L Commonwealth Edison Co 8/3/12/20 KEPPLER, J Q, Region 3, Office of Director 3pp 21714 036 24X Fiche: 50-000, 8/3/12/20, B401040533

B401050342 Forwards IE Insp Repts 50-456/83-19 & 50-457/83-18 on 831205-07 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 8/3/12/23 REED, C Commonwealth Edison Co 2pp 21729 244, 24X Fiche: 50-456, 8/3/12/23, B401050342

--B401050343 IE Insp Repts 50-456/83-19 & 50-457/83-18 on 831205-07 No noncompliance noted, Major areas inspected preoperational radiation protection program
GRANT, W B, GREGER, L R Region 3, Office of Director 8/3/12/23 4pp, 21729 246 24X Fiche 50-456, 8/3/12/23, B401050343

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 8/3/12/28 Consolidated Edison Co of New York, Inc. 124pp 21731 166 24X Fiche: 50-000, 8/3/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 8/3/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 8/3/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed," Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 8/4/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X Fiche: 50-000, 8/4/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 8/4/01/10 Consolidated Edison Co of New York, Inc. 122pp 21826 184 24X Fiche: 50-000, 8/4/01/10, B312120107

DOCKETED ITEMS

840120426 Responds to Region III concerns re piping, HVAC & electrical areas, per 831220 meeting on recent insp findings Overview of disputed issues & summary of util position encl
DELOERGE, L. O. Commonwealth Edison Co. 84/01/12 DAVIS, A. B. Region 3, Office of Director 44pp 21882 242 24X
Fiche 50-458, 84/01/12, 840120426

8312120114 IE Info Notice 84-03, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/16, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/16, 8312120117

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

8312200154 Forwards response to nine Users Group questions presented at 831130 meeting & forwarded by R Caruso 831127 ltr re standby diesel generators at nuclear power plants
MATHEWS, C. S. Transamerica Delaval, Inc 83/12/16 NOVAK, T. M. Assistant Director for Licensing 19pp 22034 358 24X
Fiche 50-000, 83/12/16, 8312200154

8401040284 Outlines procedures for reporting info promptly to region by using given telephone numbers for off & outside-of-office hours Util Urged to use numbers
COLLINS, J. T. Region 4, Office of Director 83/12/19 CAHILL, W. J. Gulf States Utilities Co 2pp 21701 209 24X
Fiche 50-458, 83/12/19, 8401040284

8401030210 Forwards info providing addl justification for absence of ammonia & chlorine detectors at facilities, info suppl
831017 ltr No adverse effects expected info will be reflected in future amend to FSAR
BOOKER, J. E. Gulf States Utilities Co 83/12/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 21728 122, 24X Fiche 50-458, 83/12/20, 8401030210

8401030271 Suppl 820217 responses to NRC 810805 & 1217 ltrs on 8401 31 re fracture prevention of containment pressure boundary matls
BOOKER, J. E. Gulf States Utilities Co. 83/12/21 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 43pp 21727 183 24X Fiche 50-458, 83/12/21, 8401030271

8401060241 Notification of 840106 meeting w/util in Arlington, TX to discuss mgt organization safety evaluation review
WEINKAM, E. J. Licensing Branch 2 83/12/23 SCHWENCER, A. Licensing Branch 2 3pp 21733 147, 24X Fiche 50-458, 83/12/23, 8401060241

840110560 Forwards TM Novak 831227 request to Mississippi Power & Light Co for addl info re emergency diesel generators mfg by Transamerica Delaval, Inc Plant-specific response required
SCHWENCER, A. Licensing Branch 2 83/12/29 CAHILL, W. J. Gulf States Utilities Co 2pp 21795 323, 24X Fiche 50-458, 83/12/29, 840110560

81250203 Forwards addl info re FSAR changes & supplemental clarifications to previously submitted responses, per 820202 & 831114 requests FSAR changes will be included in next amend.

BOOKER, J. E. Gulf States Utilities Co 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 400pp 21733 043, 24X Fiche 50-458, 83/12/30, 840120203

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D. O. Division of Licensing. 84/01/05 Consolidated Edison Co. of New York, Inc 16pp. 21746 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing. Svc list encl.
EISENHUT, D. O. Division of Licensing 84/01/06, Consolidated Edison Co. of New York, Inc 18pp 21937 267, 24X
Fiche: 50-000, 84/01/06, 8401090221

8401130455 Summary of 831201 meeting w/util in Bethesda, MD re equipment qualification programs
WEINKAM, E. J. Licensing Branch 2 84/01/10 Licensing Branch 2 22pp 21819 317 24X Fiche 50-458, 84/01/10, 8401130455

8401190191 Summary of 830929 meeting w/util & S&W in Cherry Hill, NJ re design basis flood level
WEINKAM, E. J. Licensing Branch 2 84/01/10 Licensing Branch 2 3pp 21870 022 24X Fiche 50-458, 84/01/10, 8401190191

8401190200 Summary of 831130 meeting w/util & S&W in Bethesda, MD re control room ventilation isolation requirements
WEINKAM, E. J. Licensing Branch 2 84/01/10, Licensing Branch 2 4pp 21870 017 24X Fiche 50-458, 84/01/10, 8401190200.

8401190289 Summary of 831108 meeting w/util & S&W re piping supports program
WEINKAM, E. J. Licensing Branch 2 84/01/10 Licensing Branch 2 4pp 21870 056 24X Fiche 50-458, 84/01/10, 8401190289

8401230671 Requests addl info to complete review of NF/AISC pipe support program info & clarification needed specifically in area of design of pipe supports & included as 210 109
SCHWENCER, A. Licensing Branch 2 84/01/12 CAHILL, W. J. Gulf States Utilities Co 5pp 21925 146 24X Fiche 50-458, 84/01/12, 8401230671

8401240034 Summary of 831115-16 meetings w/util re FSAR Chapter 13 topics concerning mgt organization
WEINKAM, E. J. Licensing Branch 2 84/01/12 Licensing Branch 2 4pp 21745 041 24X Fiche 50-458, 84/01/12, 8401240034

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues " Svc list encl.
EISENHUT, D. O. Division of Licensing 84/01/13, Consolidated Edison Co. of New York, Inc 18pp 21746 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J. Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

8401270290 Announces that RP Denise will become Director, Div of Resident Reactor Project & Engineering Programs, effective 840122, replacing J Gagliardo.
COLLINS, J. T. Region 4, Office of Director 84/01/23, CAHILL, W. J. Gulf States Utilities Co 1p 21775 361 24X Fiche: 50-458, 84/01/23, 8401270290

C. Utility Environmental Report (ER), amends & correspondence

8401060291 Forwards response to environ rept - DL stage, Review Question E460 1 re radwaste mgt sys info forwarded per Generic Ltr B2-14
BOOKER, J. E. Gulf States Utilities Co 83/12/29 SCHWENCER, A. Licensing Branch 2 9pp. 21741 343 24X Fiche: 50-458, 83/12/29, 8401060291

8401310241 Forwards Suppl 7 to environ rept - DL stage, Liquid radwaste treatment sys revs described.
CAHILL, W. J. Gulf States Utilities Co 84/01/27 EISENHUT, D. O. Division of Licensing 7pp 22013 274 24X Fiche 50-458, 84/01/27, 8401310241.

8401310247 Suppl 7 to environ rept - DL stage.
* Gulf States Utilities Co 84/01/27 299pp. 22013 281 24X
Fiche 50-458, 84/01/27, 8401310241

E. NRC Safety Evaluation Report (SER), suppl & correspondence

8401310439 Forwards responses to open items identified in draft SER & discussed w/Chemical Engineering Branch in Bethesda, MD on 830923. Encls 3-10 will be included in next FSAR amend.
BOOKER, J. E. Gulf States Utilities Co. 83/11/08, SCHWENCER, A. Licensing Branch 2 48pp 22012 260 24X Fiche 50-458, 83/11/08, 8401310439

8312290417 Forwards responses to draft SER open items, Licensing Review Group-11 Positions 1-13-RBB & TMI action plan requirements requested in 830421 ltr
BOOKER, J. E. Gulf States Utilities Co 83/12/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 85pp. 21660 098 24X Fiche: 50-458, 83/12/12, 8312290417

DOCKETED ITEMS

353

B401050169 Forwards response to open item identified in draft SER re structures, sys & components covered by QA program Response provides ref to revised FSAR Table 3.2-1 & necessary justification for items not included
BOOKER, J E Gulf States Utilities Co 83/12/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 48pp 21727 280
24X Fiche 50-458, 83/12/22, B401050169

B40110072 Forwards response to draft SER open items identified by NRC Mechanical Engineering Branch & response to NRC 831207 ltr requesting further clarification on design of pipe/component supports
BOOKER, J E Gulf States Utilities Co 83/12/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 118pp 21772 087
24X Fiche 50-458, 83/12/29, B40110072

B401040328 Forwards responses to draft SER open items identified by Core Performance Branch, per A Schwencer 831206 request ltr suppl info contained in 831111 ltr Attachment 1 summarizes open items & indicates changes to be made in FSAR
BOOKER, J E Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 20pp 21707 275
24X Fiche 50-458, 83/12/30, B401040328

B401090105 Forwards responses to open items identified in draft SER & response to 810805 & 1231 requests for addl info. Responses will be provided in future FSAR amend
BOOKER, J E Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 27pp 21753 209
24X Fiche 50-458, 83/12/30, B401090105

B401130313 Forwards changes to FSAR Section 2.4 in response to items identified by Environ & Hydrological Engineering Branch in draft SER re local flooding changes will be incorporated into next FSAR amend
BOOKER, J E Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 90pp 21801 229
24X Fiche 50-458, 83/12/30, B401130313

B401130388 Forwards response to items identified by Containment Sys Branch in draft SER & 810805, 1231 & 831202 ltrs Encl FSAR changes will be included in future FSAR amend W/21 oversize drawings Aperture cards are available in PDR
BOOKER, J E Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 180pp 21833 001
24X Fiche 50-458, 83/12/30, B401130388

B401190189 Summary of 830928 meeting w/util & S&W in Cherry Hill, NJ re Mechanical Engineering Branch draft SER open items
WEINKAM, E J Licensing Branch 2 84/01/10 Licensing Branch 2
4pp 21870 025 24X Fiche 50-458, 84/01/10, B401190189

B401190285 Summary of 830928-29 meetings w/util & S&W in Cherry Hill, NJ re Auxiliary Sys Branch draft SER open items
WEINKAM, E J Licensing Branch 2 84/01/10 Licensing Branch 2
8pp 21870 060, 24X Fiche 50-458, 84/01/10, B401190285

B401270245 Forwards response to Core Performance Branch draft SER open items re post-irradiation monitoring program & inadequate core cooling (NUREG-0737, Item II F 2) Indicated responses will be included in future FSAR amend
BOOKER, J E Gulf States Utilities Co 84/01/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 21982 141
24X Fiche 50-458, 84/01/20, B401270245

F. Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & D documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X
Fiche 50-000, 83/11/02, B401250163

--830516032? Recommends that Commission concur w/NRC approval of location of emergency operations facilities slightly beyond 20-mile limitations in Suppl 1 to NUREG-0737
DIRCKS, H J Office of the Executive Director for Operations
SECY-83-152 83/04/28 4app 21958 041 24X
Fiche 50-000, 83/11/02, B401250163

B401230155 Forwards IE Mgt Meeting Rept 50-458/83-17 on 831012-13 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/22, CAHILL, W J
Gulf States Utilities Co 2pp 21884 311, 24X
Fiche 50-458, 83/12/22, B401230155

--B401230140 IE Mgt Meeting Rept 50-458/83-17 on 831012-13. No violations noted Major areas discussed control room, technical support ctr & emergency operations facility
BAIRD, J D, CROSSMAN, W A Region 4, Office of Director, 83/12/20
3pp 21884 313 24X Fiche 50-458, 83/12/22, B401230155

B401090153 Forwards revised FSAR Table 13.3-1, "Emergency Action Levels, Initiating Conditions & Emergency Response" Marked items being developed as part of Tech Specs scheduled for submittal in June 1984 Info to be included in revised FSAR
BOOKER, J E Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 37pp 21754 304
24X Fiche 50-458, 83/12/30, B401090153

B401230120 Summary of 831013 meeting w/util, S&W & State of LA at facility training ctr re upcoming emergency appraisal team visit
WEINKAM, E J Licensing Branch 2 84/01/12, Licensing Branch 2
4pp 21931 001 24X Fiche 50-458, 84/01/12, B401230120

B401200291 Releases public version of state radiological emergency response plans
FELTON, J M Division of Rules and Records 84/01/17 Document
Management Branch 1p 21887 326 24X Fiche 50-458, 84/01/17, B401200291

--B401200296 Forwards public version of radiological emergency response plans for States of LA & MS
BOOKER, J E Gulf States Utilities Co 83/12/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 21887 329
24X Fiche 50-458, 84/01/17, B401200291

--B401200300 Public version of radiological emergency response plans for States of LA & MS
* Gulf States Utilities Co 83/12/31, 573pp, 21887 330 24X
Fiche 50-458, 84/01/17, B401200291

M Antitrust correspondence

B401090101 Forwards FR notice of receipt of addl antitrust info for application for OL Notices re health & safety & environ issues under review published separately
SCHWENCER, A Licensing Branch 2 83/12/20 CAHILL, W J Gulf
States Utilities Co 2pp 21757 238 24X Fiche 50-458, 83/12/20, B401090101

--B401090108 Notice of receipt of addl antitrust info for application for OL
SCHWENCER, A Licensing Branch 2 83/12/20 3pp 21757, 240, 24X
Fiche 50-458, 83/12/20, B401090101

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p, 21744:003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060130 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp, 21744 004, 24X Fiche 50-000, 83/10/20, B401060040

B401040443 Discusses SALP Rept 50-458/83-25 for Sept 1982 - Jul 1983 Licensee overall performance in functional areas continues at high level
COLLINS, J T Region 4, Office of Director, 83/12/16 CAHILL, W J
Gulf States Utilities Co 2pp 21705 083 24X
Fiche 50-458, 83/12/16, B401040443

--B401040449 Responds to NRC 831108 ltr re SALP Rept 50-458/83-15. No comments offered
BOOKER, J E Gulf States Utilities Co 83/11/21, COLLINS, J T
Region 4, Office of Director 1p, 21705 085 24X
Fiche 50-458, 83/12/16, B401040443

--B401040454 Forwards SALP Rept 50-458/83-15 for Sept 1982 - Jul 1983 Licensee overall performance in functional areas continues at high level
JOHNSON, E H Region 4, Office of Director, 83/11/08 CAHILL, W J
Gulf States Utilities Co 2pp, 21705 086 24X
Fiche 50-458, 83/12/16, B401040443

--B401040460 SALP Rept 50-458/83-15 for Sept 1982 - Jul 1983. Overall rating of Category 2 assigned.
CROSSMAN, W A, JOHNSON, E H Region 4, Office of Director, 83/11/08, 18pp, 21705 088 24X Fiche 50-458, 83/12/16, B401040443

--B401040470 Forwards input to SALP Rept 50-458/83-15 Licensee overall performance rated Category 2
WEINKAM, E J Licensing Branch 2 83/08/16 EISENHUT, D D
Division of Licensing 4pp 21705 106, 24X Fiche 50-458, 83/12/16, B401040443

DOCKETED ITEMS

8401230155 Forwards IE Mgt Meeting Rept 50-458/83-17 on 831012-13 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/22 CAHILL, W J
Gulf States Utilities Co 2pp 21884 311 24X
Fiche 50-458, 83/12/22, 8401230155

--8401230160 IE Mgt Meeting Rept 50-458/83-17 on 831012-13 No violations noted Major areas discussed control room, technical support ctr & emergency operations facility
BAIRD, J B, CROSSMAN, W A Region 4, Office of Director 83/12/20
3pp 21884 313 24X Fiche 50-458, 83/12/22, 8401230155

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Under-voltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30, Consolidated Edison Co of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401240492 Forwards IE Insp Rept 50-458/83-20 on 831017-1130 & notice of violation
JOHNSON, E H Region 4, Office of Director 84/01/05 CAHILL, W J
Gulf States Utilities Co 2pp 21920 088 24X
Fiche 50-458, 84/01/05, 8401240492

--8401240499 Notice of violation from insp on 831017-1130
* Region 4, Office of Director 84/01/05 2pp 21920:090 24X
Fiche 50-458, 84/01/05, 8401240492

--8401240507 IE Insp Rept 50-458/83-20 on 831017-1130 Violation noted failure to communicate needed diesel generator electrical & control sys design info to operating staff for incorporation in plant operating procedures
CHAMBERLAIN, D, CROSSMAN, W A Region 4, Office of Director 84/01/04 3pp 21920 092 24X Fiche 50-458, 84/01/05, 8401240492

8401130238 Confirms Region IV plan to perform independent verification insp on 840227-0309 using NDE van & contractor technicians Addl info on documentation selected for insp & list of welds for preparation of documentation packages encl
GALLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 84/01/06 CAHILL, W J Gulf States Utilities Co 3pp 21799 275 24X Fiche 50-458, 84/01/06, 8401130238

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 123pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/utills & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUSO, R Licensing Branch 2 84/01/17 SCHWENGER, A Licensing Branch 2 21pp 22027 009 24X Fiche 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc. 118pp 22000:001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401270081 Forwards QA Insp Repts 99900911/83-02, 99900403/83-03, 99900924/83-01 & 99900911/83-03 for evaluation of significance of findings re QA & acceptability of vendor product or svc Endorsement form encl W/o insp repts
JOHNSON, E H Division of Resident, Reactor Project & Engineering Programs 84/01/20 CAHILL, W J Gulf States Utilities Co 4pp 21982 014 24X Fiche 50-458, 84/01/20, 8401270081

S Reportable occurrences, LERs & related correspondence

8401170187 Interim Deficiency Rept DR-140 re engine mounted fuel oil line in standby diesel generator investigation incomplete Next rept will be provided by 831230
BOOKER, J E Gulf States Utilities Co 83/11/07 COLLINS, J T Region 4, Office of Director 1p 21833 313 24X
Fiche 50-458, 83/11/07, 8401170187

8401040219 Interim Deficiency Rept DR-105 re electrical separation between reactor protection sys & nuclear steam supply shutdown wiring within power generation control complex Next rept will be submitted by 840112
BOOKER, J E Gulf States Utilities Co 83/12/19 COLLINS, J T Region 4, Office of Director 1p 21701 206 24X
Fiche 50-458, 83/12/19, 8401040219

8401040476 Interim Deficiency Rept DR-108 re Bergen-Paterson pipe support components investigation incomplete Next rept will be provided by 840208
BOOKER, J E Gulf States Utilities Co 83/12/19 COLLINS, J T Region 4, Office of Director 1p 21707 274 24X
Fiche 50-458, 83/12/19, 8401040476

8401040525 Interim Deficiency Rept DR-147 re weld at end attachments o pipe support component supplied by Bergen-Paterson investigation incomplete Interim or final rept will be submitted by 840223
BOOKER, J E Gulf States Utilities Co 83/12/19 COLLINS, J T Region 4, Office of Director 1p 21707 145 24X
Fiche 50-458, 83/12/19, 8401040525

8401040119 Interim Deficiency Rept DR-97 re HMA relays mfg by GE in 1974 Next rept will be submitted by 840207
BOOKER, J E Gulf States Utilities Co 83/12/20 COLLINS, J T Region 4, Office of Director 1p 21703 224 24X
Fiche 50-458, 83/12/20, 8401040119

8401130216 Interim Deficiency Rept DR-148 re procurement document control of spare parts investigation incomplete Next rept expected by 840215
BOOKER, J E Gulf States Utilities Co 83/12/22 COLLINS, J T Region 4, Office of Director 1p 21801 357 24X
Fiche 50-458, 83/12/22, 8401130216

8401100450 Final Deficiency Rept DR-122 re filler matl in BF Shaw shop welds. Condition not reportable under 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T Region 4, Office of Director 1p 21761 353 24X
Fiche 50-458, 83/12/28, 8401100450

8401130060 Interim Deficiency Rept DR-150 re insulation on Posi-Seal Intl motor operator valves Next rept will be submitted by 840402
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T Region 4, Office of Director 1p 21802 342 24X
Fiche 50-458, 83/12/28, 8401130060

8401130139 Interim Deficiency Rept DR-152 re wire terminations of 480-volt Gould-Brown Boveri motor control ctrs investigation incomplete Next rept expected by 840316
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T Region 4, Office of Director 1p 21802 112 24X
Fiche 50-458, 83/12/28, 8401130139

8401130192 Interim Deficiency Rept DR-151 re partial penetration welds for square groove butt-welded HVAC ductwork investigation incomplete Next rept will be provided by 840410
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T Region 4, Office of Director 1p 21801 166 24X
Fiche 50-458, 83/12/28, 8401130192

8401130263 Interim Deficiency Rept DR-128 re stainless steel tubing supplied by Quifalloy, Hub, Inc & Capital Pipe & Steel investigation incomplete Interim or final status rept expected by 840315
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T Region 4, Office of Director 1p 21799 362 24X
Fiche 50-458, 83/12/28, 8401130263

DOCKETED ITEMS

355

B401130344 Interim Deficiency Rept DR-149 re post-weld heat treatment for fabricated pipe supports supplied by Bergen-Paterson Investigation incomplete Interim/final status rept will be submitted by B40402
BOOKER, J E Gulf States Utilities Co 83/12/28 COLLINS, J T
Region 4, Office of Director 1p 21798 276. 24X
Fiche 50-458, 83/12/28, B401130344

B401100212 Interim Deficiency Rept DR-96 re Bergen Paterson A500 Grade B tube steel investigation incomplete Next rept will be submitted by B40315
BOOKER, J E Gulf States Utilities Co 83/12/29 COLLINS, J T
Region 4, Office of Director 1p 21799 271 24X
Fiche 50-458, 83/12/29, B401100212

B401100278 Interim Deficiency Rept DR-139 re mechanical shock arresters supplied by Pacific Scientific Investigation incomplete Interim/final rept will be provided by B40330
BOOKER, J E Gulf States Utilities Co 83/12/29 COLLINS, J T
Region 4, Office of Director 1p 21758 214 24X
Fiche 50-458, 83/12/29, B401100278

B401130277 Interim Deficiency Rept DR-140 re engine mounted fuel oil line in standby diesel generator investigation incomplete Next rept will be submitted by B40402
BOOKER, J E Gulf States Utilities Co 83/12/30 COLLINS, J T
Region 4, Office of Director 1p 21800 355 24X
Fiche 50-458, 83/12/30, B401130277

B401130284 Interim Deficiency Rept DR-112 re 1E battery chargers supplied by Power Conversion Products, Inc investigation incomplete Next rept will be provided by B40315
BOOKER, J E Gulf States Utilities Co 83/12/30 COLLINS, J T
Region 4, Office of Director 1p 21801 121 24X
Fiche 50-458, 83/12/30, B401130284

B401230168 Interim Deficiency Rept DR-138 re ITE-Gould motor overload relays & trip ranges investigation incomplete Interim or final rept expected by B40330
BOOKER, J E Gulf States Utilities Co 83/12/30 COLLINS, J T
Region 4, Office of Director 1p 21884 309 24X
Fiche 50-458, 83/12/30, B401230168

B401130311 Interim Deficiency Rept DR-123 re McCrosky sheet metal HVAC ductwork fabrication investigation incomplete Interim or final rept expected by B40409
BOOKER, J E Gulf States Utilities Co 84/01/03 COLLINS, J T
Region 4, Office of Director 1p 21800 302 24X
Fiche 50-458, 84/01/03, B401130311

B401130072 Final Deficiency Rept DER-105 re electrical separation between reactor protection sys & nuclear steam supply shutdown wiring within Power Generation control complex Condition not reportable per 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 84/01/05 COLLINS, J T
Region 4, Office of Director 1p 21802 345. 24X
Fiche 50-458, 84/01/05, B401130072

B401130394 Interim Deficiency Rept DR-110 re ultrasonic couplant that did not meet chemical analysis requirements investigation incomplete Interim or final rept expected by B40406
BOOKER, J E Gulf States Utilities Co 84/01/05 COLLINS, J T
Region 4, Office of Director 1p 21798 362 24X
Fiche 50-458, 84/01/05, B401130394

B401130315 Interim Deficiency Rept DR-137 re preheat requirements for pipe support welds investigation continuing Next rept will be provided by B40410
BOOKER, J E Gulf States Utilities Co 84/01/06 COLLINS, J T
Region 4, Office of Director 1p 21798 312 24X
Fiche 50-458, 84/01/06, B401130315

B401170003 Interim Deficiency Rept DR-141 re internal attachment bolts in check valves supplied by Velan Engineering Co investigation in progress Next rept will be provided by B40411
BOOKER, J E Gulf States Utilities Co 84/01/09 COLLINS, J T
Region 4, Office of Director 1p 21834 110 24X
Fiche 50-458, 84/01/09, B401170003

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269. 24X
Fiche 50-000, 84/01/09, B401170186

B401170203 Interim Deficiency Rept DR-153 re orifice plates supplied by Bailey Controls & mfg by Allegheny Ludlum Steel Corp & Eastern Stainless Steel Co investigation ongoing Next rept will be provided by B40501
BOOKER, J E Gulf States Utilities Co 84/01/09 COLLINS, J T
Region 4, Office of Director 1p 21832 251 24X
Fiche 50-458, 84/01/09, B401170203

B401230299 Interim Deficiency Rept DR-107 re Category I 125-volt dc air circuit breakers supplied by Brown Boveri Electric Corp investigation incomplete Interim or final status rept expected by B40320
BOOKER, J E Gulf States Utilities Co 84/01/10 COLLINS, J T
Region 4, Office of Director 1p 21883 338 24X
Fiche 50-458, 84/01/10, B401230299

B401230522 Interim Deficiency Rept DR-134 re lines located at outlet of RHR sys HK shall investigation continuing Next rept will be provided by B40223
BOOKER, J E Gulf States Utilities Co 84/01/10 COLLINS, J T
Region 4, Office of Director 1p 21877 362 24X
Fiche 50-458, 84/01/10, B401230522

B401230265 Interim Deficiency Rept DR-154 re high voltage cable terminations investigation incomplete Interim or final status rept expected by B40406
BOOKER, J E Gulf States Utilities Co 84/01/11 COLLINS, J T
Region 4, Office of Director 1p 21884 216 24X
Fiche 50-458, 84/01/11, B401230265

B401230276 Interim Deficiency Rept DR-155 re personnel airlock seals supplied by WJ Woolley Co investigation incomplete Interim or final status rept will be provided by B40515
BOOKER, J E Gulf States Utilities Co 84/01/11 COLLINS, J T
Region 4, Office of Director 1p 21884 215 24X
Fiche 50-458, 84/01/11, B401230276

B401240218 Interim Deficiency Rept DR-92 re Category I stainless thermowells supplied by PYCO, Inc investigation incomplete Next rept will be submitted by B40229
BOOKER, J E Gulf States Utilities Co 84/01/11 COLLINS, J T
Region 4, Office of Director 1p 21910 302 24X
Fiche 50-458, 84/01/11, B401240218

B401230122 Final Deficiency Rept DR-97 re HMA relays mfg by GE in 1974 investigation complete Condition not reportable per 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 84/01/12 COLLINS, J T
Region 4, Office of Director 1p 21884 345. 24X
Fiche 50-458, 84/01/12, B401230122

B401230164 Final Deficiency Rept DR-124 re monorail sys supplied by Whiting Corp Condition not reportable under 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 84/01/12 COLLINS, J T
Region 4, Office of Director 1p 21884 310. 24X
Fiche 50-458, 84/01/12, B401230164

B401240122 Interim Deficiency Rept DR-156 re conductivity cell & conductivity indicators supplied by GE investigation incomplete Next rept expected by B40416
BOOKER, J E Gulf States Utilities Co 84/01/12 COLLINS, J T
Region 4, Office of Director 1p 21913 210. 24X
Fiche 50-458, 84/01/12, B401240122

B401240127 Interim Deficiency Rept DR-135 re min flow return lines in suppression pool investigation incomplete Interim or final status rept to be provided by B40320
BOOKER, J E Gulf States Utilities Co 84/01/12 COLLINS, J T
Region 4, Office of Director 1p 21912 341. 24X
Fiche 50-458, 84/01/12, B401240127

B401240231 Interim Deficiency Rept DR-142 re bellows assembly of relief valve supplied by Crosby Valve Co investigation incomplete Next rept will be submitted by B40329
BOOKER, J E Gulf States Utilities Co 84/01/12 COLLINS, J T
Region 4, Office of Director 1p 21910 182. 24X
Fiche 50-458, 84/01/12, B401240231

B401270332 Final Deficiency Rept DR-132 re separation of Class IE & non-Class IE wiring in control panel Condition not reportable under 10CFR50.55(e)
BOOKER, J E Gulf States Utilities Co 84/01/19 COLLINS, J T
Region 4, Office of Director 1p 21976 318 24X
Fiche 50-458, 84/01/19, B401270332

B401270339 Interim Deficiency Rept DR-118 re penetration of welds for platform channels on primary shield wall investigation continuing Next rept by B40326
BOOKER, J E Gulf States Utilities Co 84/01/19 COLLINS, J T
Region 4, Office of Director 1p 21976 323. 24X
Fiche 50-458, 84/01/19, B401270339

DOCKETED ITEMS

B401270503 Interim Deficiency Rept DR-143 re instrument tubing supports in auxiliary bldg. Investigation incomplete. Next rept will be provided by B40416.
BOOKER, J. E. Gulf States Utilities Co. 84/01/19 COLLINS, J. T. Region 4, Office of Director. 1p 21981 347 24X
Fiche: 50-458, 84/01/19, B401270503.

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants.
MATHEWS, C. S. Transamerica Delaval, Inc. 83/12/16 NOVAK, T. M. Assistant Director for Licensing. 19pp 22034-358 24X
Fiche: 50-000, 83/12/16, B312200154

B401040284 Outlines procedures for reporting info promptly to region by using given telephone numbers for o/c & outside-of-o/c hours. Util urged to use numbers.
COLLINS, J. T. Region 4, Office of Director. 83/12/19 CAHILL, W. J. Gulf States Utilities Co. 2pp 21701 209 24X
Fiche: 50-458, 83/12/19, B401040284

B401050210 Forwards info providing addl justification for absence of ammonia & chlorine detectors at facilities. Info suppld B31017 ltr. No adverse effects expected. Info will be reflected in future amend to FSAR.
BOOKER, J. E. Gulf States Utilities Co. 83/12/20, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 21728:122. 24X
Fiche: 50-458, 83/12/20, B401050210

B401050271 Suppld B20219 responses to NRC B10805 & 1217 ltrs on ODC 51 re fracture prevention of containment pressure boundary metls.
BOOKER, J. E. Gulf States Utilities Co. 83/12/21 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 43pp 21727:183 24X
Fiche: 50-458, 83/12/21, B401050271

B401060241 Notification of B40106 meeting w/util in Arlington, TX to discuss mgt organization safety evaluation review.
WEINKAM, E. J. Licensing Branch 2. 83/12/23 SCHWENCER, A. Licensing Branch 2. 3pp. 21753:147 24X
Fiche: 50-458, 83/12/23, B401060241.

B401105560 Forwards TM Novak B31227 request to Mississippi Power & Light Co. for addl info re emergency diesel generators mgt by Transamerica Delaval, Inc. Plant-specific response required.
SCHWENCER, A. Licensing Branch 2. 83/12/29 CAHILL, W. J. Gulf States Utilities Co. 2pp 21793:325 24X
Fiche: 50-458, 83/12/29, B401105560

B401250203 Forwards addl info re FSAR changes & supplemental clarifications to previously submitted responses, per B20202 & B31114 requests. FSAR changes will be included in next amend.
BOOKER, J. E. Gulf States Utilities Co. 83/12/30, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 400pp. 21933.045 24X
Fiche: 50-458, 83/12/30, B401250203

B401050382 Generic Ltr 84-01 to all holders of OLEs, applicants for OLEs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl.
EISENHUT, D. G. Division of Licensing. 84/01/03 Consolidated Edison Co. of New York, Inc. 16pp 21946 190 24X
Fiche: 50-000, 84/01/03, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLEs & full power authorizations re notice of meeting on facility staffing.
Svc list encl.
EISENHUT, D. G. Division of Licensing. 84/01/06. Consolidated Edison Co. of New York, Inc. 18pp 21957:267. 24X
Fiche: 50-000, 84/01/06, B401090221

B401190494 Notifies that on B40105 util board of directors announced cancellation of Unit 2.
WEINKAM, E. J. Licensing Branch 2. 84/01/09, DENTON, H. R., CASE, E. O., CARTER, J. Office of Nuclear Reactor Regulation, Director. 1p. 21861:335. 24X
Fiche: 50-459, 84/01/09, B401190494.

B401130455 Summary of B31201 meeting w/util in Bethesda, MD re equipment qualification programs.
WEINKAM, E. J. Licensing Branch 2. 84/01/10. Licensing Branch 2. 22pp. 21819:317. 24X
Fiche: 50-458, 84/01/10, B401130455

B401190191 Summary of B30929 meeting w/util & S&W in Cherry Hill, NJ re design basis flood level.
WEINKAM, E. J. Licensing Branch 2. 84/01/10. Licensing Branch 2. 3pp. 21870:022. 24X
Fiche: 50-458, 84/01/10, B401190191.

B401190200 Summary of B31130 meeting w/util & S&W in Bethesda, MD re control room ventilation isolation requirements.
WEINKAM, E. J. Licensing Branch 2. 84/01/10. Licensing Branch 2. 4pp. 21870 017 24X
Fiche: 50-458, 84/01/10, B401190200

B401190272 Summary of B31118 meeting w/util & S&W in Bethesda, MD re containment sys topics, including hydrogen ignition & containment purge.
WEINKAM, E. J. Licensing Branch 2. 84/01/10. Licensing Branch 2. 48pp. 21869 282. 24X
Fiche: 50-459, 84/01/10, B401190272

B401190289 Summary of B31108 meeting w/util & S&W re piping supports program.
WEINKAM, E. J. Licensing Branch 2. 84/01/10. Licensing Branch 2. 4pp. 21870 056 24X
Fiche: 50-458, 84/01/10, B401190289

B401240034 Summary of B31115-16 meetings w/util re FSAR Chapter 13 topics concerning mgt organization.
WEINKAM, E. J. Licensing Branch 2. 84/01/12. Licensing Branch 2. 4pp. 21945:041 24X
Fiche: 50-458, 84/01/12, B401240034

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLEs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl.
EISENHUT, D. G. Division of Licensing. 84/01/13 Consolidated Edison Co. of New York, Inc. 18pp 21946 174 24X
Fiche: 50-000, 84/01/13, B401130084

C Utility Environmental Report (ER), amends & correspondence

B401060291 Forwards response to environ rept - OL stage. Review Question E460 1 re radwaste mgt sys info forwarded per Generic Ltr B2-14.
BOOKER, J. E. Gulf States Utilities Co. 83/12/29 SCHWENCER, A. Licensing Branch 2. 9pp 21741 343 24X
Fiche: 50-458, 83/12/29, B401060291

B401310241 Forwards Suppl 7 to environ rept - OL stage. Liquid radwaste treatment sys revs described.
CAHILL, W. J. Gulf States Utilities Co. 84/01/27 EISENHUT, D. G. Division of Licensing. 7pp 22013 274. 24X
Fiche: 50-458, 84/01/27, B401310241.

--B401310247 Suppl 7 to environ rept - OL stage.
* Gulf States Utilities Co. 84/01/27 299pp 22013 281 24X
Fiche: 50-458, 84/01/27, B401310241

E. NRC Safety Evaluation Report (SER), suppl & correspondence

B401310439 Forwards responses to open items identified in draft SER & discussed w/Chemical Engineering Branch in Bethesda, MD on 830525 Encls 3-10 will be included in next FSAR amend.
BOOKER, J. E. Gulf States Utilities Co. 83/11/08 SCHWENCER, A. Licensing Branch 2. 48pp 22012, 260 24X
Fiche: 50-458, 83/11/08, B401310439.

B312290417 Forwards responses to draft SER open items, Licensing Review Group-II Positions I-13-R88 & TMI action plan requirements requested in B30421 ltr.
BOOKER, J. E. Gulf States Utilities Co. 83/12/12, DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83pp 21660 098 24X
Fiche: 50-458, 83/12/12, B312290417.

B401050169 Forwards response to open item identified in draft SER re structures, sys & components covered by GA program Response provides ref to revised FSAR Table 3 2-1 & necessary justification for items not included.
BOOKER, J. E. Gulf States Utilities Co. 83/12/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 48pp. 21727 280 24X
Fiche: 50-458, 83/12/22, B401050169

B40110072 Forwards response to draft SER open items identified by NRC Mechanical Engineering Branch & response to NRC B31207 ltr requesting further clarification on design of pipe/component supports.
BOOKER, J. E. Gulf States Utilities Co. 83/12/29 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 118pp 21772.087 24X
Fiche: 50-458, 83/12/29, B40110072.

B401040528 Forwards responses to draft SER open items identified by Core Performance Branch, per A Schwencer B31206 request Ltr suppld info contained in B31111 ltr Attachment 1 summarizes open items & indicates changes to be made in FSAR.
BOOKER, J. E. Gulf States Utilities Co. 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 20pp 21707 275 24X
Fiche: 50-458, 83/12/30, B401040528

DOCKETED ITEMS

357

8401090105 Forwards responses to open items identified in draft SER & response to 810805 & 1231 requests for addl info Responses will be provided in future FSAR amend
BOOKER, J.E. Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 27pp 21753 209
24X Fiche 50-458, 83/12/30, 8401090105

8401130313 Forwards changes to FSAR Section 2.4 in response to items identified by Environ & Hydrological Engineering Branch in draft SER re local flooding Changes will be incorporated into next FSAR amend
BOOKER, J.E. Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 90pp 21801 229
24X Fiche 50-458, 83/12/30, 8401130313

8401130388 Forwards response to items identified by Containment Sys Branch in draft SER & 810805, 1231 & 831202 ltra Encl FSAR changes will be included in future FSAR amend W/21 oversize drawings. Aperture cards are available in PDR
BOOKER, J.E. Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 185pp 21833 001.
24X Fiche 50-458, 83/12/30, 8401130388

8401190189 Summary of 830928 meeting w/util & S&W in Cherry Hill, NJ re Mechanical Engineering Branch draft SER open items.
WEINKAM, E.J. Licensing Branch 2 84/01/10 Licensing Branch 2.
4pp 21870 025 24X Fiche 50-458, 84/01/10, 8401190189

8401190285 Summary of 830928-29 meetings w/util & S&W in Cherry Hill, NJ re Auxiliary Sys Branch draft SER open items.
WEINKAM, E.J. Licensing Branch 2 84/01/10 Licensing Branch 2
8pp. 21870 060 24X Fiche 50-458, 84/01/10, 8401190285

8401270245 Forwards response to Core Performance Branch draft SER open items re post-irradiation monitoring program & inadequate core cooling (NUREG-0737, Item II F 2) Indicated responses will be included in future FSAR amend
BOOKER, J.E. Gulf States Utilities Co 84/01/20, DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 21982, 141
24X Fiche 50-458, 84/01/20, 8401270245

F Security, medical, emergency & fire protection plans

8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents, App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J.M. Division of Rules and Records 83/11/02 D'NEILL, J H
Shaw, Pittman, Potts & Trowbridge 6pp 21957:357 24X
Fiche 50-000, 83/11/02, 8401250163

--8305160329 Recommends that Commission concur w/NRC approval of location of emergency operations facilities slightly beyond 20-mile limitations in Suppl 1 to NUREG-0737
DIRCKS, W.J. Office of the Executive Director for Operations.
SECY-83-152 83/04/28 44pp 21958 041 24X
Fiche 50-000, 83/11/02, 8401250163

8401090153 Forwards revised FSAR Table 13.3-1, "Emergency Action Levels: Initiating Conditions & Emergency Response" Marked items being developed as part of Tech Specs scheduled for submittal in June 1984 Info to be included in revised FSAR.
BOOKER, J.E. Gulf States Utilities Co 83/12/30 DENTON, H R
Office of Nuclear Reactor Regulation, Director 37pp 21754 304
24X Fiche 50-458, 83/12/30, 8401090153

8401230120 Summary of 831013 meeting w/util, S&W & State of LA at facility training ctr re upcoming emergency appraisal team visit
WEINKAM, E.J. Licensing Branch 2 84/01/12 Licensing Branch 2
4pp. 21931.001 24X Fiche 50-458, 84/01/12, 8401230120.

8401200291 Releases public version of state radiological emergency response plans
FELTON, J.M. Division of Rules and Records 84/01/17 Document
Management Branch 1p 21887:326 24X Fiche. 50-458, 84/01/17,
8401200291

--8401200296 Forwards public version of radiological emergency response plans for States of LA & MS
BOOKER, J.E. Gulf States Utilities Co 83/12/28 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 1p 21887:329.
24X Fiche: 50-458, 84/01/17, 8401200291

--8401200300 Public version of radiological emergency response plans for States of LA & MS,
* Gulf States Utilities Co. 83/12/31 573pp 21887.330. 24X
Fiche: 50-458, 84/01/17, 8401200291.

G Adjudicatory correspondence

8401100146 Informs of board of directors vote not to build Unit 2
CONNER, T.B. Conner & Wetterhahn CONNER, T.B. Gulf States Utilities
Co 84/01/06 COTTER, B.P., CDLE, R.F., LINENBERGER, O Atomic Safety
and Licensing Board Panel 1p 21760 033 24X
Fiche 50-458, 84/01/06, 8401100146

H Antitrust correspondence

8401090101 Forwards FR notice of receipt of addl antitrust info for application for OL Notices re health & safety & environ issues under review published separately
SCHWENGER, A. Licensing Branch 2 83/12/20 CAHILL, W.J. Gulf
States Utilities Co 2pp 21757 238 24X Fiche 50-458, 83/12/20,
8401090101

--8401090108 Notice of receipt of addl antitrust info for application for OL
SCHWENGER, A. Licensing Branch 2 83/12/20 3pp. 21757 240 24X
Fiche 50-458, 83/12/20, 8401090101

I Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J.M. Division of Rules and Records. 83/10/20 ZAHLER, R.E
Shaw, Pittman, Potts & Trowbridge 1p. 21744:003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004 24X Fiche: 50-000, 83/10/20,
8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/12/28. Consolidated Edison Co. of New York, Inc.
124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/12/30. Consolidated Edison Co. of New
York, Inc 127pp 21826:060 24X Fiche: 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/10. Consolidated Edison Co. of New
York, Inc 125pp. 21746 053 24X Fiche: 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/10. Consolidated Edison Co. of New
York, Inc 122pp 21826 184 24X Fiche: 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/16. Consolidated Edison Co. of New
York, Inc 127pp 21957 142. 24X Fiche: 50-000, 84/01/16, 8312120114

8401300028 Notification of 840126 meeting w/util & Transamerica Delaval, Inc (TDI) in Bethesda, MD to discuss actions required to address insp results & operating experience re TDI emergency diesel generators
CARUBO, R. Licensing Branch 2. 84/01/17, SCHWENGER, A. Licensing
Branch 2. 21pp 22027:009 24X Fiche: 50-000, 84/01/17, 8401300028

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18. Consolidated Edison Co. of New
York, Inc 118pp 22000 001 24X Fiche: 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 84/01/18. Consolidated Edison Co. of New
York, Inc 120pp 22000.041 24X Fiche: 50-000, 84/01/18, 8312120117.

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utilis notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 269 24X
Fiche 50-000, 84/01/09, B401170186

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1A Application/construction stage documents & correspondence

B312200154 Forwards response to nine Users Group questions presented at B31130 meeting & forwarded by R Caruso B31129 ltr re standby diesel generators at nuclear power plants
MATHEWS, C S Transamerica Delaval, Inc 83/12/16 NOVAK, T M Assistant Director for Licensing 19pp 22054 358 24X
Fiche 50-000, 83/12/16, B312200154

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profiles for new plants.
HANMON, J Division of Licensing 84/01/17. Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

C Adjudicatory correspondence

B401050191 Submits first quarterly status rept re const activities, per ASLB B31014 memorandum & order. No const activities performed at facility during Fourth Quarter 1983, although limited engineering effort continuing.
REYNOLDS, N B Debevoise & Liberman REYNOLDS, N B Washington Public Power Supply System 83/12/30 GROSSMAN, H, HARBOUR, J, BRIGHT, O O Atomic Safety and Licensing Board Panel 1p 21727 242 24X Fiche 50-460, 83/12/30, B401050191

H General correspondence

B401240335 Informs that firm name of counsel for applicants/licensees changed from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds 84/01/19 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X
Fiche 50-000, 84/01/19, B401240335

J Insurance & indemnity information

B401110001 Forwards Endorsements 9-12 to NELIA Policy NF-270.
ABKURN, D J Marsh & McLennan, Inc 84/01/04 SALTZMAN, J Assistant Director for State & License Relations 6pp 21772 246 24X Fiche 50-397, 84/01/04, B401110001

K. Utility Final Safety Analysis Report (FSAR) & amends

B401100185 Forwards Certificate of Svc re Amend 3 to FSAR, State of WA atty general ofc removed from FSAR distribution list
SORENSEN, O C Washington Public Power Supply System 84/01/04 ADENSAH, E O Licensing Branch 4 3pp 21759 248 24X
Fiche 50-460, 84/01/04, B401100185

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982.
* Director's Office, Office of Inspection and Enforcement 83/10/20 134pp 21744 004. 24X Fiche 50-000, 83/10/20, B401060040.

S. Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utilis notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement. 5pp 21828 269 24X
Fiche 50-000, 84/01/09, B401170186.

DOCKET 50-461 CLINTON POWER STATION, UNIT 1A Application/construction stage documents & correspondence

B401230490 Requests that Stop Work Orders 014, 015 & 020 re HVAC installation be lifted due to completed recovery plan to correct deficiencies Procedures & instructions revised & training accomplished & documented
HALL, D P Illinois Power Co 83/12/15 KEPLER, J O Region 3, Office of Director 1p 21882 096 24X Fiche 50-461, 83/12/15, B401230490

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "Important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/03 Consolidated Edison Co of New York, Inc 16pp 21946, 190 24X
Fiche 50-000, 84/01/03, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946, 174 24X
Fiche 50-000, 84/01/13, B401130084

B401310363 Clarifies B10925 ltr re NUREG-0612, "Control of Heavy Loads" Permanent crane rail stops will be installed prior to fuel load to prevent fuel bldg crane travel over spent fuel storage pool throughout remaining plant life
GEIER, J D Illinois Power Co 84/01/26 SCHMENCER, A Licensing Branch 2 1p 22026 255 24X Fiche 50-461, 84/01/26, B401310363

E NRC Safety Evaluation Report (SER), suppl & correspondence

B401030293 Summary of B30923 meeting w/util & Sargent & Lundy in Bethesda, MD re outstanding SER Issue 1, "Toxic & Explosive Hazards from Railroad Accidents"
HARRISON, O Licensing Branch 2 83/12/20. Licensing Branch 2 4pp. 21693 355 24X Fiche 50-461, 83/12/20, B401030293

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 6pp 21957 357 24X
Fiche 50-000, 83/11/02, B401250163.

--B305160329 Recommends that Commission concur w/NRC approval of location of emergency operations facilities slightly beyond 20-mile limitations in Suppl 1 to NUREG-0737.
DIRCKS, W J Office of the Executive Director for Operations BECY-83-132 83/04/28 44pp 21958 041 24X
Fiche 50-000, 83/11/02, B401250163

B401030197 Forwards Amend 28 to FSAR, consisting of rev to App 13 D, "Emergency Plan" & revs to Chapter 12, "Radiation Protection"
HALL, D P Illinois Power Co 83/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p. 21679 001 24X
Fiche 50-461, 83/12/20, B401030197

--B401030203 Amend 28 to FSAR
* Illinois Power Co, 83/12/31. 467pp 21679 002 24X
Fiche 50-461, 83/12/20, B401030197

B401230143 Requests attendance at FEMA radiological emergency preparedness program B40112-13 meetings in Chicago, IL to develop final FY84/85 emergency preparedness exercise & prompt alert & notification certification schedules.
PAPERIELLO, C J Region 3, Office of Director 84/01/05 GERSTNER, W C Illinois Power Co 3pp 21884 319 24X
Fiche 50-461, 84/01/05, B401230143.

B401240018 Notification of B40131-0202 meetings w/util at mtr to discuss emergency planning.
HARRISON, O Licensing Branch 2 84/01/12 SCHMENCER, A Licensing Branch 2 3pp 21945 045 24X Fiche 50-461, 84/01/12, B401240018.

DOCKETED ITEMS

359

C Adjudicatory correspondence

B401250231 Forwards Region III B40111 memo re present interest of local residents in siting of OL proceedings in vicinity of Clinton, IL NRC supports conducting some, but not all, of hearings in Clinton area
GODDARD, R J Hearing Branch 3 84/01/13 CLARK, H K, PARIS, D H, FERGUSON, G A Atomic Safety and Licensing Board Panel 2pp
21944 132 24X Fiche 50-461, 84/01/13, B401250231

B401230420 Requests designation of site in Clinton, IL for public OL hearings, per B40113 ltr informing of Mayor Stites suggestion re hearing location
PARIS, D H Atomic Safety and Licensing Board Panel 84/01/19
GODDARD, R J Hearing Branch 3 1p 21879 190 24X
Fiche 50-461, 84/01/19, B401230420

H General correspondence

B401310361 Advises that DI Herborn, assumed position of director, nuclear licensing & configuration, effective B40123
HALL, D P Illinois Power Co 84/01/25 SCHWENGER, A Licensing Branch 2. 1p 22018 361 24X Fiche 50-461, 84/01/25, B401310361

K Utility Final Safety Analysis Report (FSAR) & amends

B401030197 Forwards Amend 2B to FSAR, consisting of rev to App 13 B, "Emergency Plan" & revs to Chapter 12, "Radiation Protection"
HALL, D P Illinois Power Co 83/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 21679 001 24X
Fiche 50-461, 83/12/20, B401030197

--B401030203 Amend 2B to FSAR
* Illinois Power Co 83/12/31 467pp 21679 002 24X
Fiche 50-461, 83/12/20, B401030197

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement.
83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401050475 Forwards comprehensive review of vendors & suppliers, per IE Bulletin 83-07 No Ray Miller, Inc matl supplied through QE or Baldwin Assoc
HALL, D P Illinois Power Co 83/12/20 KEPLER, J O Region 3, Office of Director 3pp 21729 355 24X Fiche 50-461, 83/12/20, B401050475

B401050527 Responds to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Matls will be qualified by demonstrating suitability or replaced w/matls mfg per ASME Code Section III Updated rept expected by B40423
HALL, D P Illinois Power Co 83/12/23 KEPLER, J O Region 3, Office of Director 3pp 21735 358 24X Fiche 50-461, 83/12/23, B401050527

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28. Consolidated Edison Co. of New York, Inc 124pp. 21731.166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5MK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30. Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10. Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10. Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16. Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B401230341 Ack receipt of B40110 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-461/83-15
STREETEY, J F Region 3, Office of Director 84/01/17
GERSTNER, W C Illinois Power Co 1p 21882 343 24X
Fiche 50-461, 84/01/17, B401230341

--B401230345 Responds to NRC B30929 ltr re noncompliance noted in IE Insp Rept 50-461/83-15 Corrective actions piping/mechanical QC insp criteria piping sys fabrication/installation procedure revised to clarify insp frequency
HALL, D P Illinois Power Co 84/01/10 KEPLER, J O Region 3, Office of Director 2pp 21882 344 24X Fiche 50-461, 84/01/17, B401230341

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18. Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18. Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche 50-000, 84/01/18, B312120117

S Reportable occurrences, LERs & related correspondence

B401050385 Interim Deficiency Rept 55-83-02 re lack of counterboring insp in safety-related pipe initially reported on B30113
Approx 346 piping joints involved Further investigation on joints performed
HALL, D P Illinois Power Co 83/12/20 KEPLER, J O Region 3, Office of Director 4pp. 21733:355 24X Fiche 50-461, 83/12/20, B401050385

B401040418 PNO-III-83-135 on 831222, three remaining stop work orders involving HVAC sys lifted per util request Prior to concurring in lifting work procedures, training & certification of welders reviewed
MARABITO, R, HAYES, D Region 3, Office of Director 83/12/22 1p 21706 209 24X Fiche 50-461, 83/12/22, B401040418

B401050456 Interim Deficiency Rept 82-12 re binding of sway strut/wrubbler piping component supports Initially reported on B21021 Defective parts tagged & segregated to prevent inadvertent use Final rept will be submitted in 90 days
HALL, D P Illinois Power Co. 83/12/22 KEPLER, J O Region 3, Office of Director 4pp 21724.155 24X Fiche 50-461, 83/12/22, B401050456

B401050469 Part 21 rept re defect in Electrosch Series 20k control switches Engineering completion & procurement of replacement switches expected by B40401 instead of B31231 estimated completion date
HALL, D P Illinois Power Co. 83/12/22 KEPLER, J O Region 3, Office of Director 1p. 21733 360 24X Fiche 50-461, 83/12/22, B401050469

B401060433 Interim deficiency rept re welding on containment liner dome closure weld seam Initially reported on B31201 Investigation proceeding, Final rept expected in approx 90 days
HALL, D P Illinois Power Co 83/12/29 KEPLER, J O Region 3, Office of Director. 3pp. 21741:060. 24X Fiche 50-461, 83/12/29, B401060433

B401160283 Part 21 rept re defects in Anchor Darling globe valves previously identified in IE Info Notice 83-70 & GE 831216 ltr Globe valves will be modified by QE to assure valve operability.
HALL, D P Illinois Power Co 84/01/09. KEPLER, J O Region 3, Office of Director. 2pp 21814:349. 24X Fiche 50-461, 84/01/09, B401160283

--B401160288 Part 21 rept re defects in Anchor Darling globe valves previously identified in IE Info Notice 83-70, "Vibration Induced Valve Failure." Set screws will be locked in place by staking stem collar threads or using locking compound.
SHERWOOD, G O General Electric Co. 83/12/14 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 3pp. 21814.351 24X Fiche 50-461, 84/01/09, B401160283

DOCKETED ITEMS

B401190334 Interim Deficiency Rept 55-B3-11 re laminations in 3/8-inch steel plates. Investigation continuing to determine extent & end user of potentially defective plate matl. Statement re matl defects expected in 90 days.
HALL, D. P. Illinois Power Co. 84/01/10. KEPLER, J. O. Region 3, Office of Director. 3pp. 21851:263. 24X Fiche 50-461, 84/01/10.
B401190334

B401230322 Interim Deficiency Rept 55-B2-09 re small bore/ instrumentation piping & conduit support design calculations. Initially reported on 820902 Sargent & Lundy procedures for support design corrected & clarified.
HALL, D. P. Illinois Power Co. 84/01/12. KEPLER, J. O. Region 3, Office of Director. 7pp. 21883 310. 24X Fiche 50-461, 84/01/12.
B401230322.

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

B401230143 Requests attendance at FEMA radiological emergency preparedness program B40112-13 meetings in Chicago, IL to develop final FY84/85 emergency preparedness exercise & prompt alert & notification certification schedules.
PAPERIELLO, C. J. Region 3, Office of Director. 84/01/05. GERSTNER, W. C. Illinois Power Co. 3pp. 21884 319. 24X Fiche: 50-461, 84/01/05, B401230143.

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results during 1982. Forwards IE notebook tabulating requested info. Notebook also available in PDR.
FELTON, J. M. Division of Rules and Records. 83/10/20. ZAHNER, R. E. Shaw, Pittman, Potts & Trowbridge. 1p. 21744:003. 24X Fiche: 50-000, 83/10/20, B401060040.

--B401060150 List of SAMP results during 1982.

* Director's Office, Office of Inspection and Enforcement.
83/10/20, 134pp. 21744.004. 24X Fiche: 50-000, 83/10/20, B401060040.

DOCKET 50-463 FULTON GENERATING STATION, UNIT 1

Adjudicatory correspondence

1401040108 Objection to ASLB B31214 proposed decision & order for dismissal of proceeding w/prejudice Dismissal w/prejudice constitutes unusual action & would convey erroneous impression. Certificate of Svc encl.
TURK, B. E. Hearing Branch 1. 83/12/29. Atomic Safety and Licensing Board Panel. 6pp. 21703:252. 24X Fiche: 50-463, 83/12/29, B401040108.

B401050297 Forwards objection to ASLB B31230 proposed decision & order dismissing proceeding w/prejudice Motion for summary decision & for termination of proceedings as moot & w/o prejudice encl.
IRWIN, D. P. Hunton & Williams. IRWIN, D. P. Philadelphia Electric Co. 83/12/29. COTTER, B. P., LINENBERGER, G., DESYLVA, D. P. Atomic Safety and Licensing Board Panel. 4pp. 21729 006. 24X Fiche: 50-463, 83/12/29, B401050297.

1401050302 Objection to & motion for mod of B31214 proposed decision & order dismissing proceeding w/prejudice Dismissal w/prejudice would require full adjudicatory hearing.
IRWIN, D. P. Philadelphia Electric Co. IRWIN, D. P. Hunton & Williams. 83/12/29. Atomic Safety and Licensing Board Panel. 18pp. 21729:010. 24X Fiche: 50-463, 83/12/29, B401050297.

--B401050307 Motion for summary decision & for termination of proceedings as moot & w/o prejudice. Statement of matl facts & Certificate of Svc encl.
IRWIN, D. P. Philadelphia Electric Co. IRWIN, D. P. Hunton & Williams. 83/12/29. Atomic Safety and Licensing Board Panel. 41pp. 21729:028. 24X Fiche: 50-463, 83/12/29, B401050297.

1401090363 Forwards VS Boyer executed affidavit which should be filed w/utl B31229 papers.
IRWIN, D. P. Hunton & Williams. 84/01/04. COTTER, B. P., LINENBERGER, G., DESYLVA, D. P. Atomic Safety and Licensing Board Panel. 1p. 21754:061. 24X Fiche: 50-463, 84/01/04, B401090363.

--B401090368 Affidavit of VS Boyer to be appended to B31229 filing Certificate of Svc encl.
BOYER, V. S. Philadelphia Electric Co. 84/01/03. 4pp. 21754:062. 24X Fiche: 50-463, 84/01/04, B401090363.

B401120324 Response opposing NRC & applicant objections to ASLB B31214 proposed decision & order dismissing application w/ prejudice Proposed mods should be rejected Certificate of Svc encl.
JOHNBRUD, J. H. York Committee for Safe Environment. 84/01/07. Atomic Safety and Licensing Board Panel. 4pp. 21792:133. 24X Fiche: 50-463, 84/01/07, B401120324.

B401250186 Answer supporting utl B31229 motions for summary disposition & mod of proposed decision & order Dismissal of proceeding w/o prejudice recommended Certificate of Svc encl.
TURK, B. E. Hearing Branch 1. 84/01/13. Atomic Safety and Licensing Board Panel. 7pp. 21935:203. 24X Fiche 50-463, 84/01/13, B401250186.

B401260195 Request for leave to encl reply to York intervenors B40107 response to objections of NRC & applicant to ASLB proposed decision & order re withdrawal of facility application Certificate of Svc encl.

IRWIN, D. P. Philadelphia Electric Co. 84/01/23. Atomic Safety and Licensing Board Panel. 7pp. 21956:160. 24X Fiche 50-463, 84/01/23, B401260195.

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

Q. Adjudicatory correspondence

B401040108 Objection to ASLB B31214 proposed decision & order for dismissal of proceeding w/prejudice Dismissal w/prejudice constitutes unusual action & would convey erroneous impression. Certificate of Svc encl.
TURK, B. E. Hearing Branch 1. 83/12/29. Atomic Safety and Licensing Board Panel. 6pp. 21703:252. 24X Fiche 50-463, 83/12/29, B401040108.

B401050297 Forwards objection to ASLB B31230 proposed decision & order dismissing proceeding w/prejudice Motion for summary decision & for termination of proceedings as moot & w/o prejudice encl.
IRWIN, D. P. Hunton & Williams. IRWIN, D. P. Philadelphia Electric Co. 83/12/29. COTTER, B. P., LINENBERGER, G., DESYLVA, D. P. Atomic Safety and Licensing Board Panel. 4pp. 21729:006. 24X Fiche 50-463, 83/12/29, B401050297.

--B401050302 Objection to & motion for mod of B31214 proposed decision & order dismissing proceeding w/prejudice Dismissal w/prejudice would require full adjudicatory hearing.
IRWIN, D. P. Philadelphia Electric Co. IRWIN, D. P. Hunton & Williams. 83/12/29. Atomic Safety and Licensing Board Panel. 18pp. 21729:010. 24X Fiche 50-463, 83/12/29, B401050297.

--B401050307 Motion for summary decision & for termination of proceedings as moot & w/o prejudice. Statement of matl facts & Certificate of Svc encl.
IRWIN, D. P. Philadelphia Electric Co. IRWIN, D. P. Hunton & Williams. 83/12/29. Atomic Safety and Licensing Board Panel. 41pp. 21729:028. 24X Fiche 50-463, 83/12/29, B401050297.

B401090363 Forwards VS Boyer executed affidavit which should be filed w/utl B31229 papers.
IRWIN, D. P. Hunton & Williams. 84/01/04. COTTER, B. P., LINENBERGER, G., DESYLVA, D. P. Atomic Safety and Licensing Board Panel. 1p. 21754:061. 24X Fiche: 50-463, 84/01/04, B401090363.

--B401090368 Affidavit of VS Boyer to be appended to B31229 filing Certificate of Svc encl.
BOYER, V. S. Philadelphia Electric Co. 84/01/03. 4pp. 21754:062. 24X Fiche: 50-463, 84/01/04, B401090363.

B401120324 Response opposing NRC & applicant objections to ASLB B31214 proposed decision & order dismissing application w/ prejudice Proposed mods should be rejected Certificate of Svc encl.
JOHNBRUD, J. H. York Committee for Safe Environment. 84/01/07. Atomic Safety and Licensing Board Panel. 4pp. 21792:133. 24X Fiche: 50-463, 84/01/07, B401120324.

B401250186 Answer supporting utl B31229 motions for summary disposition & mod of proposed decision & order Dismissal of proceeding w/o prejudice recommended Certificate of Svc encl.
TURK, B. E. Hearing Branch 1. 84/01/13. Atomic Safety and Licensing Board Panel. 7pp. 21935:203. 24X Fiche 50-463, 84/01/13, B401250186.

B401260195 Request for leave to encl reply to York intervenors B40107 response to objections of NRC & applicant to ASLB proposed decision & order re withdrawal of facility application Certificate of Svc encl.
IRWIN, D. P. Philadelphia Electric Co. 84/01/23. Atomic Safety and Licensing Board Panel. 7pp. 21956:160. 24X Fiche 50-463, 84/01/23, B401260195.

DOCKETED ITEMS

361

DOCKET BTN-30-470 CESSAR SYSTEM 80

A Application/construction stage documents & correspondence

B401090783 Forwards Final Design Approval FDA-2 for C-E Sys 80 NSSS ref design described in CESSAR-F FDA viewed as major milestone in standardization policy
EISENHUT, D O Division of Licensing 83/12/21 SCHERER, A E
Combustion Engineering, Inc 2pp 21767 013 24X
Fiche 50-470, 83/12/21, B401090783

--B401090786 Final Design Approval FDA-2 for CESSAR-F Sys 80 standardized ref design
EISENHUT, D O Division of Licensing 83/12/21 4pp 21767 015
Fiche 50-470, 83/12/21, B401090783

DOCKET BTN-30-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

B401170213 Advises of inability to provide certain limited number of preoperational test procedures within 60 days prior to scheduled implementation, as required in FSAR Section 14.2.3. One oversize schedule encl Aperture card available in PDR
KOESTER, O L Kansas Gas & Electric Co 83/12/09 GAGLIARDO, J E
Region 4, Office of Director 2pp 21833, 287 24X
Fiche 50-482, 83/12/09, B401170213

B401030272 Requests NRC certification by 831219 re control of atmospheric pollution, in connection w/issuance of pollution control bonds
TERRILL, R D Kansas Gas & Electric Co 83/12/13 HOLONICH, J
Office of Nuclear Reactor Regulation, Director 7pp 21681 278
24X Fiche 50-482, 83/12/13, B401030272

B401040244 Outlines procedures for reporting info promptly to region by using given telephone numbers for ofc & outside-of-ofc hours. Util urged to use numbers
COLLINS, J T Region 4, Office of Director 83/12/19 KOESTER, O L
Kansas Gas & Electric Co 2pp 21701 168 24X
Fiche 50-482, 83/12/19, B401040244

B401090390 Forwards NRC certification for furtherance of abating or controlling atmospheric pollution, per 831213 ltr.
DENTON, H R Office of Nuclear Reactor Regulation, Director.
83/12/29 TERRILL, R D Kansas Gas & Electric Co 1p 21768, 060.
24X Fiche 50-482, 83/12/29, B401090390

--B401090398 Certification that listed sys, as designed, control & abate water pollution & atmospheric pollutants.
DENTON, H R Office of Nuclear Reactor Regulation, Director.
83/12/29 2pp 21768 061 24X Fiche 50-482, 83/12/29, B401090390

B312120098 Summary Board Notification 83-191 forwards Board Notification 82-75, "Accident Sequence Precursor Program Rept." re licensing review of facility Matl not addressed in BER, FES, or SSER & irrelevant to emergency plan contention
NOVAK, T M Assistant Director for Licensing 83/12/30 Atomic
Safety and Licensing Board Panel 2pp 21739, 303 24X
Fiche 50-482, 83/12/30, B312120098

B401090048 Summary of 831025 meeting w/utills & SNUPPS, ARD Corp & Science Applications, Inc re NRC review of SNUPPS detailed control room design review program plan for facilities
HOLONICH, J J Licensing Branch 1 83/12/30 Licensing Branch 1
4pp 21757 274, 24X Fiche 50-000, 83/12/30, B401090048

B401190089 Requests summary of differences in design process between Wolf Creek & Callaway & applicability of Callaway integrated design insp rept findings to Wolf Creek Info requested in 60 days
EISENHUT, D O Division of Licensing 84/01/04, KOESTER, O L
Kansas Gas & Electric Co 3pp 21870 254, 24X
Fiche 50-482, 84/01/04, B401190089

B312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification. Bandia position is that NRC environ qualification program has problems.
EISENHUT, D O Division of Licensing 84/01/05, PALLADINO, N J
Commissioners Rpp 21993, 324 24X Fiche 50-000, 84/01/05, B312120108

B401030382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190, 24X
Fiche 50-000, 84/01/05, B401030382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D O Division of Licensing 84/01/06, Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401100204 Forwards revised FSAR Page 5 2-9 clarifying precautions for solid water operation. Clarification will be included in Rev 13 to FSAR to be submitted by Feb 1984
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/01/06 DENTON, H R Office of Nuclear Reactor Regulation,
Director 2pp 21759 282 24X Fiche 50-000, 84/01/06, B401100204

B401100405 Forwards revised pages of radiological effluent Tech Specs Revs result of discussions at 831219 meetings
KOESTER, O L Kansas Gas & Electric Co 84/01/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 21762 246
24X Fiche 50-482, 84/01/06, B401100405

--B401100410 Revised pages of radiological effluent Tech Specs
* Kansas Gas & Electric Co. 84/01/06 29pp 21762 248 24X
Fiche 50-482, 84/01/06, B401100410

B401130153 Forwards revised FSAR Page 14 2-62, modifying accumulator testing abstract of safety-related preoperational test procedures Mod will be included in Rev 13 to FSAR scheduled for submittal in Feb 1984
PETRICK, N A Standardized Nuclear Unit Power Plant System
84/01/09 DENTON, H R Office of Nuclear Reactor Regulation,
Director 2pp 21798 358 24X Fiche 50-000, 84/01/09, B401130153

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0733, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D O Division of Licensing 84/01/13, Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401180114 Forwards revised pages to GA program info will be incorporated into upcoming rev to FSAR & into DL application
KOESTER, O L Kansas Gas & Electric Co 84/01/13 DENTON, H R,
Office of Nuclear Reactor Regulation, Director COLLINS, J T, Region
4, Office of Director. 62pp 21842 008 24X Fiche 50-482, 84/01/13, B401180114

B401200059 Forwards "Purge Valve Operability Rept. SNUPPS Project," per Licensing Confirmatory Issues 28, II E 4.2 & B 28, II E 4.2. Rept demonstrates valves have capability w/margin, to perform containment isolation function
PETRICK, N A Standardized Nuclear Unit Power Plant System.
84/01/16 DENTON, H R Office of Nuclear Reactor Regulation,
Director 3pp 21863 203 24X Fiche 50-000, 84/01/16, B401200059

--B401200062 "Purge Valve Operability Rept. SNUPPS Project"
* Standardized Nuclear Unit Power Plant System 83/12/31. 39pp.
21865 204 24X Fiche 50-000, 84/01/16, B401200059

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17, Division of
Licensing 1p. 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401270443 Advises that RP Denise replaces J Gagliardo as Director, Div of Resident Reactor Project & Engineering Programs, effective 840122 Gagliardo appointed Director, Chattanooga Training Ctr
COLLINS, J T Region 4, Office of Director. 84/01/23, KOESTER, O L,
Kansas Gas & Electric Co 1p. 21980 356 24X Fiche 50-482,
84/01/23, B401270443

B401190008 Board Notification 84-017: forwards evaluation findings of possible impact of large earthquakes associated w/Mears Fault.
NOVAK, T M Assistant Director for Licensing. 84/01/27, Atomic
Safety and Licensing Board Panel 4pp 22018 047, 24X
Fiche 50-000, 84/01/27, B401190008

E. NRC Safety Evaluation Report (SER), supp & correspondence

B401190157 Forwards SSER 4 (NUREG-0881) w/o encl.
YOUNGBLOOD, B J Licensing Branch 1. 83/12/30 KOESTER, O L Kansas
Gas & Electric Co. 2pp 21870, 362 24X Fiche 50-482, 83/12/30,
B401190157

DOCKETED ITEMS

B401190177 Forwards list of GER open issues Review requested
YOUNGBLOOD, B J Licensing Branch 1 83/12/30 KOESTER, Q L Kansas
Gas & Electric Co SCHMELL, D F Union Electric Co 14pp
21861 305 24X Fiche 50-000, 83/12/30, B401190177

B401090322 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WOLF
CREEK GENERATING STATION, UNIT NO 1 Docket No 50-482
(Kansas Gas And Electric Company, et al)
* Division of Licensing NUREG-0881 804 83/12/31 91pp
Available at NRC #4 50 21766 219 24X Fiche 50-482, 83/12/31,
B401090322

F. Security, medical, emergency & fire protection plans

B401050066 Releases public version of ltr forwarding revised emergency
planning info
FELTON, J M Division of Rules and Records 83/12/28 Document
Management Branch 1p 21736 333 24X Fiche 50-482, 83/12/28,
B401050066

—B401050070 Forwards public version of revised emergency planning info,
which will be incorporated into upcoming Rev 12 to FSAR.
KOESTER, Q L Kansas Gas & Electric Co 83/11/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 21736 334
24X Fiche 50-482, 83/12/28, B401050066

B401180103 Informs that proposed interim finding returned to FEMA
Region VII for further processing as described in encl ltr
Interim findings will be submitted upon acceptance.
KRIMM, R W Federal Emergency Management Agency, B4/01/13,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 21840 308 24X Fiche 50-482, B4/01/13,
B401180103

B401200139 Forwards Rev 1 to "SAR for Safety Parameter Display Sys" in
response to Generic Ltr 82-33, Suppl 1 to NUREG-0737
PETRICK, N A Standardized Nuclear Unit Power Plant System
B4/01/13 DENTON, H R Office of Nuclear Reactor Regulation,
Director 1p, 21865 300 24X Fiche 50-000, B4/01/13, B401200139

—B401200145 Rev 1 to "SAR for Safety Parameter Display Sys"
* Standardized Nuclear Unit Power Plant System B4/01/13 31pp
21865 301 24X Fiche 50-000, B4/01/13, B401200139

G. Adjudicatory correspondence

401030152 Forwards Flint Hills Natl Wildlife Refuge B31208 ltr to
Coffey County Board of Commissioners, outlining agreement
re emergency procedures
SILBERG, J E Shaw, Pittman, Potts & Troubridge SILBERG, J E,
Kansas Gas & Electric Co 83/12/27 WOLFE, S J, ANDERSON, Q C,
PAXTON, H C Atomic Safety and Licensing Board Panel 2pp,
21681:350 24X Fiche 50-482, 83/12/27, B401030152

401030158 Amended answer to intervenor B31207 motion to add contention
& witnesses Opposition to request to call addl witnesses
withdrawn Certificate of Svc encl
SILBERG, J E Kansas Gas & Electric Co SILBERG, J E Shaw, Pittman,
Potts & Troubridge 83/12/27 Atomic Safety and Licensing Board
Panel 5pp 21682 355, 24X Fiche 50-482, 83/12/27, B401030158

31030183 Forwards prof qualifications statements for all non-Coffey
County witnesses for testimony on emergency evacuation plan
issues
SILBERG, J E Shaw, Pittman, Potts & Troubridge SILBERG, J E,
Kansas Gas & Electric Co 83/12/27 WOLFE, S J, ANDERSON, Q C,
PAXTON, H C Atomic Safety and Licensing Board Panel 41pp
21683:001 24X Fiche 50-482, 83/12/27, B401030183

401040116 Informs that addition of contention re Town of Haverly & any
addl witnesses accepted, FEMA & NRC positions identical
KARMAN, M Hearing Branch 1 83/12/27 WOLFE, S J, ANDERSON, Q C,
PAXTON, H C Atomic Safety and Licensing Board Panel 1p
21703:234 24X Fiche 50-482, 83/12/27, B401040116

401040127 Memorializes B31230 telcon wherein ABLR granted intervenor
B31208 motion to add addl contention & witnesses
KARMAN, M Hearing Branch 1 83/12/30 WOLFE, S J, PAXTON, H C,
ANDERSON, Q C Atomic Safety and Licensing Board Panel 2pp,
21702:064, 24X Fiche 50-482, 83/12/30, B401040127

401120251 Forwards SBFR 4 (NUREG-0881), W/o encl
KARMAN, M Hearing Branch 1 B4/01/04, WOLFE, S J, PAXTON, H C,
ANDERSON, Q C Atomic Safety and Licensing Board Panel 1p,
21793 281 24X Fiche 50-482, B4/01/04, B401120251

B401090365 Memorandum & order granting Christy & Salva B31208 motion
to add contention & witnesses Discovery on admitted addl
contention will begin immediately & be completed by B40130
WOLFE, S J Atomic Safety and Licensing Board Panel B4/01/05
Christy, W, Intervenor 10pp 21794 050 24X
Fiche 50-482, B4/01/05, B401090365

B401160251 Interrogatories & request for production of documents re
plume exposure pathway emergency planning zone contention
Certificate of Svc encl
RIDDWAY, D A Kansas Gas & Electric Co B4/01/11 CHRISTY, W
Christy, W, Intervenor BALAVA, M E Balava, M E, Intervenor
11pp 21814 204 24X Fiche 50-482, B4/01/11, B401160251

B401180258 Requests appearance of MM Stevens & R Johnson at B40124
hearing to make oral limited appearance statement
STEPHENS, M M Nuclear Awareness Network B4/01/11 Office of the
Secretary of the Commission 1p 21842 338 24X
Fiche 50-482, B4/01/11, B401180258

B401170221 Requests opportunity to make oral comments on B40117 & at
any proposed public hearings re proposed licensing
BURN, L W B4/01/12 Office of the Secretary of the
Commission 1p 21831:345 24X Fiche 50-482, B4/01/12, B401170221

B401240288 Requests to make oral limited appearance statement at
B40121 CL hearing in Burlington, KS
BURMEISTER, P F Affiliation Unknown B4/01/16 Office of the
Secretary of the Commission 1p 21909:334 24X
Fiche 50-482, B4/01/16, B401240288

B401240067 Petition of Nuclear Awareness Network, Inc for leave to
intervene & request for hearing Certificate of Svc encl
STEPHENS, M M Affiliation Unknown B4/01/19 Commissioners
14pp, 21912 318 24X Fiche 50-482, B4/01/19, B401240067

G. Inspection reports, IE Bulletins & correspondence

B401040450 Forwards IE Insp Rept 50-482/83-24 on B30801-31, No
violations noted
SEIDLE, W C Region 4, Office of Director, 83/09/23 KOESTER, Q L
Kansas Gas & Electric Co 2pp 21708 067 24X
Fiche 50-482, 83/09/23, B401040450

—B401040457 IE Insp Rept 50-482/83-24 on B30801-31, No violations noted
Major areas inspected startup activities & initial
preoperational test procedure review
SCHUM, W S, WHITTLESEY, K A, JOHNSON, W D Region 4, Office of
Director 83/09/22, 5pp 21708 067, 24X Fiche 50-482, 83/09/23,
B401040450

B401060040 Responds to FOIA request for IE tabulation of BALP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records, 83/10/20, ZAHLER, R E
Shaw, Pittman, Potts & Troubridge, 1p 21744:003 24X
Fiche 50-000, 83/10/20, B401060040

—B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744:004 24X Fiche 50-000, 83/10/20,
B401060040

B401040374 Forwards IE Insp Rept 50-482/83-23 on B30829-0902, No
noncompliance noted
GALLIARD, J E Region 4, Office of Director 83/10/26
KOESTER, Q L Kansas Gas & Electric Co, 2pp, 21706:339, 24X
Fiche 50-482, 83/10/26, B401040374

—B401040377 IE Insp Rept 50-482/83-23 on B30829-0902, No noncompliance
noted Major areas inspected radwaste program &
transportation activities, including organization, training,
personnel selection & liquid & gaseous radwaste mgt
BAER, R E, MURRAY, B., JOHNSON, W D Region 4, Office of Director
83/10/18, 20pp 21706 341, 24X Fiche 50-482, 83/10/26, B401040374

B401040563 Forwards IE Insp Rept 50-482/83-20 on B30822-26, No
violations noted.
GALLIARD, J E Region 4, Office of Director, 83/10/31,
KOESTER, Q L Kansas Gas & Electric Co, 2pp 21707:204, 24X
Fiche 50-482, 83/10/31, B401040563

—B401040570 IE Insp Rept 50-482/83-20 on B30822-26 No violations noted
Major areas inspected: planned radiation protection program
for operations & surveys & area posting.
CHANEY, H D, MURRAY, B., JOHNSON, W D Region 4, Office of Director
83/10/26, 34pp 21707:206, 24X Fiche 50-482, 83/10/31,
B401040563,

B401040421 Forwards IE Insp Rept 50-482/83-23 on 830816-1031 & notice of violation
QAOLIARDO, J E Region 4, Office of Director 83/11/22
KOESTER, O L Kansas Gas & Electric Co 2pp 21707 088 24X
Fiche 50-482, 83/11/22, B401040421

--B401040425 Notice of violation from insp on 830816-1031
* Region 4, Office of Director 83/11/22 1p 21707 090 24X
Fiche 50-482, 83/11/22, B401040421

--B401040435 IE Insp Rept 50-482/83-23 on 830816-1031 Noncompliance noted failure to follow & implement quality requirements causing omission of backing matl w/o establishing new procedure
ROBERDS, H W, SMITH, A L, JOHNSON, W A Region 4, Office of Director 83/11/15 6pp 21707 091 24X Fiche 50-482, 83/11/22, B401040421

B401040455 Forwards IE Insp Rept 50-482/83-33 on 831001-31 & notice of deviation
QAOLIARDO, J E Region 4, Office of Director 83/11/23
KOESTER, O L Kansas Gas & Electric Co 2pp 21707 343 24X
Fiche 50-482, 83/11/23, B401040455

--B401040459 Notice of deviation from insp on 831001-31
* Region 4, Office of Director 83/11/23 1p 21707 345 24X
Fiche 50-482, 83/11/23, B401040455

--B401040466 IE Insp Rept 50-482/83-33 on 831001-31 Deviation noted- chairmanship of joint test group changed to superintendent of regulatory, quality & administrative svcs
SCHUM, W S, WHITTLESEY, K A, JOHNSON, W D Region 4, Office of Director 83/11/23 4pp 21707 346 24X Fiche 50-482, 83/11/23, B401040455

B401270490 Responds to request for addl info re util plans for providing adequate number of qualified radiation protection technicians prior to fuel loading; per IE Insp Rept 50-482/83-20
KOESTER, O L Kansas Gas & Electric Co 83/11/30 QAOLIARDO, J E Region 4, Office of Director 30pp 21980 293 24X
Fiche 50-482, 83/11/30, B401270490

B401040422 Forwards IE Insp Rept 50-482/83-34 on 831031-1104 & notice of violation
QAOLIARDO, J E Region 4, Office of Director 83/12/12 KOESTER, O L Kansas Gas & Electric Co 2pp 21708 130 24X
Fiche 50-482, 83/12/12, B401040422

--B401040432 Notice of violation from insp on 831031-1104,
* Region 4, Office of Director 83/12/12 1p 21708 132 24X
Fiche 50-482, 83/12/12, B401040422

--B401040439 IE Insp Rept 50-482/83-34 on 831031-1104 Noncompliance noted: power cables for containment cooling fan motors A & C not secured such that one full diameter cable spacing achieved
MURPHY, M E, SMITH, W F, HUNNICUTT, D M Region 4, Office of Director 83/12/09 8pp 21708 133 24X Fiche 50-482, 83/12/12, B401040422

B401170387 Forwards SALP Rept 50-482/83-26 for Aug 1982 - Jul 1983
Overall performance satisfactory Significant improvement needed in areas of piping svcs & supports, safety-related components & preoperational testing
COLLINS, J T Region 4, Office of Director 83/12/23 KOESTER, O L Kansas Gas & Electric Co 2pp 21829 043 24X
Fiche 50-482, 83/12/23, B401170387

--B401170387 Forwards SALP Rept 50-482/83-26 for Aug 1982 - Jul 1983
QAOLIARDO, J E Region 4, Office of Director 83/11/02,
KOESTER, O L Kansas Gas & Electric Co 4pp 21829 045 24X
Fiche 50-482, 83/12/23, B401170387

--B401170394 SALP Rept 50-482/83-26 for Aug 1982 - Jul 1983
JOHNSON, W D, SEIDLE, W C, QAOLIARDO, J E Region 4, Office of Director 83/11/01 19pp 21829 049 24X Fiche 50-482, 83/12/23, B401170387

--B401170398 Discusses 831110 meeting w/NRC re SALP rept for Aug 1982 - Jul 1983. Significant measures taken to increase attention in areas critical to quality const completion & startup testing phase
KOESTER, O L Kansas Gas & Electric Co 83/11/30, COLLINS, J T Region 4, Office of Director 3pp 21829 068 24X
Fiche 50-482, 83/12/23, B401170387

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093.

B401130169 Ack receipt of 831125 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-30
QAOLIARDO, J E Region 4, Office of Director 84/01/06,
KOESTER, O L Kansas Gas & Electric Co 1p 21802-033 24X
Fiche 50-482, 84/01/06, B401130169

--B401130172 Responds to NRC 831028 ltr re violations noted in IE Insp Rept 50-482/83-30 Corrective actions chemistry surveillance program procedure & operations administrative procedure re housekeeping & cleanliness control revised
KOESTER, O L Kansas Gas & Electric Co 83/11/25, QAOLIARDO, J E Region 4, Office of Director 4pp 21802-034 24X
Fiche 50-482, 84/01/06, B401130169

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10, Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

B401230685 Notification of B40125 meeting w/utilis & SNUPPS in Fulton, MO to discuss preservice insp program & to evaluate ultrasonic insp of cast stainless steel welds. Agenda encl.
HOLDNICH, J J Licensing Branch 1 84/01/13 YOUNGBLOOD, B J Licensing Branch 1 5pp 21925 141 24X Fiche 50-000, 84/01/13, B401230685

B312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, B312120114

B401230170 Forwards GA Program Insp Rept 999000832/83-01 for evaluation of significance of reported finding w/regard to quality & acceptability of product or svc provided by vendor. W/o encl
QAOLIARDO, J E Region 5, Office of Director 84/01/16,
KOESTER, O L Kansas Gas & Electric Co 2pp 21884 307 24X
Fiche 50-482, 84/01/16, B401230170

B401230193 Forwards GA Program Insp Rept 99900404/83-02 for info & action Util should evaluate significance of reported findings re quality & acceptability of product or svc provided by vendor. W/o encl
QAOLIARDO, J E Region 4, Office of Director 84/01/16
KOESTER, O L Kansas Gas & Electric Co 2pp 21884 151 24X
Fiche 50-482, 84/01/16, B401230193.

B401230197 Forwards GA Program Insp Rept 99900255/83-01 for evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor. W/o encl
QAOLIARDO, J E Region 4, Office of Director 84/01/16
KOESTER, O L Kansas Gas & Electric Co 2pp 21884 126 24X
Fiche 50-482, 84/01/16, B401230197.

B401230218 Forwards GA Program Insp Rept 99900519/83-02 for evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor. W/o encl.
QAOLIARDO, J E Region 4, Office of Director 84/01/16,
KOESTER, O L Kansas Gas & Electric Co 2pp 21884 086 24X
Fiche 50-482, 84/01/16, B401230218.

B401230371 Forwards GA Program Insp Rept 99900209/83-02 of Bergen-Paterson pipe support for info. Util should evaluate significance of findings re quality & accountability of vendor product/svc. Receipt form encl. W/o rept.
QAOLIARDO, J E Region 4, Office of Director 84/01/16,
KOESTER, O L Kansas Gas & Electric Co 2pp 21877 353 24X
Fiche 50-482, 84/01/16, B401230371.

DOCKETED ITEMS

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117

8401240573 Advises of categories of preservice insp exam for which relief requests anticipated, in response to NRC 840109 request.
BEIKEN, B J. Standardized Nuclear Unit Power Plant System 84/01/18.
DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp
21909 125 24X Fiche 50-000, 84/01/18, 8401240573

B. Reportable occurrences, LERs & related correspondence

8401100456 Interim significant Deficiency Rept 83-13 re Limitorque valve operator limit switch rotor matl Initially reported 831116. Caused by excessive shrinkage in matl in rotors. Rotors replaced. Also reported per Part 21.
BEIKEN, B J. Standardized Nuclear Unit Power Plant System. 83/12/22
KEPPLER, J Q. Region 3, Office of Director. COLLINS, J T. Region 4, Office of Director 2pp. 21761 351. 24X Fiche 50-000, 83/12/22, 8401100456

8401100330 Interim deficiency rept re insufficient torque on structural steel bolted connections. Initially reported on 830204. Procedures revised to provide appropriate controls for use of turn-of-the-nut. Investigation ongoing.
KOEETER, G L. Kansas Gas & Electric Co. 83/12/30. OAGLIARDO, J.E. Region 4, Office of Director 2pp. 21764 142. 24X Fiche. 50-482, 83/12/30, 8401100330

8401100439 Interim deficiency rept re I-beam fabrication discrepancies. Initially reported on 831201. Three discrepancies identified re individual heats of W6x20 & W6x25 Webs either twisted or skewed.
KOEETER, G L. Kansas Gas & Electric Co. 83/12/30. OAGLIARDO, J.E. Region 4, Office of Director. 3pp 21763 104 24X Fiche: 50-482, 83/12/30, 8401100439.

8401130328 Interim deficiency rept re misinterpretation of ASME Code Section III subsection classification on welds. Initially reported on 831208. Thimble guide tube to seal tube connections penetrant tested & found acceptable.
KOEETER, G L. Kansas Gas & Electric Co. 84/01/06. OAGLIARDO, J.E. Region 4, Office of Director. 2pp 21801 335. 24X Fiche. 50-482, 84/01/06, 8401130328

401230447 Interim deficiency rept re heat numbers w/more than one pipe scheduled. Initially reported on 831213. Nonconformance rept issued to document & correct schedule.
KOEETER, G L. Kansas Gas & Electric Co. 84/01/12. OAGLIARDO, J.E. Region 4, Office of Director 2pp. 21892 312. 24X Fiche. 50-482, 84/01/12, 8401230447

8401270189 Interim deficiency rept re pulsation dampeners for positive displacement charging pump. Initially reported on 831222. RECO Industries, Inc. contacted & verified that nameplate & drawings indicate incorrect weight.
KOEETER, G L. Kansas Gas & Electric Co. 84/01/19. OAGLIARDO, J.E. Region 4, Office of Director. 2pp. 21982 071. 24X Fiche: 50-482, 84/01/19, 8401270189.

C. Hearing transcripts on non-antitrust matters

401030155 Direct testimony on emergency evacuation plan issues.
* Kansas Gas & Electric Co. 83/12/27. 238pp. 21682 001. 24X Fiche: 50-482, 83/12/27, 8401030155.

8401240234 Transcript of 840117 hearing in Burlington, KS Pp 145-332 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 84/01/17. 457pp. 21911 163. 24X Fiche: 50-482, 84/01/17, 8401240234.

8401250079 Transcript of 840118 hearing in Burlington, KS, Pp 333-573. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 84/01/18. 263pp. 21939 287. 24X Fiche: 50-482, 84/01/18, 8401250079.

8401250140 Transcript of 840119 hearing in Burlington, KS Pp 574-767.
* Atomic Safety and Licensing Board Panel. 84/01/19. 200pp 21938 190. 24X Fiche: 50-482, 84/01/19, 8401250140.

8401250092 Transcript of 840120 hearing in Burlington, KS Pp 768-987
* Atomic Safety and Licensing Board Panel. 84/01/20. 228pp 21939 030. 24X Fiche 50-482, 84/01/20, 8401250092

8401300208 Transcript of 840121 meeting in Burlington, KS Pp 988-1,243
* Atomic Safety and Licensing Board Panel. 84/01/21. 235pp 21993 001. 24X Fiche 50-482, 84/01/21, 8401300208

8401300206 Transcript of 840123 hearing in Emporia, KS Pp 1,244-1,460
* Atomic Safety and Licensing Board Panel. 84/01/23. 216pp 21994 001. 24X Fiche 50-482, 84/01/23, 8401300206

8401310003 Transcript of 840124 hearing in Emporia, KS Pp 1,461-1,637
* Atomic Safety and Licensing Board Panel. 84/01/24. 194pp 22024 051. 24X Fiche 50-482, 84/01/24, 8401310003

8401310002 Transcript of 840125 hearing in Emporia, KS Pp 1,638-1,847 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 84/01/25. 513pp 22025 068. 24X Fiche. 50-482, 84/01/25, 8401310002

8401310011 Transcript of 840126 hearing in Emporia, KS Pp 1,848-1,967
* Atomic Safety and Licensing Board Panel. 84/01/26. 123pp 22023 219. 24X Fiche. 50-482, 84/01/26, 8401310011

DOCKET 87N-50-483 CALLAWAY PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8401030419 Forwards list of documents which should respond to questions raised in 830601 & 1111 ltr re hafnium control rods.
HOLONICH, J J. Licensing Branch 1. 83/12/21. DREY, L A. Affiliation Unknown 2pp 21689 360. 24X Fiche 50-483, 83/12/21, 8401030419

8401090048 Summary of 831025 meeting w/utills & SNUPPS, ARD Corp & Science Applications, Inc re NRC review of SNUPPS detailed control room design review program plan for facilities.
HOLONICH, J J. Licensing Branch 1. 83/12/30. Licensing Branch 1 4pp. 21757 274. 24X Fiche: 50-000, 83/12/30, 8401090048

8401100339 Forwards info in response to 831026 request for references which document sitespecific applicable factor for mixing effect of discharge structure.
SCHNELL, D F. Union Electric Co. 83/12/30. DENTON, H R. Office of Nuclear Reactor Regulation, Director 6pp 21763 209. 24X Fiche: 50-483, 83/12/30, 8401100339.

--8401100353 "Mixing, Dispersion & Deposition of Suspended Sediment From Union Electric Co. Callaway Plant Discharge"
EDINGER, J.E., J.E. Edinger Associates, Inc. 82/12/01. 34pp. 21763 215. 24X Fiche: 50-483, 83/12/30, 8401100339

--8401100359 "Rept on Thermal Plume Investigations for Union Electric Co. Callaway Plant, Units 1 & 2"
* Sverdup & Parcel & Associates, Inc. 74/04/04. 23pp 21763 249. 24X Fiche 50-483, 83/12/30, 8401100339.

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification. Sandia position is that NRC environ qualification program has problems.
EISENHUT, D.G. Division of Licensing. 84/01/05. PALLADINO, N J. Commissioners 2pp. 21993 324. 24X Fiche. 50-000, 84/01/05, 8312120108

8401030382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl.
EISENHUT, D G. Division of Licensing. 84/01/05. Consolidated Edison Co. of New York, Inc. 16pp 21946 190. 24X Fiche: 50-000, 84/01/05, 8401030382

8401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing. Svc list encl.
EISENHUT, D.G. Division of Licensing. 84/01/06. Consolidated Edison Co. of New York, Inc. 18pp. 21937 267. 24X Fiche: 50-000, 84/01/06, 8401090221

8401100204 Forwards revised FSAR Page 5 2-9 clarifying precautions for solid water operation. Clarification will be included in Rev 13 to FSAR to be submitted by Feb 1984.
PETRICK, N.A. Standardized Nuclear Unit Power Plant System 84/01/06. DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 21759 282. 24X Fiche 50-000, 84/01/06, 8401100204

B401130153 Forwards revised FSAR Page 14 2-62, modifying accumulator testing abstract of safety-related preoperational test procedures. Mod will be included in Rev 13 to FSAR scheduled for submittal in Feb 1984.
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 B4/01/09 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 2pp 21798 358 24X Fiche 50-000, B4/01/09, B401130153

B401310158 Forwards proof & review Tech Specs for facility Requests results of review, identifying particular sections be provided by B40217
 THOMAS, C D Standardization & Special Projects Branch B4/01/11
 YOUNGBLOOD, J Licensing Branch 1 HOLAHAN, O Assistant Director
 for Operating Reactors LAIAW, B D Materials Engineering Branch
 3pp 22033 001 24X Fiche 50-483, B4/01/11, B401310158

--B401310162 Proof & review Tech Specs for facility
 * NRC - No Detailed Affiliation Given B4/01/11 400pp
 22033 004 24X Fiche 50-483, B4/01/11, B401310158

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" BvC list encl
 EISENHUT, D G Division of Licensing B4/01/13 Consolidated
 Edison Co of New York, Inc 18pp 21946 174 24X
 Fiche 50-000, B4/01/13, B401130084

B401200057 Forwards "Purge Valve Operability Rept, SNUPPS Project," per Licensing Confirmatory Issues 2B, II E 4 2 & B 2B, II E 4 2 Rept demonstrates Valves have capability, w/margin, to perform containment isolation function
 PETRICK, N A Standardized Nuclear Unit Power Plant System
 B4/01/16 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 3pp 21865 203 24X Fiche 50-000, B4/01/16, B401200057

--B401200062 "Purge Valve Operability Rept, SNUPPS Project"
 * Standardized Nuclear Unit Power Plant System B3/12/31 39pp
 21865 206 24X Fiche 50-000, B4/01/16, B401200057

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
 HANNON, J Division of Licensing B4/01/17, Division of
 Licensing 1p 22000 349 24X Fiche 50-000, B4/01/17, B401270536

B401310116 Forwards proposed App B to application for DL App describes nonradiological environ protection program
 SCHNELL, D F Union Electric Co B4/01/24 DENTON, H R Office of
 Nuclear Reactor Regulation, Director 3pp 22022 029 24X
 Fiche 50-483, B4/01/24, B401310116

--B401310120 Proposed environ protection plan - nonradiological
 * Union Electric Co B4/01/24 8pp 22022 032 24X
 Fiche 50-483, B4/01/24, B401310116

E NRC Safety Evaluation Report (SER), suppl's & correspondence

B401190177 Forwards list of SER open issues Review requested.
 YOUNGBLOOD, B J Licensing Branch 1 B3/12/30 KOESTER, G L Kansas
 Gas & Electric Co SCHNELL, D F Union Electric Co 14pp
 21861 305 24X Fiche 50-000, B3/12/30, B401190177

F Security, medical, emergency & fire protection plans

B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR, App C documents entirely withheld (re: FOIA Exemption 5)
 FELTON, J M Division of Rules and Records B3/11/02 O'NEILL, J H
 Shaw, Pittman, Potts & Trowbridge 8pp 21957 387 24X
 Fiche 50-000, B3/11/02, B401250163

--B305160182 Requests Commission authorization for exception to location of backup emergency operations facility 25 miles from plant site
 DIRCKS, W J Office of the Executive Director for Operations,
 SECY-B3-161 B3/05/02 5pp 21958 089 24X
 Fiche 50-000, B3/11/02, B401250163

B401030320 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records B3/12/27 Document
 Management Branch 1p 21692 202 24X Fiche 50-483, B3/12/27,
 B401030320

--B401030322 Forwards public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00216 re potassium iodide administration & EIP-ZZ-1211 re initial dose assessment
 SCHNELL, D F Union Electric Co B3/12/02 KEFFLER, J O Region
 3, Office of Director 3pp 21692 203 24X Fiche 50-483,
 B3/12/27, B401030320

--B401030326 Public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00216 re potassium iodide administration & EIP-ZZ-01211 re initial dose assessment
 * Union Electric Co B3/11/23 209pp 21692 206 24X
 Fiche 50-483, B3/12/27, B401030320

B401040464 Forwards IE Safeguards Insp Rept 50-483/B3-29 on B31128-1202 No noncompliance noted
 AXELSON, W L Region 3, Office of Director B3/12/28 SCHNELL, D F
 Union Electric Co 2pp 21707 337 24X Fiche 50-483, B3/12/28,
 B401040464

--B401040480 IE Safeguards Insp Rept 50-483/B3-29 on B31128-1202 No noncompliance noted Major areas inspected status of implementation, installation & operability of security program Safeguards info deleted (ref 10CFR73.21)
 PIRTLE, G L, STAPLETON, B W., CREED, J R Region 3, Office of
 Director B3/12/27 2pp 21707 339 24X Fiche 50-483, B3/12/28,
 B401040464

B401050134 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records B3/12/28 Document
 Management Branch 1p 21743 225 24X Fiche 50-483, B3/12/28,
 B401050134

--B401050141 Forwards public version of Rev 0 to Emergency Plan Implementing Procedure EIP-ZZ-C0010, "Duties of Corporate Emergency Organization" & Rev 0 to Procedure EIP-ZZ-C0020, "Callout of Corporate Emergency Organization"
 KANYO, J P Union Electric Co B3/12/07 NRC - No Detailed
 Affiliation Given 1p 21743 226 24X Fiche 50-483, B3/12/28,
 B401050134

--B401050146 Public version of Rev 0 to Emergency Plan Implementing Procedure EIP-ZZ-C0010, "Duties of Corporate Emergency Organization" & Rev 0 to Procedure EIP-ZZ-C0020, "Callout of Corporate Emergency Organization." Revised index encl.
 SULLIVAN, R L Union Electric Co B3/12/07 24pp 21743 227
 24X Fiche 50-483, B3/12/28, B401050134

B401060018 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records B3/12/28 Document
 Management Branch 1p 21755 200 24X Fiche 50-483, B3/12/28,
 B401060018

--B401060022 Forwards public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00214 re personnel/vehicle monitoring & decontamination.
 KANYO, J P, Union Electric Co B3/12/13, EDISON, G NRC - No
 Detailed Affiliation Given 1p 21755 201 24X
 Fiche 50-483, B3/12/28, B401060018

--B401060037 Public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00214 re personnel/vehicle monitoring & decontamination
 * Union Electric Co B3/12/13 88pp 21755 202 24X
 Fiche 50-483, B3/12/28, B401060018

B401060035 Releases public version of revised health physics dept emergency plan implementing procedure
 FELTON, J M Division of Rules and Records B3/12/28 Document
 Management Branch 1p 21748 129 24X Fiche 50-483, B3/12/28,
 B401060035

--B401060041 Public version of Rev 2 to Health Physics Dept Emergency Plan Implementing Procedure HDP-ZZ-01200, "Radiation Work Permit Program" W/B31109 1tr & receipt form.
 POLCHOW, J R., KANYO, J P Union Electric Co B3/11/14, EDISON, G
 NRC - No Detailed Affiliation Given 26pp 21748 130 24X
 Fiche 50-483, B3/12/28, B401060035

B401190095 Forwards request for addl info & comments on Rev 5A to emergency plan. Requested info & page changes should be submitted within 30 days
 YOUNGBLOOD, B J Licensing Branch 1 B4/01/05, SCHNELL, D F, Union
 Electric Co 9pp 21870 243 24X Fiche 50-483, B4/01/05, B401190095

DOCKETED ITEMS

8401230304 Ack receipt of util 831219 ltr providing objectives & guidelines for Mar 1984 emergency exercise.
PAPERIELLO, C J Region 3, Office of Director 84/01/05
SCHNELL, D F Union Electric Co 1p 21883 180 24X
Fiche 50-483, 84/01/05, 8401230304

--8401230313 Forwards, for review & comment, proposed objectives & guidelines for initial emergency preparedness field exercise scheduled for 840321
STILLER, M A Union Electric Co 83/12/19. KEPLER, J G Region 3, Office of Director. 14pp. 21883 181 24X
Fiche 50-483, 84/01/05, 8401230304

8401200139 Forwards Rev 1 to "BAR for Safety Parameter Display Sys" in response to Generic Ltr 82-33, Suppl 1 to NUREG-0737
PETRICK, N A. Standardized Nuclear Unit Power Plant System 84/01/13. DENTON, M R Office of Nuclear Reactor Regulation, Director 1p. 21865 300 24X Fiche 50-000, 84/01/13, 8401200139

--8401200145 Rev 1 to "BAR for Safety Parameter Display Sys." * Standardized Nuclear Unit Power Plant System 84/01/13. 31pp 21865 301 24X Fiche 50-000, 84/01/13, 8401200139

8401250073 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 84/01/18 Document Management Branch 1p 21946 318 24X Fiche 50-483, 84/01/18, 8401250073.

--8401250075 Forwards public version of revised emergency plan implementing procedures, including Procedures RTN-HB-00001 re reactor coolant drain tank operation & RTN-HB-00006 re laundry & hot shower tank subsystem operation
KANYO, J P. Union Electric Co 83/12/19 NRC - No Detailed Affiliation Given. 1p 21946 319 24X Fiche 50-483, 84/01/18, 8401250073

--8401250077 Public version of revised emergency plan implementing procedures, including Procedures RTN-HB-00001 re reactor coolant drain tank operation & RTN-HB-00006 re laundry & hot shower tank subsystem operation
MAYER, M E Union Electric Co. 83/12/19 61pp 21946 320. 24X Fiche 50-483, 84/01/18, 8401250073

8401250045 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 84/01/20 Document Management Branch. 1p. 21948 128 24X Fiche 50-483, 84/01/20, 8401250045

--8401250049 Forwards public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00102 re emergency implementing actions, EIP-ZZ-00214 re personnel/vehicle monitoring & EIP-ZZ-00230 re evacuation.
KANYO, J P. Union Electric Co 83/12/13. Document Management Branch. 1p. 21948 129. 24X Fiche 50-483, 84/01/20, 8401250045

--8401250052 Public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00102 re emergency implementing actions, EIP-ZZ-00214 re personnel/vehicle monitoring & EIP-ZZ-00230 re evacuation.
WOLFE, R. Union Electric Co 83/12/13 100pp. 21948 130 24X Fiche 50-483, 84/01/20, 8401250045.

8401310190 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 84/01/20. Document Management Branch. 1p. 22035 121 24X Fiche 50-483, 84/01/20, 8401310190

--8401310192 Public version of Rev 1 to Emergency Plan Implementing Procedure EIP-ZZ-00101, "Classification of Emergencies." W/840105 ltr & receipt form.
KANYO, J. P., GRUNDBROM, R. J. Union Electric Co 84/01/05 Document Management Branch. 60pp. 22035 122. 24X Fiche 50-483, 84/01/20, 8401310190

I. Adjudicatory correspondence

8401110178 Order extending time until 840208 for Commission to act to review ALAB-740, ALAB-750, ALAB-750A & ALAB-754
CHILK, B. J. Office of the Secretary of the Commission 84/01/09. Commissioners. 1p. 21772 337. 24X Fiche 50-483, 84/01/09, 8401110178.

H General correspondence

840120168 Informs that SER containing info re structural design audit, staff testimony & info pertaining to license application available for insp at LPDR, in response to 831107 request
YOUNGBLOOD, B J Licensing Branch 1 83/12/27 DREY, L A Affiliation Unknown 1p 21805 060 24X Fiche 50-483, 83/12/27, 840120168

K Utility Final Safety Analysis Report (FSAR) & amends

8401270411 Forwards Rev 6 to FSAR, including revised Section 17 2 re GA during operating phase & App 3A addressing reg guides, per util 831128 ltr
SCHNELL, D F Union Electric Co. 84/01/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21977 001 24X Fiche 50-483, 84/01/13, 8401270411

--8401270413 Rev 6 to FSAR * Union Electric Co 83/12/31 856pp 21977 004 24X Fiche 50-483, 84/01/13, 8401270411

G. Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge. 1p 21744 003 24X Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982 * Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744 004. 24X Fiche 50-000, 83/10/20, 8401060040.

8401230177 Forwards second response to 831116 transmittal of integrated design insp rept Bachtel Program ME 101 nonconservatism postulated by NRC does not exist
SCHNELL, D F Union Electric Co 83/12/19 NORELIOUS, C E Division of Project & Resident Programs 7pp 21884 176 24X Fiche 50-483, 83/12/19, 8401230177

8401100069 Forwards IE Insp Rept 50-483/83-25 on 831016-1130 & notice of violation
KNOP, R C. Region 3, Office of Director 83/12/20 SCHNELL, D F Union Electric Co 2pp 21761 225 24X Fiche 50-483, 83/12/20, 8401100069.

--8401100072 Notice of violation from insp on 831016-1130
KNOP, R C Region 3, Office of Director 83/12/20 1p 21761 227 24X Fiche 50-483, 83/12/20, 8401100069.

--8401100076 IE Insp Rept 50-483/83-25 on 831016-1130. Noncompliance noted, reactor coolant pumps B & D started prior to establishing steam bubble in pressurizer, contrary to preoperational test procedure requirements.
LITTLE, B H, KONKLIN, J E. Region 3, Office of Director 83/12/19 5pp. 21761 228 24X Fiche 50-483, 83/12/20, 8401100069

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 83/12/28. Consolidated Edison Co of New York, Inc 12pp. 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8401040464 Forwards IE Safeguards Insp Rept 50-483/83-29 on 831128-1202 No noncompliance noted.
AXELSON, W L. Region 3, Office of Director 83/12/28 SCHNELL, D F Union Electric Co 2pp 21707 337. 24X Fiche 50-483, 83/12/28, 8401040464

--8401040480 IE Safeguards Insp Rept 50-483/83-29 on 831128-1202 No noncompliance noted. Major areas inspected, status of implementation, installation & operability of security program Safeguards info deleted (ref 10CFR73 21)
PIRTLE, Q L., STAPLETON, B W, CREED, J. R. Region 3, Office of Director. 83/12/27 2pp 21707 337 24X Fiche 50-483, 83/12/28, 8401040464

8401120222 Forwards IE Insp Rept 50-483/83-28 on 831128-30 & 1201-02 & notice of violation
LITTLE, W B. Region 3, Office of Director 83/12/28, SCHNELL, D F Union Electric Co. 2pp. 21793 337. 24X Fiche 50-483, 83/12/28, 8401120222

--8401120225 Notice of violation from insp on 831128-30 & 1201-02
LITTLE, W B Region 3, Office of Director. 83/12/28. 2pp. 21793 337 24X Fiche 50-483, 83/12/28, 8401120222

DOCKETED ITEMS

367

--8401120227 IE Insp Rept 50-483/83-28 on 831128-30 & 1201-02 Violation noted failure to incorporate acceptance criteria for torquing Class IE relay panels into procedures
MENDEZ, R., WILLIAMS, C C Region 3, Office of Director 83/12/28
9pp 21793 341 24X Fiche 50-483, 83/12/28, 8401120222

8401190395 Forwards IE Insp Rept 50-483/83-26 on 831001-1205 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/12/29 SCHNELL, D F Union Electric Co 2pp 21850 115 24X Fiche 50-483, 83/12/29, 8401190395

--8401190399 IE Insp Rept 50-483/83-26 on 831001-1205 No noncompliance noted Major areas inspected licensee action on previously identified insp items, 10CFR50.55(e) items, IE bulletins & circulars & electrical & instrumentation const activities
NEISLER, J M, KONKLIN, J E Region 3, Office of Director 83/12/29 8pp 21850 117 24X Fiche 50-483, 83/12/29, 8401190395

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8401190566 Informs that IDVP not necessary for facility at present, based on results from recent integrated design insp.
EISENHUT, D O Division of Licensing 84/01/04 SCHNELL, D F Union Electric Co 3pp 21861 188 24X Fiche 50-483, 84/01/04, 8401190566

8401230379 Forwards IE Insp Rept 50-483/83-30 on 831213-15, 19 & 21 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 84/01/09 SCHNELL, D F Union Electric Co 2pp 21878 242 24X Fiche 50-483, 84/01/09, 8401230379

--8401230387 IE Insp Rept 50-483/83-30 on 831213, 15, 19 & 21. No noncompliance noted Major areas inspected preoperational radiological environ monitoring program, including mgt controls, program implementation, QA & chemistry program.
DESTHANN, M J, JANUSKA, A G, SCHUMACHER, M C Region 3, Office of Director 84/01/06 8pp 21878 244 24X Fiche 50-483, 84/01/09, 8401230379

8401240420 Forwards IE Insp Rept 50-483/83-31 on 831213-16. No noncompliance noted
STREETER, J F Region 3, Office of Director 84/01/09 SCHNELL, D F Union Electric Co 2pp 21916 051 24X Fiche 50-483, 84/01/09, 8401240420

--8401240426 IE Insp Rept 50-483/83-31 on 831213-16. No noncompliance noted Major areas inspected previous insp findings & preoperational testing QA program
CHOULES, N C, WESTBERG, R A, STREETER, J F Region 3, Office of Director 84/01/09 4pp 21916 053 24X Fiche 50-483, 84/01/09, 8401240420

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8401160172 Ack receipt of 840103 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/83-18
Corrective actions will be examined during subsequent insp
STREETER, J F Region 3, Office of Director 84/01/12, SCHNELL, D F Union Electric Co. 1p. 21813 293 24X Fiche 50-483, 84/01/12, 8401160172

--8401160179 Responds to NRC 831206 ltr re violations noted in IE Insp Rept 50-483/83-18 Corrective actions startup field rept written to obtain clarification of acceptance criteria from responsible design agency
SCHNELL, D F Union Electric Co 84/01/03 STREETER, J F Region 3, Office of Director 5pp 21813 294 24X Fiche 50-483, 84/01/12, 8401160172

8401230685 Notification of 840125 meeting w/utis & SNUPPS in Fulton, MD to discuss preservice insp program & to evaluate ultrasonic insp of cast stainless steel welds. Agenda encl
HOLONICH, J J Licensing Branch 1 84/01/13 YOUNGBLOOD, B J Licensing Branch 1 5pp 21925 141 24X Fiche 50-000, 84/01/13, 8401230685.

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117.

8401240573 Advises of categories of preservice insp exam for which relief requests anticipated, in response to NRC 840109 request
SEIKEN, B J Standardized Nuclear Unit Power Plant System 84/01/18, DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21909 125 24X Fiche 50-000, 84/01/18, 8401240573

8401310356 Ack receipt of 840119 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-483/83-25
KNOP, R C Region 3, Office of Director 84/01/26, SCHNELL, D F Union Electric Co 1p 22026 251 24X Fiche 50-483, 84/01/26, 8401310356

--8401310368 Responds to NRC 831220 ltr re noncompliance noted in IE Insp Rept 50-483/83-25 Corrective actions personnel reminded of requirement for providing documented evaluation of AOs prior to resumption of operation of equipment s/or testing
SCHNELL, D F Union Electric Co. 84/01/19, KNOP, R C Region 3, Office of Director 2pp 22026 252 24X Fiche 50-483, 84/01/26, 8401310356

R Periodic operating reports & related correspondence

8401100189 Submits quarterly followup response to NRC 810527 ltr re const progress Schedule remains unchanged. Fuel load scheduled for late 1984 or early 1985.
DOUGHERTY, C J Union Electric Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21760 148 24X Fiche 50-483, 83/12/30, 8401100189.

S. Reportable occurrences, LERs & related correspondence

8401100456 Interim significant Deficiency Rept 83-13 re Limitorque valve operator limit switch rotor matl Initially reported 831116 Caused by excessive shrinkage in matl in rotors. Rotors replaced Also reported per Part 21.
SEIKEN, B J Standardized Nuclear Unit Power Plant System 83/12/22, KEPPLER, J Q Region 3, Office of Director COLLINS, J T Region 4, Office of Director 2pp 21761 351 24X Fiche 50-000, 83/12/22, 8401100456

8401060363 Final Deficiency Rept U-51 re cable routing through field designed electrical junction boxes in violation of min bend radius requirements. Initially reported on 830314 Cables tested & replaced in 19 of 23 junction boxes
SCHNELL, D F Union Electric Co. 83/12/28, KEPPLER, J Q Region 3, Office of Director 2pp 21741 096 24X Fiche 50-483, 83/12/28, 8401060363

8401240137 Interim Deficiency Rept U-66 re failure of contractor coils in ITE Gould motor control ctr two-speed starters for containment cooling fan motors. Util awaits Bechtel info on failure. Final rept expected within 90 days.
SCHNELL, D F Union Electric Co. 84/01/06, KEPPLER, J Q Region 3, Office of Director 1p 21910 288 24X Fiche 50-483, 84/01/06, 8401240137.

8401240152 Interim Deficiency Rept U-65 re failure of mechanical interlock on ITE Gould motor control ctr two-speed starters for containment cooling fan motors. Initially reported on 831123 Final rept expected in 90 days
SCHNELL, D F Union Electric Co. 84/01/06, KEPPLER, J Q Region 3, Office of Director 1p 21910 264 24X Fiche 50-483, 84/01/06, 8401240152.

8401230350 Final Deficiency Rept U-37 re Cutler Hammer control switches. Initially reported on 830627. Commis. main control board vendor, directed to discontinue practice of bending switch contact block terminal lugs
SCHNELL, D F Union Electric Co 84/01/10, KEPPLER, J Q Region 3, Office of Director 2pp 21884 260 24X Fiche 50-483, 84/01/10, 8401230350

DOCKETED ITEMS

8401230231 Interim deficiency Rept U-64 re Limitorque gear failure Westinghouse delayed submittal of final rept until 840130
 Until will submit final rept by 840301
 SCHMELL, D F Union Electric Co 84/01/16 KEPPLER, J O Region 3,
 Office of Director 2pp 21884 077 24X Fiche 50-000, 84/01/16, 8401230231

8401270501 Deficiency rept, item U-46 re structural steel bolts not tightened to spec requirements after connections considered complete Initially reported on 830127 Structural connections adequate Next rept by 840301
 SCHMELL, D F Union Electric Co 84/01/18 KEPPLER, J O Region 3,
 Office of Director 2pp 21980 135 24X Fiche 50-000, 84/01/18, 8401270501

DOCKET BTN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8401100339 Forwards info in response to 831026 request for references which document sitespecific applicable factor for mixing effect of discharge structure
 SCHMELL, D F Union Electric Co 83/12/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 21763 209 24X Fiche: 50-483, 83/12/30, 8401100339

--8401100339 "Rept on Thermal Plume Investigations for Union Electric Co Callaway Plant, Units 1 & 2"
 & Sverdup & Parcel & Associates, Inc 74/04/04 25pp 21763 249 24X Fiche 50-483, 83/12/30, 8401100339

DOCKET BTN-50-488 PERKINS NUCLEAR STATION, UNIT 1

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licenseses charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
 REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds 84/01/19
 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361, 24X Fiche 50-000, 84/01/19, 8401240335

DOCKET BTN-50-489 PERKINS NUCLEAR STATION, UNIT 2

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licenseses charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds, Svc lists should be revised accordingly
 REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds, 84/01/19
 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361, 24X Fiche 50-000, 84/01/19, 8401240335

DOCKET BTN-50-490 PERKINS NUCLEAR STATION, UNIT 3

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licenseses charged from Debevoise & Liberman to Bishop, Liberman, Cook, Purcell & Reynolds Svc lists should be revised accordingly
 REYNOLDS, N B Bishop, Liberman, Cook, Purcell & Reynolds, 84/01/19,
 CLEMENTS, W L Docketing & Services Branch 2pp 21919 361 24X Fiche 50-000, 84/01/19, 8401240335,

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement, 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731 166, 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers." Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30, Consolidated Edison Co. of New York, Inc. 127pp 21826 040 24X Fiche: 50-000, 83/12/30, 8312120093.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp, 21946 053 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117,

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Svc list encl.
 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, 8312120093

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053, 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21937 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche: 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche: 50-000, 84/01/18, 8312120117

DOCKET BTN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
 FELTON, J M Division of Rules and Records, 83/10/18 WEISS, E R Union of Concerned Scientists. 3pp, 21960 003, 24X Fiche: 50-000, 83/10/18, 8401250015

--8209160068 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys.
 DIRCKS, W J Office of the Executive Director for Operations, SECY-82-352, 82/08/20, 37pp 21966 033, 24X Fiche 50-000, 83/10/18, 8401250015.

DOCKETED ITEMS

369

B401040249 Outlines procedures for reporting info promptly to region by using given telephone numbers for ofc & outside-of-ofc hours Util urged to use numbers
COLLINS, J T Region 4, Office of Director 83/12/19 OPREA, G W Houston Lighting & Power Co 2pp 21701 170 24X
Fiche 50-498, 83/12/19, B401040249

B401090711 Forwards review results re B20517 request for addl info & staff positions pertaining to GA Clarifications re Reg Guide 1 94 acceptable New clarification re Reg Guide 1 137 under review
KNIGHTON, G W Licensing Branch 3 83/12/20 OPREA, G W Houston Lighting & Power Co 7pp 21767 030 24X Fiche 50-498, 83/12/20, B401090711

B401090582 Forwards engineering assurance documentation describing program & repts re evaluated area findings & corrective action Comments requested by B40131
NOVAK, T M Assistant Director for Licensing 83/12/27
VOLLMER, R H Division of Engineering MATTSO, R J Division of Systems Integration (post 811005) PARTLOW, J O Division of GA, Safeguards & Inspection Programs (Post 830103) 1p 21756, 053 24X
Fiche 50-498, 83/12/27, B401090582

B401160038 Forwards criteria guidelines for NUREG-0737, Item II B 3, "Post-Accident Sampling Capability," to replace info following B30204 Request for Addl Info 281 7
KNIGHTON, G W Licensing Branch 3 83/12/27 OPREA, G W Houston Lighting & Power Co 11pp 21822 353 24X Fiche 50-498, 83/12/27, B401160038

B401060302 Forwards response to Generic Ltr 83-10C re TMI Action Item II, K 3 05, "Automatic Trip of Reactor Coolant Pumps" Response to Item 1 2 will be provided by B40515
GOLDBERG, J H Houston Lighting & Power Co 83/12/28 EISENHUT, D O Division of Licensing 5pp 21742 322 24X Fiche 50-498, 83/12/28, B401060302

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "Important to safety" & "safety-related" Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267, 24X
Fiche 50-000, 84/01/06, B401090221

B401310090 Forwards BER re tornado missile protection for isolation valve cubicle (IVC) Probability of tornado missile damage to IVCs & associated essential equipment adequately demonstrated Util complies w/GDC 2 & 4
NOVAK, T M Assistant Director for Licensing 84/01/06
GOLDBERG, J H Houston Lighting & Power Co 3pp 22021 130 24X
Fiche 50-498, 84/01/06, B401310090

--B401310098 BER approving tornado missile protection for isolation valve cubicle
* NRC - No Detailed Affiliation Given 84/01/06 6pp
22021 133 24X Fiche 50-498, 84/01/06, B401310090

--B401310104 "Technical Evaluation of PRA for Tornado & Hurricane Missile Hazard to Containment Isolation Valve Compartment Equipment, South Texas Project"
SIMIU, E Commerce, Dept of, National Bureau of Standards 84/01/06 NRC - No Detailed Affiliation Given 17pp
22021 139 24X Fiche 50-498, 84/01/06, B401310090.

--B401310108 Provides answers to NRC questions re evaluation of supplemental info on PRA assessment for tornado & hurricane missile hazard to containment isolation valve compartment equipment
SIMIU, E Commerce, Dept of, National Bureau of Standards 83/12/23 SINGH, B K NRC - No Detailed Affiliation Given 3pp.
22021 156 24X Fiche 50-498, 84/01/06, B401310090

B401310443 Requests IE review util documentation re engineering assurance program for eliminating need for addl verification program as prerequisite to issuing OL
KNIGHTON, G W Licensing Branch 3 84/01/10 MILHOAN, J L GA Branch 1p 22036 343 24X Fiche 50-498, 84/01/10, B401310443

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues," Svc list encl
EISENHUT, D O Division of Licensing 84/01/13 Consolidated Edison Co. of New York, Inc. 18pp 21946 174, 24X
Fiche 50-000, 84/01/13, B401130084

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401270396 Advises that RP Denise will be new Director, Div of Resident, Reactor Project & Engineering Programs, effective B40122
COLLINS, J T Region 4, Office of Director 84/01/23 OPREA, G W Houston Lighting & Power Co 1p 21976 246 24X
Fiche 50-498, 84/01/23, B401270396

F Security, medical, emergency & fire protection plans

B401090647 Summary of B30714 meeting w/util re fire protection, elimination of tornado-proof roof on isolation valve cubicle & pipe break
VIETTI, A Licensing Branch 3 83/12/13 Licensing Branch 3 5pp 21767 309 24X Fiche 50-498, 83/12/13, B401090647

B401270405 Responds to B20513 ltr re Rev 1 to security personnel training & qualification plan Portions of plan require addl mods Appropriate page changes should be submitted per encl comments Comments withheld (ref 10CFR73 21)
KNIGHTON, G W Licensing Branch 3 84/01/25 OPREA, G W Houston Lighting & Power Co 3pp 21981 054 24X Fiche 50-498, 84/01/25, B401270405

G Adjudicatory correspondence

B401240292 Suggests review of South Texas Nuclear Project vs Brown & Root, for evidence important to ASLB decision on OL application
SINKIN, L Sinkin, L A 84/01/16 OILINGKY, V Commissioners 1p 21907 270 24X Fiche: 50-498, 84/01/16, B401240292

B401180188 Suppl to Citizens Concerned About Nuclear Power proposed findings of fact & conclusions of law re level of intimidation & harassment experienced by inspectors. Certificate of Svc encl
SINKIN, L A Citizens Concerned About Nuclear Power, Inc. SINKIN, L A Sinkin, L A 84/01/17 11pp 21840 350 24X
Fiche: 50-498, 84/01/17, B401180188

B401300249 Notice of svc list name change & amend of notices of appearance Certificate of Svc encl
SILVERMAN, D J Houston Lighting & Power Co SILVERMAN, D J Lowenstein, Neuman, Reis, Axelrad & Toll 84/01/25 Atomic Safety and Licensing Board Panel 4pp 21995, 199 24X
Fiche 50-498, 84/01/25, B401300249

B401300260 Informs that util already responded to issues in Citizens Concerned About Nuclear Power (CCANP) suppl to proposed findings of fact & conclusions of law CCANP filing violates regulations No ASLB answer needed w/Certificate of Svc
SILVERMAN, D J Newman & Holtzinger SILVERMAN, D J Houston Lighting & Power Co 84/01/25 BECHHOEFFER, C, LAMB, J C, MILL, E E Atomic Safety and Licensing Board Panel. 5pp. 21998 326 24X
Fiche 50-498, 84/01/25, B401300260

K Utility Final Safety Analysis Report (FSAR) & amends

B401270363 Forwards Amend 36 to FSAR, consisting of responses to NUREG-0737, Item II, E 4 2, revised responses to NRC questions & miscellaneous FSAR test revs & editorial changes
GOLDBERG, J H Houston Lighting & Power Co 84/01/25 DENTON, H Office of Nuclear Reactor Regulation, Director. 4pp 21983 001 24X Fiche: 50-498, 84/01/25, B401270363

--B401270368 Amend 36 to FSAR.
* Houston Lighting & Power Co. 84/01/25. 1,017pp 21983, 005. 24X Fiche 50-498, 84/01/25, B401270363

Q Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR
FELTON, J M. Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge. 1p. 21744 003, 24X
Fiche: 50-000, 83/10/20, B401060040.

--B401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040.

DOCKETED ITEMS

B401240235 Revises response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks." Revised sys summary table encl
OPREA, G W. Houston Lighting & Power Co 83/11/01 COLLINS, J T
Region 4, Office of Director App 21910 037 24X
Fiche 50-498, 83/11/01, B401240235.

B401170312 Forwards QA Program Insp Rept 97900902/B3-03 re quality & acceptability of product or svc provided by vendor Receipt
ack requested w/o encl
JOHNSON, E H Region 4, Office of Director 83/11/29 OPREA, G W
Houston Lighting & Power Co 1p 21833 285 24X
Fiche 50-498, 83/11/29, B401170312

B401040553 Forwards IE Insp Rept 50-498/83-23 on 831031-1104 No violations noted
JOHNSON, E Region 4, Office of Director 83/12/07 OPREA, G W
Houston Lighting & Power Co 2pp 21707 355 24X
Fiche 50-498, 83/12/07, B401040553

--B401040559 IE Insp Rept 50-498/83-23 on 831031-1104 No violations noted Major areas inspected const activities, including site tour, review of QA programs & procedures for receipt, storage & handling of electrical & instrumentation cables
BESS, J E, CROSSMAN, W A, JOHNSON, W D Region 4, Office of Director, 83/12/06 App. 21707:357 24X Fiche 50-498, 83/12/07, B401040553

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEVYUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp, 21731, 166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/12/30, Consolidated Edison Co of New York, Inc 127pp 21826 060, 24X Fiche 50-000, 83/12/30, B312120093

B401270001 Forwards IE Insp Repts 50-498/83-22 & 50-499/83-22 on 831024-28 & notice of violation
JOHNSON, E H Region 4, Office of Director, 84/01/05 OPREA, G W
Houston Lighting & Power Co 2pp 21973 282 24X
Fiche: 50-498, 84/01/05, B401270001

--B401270002 Notice of violation from insp on 831024-28
* Region 4, Office of Director 84/01/05 3pp 21973 284 24X
Fiche 50-498, 84/01/05, B401270001

--B401270003 IE Insp Repts 50-498/83-22 & 50-499/83-22 on 831024-28 Violations noted, failure to take corrective action to assure acceptability of thread dimensions for site fabricated anchor bolts. Matl nonconformances not corrected
BOARDMAN, J R., CROSSMAN, W A Region 4, Office of Director 84/01/05 11pp, 21973:287, 24X Fiche 50-498, 84/01/05, B401270001

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc. 125pp, 21946 053 24X Fiche: 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10 Consolidated Edison Co of New York, Inc. 122pp 21826 184, 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-03, "Exercise Frequency." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp, 21957, 142, 24X Fiche: 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18, Consolidated Edison Co. of New York, Inc 118pp, 22000 001, 24X Fiche 50-000, 84/01/18, B312120116

I2120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp, 22000 041, 24X Fiche 50-000, 84/01/18, B312120117

B Reportable occurrences, LERS & related correspondence

B401100375 PNO-IV-83-034A on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212 Order issued due to breakdown in QA program Stop work order to be lifted on 831216 in site fabrication shop
CROSSMAN, W A Region 4, Office of Director 83/12/16 1p 21763 289 24X Fiche 50-498, 83/12/16, B401100375

B401030266 Final deficiency rept re tight seal on Target Rock pilot actuated solenoid valves Initially reported on 831118 Valves may be replaced or supplemented Item not reportable per 10CFR50.55(e)
OPREA, G W Houston Lighting & Power Co 83/12/19 COLLINS, J T
Region 4, Office of Director 3pp 21A81 171 24X
Fiche 50-498, 83/12/19, B401030266

B401100327 PNO-IV-83-034B on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212 Order involved breakdown in QA program re document control sys Order lifted on 831219
CROSSMAN, W A Region 4, Office of Director 83/12/19, 1p, 21764 144 24X Fiche 50-498, 83/12/19, B401100327

B401130173 Final deficiency rept re installation of cathodic protection devices on stainless steel piping Initially reported on 831202 Affected piping will be cut & replaced per ASME Code & weld specs Sys installation documents will be revised.
OPREA, G W Houston Lighting & Power Co 83/12/29 COLLINS, J T
Region 4, Office of Director App 21802 040 24X
Fiche 50-498, 83/12/29, B401130173

B401270482 Eighth interim deficiency rept re nonconforming welds in vendor fabricated Category 1 structural steel Initially reported on 810108 Bechtel will provide recommendations.
Final rept anticipated by 840323
OPREA, G W Houston Lighting & Power Co 84/01/16 COLLINS, J T
Region 4, Office of Director 2pp 21981 341 24X
Fiche 50-498, 84/01/16, B401270482

B401270138 Final deficiency rept re control & issuance of design related drawings. Initially reported on 831216 Configuration control program assures compliance w/technical requirements Item not reportable per 10CFR50.55(e)
OPREA, G W Houston Lighting & Power Co 84/01/20 COLLINS, J T
Region 4, Office of Director 3pp, 21982 034 24X
Fiche, 50-498, 84/01/20, B401270138

B401270240 Second interim deficiency rept re design basis flood Initially reported on 830830 Studies initiated to demonstrate integrity of main cooling reservoir embankment
Final rept expected by 840525
OPREA, G W Houston Lighting & Power Co 84/01/20 COLLINS, J T
Region 4, Office of Director 2pp 21982 154 24X
Fiche 50-498, 84/01/20, B401270240

B401270251 Suppl to final deficiency rept re improper installation of cathodic protection devices on stainless steel piping Initially reported on 831202 Deficiency determined to be reportable per Part 21 Brown & Root, Inc will be informed
OPREA, G W Houston Lighting & Power Co 84/01/20 COLLINS, J T
Region 4, Office of Director 2pp 21982 180 24X
Fiche 50-498, 84/01/20, B401270251

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

B401230015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche, 50-000, 83/10/18, B401230015

--B209160068 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys.
DIRCKS, W J Office of the Executive Director for Operations SECY-82-352 82/08/20 37pp 21966 035, 24X
Fiche 50-000, 83/10/18, B401250015

B401040249 Outlines procedures for reporting info promptly to region by using given telephone numbers for ofc & outside-of-ofc hours. Util urged to use numbers
COLLINS, J T Region 4, Office of Director 83/12/19 OPREA, G W
Houston Lighting & Power Co 2pp 21701 170 24X
Fiche 50-498, 83/12/19, B401040249

DOCKETED ITEMS

371

B40109011 Forwards review results re B20517 request for addl info & staff positions pertaining to QA Clarifications re Reg Guide 1 94 acceptable New clarification re Reg Guide 1 137 under review
KNIGHTON, G W Licensing Branch 3 83/12/20 OPREA, G W Houston Lighting & Power Co 7pp 21767 030 24X Fiche 50-498, 83/12/20, B401090711

B401090582 Forwards engineering assurance documentation describing program & repts re evaluated area findings & corrective action Comments requested by B40131
NEVAK, T M Assistant Director for Licensing 83/12/27
VOLLMER, R H Division of Engineering MATTSOHN, R J Division of Systems Integration (post B11005) PARTLOW, J G Division of QA, Safeguards & Inspection Programs (Post B30103) 1p 21756 055 24X Fiche 50-498, 83/12/27, B401090582

B401160038 Forwards criteria guidelines for NUREG-0737, Item II B 3, "Post-Accident Sampling Capability," to replace info following B30204 Request for Addl Info 281 7
KNIGHTON, G W Licensing Branch 3 83/12/27 OPREA, G W Houston Lighting & Power Co 11pp 21822 353 24X Fiche 50-498, 83/12/27, B401160038

B401060302 Forwards response to Generic Ltr 83-10C re TMI Action Item II K 3 03, "Automatic Trip of Reactor Coolant Pumps"
Response to Item 1 2 will be provided by B40915
GOLDBERG, J H Houston Lighting & Power Co 83/12/28, EISENHUT, D G Division of Licensing 5pp 21742 322 24X Fiche 50-498, 83/12/28, B401060302

B401050382 Generic Ltr B4-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Bvc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing
Bvc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, B401090221

B401310090 Forwards BER re tornado missile protection for isolation valve cubicle (IVC) Probability of tornado missile damage to IVCs & associated essential equipment adequately demonstrated Util complies w/ODC 2 & 4
NEVAK, T M Assistant Director for Licensing 84/01/06
GOLDBERG, J H Houston Lighting & Power Co 3pp 22021 130 24X Fiche 50-498, 84/01/06, B401310090

--B401310098 BER approving tornado missile protection for isolation valve cubicle
* NRC - No Detailed Affiliation Given 84/01/06 6pp
22021 133 24X Fiche 50-498, 84/01/06, B401310090

--B401310104 "Technical Evaluation of PRA for Tornado & Hurricane Missile Hazard to Containment Isolation Valve Compartment Equipment, South Texas Project"
SIMIU, E Commerce, Dept of, National Bureau of Standards 84/01/06
* NRC - No Detailed Affiliation Given 17pp
22021 139 24X Fiche 50-498, 84/01/06, B401310090

--B401310108 Provides answers to NRC questions re evaluation of supplemental info on PRA assessment for tornado & hurricane missile hazard to containment isolation valve compartment equipment
SIMIU, E Commerce, Dept of, National Bureau of Standards 83/12/23
* NRC - No Detailed Affiliation Given 3pp
22021 156 24X Fiche 50-498, 84/01/06, B401310090

B401310443 Requests IE review util documentation re engineering assurance program for eliminating need for addl verification program as prerequisite to issuing OL
KNIGHTON, G W Licensing Branch 3 84/01/10 MILHOAN, J L QA Branch 1p 22036 343 24X Fiche 50-498, 84/01/10, B401310443

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Bvc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, B401130084

B401270396 Advises that RP Denise will be new Director, Div of Resident Reactor Project & Engineering Programs, effective B40122
COLLINS, J T Region 4, Office of Director 84/01/23 OPREA, G W Houston Lighting & Power Co 1p 21976 246 24X Fiche 50-498, 84/01/23, B401270396

F Security, medical, emergency & fire protection plans

B401090647 Summary of B30714 meeting w/util re fire protection, elimination of tornado-proof roof on isolation valve cubicle & pipe break
VIETTI, A Licensing Branch 3 83/12/13 Licensing Branch 3 5pp 21767 309 24X Fiche 50-498, 83/12/13, B401090647

B401270405 Responds to B20513 ltr re Rev 1 to security personnel training & qualification plan Portions of plan require addl mode Appropriate page changes should be submitted per encl comments, Comments withheld (ref 10CFR73 21)
KNIGHTON, G W Licensing Branch 3 84/01/25 OPREA, G W Houston Lighting & Power Co 3pp 21981 054 24X Fiche 50-498, 84/01/25, B401270405

G Adjudicatory correspondence

B401240292 Suggests review of South Texas Nuclear Project vs Brown & Root for evidence important to ASLB decision on OL application
SINKIN, L Binkin, L A 84/01/16 GILINSKY, V Commissioners 1p 21909 270 24X Fiche 50-498, 84/01/16, B401240292

B401180188 Suppl to Citizens Concerned About Nuclear Power proposed findings of fact & conclusions of law re level of intimidation & harassment experienced by inspectors Certificate of Svc encl
SINKIN, L A Citizens Concerned About Nuclear Power, Inc
SINKIN, L A Sinkin, L A 84/01/17 11pp 21840 350 24X Fiche 50-498, 84/01/17, B401180188

B401300249 Notice of svc list name change & amend of notices of appearance, Certificate of Svc encl
SILVERMAN, D J Houston Lighting & Power Co SILVERMAN, D J Louenstein, Neuman, Reis, Axelrad & Toll 84/01/25 Atomic Safety and Licensing Board Panel App 21995 199 24X Fiche 50-498, 84/01/25, B401300249

B401300260 Informs that util already responded to issues in Citizens Concerned About Nuclear Power (CCANP) suppl to proposed findings of fact & conclusions of law CCANP filing violates regulations, No ASLB answer needed, W/Certificate of Svc
SILVERMAN, D J Newman & Holtzinger SILVERMAN, D J Houston Lighting & Power Co 84/01/25 BECHTOLD, C, LAMB, J C, HILL, E E Atomic Safety and Licensing Board Panel 5pp 21998 326 24X Fiche 50-498, 84/01/25, B401300260

K Utility Final Safety Analysis Report (FSAR) & amends

B401270363 Forwards Amend 36 to FSAR, consisting of responses to NUREG-0737, Item II E 4.2, revised responses to NRC questions & miscellaneous FSAR test revs & editorial changes
GOLDBERG, J H Houston Lighting & Power Co 84/01/25 DENTON, H Office of Nuclear Reactor Regulation, Director 4pp 21983 001 24X Fiche 50-498, 84/01/25, B401270363

--B401270368 Amend 36 to FSAR
* Houston Lighting & Power Co 84/01/25 1.017pp 21983 003 24X Fiche 50-498, 84/01/25, B401270363

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SALP results during 1982, Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 1p 21744 003 24X Fiche 50-000, 83/10/20, B401060040

--B401060150 List of SALP results during 1982
* Director's Office, Office of Inspection and Enforcement, 83/10/20 134pp 21744 004 24X Fiche 50-000, 83/10/20, B401060040

B401240235 Revises response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks," Revised sys summary table encl
OPREA, G W Houston Lighting & Power Co 83/11/01 COLLINS, J T Region 4, Office of Director 4pp 21910 037 24X Fiche 50-498, 83/11/01, B401240235

B401170312 Forwards QA Program Insp Rept 99900902/B3-03 re quality & acceptability of product or svc provided by vendor Receipt ack requested w/o encl
JOHNSON, E H Region 4, Office of Director 83/11/29 OPREA, G W Houston Lighting & Power Co 1p 21833 285 24X Fiche 50-498, 83/11/29, B401170312

DOCKETED ITEMS

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl DEVOUNO, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731, 166 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp 21826 060 24X Fiche: 50-000, 83/12/30, 8312120093

8401270001 Forwards IE Insp Repts 50-498/83-22 & 50-499/83-22 on 831024-28 & notice of violation JOHNSON, E H Region 4, Office of Director 84/01/05 OPREA, Q W Houston Lighting & Power Co 2pp 21973 282 24X Fiche: 50-498, 84/01/05, 8401270001

--8401270002 Notice of violation from insp on 831024-28. * Region 4, Office of Director. 84/01/05 3pp 21973 284 24X Fiche 50-498, 84/01/05, 8401270001.

--8401270003 IE Insp Repts 50-498/83-22 & 50-499/83-22 on 831024-28 Violations noted failure to take corrective action to assure acceptability of thread dimensions for site fabricated anchor bolts Metl nonconformances not corrected. BOARDMAN, J R., CROSSMAN, W A Region 4, Office of Director 84/01/05 11pp 21973 287 24X Fiche: 50-498, 84/01/05, 8401270001

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946 053 24X Fiche: 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10, Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107

8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp. 21957 142 24X Fiche: 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18, Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116.

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18, Consolidated Edison Co. of New York, Inc. 120pp 22000 041, 24X Fiche: 50-000, 84/01/18, 8312120117.

B. Reportable occurrences, LERs & related correspondence

8401100375 PNO-IV-83-034A: on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212. Order issued due to breakdown in QA program Stop work order to be lifted on 831216 in site fabrication shop. CROSSMAN, W A Region 4, Office of Director. 83/12/16, 1p 21763 289, 24X Fiche: 50-498, 83/12/16, 8401100375.

8401030266 Final deficiency rept re tight seal on Target Rock pilot actuated solenoid valves. Initially reported on 831118 Valves to be replaced or supplemented. Item not reportable per CFR50, 55(e), IEA, Q W Houston Lighting & Power Co 83/12/19, COLLINS, J T, Region 4, Office of Director, 3pp. 21681 171, 24X Fiche: 50-498, 83/12/19, 8401030266

100327 PNO-IV-83-034B: on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212. Order involved breakdown in QA program re document control sys Order lifted on 831219. CROSSMAN, W A Region 4, Office of Director. 83/12/19 1p 21764 144, 24X Fiche: 50-498, 83/12/19, 8401100327.

1130173 Final deficiency rept re installation of cathodic protection devices on stainless steel piping Initially reported on 831202. Affected piping will be cut & replaced per ASME Code weld specs. Sys installation documents will be revised. OPREA, Q W Houston Lighting & Power Co 83/12/29, COLLINS, J T, Region 4, Office of Director, 4pp. 21802 040 24X Fiche: 50-498, 83/12/29, 8401130173.

8401270482 Eighth interim deficiency rept re nonconforming welds vendor fabricated Category I structural steel Initially reported on 810108 Bechtel will provide recommendations Final rept anticipated by 840323 OPREA, Q W Houston Lighting & Power Co 84/01/16 COLLINS, J T Region 4, Office of Director 2pp 21981 341 24X Fiche 50-498, 84/01/16, 8401270482

8401270138 Final deficiency rept re control & issuance of design related drawings Initially reported on 831216 Configuration control program assures compliance w/technical requirements Item not reportable per 10CFR50 55(e) OPREA, Q W Houston Lighting & Power Co 84/01/20 COLLINS, J T Region 4, Office of Director 3pp 21982 054 24X Fiche 50-498, 84/01/20, 8401270138

8401270240 Second interim deficiency rept re design basis flood Initially reported on 830830 Studies initiated to demonstrate integrity of main cooling reservoir embankment Final rept expected by 840525 OPREA, Q W Houston Lighting & Power Co 84/01/20 COLLINS, J T Region 4, Office of Director 2pp 21982 154 24X Fiche: 50-498, 84/01/20, 8401270240

8401270251 Suppl to final deficiency rept re improper installation of cathodic protection devices on stainless steel piping Initially reported on 831202 Deficiency determined to be reportable per Part 21 Brown & Root, Inc will be informed OPREA, Q W Houston Lighting & Power Co 84/01/20 COLLINS, J T Region 4, Office of Director 2pp 21982 180, 24X Fiche 50-498, 84/01/20, 8401270251

DOCKET 87N-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8401090091 Discusses deferring WPPSS-3 Instrumentation & Control Sys Branch work until Callaway issues resolved KNIGHTON, Q W Licensing Branch 3 83/12/27 ROBA, F Instrumentation & Control Systems Branch 1p. 21757 281 24X Fiche: 50-508, 83/12/27, 8401090091

8401190123 Ack receipt of 831118 ltr re const & DL review schedules Requested response date of 831205 could not be met Schedule review under way. New schedule date will be provided KNIGHTON, Q W Licensing Branch 3, 84/01/03 SORESEN, Q C Washington Public Power Supply System 2pp 21871 032, 24X Fiche 50-508, 84/01/03, 8401190123

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related " Svc list encl EISENHUT, D Q Division of Licensing 84/01/05 Consolidated Edison Co. of New York, Inc 16pp 21946 190 24X Fiche: 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing Svc list encl EISENHUT, D Q Division of Licensing 84/01/06 Consolidated Edison Co. of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401130084 Generic Ltr 84-03 to all licensees of operating reactors applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues." Svc list encl EISENHUT, D Q Division of Licensing. 84/01/13 Consolidated Edison Co. of New York, Inc 18pp 21946 174, 24X Fiche: 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants. HAMMOND, J Division of Licensing 84/01/17 Division of Licensing, 1p. 22000 349, 24X Fiche: 50-000, 84/01/17, 8401270536

8401310276 Forwards responses to NRC request for addl info re Genav. Ltr 82-14 concerning structural engineering audit. SORESEN, Q C Washington Public Power Supply System. 84/01/17 KNIGHTON, Q W Licensing Branch 3 153pp. 22015 059 24X Fiche: 50-508, 84/01/17, 8401310276.

D. NRC Draft/Final Environmental Statements, suppl & correspondence

8401250160 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF WPPSS NUCLEAR PROJECT NO 3 Docket No 50-508 (Washington Public Power Supply System) * Division of Licensing NUREG-1033 83/12/31 191pp Available at NRC. \$6.00 21931 249 24X Fiche: 50-508, 83/12/31, 8401250160

8401270510 Forwards DES & FR notice W/o encl
KNIGHTON, O W Licensing Branch 3 84/01/13 CHERRY, M Cherry,
M M/Cherry, Flynn & Kanter 3pp 22002 205 24X
Fiche 50-508, 84/01/13, 8401270510

8401270513 Forwards DES (NUREG-1033) & FR notice of availability W/o
encl
KNIGHTON, O W Licensing Branch 3 84/01/13 MAZUR, D W Washington
Public Power Supply System 2pp 22002 203 24X
Fiche 50-508, 84/01/13, 8401270513

8401310181 Forwards for review & comment, DES & FR notice of
availability, W/o DES
KNIGHTON, O W Licensing Branch 3 84/01/13 WOOD, J M Commerce,
Dept of, Natl Oceanographic & Atmospheric Administration 3pp
22032 355 24X Fiche 50-508, 84/01/13, 8401310181

--8401310184 Notice of availability of DES for facility
KNIGHTON, O W Licensing Branch 3 84/01/13 4pp 22032 360
24X Fiche 50-508, 84/01/13, 8401310181

F Security, medical, emergency & fire protection plans

8401190121 Responds to 821203 & 830616 ltrs re location of primary &
backup emergency operations facility Primary facility approx
0.85 miles from site & alternate location in Olympia, WA, 30
miles from site, acceptable
EISENHUT, D G Division of Licensing 84/01/04 MAZUR, D W
Washington Public Power Supply System 2pp 21871 034, 24X
Fiche 50-508, 84/01/04, 8401190121

G Adjudicatory correspondence

8401030245 Advises that time for Commission to review ALAB-747 expired
Commission declined review Decision became final agency
action on 831228
CHILK, S J Office of the Secretary of the Commission 83/12/29
Coalition for Safe Power 1p 21729 108 24X Fiche 50-508,
83/12/29, 8401030245

8401160197 Suppl to petition of Coalition for Safe Power for
leave to intervene & request for hearing, per ABLB 831206
Order Certificate of Svc encl
BELL, N Coalition for Safe Power 84/01/10 Atomic Safety and
Licensing Board Panel 3pp 21808 303 24X Fiche 50-508, 84/01/10,
8401160197

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees
charged from Debevoise & Liberman to Bishop, Liberman, Cook,
Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds, 84/01/19
CLEMENTS, W L Docketing & Services Branch 2pp 21919.361 24X
Fiche 50-000, 84/01/19, 8401240335

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of SAMP results
during 1982 Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20, ZAHNER, R E
Shaw, Pittman, Potts & Troubridge 1p 21744 003 24X
Fiche 50-000, 83/10/20, 8401060040

--8401060150 List of SAMP results during 1982
* Director's Office, Office of Inspection and Enforcement,
83/10/20, 134pp, 21744:004 24X Fiche 50-000, 83/10/20,
8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys." Svc list encl
DEVOUNG, R C Director's Office, Office of Inspection and
Enforcement, 83/12/28 Consolidated Edison Co. of New York, Inc.
124pp 21731.166 24X Fiche 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 5HK Breakers" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/12/30 Consolidated Edison Co. of New
York, Inc 127pp 21826:060 24X Fiche 50-000, 83/12/30, 8312120093.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/10 Consolidated Edison Co. of New
York, Inc 125pp 21946:053, 24X Fiche 50-000, 84/01/10, 8312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/10 Consolidated Edison Co. of New
York, Inc 122pp 21826:184 24X Fiche 50-000, 84/01/10, 8312120107

8401260358 Advises that implementation schedule required by IE Bulletin
83-08, "Electrical Circuit Breakers Undervoltage Trip
Feature in Use in Safety-Related Applications Other Than
Reactor Trip Sys." will be provided upon const restart
KOHLE, A D Washington Public Power Supply System 84/01/11
MARTIN, J B Region 5, Office of Director 2pp 21956 024 24X
Fiche 50-508, 84/01/11, 8401260358

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/16 Consolidated Edison Co. of New
York, Inc 127pp 21957 142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators" Svc list
encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/18 Consolidated Edison Co. of New
York, Inc 118pp 22000 001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/18 Consolidated Edison Co. of New
York, Inc. 120pp, 22000:041 24X Fiche 50-000, 84/01/18, 8312120117.

DOCKET BTN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

A Application/construction stage documents & correspondence

8401170062 FOIA request for six categories of documents re facilities
ANDERSON, S I Garvey, Schubert, Adams & Barer, 83/09/28 Office
of Administration, 2pp 21838 001 24X Fiche 50-509, 83/09/28,
8401170062

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees
charged from Debevoise & Liberman to Bishop, Liberman, Cook,
Purcell & Reynolds Svc lists should be revised accordingly.
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds, 84/01/19.
CLEMENTS, W L Docketing & Services Branch 2pp, 21919.361 24X
Fiche 50-000, 84/01/19, 8401240335

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

A. Application/construction stage documents & correspondence

8401170062 FOIA request for six categories of documents re facilities
ANDERSON, S I Garvey, Schubert, Adams & Barer, 83/09/28, Office
of Administration, 2pp 21838 001, 24X Fiche 50-509, 83/09/28,
8401170062

H General correspondence

8401240335 Informs that firm name of counsel for applicants/licensees
charged from Debevoise & Liberman to Bishop, Liberman, Cook,
Purcell & Reynolds Svc lists should be revised accordingly
REYNOLDS, N S Bishop, Liberman, Cook, Purcell & Reynolds, 84/01/19.
CLEMENTS, W L Docketing & Services Branch 2pp, 21919.361, 24X
Fiche 50-000, 84/01/19, 8401240335

B. Reportable occurrences, LERs & related correspondence

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by
Lovejoy Coupling & installed by Transamerica Delaval, on
shafts in overspeed governor fuel transfer pump drive, inap
of hubs in listed facilities recommended, Utilis notified.
BOYER, R E Transamerica Delaval, Inc. 84/01/09 Director's
Office, Office of Inspection and Enforcement, 3pp, 21828:269, 24X
Fiche 50-000, 84/01/09, 8401170186

DOCKETED ITEMS

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8401310520 Forwards itemized breakdown of NRC costs incurred by review of withdrawn CP application, in response to 831011 request. Interest charges as of 831128 waived. Interest will be due on any late payment beyond 840213. MILLER, W. D. License Fee Management Branch. 84/01/23 WITHERS, B. D. Portland General Electric Co App 22036-352 24X Fiche: 50-514, 84/01/23, 8401310520

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8401310520 Forwards itemized breakdown of NRC costs incurred by review of withdrawn CP application, in response to 831011 request. Interest charges as of 831128 waived. Interest will be due on any late payment beyond 840213. MILLER, W. D. License Fee Management Branch. 84/01/23 WITHERS, B. D. Portland General Electric Co App 22036-352 24X Fiche: 50-514, 84/01/23, 8401310520.

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

I. Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II. KAMMER, D. S. Tennessee Valley Authority. 84/01/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 21865-001 24X Fiche: 50-000, 84/01/12, 8401200194

--8401200199 Annual Financial Rept 1982, Vol I. PARRIS, H. G. Tennessee Valley Authority. 84/01/12. 75pp. 21865-002. 24X Fiche: 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II. PARRIS, H. G. Tennessee Valley Authority. 84/01/12. 96pp. 21865-077. 24X Fiche: 50-000, 84/01/12, 8401200194

O. Inspection reports, IE Bulletins & correspondence

8401090350 Forwards IE Insp Rept 50-518/83-02 on 831026. No violations noted. VERRELLI, D. M. Division of Project & Resident Programs. 83/12/13. PARRIS, H. G. Tennessee Valley Authority. 2pp. 21754-038 24X Fiche: 50-518, 83/12/13, 8401090350

--8401090357 IE Insp Rept 50-518/83-02 on 831026. No violations noted. Major areas inspected: storage & maint of safety-related equipment. SHAW, W. B. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. 83/12/14. 4pp. 21754-040 24X Fiche: 50-518, 83/12/13, 8401090350

B. Reportable occurrences, LERs & related correspondence

8401130053 First interim deficiency rept re Transamerica Delaval, Inc GA program. Initially reported on 831206. Final configuration for control cabinet indicates drawing Revs K.L. & M not incorporated. Also reportable per Part 21. MILLS, L. M. Tennessee Valley Authority. 84/01/03. O'REILLY, J. P. Region 2, Office of Director. 2pp. 21802-354 24X Fiche: 50-000, 84/01/03, 8401130053.

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended. Utilis notified. BOYER, R. E. Transamerica Delaval, Inc. 84/01/09. Director's Office, Office of Inspection and Enforcement. 5pp. 21828-269. 24X Fiche: 50-000, 84/01/09, 8401170186

8401300246 Final deficiency rept re Delaval problem w/starting air valve assembly on standby diesels. Initially reported on 821201. Capscrews replaced per approved procedure & drawings revised to reflect shorter length. MILLS, L. M. Tennessee Valley Authority. 84/01/23. O'REILLY, J. P. Region 2, Office of Director. 2pp. 21993-360. 24X Fiche: 50-000, 84/01/23, 8401300246.

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

O. Adjudicatory correspondence

8401270221 Motion to terminate appellate jurisdiction retained in ALAB-463, ALAB-554 & ALAB-558 on environ effects of radon releases from mining & milling of U for reactor fuel & to dismiss proceedings as moot. Certificate of Svc encl. SANGER, H. S., WALLACE, L. E., BURGER, J. F. Tennessee Valley Authority. 84/01/23. Atomic Safety and Licensing Appeal Panel. 17pp. 21973-309. 24X Fiche: 50-519, 84/01/23, 8401270221

8401300252 Memorandum & Order ALAB-760, terminating limited appellate jurisdiction previously retained over CP proceeding. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 84/01/27. 2pp. 21998-298. 24X Fiche: 50-519, 84/01/27, 8401300252

I. Financial information

8401200194 Forwards Annual Financial Rept 1982, Vols I & II. KAMMER, D. S. Tennessee Valley Authority. 84/01/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 21865-001 24X Fiche: 50-000, 84/01/12, 8401200194.

--8401200199 Annual Financial Rept 1982, Vol I. PARRIS, H. G. Tennessee Valley Authority. 84/01/12. 75pp. 21865-002. 24X Fiche: 50-000, 84/01/12, 8401200194

--8401200206 Annual Financial Rept 1982, Vol II. PARRIS, H. G. Tennessee Valley Authority. 84/01/12. 96pp. 21865-077. 24X Fiche: 50-000, 84/01/12, 8401200194

B. Reportable occurrences, LERs & related correspondence

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended. Utilis notified. BOYER, R. E. Transamerica Delaval, Inc. 84/01/09. Director's Office, Office of Inspection and Enforcement. 5pp. 21828-269. 24X Fiche: 50-000, 84/01/09, 8401170186

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

B. Reportable occurrences, LERs & related correspondence

8401130053 First interim deficiency rept re Transamerica Delaval, Inc GA program. Initially reported on 831206. Final configuration for control cabinet indicates drawing Revs K.L. & M not incorporated. Also reportable per Part 21. MILLS, L. M. Tennessee Valley Authority. 84/01/03. O'REILLY, J. P. Region 2, Office of Director. 2pp. 21802-354 24X Fiche: 50-000, 84/01/03, 8401130053

8401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended. Utilis notified. BOYER, R. E. Transamerica Delaval, Inc. 84/01/09. Director's Office, Office of Inspection and Enforcement. 5pp. 21828-269. 24X Fiche: 50-000, 84/01/09, 8401170186

8401300246 Final deficiency rept re Delaval problem w/starting air valve assembly on standby diesels. Initially reported on 821201. Capscrews replaced per approved procedure & drawings revised to reflect shorter length. MILLS, L. M. Tennessee Valley Authority. 84/01/23. O'REILLY, J. P. Region 2, Office of Director. 2pp. 21993-360. 24X Fiche: 50-000, 84/01/23, 8401300246

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

O. Adjudicatory correspondence

8401270221 Motion to terminate appellate jurisdiction retained in ALAB-463, ALAB-554 & ALAB-558 on environ effects of radon releases from mining & milling of U for reactor fuel & to dismiss proceedings as moot. Certificate of Svc encl. SANGER, H. S., WALLACE, L. E., BURGER, J. F. Tennessee Valley Authority. 84/01/23. Atomic Safety and Licensing Appeal Panel. 17pp. 21973-309. 24X Fiche: 50-519, 84/01/23, 8401270221.

8401300252 Memorandum & Order ALAB-760, terminating limited appellate jurisdiction previously retained over CP proceeding. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 84/01/27. 2pp. 21998-298. 24X Fiche: 50-519, 84/01/27, 8401300252.

DOCKETED ITEMS

375

S Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive Insp of hubs in listed facilities recommended Utilis notified
BOYER, R E Transamerica Delaval, Inc 84/01/09 Director's Office, Office of Inspection and Enforcement 5pp 21828 267 24X
Fiche 50-000, 84/01/09, B401170186

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "Important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

G Inspection reports, IE Bulletins & correspondence

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X
Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X
Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X
Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X
Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X
Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X
Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X
Fiche 50-000, 84/01/18, B312120117

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

B401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "Important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 18pp 21946 190 24X
Fiche 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000, 84/01/06, B401090221

B401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues" Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

G Inspection reports, IE Bulletins & correspondence

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X
Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X
Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 125pp 21946 053 24X
Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X
Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/16 Consolidated Edison Co of New York, Inc 127pp 21957 142 24X
Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 118pp 22000 001 24X
Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/18 Consolidated Edison Co of New York, Inc 120pp 22000 041 24X
Fiche 50-000, 84/01/18, B312120117

DOCKET 50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B401180008 FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983
BERNABEI, L Government Accountability Project 83/09/15 Office of Administration 2pp 21853 001 24X
Fiche 50-528, 83/09/15, B401180008

B401180009 Responds to FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983 for facilities. Forwards documents listed on app.
FELTON, J M Division of Rules and Records, 83/10/11, BERNABEI, L Government Accountability Project 5pp 21853 003 24X
Fiche 50-528, 83/10/11, B401180009

DOCKETED ITEMS

- 8401180013 Trip report of 830422-24 Caseload Forecast Panel site visit re projected fuel load dates
LICITRA, E. A. Licensing Branch 3 83/10/11 NOVAK, T. M. Assistant Director for Licensing. 2pp 21853 017 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180017 "Palo Verde Nuclear Generating Station Caseload Forecast Startup Status."
* Arizona Public Service Co 83/06/22 58pp. 21853 067 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180020 "Palo Verde Nuclear Generating Station Caseload Forecast."
* Arizona Public Service Co 83/06/22. 86pp 21853 125 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180022 "Palo Verde Nuclear Generating Station Caseload Forecast"
* Arizona Public Service Co. 83/03/31 86pp 21853 211 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180026 NRC questions & util responses re facility startup Related documentation encl.
* NRC - No Detailed Affiliation Given 82/03/18 21pp.
21853 286. 24X Fiche: 50-528, 83/10/11, 8401180009
- 8401180028 Palo Verde Nuclear Generating Station Caseload Forecast Panel meeting
* Arizona Public Service Co 80/10/28. 113pp. 21853.306. 24X
Fiche: 50-528, 83/10/11, 8401180009.
- 8401180033 Palo Verde Nuclear Generating Station Caseload Forecast Panel 790425 & 26 meetings
* Arizona Public Service Co. 79/04/25. 63pp 21854.057. 24X
Fiche: 50-528, 83/10/11, 8401180009.
- 8401180036 Agenda for Caseload Forecast Panel 790425-26 meetings
* NRC - No Detailed Affiliation Given. 79/04/25 NRC - No Detailed Affiliation Given. 2pp 21854:120 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180042 Submits 790509 daily staff notes.
GOSSICK, L. V. Office of the Executive Director for Operations
79/05/10. HENDRIE, J., OILINSKY, V., AHEARNE, J. F. Commissioners
2pp. 21854:129. 24X Fiche: 50-528, 83/10/11, 8401180009.
- 8401180047 Notes re test & startup.
* NRC - No Detailed Affiliation Given 79/04/25. 2pp.
21854:140. 24X Fiche: 50-528, 83/10/11, 8401180009
- 8401180067 Chart re NRC permits & licenses.
* NRC - No Detailed Affiliation Given 83/10/11. 3pp
21854:155 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180073 Confirms 780227 telcon w/R Robb re corrections to Jan 1978 yellowbook (NREG-0030). Corrections listed
VAN BRUNT, E. E. Arizona Public Service Co. 78/02/27.
LOVELACE, W. H. NRC - No Detailed Affiliation Given 3pp.
21854:158. 24X Fiche: 50-528, 83/10/11, 8401180009
- 8401180075 Chart & info denoting facility cable & termination percentages.
* Arizona Public Service Co 83/10/11. 5pp. 21854:168 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180077 Chart re design/procurement & mechanical/electrical installation/insp
* Arizona Public Service Co. 83/10/11. 8pp. 21854:182. 24X
Fiche: 50-528, 83/10/11, 8401180009.
- 8401180082 "Palo Verde Nuclear Generating Station Test Index."
* Arizona Public Service Co. AES90-RJ. 83/10/11. 27pp.
21854:190. 24X Fiche: 50-528, 83/10/11, 8401180009
- 8401180088 Notes re facility fuel load dates.
* NRC - No Detailed Affiliation Given. 82/11/30. 4pp.
21854:218. 24X Fiche: 50-528, 83/10/11, 8401180009
- 8401180090 Palo Verde Nuclear Generating Station master startup schedule.
* Arizona Public Service Co. 80/10/27. 33pp 21854:275. 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401180094 Unit 1 & common startup schedule milestones.
* Arizona Public Service Co. 80/10/28 4pp. 21854:308. 24X
Fiche: 50-528, 83/10/11, 8401180009.
- 8401180097 Agenda for Caseload Forecast Panel site visit for ut of 820323
* NRC - No Detailed Affiliation Given 82/03/15. NRC - No Detailed Affiliation Given 3pp 21854 312 24X
Fiche 50-528, 83/10/11, 8401180009
- 8401180102 Summary of 810824 meeting w/util in Washington, DC re NRC 1980 review of facility project schedule.
LOVELACE, W. H. HUBBARD, R. NRC - No Detailed Affiliation Given 81/08/24 NRC - No Detailed Affiliation Given 2pp 21854 315 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180106 Agenda for Caseload Forecast Panel 801028 meeting
* NRC - No Detailed Affiliation Given 80/10/28 NRC - No Detailed Affiliation Given 1p 21854 323 24X
Fiche 50-528, 83/10/11, 8401180009
- 8401180116 Computer printout re predecessor/successor analysis listing of cumulative resource requirements based on facility early & late start
* Arizona Public Service Co 83/07/23 34pp. 21854:347 24X
Fiche: 50-528, 83/10/11, 8401180009
- 8401170176 Further response to FOIA request for records re R Gunderson & W Royce allegations concerning facility Documents subj to request entirely withheld (ref FOIA Exemptions 5 & 7).
FELTON, J. M. Division of Rules and Records. 83/11/04. GARDE, B. Government Accountability Project 2pp 21837:353 24X
Fiche 50-528, 83/11/04, 8401170176.
- 8401050204 Requests issuance of certification that facilities designed in furtherance of abating or controlling atmospheric pollutants, contaminants or water pollution Certification required for bond financing
VAN BRUNT, E. E. Arizona Public Service Co 83/12/05 NRC - No Detailed Affiliation Given 6pp 21727 247 24X
Fiche: 50-528, 83/12/05, 8401050204
- 8312230326 Forwards staffing survey to assist in developing expected staffing profile in place at time OL is obtained. Form should be completed by 831216
KNIGHTON, G. W. Licensing Branch 3 83/12/06. VAN BRUNT, E. E. Arizona Public Service Co 3pp 21619 325 24X
Fiche: 50-528, 83/12/06, 8312230326
- 8401050024 Responds to 831017 ltr expressing dissatisfaction w/not receiving info re hot functional testing problems. Apologizes for withholding handout at 831012 meeting. Util continuing to give status briefings as necessary
REHM, T. A. Office of the Executive Director for Operations
83/12/07 BERNABEI, L. Government Accountability Project. 4pp.
21736:217 24X Fiche 50-528, 83/12/07, 8401050024
- 840110365 Forwards request for addl info re TMI Item 11.F.2 re reactor vessel monitoring sys to complete review of 830729 response
KNIGHTON, G. W. Licensing Branch 3 83/12/20 VAN BRUNT, E. E. Arizona Public Service Co 3pp 21794.332 24X
Fiche 50-528, 83/12/20, 840110365
- 8401030061 Forwards general description of facilities, revising 831205 request for certification that facilities designed to further abate or control atmospheric pollutants or contaminants or water pollution
VAN BRUNT, E. E. Arizona Public Service Co 83/12/23 NRC - No Detailed Affiliation Given 5pp 21683 101. 24X
Fiche: 50-528, 83/12/23, 8401030061
- 8401180031 Forwards certification of pollution control facilities, in response to 831205 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/12/29 VAN BRUNT, E. E. Arizona Public Service Co. 2pp.
21847 341. 24X Fiche: 50-528, 83/12/29, 8401180031.
- 8401180037 Certification of pollution control facilities.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/12/29 4pp 21847:343. 24X Fiche 50-528, 83/12/29, 8401180031
- 8401190086 Discusses evaluation of util 820924 submittal re potential Joy Mfg Co fan blade missile hazards. Adequate protection against missile effects provided
EISENHUT, D. O. Division of Licensing 83/12/29 EISENHUT, T. W. Division of Resident Reactor Project & Engineering Programs. 2pp.
21870:257 24X Fiche: 50-528, 83/12/29, 8401190086.
- 8401310138 Forwards order extending latest const completion date for CFFR-141 from 830831 to 841231, in response to 830512 & 0909 requests
EISENHUT, D. O. Division of Licensing 83/12/29. VAN BRUNT, E. E. Arizona Public Service Co. 2pp 22026:337 24X
Fiche: 50-528, 83/12/29, 8401310138.

DOCKETED ITEMS

377

--8401310144 Order extending latest const completion date for CPPR-41 from 830831 to 841231
EISENHUT, D G Division of Licensing 83/12/29 Arizona Public Service Co 3pp 22026 339 24X Fiche 50-528, 83/12/29, 8401310138

--8401310148 Evaluation supporting issuance of order extending latest const completion date for CPPR-141 to 841231
* NRC - No Detailed Affiliation Given 83/12/29 3pp 22026 342 24X Fiche 50-528, 83/12/29, 8401310138

8312120108 Board Notification 84-004 notifies of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D G Division of Licensing 84/01/05 FALLADINO, N J Commissioners 2pp 21993 324 24X Fiche 50-000, 84/01/05, 8312120108

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated Edison Co of New York, Inc 18pp 21957 267 24X Fiche 50-000, 84/01/06, 8401090221

8401190201 Submits daily highlights Andognini resigned for health reasons E Van Brunt will assume responsibility for engineering, const, startup, operation & maint
KNIGHTON, Q W Licensing Branch 3 84/01/09 DENTON, H., CABE, E, CARTER, J NRC - No Detailed Affiliation Given 1p 21870 016 24X Fiche 50-528, 84/01/09, 8401190201

8401160068 Forwards responses to Questions 640 01 640 02 & 640 03 re procedure generation package
VAN BRUNT, E E Arizona Public Service Co 84/01/10 KNIGHTON, Q Licensing Branch 3 12pp 21815 214 24X Fiche 50-528, 84/01/10, 8401160068

8401130084 Generic Ltr 84-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X Fiche 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, 8401270536

8401270467 Documents understanding of 840111 telcon re justifications for interim operation (JOI) for unqualified safety-related equipment, per util 831202 ltr Util will submit marked-up revs to equipment rept summary tables
VAN BRUNT, E E Arizona Public Service Co 84/01/24 KNIGHTON, Q Licensing Branch 3, 2pp 21980 326 24X Fiche 50-528, 84/01/24, 8401270467

8401270277 Forwards response to 831206 ltr transmitting facility staffing survey
VAN BRUNT, E E Arizona Public Service Co 84/01/25 KNIGHTON, Q Licensing Branch 3 10pp 21975 298 24X Fiche 50-528, 84/01/25, 8401270277

8401310313 Forwards corrected 830913 ltr re steam generator tube rupture accident analysis, incorrect figures submitted.
VAN BRUNT, E E Arizona Public Service Co. 84/01/27, KNIGHTON, Q Licensing Branch 3 2pp 22026 308 24X Fiche 50-528, 84/01/27, 8401310313

--8401310317 Corrected ltr forwarding, for review, steam generator tube rupture analysis
VAN BRUNT, E E Arizona Public Service Co. 83/09/13 KNIGHTON, Q Licensing Branch 3, 23pp 22026 310 24X Fiche 50-528, 84/01/27, 8401310313

E NRC Safety Evaluation Report (SER), supp's & correspondence

8312090366 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2, AND 3 Docket Nos. STN 50-528, STN 50-529 & STN 50-530 (Arizona Public Service Company, et al)
* Division of Licensing NUREG-0857 805 83/11/30 41pp Available at NRC 85 00 21445 118 24X Fiche 50-528, 83/11/30, 8312090366

8401030261 Forwards schedules for completion of DL review of open & confirmatory issues identified in SSER 5
VAN BRUNT, E E Arizona Public Service Co 83/12/23 KNIGHTON, Q Licensing Branch 3 3pp 21681 287 24X Fiche 50-528, 83/12/23, 8401030261

8401100418 Responds to SSER 5 (NUREG-0857) requesting addl info re meteorological effect of Palo Verde hills Data for primary meteorological tower representative of meteorology in emergency planning zone
VAN BRUNT, E E Arizona Public Service Co 84/01/03 KNIGHTON, Q Licensing Branch 3 3pp 21763 124 24X Fiche 50-528, 84/01/03, 8401100418

8401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per SSER 5 (NUREG-0857) & util 831223 ltr.
VAN BRUNT, E E Arizona Public Service Co 84/01/24 KNIGHTON, Q Licensing Branch 3 2pp 21975 255 24X Fiche 50-528, 84/01/24, 8401270302

--8401270306 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone"
* Arizona Public Service Co 84/01/31 24pp. 21975 257. 24X Fiche 50-528, 84/01/24, 8401270302.

F Security, medical, emergency & fire protection plans

8401090174 Forwards info re backfitting issue concerning source range neutron flux monitor in remote shutdown panel per App R to 10CFR50 Util latest response must be revised.
LICITRA, E A Licensing Branch 3, 83/12/29 EISENHUT, D G, Division of Licensing, 2pp 21737 213 24X Fiche 50-528, 83/12/29, 8401090174.

8401100418 Responds to SSER 5 (NUREG-0857) requesting addl info re meteorological effect of Palo Verde hills Data for primary meteorological tower representative of meteorology in emergency planning zone
VAN BRUNT, E E Arizona Public Service Co 84/01/03 KNIGHTON, Q Licensing Branch 3 3pp 21763 124. 24X Fiche 50-528, 84/01/03, 8401100418

8401300001 Forwards staff comments on detailed control room design review program plan submitted per Suppl i to NUREG-0737.
Schedule for response to comments requested by 840131 KNIGHTON, Q W. Licensing Branch 3 84/01/10. VAN BRUNT, E E. Arizona Public Service Co 9pp. 22027 321 24X Fiche 50-528, 84/01/10, 8401300001.

8401200051 Summary of 831109 public meeting in Phoenix, AZ re emergency preparedness.
SCARANO, R A Division of Radiological Safety & Safeguards Program 84/01/16. MARTIN, J. B Region 5, Office of Director. 4pp 21865 277. 24X Fiche 50-528, 84/01/16, 8401200051

--8401200053 Forwards operations summary of notification alert network telephone during 830511 exercise, per 831109 request Summary indicates two periods of time when phone not operational
ANDOGNINI, Q C. Arizona Public Service Co. 83/12/09. MARTIN, J. B Region 5, Office of Director 4pp. 21865 281 24X Fiche 50-528, 84/01/16, 8401200051

8401230656 Releases public version of revised facility emergency plan
FELTON, J. M Division of Rules and Records. 84/01/18 Document Management Branch. 1p. 21925 249 24X Fiche 50-528, 84/01/18, 8401230656.

--8401230661 Public version of Rev 3 to Facility emergency plan. W/831220 transmittal sheet
* Arizona Public Service Co. 83/10/31 413pp. 21925 251 24X Fiche 50-528, 84/01/18, 8401230656

8401250084 Forwards description of offsite protective action decision process & activation of technical support ctr & satellite technical support ctr, per request.
VAN BRUNT, E E Arizona Public Service Co 84/01/20. KNIGHTON, Q. Licensing Branch 3 4pp 21940 225. 24X Fiche 50-528, 84/01/20, 8401250084

DOCKETED ITEMS

8401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per 88ER 5 (NUREG-0857) & until 831223 ltr VAN BRUNT, E. E. Arizona Public Service Co. 84/01/24 KNIGHTON, G. Licensing Branch 3 2pp 21975 255 24X Fiche 50-528, 84/01/24, 8401270302

--8401270306 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone" * Arizona Public Service Co. 84/01/31 24pp 21975 257 24X Fiche 50-528, 84/01/24, 8401270302

H General correspondence

8401240068 Informs of rev to organizational structure. Rev adds new Vice President, EE Van Brunt & lists added responsibilities WOODS, T. O. Arizona Public Service Co. 84/01/16 KNIGHTON, G. Licensing Branch 3 1p 21913.213 24X Fiche 50-528, 84/01/16, 8401240068

G Inspection reports, IE Bulletins & correspondence

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info Notebook also available in PDR. FELTON, J. M. Division of Rules and Records 83/10/20, ZAHLE, R. E. Shaw, Pittman, Potts & Trowbridge, Inc. 21744.003. 24X Fiche: 50-000, 83/10/20, 8401060040

--8401060150 List of BALP results during 1982 * Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp. 21744.004 24X Fiche: 50-000, 83/10/20, 8401060040.

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bays" Svc list encl DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/12/28 Consolidated Edison Co. of New York, Inc. 124pp 21731.166. 24X Fiche: 50-000, 83/12/28, 8312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc. 127pp. 21826.060 24X Fiche: 50-000, 83/12/30, 8312120093

8401170393 Submits final response on actions taken to mitigate concerns of IE Bulletin 83-06, "Nonconforming Hattis Supplied by Tube-Line Corp." Flange piece will be replaced & testing completed by 840229. ANDOGNINI, G. C. Arizona Public Service Co. 84/01/04. MARTIN, J. B. Region 5, Office of Director. 3pp 21828.337. 24X Fiche: 50-528, 84/01/04, 8401170393.

8401200208 Forwards IE Insp Repts 50-528/83-46, 50-529/83-23 & 50-530/83-18 on 83101-1209. No noncompliance noted. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 84/01/06. VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 21862.349. 24X Fiche: 50-528, 84/01/06, 8401200208

--8401200211 IE Insp Repts 50-528/83-46, 50-529/83-23 & 50-530/83-18 on 83101-1209 No noncompliance noted Major areas inspected, const activities re Unit 1 NSSS piping made & Unit 2 reactor vessel internals installation records. VORDERBERGEN, YOUNG, T. Region 5, Office of Director. 84/01/03 3pp. 21862.391 24X Fiche: 50-528, 84/01/06, 8401200208.

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946.053. 24X Fiche: 50-000, 84/01/10, 8312120104.

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10. Consolidated Edison Co. of New York, Inc. 122pp. 21826.184. 24X Fiche: 50-000, 84/01/10, 8312120107.

8401180107 Requests extension until 840201 to respond to 831212 notice of violation Request based on recent changes in executive mpt. VAN BRUNT, E. E. Arizona Public Service Co. 84/01/11. Director's Office, Office of Inspection and Enforcement. 3pp 21841.353 24X Fiche: 50-528, 84/01/11, 8401180107.

8401170378 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/83-40 & 50-529/83-19. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 84/01/12. ANDOGNINI, G. C. Arizona Public Service Co. 1p 21828.354. 24X Fiche: 50-528, 84/01/12, 8401170378.

--8401170383 Responds to NRC 83121 ltr re violations noted in IE Insp Repts 50-528/83-40 & 50-529/83-19 Corrective actions dept instruction developed to address identification & reporting of deficient equipment & walkdown insps conducted ANDOGNINI, G. C. Arizona Public Service Co. 83/12/22 MARTIN, J. B. Region 5, Office of Director. 3pp 21828.355 24X Fiche 50-528, 84/01/12, 8401170378

8401300289 Forwards IE Insp Repts 50-528/83-43 & 50-529/83-22 on 831201-21 No noncompliance noted BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 84/01/12. ANDOGNINI, G. C. Arizona Public Service Co. 2pp 21993.340 24X Fiche 50-528, 84/01/12, 8401300289

--8401300302 IE Insp Repts 50-528/83-43 & 50-529/83-22 on 831201-21 No noncompliance or deviations noted Major areas inspected startup testing program review, personnel certifications & startup QA/QC containment sump overflow FIORELLI, G., YOUNG, T. Region 5, Office of Director. 84/01/06 3pp 21993.342 24X Fiche 50-528, 84/01/12, 8401300289

8312120114 IE Info Notice 84-05, "Exercise Frequency" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21957.142 24X Fiche 50-000, 84/01/16, 8312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000.001 24X Fiche 50-000, 84/01/18, 8312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000.041 24X Fiche 50-000, 84/01/18, 8312120117

8401300222 Ack receipt of 840111 ltr informing NRC of steps taken to correct deviations noted in IE Special Const Appraisal Insp Rept 50-528/83-34. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 84/01/25. VAN BRUNT, E. E. Arizona Public Service Co. 1p 22062.122 24X Fiche 50-528, 84/01/25, 8401300222.

--8401300225 Responds to NRC 83121 ltr re deviation noted in IE Special Const Appraisal Insp Rept 50-528/83-34. Corrective actions: structural & miscellaneous steel welding requirements revised, per Spec 13-CM-320. VAN BRUNT, E. E. Arizona Public Service Co. 84/01/11 MARTIN, J. B. Region 5, Office of Director. 3pp 22062.123. 24X Fiche 50-528, 84/01/25, 8401300222

B Reportable occurrences, LERs & related correspondence

8401040298 Corrected Final Deficiency Rept DER 83-48 re Valcor solenoid valves subj to excessive heat Deficiency determined not reportable under requirements of 10CFR50.55(a) VAN BRUNT, E. E. Arizona Public Service Co. 83/10/28 BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 2pp 21704.361 24X Fiche 50-528, 83/10/28, 8401040298

8401040222 Interim Deficiency Rept DER 83-49 re diffuser bolts broken loose in reactor coolant pump file initially reported on 830715. Final rept will not be complete until 840127. VAN BRUNT, E. E. Arizona Public Service Co. 83/11/29 BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 2pp 21701.152 24X Fiche: 50-528, 83/11/29, 8401040222.

8401040266 Interim Deficiency Rept DER 83-50 re broken impeller blade on reactor coolant pump. Initially reported on 830718 Due to extensive investigation, final rept submittal will be delayed until 840127. VAN BRUNT, E. E. Arizona Public Service Co. 83/11/29. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 2pp. 21701.129. 24X Fiche: 50-528, 83/11/29, 8401040266

8401040313 Interim Deficiency Rept DER 83-42 re thermowells in RCB Initially reported on 830629 Time extension until 840105 for final rept requested. VAN BRUNT, E. E. Arizona Public Service Co. 83/11/30. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 2pp 21706.361 24X Fiche: 50-528, 83/11/30, 8401040313.

8401040366 Deficiency Rept DER 83-56 re discrepancies w/Anchor-Darling MBIVE Initially reported on 830808. Extension until 840221 for final rept requested due to extensive evaluation required. VAN BRUNT, E. E. Arizona Public Service Co. 83/11/30. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 2pp. 21706.184 24X Fiche: 50-528, 83/11/30, 8401040366.

B401040371 Interim Deficiency Rept DER 83-76 re logic for auxiliary feedwater pump turbine steam supply valves. Initially reported on 831102 Bechtel corresponding w/C-E to determine interface requirement for mods Final rept expected 840128
VAN BRUNT, E E Arizona Public Service Co 83/12/05 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21708 023 24X Fiche 50-528, 83/12/05, B401040371

B401040431 Interim Deficiency Rept DER 83-75 re bolts securing two D0126SA panel filler assemblies, supplied by Foxboro improperly torqued Initially reported on 831102 Submittal of final rept expected by 840128 Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/12/05 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21708 127 24X Fiche 50-528, 83/12/05, B401040431

B401040342 Interim Deficiency Rept DER 83-40 re defective welds & leaking oil in low pressure safety injection & containment safety pump motors Initially reported on 830629 Extensive investigation required Final rept expected by 840106
VAN BRUNT, E E Arizona Public Service Co 83/12/06 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
21707 153 24X Fiche 50-528, 83/12/06, B401040342

B401120391 Interim Deficiency Rept DER 83-36 re excessive recycling of ITT Hydramotor actuators Initially reported on 830629 Final rept expected by 840112
VAN BRUNT, E E Arizona Public Service Co 83/12/09 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 2pp.
21791 080 24X Fiche 50-528, 83/12/09, B401120391

B401120302 Interim Deficiency Rept DER 83-80 re closure of Anchor Barring main feedwater isolation valves in 20 s Initially reported on 831122 Extensive investigation & evaluation will be finalized by 840217.
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21793 355 24X Fiche 50-528, 83/12/19, B401120302.

B401120304 Interim Deficiency Rept DER 83-67 re ex-core detector enclos below design basis flood level Initially reported on 830928 Investigation in progress Next rept will be submitted by 840202
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp.
21793 358 24X Fiche 50-528, 83/12/19, B401120304.

B401120352 Interim Deficiency Rept DER 83-68 re PK battery racks constructed w/nuts & bolts not meeting spec requirements. Initially reported on 830928 Due to extensive investigation & evaluation required, final rept expected by 840118
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp.
21792 025 24X Fiche 50-528, 83/12/19, B401120352.

B401120399 Interim Deficiency Rept DER 83-54 re washers found in steam generators 1 & 2 Initially reported on 830802, Time extension requested to 840118 for filing Final rept
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
21791 018 24X Fiche 50-528, 83/12/19, B401120399

B401120393 Interim Deficiency Rept DER 83-81 re Schedule 160 88 pipe supplied by Gulfway, Inc containing mfg defect which violates min wall thickness Initially reported on 831128. Final rept expected by 840228
VAN BRUNT, E E Arizona Public Service Co 83/12/20, BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21791 082 24X Fiche 50-528, 83/12/20, B401120393

B401120220 Interim Deficiency Rept DER 83-46 re Borg-Warner valve manually overtorqued during hydrostatic testing. Initially reported 830715. Final rept delayed until 840130 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 83/12/21, BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
21791 202 24X Fiche 50-528, 83/12/21, B401120220

B401120404 Interim Deficiency Rept DER 83-79 re spikes on 125-volt dc bus exceeding specs. Initially reported on 831118 Bechtel & Cooper Energy investigating corrective action Final rept expected by 840207.
VAN BRUNT, E E Arizona Public Service Co 83/12/21, BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp.
21791 124 24X Fiche 50-528, 83/12/21, B401120404

B401120429 Final Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators. Actuators refurbished & retested. Deficiency determined not reportable per 10CFR50.55(e)
VAN BRUNT, E E Arizona Public Service Co 83/12/21, BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 25pp.
21791 040. 24X Fiche 50-528, 83/12/21, B401120429.

B401120388 Interim Deficiency Rept DER 83-84 re 87 3/8-inch bolts found missing from seismic tie downs of floor frame assemblies for six motor control ctrs Initially reported on 831206 Investigation underway Final rept expected by 840221
VAN BRUNT, E E Arizona Public Service Co 83/12/22 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 3pp
21791 324 24X Fiche 50-528, 83/12/22, B401120388

B401120402 Rev 3 to Interim Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E not meeting overpressure requirements Initially reported on 820824 Final rept expected by 840214 Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/12/22 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21791 116. 24X Fiche 50-528, 83/12/22, B401120402

B401120430 Final Deficiency Rept DER 83-92 re power supplies by Beta Products feeding noise into 125-volt dc bus. Beta will install ac filter components to reduce &/or eliminate ac spike interference Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 83/12/22 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 4pp
21791 071. 24X Fiche 50-528, 83/12/22, B401120430

B401130366 Final Deficiency Rept DER 83-55 re missing thermal liner in safety injection sys line Initially reported on 830801 Expansion grooves will be blended into nozzle wall area, per GEN-264(v)-P Rept withheld (ref 10CFR2 790)
VAN BRUNT, E E Arizona Public Service Co 83/12/30 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 7pp
21799 350 24X Fiche 50-528, 83/12/30, B401130366.

B401160226 Rev 1 to Interim Deficiency Rept DER 82-80 re Conax Corp low insulation resistance values during DBE simulation tests. Initially reported on 831217 Conax to conduct Raychem splice test Final rept by 840302
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 3pp
21815 111. 24X Fiche 50-528, 84/01/03, B401160226.

B401160272 Interim Deficiency Rept DER 83-73 re unqualified Foxboro power supplies installed in IE instrumentation cabinets Initially reported on 831027 Final rept not expected until 840302 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 2pp
21814 354 24X Fiche: 50-528, 84/01/03, B401160272.

B401160321 Interim Deficiency Rept DER 83-82 re cables in diesel generator control cabinets & Unit 1 diesel generator bldg w/small bend radius. Initially reported on 831202 Cable REPE02A1CC replaced. Next rept by 840301
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs 4pp
21814 316 24X Fiche: 50-528, 84/01/03, B401160321.

B401170349 Final Deficiency Rept DER 83-55 re missing liner in safety injection sys line. Item determined not reportable per 10CFR50.55(e) C-E rept re safety injection nozzle thermal liner withheld (ref 10CFR 2 790)
VAN BRUNT, E E Arizona Public Service Co 84/01/03 LICITRA, E
NRC - No Detailed Affiliation Given 7pp 21829 292 24X
Fiche: 50-528, 84/01/03, B401170349

B401260325 Final Deficiency Rept DER 83-19 re failure of Pacific Scientific safety injection sys mechanical shock arrestors to function properly Condition determined not reportable per 10CFR50.55(e)
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 5pp.
21955 189 24X Fiche: 50-528, 84/01/03, B401260325.

B401260362 Final Deficiency Rept DER 83-39 re rejectable indications on C-E supplied reactor coolant pump 1A Initially reported on 830701. Item determined not reportable under 10CFR50.55(e) or Part 21.
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 3pp
21955 224 24X Fiche: 50-528, 84/01/03, B401260362.

B401260035 Interim Deficiency Rept DER 83-40 re low pressure safety injection & CB pump motors w/defective welds & oil leaks Initially reported on 830629 Due to extensive investigation, final rept will not be submitted until 840204.
VAN BRUNT, E E Arizona Public Service Co 84/01/05 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 2pp.
21956 299 24X Fiche: 50-528, 84/01/05, B401260035.

B401260011 Final Deficiency Rept DER 82-51 re Pullman-Kellog pipe line failure in Unit 1 essential cooling water sys Caused by high film thickness beyond specs & capping pipe w/solid end caps.
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W
Division of Resident, Reactor Project & Engineering Programs. 15pp.
21956 322 24X Fiche: 50-528, 84/01/09, B401260011.

DOCKETED ITEMS

B401260120 Interim Deficiency Rept DER 83-71 re Pacific Scientific shock arrestors w/possible generic defect Initially reported on 831011 Due to extensive investigation & evaluation, complete rept will not be submitted until 840330
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21957 040 24X Fiche: 50-528, 84/01/09, 8401260120

B401260236 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830629 Due to extensive investigation & evaluation, final rept will not be submitted until 840124
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21955 101 24X Fiche: 50-528, 84/01/09, 8401260236

B401260248 Final Deficiency Rept DER 83-35 re inverters supplied by Elgar found to produce voltage spikes on dc supply bus Rept will be sent to Elgar Corp for review & disposition under 10CFR21 Also reportable per Part 21
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 21955 130 24X Fiche: 50-528, 84/01/09, 8401260248

B401260317 Deficiency Rept DER 83-32 re socket welds in steam generator process piping in violation of requirements Initially reported on 830523 Final rept postponed until 840228 due to extensive investigation required.
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp. 21955 194 24X Fiche: 50-528, 84/01/09, 8401260317

B401260341 Final Deficiency Rept DER 83-46 re manual overtorquing of Berg-Warner Valve during hydrostatic testing, resulting in mounting bolt failure Corrective actions enumerated Also reportable under Part 21
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 21955 151 24X Fiche: 50-528, 84/01/09, 8401260341

B401260109 Interim Deficiency Rept DER 83-69 re seismic supports on Passi-seal valves not installed per spec Initially reported on 831011 Due to extensive investigation & evaluation, complete rept will not be submitted until 840301
VAN BRUNT, E E Arizona Public Service Co 84/01/10 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21957 104 24X Fiche: 50-528, 84/01/10, 8401260109

B401260349 Interim Deficiency Rept DER 83-76 re logic for auxiliary feedwater pump turbine steam supply valves contrary to FSAR requirements Due to extensive investigation & evaluation, next rept will not be submitted until 840330.
VAN BRUNT, E E Arizona Public Service Co 84/01/10 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp. 21955 155 24X Fiche: 50-528, 84/01/10, 8401260349

B401260150 Interim Deficiency Rept DER 83-68 re const of PK battery racks w/out-of-spec nuts & bolts Initially reported on 830928 Due to extensive investigation required, final rept will not be submitted until 840306.
VAN BRUNT, E E Arizona Public Service Co 84/01/11 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21956 030 24X Fiche: 50-528, 84/01/11, 8401260150

V. Operator Examinations

B401240186 Forwards estimate of schedule for operator licensing exams for FY84-FY87.
VAN BRUNT, E E Arizona Public Service Co 84/01/17, BECKHAM, D Operator Licensing Branch 3pp. 21908 341 24X Fiche: 50-528, 84/01/17, 8401240186

CKET BTN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

Application/construction stage documents & correspondence

W0180008 FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983
BERNABEI, L. Government Accountability Project 83/09/15 Office of Administration 2pp 21853 001 24X Fiche: 50-528, 83/09/15, 840180008

W0180009 Responds to FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983 for facilities Forwards documents listed on app.
FELTON, J M. Division of Rules and Records 83/10/11, BERNABEI, L. Government Accountability Project. 5pp 21853 003 24X Fiche: 50-528, 83/10/11, 840180009

--B40180013 Trip rept of 830622-24 Caseload Forecast Panel site visit re projected fuel load dates
LICITRA, E A Licensing Branch 3 83/10/11 NOVAK, T M Assistant Director for Licensing 2pp 21853 017 24X Fiche 50-528, 83/10/11, 840180009

--B40180017 "Palo Verde Nuclear Generating Station Caseload Forecast Startup Status."
* Arizona Public Service Co 83/06/22 58pp 21853.067 24X Fiche 50-528, 83/10/11, 840180009

--B40180020 "Palo Verde Nuclear Generating Station Caseload Forecast"
* Arizona Public Service Co 83/06/22 86pp. 21853.125 24X Fiche 50-528, 83/10/11, 840180009

--B40180022 "Palo Verde Nuclear Generating Station Caseload Forecast"
* Arizona Public Service Co 83/03/31 86pp 21853 211 24X Fiche 50-528, 83/10/11, 840180009

--B40180026 NRC questions & util responses re facility startup Related documentation encl
* NRC - No Detailed Affiliation Given 82/03/18 21pp 21853 286 24X Fiche 50-528, 83/10/11, 840180009

--B40180028 Palo Verde Nuclear Generating Station Caseload Forecast Panel meeting
* Arizona Public Service Co 80/10/28 113pp 21853.306 24X Fiche 50-528, 83/10/11, 840180009

--B40180033 Palo Verde Nuclear Generating Station Caseload Forecast Panel 790423 & 26 meetings
* Arizona Public Service Co 79/04/25 43pp 21854 057 24X Fiche 50-528, 83/10/11, 840180009

--B40180036 Agenda for Caseload Forecast Panel 790425-26 meetings
* NRC - No Detailed Affiliation Given 79/04/25 NRC - No Detailed Affiliation Given 2pp 21854 120 24X Fiche: 50-528, 83/10/11, 840180009

--B40180042 Submits 790509 daily staff notes
GOSBICK, L V Office of the Executive Director for Operations 79/05/10 HENDRIE, J, OILINSKY, V, AHEARNE, J F. Commissioners. 2pp 21854 129 24X Fiche 50-528, 83/10/11, 840180009

--B40180047 Notes re test & startup
* NRC - No Detailed Affiliation Given 79/04/25 2pp. 21854 140 24X Fiche: 50-528, 83/10/11, 840180009

--B40180067 Chart re NRC permits & licenses
* NRC - No Detailed Affiliation Given. 83/10/11 3pp 21854 155 24X Fiche 50-528, 83/10/11, 840180009.

--B40180073 Confirms 780227 telcon w/R Robb re corrections to Jan 1978 yellowbook (NUREG-0030) Corrections listed
VAN BRUNT, E E Arizona Public Service Co. 78/02/27. LOVEACE, W H NRC - No Detailed Affiliation Given 3pp 21854 198 24X Fiche 50-528, 83/10/11, 840180009.

--B40180077 Chart re design/procurement & mechanical/electrical installation/insp
* Arizona Public Service Co 83/10/11 8pp 21854 182 24X Fiche: 50-528, 83/10/11, 840180009

--B40180082 "Palo Verde Nuclear Generating Station Test Index."
* Arizona Public Service Co AEB50-R1. 83/10/11 27pp 21854 190 24X Fiche: 50-528, 83/10/11, 840180009

--B40180088 Notes re facility fuel load dates.
* NRC - No Detailed Affiliation Given 82/11/30 4pp 21854 218 24X Fiche 50-528, 83/10/11, 840180009

--B40180090 Palo Verde Nuclear Generating Station master startup schedule.
* Arizona Public Service Co 80/10/27 33pp 21854 275 24X Fiche: 50-528, 83/10/11, 840180009.

--B40180097 Agenda for Caseload Forecast Panel site visit for wk of 820325.
* NRC - No Detailed Affiliation Given 82/03/15 NRC - No Detailed Affiliation Given. 3pp 21854 312 24X Fiche 50-528, 83/10/11, 840180009

--B40180102 Summary of 810824 meeting w/util in Washington, DC re NRC 1980 review of facility project schedule.
LOVELACE, W, HUBBARD, R NRC - No Detailed Affiliation Given. 81/08/24 NRC - No Detailed Affiliation Given 2pp. 21854 315 24X Fiche: 50-528, 83/10/11, 840180009

DOCKETED ITEMS

381

8401180106 Agenda for Caseload Forecast Panel 801028 meeting
* NRC - No Detailed Affiliation Given 80/10/28 NRC - No
Detailed Affiliation Given 1p 21854 323 24X
Fiche 50-528, 83/10/11, 8401180009

8401180116 Computer printout re predecessor/successor analysis listing
of cumulative resource requirements based on facility early
* late start
* Arizona Public Service Co 83/07/23 34pp 21854 347 24X
Fiche 50-528, 83/10/11, 8401180009

8401050204 Requests issuance of certification that facilities designed
in furtherance of abating or controlling atmospheric
pollutants, contaminants or water pollution Certification
required for bond financing
VAN BRUNT, E E Arizona Public Service Co 83/12/05 NRC - No
Detailed Affiliation Given 4pp 21727 247 24X
Fiche 50-528, 83/12/05, 8401050204

8312230326 Forwards staffing survey to assist in developing expected
staffing profile in place at time OL is obtained. Form
should be completed by 831216
KNIGHTON, O W Licensing Branch 3 83/12/06 VAN BRUNT, E. E.
Arizona Public Service Co 5pp 21619 325 24X
Fiche 50-528, 83/12/06, 8312230326

8401050024 Responds to 831017 ltr expressing dissatisfaction w/not
receiving info re hot functional testing problems Apologizes
for withholding handout at 831012 meeting Util continuing to
give status briefings as necessary
REHM, T A Office of the Executive Director for Operations
83/12/07 BERNABEI, L Government Accountability Project 4pp
21734 217. 24X Fiche 50-528, 83/12/07, 8401050024.

8401110365 Forwards request for addl info re TMI Item II F.2 re reactor
vessel monitoring sys to complete review of 830729 response.
KNIGHTON, O W Licensing Branch 3 83/12/20 VAN BRUNT, E. E.
Arizona Public Service Co 3pp 21794 332 24X
Fiche 50-528, 83/12/20, 8401110365

8401030061 Forwards general description of facilities, revising 831205
request for certification that facilities designed to
further abate or control atmospheric pollutants or
contaminants or water pollution
VAN BRUNT, E E Arizona Public Service Co 83/12/23 NRC - No
Detailed Affiliation Given 5pp 21683 101 24X
Fiche 50-528, 83/12/23, 8401030061

8401180031 Forwards certification of pollution control facilities, in
response to 831205 ltr
DENTON, H R Office of Nuclear Reactor Regulation, Director.
83/12/29, VAN BRUNT, E E Arizona Public Service Co 2pp.
21847 341 24X Fiche 50-528, 83/12/29, 8401180031.

8401180037 Certification of pollution control facilities.
DENTON, H R Office of Nuclear Reactor Regulation, Director.
83/12/29, 4pp 21847 343 24X Fiche 50-528, 83/12/29, 8401180031

8312120108 Board Notification 84-004, notifies of Chairman Dec 1983
trip to Sandia re briefing on environ qualification. Sandia
position is that NRC environ qualification program has
problems
EISENHUT, D O Division of Licensing 84/01/05 PALLADINO, N. J.
Commissioners. 2pp. 21993 324 24X Fiche 50-000, 84/01/05,
8312120108.

8401050382 Generic Ltr 84-01 to all holders of DLs, applicants for DLs
& holders of CPs for power reactors re NRC use of terms:
"important to safety" & "safety-related." Bvc list encl
EISENHUT, D. O. Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000, 84/01/05, 8401050382

8401090221 Generic Ltr 84-02 to all applicants for DLs & full power
authorizations re notice of meeting on facility staffing.
Bvc list encl
EISENHUT, D O Division of Licensing 84/01/06 Consolidated
Edison Co. of New York, Inc 18pp. 21957, 267 24X
Fiche: 50-000, 84/01/06, 8401090221.

8401190201 Submits daily highlights Andognini resigned for health
reasons. E Van Brunt will assume responsibility for
engineering, const, startup, operation & maint.
KNIGHTON, O W Licensing Branch 3 84/01/09 DENTON, H , CASE, E.,
CARTER, J NRC - No Detailed Affiliation Given. 1p. 21870 016. 24X
Fiche 50-528, 84/01/09, 8401190201

8401160068 Forwards responses to Questions 640 01 640 02 & 640 03 re
procedure generation package
VAN BRUNT, E. E. Arizona Public Service Co 84/01/10, KNIGHTON, O.
Licensing Branch 3. 12pp 21815, 214. 24X Fiche: 50-528, 84/01/10,
8401160068.

8401130084 Generic Ltr 84-03 to all licensees of operating reactors,
applicants for DLs & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D O Division of Licensing. 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, 8401130084

8401270536 Notification of 840126 meeting w/OL applicants in Bethesda,
MD to discuss limited operational experience on operating
crews & development of acceptable experience profiles for
new plants
HANNON, J. Division of Licensing 84/01/17 Division of
Licensing 1p 22000, 349 24X Fiche 50-000, 84/01/17, 8401270536.

8401270467 Documents understanding of 840111 telcon re justifications
for interim operation (JOI) for unqualified safety-related
equipment, per util 831202 ltr Util will submit marked-up
revs to equipment rept summary tables
VAN BRUNT, E E Arizona Public Service Co 84/01/24 KNIGHTON, O
Licensing Branch 3 2pp 21980 326 24X Fiche 50-528, 84/01/24,
8401270467

8401270277 Forwards response to 831206 ltr transmitting facility
staffing survey
VAN BRUNT, E E Arizona Public Service Co 84/01/25 KNIGHTON, O.
Licensing Branch 3. 10pp 21975 298. 24X Fiche 50-528, 84/01/25,
8401270277

8401310313 Forwards corrected 830913 ltr re steam generator tube
rupture accident analysis Incorrect figures submitted.
VAN BRUNT, E E Arizona Public Service Co 84/01/27 KNIGHTON, O
Licensing Branch 3. 2pp 22026 308 24X Fiche 50-528, 84/01/27,
8401310313

8401310317 Corrected ltr forwarding, for review, steam generator tube
rupture analysis.
VAN BRUNT, E E Arizona Public Service Co 83/09/13 KNIGHTON, O
Licensing Branch 3 23pp. 22026 310 24X Fiche 50-528, 84/01/27,
8401310313

E NRC Safety Evaluation Report (SER), supp's & correspondence

8312090366 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO
VERDE NUCLEAR GENERATING STATION, UNITS 1, 2, AND 3 Docket
Nos. STN 50-528, STN 50-529 & STN 50-530. (Arizona Public
Service Company, et al)
* Division of Licensing NUREG-0857 805, 83/11/30 61pp.
Available at NRC. \$5 00. 21445 118. 24X Fiche 50-528, 83/11/30,
8312090366

8401100418 Responds to SBER 5 (NUREG-0857) requesting addl info re
meteorological effect of Palo Verde hills Data for primary
meteorological tower representative of meteorology in
emergency planning zone.
VAN BRUNT, E E. Arizona Public Service Co. 84/01/03 KNIGHTON, O.
Licensing Branch 3. 5pp 21763 124 24X Fiche 50-528, 84/01/03,
8401100418

8401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency
Planning Zone," per SBER 5 (NUREG-0857) & util 831223 ltr.
VAN BRUNT, E E. Arizona Public Service Co 84/01/24 KNIGHTON, O
Licensing Branch 3 2pp 21975, 255 24X Fiche 50-528, 84/01/24,
8401270302

F. Security, medical, emergency & fire protection plans

8401090174 Forwards info re backfitting issue concerning source range
neutron flux monitor in remote shutdown panel per App R to
10CFR50 Util latest response must be revised
LICHTA, E. A Licensing Branch 3 83/12/29, EISENHUT, D. O. Division
of Licensing 2pp. 21737 213 24X Fiche: 50-528, 83/12/29,
8401090174

8401100418 Responds to SBER 5 (NUREG-0857) requesting addl info re
meteorological effect of Palo Verde hills Data for primary
meteorological tower representative of meteorology in
emergency planning zone.
VAN BRUNT, E E Arizona Public Service Co. 84/01/03 KNIGHTON, O.
Licensing Branch 3 5pp. 21763 124. 24X Fiche 50-528, 84/01/03,
8401100418

8401300001 Forwards staff comments on detailed control room design
review program plan submitted per Suppl 1 to NUREG-0737.
Schedule for response to comments requested by 840131
KNIGHTON, O. W Licensing Branch 3. 84/01/10. VAN BRUNT, E. E.
Arizona Public Service Co 9pp. 22027 321. 24X
Fiche: 50-528, 84/01/10, 8401300001.

DOCKETED ITEMS

B401200051 Summary of B31109 public meeting in Phoenix, AZ re emergency preparedness
 SCARANO, R A Division of Radiological Safety & Safeguards Program
 B4/01/16, MARTIN, J B Region 5, Office of Director. 4pp
 21865, 277 24X Fiche 50-528, B4/01/16, B401200051

--B401200053 Forwards operations summary of notification alert network telephone during B30511 exercise, per B31107 request Summary indicates two periods of time when phone not operational
 ANDOGNINI, O C Arizona Public Service Co B3/12/09 MARTIN, J B Region 5, Office of Director 4pp 21865 281. 24X
 Fiche 50-528, B4/01/16, B401200051.

B401230656 Releases public version of revised facility emergency plan
 FELTON, J M. Division of Rules and Records B4/01/18. Document Management Branch 1p 21925, 249 24X Fiche 50-528, B4/01/18, B401230656

--B401230661 Public version of Rev 3 to facility emergency plan W/B31220 transmittal sheet
 * Arizona Public Service Co B3/10/31 413pp 21925, 251 24X
 Fiche 50-528, B4/01/18, B401230656

B401250084 Forwards description of offsite protective action decision process & activation of technical support ctr & satellite technical support ctr, per request
 VAN BRUNT, E E Arizona Public Service Co. B4/01/20 KNIIGHTON, O Licensing Branch 3. App. 21940 225. 24X Fiche 50-528, B4/01/20, B401250084.

B401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per B3ER 5 (NUREG-0897) & util B31223 1tr
 VAN BRUNT, E E. Arizona Public Service Co. B4/01/24. KNIIGHTON, O Licensing Branch 3. 2pp 21973 235 24X Fiche 50-528, B4/01/24, B401270302.

--B401270306 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone"
 * Arizona Public Service Co B4/01/31. 24pp 21975, 257. 24X
 Fiche 50-528, B4/01/24, B401270302

0. Adjudicatory correspondence

B401250175 Ack receipt of B40109 1tr transmitting Golsys comments re source term contentions. Comments will be reviewed before NRC takes position on proposed withdrawal of West Valley Agricultural Protection Council, Inc contentions.
 DEMEY, L B. Hearing Branch 3 B4/01/16 BERLIN, K Berlin, K. 1p. 21937, 124 24X Fiche 50-529, B4/01/16, B401250175

H General correspondence

B401240068 Informs of rev to organizational structure Rev adds new Vice President, EE Van Brunt & lists added responsibilities
 WOODS, T. O. Arizona Public Service Co. B4/01/16 KNIIGHTON, O Licensing Branch 3. 1p 21913 213 24X Fiche 50-528, B4/01/16, B401240068

G Inspection reports, IE Bulletins & correspondence

'01060040 Responds to FOIA request for IE tabulation of SAMP results during 1982 Forwards IE notebook tabulating requested info.
 Notebook also available in PDR
 FELTON, J M Division of Rules and Records B3/10/20 ZAHLE, R E Shaw, Pittman, Fette & Trowbridge 1p 21744 003 24X
 Fiche 50-000, B3/10/20, B401060040.

B401060150 List of SAMP results during 1982.
 * Director's Office, Office of Inspection and Enforcement
 B3/10/20, 134pp 21744 004 24X Fiche 50-000, B3/10/20, B401060040.

2120090 IE Bulletin B3-08, "Electrical Circuit Breakers / Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. B3/12/28 Consolidated Edison Co. of New York, Inc 124pp, 21731, 166 24X Fiche 50-000, B3/12/28, B312120090.

L2120093 IE Info Notice B3-B4, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers." Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/12/30. Consolidated Edison Co. of New York, Inc. 127pp, 21826-060. 24X Fiche 50-000, B3/12/30, B312120093

B401170393 Submits final response on actions taken to mitigate concern of IE Bulletin B3-06, "Nonconforming Matts Supplied by Tubal Line Corp." Flange piece will be replaced & testing completed by B40229
 ANDOGNINI, O C Arizona Public Service Co B4/01/04 MARTIN, J B Region 5, Office of Director 2pp, 21828 337 24X
 Fiche 50-528, B4/01/04, B401170393

B401200208 Forwards IE Insp Repts 50-528/B3-46, 50-529/B3-23 & 50-530/B3-18 on B31101-1209 No noncompliance noted
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs B4/01/06 VAN BRUNT, E E Arizona Public Service Co 2pp 21862 349 24X Fiche 50-528, B4/01/06, B401200208

--B401200211 IE Insp Repts 50-528/B3-46, 50-529/B3-23 & 50-530/B3-18 on B31101-1209 No noncompliance noted Major areas inspected consist activities re Unit 1 NSSB piping mods & Unit 2 reactor vessel internals installation records
 VORDERBRUEGGEN, YOUNG, T Region 5, Office of Director. B4/01/03 6pp 21862 351 24X Fiche 50-528, B4/01/06, B401200208.

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/10 Consolidated Edison Co. of New York, Inc 125pp 21946 053 24X Fiche 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/10. Consolidated Edison Co. of New York, Inc 122pp 21826 184 24X Fiche 50-000, B4/01/10, B312120107

B401170378 Ack receipt of B31222 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-528/B3-40 & 50-529/B3-19
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs B4/01/12 ANDOGNINI, O C Arizona Public Service Co 1p 21828 354 24X Fiche 50-528, B4/01/12, B401170378

--B401170383 Responds to NRC B31121 1tr re violations noted in IE Insp Repts 50-528/B3-40 & 50-529/B3-19. Corrective actions dept instruction developed to address identification & reporting of deficient equipment & walkdown insps conducted
 ANDOGNINI, O C Arizona Public Service Co B3/12/22. MARTIN, J B Region 5, Office of Director 5pp 21828 355. 24X
 Fiche 50-528, B4/01/12, B401170378

B401300289 Forwards IE Insp Repts 50-528/B3-43 & 50-529/B3-22 on B31201-21 No noncompliance noted.
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs B4/01/12 ANDOGNINI, O C Arizona Public Service Co 2pp 21993 340. 24X Fiche 50-528, B4/01/12, B401300289

--B401300302 IE Insp Repts 50-528/B3-45 & 50-529/B3-22 on B31201-21 No noncompliance or deviations noted Major areas inspected: startup testing program review, personnel certifications & startup GA/GC containment sump overflow
 FIORELLI, O., YOUNG, T. Region 5, Office of Director. B4/01/06 5pp, 21993 342. 24X Fiche 50-528, B4/01/12, B401300289

B312120114 IE Info Notice B4-05, "Exercise Frequency." Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/16 Consolidated Edison Co. of New York, Inc 127pp, 21957 142 24X Fiche 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/18 Consolidated Edison Co. of New York, Inc 118pp 22000, 001 24X Fiche 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103). B4/01/18 Consolidated Edison Co. of New York, Inc. 120pp, 22000 041. 24X Fiche 50-000, B4/01/18, B312120117

B Reportable occurrences, LERs & related correspondence

B401040298 Corrected final Deficiency Rept DER B3-4B re Valcor solenoid valves subj to excessive heat Deficiency determined not reportable under requirements of 10CFR50.55(e).
 VAN BRUNT, E E Arizona Public Service Co B3/10/28 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs. 2pp, 21704, 361 24X Fiche 50-528, B3/10/28, B401040298.

DOCKETED ITEMS

8401040129 Interim Deficiency Rept DER 83-59 re IEEE-384 separation criteria violation in post-accident control room cabinet & safety radiation monitoring cabinet Initially reported on 830830 FSAR change notice to be issued Final rept by 840330
VAN BRUNT, E E Arizona Public Service Co 83/11/30 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21702-066 24X Fiche 50-529, 83/11/30, 8401040129

8401040220 Deficiency Rept DER 83-60 re wiring in main steam & feedwater actuation sys supplied by Vitro not meeting IEEE-384 separation criteria Initially reported on 830830 Final rept will not be submitted until 831228
VAN BRUNT, E E Arizona Public Service Co 83/11/30 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21701-289 24X Fiche 50-529, 83/11/30, 8401040220

8401040366 Deficiency Rept DER 83-56 re discrepancies w/Anchor-Darling MSIVs Initially reported on 830808 Extension until 840221 for final rept requested due to extensive evaluation required
VAN BRUNT, E E Arizona Public Service Co 83/11/30 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21706-184 24X Fiche 50-528, 83/11/30, 8401040366

8401040581 Interim Deficiency Rept DER 83-77 re concrete pour containing honey-combed concrete around vertical tendon sheath block outs Initially reported on 831109 Next rept expected by 840209
VAN BRUNT, E E Arizona Public Service Co 83/12/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21705-357 24X Fiche 50-529, 83/12/06, 8401040581

8401120391 Interim Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Initially reported on 830629 Final rept expected by 840112
VAN BRUNT, E E Arizona Public Service Co 83/12/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21791-080 24X Fiche 50-528, 83/12/09, 8401120391

8401120209 Interim Deficiency Rept DER 82-73 re ITT Grinnel improperly secured pipe support clamps Initially reported on 821124 Investigation in progress, Next rept will be submitted by 840113
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21791-205 24X Fiche 50-529, 83/12/19, 8401120209

8401120302 Interim Deficiency Rept DER 83-80 re closure of Anchor Darling main feedwater isolation valves in 20 s. Initially reported on 831122 Extensive investigation & evaluation will be finalized by 840217
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21793-355 24X Fiche 50-528, 83/12/19, 8401120302

8401120304 Interim Deficiency Rept DER 83-67 re ex-core detector encls below design basis flood level Initially reported on 830928 Investigation in progress Next rept will be submitted by 840202
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21793-338 24X Fiche 50-528, 83/12/19, 8401120304

8401120352 Interim Deficiency Rept DER 83-68 re PK battery racks constructed w/nuts & bolts not meeting spec requirements Initially reported on 830928 Due to extensive investigation & evaluation required, final rept expected by 840118
VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21792-025 24X Fiche 50-528, 83/12/19, 8401120352

8401120393 Interim Deficiency Rept DER 83-81 re Schedule 160 SS pipe supplied by Oufalloy, Inc containing mfg defect which violates min wall thickness Initially reported on 831128. Final rept expected by 840228.
VAN BRUNT, E E Arizona Public Service Co 83/12/20 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791-082 24X Fiche 50-528, 83/12/20, 8401120393

8401120220 Interim Deficiency Rept DER 83-46 re Borg-Warner valve manually overtorqued during hydrostatic testing. Initially reported 830715 Final rept delayed until 840130 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21791-202 24X Fiche 50-528, 83/12/21, 8401120220

8401120404 Interim Deficiency Rept DER 83-79 re spikes on 125-volt dc bus exceeding specs Initially reported on 831118. Bechtel & Cooper Energy investigating corrective action Final rept expected by 840207
VAN BRUNT, E E Arizona Public Service Co 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791-124 24X Fiche 50-528, 83/12/21, 8401120404

8401120429 Final Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Actuators refurbished & retested Deficiency determined not reportable per 10CFR50.55(e)
VAN BRUNT, E E Arizona Public Service Co 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 25pp 21791-040 24X Fiche 50-528, 83/12/21, 8401120429

8401120388 Interim Deficiency Rept DER 83-84 re 87 3/8-inch bolts four missing from seismic tie downs of floor frame assemblies for six motor control ctrs Initially reported on 831206 Investigation underway Final rept expected by 840221
VAN BRUNT, E E Arizona Public Service Co 83/12/22 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791-324 24X Fiche 50-528, 83/12/22, 8401120388

8401160226 Rev 1 to Interim Deficiency Rept DER 82-80 re Conax Corp low insulation resistance values during DBE simulation tests. Initially reported on 821217. Conax to conduct Raychem splice test Final rept by 840302
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21815-111 24X Fiche 50-528, 84/01/03, 8401160226

8401160272 Interim Deficiency Rept DER 83-73 re unqualified Forbore power supplies installed in IE instrumentation cabinets Initially reported on 831027. Final rept not expected until 840302 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21814-354 24X Fiche 50-528, 84/01/03, 8401160272

8401160321 Interim Deficiency Rept DER 83-82 re cables in diesel generator control cabinets & Unit 1 diesel generator bldg w/small bend radius Initially reported on 831202 Cable 2EPE02A1C replaced Next rept by 840301
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 21814-316 24X Fiche 50-528, 84/01/03, 8401160321

8401160266 Interim Deficiency Rept DER 83-83 re incorrect sway strut supporting Class G/A piping installation Initially reported on 831202 Sway strut to be replaced w/ITT Grinnell sway strut Final rept expected by 840409
VAN BRUNT, E E Arizona Public Service Co 84/01/04 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21814-360 24X Fiche 50-529, 84/01/04, 8401160266

8401260370 Interim Deficiency Rept DER 83-60 re Vitro wiring in main steam & feedwater actuation sys not meeting IEEE-384 separation criteria Initially reported on 830901 Final rept will be submitted by 840222
VAN BRUNT, E E Arizona Public Service Co 84/01/04 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21955-124 24X Fiche 50-529, 84/01/04, 8401260370

8401260011 Final Deficiency Rept DER 82-51 re Pullman-Kellogg pipe line failure in Unit 1 essential cooling water sys Caused by high film thickness beyond specs & capping pipe w/solid end caps
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 15pp 21956-322 24X Fiche 50-528, 84/01/09, 8401260011

8401260120 Interim Deficiency Rept DER 83-71 re Pacific Scientific shock arrestors w/possible generic defect Initially reported on 831011 Due to extensive investigation & evaluation, complete rept will not be submitted until 840330.
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21957-040 24X Fiche 50-528, 84/01/09, 8401260120

8401260180 Interim Deficiency Rept DER 83-30 re Marathon ASTM A354 bol breaking while torquing bolt on feedwater pump. Initially reported on 830505 Due to extensive evaluation, next rept delayed until 840214
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21956-091 24X Fiche 50-529, 84/01/09, 8401260180

V. Operator Examinations

8401240186 Forwards estimate of schedule for operator licensing exams for FY84-FY87
VAN BRUNT, E E Arizona Public Service Co 84/01/17 BECKHAM, D. Operator Licensing Branch 3pp 21908-341 24X Fiche 50-528, 84/01/17, 8401240186

DOCKETED ITEMS

DOCKET BTN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

- 8401180008 FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983
BERNABEI, L. Government Accountability Project 83/09/15 Office of Administration 2pp 21853 001 24X Fiche 50-528, 83/09/15, 8401180008
- 8401180009 Responds to FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983 for Facilities Forewards documents listed on app
FELTON, J. M. Division of Rules and Records 83/10/11 BERNABEI, L. Government Accountability Project. 3pp 21853 003 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180013 Trip rept of 830622-24 Caseload Forecast Panel site visit re projected fuel load dates
LICHTER, E. A. Licensing Branch 3 83/10/11 NOVAK, T. M. Assistant Director for Licensing 2pp. 21853 017 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180017 "Palo Verde Nuclear Generating Station Caseload Forecast Startup Status"
* Arizona Public Service Co 83/06/22 38pp 21853 067. 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180020 "Palo Verde Nuclear Generating Station Caseload Forecast"
* Arizona Public Service Co 83/06/22 86pp 21853 125 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180022 "Palo Verde Nuclear Generating Station Caseload Forecast."
* Arizona Public Service Co 83/03/31 86pp 21853-211. 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180026 NRC questions & util responses re facility startup Related documentation encl
* NRC - No Detailed Affiliation Given 82/03/18 21pp 21853-286. 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180028 Palo Verde Nuclear Generating Station Caseload Forecast 801028 meeting
* Arizona Public Service Co 80/10/28 113pp 21853 306 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180033 Palo Verde Nuclear Generating Station Caseload Forecast Panel 790425 & 26 meetings
* Arizona Public Service Co 79/04/25 63pp. 21854-057 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401180036 Agenda for Caseload Forecast Panel 790425-26 meetings
* NRC - No Detailed Affiliation Given 79/04/25. NRC - No Detailed Affiliation Given. 2pp 21854 120 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180042 Submits 790509 daily staff notes
OGBRICK, L. V. Office of the Executive Director for Operations 79/05/10. HENDRIE, J. Commissioners 2pp 21854.129 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401180047 Notes re test & startup
* NRC - No Detailed Affiliation Given 79/04/25 2pp 21854 140 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401180047 Chart re NRC permits & licenses
* NRC - No Detailed Affiliation Given 83/10/11 3pp 21854 155 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180073 Confirms 780227 telcon w/R Robb re corrections to Jan 1978 yellowbook (NUREG-0030) Connections listed.
VAN BRUNT, E. E. Arizona Public Service Co 78/02/27 LOVELACE, W. H. NRC - No Detailed Affiliation Given 3pp. 21854-158. 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180077 Chart re design/procurement & mechanical/electrical installation/insp.
* Arizona Public Service Co 83/10/11 8pp. 21854-182 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180082 "Palo Verde Nuclear Generating Station Text Index"
* Arizona Public Service Co. A8850-R1. 83/10/11. 27pp 21854.190. 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401180088 Notes re facility fuel load dates
* NRC - No Detailed Affiliation Given. 82/11/30 4pp. 21854.218. 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180090 Palo Verde Nuclear Generating Station master startup schedule
* Arizona Public Service Co. 80/10/27 33pp 21854-275 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401180097 Agenda for Caseload Forecast Panel site visit for wk of 820325
* NRC - No Detailed Affiliation Given 82/03/15 NRC - No Detailed Affiliation Given 3pp 21854 312 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180102 Summary of 810824 meeting w/util in Washington, DC re NRC 1980 review of facility project schedule
LOVELACE, W. NRC - No Detailed Affiliation Given 81/08/24 NRC - No Detailed Affiliation Given 2pp 21854-315 24X Fiche 50-528, 83/10/11, 8401180009
- 8401180106 Agenda for Caseload Forecast Panel 801028 meeting
* NRC - No Detailed Affiliation Given 80/10/28 NRC - No Detailed Affiliation Given 1p 21854.323 24X Fiche 50-528, 83/10/11, 8401180009.
- 8401050204 Requests issuance of certification that facilities designed in furtherance of abating or controlling atmospheric pollutants, contaminants or water pollution Certification required for bond financing
VAN BRUNT, E. E. Arizona Public Service Co 83/12/05 NRC - No Detailed Affiliation Given 6pp 21727-247. 24X Fiche 50-528, 83/12/05, 8401050204
- 8312230326 Forwards staffing survey to assist in developing expected staffing profile in place at time OL is obtained Form should be completed by 831216
KNIGHTON, G. W. Licensing Branch 3 83/12/06 VAN BRUNT, E. E. Arizona Public Service Co 5pp 21619-325 24X Fiche 50-528, 83/12/06, 8312230326.
- 8401050024 Responds to 831017 ltr expressing dissatisfaction w/not receiving info re hot functional testing problems Apologizes for withholding handout at 831012 meeting Util continuing to give status briefings as necessary
REHM, T. A. Office of the Executive Director for Operations 83/12/07 BERNABEI, L. Government Accountability Project 4pp. 21736-217 24X Fiche 50-528, 83/12/07, 8401050024.
- 840110365 Forwards request for addl info re TMI Item 11 F.2 re reactor vessel monitoring sys to complete review of 830729 response
KNIGHTON, G. W. Licensing Branch 3 83/12/20 VAN BRUNT, E. E. Arizona Public Service Co. 3pp 21794 332. 24X Fiche 50-528, 83/12/20, 840110365
- 8401030061 Forwards general description of facilities, revising 831203 request for certification that facilities designed to further abate or control atmospheric pollutants or contaminants or water pollution.
VAN BRUNT, E. E. Arizona Public Service Co. 83/12/23 NRC - No Detailed Affiliation Given. 5pp. 21683-101 24X Fiche 50-528, 83/12/23, 8401030061
- 8401180031 Forwards certification of pollution control facilities, in response to 831205 ltr
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/12/29 VAN BRUNT, E. E. Arizona Public Service Co 8pp 21847-341 24X Fiche 50-528, 83/12/29, 8401180031
- 8401180037 Certification of pollution control facilities.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/12/29 4pp 21847-343. 24X Fiche 50-528, 83/12/29, 8401180031
- 8312120108 Board Notification 84-004: notices of Chairman Dec 1983 trip to Sandia re briefing on environ qualification Sandia position is that NRC environ qualification program has problems
EISENHUT, D. G. Division of Licensing 84/01/05 PALLADINO, H. J. Commissioners. 2pp. 21993-324. 24X Fiche 50-000, 84/01/05, 8312120108
- 8401050382 Generic Ltr 84-01 to all holders of OLS, applicants for OLS & holders of CPs for power reactors re NRC use of terms. "important to safety" & "safety-related." Svc list encl.
EISENHUT, D. G. Division of Licensing 84/01/05. Consolidated Edison Co. of New York, Inc. 16pp. 21946-190. 24X Fiche 50-000, 84/01/05, 8401050382
- 8401090221 Generic Ltr 84-02 to all applicants for OLS & full power authorizations re notice of meeting on facility staffing. Svc list encl.
EISENHUT, D. G. Division of Licensing 84/01/06. Consolidated Edison Co. of New York, Inc 18pp 21957-267 24X Fiche 50-000, 84/01/06, 8401090221

DOCKETED ITEMS

385

B401190201 Submits daily highlights Andognini resigned for health reasons E Van Brunt will assume responsibility for engineering, const, startup, operation & maint
KNIGHTON, G W Licensing Branch 3 84/01/09 DENTON, H , CASE, E , CARTER, J NRC - No Detailed Affiliation Given 1p 21870 016 24X
Fiche 50-52B, 84/01/09, B401190201

B401160068 Forwards responses to Questions 640 01 640 02 & 640 03 re procedure generation package
VAN BRUNT, E E Arizona Public Service Co 84/01/10 KNIGHTON, G Licensing Branch 3 12pp 21815 214 24X Fiche 50-52B, 84/01/10, B401160068

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for DLs & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000, 84/01/13, B401130084

B401270536 Notification of B40126 meeting w/DL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HANNDON, J Division of Licensing 84/01/17 Division of Licensing 1p 22000 349 24X Fiche 50-000, 84/01/17, B401270536

B401270467 Documents understanding of B40111 telcon re justifications for interim operation (JOI) for unqualified safety-related equipment, per util 831202 ltr Util will submit marked-up revs to equipment rept summary tables
VAN BRUNT, E E Arizona Public Service Co 84/01/24, KNIGHTON, G Licensing Branch 3, 2pp 21980 326 24X Fiche 50-52B, 84/01/24, B401270467

B401270277 Forwards response to 831206 ltr transmitting facility staffing survey
VAN BRUNT, E E Arizona Public Service Co 84/01/25 KNIGHTON, G Licensing Branch 3 10pp 21975 298 24X Fiche 50-52B, 84/01/25, B401270277

B401310313 Forwards corrected 830913 ltr re steam generator tube rupture accident analysis incorrect figures submitted
VAN BRUNT, E E Arizona Public Service Co 84/01/27, KNIGHTON, G Licensing Branch 3, 2pp 22026 308 24X Fiche 50-52B, 84/01/27, B401310313

--B401310317 Corrected ltr forwarding, for review, steam generator tube rupture analysis,
VAN BRUNT, E E Arizona Public Service Co 83/09/13 KNIGHTON, G Licensing Branch 3 23pp 22026 310 24X Fiche 50-52B, 84/01/27, B401310313

E. NRC Safety Evaluation Report (SER): supply & correspondence

B312090366 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2, AND 3 Docket Nos. STN 50-52B, STN 50-529 & STN 50-530 (Arizona Public Service Company, et al)
* Division of Licensing NUREG-0857 805, 83/11/30 61pp
Available at NRC \$5 00 21445 118 24X Fiche 50-52B, 83/11/30, B312090366

B401100418 Responds to SSER 5 (NUREG-0857) requesting addl info re meteorological effect of Palo Verde hills. Data for primary meteorological tower representative of meteorology in emergency planning zone
VAN BRUNT, E E Arizona Public Service Co 84/01/03 KNIGHTON, G Licensing Branch 3 5pp 21763 124 24X Fiche 50-52B, 84/01/03, B401100418

B401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per SSER 5 (NUREG-0857) & util 831223 ltr
VAN BRUNT, E E Arizona Public Service Co, 84/01/24 KNIGHTON, G Licensing Branch 3 2pp 21975 255 24X Fiche 50-52B, 84/01/24, B401270302

F. Security, medical, emergency & fire protection plans

B401090174 Forwards info re backfitting issue concerning source range neutron flux monitor in remote shutdown panel per App R to 10CFR50 Util latest response must be revised.
LICHTRA, E A Licensing Branch 3 83/12/29 EISENHUT, D G Division of Licensing 2pp 21757 213 24X Fiche 50-52B, 83/12/29, B401090174

B401100418 Responds to SSER 5 (NUREG-0857) requesting addl info re meteorological effect of Palo Verde hills. Data for primary meteorological tower representative of meteorology in emergency planning zone
VAN BRUNT, E E Arizona Public Service Co 84/01/03 KNIGHTON, G Licensing Branch 3 5pp 21763 124 24X Fiche 50-52B, 84/01/03, B401100418

B401300001 Forwards staff comments on detailed control room design review program plan submitted per Suppl 1 to NUREG-0737
Schedule for response to comments requested by B40131
KNIGHTON, G W Licensing Branch 3 84/01/10 VAN BRUNT, E E Arizona Public Service Co 9pp 22027 321 24X
Fiche 50-52B, 84/01/10, B401300001

B401200051 Summary of 831109 public meeting in Phoenix, AZ re emergency preparedness
SCARAND, R A Division of Radiological Safety & Safeguards Program 84/01/16 MARTIN, J B Region 5, Office of Director App 21865 277 24X Fiche 50-52B, 84/01/16, B401200051

--B401200053 Forwards operations summary of notification alert network telephone during 830511 exercise, per 831109 request Summary indicates two periods of time when phone not operational
ANDRONINI, G C Arizona Public Service Co 83/12/09 MARTIN, J B Region 5, Office of Director App 21865 281 24X
Fiche 50-52B, 84/01/16, B401200053

B401230656 Releases public version of revised facility emergency plan
FELTON, J M Division of Rules and Records 84/01/18 Document Management Branch 1p 21925 249 24X Fiche 50-52B, 84/01/18, B401230656

--B401230661 Public version of Rev 3 to facility emergency plan w/831220 transmittal sheet
* Arizona Public Service Co 83/10/31 413pp. 21925 251 24X
Fiche 50-52B, 84/01/18, B401230656

B401250084 Forwards description of offsite protective action decision process & activation of technical support ctr & satellite technical support ctr, per request
VAN BRUNT, E E Arizona Public Service Co, 84/01/20 KNIGHTON, G Licensing Branch 3 App 21940 225 24X Fiche 50-52B, 84/01/20, B401250084

B401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per SSER 5 (NUREG-0857) & util 831223 ltr
VAN BRUNT, E E Arizona Public Service Co 84/01/24 KNIGHTON, G Licensing Branch 3 2pp 21975 255 24X Fiche 50-52B, 84/01/24, B401270302

--B401270306 "Evacuation Time Analysis, 10-Mile Emergency Planning Zone"
* Arizona Public Service Co 84/01/31 24pp 21975 257 24X
Fiche 50-52B, 84/01/24, B401270302

G. Adjudicatory correspondence

B401250173 Ack receipt of B40109 ltr transmitting Colays comments re source term contentions. Comments will be reviewed before NRC takes position on proposed withdrawal of West Valley Agricultural Protection Council, Inc contentions
DEWEY, L S Hearing Branch 3 84/01/16 BERLIN, K Berlin, K 1p 21937 124 24X Fiche 50-529, 84/01/16, B401250173

H. General correspondence

B401240068 Informs of rev to organizational structure Rev adds new Vice President, EE Van Brunt & lists added responsibilities.
WOODS, T G Arizona Public Service Co 84/01/16, KNIGHTON, G Licensing Branch 3 1p 21913 213 24X Fiche 50-52B, 84/01/16, B401240068

G. Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 ZAHLER, R E Shaw, Pittman, Potts & Troubridge, 1p. 21744:003 24X
Fiche 50-000, 83/10/20, B401060040

--B401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement. 83/10/20 134pp 21744.004 24X Fiche 50-000, 83/10/20, B401060040

DOCKETED ITEMS

- 8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166. 24X Fiche 50-000, 83/12/28, 8312120090
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/12/30 Consolidated Edison Co of New York, Inc 127pp. 21826 060 24X Fiche 50-000, 83/12/30, 8312120093
- 8401170393 Submits final response on actions taken to mitigate concerns of IE Bulletin 83-06, "Nonconforming Natis Supplied by Tube-Line Corp." Flange piece will be replaced & testing completed by 840229 ANDOONINI, Q C Arizona Public Service Co 84/01/04 MARTIN, J B Region 5, Office of Director, 2pp 21828, 337 24X Fiche, 90-328, 84/01/04, 8401170393
- 8401200208 Forwards IE Insp Repts 50-528/83-46, 50-529/83-23 & 50-530/83-18 on 831101-1209 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 84/01/06, VAN BRUNT, E E Arizona Public Service Co, 2pp 21862, 349 24X Fiche 50-528, 84/01/06, 8401200208
- 8401200211 IE Insp Repts 50-528/83-46, 50-529/83-23 & 50-530/83-18 on 831101-1209, No noncompliance noted Major areas inspected const activities re Unit 1 NSS piping mods & Unit 2 reactor vessel internals installation records VORDERBRUGGEN, YOUNG, T Region 5, Office of Director 84/01/03 6pp. 21862, 351. 24X Fiche 50-528, 84/01/06, 8401200208
- 8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10, Consolidated Edison Co of New York, Inc 129pp 21946 053 24X Fiche 50-000, 84/01/10, 8312120104
- 312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/10, Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, 8312120107
- 3312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/16 Consolidated Edison Co of New York, Inc 127pp. 21957 142 24X Fiche 50-000, 84/01/16, 8312120114
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18, Consolidated Edison Co of New York, Inc. 118pp 22000 001. 24X Fiche 50-000, 84/01/18, 8312120116
- 120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/01/18, Consolidated Edison Co of New York, Inc 120pp 22000 041 24X Fiche 50-000, 84/01/18, 8312120117
- Reportable occurrences, LERs & related correspondence
- D1040298 Corrected Final Deficiency Rept DER 83-48 re Valcor solenoid valves subj to excessive heat Deficiency determined not reportable under requirements of 10CFR50.55(a) VAN BRUNT, E E Arizona Public Service Co, 83/10/28 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21704: 361 24X Fiche 50-528, 83/10/28, 8401040298
- 401040344 Rev 1 to Final Deficiency Rept DER 83-33 re GE AKR-50 breakers w/EG-1 trips Rev lists specific nonconformance repts & breakers included in corrective action plan VAN BRUNT, E E Arizona Public Service Co, 83/11/28 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 3pp 21706: 128 24X Fiche 50-530, 83/11/28, 8401040344
- 8401040338 Revised Interim Deficiency Rept DER 83-53 re Type N embed plate failure to meet specs Initially reported on 830801 Final rept will be submitted by 840215 VAN BRUNT, E E Arizona Public Service Co, 83/11/30, BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp. 21704: 353. 24X Fiche 50-530, 83/11/30, 8401040338
- 8401040366 Deficiency Rept DER 83-56 re discrepancies w/Anchor-Darling MBIVs Initially reported on 830808 Extension until 840221 For final rept requested due to extensive evaluation required VAN BRUNT, E E Arizona Public Service Co 83/11/30 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21706: 184 24X Fiche 50-528, 83/11/30, 8401040366
- 8401040581 Interim Deficiency Rept DER 83-77 re concrete pour containing honey-combed concrete around vertical tendon sheath block outs Initially reported on 831109 Next rept expected by 840209 VAN BRUNT, E E Arizona Public Service Co 83/12/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21705: 357 24X Fiche 50-529, 83/12/06, 8401040581
- 8401120391 Interim Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Initially reported on 830629 Final rept expected by 840112 VAN BRUNT, E E Arizona Public Service Co, 83/12/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21791 080 24X Fiche 50-528, 83/12/09, 8401120391
- 8401120302 Interim Deficiency Rept DER 83-80 re closure of Anchor Darling main feedwater isolation valves in 20 s Initially reported on 831122 Extensive investigation & evaluation will be finalized by 840217 VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21793: 355 24X Fiche 50-528, 83/12/19, 8401120302
- 8401120304 Interim Deficiency Rept DER 83-67 re ex-core detector encls below design basis flood level Initially reported on 830928 Investigation in progress Next rept will be submitted by 840202 VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21793: 358 24X Fiche 50-528, 83/12/19, 8401120304
- 8401120352 Interim Deficiency Rept DER 83-68 re PK battery racks constructed w/nuts & bolts not meeting spec requirements Initially reported on 830928 Due to extensive investigation & evaluation required, final rept expected by 840118 VAN BRUNT, E E Arizona Public Service Co 83/12/19 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21792: 025. 24X Fiche 50-528, 83/12/19, 8401120352
- 8401120393 Interim Deficiency Rept DER 83-81 re Schedule 160 HB pipe supplied by Gulfalloy, Inc containing mfg defect which violates min wall thickness Initially reported on 831128 Final rept expected by 840228 VAN BRUNT, E E Arizona Public Service Co 83/12/20 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791 082. 24X Fiche 50-528, 83/12/20, 8401120393
- 8401120220 Interim Deficiency Rept DER 83-46 re Borg-Warner valve manually overtightened during hydrostatic testing Initially reported 830715 Final rept delayed until 840130 due to extensive investigation & evaluation VAN BRUNT, E E Arizona Public Service Co 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 2pp 21791: 202 24X Fiche 50-528, 83/12/21, 8401120220
- 8401120404 Interim Deficiency Rept DER 83-79 re spikes on 125-volt dc bus exceeding specs Initially reported on 831118 Berchtel & Cooper Energy investigating corrective action Final rept expected by 840207 VAN BRUNT, E E Arizona Public Service Co 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791: 124 24X Fiche 50-528, 83/12/21, 8401120404
- 8401120429 Final Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Actuators refurbished & retested Deficiency determined not reportable per 10CFR50.55(a) VAN BRUNT, E E Arizona Public Service Co, 83/12/21 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs, 25pp 21791 040 24X Fiche 50-528, 83/12/21, 8401120429
- 8401120388 Interim Deficiency Rept DER 83-84 re 87 3/8-inch bolts found missing from seismic tie downs of floor frame assemblies for six motor control ctrs Initially reported on 831206 Investigation underway Final rept expected by 840221 VAN BRUNT, E E Arizona Public Service Co 83/12/22 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21791 324. 24X Fiche 50-528, 83/12/22, 8401120388
- 8401160226 Rev 1 to Interim Deficiency Rept DER 82-80 re Connex Corp low insulation resistance values during DBE simulation tests Initially reported on 821217 Connex to conduct Raychem splice test Final rept by 840302 VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 3pp 21815: 111 24X Fiche 50-528, 84/01/03, 8401160226

DOCKETED ITEMS

38

B401160272 Interim Deficiency Rept DER 83-73 re unqualified Foxboro power supplies installed in IE instrumentation cabinets initially reported on B31027 Final rept not expected until B40302 due to extensive investigation & evaluation
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21814 354 24X Fiche 50-528, 84/01/03, B401160272

B401160321 Interim Deficiency Rept DER 83-82 re cables in diesel generator control cabinets & Unit 1 diesel generator bldg w/small bend radius Initially reported on B31202 Cable 2EPE02A1CC replaced Next rept by B40301
VAN BRUNT, E E Arizona Public Service Co 84/01/03 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 21814 316 24X Fiche 50-528, 84/01/03, B401160321

B401260011 Final Deficiency Rept DER 82-51 re Pullman-Kellogg pipe line failure in Unit 1 essential cooling water sys Caused by high film thickness beyond specs & capping pipe w/solid end caps
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 13pp 21956 322 24X Fiche 50-528, 84/01/09, B401260011

B401260120 Interim Deficiency Rept DER 83-71 re Pacific Scientific shock arrestors w/possible generic defect Initially reported on B31011. Due to extensive investigation & evaluation, complete rept will not be submitted until B40330
VAN BRUNT, E E Arizona Public Service Co 84/01/09 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 21957 040 24X Fiche 50-528, 84/01/09, B401260120

V Operator Examinations

B4012401B6 Forwards estimate of schedule for operator licensing exams for FYB4-FYB7
VAN BRUNT, E E Arizona Public Service Co 84/01/17 BECKHAM, D Operator Licensing Branch 3pp 21908 341. 24X Fiche 50-528, 84/01/17, B4012401B6

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

B401190353 Informs of receipt & storage, through B&W Engineering, of spent fuel transfer port assembly large shield plug Due to failure of Congress to appropriate addl funding, DOE no longer seeking CP & is closing all licensing activities
ORUSB, P J Energy, Dept of 84/01/13 Director's Office, Office of Inspection and Enforcement 2pp 21850 320 24X Fiche 50-537, 84/01/13, B401190353

E NRC Safety Evaluation Report (SER), supp's & correspondence

B401090113 Summarizes current status of SER open items re structural response during faulted conditions & beyond DBAs Program lacks planned analytical support Models to support experimental efforts should be developed
BUTLER, T A Los Alamos Scientific Laboratory 83/11/15 HDLZ, H. Clinch River Breeder Reactor Program Office 4pp 21753 193 24X Fiche 50-537, 83/11/15, B401090113

G Adjudicatory correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 003 24X Fiche 50-000, 83/10/18, B401250015

--B401250302 Forwards info re NRC opposition to motion by NRDC & Sierra Club to stay exemption for facility
BICKWIT, L Office of the General Counsel SECY-82-3348 82/08/30 43pp 21963 349 24X Fiche 50-000, 83/10/18, B401250015

B401100149 Response to NRDC reply per ASLB B31228 order Contentions raised in NRDC motion to intervene moot Motion should be denied Certificate of Svc encl
EDGAR, Q L Project Management Corp LUCK, W D Energy, Dept of 84/01/09 Atomic Safety and Licensing Board Panel 7pp. 21760 178 24X Fiche 50-537, 84/01/09, B401100149

B401100297 Advises that svc of DOE & Project Mgt Corp B31227 notification re project termination affected again on all parties on attached svc list
EDGAR, Q L Newman & Holzinger EDGAR, Q L Project Management Corp 84/01/10 Docketing & Services Branch 1p 21772 261 24X Fiche 50-537, 84/01/10, B401100297

B401250198 Answer to NRDC B31212 reply to applicant & NRC response to NRDC motion to intervene & to terminate proceeding prior to issuance of partial initial decision Motion to intervene should be denied Certificate of Svc encl
TURK, S E Hearing Branch 1 84/01/11 Atomic Safety and Licensing Board Panel 8pp 21937 134 24X Fiche 50-537, 84/01/11, B401250198

B401250173 Notice of B40314 conference w/parties in Bethesda, MD re CRBR termination
MILLER, M E Atomic Safety and Licensing Board Panel 84/01/20 3pp 21937 159 24X Fiche 50-537, 84/01/20, B401250173

B401250197 Order denying B31123 motion for leave to intervene in CP phase of proceeding NRDC attempt to reintervene after deliberately withdrawing remaining contentions not conducive to orderly practice
MILLER, M E Atomic Safety and Licensing Board Panel 84/01/20 Natural Resources Defense Council 4pp 21937 125 24X Fiche 50-537, 84/01/20, B401250197

B401300089 Memorandum LBP-B4-4 of Findings from CP phase hearings HAND, C H, LINENBERGER, G, MILLER, M E Atomic Safety and Licensing Board Panel 84/01/20 242pp 21978 001 24X Fiche 50-537, 84/01/20, B401300089

B401260111 Advises that time for Commission to review ALAB-755 expired Commission declined review Decision became final agency action on B40124
CHILK, S J Office of the Secretary of the Commission 84/01/25 Atomic Safety and Licensing Board Panel 1p 21956 362 24X Fiche 50-537, 84/01/25, B401260111

G Inspection reports, IE Bulletins & correspondence

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys" Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, B312120090.

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type SHK Breakers" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/12/30 Consolidated Edison Co of New York, Inc 127pp 21826 060 24X Fiche 50-000, 83/12/30, B312120093

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/01/10 Consolidated Edison Co of New York, Inc 122pp 21826 184 24X Fiche 50-000, 84/01/10, B312120107

DOCKET BTN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 003 24X Fiche 50-000, 83/10/18, B401250015

--B209160068 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations SECY-82-352 82/08/20 37pp. 21966 035 24X Fiche 50-000, 83/10/18, B401250015

B401050382 Generic Ltr 84-01 to all holders of OLs, applicants for OLs & holders of CPs for power reactors re NRC use of terms, "important to safety" & "safety-related." Svc list encl
EISENHUT, D O Division of Licensing 84/01/05 Consolidated Edison Co of New York, Inc 16pp 21946 190 24X Fiche: 50-000, 84/01/05, B401050382

B401090221 Generic Ltr 84-02 to all applicants for OLs & full power authorizations re notice of meeting on facility staffing Svc list encl.
EISENHUT, D O Division of Licensing. 84/01/06 Consolidated Edison Co of New York, Inc. 18pp. 21957 267. 24X Fiche: 50-000, 84/01/06, B401090221

DOCKETED ITEMS

B401130084 Generic Ltr B4-03 to all licensees of operating reactors, applicants for OLS & holders of CPs re availability of NUREG-0933, "Prioritization of Generic Safety Issues " Svc list encl
EISENHUT, D. G. Division of Licensing. B4/01/13 Consolidated
Edison Co. of New York, Inc. 18pp 21946 174 24X
Fiche. 50-000, B4/01/13, B401130084.

B401270536 Notification of B40126 meeting w/OL applicants in Bethesda, MD to discuss limited operational experience on operating crews & development of acceptable experience profile for new plants
HAMMON, J. Division of Licensing B4/01/17. Division of
Licensing. 1p. 22000 349 24X Fiche. 50-000, B4/01/17, B401270536.

B401260223 Forwards until B40116 press release explaining financial reasons for halting facility const. Certificate of Svc encl
VOIGT, H. H. LeBeauf, Lamb, Leiby & MacRae VOIGT, H. H. Public
Service Co. of Indiana, Inc. B4/01/20 SMITH, I., LINENBERGER, G.,
PARIS, D. H. Atomic Safety and Licensing Board Panel. 6pp.
21954 283 24X Fiche. 50-546, B4/01/20, B401260223.

F Security, medical, emergency & fire protection plans

B401230016 Notices of FENA radiological emergency preparedness B40112-13 program meetings at Ramada Inn, O'Hare Hotel Agenda encl
PAPERIELLO, C. J. Region 3, Office of Director B4/01/03
SHIELDS, S. W. Public Service Co. of Indiana, Inc. 3pp. 21884 188
24X Fiche. 50-546, B4/01/03, B401230016.

G Adjudicatory correspondence

B401260223 Forwards until B40116 press release explaining financial reasons for halting facility const. Certificate of Svc encl
VOIGT, H. H. LeBeauf, Lamb, Leiby & MacRae VOIGT, H. H. Public
Service Co. of Indiana, Inc. B4/01/20. SMITH, I., LINENBERGER, G.,
PARIS, D. H. Atomic Safety and Licensing Board Panel. 6pp.
21954 283 24X Fiche. 50-546, B4/01/20, B401260223.

H Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of BALP results during 1982 Forwards IE notebook tabulating requested info. Notebook also available in PDR.
FELTON, J. H. Division of Rules and Records B3/10/20. ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge. 1p. 21744 003 24X
Fiche. 50-000, B3/10/20, B401060040

--B401060150 List of BALP results during 1982.
* Director's Office, Office of Inspection and Enforcement
B3/10/20 134pp 21744 004 24X Fiche. 50-000, B3/10/20,
B401060040

B312120090 IE Bulletin B3-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. B3/12/28. Consolidated Edison Co. of New York, Inc. 124pp. 21731 166. 24X Fiche. 50-000, B3/12/28, B312120090.

B312120093 IE Info Notice B3-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 5HK Breakers " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/12/30 Consolidated Edison Co. of New York, Inc. 127pp. 21826 060 24X Fiche. 50-000, B3/12/30, B312120093

B401230510 Forwards IE Insp Repts 50-546/B3-20 & 50-547/B3-21 on B31105-1223 & notice of violation.
KNOP, R. C. Region 3, Office of Director. B4/01/05 SHIELDS, S. W. Public Service Co. of Indiana, Inc. 2pp 21875 298. 24X
Fiche. 50-546, B4/01/05, B401230510

--B401230513 Notice of violation from Insp on B31107-1223.
KNOP, R. C. Region 3, Office of Director. B4/01/05. 1p
21875 300. 24X Fiche. 50-546, B4/01/05, B401230510

--B401230523 IE Insp Repts 50-546/B3-20 & 50-547/B3-21 on B31105-1223
Violation noted: improper preheat technique used during welding of electrical cable tray support in Unit 1 containment
SCHAFER, J. F., BUNDY, H. F., KONKLIN, J. E. Region 3, Office of Director. B4/01/05. 7pp. 21875 301. 24X Fiche. 50-546, B4/01/05, B401230510.

B401130298 Ack receipt of B31214 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/B3-19 & 50-547/B3-20.
KNOP, R. C. Region 3, Office of Director B4/01/09. SHIELDS, S. W. Public Service Co. of Indiana, Inc. 1p. 21799 346. 24X
Fiche. 50-546, B4/01/09, B401130298

--B401130301 Responds to NRC B31117 ltr re violations noted in IE Insp Repts 50-546/B3-19 & 50-547/B3-20 Corrective actions sys developed to identify matls requiring periodic maint & storage procedures revised to identify sys
SHIELDS, S. W. Public Service Co. of Indiana, Inc. B3/12/14
KEPPLER, J. O. Region 3, Office of Director 3pp 21799 347 24X
Fiche. 50-546, B4/01/09, B401130298

B312120104 IE Info Notice B4-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co. of New York, Inc. 123pp 21946 033 24X Fiche. 50-000, B4/01/10, B312120104

B312120107 IE Info Notice B4-01, "Excess Lubricant in Electric Cable Sheaths " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/10 Consolidated Edison Co. of New York, Inc. 122pp 21826 184 24X Fiche. 50-000, B4/01/10, B312120107.

B312120114 IE Info Notice B4-05, "Exercise Frequency " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/16 Consolidated Edison Co. of New York, Inc. 127pp 21957 142 24X Fiche. 50-000, B4/01/16, B312120114

B312120116 IE Info Notice B4-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co. of New York, Inc. 118pp 22000 001 24X Fiche. 50-000, B4/01/18, B312120116

B312120117 IE Info Notice B4-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/01/18 Consolidated Edison Co. of New York, Inc. 120pp 22000 041 24X Fiche. 50-000, B4/01/18, B312120117

B401300227 Ack receipt of B40111 ltr informing NRC that IE Insp Repts 50-546/B3-20 & 50-547/B3-21 & notice of violation placed w/ other util quality records to be addressed when const resumed.
KNOP, R. C. Region 3, Office of Director B4/01/26. SHIELDS, S. W. Public Service Co. of Indiana, Inc. 1p 22062 134 24X
Fiche. 50-546, B4/01/26, B401300227

--B401300229 Responds to NRC B40105 ltr re IE Insp Repts 50-546/B3-20 & 50-547/B3-21 Const suspended Insp repts & notice of violation will be placed w/util records of nonconforming conditions to be addressed when const resumed.
SHIELDS, S. W. Public Service Co. of Indiana, Inc. B4/01/11.
KNOP, R. C. Region 3, Office of Director 1p 22062 135. 24X
Fiche. 50-546, B4/01/26, B401300227

E. Reportable occurrences, LERs & related correspondence

B401050576 Interim deficiency rept re diesel generator component support welds accepted by unqualified inspector Initially reported on B31118 Evaluation continuing Next rept will be filed by B40413
SHIELDS, S. W. Public Service Co. of Indiana, Inc. B3/12/19
KEPPLER, J. O. Region 3, Office of Director 2pp. 21726 145 24X
Fiche. 50-546, B3/12/19, B401050576

B401040462 PNO-III-B3-134, on B31221, five member task force appointed by governor of IN to study feasibility of completing plant recommended cancellation Findings not binding Public Svc Commission inquires expected
SCHAFER, J., KNOP, R. Region 3, Office of Director B3/12/22. 1p
21705 313 24X Fiche. 50-546, B3/12/22, B401040462.

B401040454 PNO-III-B3-134A on B31230, licensee announced suspension of all const activities, effective immediately & halt of all contract work, effective B40103 Maint & storage of records, matls & equipment will continue. Alternatives under exam
PELKE, P. J. KNOP, R. Region 3, Office of Director B4/01/03. 1p
21761 285 24X Fiche. 50-546, B4/01/03, B401040454.

B401230392 PNO-III-B4-006, on B40116, util announced company financially unable to proceed w/const Cancellation of project contingent on approval of Wabash Valley Assoc which owns portion of plant.
KONKLIN, J., KNOP, R. Region 3, Office of Director. B4/01/16 1p
21873 354 24X Fiche. 50-546, B4/01/16, B401230392

DOCKETED ITEMS

38

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

B401250015 Partial response to FOIA request for all 1982 SECY papers
Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000,83/10/18,B401250015

--8209160068 Informs Commission of NRC initiatives to improve QA in
nuclear project design & const Approval requested to revise
NRC statutory authority to permit implementation of
representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations
SECY-82-352 82/08/20 97pp 21966 035 24X
Fiche 50-000,83/10/18,B401250015

B401050382 Generic Ltr B4-01 to all holders of OLS, applicants for OLS
& holders of CPs for power reactors re NRC use of terms,
"important to safety" & "safety-related" Svc list encl
EISENHUT, D G Division of Licensing 84/01/05 Consolidated
Edison Co of New York, Inc 16pp 21946 190 24X
Fiche 50-000,84/01/05,B401050382

B401090221 Generic Ltr B4-02 to all applicants for OLS & full power
authorizations re notice of meeting on facility staffing
Svc list encl
EISENHUT, D G Division of Licensing 84/01/06 Consolidated
Edison Co of New York, Inc 18pp 21957 267 24X
Fiche 50-000,84/01/06,B401090221

B401130084 Generic Ltr B4-03 to all licensees of operating reactors,
applicants for OLS & holders of CPs re availability of
NUREG-0933, "Prioritization of Generic Safety Issues"
Svc list encl
EISENHUT, D G Division of Licensing 84/01/13 Consolidated
Edison Co of New York, Inc 18pp 21946 174 24X
Fiche 50-000,84/01/13,B401130084

B401260223 Forwards until 840116 press release explaining financial
reasons for halting facility const Certificate of Svc encl
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 84/01/20 SMITH, I
Atomic Safety and Licensing Board Panel 6pp 21956 283 24X
Fiche 50-546,84/01/20,B401260223

F Security, medical, emergency & fire protection plans

B401230016 Notifies of FEMA radiological emergency preparedness 840112-
13 program meetings at Ramada Inn, O'Hare Hotel Agenda encl
PAPERIELLO, C J Region 3, Office of Director 84/01/05
SHIELDS, S W Public Service Co of Indiana, Inc 3pp 21884 189
24X Fiche 50-546,84/01/05,B401230016

G Adjudicatory correspondence

B401260223 Forwards until 840116 press release explaining financial
reasons for halting facility const Certificate of Svc encl
VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae VOIGT, H H, Public
Service Co of Indiana, Inc 84/01/20 SMITH, I, LINENBERGER, O,
PARIS, D H Atomic Safety and Licensing Board Panel 6pp
21956 283 24X Fiche 50-546,84/01/20,B401260223

G Inspection reports, IE Bulletins & correspondence

B401060040 Responds to FOIA request for IE tabulation of SAMP results
during 1982 Forwards IE notebook tabulating requested info.
Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20, ZAHNER, R E
Shaw, Pittman, Potts & Trowbridge 1p, 21744 003 24X
Fiche 50-000,83/10/20,B401060040

--B401060150 List of SAMP results during 1982.
* Director's Office, Office of Inspection and Enforcement
83/10/20 134pp 21744 004, 24X Fiche 50-000,83/10/20,
8401060040

8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys" Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and
Enforcement, 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731 166 24X Fiche 50-000,83/12/28,B312120090

8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type SHK Breakers." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co. of New
York, Inc. 127pp 21826 060 24X Fiche 50-000,83/12/30,B312120093

B401230510 Forwards IE Insp Repts 50-546/83-20 & 50-547/83-21 on
831105-1223 & notice of violation
KNOP, R C Region 3, Office of Director 84/01/05 SHIELDS, S W
Public Service Co of Indiana, Inc 2pp 21875 298 24X
Fiche 50-546,84/01/05,B401230510

--B401230523 IE Insp Repts 50-546/83-20 & 50-547/83-21 on 831105-1223
Violation noted: improper preheat technique used during
welding of electrical cable tray support in Unit 1
containment
SCHAFER, J F, BUNDY, H F, KONKLIN, J E Region 3, Office of
Director 84/01/05 7pp 21875 301 24X Fiche 50-546,84/01/05,
B401230510

B401130298 Ack receipt of 831214 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-546/83-19 &
50-547/83-20
KNOP, R C Region 3, Office of Director 84/01/09 SHIELDS, S W
Public Service Co of Indiana, Inc 1p 21799 346 24X
Fiche 50-546,84/01/09,B401130298

--B401130301 Responds to NRC 831117 ltr re violations noted in IE Insp
Repts 50-546/83-19 & 50-547/83-20 Corrective actions sys
developed to identify matls requiring periodic maint &
storage procedures revised to identify sys
SHIELDS, S W Public Service Co of Indiana, Inc 83/12/14
KEPPLER, J O Region 3, Office of Director 3pp 21799 347, 24X
Fiche 50-546,84/01/09,B401130298

8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co. of New
York, Inc 123pp 21946 033 24X Fiche 50-000,84/01/10,B312120104

8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc 122pp 21826 184 24X Fiche 50-000,84/01/10,B312120107

8312120114 IE Info Notice 84-03, "Exercise Frequency" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc 127pp 21957 142, 24X Fiche 50-000,84/01/16,B312120114

8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators" Svc list
encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 118pp, 22000 001 24X Fiche 50-000,84/01/18,B312120116

8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/18 Consolidated Edison Co of New
York, Inc 120pp, 22000 041, 24X Fiche 50-000,84/01/18,B312120117

B401300227 Ack receipt of 840111 ltr informing NRC that IE Insp Repts
50-546/83-20 & 50-547/83-21 & notice of violation placed w/
other util quality records to be addressed when const
resumed.
KNOP, R C Region 3, Office of Director 84/01/26 SHIELDS, S W
Public Service Co. of Indiana, Inc 1p, 22062 134 24X
Fiche 50-546,84/01/26,B401300227

--B401300227 Responds to NRC 840105 ltr re IE Insp Repts 50-546/83-20 &
50-547/83-21 Const suspended Insp repts & notice of
violation will be placed w/util records of nonconforming
conditions to be addressed when const resumed.
SHIELDS, S W Public Service Co of Indiana, Inc 84/01/11
KNOP, R C Region 3, Office of Director 1p, 22062 135, 24X
Fiche 50-546,84/01/26,B401300227

B Reportable occurrences, LERs & related correspondence

B401050976 Interim deficiency rept re diesel generator component
support welds accepted by unqualified inspector Initially
reported on 831118 Evaluation continuing Next rept will be
filed by 840413
SHIELDS, S W Public Service Co of Indiana, Inc 83/12/19,
KEPPLER, J O Region 3, Office of Director 2pp, 21726 145, 24X
Fiche 50-546,83/12/19,B401050976

B401040462 PNO-111-83-134 on 831221, five member task force appointed
by governor of IN to study feasibility of completing plant
recommended cancellation. Findings not binding. Public Svc
Commission inquiries expected
SCHAFER, J., KNOP, R. Region 3, Office of Director 83/12/22 1p
21705 313 24X Fiche 50-546,83/12/22,B401040462

DOCKETED ITEMS

B401100454 PNO-III-B3-134A on B31230, licensee announced suspension of all const activities, effective immediately & halt of all contract work, effective B40103 Maint & storage of records, matls & equipment will continue Alternatives under exam
 PELKE, P. KNOP, R. Region 3, Office of Director B4/01/03 1p
 21761.283 24X Fiche 50-546, B4/01/03, B401100454

B401230392 PNO-III-B4-006 on B40116, Util announced company financially unable to proceed w/const Cancellation of project contingent on approval of Habbash Valley Assoc which owns portion of plant
 KONKLIN, J. KNOP, R. Region 3, Office of Director B4/01/16 1p.
 21873 354 24X Fiche 50-546, B4/01/16, B401230392

DOCKET BTN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

G Inspection reports, IE Bulletins & correspondence

B401090111 Forwards IE Insp Rept 50-553/B3-01 on B31107 No violation noted.
 VERRELLI, D. M. Division of Project & Resident Programs B3/12/14.
 PARRIS, H. G. Tennessee Valley Authority 2pp 21753 203 24X
 Fiche 50-553, B3/12/14, B401090111

--B401090117 IE Insp Rept 50-553/B3-01 on B31107, No violation noted Major areas inspected, storage & maint of safety-related equipment.
 SHAW, W. B. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. B3/12/14 4pp 21753:205 24X
 Fiche: 50-553, B3/12/14, B401090111.

B Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended. Utills notified.
 BOYER, R. E. Transamerica Delaval, Inc. B4/01/09 Director's Office, Office of Inspection and Enforcement. 3pp 21828.269 24X
 Fiche 50-000, B4/01/09, B401170186

DOCKET BTN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

B. Reportable occurrences, LERs & related correspondence

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive. Insp of hubs in listed facilities recommended. Utills notified.
 BOYER, R. E. Transamerica Delaval, Inc. B4/01/09 Director's Office, Office of Inspection and Enforcement. 3pp 21828.269. 24X
 Fiche: 50-000, B4/01/09, B401170186

DOCKET BTN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

I Financial information

B401200194 Forwards Annual Financial Rept 1982, Vols I & II.
 KAMMER, D. B. Tennessee Valley Authority B4/01/12 DENTON, H. R.
 Office of Nuclear Reactor Regulation, Director 1p 21865.001 24X
 Fiche: 50-000, B4/01/12, B401200194.

--B401200199 Annual Financial Rept 1982, Vol I.
 PARRIS, H. G. Tennessee Valley Authority B4/01/12. 75pp
 21865.002. 24X Fiche. 50-000, B4/01/12, B401200194

B401200206 Annual Financial Rept 1982, Vol II
 PARRIS, H. G. Tennessee Valley Authority. B4/01/12. 96pp.
 21865.077. 24X Fiche. 50-000, B4/01/12, B401200194

Inspection reports, IE Bulletins & correspondence

B401090125 Forwards IE Insp Rept 50-566/B3-01 on B31026-27 No violation noted.
 VERRELLI, D. M. Division of Project & Resident Programs. B3/12/14
 PARRIS, H. G. Tennessee Valley Authority. 2pp. 21750 354. 24X
 Fiche: 50-566, B3/12/14, B401090125.

B401090134 IE Insp Rept 50-566/B3-01 on B31026-27, No violation noted. Major areas inspected: storage & maint of safety-related equipment
 SHAW, W. B. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. B3/12/14 4pp 21750:356 24X
 Fiche: 50-566, B3/12/14, B401090125.

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

I Financial information

B401200194 Forwards Annual Financial Rept 1982, Vols I & II
 KAMMER, D. B. Tennessee Valley Authority B4/01/12 DENTON, H. R.
 Office of Nuclear Reactor Regulation, Director 1p 21865.001 24X
 Fiche 50-000, B4/01/12, B401200194

--B401200199 Annual Financial Rept 1982, Vol I
 PARRIS, H. G. Tennessee Valley Authority B4/01/12 75pp
 21865.002 24X Fiche 50-000, B4/01/12, B401200194

--B401200206 Annual Financial Rept 1982, Vol II
 PARRIS, H. G. Tennessee Valley Authority B4/01/12 96pp
 21865.077. 24X Fiche 50-000, B4/01/12, B401200194

DOCKET STN-50-584 GIBBS & HILL

A Application/construction stage documents & correspondence

B312050593 Forwards GA program Topical Rept GIBBS 17A, Amend 7 per B31019 acceptance ltr & Vendor Program Branch rept Rept withheld.
 KEDDIS, N. N. Gibbs & Hill, Inc (subs of Dravo Corp) B3/11/21
 NRC - No Detailed Affiliation Given 2pp 21379 023 24X
 Fiche: 50-584, B3/11/21, B312050593

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA

B401240242 Advises that Phase IIA & III areas surveyed & found to meet NRC guidelines for release for unrestricted use Confirmatory survey rept encl
 THOMAS, R. D. Region 3, Office of Director B3/12/27 CROW, W. T.
 Uranium Fuel Licensing Branch 4pp 21945.056

DOCKET 70-0027 BABCOCK & WILCOX CO., LYNCHBURG, VA

B401130056 Requests extension re installation of security surveillance device Completion of project expected by B40120
 REGAN, N. A. Babcock & Wilcox Co B3/11/28 BROWN, W. B. Fuel
 Facility Safeguards Licensing Branch 3pp 21821.141.

B401050597 Forwards IE Insp Rept 70-0027/B3-27 on B31114-16 No violations or deviations noted.
 STOHR, J. P. Region 2, Office of Director B3/12/08 ECKERT, J. P.
 Babcock & Wilcox Co 2pp 21724.110.

--B401050608 IE Insp Rept 70-0027/B3-27 on B31114-16 No violations noted Major areas inspected radiological environ monitoring & lab quality control, including review of procedures & records
 TROUP, G. L. Region 2, Office of Director MONTGOMERY, D. M.
 Division of Emergency Preparedness & Materials Safety B3/12/07.
 7pp. 21724.112.

B401090576 Revises Safeguards Amend MPP-1 to License SNW-42 by adding unnumbered license condition extending time limit for completion & distribution of nuclear matl transfer repts per 10CFR70.54 to 37 days.
 BROWN, W. B. Fuel Facility Safeguards Licensing Branch. B3/12/09
 REGAN, N. A. Babcock & Wilcox Co 1p 21757.258

B40110369 Responds to B31128 ltr re delayed receipt of certain closed circuit television (CCTV) equipment Compensatory measures must continue until CCTV in place
 BROWN, W. B. Fuel Facility Safeguards Licensing Branch B3/12/09
 REGAN, N. A. Babcock & Wilcox Co 1p 21794.329

B401050520 Ack receipt of B31115 ltr informing NRC of change of date for correction of violation noted in IE Insp Repts 70-0027/B3-09 to B31130. Extension acceptable Corrective actions to be examined in future insp
 STOHR, J. B. Division of Emergency Preparedness & Materials Safety. B3/12/21 ECKERT, J. P. Babcock & Wilcox Co 1p 21725.280

--B401050533 Updates response to NRC telcon re violation noted in IE Insp Rept 70-0027/B3-09 Corrective actions, data from study re collection efficiency of stack air sample filter paper will be available by B41130
 ECKERT, J. P. Babcock & Wilcox Co B3/11/15. O'REILLY, J. P. Region 2, Office of Director. 1p. 21725.281

DOCKETED ITEMS

391

8401090590 Responds to 830401 & 1104 ltrs re changes to physical protection plan Page changes acceptable for inclusion in plan Compensatory measures must be provided until closed circuit television equipment installed
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/27
REGAN, N A Babcock & Wilcox Co 2pp 21757 286

8401240370 Forwards IE Safeguards Insp Rept 70-0027/83-29 on 831205-08
No violations noted
STOHR, J P Division of Project & Resident Programs 83/12/27
ECKERT, J P Babcock & Wilcox Co 2pp 21920 006

--8401240375 IE Safeguards Insp Rept 70-0027/83-29 on 831205-08 No violations noted Major areas inspected verification of import shipment & followup on previous insp Findings Details withheld (ref 10CFR2 790)
BARADUS, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/12/27
1p 21920 008

8401240345 Forwards IE Insp Rept 70-0027/83-31 on 831212-16 No violations noted Rept withheld (ref 10CFR2 790 & 73 21)
STOHR, J P Division of Emergency Preparedness & Materials Safety 84/01/04
ECKERT, J P Babcock & Wilcox Co 2pp 21920 301.

DOCKET 70-0036 COMBUSTION ENGINEERING, INC, WINDSOR, CT

8401200052 Forwards Matl License SNM-33 Renewed license expires on 881231 Byproduct Matl License 24-16206-01 canceled
Possession & use of byproduct matl included in License SNM-33
PAGE, R O Uranium Fuel Licensing Branch 83/12/30
ESKRIDGE, H E Combustion Engineering, Inc 1p 21871 320

--8401200058 Renewed License SNM-33 for C-E authorizing treatment or disposal of waste & scrap matl containing U-enriched in U-235/source matl by incineration
PAGE, R O Uranium Fuel Licensing Branch 83/12/30
2pp 21871 321

--8401200061 SER supporting renewal of License SNM-33 for C-E nuclear fuel manufacturing facility in Hematite, MD
SOONG, A L, BIDINGER, O H, CROW, W T Division of Fuel Cycle & Material Safety 83/12/30
36pp 21871 329

DOCKET 70-0083 HARVARD UNIV, CAMBRIDGE, MA

8401040019 Responds to FOIA request for list of schools, businesses & hosps in Cambridge, MA possessing NRC licenses for use of radioactive compounds & for copy of licenses Forwards App A documents
FELTON, J M Division of Rules and Records 83/10/14
CHRISTENSEN, D Citizens Against Research Bans 5pp 21731 312

--8005070405 Matl/Byproduct License SNM-71 for Harvard Univ is amended in its entirety per 800228 ltr Amend 4 authorizes Pu, U, Pu-236, Pu-238 & Pu-239 for R&D
LAMASTRA, M A Material Licensing Branch. 80/04/10 3pp.
67052 001

--8401040287 Amend 5 to License SNM-71 for Harvard Univ, changing licensee address, per 820727 ltr
GLENN, J E Division of Fuel Cycle & Material Safety 82/10/12.
1p 21732 106

DOCKET 70-0113 PENNSYLVANIA STATE UNIV, UNIVERSITY PARK, PA

8401030169 Forwards IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on 831108-10, No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 83/12/16
CUNNINGHAM, R Pennsylvania State Univ, University Park, PA 2pp
21680 320 24X Fiche 50-005, 83/12/16, 8401030169

--8401030176 IE Safeguards Insp Repts 50-005/83-03 & 70-0113/83-02 on 831108-10 No noncompliance noted Major areas inspected, physical protection measures for protecting SNM of low strategic significance
MADDEN, W, GIDDY, A Region 1, Office of Director 83/12/15 2pp
21680 322 24X Fiche: 50-005, 83/12/16, 8401030169.

DOCKET 70-0121 INTERIOR, DEPT OF, DENVER, CO

8401030254 IE Insp Findings & Licensee Ack dtd 831129 of Licensee SNM-111 Insp Findings: no violations observed
SHOPENN, N M Region 4, Office of Director. 83/11/29. 1p
21729.264.

DOCKET 70-0135 BABCOCK & WILCOX CO, APOLLO, PA

8401260308 Forwards IE Safeguards Insp Repts 70-0135/83-07 & 70-0344/83-08 & on 831031-1118 No violations noted
MARTIN, T T Division of Engineering & Technical Programs 84/01/12
COLEMAN, W L Babcock & Wilcox Co 2pp 21955 213

--8401260315 IE Insp Repts 70-0135/83-07 & 70-0344/83-08 on 831031-1118 No violations noted Major areas inspected Pu holdup measurements during decommissioning & review of decommissioning activities for U facilities
DELLA RATTI, A, KUSHNER, W, WOLTER, E Region 1, Office of Director 84/01/12 5pp 21955 215

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC, ERWIN, TN

8312080260 Forwards NFB site training plan, Rev 6 Rev incorporates changes required in JP Btohr 830914 ltr, organizational structure changes & rewording of certain sections for clarity Encl withheld
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/10/17
O'REILLY, J P Region 2, Office of Director 1p
21433 257

8401250015 Partial response to FOIA request for all 1982 SECY papers. Forwards App A documents Remaining documents under review
FELTON, J M Division of Rules and Records 83/10/18
WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X
Fiche. 50-000, 83/10/18, 8401250015

840120145 Forwards preliminary flow diagrams for as-built ventilation sys
IDEKER, R L Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/11/22
PAGE, R O Uranium Fuel Licensing Branch. 33pp
21805:070.

8401090120 Informs of review of 831129 Rev 10 to physical security plan Scheduled revs acceptable
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/08.
HENSLEY, K Nuclear Fuel Services, Inc (subs of Getty Oil Co.). 1p 21757 236.

8401090568 Forwards suggested revs to Section 7.7 of fundamental nuclear matl control plan (FNHCP) & suggested App D Revs would be incorporated as license condition Encl withheld (ref 10CFR2 790)
BROWN, W B. Fuel Facility Safeguards Licensing Branch 83/12/15.
HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 3pp 21757 253

8401090112 Forwards IE Insp Rept 70-0143/83-46 on 831128-1202 No violations noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/12/20.
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 21753 242

--8401090121 IE Insp Rept 70-0143/83-46 on 831128-1202 No violations noted Major areas inspected: gaseous effluents, liquid effluents, solid waste mgt & followup on previous identified enforcement matters.
KAHLE, J B. Region 2, Office of Director BARR, K P. Division of Engineering & Operational Programs. 83/12/18 9pp. 21753:243.

8401250285 Ack receipt of 831031 & 1209 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-0143/83-38
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/12/21
QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 21944 184

--8401250298 Responds to NRC 830923 ltr re violations noted in IE Safeguards Insp Rept 70-0143/83-38 Corrective actions. Instructions re affected documentation will be included in procedure by 840301. Details withheld (ref 10CFR2 790)
QUINN, F K Nuclear Fuel Services, Inc (subs. of Getty Oil Co.). 83/12/09
STOHR, J P. Division of Emergency Preparedness & Materials Safety 2pp. 21944 185.

--8401250300 Responds to NRC 831005 ltr re violations noted in IE Safeguards Insp Rept 70-0143/83-38. Corrective action details withheld (ref 10CFR2 790)
QUINN, F K Nuclear Fuel Services, Inc (subs. of Getty Oil Co.). 83/10/31
STOHR, J P Division of Emergency Preparedness & Materials Safety. 3pp 21944 187

DOCKETED ITEMS

B401060237 Responds to B30217 ltr requesting rev to Safeguards License Condition 3 re matl measurements change acceptable.
BROWN, W.B. Fuel Facility Safeguards Licensing Branch 83/12/22
HENSLEY, M.D. Nuclear Fuel Services, Inc. (subs of Getty Oil Co.)
2pp 21735 152

B401170494 Confirms B40105 telcon re mod of Condition 23 to License SNM-124, suggested in B30712 ltr. Changes represent min requirements needed to meet ALARA philosophy specified in 10CFR20
CROW, W.T. Uranium Fuel Licensing Branch. 84/01/10 IDEKER, R
Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 1p.
21847-175

1401240330 Ack receipt of B31222 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-0143/83-43
STOHR, J.P. Division of Emergency Preparedness & Materials Safety
84/01/10 QUINN, F.K. Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 1p 21920:001

--B401240338 Responds to NRC B31130 ltr re violations noted in IE Safeguards Insp Rept 70-0143/83-43 Corrective actions: Future callbr on BCA-3 low enriched matl measurement sys will include zero std.
QUINN, F.K. Nuclear Fuel Services, Inc (subs. of Getty Oil Co.)
83/12/22. STOHR, P. Division of Emergency Preparedness & Materials Safety 4pp. 21920 002.

--B401240346 Forwards IE Safeguards Insp Rept 70-0143/83-43 on B31017-21 & notice of violation. Encls withheld (ref 10CFR2.790)
STOHR, J.P. Division of Emergency Preparedness & Materials Safety
83/11/30. QUINN, F.K. Nuclear Fuel Services, Inc (subs of Getty Oil Co.). 2pp. 21920.004.

B401300288 PNO-II-B4-004 on B40124, dead fish observed along bank of Banner Spring. Licensee analyzing stream samplst & fish for radioactivity & chemical pollutants & investigating sources of pollutants within plant.
KAHLE, J., MCALPINE, E.J. Region 2, Office of Director 84/01/25
1p. 21997 300.

DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA

1260308 Forwards IE Safeguards Insp Repts 70-0135/83-07 & 0-0364/83-08 & on B31031-1118 No violations noted
ARTIN, T.T. Division of Engineering & Technical Programs 84/01/12.
COLEMAN, W.L. Babcock & Wilcox Co 2pp. 21955:213

1401260315 IE Insp Repts 70-0135/83-07 & 70-0364/83-08 on B31031-1118 No violations noted Major areas inspected: Pu holdup measurements during decommissioning & review of decommissioning activities for U facilities.
DELLA RATTI, A., KUSHNER, W., WOLTNER, E. Region 1, Office of Director. 84/01/12. 3pp. 21955:215.

DOCKET 70-0368 NAVY, DEPT. OF, ANNAPOLIS, MD

B401310350 Forwards IE Insp Repts 30-00748/83-01 & 70-0368/83-01 on B31209 & notice of violation.
MARTIN, T.T. Division of Engineering & Technical Programs. 84/01/25
COLLINS, J. U.S. Naval Academy. 2pp. 22019:312

01310354 Notice of violation from insp on B31209 Violations noted, failure to evaluate wholebody radiation dose received by individual between B30809 & 0929. Sealed source containing AM-241 possessed at unauthorized location.
* Region 1, Office of Director. 84/01/25. 2pp. 22019:314.

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT

01060653 Responds to B31025 ltr reporting completion of all const projects associated w/upgrading physical protection plan. Interim physical protection measures issued B31228 rescinded & Section 9.0 reassued.
BROWN, W.B. Fuel Facility Safeguards Licensing Branch. 83/12/27.
DUSTAFSON, R.B. United Nuclear Corp. 2pp. 21754:361.

DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC

B312150272 Advises of issuance of Amend 6 to License SNM-362, reducing quantity of SNM, revising type & form of SNM & including storage vault under exemption from criticality monitoring requirements, per B31031 application. BER encl.
PAGE, R.G. Uranium Fuel Licensing Branch. 83/12/02 PEVEY, L.E.
Commerce, Dept. of, National Bureau of Standards. 3pp. 21540:296.

--B312150273 Safety evaluation supporting Amend 6 to License SNM-362
BODNO, A.L., CROW, W.T. Uranium Fuel Licensing Branch 83/12/02
4pp 21540 299

DOCKET 70-0687 UNION CARBIDE CORP., TUXEDO, NY

B401190416 Submits Amend 9 to License SNM-639, authorizing longer storage period for recovered U shipping containers in gamma facility
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 83/12/19
MCDOVERN, J.J. Union Carbide Corp 1p 21870 011

--B401190418 Safety evaluation supporting Amend 9 to License SNM-639
CLARK, A.T. Advanced Fuel & Spent Fuel Licensing Branch 83/12/19
1p 21870 012

B401310094 Forwards IE Insp Rept 70-0687/83-05 on B31212-16 No violation noted
MARTIN, T.T. Division of Engineering & Technical Programs 84/01/16
MCDOVERN, J.J. Union Carbide Corp 2pp 22022 022

--B401310099 IE Insp Rept 70-0687/83-05 on B31212-16 No violation noted Major areas inspected nuclear matl control & accounting, including facility organization, operation, measurement control & interval control
ZIBULSKY, H., DELLA RATTI, A., SMITH, G. Region 1, Office of Director 84/01/16 3pp 22022 024

DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

B401110134 Forwards Rev 4 to application for renewal of License SNM-770, requesting authorization for possession of addl 350 g U-235
NARDI, A.J. Westinghouse Electric Corp. 83/10/13. PAGE, R.G.
Uranium Fuel Licensing Branch 2pp 21795:220

--B401110140 Rev 4 to application for renewal of License SNM-770, requesting authorization for possession of addl 350 g U-235
* Westinghouse Electric Corp 83/10/13 10pp 21795 222

B401120103 Forwards "Results of Quarterly Groundwater Monitoring Samples at Waltz Mill Site," Rept 4 Concentration of Br-90 in six wells sampled within restricted area exceeded max permissible concentration for restricted areas
GALM, D.T. Westinghouse Electric Corp. 83/12/19 MURLEY, T. Region 1, Office of Director 3pp 21805 234

--B401120106 "Results of Quarterly Groundwater Monitoring Samples at Waltz Mill Site," Rept 4
* Westinghouse Electric Corp. 83/11/28 14pp. 21805 237

DOCKET 70-0712 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

B401250133 FOIA request for listed documents re Kerr-McGee Nuclear Corp. Licenses SNM-664 & SNM-695
BARNES, C. Affiliation Unknown 83/10/12 FELTON, J.M. Division of Rules and Records 1p 21958 333

B401250136 Responds to FOIA request for five listed documents Forwards Documents 4 & 5 Request for Documents 1-3 referred to PDR.
FELTON, J.M. Division of Rules and Records 83/11/04 BARNES, C. Affiliation Unknown 1p 21958:334.

--B401250137 Application for SNM license, authorizing transfer, possession & processing of U from Spencer Chemical Co
COBB, G.H. Kerr-McGee Corp. 62/10/12. Atomic Energy Commission 13pp 21958:335

DOCKET 70-0734 QA TECHNOLOGIES, INC., SAN DIEGO, CA

B401030363 Submits changes to physical protection plan for protection of SNM. Changes cover number of weapons available to guard force.
* QA Technologies, Inc./General Atomic Co 83/10/24 MARTIN, J.B. Region 3, Office of Director. 1p. 21687:360.

B401190421 Application for amend to License SNM-696, requesting approval of B31024 changes to Category I physical protection plan
MOWRY, W.R. QA Technologies, Inc./General Atomic Co 83/12/02.
RENTSCHLER, R. Physical Security Licensing Branch 3pp. 21869:331

DOCKETED ITEMS

393

B40110537 Revises Section 7.1 A of Amend MPP-1 to License SNM-696, delineating procedures re Category I fixed-site physical protection plan
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/05
QA Technologies, Inc /General Atomic Co 1p 21790 333

B401090604 Forwards specific comments re four potential conflicts in B31021 ltr concerning adequate separation of functions in matl control & accounting organization structure Encl withheld (ref 10CFR2 790)
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/15
HOWRY, W R QA Technologies, Inc /General Atomic Co 1p 21764 362

B401090093 Responds to B30729 change to IRS-B4 of Category I physical protection plan Change acceptable
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/20
HOWRY, W R QA Technologies, Inc /General Atomic Co 1p 21757 260

B401090187 Ack receipt of B30728 changes to "Fixed Site & Transportation Plan for Protection of SNM of Moderate & Low Strategic Significance" Changes acceptable
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/20
HOWRY, W R QA Technologies, Inc /General Atomic Co 1p 21757 210

B401090588 Submits review of B30804 changes to Category I physical protection plan. Changes do not decrease effectiveness of plan & are acceptable
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/23
HOWRY, W R QA Technologies, Inc /General Atomic Co 1p 21757 284

B401040213 Forwards IE Safeguards Insp Rept 70-0734/B3-15 on B31213-16 No violation noted
NORDERHAUG, L R Region 5, Office of Director 83/12/28
PARKER, J W QA Technologies, Inc /General Atomic Co 2pp. 21701 211

B401040223 IE Safeguards Insp Rept 70-0734/B3-15 on B31213-16 No violations noted. Major areas inspected preinsp, site orientation, security organization-response, records & repts, locks & keys. Details withheld (ref 10CFR73 21)
SCHWAN, C A NORDERHAUG, L R Region 5, Office of Director 83/12/28 1p 21701 213

B401090583 Submits review of B30909 changes to Category I physical protection plan. Changes do not decrease effectiveness of plan & are acceptable.
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/29
HOWRY, W R QA Technologies, Inc /General Atomic Co 1p 21757 285

B401160211 Forwards IE Safeguards Insp Rept 70-0734/B3-14 on B31205 & 09 No noncompliance noted. Rept withheld (ref 10CFR2 790).
NORDERHAUG, L R Region 5, Office of Director 84/01/09
PARKER, J W QA Technologies, Inc /General Atomic Co, 2pp. 21815 086

DOCKET 70-0754 GENERAL ELECTRIC CO , PLEASANTON, CA

B401110384 Application for amend to License SNM-960, changing Section 7.1 to require radiation safety component & area manager approval for occupational health stds
CUNNINGHAM, O E General Electric Co. 83/12/12 ROUSE, L C
Advanced Fuel & Spent Fuel Licensing Branch 4pp 21794 312

B401090344 Motion for extension of time until B40130 to respond to J Turk revised contentions. Delay needed due to intervenor intent to advance contentions in original petition & revised contentions. Granted by ASLB on B40105
EDGAR, Q L General Electric Co EDGAR, Q L Edgar, Q L 83/12/27.
Atomic Safety and Licensing Board Panel, 3pp 21754 097. 24X
Fiche: 50-070, 83/12/27, B401090344.

B401110347 Concurs w/agreement to stipulation & dismissal re license renewal proceeding being presented to ASLB
ROUSE, L C Division of Fuel Cycle & Material Safety 83/12/30
TREBY, S A Hearing Branch 1. 1p 21794 350.

B401310475 Issues Amend 23 to License SNM-960 in response to B31212 application. Amend clarifies intent of Section 7.1 re radiation instructions
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 84/01/12.
CUNNINGHAM, O E General Electric Co 3pp 22037:344

B401310477 Safety evaluation supporting Amend 23 to License SNM-960 to clarify intent of Section 7.1 re radiation instructions
KRATZKE, R T Advanced Fuel & Spent Fuel Licensing Branch.
84/01/12, 9pp 22037 347.

B401170271 Forwards stipulation & request for dismissal of license renewal proceedings
EDGAR, Q L Newman & Holtzinger EDGAR, Q L General Electric Co
84/01/16 FRYE, J H Atomic Safety and Licensing Board Panel 1p.
21831 074 24X Fiche 50-070, 84/01/16, B401170271

B401170286 Stipulation & request for dismissal of license renewal proceedings Certificate of Svc encl.
TURK, S E Hearing Branch 1 EDGAR, Q L General Electric Co
TURK, J Turk, J 84/01/13 3pp 21831 075 24X
Fiche 50-070, 84/01/16, B401170271

B401170309 Forwards notice of appearance in proceeding Certificate of Svc encl
RASKIN, D B Newman & Holtzinger 84/01/16 Office of the
Secretary of the Commission 4pp 21833.237 24X
Fiche 50-070, 84/01/16, B401170309

B401300279 Forwards IE Insp Rept 70-0754/B3-02 on B31012-18. No violations noted
WENSLAWSKI, F A Region 5, Office of Director 84/01/16
DARMITZEL, R W General Electric Co 2pp. 21797.320

B401300282 IE Insp Rept 70-0754/B3-02 on B31012-18 No violations noted
Major areas inspected organization, facility changes & mods, internal review & audit, safety committee, operation review, criticality safety & radiation protection.
BROCK, B L, ZURAKOWSKI, P R, THOMAS, R D. Region 5, Office of Director 84/01/13 16pp 21997.322

B401300020 Forwards SER re B21029 radiological contingency plan. Plan meets requirements of B10417 order. Requests incorporation of condition to implement, maintain & execute response measures of plan
TERRY, Q A Uranium Fuel Licensing Branch. 84/01/19. ROUSE, L C.
Advanced Fuel & Spent Fuel Licensing Branch 1p 22005:295

B401300078 SER supporting radiological contingency plan for License SNM-960
CARDARELLI, R D., TERRY, Q A Uranium Fuel Licensing Branch.
84/01/19 4pp 22005 295

B401230400 Memorandum & order dismissing License SNM-960 renewal proceeding, per B40116 stipulation
FRYE, J H Atomic Safety and Licensing Board Panel 84/01/20 1p.
21879 152 24X Fiche 50-070, 84/01/20, B401230400

B401310235 Response opposing J Turk B31128 contentions & revs, per ASLB B30408 order Contentions not admissible
EDGAR, Q L General Electric Co EDGAR, Q L Newman & Holtzinger.
84/01/30 Atomic Safety and Licensing Board Panel 35pp.
22021:161 24X Fiche 50-070, 84/01/30, B401310235

B401310239 Affidavit of RW Darnitzel re releases of water containing radioactive matls Certificate of Svc encl.
DARMITZEL, R W General Electric Co 84/01/25 4pp 22021:196
24X Fiche 50-070, 84/01/30, B401310235

DOCKET 70-0820 UNITED NUCLEAR CORP , HOOD RIVER JUNCTION, RI

B401100175 Forwards IE Insp Rept 70-0820/B3-08 on B31003-21. No violations noted
STAROSTECKI, R. Division of Project & Resident Programs 83/12/21.
AMY, Q D United Nuclear Corp 2pp 21760 351.

B401100177 IE Insp Rept 70-0820/B3-08 on B31003-21 No violations noted.
Major areas inspected: confirmatory survey of licensee decommissioned facility by Oak Ridge Assoc Univs
ROYH, J., ELBASSER, T C Region 1, Office of Director 83/12/21
Bpp. 21760:353

B401270055 Informs that due to decommissioning progress, no liquid or gaseous effluents being emitted from facility. All sources of effluent discharge to unrestricted areas eliminated.
HELGESON, K A United Nuclear Corp 84/01/09 Region 1, Office of Director. 1p. 21797:151

B401190176 Briefs ofc director on recent items of interest, including B40111 CROR review, B40109 meeting re West Lake Landfill, B40110 meeting re Hood River Junction groundwater & B40111 meeting re Westinghouse license renewal
PAOE, R Q Uranium Fuel Licensing Branch 84/01/12 BAVIS, J O.
Office of Nuclear Material Safety & Safeguards, Director. 2pp. 21861:317.

DOCKETED ITEMS

B401310053 Trip rept of B40110 meeting w/DL Warner at Univ of Missouri. Rolla to discuss status of evaluation of groundwater conditions at United Nuclear Corp site in Wood River Junction, RI
WYNGARDEN, B D. Uranium Fuel Licensing Branch B4/01/18 CROW, W T
Uranium Fuel Licensing Branch 1p. 22032-341

DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

B401230324 Ack receipt of B31206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1193/B3-04 & 70-0925/B3-03
PAPERIELLO, C J. Region 3, Office of Director B4/01/17
BHELLEY, W J. Kerr-McGee Nuclear Corp 1p. 21883-203.

--B401230328 Responds to NRC B31107 ltr re violations noted in IE Insp Repts 70-1193/B3-04 & 70-0925/B3-03 Corrective actions. Procedure KM-MP-10-B2, "Transuranic Waste Packaging, Storage & Shipping," revised B31028
BHELLEY, W J. Kerr-McGee Nuclear Corp B3/12/06 PAPERIELLO, C J.
Region 3, Office of Director 1p. 21883-206

DOCKET 70-0938 MASSACHUSETTS INSTITUTE OF TECHNOLOGY, CAMBRIDGE, MA

B401040019 Responds to FOIA request for list of schools, businesses & shops in Cambridge, MA possessing NRC licenses for use of radioactive compounds & for copy of licenses Forwards App A documents
FELTON, J M. Division of Rules and Records. B3/10/14.
CHRISTENSEN, D. Citizens Against Research Bans 5pp. 21731-312.

911160348 Notices of Amend 6 to License SNM-986 for 5 g U-235 enriched to 93.13 in hermetically sealed containers used for light absorption measurement experiments
MOULSEY, R T. Atomic Energy Commission 71/11/17 COCHRANE, J L.
Massachusetts Institute of Technology, Cambridge, MA 1p.
21731-357

111160381 Notices of Amend 5 to License SNM-986 for 16 g Pu in form of metal foils for testing.
ROUSE, L C. Atomic Energy Commission. 71/01/13. COCHRANE, J L.
Massachusetts Institute of Technology, Cambridge, MA 2pp.
21731-360

--B401040092 Advises of issuance of Amend 4 to License SNM-986, describing limitations on radioactive matl use, per 701124 request.
ROUSE, L C. Atomic Energy Commission 71/01/05. CLARK, L.
Massachusetts Institute of Technology, Cambridge, MA 1p.
21731-362.

--B401040094 Advises of issuance of Amend 2 to License SNM-986, describing limitations on radioactive matl use, per 700112 & 28 applications.
ROUSE, L C. Atomic Energy Commission. 70/02/18 CLARK, L.
Massachusetts Institute of Technology, Cambridge, MA 1p.
21732-001

B401040098 Advises of issuance of Amend 3 to License SNM-986, authorizing storage only of 16 g Pu in form of metal foils, per 701014 application.
MUSSEBAUMER, D A. Atomic Energy Commission 70/11/24 COCHRANE, J.
Massachusetts Institute of Technology, Cambridge, MA 1p.
21732-002

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NC

401170455 Application to amend License SNM-1097, requesting time extension for reporting receipt of SNM on one-time basis. Supporting info encl. Encl withheld (ref 10CFR2.790).
VAUGHAN, C M. General Electric Co B3/12/02. BROWN, W B. Fuel
Facility Safeguards Licensing Branch. 1p. 21836-304

401030358 Forwards revs to fundamental nuclear matl control plan. Revs withheld (ref 10CFR2.790).
VAUGHAN, C M. General Electric Co B3/12/08. O'REILLY, J P. Region
2, Office of Director. 1p. 21687-358

101170452 Forwards revs to fundamental nuclear matl control plan. Revs withheld (ref 10CFR2.790).
VAUGHAN, C M. General Electric Co B3/12/09. BROWN, W B. Fuel
Facility Safeguards Licensing Branch. 1p. 21836-306.

101090607 Responds to B31202 request for 15-day extension to rept receiver value for specific receipt of low enriched U. No adverse effects exist in granting one-time extension. Unnumbered license condition added to Amend MFP-3.
BROWN, W B. Fuel Facility Safeguards Licensing Branch B3/12/15
VAUGHAN, C M. General Electric Co 2pp. 21766-217

B401090775 Forwards BER re const of facilities to recover U from lagoon sludge. Supplemental environ info not required, however, amend to Matis License SNM-1097 required.
VAUGHAN, C. Uranium Fuel Licensing Branch B3/12/21 PAGE, R Q.
General Electric Co 1p. 21767-019

--B401090779 SER supporting B30922 application for const & use of facilities to recover U from lagoon sludge.
BIDINGER, O H. CROW, W T. Uranium Fuel Licensing Branch B3/12/21-
2pp. 21767-020

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

B401310154 Forwards "Bldg B Evaluation Rept," per Condition 19 to License SNM-1120 Rept validates decision to proceed w/lab demolition. No significant increase in employee exposure or unreviewed safety question involved.
NARDI, A J. Westinghouse Electric Corp B4/01/04 MURLEY, T E.
Region 1, Office of Director 1p. 22037-074

--B401310159 "Bldg B Evaluation Rept"
* Westinghouse Electric Corp B4/01/04 7pp. 22037-075

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

B401050008 Forwards addl info to application for renewal of License SNM-1107, in response to NRC B30406 ltr.
NARDI, A J. Westinghouse Electric Corp B3/12/12 PAGE, R Q.
Division of Fuel Cycle & Material Safety 1p. 21736-178

--B401050011 Rev 1 to application for renewal of License SNM-1107
* Westinghouse Electric Corp. B3/12/12 37pp. 21736-179.

B401090696 Forwards "Addendum to Safeguards Amend 50-1, License SNM-1107 US/IAEA Safeguards Agreement," re transitional facility agreement for implementation of protocol for safeguards agreement.
BROWN, W B. Fuel Facility Safeguards Licensing Branch. B3/12/19.
NARDI, A J. Westinghouse Electric Corp 5pp. 21757-036.

B401240378 Forwards IE Insp Rept 70-1151/B3-28 on B31205-09 No violations noted. Rept withheld (ref 10CFR2.21 & 2.790).
STOHR, J P. Division of Emergency Preparedness & Materials Safety.
B3/12/21 BRITTON, W H. Westinghouse Electric Corp 2pp.
21932-126

B401050348 Ack receipt of B31215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/B3-24.
STOHR, J P. Division of Engineering & Operational Programs
B3/12/27 BRITTON, W H. Westinghouse Electric Corp 1p. 21731-035

--B401050351 Responds to NRC B31118 ltr re violations noted in IE Insp Rept 70-1151/B3-24 Corrective actions, administrative controls initiated to assure renewal of mutual agreement contracts.
BRITTON, W H. Westinghouse Electric Corp B3/12/15 STOHR, J P.
Division of Engineering & Operational Programs 2pp. 21731-036

--B401050355 Forwards IE Insp Rept 70-1151/B3-24 on B31024-27 & notice of violation.
STOHR, J P. Division of Engineering & Operational Programs
B3/11/18 BRITTON, W H. Westinghouse Electric Corp. 2pp.
21731-038.

--B401050357 Notice of violation from insp on B31024-27
* Region 2, Office of Director B3/11/18, 1p. 21731-040

--B401050361 IE Insp Rept 70-1151/B3-24 on B31024-27. Noncompliance noted: failure to implement site emergency plan requirement for maintaining agreements w/offsite support organizations.
HUFFMAN, O H. KREH, J L. Region 2, Office of Director
JENKINS, O R. Division of Engineering & Operational Programs
B3/11/16 5pp. 21731-061

B401250265 Ack receipt of B31216 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-1151/B3-25.
STOHR, J P. Division of Emergency Preparedness & Materials Safety
B3/12/28 BRITTON, W H. Westinghouse Electric Corp. 1p. 21944-183.

--B401250267 Forwards proprietary response to violations noted in IE Safeguards Insp Rept 70-1151/B3-25. Response withheld (ref 10CFR2.790).
BRITTON, W H. Westinghouse Electric Corp B3/12/16 O'REILLY, J P.
Region 2, Office of Director. 1p. 21944-189

DOCKETED ITEMS

398

8401240528 Ack receipt of 831207 ltr re IE Insp Rept 70-1131/83-27 on 831114-18
SANDERS, C F Westinghouse Electric Corp 84/01/03 O'REILLY, J P
Region 2, Office of Director 1p 21918 162

8401240366 Ack receipt of 831221 ltr re IE Insp Rept 70-1131/83-28 on 831205-09
SANDERS, C F Westinghouse Electric Corp 84/01/06 O'REILLY, J P
Region 2, Office of Director 1p 21920 243

8401190176 Briefs of director on recent items of interest, including 840111 CRGR review, 840109 meeting re West Lake Landfill, 840110 meeting re Wood River Junction groundwater & 840111 meeting re Westinghouse license renewal
PAGE, R G Uranium Fuel Licensing Branch 84/01/12 DAVIS, J G
Office of Nuclear Material Safety & Safeguards, Director 2pp 21861 319

8401240356 Ack receipt of 831208 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1131/83-18
STOHR, J P Division of Emergency Preparedness & Materials Safety 84/01/12 BRITTON, W H Westinghouse Electric Corp 1p 21919 347

--8401240357 Responds to NRC 831122 ltr re violation noted in IE Insp Rept 70-1131/83-18 Corrective actions internal audits & insps as result of fire caused by presence of U-contaminated Zircaloy chips continuing
BRITTON, W H Westinghouse Electric Corp. 83/12/08 O'REILLY, J P
Region 2, Office of Director 2pp 21919.348

--8401240361 Forwards IE Insp Rept 70-1131/83-1B on 830817-19 & notice of violation
O'REILLY, J P Region 2, Office of Director. 83/11/22.
BRITTON, W H Westinghouse Electric Corp. 2pp 21919.350

--8401240362 Notice of violation from insp on 830817-19
O'REILLY, J P Region 2, Office of Director. 83/11/22 2pp 21919 352

--8401240365 Forwards IE Insp Rept 70-1131/83-1B on 830815 & 17-19
O'REILLY, J P Region 2, Office of Director 83/11/22
BRITTON, W H Westinghouse Electric Corp. 1p 21919 354

DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8401230324 Ack receipt of 831206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1193/83-04 & 70-0925/83-03
PAPERIELLO, C J Region 3, Office of Director 84/01/17.
SHELLEY, W J Kerr-McGee Nuclear Corp 1p 21883 205

--8401230328 Responds to NRC 831107 ltr re violations noted in IE Insp Repts 70-1193/83-04 & 70-0925/83-03 Corrective actions: Procedure KM-MP-10-82, "Transuranic Waste Packaging, Storage & Shipping," revised 831028
SHELLEY, W J Kerr-McGee Nuclear Corp 83/12/06 PAPERIELLO, C J
Region 3, Office of Director 1p 21883.206

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

8401120167 Grants 831121 request for 4-wk extension in beginning next low enriched U physical inventory
BURNETT, R F Division of Safeguards 83/12/06 FORD, J T Babcock & Wilcox Co 1p 21805 061

8401050433 Forwards IE Insp Rept 70-1201/83-13 on 831117-18. No violations noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/12/09 ALTO, R A Babcock & Wilcox Co. 2pp. 21729 346

--8401050435 IE Insp Rept 70-1201/83-13 on 831117-18. No violations noted
Major areas inspected, radiological environ monitoring & lab GC, including status of environ monitoring program & mgt controls
TROUP, G L Region 2, Office of Director MONTGOMERY, D. M.
Division of Emergency Preparedness & Materials Safety 83/12/06.
Spp 21729 348.

8401090600 Submits amend to safeguards Amend MPP-2 to License SNM-1168 adding Condition 2.1.1 requiring licensee to follow transitional Facility Attachment & for protocol of US/IAEA safeguards agreement
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/19
FORD, J T Babcock & Wilcox Co 6pp. 21764-356

DOCKET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA

8401090597 Advises of issuance of rev to License Condition 2.1 to Amend MPP-1 to License SNM-1227, per 831017 request Rev describes procedures for following fundamental nuclear matl control plan
BROWN, W B Fuel Facility Safeguards Licensing Branch 83/12/01
SCHNEIDER, R A Exxon Nuclear Co , Inc (subs of Exxon Corp) 2pp 21767 307

DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA

8401200130 Forwards table providing current status of spent fuel storage at facility
DANBON, D M General Electric Co 84/01/03 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp. 21872 148

DOCKET 70-1331 VETERANS ADMIN MEDICAL CENTER, BUFFALO, NY

8401310225 Discusses IE Insp Repts 70-1331/83-01, 70-1409/83-01 & 30-0261B/83-01 on 831101-02 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/01/25
PARIS, J Veterans Admin Medical Center, Buffalo, NY 2pp 22021 223

--8401310232 Notice of violation from insp on 831101-02 Violation noted: Failure to perform surveys to assure compliance w/ 10CFR20.301 re authorized means of disposing of licensed matl contained in waste
* Region 1, Office of Director 84/01/25 2pp 22021 225.

DOCKET 70-1409 VETERANS ADMIN MEDICAL CENTER, BUFFALO, NY

8401310225 Discusses IE Insp Repts 70-1331/83-01, 70-1409/83-01 & 30-0261B/83-01 on 831101-02 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 84/01/25
PARIS, J Veterans Admin Medical Center, Buffalo, NY 2pp 22021 223

DOCKET 70-1470 VETERANS ADMIN HOSP , LOS ANGELES, CA

8401310020 IE Insp Findings & Licensee Ack dtd 831108 of License SNM-1440. Insp findings no violations observed
ZURAKOWSKI, P R Region 5, Office of Director 83/11/23 1p 22024 036

DOCKET 70-1795 GEORGE WASHINGTON UNIV , WASHINGTON, DC

8312230327 Ack receipt of check in amount of \$2,500 in full payment of civil penalties imposed on 831115
AXELRAD, J A Enforcement Staff 83/12/16 LEONARD, F. George Washington Univ Medical Center, Washington, DC 2pp 21619-323

DOCKET 70-2427 JOHN F KENNEDY MEMORIAL HOSP , STRATFORD, NJ

8401100435 Discusses IE insp of Licensee SNM-1690 & 29-12167-01 on 830627, 0705, 19 & 0830 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/12/23
WISER, P John F Kennedy Memorial Hosp., Stratford, NJ 2pp 21762 164

--8401100438 Notice of violation from insp on 830627, 0705, 19 & 0830. Violation noted failure to perform followup exam on patients implanted w/nuclear pacemakers
* Region 1, Office of Director 83/12/23 1p. 21762.166

DOCKET 70-2786 GENERAL ELECTRIC CO , SAN JOSE, CA

8401170449 Forwards info supporting request for revalidation of previously approved route for shipment of irradiated reactor fuel w/o encl
KIRKLAND, M W General Electric Co 83/12/12 HILLMAN, C R Office of Nuclear Material Safety & Safeguards, Director 1p. 21836/305

DOCKETED ITEMS

DOCKET 70-2876 VETERANS ADMIN HOSP , BROOKLYN, NY

8401100259 Advises of expiration of License SNM-1828 & discusses actions to be taken by licensee. Actions include explanation of disposal of matls & submittal of calendar yr annual rept if expired license subj to 10CFR20 requirements
MARTIN, T. T. Division of Engineering & Technical Programs 83/12/23
GARFUNKEL, B Veterans Admin Hosp & Medical Center, Brooklyn, NY 2pp. 21759 192

DOCKET 70-2887 PHELPS COUNTY MEMORIAL HOSP , ROLLA, MO

8401040389 Ack receipt of 831213 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 24-18295-01 & SNM-1842 on 831102
WIEDEMAN, D. O Region 3, Office of Director. 83/12/30 EMERY, R. M.
Phelps County Memorial Hosp , Rolla, MO 1p. 21706:280

--8401040394 Responds to NRC 831116 ltr re violations noted in IE insp of Licenses 24-18295-01 & SNM-1842 on 831102 Corrective actions. Medical isotope committee expanded to include E Atkinson & B Green of nursing svc ofc
EMERY, R. M Phelps County Memorial Hosp., Rolla, MO 83/12/13
WIEDEMAN, D. O. Region 3, Office of Director. 2pp 21706 281.

DOCKET 70-2945 UNION ELECTRIC CO., ST. LOUIS, MO

8401090594 Approves 830715 Rev 2 to security plan for protection of BNM of low strategic significance. Addl measures contained in encl. "Supplemental Physical Security Conditions " Encl withheld (ref 10CFR73.21)
BROWN, W. B. Fuel Facility Safeguards Licensing Branch. 83/10/28.
SCHNELL, D. E. Union Electric Co 1p 21767:256

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO , NEW ORLEANS, LA

401190097 Issues Amend 2 to License SNM-1913 & SER, adding Conditions A, C, 7, C & B, C to include U, enriched in U-235 isotope, contained in sealed source & 9 g U-235 at any enrichment
PAGE, R. O Uranium Fuel Licensing Branch. 83/12/29. DRUMMOND, F. J.
Louisiana Power & Light Co. 1p. 21870.239.

--8401190102 Safety evaluation supporting Amend 2 to License SNM-1913
KETZLACH, N., CROW, W. T. Uranium Fuel Licensing Branch. 83/12/29.
3pp. 21870:240.

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO , PHOENIX, AZ

8401060559 Unexecuted Amend 1 to Indemnity Agreement B-95.
SALTZMAN, J Assistant Director For State & Licensee Relations
83/11/30. 3pp. 21755:126

DOCKET 70-2959 EDLOW INTERNATIONAL CO , WASHINGTON, DC

8401030319 Discusses impact of new environ stds on West Chicago Rare Earths Facility Table B-3 narrative explanation sent to ACRS, DOE trying to obtain info re Canonsburg & fire at Edlow warehouse for storage of BNM
PAGE, R. O. Uranium Fuel Licensing Branch. 83/12/15. DAVIS, J. O
Office of Nuclear Material Safety & Safeguards, Director 2pp.
21693:335.

8312230300 Submits recommendations resulting from review of 831207 fire in East St Louis, IL, including discussion of license issuance w/local govt officials, prelicense insp, license mod & assessing integrity of 2.5 ton cylinders in major fire.
BIDINGER, G. H Uranium Fuel Licensing Branch 83/12/20 CROW, W. T
Uranium Fuel Licensing Branch 4pp. 21619.302

8401030552 Confirmatory action ltr re agreement reached during 831230 telcon pertaining to mod of firewatch condition identified in Paragraph 2.3 of 831209 confirmatory action ltr.
KEPPLER, J. O. Region 3, Office of Director 83/12/30. PODHURST, B. W.
Edlow International Co. 1p. 21724:269

8401160292 Confirmatory action ltr accepting scheduled shipment of U ore concentrates on 830111. Enforcement conference on 840119 at Region III also confirmed.
HIND, J. A. Division of Radiological & Materials Safety Programs.
84/01/11. PODHURST, B. W. Edlow International Co. 2pp. 21814:001.

--8401160297 Requests permission to receive & store U ore concentrates at facility until written agreements obtained
PODHURST, B. W Edlow International Co 84/01/04 AXELSON, B
Region 3, Office of Director 1p 21814 003

8401190443 Corrected confirmatory action ltr requesting that future incoming shipments of low enriched U hexafluoride be postponed until concerns resolved re fire protection sys upgrades & completion of ltr of agreement
HIND, J. A Division of Radiological & Materials Safety Programs
84/01/13 PODHURST, B. W Edlow International Co 2pp 21849.237

8401160091 Notice of 840119 significant licensee meeting in Glen Ellyn, IL to discuss NRC findings during recent insp, enforcement options available & licensee corrective actions.
* Region 3, Office of Director 84/01/16 Region 3, Office of Director 1p 21809 362

8401240170 Denies 840114 request to terminate firewatch until further NRC analyses complete.
AXELSON, W. L Region 3, Office of Director 84/01/20 PODHURST, B. W
Edlow International Co 1p 21908 350

--8401240176 Requests authorization to terminate firewatch established 831230 during mods to sprinkler sys Mods requested by East St Louis Fire Dept now complete
PODHURST, B. W Edlow International Co 84/01/16 AXELSON, W
Region 3, Office of Director 1p 21908 351

8401310344 PND-III-84-010 on 840126, approx 135 persons participated in demonstration opposing continued storage of U at util warehouse in East St Louis, IL Major fire occurred at warehouse on 831207
LABUM, B , AXELSON, W Region 3, Office of Director 84/01/27 1p 22015.058

DOCKET 70-2972 COMMONWEALTH EDISON CO , CHICAGO, IL

8401090628 Informs of review of 830713 Rev 1 to security plan Change does not decrease effectiveness of plan & is acceptable
BROWN, W. B. Fuel Facility Safeguards Licensing Branch 83/10/31.
DELGEORE, L. O Commonwealth Edison Co 1p 21757 360.

DOCKET 70-2973 COMMONWEALTH EDISON CO , CHICAGO, IL

8401090628 Informs of review of 830713 Rev 1 to security plan Change does not decrease effectiveness of plan & is acceptable
BROWN, W. B Fuel Facility Safeguards Licensing Branch. 83/10/31
DELGEORE, L. O Commonwealth Edison Co 1p 21757.360.

DOCKET 70-2984 ARIZONA PUBLIC SERVICE CO , PHOENIX, AZ

8401060559 Unexecuted Amend 1 to Indemnity Agreement B-95
SALTZMAN, J Assistant Director for State & Licensee Relations
83/11/30 3pp 21755.126

8401090031 Requests change in annual indemnity fee for SNM license issuance
DINITZ, I. Assistant Director for State & Licensee Relations.
83/12/30 PUOLIRE, A. S. Division of Accounting 1p. 21757-283

DOCKET 70-2985 DUKE POWER CO , CHARLOTTE, NC

8401090707 Advises that 830510 storage & in-transit security plan for SNM of low strategic significance acceptable.
BROWN, W. B Fuel Facility Safeguards Licensing Branch. 83/12/13
TUCKER, H. B Duke Power Co. 1p. 21767:029.

8401170511 Unexecuted Indemnity Agreement B-100
SALTZMAN, J Assistant Director for State & Licensee Relations.
84/01/03 15pp 21847:117

8401250331 Forwards License SNM-1920, authorizing util to receive & store enriched U contained in shipping container in fuel receiving area specified in license application dtd 831122
PAGE, R. O Uranium Fuel Licensing Branch 84/01/03 TUCKER, H. B
Duke Power Co 1p 21952:340

--8401250334 License SNM-1920 for Duke Power Co, authorizing receipt & storage of fuel assemblies in shipping container in fuel receiving area specified in license application dtd 831122
PAGE, R. O Uranium Fuel Licensing Branch. 84/01/03 15pp 21952:341.

DOCKETED ITEMS

B401310334 Forwards License SNM-1920 & SER in support of license
License authorizes use of Pu-238 contained in two Pu-Da
neutron sources & receipt, possession, insp & storage of U
contained in fuel assemblies
PAGE, R Q Uranium Fuel Licensing Branch 84/01/16 TUCKER, H B.
Duke Power Co ip 22034 327

--B401310342 Safety evaluation supporting issuance of License SNM-1920
SERINI, B L, CROW, W T Uranium Fuel Licensing Branch 84/01/16
16pp 22034 333

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0001 ANEFCO, INC

B401130088 Forwards second edition of "QA Manual for ANEFCO Shipping
Packages for Radioactive Matl," for review & approval W/O
encl
MURPHY, J D Anefco, Inc 83/12/22 MACDONALD, C E Transportation
Certification Branch ip 21821 126

DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS, INC

B401100152 Forwards revised "QA Plan for Transportation Packages for
Normal/Special Form Radioactive Matl (10CFR71)," reflecting
organizational changes from assumption of KSC base
operations contract
FERGUSON, E B EG&O, Inc 83/12/05 MACDONALD, C E Transportation
Certification Branch 8pp 21768 342

--B401100156 Revised "QA Plan for Transportation Packages for Normal/
Special Form Radioactive Matl (10CFR71)"
FERGUSON, E B EG&O, Inc 83/11/30. 7pp 21768 343

B401310463 Forwards QA program approval for radioactive matl package
0096, Rev 2
MACDONALD, C E Transportation Certification Branch 84/01/17
FERGUSON, E B EG&O, Inc ip 22036 309

--B401310464 QA program approval for radioactive matl package 0096, Rev 2
MACDONALD, C E Transportation Certification Branch. 84/01/17.
ip 22036 310

DOCKET 71-0281 WESTINGHOUSE ELECTRIC CORP

B401200119 Requests one-time exemption from requirements of approved QA
plan for transportation of radioactive matl under License
BNN-770, permitting one-time shipment of Type A quantity of
enriched U in form of Zircaloy clad fuel rods
NARDI, A J Westinghouse Electric Corp 84/01/04 MACDONALD, C E
Transportation Certification Branch 2pp 21872 171

B401310466 Forwards QA program approval for radioactive matl package
0251, Rev 2
MACDONALD, C E Transportation Certification Branch. 84/01/17
NARDI, A J Westinghouse Electric Corp ip 22036 311.

--B401310467 QA Program approval for radioactive matl package 0251, Rev 2.
MACDONALD, C E Transportation Certification Branch. 84/01/17
ip 22036 312

DOCKET 71-0510 GESELLSCHAFT FUR NUKLEAR SERVICE

B401060528 Responds to 831121 submittal of "QNS QA Handbook for Caster
Dry Storage Casks." Submittal provides insufficient info
to make determination whether requirements of 10CFR71 met.
Application requested per 10CFR71 101
MACDONALD, C E Transportation Certification Branch 83/12/29
ROLLINS, J D Gesellschaft Fuer Nuklear Service, mbH. ip
21743 333.

DOCKET 71-0511 DELTAK CORP

B401060619 Forwards App H "QA Program for Transportation of
Radioactive Matls," for review & registration.
JORDAN, D Deltak Corp 83/12/07 GORDON, L Transportation
Certification Branch 5pp. 21755 108

--B401060625 App H "QA Program for Transportation of Radioactive Matls."
* Deltak Corp 83/12/07 4pp 21755 109.

DOCKET 71-4909 MODEL. GE-21PF-1, GENERAL ELECTRIC CO

B401240266 Requests permission to ref 1982 & 1971 editions of ANSI Std
N14.1 re 300 cylinders used for source or low enriched U
hexafluoride SNM transportation
VAUGHAN, C M General Electric Co 83/11/11 RAWL, R R
Transportation, Dept of ip 21945 054

B401040004 Application for amend to Certificate of Compliance 4909 for
W-21PF-1 shipping container, incorporating minor changes
into four encl Westinghouse proprietary oversize drawings
Aperture cards in Central File
NARDI, A J Westinghouse Electric Corp 83/11/21 MACDONALD, C E
Transportation Certification Branch 3pp 21714 312

B401200113 Responds to 831202 request for addl info on 830923
application to amend Certificate of Compliance 4909 for
Model GE-21PF-1 shipping package Info will be submitted in
form of revised pages & drawings by 840228
VAUGHAN, C M General Electric Co 83/12/27 MACDONALD, C E
Transportation Certification Branch 2pp 21872 175

B401170272 Forwards Rev 3 to Certificate of Compliance 4909 for
Models GE-21PF-1 & W-21PF-1
MACDONALD, C E Transportation Certification Branch 84/01/06
VAUGHAN, C M General Electric Co 2pp 21836 354

--B401170275 Certificate of Compliance 4909, Rev 3, for Models GE-21PF-1 &
W-21PF-1.
MACDONALD, C E Transportation Certification Branch. 84/01/06
3pp 21836 356

DOCKET 71-8450 MODEL RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP.

B401270326 Forwards Rev 1B to Certificate of Compliance 3450 for Models
RCC, RCC-1, RCC-2, RCC-3 & RCC-4.
MACDONALD, C E Transportation Certification Branch 84/01/13.
NARDI, A J Westinghouse Electric Corp 2pp. 22000 350

--B401270330 Certificate of Compliance 3450, Rev 1B, for Models RCC, RCC-1,
RCC-2, RCC-3 & RCC-4
MACDONALD, C E Transportation Certification Branch 84/01/13
6pp 22000 352

DOCKET 71-5797 MODEL INNER & OUTER HFIR UN, ENERGY, DEPT OF

B401200293 Forwards Rev 2 to Certificate of Compliance 5797 for
Model HFIR.
MACDONALD, C E Transportation Certification Branch 84/01/13.
BLALOCK, L Energy, Dept of ip 21872 095

--B401200297 Certificate of Compliance 5797, Rev 2, for Model HFIR. Approva
record encl
MACDONALD, C E Transportation Certification Branch. 84/01/13.
4pp 21872 096

B401310448 Forwards Rev 3 to Certificate of Compliance 5797 for inner &
outer HFIR unirradiated fuel element shipping container
packages
MACDONALD, C E Transportation Certification Branch 84/01/18
BLALOCK, L Energy, Dept. of 2pp 22036 324

--B401310450 Certificate of Compliance 5797, Rev 3, for inner & outer HFIR
unirradiated fuel element shipping container packages
MACDONALD, C E Transportation Certification Branch 84/01/18
4pp 22036 326

DOCKET 71-5800 MODEL: ORNL TRITIUM TARGET CONTAINER

B401120007 Forwards ORNL responses to NRC 830831 request for addl info
re upgrading IAEA certificate of competent authority for
ORNL tritium target assembly to 1973 requirements.
WEINTRAUB, A A Energy, Dept of 83/11/22 RAWL, R R
Transportation, Dept. of. 16pp. 21807 019.

DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO

B401120530 Requests registration as user of Model GE-1500. Revised
certificate of compliance requested.
SMITH, J L Long Island Lighting Co 83/12/27 DAVIS, J O Office
of Nuclear Material Safety & Safeguards, Director. 2pp. 21804 089

DOCKETED ITEMS

DOCKET 71-5957 MODEL BHI-1, BATTELLE COLUMBUS LABORATORY

B401120552 Application for amend to Certificate of Compliance 5957 for Model BHI-1 Responses to B30922 questions also encl
BURIAN, R J Battelle Memorial Institute, Columbus Laboratories
B3/12/28 MACDONALD, C E Transportation Certification Branch 5pp
21803 037

--B401120553 Rev E to "BAR for Model BHI-1 Shipping Cask"
* Battelle Memorial Institute, Columbus Laboratories B3/12/28
18pp 21803 042

DOCKET 71-4058 MODEL B-3, U S ECOLOGY, INC

B401170526 Forwards Rev B to Certificate of Compliance 4058 for Model B-3
MACDONALD, C E Transportation Certification Branch. B4/01/06
SCOVILLE, J J U S Ecology, Inc. (formerly Nuclear Engineering, Inc.) 3pp 21847 106

--B401170529 Certificate of Compliance 4058, Rev B for Model B-3 Approval record encl
MACDONALD, C E Transportation Certification Branch B4/01/06
6pp 21847 109

DOCKET 71-6346 MODEL FSU-1, QA TECHNOLOGIES, INC

B401170539 Advises that util intends to utilize listed containers for shipment of radioactive matl generated at facility
Correspondence fulfills notification requirement of 10CFR71.12(b)(1)(iii)
FIEDLER, P B General Public Utilities - GPU Service Corp B3/12/30
MACDONALD, C E Transportation Certification Branch 2pp
21847 056

DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

B401060664 Summary of B31221 meeting w/Hittman Nuclear & Development Corp in Silver Spring, MD re leak testing & other transportation issues
ODEGAARDEN, R H Transportation Certification Branch B3/12/23
Transportation Certification Branch 7pp 21755 043

B401130058 Advises that addl info on Model HN-200 packaging will be provided by B40330
SHEEHAN, D Hittman Nuclear & Development Corp (subs of Hittman Corp.) B3/12/28 MACDONALD, C E Transportation Certification Branch 1p 21821 138

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

B004280166 Requests Renewal of Certificate of Compliance 9010 for Model NLI-1/2. Forwards drawings & "BAR, NLI-1/2 Spent Fuel Shipping Cask," Drawings & rept available in Central Files only.
WILLIAMS, C E NL Industries, Inc. B0/03/07 MACDONALD, C E Transportation Certification Branch 6pp 21868 071

--B401190077 "Safety Analysis Rept, NLI 1/2 Spent Fuel Shipping Cask"
* NL Industries, Inc. B0/02/29 550pp 21868 077

DOCKET 71-9016 MODEL TN-9, NO USERS

B401170539 Advises that util intends to utilize listed containers for shipment of radioactive matl generated at facility
Correspondence fulfills notification requirement of 10CFR71.12(b)(1)(iii)
FIEDLER, P B General Public Utilities - GPU Service Corp B3/12/30
MACDONALD, C E Transportation Certification Branch 2pp
21847 056

DOCKET 71-9044 MODEL QE-1400, GENERAL ELECTRIC CO.

B401190085 Application for amend to Certificate of Compliance 9044, authorizing use of auxiliary shield inside cask to allow shipping of solid mats of higher source values
POPPE, L K Chem-Nuclear Systems, Inc B3/11/16 MACDONALD, C E Transportation Certification Branch 31pp 21868 037

--B401190088 Requests addl fee in connection w/B31116 application for amend to Certificate of Compliance 9044
JACKSON, G License Fee Management Branch B3/12/05 POPPE, L K Chem-Nuclear Systems, Inc 1p 21868 068

--B401190093 Forwards check in payment of addl fee requested in B31205 1tr re application for amend to Certificate of Compliance 9044
POPPE, L K Chem-Nuclear Systems, Inc B3/12/13 JACKSON, G License Fee Management Branch 2pp 21868 069

DOCKET 71-9071 MODEL AP-101, ANEFCO, INC

B401170539 Advises that util intends to utilize listed containers for shipment of radioactive matl generated at facility
Correspondence fulfills notification requirement of 10CFR71.12(b)(1)(iii)
FIEDLER, P B General Public Utilities - GPU Service Corp B3/12/30
MACDONALD, C E Transportation Certification Branch 2pp
21847 056

DOCKET 71-9073 MODEL OH-142, NUCLEAR PACKAGING, INC

B401060664 Summary of B31221 meeting w/Hittman Nuclear & Development Corp in Silver Spring, MD re leak testing & other transportation issues
ODEGAARDEN, R H Transportation Certification Branch B3/12/23
Transportation Certification Branch 7pp 21755 043

DOCKET 71-9080 MODEL HN-600, NUPAC 7-100 & CNS 7-100, HITTMAN NUCLEAR

B401060664 Summary of B31221 meeting w/Hittman Nuclear & Development Corp in Silver Spring, MD re leak testing & other transportation issues
ODEGAARDEN, R H Transportation Certification Branch B3/12/23
Transportation Certification Branch 7pp 21755 043

DOCKET 71-9089 MODEL HN-100B, HITTMAN NUCLEAR & DEVELOP. CORP

B401060664 Summary of B31221 meeting w/Hittman Nuclear & Development Corp in Silver Spring, MD re leak testing & other transportation issues
ODEGAARDEN, R H Transportation Certification Branch B3/12/23
Transportation Certification Branch 7pp 21755 043

DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP

B401190103 Requests further info re application for renewal of Certificate of Compliance 9092 for Model HN-300 packaging. Consolidated application w/drawings, incorporating previous submittals & response to encl questions, requested
MACDONALD, C E Transportation Certification Branch B4/01/03
ROWE, B B Hittman Nuclear & Development Corp (subs of Hittman Corp) 3pp 21870 234

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

B401190110 Requests further info re application for renewal of Certificate of Compliance 9093 for Model HN-400 packaging. Consolidated application w/drawings, incorporating previous submittals & response to encl questions, requested
MACDONALD, C E Transportation Certification Branch B4/01/03
ROWE, B B Hittman Nuclear & Development Corp (subs of Hittman Corp) 3pp 21871 049

DOCKET 71-9107 MODEL 771, TECHNICAL OPERATIONS, INC

B401160020 Requests registration as user of Rev 1 to Certificate of Compliance 9107 & Rev 0 to Certificate of Compliance 9148
KRUIZIG, R W Chicago Bridge & Iron Co B4/01/03 MACDONALD, C E Transportation Certification Branch 1p 21821 361

DOCKET 71-9134 MODEL ETR, EXXON NUCLEAR IDAHO CO

B401310453 Forwards Rev 2 to Certificate of Compliance 9134 for Model ETR.
MACDONALD, C E Transportation Certification Branch B4/01/17
OLSON, M C Exxon Nuclear Co, Inc (subs. of Exxon Corp) 2pp
22036 319

DOCKETED ITEMS

399

---8401210454 Certificate of Compliance 9134, Rev 2, for Model ETR
MACDONALD, C E Transportation Certification Branch 84/01/17
3pp 22036 321

DOCKET 71-9143 MODEL 920, TECHNICAL OPERATIONS, INC

8401200106 Requests registration as user of Tech/Ops Model 920
RICHARDSON, C A ABC Testing 84/01/06 MACDONALD, C E
Transportation Certification Branch 2pp 21872 179

DOCKET 71-9148 MODEL 770, TECHNICAL OPERATIONS, INC

8401160020 Requests registration as user of Rev 1 to Certificate of
Compliance 9107 & Rev 0 to Certificate of Compliance 9148
KRUIZIC, R W Chicago Bridge & Iron Co 84/01/03 MACDONALD, C E
Transportation Certification Branch 1p 21821 361

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8401120093 Requests registration as user of Model HN-100
MURRAY, T D Toledo Edison Co 83/12/13 DAVIS, J O Office of
Nuclear Material Safety & Safeguards, Director 1p 21806 204

8401060664 Summary of 831221 meeting w/Hittman Nuclear & Development
Corp in Silver Spring, MD re leak testing & other
transportation issues
ODEGAARDEN, R H Transportation Certification Branch 83/12/23
Transportation Certification Branch 7pp 21755 043

DOCKET 71-9160 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC

8401130063 Advises that info on Models R, 20-VS & 40-VS packaging will
be provided by 840120
HOPCRAFT, C P Gulf Nuclear, Inc 83/12/22 MACDONALD, C E
Transportation Certification Branch 1p 21821 135

DOCKET 71-9161 MODEL R, GULF NUCLEAR, INC

8401130063 Advises that info on Models R, 20-VS & 40-VS packaging will
be provided by 840120
HOPCRAFT, C P Gulf Nuclear, Inc 83/12/22 MACDONALD, C E
Transportation Certification Branch 1p 21821 135

DOCKET 71-9165 MODEL 855, TECHNICAL OPERATIONS, INC

8401110563 Forwards Rev 0 to Certificate of Compliance 9165 for
Model 855 & safety evaluation
MACDONALD, C E Transportation Certification Branch 83/12/30
MUNRO, J J Technical Operations, Inc 1p, 21795 315

---8401110565 Certificate of Compliance 9165, Rev 0, for Model 855
MACDONALD, C E Transportation Certification Branch 83/12/30
2pp 21795 316

---8401110567 SER supporting Rev 0 to Certificate of Compliance 9165 for
Model 855
MACDONALD, C E Transportation Certification Branch 83/12/30
7pp 21795 318

DOCKET 71-9175 MODEL CN86-808, NUCLEAR PACKAGING, INC

8401190300 Summary of 831210 meeting w/Nuclear Packaging, Inc in
Bethesda, MD re structural analyses of shipping packages
ODEGAARDEN, R H Transportation Certification Branch 84/01/12
Transportation Certification Branch 2pp 21870 040

DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC

8401130068 Advises that info on Model PAS-2 packaging will be
provided by 840131
TEMUS, C J Nuclear Packaging, Inc 83/12/28 MACDONALD, C E
Transportation Certification Branch 1p 21821 131

DOCKET 71-9183 MODEL 9183, DUKE POWER CO

8401170537 Advises that util intends to utilize listed containers for
shipment of radioactive matl generated at facility
Correspondence fulfills notification requirement of
10CFR71.12(b)(1)(iii)
FIEDLER, P B General Public Utilities - GPU Service Corp 83/12/30
MACDONALD, C E Transportation Certification Branch 2pp
21847 036

DOCKET 71-9184 MODEL PAS-1, NUCLEAR PACKAGING, INC

8401060677 Forwards request for addl info re 831006 application for
approval of Model PAS-1, covering drawings, structure,
containment & operating procedures
MACDONALD, C E Transportation Certification Branch 83/12/29
TEMUS, C J NI-TEC, Inc 3pp 21755 030

8401190300 Summary of 831210 meeting w/Nuclear Packaging, Inc in
Bethesda, MD re structural analyses of shipping packages
ODEGAARDEN, R H Transportation Certification Branch 84/01/12
Transportation Certification Branch 2pp 21870 040

DOCKET 71-9190 MODEL CASTOR V, GESELLSCHAFT FUER NUKLEAR SERVICE, MKH

8401120523 Forwards "Drop Test Specs for Castor Vb Cask" & "Analysis to
Determine Worst Case Drop Orientation for Castor Vb."
* Gesellschaft fuer Nuklear Service, mbH 83/11/07 MACDONALD, C E
Transportation Certification Branch 2pp 21796 185

---8401120527 "Drop Test Specs for Castor Vb Cask"
* Gesellschaft fuer Nuklear Service, mbH 83/09/30, 5pp,
21796 187

---8401120532 "Analysis to Determine Worst Case Drop Orientation for
Castor Vb"
* Swanson Environmental, Inc 83/09/30 70pp 21796 192

DOCKET 71-9853 MODEL ORNL, BNL & NBS UNIR CONTS, ENERGY, DEPT. OF

8401200272 Forwards Rev 3 to Certificate of Compliance 9853 for Model
ORNL, BNL & NBS
MACDONALD, C E Transportation Certification Branch 84/01/13
BLALOCK, L Energy, Dept of 2pp 21872 080

---8401200280 Certificate of Compliance 9853, Rev 3, for Model ORNL, BNL &
NBS Approval record encl
MACDONALD, C E Transportation Certification Branch 84/01/13
4pp 21872 082

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8401200130 Forwards table providing current status of spent fuel
storage at facility
DAWSON, D M General Electric Co 84/01/03 ROUSE, L C Advanced
Fuel & Spent Fuel Licensing Branch 3pp 21872 148

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8401030279 Trip rept of 831206 site visit w/util & Bechtel re proposed
ISFSI & discussion of environ info
STURZ, F. Advanced Fuel & Spent Fuel Licensing Branch 83/12/19
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 2pp
21693 360 24X Fiche: 50-280, 83/12/19, 8401030279

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

B401090524 Staff requirements memo re B31219 briefing in Washington, DC on development of proposed rule on highly enriched U at domestic reactors Commission agreed to tentatively schedule meeting on B40127 to discuss safeguard issues
CHILK, S J Office of the Secretary of the Commission MB31219
B3/12/30 Office of the Secretary of the Commission 1p
21767 358

B40110561 Transcript of B40106 discussion/possible vote on equipment qualification policy statement & proposed rule in Washington, DC Pp 1-29 Supporting documentation encl.
* Commissioners B4/01/06 151pp 21796 018

B401120119 Transcript of Commission B40104 discussion of NRC enforcement policy in Washington, DC Viewgraphs encl Pp 1-82
* Commissioners B4/01/04 99pp 21806 211

B401160365 Responds to FOIA request for B20608 & B30207 memos re imposition of civil penalties for matl false statements to be placed in PDR Forwards similar, partially deleted B20608 memo Memo dtd B30207 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records B3/10/26 BUCKLES, R NUS Corp 2pp 21834 233

--B401160370 Staff requirements memo re B20528 enforcement action conference concerning proposed Commission authorization to impose civil penalties for matl false statements Info deleted
CHILK, S J Office of the Secretary of the Commission B2/06/08
DIRCKS, W J Office of the Executive Director for Operations 1p
21834 235

B401170138 Transcript of Commission B40110 meeting in Washington, DC re discussion/possible vote on TMI steam generators Pp 1-15
* Commissioners B4/01/10 18pp 21838, 342 24X
Fiche 50-289, B4/01/10, B401170138

B401170474 Staff requirements memo re B40104 discussion of NRC enforcement policy in Washington, DC Commission agreed to submit votes & comments on proposed statement of policy & procedures during wk of B40109
CHILK, S J Office of the Secretary of the Commission MB40104
B4/01/09 DIRCKS, W J Office of the Executive Director for Operations 2pp 21844 290

B401170479 Staff requirements memo re B40106 discussion & possible vote in Washington, DC on equipment qualification policy statement & proposed rule & NRC response to Court of Appeals decision
HOYLE, J C Office of the Secretary of the Commission MB40106
B4/01/10 DIRCKS, W J Office of the Executive Director for Operations 1p 21844 289

B401190175 Transcript of Commission B40112 briefing in Washington, DC re BWR pipe replacements Pp 1-81 Supporting documentation encl.
* Commissioners B4/01/12 93pp 21861 209

B401230053 Transcript of Commission B40111 meeting in Washington, DC for oral presentations on "NRC Concurrence or Nonconcurrence in DDE Waste Repository Siting Guidelines " Pp 1-244 Supporting documentation encl
* Commissioners B4/01/11 766pp 21928, 225

B401260004 Transcript of B40112 affirmation/discussion & vote re request for stay of fuel loading at Diablo Canyon & 10CFR1 in Washington, DC, Pp 1-3, Supporting documentation encl.
* Commissioners B4/01/12 7pp 21989 351, 24X
Fiche: 50-275, B4/01/12, B401260004

B401260496 Transcript of Commission B40116 meeting in Washington, DC re corrosion in PDRVs at TMI-1 Pp 1-16 Viewgraphs encl
* Commissioners B4/01/16 22pp 21939 224 24X
Fiche 50-289, B4/01/16, B401260496

B401270523 Transcript of Commission B40119 affirmation/discussion & vote in Washington, DC re SECY-83-452 on regionalization Pp 1-2
* Commissioners B4/01/19 22pp, 22002 148

B401300116 Staff requirements memo re B40110 discussion/possible vote on TMI steam generators License amend will not be issued until Commission votes on NSHC question
CHILK, S J Office of the Secretary of the Commission MB40110B
B4/01/16 DIRCKS, W J Office of the Executive Director for Operations 1p 22006, 162 24X Fiche: 50-289, B4/01/16, B401300116

B401310100 Staff requirements memo re B40119 affirmation/discussion & vote Policy statement on regionalization should be revised as indicated & forwarded to Opc of FR for publication Public announcement should be issued & Congress notified
CHILK, S J Office of the Secretary of the Commission MB40119.
B4/01/19 DIRCKS, W J Office of the Executive Director for Operations FOUCHARD, J J Office of Public Affairs KAMMERER, C Office of Congressional Affairs 17pp, 22028 263

B401310102 Staff requirements memo re B40112 briefing on proposed procedural guidance for pipe replacement at BWRs Commission agreed to review revised guidance package
CHILK, S J Office of the Secretary of the Commission MB40112A
B4/01/20 Office of the Secretary of the Commission 1p
22028-262

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

B310310465 Summarizes ACRS 282nd meeting on B31013-15 on NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 re PWR steam generators. Proposals should be implemented as recommendations only.
RAY, J J ACRS - Advisory Committee on Reactor Safeguards, B3/10/18
PALLADINO, N J Commissioners 26pp 21855 019

--B31010265 Forwards for review, draft program rept to be designated NUREG-0844, "NRC Integrated Program for Resolution of Unresolved Safety Issues A-3, A-4 & A-5 re Steam Generator Tube Integrity"
ETSENHUT, D O Division of Licensing, B3/09/29 FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards 300pp 21855 045

--B308190529 "Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events." final rept
MOREHOUSE, J H Science Applications, Inc. NRC-83-82-131
B3/02/02 Division of Licensing 325pp 21856 057

--B401180028 "Prioritization of Steam Generator Generic Requirements Concerning Tube Degradation & Rupture Events "
* Division of Safety Technology, B3/10/18 49pp 21857 019

--B308190537 "Prioritization of Staff Actions "
RIGGS, R, Division of Safety Technology B3/02/14 44pp, 21857, 069

--B401180035 NP-2704-SR
"PWR Secondary Water Chemistry Guidelines."
BELL, M J, BLOMGREN, J C., FACKELMANN, J M Steam Generator Owners Group B2/10/31 92pp 21857 113

B401060560 Summarizes ACRS 284th meeting on B31215-16 re draft reg guides, Task OP 713-4, "Applications of Bioassay for Tritium" & OP 032-5, "Radiation Protection Instrumentation Test & Calibr for Reactor Licensees."
RAY, J J ACRS - Advisory Committee on Reactor Safeguards B3/12/20, DIRCKS, W J Office of the Executive Director for Operations, 3pp, 21794 159.

NONDOCKETED ITEMS

B401090082 Transcript of ACRS Subcommittee on Shearon Harris Nuclear Plant B40104 meeting in Apex, NC Pp 190-356
 * ACRS - Advisory Committee on Reactor Safeguards 83/01/04
 167pp 21749 001 24X Fiche 50-400, B4/01/04, B401090082

B401090234 Transcript of ACRS Subcommittee on Shearon Harris B40103 meeting in Apex, NC Pp 1-189 Supporting documentation encl.
 * ACRS - Advisory Committee on Reactor Safeguards 84/01/03
 375pp 21749 226 24X Fiche 50-400, B4/01/03, B401090234

B40110456 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re proposed addition of human factors criterion to 10CFR50.
 App A
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/12/19
 PALLADINO, N. J. Commissioners 1p. 21790-351

B40110460 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re training & qualification of nuclear power plant personnel
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/12/19
 PALLADINO, N. J. Commissioners 1p 21790-350

B40110464 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re NRC requirements for reinsp of BWR piping & repair of cracked piping
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/12/19
 PALLADINO, N. J. Commissioners 2pp. 21790-347.

B40110473 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re DOE general guidelines for recommendation of sites for nuclear waste repositories (10CFR960)
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/12/20
 DIRCKS, W. J. Office of the Executive Director for Operations 3pp
 21795-353

B40110493 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re Rev 1 to proposed Reg Guide 1.89, Task EE 042-2 on environ qualification of electrical equipment important to safety for nuclear power plants.
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/12/19
 PALLADINO, N. J. Commissioners 2pp. 21790-345

B40110499 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re proposed rev to stds for protection against radiation, per 10CFR20
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/12/20.
 PALLADINO, N. J. Commissioners 2pp. 21790-343.

B40110572 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re decentralization of NRC regulatory activities
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/12/20
 PALLADINO, N. J. Commissioners 2pp 21790-360.

B401120187 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re working paper of draft reg guide to assure availability of funds for decommissioning nuclear reactors
 RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/12/20
 DIRCKS, W. J. Office of the Executive Director for Operations. 2pp
 21804-351

B401130104 Summary of ACRS Subcommittee on Extreme External Phenomena B20128-29 meetings in Reston, VA re exam of uncertainties associated w/determination of DBE for nuclear power plants in eastern USA & need for research
 * ACRS - Advisory Committee on Reactor Safeguards. 82/06/12
 ACRS - Advisory Committee on Reactor Safeguards 22pp 21821-100.

01130114 Summary of ACRS Human Factors Subcommittee B30819 meeting w/NRC, B&W, BGE, Sandia Natl Lab, S&W, Taylor & Waddinghouse in Washington, DC re emergency procedures guidelines
 * ACRS - Advisory Committee on Reactor Safeguards. 83/09/14
 ACRS - Advisory Committee on Reactor Safeguards 24pp 21821-016

01130116 Summary of ACRS Subcommittee on Metal Components B30817 meeting w/EPRI, BWR Owners Group, GE & NUTECH in Washington, DC re results of industry round robin on ultrasonic test crack depth determination & implications.
 * ACRS - Advisory Committee on Reactor Safeguards 83/10/14
 CRB - Advisory Committee on Reactor Safeguards. 11pp 21820-341.

1130118 Summary of ACRS Human Factors Subcommittee B30803 meeting /NRC, Westinghouse, Gessner Assoc, EEI, WMC, Inc & Nuclear Safety Analysis Ctr in Washington, DC re fitness for duty rule (10CFR50.54).
 * ACRS - Advisory Committee on Reactor Safeguards. 83/09/30
 CRB - Advisory Committee on Reactor Safeguards. 12pp 21820-327.

B401130121 Summary of ACRS Subcommittee on Regulatory Activities B30104 meeting w/NRC in Washington, DC re Rev 3 to Reg Guide 1.97.
 "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environ Conditions"
 * ACRS - Advisory Committee on Reactor Safeguards 83/02/07
 ACRS - Advisory Committee on Reactor Safeguards Bpp 21820-277

B401130127 Summary of ACRS Reliability & Probabilistic Assessment Subcommittee B21103 meeting w/NRR & BNL re NRC schedule & plan to review Indian Point probabilistic safety study & Limerick PRA Viewgraphs encl
 * ACRS - Advisory Committee on Reactor Safeguards 82/12/06
 ACRS - Advisory Committee on Reactor Safeguards 38pp 21820-237
 24X Fiche 50-000, B2/12/06, B401130127

B401130307 Transcript of ACRS Subcommittee on Class 9 Accidents B40111 meeting in Washington, DC Pp 1-214 Supporting documentation encl
 * ACRS - Advisory Committee on Reactor Safeguards 84/01/11
 376pp 21797-001

B401130361 Summary of ACRS Sequoyah Subcommittee B21207 meeting w/TVA, NRR & REB re proposed hydrogen control sys
 * ACRS - Advisory Committee on Reactor Safeguards 83/01/17
 ACRS - Advisory Committee on Reactor Safeguards 19pp 21817-303
 24X Fiche 50-327, B3/01/17, B401130361

B401160149 Transcript of ACRS 285th general meeting on B40112 in Washington, DC Pp 1-260 Supporting documentation encl
 * ACRS - Advisory Committee on Reactor Safeguards 84/01/12
 346pp 21809-001 24X Fiche 50-400, B4/01/12, B401160149

B401160369 Summary of ACRS Subcommittee on Human Factors B30830 meeting in Washington, DC re proposed rulemaking for operator licensing & safety personnel training & qualifications
 * ACRS - Advisory Committee on Reactor Safeguards 83/09/20
 ACRS - Advisory Committee on Reactor Safeguards 22pp 21824-248

B401160376 Summary of ACRS Air Sys Subcommittee B30923 meeting in Washington, DC re review of QESBAR II design relative to control room habitability & overview of GE BWR suppression pool scrubbing program
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/09.
 ACRS - Advisory Committee on Reactor Safeguards 16pp 21824-232
 24X Fiche 50-447, B3/11/09, B401160376

B401160386 Summary of ACRS Subcommittee on DHR B31004 meeting w/C-E in Washington, DC re evaluations performed by NRC & C-E concerning rapid depressurization & DHR capability of C-E plants w/o PORV
 * ACRS - Advisory Committee on Reactor Safeguards 83/12/07
 ACRS - Advisory Committee on Reactor Safeguards 17pp. 21823-339

B401160392 Summary of ACRS Subcommittee on St Lucie 2 B11030-31 meetings in West Palm Beach, FL re review of DL application
 * ACRS - Advisory Committee on Reactor Safeguards 81/12/16
 ACRS - Advisory Committee on Reactor Safeguards 20pp 21823-317
 24X Fiche 50-389, B1/12/16, B401160392

B401160399 Summary of ACRS Subcommittee on Limerick Generating Station B31007-08 meetings w/util in Pottstown, PA re review of DL application
 * ACRS - Advisory Committee on Reactor Safeguards 84/01/11
 ACRS - Advisory Committee on Reactor Safeguards. 31pp 21823-286
 24X Fiche 50-352, B4/01/11, B401160399

B401160408 Summary of ACRS Subcommittee on BEP B30920-21 meetings w/util in Traverse City, MI re review of integrated plant safety assessment for facility
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/17
 ACRS - Advisory Committee on Reactor Safeguards 22pp 21823-264
 24X Fiche 50-155, B3/11/17, B401160408

B401160411 Summary of ACRS 280th meeting on B30804-06 in Washington, DC re radiological effects & site evaluation repts, BWR pipe cracking & proposed rules Agenda encl
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/04
 ACRS - Advisory Committee on Reactor Safeguards. 226pp 21835-060

B401160417 Summary of ACRS Procedures Subcommittee B31012 meeting in Washington, DC re implementation of Federal Advisory Committee rev to 41CFR101-106, review of ACRS procedures, reappointment of ACRS members & ACRS Fellowship program
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/15.
 ACRS - Advisory Committee on Reactor Safeguards 34pp 21821-220

B401160422 Summary of ACRS Subcommittee on Metal Components & DHR B31012 combined meeting in Washington, DC re review of NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 concerning PWR steam generators.
 * ACRS - Advisory Committee on Reactor Safeguards 83/11/10
 ACRS - Advisory Committee on Reactor Safeguards 19pp 21821-273.

NONDOCKETED ITEMS

403

B401170136 Summary of ACRS Fire Protection Subcommittee B30923 meeting in Washington, DC re review of current status of fire protection sys & incidents where actuation of fire protection sys affected safety sys
* ACRS - Advisory Committee on Reactor Safeguards 83/11/01
ACRS - Advisory Committee on Reactor Safeguards 23pp 21836 322

B401170533 Summary of ACRS Ad Hoc Subcommittee on DHR Sys B10908 meeting in Washington, DC re DHR requirements
* ACRS - Advisory Committee on Reactor Safeguards 81/10/08
ACRS - Advisory Committee on Reactor Safeguards 13pp 21847 059

B401170541 Summary of ACRS Subcommittees on Electrical Sys & Qualification Program for Safety-Related Equipment B20701 combined meeting in Washington, DC re FYB2 RES programs, expected FYB3 & proposed FYB4 & B5 budgets
* ACRS - Advisory Committee on Reactor Safeguards 82/08/31
ACRS - Advisory Committee on Reactor Safeguards 38pp 21847 018

B401170544 Summary of ACRS Subcommittee on Reactor Radiological Effects B30922 meeting in Washington, DC re review of proposed rev to 10CFR20 (std for protection against radiation) & DOE dose reduction working group final rept
* ACRS - Advisory Committee on Reactor Safeguards 83/11/04
ACRS - Advisory Committee on Reactor Safeguards 17pp. 21847.001

B401170551 Summary of ACRS Subcommittee on Class 9 Accidents B30823 meeting in Washington, DC re list of regulatory issues for severe accident research plan Attendance list encl
* ACRS - Advisory Committee on Reactor Safeguards 83/09/15
ACRS - Advisory Committee on Reactor Safeguards 16pp. 21844 327

B401170558 Summary of ACRS Subcommittee on Extreme External Phenomena B20707 meeting in Washington, DC re review of RES proposals for FYB4-B5 budget & long-range research plan in area of extreme external events
* ACRS - Advisory Committee on Reactor Safeguards 82/08/10
ACRS - Advisory Committee on Reactor Safeguards 12pp 21844.305

B401170559 Summary of ACRS Subcommittee on SEP B31107 meeting w/util in Washington, DC re SEP integrated assessment rept for facility (NUREG-0828)
* ACRS - Advisory Committee on Reactor Safeguards 83/12/16
ACRS - Advisory Committee on Reactor Safeguards 13pp 21844 292
24X Fiche 50-155, 83/12/16, B401170559

B401200087 Transcript of 285th ACRS general meeting on B40113 in Washington, DC Pp 261-424 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/13
232pp 21863 001

B401230088 Transcript of ACRS Subcommittee on Diablo Canyon B40119 hearing in Los Angeles, CA Pp 1-245 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/19
288pp 21935 246 24X Fiche 50-275, 84/01/19, B401230088.

B401240368 Transcript of ACRS Subcommittee on Reactor Radiological Effects B40123 meeting in Washington, DC Pp 1-247. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 84/01/23.
413pp 21934.048

B401310269 Transcript of ACRS Subcommittee on Class 9 Accidents B40127 meeting in Washington, DC Pp 1-217. Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 84/01/27
275pp 22013 001.

B401310273 Transcript of ACRS Subcommittee on Reactor Radiological Effects B40124 meeting in Washington, DC, Pp 246-406 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 84/01/24
187pp. 22012 069

B401310510 Submits comments on Class 9 accidents & possible recommendations
SEALE, R L. Arizona, Univ of, Tucson, AZ. SEALE, R.L. ACRS - Advisory Committee on Reactor Safeguards. 80/05/28. KERR, W. ACRS - Advisory Committee on Reactor Safeguards. 4pp 22036.356.

B401310512 Submits observations on particular concerns raised in ACRS Subcommittee on Class 9 Accidents B01121 meeting
SCHOTT, G.L. Los Alamos Scientific Laboratory. SCHOTT, G L. ACRS - Advisory Committee on Reactor Safeguards 80/12/05. KERR, W. ACRS - Advisory Committee on Reactor Safeguards. 3pp 22036 360.

B401310513 Submits observations & opinions re hydrogen control in ice condenser containment of Sequoyah reactor, based on evaluation of info gathered
SCHOTT, G L. Los Alamos Scientific Laboratory. SCHOTT, G L. ACRS - Advisory Committee on Reactor Safeguards. 81/05/07. MARK, J C. ACRS - Advisory Committee on Reactor Safeguards 7pp 22036.345 24X Fiche 50-327, 81/05/07, B401310513

ADVCM NRC ADVISORY COMMITTEE

B401310163 Transcript of B31208 hearing in Harrisburg, PA re decontamination of TMI-2 Pp 1-91 Supporting documentation encl
* Advisory Council for Decontamination of TMI Unit 2 83/12/08
150pp 22034 181 24X Fiche 50-320, 83/12/08, B401310163

COMMISSION NRC COMMISSIONERS

B401040008 Weekly info rept for wk ending B31216
REHM, T A Office of the Executive Director for Operations
83/12/22 43pp. 21711 263

B401050001 Weekly info rept for wk ending B31223
REHM, T A Office of the Executive Director for Operations
83/12/30 29pp 21736 144

B401090616 Package of 48 ltrs requesting comments re V Olinisky ltr conveying views concerning use of highly enriched U fuel at univ research reactors Subj will be addressed at B31219 public meeting
PALLADINO, N J Commissioners 83/12/02 KENNEDY, R T State, Dept of BREWER, S T Energy, Dept of WANG, C Oregon State Univ, Corvallis, OR. 48pp 21766:169.

B401100126 Responds to B31101 ltr expressing concerns re NRC efforts to pursue allegations of safety-related deficiencies at nuclear const sites Use of confidentiality formally incorporated into Opc of investigations procedures
PALLADINO, N J Commissioners 84/01/09 UDALL, M K. House of Rep, Interior & Insular Affairs 5pp 21761.067 24X Fiche 50-413, 84/01/09, B401100126

--B401100133 Expresses concern re Commission effort to pursue allegations of safety-related deficiencies at nuclear const sites Advisory Committee for Review of Investigation Policy . rept failed to address grant of confidentiality
UDALL, M K. House of Rep., Interior & Insular Affairs 83/11/01, PALLADINO, N J Commissioners 2pp. 21761.072. 24X Fiche. 50-413, 84/01/09, B401100136

B40110244 Forwards response to B30929 request for answers to questions re util review of draft IE rept re Unit 2 accident (NUREG-0600).
PALLADINO, N J Commissioners. 83/12/09. UDALL, M K. House of Rep., Interior & Insular Affairs. 5pp. 21775.028 24X Fiche 50-320, 83/12/09, B40110244.

--B40110247 Forwards "Rept on Comparison of NUREG-0600 to 790715 Draft" for review. All changes to rept proper & no impropriety associated w/release of rept Investigation Unwarranted
STELLO, V Regional Operations & Generic Requirements. 83/09/16 PALLADINO, N J Commissioners. 11pp. 21795 033 24X Fiche 50-320, 83/12/09, B40110244

--B40110250 Forwards draft IE investigation rept re 790328 accident. Review for proprietary info requested
GRIER, B.H. Region 1, Office of Director 79/07/16. ARNOLD, R C. Metropolitan Edison Co 2pp 21795 044. 24X Fiche 50-320, 83/12/09, B40110244.

--B40110255 Advises that IE investigation rept re nuclear accident on 790328-30 contains no proprietary info
STELLO, V Office of Inspection & Enforcement, Office of the Director. 79/08/01. HERBER, J.G. Metropolitan Edison Co. 1p 21795:046 24X Fiche. 50-320, 83/12/09, B40110244.

--B40110258 Ack receipt of V Stello B30916 memo re release of NUREG-0600 in draft form No further internal inquiry required
PALLADINO, N.J. Commissioners. 83/10/04. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 21795.047. 24X Fiche: 50-320, 83/12/09, B40110244.

--B40110264 Questions why draft IE rept re accident (NUREG-0600) sent to util for comments
PALLADINO, N.J. Commissioners. 83/09/29 UDALL, M.K. House of Rep, Interior & Insular Affairs 2pp. 21795.048 24X Fiche 50-320, 83/12/09, B40110244.

NONDOCKETED ITEMS

- 840110325 Forwards rept "Price-Anderson Act--Third Decade," containing exam of nuclear industry condition, nuclear safety state of knowledge & availability of private insurance. W/o encl
PALLADINO, N. J. Commissioners 83/12/16 O'NEILL, T. P. House of Rep., Speaker of the House 1p 21795 013
- 840110326 Forwards rept "Price-Anderson Act--Third Decade" containing exam of nuclear industry condition, nuclear safety state of knowledge & availability of private insurance. W/o encl
PALLADINO, N. J. Commissioners 83/12/16 BUSH, G. Senate, President of the Senate 1p 21795 014.
- 840110327 Declines invitation to participate in restart hearing Meeting to be held on 840110 will evaluate alternatives for addressing mgt integrity, not reach decision re restart
PALLADINO, N. J. Commissioners. 83/12/15 SPECTER, A. Senate 2pp 21795.008 24X Fiche 50-289, 83/12/08, 840110327
- 840110328 Requests delay in administrative proceedings re Unit 1 operation until conclusion of util criminal misconduct trial Schedule conflict re witness testimony at both proceedings possible
JENSEN, D. L. Justice, Dept. of. 83/12/14. PALLADINO, N. J. Commissioners. 2pp. 21795:010 24X Fiche 50-289, 83/12/08, 840110327
- 840110329 Extends invitation to attend & participate in 831216 hearing in Harrisburg, PA re Unit 1 restart
SPECTOR, A. Senate 83/12/09. PALLADINO, N. Commissioners. 1p 21795 012. 24X Fiche 50-289, 83/12/08, 840110327.
- 840110331 Responds to 831114 proposal for agreement between NRC & State of UT re state assumption of regulatory authority over certain sources of ionizing radiation. Assessment to be published in FR & acted on after 30-day comment period
PALLADINO, N. J. Commissioners 83/12/08 MATHESON, S. M. Utah, State of 1p. 21795-140
- 840110333 Requests agreement between NRC & State of UT under which NRC will discontinue & State of UT will assume regulatory authority over radioisotopes, source U & thorium matl & BNM insufficient to form critical mass
MATHESON, S. M. Utah, State of 83/11/14. PALLADINO, N. J. Commissioners 2pp. 21795-141.
- 840110474 Submits NRC response to GPU 830610 mgt organization proposal & changes to proposal as of 831128. Proposal viable alternative to waiting for completion of ongoing OFC of Investigations inquiry
DIRCKB, W. J. Office of the Executive Director for Operations 84/01/03 PALLADINO, N. J., GILINSKY, V., ROBERTS, T. Commissioners. 19pp. 21817:336 24X Fiche 50-289, 84/01/03, 840110474
- 8401190493 Responds to 830928 ltr posing questions re apparently improper release of draft documents to applicant by NRC inspector
PALLADINO, N. J. Commissioners 83/12/21 HEAVER, J. House of Rep., Interior & Insular Affairs 72pp. 21857:207. 24X Fiche 50-397, 83/12/21, 8401190493
- 840119047 Requests response to questions re apparently improper release of draft documents to applicant by NRC inspector Documentation on QA/QC, design deficiencies & mgt problems also requested.
HEAVER, J. House of Rep., Interior & Insular Affairs. 83/09/28. PALLADINO, N. J. Commissioners. 2pp. 21857 335 24X Fiche 50-397, 83/12/21, 8401190493
- 8401200054 Forwards response to 831026 ltr re NRC employees who were recipients of 1983 senior executive svc rank & bonus awards.
PALLADINO, N. J. Commissioners. 83/12/21. MARKEY, E. J. House of Rep., Interior & Insular Affairs. 24pp. 21871:289.
- 8401200057 Requests response to questions re process NRC uses to determine recipients of senior executive svc rank & bonus awards.
MARKEY, E. J. House of Rep., Interior & Insular Affairs. 83/10/26. PALLADINO, N. J. Commissioners. 2pp. 21871.313.
- 8401200209 Notifies that BC has been added to list of participants in 84011 public meeting on DOE general guidelines for recommendation of sites for nuclear waste repositories.
PALLADINO, N. J. Commissioners. 84/01/04. RILEY, R. W. South Carolina, State of. 1p. 21871:242.
- 8401200210 Responds to 831214 & 30 requests to participate in Commission 84011 public meeting on NRC concurrence in DOE siting guidelines for high level repositories Participation limited. Request denied.
CHILK, B. J. Office of the Secretary of the Commission. 84/01/04. PENBERTHY, L. Penberthy Electromelt International, Inc. 1p. 21871:245.
- 8401200212 Confirms request to participate in 84011 hearing on DOE guidelines
PENBERTHY, L. Penberthy Electromelt International, Inc. 83/12/30 CHILK, B. J. Office of the Secretary of the Commission 1p 21871:247
- 8401200214 Notifies that State of WA has been added to list of participants in 84011 public meeting on DOE general guidelines for recommendation of sites for nuclear waste repositories
CHILK, B. J. Office of the Secretary of the Commission 84/01/04 ROE, C. B. Olympia, WA 1p 21871:248
- 8401200216 Submits NRC response to recommendation made in QAO rept. "NRC Needs Alternative to Mandatory Relocation for Maintaining Objectivity of Resident Inspectors" Commission concurs in recommendation
PALLADINO, N. J. Commissioners 83/12/30 BROOKS, J. House of Rep., Government Operations ROTH, W. V. Senate, Governmental Affairs STOCKMAN, D. A. Office of Management & Budget 4pp 21871:253
- 8401200218 Ack receipt of response to 831104 ltr addressing concern for assuring highest stds on nuclear safety
DELBELLO, A. B. New York, State of 83/11/28. PALLADINO, N. Commissioners 2pp 21871:258
- 8401200220 Forwards addl info on how evaluation of sys of internal accounting & administrative control of NRC during yr ending 831231 was conducted.
PALLADINO, N. Commissioners 83/12/30 President of U. B. & Executive Offices O'NEILL, T. P. House of Rep., Speaker of the House BUSH, G. H. Senate, President of the Senate 14pp. 21871:260
- 8401230001 Further response to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests App A info partially withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records 83/11/07 VOIGT, H. H. LeBoeuf, Lamb, Leiby & MacRae 3pp 21930.322 24X Fiche 50-289, 83/11/07, 8401230001
- 8401230008 Summary of recent meeting w/DOJ officials re differences concerning question of whether DOJ had lifted request to stop NRC investigation of Hartman allegations
PLAINE, H. H. Office of the General Counsel 83/08/30 PALLADINO, N. J. Commissioners 1p 21930 332
- 8401230011 Requests explanation of conflict between NJ Palladino 830325 testimony & DL Jensen 830517 ltr re NRC investigation into allegations that leak rate calculations at TMI-2 improperly conducted prior to accident
UDALL, M. K. House of Rep., Interior & Insular Affairs. 83/05/23 PALLADINO, N. J. Commissioners. 1p. 21930 333
- 8401230015 Requests investigation of Hartman allegations of leak rate falsification at TMI-2, per DL Jensen 830517 ltr indicating no bar to NRC proceeding w/independent investigations.
PALLADINO, N. J. Commissioners 83/11/07 HAYES, B. Office of Investigation 1p 21930.334 24X Fiche 50-320, 83/11/07, 8401230001
- 8401230019 Requests opinion by 830523 re factual assertions contained in third paragraph of Assistant Atty General DL Jensen 830517 ltr to Commission W/o stated encl
GILINSKY, V. Commissioners 83/05/19 CUMMINGS, J. J. Office of Inspector & Auditor. 1p 21930 335
- 8401230026 Responds to 830523 request for explanation of conflict between NJ Palladino 830325 testimony & DL Jensen 830517 ltr re propriety of NRC investigation into allegations that leak rate calculations at TMI-2 improperly conducted
PALLADINO, N. J. Commissioners. 83/07/14 UDALL, M. K. House of Rep., Interior & Insular Affairs 3pp. 21930 337
- 8401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents, App A & B documents available in PDR. App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records. 83/11/02 O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge. 6pp 21937:357. 24X Fiche 50-000, 83/11/02, 8401250163
- 8202120297 Discusses SECY-BI-509 & NUREG-0696 re criteria for emergency operations facilities. Recommends Commission approve NRC request to accept close in hardened emergency operations facilities.
REMICK, F. J. NRC - No Detailed Affiliation Given 81/08/08. PALLADINO, N. J. Commissioners. 2pp. 21958:316

NONDOCKETED ITEMS

405

--B401250182 Requests reply to questions on Page 2 of B211B memo to Commissioners re emergency operations facilities (SECY-B2-111)
QILINSKY, V. Commissioners 82/11/19 DIRCKS, W J Office of the Executive Director for Operations 1p 2195B 003

--B401250185 Discusses how SECY-B2-111 unravels NRC emergency preparedness requirements, per author B21103 memo Table III.A 1 2-2 not changed in any way by SECY-B2-111 Responses to listed questions requested
QILINSKY, V. Commissioners 82/11/18 Commissioners 2pp 2195B 004 24X Fiche 50-000, 83/11/02, B401250163

--B401250188 Agrees w/801120 memo recommending options for utils. per TMI Action Item III A.1 2, "Emergency Operation Facilities" Proposes that under Option 4, facility should be beyond 10 miles
QILINSKY, V. Commissioners. COMJA-80-35 80/12/04 AHEARNE, J. Commissioners 1p 2195B 014

--B401250192 Notifies that emergency operations facility for plant paper (SECY-B3-199) before Commission As negative consent paper. Agrees w/NRC disapproval of licensee proposal
ASSELSTINE, J K Commissioners 83/04/07 CHILK, B J Office of the Secretary of the Commission 1p 2195B 015. 24X Fiche. 50-000, 83/11/02, B401250163

--B401250248 Forwards B10121 memo to WJ Dirck, requesting completion of SECY action on COMJA-80-37
CHILK, S. J. Office of the Secretary of the Commission COMJA-80-37 81/01/21 AHEARNE, J., QILINSKY, V., HENDRIE, J. Commissioners 1p. 2195B 312

B401310168 Forwards rept addressing issues raised in B31101 ltr re NRC handling of drafts of GA case studies, in particular Diablo Canyon. Commission has concluded no further investigation necessary.
PALLADINO, N J Commissioners 84/01/09 MARKEY, E J. House of Rep , Interior & Insular Affairs 1p 22032 001 24X Fiche: 50-275, 84/01/09, B401310168

--B401310169 "Rept on Review of Issues Raised by Congressman Markey Ltr of B31101"
DIRCKS, W J Office of the Executive Director for Operations 84/01/09 200pp 22032 002 24X Fiche 50-275, 84/01/09, B401310168.

--B401310172 Raises concerns re NRC handling of drafts of GA case studies
MARKEY, E. J. House of Rep , Interior & Insular Affairs. 83/11/01 PALLADINO, N. J. Commissioners 13pp 22032:281 24X Fiche 50-275, 84/01/09, B401310168

B401310175 Comments on proposed amends to Clean Air Act. Proposed amends do not affect NRC regulatory program in any significant respects Further study of radon should be considered.
PALLADINO, N J Commissioners 84/01/09 PETERSON, R. K. Office of Management & Budget 2pp 22035, 235

--B401310177 Requests comments on amends to encl Clean Air Act. Comments required by B31128.
PETERSON, R K Office of Management & Budget. 83/10/24. Commissioners 115pp 22035 237

CONTRACT NRC CONTRACTS AND MODIFICATIONS

B401030079 Notification of contract execution, Mod 4 to "Lease of Vehicles." Contractor We Try Harder, Inc
BROMBERG, B. J. Administrative Contracts Branch. FIN B-8153. NRC-10-82-377 83/12/14. CORLEY, J. Division of Facilities & Operations GRANT L. NRC - No Detailed Affiliation Given. 1p 21695 254

--B401030088 Mod 4, incorporating provisions for electronic transfer of funds, to "Lease of Vehicles."
* We Try Harder, Inc. HAGAN, T.F. Division of Contracts. FIN B-8153. NRC-10-82-377. 83/12/14 2pp. 21695 255.

B401030299 Notification of contract execution, Mod 22 to "Local ECCS Support Studies." Contractor MPR Assoc, Inc
JACOBBS, A. Administrative Contracts Branch. FIN B-5537. NRC-04-75-183 83/12/08 BATSON, W. Office of Nuclear Regulatory Research, Director. RHEE, Q. NRC - No Detailed Affiliation Given 1p. 21693 315.

--B401030310 Mod 22, adding incremental funding action, to "Local ECCS Support Studies"
KANDIL, I H MPR Associates, Inc. GUSTAVE, R. P. Division of Contracts. FIN B-5537. NRC-04-75-183 83/12/08. 3pp. 21693 316.

B401030329 Notification of contract execution, Mod 4 to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities." Contractor, NUSAC, Inc
JACOBBS, A. Administrative Contracts Branch. FIN B-7379-4. NRC-02-83-027 83/12/09 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. MILLER, M. NRC - No Detailed Affiliation Given 1p 21685 254

--B401030345 Mod 4, adding incremental funding action, to "Evaluation of Matl Accounting Performances of Nuclear Fuel Cycle Facilities"
LUMB, R F. NUSAC, Inc. GUSTAVE, R P. Division of Contracts. FIN B-7379-4. NRC-02-83-027 83/12/09 1p 21685 255

B401030361 Notification of contract execution, Mod 2 to "Preventive, Remedial & On-Call Maint on Data General MV/6000 & VM/6000 Computers & Peripheral Equipment." Contractor Data Consultants, Inc
PERLMAN, J. Administrative Contracts Branch. NRC-33-83-457 83/12/14 BASSETT, H S. Division of Data Automation & Management Information JOHNBDON, C. NRC - No Detailed Affiliation Given 1p 21687 361.

--B401030369 Mod 2, incorporating provision for electronic transfer of funds, to "Preventive, Remedial & On-Call Maint on Data General MV/6000 & VM/6000 Computers & Peripheral Equipment"
* Data Consultants, Inc. HAGAN, T.F. Division of Contracts. NRC-33-83-457. 83/12/14 2pp 21687 362

B401030375 Notification of contract execution, Mod 10 to "Document Registration, Announcement, Marketing & Purchases" Contractor, NTIS.
PERLMAN, J. Administrative Contracts Branch. NRC-10-75-106 83/12/19 DORIE, W. Office of Administration. ZUNGOLI, B., SKOCZLAB, J. Division of Technical Information & Document Control. 1p. 21695, 338

--B401030379 Mod 10, replacing technical representative, to "Document Registration, Announcement, Marketing & Purchases"
* Commerce, Dept. of, National Technical Information Services. HAGAN, T.F. Division of Contracts NRC-10-75-106. 83/12/19 1p 21695 339

B401030382 Notification of contract execution, Mod 19 to "PDR Micrographic Storage & Retrieval Sys." Contractor: Access Corp
PERLMAN, J. Administrative Contracts Branch. NRC-17-79-449. 83/12/14. CHILK, B. J. Office of the Secretary of the Commission. SCATTOLINI, L. Public Document Branch 1p. 21695:335

--B401030389 Mod 19, incorporating provisions for electronic transfer of funds, to "PDR Micrographic Storage & Retrieval Sys."
* Access Corp. HAGAN, T.F. Division of Contracts. NRC-17-79-449. 83/12/14 2pp. 21695 336

B401040041 Notification of contract execution, Mod 5 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals." Contractor, Q Charnoff
TOWNSEND, B. Administrative Contracts Branch. FIN B-8179. NRC-18-82-481 83/12/19. NOTHSCHILD, T. Office of the General Counsel. 1p 21711:261

--B401040046 Mod 5, increasing monetary value for miscellaneous expenses, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals."
CHARNOFF, Q. Charnoff, Q. REBELLO, J.E. Division of Contracts FIN B-8179 NRC-18-82-481. 83/12/19. 1p. 21711:262.

B401050016 Notification of contract execution, Mod 4 to "Furnishing, Engineering, Installation & Maint of Complete Operational In-Svc Automatic Switching Sys/Equipment." Contractor American Telephone & Telegraph.
GILDENHORN, A. J. Administrative Contracts Branch. NRC-31-83-661. 83/12/14. COLLINS, J. Region 4, Office of Director. COHEN, S. NRC - No Detailed Affiliation Given. 1p 21736:175

--B401050020 Mod 4, incorporating provisions for electronic transfer of funds, to "Furnishing, Engineering, Installation & Maint of Complete Operational In-Svc Automatic Switching Sys/Equipment"
* American Telephone & Telegraph Co /American Bell. HAGAN, T.F. Division of Contracts NRC-31-83-661. 83/12/14 2pp 21736:176.

B401050074 Notification of contract execution, Mod 5 to "Page Make-Up Svcs." Contractor: Art Svcs & Publications, Inc.
PERLMAN, J. Administrative Contracts Branch. NRC-10-82-365. 83/12/14. DORIE, W. J. Division of Contracts. THOT-THOMPSON NRC - No Detailed Affiliation Given. 1p. 21736:315.

--B401050087 Mod 5, incorporating provisions for electronic transfer of funds, to "Page Make-Up Svcs."
* ASAP, Inc. HAGAN, T.F. Division of Contracts NRC-10-82-365. 83/12/14. 2pp. 21736:316.

NONDOCKETED ITEMS

8401090097 Notification of contract execution, Mod 1 to "Maint for IBM Mag Cards & Memory Typewriters " Contractor: Technical Specialties, Inc
 PERLMAN, J Administrative Contracts Branch NRC-33-83-459
 83/12/14 BASSETT, H B. Office of Resource Management, Director
 JOHNSON, C. NRC - No Detailed Affiliation Given ip 21736 251

--8401050105 Mod 1, incorporating provisions for electronic transfer of funds, to "Maint for IBM Mag Cards & Memory Typewriters "
 * Technical Specialties, Inc. HAGAN, T.F. Division of Contracts
 NRC-33-83-459. 83/12/14. 2pp 21736 252

8401050118 Notification of grant execution, Mod 2 to "Development of Recommendation for Periodic Surveillance of Response of Neutron Sensors Used in Nuclear Power Reactor Protection Sys " Grantee: Ohio State Univ Research Foundation
 UMBEL, D Technical Assistance Contracts Branch. FIN Q-1044
 NRC-Q-04-82-011 83/12/12 BATSON, W Office of Nuclear Regulatory Research, Director. HINTZE, A NRC - No Detailed Affiliation Given ip 21743 281.

--8401030131 Mod 2, extending grant period to 841030, to "Development of Recommendation for Periodic Surveillance of Response of Neutron Sensors Used in Nuclear Power Reactor Protection Sys."
 BUONO, R. S. Ohio State Univ., Columbus, OH. MORTON, K. V. Technical Assistance Contracts Branch. FIN Q-1044 NRC-Q-04-82-011. 83/12/12. ip. 21743. 282.

8401050144 Notification of grant execution, Mod 4 to "Geological Studies of Faults & Terraces of Central & Western Kentucky." Grantee: Univ of Kentucky Research Foundation
 UMREL, D. Technical Assistance Contracts Branch. FIN Q-1020
 NRC-Q-04-81-018 83/10/20. BATSON, W Office of Nuclear Regulatory Research, Director. O'DONNELL, E. NRC - No Detailed Affiliation Given. ip. 21743: 210.

-8401050153 Mod 4, extending grant period to 840930, to "Geological Studies of Faults & Terraces of Central & Western Kentucky." McDONALD, J. Y. Kentucky, Univ of, Lexington, KY MORTON, K. V. Technical Assistance Contracts Branch. FIN Q-1020
 NRC-Q-04-81-018 83/10/20. ip. 21743: 211

01060198 Notification of contract execution, Mod 3 to "Safety Aspects of Industrial Radiography Courses." Contractor Gamma Industries, Div of Nuclear Sys, Inc.
 QILDENHORN, A. J Administrative Contracts Branch. NRC-03-82-251
 83/12/28. BLAHA, J. L. Program Support Branch. HABELBERG, R. NRC - No Detailed Affiliation Given. ip. 21744: 176

-8401060201 Mod 3, changing key personnel, to "Safety Aspects of Industrial Radiography Courses."
 RIDDLE, D. H. Nuclear System. HAGAN, T. F. Division of Contracts
 NRC-03-82-251. 83/12/28 ip. 21744. 177.

8401060203 Notification of contract execution, Mod 8 to "Career Counseling." Contractor: Binder, Elster, Mendelson & Wheeler
 PERLMAN, J Administrative Contracts Branch. NRC-10-82-358
 3/12/14. DORIE, W. Division of Technical Information & Document Control. VAN SANTEN, L. Management Development & Training Staff. n. 21744. 173.

401060207 Mod 8, incorporating provisions for electronic transfer of funds, to "Career Counseling."
 * Binder, Elster, Mendelson & Wheeler, Inc HAGAN, T. F. Division of Contracts. NRC-10-82-358 83/12/14. 2pp 21744: 174

1060205 Notification of contract execution, Mod 2 to "Cost Analyses of Proposed Changes in NRC Requirements." Contractor Science & Engineering Assoc, Inc
 ILDENHORN, A. J. Administrative Contracts Branch. FIN B-8838.
 3-33-83-500 83/12/28 BARRY, L. J. Office of Resource Management, Director. FOWLER, O. NRC - No Detailed Affiliation Given. ip. 21744: 169.

1060222 Mod 2, increasing overhead rate, adding Fringe rates & correcting negotiation authority, to "Cost Analyses of Proposed Changes in NRC Requirements."
 JOBS, B. Science & Engineering Associates, Inc. HAGAN, T. F. Division of Contracts. FIN B-8838. NRC-33-83-500. 83/12/28 2pp. 21744: 170.

40215 Notification of contract execution, Mod 1 to "Automated Library Sys " Contractor: On-Line Computer Sys, Inc.
 BERQ, B. J Administrative Contracts Branch. NRC-33-83-454
 2/14. BASSETT, H. B. Office of Resource Management, Director
 QLI, S. NRC - No Detailed Affiliation Given. ip. 21744: 159.

1060223 Mod 1, incorporating provisions for electronic transfer of funds, to "Automated Library Sys."
 * On-Line Computer Systems, Inc. HAGAN, T. F. Division of Contracts. NRC-33-83-454. 83/12/14. 2pp. 21744: 160

8401060634 Notification of contract execution, Mod 3 to "NRC Issuances & Indexes " Contractor Herner & Co
 QILDENHORN, A. J Administrative Contracts Branch NRC-10-83-336
 83/12/14 BEBAW, W. LARKINS, P Division of Technical Information & Document Control ip 21753: 062

--8401060640 Mod 3, incorporating provisions for electronic transfer of funds, to "NRC Issuances & Indexes "
 * Herner & Co HAGAN, T. F. Division of Contracts NRC-10-83-336
 83/12/14 2pp 21753 063

8401060645 Notification of contract execution, Mod 5 to "Shuttle Bus Svc " Contractor Beltway Limousine Svcs, Inc
 BROMBERG, B J Administrative Contracts Branch NRC-10-82-378
 83/12/14 CORLEY, J Division of Facilities & Operations GRANT, L
 NRC - No Detailed Affiliation Given ip 21753 055

--8401060648 Mod 3, incorporating provisions for electronic transfer of funds, to "Shuttle Bus Svc "
 * Beltway Limousine Service, Inc HAGAN, T. F. Division of Contracts NRC-10-82-378 83/12/14 2pp 21753 056.

8401090454 Notification of contract execution, Mod 4 to "Keypunch & Verification Svcs " Contractor SBA Subcontractor Info Sys & Networks Corp
 BROMBERG, O Administrative Contracts Branch NRC-25-82-318.
 83/12/14 BASSETT, H Division of Data Automation & Management Information OLIVER, D NRC - No Detailed Affiliation Given ip 21767 359

--8401090459 Mod 4, incorporating provisions for electronic transfer of funds & changing project officer, to "Keypunch & Verification Svcs."
 * Small Business Administration * Information Systems & Network Corp. HAGAN, T. F. Division of Contracts NRC-25-82-318. 83/12/14 2pp 21767 360

8401090736 Notification of contract execution, Mod 14 to "Analytical Studies of Aerosol Behavior of Fast Reactors " Contractor: Battelle Columbus Labs
 PAGE, M Technical Assistance Contracts Branch. FIN A-4063
 NRC-04-76-293 83/12/22. BATSON, W Office of Nuclear Regulatory Research, Director LARKINS, S NRC - No Detailed Affiliation Given ip. 21757. 331

--8401090742 Mod 14, providing no cost extension to 840215, to "Analytical Studies of Aerosol Behavior of Fast Reactors "
 * Battelle Memorial Institute, Columbus Laboratories
 GUSTAVE, R P Division of Contracts. FIN A-4063 NRC-04-76-293
 83/12/22 ip 21757 332

8401090748 Notification of contract execution, Mod 30 to "Downcomer Effects Experimental Program " Contractor Creare, Inc
 WOLLETT, S Administrative Contracts Branch. FIN A-4070
 NRC-04-75-162 83/12/07 BATSON, W Office of Nuclear Regulatory Research, Director. REYES, J NRC - No Detailed Affiliation Given ip 21767 037

--8401090754 Mod 30, providing addl funding & extending period of performance to 840229, to "Downcomer Effects Experimental Program "
 HICKIN, R A Creare, Inc MORTON, K V Division of Contracts. FIN A-4070. NRC-04-75-162 83/12/07 3pp. 21767 038.

8401100042 Notification of contract execution, Mod 6 to "Statistical Review of Documents & Statistical Methods in Risk Assessment " Contractor: SBA Subcontractor, Automated Sciences Group, Inc
 BROMBERG, B J Administrative Contracts Branch. FIN B-6321
 NRC-07-79-312 83/12/14 HALLER, N. Office of Management and Program Analysis ABRAMSON, L NRC - No Detailed Affiliation Given ip. 21777 172

--8401100045 Mod 6, incorporating provisions for electronic transfer of funds, to "Statistical Review of Documents & Statistical Methods in Risk Assessment "
 * Small Business Administration * Automated Sciences Group, Inc. HAGAN, T. F. Division of Contracts. FIN B-1321
 NRC-07-79-312. 83/12/14. 2pp. 21777 173

8401100092 Notification of contract execution, Mod 1 to "Ultrasensitive Bioassay Measurements Using Sputter Initiated Resonance Ionization Spectroscopy " Contractor: Atom Sciences, Inc
 DELATCH, V Technical Assistance Contracts Branch. FIN B-1127.
 NRC-04-83-180 83/12/16 FOREHAND, W Office of Nuclear Regulatory Research, Director. NEEL, R. NRC - No Detailed Affiliation Given. ip. 21776 277

--8401100095 Mod 1, adding incremental funding, to "Ultrasensitive Bioassay Measurements Using Sputter Initiated Resonance Ionization Spectroscopy "
 * Atom Sciences, Inc. GUSTAVE, R Division of Contracts. FIN B-1127. NRC-04-83-180 83/12/16 ip. 21776 278

NONDOCKETED ITEMS

407

- 8401100110 Notification of contract execution, Mod 3 to "Svcs of Dr R Johnson to Render Adjudicatory Decisions on Licensing Procedures as Panel Member of ASLAB " Contractor Univ of Virginia
PERLMAN, J Administrative Contracts Branch NRC-10-82-424
83/12/14 ROSENTHAL, A Atomic Safety and Licensing Appeal Panel
83/12/14 21776 281
- 8401100114 Mod 3, incorporating provisions for electronic transfer of funds, to "Svcs of Dr R Johnson to Render Adjudicatory Decisions on Licensing Procedures as Panel Member of ASLAB "
* Virginia, Univ of, Charlottesville, VA HAQAN, T Division of Contracts NRC-10-82-424 83/12/14 2pp 21776 282
- 8401100119 Notification of contract execution, Mod 10 to "Card-Entry Access Control Sys " Contractor Vikonics, Inc
GILDENHORN, A Administrative Contracts Branch NRC-10-82-399
83/12/14. BRADY, R J Division of Security FINGER, R NRC - No Detailed Affiliation Given 1p 21768 350
- 8401100125 Mod 10, incorporating provisions for electronic transfer of funds, to "Card-Entry Access Control Sys "
* Vikonics, Inc HAQAN, T Division of Contracts NRC-10-82-399
83/12/14 2pp 21768 351
- 8401100121 Notification of contract execution, Mod 2 to "Panel Member & Documentation Review of NUREG Prior to . Review of Draft Rept on Radionuclide Release Under LWR Specific Accident Conditions " Contractor Univ of Virginia
TOWNSEND, B L Administrative Contracts Branch. FIN B-8985
NRC-04-83-010 83/12/30 BASSETT, O E Division of Accident Evaluation (Prs 840101) JANKOWSKI NRC - No Detailed Affiliation Given 1p 21776 279
- 8401100123 Mod 2, extending period of performance to 840201, to "Panel Member & Documentation Review of NUREG Prior to . Review of Draft Rept on Radionuclide Release Under LWR Specific Accident Conditions "
* REYNOLDS, A D Virginia, Univ of, Charlottesville, VA
REBELLO, J E Division of Contracts FIN B-8985 NRC-04-83-010
83/12/30 1p 21776 280
- 8401100135 Notification of contract execution, Mod 11 to "Operation & Maint of NRC Document Control Sys (DCS) " Contractor Planning Research Corp
BROMBERG, B J Administrative Contracts Branch NRC-10-82-356
83/12/14 NORRY, P Office of Administration LUNDY, J NRC - No Detailed Affiliation Given 1p. 21768 235
- 8401100138 Mod 11, incorporating provisions for electronic transfer of funds, to "Operation & Maint of NRC Document Control Sys (DCS) "
* Planning Research Corp HAQAN, T F. Division of Contracts
NRC-10-82-356 83/12/14 2pp. 21768 236
- 840110009 Notification of contract execution, Mod 3 to "Comprehensive Current (Real Time) Geophysical Data Storage & Retrieval Sys " Contractor WSI Corp
GILDENHORN, A Administrative Contracts Branch. NRC-33-83-456
83/12/14 BASSETT, H Office of Resource Management, Director.
JOHNSON, C NRC - No Detailed Affiliation Given 1p 21795:244.
- 840110011 Mod 3, incorporating provisions for electronic transfer of funds, to "Comprehensive Current (Real Time) Geophysical Data Storage & Retrieval Sys."
* WSI Corp. NRC-33-83-456 83/12/14 2pp 21795 245.
- 840110018 Notification of contract execution, Mod 3 to "Cost Analyses of Proposed Changes in NRC Requirements " Contractor Science & Engineering Assoc, Inc.
GILDENHORN, A J. Administrative Contracts Branch. NRC-33-83-500
83/12/14 BARRY, L. J. Office of Resource Management, Director.
FOWLER, G NRC - No Detailed Affiliation Given. 1p. 21795.241.
- 840110022 Mod 3, incorporating provisions for electronic transfer of funds, to "Cost Analyses of Proposed Changes in NRC Requirements "
* Science & Engineering Associates, Inc. HAQAN, T Division of Contracts NRC-33-83-500. 83/12/14. 2pp. 21795 242
- 8401120097 Notification of contract execution, Mod 1 to "Subscription Svcs to 1983 Edition of ASME Boiler & Pressure Vessel Code " Contractor ASME.
HAWKINS, D A Administrative Contracts Branch NRC-10-83-369.
83/12/15 BESAW, W J Division of Technical Information & Document Control. CONYNGHAM, M NRC - No Detailed Affiliation Given 1p 21806.071.
- 8401120102 Mod 1, revising method of payment to accommodate payments by wire transfer through Treasury Financial Communications Sys, to "Subscription Svcs to 1983 Edition of ASME Boiler & Pressure Vessel Code "
* American Society of Mechanical Engineers HAQAN, T F Division of Contracts NRC-10-83-369 83/12/15 2pp 21806.072
- 8401120122 Notification of contract execution, Mod 3 to "Provide Expert Technical Consulting Svcs to DCS on Task Order Basis."
Contractor Dept of Air Force
BROMBERG, J Administrative Contracts Branch NRC-10-82-404
83/12/30 NORRY, P Office of Administration. LUNDY, J. NRC - No Detailed Affiliation Given 1p 21805 186
- 8401120138 Mod 3, extending period of performance to 841230, to "Provide Expert Technical Consulting Svcs to DCS on Task Order Basis "
BLAIR, R L Army, Dept of HAQAN, T F Division of Contracts.
NRC-10-82-404 83/12/30 2pp. 21805 187
- 8401120129 Notification of contract execution, Mod 9 to "NRC - Issuances & Indexes " Contractor: Data Composition Svcs, Inc
HAWKINS, A Administrative Contracts Branch NRC-10-80-661.
84/01/02 BESAW, W J Division of Technical Information & Document Control BAVOLAINEN, A NRC - No Detailed Affiliation Given 1p. 21805 156
- 8401120137 Mod 9, deobligating balance remaining under contract, to "NRC - Issuances & Indexes."
HALEY, K T. Data Composition Services, Inc HAQAN, T F Division of Contracts NRC-10-80-661. 84/01/02 1p. 21805 157
- 8401120531 Notification of contract execution, Mod 1 to "Common Cause Failure Analysis " Contractor: JBF Assoc, Inc
JESSUP, B Technical Assistance Contracts Branch NRC-04-83-183
83/12/22 BATSON, W Office of Nuclear Reactor Regulation, Director
ROBINSON, R C NRC - No Detailed Affiliation Given. 1p 21804:087
- 8401120533 Mod 1, adding reporting requirements & substituting address, to "Common Cause Failure Analysis "
MONTAGUE, D F JBF Associates MORTON, K V Technical Assistance Contracts Branch NRC-04-83-183. 83/12/22 1p 21804:088.
- 8401120534 Notification of contract execution, Mod 1 to "Uncertainties in Sys Analysis Part of Seismic PRA " Contractor Future Resources Assoc, Inc
JESSUP, B Technical Assistance Contracts Branch NRC-04-83-182
83/12/21 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, J NRC - No Detailed Affiliation Given 1p. 21803.105
- 8401120541 Mod 1, adding rept requirements, to "Uncertainties in Sys Analysis Part of Seismic PRA "
BUDNITZ, R Future Resources Associates, Inc MORTON, K V. Division of Contracts NRC-04-83-182 83/12/21. 1p 21803:106
- 8401120554 Notification of contract execution, Mod 1 to "Software Maint " Contractor Intel Sys Corp.
PERLMAN, J Administrative Contracts Branch FIN B-8860.
NRC-33-83-461 83/12/14 BASSETT, H S Division of Data Automation & Management Information. JOHNSON, C NRC - No Detailed Affiliation Given 1p. 21803 089
- 8401120558 Mod 1, incorporating provisions for electronic transfer of funds to "Software Maint "
* Intel Corp HAQAN, T F Division of Contracts FIN B-8860.
NRC-33-83-461. 83/12/14 2pp 21803 090.
- 8401120559 Notification of contract execution, Mod 1 to "Development for PWR Transient Analysis Model " Contractor: S Levy, Inc.
JESSUP, B Technical Assistance Contracts Branch NRC-04-83-184.
83/12/29 BATSON, W Office of Nuclear Regulatory Research, Director. LUKER, N. NRC - No Detailed Affiliation Given 1p 21803.097
- 8401120569 Mod 1, adding reporting requirements, to "Development for PWR Transient Analysis Model "
* S Levy, Inc MORTON, K V. Division of Contracts.
NRC-04-83-184 83/12/29. 1p. 21803:088.
- 8401120590 Notification of contract execution, Mod 1 to "Technical Basis for Foreign Exchange of Codes " Contractor Intl Energy Assoc, Ltd.
JESSUP, B Technical Assistance Contracts Branch. NRC-04-83-185.
83/12/21 BATSON, W Office of Nuclear Regulatory Research, Director KELBER, C NRC - No Detailed Affiliation Given 1p. 21796:298
- 8401120592 Mod 1, adding reporting requirements, to "Technical Basis for Foreign Exchange of Codes."
ALIKONIS, N A. International Energy Associates, Ltd. MORTON, K V. Division of Contracts. NRC-04-83-185 83/12/21. 1p 21796.299

NONDOCKETED ITEMS

B401130005 Notification of contract execution, Mod 6 to "Maint of Data General Computers & Peripheral Equipment." Contractor: Data Consultants, Inc
DORSEY, M Administrative Contracts Branch NRC-25-82-311
83/12/16 CASPER, R NRC - No Detailed Affiliation Given 1p
21821 001

--B401130008 Mod 6, incorporating provisions for electronic transfer of funds, to "Maint of Data General Computers & Peripheral Equipment"
* Data Consultants, Inc HAGAN, T F. Division of Contracts
NRC-25-82-311. 83/12/16 2pp 21821 002

B401130013 Notification of contract execution, Mod 2 to "Mr Hill Shall Serve as Administrative Judge on ABLAB." Contractor E Hill
HAWKINS, D A Administrative Contracts Branch. FIN B-8184
NRC-21-83-426 83/12/15, COTTER, B. P. Atomic Safety and Licensing
Board Panel FITTI, C. NRC - No Detailed Affiliation Given. 1p
21820, 352

--B401130018 Mod 2, revising method of payment to accommodate payments through wire transfer via Treasury Financial Communications Sys, to "Mr Hill Shall Serve as Administrative Judge on ABLAB"
* Affiliation Unknown. HAGAN, T F Division of Contracts FIN
B-8184. NRC-21-83-426 83/12/15 2pp 21820: 353

B401130015 Notification of contract execution, Mod 7 to "On-Call Maint for Computer Peripheral Equipment" Contractor: Computer Sys Support Corp.
PERLMAN, J. Administrative Contracts Branch. FIN B-8174
NRC-33-83-451. 83/12/14. BASSETT, H S Division of Data Automation & Management Information. JOHNSON, C NRC - No Detailed Affiliation Given. 1p. 21819: 358.

--B401130020 Mod 7, incorporating electronic transfer of funds, to "On-Call Maint for Computer Peripheral Equipment."
* Computer Systems Support Corp HAGAN, T F Division of Contracts
FIN B-8174 NRC-33-83-451 83/12/14 2pp.
21819: 359.

B401130032 Notification of contract execution, Mod 1, to "Behavior of Sub-Critical & Blow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle." Contractor: Matls Engineering Assoc.
JESSUP, B Technical Assistance Contracts Branch. FIN D-1134
NRC-04-83-187. 83/12/23. BATSON, W Office of Nuclear Regulatory Research, Director. STOBNIER, J NRC - No Detailed Affiliation Given. 1p 21819: 356

--B401130037 Mod 1, adding rept requirements, to "Behavior of Sub-Critical & Blow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle"
GREENSLATT, M. Materials Engineering Associates, Inc. MORTON, K V
Division of Contracts. NRC-04-83-187. 83/12/23. 1p 21819: 357

B401130123 Notification of contract execution, Mod 2, to "Panel Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions'." Contractor: Rowe Assoc
TOWNSEND, B L. Administrative Contracts Branch. FIN B-8968
NRC-04-83-007. 83/12/30. BASSETT, D E. Division of Accident Evaluation (Pre B40101). JANKOWSKI, M W NRC - No Detailed Affiliation Given. 1p. 21820 275.

--B401130129 Mod 2, extending period of performance to B40201, to "Panel Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions'."
ROME, D. S Rowe Associates REBELLO, J. E. Division of Contracts
FIN B-8968. NRC-04-83-007 83/12/30 1p. 21820 276.

B401130443 Notification of contract execution, Mod 5 to "Stenographic Reporting Svcs." Contractor: Tayloe Assoc
MCLEAREN, T. Administrative Contracts Branch FIN B-8177.
NRC-17-83-399. 84/01/11. HOYLE, J. C. Office of the Secretary of the Commission BULLIVANT, P.; MORAN, D. NRC - No Detailed Affiliation Given. 1p. 21819: 348.

--B401130445 Mod 5, increasing total amount obligated, to "Stenographic Reporting Svcs."
* Tayloe Associates. HAGAN, T F. Division of Contracts. FIN
B-8177. NRC-17-83-399. 84/01/11. 1p 21819: 347.

B401130444 Notification of contract execution, Mod 7 to "Technical Assistance in Repository Design." Contractor: Golder Assoc.
DELATCHY, V Technical Assistance Contracts Branch. NRC-02-81-027.
84/01/10. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. PITTIGLIO, L. NRC - No Detailed Affiliation Given. 1p 21819: 346.

--B401130447 Mod 7, extending period of performance at no addl cost, to "Technical Assistance in Repository Design."
* Golder Associates. GUSTAVE, R. P. Division of Contracts
NRC-02-81-027. 84/01/10. 1p 21819: 345.

B401160391 Notification of contract execution, Mod 2 to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp Before OSA Board of Contract Appeals" Contractor Dataflow Sys, Inc
TOWNSEND, B L. Administrative Contracts Branch NRC-10-83-368
84/01/04 NORRY, P O Office of Administration AVERY, R E NRC - No Detailed Affiliation Given 1p 21823 337

--B401160409 Mod 2, adding one addl trip to San Francisco, CA & increasing level of effort, travel & funding, to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp Before OSA Board of Contract Appeals"
* Dataflow Systems, Inc REBELLO, J E Division of Contracts
NRC-10-83-368 84/01/04 1p 21823 338

B401160457 Notification of contract execution "Technical Assistance for In Situ Testing." awarded to Engineers Intl, Inc
WIGGINS, E. Technical Assistance Contracts Branch FIN D-1004-4
NRC-02-84-002 83/12/28 BROWN, R S Program Support Branch.
BUCKLEY, J NRC - No Detailed Affiliation Given. 1p 21834 236.

--B401160462 Contract "Technical Assistance for In Situ Testing." awarded to Engineers Intl, Inc
BINGH, M M Engineers International, Inc MORTON, K V Division of Contracts FIN D-1004-4 NRC-02-84-002 83/12/28 183pp
21834: 237

B401170113 Notification of contract execution, Mod 2 to "Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions' " Contractors S Levy
TOWNSEND, B L. Administrative Contracts Branch FIN B-8989.
NRC-04-83-014 83/12/30 BASSETT, D E Division of Accident Evaluation (Pre B40101). JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 21836 345

--B401170119 Mod 2, extending period of performance to "Review of Draft Rept Entitled 'Radionuclide Release Under LWR Specific Accident Conditions' "
LEVY, S S Levy, Inc. REBELLO, J E Division of Contracts FIN
B-8989 NRC-04-83-014 83/12/30 1p 21836: 346.

B401170506 Notification of contract execution, Mod 2 to "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins-Project B" Contractor Golder Assoc
FLEENOR, C Technical Assistance Contracts Branch. NRC-02-83-034
83/12/15. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director COOKE, B NRC - No Detailed Affiliation Given 1p. 21847. 152.

--B401170512 Mod 2, incorporating new project officer, to "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins-Project B."
* Golder Associates GUSTAVE, R P. Division of Contracts
NRC-02-83-034 83/12/15. 1p 21847 153.

B401170519 Notification of contract execution, Mod 4, to "Developing Licensing Procedures, Performance Objectives & Technical Criteria for Disposal of Low Level Waste" Contractor US Ecology.
FLEENOR, C Technical Assistance Contracts Branch. NRC-02-81-047
83/12/02 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director ROLES, G NRC - No Detailed Affiliation Given 1p. 21844: 360

--B401170525 Mod 4, extending period of performance to B40430, to "Developing Licensing Procedures, Performance Objectives & Technical Criteria for Disposal of Low Level Waste"
ERABE, A U S Ecology, Inc (formerly Nuclear Engineering, Inc.)
GUSTAVE, R. P. Division of Contracts NRC-02-81-047. 83/12/02 1p. 21844. 361

B401170532 Notification of contract execution, Mod 3, to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling" Contractor: Water, Waste & Land
FLEENOR, C. Technical Assistance Contracts Branch. NRC-02-83-030
83/11/30 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director WIDMAYER, D NRC - No Detailed Affiliation Given. 1p. 21847 072.

--B401170537 Mod 3, extending period of performance to B31201, to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling."
DAVIS, L A. Water, Waste & Land, Inc GUSTAVE, R P. Division of Contracts. NRC-02-83-030 83/11/30. 1p. 21847: 073

B401170543 Notification of contract execution, Mod 4 to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling." Contractor: Water, Waste & Land.
FLEENOR, C Technical Assistance Contracts Branch. NRC-02-83-030.
83/12/05 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director WIDMAYER, D NRC - No Detailed Affiliation Given. 1p 21844 348

NONDOCKETED ITEMS

409

--B401170549 Mod 4, extending period of performance to B40101, to "Model Documentation & In-House Training for Unsaturated Flow & Transport Modeling"
DAVIS, L A Water, Waste & Land, Inc GUSTAVE, R P Division of Contracts NRC-02-83-030 83/12/05 1p 21844 349

B401180002 Notification of contract execution, Mod 7 to "Benchmarking of Computer Codes & Licensing Assistance" Contractor Teknekron Research, Inc
GUSTAVE, R Technical Assistance Contracts Branch NRC-02-81-026 83/12/27 JACOBS, A Office of Nuclear Material Safety & Safeguards, Director FEHRINGER, D NRC - No Detailed Affiliation Given 1p 21848 308

--B401180003 Mod 7, Task 4 & 5, increasing funding per Article XIII, to "Benchmarking of Computer Codes & Licensing Assistance"
VDDT, D K Teknekron, Inc GUSTAVE, R P Division of Contracts NRC-02-81-026 83/12/27 3pp 21848 309

B401180014 Notification of contract execution, Mod 2 to "Severe Accident Consequences Mitigation" Contractor R&D Assoc
FLEENOR, C Technical Assistance Contracts Branch FIN B-8625 NRC-03-83-092 83/12/12 MATTSOON, R J Division of Systems Integration (past 811005) NEWTON, R NRC - No Detailed Affiliation Given 1p 21848 265

--B401180016 Mod 2, providing incremental funding for FY84, to "Severe Accident Consequences Mitigation"
* R&D Associates GUSTAVE, R P Division of Contracts FIN B-8625 NRC-03-83-092 83/12/12 2pp 21848 266

B401180021 Notification of contract execution, Mod 3 to "Presentation of General & Refresher Courses in NDE" Contractor Rockwell Intl Corp
JACOBS, A Technical Assistance Contracts Branch NRC-03-82-246, 83/12/12 BLAHA, J Program Support Branch HASSELBERG, R NRC - No Detailed Affiliation Given 1p 21847 347

--B401180024 Mod 3, adding addl individual to key personnel, to "Presentation of General & Refresher Courses in NDE"
JOHNSON, R A Rockwell International Corp. GUSTAVE, R P Division of Contracts NRC-03-82-246 83/12/12 1p 21847 348

B401190327 Notification of contract execution, Mod 13 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2" Contractor Franklin Inst
WOLLETT, B Technical Assistance Contracts Branch FIN B-6891, NRC-03-81-130 84/01/09 EISENHUT, D G Division of Licensing, CARRINGTON, M NRC - No Detailed Affiliation Given 1p 21867 296

--B401190332 Mod 13, exercising option & extending period of performance to B40331, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2"
ROSENBERG, E B Franklin Institute/Franklin Research Center GUSTAVE, R P Division of Contracts FIN B-6891 NRC-03-81-130, 84/01/09 102pp 21867 297

B401190354 Notification of contract execution, Mod 1 to "Developing Guidelines to Perform Safety/Reliability Analyses," Contractor NASA
EDGEWORTH, P Administrative Contracts Branch NRC-03-84-158 83/12/27 MUIR, A Director's Office, Office of Inspection and Enforcement BRACH, E NRC - No Detailed Affiliation Given 1p 21870 013

--B401190356 Mod 1, correcting contract number, to "Developing Guidelines to Perform Safety/Reliability Analyses"
* National Aeronautics & Space Admin MORTON, K V Division of Contracts NRC-03-84-158 83/12/27 1p. 21870 014

B401190469 Notification of contract execution, Mod 4 to "Inservice Insp Courses" Contractor Rockwell Intl Corp.
WOLLETT, B Technical Assistance Contracts Branch FIN B-1274, NRC-03-81-243 83/12/13 COBB, L I Training & Administration Staff FOX, E NRC - No Detailed Affiliation Given 1p 21861 343

--B401190471 Mod 4, adding funds & correcting amount added under Mod 3, to "Inservice Insp Courses"
JOHNSON, R A Rockwell International Corp. GUSTAVE, R P Division of Contracts FIN B-1274 NRC-03-81-243, 83/12/13 1p 21861 344

B401230025 Notification of contract execution: "Operation & Maint of NRC Document Control Sys" awarded to SBA Subcontractor, Technassociates, Inc
BROMBERG, B J Administrative Contracts Branch NRC-10-84-211 83/12/27 NORRY, P G Office of Administration LUNDY, J NRC - No Detailed Affiliation Given 2pp 21931 010

--B401230031 Contract "Operation & Maint of NRC Document Control Sys," awarded to SBA Subcontractor Technassociates, Inc
* Smail Business Administration VTHIER, P Technical Welding Laboratories of Alaska, Inc HILL, D Division of Contracts NRC-10-84-211 83/12/27 63pp 21931 012

B401230182 Notification of contract execution, Mod 2 to "review of rept entitled 'Radionuclide Release Under LWR Specific Accident Conditions'" Contractor: LR Zumwalt
TOWNSEND, B L Purchasing Section FIN B-8984 NRC-04-83-009 84/01/16 BASSETT, D E Division of Accident Evaluation (Pre B40101) JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 21928 001

--B401230204 Mod 2, extending period of performance to B40201, adding addl meeting & document review & increasing funding, to "review of rept entitled 'Radionuclide Release Under LWR Specific Accident Conditions'"
ZUMWALT, L R Zumwalt, L R REDELLO, J E Division of Contracts FIN B-8984 NRC-04-83-009 84/01/16 1p. 21928 002

B401230705 Notification of contract execution, Mod 1 to "Ultra-High Speed Residue Processor for Shaft Insp Sys Image Enhancement" Contractor Spectron Development Lab, Inc
JESSUP, B Technical Assistance Contracts Branch NRC-04-83-186 83/12/21 BATSON, W Office of Nuclear Reactor Regulation, Director, STROBNIDER, J NRC - No Detailed Affiliation Given 1p 21925 247

--B401230706 Mod 1, adding reporting requirements & changing personnel, to "Ultra-High Speed Residue Processor for Shaft Insp Sys Image Enhancement"
HILDEBRAND, B P Spectron Development Laboratories MORTON, K V Technical Assistance Contracts Branch NRC-04-83-186 83/12/21 1p. 21925 248

B401250119 Notification of contract execution: "Carryover & Fall Back in Steam Generators," awarded to MIT
UMBEL, D Technical Assistance Contracts Branch FIN Q-1064, NRC-0-04-84-001 84/01/12 BATSON, W Office of Nuclear Regulatory Research, Director GRIFFITH, P, HOPPENFELD, J NRC - No Detailed Affiliation Given 1p 21959 023

--B401250122 Contract: "Carryover & Fall Back in Steam Generators," awarded to MIT
HUMMER, Q D Massachusetts Institute of Technology, Cambridge, MA MORTON, K V Technical Assistance Contracts Branch FIN Q-1064 NRC-0-04-84-001, 84/01/12 2pp. 21959 024

B401250355 Notification of grant execution "Transient Critical Heat Flux Behavior," awarded to Univ of Central Florida
UMBEL, D Technical Assistance Contracts Branch FIN Q-1061 NRC-0-04-84-200, 84/01/12 BATSON, W Office of Nuclear Regulatory Research, Director YOUNG, M NRC - No Detailed Affiliation Given 1p 21952 152

--B401250366 Grant: "Transient Critical Heat Flux Behavior," awarded to Univ of Central Florida.
BURN, J R Central Florida, Univ. of, MORTON, K V, Technical Assistance Contracts Branch FIN Q-1061 NRC-0-04-84-200, 84/01/12 2pp 21952 153

B401260191 Notification of grant execution, Mod 1 to "Proposal For Scaling of Mixing in Thermally Stratified Flows" Grantee: Purdue Univ.
UMBEL, D Technical Assistance Contracts Branch FIN Q-1047, NRC-0-04-83-003 84/01/12 BATSON, W Office of Nuclear Regulatory Research, Director REYES, J NRC - No Detailed Affiliation Given 1p. 21971 322

--B401260197 Mod 1, providing funds for FY84 & extending period of performance to B40930, to "Proposal For Scaling of Mixing in Thermally Stratified Flows,"
GREENKORN, R A Purdue Univ., West Lafayette, IN, MORTON, K V Technical Assistance Contracts Branch FIN Q-1047 NRC-0-04-83-003 84/01/12 1p 21971 323.

B401260477 Notification of contract execution, Mod 2, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation," Contractor Univ of Arizona.
JACOBS, A Technical Assistance Contracts Branch NRC-04-81-220, 84/01/05 BATSON, W Office of Nuclear Regulatory Research, Director O'DONNELL, E NRC - No Detailed Affiliation Given 1p 21959 329.

--B401260485 Mod 2, extending period of performance to B40930 & providing funding, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation"
SHENBON, F A Arizona, Univ. of, Tucson, AZ, GUSTAVE, R P Division of Contracts, NRC-04-81-220, 84/01/05 2pp 21959 330.

NONDOCKETED ITEMS

B401270531 Notification of contract execution "Developing Guidelines to Perform Safety/Reliability Analyses," awarded to NASA EDGEWORTH, P., UMBEL, D. Administrative Contracts Branch. FIN B-8230 NRC-05-84-158 83/12/27 MUIR, A. Director's Office, Office of Inspection and Enforcement BRACH, E. NRC - No Detailed Affiliation Given 1p 22002 137

--B401270539 Ltr Contract NRC-04-84-158, "Developing Guidelines to Perform Safety/Reliability Analyses," awarded to NASA MORTON, K. V. Technical Assistance Contracts Branch FIN B-8230 NRC-04-84-158 83/11/16 SMITH, R. G. National Aeronautics & Space Admin 8pp 22002 138

B401300010 Notification of contract execution, Mod 8, to "Environ Study of U Fuel Cycle." Contractor NUS Corp. EDGEWORTH, P. Technical Assistance Contracts Branch FIN B-61454 NRC-02-78-044 83/12/23 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director THOMPSON, B. NRC - No Detailed Affiliation Given 1p 22027 318

--B401300012 Mod 8, obligating funds, to "Environ Study of U Fuel Cycle." EDMONSON, L. R. NUS Corp. MORTON, K. V. Division of Contracts FIN B-61454. NRC-02-78-044 83/12/23 2pp. 22027 319

B401300128 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements." Contractor NY State Dept of Health. UMBEL, D. Technical Assistance Contracts Branch. FIN B-8335 NRC-28-83-610. 84/01/13 MCSHAR, J. Division of Resource Management & Administration KOTTAN, J. J. NRC - No Detailed Affiliation Given 1p 22005 030

--B401300141 Mod 2, providing funds for CY84, incorporating environ monitoring at facility & changing assigned NRC representative, to "Radiation Monitoring Program Requirements." LEAVY, W. F. New York, State of. GUSTAVE, R. P. Division of Contracts FIN B-8335. NRC-28-83-610. 84/01/13 1p. 22005 031

B401300153 Notification of grant execution, Mod 3 to "Partial Support of Committee on Seismology." Grantee: Natl Academy of Sciences. UMBEL, D. Technical Assistance Contracts Branch. FIN G-1028. NRC-04-81-023 84/01/13 BATSON, W. Office of Nuclear Regulatory Research, Director MURPHY, A. NRC - No Detailed Affiliation Given 1p. 22005 028

--B401300154 Mod 3, extending period of performance to 840930 & increasing funds, to "Partial Support of Committee on Seismology." SMITH, F. M. National Academy of Sciences. MORTON, K. V. Division of Contracts FIN G-1028 NRC-04-81-023. 84/01/13 1p. 22005 029

B401310059 Notification of contract execution, Mod 13 to "JURIS Automatic Legal Research Sys." Contractor DOJ. HAWKINS, D. Administrative Contracts Branch. FIN B-1673 NRC-10-76-335. 84/01/19 DUBE, N. L. Office of the Executive Legal Director DAVID, C. NRC - No Detailed Affiliation Given 1p. 22032 339

--B401310068 Mod 13, correcting amount of unliquidated balance, to "JURIS Automatic Legal Research Sys." MANCHER, R. R. Justice, Dept of. HAGAN, T. F. Division of Contracts FIN B-1673 NRC-10-76-335 84/01/19. 1p. 22032 340.

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

B401300014 FOIA request for documents dtd B20427 or later re radiation at WR Grace & Co in Wayne or Pompton Plains, NJ. AIKMAN, R. Records, Hackensack, NJ. 83/04/21. FELTON, J. M. Division of Rules and Records 1p. 21695 349.

B401300015 Responds to FOIA request for documents dtd B20427 or after re radiation at WR Grace & Co in Wayne or Pompton Plains, NJ. Forwards App A documents. Documents also available in PDR Documents partially withheld (ref FOIA Exemption 6). FELTON, J. M. Division of Rules and Records 83/09/20 AIKMAN, R. Records, Hackensack, NJ 9pp. 21695 350

--B206130010 Forwards B20603 ltr from former resident of Wayne, NJ expressing concern re radioactive thorium buried along Black Oak Ridge Road. Info deleted. Related info encl. BRADY, N. F. Senate. 82/06/14 Office of Congressional Affairs. 9pp 21696 055

--B206130011 Forwards B20601 ltr from Wayne, NJ resident expressing concern re thorium buried along Black Oak Ridge Road. Info deleted. Related info encl. BRADLEY, B. Senate. 82/06/14 KAMMERER, C. Office of Congressional Affairs. 9pp. 21696 046

--B207110071 Requests that Commission increase radiological survey scope of former WR Grace & Co property in Wayne, NJ. Boundaries of aerial survey did not include area wide enough to detect all radiation anomalies. Related info encl. BOQUARD, M. L., ROE, R. A. House of Rep., Science & Technology 82/08/10 PALLADINO, N. J. Commissioners App 21696 185.

--B207180008 Requests response to encl ltrs re investigation of radiation levels at WR Grace & Co property in Wayne, NJ. Info deleted. Related info encl. ROE, R. A. House of Rep. 82/08/11 PALLADINO, N. J. Commissioners App 21696 189

--B208010037 Forwards correspondence from Township of Pequannock, Morris County, NJ re excess radiation levels in township Assistance in resolving township problem requested. COURTER, J. House of Rep. 82/08/26 HENDRIE, J. M. Commissioners App 21696 197

--B208010047 Forwards F Fitzpatrick B20823 ltr requesting update on B20812 NRC tests of possible thorium radiation. ROE, R. A. House of Rep. 82/09/14 DIRCKS, W. J. Office of the Executive Director for Operations App 21696 209

--B209150025 Forwards M Resinoff preliminary assessment of thorium radiation situation in Wayne, NJ. WR Grace & Co violated 10CFR20.304 in establishing burial site. ROE, R. A. House of Rep. 82/10/08 DIRCKS, W. J. Office of the Executive Director for Operations 11pp 21696 276

--B212010495 Forwards addl copies of "Radiological Survey Rept of Sheffield Brook in Wayne, NJ." Survey rept of plant site will be transmitted upon completion in Jan 1983 W/o encl. PAGE, R. Q. Uranium Fuel Licensing Branch 82/11/12 MOTT, W. Energy, Dept of 1p 21696 316

--B401300016 Forwards press releases re thorium radiation found in NJ. I hope that responsible party will remove source. Info deleted. * Affiliation Unknown 82/04/30 Affiliation Unknown. App 21695 359

--B401300017 Forwards Oct 1982 "Radiological Survey of Sheffield Brook, Wayne, NJ." final rept Results of surveys & measurements of WR Grace & Co property will be subj of addl rept W/o encl. Info deleted. KINNEHAN, J. D. Region 1, Office of Director 82/10/27 Affiliation Unknown 1p 21696 295.

--B401300018 Submits name of employer & telephone number of reporter who supplied info re possible thorium-bearing waste disposal in Riverdale, NJ. SANBORN, G. NRC - No Detailed Affiliation Given. 82/05/07 KINNEHAN, J., CAMPBELL, M., ABRAHAM, K. NRC - No Detailed Affiliation Given 2pp 21696 001

--B401300020 Forwards "Radiological Surveys of Sheffield Brook." final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept W/o encl. KINNEHAN, J. D. Division of Engineering & Technical Programs 82/10/27 FITZPATRICK, F. Pequannock, NJ 1p 21696 298

--B401300021 Forwards Congressman Roe B20423 ltr re soil contamination at WR Grace & Co in NJ. Coordination w/Region I & IE in preparing response requested. DAVIS, J. G. NRC - No Detailed Affiliation Given 82/05/12 CUNNINGHAM, R. E. NRC - No Detailed Affiliation Given 3pp 21696 007.

--B401300022 Forwards "Radiological Surveys of Sheffield Brook." final rept. Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept W/o encl. KINNEHAN, J. D. Division of Engineering & Technical Programs 82/10/27 FELDMAN, J. Environmental Protection Agency. 1p 21696 299

--B401300024 Requests addl info re investigation of WR Grace & Co & surrounding Wayne, NJ area due to indications of radiation levels & surface soil contamination exceeding unrestricted use criteria. ROE, R. A. House of Rep. 82/04/23. PALLADINO, N. J. Commissioners App 21696 010.

--B401300025 Forwards "Radiological Surveys of Sheffield Brook." final rept Measurements of WR Grace & Co property in Wayne, NJ will be subj of separate rept W/o encl. KINNEHAN, J. D. Division of Engineering & Technical Programs 82/10/27 COSOLITO, F. New Jersey, State of 1p 21696 300

NONDOCKETED ITEMS

4

- B401030027 Responds to B20423 ltr re WR Grace & Co property & surrounding Wayne,NJ area indicating radiation levels & soil contamination exceeding normal criteria NRC evaluating info to determine if soil should be removed
DIRCKS,W J Office of the Executive Director for Operations
82/05/13 ROE,R A House of Rep 2pp 21696 012
- B401030029 Responds to B20423 ltr re WR Grace & Co property & surrounding Wayne,NJ area indicating radiation levels & soil contamination exceeding normal criteria NRC evaluating info to determine if soil should be removed
DIRCKS,W J Office of the Executive Director for Operations
82/05/21 ROE,R A House of Rep 3pp 21696 014
- B401030031 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/27 ORISI,F Lincoln Park, NJ 1p. 21696 301.
- B401030033 Ack receipt of B20423 ltr re investigation of thorium radiation at WR Grace & Co in Wayne,NJ Swift resolution of issue requested.Related info encl
ROE,R A House of Rep 82/05/19 PALLADINO,N J Commissioners
7pp 21696 020
- B401030036 Forwards ltr from Wayne,NJ Council & B20528 reply re low level radiation omitted from site & stream bed down stream from site Related info encl No immediate hazard to health & safety of property owners identified
MOBLEY,B L W R Grace & Co 82/06/01. CROW,W NRC - No Detailed Affiliation Given 9pp 21696 034
- B401030040 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/27 JASINSKI,W Wayne, NJ 1p 21696 302
- B401030042 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/27 MARCO,D Affiliation Unknown 1p 21696 309
- B401030043 Comments on FOIA Request B2-219 re WR Grace & Co Review of info indicates Item 4,Encl 1 & Item 33 Pages 2 A-4,Encl 2 contain proprietary info & Items 2 a & b,Encl 1 same as Item 160,Encl 2
SNYDER,Q L Division of Emergency Preparedness & Operational Support 82/06/21 FELTON,J M Division of Rules and Records
1p. 21696 072
- B401030046 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl Info deleted.
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/29 Affiliation Unknown 1p 21696 310
- B401030048 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/29 BAUER,F Wayne, NJ 1p 21696 311
- B401030049 Responds to B20614 request for info re thorium contamination in Wayne,NJ.Surveys performed to evaluate if removal of contaminated soil necessary
DIRCKS,W J Office of the Executive Director for Operations.
82/07/01 BRADY,N F Senate 5pp. 21696 087
- B401030050 Responds to B20715 request for description of NRC surveys performed in Wayne,NJ Oak Ridge Assoc Univ "Radiological Survey Plan" forwarded
KINNEMAN,J D Region 1, Office of Director. 82/07/21
BARTOLOZZI,A Wayne, NJ 1p 21696 092
- B401030052 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj in separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs.
82/10/29. WAKS,D Wayne, NJ 1p 21696 312
- B401030053 Requests info re program to conduct tests for thorium, radium & radon gas products onsite at WR Grace & Co
BARTOLOZZI,A R. Wayne, NJ 82/07/15 KINNEMAN,J D. Region 1, Office of Director 1p 21696 093
- B401030054 "Proposed Radiological Survey Plan "
* Oak Ridge Associated Univs 82/03/15 Bpp 21696 094
- B401030055 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs.
82/10/29 O'BRIEN,J Wayne, NJ 1p 21696 313
- B401030057 "Radiological Survey of Sheffield Brook,Wayne,NJ," draft preliminary rept Related info encl,Info deleted
FRAME,P W Oak Ridge Associated Univs 82/07/31 Division of Fuel Cycle & Material Safety 66pp 21696 102
- B401030058 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj in separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/29 WEBB,Q Wayne, NJ 1p 21696 314
- B401030060 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/29 RESNIKOFF,M Council on Economic Priorities 1p. 21696 315
- B401030063 Requests rept on radiation on Black Oak Ridge Road,Wayne,NJ Const approval for new nursing home on subj road in progress
HAYEMANN,B Willowbrook Nursing Home Wayne, NJ. 82/07/29. CAMPBELL,M Region 1, Office of Director 1p. 21696 173
- B401030065 Forwards "Radiological Surveys of Sheffield Brook," final rept Measurements of WR Grace & Co property in Wayne,NJ will be subj of separate rept W/o encl
KINNEMAN,J D Division of Engineering & Technical Programs
82/10/29 CASEY,D Affiliation Unknown 1p 21696 317.
- B401030066 Forwards comments on "Radiological Survey of Sheffield Brook,Wayne,NJ," Jul 1982 preliminary rept,Contractor selecting guidelines or criteria inappropriate.
JOYNER,J H Region 1, Office of Director 82/08/11. CROW,W.T. Uranium Fuel Licensing Branch 3pp 21696 175.
- B401030069 Forwards "Radiological Surveys of Sheffield Brook ," preliminary rept W/o encl Related info encl
JOYNER,J H. Division of Engineering & Technical Programs
82/08/16 MOBLEY,B W R Grace & Co. 7pp 21696 178.
- B401030070 Forwards "Radiological Survey of Sheffield Brook,Wayne,NJ," containing addendum describing He-226 in water analysis W/o encl.
ENJO,J New Jersey, State of 82/11/12 KINNEMAN,J NRC - No Detailed Affiliation Given. 1p 21696 318
- B401030073 Responds to B21110 ltr re review & surveys of WR Grace & Co property & surrounding area in Wayne,NJ indicating presence of thorium.Oak Ridge Assoc Univ rept will be sent when available in early 1983
GLENN,J E Division of Engineering & Technical Programs.
82/12/06 COLLICA,C.J. Norwalk Hosp., Norwalk, CT 1p. 21697 007.
- B401030076 Forwards soil analysis from residences close to old WR Grace railroad siding in Pompton Plains,NJ.Samples 15 & 16 indicated highest levels.Further soil sampling authorization requested Info deleted.
COLLICA,C J Norwalk Hosp , Norwalk, CT 82/11/10. GLENN,J Region 1, Office of Director 2pp 21697:008
- B401030081 Excerpt from rept re radioactive contamination on WR Grace & Co property & surrounding area along Sheffield Brook in Wayne,NJ.
* Affiliation Unknown 82/12/09 4pp. 21697:016.
- B401030082 Responds to encl B20604 ltr to president re thorium waste buried on Black Oak Ridge Road in Wayne,NJ.Surveys indicate presence of matl does not present immediate hazard to residents Info deleted.
KINNEMAN,J.D. Region 1, Office of Director. 82/09/27. Affiliation Unknown. 2pp. 21696 204
- B401030086 Responds to F Fitzpatrick of NJ B20823 ltr re thorium contamination found in Pequannock Township,NJ.Based on NRC surveys,thorium radiation not hazardous to nearby residents.
DIRCKS,W Office of the Executive Director for Operations.
82/09/23 ROE,R A. House of Rep 3pp 21696 206
- B401030089 Forwards "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct,Bources & SNM," per B21201 request W/o encl.
KINNEMAN,J D Division of Engineering & Technical Programs.
82/12/28. RESNIKOFF,M. Affiliation Unknown. 1p. 21697:022.

NONDOCKETED ITEMS

- B401030092 Ack receipt of "Radiological Surveys of Sheffield Brook," final rept Listed refs requested
RESNIKOFF, M Affiliation Unknown 82/12/01 KINNEHAN, J D
Region 1, Office of Director 1p 21697:023.
- B401030096 Responds to F Fitzpatrick 820823 ltr re thorium contamination found in NJ Based on NRC surveys, thorium contamination not hazardous to nearby residents
DIRCKS, W J Office of the Executive Director for Operations 82/09/23 COURTER, J. House of Rep 2pp. 21696 211.
- B401030097 "Results of Mobile Gamma Scanning Activities at Wayne, NJ & Surrounding Communities"
* Oak Ridge National Laboratory 83/01/31. 17pp 21697:032.
- B401030102 Forwards draft "Radiological Survey of WR Grace & Co Property, Wayne, NJ." W/o encl
FRAME, P. W. Oak Ridge Associated Univs 83/01/12 CROW, W
Division of Fuel Cycle & Material Safety 1p. 21697:207
- B401030103 Responds to F Fitzpatrick 820823 ltr re thorium contamination found in NJ Based on NRC surveys, thorium radiation not hazardous to nearby residents
DIRCKS, W J Office of the Executive Director for Operations 82/09/29 ROE, R A House of Rep 2pp 21696 213
- B401030104 Forwards comments on draft radiological survey of WR Grace & Co property, Wayne, NJ. More complete presentations of surface & meter exposure data & clearer conclusions about actual conditions necessary
JOYNER, J. H Division of Engineering & Technical Programs. 83/01/18. PAGE, R O Uranium Fuel Licensing Branch. 6pp 21697:208
- B401030105 "Radiological Survey of Sheffield Brook, Wayne, NJ."
* New Jersey, State of 82/10/31 43pp 21696 223.
- B401030107 Ack receipt of 820924 ltr & addl inquiry re impact of thorium contamination in Wayne, NJ on nursing facility. Based on aerial radiological survey, contamination not hazardous to residents of facility W/o stated encl
ABRAHAM, K Office of Public Affairs 82/10/05. SUCH, P. P Willowbrook Nursing Home Wayne, NJ. 1p. 21696:267.
- B401030110 Requests info re thorium levels found on Black Oak Ridge Road & Pompton Cross Road
SUCH, P. Willowbrook Nursing Home Wayne, NJ. 82/09/24
ABRAHAM, K. Office of Public Affairs. 1p 21696:268.
- B401030111 Forwards Oct 1982 "Radiological Survey of WR Grace & Co Property, Wayne, NJ." final rept W/o encl. Info deleted
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/01. Affiliation Unknown 1p. 21697:215
- B401030114 Responds to 820805 ltr re Electronuclears use of thorium in NJ. Use of thorium caused contamination Surveys & assessments of thorium hazards in progress.
KINNEHAN, J. D Region 1, Office of Director. 82/10/05
CRANDALL, C. B Justice, Dept of, Attorney General, Office of 1p. 21696:270
- B401030115 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl Info deleted
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/01 Affiliation Unknown. 1p. 21697 216
- B401030117 Forwards 820714 ltr from Concerned Citizens Committee of Wayne & Resolution of Municipal Council of Township of Wayne re thorium storage at Electronuclears (related to WR Grace & Co) & radioactive dump site Info deleted.
DUMONT, W. H., CRANDALL, C. B. Justice, Dept. of, Attorney General, Office of 82/08/05. KINNEHAN, J Region 1, Office of Director 3pp. 21696,271.
- B401030118 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl.
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/01. FITZPATRICK, F Pequannock, NJ. 1p. 21697:217.
- B401030122 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl.
KINNEHAN, J. D. Division of Engineering & Technical Programs. 83/02/01. FELDMAN, J. Environmental Protection Agency. 1p. 21697:218.
- B401030124 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D. Division of Engineering & Technical Programs. 83/02/01. COSOLITO, F. New Jersey, State of, 1p. 21697:219.
- B401030125 Responds to M Resnikoff 820912 ltr re WR Grace & Co & surrounding area in Wayne, NJ Twelve burials of up to 1,000 lbs thorium each per yr permitted per 10CFR20.304
DIRCKS, W J Office of the Executive Director for Operations 82/10/26 ROE, R A House of Rep 2pp 21696 273
- B401030127 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D Division of Engineering & Technical Programs 83/02/01 WEBB, G Wayne, NJ 1p 21697 220
- B401030130 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D Region 1, Office of Director 83/02/01
RESNIKOFF, M Council on Economic Priorities 1p 21697,221
- B401030131 Advises that well water sample analysis taken from home indicated water met EPA drinking stds. Info deleted
KINNEHAN, J. D Region 1, Office of Director 82/09/23 Affiliation Unknown 1p 21696 275
- B401030132 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D Region 1, Office of Director 83/02/01 BAUER, F Wayne, NJ 1p 21697 222
- B401030138 Forwards QA Program Insp Rept 99990001/82-03 per 820908 telcon request Rept documents surveys of recipient property Radiation level not hazardous Info deleted
KINNEHAN, J. D Region 1, Office of Director 83/10/18 Affiliation Unknown 2pp. 21696 287.
- B401030139 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D Division of Engineering & Technical Programs 83/02/01 GRIBI, F Lincoln Park, NJ 1p 21697 223
- B401030140 QA Program Insp Rept 99990001/82-03 on 820428 & 0313 Noncompliance noted one area in Wayne, NJ where radioactive matl exists as contamination in uncontrolled areas identified
CAMPBELL, M., KINNEHAN, J. D Region 1, Office of Director 82/06/28 4pp. 21696 287.
- B401030142 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl.
KINNEHAN, J. D. Division of Engineering & Technical Programs. 83/02/01 LEIDY, J Wayne, NJ 1p 21697:224
- B401030146 Responds to 820920 ltr re in-depth study of aerial photography map & addl info concerning thorium contamination in Wayne & Pompton Plains, NJ Contamination not hazardous to Chilton Memorial Hosp
ABRAHAM, K. Office of Public Affairs 82/10/20 MARCY, S William Mercy Agency 2pp. 21696 293
- B401030147 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/01 DIDONATO, J Wayne, NJ 1p. 21697,225
- B401030151 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/01 JASINSKI, W Wayne, NJ 1p 21697:226
- B401030154 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl
KINNEHAN, J. D Division of Engineering & Technical Programs 83/02/01. O'BRIEN, J Wayne, NJ 1p 21697:227
- B401030156 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl.
KINNEHAN, J. D Division of Engineering & Technical Programs. 83/02/01. WAKS, D Wayne, NJ 1p 21697:228
- B401030161 Requests info re results of NRC study at WR Grace & Co site conducted in late 1982.
BARTOLOZZI, A. R Wayne, NJ 83/02/03 KINNEHAN, J. D Region 1, Office of Director 1p 21697,229
- B401030164 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl. Info deleted
KINNEHAN, J. D. Division of Engineering & Technical Programs 83/02/07 Affiliation Unknown 1p 21697,230.
- B401030168 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ." W/o encl Info deleted
KINNEHAN, J. D Division of Engineering & Technical Programs 83/02/10. Affiliation Unknown 1p. 21697 231

NONDOCKETED ITEMS

413

- B401030171 Forwards "Radiological Surveys of WR Grace & Co Property, Wayne, NJ " W/o encl
KINNEMAN, J D Division of Engineering & Technical Programs
83/02/22 Affiliation Unknown 1p 21697 232
- B401030178 Summarizes B30201 radiological survey of WR Grace & Co property. Survey is most complete rept available of radioactive contamination of company property. Site extremely poor for radwaste disposal.
RESNIKOFF, M Affiliation Unknown 83/02/09 JASINSKI, W.
BARTOLOZZI, A Wayne, NJ 7pp 21697 247
- B401030181 Advises that Oak Ridge Assoc Univ sampling of groundwater/ wells at WR Grace & Co not representative of actual groundwater due to heavy rains. Six new wells will be sampled & included in analysis. Related info encl
KINNEMAN, J D Division of Engineering & Technical Programs
83/02/16 JOYNER, J H Region 1, Office of Director 20pp 21697 254
- B401030188 Forwards "Radiological Survey of Former Thorium/Rare Earths Processing Facility (WR Grace Property, Wayne, NJ)" containing Dept of Environ Protection technical findings from Aug 1982 survey. W/o stated encl. Related info incl
KUHRTZ, S O New Jersey, State of 83/04/08 MACE, R W R Grace & Co 5pp 21697 274
- B401030191 "Radiological Survey of Monazite Unloading Area, Pompton Plains Railroad Spur (Pompton Plains, NJ) "
* New Jersey, State of 83/04/30 27pp 21697 279
- B401030195 Responds to B30301 ltr re health hazards of elevated levels of radionuclide concentrations & proposed cleanup operations at WR Grace & Co property & area. Rept indicates no health hazards to residents in area. Info deleted
MARTIN, T T Division of Engineering & Technical Programs
83/04/19 Affiliation Unknown 3pp 21697 309
- B401030200 Requests addl info on "Radiological Survey of WR Grace & Co, Property, Wayne, NJ " Info deleted
* Affiliation Unknown 83/03/01 MARTIN, T T Division of Engineering & Technical Programs 2pp 21697 312
- B401040016 FOIA request for list of schools, businesses & hosps in Cambridge, MA possessing NRC licenses for use of radioactive compounds & for copy of licenses
CHRISTENSEN, D Citizens Against Research Bans 83/09/20 Office of Administration 1p 21731 311
- B401040019 Responds to FOIA request for list of schools, businesses & hosps in Cambridge, MA possessing NRC licenses for use of radioactive compounds & for copy of licenses. Forwards App A documents.
FELTON, J M Division of Rules and Records 83/10/14
CHRISTENSEN, D Citizens Against Research Bans 5pp 21731 312
- 7902020317 In accordance w/780517 application, Matl/Byproduct License 20-15624-01 for Charles Stark Draper Lab is assigned Amend 3, authorizing use of irradiated equipment & Co-137 sealed sources for radiation damage studies & 10CFR30 4(g) R & D.
QUINN, P R Radioisotopes Licensing Branch (Pre 790501) 79/01/11 2pp. 67052 001
- 7903090050 In accordance w/781228 application, Matl/Byproduct License 20-00297-58 for Harvard Univ is amended for use of Co-60 in irradiator to irradiate various matls under 6 conditions listed including location & supervision
BABSIN, N Radioisotopes Licensing Branch (Pre 790501). 79/02/14 2pp. 67052 001
- 7903090070 In accordance w/790104 application, Matl/Byproduct License 20-02848-03 for Polaroid Corp is amended for use of Am-241 in analyzer for X-ray spectrochemical analysis.
QUINN, P R. Radioisotopes Licensing Branch (Pre 790501). 79/02/15, 1p. 67052 001.
- 7904050425 In accordance w/790131 application, Matl/Byproduct License 20-15624-01 for Charles Stark Draper Lab, Inc, is amended to amend condition 10 stating licensed matl shall be used only at licensee stated address
QUINN, P R. Radioisotopes Licensing Branch (Pre 790501). 79/03/06 1p 67052 001
- 7908000203 Matl/Byproduct License 20-12063-02 for Mt Auburn Hosp, Dept of Radiology authorizing use of Co-60 in sealed source in AECL theratron 80
WALKER, W J. Material Licensing Branch. 79/07/03 5pp. 67052 001.
- 7909070539 Matl/Byproduct License 20-467 for MA Inst of Technology is amended in its entirety per 790426 application Amend 2 authorizes use of U in cylindrical slugs in light water & graphite moderated assembly
VACCA, P C Material Licensing Branch 79/08/03 2pp 67052 001
- 8002190404 Matl/Byproduct License 20-13302-01 for MM Bolton is amended in its entirety per 790531 application Amend 2 authorizes any byproduct matl for possession incident to performance of wipe testing
JONES, J A Material Licensing Branch 80/01/11. 2pp 67052 001
- 8003130307 Matl/Byproduct License 20-02848-03 for Polaroid Corp is amended per 790928 application Amend 16 authorizes use of I-125, as sealed source for research purpose by B Levy, M Ryan, A Gerber, W Burgess & F Forster
JONES, J A Material Licensing Branch 80/02/08 1p 67052 001.
- 8003070343 Matl/Byproduct License 20-16407-01 for Energy Resources Co, Inc is amended in its entirety per 800318 application Amend 5 authorizes NI-63 in detector cells in gas chromatographs for sample analysis
BROWN, J M Material Licensing Branch 80/04/11 3pp 67052 001
- 8005070403 Matl/Byproduct License 20-19393-01 for Harvard Univ is amended in its entirety per 800228 ltr Amend 4 authorizes Pu-U, Pu-236, Pu-238 & Pu-239 for R&D
LAMASTRA, M A Material Licensing Branch. 80/04/10 3pp 67052 001
- 8006200261 Matl/Byproduct License 20-01537-11 for MA Inst of Technology is amended in its entirety per 790726 renewal application Amend 1 authorizes use of Cs-137 in sealed sources for irradiation of small animals & cell cultures.
BROWN, J M Material Licensing Branch 80/05/12 2pp. 67052 001
- 8008280420 Matl/Byproduct License 20-19393-01 for Immunotech Corp authorizing use of I-125 in any form for tracer studies in radioimmunoassay R&D
JONES, J A Material Licensing Branch. 80/08/08. 2pp. 21732 077
- 8010070383 Matl/Byproduct License 20-14925-02 for Kor, Inc authorizes use of C-14, tritium, P-32, S-35, I-125, I-131, I-129 & Cr-51 for possession, storage, mfg & distribution.
QUINN, P R Material Licensing Branch. 80/09/12 3pp 21731 347.
- 8010310427 Matl/Byproduct License 20-00297-59 for President & Fellows of Harvard College is amended in its entirety per 800905 application Amend 3 authorizes use of Cs-137 & Co-60, sealed sources, in irradiators for biological samples
LAMASTRA, M A Material Licensing Branch 80/10/21 3pp. 21731 325
- 8104060208 Matl/Byproduct License 20-16407-01 for Energy Resources Co, Inc is amended per 810127 ltr Amend 6 adds NI-63 plated sources in detector cell of Hewlett-Packard gas chromatograph for sample analysis.
QUINN, P R Material Licensing Branch. 81/02/24 1p. 21732 067.
- 8104230201 Matl/Byproduct License 20-19393-01 for Immunotech Corp is amended in its entirety per 801007 ltr. Amend 1 authorizes I-125 for tracer studies in radioimmunoassay R&D
QUINN, P R Material Licensing Branch 81/04/03 2pp. 21732 075.
- 811160348 Notifies of Amend 6 to License 8NM-986 for 5 g U-235 enriched to 93.15 in hermetically sealed containers used for light absorption measurement experiments.
WOOLSEY, R T Atomic Energy Commission. 71/11/17. COCHRANE, J L Massachusetts Institute of Technology, Cambridge, MA 1p. 21731 359.
- 811160351 Notifies of Amend 5 to License 8NM-986 for 16 g Pu in form of metal foils for testing.
ROUBE, L. C. Atomic Energy Commission 71/01/13 COCHRANE, J. L. Massachusetts Institute of Technology, Cambridge, MA. 2pp. 21731 360.
- 8401040023 Computer listing of active NRC licenses in Cambridge, MA
* NRC - No Detailed Affiliation Given. 83/09/27 6pp. 21731 317
- 8401040028 Amend 4 to Matl/Byproduct License 20-00297-59 for Harvard College, authorizing use of 408 Ci Cs-137 sealed source, in AECL Gammacell 10 irradiator, for genetic studies of fruit flies, per 800905 application.
WALKER, W J Material Licensing Branch. 81/10/29. 2pp 21731 328

NONDOCKETED ITEMS

- B401040027 Amend 6 to Matl/Byproduct License 20-01489-05 for AD Little, Inc. authorizing use of Co-60 & Cs-137 for irradiation of small animals, per B10923 application
QUINN, P R Material Licensing Branch 81/11/02 2pp 21731 330
- B401040051 Amend 16 to Matl/Byproduct License 20-13881-01 for Travencol Labs, Inc. authorizing use of I-125, I-131, tritium, C-14 & Sr-75, in any form, for in vitro testing, per B30309 ltr.
HICKEY, J M Material Licensing Branch 83/06/07 2pp. 21731.339
- B401040055 Amends 5 to Matl/Byproduct License 20-13881-02E for Travencol Labs, Inc. authorizing distribution of tritium, I-125, C-14 & Sr-75, per B10914 application
BASSIN, N Material Licensing Branch 82/04/30. 2pp 21731 341
- B401040058 Amend 2 to Matl/Byproduct License 20-13881-03G for Travencol Labs, Inc. authorizing distribution of in vitro kits containing I-125, I-131, tritium & C-14, per B20224 application.
QUINN, P R Material Licensing Branch 82/09/07 1p 21731 343
- B401040061 Amend 3 to Matl/Byproduct License 20-14010-01 for DDT, authorizing use of tritium & Ni-63 foil in chromatographs for sample analysis, per B10424 application
GLENN, J E Material Licensing Branch 81/06/30. 3pp 21731.344
- B401040066 Amend 6 to Matl/Byproduct License 20-14925-01 for Kor, Inc. authorizing use of tritium foil in gas chromatographs for sample analysis, per B10922 & 1103 ltrs.
QUINN, P R Material Licensing Branch 81/12/10 2pp 21731.350
- B401040071 Amend 1 to Matl/Byproduct License 20-20526-01 for BioClinical Group, Inc. authorizing possession & distribution of in vitro kits containing I-125, in any form, per B20120 application
QUINN, P. R. Material Licensing Branch. 82/05/27 2pp 21731.352
- B401040076 Matl/Byproduct License 20-20526-02E for BioClinical Group, Inc. authorizing distribution of I-125, per B20212 ltr.
QUINN, P. R. Material Licensing Branch. 82/05/27 1p. 21731.354
- B401040080 Matl/Byproduct License 20-20526-03G for BioClinical Group, Inc. authorizing distribution of in vitro kits containing I-125, per B20212 ltr.
QUINN, P. R. Material Licensing Branch. 82/05/27. 1p 21731.355
- B401040083 Matl/Byproduct License 20-20577-02 for Cambridge Research Lab. authorizing use of Cs-137 sealed source for irradiation of small animals, per B30413 application & B30607 ltr.
HICKEY, J. W. Material Licensing Branch. 83/07/13 3pp 21731.356
- B401040092 Advises of issuance of Amend 4 to License SNM-986, describing limitations on radioactive matl use, per 701124 request
ROUSE, L C Atomic Energy Commission 71/01/05 CLARK, L. Massachusetts Institute of Technology, Cambridge, MA 1p. 21731.362
- B401040094 Advises of issuance of Amend 2 to License SNM-986, describing limitations on radioactive matl use, per 70112 & 28 applications.
ROUSE, L. C Atomic Energy Commission. 70/02/18 CLARK, L. Massachusetts Institute of Technology, Cambridge, MA 1p. 21732.001.
- B401040098 Advises of issuance of Amend 3 to License SNM-986, authorizing storage only of 16 g Pu in form of metal foils, per 701014 application.
NUSSBAUMER, D A Atomic Energy Commission. 70/11/24. COCHRANE, J Massachusetts Institute of Technology, Cambridge, MA. 1p 21732.002.
- B401040104 Amend 2 to Matl/Byproduct License 20-01537-10 for MIT, authorizing use of Co-60 sealed sources for irradiation of matl, per B30501 ltr.
ST MARY, F. A. Material Licensing Branch. 83/09/22. 2pp 21732.008.
- B401040115 Amend 43 to Matl/Byproduct License 20-01489-01 for AD Little, Inc. authorizing use of any byproduct matl w/Atomic Numbers 3-95, tritium, C-14, Kr-85, Ni-63, Am-241 & Ir-192 for R&D animal studies, per B30113 application.
GLENN, J. E. Region 1, Office of Director. 83/03/22. 4pp. 21732 023
- B401040120 Amend 43 to Matl/Byproduct License 20-01937-02 for MIT, authorizing use of any byproduct matl w/Atomic Numbers 3-95, tritium, Po-210, Am-241 & Cf-252 for R&D, animal studies & educational purposes, per 790620 application
GLENN, J E Region 1, Office of Director 83/05/10 4pp 21732 027
- B401040124 Amend 19 to Matl/Byproduct License 20-02848-03 for Polaroid Corp. adding B Levy, M Ryan, WA Burgess, FQ Forster & AB Holland as supervisors of radioactive matl use, per B30125 ltr.
JERMAN, P C Region 1, Office of Director 83/03/02 1p 21732 031
- B401040130 Amend 18 to Matl/Byproduct License 20-02848-03 for Polaroid Corp. authorizing use of Fe-55 for evaluation of X-ray fluorescence, per B20412 & 0812 ltrs.
JERMAN, P C. Material Licensing Branch 82/09/09 1p. 21732.032
- B401040134 Amend 17 to Matl/Byproduct License 20-02848-03 for Polaroid Corp. changing place of use, per B00926 ltr.
QUINN, P R Material Licensing Branch 81/04/24 1p 21732 033
- B401040141 Amend 14 to Matl/Byproduct License 20-02848-03 for Polaroid Corp. authorizing use of any byproduct matl w/Atomic Numbers 3-83, tritium, Fe-55, Am-241 & Ni-63 for research, per 780426 application
COMBS, F C Material Licensing Branch 78/08/07 4pp 21732 036
- B401040148 Amend 38 to Matl/Byproduct License 20-07288-01 for American Science & Engineering, Inc. authorizing use of any byproduct matl w/Atomic Numbers 1-83, Po-210, Am-241 & Cm-244 for instrument development & testing, per B30614 application
KINNEMAN, J D Region 1, Office of Director 83/07/10 3pp 21732.040
- B401040151 Amend 9 to Matl/Byproduct License 20-07896-01 for Moleculon Research Corp. authorizing use of any byproduct matl w/Atomic Numbers 3-83 & tritium in lab studies, instrument calibr, counting, gauging & sample analysis, per 771025 application.
QUINN, P R Material Licensing Branch 78/04/21 2pp. 21732 043
- B401040156 Amend 33 to Matl/Byproduct License 20-12063-01 for Mount Auburn Hosp. authorizing use of byproduct matl listed in Groups I-V of 10CFR35 100 & in 10CFR31 11 & Xe-133 for diagnostic & therapeutic procedures, per B30623 application
GLENN, J E Region 1, Office of Director 83/07/19 4pp. 21732 045
- B401040161 Amend 2 to Matl/Byproduct License 20-13162-02 for Cambridge Hosp. authorizing use of byproduct matl listed in Groups I-III of 10CFR35 100 & in 10CFR31 11(a) & Xe-133 for diagnostic procedures, per B00528 application
GLENN, J E Material Licensing Branch 82/04/04 4pp. 21732 049
- B401040166 Amend 9 to Matl/Byproduct License 20-14000-01 for Sancta Maria Hosp. authorizing use of byproduct matl in Groups I-III in 10CFR35 100 & in 10CFR35 11(a) & Xe-133 for diagnostic procedures, per B11020 application
JERMAN, P C Material Licensing Branch 81/12/22 3pp 21732.055
- B401040172 Amend 7 to Matl/Byproduct License 20-13174-01 for Dynatech R&D Co. authorizing use of tritium & C-14 in any form for lab research studies, per B11230 application
JERMAN, P C. Division of Fuel Cycle & Material Safety. 82/09/30 2pp 21732 058.
- B401040176 Amend 5 to Matl/Byproduct License 20-15223-01 for SISA, Inc. authorizing use of tritium, C-14, S-35 & I-125 for lab studies in animals & animal tissues, per B20607 application
JERMAN, P C. Division of Fuel Cycle & Material Safety 82/09/30 2pp 21732 060
- B401040180 Amend 6 to Matl/Byproduct License 20-15624-01 for CG Draper Lab. Inc. authorizing AE Palty & RB Miller as users of licensed matl, per 780517 & 1212 applications & B20527 ltr.
JERMAN, P C Division of Fuel Cycle & Material Safety. 82/07/08 1p 21732.062
- B401040184 Amend 5 to Matl/Byproduct License 20-15624-01 for CG Draper Lab. Inc. authorizing use of Ni-63 plated sources, in Hewlett-Packard 18B03-60520 detector cells in gas chromatographs for sample analysis, per B10323 ltr.
QUINN, P. R Material Licensing Branch 81/05/11 1p 21732 063
- B401040192 Amend 2 to Matl/Byproduct License 20-16407-02 for Energy Resources Co, Inc. authorizing use of P-32, tritium, I-125, C-14 & S-35 for lab studies, per B11001 application.
JERMAN, P. C Material Licensing Branch 82/01/18. 2pp. 21732.071

NONDOCKETED ITEMS

415

- B401040194 Amend 2 to Matl/Byproduct License 20-18150-01 for Harvard Community Health Plan Central Lab, authorizing use of I-125, I-129 & Cs-137 for in vitro studies, per B30728 application
GLENN, J E Region 1, Office of Director 83/09/27 2pp
21732 073
- B401040201 Amend 2 to Matl/Byproduct License 20-19806-01 for Biogen, Inc, authorizing use of Ca-45 for biochemical research, per B30620 ltr
GLENN, J E Region 1, Office of Director 83/07/08 1p.
21732 079
- B401040206 Amend 1 to Matl/Byproduct License 20-19808-01 for Biogen, Inc, changing corporate name & business address, per B20322 & 1207 & B30310 ltrs
JERMAN, P C Region 1, Office of Director 83/03/25 1p
21732 080
- B401040211 Corrected Matl/Byproduct License 20-19808-01 for Biogen, Inc, authorizing use of tritium, C-14, P-32, S-35 & I-125, in any form, for biochemical research, per B10615 application & B10911 & 22 ltrs
GLENN, J E Material Licensing Branch 81/11/09 2pp 21732 081
- B401040215 Matl/Byproduct License 20-19808-01 for Biogen, Inc, authorizing use of tritium, C-14, P-32, S-35 & I-125, in any form, for biochemical research, per B10615 application & B10911 & 22 ltrs
GLENN, J E Material Licensing Branch 81/10/13 2pp 21732 083.
- B401040224 Amend 2 to Matl/Byproduct License 20-19856-01 for Angenics, Inc, authorizing use of I-125 & tritium, per B30504 ltr
JERMAN, P C Region 1, Office of Director 83/06/08 1p
21732 085
- B401040227 Amend 1 to Matl/Byproduct License 20-19856-01 for Angenics Inc, authorizing use of I-125, C-14, S-35, P-32, tritium, I-129 & Am-241 for in vitro assays & instrument calibr, per B20503 ltr
JERMAN, P C Division of Fuel Cycle & Material Safety. 82/06/29 2pp 21732 086
- B401040231 Matl/Byproduct License 20-19939-01 for BTC Diagnostics, Inc, authorizing use of I-125 for lab studies, per B20111 application & B20422, 0529, 0622 & 24 ltrs
GLENN, J E Division of Fuel Cycle & Material Safety 82/07/13, 2pp 21732 088
- B401040236 Corrected Amend 4 to Matl/Byproduct License 20-20503-01 for Repligen Corp, describing limitations on radioactive matl use, per B10902 application & B11007, B20429 & Feb 1983 ltrs
GLENN, J E Region 1, Office of Director 83/04/13 1p
21732 090
- B401040238 Amend 4 to Matl/Byproduct License 20-20503-01 for Repligen Corp, describing limitation on radioactive matl use, per B10902 application & B11007, B20429 & Feb 1983 ltrs.
GLENN, J E Region 1, Office of Director 83/03/14, 1p
21732 091
- B401040241 Amend 3 to Matl/Byproduct License 20-20503-01 for Repligen Corp, authorizing use of Ca-45, Rh-86, Cl-36 & Na-22, in any form, for cell labeling, per B21018 ltr
JERMAN, P C Division of Fuel Cycle & Material Safety 82/11/04 1p 21732 092
- B401040246 Amend 2 to Matl/Byproduct License 20-20503-01 for Repligen Corp, designating authorized users, per B20429 ltr
JERMAN, P C Material Licensing Branch 82/05/19, 1p 21732 093
- B401040251 Amend 1 to Matl/Byproduct License 20-20503-01 for Repligen Corp, changing licensee address, per B20218 ltr
GLENN, J E Material Licensing Branch, 82/03/05 1p, 21732 094
- B401040258 Matl/Byproduct License 20-20503-01 for Repligen Corp, authorizing use of P-32, S-35, C-14, I-125 & tritium, in any form, for in vitro labeling & iodination of antibodies & antigens, per B10902 application & B11007 ltr
GLENN, J E Material Licensing Branch, 81/10/29 2pp 21732 095
- B401040264 Matl/Byproduct License 20-20506-01 for BioTechnica Intl, Inc, authorizing use of tritium, C-14, P-32, S-35 & I-125 for biochemical research, per B10826 application & B11103 ltr
JERMAN, P C Material Licensing Branch 81/12/03, 2pp
21732 097
- B401040271 Matl/Byproduct License 20-20577-01 for Ortho Diagnostic Sys, Inc, authorizing use of tritium, C-14, P-32, S-35, Cr-51, I-125, I-131 & Se-75, in any form, for R&D, per B20930 application & B31029 ltr
GLENN, J E Region 1, Office of Director 83/01/26 2pp
21732 099
- B401040274 Source Matl License SUB-1427 for ManLabs, Inc, authorizing use of U-235, as metal & alloys, for metallurgical testing, per B30421 application & O&O6 ltr
JERMAN, P C Division of Fuel Cycle & Material Safety 83/06/21 1p 21732 101
- B401040282 Amend 2 to Source Matl License SUB-706 for Myerson Tooth Corp, authorizing use of natural U as sodium uranate, for colorant in artificial teeth, per 790314 application & O&19 & O803 ltrs
BASSIN, N Material Licensing Branch 79/09/24 2pp 21732 102
- B401040287 Amend 5 to License SNM-71 for Harvard Univ, changing licensee address, per B20729 ltr
GLENN, J E Division of Fuel Cycle & Material Safety 82/10/12 1p. 21732 106
- B401040294 "NRC Rules & Regulations, 10CFR9: Public Records "
* NRC - No Detailed Affiliation Given, 82/09/01 24pp
21732 110
- B401040296 List of licensees & assigned license numbers for Cambridge, MA area.
* NRC - No Detailed Affiliation Given 83/10/04 1p. 21732 134
- B401040044 Responds to FOIA request for records re review of structural adequacy of diesel generator bldg at facilities subsequent to May testimony of R Landsman in ASLB proceeding.
FELTON, J M Division of Rules and Records 83/10/27. GARDE, B P Government Accountability Project 3pp 21714 289 24X Fiche 50-329, 83/10/27, B401040044
- B310280277 Forwards initial response to RB Landsman concerns on structural integrity of diesel generator bldg, as prepared during B30728 working meeting w/consultants J Matra & Q Harstead
RINALDI, F Structural & Geotechnical Engineering Branch, 83/10/21 KUD, P T Structural & Geotechnical Engineering Branch 10pp 21714 299 24X Fiche 50-329, 83/10/27, B401040044
- B401040048 "Comments on J Matra Study - Structural Reanalysis of Diesel Generator Bldg "
KANE, J NRC - No Detailed Affiliation Given 83/02/12 2pp
21714 292.
- B401040052 "Review Comments of J Kane, Diesel Generator Bldg Concerns at Midland "
KANE, J NRC - No Detailed Affiliation Given 83/10/27 5pp
21714 294 24X Fiche 50-329, 83/10/27, B401040044
- B401040146 FOIA request for PNO-III-83-76
DISPIGNO, V W Gamma Diagnostic Laboratories 83/10/12 NRC - No Detailed Affiliation Given 1p 21714; 294
- B401040149 Responds to FOIA request for PNO-III-83-76 Forwards requested document
FELTON, J M Division of Rules and Records 83/10/26 DISPIGNO, V W Gamma Diagnostic Laboratories, 1p 21714 235
- B401040154 FOIA request for documents re total expenditure between time contract initiated & closed out for FTN A-1123, performed by Sandia Natl Labs & subcontractors for NRC.
RILEY, J L. Affiliation Unknown FIN A-1123, 83/09/13. FELTON, J M Division of Rules and Records, 1p. 21714 316
- B401040159 Partial response to FOIA request for documents re total expenditure between time contract initiated & closed out for FIN A-1123, performed by Sandia Natl Labs & subcontractors for NRC Forwards requested info
FELTON, J M Division of Rules and Records FIN A-1123, 83/09/29 RILEY, J L Affiliation Unknown 1p 21714-317.
- B401040164 Excerpt from "Regulation Field Costs as Reported Through FIS by Financial Plan Organization & FIN Number, FY82 (Through Sept 30, 1982) "
* NRC - No Detailed Affiliation Given 82/11/03 3pp
21714 318
- B401040171 FOIA request for "Rept on Investigation of Allegations of Breaches of Confidentiality re OPU in Stress Control Relationships."
WISE, J R. Debevoise & Liberman 83/09/07 FELTON, J M Division of Rules and Records, 1p 21714-237

NONDOCKETED ITEMS

- 8401040177 Responds to FOIA request for "Rept on Investigation of Allegations of Breaches of Confidentiality re QPU in Stress Control Relationships " NRC unable to identify requested rept.
FELTON, J M Division of Rules and Records 83/10/27. WISE, J R. Debevoise & Liberman 1p 21714:238
- 8401040188 Responds to FOIA request for five categories of documents re NRC 831121 meeting w/nuclear industry degraded core rulemaking program representatives. Forwards listed documents
FELTON, J M Division of Rules and Records 83/12/01. SKOLLY, S C Union of Concerned Scientists. 1p 21714:241.
- 8401040191 Notification of canceled 831121 meeting w/nuclear industry degraded core group in Chicago, IL to discuss alternatives of various decision approaches for severe accidents Agenda encl.
MATTSON, R J. Division of Systems Integration (post 811005). 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21714:242
- 8401040221 FOIA request for working paper on App J to 10CFR50, "Leak Tests for Primary & Secondary Containments of Light-Water-Cooled Nuclear Power Plants "
GRABER, L D. NUS Corp. CD-18-83-396 83/09/28 Division of Rules and Records. 1p. 21714:153.
- 8401040225 Responds to FOIA request for working paper on App J to 10CFR 50, "Leak Tests for Primary & Secondary Containments of Light-Water-Cooled Nuclear Power Plants." Forwards requested document. Document also available in PDR
FELTON, J M. Division of Rules and Records 83/10/21. GRABER, L D NUS Corp 1p 21714:154
- 8401040228 Marked-Up Working Paper D re "Domestic Licensing of Production & Utilization Facilities, App J Leak Tests for Primary & Secondary Containments of Light-Water-Cooled Nuclear Power Plants."
ARNOLD, C NRC - No Detailed Affiliation Given 82/05/17 30pp 21714:155.
- 8401040404 FOIA request for list of NRC research programs in progress at Sandia Natl Labs, ANL, Battelle, ORNL, LLL & BNL
DOVE, K. L. 83/10/05. FELTON, J M Division of Rules and Records 1p. 21714:185.
- 8401040606 Responds to FOIA request for list of NRC research programs in progress at Sandia Natl Labs, ANL, Battelle, ORNL, LLL & BNL Forwards requested list.
FELTON, J M. Division of Rules and Records 83/10/21. DOVE, K Dove, K. L. 7pp 21714:186
- 8401040607 List of NRC research programs in progress at Sandia Natl Labs, ANL, Battelle, ORNL, LLL & BNL.
* NRC - No Detailed Affiliation Given. 83/10/17 6pp. 21714:187.
- 8401040609 FOIA request for "People Against Nuclear Energy Draft Contentions" re facility restart.
WILEY, D K Affiliation Unknown. 83/09/26. Office of Administration. 1p. 21714:195. 24X Fiche: 50-289, 83/09/26.
8401040609
- 8401040611 Responds to FOIA request for "People Against Nuclear Energy Draft Contentions." Forwards requested document.
FELTON, J M Division of Rules and Records. 83/10/21 WILEY, D K. Affiliation Unknown. 1p. 21714:195 24X Fiche: 50-289, 83/10/21.
8401040611.
- 8401040614 FOIA request for minutes of CROR 830810 meeting re integrated safety assessment program.
PHILIPS, M H Debevoise & Liberman 83/09/07. FELTON, J M. Division of Rules and Records. 1p. 21714:200.
- 8401040616 Responds to FOIA request for minutes of CROR 830810 meeting re integrated safety assessment program Requested document entirely withheld (ref FOIA Exemption 5).
FELTON, J M. Division of Rules and Records. 83/10/20. PHILIPS, M H. Debevoise & Liberman. 2pp. 21714:201.
- 8401040617 FOIA request for documents made available under B Hafner FOIA Request 83-386, for list of inaccessible sys in containment considered to be safety-related for facility.
EARLEY, A F. Hutton & Williams. 83/10/03. FELTON, J M Division of Rules and Records. 1p. 21714:203 24X Fiche: 50-322, 83/10/03.
8401040617.
- 8401040620 Responds to FOIA request for documents made available under B Hafner FOIA Request 83-386 Requested documents available in PDR
FELTON, J M Division of Rules and Records 83/10/19 EARLEY, A F Hutton & Williams 1p 21714:204
- 8401040621 FOIA request for documents re legal aspects of establishing in-state-only low level radwaste disposal facilities
CONRAD, J W Affiliation Unknown 83/10/04 FELTON, J Division of Rules and Records 1p 21731:289
- 8401040623 Responds to FOIA request for documents re legal aspects of establishing in-state-only low level radwaste disposal facilities Forwards documents
FELTON, J M Division of Rules and Records 83/10/25 CONRAD, J W Affiliation Unknown 1p 21731:290
- 8406130374 Responds to 800220 & 0429 legal questions re low-level waste storage W/encl
BHAPAR, H Office of the Executive Legal Director 80/05/13 DIRCKS, W J Office of Nuclear Material Safety & Safeguards, Director 18pp 21731:291
- 8401050027 FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies Supporting ltrs encl.
CALSDYAB, C D Affiliation Unknown 83/10/10 NRC - No Detailed Affiliation Given 4pp 21736:232 24X Fiche 50-000, 83/10/10.
8401050027
- 8401050038 FOIA request for application for license, correspondence re application & actual radioactive matls license for nuclear pharmacy facility operated by Mallinckrodt in Philadelphia, PA
MCDONALD, D D Nuclear Pharmacy, Inc DDM 983-01. 83/09/06 FELTON, J M Division of Rules and Records 1p 21742:049
- 8401050040 Partial response to FOIA request for application for license, correspondence re application & actual radioactive matls license for facility operated by Mallinckrodt Info partially withheld (ref FOIA Exemption 6)
FELTON, J M Division of Rules and Records 83/10/04 MCDONALD, D D Nuclear Pharmacy, Inc 2pp 21742:001
- 8401050045 Amend 1 to Matl/Byproduct License 37-21345-01MD, revising Condition 12 re users of licensed matl
VACCA, P C Division of Fuel Cycle & Material Safety 83/08/09 1p 21742:051
- 8401050051 Matl/Byproduct License 37-21345-01MD for Mallinckrodt, Inc, authorizing use of Mo-99, I-131, Xe-133, Tc-99m & 10CFR35 matl in various forms for listed uses, per 830408 application & 830630 & 0719 ltrs
VACCA, P C Division of Fuel Cycle & Material Safety 83/08/05 3pp 21742:052.
- 8401050056 Expresses appreciation for assistance in locating suppl to vendor license
COLE, C N. Mallinckrodt, Inc 83/08/05 VACCA, P. Division of Fuel Cycle & Material Safety 1p 21742:057.
- 8401050060 Forwards training & experience records for listed individuals, in response to NRC request re application for byproduct matls license
COLE, C N Mallinckrodt, Inc 14525 83/08/04 DELMEDICO, J Division of Fuel Cycle & Material Safety 5pp 21742:058
- 8401050065 Forwards distribution license for Folcroft facility Au-198 not commercially available from supplier in US & not included on license. Addl info, per 830728 meeting, requested
DELMEDICO, J. Division of Fuel Cycle & Material Safety. 14525 83/08/05 COLE, C N. Mallinckrodt, Inc 2pp 21742:063
- 8401050068 Forwards State of PA pharmacy permit & emergency plan to b followed in event of accidental release of radioactive gas, in response to NRC request at 830728 meeting.
COLE, C N Mallinckrodt, Inc. 1104 83/08/01. DELMEDICO, J Division of Fuel Cycle & Material Safety 3pp 21742:065
- 8401050071 Submits info re application for byproduct matl license, per 830713 telcon. Licensing statement, radiation protection, program & Xe-133 & Xe-127 gas stability data encl Related telcon record encl
COLE, C N, HAGEN, K A Mallinckrodt, Inc 14525 83/07/19. DELMEDICO, J. Division of Fuel Cycle & Material Safety 15pp 21742:068

NONDOCKETED ITEMS

417

--8401050073 Responds to 830607 request for info re application for matl/byproduct license Compliance & radiation safety audits will be performed quarterly by DW Saldan
COLE, C N, HAGEN, K A Mallinckrodt, Inc 0916 83/06/30
DELMEDICO, J Division of Fuel Cycle & Material Safety 5pp
21742 083

--8401050076 "Radiation Protection Program " Related info encl
* Mallinckrodt, Inc 14525 83/10/04 29pp 21742 088

--8401050078 Procedure A-02, "Thyroid Bioassay " Related info encl
* Mallinckrodt, Inc 83/06/03 13pp 21742 117

--8401050080 Procedure 74710B, "Insp Requirements "
* Mallinckrodt, Inc 76/10/01 15pp 21742 130

--8401050082 Procedure A-06, "Receiving & Opening RAM Packages "
* Mallinckrodt, Inc 83/10/04 2pp 21742 145

--8401050083 Procedure A-08, "Personnel Contamination Surveys " Related info encl
* Mallinckrodt, Inc 83/06/22 10pp 21742 147

--8401050088 Requests addl info re 830408 application for byproduct matl license Survey meter capable of reading up to 1 roentgen per h should be available to measure radiation doses near Tc-99m generators
DELMEDICO, J Division of Fuel Cycle & Material Safety 14525
83/06/07 COLE, C N Mallinckrodt, Inc 8pp 21742 137

--8401050091 Forwards application for matl/byproduct license authorizing possession, storage & distribution of radiopharms
COLE, C N Mallinckrodt, Inc 14525 83/04/08 Division of
Fuel Cycle & Material Safety 2pp 21742 165

--8401050095 Application for matl/byproduct license authorizing use of Mo-99, Tc-99m, Xe-133, I-131, Co-57, Cs-137, Ba-133, I-129, Xe-127 & I-125 matls in various forms for uses specified Related info encl
COLE, C N Mallinckrodt, Inc 02120 83/04/08 50pp. 21776:293

--8401050100 Procedure A-01, "TLD Badge Program "
* Mallinckrodt, Inc 14525 81/01/30 5pp 21742 244

--8401050103 Procedure A-02, "Urinalysis Program "
* Mallinckrodt, Inc. 81/01/30 5pp 21742 249

--8401050106 Procedure A-03, "Air Sampling Program Ga-67/TL-201 "
* Mallinckrodt, Inc 81/01/30 3pp 21742 254

--8401050109 Procedure A-04, "Instrument Calibr "
* Mallinckrodt, Inc 81/01/30. 5pp 21742.257

--8401050113 Procedure A-05, "Records of Receipt, Transfer & Disposal."
* Mallinckrodt, Inc. 81/01/30. 2pp 21742.262

--8401050117 Procedure A-06, "Receiving & Opening RAM Packages."
* Mallinckrodt, Inc 81/04/29. 2pp 21742 264

--8401050120 Procedure A-07, "Loose Contamination Level Survey "
* Mallinckrodt, Inc 81/01/30 3pp. 21742 266

--8401050123 Procedure A-08, "Personal Contamination Surveys "
* Mallinckrodt, Inc 81/01/30 1p 21742.269

--8401050127 Procedure A-09, "Radiation Level Survey "
* Mallinckrodt, Inc 81/04/29 3pp 21742.270

--8401050130 Procedure A-10, "Self-Reading Dosimeter Program."
* Mallinckrodt, Inc 81/01/30 1p 21742 273.

--8401050133 Procedure A-11, "Radwaste Matls Mgt Ga-67/TL-201 "
* Mallinckrodt, Inc. 81/01/30 3pp 21742 274

--8401050137 Procedure A-12, "Emergency Response Call List "
* Mallinckrodt, Inc. 81/02/03. 2pp 21742.277

--8401050138 Procedure A-13, "Emergency Planning "
* Mallinckrodt, Inc 14525 81/04/29 3pp 21742.279

--8401050143 Forwards revised training & experience forms clarifying FM Guyann & BD Scavullo experience, per 830808 telcon
Telcon record encl
COLE, C N Mallinckrodt, Inc 1139 83/08/08 VACCA, P Division
of Fuel Cycle & Material Safety 5pp 21742 282

8401050043 Responds to FOIA request for info re whether facilities rated for earthquakes by Lloyds of London or other rating agencies NRC has no records subj to request Utilte not required to submit insurance rating to NRC.
FELTON, J M Division of Rules and Records 83/10/25 CALBOVAS, C N
Affiliation Unknown 1p 21736 236 24X Fiche 50-000, 83/10/25, 8401050043

8401050064 FOIA request for 27 listed LERs
GRABER, L D NUS Corp CD-16-83-439 83/10/07 Division of Rules
and Records 2pp 21736 343 24X Fiche 50-000, 83/10/07, 8401050064

8401050075 Responds to FOIA request for 27 LERs Forwards three listed LERs. Remaining LERs unavailable in NRC records sus, canceled, or never issued
FELTON, J M Division of Rules and Records 84/10/25. GRABER, L D
NUS Corp 1p 21736 345 24X Fiche 50-000, 83/10/25, 8401050075

--8401050085 LER 83-002/03L-0 on 830307, safety-related shock suppressor safety injection sys 134 removed to accommodate maint on control element drive mechanism & not replaced within 72 h after core reloading begun Snubber replaced, W/830406 ltr
BURGORA, F M O, JONES, W C, Omaha Public Power District FC-194-83
83/03/22 SEIDLE, W C Region 4, Office of Director 5pp.
21736 349 24X Fiche 50-000, 83/10/25, 8401050075

8401050171 Further response to FOIA request for documents re preparations by Govt of India for nuclear test site. Forwards App A documents App B documents partially & entirely withheld (ref FOIA Exemptions 1, 4 & 5)
FELTON, J M Office of Administration 83/10/21 LEVENTHAL, P L
Nuclear Control Institute. 4pp 21743 193.

--8401050189 Forwards cables providing official clarification of news reports re Govt of India reprocessing plans W/o encl
PETERSON, M R Assistant Director for Export/Import & International
Safetyguards 81/04/21 HASSELL, D, GOLDSMITH, R., GIBSON, T
Commissioners 1p 21743.200

--8401050192 Forwards NRC questions & answers re health & safety concern at Tarapur Nuclear Power Plant info deleted.
DIRCKS, W J Office of the Executive Director for Operations.
83/05/23. PALLADINO, N J, GILINSKY, V, AHEARNE, J F
Commissioners 7pp. 21743.201

8401060031 FOIA request for IE tabulation of BALP results during 1982 (ref Page 7 of encl Public Citizen 1983 Nuclear Power Safety Rept)

IAHLER, R E Shaw, Pittman, Potts & Trowbridge 83/10/07. Office
of Administration 2pp 21744:001.

8401060040 Responds to FOIA request for IE tabulation of BALP results during 1982. Forwards IE notebook tabulating requested info Notebook also available in PDR
FELTON, J M Division of Rules and Records 83/10/20 IAHLER, R E.
Shaw, Pittman, Potts & Trowbridge 1p 21744.003. 24X
Fiche 50-000, 83/10/20, 8401060040.

--8401060150 List of BALP results during 1982
* Director's Office, Office of Inspection and Enforcement.
83/10/20. 103pp. 21744.004 24X Fiche 50-000, 83/10/20, 8401060040

8401090580 Further response to FOIA request for four categories of documents re facility restart Listed documents available in PDR.
FELTON, J M. Division of Rules and Records 83/10/04 ADATO, M
Union of Concerned Scientists 1p 21766 125. 24X
Fiche 50-289, 83/10/04, 8401090580

8401090693 Responds to FOIA request for document prepared by NRC in response to objectives of 1981 Executive Order, "Natl Emergency Preparedness Plan " IE informed that consolidated agency plan never developed
FELTON, J M. Division of Rules and Records 83/12/30 ISENBERG, D.
Pacific Northwest Research Center. 1p 21757.341

8401090697 FOIA request for document prepared by NRC in response to objectives of 1981 Executive Order, "Natl Emergency Preparedness Plan "
ISENBERG, D Pacific Northwest Research Center 83/12/09. NRC -
No Detailed Affiliation Given. 2pp. 21757.342

NONDOCKETED ITEMS

- 8401100020 Further response to FOIA request for 3 categories of documents Forwards documents
FELTON, J. M. Division of Rules and Records 83/09/27 SHOLLY, S. C.
Union of Concerned Scientists 1p 21777 179.
- 8401100025 NUREG/CR-3268 DR V01
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
1 - Main Rept
VARNADO, G. B. Sandia Laboratories HORTON, W. H. Science
Applications, Inc. FIN A-1360. SAND83-0963 83/07/31
Division of Risk Analysis. 70pp 21777:180.
- 8401100030 NUREG/CR-3268 DR V02
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
2 - Appendices A to C
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360
SAND83-0963 83/07/20. Division of Risk Analysis 500pp
21777 250
- 8401100037 NUREG/CR-3268 DR V03
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
3 - Appendices D to H
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360
SAND83-0963 83/07/20 NRC - No Detailed Affiliation Given
434pp. 21779 053
- 8401100040 NUREG/CR-3268 DR V04
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
4 - Appendix I
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360.
SAND83-0963 83/07/20 NRC - No Detailed Affiliation Given
155pp. 21780 127.
- 8401100082 Further response to FOIA request for application for
license, correspondence re application & actual radioactive
matls license for nuclear pharmacy operated by Mallinckrodt
Forwards requested documents Documents also in PDR
FELTON, J. M. Division of Rules and Records 83/10/11 McDONALD, D. D.
Nuclear Pharmacy, Inc. 1p 21776:284
- 8401100084 Matl/Byproduct License 37-21345-01MD for Mallinckrodt, Inc.
authorizing Mo-99, Xe-133, I-131, Tc-99m & 10CFR35 matl in
specified forms for listed uses, per 830408 application &
830630 & 0719 ltrs.
VACCA, P. C. Material Licensing Branch 83/08/05 6pp 21776 285
- 8401100087 Amend 1 to Matl/Byproduct License 37-21345-01MD, authorizing
use of licensed matl by RA Sheriff, KA Hagen, CE Wood,
DW Sullivan, CE Cole, BD Scavullo & FM Gwynn, per 830804 ltr
VACCA, P. C. Material Licensing Branch 83/08/09 1p 21776 291
- 8401100090 Forwards application for radioactive matls license
COLE, C. N. Mallinckrodt, Inc. 14525. 83/04/08. Office of
Nuclear Material Safety & Safeguards, Director. 1p 21776:292.
- 8401100098 Requests addl info re type & frequency of compliance &
radiation safety audits to be performed & identity of
individual performing audits
DELMEDICO, J. Material Licensing Branch 14525 83/06/07
COLE, C. N. Mallinckrodt, Inc. 7pp. 21777:048
- 8401100102 Responds to 830607 ltr re application for matl/byproduct
license Compliance & radiation safety audits will be
performed quarterly by D Bolden
COLE, C. N., HAGEN, K. A. Mallinckrodt, Inc. 0916. 83/06/30
DELMEDICO, J. Material Licensing Branch 73pp 21777:055
- 8401100105 Responds to 830713 conversation re application for matl/
byproduct license, Xe-133 will be stored in glove box within
pharmacy area Results of Xe-133 gas vial retention study
encl
COLE, C. N., HAGEN, K. A. Mallinckrodt, Inc. 14525 83/07/19.
DELMEDICO, J. Material Licensing Branch 13pp 21777:128
- 8401100109 Responds to 830728 meeting re application for matl/byproduct
license, Xenon gas filled vials in stability study dtd 830721
assayed w/Radar Corp Assayer I dose calibrator, PA State
Board of Pharmacy permit encl
COLE, C. N. Mallinckrodt, Inc. 1104 83/08/01. DELMEDICO, J.
Material Licensing Branch. 3pp. 21777:141.
- 8401100111 Forwards training & experience records for CN Cole, FM Gwynn
& BD Scavullo
COLE, C. N. Mallinckrodt, Inc. 14525. 83/08/04 DELMEDICO, J.
Material Licensing Branch. 7pp. 21777:144.
- 8401100116 Forwards supplemental info to application for matl/byproduct
license
COLE, C. N. Mallinckrodt, Inc. 15525. 83/08/05 VACCA, P.
Material Licensing Branch. 7pp 21777:151
- 8401100118 Forwards revised training & experience forms clarifying
Gwynn & Scavullo experience at Mallinckrodt facility in
Folcroft, PA
COLE, C. N. Mallinckrodt, Inc. 15525 83/08/08 VACCA, P.
Material Licensing Branch 5pp 21777 157
- 8401160360 FOIA request for BJ Chilk 820608 memo to L Bickwit &
MQ Malsch 830207 memo to NJ Palladino re imposition of civil
penalties for matl false statements to be placed in PDR
BUCKLES, R. NUS Corp CD-18-83-285 83/08/23 Division of Rules
and Records 1p 21834 232
- 8401160365 Responds to FOIA request for 820608 & 830207 memos re
imposition of civil penalties for matl false statements to
be placed in PDR Forwards similar, partially deleted 820608
memo Memo dtd 830207 withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records 83/10/26 BUCKLES, R.
NUS Corp 2pp 21834 233
- 8401160370 Staff requirements memo re 820528 enforcement action
conference concerning proposed Commission authorization to
impose civil penalties for matl false statements Info
deleted
CHILK, B. J. Office of the Secretary of the Commission 82/06/08
DIRCKS, W. J. Office of the Executive Director for Operations 1p
21834 235
- 8401160373 Further response to FOIA request for documents re cleanup &
decision to close down U mill in Edgemont, BD Forwards
W Dircks 800515 note to J Martin review of remaining
documents subj to request in progress
FELTON, J. M. Division of Rules and Records 83/11/09 GARGUS, M.
Frankfurt, Gargus, Klein & Selz 1p 21836 247
- 8401160379 Forwards info re Edgemont, U mill tailings
DIRCKS, W. Office of the Executive Director for Operations
80/05/15 MARTIN, J. NRC - No Detailed Affiliation Given 5pp
21836 249
- 8401160385 FOIA request for four categories of documents
HIATT, B. L. Ohio Citizens for Responsible Energy 83/09/27
FELTON, J. M. Division of Rules and Records 1p 21836 030 24X
Fiche: 50-440, 83/09/27, 8401160385.
- 8401160390 Responds to FOIA request for four categories of documents
Forwards App A documents Request for documents released
under FOIA Request 83-506 pending
FELTON, J. M. Division of Rules and Records. 83/10/26 HIATT, B. L.
Ohio Citizens for Responsible Energy 3pp 21836 031 24X
Fiche: 50-440, 83/10/26, 8401160390
- 8401160396 Agenda for review meeting w/EPRI & Nuclear Safety Analysis
Ctr to discuss hydrogen combustion demonstration test at
NV Test Site
* NRC - No Detailed Affiliation Given. 83/09/02 NRC - No
Detailed Affiliation Given 3pp 21836 038
- 8401160400 Discusses assignments for std problem & review of
experimental results, per 830719 meeting Related info encl
SILBERBERG, M. Accident Source Term Program Office 83/07/29
Accident Source Term Program Office 107pp 21836 041
- 8401160402 "Rept of Steam Spike Std Problem," Related info encl
THEOFANOUS, T. O., NOURBAKHSHI, H. P., YANG, J. W. Purdue Univ., West
Lafayette, IN. 83/10/26 31pp 21836 147
- 8401160403 Forwards description of calculations for Containment Loads
Working Group, in response to 830729 ltr
HASKIN, F. E. Sandia Laboratories 83/09/01 SILBERBERG, M.
Accident Source Term Program Office 19pp 21836 198
- 8401160407 "Evaluation & Assessment of Steam Spike Experiments"
THEOFANOUS, T. O., GINSBERG, T. Purdue Univ., West Lafayette, IN
83/10/26 16pp. 21836 231
- 8401160421 FOIA request for magnetic tape matl license master file
Record layout describing file encl
TODD, W. E. Siemens Gammasonics, Inc. 83/10/07 CARR, J. NRC - No
Detailed Affiliation Given. 5pp 21824 280
- 8401160426 Responds to FOIA request for magnetic tape matl licensing
master file Forwards excerpt containing requested
explanation of codes. Tape will be sent under separate cover
FELTON, J. M. Division of Rules and Records 83/10/28 TODD, W. E.
Siemens Gammasonics, Inc. 1p 21824 285
- 8401160428 Master file data element definitions.
* NRC - No Detailed Affiliation Given M/L-005/006 83/10/07
9pp. 21824 286

- 401160431 FOIA request for documents re general counsel interpretations under 10CFR50.3 & official interpretation re QA descriptions
RUHLMAN, W A Theophilus, Inc 83/10/13 Office of the General Counsel 2pp 21824 277
- 401160435 Responds to FOIA request for documents re general counsel interpretations under 10CFR50.3 Documents pertaining to request nonexistent Further request for official interpretation under consideration
FELTON, J M Division of Rules and Records 83/11/01 RUHLMAN, W A Theophilus, Inc 1p 21824 279
- 401160436 FOIA request for SECY-83-301 & SECY-83-312 to be placed in PDR
GRABER, L D NUS Corp CD-18-83-416 83/10/04 Division of Rules and Records 1p 21824 274
- 401160437 Responds to FOIA request for SECY-83-301 & SECY-83-312 to be placed in PDR Requested documents withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/10/28 GRABER, L D NUS Corp 2pp 21824,275
- 401160440 FOIA request for Contract NRC-31-83-661 & amends
FANNING, M K Northern Telecom NRC-31-83-661 83/10/24 Division of Contracts 1p 21824 272
- 401160442 Responds to FOIA request for Contract NRC-31-83-661 & amends Contract & two mods available in PDR
FELTON, J M Division of Rules and Records NRC-31-83-661, 83/11/01 FANNING, M K Northern Telecom 2pp 21824 273
- 401160445 FOIA request for draft or final Hoyt investigation rept re Facility
LEGNITTO, J CBS News, CBS, Inc 83/10/12 FELTON, J M Division of Rules and Records 1p 21824 270 24X Fiche 50-358, 83/10/12, 8401160445
- 401160446 Responds to FOIA request for Hoyt rept Release of Hoyt rept currently before Commission No info available at present time
FELTON, J M Division of Rules and Records 83/10/28 LEGNITTO, J CBS News, CBS, Inc 1p, 21824 271 24X Fiche 50-358, 83/10/28, 8401160446
- 401160448 FOIA request for draft memo from R Mattson to H Denton, "Resolution of Reactor Coolant Pump Trip Issue," referenced in NUREG-0933, to be placed in PDR
GRABER, L D NUS Corp CD-18-83-411 83/10/03 Division of Rules and Records 1p 21835 286
- 401160452 Responds to FOIA request for placement of draft memo from R Mattson to H Denton, "Resolution of Reactor Coolant Pump Trip Issue," referenced in NUREG-0933, in PDR Forwards documents Document also available in PDR
FELTON, J M Division of Rules and Records 83/10/21 GRABER, L D NUS Corp 1p 21835 287
- 8208230015 Submits for concurrence, proposed resolution of reactor coolant pump (RCP) trip issue per request Discussions w/ industry representatives on RCP trip during accidents encl
MATTSON, R J Division of Systems Integration (post 811005) 82/07/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 21835 340
- 8401160454 Submits for concurrence, proposed resolution of reactor coolant pump (RCP) trip issue per request Discussions w/ industry representatives on RCP trip during accidents encl. Draft ltr
MATTSON, R J Division of Systems Integration (post 811005) 81/07/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 21835 288
- 401160460 Further response to FOIA request for 42 categories of documents Forwards requested documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/10/14 SHOLLY, B C Union of Concerned Scientists 1p 21826 309
- 8107160006 Discusses operating experience repts on safety injection actuations on US PHRs Rept focuses on unnecessary challenges of safety injection sys, but provides recommendations to improve emergency & test procedures.
FOUREST, B Operating Experience Evaluation Branch, 81/06/11 ERNST, M L Assistant Director for Technology Review 21pp, 21826 306
- 8208110023 Forwards rept of completion of NUREG-0737, Item III D 2 4(2), "Offsite Dose Measurements " Followup assignments necessary in order to complete item
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/06/30 DIRCKS, W J Office of the Executive Director for Operations 5pp 21827 054
- 8303090323 Forwards completed rept on TMI Action Item III A 3 1 re nuclear emergencies & Manual Chapter 0502, "NRC Incident Response Plan "
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/01/26 DIRCKS, W J Office of the Executive Director for Operations 28pp 21827 059
- 8303090540 Discusses prioritization of generic issues re environ & licensing improvements Evaluation of environ issues encl
FUNCHES, J L Planning & Program Analysis Staff 83/02/24 SPEIS, T P Division of Safety Technology 14pp 21826 349
- 8401160472 Comments on short & long-term NRRD needs for improved seismic analysis methodology per seismic safety margins research program & long-range research plan (NUREG-0784) Needs, goals & comprehensive program plan summary listed.
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/04/07 MINOQUE, R B Office of Nuclear Regulatory Research, Director 14pp 21827 001
- 8401160474 Responds to 821220 request for prioritization of non-NRRD TMI action plan items draft rept work scope & completion schedules
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 21827 015
- 8401160475 Forwards comments on prioritization of non-NRRD TMI action plan items draft rept, per 821220 memo Prioritization methodology used to rank generic issues acceptable
MINOQUE, R B Office of Nuclear Regulatory Research, Director 83/03/29 DENTON, H Office of Nuclear Reactor Regulation, Director 29pp 21827 025.
- 8401170015 Further response to FOIA request for 42 documents Forwards Documents 14 & 20 Documents also available in PDR.
FELTON, J M Division of Rules and Records 83/10/25 SHOLLY, B C Union of Concerned Scientists 1p 21837 307
- 8204260021 Discusses Containment Sys Branch review of Accident Evaluation Branch generic evaluation of radiological consequence of containment purging & venting while reactor pressurized, item considered complete.
SPEIS, T Assistant Director for Reactor Safety 82/04/09 MATTSON, R J Division of Systems Integration (post 811005) 4pp 21837 340
- 8401170018 Responds to 820225 memo re draft licensing guidelines for implementation of NUREG-0666, Recommendation 4 concerning Generic Issue A-30, "Adequacy of Safety-Related DC Power Supplies " Concern could be met w/o major mod
PARR, D D Auxiliary Systems Branch SHERON, B, Reactor Systems Branch 82/03/12 SRINIVASAN, M Power Systems Branch, 2pp 21837 312
- 8401170021 Forwards, status rept on radiological consequences of containment venting & purging while reactor pressurized TMI Action Plan Item II E 4, 4 addressed in SRP 6 2 4 & Branch Technical Position CSB 6-4
MATTSON, R J Division of Systems Integration (post 811005) 82/05/13 DIRCKS, W J Office of the Executive Director for Operations 3pp 21837 314
- 8401170023 Forwards generic safety evaluation of radiological consequences of containment venting & purging while reactor pressurized, per NUREG-0737, Item II E 4 2, SRP 6 2 4 & Branch Technical Position 6-4
HOUSTON, R W Assistant Director for Radiation Protection 82/03/03 SPEIS, T P Assistant Director for Reactor Safety 23pp 21837 317
- 8401170026 Final response to FOIA request for rept re mgt integrity issues for TMI-1 restart, SECY-83-167 & SECY-83-198, Rept & SECY-83-167 addressed in 830916 ltr SECY-83-198 entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/10/20 RYAN, M L McQuay-Norris Publications Co 1p 21837:362, 24X Fiche 50-289, 83/10/20, 8401170026
- 8401170029 Further response to FOIA request for 14 categories of documents Forwards app documents, Info also available in PDR DOE & Sandia Natl Labs should be contacted for Items 1, 2 & 12 & Items 5 & 14-16, respectively
FELTON, J M Division of Rules and Records, 83/10/11 SHOLLY, B C Union of Concerned Scientists 3pp 21839, 276

NONDOCKETED ITEMS

- B001230101 Info requested by 790921 memo has not been received Memo of understanding re division of responsibility for reactor safeguards matters will be utilized as interim practice
EISENHUT, D. G. Division of Operating Reactors. 80/01/04
BURNETT, R. F. Division of Safeguards 1p. 21837 325
- B003130526 Forwards draft Div of Nuclear Reactor Regulation/NMSS memorandum of understanding re responsibility for reactor safeguards matters Reactor safeguard interactions will be handled through Safeguards Interface Group
EISENHUT, D. G. Division of Operating Reactors 80/01/10
VOLLMER, R. H. Division of Operating Reactors 5pp 21839:320
- B003130530 Forwards draft Div of Nuclear Reactor Regulation/NMSS memorandum of understanding re responsibility for reactor safeguards
EISENHUT, D. Division of Operating Reactors 79/09/21
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 21837, 326
- B401170033 BAND75-6157
"Effectiveness Evaluation of Alternative Fixed-Bite Safeguard Security Sys." presented at 760712-14 Summer Computer Simulation Conference in Washington, DC
CHAPMAN, L. D. Sandia Laboratories 76/07/12 17pp. 21837, 281.
- B401170035 BAND75-0658
"Security Force - Adversary Engagement simulation," presented at 751218-19 Winter Computer Conference in Sacramento, CA
BENNETT, H. A. Sandia Laboratories 76/04/30 22pp 21837 298
- B401170032 FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const.
GANULIN, R. Ohio, State of. 83/09/30. Office of Administration. 2pp. 21837:001 24X Fiche 50-440, 83/09/30, 8401170032.
- B401170034 Responds to FOIA request for documents re 1982 & 1983 Caseload Forecast Panel meetings concerning facility const
Forwards App A documents
FELTON, J. M. Division of Rules and Records 83/10/21 GANULIN, R. Ohio, State of 3pp. 21837 003. 24X Fiche 50-440, 83/10/21, 8401170034.
- B21180523 Recommends mgt level meeting w/util in Bethesda or caseload forecast panel site visit prior to 821231, since some review areas may have licensing impact
NOVAK, T. M. Assistant Director for Licensing 82/11/12
EISENHUT, D. G. Division of Licensing 2pp. 21837 302 24X Fiche 50-440, 83/10/21, 8401170034.
- B401170036 Graph of preoperational & acceptance testing of facility components
* Affiliation Unknown 82/01/11 3pp. 21837:008 24X Fiche 50-440, 83/10/21, 8401170034.
- B401170038 Discusses cancellation of 830321 Caseload Forecast Panel mgt meeting due to slip of fuel load to Dec 1984 Press release will be issued by util
STEFANO, J. J. Licensing Branch 1. 83/03/08 NOVAK, T. M. Assistant Director for Licensing 3pp 21837:011. 24X Fiche 50-440, 83/10/21, 8401170034
- B401170042 Info re facility const. Related info encl
* Cleveland Electric Illuminating Co. 83/10/21 50pp 21837 063 24X Fiche 50-440, 83/10/21, 8401170034
- B401170044 Handwritten notes re facility const.
* Affiliation Unknown 81/10/07 5pp 21837 221. 24X Fiche 50-440, 83/10/21, 8401170034.
- B401170048 Handwritten "Piping Status " Related info encl
* Affiliation Unknown. 79/10/31. 16pp 21837:233 24X Fiche: 50-440, 83/10/21, 8401170034.
- B401170051 "Progress for Perry." Related info encl.
* Affiliation Unknown. 79/11/13. 5pp. 21837:256 24X Fiche: 50-440, 83/10/21, 8401170034.
- B401170052 Partial response to FOIA request for 42 categories of documents. Forwards listed documents. Documents also available in PDR. Review of addl records subj to request in progress
FELTON, J. M. Division of Rules and Records. 83/10/03. SHOLLY, B. C. Union of Concerned Scientists. 1p. 21846:163.
- B203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NUREG-0660, Item II E 5 1, design sensitivity of B&W reactors Lists of NUREG-0667 recommendations reviewed & NRC evaluation encl
MATTBON, R. Division of Systems Integration (post 811005) 82/02/26 HANAUER, S. Division of Safety Technology 25pp 21846 227 24X Fiche 50-329, 83/10/03, 8401170052
- B207150195 Submits suggestions re design sensitivity of B&W reactors CPC or contractor should obtain cost of necessary changes & estimate of occupational exposure that might be incurred
Info should then be used to develop value impact statement
HANAUER, S. H. Division of Systems Integration (post 811005). 82/06/21 MATTBON, R. J. Division of Systems Integration (post 811005) 2pp 21846 232
- B21160324 Notifies of status of unresolved items in draft NUREG-0933, "Prioritization of Generic Safety Issues " Four items resolved B-17 should be dropped as generic issue A-16 & NUREG-0737, Item II E 5 1 nearly complete
MATTBON, R. J. Division of Systems Integration (post 811005) 82/11/05 FUNCHES, J. L. Planning & Program Analysis Staff. App 21846 220
- B301260532 Forwards detailed work plan & schedule milestones for FY83 generic issues & discussion of 10 generic issues assigned to Div of Sys Integration in Operating Plan
MATTBON, R. J. Division of Systems Integration (post 811005) 83/01/21 MINNERS, W. Safety Program Evaluation Branch. 36pp. 21846 184
- B305160338 Forwards response to 821220 request for comments on draft rept re prioritization of non-NRR TMI action plan items
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 8pp 21846 340
- B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-48, B-64, C-7, C-12 & III D 2.3, per Denton request
VOLLMER, R. H. Division of Engineering IEB-82-02. 83/02/01 SPEIS, T. P. Division of Safety Technology 16pp. 21846 168
- B401170090 Discusses status of branch work on Generic Issue B-6, in response to RJ Bosnak 820826 memo to W Minners More detailed study on loads & load combinations initiated at INE. No further investigation required
SCHAUER, F. P. Structural Engineering Branch 82/09/02 MINNERS, W. Safety Program Evaluation Branch 1p. 21846 226
- B401170099 Comments on prioritization of licensing improvement issues, per B30111 memo Many items identified as licensing improvement issues do not fit generic issue definition. Summary of recommended disposition of 28 issues encl
MATTBON, R. J. Division of Systems Integration (post 811005) 83/02/02, FUNCHES, J. L. Planning & Program Analysis Staff 51pp 21846 254
- B401170101 Forwards status rept on TMI action plan items assigned to IE in response to Dircks 820514 memo Revised schedule for open action items included.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/06/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 11pp 21846 326.
- B401170104 Forwards rept on completion of TMI Action Plan Item II, J, 1, 2, "Mod of Vendor Insp Program," per 810603 memo. No followup assignments necessary w/completion of action item
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/10/29 DIRCKS, W. J. Office of the Executive Director for Operations 3pp. 21846 337
- B401170108 Forwards rept on completion of TMI Action Plan Item IV, A 2. "Revised Enforcement Policy," per 810603 memo Enforcement policy revised & approved by Commission & issued in effective form on 820309
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/03/11 DIRCKS, W. J. Office of the Executive Director for Operations 3pp. 21846:348
- B401170114 Forwards rept on completion of TMI Action Plan Items III A 3 & "Emergency Preparedness, NRC & Other Agencies," & III, B 2, "Implementation of NRC & FEMA Responsibilities," per 810603 memo.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/06/02 DIRCKS, W. J. Office of the Executive Director for Operations. 6pp 21846, 351.
- B401170062 FOIA request for six categories of documents re facilities
ANDERSON, S. I. Carvey, Schubert, Adams & Barer. 83/09/28 Office of Administration. 2pp. 21837:001 24X Fiche 50-309, 83/09/28, 8401170062.

NONDOCKETED ITEMS

421

B401170117 FOIA request for studies, repts & calculations leading to repudiation of Rasmussen rept Related info encl
CALSDYAS, C D Affiliation Unknown 83/10/13 NRC - No Detailed Affiliation Given 4pp 21837 357

B401170121 Responds to FOIA request for studies, repts & calculations leading to repudiation of Rasmussen rept Records available in PDR W/o stated 790119 press release
FELTON, J M Division of Rules and Records 83/10/27 CALSDYAS, C D Affiliation Unknown 1p 21837 361

B401170125 FOIA request for Dircks 830607 memo to Ebersole re development of ACRB control room habitability program & copy of program to be placed in PDR
PEDRO, J NUS Corp CD-18-83-455 83/10/18 Division of Rules and Records 1p 21837 344

B401170129 Responds to FOIA request for Dircks 830607 memo to Ebersole re development of ACRB control room habitability program & copy of program to be placed in PDR Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/10/31 PEDRO, J NUS Corp 1. 21837 345

--B306170082 Discusses ACRB Subcommittee on Reactor Radiological Effects rept on control room habitability NRR & IE instructed to develop plan by 830801 to handle issues
DIRCKS, W J Office of the Executive Director for Operations 83/06/07 EBERSOLE, J C ACRB - Advisory Committee on Reactor Safeguards. 1p 21837 346

--B308180433 Forwards proposed plan to assess NRC consideration of control room habitability, in response to 830607 request Effort recommended by encl plan & NRR prioritization will be held in abeyance pending receipt of approval or comments
BENTON, H R Office of Nuclear Reactor Regulation, Director 83/07/27 DIRCKS, W J Office of the Executive Director for Operations 6pp 21837 347

B401170135 FOIA request for SECY-83-24 & SECY-83-153 to be placed in PDR
PEDRO, J NUS Corp. CD-18-83-257 83/08/16 Division of Rules and Records 1p 21836 254

B401170137 Responds to FOIA request for SECY-83-24 & SECY-83-153 to be placed in PDR Forwards documents SECY-83-24 partially withheld (ref FOIA Exemption 1) SECY-83-153 available in PDR
FELTON, J M Division of Rules and Records 83/10/31 PEDRO, J NUS Corp 1p 21836 255

--B305170230 SECY-83-153
Recommends that Commission approve FR publication of encl proposed amend to 10CFR50, App E re frequency of full-scale emergency preparedness exercises
DIRCKS, W J Office of the Executive Director for Operations 83/04/28 40pp 21836 256

--B401170142 SECY-83-024
Requests approval of proposed ltr to Dept of Commerce re export of licensed nuclear reactor components to India for use in Tarapur Atomic Power Station Info deleted
DIRCKS, W J Office of the Executive Director for Operations 83/01/19, Commissioners 7pp 21836 256.

B401170148 Further response to FOIA request for documents concerning PNO-111-80-57, PNO-V-83-29 & PNO-V-83-29A Forwards App A documents
FELTON, J M. Division of Rules and Records. 83/11/01 BERNABEI, L Government Accountability Project 2pp. 21836 307

B401170170 Final response to FOIA request for three categories of records re Suppl 1 to NUREG-0737 at Table 1 re emergency operations Facility less than 10 miles from plant Forwards response to broader FOIA request from JH O'Neill, W/o encl.
FELTON, J M Division of Rules and Records 83/11/03, PHILIPS, M H Bebevoise & Liberman 1p 21836 359

B401170176 Further response to FOIA request for records re R Gunderson & W Royce allegations concerning facility Documents subj to request entirely withheld (ref FOIA Exemptions 5 & 7).
FELTON, J M Division of Rules and Records. 83/11/04 GARDE, B Government Accountability Project 2pp 21837:393 24X Fiche: 50-528, 83/11/04: B401170176

B401170180 FOIA request for Hoyt rept & Hoyt & Alost investigation re T Aggregate allegation documents leading up to & resulting in rept publication.
BERNABEI, L Government Accountability Project 83/09/16, Division of Rules and Records 2pp 21836 347

B401170183 Responds to FOIA request for Hoyt rept & Hoyt & Alost investigation documents leading up to & resulting in rept publication Documents available in PDR
FELTON, J M Division of Rules and Records 83/11/04 BERNABEI, L Government Accountability Project 1p 21836 349

B401180008 FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983
BERNABEI, L Government Accountability Project 83/09/15 Office of Administration 2pp 21853 001. 24X Fiche 50-528, 83/09/15: B401180008

B401180009 Responds to FOIA request for documents re Caseload Forecast Panel meetings during 1982 & 1983 for facilities Forwards documents listed on app
FELTON, J M Division of Rules and Records 83/10/11 BERNABEI, L Government Accountability Project 5pp 21853 003 24X Fiche 50-528, 83/10/11: B401180009

--B401180013 Trip rept of 830622-24 Caseload Forecast Panel site visit re projected fuel load dates
LICITRA, E A Licensing Branch 3 83/10/11 NOVAK, T M Assistant Director for Licensing 2pp 21853 017 24X Fiche 50-528, 83/10/11: B401180009

--B401180017 "Palo Verde Nuclear Generating Station Caseload Forecast Startup Status "
* Arizona Public Service Co 83/06/22 58pp 21853 0A7. 24X Fiche 50-528, 83/10/11: B401180009

--B401180020 "Palo Verde Nuclear Generating Station Caseload Forecast "
* Arizona Public Service Co 83/06/22. 86pp 21853 125 24X Fiche 50-528, 83/10/11: B401180009.

--B401180022 "Palo Verde Nuclear Generating Station Caseload Forecast "
* Arizona Public Service Co. 83/03/31 86pp 21853: 211. 24X Fiche. 50-528, 83/10/11: B401180009

--B401180026 NRC questions & util responses re facility startup Related documentation encl.
* NRC - No Detailed Affiliation Given 82/03/18 21pp 21853 286 24X Fiche. 50-528, 83/10/11: B401180009

--B401180028 Palo Verde Nuclear Generating Station Caseload Forecast Panel meeting
* Arizona Public Service Co. 80/10/28 113pp. 21853 306 24X Fiche. 50-528, 83/10/11: B401180009

--B401180033 Palo Verde Nuclear Generating Station Caseload Forecast Panel 790425 & 26 meetings
* Arizona Public Service Co 79/04/25. 63pp 21854: 057. 24X Fiche 50-528, 83/10/11: B401180009

--B401180036 Agenda for Caseload Forecast Panel 790425-26 meetings.
* NRC - No Detailed Affiliation Given 79/04/25 NRC - No Detailed Affiliation Given 2pp 21854 120 24X Fiche 50-528, 83/10/11: B401180009.

--B401180042 Submits 790509 daily staff notes
QBBIICK, L V Office of the Executive Director for Operations 79/05/10. HENDRIE, J., GILJINSKY, V., AHEARNE, J F. Commissioners 2pp 21854 129. 24X Fiche 50-528, 83/10/11: B401180009.

--B401180047 Notes re test & startup
* NRC - No Detailed Affiliation Given. 79/04/25. 2pp. 21854. 140. 24X Fiche. 50-528, 83/10/11: B401180009

--B401180067 Chart re NRC permits & licenses.
* NRC - No Detailed Affiliation Given. 83/10/11. 3pp. 21854. 155. 24X Fiche. 50-528, 83/10/11: B401180009

--B401180073 Confirms 780227 telcon w/R Robb re corrections to Jan 1978 yellowbook (NUREG-0030). Corrections listed.
VAN BRUNT, E E Arizona Public Service Co. 78/02/27. LOVEACE, H. H. NRC - No Detailed Affiliation Given. 3pp 21854 158. 24X Fiche: 50-528, 83/10/11: B401180009.

--B401180075 Chart & info denoting facility cable & termination percentages.
* Arizona Public Service Co 83/10/11. 5pp. 21854: 168. 24X Fiche. 50-528, 83/10/11: B401180009.

--B401180077 Chart re design/procurement & mechanical/electrical installation/insp
* Arizona Public Service Co 83/10/11. 8pp 21854: 182 24X Fiche 50-528, 83/10/11: B401180009.

NONDOCKETED ITEMS

- B401180082 AEB50-R1
"Palo Verde Nuclear Generating Station Test Index"
* Arizona Public Service Co 83/10/11 27pp. 21854 190. 24X
Fiche 50-528,83/10/11,8401180009
- B401180088 Notes re facility fuel load dates.
* NRC - No Detailed Affiliation Given 82/11/30 4pp
21854,218 24X Fiche: 50-528,83/10/11,8401180009
- B401180089 Key interface dates Related info encl
* NRC - No Detailed Affiliation Given 82/03/18. 53pp
21854,222.
- B401180090 Palo Verde Nuclear Generating Station master startup
schedule
* Arizona Public Service Co 80/10/27. 33pp 21854 275 24X
Fiche 50-528,83/10/11,8401180009
- B401180094 Unit 1 & common startup schedule milestones
* Arizona Public Service Co 80/10/28. 4pp 21854 308 24X
Fiche 50-528,83/10/11,8401180009
- B401180097 Agenda for Caseload Forecast Panel site visit for wk of
820325
* NRC - No Detailed Affiliation Given. 82/03/15. NRC - No
Detailed Affiliation Given. 3pp. 21854:312. 24X
Fiche: 50-528,83/10/11,8401180009.
- B401180102 Summary of 810824 meeting w/util in Washington, DC re NRC
1980 review of facility project schedule
LOVELACE, W., HUBBARD, R. NRC - No Detailed Affiliation Given
81/08/24 NRC - No Detailed Affiliation Given 2pp 21854:315
24X Fiche 50-528,83/10/11,8401180009
- B401180106 Agenda for Caseload Forecast Panel 801028 meeting
* NRC - No Detailed Affiliation Given. 80/10/28. NRC - No
Detailed Affiliation Given 1p. 21854:323 24X
Fiche. 50-528,83/10/11,8401180009.
- B401180116 Computer printout re predecessor/successor analysis listing
of cumulative resource requirements based on facility early
& late start
* Arizona Public Service Co. 83/07/23 34pp 21854.347. 24X
Fiche. 50-528,83/10/11,8401180009.
- B401200232 Responds to FOIA request for correspondence between NRC &
util re facility in Southport, NC Forwards App A documents.
FELTON, J. M. Division of Rules and Records 84/01/06. BELEN, R. H.
Star-News Newspapers, Wilmington, NC 2pp. 21887 286. 24X
Fiche: 50-324,84/01/06,8401200232
- B401200234 FOIA request for NRC recent order requiring util to meet
testing requirements at Southport generating plant or take
unit out of operation & correspondence requiring util to
meet safety stds per Reg Guide 1.118.
BELEN, R. H. Star-News Newspapers, Wilmington, NC 83/12/07 NRC
- No Detailed Affiliation Given. 2pp. 21887 288. 24X
Fiche. 50-324,84/01/06,8401200232.
- B401230048 Forwards intergranular stress corrosion cracking insp order
confirming shutdown of plant.
VASSALLO, D. B. Operating Reactors Branch 2 83/08/26. UTLEY, E. E.
Carolina Power & Light Co. 2pp. 21887:290. 24X
Fiche: 50-324,84/01/06,8401200232.
- B401200318 FOIA request for lists of active & retired Co-60 licenses.
repts of missing, misplaced or mishandled Co-60 within past
5 yrs & list of Auburn Memorial Hosp licensed radioactive
matl.
COWIE, D. J. Bouck, Holloway, Kiernan & Casey 83/09/29.
Director's Office, Office of Inspection and Enforcement. 2pp.
21872:109.
- B401200324 Partial response to FOIA request for lists & records re
Co-60 licenses Forwards lists of active & retired licenses
w/NY mailing addresses Search for third request item in
progress, Auburn Memorial Hosp not NRC licensee. W/o encl.
FELTON, J. M. Division of Rules and Records. 83/11/01 COWIE, D. J.
Bouck, Holloway, Kiernan & Casey 1p. 21872:111.
- B401230001 Further response to FOIA request for correspondence between
Chairman Palladino & DOJ re investigation of alleged
falsification of RCS leak rate tests. App A info partially
withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records. 83/11/07 VOIGT, H. H.
LeBonof, Lamb, Leiby & MacRae. 3pp 21930.322. 24X
Fiche: 50-289,83/11/07,8401230001.
- B401230005 Draft response to Question 3 in Congressman Udall & Markey
830801 ltr
* NRC - No Detailed Affiliation Given. 83/11/07. 1p 21930:331.
- B401230008 Summary of recent meeting w/DOJ officials re differences
concerning question of whether DOJ had ltr'd request to
stop NRC investigation of Hartman allegations
PLAINE, H. H. Office of the General Counsel 83/08/30
PALLADINO, N. J. Commissioners 1p 21930 332
- B401230011 Requests explanation of conflict between NJ Palladino 830325
testimony & DL Jensen 830517 ltr re NRC investigation into
allegations that leak rate calculations at TMI-2 improperly
conducted prior to accident
UDALL, M. K. House of Rep., Interior & Insular Affairs 83/05/23
PALLADINO, N. J. Commissioners 1p 21930 333 24X
Fiche 50-289,83/11/07,8401230001
- B401230015 Requests investigation of Hartman allegations of leak rate
falsification at TMI-2, per DL Jensen 830517 ltr indicating
no bar to NRC proceeding w/independent investigations
PALLADINO, N. J. Commissioners 83/11/07 HAYES, B. Office of
Investigation 1p 21930.334 24X Fiche 50-320,83/11/07,
8401230001
- B401230019 Requests opinion by 830523 re factual assertions contained
in third paragraph of Assistant Atty General DL Jensen
830517 ltr to Commission W/o stated encl
OILINSKY, V. Commissioners 83/05/19 CUMMINGS, J. J. Office of
Inspector & Auditor 1p 21930 335
- B401230023 Recommends that all documents involved in FOIA Request
83-285 be withheld per FOIA Exemption 7 because info relates
directly to Hartman allegations currently under criminal
investigation by DOJ
CUMMINGS, J. J. Office of Inspector & Auditor. 83/04/15.
PLAINE, H. H. Office of the General Counsel. 1p 21930.336
- B401230026 Responds to 830523 request for explanation of conflict
between NJ Palladino 830325 testimony & DL Jensen 830517 ltr
re propriety of NRC investigation into allegations that leak
rate calculations at TMI-2 improperly conducted
PALLADINO, N. J. Commissioners 83/07/14 UDALL, M. K. House of
Rep., Interior & Insular Affairs 3pp 21930 337 24X
Fiche: 50-289,83/11/07,8401230001
- B401230030 Discusses propriety of NRC civil investigation into Hartman
allegation concurrent w/DOJ criminal investigation of same.
Noncensored version.
CUMMINGS, J. J. Office of Inspector & Auditor 83/05/31
JENSEN, D. L. Justice, Dept of 3pp 21930 343 24X
Fiche 50-289,83/11/07,8401230001
- B401230037 FOIA request for GW Kerr or other employee response to
Governor Janklow 831006 ltr re NRC position on low level
waste
PAY, D. Technical Information Project 83/10/17. Office of
Administration. 1p 21905.358
- B401230041 Responds to FOIA request for GW Kerr or other employee
response to Governor Janklow 831006 ltr Requested document
not yet prepared. Request should be resubmitted in late Nov.
FELTON, J. M. Division of Rules and Records 83/11/02 PAY, D.
Technical Information Project 1p. 21905.359.
- B401230052 Final response to FOIA request for four categories of
documents Forwards App A documents. Documents also available
in PDR.
FELTON, J. M. Division of Rules and Records 83/11/01. ADATO, M.
Union of Concerned Scientists. 2pp 21930.271. 24X
Fiche. 50-289,83/11/01,8401230052
- B401230061 Advises of NRC approval of recommendations to defer
final implementation date of NUREG-0737, Items II B.3, II F 1.4,
II F.1.5 & II. F.1.6 until 830331 or before restart. Approval
of Item II B.2.2 date withheld until review completed.
CHILK, S. J. Office of the Secretary of the Commission. 82/10/19
DIRCKS, W. J. Office of the Executive Director for Operations 1p
21930 274. 24X Fiche. 50-289,83/11/01,8401230052
- B401230067 Advises that Commission approved recommendation to defer
final implementation date for NUREG-0737, Item II B.2.2 until
first refueling outage following restart.
CHILK, S. J. Office of the Secretary of the Commission. 83/01/03
DIRCKS, W. J. Office of the Executive Director for Operations 1p
21930.275. 24X Fiche: 50-289,83/11/01,8401230052
- B401230070 SECY-82-384A
Recommends deferral of NUREG-0737, Item II. B.2.2. "Plant
Shielding Mode," implementation to first refueling outage
following restart
DIRCKS, W. J. Office of the Executive Director for Operations.
82/12/06 4pp 21930.276 24X Fiche 50-289,83/11/01,8401230052

NONDOCKETED ITEMS

423

- 8401230079 SECY-83-340
 Informs of status of facility restart certification effort & provides updates on noncertification item status
 DIRCKB, W J Office of the Executive Director for Operations
 83/08/16 42pp 21930 280 24X Fiche 50-329, 83/11/01, 8401230052
- 8401230594 FOIA request for safeguards watch list documents, per
 WD Lanning 810624 memo, to be placed in PDR.
 SHOLLY, S C Union of Concerned Scientists 83/11/09 FELTON, J M
 Division of Rules and Records 2pp 21927 346
- 8401230597 FOIA request for NRC "Final Waste Classification & Waste
 Form Technical Position Papers"
 DEARMAS, M Cordis Corp 83/09/20 Food & Drug Administration
 1p 21927 344
- 8401230599 Responds to FOIA request for safeguards watch list
 documents, per W Lanning 810624 memo, to be placed in PDR NRC
 does not have safeguards watch list
 FELTON, J M Division of Rules and Records 83/11/22 SHOLLY, S C
 Union of Concerned Scientists 1p. 21927 348
- 8401230603 Responds to FOIA request for "Final Waste Classification &
 Waste Form Technical Position Papers" Forwards requested
 documents W/o encl
 FELTON, J M Division of Rules and Records 83/11/22 DEARMAS, M
 Cordis Corp 1p 21927 345
- 8401230605 FOIA request for documents re NRC-sponsored program at
 Sandia Natl Labs concerning classification of safety-related
 equipment, RM Bernero trip to Japan & Taiwan & 831031 meeting
 concerning vital area identification assumptions
 SHOLLY, S C Union of Concerned Scientists 83/11/07 FELTON, J M
 Division of Rules and Records 1p 21927 335
- 8401230609 FOIA request for Aug 1983 SECY-83-313 "Rept on FOIA Policy."
 CLARK, L. STEINKENIG, K. Government Accountability Project
 83/11/04 FELTON, J M Division of Rules and Records 1p
 21925 138
- 8401230610 Partial response to FOIA request for four categories of
 documents, Forwards documents re 830907 std work order for
 DOE work, Search for Category C & D documents in progress
 FELTON, J M Division of Rules and Records 83/11/22 SHOLLY, S C.
 Union of Concerned Scientists 1p 21927 336
- 8401230620 Forwards std work order for DOE work, "Classification of
 Equipment & Activities Important to Safety"
 BURDA, A J Director's Office, Office of Inspection and
 Enforcement, FIN A-1353 83/09/07, ROMATOWSKI, R A Energy,
 Dept of 1p 21927 337
- 8401230625 Std work order for DOE work "Classification of Equipment &
 Activities Important to Safety," issued to Sandia Natl Labs
 BURDA, A J Director's Office, Office of Inspection and
 Enforcement FIN A-1353 30-83-40 83/09/07. 6pp. 21927 338.
- 8401230614 Responds to FOIA request for Aug 1983 SECY-83-313 "Rept on
 FOIA Policy" Document entirely withheld (ref FOIA
 Exemption 5)
 FELTON, J M Division of Rules and Records 83/11/22. CLARK, L
 Government Accountability Project 2pp 21925 139.
- 8401230621 FOIA request for IE 800103 rept re review of matl false
 statement at facilities, associated & supporting records to
 rept & repts prepared in response
 WINSLOW, R Wall Street Journal 83/09/28 NRC - No Detailed
 Affiliation Given 1p 21905 336 24X Fiche 50-329, 83/09/28,
 8401230621.
- 8401230630 Partial response to FOIA request for IE 800103 rept re
 review of matl false statement at facilities, associated &
 supporting records to rept & repts prepared in response.
 Forwards App A documents, Review of addl records in progress
 FELTON, J M Division of Rules and Records 83/11/01. WINSLOW, R.
 Wall Street Journal 2pp 21905 337 24X Fiche 50-329, 83/11/01,
 8401230630
- 7812070139 Recommends that the Board be notified re reported settlement
 in diesel generator bldg. Related interim deficiency rept
 submitted on 780929 & insp conducted on 781024-27 to examine
 details of problem (Encl 7810060285)
 THORNBURG, H D Division of Reactor Construction Inspection
 78/11/09 GOWER, G. C. Executive Officer for Operations Support.
 1p. 21905 339 24X Fiche 50-329, 83/11/01, 8401230630.
- 7908070022 Forward comments & recommendation resulting from review of
 Region 3 enforcement package dtd 790403 on facility
 settlement problems Four matl false statement identified out
 of five Expects imposition of civil penalties
 THORNBURG, H D Division of Reactor Construction Inspection.
 79/06/13 THOMPSON, D. Executive Officer for Operations Support.
 2pp 21905 341 24X Fiche 50-329, 83/11/01, 8401230630.
- 7912140279 Comments on action needed for 790423 enforcement package
 re matl false statement in FSAR
 THORNBURG, H D Division of Reactor Construction Inspection.
 79/09/27 GOWER, G. C. Executive Officer for Operations Support.
 2pp 21905 344 24X Fiche 50-329, 83/11/01, 8401230630
- 8002120130 Forwards info re order to modify CP including matl false
 statement consideration
 THORNBURG, H D Division of Reactor Construction Inspection.
 80/01/03 FORTUNA, R Office of Inspector & Auditor. App
 21905 348 24X Fiche 50-329, 83/11/01, 8401230630
- 8401230639 Discusses IE investigation re FSAR submittals Several
 incorrect statements re soil foundation appear to reflect
 matl false statements
 SINCLAIR, J R Office of Inspector & Auditor 79/03/20 Office
 of Inspector & Auditor 1p. 21905 340 24X Fiche 50-329,
 83/11/01, 8401230630
- 8401230644 Discusses status of IE investigation re FSAR submittals
 SINCLAIR, J R Office of Inspector & Auditor 79/06/26 Office
 of Inspector & Auditor 1p 21905 343. 24X Fiche: 50-329,
 83/11/01, 8401230630
- 8401230651 Discusses enforcement action re diesel generator bldg &
 plant fill areas, per 790403 memo to HD Thornburg Item 1
 considered matl false statement Four items should be
 treated as items of noncompliance.
 GOWER, G C Executive Officer for Operations Support. 79/10/04
 KEPPLER, J Q. Region 3, Chicago. Office of the Director. 2pp.
 21905 346 24X Fiche: 50-329, 83/11/01, 8401230630
- 8401250010 FOIA request, on behalf of UCS, for all 1982 SECY papers.
 WEISS, E R. Harmon & Weiss. WEISS, E. R. Union of Concerned
 Scientists 83/06/28 FELTON, J Division of Rules and Records.
 1p. 21960 004.
- 8401250015 Partial response to FOIA request for all 1982 SECY papers.
 Forwards App A documents Remaining documents under review.
 FELTON, J. M Division of Rules and Records. 83/10/18. WEISS, E. R.
 Union of Concerned Scientists 3pp 21960 005 24X
 Fiche 50-000, 83/10/18, 8401250015.
- 8203040434 SECY-82-045
 Provides quarterly rept updating info on petitions for
 rulemaking submitted to NRC between Oct-Dec 1981
 DIRCKB, W J Office of the Executive Director for Operations
 82/02/03 21pp 21960 129.
- 8203050072 SECY-82-054
 Provides update on status of waste mgt legislation &
 comparison of major bills in Congress Major differences in
 bills include degree of priority of retrievable monitored
 storage as alternative to deep geologic storage
 DIRCKB, W J. Office of the Executive Director for Operations
 82/02/05 11pp. 21960 150
- 8203050106 SECY-82-056
 Informs of progress & schedule of Reactor Operator
 Qualifications Peer Review Panel Meetings on 811116-18 &
 820112-13 discussed
 DIRCKB, W J Office of the Executive Director for Operations.
 82/02/09 4pp. 21960 161.
- 8203050118 SECY-82-064
 Describes calculation of proposed civil penalties Events
 indicated need for aggressive involvement of higher
 licensee mgt in assuring safe operation.
 DIRCKB, W J. Office of the Executive Director for Operations.
 82/02/12. 2pp. 21960 165. 24X Fiche 50-000, 83/10/18, 8401250015.
- 8203110330 SECY-82-066
 Forwards NUREG-0886, "Steam Generator Tube Experience"
 DIRCKB, W J. Office of the Executive Director for Operations.
 82/02/12 68pp 21960 167
- 8203120409 SECY-82-079
 Informs of dismissal of NFB challenge to Commission 811106
 order affirming NRC issuance of amend.
 FITZGERALD, J A Office of the General Counsel 82/02/25. 1p.
 21961 063

NONDOCKETED ITEMS

- 8203120411 SECY-82-083
Advises of CP&L 820201 petition for review of Commission final rule on interim requirements re hydrogen control
FITZGERALD, J.A. Office of the General Counsel 82/03/01. 11pp
21961 187.
- 8203120423 SECY-82-081
Recommends approval of proposed AO determination re seismic design errors Draft FR notice encl
DIRCKS, W.J. Office of the Executive Director for Operations 82/02/25 81pp 21961 065 24X Fiche 50-000,83/10/18,8401250015
- 8203180400 SECY-82-092
Informs of status of staff action & plans re environ assessment of psychological stress in restart staffing plan. Major milestones & resource requirements & draft workshop rept encl
DIRCKS, W.J. Office of the Executive Director for Operations 82/03/02 102pp 21961:178 24X Fiche 50-000,83/10/18, 8401250015
- 8203180405 SECY-82-099
Recommends approval on encl FR notice of proposed rule 10CFR50, clarifying applicability of license conditions & Tech Specs in emergency
* Office of the Executive Director for Operations 82/03/05 23pp. 21962.073
- 8203240020 SECY-82-076
Forwards quarterly summary rept of NRC rulemaking activities
DIRCKS, W.J. Office of the Executive Director for Operations. 82/02/18 137pp. 21960:238
- 8203300068 SECY-82-112
Discusses 820222 brief re emergency preparedness at facilities
FITZGERALD, J.A. Office of the General Counsel 82/03/16. 33pp. 21962 096 24X Fiche.50-000,83/10/18,8401250015
- 8204050459 SECY-82-122
Provides Commission info re adequacy of existing Board notification policy. Submits recommendation to accommodate greater role of regions in policy decisions.
DIRCKS, W.J. Office of the Executive Director for Operations. 82/03/18. 3pp 21962 183
- 8204070577 SECY-82-132
Notifies Commission of successful defense of Kerr-McGee Nuclear Corp. et al vs NRC, et al re lawsuit on U mill licensing requirements
BICKWIT, L. Office of the General Counsel 82/03/29. 73pp. 21962-186.
- 8204070589 SECY-82-073A
Advises that Judge McCarr denied renewed motion for preliminary injunction filed by City of West Chicago, IL & granted motion to dismiss filed by NRC. Opinion follows.
BICKWIT, L. Office of the General Counsel 82/03/26. 1p. 21960.235
- 8204080204 SECY-82-134
Informs Commission of current status of steam generator insp & repairs following 820125 steam generator tube rupture at facility.
DIRCKS, W.J. Office of the Executive Director for Operations 82/03/31 3pp. 21962:239 24X Fiche:50-000,83/10/18,8401250015.
- 8204220088 SECY-82-141
Informs Commission of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operators & describes routine repts to be submitted on status of DL Tables of pass/fail rates encl.
DIRCKS, W.J. Office of the Executive Director for Operations. 82/04/05. 4pp. 21962:262
- 8204220364 SECY-82-152
Recommends that Commission accept Fitzgerald & Rothschild conclusions re employment of Newark to work on matters re facility.
BICKWIT, L. Office of the General Counsel. 82/04/12. 4pp 21962:319. 24X Fiche.50-000,83/10/18,8401250015
- 8204220376 SECY-82-160
Forwards info re sua sponte issue: whether addl primary sys depressurization capability should be added to plant design.
MALSCHE, H.O. Office of the General Counsel. 82/04/15. 80pp. 21963:075. 24X Fiche:50-000,83/10/18,8401250015
- 8204300109 SECY-82-143
Provides info on operation & testing of containment isolation valves at facility
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/05 19pp 21962 266 24X Fiche 50-000,83/10/18,8401250015.
- 8205050087 SECY-82-092A
Forwards final rept. "Summary Rept-Workshop on Psychological Stress Associated W/Proposed Restart of TMI-1,"
NUREG/CP-0024
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/14. 131pp 21961 287 24X Fiche 50-000,83/10/18, 8401250015
- 8205050098 SECY-82-156
Informs of plan to permit regional administrators to sign proposed civil penalties in certain cases
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/13 2pp 21963 066
- 8205050499 SECY-82-162
Forwards "Rept of Peer Advisory Panel & NRC on Operator Qualifications"
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/15 117pp 21963 173.
- 8205050987 SECY-82-161
Informs of issuance of draft rept (NUREG-0820) on SEP integrated plant safety assessment W/o encl NUREG-0820
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/15 2pp. 21963 171 24X Fiche 50-000,83/10/18,8401250015
- 8205070412 SECY-82-172
Forwards quarterly summary of rules & petition for rulemaking. Rept expanded to include NRC petitions for rulemaking & updates info on all rules & petitions on which NRC has proposed, or is considering action
DIRCKS, W.J. Office of the Executive Director for Operations 82/04/23 194pp 21963:298.
- 8205240406 SECY-82-197
Recommends that Ofc of General Counsel be directed to prepare draft statement of policy indicating Commission intention not to alter licensing procedures
BICKWIT, L. Office of the General Counsel 82/05/17 36pp 21964 171
- 8205270663 SECY-82-195
Provides info re qualifications & experience of personnel operating plant during current strike, in response to Chairman Palladino request
DIRCKS, W.J. Office of the Executive Director for Operations 82/05/14. 4pp 21964 154 24X Fiche 50-000,83/10/18,8401250015
- 8205280489 SECY-82-193
Notifies Commission that J Jaffer petition to suspend license amends for facilities has been denied.
MALSCHE, H.O. Office of the General Counsel 82/05/12 13pp. 21964.158 24X Fiche.50-000,83/10/18,8401250015
- 8206110014 SECY-82-219
Informs of status of util ability to provide addl senior reactor operator on shift by 820701 per requirements of TMI Item I A 1.3. "Shift Manning Requirements."
DIRCKS, W.J. Office of the Executive Director for Operations 82/06/01. 6pp 21964.235 24X Fiche.50-000,83/10/18,8401250015
- 8206110136 SECY-82-223
Discusses Nuclear Club, Inc 820528 suit, filed under FOIA seeking access to Morgan rept.
BLAQOIE, E.L. Office of the General Counsel 82/06/03 1p 21964:241.
- 8206110164 SECY-82-206
Informs Commission that review of 820125 steam generator tube rupture event completed & permission to restart facility granted.
DIRCKS, W.J. Office of the Executive Director for Operations 82/05/21. 3pp. 21964:232 24X Fiche.50-000,83/10/18,8401250015
- 8206290623 SECY-82-262
Informs Commission of 820524 petition for review filed by New England Coalition on Nuclear Pollution & others re Commission final rule on financial qualification, w/DC Circuit.
BLAQOIE, E.L. Office of the General Counsel 82/06/22 15pp 21964:298.

NONDOCKETED ITEMS

425

- B206300033 SECY-82-247
 Informs of Washington DC Circuit Court 820611 decision favoring NRC in NRDC vs NRC re NFB/Erwin hearing concerning military function rule cases
 SHULMAN, H J Office of the General Counsel 82/06/15 12pp
 21964 247
- B206300039 SECY-82-250
 Informs of NRC plan for certifying completion of TMI-1 restart requirements in response to 820316 memo
 DIRCKS, W J Office of the Executive Director for Operations 82/06/16 16pp 21964 278 24X Fiche 50-000, 83/10/18, 8401250015
- B206300094 SECY-82-197C
 Advises that on 820610, Solicitor General approved filing of motion for rehearing & reconsideration en banc in 8-3 case On 820611, petition for rehearing & suggestion for rehearing filed
 SLAQOIE, E L Office of the Executive Legal Director 82/06/14 22pp 21964 210
- B2063000371 SECY-82-263
 Discusses Carole Burstein suit seeking injunction to enjoin NRC from considering granting OL to LAPL Motion planned to dismiss suit for lack of jurisdiction & finality failure to exhaust administrative remedies
 SHULMAN, H J Office of the General Counsel 82/06/24 2pp, 21964 313 24X Fiche 50-000, 83/10/18, 8401250015
- B207060317 Advises that documents withheld under TC Wheeler 820314 FOIA request re Atlas Machine & Iron Works, Inc can be released Contemplated referral to FBI never occurred
 ROTHCHILD, T. Office of the General Counsel 82/06/15, 19pp 21964 259
- B207230670 SECY-82-297
 Informs of T Devine (Govt Accountability Project) 820709 ltr responding to Chairman question at 820616 meeting & requesting investigation of alleged until false statements.
 BICKWIT, L Office of the General Counsel 82/07/15 99pp 21965 226 24X Fiche 50-000, 83/10/18, 8401250015
- B207230676 SECY-82-293
 Provides quarterly summary of NRC rules & petitions for rulemaking for 820409-0630.
 DIRCKS, W J Office of the Executive Director for Operations 82/07/12 204pp 21965 032
- B208040142 SECY-82-157A
 Provides status rept on NRR investigation of effects of electromagnetic pulse on nuclear power plants
 DIRCKS, W J Office of the Executive Director for Operations 82/07/16 7pp 21963 048.
- B208230483 SECY-82-333
 Advises of issuance of NUREG-0661, Suppl 1, "Mark I Containment Long-Term Program Safety Evaluation Rept " NUREG-0661, Suppl 1 & draft notice of availability encl
 DIRCKS, W J Office of the Executive Director for Operations 82/08/09 24pp 21965 325
- B209010239 SECY-82-013C
 Informs Commission of status of implementation of 10CFR50.48 & App R to 10CFR50 for quarter ending 820630 per BJ Chalk 801103 memo. As of 820630, 31 licensees have not completed responses
 DIRCKS, W J. Office of the Executive Director for Operations, 82/07/26, 8pp 21960, 008
- B209150435 SECY-82-150A
 Describes process of IE evaluation of NRC insp program effectiveness. IE appraisal team role & relationship to evaluation of insp program effectiveness & expansion plans & resource requirements.
 DIRCKS, W J Office of the Executive Director for Operations 82/08/25, 32pp, 21962 288.
- B209160068 SECY-82-352
 Informs Commission of NRC initiatives to improve QA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys.
 DIRCKS, W J. Office of the Executive Director for Operations 82/08/20, 37pp, 21966 035 24X Fiche 50-000, 83/10/18, 8401250015.
- B209200347 SECY-82-346
 Informs of current status of NRC efforts re psychological stress associated w/TMI restart. Natl Inst of Mental Health is reviewing proposed psychological survey.
 DIRCKS, W J. Office of the Executive Director for Operations, 82/08/19 2pp, 21966 030, 24X Fiche: 50-000, 83/10/18, 8401250015.
- B209200377 SECY-82-354
 Informs of INPO accreditation program for training programs in nuclear power industry for Commission consideration. INPO program is effort to reflect responsive posture by industry to TMI Action Plan Item I A 2 7
 DIRCKS, W J Office of the Executive Director for Operations 82/08/23 2pp 21967, 231
- B209210015 SECY-82-357
 Informs Commission of Commonwealth of MA 820813 petition to review Order CLI-82-16, denying hearing in Pilgrim enforcement matter.
 SLAQOIE, E L Office of the General Counsel CLI-82-16 82/08/26 2pp 21966 073
- B209230146 SECY-82-349
 Informs Commission of issuance of NUREG/CR-2837, "BHNL Technical Review of Pressurized Thermal Shock Issues." DIRCKS, W J Office of the Executive Director for Operations 82/08/20, 1p, 21966 034
- B210270322 SECY-82-407
 Advises of issues remaining from 820108 meeting re instrumentation for detection of inadequate core cooling in PWRs Requests action on update recommendations for implementation of NUREG-0737, Item II.F.2
 DIRCKS, W J Office of the Executive Director for Operations, 82/10/07 97pp 21966 303
- B211020239 SECY-82-403
 Informs Commission of results of SEP integrated safety assessment
 DIRCKS, W J. Office of the Executive Director for Operations, 82/10/01 115pp, 21966: 272 24X Fiche 50-000, 83/10/18, 8401250015.
- B211030044 SECY-82-400
 Submits litigation rept for wk of 820927.
 SLAQOIE, E L Office of the General Counsel 82/10/01 32pp 21966 239
- B211030079 SECY-82-406
 Submits litigation rept for wk of 821004.
 SLAQOIE, E L Office of the General Counsel 82/10/08, 4pp, 21966 296
- B211090002 SECY-82-430
 Informs of NRC brief filed on 821019 re New England Coalition on Nuclear Pollution vs NRC Brief & Certificate of Svc encl.
 SLAQOIE, E L. Office of the General Counsel, 82-1581, 82/10/22 64pp, 21967 047
- B211090006 SECY-82-432
 Informs of issuance of NUREG-0744, Vols I & II, Rev 1, "Resolution of Task A-11, Reactor Vessel Matls Toughness Safety Issue." DIRCKS, W J. Office of the Executive Director for Operations, 82/10/22, 2pp, 21967 111
- B211090063 SECY-82-422
 Submits litigation rept for wk of 821011.
 SLAQOIE, E L. Office of the General Counsel, 82/10/19, 3pp, 21966 300
- B211190003 SECY-82-445
 Responds to Commission request that IE evaluate proposal of assigning two resident inspectors to each const site. Proposal not advocated.
 DIRCKS, W J Office of the Executive Director for Operations, 82/11/01 2pp, 21967: 113.
- B211190008 SECY-82-450
 Submits litigation rept for wk of 821101, Burstein vs NRC & USNRC vs Pane discussed
 SLAQOIE, E L Office of the General Counsel 82/11/08 2pp, 21967 115 24X Fiche: 50-000, 83/10/18, 8401250015.
- B301070135 SECY-82-498
 Recommends withdrawal of proposed rule to codify NUREG-0737 requirements for OL applicants, per encl draft FR notice.
 DIRCKS, W J. Office of the Executive Director for Operations, 82/12/27 8pp, 21967: 206.
- B301070135 SECY-82-500
 Informs Commission of status of psychological stress survey proposal to predict stress resulting from restart of TMI-1 & remanuals of three studies of psychological stress caused by accident & aftermath at TMI-2.
 DIRCKS, W J. Office of the Executive Director for Operations, 82/12/27, 6pp 21967 216, 24X Fiche: 50-000, 83/10/18, 8401250015.

NONDOCKETED ITEMS

- 8301070163 SECY-82-502
Informs Commission of status of nonhearing issues on TMI-1 re auxiliary feedwater header problem & make-up nozzle cracking problem at B&W plants & steam generator tube problem at plant
DIRCKS, W J Office of the Executive Director for Operations 82/12/29 3pp 21967 222 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250106 SECY-82-016E
Forwards petition for Supreme Court review of Pane psychological stress issue in TMI-1 restart case filed by solicitor general
MALBACH, M Q Office of the General Counsel 82/09/02 20pp 21960 016 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250112 SECY-82-040
Recommends J Fitzgerald & T Rothschild Newark inquiry rept be made available for comment before decision made based on info reached
BICKWIT, L Office of the General Counsel 82/01/29 3pp 21960 044,
- 8401250117 SECY-82-044
Requests Commission approval of 1982 audit plan.
CUMMINGS, J J Office of Inspector & Auditor, 82/01/29 8pp 21960 047
- 8401250148 SECY-82-073
Summarizes 820212 District Court status hearing in City of West Chicago vs NRC City may drop lawsuit if Commission Order CLI-82-2, disposing of hearing petitions is followed by DES in Spring 1982
BICKWIT, L Office of the General Counsel, CLI-82-2, 82/02/18 2pp, 21960 074
- 8401250164 SECY-82-082
Discusses T Davine FOIA Appeal (82-A-1C) re OIA facility rept. Authorizes secretary to sign & dispatch attached ltr denying appeal
BICKWIT, L Office of the General Counsel 82/03/01 20pp 21961 147 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250223 SECY-82-197 ERR
Errata to SECY-82-197, replacing Pages 19 & 20 re NRDC vs NRC, DC Circuit Court of Appeals 74-1586 & consolidated cases (decision holding invalid NRC original, interim & final Table B-3 fuel cycle rules)
* Office of the Secretary of the Commission 82/05/20 3pp 21964:207
- 8401250240 SECY-82-241A
Submits request to Comptroller General for advice re payment of awards to intervenors under Equal Access to Justice Act, per Secretary of Commission 820723 memo QAO reply not expected until Sept.
MALBACH, M Q Office of the General Counsel, 82/08/09, 5pp, 21964, 242
- 8401250258 SECY-82-249
Forwards draft revised resumption of hearing order before Commission in facility matl control & accounting amend, issuance of order recommended
BICKWIT, L Office of the General Counsel 82/06/25 12pp 21964, 315
- 8401250263 SECY-82-272
Forwards NRC brief in Lorion vs NRC (DC Circuit Court of Appeals 82-1132) case.
BLAGGIE, E L Office of the General Counsel 82/06/28 40pp, 21964 327, 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250269 SECY-82-283
Discusses T Applegate vs NRC (82-1829) case re allegations that NRC improperly withheld documents & failed to identify others in response to 811123 request for records concerning 810807 OIA rept on IE investigation at facility
BLAGGIE, E L Office of the General Counsel, 82/07/06 6pp 21965, 026, 24X Fiche, 50-000, 83/10/18, 8401250015,
- 8401250302 SECY-82-334B
Forwards info re NRC opposition to motion by NRDC & Sierra Club to stay exemption for facility.
BICKWIT, L Office of the General Counsel, 82/08/30 43pp, 21965 349, 24X Fiche: 50-000, 83/10/18, 8401250015,
- 8401250311 SECY-82-346A
Informs of status of staff effort re psychological stress associated w/TMI-1 restart.
DIRCKS, W J Office of the Executive Director for Operations 82/09/13 8pp, 21966, 032, 24X Fiche: 50-000, 83/10/18, 8401250015
- 8401250322 SECY-82-382
Informs of status of ongoing & completed litigation from Sept 1981 to Sept 1982
BICKWIT, L Office of the General Counsel 82/09/17 52pp 21966 075
- 8401250325 SECY-82-378
Informs of results of facility SEP integrated safety assessment
DIRCKS, W J Office of the Executive Director for Operations 82/09/15 58pp 21966 129 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250353 SECY-82-473
Recommends issuance of encl order granting in part & denying in part motion to direct staff to reschedule 831013 meeting re Sandia Lab preliminary evaluation of facility safety study
MALBACH, M Q Office of the General Counsel 82/11/30, 5pp 21967 121 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250359 SECY-82-478
Provides info re rotation policy for resident inspectors & assessment of program Pending Congressional approval, policy established to allow resident inspector tour extensions to be approved on case by case basis
DIRCKS, W J Office of the Executive Director for Operations, 82/12/06 9pp 21967 126
- 8401250363 SECY-82-488
Provides litigation rept for wk of 821206
BLAGGIE, E L Office of the General Counsel 82/12/14 2pp 21967 138
- 8401250370 SECY-82-496
Informs of results of SEP review Rept will be published & distributed by 821230
DIRCKS, W J Office of the Executive Director for Operations, 82/12/21 64pp 21967 140 24X Fiche 50-000, 83/10/18, 8401250015
- 8401250376 SECY-82-501
Provides weekly litigation rept
ROTTSCHILD, T Office of the General Counsel 82/12/28 2pp 21967 214
- 8401250385 SECY-82-504
Informs Commission of progress & plans for improving state capabilities to do need-for-power evaluations
DIRCKS, W J Office of the Executive Director for Operations 82/12/30 5pp 21967 225
- 8401250133 FOIA request for listed documents re Kerr-McGee Nuclear Corp. Licenses SMB-664 & SNM-695
BARNES, C Affiliation Unknown 83/10/12 FELTON, J M Division of Rules and Records, 1p 21958 333,
- 8401250136 Responds to FOIA request for five listed documents. Forwards Documents 4 & 5 Request for Documents 1-3 referred to PDR
FELTON, J M Division of Rules and Records, 83/11/04, BARNES, C Affiliation Unknown 1p, 21958 334
- 8401250139 Application for SNM license, authorizing transfer, possession & processing of U from Spencer Chemical Co.
COBB, Q H, Kerr-McGee Corp 62/10/12 Atomic Energy Commission 13pp 21958 335,
- 8401250142 Forwards Source Matl License SMB-664 Condition of license requires results of evaluation described in Item 5 of H Lambertus 621022 ltr within 30 days of completion of evaluation Public insp Drawing NPD-4 withheld (ref 10CFR2)
PRICE, E R Atomic Energy Commission 62/11/07, LAMBERTUS, H Kerr-McGee Corp, 1p 21958 348,
- 8401250143 Source Matl License SMB-664 for Kerr-McGee Oil Industries, Inc. authorizing use of unlimited amounts of U & thorium at Cushing, OK oil refinery, per 620703 application & 620917, 1009 & 22 suppl
NUSSBAUMER, D A Atomic Energy Commission, 62/11/07, 1p 21958, 349
- 8401250146 Application for source matl license, authorizing transfer, possession & sale of U & depleted U from Spencer Chemical Co.
COBB, Q H, Kerr-McGee Corp 62/07/03 Atomic Energy Commission 7pp, 21958 350
- 8401250150 Responds to 621003 telcon re issuance of source matl license Request for withholding Drawings NPD-4 & NPD-5 from public disclosure, per 620917 application, withdrawn. Air effluent sampling method described
LAMBERTUS, H Kerr-McGee Corp 62/10/09 NUSSBAUMER, D A Atomic Energy Commission 17pp 21958 357,

NONDOCKETED ITEMS

427

- B401250153 Responds to 620821 ltr re application for source matl license Refinery located in rolling pasture land, 3 miles from Cushing, OK Gases from equipment areas vented into main exhaust manifold
LAMBERTUS, H Kerr-McGee Corp 62/09/17 Atomic Energy Commission 7pp 21959 012
- B401250157 Responds to 621018 telcon re application for source matl license Written instructions provided to employees re locker room procedures
LAMBERTUS, H Kerr-McGee Corp 62/10/22 Atomic Energy Commission 4pp 21959 019
- B401250163 Further response to FOIA request for documents re emergency operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/11/02 O'NEILL, J H Shaw, Pittman, Potts & Traubridge 6pp 21957:357 24X Fiche 50-000, 83/11/02, B401250163
- B202020366 Forwards Central Files version of layout of interim emergency operations & backup facilities Communications & dose assessment capabilities for backup facility listed.
MAURIN, L V Louisiana Power & Light Co. W3P82-0225, 82/01/28 TEDESCO, R L Assistant Director for Licensing 12pp 21958 241 24X Fiche 50-000, 83/11/02, B401250163
- B202120297 Discusses SECY-81-509 & NUREG-0696 re criteria for emergency operations facilities Recommends Commission approve NRC request to accept close in hardened emergency operations facilities
RENICK, F J NRC - No Detailed Affiliation Given 81/08/08, PALLADINO, N J Commissioners 2pp 21958, 316
- B301060498 Discusses status of implementation of emergency operations facilities in response to Secretary B21126 memo re possible vote on full power OL Supporting documentation encl
DIRCKS, W J Office of the Executive Director for Operations 82/12/27 PALLADINO, N Commissioners 7pp 21958, 305 24X Fiche: 50-000, 83/11/02, B401250163
- B303110415 SECY-83-085
Requests Commission disapprove exception for backup emergency operations facility for plant
DIRCKS, W J Office of the Executive Director for Operations 83/02/28 9pp 21958 016 24X Fiche 50-000, 83/11/02, B401250163
- B304050512 SECY-83-111
Requests Commission approval of exception for location of emergency operations facility for facilities
DIRCKS, W J Office of the Executive Director for Operations. 83/03/21 7pp 21958 033 24X Fiche 50-000, 83/11/02, B401250163.
- B303160182 SECY-83-161
Requests Commission authorization for exception to location of backup emergency operations facility 25 miles from plant site
DIRCKS, W J Office of the Executive Director for Operations. 83/05/02 5pp 21958 089 24X Fiche 50-000, 83/11/02, B401250163.
- B305160329 SECY-83-152
Recommends that Commission concur w/NRC approval of location of emergency operations facilities slightly beyond 20-mile limitations in Suppl 1 to NUREG-0737
DIRCKS, W J Office of the Executive Director for Operations 83/04/28 44pp 21958 041 24X Fiche 50-000, 83/11/02, B401250163.
- B305260352 Urges discussion on licensee disregard for NRC guidance re location of permanent & backup emergency operations facilities, per W Dircks B21227 memo Requests explanation re Waterford, Millstone & San Onofre plans
GILINSKY, V Commissioners 83/01/06, Commissioners 2pp. 21958 001, 24X Fiche 50-000, 83/11/02, B401250163
- B305260362 Responds to Commissioner Gilinsky B30106 comments on B21227 memo re implementation of emergency response facilities guidance Requested explanations re Waterford, San Onofre & Millstone plans provided.
DIRCKS, W J Office of the Executive Director for Operations. 83/02/13, PALLADINO, N Commissioners. 2pp 21958:303, 24X Fiche: 50-000, 83/11/02, B401250163
- B306020457 SECY-83-199
Requests Commission review NRC disapproval of primary emergency operations facility w/no habitability features.
DIRCKS, W J Office of the Executive Director for Operations 83/05/20 7pp 21958 183, 24X Fiche 50-000, 83/11/02, B401250163
- B306030153 SECY-83-192
Recommends Commission concurrence w/approval for exception to location of backup emergency operations facility beyond 20 miles for Maine Yankee Atomic power plant
DIRCKS, W J Office of the Executive Director for Operations 83/05/19 5pp 21958:167, 24X Fiche 50-000, 83/11/02, B401250163
- B306030404 SECY-83-191
Requests Commission review approval for exception to location of backup emergency operations facility beyond 20 miles from plant
DIRCKS, W J Office of the Executive Director for Operations. COMJA-80-37 83/05/18 8pp. 21958, 105 24X Fiche 50-000, 83/11/02, B401250163
- B306150117 SECY-83-223
Requests Commission review & disapprove divided emergency operations facility (EOF) concept for facilities.
DIRCKS, W J Office of the Executive Director for Operations. 83/06/07 7pp 21958:233 24X Fiche 50-000, 83/11/02, B401250163
- B306210319 SECY-83-205
Requests Commission review of staff approval for exception to location of backup emergency operations facility beyond 20-mile limit
DIRCKS, W J Office of the Executive Director for Operations 83/05/26, 8pp 21958 232 24X Fiche, 50-000, 83/11/02, B401250163
- B306280028 Advises that request to relocate overall accident mgt of emergency operations facility 100 miles from plant will be considered during second & third wks of June 1983. Proposal far exceeds current distance limitations.
DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 83/06/03, FAY, C W, Wisconsin Electric Power Co 2pp 21958:291 24X Fiche, 50-000, 83/11/02, B401250163.
- B306280032 Requests to be advised of date & time Commissioners will consider B20406 request to relocate emergency operations facility at corporate headquarters beyond guideline distance contained in NUREG-0696
FAY, C W, Wisconsin Electric Power Co. 83/03/30 CHILK, S J Office of the Secretary of the Commission. 1p 21958 289 24X Fiche 50-000, 83/11/02, B401250163.
- B401250182 Requests reply to questions on Page 2 of B21118 memo to Commissioners re emergency operations facilities (SECY-82-111)
GILINSKY, V Commissioners. 82/11/19 DIRCKS, W J Office of the Executive Director for Operations 1p 21958:003
- B401250185 Discusses how SECY-82-111 unravels NRC emergency preparedness requirements, per author B21103 memo Table III A 1 2-2 not changed in any way by SECY-82-111. Responses to listed questions requested.
GILINSKY, V Commissioners. 82/11/18 Commissioners. 2pp. 21958 004 24X Fiche, 50-000, 83/11/02, B401250163
- B401250188 Agrees w/B01120 memo recommending options for utils. per TMI Action Item III A 1 2, "Emergency Operation Facilities." Proposes that under Option 4, facility should be beyond 10 miles
GILINSKY, V Commissioners. COMJA-80-35 80/12/04 AHEARNE, J. Commissioners. 1p 21958 014
- B401250192 Notifies that emergency operations facility for plant paper (SECY-83-199) before Commission as negative consent paper. Agrees w/NRC disapproval of licensee proposal.
ABBELSTINE, J K Commissioners. 83/06/07, CHILK, S J Office of the Secretary of the Commission 1p. 21958 015, 24X Fiche: 50-000, 83/11/02, B401250163.
- B401250241 SECY-82-390
Recommends approval of request for exception under requirements & conditions of COMJA-80-35 & SECY-82-111 for location of emergency operations facility.
DIRCKS, W J Office of the Executive Director for Operations COMJA-80-35, 82/09/21, 10pp 21958:293, 24X Fiche: 50-000, 83/11/02, B401250163.
- B401250268 Forwards B10121 memo to WJ Dircks, requesting completion of SECY action on COMJA-80-37
CHILK, S J Office of the Secretary of the Commission. COMJA-80-37, 81/01/21, AHEARNE, J., GILINSKY, V, HENDRIE, J. Commissioners 1p 21958:312
- B401250281 Advises that Commission approved proposed policy statement, Suppl 1 to NUREG-0737 & draft 50 54(f) ltr re SECY-82-111B, "Requirements for Emergency Response Capability," subj to listed mods Marked-up policy statement encl
CHILK, S J Office of the Secretary of the Commission. 82/11/22, DIRCKS, W J Office of the Executive Director for Operations 5pp. 21958, 319,

NONDOCKETED ITEMS

--B401250283 Submits responses to questions raised re T-131 airborne releases during plant accident. Estimates of releases use actual effluent radiation readings & sample analyses during emergency conditions.
DIRCKEN, W. Office of the Executive Director for Operations
81/01/28 BRADFORD, P. Commissioners 3pp 21758 325 24X
Fiche: 50-000, 83/11/02, 8401250163

--B401250286 Forwards comments on proposed Commission papers. NRC should consider significant economic impact which would result if backup emergency operation facility rejected & dismantled into two separate locations.
EISENHUT, D. Q. Division of Licensing. 83/06/24 JORDAN, E. L.
Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 21758 328 24X Fiche: 50-000, 83/11/02, 8401250163

GEN TEC IS GENERIC TECHNICAL ISSUES

B310310465 Summarizes ACRS 282nd meeting on B31013-15 on NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 re PWR steam generators. Proposals should be implemented as recommendations only.
RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/10/18
PALLADINO, N. J. Commissioners 26pp 21855 019

--B310110265 Forwards for review draft program rept to be designated NUREG-0844, "NRC Integrated Program for Resolution of Unresolved Safety Issues A-3, A-4 & A-5 re Steam Generator Tube Integrity."
EISENHUT, D. Q. Division of Licensing 83/09/29 FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 300pp. 21855-045

--B308190529 "Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events." final rept.
MOREHOUSE, J. H. Science Applications, Inc. NRC-03-82-131
83/02/02 Division of Licensing. 325pp 21856-057.

--B401180025 "Prioritization of Steam Generator Generic Requirements Concerning Tube Degradation & Rupture Events."
* Division of Safety Technology. 83/10/18 49pp. 21857 019

--B308190537 "Prioritization of Staff Actions."
RIORDAN, R. Division of Safety Technology 83/02/14 44pp.
21857 069

--B401180035 NP-2704-BR
"PWR Secondary Water Chemistry Guidelines"
BELL, R. J., BLOMQUEN, J. C., FACKELMANN, J. M. Steam Generator Owners Group. 82/10/31. 92pp. 21857-113

B401030318 Forwards LABL draft, "TRAC Analyses of Potential Overcooling Transients at Calvert Cliffs-1 for Pressurized Thermal Shock Risk Assessment: Preliminary Summary."
JOHNSON, C. Reactor Risk Branch. 83/12/23 WOODS, R. Generic Issues Branch 2pp. 21695-259. 24X Fiche: 50-317, 83/12/23, 8401030318

--B401030323 Draft "TRAC Analysis of Potential Overcooling Transients at Calvert Cliffs-1 for Pressurized Thermal Shock Risk Assessment: Preliminary Summary."
KOENIG, J. E., SPRIGGS, O. D., SMITH, R. C. Los Alamos Scientific Laboratory 83/12/13. NRC - No Detailed Affiliation Given. 69pp. 21695-261 24X Fiche: 50-317, 83/12/23, 8401030318.

B401090520 Forwards BER based on encl technical evaluation rept of util response to NUREG-0612, Section 3.1.1 & 5.3 re control of heavy loads.
MILLER, J. R. Operating Reactors Branch 3 83/12/30. GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp 21768 115 24X
Fiche: 50-309, 83/12/30, 8401090520.

--B401090522 Safety evaluation in support of util response to NUREG-0612, "Control of Heavy Loads at Nuclear Plants." Phase 1.
* Office of Nuclear Reactor Regulation, Director. 83/12/30 2pp 21768-117. 24X Fiche: 50-309, 83/12/30, 8401090520.

--B312060211 TER-C5504-365
"Control of Heavy Loads (C-10) at Maine Yankee Nuclear Power Station." technical evaluation rept.
BOMBERGER, C. Franklin Institute/Franklin Research Center. NRC-03-81-130. TAC 08059. 83/12/02. SINGH, A., CHAN, T. NRC - No Detailed Affiliation Given. 28pp. 21768-119. 24X
Fiche: 50-309, 83/12/30, 8401090520

.B40160077 Forwards details of NUREG-0612, Section 5.1.1 guideline & compliance methodology review & response to Technical Evaluation Rept C5257-61/62/63 re special lifting device review, per 830526 ltr concerning control of heavy loads.
MILLS, L. M. Tennessee Valley Authority. 84/01/06 VASSALLO, D. B. Operating Reactors Branch 2. 19pp. 21815-067 24X
Fiche: 50-259, 84/01/06, 8401160077.

B401160159 Submits addl info re integral neutron sources for future core configurations, per NRC B31202 request re pressurized thermal shock Addl response will be submitted by end of Jan 1984
WHITTIER, O. D. Maine Yankee Atomic Power Co. MN-84-01 84/01/06
MILLER, J. R. Operating Reactors Branch 3 2pp 21809 360 24X
Fiche: 50-309, 84/01/06, 8401160159

B401160422 Summary of ACRS Subcommittees on Metal Components & DHR
B31012 combined meeting in Washington, DC re review of NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 concerning PWR steam generators
* ACRS - Advisory Committee on Reactor Safeguards 83/11/10
ACRS - Advisory Committee on Reactor Safeguards 19pp 21821 273

B401160425 Notification of B40112 meeting w/REB & Pacific Northwest Lab in Bethesda, Md to discuss feasibility study by Pacific Northwest Lab re vessel failure mode analyses for pressurized thermal shock events
WOODS, R. Generic Issues Branch 84/01/05 KNIEL, K. Generic Issues Branch 2pp 21821 292

B401170015 Further response to FOIA request for 42 documents Forwards Documents 14 & 20 Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/25 SHOLLY, B. C. Union of Concerned Scientists. 1p 21837 307

--B401170018 Responds to B20225 memo re draft licensing guidelines for implementation of NUREG-0646, Recommendation 4 concerning Generic Issue A-30, "Adequacy of Safety-Related DC Power Supplies." Concern could be met w/o major mod.
PARR, D. D. Auxiliary Systems Branch SHERON, B. Reactor Systems Branch. 82/03/12 SRINIVASAN, M. Power Systems Branch 2pp 21837 312

B401170052 Partial response to FOIA request for 42 categories of documents Forwards listed documents Documents also available in PDR Review of addl records subj to request in progress.
FELTON, J. M. Division of Rules and Records 83/10/03 SHOLLY, B. C. Union of Concerned Scientists. 1p 21846 163

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-64, C-7, C-12 & III, D 2, 3, per Denton request.
VOLLMER, R. H. Division of Engineering IEB-82-02 83/02/01
SPEIB, T. P. Division of Safety Technology 16pp 21846-168

--B21160524 Notifies of status of unresolved items in draft NUREG-0933, "Prioritization of Generic Safety Issues." Four items resolved, B-19 should be dropped as generic issue, A-16 & NUREG-0737, Item II, E 5.1 nearly complete
MATTSOHN, R. J. Division of Systems Integration (post 811005). 82/11/05 FUNCHES, J. L. Planning & Program Analysis Staff 6pp 21846-220.

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-64, C-7, C-12 & III, D 2, 3, per Denton request.
VOLLMER, R. H. Division of Engineering IEB-82-02 83/02/01
SPEIB, T. P. Division of Safety Technology. 16pp 21846-168.

--B201750195 Submits suggestions re design sensitivity of B&W reactors CPC or contractor should obtain cost of necessary changes & estimate of occupational exposure that might be incurred
Info should then be used to develop value impact statement.
HANAUER, B. H. Division of Systems Integration (post 811005) 82/06/21 MATTSOHN, R. J. Division of Systems Integration (post 811005). 2pp. 21846-252

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-64, C-7, C-12 & III, D 2, 3, per Denton request.
VOLLMER, R. H. Division of Engineering IEB-82-02 83/02/01
SPEIB, T. P. Division of Safety Technology. 16pp 21846-168

--B401170090 Discusses status of branch work on Generic Issue B-6, in response to RJ Bosnak B20826 memo to W Minners More detailed study on loads & load combinations initiated at BNL. No further investigation required.
SCHAUER, F. P. Structural Engineering Branch. 82/09/02 MINNERS, W. Safety Program Evaluation Branch 1p 21846 226

--B21160524 Notifies of status of unresolved items in draft NUREG-0933, "Prioritization of Generic Safety Issues." Four items resolved, B-19 should be dropped as generic issue, A-16 & NUREG-0737, Item II, E 5.1 nearly complete
MATTSOHN, R. J. Division of Systems Integration (post 811005). 82/11/05 FUNCHES, J. L. Planning & Program Analysis Staff. 6pp 21846-220.

NONDOCKETED ITEMS

429

--8207150195 Submits suggestions re design sensitivity of B&W reactors CPC or contractor should obtain cost of necessary changes & estimate of occupational exposure that might be incurred Info should then be used to develop value impact statement
HAWAUER, S H Division of Systems Integration (post B1005)
82/05/21 MATTHEW, R J Division of Systems Integration (post B1005) 2pp 21846 232

--8211160524 Notifies of status of unresolved items in draft NUREG-0933, "Prioritization of Generic Safety Issues " Four items resolved B-19 should be dropped as generic issue A-16 & NUREG-0737, Item 11 E 5 1 nearly complete
MATTHEW, R J Division of Systems Integration (post B1005)
82/11/05 FUNCHES, J L Planning & Program Analysis Staff 6pp 21846.220

B401170181 Informs that util will not be able to respond to draft technical evaluation reft open items re control of heavy loads within recommended time frame Responses to open items will be provided by B40203
ZIMMERMAN, S R Carolina Power & Light Co NLS-B4-013 B4/01/12
VASSALLO, D B Operating Reactors Branch 2 1p 21834 152 24X
Fiche 50-324, B4/01/12, B401170181

B401170515 Advises that util actions taken in response to NRC B01222 ltr & Generic Ltr B1-07 re control of heavy loads satisfy requirements
SNYDER, B J THF Program Office OL-B1-07 B4/01/05 KANGA, B K General Public Utilities - OPU Service Corp 3pp 21847, 132 24X
Fiche 50-320, B4/01/05, B401170515

B401170533 Summary of ACRS Ad Hoc Subcommittee on DHR Sys B10908 meeting in Washington, DC re DHR requirements
* ACRS - Advisory Committee on Reactor Safeguards B1/10/08
ACRS - Advisory Committee on Reactor Safeguards 13pp 21847 059

B401190193 Forwards INEL repts EGO-EA-6473 & EGO-EA-6468 re Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Comments on technical accuracy requested by B40213
SZUKIEWICZ, A J Generic Issues Branch B4/01/12 STRIBLING, T Carolina Power & Light Co 2pp 22035 352

--B401310429 EGO-EA-6473
"Rept Concerning Effects of Control Sys Failures on Steam Generator Overfill & RCS Overcooling Events at Typical Westinghouse 3-Loop Plant," informal rept
BAKTER, D E , BRUSKE, S J , RAMSOM, C B EG&O, Inc FIN A-6477
B3/12/31 NRC - No Detailed Affiliation Given 126pp
22036 001

--B401310435 EGO-EA-6468
"Westinghouse 3-Loop Other Transients Failure Mode & Effects Analysis & Rejected Sys Justification Rept," informal rept
BAKTER, D E , BRUSKE, S J , STROMBERG, H M EG&O, Inc FIN A-6477
B3/12/31 NRC - No Detailed Affiliation Given 122pp
22036 118

B401200115 Forwards safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads "
CRUTCHFIELD, D Operating Reactors Branch 5 L505-B4-01-025
B4/01/18 MAIER, J E Rochester Gas & Electric Corp 2pp
21863 251 24X Fiche 50-244, B4/01/18, B401200115

--B401200121 Safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads "
* Office of Nuclear Reactor Regulation, Director B4/01/18 3pp
21863 253 24X Fiche 50-244, B4/01/18, B401200115

--B312060347 TER-C5506-357
"Control of Heavy Loads C-10, RE Ginna Nuclear Power Plant," technical evaluation rept.
VOSSURV, F W , BOMBERGER, C Franklin Institute/Franklin Research Center NRC-03-B1-130 TAC 07992. B3/12/02 BINGH, A., CHAN, T
NRC - No Detailed Affiliation Given 30pp 21863 256 24X
Fiche 50-244, B4/01/18, B401200115

B401230042 Notifies of intent to load & move during power operation, cask similar to 7-1/2 ton cask referred to in SER Also reaffirms 76108 commitment not to use 60 ton fuel shipping cask w/o prior NRC approval
BORDONE, T C Consumers Power Co B4/01/18 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 21884, 346 24X
Fiche 50-155, B4/01/18, B401230042

B401230227 Advises that Guidelines 1, 2, 3 & 4 of NUREG-0612 re control of heavy loads fully implemented
MAIER, J E Rochester Gas & Electric Corp B4/01/11 CRUTCHFIELD, D. Operating Reactors Branch 5, 1p 21884 079 24X
Fiche 50-244, B4/01/11, B401230227

B401240118 Informs that addl mods & heavy loads procedure revs required, per B20122 ltr Redundant upper travel limit switch installation on main & auxiliary hooks for turbine & fuel bldgs & containment polar cranes completed per NUREG-0612.
WITHERS, B D Portland General Electric Co B4/01/18 EISENHUT, D. O Division of Licensing 1p 21912 287 24X Fiche 50-344, B4/01/18, B401240118

B401240174 Answer opposing, in every aspect, Intervenor Lewis B31227 motion for reconsideration of ASLB decision granting util motion for summary disposition of Contention I-62 re pressurized thermal shock Insinuations unfounded
WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn B4/01/20 Atomic Safety and Licensing Board Panel 11pp 21908 280 24X Fiche 50-352, B4/01/20, B401240174

B401250008 Summary of B31215 meeting in Bethesda, MD w/seismic qualification util group & senior seismic review advisory panel re recommendations for use of non-nuclear plant seismic experience data to evaluate seismic adequacy
CHANG, T Y Generic Issues Branch B4/01/09 KNIEL, K Generic Issues Branch 3pp 22027 001

--B312220016 Notification of B31215 meeting w/senior Seismic Review Advisory Panel & Seismic Qualification Util Group to discuss findings & recommendations on use of seismic experience data from non-nuclear plants for evaluating equipment
CHANG, T Y Generic Issues Branch B3/12/09 KNIEL, K Generic Issues Branch 6pp 22027 003

B401250015 Partial response to FOIA request for all 1982 SECY papers. Forwards App A documents. Remaining documents under review
FELTON, J M Division of Rules and Records B3/10/18 WEISS, E R Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, B3/10/18, B401250015

--B21090006 SECY-B2-432
Informs of issuance of NUREG-0744, Vols I & II, Rev 1, "Resolution of Task A-11, Reactor Vessel Matls Toughness Safety Issue "
DROCKE, W J Office of the Executive Director for Operations. B2/10/22 2pp 21967 111.

B401300030 Forwards "App B, Comparison of Special Lifting Device Design to ANSI N14 6-1978," per B30729 response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants "
BECKHAM, J T Georgia Power Co NED B4-019 B4/01/23. STOLZ, J F Operating Reactors Branch 4 15pp. 21999 248 24X
Fiche 50-321, B4/01/23, B401300030

B401300250 Forwards responses to B20315 request for addl info, Items 5, 6(b) & 7 re control of heavy loads Ltr completes response to all NRC questions.
OTTOLE, J D Consolidated Edison Co of New York, Inc B4/01/20 VARGA, B A . Operating Reactors Branch 1 21pp 21995 209. 24X
Fiche 50-247, B4/01/20, B401300250

B401310057 Forwards "RELAP5 Thermal-Hydraulic Analyses of Pressurized Thermal Shock Sequences for HB Robinson, Unit 2 PWR," for placement in PDR. Transients described are hypothetical & have not actually occurred.
REYES, J N Division of Accident Evaluation (Pre B40101). B4/01/16 MCKNIGHT, J. C Document Management Branch 1p 22029 001 24X
Fiche 50-261, B4/01/16, B401310057

--B401310061 EGO-SAAM-6476
"RELAP5 Thermal-Hydraulic Analyses of Pressurized Thermal Shock Sequences for HB Robinson, Unit 2 PWR," informal rept.
FLETCHER, C D., BOLANDER, M. A., WATERMAN, M E EG&O, Inc FIN A-6047 B3/12/31 NRC - No Detailed Affiliation Given. 285pp
22029 002 24X Fiche 50-261, B4/01/16, B401310057.

B401310302 Responds to B31123 request re reactor vessel fluence associated w/current & future core configurations Info including core power & calculated flux distributions at vessel wall will be sent by B40530
JONES, W C Omaha Public Power District LIC-B4-022 B4/01/24 MILLER, J R Operating Reactors Branch 3 2pp 22026, 224. 24X
Fiche 50-285, B4/01/24, B401310302.

B401310363 Clarifies B10925 ltr re NUREG-0612, "Control of Heavy Loads." Permanent crane rail stops will be installed prior to fuel load to prevent fuel bldg crane travel over spent fuel storage pool throughout remaining plant life.
OELER, J D Illinois Power Co U-0690 B4/01/26. SCHWENCER, A. Licensing Branch 2 1p 22026:255. 24X Fiche 50-461, B4/01/26, B401310363

B401310366 Forwards schedule of commitments adjusted to new fuel load schedule, per util B31216 ltr Appropriate date changes will appear in next FSAR amend
KAHMER, D S Tennessee Valley Authority B4/01/27. ADENSAM, E. Licensing Branch 4. 2pp 22015:051. 24X Fiche 50-438, B4/01/27, B401310366

NONDOCKETED ITEMS

I&E INSPECTION AND ENFORCEMENT

- 8312120090 IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/12/28 Consolidated Edison Co. of New York, Inc 124pp 21731 166 24X Fiche 50-000, 83/12/28, 8312120090
- 8312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in Brown Boveri Electric Type 3HK Breakers." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/12/30 Consolidated Edison Co. of New York, Inc 127pp. 21826:060. 24X Fiche 50-000, 83/12/30, 8312120093
- 8312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at Voltage Levels Lower Than Analyzed." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc. 125pp. 21946:053 24X Fiche 50-000, 84/01/10, 8312120104
- 8312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable Sheaths." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/10 Consolidated Edison Co. of New York, Inc 122pp. 21826:184 24X Fiche 50-000, 84/01/10, 8312120107.
- 8312120114 IE Info Notice 84-05, "Exercise Frequency " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/16 Consolidated Edison Co. of New York, Inc 127pp. 21937:142 24X Fiche: 50-000, 84/01/16, 8312120114
- 8312120116 IE Info Notice 84-03, "Compliance W/Conditions of License & Notification of Disability by Licensed Operators." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18 Consolidated Edison Co. of New York, Inc 118pp. 21999:284 24X Fiche: 50-000, 84/01/18, 8312120116
- 8312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly Valves Used Only During Cold Shutdowns " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/01/18. Consolidated Edison Co. of New York, Inc. 120pp 22000 041. 24X Fiche: 50-000, 84/01/18, 8312120117.
- 8312190241 EN-83-080: on 831219, notice of violation & proposed imposition of civil penalties in amount of \$6,400 will be issued. Action involves violations re inadequate training, control of licensed matl & control of exposure. FLACK, E, AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/12/14. 1p. 21561:208
- 8312210189 PNO-I-83-097A: licensee reviewed charts of all telotherapy patients treated w/wedges during Jul 1980 to Aug 1983. Licensee identified 33 cases w/doses 10X below prescribed medical protocols. Physicians notified of patient status. JOHANSEN, J., GLENN, J., JOYNER, J. Region 1, Office of Director 83/12/15 1p. 21600:119.
- 401030245 PNB-V-83-014: on 831219, accidental discharge of security weapon occurred in security of bldg during routine shift change. Projectile struck floor, causing minor damage. No injuries occurred. BCHAN, C., NORDERHAUS, L. Region 5, Office of Director 83/12/20. 1p. 21680:362. 24X Fiche, 50-275, 83/12/20, 8401030245.
- 8401040356 PNO-I-83-128: on 831228, inspector found Automation Industries Model 500 SU source changer on street Changer intact, padlocked & labeled w/radioactive yellow III label. Changer contained In-192 w/transport index of 1 m/h. DENNIS, N., KINNEMAN, J. Region 1, Office of Director, 83/12/28. 2pp. 21706:149.
- 401040418 PNO-III-83-135 on 831222, three remaining stop work orders involving HVAC sys lifted per util request Prior to concurring in lifting work procedures, training & certification of welders reviewed. MARABITO, R., HAYES, D. Region 3, Office of Director 83/12/22. 1p 21706:209 24X Fiche: 50-461, 83/12/22, 8401040418
- 8401040462 PNO-III-83-134: on 831221, five member task force appointed by governor of IN to study feasibility of completing plant recommended cancellation. Findings not binding. Public Svc Commission inquiries expected. SCHAPKER, J., KNOP, R. Region 3, Office of Director 83/12/22 1p. 21709:313. 24X Fiche: 50-546, 83/12/22, 8401040462.
- 8401040537 PNO-V-83-060 on 831215, w/svc air compressor C out of svc, compressor B tripped out of svc Pressure dropped to 95 psig. Temporary air compressors installed & pressure returned to normal Plant will be placed in cold shutdown YOUNG, T. Region 5, Office of Director 83/12/15 1p 21707 241 24X Fiche 50-312, 83/12/15, 8401040537
- 8401050318 PNO-I-84-001 on 831230, emergency diesel generator 101 shut down manually due to loud noise Insp revealed rocker arm hold down bolts on cylinder subcover had come loose, causing rocker arm assembly to strike other components KELLY, E., PETRONE, C., ESELDOROTH, P. Region 1, Office of Director, 84/01/03 1p 21726 358 24X Fiche 50-322, 84/01/03, 8401050318
- 8401050399 PNO-II-84-001 on 840103, bomb threats received at facility Searches revealed no bomb FBI, media & info assessment team notified MCGUIRE, D R., TOBIN, W J. Region 2, Office of Director, 84/01/03 1p 21731 124 24X Fiche, 50-321, 84/01/03, 8401050399
- 8401100190 PNO-III-84-002 on 831129, offsite power circuit breaker opened for no apparent cause investigation determined magnetic coupling became weak Allis Chalmers supplied mod kits. Mods complete JORDAN, M., SHAFER, W. Region 3, Office of Director 84/01/04 1p 21760 150 24X Fiche 50-409, 84/01/04, 8401100190
- 8401100327 PNO-IV-83-034B on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212 Order involved breakdown in QA program re document control sys Order lifted on 831219 CROSSMAN, W A. Region 4, Office of Director 83/12/19 1p. 21764 144 24X Fiche 50-498, 83/12/19, 8401100327
- 8401100375 PNO-IV-83-034A. on 831213, licensee informed Region IV that stop work order imposed on safety-related const activities on 831212 Order issued due to breakdown in QA program Stop work order to be lifted on 831216 in site fabrication shop. CROSSMAN, W A. Region 4, Office of Director 83/12/16. 1p 21763. 289 24X Fiche 50-498, 83/12/16, 8401100375
- 8401100454 PNO-III-83-134A on 831230, licensee announced suspension of all const activities, effective immediately & halt of all contract work, effective 840103 Maint & storage of records, matls & equipment will continue Alternatives under exam PELKE, P., KNOP, R. Region 3, Office of Director 84/01/03 1p. 21761. 285 24X Fiche, 50-546, 84/01/03, 8401100454.
- 8401120343 EN-83-063A notice of violation & proposed imposition of civil penalty in amount of \$8,000 to be issued, based on noncompliance in emergency procedures & inadequate surveys during retrieval of 47 Ci Ir-192 source & evaluation FLACK, E, AXELRAD, J. Director's Office, Office of Inspection and Enforcement 84/01/10 1p. 21791 012
- 8401120380 EN-84-002, on 840109, notice of violation & proposed imposition of civil penalty of \$40,000 to be issued Action based on violations of fire protection requirements Notice includes citation for matl false statement. CRAIG, J., AXELRAD, J. Director's Office, Office of Inspection and Enforcement, EN 84-002. 84/01/09 1p 21791:017. 24X Fiche 50-324, 84/01/09, 8401120380
- 8401120420 PNO-I-84-002 on 840105, reactor automatically scrammed from full power due to pressure oscillation induced by turbine generator electrical pressure regulator Alternate power supply to reactor protection sys lost RAYMOND, W J., GALLG, R., KISTER, H. Region 1, Office of Director 84/01/06 2pp 21791 181. 24X Fiche, 50-271, 84/01/06, 8401120420
- 8401120422 PNO-V-84-002 on 840102, NRC resident inspector observed asdla repts of 2.5 to 2.7 magnitude earthquake reportedly occurring seven miles from facility. Plant seismic instrumentation not triggered by event. * Region 5, Office of Director, 84/01/03. 1p. 21791:021. 24X Fiche, 50-275, 84/01/03, 8401120422
- 8401130280 EN-84-001: confirmatory order will be issued on or about 840112, Order confirms commitment & requires util to submit plan for independent appraisal of site & corporate mgt organizations & functions KLINOLER, O., AXELRAD, J. Director's Office, Office of Inspection and Enforcement, 84/01/06 1p. 21798. 360 24X Fiche: 50-329, 84/01/06, 8401130280
- 8401130317 PNO-I-84-003, on 831220, licensee employee reported exposure to tip of thumb of 3,400 rad & 1,200 rad to tip of right index finger. Interlocks used to prevent entry while machine malfunctioned. Investigation ongoing. GLENN, J. Region 1, Office of Director, 84/01/09 1p 21798. 308

NONDOCKETED ITEMS

43

8401130393 PNO-III-83-003 on 840108, reactor tripped automatically due to neutron flux imbalance in reactor core. Caused by axial power shaping rods automatically inserting. Reactor in hot shutdown until Region III concurs in resolution.
JORDAN, M., JACKMAN, I., SHAFER, W. Region 3, Office of Director
84/01/10 1p 21798 361 24X Fiche 50-346, 84/01/10, 8401130393

8401160161 PNO-III-84-004 on 840109, reactor operator omitted 20 steps in rod insertion procedure during shutdown process. Procedure indicated slash when control rod inserted & operator interpreted slash as omission of step. No fuel damage noted.
MADISON, A., WALKER, R. Region 3, Office of Director 84/01/10 1p
21815 345 24X Fiche 50-237, 84/01/10, 8401160161

8401160223 PNO-V-84-001 on 840101, unplanned gaseous releases occurred, causing plant vent stack to alarm. Release caused by draining 20 gallons of water from charging sys to floor drain. Release estimated to be 80 Ci mixed noble gases.
YUHAS, G., WENSLAWSKI, F. Region 3, Office of Director 84/01/04 1p
21815 358 24X Fiche 50-362, 84/01/04, 8401160223

8401160230 PNO-III-84-005 on 840108, during plant shutdown, diesel generator 1-1 overheated & was manually tripped, resulting in loss of all onsite power. Caused by breaker malfunction. Malfunctioning breaker replaced.
BOYD, D., SHAFER, W. Region 3, Office of Director 84/01/10 2pp
21814 220 24X Fiche 50-255, 84/01/10, 8401160230

8401180247 PNO-I-84-005 on 840113, one individual identified w/ thyroid burden at approx 6 uCi. I-125 inspectors will conduct complete insp on 840116. Licensee initiated complete investigation.
KINNEHAN, J., JOYNER, J. Region 1, Office of Director 84/01/16 2pp
21844 115

8401180271 PNO-I-84-004 on 830112, well supplying drinking water to community near facility closed during wk of 840102 due to exceeding EPA drinking water std for gross alpha activity. Addl analysis & resampling for isotopes conducted.
KINNEHAN, J., JOYNER, J. Region 1, Office of Director 84/01/12 2pp
21843 247

8401190347 PNO-I-84-006 on 840114, while performing monthly surveillance testing of emergency diesel generator, D/crankcase explosion occurred. Event under investigation. Piston & liner being replaced.
PLISCO, L., MCCABE, E. Region 1, Office of Director 84/01/16 1p.
21850 319 24X Fiche 50-387, 84/01/16, 8401190347

8401190367 EN-83-068A on 840117, order imposing monetary penalty in amount of \$2,500 issued. Action based on 12 violations including five identified during previous insp. Payments or request for hearing expected within 30 days.
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 84/01/17 1p
21850 157

8401190389 PNO-I-84-001A on 831230, emergency diesel generator 101 rocker arm hold-down bolts on cylinder 3 failed. Caused by untorqued bolts during preassembly procedure. Assembly procedures reviewed & subcovers to be replaced by 840104.
KELLY, E., PETRONE, C., ESELROTH, P. Region 1, Office of Director, 84/01/04 1p
21849 321 24X Fiche 50-322, 84/01/04, 8401190389

8401200044 PNV-V-84-001 on 840102-13, Abalone Alliance distributed leaflets in community surrounding facility announcing next anti-nuclear demonstration will begin on 840113. Coordinated command ctr established for all law enforcement agencies.
SCHAEFER, D. W. Region 5, Office of Director 84/01/12 1p
21867 029 24X Fiche 50-275, 84/01/12, 8401200044

8401230258 PNO-III-84-007 on 840116, flexible metallic joint in steam exhaust sys from turbine ruptured, causing loss of vacuum in condenser & reactor shutdown. Repairs to flexible metallic joint to take 2-3 days.
MADISON, A., SHAFER, W. Region 3, Office of Director, 84/01/05 1p
21883 362 24X Fiche 50-373, 84/01/17, 8401230258

8401230392 PNO-III-84-006 on 840116, Util announced company financially unable to proceed w/ const. Cancellation of project contingent on approval of Wabash Valley Assoc which owns portion of plant.
KONKLIN, J., KNOP, R. Region 3, Office of Director, 84/01/16 1p.
21873 354 24X Fiche 50-346, 84/01/16, 8401230392

8401240004 PNO-II-84-002 on 840118, 12-inch raw cooling water line, located 15 ft underground, broke & flooded underground vault housing devices for treating offgas activity. Cause not determined. Water pumped out.
CANTRELL, F. S., VERRELLI, D. M. Region 2, Office of Director, 84/01/18 2pp
21912 307 24X Fiche 50-259, 84/01/18, 8401240004

8401240080 PNO-V-84-004 radiographer received possible exposure dose of 4.5 rem for Dec 1983. Licensee investigation underway.
THOMAS, R. D., PANQ, J. F. Region 3, Office of Director 84/01/16 1p
21912 342

8401240154 PNO-I-84-007 on 840117, package received missing one of three vials of 1.1 mCi Cs-141. Package received at Univ of Rochester had been opened & resealed. NRC issuing press release.
GLENN, J., JOYNER, J. Region 1, Office of Director 84/01/18 2pp
21910 253

8401240478 PNO-I-84-005A on 840116, circumstances re finding that one individual had thyroid burden of 6 mCi. I-125 reviewed. No radiation levels above background at home of individual noted.
NICOLOSI, J., JOYNER, J. Region 1, Office of Director 84/01/19 1p
21920 056

8401260348 PNO-II-84-003 on 840123, Util began curtailing various refueling & mod activities which will result in layoff of 200 to 300 employees. Operations not affected. Media interest occurred. No news release planned.
CANTRELL, F. S., VERRELLI, D. M. Region 2, Office of Director, 84/01/23 1p
21955 126 24X Fiche 50-296, 84/01/23, 8401260348

8401270120 PNO-IV-84-001 on 840117, State of NM Radiation Protection notified NRC that Smith Pipe & Steel truck discovered carrying Co-60 contaminated rebar. Shipment distributed through broker in Phoenix, AZ from sales company in Mexico.
HEYER, R. S., DODA, R. J. Region 4, Office of Director 84/01/09 2pp.
21982 025

8401300110 PNO-III-84-009 on 840120, two workmen accidentally uncoupled 1/2-inch swagloc fitting on unsolable portion of in-core thimble. Flow rate was approx 100 gpm. Workmen decontaminated & swagloc fitting replaced.
BOYD, D., SHAFER, W. Region 3, Office of Director, 84/01/23 2pp
21999 187 24X Fiche 50-295, 84/01/23, 8401300110

8401300133 PNO-I-84-008 on 840124, Util announced delay in completing Unit 2 due to PUC of PA ruling based on determination of no need for addl power.
BAURACK, CONNER Region 1, Office of Director 84/01/24 1p
21998 286 24X Fiche 50-353, 84/01/24, 8401300133

8401300143 PNO-III-84-008 on 840121, licensee announced that facility will be converted to coal-fired plant rather than nuclear plant. Facility expected to be operational in 1991.
FORNEY, W., WARNICK, R. Region 3, Office of Director 84/01/23 1p
21998 262 24X Fiche 50-358, 84/01/23, 8401300143

8401300169 PNO-I-84-009 on 840124, small amount of water observed on containment floor. Leak could not be isolated & plant began shutdown in accordance w/ Tech Specs. Lagging on steam generator 1 water box vent line wet & drip observed.
FERLIC, GREENAN Region 1, Office of Director 84/01/25 1p
21997 121 24X Fiche 50-029, 84/01/25, 8401300169

8401300288 PNO-II-84-004 on 840124, dead fish observed along bank of Banner Spring. Licensee analyzing stream samples & fish for radioactivity & chemical pollutants & investigating sources of pollutants within plant.
KAHLE, J., MCALPINE, E. J. Region 2, Office of Director 84/01/25 1p.
21977 300

8401300290 PNV-I-84-001 on 840124, bomb threat received at plant. Bomb search initiated of protected & vital areas. Results of search negative. No areas of plant evacuated.
SMITH, G., JOYNER, J. Region 1, Office of Director 84/01/25 1p.
21977 344 24X Fiche 50-213, 84/01/25, 8401300290

8401300292 PNO-II-84-005 on 840125, special emergency drill temporarily suspended due to discovery of plastic bottle at radiation control point exterior to vital areas, w/ handwritten label, "Danger Nitroglycerine." Event determined to be hoax.
TOBIN, W. J., MCGUIRE, D. R. Region 2, Office of Director, 84/01/25 2pp.
21975 357 24X Fiche 50-389, 84/01/25, 8401300292

8401310211 PNO-I-84-010 on 831227, film badge of employee involved w/ patient on 831227 receiving 200 mCi I-131, showed high exposure. Employee also involved in therapy treatment w/ I-192 during Dec 1983.
JERMAN, P., GLENN, J., JOYNER, J. Region 1, Office of Director, 84/01/25 1p.
22021 348

8401310290 PNO-III-84-011 between 831209-16, 10 truckloads of contaminated steel castings received from Aceros de Chihuahua Foundry in Mexico. Matl will be isolated until disposal determination made. Consultant will be onsite.
BRENTAWSKI, D., AXELSON, W. Region 3, Office of Director 84/01/27 2pp
22020 232

NONDOCKETED ITEMS

8401310344 PNO-III-84-010 on 840126, approx 135 persons participated in demonstration opposing continued storage of U at utility warehouse in East St Louis, IL. Major fire occurred at warehouse on 831207
 LABUM, S., AXELSON, W Region 3, Office of Director 84/01/27. 1p.
 22015 05B

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8312080191 Submits concurrence on proposed rule package containing clarifying amend to 100FR73 40(a) re general physical protection, in response to 831110 request. Verbal concurrence provided on 831117
 EISENHUT, D O. Division of Licensing 83/11/21 BURNETT, R F
 Division of Safeguards 1p 21434-024

8312000510 Submits results of actions identified as Items 1-4 of IE Bulletin 83-07 & Suppl 1, "Apparently Fraudulent Products Sold by Ray Miller, Inc."
 BUCKHAM, J A Allied General Nuclear Services 83/12/14
 O'REILLY, J P Region 2, Office of Director 3pp 21584-033.

8312000034 Forwards comments & markup of packages of matls pursuant to Section 306 of Public Law 97-425 Several concerns remain
 OLMSTEAD, W J Regulations Division 83/11/01 THOMPSON, H L
 Division of Human Factors Safety 1p. 21668-027

8401060531 Advises that proposed response to Critical Mass Energy Project ltr re public access to NPRDS should indicate application of liberal policy
 DENTON, H R. Office of Nuclear Reactor Regulation, Director.
 83/12/14 HELTEMES, C J Director's Office. 1p. 21753-134.

--8401060536 Forwards for review & comment, draft description of NRC needs re public access to & use of NPRDS & draft response to questions raised. Comments requested by 831207. W/o encl.
 HELTEMES, C J. Director's Office 83/12/28 DENTON, H R Office of Nuclear Reactor Regulation, Director. DEVLINO, R C. Director's Office, Office of Inspection and Enforcement MINOQUE, R B. Office of Nuclear Regulatory Research, Director. 1p 21753-135

--8401060545 Expresses concern re NRC arrangement to have certain categories of events reported to INPD info re reporting methods & public access requested.
 TOTYEN, M Critical Mass Energy Project. 83/09/29 PALLADINO, N J
 Commissioners 11pp. 21753-136.

8401090531 Informs of review of proposed research project re quantification of risk of core damage due to deliberate acts at nuclear power reactors. Div of Licensing concurs w/ listed comments
 EISENHUT, D O. Division of Licensing. 83/12/22 SPEIB, T P
 Division of Safety Technology. 1p 21767-357.

01110403 Responds to 831028 ltr requesting reconsideration of IE Info Notice 83-60, "Falsification of Test Results for Protective Coatings." NRC concern re falsified matls evident in listed bulletins & notices.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). IEIN-83-60 83/12/27 RICE, S. P. Kindel & Anderson. 4pp. 21795-152.

--840110411 Requests amend to IE Info Notice 83-60, "Fabrication of Test Results for Protective Coatings." Notice inaccurate, incomplete & misleading in several important aspects. Public should be informed of errors/omissions in notice
 RICE, S P. Kindel & Anderson IEIN-83-60. 83/10/28 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 3pp. 21795-207

01120340 Comments on fee for review & approval of senior reactor operator requalification programs. Need for NRC review & approval of requalification program codified in regulations Fee appropriate.
 FONNER, R. L. Regulations Division. 84/01/06. MILLER, W. O. License Fee Management Branch. 1p. 21792-032.

--8401120349 Forwards General Physics Corp 830902 ltr transmitting senior reactor operator requalification program for review Opinion re applicability of assessing review fees under 100FR170 requested.
 MILLER, W O. License Fee Management Branch 83/12/22. FONNER, R. L. Regulations Division 2pp. 21792-033

--8401120361 Forwards outline of senior reactor operator requalification program for review.
 ANTONACCI, T General Physics Corp OP-L-122525 83/09/02
 THOMPSON, H L. Division of Human Factors Safety. 4pp. 21792-035.

8401160433 Forwards draft IE bulletin, "Undervoltage Trip Attachments of Reactor Trip Breakers." Comments received by 840120 will be considered in final draft
 ROSSI, C Events Analysis Branch 84/01/09 GILLISPIE, D L
 Institute of Nuclear Power Operations 5pp 21821-268

8401160449 Forwards draft IE bulletin, "Undervoltage Trip Attachments of Reactor Trip Breakers." Comments received prior to 840120 will be considered in final draft
 ROSSI, C Events Analysis Branch 84/01/09 BIVENS, A Atomic
 Industrial Forum 5pp 21821-263

8401190107 Summary of 831129-1201 meetings w/ Industry Degraded Core Rulemaking Program (IDCOR) in Harpers Ferry, WV re accident phenomenology & containment loading Severe accidents, areas of disagreements & uncertainties discussed
 SPEIB, T P Division of Safety Technology 83/12/14 DENTON, H R, CASE, E Office of Nuclear Reactor Regulation, Director MATTSON, R
 Division of Systems Integration (post 811005) 7pp 21871-062

8401200320 Responds to questions raised during R Baer recent trip to South Korea re extent of NRC support to nuclear emergency response program in Taiwan NRC has not participated in any emergency exercises conducted in Taiwan
 SHEA, J R Office of International Programs, Director 84/01/11
 PARK, S Korea, Republic of (South Korea) 5pp 21872-090

8401230157 "Radiological Survey of American Bearing Corp, Indianapolis, IN."
 ROCCO, B P, BERGER, J D, CONDRA, R D Oak Ridge Associated Univs
 FIN A-9093. 83/11/30 Division of Fuel Cycle & Material Safety
 59pp. 21931-105.

8401230562 Forwards responses to questions asked during 831128-1201 Ka-Ri-1 nuclear plant emergency exercise
 BAER, R L Engineering & Generic Communications Branch. 84/01/13
 MOON, P S Korea, Republic of (South Korea) 23pp. 21902-064

8401250166 Forwards draft IE bulletin re undervoltage trip attachments of reactor trip breakers Input received prior to 840120 will be considered in preparation of final draft to be presented to CRGR
 ROSSI, C E Events Analysis Branch 84/01/12 GOERING, G
 Westinghouse Operating Plants Owners Group GOERING, G Northern
 States Power Co 5pp 21952-356.

8401250440 Discusses Public Law 97-415 authorizing NRC to issue & make immediately effective amendments to OL involving NSMC Legislation requires NRC to publish notice of amendments issued or proposed to be issued Sample notice encl. W/o encl
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 84/01/05 SIMPSON, A Senate, Environment & Public Works.
 UDALL, M K House of Rep., Interior & Insular Affairs OTTINGER, R L
 House of Rep., Energy & Commerce 2pp 21949-024

8401250447 Forwards 830912 "Trip Rept-Audit of Rockbestos Co Qualification Documents" for placement in PDR.
 NOONAN, V S Equipment Qualification Branch 84/01/10
 MCKNIGHT, J C. Document Management Branch 1p. 21999-269

--8309230072 Trip rept of 830816 & 17 visit to Sandia Natl Lab & Franklin Research Ctr re audit of Rockbestos Co environ qualification program
 MASCANTONIO, A Equipment Qualification Branch 83/09/12
 NOONAN, V S Equipment Qualification Branch. 7pp 21999-270

--8309230076 TER-C5B63-1
 "Evaluation of Rockbestos Environ Qualification Test Data," technical evaluation rept.
 BACANABAS, V P. Franklin Institute/Franklin Research Center
 NRC-03-83-112 83/09/31. LAGRANGE, R NRC - No Detailed
 Affiliation Given. 7pp. 21999-277.

8401250469 Forwards draft IE bulletin re undervoltage trip attachments of reactor trip breakers. Input requested prior to 840120 to be considered for final draft to be presented to CRGR.
 ROSSI, C E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/12 VANDEWALLE, D C-E Operating Plants Owners
 Group VANDEWALLE, D Consumers Power Co 5pp 21949-001

8401300192 Notifies of results of compliance action against HJ Kaiser Co. Investigation revealed that termination was due to general reduction in work force & not refusal to falsify &/or augment GA-related documents
 FIERST, G A Labor, Dept. of 84/01/20 ABSON, J E Affiliation
 Unknown 3pp 21998-256.

8401310079 Forwards special study rept, "Human Error in Events Involving Wrong Unit or Wrong Train." Study concerns events similar to Apr 1983 Turkey Point 3 event re inoperable auxiliary feedwater sys.
 HELTEMES, C J Director's Office 84/01/13, DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22028-295

NONDOCKETED ITEMS

433

--8401310084 "Human Error in Events Involving Wrong Unit or Wrong Train " TRAGER, E A Director's Office AE00/3401 84/01/31 63pp 22028 297

8401310091 Advises that NRR will provide licensing interface to support truck bomb threat project DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/13 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 22026 362

8401310128 Recommends amend to 810519 std furniture list for resident inspectors Amend provides protection for natl security insp & safeguards info DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/11/17 NORRY, P G Office of Administration 2pp 22026 345

--8401310133 Forwards final approved list of std ofc furniture for resident inspectors DONNELLY, L J Records Management Branch 81/05/19 MCOSCAR, J, CHENDEMI, P, PAPPAS, H Administrative Contracts Branch 4pp 22026 347

8401310183 Informs that all licensees have not applied TMI Item I C 6. "Guidance on Procedures for Verifying Correct Performance of Operating Activities," criteria to surveillance testing Procedures should be reviewed during future insps. NDRELIUS, C E Division of Project & Resident Programs 83/07/27 Division of Project & Resident Programs 7pp 22037 190

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8312070296 NUREG-0820 801 INTEGRATED PLANT SAFETY ASSESSMENT REPORT, SYSTEMATIC EVALUATION PROGRAM Palisades Plant, Docket No 50-255 (Consumers Power Company) * Division of Licensing 83/11/30 37pp Available at NRC \$3 75 21416 281 24X Fiche 50-255, 83/11/30, 8312070296

8312090111 NUREG-0797 804 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF COCHACHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2, Docket Nos 50-445 And 50-446 (Texas Utilities Generating Company, et al) * Division of Licensing 83/11/30 49pp Available at NRC \$4 25 21447 200 24X Fiche 50-445, 83/11/30, 8312090111

8312090366 NUREG-0857 805 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2, AND 3 Docket Nos STN 50-528, STN 50-529 & STN 50-530 (Arizona Public Service Company, et al) * Division of Licensing 83/11/30 41pp Available at NRC \$5 00 21445 118 24X Fiche 50-528, 83/11/30, 8312090366

8312120095 Board Notification 83-192 forwards EDO 831223 memo & SBER 20 (NUREG-0675) re authorization for criticality & low power testing. EISENHUT, D O Division of Licensing 83/12/29 Atomic Safety and Licensing Appeal Panel 2pp 21740 272 24X Fiche 50-275, 83/12/29, 8312120095

--8401303097 Forwards SBER 20 on criticality/low power authorization re design verification program Issues flowing from IDVP/ITP requiring satisfactory resolution resolved DIRCKS, W Office of the Executive Director for Operations 83/12/23 PALLADINO, N C Commissioners 41pp 21740, 274. 24X Fiche 50-275, 83/12/29, 8312120095

8312120186 NUREG-0874 803 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF BYRON STATION, UNITS 1 & 2 Docket Nos. STN 50-454 And STN 50-455 (Commonwealth Edison Company) * Division of Licensing 83/11/30 31pp Available at NRC \$3 75 21511 100 24X Fiche 50-454, 83/11/30, 8312120186.

8312270412 NUREG/CR-3332 RADIOLOGICAL ASSESSMENT-A TEXTBOOK ON ENVIRONMENTAL DOSE ANALYSIS TILL, J. E., MEYER, H. R Oak Ridge National Laboratory FIN B-0766 ORNL-5968 83/09/30. Division of Systems Integration (post 811005) 828pp Available at NRC \$16.00. 22044, 026

8312300205 Forwards list of dates acceptable to util per confirmatory orders re integrated implementation schedules for Suppl 1 to NUREG-0737, Generic Ltr 82-33, "Requirements for Emergency Response Capability " COUNCIL, W O. Connecticut Yankee Atomic Power Co 81-82-33 83/12/20. MILLER, J R Operating Reactors Branch 3 5pp. 21673 114 24X Fiche 50-000, 83/12/20, 8312300205.

8401030144 Submits interim operation justification for equipment not qualified for scram discharge vol break environ, per NUREG-0803 Util endorses BWR Owners Group PRA, NEDO-22209 CURTIS, N W Pennsylvania Power & Light Co PLA-2011 83/12/27. SCHWENGER, A Licensing Branch 2 4pp 21682 273 24X Fiche 50-388, 83/12/27, 8401030144

8401030201 Forwards "Repair of 1B Forced Circulation Pump Discharge Valve Bypass Line Weld, 92A " No pipings or fittings replaced Insp conducted per NUREG-0313 LINDER, F Dairymead Power Cooperative, LAC-9493. 83/12/21 NRC - No Detailed Affiliation Given 2pp 21682 297. 24X Fiche 50-409, 83/12/21, 8401030201

8401030216 Forwards Rev 2 to util 830414 response to Suppl 1 to NUREG-0737, consisting of changes to proposed schedule for upgraded emergency preparedness program, delaying implementation of new emergency procedures to Oct 1985. TUCKER, H B Duke Power Co 83/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 21682, 317. 24X Fiche 50-249, 83/12/27, 8401030216

8401030229 Forwards safety parameter display sys safety analysis, per Suppl 1 to NUREG-0737, including verification & validation (V&V) plan & criteria for parameter selection, implementation will vary at each facility. SMARTZ, E D Commonwealth Edison Co 7842N. 83/12/29 DENTON, H R Office of Nuclear Reactor Regulation, Director. 22pp. 21680, 283 24X Fiche 50-000, 83/12/29, 8401030229

8401030255 Forwards IE Insp Rept 50-289/83-31 on 831103-04 No violations noted. MARTIN, T. T Division of Engineering & Technical Programs 83/12/14 HUKILL, L. H General Public Utilities - GPU Service Corp 2ap. 21681 164 24X Fiche 50-289, 83/12/14, 8401030255.

--8401030256 IE Insp Rept 50-289/83-31 on 831103-04. No noncompliance noted. Major areas inspected, public prompt notification sys. COHEN, I, HAWKHURST, J CROCKER, H W Region 1, Office of Director. 83/12/12 5pp 21681 166 24X Fiche 50-289, 83/12/14, 8401030255

8401030269 Forwards IE Insp Rept 50-322/83-35 on 831017-1127. No violations noted. STAROSTECKI, R Division of Project & Resident Programs. 83/12/14. POLLOCK, M B Long Island Lighting Co 18pp 21681 176. 24X Fiche 50-322, 83/12/14, 8401030269

--8401030273 IE Insp Rept 50-322/83-35 on 831017-1127 No violations noted. Major areas inspected, emergency diesel crankshaft failures, circuit breaker latch failures, simulator training exams & TMI action items PETRONE, C., SHEDLOCK, J T Region 1, Office of Director. MCCABE, E. C Division of Project & Resident Programs IE8-81-25 83/12/12 13pp 21681 178 24X Fiche 50-322, 83/12/14, 8401030269

8401030286 Discusses review of final version of "Power Reactor Events " Conference for publication verbally forwarded to S Massard DENTON, H R Office of Nuclear Reactor Regulation, Director. 83/12/20 HELTENES, C J Director's Office 42pp 21693 256

--8312210014 Forwards NUREG/8R-0051, "Power Reactor Events," Vol 5, Number 3 for May-June 1983 for review & concurrence HELTENES, C J Director's Office. 83/12/07 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 43pp. 21693 257.

8401030288 Responds to util 831107 submittal re implementation of guidance in NUREG-0737, Item III D.3.4, "Control Room Habitability " Util commitment adequately addresses effect of fire on control room habitability CRUTCHFIELD, D Operating Reactors Branch 5. LB05-83-12-048 83/12/30 VANDEWALLE, D J Consumers Power Co 4pp 21680, 115 24X Fiche 50-155, 83/12/30, 8401030288

8401030297 Forwards Suppl 1 to DES & FR notice of availability. After receipt of comments, FES will be prepared w/o DES SCHWENGER, A. Licensing Branch 2 83/12/16. PERRIN, B. Environmental Protection Agency. 2pp. 21693, 350. 24X Fiche 50-352, 83/12/16, 8401030297

--8401030301 Notice of availability of Suppl 1 to DES SCHWENGER, A. Licensing Branch 2. 83/12/16 2pp 21693, 352. 24X Fiche 50-352, 83/12/16, 8401030297.

8401030309 Forwards Suppl 1 to DES (NUREG-0974) for review & comment Response requested in 45 days, w/o encl. SCHWENGER, A. Licensing Branch 2 83/12/16. WOOD, J. M. Commerce, Dept. of, Natl. Oceanographic & Atmospheric Administration. 4pp. 21693, 337. 24X Fiche 50-352, 83/12/16, 8401030309.

NONDOCKETED ITEMS

- 8401030340 NUREQ/CR-3576
THE MEASUREMENT OF PHASE DISTRIBUTION PHENOMENA IN A
TRIANGULAR CONDUIT
SIN, B., LAHEY, R. T. Rensselaer Polytechnic Institute, Troy, NY FIN
B-7272 83/12/31 Division of Accident Evaluation (Pre 840101)
166pp Available at NRC \$5 50 21691 215
- 8401030342 NUREQ/BR-0025 V09 N8
INFORMATION REPORT ON STATE LEGISLATION
LANDAU, M. Office of State Programs, Director 83/12/15 13pp
21693 319
- 8401030350 NUREQ/CR-3154
THE IN-PLANT RELIABILITY DATA BASE FOR NUCLEAR PLANT
COMPONENTS INTERIM REPORT-THE VALVE COMPONENT
BORKOWSKI, R. J., KAHL, W. K., HEBBLE, T. L. Oak Ridge National
Laboratory FIN B-0445, ORNL/TM-8647. 83/12/31 Division of
Risk Analysis 66pp 21689 119
- 8401030355 NUREQ/CR-3557
CRT DISPLAY EVALUATION THE CHECKLIST EVALUATION OF CRT-
GENERATED DISPLAYS
BLACKMAN, H. S., GERTMAN, D. I., GILMORE, W. E. Idaho National Engineering
Laboratory FIN A-6308 EGO-2285 83/12/31 Division of Risk
Analysis 44pp. 21689 320
- 8401030356 NUREQ-0871 V02 N04
SUMMARY INFORMATION REPORT Data As Of September 30, 1983
(Brown Book)
* Management Information Branch 83/12/31 53pp 21692 019
- 8401030364 NUREQ/CR-3233
THE EFFECT OF RESOLUTION OF THE HILLSTONE POINT UNIT 1
SYSTEMATIC EVALUATION PROGRAM ISSUES ON PROBABILISTIC
CALCULATIONS OF RISK
SPULAK, R. O., STACK, D. Sandia Laboratories AMICD, P. J. Science
Applications, Inc. FIN A-1300 SAND82-2429 83/12/31 Division
of Safety Technology 94pp Available at NRC \$4 50 21685 256
24X Fiche 50-243, 83/12/31, 8401030364
- 8401030370 NUREQ/CR-3542
MODELING MESOSCALE DIFFUSION AND TRANSPORT PROCESSES FOR
RELEASES WITHIN COASTAL ZONES DURING LAND/SEA BREEZES
LYONS, W., KEEN, C. S., SCHUH, J. A. Minnesota, Univ. of, Minneapolis,
MN FIN B-6048 83/12/31 Division of Health, Siting & Waste
Management 11pp Available at NRC \$6 00 21685 350
- 8401030373 NUREQ-0580 V12 N11
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
November 30, 1983 (Blue Book)
* Management Information Branch 83/12/31 60pp 21692 073
- 8401030376 NUREQ-0540 V05 N09
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE September
1-30, 1983.
* Division of Technical Information & Document Control 83/12/31,
57pp. 21690, 001
- 8401030443 NUREQ/CR-2000 V02N11
LICENBEE EVENT REPORT (LER) COMPILATION For Month Of
November 1983
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
83/12/31 Director's Office 140pp 21689 179
- 8401030446 NUREQ-0519 B07
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF LA
SALLE COUNTY STATION, UNITS 1 AND 2 Docket Nos 50-373 And
50-374. (Commonwealth Edison Company)
* Division of Licensing 83/12/31. 64pp 21692 134 24X
Fiche 50-373, 83/12/31, 8401030446
- 8401040032 NUREQ-0748 V03 N10
OPERATING REACTORS LICENSING ACTION SUMMARY, Data As Of
October 31, 1983 (Orange Book)
* Management Information Branch 83/12/31. 326pp 21713 060
- 8401040036 NUREQ-0892 B04
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WPP88
NUCLEAR PROJECT NO 2, Docket No. 50-397 (Washington Public
Power Supply System)
* Division of Licensing. 83/12/31 142pp 21711 116 24X
Fiche 50-397, 83/12/31, 8401040036
- 8401040043 NUREQ/CR-2679 V02
ADVANCED REACTOR SAFETY RESEARCH QUARTERLY REPORT, April-June
1982, Vol 22
* Sandia Laboratories FIN A-1016 SAND82-0904, 83/12/31
Division of Accident Evaluation (Pre 840101) 446pp 21711 334
- 8401040057 Forwards FR notice of availability of Suppl 1 to DES
(NUREG-0974)
SCHMENCER, A. Licensing Branch 2 83/12/16 DAVIS, J. F. Affiliation
Unknown CHERRY, M. Cherry, M. M./Cherry, Flynn & Kanter 1p
21711 330 24X Fiche 50-352, 83/12/16, 8401040057
- 8401040064 Notice of availability of Suppl 1 to DES (NUREG-0974)
SCHMENCER, A. Licensing Branch 2 83/12/16 3pp 21711 331 24X
Fiche 50-352, 83/12/16, 8401040057
- 8401040089 NUREQ-0750 V18 N02
NUCLEAR REGULATORY COMMISSION ISSUANCES August 1983 Pages
157-298
* Division of Technical Information & Document Control 83/08/31
145pp 21708 169
- 8401040154 FOIA request for documents re total expenditure between time
contract initiated & closed out for FIN A-1123, performed by
Sandia Natl Labs & subcontractors for NRC
RILEY, J. L. Affiliation Unknown FIN A-1123 83/09/13 FELTON, J. H.
Division of Rules and Records 1p 21714 316
- 8401040159 Partial response to FOIA request for documents re total
expenditure between time contract initiated & closed out for
FIN A-1123, performed by Sandia Natl Labs & subcontractors
for NRC Forwards requested info.
FELTON, J. M. Division of Rules and Records FIN A-1123 83/09/29
RILEY, J. L. Affiliation Unknown 1p 21714 317
- 8401040173 Responds to final SER dtd 821020 re SEP Topic VII-1 A.
"Isolation of Reactor Protection Sys From Non-Safety Sys,
Including Qualifications of Isolation Devices," resolving
concerns in integrated plant safety assessment (NUREG-0826)
COUNSIL, W. Q. Connecticut Yankee Atomic Power Co 810953. 83/12/14
CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 21702 018 24X
Fiche 50-213, 83/12/14, 8401040173
- 8401040193 Forwards Rev 1 to "Program Plan Rept for Detailed Control
Room Design Review for Indiana & Michigan Electric Co.
DC Cook Units 1 & 2 to NRC " Rept defines overall process by
which plan will be implemented
ALEXICH, M. P. Indiana & Michigan Electric Co AEP NRC 0773C
83/12/29 DENTON, H. R. Office of Nuclear Reactor Regulation,
Director 2pp 21703 018 24X Fiche 50-315, 83/12/29, 8401040193
- 8401040196 Rev 1 to "Program Plan Rept for Detailed Control Room Design
Review for Indiana & Michigan Electric Co, DC Cook Units 1 &
2 to NRC "
* American Electric Power Service Corp * Westinghouse Electric
Corp. * Canyon Research Corp 83/12/02 180pp 21703 020 24X
Fiche 50-315, 83/12/29, 8401040193
- 8401040229 Informs of completed evaluation of safety & relief valve
discharge piping, per NUREG-0737, Item II D 1 2 Util will
proceed w/final engineering & required mods based on
retention of safety valve loop seals
STEWART, W. L. Virginia Electric & Power Co 743 83/12/29
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
EISENHUT, D. Q. Division of Licensing 1p 21701 188 24X
Fiche 50-338, 83/12/29, 8401040229
- 8401040265 Forwards evaluation rept on existing accident monitoring
instrumentation & control sys. in conjunction w/Suppl 1 to
NUREG-0737 & requirements of Rev 3 to Reg Guide 1.97
WILLIAMS, J. W. Florida Power & Light Co L-83-605 83/12/30
EISENHUT, D. Q. Division of Licensing 1p 21703 268 24X
Fiche 50-335, 83/12/30, 8401040265
- 8401040272 "Engineering Evaluation of Instrumentation Sys for Rev 3 to
Reg Guide 1.97, Bt Lucie Plant Unit 1 "
* Florida Power & Light Co GL-82-33 83/11/30 70pp
21703 269. 24X Fiche 50-335, 83/12/30, 8401040265
- 8401040401 Forwards IE Insp Rept 50-333/83-27 on 831008-1106 & notice
of violation
STAROSTECKI, R. Division of Project & Resident Programs 83/12/19
MCNEILL, C. A. Power Authority of the State of New York 2pp
21707; 072 24X Fiche 50-333, 83/12/19, 8401040401
- 8401040405 IE Insp Rept 50-333/83-27 on 831008-1106 Noncompliance
noted, failure to submit LER re inoperable safety-related
snubber.
DOERFLEIN, L. T. Region 1, Office of Director COLLINS, B. J.
Division of Project & Resident Programs IEB-80-16. 83/12/15
10pp. 21707; 075 24X Fiche 50-333, 83/12/19, 8401040401
- 8401040407 Forwards IE Insp Rept 50-285/83-32 on 831001-31 No
noncompliance noted
OGLIARDO, J. E. Region 4, Office of Director 83/11/21 JONES, W. C.
Omaha Public Power District 2pp 21705 001 24X
Fiche 50-285, 83/11/21, 8401040407

NONDOCKETED ITEMS

435

--8401040411 IE Insp Rept 50-285/83-32 on 831001-31 No noncompliance noted. Major areas inspected: operational safety verification, surveillance testing, maint activities, followup of NUREQ-0737 items & spent fuel storage rack mods.
YANDELL, L. A., JOHNSON, W. D. Region 4, Office of Director
83/11/15 8pp 21705 003 24X Fiche 50-285, 83/11/21, 8401040407

8401040415 Forwards "Abnormal Transient Operating Guidelines" per TMI Item 1 C. 1 Finalized procedure generation package to be provided by 840131 Revised emergency operating procedure will be in effect for use by operators in Jan 1984.
HUKILL, H. D. General Public Utilities - GPU Service Corp. GL-82-33
83/12/29. STOLZ, J. F. Operating Reactors Branch 4 3pp. 21706 064
24X Fiche 50-289, 83/12/29, 8401040415

--8401040417 "Abnormal Transient Operating Guidelines"
General Public Utilities - GPU Service Corp. GL-82-33
83/12/29 73pp 21706 067 24X Fiche 50-289, 83/12/29, 8401040415

8401040471 Forwards IE Insp Rept 50-285/83-23 on 830823-0930 No noncompliance noted.
GAULIARD, D. J. E. Region 4, Office of Director 83/10/24. JONES, W. C.
Omaha Public Power District 2pp 21705 296 24X
Fiche 50-285, 83/10/24, 8401040471

--8401040494 IE Insp Rept 50-285/83-23 on 830823-0930 No noncompliance noted. Major areas inspected: operational safety verification, surveillance testing, maint activities, followup of violations & NUREQ-0737 items.
YANDELL, L. A., JOHNSON, W. D. Region 4, Office of Director.
83/10/21 7pp 21705 298 24X Fiche 50-285, 83/10/24, 8401040471

8401040485 Notifies that B&W rept re NUREQ-0737, Item II K 3 5, "Reactor Coolant Pump Trip," will not be available until Jan 1984. Addl time required to prepare plant-specific portion of submittal Final submittal will be provided by 840331.
MARSHALL, J. R. Arkansas Power & Light Co. ICAN128310. 83/12/27
STOLZ, J. F. Operating Reactors Branch 4 1p 21705 348 24X
Fiche: 50-313, 83/12/27, 8401040485

8401040517 Forwards addl clarification to 830209 & 1123 responses to NUREQ-0737, Item II, B 3 re emergency power & post-accident chloride analysis Autosampler expected to be available at site by Apr 1984.
HUKILL, H. D. General Public Utilities - GPU Service Corp.
8311-83-336 83/12/28 STOLZ, J. F. Operating Reactors Branch 4
2pp 21707 295 24X Fiche 50-289, 83/12/28, 8401040517

8401040528 Forwards responses to draft SER open items identified by Core Performance Branch, per A Schwencer 831206 request Ltr suppls info contained in 831111 ltr Attachment 1 summarizes open items & indicates changes to be made in FBAR.
BOOKER, J. E. Gulf States Utilities Co. RBG-16, 669 83/12/30
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 20pp
21707, 275 24X Fiche 50-458, 83/12/30, 8401040528

8401040541 Informs that core damage estimate procedure will be developed as result of review to satisfy NUREQ-0737, Item II, B 3 re post-accident sampling sys & address concerns raised in 830714 & 1031 ltrs Schedule expected by 840131.
MARSHALL, J. R. Arkansas Power & Light Co. ICAN128309 83/12/27
STOLZ, J. F. Operating Reactors Branch 4 MILLER, J. R. Operating Reactors Branch 3 1p 21706 323 24X Fiche: 50-313, 83/12/27, 8401040541.

8401040560 Submits status of evaluation of NUREQ-0737, Item II, D. 1 2 re safety & relief valve discharge piping Completion of final engineering expected in 1984.
STEWART, W. L. Virginia Electric & Power Co. 721. 83/12/29,
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
EISENHUT, D. O. Division of Licensing 2pp 21706 316 24X
Fiche 50-280, 83/12/29, 8401040560.

8401040565 Forwards evaluation of Amend 3 to radiological emergency plan Actions taken to resolve deficiencies requested within 30 days.
NORDENHAU, L. R. Region 5, Office of Director. 83/12/28
WITHERS, B. D. Portland General Electric Co 21pp. 21707 250 24X
Fiche: 50-344, 83/12/28, 8401040565

8401040587 Discusses 831129 request to extend implementation schedule for NUREQ-0737, Items II F 1 1 & II F 1 2 from 831231 until startup from 1984 refueling outage Interim procedures described in 800102 & 0423 ltrs remain in effect.
WITHERS, B. D. Portland General Electric Co 83/12/29. EISENHUT, D. O.
Division of Licensing 2pp. 21705 355 24X Fiche 50-344, 83/12/29, 8401040587

8401050164 Forwards Rev 1 to Westinghouse Owners Group "Emergency Response Guidelines Low Pressure Version" & "Emergency Response Guidelines High Pressure Version" Rept addresses NUREQ-0737, Item 1 C 1 Plant-specific activities may begin.
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group
SHEPPARD, J. J. Carolina Power & Light Co. 00-111. 83/11/30
THOMPSON, H. L. Division of Human Factors Safety 12pp. 21716. 118

8401050198 Suppl to B10728 & B21210 applications for amends to Licenses DPR-71 & DPR-62, incorporating corporate & plant organizational changes.
HOWE, P. W. Carolina Power & Light Co. LAP-83-569 83/12/29,
VASSALLO, D. B. Operating Reactors Branch 2 26pp 21730 001 24X
Fiche 50-324, 83/12/29, 8401050198

8401050278 Confirms that scheduled submittal of design details for reactor coolant inventory trending sys, per TMI Action Item II F. 2 will be provided in Jan 1984, per 831228 discussion w/ JV Viet.
HUKILL, H. D. General Public Utilities - GPU Service Corp.
5122-83-383 83/12/29 STOLZ, J. F. Operating Reactors Branch 4
1p 21727 240 24X Fiche 50-289, 83/12/29, 8401050278

8401050308 Advises that response to reanalysis of main steam line break w/continued feedwater addition will be provided by 840315. Response to TMI Item II B 1 re RCS vents will be sent by 840123.
D'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. GL-83-37.
83/12/29 VARQA, B. A. Operating Reactors Branch 1 2pp. 21729. 082.
24X Fiche 50-247, 83/12/29, 8401050308

8401050418 Forwards IE Insp Repts 50-454/83-57 & 50-455/83-40 on 831128-1202. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director 83/12/23. REED, C.
Commonwealth Edison Co. 2pp 21731:140 24X Fiche: 50-454, 83/12/23, 8401050418

--8401050421 IE Insp Repts 50-454/83-57 & 50-455/83-40 on 831128-1202 No noncompliance noted. Major areas inspected: radiation protection procedures, respiratory protection program, NUREQ-0737 items & preoperational sys demonstrations.
HUSTER, L. J., GREGER, L. R. Region 3, Office of Director.
50-455/83-40. 83/12/23. 7pp. 21731:142 24X
Fiche 50-454, 83/12/23, 8401050418

8401050653 Ack receipt of 831104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-20 & 50-281/83-20.
DANCE, H. C. Division of Project & Resident Programs 83/12/20
STEWART, W. L. Virginia Electric & Power Co 1p. 21724:114. 24X
Fiche 50-280, 83/12/20, 8401050653

--8401050681 IE Insp Repts 50-280/83-20 & 50-281/83-20 on 830702-0803 Violations noted: inadequate procedures for hydrostatic testing of containment spray & piping, surveillance not performed & cable tray cover not installed.
BURKE, D. J., LEUHMANN, J., MATHIS, J. Region 2, Office of Director
50-281/83-20 83/10/04 7pp 21724:125. 24X
Fiche 50-280, 83/12/20, 8401050653.

8401060051 Forwards Rev 0 to "Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
Rept describes torus mods implemented & gives supporting analyses.
MILLS, L. M. Tennessee Valley Authority 84/01/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p 21738:098. 24X
Fiche: 50-259, 84/01/03, 8401060051.

--8401060067 CEB-83-34 R00
"Browns Ferry Nuclear Plant Torus Integrity Long-Term Program Plant-Unique Analysis Rept"
ROCHELLE, J. K. Tennessee Valley Authority 83/12/21 20pp.
21738 100 24X Fiche: 50-259, 84/01/03, 8401060051.

8401060189 Forwards BER re steam generator repair (NUREG-1004) & FR notice of rept availability w/o NUREQ.
VARQA, B. A. Operating Reactors Branch 1 83/12/23 UTLEY, E. E.
Carolina Power & Light Co 2pp. 21744:181 24X
Fiche: 50-261, 83/12/23, 8401060189

--8401060192 Notice of availability of BER re steam generator repair (NUREG-1004).
VARQA, B. A. Operating Reactors Branch 1. 83/12/23 2pp.
21744:183 24X Fiche: 50-261, 83/12/23, 8401060189.

8401060197 Forwards NUREQ-1004, BER re steam generator repair & FR notice of availability, w/o NUREQ.
VARQA, B. A. Operating Reactors Branch 1. 83/12/22. PERRIN, S.
Environmental Protection Agency. 1p 21744:178. 24X
Fiche: 50-261, 83/12/22, 8401060197

NONDOCKETED ITEMS

8401060204 Forwards revised FSAR pages providing addl info re monitoring of leakage from sys outside containment, satisfying concern in NUREG-0737, Item III D.1.1. Info should close upon BER Confirmatory Issue 28(a).
TRAMM, T. R. Commonwealth Edison Co 7877N 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 21739.169.
24X Fiche: 50-000, 83/12/30, 8401060204

8401060210 Forwards BER re steam generator repair (NUREG-1004). W/o encl
VARGA, S. A. Operating Reactors Branch 1 83/12/23 WOOD, J. M. Commerce, Dept. of Natl Oceanographic & Atmospheric Administration
ip 21744.172. 24X Fiche: 50-261, 83/12/23, 8401060210

8401060224 Forwards FR notice of availability of BER re steam generator repair (NUREG-1004) W/o encl
VARGA, S. A. Operating Reactors Branch 1. 83/12/23 SMITH, P. H. Advisory Council on Historic Preservation SMITH, P. H., BINDER, J. R. Agriculture, Dept. of. 6pp 21744.131 24X Fiche: 50-261, 83/12/23, 8401060224

8401060230 Provides schedule for submittal of revised procedure for estimating extent of core damage & confirming that heat tracing will be installed on containment sampling lines by 840630, per NUREG-0737, Item II. B.3
MUSOLF, D. M. Northern States Power Co 83/12/22 Office of Nuclear Reactor Regulation, Director. ip 21740.111 24X Fiche: 50-282, 83/12/22, 8401060230

8401060306 Provides addl response to Generic Ltr 82-10, addressing NUREG-0737, Item III D.3.4 re control room habitability requirements. Completed mods to control room include installation of redundant bottled air sys.
STENART, W. L. Virginia Electric & Power Co 746. 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. O. Division of Licensing. 3pp. 21741.352 24X Fiche: 50-280, 83/12/30, 8401060306.

8401090077 NUREG-1013
TECHNICAL SPECIFICATIONS FOR LASALLE COUNTY STATION, UNIT NO. 2 Docket No. 50-374, (Commonwealth Edison Company)
HOFFMAN, D. R. Division of Licensing 83/12/31 484pp 21765.001
24X Fiche: 50-374, 83/12/31, 8401090077

8401090132 Forwards status of current plans for implementation of provisions of Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability," transmitted by Generic Ltr 82-33.
COUNSEL, W. O. Connecticut Yankee Atomic Power Co. QL-82-33 83/11/28 EISENHUT, D. O. Division of Licensing 23pp. 21749.170.
24X Fiche: 50-000, 83/11/28, 8401090132

401090162 Forwards request for addl info to continue review of submittals re NUREG-0737, Item II B.3, "Post-Accident Sampling Sys." Response schedule requested in 30 days
VARGA, S. A. Operating Reactors Branch 1. 83/12/16 STENART, W. L. Virginia Electric & Power Co 8pp 21797.217 24X Fiche: 50-000, 83/12/16, 8401090162.

401090198 NUREG-1004
SAFETY EVALUATION REPORT RELATED TO STEAM GENERATOR REPAIR AT H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2 Docket No. 50-261, (Carolina Power And Light Company)
* Division of Licensing 83/11/30 60pp. Available at NRC #425 21757.132. 24X Fiche: 50-261, 83/11/30, 8401090198

8401090204 Responds to open item identified in Yankee integrated assessment (NUREG-0825) re SEP Topic II-3 C concerning need for mods to drainage channel at base of southeast slopes. Mod scheduled for completion during Summer 1985.
KAY, J. A. Yankee Atomic Electric Co. FYR 84-01 83/12/30 CRUTCHFIELD, D. Operating Reactors Branch 3 ip 21750.330. 24X Fiche: 50-029, 83/12/30, 8401090204

401090237 Forwards IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16. No violations noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/12/20 FARRIS, H. G. Tennessee Valley Authority. 2pp. 21750.291. 24X Fiche: 50-259, 83/12/20, 8401090237

--8401090264 IE Insp Repts 50-259/83-48, 50-260/83-48 & 50-296/83-48 on 831115-16. No violations noted. Major areas inspected emergency preparedness exercise.
DECKER, T. R. Region 2, Office of Director. 50-296/83-48, 83/12/13 9pp. 21750.293. 24X Fiche: 50-259, 83/12/20, 8401090237

8401090239 Forwards evaluation of compliance w/emergency response facility criteria presented in Suppl 1 to NUREG-0737, per 830415 ltr. Several areas identified that depart from criteria.
MANGAN, C. V. Niagara Mohawk Power Corp. 84/01/03 VASSALLO, D. B. Operating Reactors Branch 2. 5pp. 21753.929 24X Fiche: 50-220, 84/01/03, 8401090239

8401090265 Forwards safety parameter display sys implementation plan & SAR, per NUREG-0737, Suppl 1 requirements Sys installation does not require Tech Spec change
MCOAUGHY, R. W. Iowa Electric Light & Power Co NO-84-0012 84/01/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 21754.238 24X Fiche: 50-331, 84/01/03, 8401090265

8401090311 Advises that portions of in-core thermocouple sys outside containment will not be upgraded by 831231, per license condition Request to amend condition to reflect data consistent w/NUREG-0737, Suppl 1 will be submitted by 840113
TUCKER, H. B. Duke Power Co 83/12/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENBAM, E. G. Licensing Branch 4 ip 21754.201 24X Fiche: 50-369, 83/12/30, 8401090311

8401090313 Forwards review of interim reliability evaluation program (IREP) Analysis Operator error contribution may be significantly higher than study assumed
STOLZ, J. F. Operating Reactors Branch 4 83/12/23 GRIFFIN, J. K. Arkansas Power & Light Co 11pp 21768.147 24X Fiche: 50-313, 83/12/23, 8401090313

8401090321 Forwards "Control Room Design Review Plan," per requirements of Suppl 1 to NUREG-0737 transmitted by Generic Ltr 82-33 Summary rept of completed review to be submitted at later date.
MUSOLF, D. Northern States Power Co QL-82-33 83/12/28 Office of Nuclear Reactor Regulation, Director ip 21754.156 24X Fiche: 50-263, 83/12/28, 8401090321

--8401090328 "Control Room Design Review Plan"
* Northern States Power Co QL-82-33 83/12/28 34pp 21754.157 24X Fiche: 50-263, 83/12/28, 8401090321

8401090322 NUREG-0881 804
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF WOLF CREEK GENERATING STATION, UNIT NO. 1 Docket No. 50-482 (Kansas Gas And Electric Company, et al)
* Division of Licensing 83/12/31 91pp Available at NRC #4 50 21766.219 24X Fiche: 50-482, 83/12/31, 8401090322.

8401090326 Forwards info re safety parameter display sys, in response to 830415 ltr Requests preimplementation review prior to undertaking addl efforts in software development, per Suppl 1 to NUREG-0737
MANGAN, C. V. Niagara Mohawk Power Corp 84/01/03 VASSALLO, D. B. Operating Reactors Branch 2 24pp 21754.114 24X Fiche: 50-220, 84/01/03, 8401090326

8401090367 Responds to NRC request for info re Target Rock solenoid valves & York/Relliance DX refrigeration unit Refrigeration unit water regulating valve will be replaced prior to fuel load W/updated component work sheets
CURTIS, N. W. Pennsylvania Power & Light Co PLA-2028 84/01/05 SCHWENCER, A. Licensing Branch 2 4pp 21754.046 24X Fiche: 50-388, 84/01/05, 8401090367

8401090372 Forwards safety analysis for safety parameter display sys per 830415 commitment re Generic Ltr 82-33, Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability" Verification & validation plan encl
MILLS, L. M. Tennessee Valley Authority QL-82-33 84/01/04 ADENBAM, E. Licensing Branch 4 20pp 21750.279 24X Fiche: 50-327, 84/01/04, 8401090372.

8401090432 Responds to 831028 request for addl info re NUREG-0737, Item II.F.2, concerning installation & preoperational testing of reactor vessel level instrumentation sys (RVLIS) RVLIS will be installed & tested prior to fuel load
MILLS, L. M. Tennessee Valley Authority. 84/01/04 ADENBAM, E. Licensing Branch 4 12pp 21750.302 24X Fiche: 50-390, 84/01/04, 8401090432

8401090477 Forwards repts re means for assuring fire protection for structural steel in lieu of strict application of protective coating, per 831213 request & BER (NUREG-0991).
KEMPER, J. B. Philadelphia Electric Co 84/01/04 SCHWENCER, A. Licensing Branch 2 28pp 21752.248 24X Fiche: 50-352, 84/01/04, 8401090477

8401090520 Forwards BER based on encl technical evaluation rept of util response to NUREG-0612, Section 5.1.1 & 5.3 re control of heavy loads
MILLER, J. R. Operating Reactors Branch 3 83/12/30 GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp 21768.115. 24X Fiche: 50-309, 83/12/30, 8401090520

--8401090522 Safety evaluation in support of util response to NUREG-0612, "Control of Heavy Loads at Nuclear Plants," Phase 1
* Office of Nuclear Reactor Regulation, Director. 83/12/30. 2pp 21768.117 24X Fiche: 50-309, 83/12/30, 8401090520

--8312060211 TER-C5506-365
"Control of Heavy Loads (C-10) at Maine Yankee Nuclear
Power Station," technical evaluation rept
BOMBERGER, C. Franklin Institute/Franklin Research Center
NRC-03-91-130 TAC 08059 83/12/02 SINGH, A., CHAN, T. NRC - No
Detailed Affiliation Given 28pp 21768:119 24X
Fiche 50-309, 83/12/30, 8401090520

8401090506 NUREG/CR-3574
CRITICAL PATHWAYS OF RADIONUCLIDES TO MAN FROM
AGRO-ECOSYSTEMS Annual Progress Report, October 1981-
September 1982
SMITH, M. H., ALBERTS, J. J., ADRIANO, D. C. Savannah River Laboratory
FIN B-4124. 83/12/31 Division of Health, Siting & Waste
Management 26pp Available at NRC #4 00 21767 257

8401090512 NUREG/CR-3128
SIMILAR SIMULATION OF MATERIALS LICENSING REVIEW
SABBER, D. W. Sandia Laboratories. FIN A-1163 SAND82-0679
83/12/31 Division of Fuel Cycle & Material Safety 36pp
Available at NRC #4 50, 21764 292

8401090513 NUREG-0683 S01 DRFT
PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO
DECONTAMINATION AND DISPOSAL OF RADIOACTIVE WASTES RESULTING
FROM MARCH 28, 1979 ACCIDENT, THREE MILE ISLAND NUCLEAR
STATION, UNIT 2 Docket No. 50-320
* TMI Program Office 83/12/31 50pp 21767 160 24X
Fiche: 50-320, 83/12/31, 8401090613

8401090615 NUREG/CR-3125
CURRENT PRACTICES FOR MAINTAINING OCCUPATIONAL EXPOSURES
ALARA AT LOW-LEVEL WASTE DISPOSAL SITES.
HADLOCK, D. E., HERRINGTON, W. N., HOOKER, C. D. Battelle Memorial
Institute, Pacific Northwest Laboratory. FIN B-2473. PNL-4372
83/12/31 Division of Waste Management 54pp Available at NRC,
#4 75 21767 063

8401090652 Responds to telcon re clarification of review of NUREG-0737,
Items II.K.3.1 & II.K.3.2 (automatic PORV isolation) Review
combined Items II.K.3.7 & II.K.3.2, resolving Item II.K.3.7.
STOLZ, J. F. Operating Reactors Branch 4 83/12/28 TUCKER, H. B.
Duke Power Co. 1p 21757 359 24X Fiche: 50-269, 83/12/28,
8401090652

8401090663 NUREG-1041
IMPACTS OF NRC PROGRAMS ON STATE AND LOCAL GOVERNMENTS
NUSSBAUMER, D. A., LUDENAU, J. O. Office of State Programs, Director
83/12/31 13pp 21766 296

8401090708 Discusses review of submittal re control room habitability
raised in NUREG 0737, Item III.D.3.4 Two concerns raised
inadequately addressed as indicated in Reg Guides 1.7B &
1.95 & SRP & 4 W/o evaluation rept
STOLZ, J. F. Operating Reactors Branch 4 83/12/28 HUKILL, H. D.
General Public Utilities - GPU Service Corp. 2pp. 21757, 334 24X
Fiche 50-289, 83/12/28, 8401090708

8401090763 Board Notification 83-195 forwards ACRS rept on BEP
Integrated plant safety assessment rept (NUREG-0828), per
util proposal to expand spent fuel pool capacity
MIRAGLIA, F. Assistant Director for Safety Assessment 83/12/28.
BLOCH, P. B., PARIS, D. H., SHON, F. Atomic Safety and Licensing Board
Panel 3pp. 21767 041 24X Fiche 50-155, 83/12/28, 8401090763.

8401090767 Forwards concerns re review of 830325 & 0421 responses to
Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation
Sys." Approach acceptable Core exist thermocouple design
per TMI Item II.F.2 unacceptable.
VARGA, B. A. Operating Reactors Branch 1 01-82-28, 83/12/16
CAREY, J. J. Duquesne Light Co. 11pp 21767, 049 24X
Fiche 50-334, 83/12/16, 8401090767.

8401100019 Notification of 840111 meeting w/util in Bethesda, MD to
discuss util request for extension for completion of
NUREG-0737, Item II.B.3. "Post-Accident Sampling Sys."
RIVENBARK, Q. Operating Reactors Branch 4 84/01/04 STOLZ, J. F.
Operating Reactors Branch 4 2pp 21776 058 24X
Fiche: 50-321, 84/01/04, 8401100019

8401100020 Further response to FOIA request for 3 categories of
documents, Forwards documents.
FELTON, J. M. Division of Rules and Records, 83/09/27. SHOLLY, B. C.
Union of Concerned Scientists 1p. 21777 179

--8401100025 NUREG/CR-3268 DR V01
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
1 - Main Rept
VARNADO, G. B. Sandia Laboratories. HORTON, W. H. Science
Applications, Inc. FIN A-1360 SAND83-0963. 83/07/31
Division of Risk Analysis. 70pp 21777 180.

--8401100030 NUREG/CR-3268 DR V02
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
2 - Appendices A to C
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360
SAND83-0963 83/07/20 Division of Risk Analysis 500pp
21777 250

--8401100037 NUREG/CR-3268 DR V03
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
3 - Appendices D to H
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360
SAND83-0963 83/07/20 NRC - No Detailed Affiliation Given
434pp 21779:083

--8401100040 NUREG/CR-3268 DR V04
Draft MODULAR FAULT TREE ANALYSIS PROCEDURES GUIDE Volume
4 - Appendix I
HORTON, W. H., LOBNER, P. Science Applications, Inc. FIN A-1360
SAND83-0963 83/07/20 NRC - No Detailed Affiliation Given
159pp 21780 127

8401100034 Forwards BSR 1 (NUREG-0991). W/o encl
SCHWENCER, A. Licensing Branch 2 83/12/13 BAUER, E. O.
Philadelphia Electric Co. 4pp 21777 175 24X
Fiche: 50-352, 83/12/13, 8401100034.

8401100075 NUREG/CR-3088
AN AUTOMATED DEFICIENCY LETTER DATA BASE.
JONES, R. D. Sandia Laboratories. FIN A-1162. SAND82-0767.
83/12/31 Division of Fuel Cycle & Material Safety 62pp.
Available at NRC #4 50 21776:217.

8401100088 NUREG/CR-3568
A HANDBOOK FOR VALUE-IMPACT ASSESSMENT
HEASERLIN, S. W., BURNHAM, J. B., GALLUCCI, R. H. Battelle Memorial
Institute, Pacific Northwest Laboratory. FIN B-2386 PNL-4646
83/12/31 Division of Risk Analysis. 152pp Available at NRC.
#5. 50 21776:061

8401100097 NUREG-0020 V07 N10
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT. Data As
Of September 30, 1983. (Grey Book)
* Management Information Branch. 83/12/31 405pp 21775:001.

8401100181 Forwards Tables CET-1 & CET-2 which provide point-by-point
evaluation of inadequate core cooling instrumentation, per
NUREG-0737, Item II.F.2 Info supple 830208 response to
Question B of NRC 821027 ltr BER Outstanding Item 9 closed.
TRAMM, T. R. Commonwealth Edison Co. 83/12/27. DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 6pp 21760:345 24X
Fiche: 50-000, 83/12/27, 8401100181.

8401100193 Provides addl info re NUREG-0737, Item II.K.3.1, "Isolation &
Testing of Automatic PORV Isolation Sys." to close out BER
Confirmatory Issue 28 Automatic PORV isolation unnecessary,
based on Westinghouse Owners Group study.
TRAMM, T. R. Commonwealth Edison Co. 83/12/27. DENTON, H. R. Office
of Nuclear Reactor Regulation, Director. 1p 21759, 279. 24X
Fiche: 50-000, 83/12/27, 8401100193

8401100218 Submits evaluation results re BEP Topic VIII-4,
"Evaluation of Category B Low Voltage Penetrations." All
Category B penetrations have at least primary protection
devices.
KAY, J. A. Yankee Atomic Electric Co. FYR 84-03 84/01/04.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 21759 272. 24X
Fiche: 50-029, 84/01/04, 8401100218

8401100318 Forwards status of unresolved safety issues re conversion of
provisional license to Full-term license
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 01-82-26
84/01/03 CRUTCHFIELD, D. Operating Reactors Branch 5. 5pp.
21763:277. 24X Fiche 50-219, 84/01/03, 8401100318

8401100392 Discusses integrated assessment of regulatory requirements,
per util 830613 & 0914 & NRC 831005 ltrs. Scheduler relief
from requirements identified in Encls 1 & 5 requested by
840120. Issues to be included in expanded assessment encl.
COUNSILL, W. O. Connecticut Yankee Atomic Power Co. 1E8-79-14
83/12/28 EISENHUT, D. O. Division of Licensing 97pp. 21762:297.
24X Fiche: 50-000, 83/12/28, 8401100392

8401100394 Forwards addl info re TMI Item II.F.2, "Instrumentation for
Detection of Inadequate Core Cooling" & justification for
proposed implementation schedule for heated junction
thermocouples sys
GARY, R. J. Texas Utilities Generating Co. TXX-4086. 84/01/03.
YOUNGBLOOD, B. J. Licensing Branch 1 37pp. 21762:183. 24X
Fiche: 50-445, 84/01/03, 8401100394.

NONDOCKETED ITEMS

- 8401100406 Responds to NRC 831006 request for plan of action re improvement of LPIB availability per TMI Item II K 3 17. Primary reason for high unavailability caused by malfunction of valves DHV-110 & DHV-111 Analog control sys installed. WESTAFER, D R Florida Power Corp 3F0184-02 84/01/03 STOLZ, J F Operating Reactors Branch 4 2pp 21762 286 24X Fiche 50-302, 84/01/03, 8401100406
- 8401100418 Responds to BSR 5 (NUREG-0857) requesting addl info re meteorological effect of Palo Verde Hills Data for primary meteorological tower representative of meteorology in emergency planning zone. VAN BRUNT, E E Arizona Public Service Co ANPP-28525-WFQ/ 84/01/03 KNIGHTON, Q Licensing Branch 3 3pp 21763:124 24X Fiche: 50-328, 84/01/03, 8401100418
- 8401100449 Requests final radiological effluent Tech Specs, incorporating resolution of items discussed w/Franklin Research Ctr in Jan 1982 Specs due in 30 days Guidance given in encl Draft 7 of Rev 3 to NUREG-0472. CRUTCHFIELD, D Operating Reactors Branch 5, L805-84-01-004, 84/01/05 COUNSEL, W O Connecticut Yankee Atomic Power Co 86pp, 21762:001 24X Fiche: 50-213, 84/01/05, 8401100449
- 8401100468 Clarifies operational status of mod re NUREG-0737, Item III, D 3 4, "Control Room Habitability" Mod providing automatic isolation of control room outside air intake on safety injection signal completed 831222. LENTINE, F O Commonwealth Edison Co, 7935N 84/01/06, DENTON, H R, Office of Nuclear Reactor Regulation, Director 2pp 21761:336, 24X Fiche 50-295, 84/01/06, 8401100468
- 8401100483 Forwards integrated schedule in bar-chart format per Suppl 1 to NUREG-0737, describing emergency response capability upgrades. ABHAR, R F Baltimore Gas & Electric Co 83/12/30 MILLER, J R Operating Reactors Branch 3 18pp, 21763 067 24X Fiche: 50-317, 83/12/30, 8401100483
- 8401100484 Discusses upgrading of emergency procedures per NUREG-0737, Suppl 1. Approach integrates components of symptom-oriented emergency operation procedures, control room design, safety parameter display sys & operator training. KAY, J A Yankee Atomic Electric Co FYR 84-04 84/01/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 21761 304 24X Fiche: 50-029, 84/01/03, 8401100484
- 8401100044 Forwards supplemental response to TMI Action Item II K 3 5 re automatic trip of reactor coolant pumps. Delays occurred in release of Westinghouse rept re justification for manual reactor coolant pump trip. HILLS, L M Tennessee Valley Authority, 84/01/06 ADENSAH, E, Licensing Branch 4, 3pp 21772:216, 24X Fiche 50-327, 84/01/06, 8401100044
- 840110048 Forwards supplemental response to Suppl 1 to NUREG-0737 (Generic Ltr 82-33) re safety parameter display sys implementation approval not required prior to Unit 1 fuel load data. HILLS, L M Tennessee Valley Authority 0L-82-33 84/01/05 ADENSAH, E, Licensing Branch 4, 7pp, 21772:229 24X Fiche: 50-390, 84/01/05, 840110048
- 840110094 Responds to TMI Item II, F 2, "Inadequate Core Cooling Instrumentation," Calibr & test info for Unit 2 tentatively scheduled for submittal by 840301. LIDEN, E A Public Service Electric & Gas Co of New Jersey, 83/12/23 VARGA, S A, Operating Reactors Branch 1 3pp, 21772, 212, 24X Fiche: 50-272, 83/12/23, 840110094
- 840110149 Forwards control room design review summary rept required by Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability," w/o encl. LIDEN, E A Public Service Electric & Gas Co. of New Jersey, 83/12/29 VARGA, S A, Operating Reactors Branch 1 1p 21772 211, 24X Fiche: 50-272, 83/12/29, 840110149
- 840110244 Forwards response to 830929 request for answers to questions re util review of draft IE rept re Unit 2 accident (NUREG-0600). PALLADINO, N J Commissioners, 83/12/09 UDALL, M K House of Rep., Interior & Insular Affairs, 3pp, 21795 028, 24X Fiche: 50-320, 83/12/09, 840110244
- 840110247 Forwards "Rept on Comparison of NUREG-0600 to 790715 Draft" for review. All changes to rept proper & no impropriety associated w/release of rept. Investigation unwarranted. STELLO, V Regional Operations & Generic Requirements, 83/09/16, PALLADINO, N J Commissioners 11pp, 21795, 033 24X Fiche: 50-320, 83/12/09, 840110244
- 840110258 Ack receipt of V Stello 830916 memo re release of NUREG-0600 in draft form. No further internal inquiry required. PALLADINO, N J Commissioners 83/10/04 DIRCKS, W J Office of the Executive Director for Operations 1p 21795 047 24X Fiche 50-320, 83/12/09, 840110244
- 840110264 Questions why draft IE rept re accident (NUREG-0600) sent to util for comments. PALLADINO, N J Commissioners 83/09/29 UDALL, M K House of Rep., Interior & Insular Affairs 2pp 21795 048 24X Fiche 50-320, 83/12/09, 840110244
- 840110370 Forwards FR notice of availability of Suppl 1 to DES (NUREG-0974). SCHWENCER, A Licensing Branch 2 83/12/16 BAUER, E O Philadelphia Electric Co 3pp 21794 293 24X Fiche 50-352, 83/12/16, 840110370
- 840110392 Responds to 831213 memo re review of proposed AD rept to Congress for Third Quarter CY83 Issue of large recirculation pipe crack & BWR feedwater pipe crack should be separated & new AD submitted. DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/04 HELTEMES, C J Director's Office 7pp 21795 030
- 8312300296 Forwards draft Commission paper, AD rept to Congress (NUREG-0090) for Third Quarter CY83, summary of other events considered for AD reporting & transmittal ltrs, based on response to AEOB 831012 memo Comments requested. HELTEMES, C J Director's Office 83/12/13, DENTON, H R Office of Nuclear Reactor Regulation, Director DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director MINOQUE, R B, Office of Nuclear Regulatory Research, Director 60pp 21795 056
- 840110400 Forwards GER (NUREG-0876) w/o encl. NOVAK, T M Assistant Director for Licensing 83/12/30 RAY, J J ACRB - Advisory Committee on Reactor Safeguards 3pp 21794:309, 24X Fiche 50-456, 83/12/30, 840110400
- 8401120073 NUREG/CR-3582 POSTIRRADIATION ANNEALING RECOVERY OF HIGH COPPER REACTOR PRESSURE VESSEL WELD METAL TOUGHNESS PROPERTIES. SEVER, W L EQ&O, Inc. FIN A-6318 EQO-MS-6388 83/12/31 Division of Engineering Technology 61pp Available at NRC \$4 50 21806 312
- 8401120095 NUREG/CR-3343 RECOMMENDED RADIATION PROTECTION PRACTICES FOR LOW-LEVEL WASTE DISPOSAL SITES. HADLOCK, D E, HOOKER, C D, HERRINGTON, W N Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2473-2 PNL-4561, 83/12/31 Division of Waste Management, 133pp Available at NRC \$5.50 21806 074.
- 8401120098 NUREG/CR-3586 PARAMETERS & VARIABLES APPEARING IN REPOSITORY DESIGN MODELS. CURTIS, R H, WART, R J Teknekron Research, Inc. CURTIS, R H Acres American, Inc FIN B-6985 83/12/31 Division of Waste Management 180pp Available at NRC \$6 00 21805 252.
- 8401120251 Forwards BSR 4 (NUREG-0881) w/o encl. KARNAM, M Hearing Branch 1 ISSUANCES OL 84/01/04 WOLFE, S J, PAYTON, H C, ANDERSON, Q C Atomic Safety and Licensing Board Panel 1p, 21793 281 24X Fiche 50-482, 84/01/04, 8401120251.
- 8401120318 Requests extension until 840115 for submittal of NUREG-0737 Tech Specs for RCB vents, in response to Generic Ltr 83-37. RODRIQUEZ, R J Sacramento Municipal Utility District 0L-83-37 83/12/09, STOLZ, J F Operating Reactors Branch 4 2pp, 21794 142 24X Fiche: 50-312, 83/12/09, 8401120318
- 8401120409 Discusses SEP Topic V-6 re reactor vessel integrity 800305 evaluation (NUREG-0569) Evaluation reviewed design & const of reactor vessels for SEP plants Updated status evaluation appropriate. Topic complete. PAULSON, W A Operating Reactors Branch 5, L805-84-01-007 84/01/10 BASKIN, K Southern California Edison Co 4pp, 21791:141 24X Fiche 50-206, 84/01/10, 8401120409
- 8401130026 Forwards Amends 3B & 2B to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends change Tech Specs to incorporate overtime limitations in Generic Ltr 82-12 per TMI Action Item I, A 1 3. REEVER, E A Operating Reactors Branch 1 0L-82-12 83/12/30 CLAYTON, F L Alabama Power Co, 2pp 21821 004, 24X Fiche: 50-348, 83/12/30, 8401130026
- 8401130030 Amends 3B & 2B to Licenses NPF-2 & NPF-8, respectively, changing Tech Specs to incorporate overtime limitations in Generic Ltr 82-12 per TMI Action Item I, A 1.3. VARGA, S A, Operating Reactors Branch 1 NPF-08 A 028 83/12/30 8pp 21821 006, 24X Fiche: 50-348, 83/12/30, 8401130026

NONDOCKETED ITEMS

439

B401130082 Forwards response to Generic Ltr 82-33 (NUREG-0737, Suppl 1), re compliance w/Reg Guide 1.97 concerning instrumentation for light-water-cooled nuclear plants to assess plant & environs conditions during & following accident
MUSOLF, D Northern States Power Co QL-82-33. 83/12/30. Office of Nuclear Reactor Regulation, Director 15pp. 21802 058. 24X
Fiche 50-263, 83/12/30, B401130082

B401130092 NUREG/CR-3556
NONINTERACTIVE SIMULATION EVALUATION FOR CRT-GENERATED DISPLAYS
BLACKMAN, H B, GERTMAN, D I, OILMORE, W E EG&O, Inc FIN A-6308
E06-2284 84/01/31 Division of Facility Operations. 36pp.
21820 289

B401130105 NUREG/CR-3532
RESPONSE OF RUBBER INSULATION MATERIALS TO MONOENERGETIC ELECTRON IRRADIATIONS
BUCKALEW, W M, WYANT, F J, LOCKWOOD, Q J Sandia Laboratories FIN A-1051. SAND83-2098 84/01/31 Division of Engineering Technology 60pp 21821 040

B401130117 Notification of B40106 meeting w/utkl in Bethesda, MD to discuss procedures generation package for developing upgraded emergency operating procedures per NUREG-0737, Suppl 1 & TH1 Item 1 C 1
VAN VLIET, J Operating Reactors Branch 4 83/12/30 STOLZ, J F
Operating Reactors Branch 4 2pp 21820 339 24X
Fiche 50-289, 83/12/30, B401130117

B401130124 Requests submission of radiological effluent Tech Specs, using Draft 7 of Rev 3 to NUREG-0472 as guidance, within 60 days of receipt of ltr w/o BER
MILLER, J R Operating Reactors Branch 3 83/12/29 JONES, W C
Omaha Public Power District 2pp 21819 361. 24X
Fiche 50-285, 83/12/29, B401130124

B401130207 Responds to request for review of certain differences between current guidelines for new reactor const & original const stds, per SEP integrated plant safety assessment (NUREG-0827) Summary of proposed actions encl.
LINDER, F Dairyland Power Cooperative LAC-9514 83/12/29
CRUTCHFIELD, D Operating Reactors Branch 5 153pp 21799.001 24X
Fiche 50-409, 83/12/29, B401130207

B401130220 NUREG/CR-2800 S02
GUIDELINES FOR NUCLEAR POWER PLANT SAFETY ISSUE PRIORITIZATION INFORMATION DEVELOPMENT.
ANDREW, M G, GALLUCCI, R H, KONZEK, Q J Battelle Memorial Institute, Pacific Northwest Laboratory PNL-4297 83/12/31 Division of Safety Technology 42pp Available at NRC \$8.50 21816 001

B401130224 NUREG/CR-3165
PHYSICAL TESTS ON SOLIDIFIED DECONTAMINATION WASTES FROM DRESDEN UNIT 1
BARLETTA, R E, ADAMS, J W, DAVIS, R E Brookhaven National Laboratory FIN A-3159 BNL-NUREG-51648 83/12/31 Division of Waste Management 109pp Available at NRC \$5.00 21820.001 24X
Fiche 50-010, 83/12/31, B401130224

B401130231 NUREG/CR-3503
STEAM GENERATOR DECONTAMINATION METHODS AND PAST APPLICATIONS
CARD, C J Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2522 PNL-4209 83/12/31. Division of Systems Integration (post B11005). 70pp Available at NRC \$4.50 21834.153.

B401130303 Forwards revs to certain human engineering deficiencies contained in Util 830509 ltr re control room preliminary design assessment along w/Suppl 1 & II in response to NUREG-0660 & Section 18 of BER Byron 55ER Item 17 closed
SWARTZ, E D Commonwealth Edison Co 7931N 84/01/06. DENTON, H R
Office of Nuclear Reactor Regulation, Director 28pp. 21799 305. 24X Fiche 50-000, 84/01/06, B401130303

B401130356 NUREG/CR-3540
RADIOLOGICAL ASSESSMENT OF STEAM GENERATOR REPAIR AND REPLACEMENT.
PARKHURST, M A, RATHBUN, L A, MURPHY, D W Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2522 PNL-4877. 83/12/31 Division of Systems Integration (post B11005). 93pp. Available at NRC \$4.50 21817 171.

B401130357 Notices of equipment qualification problems which could result in request for extension of 10CFR50.49 rulemaking deadline.
QUICHA, L T. Georgia Power Co NED-84-013. 84/01/06. STOLZ, J. F.
Operating Reactors Branch 4 2pp 21800 316 24X
Fiche 50-366, 84/01/06, B401130357.

B401130360 NUREG/CR-3456
HANFORD ATMOSPHERIC DISPERSION DATA 1960 Through June 1967
NICKOLA, P. W., RAMBOELL, J. V., QLANTZ, C. S Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2384 PNL-4814 83/11/30 Division of Health, Siting & Waste Management 673pp
Available at NRC \$12.00 21818 001

B401130379 NUREG/CR-3427 V02
LONG-TERM PERFORMANCE OF MATERIALS USED FOR HIGH-LEVEL WASTE PACKAGING Quarterly Report, July - September 1983
STAHL, D., MILLER, M E Battelle Memorial Institute, Columbus Laboratories FIN B-6764 83/12/31 Division of Health, Siting & Waste Management 93pp Available at NRC \$4.75 21817.066

B401160012 Forwards safety evaluation accepting licensee compliance w/ NUREG-0737, Item II B 3, "Post-Accident Sampling Bya." Info submitted demonstrates ability of sys to function under expected accident conditions.
VASSALLO, D B Operating Reactors Branch 2 83/12/07 PILANT, J M
Nebraska Public Power District 9pp 21821.348 24X
Fiche 50-298, 83/12/07, B401160012

B401160038 Forwards criteria guidelines for NUREG-0737, Item II B 3, "Post-Accident Sampling Capability," to replace info following 830204 Request for Addl Info 281 7
KNIGHTON, O W. Licensing Branch 3 83/12/27. OPREA, O W Houston Lighting & Power Co. 11pp 21822.353 24X Fiche 50-498, 83/12/27, B401160038

B401160077 Forwards details of NUREG-0612, Section 5.1.1 guideline & compliance methodology review & response to Technical Evaluation Rept C5257-61/62/63 re special lifting device review, per 830526 ltr concerning control of heavy loads.
MILLS, L M Tennessee Valley Authority. 84/01/06 VASSALLO, D B
Operating Reactors Branch 2. 19pp. 21815 067. 24X
Fiche 50-289, 84/01/06, B401160077.

B401160095 Discusses plans for establishing emergency offsite facility, per NUREG-0737, Suppl 1, in response to NRC B31103 ltr
Clarification of NUREG-0737 guidance re contained sources, leakage rates & release pathways requested.
HARRINGTON, W. D. Boston Edison Co BECO 84-007. 84/01/10
EISENHUT, D G. Division of Licensing 3pp 21815 205 24X
Fiche 50-293, 84/01/10, B401160095.

B401160143 Informs that control room design review completed. Draft rept prepared for internal review. Earlier human factor review incorporated as result of NUREG-0737 to accurately reflect human factors considerations.
WHITTIER, Q D Maine Yankee Atomic Power Co. MN-84-04 84/01/06.
MILLER, J R Operating Reactors Branch 3 1p. 21815.006. 24X
Fiche 50-309, 84/01/06, B401160143.

B401160148 Forwards comments on detailed control room design review program plan. Majority of Suppl 1 to NUREG-0737 requirements addressed. Plan provides inadequate basis for design review. Meeting suggested to discuss deficiencies.
STOLZ, J. F. Operating Reactors Branch 4 83/12/22. RODRIGUEZ, R J
Sacramento Municipal Utility District 15pp 21822.338. 24X
Fiche 50-312, 83/12/22, B401160148

B401160178 Responds to Generic Ltr 83-41 Eight diesel generator fast starts noted during Dec 1982 - Nov 1983 due to excessive equipment cycling on breakers, relay contacts & shaft driven components & increased mechanical wear on bearings.
CAREY, J. J. Duquesne Light Co QL-83-41. 84/01/06 EISENHUT, D G.
Division of Licensing 2pp. 21815.350 24X Fiche 50-334, 84/01/06, B401160178

B401160269 Forwards response to NRC B31012 ltr re radiological ETB. Withdrawal of Proposed Change 68 requested since performance record demonstrates compliance w/NRC regulations
WHITTIER, Q D Maine Yankee Atomic Power Co. MN-84-03 84/01/06.
MILLER, J R Operating Reactors Branch 3. 6pp 21813.309. 24X
Fiche 50-309, 84/01/06, B401160269

B401160289 Forwards BER & technical evaluation rept re Mark I containment long-term program pool dynamic loads issue. Nodes acceptable. Commitments re vacuum breakers per Generic Ltr B3-02 will be reviewed independently
CRUTCHFIELD, D. Operating Reactors Branch 5 L805-B4-01-016
84/01/13 FIEDLER, P. B. General Public Utilities - GPU Service Corp 4pp. 21814.227 24X Fiche 50-219, 84/01/13, B401160289.

---B401160281 Safety evaluation supporting Mark I containment long-term program pool dynamic loads issue
* Office of Nuclear Reactor Regulation, Director. 84/01/13 2pp.
21814.231. 24X Fiche 50-219, 84/01/13, B401160281

NONDOCKETED ITEMS

---B401160284 04243

"Technical Evaluation of Oyster Creek Plant Unique Analysis Repts."

LEHNER, J. R., BIENKOWSKI, G., LIN, C. C. Brookhaven National Laboratory. FIN A-3713 04243 83/09/30 NRC - No Detailed Affiliation Given 26pp 21814 233 24X Fiche 50-219, 84/01/13, 8401160280

B401160413 Summary of 831220 meeting w/util in Bethesda, MD re exemption request from NUREG-0737, Item II F 1, "Add'l Accident Monitoring Instrumentation"

KENYON, T. J. Licensing Branch 4. 84/01/09 Licensing Branch 4 7pp. 21821, 254 24X Fiche 50-370, 84/01/09, 8401160413

B401160434 NUREG/CR-3594

AXIAL STRENGTH OF CEMENT BOREHOLE PLUGS IN GRANITE & BASALT

Topical Rept On Rock Mass Sealing
STORMONT, J. C., DAEMEN, J. J. Arizona State Univ. FIN B-6627 83/12/31 NRC - No Detailed Affiliation Given 200pp. Available at NRC \$6.00 21822 001

B401160438 NUREG/CR-3018

CHARACTERIZATION OF CLASS B STABLE RADIOACTIVE WASTE

PACKAGES OF THE NEW ENGLAND NUCLEAR CORPORATION.
GABSE, E. P., VEAKIB, E., SMALLEY, J. Brookhaven National Laboratory
FIN A-3165 BNL-NUREG-51607. 83/12/31 Division of Waste Management 72pp. Available at NRC \$4.50 21822 191

B401160443 NUREG/CR-2970 V04

MATERIALS SCIENCE AND TECHNOLOGY DIVISION LIGHT-WATER-REACTOR SAFETY RESEARCH PROGRAM. QUARTERLY PROGRESS REPORT OCTOBER - DECEMBER 1982

SHACK, W. J., REST, J., KASSNER, T. F. Argonne National Laboratory FIN A-2016 ANL-82-41 84/01/31. Office of Nuclear Regulatory Research, Director. 125pp. 21824 001

B401160448 FOIA request for draft memo from R Mattson to H Denton,

"Resolution of Reactor Coolant Pump Trip Issue," referenced in NUREG-0933, to be placed in PDR.
GRABER, L. D. NUS Corp. CD-18-83-411 83/10/03 Division of Rules and Records. 1p 21835 286

B401160450 NUREG/CR-3510

FIELD TESTING OF FUGITIVE DUST CONTROL TECHNIQUES AT A URANIUM MILL TAILINGS PILE - 1982 FIELD TEST, GAS HILLS, WYOMING

ELMORE, R. HARTLEY, J. N. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2370 PNL-4798. 83/12/31. Division of Health, Siting & Waste Management. 60pp Available at NRC. \$4.50. 21822 261.

B401160452 Responds to FOIA request for placement of draft memo from

R Mattson to H Denton, "Resolution of Reactor Coolant Pump Trip Issue, referenced in NUREG-0933, in PDR Forwards documents. Document also available in PDR.
FELTON, J. M. Division of Rules and Records 83/10/21 GRABER, L. D. NUS Corp. 1p. 21835 287

---B208230015 Submits for concurrence, proposed resolution of reactor

coolant pump (RCP) trip issue per request Discussions w/ industry representatives on RCP trip during accidents encl.
MATTSON, R. J. Division of Systems Integration (post 811005) 82/07/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 32pp. 21835 340.

---B401160454 Submits for concurrence, proposed resolution of reactor

coolant pump (RCP) trip issue per request, Discussions w/ industry representatives on RCP trip during accidents encl. Draft 1p
MATTSON, R. J. Division of Systems Integration (post 811005). 81/07/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 32pp. 21835 288

B401160460 Further response to FOIA request for 42 categories of

documents. Forwards requested documents. Documents also available in PDR
FELTON, J. M. Division of Rules and Records. 83/10/14. SHOLLY, B. C. Union of Concerned Scientists. 1p 21826 305.

---B401160472 Comments on short & long-term NRRD needs for improved

seismic analysis methodology per seismic safety margins research program & long-range research plan (NUREG-0784). Needs, goals & comprehensive program plan summary listed.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 82/04/07. HINDS, R. B. Office of Nuclear Regulatory Research, Director. 14pp. 21827 001.

B401160477 NUREG-1009

TECHNICAL SPECIFICATIONS FOR WPPSS NUCLEAR PROJECT NO. 2
Docket No. 50-397, (Washington Public Power Supply System)
HOFFMAN, D. R. Division of Licensing 83/12/31. 47pp. Available at NRC. \$9.50 21824 299. 24X Fiche: 50-397. 83/12/31, 8401160477.

B401170009 Submits general plan to identify & resolve outstanding plant-specific issues re Suppl 1 to NUREG-0821, "Cable Tray Seismic Evaluation." Final schedule will be established after progress toward resolution of NRC questions occurs.
MAIER, J. E. Rochester Gas & Electric Corp. 84/01/10 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 21834 103 24X Fiche 50-244, 84/01/10, 8401170009

B401170015 Further response to FOIA request for 42 documents Forwards Documents 14 & 20 Documents also available in PDR
FELTON, J. M. Division of Rules and Records 83/10/25 SHOLLY, B. C. Union of Concerned Scientists. 1p 21837 307

---B401170021 Forwards status rept on radiological consequences of containment venting & purging while reactor pressurized TMI Action Plan Item II E 4 addressed in SRP 6 2 4 & Branch Technical Position CSB 6-4
MATTSON, R. J. Division of Systems Integration (post 811005) 82/05/13 DIRCKS, W. J. Office of the Executive Director for Operations 3pp 21837 314

---B401170018 Responds to 820225 memo re draft licensing guidelines for implementation of NUREG-0666, Recommendation 4 concerning Generic Issue A-30, "Adequacy of Safety-Related DC Power Supplies." Concern could be met w/o major mod.
PARR, D. D. Auxiliary Systems Branch SHERON, B. Reactor Systems Branch 82/03/12 BRINIVASAN, M. Power Systems Branch 2pp 21837 312

---B401170023 Forwards generic safety evaluation of radiological consequences of containment venting & purging while reactor pressurized, per NUREG-0737, Item II E 4 2, SRP 6 2 4 & Branch Technical Position 6-4
HOUSTON, R. W. Assistant Director for Radiation Protection 82/03/03 SPEIS, T. P. Assistant Director for Reactor Safety. 23pp 21837 317

B401170052 Partial response to FOIA request for 42 categories of documents Forwards listed documents Documents also available in PDR Review of add'l records subj to request in progress.
FELTON, J. M. Division of Rules and Records 83/10/03. SHOLLY, B. C. Union of Concerned Scientists 1p 21846 163

---B21160524 Notices of status of unresolved items in draft NUREG-0933, "Prioritization of Generic Safety Issues." Four items resolved B-19 should be dropped as generic issue. A-16 & NUREG-0737, Item II E 5 1 nearly complete.
MATTSON, R. J. Division of Systems Integration (post 811005) 82/11/05 FUNCHES, J. L. Planning & Program Analysis Staff. 6pp 21846 220.

---B401170076 Forwards generic issue mgt control info & detailed milestones schedules for Issues 4, 14, 29, A-15, B-6, B-48, B-64, C-7, C-12 & III D 2 3, per Denton request.
VOLLMER, R. H. Division of Engineering IEN-82-02. 83/02/01 SPEIS, T. P. Division of Safety Technology 16pp 21846 168

---B203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NUREG-0660, Item II E 5 1, design sensitivity of B&W reactors. Lists of NUREG-0667 recommendations reviewed & NRC evaluation encl.
MATTSON, R. J. Division of Systems Integration (post 811005) 82/02/26 HANAUER, S. Division of Safety Technology 28pp 21846 227.

---B401170104 Forwards rept on completion of TMI Action Plan Item II J 1 2, "Mod of Vendor Insp Program," per 810603 memo. No followup assignments necessary w/ completion of action item
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/10/29 DIRCKS, W. J. Office of the Executive Director for Operations 3pp 21846 337.

---B401170108 Forwards rept on completion of TMI Action Plan Item IV A 2, "Revised Enforcement Policy," per 810603 memo Enforcement policy revised & approved by Commission & issued in effective form on 820309.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/03/11 DIRCKS, W. J. Office of the Executive Director for Operations. 3pp. 21846 348

---B401170114 Forwards rept on completion of TMI Action Plan Items III A 3 & "Emergency Preparedness, NRC & Other Agencies," & III B 2, "Implementation of NRC & FEMA Responsibilities," per 810603 memo
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 82/04/02 DIRCKS, W. J. Office of the Executive Director for Operations 6pp 21846 351.

NONDOCKETED ITEMS

441

--B203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NUREG-0660, Item II E 5.1, design sensitivity of B&W reactors Lists of NUREG-0667 recommendations reviewed & NRC evaluation encl
MATTSON, R Division of Systems Integration (post B11005)
82/02/26 HANAUER, S Division of Safety Technology 25pp
21846 227

--B207150195 Submits suggestions re design sensitivity of B&W reactors CPC or contractor should obtain cost of necessary changes & estimate of occupational exposure that might be incurred Info should then be used to develop value impact statement
HANAUER, S H Division of Systems Integration (post B11005)
82/06/21 MATTSON, R J Division of Systems Integration (post B11005) 2pp 21846 252

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-44, C-7, C-12 & III D 2 3, per Denton request
VOLLNER, R H Division of Engineering IEB-82-02 83/02/01
SPEIS, T P Division of Safety Technology 16pp 21846 168

--B401170114 Forwards rept on completion of TMI Action Plan Items III A 3 & "Emergency Preparedness, NRC & Other Agencies," & III B 2, "Implementation of NRC & FEMA Responsibilities," per B10603 memo
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/06/02 DIRCKS, W J Office of the Executive Director for Operations 6pp 21846 351

--B203170235 Recommends that B&W plant owners implement needs to conform w/requirements of NUREG-0660, Item II E 5.1, design sensitivity of B&W reactors Lists of NUREG-0667 recommendations reviewed & NRC evaluation encl
MATTSON, R Division of Systems Integration (post B11005)
82/02/26 HANAUER, S Division of Safety Technology 25pp
21846 227

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-44, C-7, C-12 & III D 2 3, per Denton request
VOLLNER, R H Division of Engineering IEB-82-02 83/02/01
SPEIS, T P Division of Safety Technology 16pp 21846 168

--B401170114 Forwards rept on completion of TMI Action Plan Items III A 3 & "Emergency Preparedness, NRC & Other Agencies," & III B 2, "Implementation of NRC & FEMA Responsibilities," per B10603 memo
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/06/02 DIRCKS, W J Office of the Executive Director for Operations 6pp 21846 351

--B21160524 Notifies of status of unresolved items in draft NUREG-0733, "Prioritization of Generic Safety Issues" Four items resolved, B-19 should be dropped as generic issue A-16 & NUREG-0737, Item II E 5.1 nearly complete
MATTSON, R J Division of Systems Integration (post B11005), 82/11/05, FUNCHES, J L Planning & Program Analysis Staff, 6pp
21846 220

--B401170090 Discusses status of branch work on Generic Issue B-6, in response to RJ Boshak 820826 memo to W-Minners More detailed study on loads & load combinations initiated at BNL No further investigation required
SCHAUER, F P Structural Engineering Branch 82/09/02, MINNERB, W Safety Program Evaluation Branch, 1p 21846 226

--B401170076 Forwards generic issue mgt control info & detailed milestone schedules for Issues 4, 14, 29, A-15, B-6, B-4B, B-44, C-7, C-12 & III D 2 3, per Denton request
VOLLNER, R H Division of Engineering IEB-82-02, 83/02/01
SPEIS, T P, Division of Safety Technology 16pp 21846 168.

B401170111 Forwards comments on B31025 detailed control room design review program plan, per requirements of Suppl 1 to NUREG-0737
HILLER, J R. Operating Reactors Branch 3 83/12/30, JONES, W C Omaha Public Power District 11pp 21839 331 24X
Fiche: 50-285, 83/12/30, B401170111

B401170143 NUREG-0675 S21
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos. 50-275 AND 50-323 (Pacific Gas and Electric Company)
Division of Licensing, 83/12/31 275pp. Available at NRC.
\$7.00 21839-001 24X Fiche: 50-275, 83/12/31, B401170143.

B401170154 Informs of delay of completion of plant-specific risk assessment from B31115 to Apr 1984. Assessment conducted to select mod to automatic depressurization sys logic, per NUREG-0737, Item II K.3.18.
FIEDLER, P B. General Public Utilities - GPU Service Corp. 84/01/12
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 21834, 127. 24X
Fiche: 50-219, 84/01/12, B401170154

B401170170 Final response to FOIA request for three categories of records re Suppl 1 to NUREG-0737 at Table 1 re emergency operations facility less than 10 miles from plant Forwards response to broader FOIA request from JH O'Neill w/o encl
FELTON, J M Division of Rules and Records 83/11/03 PHILIPS, M H. Debevoise & Liberman 1p 21836 359

B401170181 Informs that util will not be able to respond to draft technical evaluation rept open items re control of heavy loads within recommended time frame Responses to open items will be provided by B40203
ZIMMERMAN, B R Carolina Power & Light Co. NLS-B4-013 84/01/12
VASSALLO, D B Operating Reactors Branch 2 1p. 21834 152. 24X
Fiche 50-324, 84/01/12, B401170181

B401170202 Forwards response to B31103 ltr re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." Radionuclide concentrations will be accomplished by using Geli detector in conjunction w/ND6600 computer.
LINDER, F Dairyland Power Cooperative LAC-9526 84/01/10.
CRUTCHFIELD, D Operating Reactors Branch 5 5pp 21831 323 24X
Fiche: 50-409, 84/01/10, B401170202.

B401170204 Advises that backup emergency operations facility will be provided in case existing primary facility becomes uninhabitable Conowingo Hydro Electric Station will be provided w/communication equipment
DALTROFF, B L Philadelphia Electric Co 84/01/11. STOLZ, J F. Operating Reactors Branch 4 4pp 21832 252 24X
Fiche 50-277, 84/01/11, B401170204

B401170224 Forwards addl info in support of util position on compliance to QDC-51, per B31028 request NUREG-0577 NDT (+57F) statistically generated bounding valve based on 90% confidence.
MILLS, L M Tennessee Valley Authority. 84/01/09 ADENSAM, E Licensing Branch 4. 7pp 21833 314 24X Fiche: 50-390, 84/01/09, B401170224

B401170235 Requests exemption from 10CFR20, App A, to allow credit for radiiodine protection factor in employing MSA 46620 QMR-I canister Limitations in use of canister listed Test results, proposed test protocol & QA sampling plan encl
CLAYTON, F L Alabama Power Co 84/01/13 VAROA, S A Office of Nuclear Reactor Regulation, Director. 6pp 21831 353 24X
Fiche 50-348, 84/01/13, B401170235

B401170250 Forwards revised response to Criterion 11 B re B31123 proposed license amend allowing completion of mod for post-accident sampling, per NUREG-0737, Item II B.3. Isolation valves backed by Class IE power
MILLS, L M Tennessee Valley Authority. 84/01/09 ADENSAM, A E. Licensing Branch 4. 2pp 21832 224 24X Fiche: 50-327, 84/01/09, B401170250

B401170364 Forwards IE Insp Rept 50-267/83-31 on B31101-30 No violations noted
JOHNSON, E H Region 4, Office of Director 83/12/28 LEE, O R. Public Service Co of Colorado. 2pp 21828 199. 24X
Fiche: 50-267, 83/12/28, B401170364

--B401170370 IE Insp Rept 50-267/83-31 on B31101-30, No violations noted. Major areas inspected: licensee action on previous insp findings, operational safety verification, surveillance, maint, IE bulletin followup & review of periodic & special repts
PLUMLEE, G L, HUNNICUTT, D M Region 4, Office of Director IEI-83-03. 83/12/28 11pp. 21828 201. 24X Fiche: 50-267, 83/12/28, B401170364.

B401170379 Advises that results of C-E Owners Group program & completion dates for operator training/emergency operating procedure revs per NUREG-0737, Item II K.3.3 will be submitted by B40501.
COUNSIL, W G, BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, W G. Northeast Utilities, 10991, 83/12/30 EISENHUT, D G Division of Licensing. 1p 21828 281 24X Fiche: 50-336, 83/12/30, B401170379

B401170382 Forwards response to safety evaluation outstanding questions re NUREG-0737, Item II F 2 on detection of inadequate core cooling requirements. Scheduled dates for completion of milestones listed
MARSHALL, J R. Arkansas Power & Light Co ICAND18404. 84/01/13, STOLZ, J F. Operating Reactors Branch 4. 6pp. 21828, 282. 24X
Fiche: 50-313, 84/01/13, B401170382.

B401170392 Advises that written documentation not received re NRC determination & associated explanations of state comments on certain issues identified in util applications for license amends covered by Tech Specs (NUREG-0728)
FUENTE, E B. Mississippi State of 84/01/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p. 21844 260 24X
Fiche: 50-416, 84/01/12, B401170392.

NONDOCKETED ITEMS

B401170423 Suppl's B31123 application to amend License# DPR-77 & DPR-79, allowing completion of post-accident sampling mod per NUREG-0737, Item II. B 3 Expedient review of application requested to allow mod during Feb 1984 refueling outage.
MILLS, L. M. Tennessee Valley Authority 84/01/10 ADENBAM, E.
Licensing Branch 4 2pp 21829 221 24X Fiche 50-327, 84/01/10, 8401170423

B401170437 Application to amend Licenses DPR-32 & DPR-37, consisting of suppl to Tech Spec change to clarify radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3.
STEWART, W. L. Virginia Electric & Power Co 84/01/11 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 3pp. 21827 103 24X
Fiche 50-280, 84/01/11, 8401170437

--B401170440 Suppl to proposed Tech Spec change clarifying radiological effluent Tech Specs to comply w/requirements of NUREG-0472, Rev 3
* Virginia Electric & Power Co. 84/01/11 13pp. 21827 106 24X
Fiche 50-280, 84/01/11, 8401170437

B401170495 Forwards NRC comments on detailed control room design review program plan submitted in response to Generic Ltr 83-28 (NUREG-0737, Suppl 1) In-progress audit should be scheduled during last 7 months of 1984
VARQA, S. A. Operating Reactors Branch 1 0L-83-28 84/01/04.
CAREY, J. J. Duquesne Light Co 15pp 21847 160 24X
Fiche 50-334, 84/01/04, 8401170495

B401170515 Advises that util actions taken in response to NRC 801222 ltr & Generic Ltr 81-07 re control of heavy loads satisfy requirements.
BNYDER, B. J. TMI Program Office. 0L-81-07. 84/01/05 KANGA, B. K.
General Public Utilities - GPU Service Corp 3pp 21847 132 24X
Fiche 50-320, 84/01/05, 8401170515

B401170559 Summary of ACRS Subcommittee on SEP 831107 meeting w/util in Washington, DC re SEP integrated assessment rept for facility (NUREG-0828)
* ACRS - Advisory Committee on Reactor Safeguards 83/12/16
ACRS - Advisory Committee on Reactor Safeguards 13pp 21844 292
24X Fiche 50-133, 83/12/16, 8401170559

B401170560 Forwards License NPF-21 for facility, environ protection plan & Tech Specs (NUREG-1009) Pending Commission approval, operation restricted to power levels not in excess of 5% of full power Assessment of effect of license duration encl.
EIBENHUT, D. O. Division of Licensing 83/12/20 MAZUR, D. W.
Washington Public Power Supply System 9pp. 21845 001. 24X
Fiche 50-397, 83/12/20, 8401170560.

--B401170561 License NPF-21 for facility Tech Specs (NUREG-1009) encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director.
83/12/20 497pp. 21845 010 24X Fiche 50-397, 83/12/20,
8401170560

B401180072 NUREG/CR-3430 V01
NUCLEAR POWER PLANT OPERATING EXPERIENCE-1981. Annual Report
SILVER, E. Q. MAYS, G. T. Oak Ridge National Laboratory. FIN B-1637.
ORNL/N81C-215/V 83/12/31. Division of Data Automation &
Management Information 397pp Available at NRC. \$8 50.
21851 323

B401180087 Requests submittal of plant-specific responses to NUREG-0803 & Generic Ltr 81-34 re safety concerns associated w/pipeline breaks in BWR steam sys piping. Responses should be submitted by 840305
CRUTCHFIELD, D. Operating Reactors Branch 5 LS05-84-01-017
84/01/17. FIEDLER, P. B. General Public Utilities - GPU Service Corp
2pp 21840 306. 24X Fiche 50-219, 84/01/17, 8401180087.

B401180120 NUREG-1026
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF
BRAIDWOOD STATION UNITS 1 AND 2 Docket Nos. STN 50-456 And
STN 50-457. (Commonwealth Edison Company)
* Division of Licensing 83/12/31 213pp. Available at NRC
\$6.50 21848 001. 24X Fiche 50-456, 83/12/31, 8401180120

B401180126 NUREG-0995
SAFETY EVALUATION REPORT RELATED TO PLANT RESTART OF SALEM
NUCLEAR GENERATING STATION, UNIT NOS. 1 AND 2 Docket Nos
50-272 And 50-311. (Public Service Electric And Gas Company,
et al).
* Division of Licensing. 83/12/31. 117pp. Available at NRC
\$5.00. 21847 176. 24X Fiche 50-272, 83/12/31, 8401180126.

B401180146 Forwards safety evaluation re Mark I containment long-term
program structural review Deviations from NUREG-0661
acceptable. Original design safety margin restored.
CRUTCHFIELD, D. Operating Reactors Branch 5 LS05-84-01-015
84/01/13. FIEDLER, P. B. General Public Utilities - GPU Service Corp.
3pp. 21848 312. 24X Fiche 50-219, 84/01/13, 8401180146.

--B401180260 Safety evaluation supporting Mark I containment long-term
program structural review Mods acceptable, per NUREG-0661
& ASME Code, Sections XI & III
* Office of Nuclear Reactor Regulation, Director 84/01/13 3pp
21848 315 24X Fiche 50-219, 84/01/13, 8401180146

B401180147 NUREG/CR-2522 R01
EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS
PROGRAM PLAN
MILLER, R. L. U S Ecology, Inc (formerly Nuclear Engineering, Inc)
FIN B-7568 83/12/31 Division of Engineering Technology 32pp
Available at NRC \$3 75 21847 295

B401180189 Informs that FEMA has confirmed receipt of revised
transition plan & revised NUREG-0654 cross-reference for
facility.
KRIMM, R. W. Federal Emergency Management Agency 84/01/13
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 21844 081 24X Fiche 50-322, 84/01/13,
8401180189

B401180231 Forwards IE Insp Repts 50-387/83-23 & 50-388/83-21 on
831003-1105 & notice of violation, App A & B
STANDSTECK, R. Division of Project & Resident Programs 84/01/04
KENYON, B. D. Pennsylvania Power & Light Co 2pp 21843 342 24X
Fiche 50-387, 84/01/04, 8401180231

--B401180268 IE Insp Repts 50-387/83-23 & 50-388/83-21 on 831003-1105
Violations noted FSAR not updated at completion of Unit 1
canst Required 31-day surveillance not performed on valve
137-014 Safeguards info deleted (ref 10CFR73 21)
RHODAS, G. Region I, Office of Director. IES-83-01 83/11/18
18pp 21843 346 24X Fiche 50-387, 84/01/04, 8401180251

B401190090 Forwards SSER 4 (NUREG-0892) W/o encl
SCHWENGER, A. Licensing Branch 2. 83/12/29 SORENSEN, G. C.
Washington Public Power Supply System 2pp 21870 252 24X
Fiche 50-397, 83/12/29, 8401190090

B401190092 Forwards comments on 830901 detailed control room design
review program plan per Suppl 1 to NUREG-0737
MILLER, J. R. Operating Reactors Branch 3 83/12/30 LUNDVALL, A. E.
Baltimore Gas & Electric Co 14pp 21870 266 24X
Fiche 50-317, 83/12/30, 8401190092

B401190095 Forwards request for addl info & comments on Rev 5A to
emergency plan Requested info & page changes should be
submitted within 30 days
YOUNGBLOOD, B. J. Licensing Branch 1 84/01/05 SCHNELL, D. F. Union
Electric Co 9pp 21870 243. 24X Fiche 50-483, 84/01/05, 8401190095

B401190128 Forwards safety evaluation re TMI Action Item II K 2 17,
"Voiding in RCS" Item resolved
MILLER, J. R. Operating Reactors Branch 3 84/01/03 WITHERS, D. D.
Portland General Electric Co 3pp. 21870 001 24X
Fiche 50-344, 84/01/03, 8401190128

B401190139 Forwards DES (NUREG-1026) W/o encl
YOUNGBLOOD, B. J. Licensing Branch 1 84/01/06 FARRAR, D. L.
Commonwealth Edison Co 2pp 21871 017 24X Fiche 50-456, 84/01/06,
8401190139

B401190144 Forwards SSER 20 (NUREG-0676) W/o encl.
KNIGHTON, G. W. Licensing Branch 3 84/01/04 SCHUYLER, J. D. Pacific
Gas & Electric Co 4pp 21871 006 24X Fiche 50-275, 84/01/04,
8401190144

B401190157 Forwards SSER 4 (NUREG-0881) W/o encl
YOUNGBLOOD, B. J. Licensing Branch 1 83/12/30. KOESTER, O. L. Kansas
Gas & Electric Co 2pp 21870 362 24X Fiche 50-482, 83/12/30,
8401190157

B401190159 Forwards evaluation of NUREG-0737, Item II K 2 17 re
potential voiding in RCS during anticipated transients. Steam
voids will not result in unacceptable consequences during
transients
MILLER, J. R. Operating Reactors Branch 3 83/12/30 MUSOLF, D. M.
Northern States Power Co 4pp 21870 356 24X
Fiche 50-282, 83/12/30, 8401190159

B401190161 Advises that facility complies w/habitability & location
requirements of emergency operations facility per Suppl 1 to
NUREG-0737, based on review of 831206 submittal
VARQA, S. A. Operating Reactors Branch 1 84/01/03 UTLEY, E. E.
Carolina Power & Light Co 2pp 21870 354. 24X
Fiche 50-261, 84/01/03, 8401190161.

NONDOCKETED ITEMS

443

840190168 Notices of review of 82122i submittal re habitability & location of emergency operations facility Facility complies w/requirements of Table 1 of Suppl 1 to NUREG-0737
MILLER, J R Operating Reactors Branch 3 83/12/15 WILLIAMS, J W
Florida Power & Light Co 2pp 21861 362 24X
Fiche 50-335, 83/12/15, 840190168

840190192 Forwards SER (NUREG-0876) for Byron in support of ACRS review of Braidwood SER W/o encl
NOVAK, T M Assistant Director for Licensing. 84/01/03
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards ip
21870 021 24X Fiche 50-454, 84/01/05, 840190192

840190250 NUREG/CR-3307 V02
REACTOR SAFETY RESEARCH PROGRAMS Quarterly Report April-June 1983
EDLER, S K Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2101 PNL-4705-2 83/12/31 Division of Accident Evaluation (Pre 840101) 72pp Available at NRC \$4 50 21870 098.

840190387 Forwards application for amend to Licensee DPR-42 & DPR-60, to provide assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, Item 11 B 1
MUSOLF, D. Northern States Power Co 84/01/13 Office of Nuclear Reactor Regulation, Director 2pp 21849 349. 24X
Fiche 50-282, 84/01/13, 840190387

--840190392 Application for amend to License DPR-42 & DPR-60, providing assurance of reactor coolant vent sys operability & reliability, implementing requirements of NUREG-0737, Item 11 B 1.
MUSOLF, D Northern States Power Co 84/01/13 App 21849 351 24X Fiche. 50-282, 84/01/13, 840190387

840190409 Requests that final submission of radiological Tech Specs be written according to NUREG-0472, Rev 3, Draft 7 guidance Tech Specs should be submitted by 840731
CRUTCHFIELD, D Operating Reactors Branch 5 L805-84-01-019 84/01/17. VANDEWALLE, D J Consumers Power Co 2pp 21850 096 24X Fiche 50-255, 84/01/17, 840190409

8401200017 Forwards IE Insp Rept 50-312/83-26 on 831122-23 No noncompliance noted
WENSLAWSKI, F A Region 5, Office of Director 83/12/30.
RODRIGUEZ, R J Sacramento Municipal Utility District. 2pp 21864 345 24X Fiche 50-312, 83/12/30, 8401200017

--8401200023 IE Insp Rept 50-312/83-26 on 831122-23 No noncompliance noted. Major areas inspected. Followup of reported resin bag failures & post-implementation insp of NUREG-0737, Items 11 B.3 re post-accident sampling & 11 F 1 re monitoring.
NORTH, H S, WENSLAWSKI, F A Region 5, Office of Director. 83/12/30 7pp 21864 347 24X Fiche 50-312, 83/12/30, 8401200017.

8401200027 Forwards IE Insp Rept 50-397/83-59 on 831114-18 & 1205-08. No noncompliance noted
BISHOP, T W Division of Resident Reactor Project & Engineering Programs 84/01/05 BORENSEN, G C Washington Public Power Supply System 2pp 21864 356. 24X Fiche 50-397, 84/01/05, 8401200027

--8401200028 IE Insp Rept 50-397/83-59 on 831114-18 & 1205-08. No noncompliance noted. Major areas inspected preoperational test results, followup items, TMI (NUREG-0737) activities, bulletins & circulars.
HILLET, D J, DODDS, R T Region 5, Office of Director. IEB-82-03 83/12/16 5pp. 21864 358. 24X Fiche 50-397, 84/01/05, 8401200027

8401200105 Requests that ASLB defer ruling on applicant motion for summary disposition re manual reactor trip testing.
Stipulation of withdrawal of Contention I, D 2 will be filed within 2 wks
CURRAN, D Harmon & Weiss CURRAN, D New England Coalition on Nuclear Pollution 84/01/17. HOYT, H F, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p. 21866 393. 24X Fiche 50-443, 84/01/17, 8401200105.

8401200115 Forwards safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads"
CRUTCHFIELD, D Operating Reactors Branch 5. L805-84-01-025 84/01/18. MAIER, J E Rochester Gas & Electric Corp 2pp. 21863 251 24X Fiche 50-244, 84/01/18, 8401200115

--8401200121 Safety evaluation supporting util Phase I response to NUREG-0612, "Control of Heavy Loads"
* Office of Nuclear Reactor Regulation, Director 84/01/18. 3pp 21863 253 24X Fiche. 50-244, 84/01/18, 8401200115.

--8312060347 TER-C5506-357
"Control of Heavy Loads C-10, RE Ginna Nuclear Power Plant." technical evaluation rept
VOSBURY, F W, BOMBERGER, C. Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 07992 83/12/02 SINOH, A, CHAN, T NRC - No Detailed Affiliation Given 30pp 21863 256 24X Fiche 50-244, 84/01/18, 8401200115

8401200126 Forwards SER on NUREG-0737, Item 11 K.2 17, "Potential for Voiding in RCS During Transients," for Westinghouse plants. Steam void will not result in unacceptable consequences during anticipated transients
VARGA, S A Operating Reactors Branch 1 84/01/06 QIEBLER, C W Wisconsin Public Service Corp App. 21872 160 24X Fiche 50-305, 84/01/06, 8401200126

8401200133 Forwards SER on NUREG-0737, Item 11 K.2 17, "Potential for Voiding in RCS During Transients," for Westinghouse plants. Steam void will not result in unacceptable consequences during anticipated transients
VARGA, S A Operating Reactors Branch 1 84/01/06. WILLIAMS, J H. Florida Power & Light Co 2pp. 21872 139 24X Fiche 50-250, 84/01/06, 8401200133

8401200139 Forwards Rev 1 to "SAR for Safety Parameter Display Sys" in response to Generic Ltr B2-33, Suppl 1 to NUREG-0737
PETRICK, N A Standardized Nuclear Unit Power Plant System. QL-B2-33 84/01/13 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p. 21865 300 24X Fiche 50-000, 84/01/13, 8401200139

--8401200145 Rev 1 to "SAR for Safety Parameter Display Sys." * Standardized Nuclear Unit Power Plant System. 84/01/13. 31pp. 21865 301 24X Fiche. 50-000, 84/01/13, 8401200139

8401200186 Application for amend to License NPF-9, extending required implementation data for outside-containment portion of in-core thermocouple sys upgrade, per NUREG-0737, Item 11.F.2; "Inadequate Core Cooling Instruments," & Suppl 1 to NUREG.
TUGHER, H E. Duke Power Co. 84/01/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4 8pp 21864 335 24X Fiche 50-369, 84/01/12, 8401200186

8401200284 Releases public version of addition to emergency plan rev. FELTON, J M Division of Rules and Records. 84/01/17 Document Management Branch 1p 21890 361. 24X Fiche 50-348, 84/01/17, 8401200284

--8401200288 Public version of addition to Rev 5 to emergency plan entitled, "Region II Suppl to NUREG-0845." * Alabama Power Co. 83/10/31. 164pp 21890 362 24X Fiche 50-348, 84/01/17, 8401200284

8401200362 NUREG-0485 V05 N11
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As Of November 30, 1983 (Buff Book)
* Office of Resource Management, Director. 84/01/31. 75pp. 21872 003

8401200024 Forwards responses to Environ Qualification Section 831219 request for addl info Responses will be included in Rev 1 to environ qualification rept scheduled for submittal in Apr 1984.
KEMPER, J S. Philadelphia Electric Co. 84/01/16 SCHWENGER, A. Licensing Branch 2 527pp 21886 117. 24X Fiche 50-352, 84/01/16, 8401200024

--8401200028 Rev 1 to "Drywell Temp Response to Small Steam Break, Realistic Environ Qualification Envelope." NGUYEN, D V, JONES, D D General Electric Co. 83/11/18 12pp. 21887 274. 24X Fiche 50-352, 84/01/16, 8401200024.

8401200039 NUREG/CR-3439 V01
A DESCRIPTION OF THE HARDWARE AND SOFTWARE OF THE POWER SPECTRAL DENSITY RECOGNITION (PSDREC) CONTINUOUS ON-LINE REACTOR SURVEILLANCE SYSTEM (CALIFORNIA DISTRIBUTION), VOLUME 1.
SMITH, C M Oak Ridge National Laboratory FIN B-0442. ORNL/TM-8862/V1 84/01/31 Office of Nuclear Regulatory Research, Director. 73pp 21931 322.

8401200042 Notices of intent to load & move during power operation, cask similar to 7-1/2 ton cask referred to in SER Also reaffirms 761108 commitment not to use 60 ton fuel shipping cask w/o prior NRC approval.
BORDINE, T C Consumers Power Co. 84/01/18. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp 21884 346 24X Fiche 50-155, 84/01/18, 8401200042

NONDOCKETED ITEMS

B401230032 Final response to FOIA request for four categories of documents Forwards App A documents. Documents also available in PDF
FELTON, J M Division of Rules and Records 83/11/01. ADATO, M
Union of Concerned Scientists. 2pp 21930.271

--B401230061 Advises of NRC approval of recommendations to defer implementation date of NUREG-0737, Items II B 3.11 F.1 4, II F.1 5 & II F.1 6 until 830331 or before restart Approval of Item II B 2 2 date withheld until review completed
CHILK, S J Office of the Secretary of the Commission 82/10/19
DIRCKS, W J Office of the Executive Director for Operations 1p.
21930.274 24X Fiche 50-289, 83/11/01, B401230052

--B401230067 Advises that Commission approved recommendation to defer final implementation date for NUREG-0737, Item II B 2 2 until first refueling outage following restart
CHILK, S J Office of the Secretary of the Commission 83/01/05.
DIRCKS, W J Office of the Executive Director for Operations. 1p.
21930.275 24X Fiche 50-289, 83/11/01, B401230052.

--B401230070 SECY-82-384A
Recommends deferral of NUREG-0737, Item II B 2.2, "Plant Shielding Mods." implementation to first refueling outage following restart
DIRCKS, W J Office of the Executive Director for Operations
82/12/06. 4pp 21930.276.

--B401230079 SECY-83-340
Informs of status of facility restart certification effort & provides update on noncertification item status
DIRCKS, W J Office of the Executive Director for Operations
83/08/16 42pp 21930.280.

B401230062 NUREG/CR-3339 V03
PHYSICS OF REACTOR SAFETY. Quarterly Rept, July-September 1983
* Argonne National Laboratory FIN A-2015 ANL-83-11 V III
84/01/31. Division of Accident Evaluation (Pre B40101) 15pp.
21931.075

B401230066 NUREG/CR-3334 V02
HEAVY-SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS REPORT FOR APRIL-JUNE 1983
PUOH, C E Oak Ridge National Laboratory. FIN B-0117
ORNL/TM-8787/V2 84/01/31 Division of Engineering Technology
68pp 21921.001

B401230162 NUREG-0713 V04
OCCUPATIONAL RADIATION EXPOSURE AT COMMERCIAL NUCLEAR POWER REACTORS-1982. Annual Report.
BROOKS, B Q Division of Data Automation & Management Information
83/12/31. 129pp 21931.164

B401230173 Forwards addl info on implementation of NUREG-0737, Suppl 1. Item 6 & Reg Guide 1.97 re application to emergency response facilities. Results of evaluation for all instrumentation variables of Reg Guide 1.97 included.
DALTROFF, B L Philadelphia Electric Co. 84/01/16 EISENHUT, D G, Division of Licensing 132pp. 21885.267 24X Fiche 50-277, 84/01/16, B401230173.

B401230178 Informs that equipment installed in fulfillment of NUREG-0737, Items II F.1 1 & II F.1 2 declared operational in mid-Dec 1983 Tech Specs required by Generic Ltr 83-37 being prepared.
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL, W G Northeast Utilities 0L-83-37. 84/01/10.
CRUTCHFIELD, D. Operating Reactors Branch 5 MILLER, J R Operating Reactors Branch 3 2pp 21884.174 24X Fiche 50-245, 84/01/10, B401230178

B401230227 Advises that Guidelines 1, 2, 3 & 4 of NUREG-0612 re control of heavy loads fully implemented
MAYER, J E Rochester Gas & Electric Corp 84/01/11 CRUTCHFIELD, D
Operating Reactors Branch 3 1p. 21884.079 24X
Fiche 50-244, 84/01/11, B401230227.

B401230286 Discusses procedural changes to integrated plant safety assessment (NUREG-0826) re ability to balance svc water sys flow to maintain sys components below design thermal limits for active & passive failures, per SEP Topic IX-3
COUNSIL, W G, Connecticut Yankee Atomic Power Co. 810998. 84/01/12
CRUTCHFIELD, D. Operating Reactors Branch 3 3pp 21884.198 24X
Fiche 50-218, 84/01/12, B401230286

B401230308 Forwards application for amend to License DPR-63, revising Tech Specs to conform to SER "Application of NUREG-0737, Item II K.3.14, 'Isolation of Isolation Condensers' to Operating BWRs." per Generic Ltr 83-19
MANGAN, C V Niagara Mohawk Power Corp. 0L-83-19. 84/01/05.
VASSALLO, D B Operating Reactors Branch 2 1p 21883.321 24X
Fiche 50-220, 84/01/05, B401230308

--B401230314 Application for amend to License DPR-63, revising Tech Specs to conform to SER "Application of NUREG-0737, Item II K.3.14, 'Isolation of Isolation Condensers' to Operating BWRs." MANGAN, C V Niagara Mohawk Power Corp 84/01/13 2pp 21883.322
24X Fiche 50-220, 84/01/05, B401230308

--B401230318 Proposed Tech Spec Tables 3.2.7, "RCS Isolation Valves" & 3.6.2c & 4.6.2c. "Instrumentation that Initiates or Isolates Emergency Cooling"
* Niagara Mohawk Power Corp 84/01/05 9pp 21883.324 24X
Fiche 50-220, 84/01/05, B401230308

B401230335 Forwards "Program Description & Summary Rept of Detailed Control Room Design Review of TMI Unit 1 Control Room," in response to NUREG-0737, Item I D 1 & Suppl 1 & NUREG-0752 & Suppl 1, including analysis of emergency operations tasks
HUXILL, H D General Public Utilities - GPU Service Corp
3211-84-2001 84/01/16 STOLZ, J F Operating Reactors Branch 4 1p. 21875.159. 24X Fiche 50-289, 84/01/16, B401230335

B401230373 Forwards SEP evaluation completion schedules for integrated plant safety assessment repts (NUREG-0826 & NUREG-0824), in response to NRC 831006 ltr
COUNSIL, W G Connecticut Yankee Atomic Power Co SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) A03533
84/01/11 CRUTCHFIELD, D Operating Reactors Branch 5 8pp
21873.336 24X Fiche 50-000, 84/01/11, B401230373

B401230394 Submits addl info re harsh environ safety-related electrical equipment, per NRC request Info includes evaluation of FSAR Chapter 15 re DBE & NUREG-0737 & NUREG-0588 associated equipment
TAUBER, H Detroit Edison Co EFR-66,759 84/01/16
YOUNGBLOOD, B J Licensing Branch 1 37pp 21879.082 24X
Fiche 50-341, 84/01/16, B401230394

B401230418 Responds to Generic Ltr 82-33 re safety parameter display sys completion Difficulties encountered w/testing & installation of sys per Suppl 1 to NUREG-0737 Achieving
B40131 operational data doubtful
CURTIS, N W Pennsylvania Power & Light Co PLA-2024 84/01/18
SCHWENCER, A Licensing Branch 2 2pp 21877.347 24X
Fiche 50-387, 84/01/18, B401230418

B401230467 Submits revised integrated implementation schedule re Suppl 1 to NUREG-0737 requirements for emergency response capability per Generic Ltr 82-33 Control room design review final rept scheduled for 841101
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G, SEARS, C F Northeast Utilities A02959
84/01/11. YOUNGBLOOD, B J Licensing Branch 1 4pp 21877.021
24X Fiche 50-423, 84/01/11, B401230467

B401230494 Forwards "Procedures Generation Package for Seabrook Station," in response to Generic Ltr 82-33 requirements re emergency operating procedures Rev 1 to "Westinghouse Owners Group Emergency Response Guidelines," also encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J. Public Service Co of New Hampshire 0L-82-33. 84/01/17 KNIGHTON, O W
Licensing Branch 3. 3pp. 21874.005 24X Fiche 50-443, 84/01/17, B401230494

--B401230500 "Procedures Generation Package for Seabrook Station"
* Public Service Co of New Hampshire. 84/01/17 27pp.
21874.008 24X Fiche 50-443, 84/01/17, B401230494.

--B4010070199 Requests detailed description of task analyses performed to support development of Westinghouse Owners Group emergency response guidelines (ERG) & program plan for verification/validation to be performed on ERGs, Rev 1
CRUTCHFIELD, D. Operating Reactors Branch 5 0L-82-33. 83/09/12
SHEPPARD, J J Westinghouse Operating Plants Owners Group.
SHEPPARD, J J Carolina Power & Light Co. 2pp. 21874.038 24X
Fiche 50-443, 84/01/17, B401230494

--B401230520 Rev 0 to "Seabrook Station Writers Guide for Emergency Response Procedures."
* Westinghouse Operating Plants Owners Group 0L-82-33
83/10/31 277pp. 21874.242 24X Fiche 50-443, 84/01/17, B401230494

B401230552 NUREG-0340 V05 N10
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE October 1-31, 1983
* Division of Technical Information & Document Control. 83/12/31
604pp. 21903.163

B401230657 NUREG-0933
A PRIORITIZATION OF GENERIC SAFETY ISSUES
EMRIT, R, MINNERS, W, VANDER MOLEN, H Division of Safety Technology
83/12/31. 777pp. 21923.081

NONDOCKETED ITEMS

445

8401230677 NUREG/CR-1735
TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING NUCLEAR
REACTORS AT MULTIPLE-REACTOR STATIONS
WITTENBERG, N Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-2117 82/01/31 Division of Engineering
Technology 339pp Available at NRC \$11.00 21901 083

8401230690 NUREG/CR-3439 V02
A DESCRIPTION OF THE HARDWARE AND SOFTWARE OF THE POWER
SPECTRAL DENSITY RECOGNITION (PSDREC) CONTINUOUS ON-LINE
REACTOR SURVEILLANCE SYSTEM (CALIFORNIA DISTRIBUTION),
VOLUME 2
SMITH, C M Oak Ridge National Laboratory FIN B-0442
ORNL/TM-8862/V2 84/01/31 Division of Facility Operations
139pp 21900 300

8401240039 Notices of completion of review of post-accident sampling
sys (NUREG-0737, Item II B 3) Response to criterion requiring
procedure for estimating core damage extent acceptable on
interim basis Plant-specific procedure due 840831
STOLZ, J F Operating Reactors Branch 4 84/01/11 TUCKER, H B
Duke Power Co 21pp 21945 001 24X Fiche 50-269, 84/01/11,
8401240039

8401240075 Forwards IE Insp Repts 50-280/83-35 & 50-281/83-37 on
831101-30 No violations noted
DANCE, H C Division of Project & Resident Programs 83/12/21,
STEWART, W L Virginia Electric & Power Co 2pp 21913 217 24X
Fiche 50-280, 83/12/21, 8401240075

--8401240082 IE Insp Repts 50-280/83-35 & 50-281/83-37 on 831101-30 No
violations noted Major areas inspected: plant operations &
operating records, plant maint & surveillance & NUREG-0737
items
BURKE, D J, DAVIS, M J Region 2, Office of Director ELROD, S
Division of Project & Resident Programs 50-281/83-37 83/12/21
7pp 21913 217 24X Fiche 50-280, 83/12/21, 8401240075,

8401240109 Forwards IE Insp Rept 50-029/83-15 on 831024-1212 No
violations noted
STAROSTECKI, R Division of Project & Resident Programs 84/01/10
HEIDER, L H Yankee Atomic Electric Co 8pp 21913 156 24X
Fiche 50-029, 84/01/10, 8401240109

--8401240126 IE Insp Rept 50-029/83-15 on 831024-1212 No violations
noted Major areas inspected: operational safety verification
reviews, plant info rept, maint, LERS, transportation
activities & SEP action items
EICHENHOLZ, H, COLLINS, S, ELASBER, T C Region 1, Office of
Director 84/01/09 24pp 21913 158 24X Fiche 50-029, 84/01/10,
8401240109

8401240118 Informs that addl mods & heavy loads procedure revs
required, per 830122 ltr Redundant upper travel limit switch
installation on main & auxiliary hooks for turbine & fuel
bldgs & containment polar cranes completed per NUREG-0612
WITHERS, B D Portland General Electric Co 84/01/18 EISENHUT, D G
Division of Licensing 1p 21912 287 24X Fiche 50-344, 84/01/18,
8401240118

8401240138 Application to amend License NPF-12, revising Tech Specs re
combustible gas control, per Generic Ltr 83-37 Tech Specs for
reactor vessel head vent valves meet NUREG-0737, Item II.B.1
requirements
DIXON, D W South Carolina Electric & Gas Co 0L-83-37, 84/01/18,
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
21913 230 24X Fiche 50-395, 84/01/18, 8401240138

8401240162 Suggests rev to SSER 4, NUREG-0892 Backup emergency 4
operations facility (EDF) located 9.5 miles from plant
Facility should be referred to as location rather than
backup EDF
SDRENGSEN, G C Washington Public Power Supply System 002-84-31
84/01/19 SCHWENGER, A Licensing Branch 2 2pp 21910 294, 24X
Fiche 50-397, 84/01/19, 8401240162,

8401240194 Forwards DJ Vandewalle 831216 Tech Spec amend request re
stack gas monitoring sys Util no longer intends to install
gamma scintillation detector for continuous sampling
suggested in NUREG-0737, Item II F 1
GALLO, J J, Isham, Lincoln & Seale GALLO, J Consumers Power Co
84/01/20, BLOCH, P B, PARIS, O H, SHON, F J Atomic Safety and
Licensing Board Panel 11pp 21910 304 24X Fiche 50-155, 84/01/20,
8401240194,

8401240195 Forwards response to NRC 831130 request for addl info re
NUREG-0737, Item II B.3 concerning post-accident sampling
sys Boron analysis will be performed per Procedure PASAP 3 4
using carminic acid analysis method
MC GAUGHY, R W Iowa Electric Light & Power Co NQ-84-0138,
84/01/19, DENTON, H, Office of Nuclear Reactor Regulation, Director
6pp 21910 325, 24X Fiche 50-331, 84/01/19, 8401240196,

8401240314 Forwards IE Insp Repts 50-282/83-19 & 50-306/83-20 on
831011-1210 & notices of violation & deviation
SHAFER, W D Region 3, Office of Director 84/01/06 LARSON, C E
Northern States Power Co 2pp 21932 178 24X
Fiche 50-282, 84/01/06, 8401240314

--8401240332 IE Insp Repts 50-282/83-19 & 50-306/83-20 on 831011-1210
Noncompliance noted Failure to provide required changes to
procedures Deviation noted failure to perform committed test
re IE bulletin
FEIERABEND, C D, HARD, J E, HARTMANN, P L Region 3, Office of
Director 50-306/83-20, 84/01/06 12pp 21932 182 24X
Fiche 50-282, 84/01/06, 8401240314

8401240397 Forwards safety evaluation of util 830301, 0812 & 1204
responses to NUREG-0737, Item II.B 3 re post-accident
sampling sys Nine of 11 criteria met Open items should be
addressed within 45 days
CRUTCHFIELD, D Operating Reactors Branch 5 1905-84-01-031,
84/01/23 VANDEWALLE, D J Consumers Power Co 39pp 21920 154
24X Fiche 50-255, 84/01/23, 8401240397

8401240456 Forwards mailed-up proposed Tech Spec, replacing certain time
frames w/annotation "later" in several specs & Rev 0 to
"Offsite Dose Calculation Manual"
DALTROFF, S L Philadelphia Electric Co 84/01/19 SCHWENGER, A
Licensing Branch 2 645pp 21913 253 24X Fiche 50-352, 84/01/19,
8401240456

8401240466 Forwards IE Insp Rept 50-029/83-13 on 831024-27 No
violations noted.
MARTIN, T T Division of Engineering & Technical Programs 84/01/10
HEIDER, L H Yankee Atomic Electric Co 2pp 21908 177 24X
Fiche 50-029, 84/01/10, 8401240466

--8401240476 IE Insp Rept 50-029/83-13 on 831024-27, No violations noted
Major areas inspected: emergency preparedness items from
appraisal performed 811201-09 & prompt public notification
sys ins performed 830503-04
TERC, N M, COHEN, I, CROCKER, H W Region 1, Office of Director
83/12/12 12pp 21908 179 24X Fiche 50-029, 84/01/10, 8401240466

8401240562 Ack receipt of 831222 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-302/83-23.
LEWIS, R C Division of Project & Resident Programs 84/01/09,
WILGUS, W B Florida Power Corp 1p 21909 080 24X
Fiche 50-302, 84/01/09, 8401240562

--8401240589 IE Insp Rept 50-302/83-23 on 830730-0830, Noncompliance
noted failure to meet intent of NUREG-0737, Item I C.6 re
independent verification of sys & components
STETKA, T F Region 2, Office of Director PANCIERA, V, Division
of Project & Resident Programs 83/11/02, 6pp 21909 088, 24X
Fiche 50-302, 84/01/09, 8401240562

8401250015 Partial response to FOIA request for all 1982 BECY papers.
Forwards A documents Remaining documents under review.
FELTON, J M Division of Rules and Records 83/10/18 WEISS, E R
Union of Concerned Scientists 3pp 21960 005 24X
Fiche 50-000, 83/10/18, 8401250015

--8401250385 BECY-82-804
Informs Commission of progress & plans for improving state
capabilities to do need-for-power evaluations
DIRCKS, W J Office of the Executive Director for Operations
82/12/30, 5pp 21967 225

--8206110014 BECY-82-219
Informs of status of util ability to provide addl senior
reactor operator on shift by 820701 per requirements of
TMI Item I.A.1.3: "Shift Manning Requirements"
DIRCKS, W J, Office of the Executive Director for Operations
82/06/01, 6pp 21964 235 24X Fiche 50-000, 83/10/18, 8401250015,

--8208230483 BECY-82-333
Advises of issuance of NUREG-0661, Suppl 1, "Mark I
Containment Long-Term Program Safety Evaluation Rept"
NUREG-0661, Suppl 1 & draft notice of availability encl.
DIRCKS, W J Office of the Executive Director for Operations.
82/08/09, 24pp 21965 325

--8206110014 BECY-82-219
Informs of status of util ability to provide addl senior
reactor operator on shift by 820701 per requirements of
TMI Item I.A.1.3: "Shift Manning Requirements."
DIRCKS, W J, Office of the Executive Director for Operations.
82/06/01, 6pp 21964 235, 24X Fiche 50-000, 83/10/18, 8401250015,

NONDOCKETED ITEMS

--B210270322 SECY-B2-407

Advises of issues remaining from B20108 meeting re instrumentation for detection of inadequate core cooling in PWRs. Requests action on update recommendations for implementation of NUREG-0737, Item II F.2
DIRCKS, W. J. Office of the Executive Director for Operations
B2/10/07. 97pp. 21966 303

--B301070135 SECY-B2-498

Recommends withdrawal of proposed rule to codify NUREG-0737 requirements for OL applicants, per encl draft FR notice
DIRCKS, W. J. Office of the Executive Director for Operations
B2/12/27 Bpp. 21967 206

--B211090006 SECY-B2-432

Inform of issuance of NUREG-0744, Vols I & II, Rev 1, "Resolution of Task A-11, Reactor Vessel Matix Toughness Safety Issue"
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/10/22 2pp. 21967 111

--B205050587 SECY-B2-161

Inform of issuance of draft rept (NUREG-0820) on SEP integrated plant safety assessment W/o encl NUREG-0820
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/04/15. 2pp. 21963 171 24X Fiche 50-000, B3/10/18, B401250015

--B401250325 SECY-B2-378

Inform of results of facility SEP integrated safety assessment.
DIRCKS, W. J. Office of the Executive Director for Operations
B2/09/15 58pp. 21966 129 24X Fiche 50-000, B3/10/18, B401250015

--B211020259 SECY-B2-403

Inform Commission of results of SEP integrated safety assessment.
DIRCKS, W. J. Office of the Executive Director for Operations
B2/10/01. 115pp. 21966 272 24X Fiche. 50-000, B3/10/18, B401250015.

--B203110330 SECY-B2-066

Forwards NUREG-0886, "Steam Generator Tube Experience."
DIRCKS, W. J. Office of the Executive Director for Operations
B2/02/12. 68pp. 21960 167

--B401250385 SECY-B2-504

Inform Commission of progress & plans for improving state capabilities to do need-for-power evaluations
DIRCKS, W. J. Office of the Executive Director for Operations
B2/12/30 5pp. 21967 225

--B205050087 SECY-B2-092A

Forwards final rept, "Summary Rept-Workshop on Psychological Stress Associated W/Proposed Restart of TMI-1,"
NUREG/CP-0026.
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/04/14 151pp. 21961 287 24X Fiche. 50-000, B3/10/18, B401250015

--B209230146 SECY-B2-349

Inform Commission of issuance of NUREG/CR-2837, "BMNL Technical Review of Pressurized Thermal Shock Issues."
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/08/20 1p. 21966 034

/401250028 Application for amend to Licenses DPR-58 & DPR-74, revising Tech Specs re RCS Vents, per NUREG-0737, Item II B 1. Proposed specs modeled as suggested in Generic Ltr B3-37
ALEXICH, M. P. Indiana & Michigan Electric Co. AEP NRC 05848.
B4/01/20. BENTON, H. R. Office of Nuclear Reactor Regulation.
Director 2pp. 21935 227. 24X Fiche 50-315, B4/01/20, B401250028.

B401250040 Inform of completed review of BWR Owners Group B01230 responses to NUREG-0737, Item II, K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Alternative modes of depressurization would not contribute to safety.
CRUTCHFIELD, D. Operating Reactors Branch 3. LB05-B4-01-032
B4/04/23 FARRAR, D. L. Commonwealth Edison Co 6pp. 21933 240.
24X Fiche 50-237, B4/01/23, B401250040.

B401250084 Forwards description of offsite protective action decision process & activation of technical support ctr & satellite technical support ctr, per request.
VAN BRUNT, E. E. Arizona Public Service Co. ANPP-28653-ACR/
B4/01/20. KNIGHTON, C. Licensing Branch 3. 4pp. 21940 225 24X Fiche. 50-528, B4/01/20, B401250084

B401250125 NUREG/CP-0048 V05
PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING.
SZAWLEWICZ, S. A. Brawlewicz, S. A. B4/01/31 206pp. Available at NRC. \$4.50. 21950 046.

B401250129 NUREG/CR-3615

HYDRODYNAMICS OF TWO PHASE FLOW THROUGH HOMOGENEOUS AND STRATIFIED POROUS LAYERS
CHU, W., LEE, H., DHIR, V. K. California, Univ of, Los Angeles, CA
B4/01/31 Division of Accident Evaluation (Pre B40101) 158pp
Available at NRC \$5.50 21947 251

B401250134 NUREG/CR-3577

THE MEASUREMENT OF COUNTERCURRENT PHASE SEPARATION AND DISTRIBUTION IN A TWO-DIMENSIONAL TEST SECTION
BUKHARI, M., LAHEY, R. T. Rensselaer Polytechnic Institute, Troy, NY
FIN B-7272 B4/01/31 Division of Accident Evaluation (Pre B40101) 220pp Available at NRC \$6.50 21949 028

B401250160 NUREG-1033

DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF WPPSS NUCLEAR PROJECT NO. 3 Docket No. 50-508 (Washington Public Power Supply System)
* Division of Licensing B3/12/31 191pp Available at NRC \$6.00 21951 249 24X Fiche 50-508, B3/12/31, B401250160

B401250162 NUREG/CP-0048 V05

PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING
SZAWLEWICZ, S. A. Brawlewicz, S. A. B4/01/31 353pp Available at NRC \$8.00 21950 254

B401250163 Further response to FOIA request for documents re emergency

operation facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON, J. M. Division of Rules and Records B3/11/02. O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge App 21957 357 24X Fiche 50-000, B3/11/02, B401250163

--B202020366 Forwards Central Files version of layout of interim

emergency operations & backup facilities Communications & dose assessment capabilities for backup facility listed
MAURIN, L. V. Louisiana Power & Light Co W3P82-022B B2/01/28
TEDESCO, R. L. Assistant Director for Licensing 12pp. 21958 241
24X Fiche 50-000, B3/11/02, B401250163

--B401250283 Submits responses to questions raised re I-131 airborne

releases during plant accident Estimates of releases use actual effluent radiation readings & sample analyses during emergency conditions
DIRCKS, W. Office of the Executive Director for Operations
B1/01/28. BRADFORD, P. Commissioners 3pp. 21958 325 24X Fiche 50-000, B3/11/02, B401250163

--B202120297 Discusses SECY-B1-509 & NUREG-0696 re criteria for emergency

operations facilities Recommends Commission approve NRC request to accept close in hardened emergency operations facilities
REMICK, F. J. NRC - No Detailed Affiliation Given B1/08/08
PALLADINO, N. J. Commissioners 2pp. 21958 316

--B306280032 Requests to be advised of date & time Commissioners will

consider B20406 request to relocate emergency operations facility at corporate headquarters beyond guideline distance contained in NUREG-0696
FAY, C. W. Wisconsin Electric Power Co B3/03/30 CHILK, S. J. Office of the Secretary of the Commission 1p. 21958 289 24X Fiche 50-000, B3/11/02, B401250163

--B401250241 SECY-B2-390

Recommends approval of request for exception under requirements & conditions of COMJA-B0-35 & SECY-B2-111 for location of emergency operations facility
DIRCKS, W. J. Office of the Executive Director for Operations
COMJA-B0-35 B2/09/21 10pp. 21958 293. 24X Fiche 50-000, B3/11/02, B401250163

--B301060498 Discusses status of implementation of emergency operation

facilities in response to Secretary B21126 memo re possible vote on full power OL Supporting documentation encl.
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/12/27 PALLADINO, N. Commissioners 7pp. 21958 305. 24X Fiche 50-000, B3/11/02, B401250163.

--B306020457 SECY-B3-199

Requests Commission review NRC disapproval of primary emergency operations facility w/no habitability features.
DIRCKS, W. J. Office of the Executive Director for Operations
B3/03/20 7pp. 21958 183. 24X Fiche: 50-000, B3/11/02, B401250163

--B306030153 SECY-B3-192

Recommends Commission concurrence w/approval for exception to location of backup emergency operations facility beyond 20 miles for Maine Yankee Atomic power plant
DIRCKS, W. J. Office of the Executive Director for Operations
B3/03/19 5pp. 21958 167 24X Fiche. 50-000, B3/11/02, B401250163

NONDOCKETED ITEMS

447

--B306030404 SECY-83-191
Requests Commission review approval for exception to location of backup emergency operations facility beyond 20 miles from plant
DIRCKS, W J Office of the Executive Director for Operations
OL-82-33 83/05/18 8pp 21958 105 24X Fiche 50-000, 83/11/02, 8401250163

--B306150117 SECY-83-223
Requests Commission review & disapprove divided emergency operations facility (EOF) concept for facilities
DIRCKS, W J Office of the Executive Director for Operations
83/06/07 7pp 21958 253 24X Fiche 50-000, 83/11/02, 8401250163

--B306210319 SECY-83-205
Requests Commission review of staff approval for exception to location of backup emergency operations facility beyond 20-mile limit
DIRCKS, W J Office of the Executive Director for Operations.
83/05/26 8pp 21958 232 24X Fiche 50-000, 83/11/02, 8401250163

--B401250281 Advises that Commission approved proposed policy statement, Suppl 1 to NUREG-0737 & draft 50 54(F) 1tr re SECY-82-111B, "Requirements for Emergency Response Capability," subj to listed mods Marked-up policy statement encl.
CHILK, S J Office of the Secretary of the Commission. 82/11/22
DIRCKS, W J Office of the Executive Director for Operations. 8pp 21958 319

8401250234 Forwards procedures generation package per NUREG-0737, Suppl 1, Section 7 Encl withheld (ref 10CFR2 790)
DALTROFF, B L Philadelphia Electric Co GOVT 1-1(NRC) 84/01/19
SCHWENGER, A Licensing Branch 2 5pp 21941 337, 24X
Fiche 50-352, 84/01/19, 8401250234

8401250388 Reviews scheduling info for detailed description of conformance to Reg Guide 1.87, Rev 2 re emergency response capability, submitted in response to Generic Ltr B2-33 Util provided explicit commitment except for items in encl
SCHWENGER, A Licensing Branch 2 OL-82-33 83/12/30 CURTIS, N W Pennsylvania Power & Light Co 2pp 21948 016 24X
Fiche 50-387, 83/12/30, 8401250388

--B312230302 "Conformance to Reg Guide 1.97, Susquehanna Steam Electric Station, Units 1 & 2"
UDY, A C. EQ&O, Inc FIN A-6483 83/09/30 NRC - No Detailed Affiliation Given 11pp 21948 018 24X Fiche 50-387, 83/12/30, 8401250388.

8401250394 Requests comments on working draft NUREG-1070, "Severe Accident Program for Nuclear Power Plant Regulation"
Comments requested by 840124
MATTHEW, R Division of Systems Integration (post 811005). 84/01/10
EISENHUT, D O Division of Licensing SPEIS, T Division of Safety Technology THOMPSON, H Division of Human Factors Safety 72pp, 21952 080

8401250486 Forwards 88ER 21 (NUREG-0675) Suppl provides info on status of staff review of allegations & concerns about design, const & operation W/o encl
KNIGHTON, O W Licensing Branch 3 84/01/11 SCHUYLER, J D Pacific Gas & Electric Co 4pp 21948 347, 24X Fiche 50-275, 84/01/11, 8401250486

8401250520 Notifies that THI Action Items II K 3 30 & II K.3.31 re GE small break LOCA model complete Adequacy of core cooling w/ spray distribution utilizing existing chargers currently under review
VASSALLO, D Operating Reactors Branch 1 84/01/04 RHODE, O K Niagara Mohawk Power Corp 2pp 21948 338 24X
Fiche 50-220, 84/01/04, 8401250520

8401260013 Forwards safety evaluation of util 831230 response to SEP Topic VI-7 C 1, "Electrical Instrumentation & Control Rereview," in NUREG-0823, Section 4 21 Adequate relay coordination exists
CRUTCHFIELD, D Operating Reactors Branch 5 LB05-84-01-035, 84/01/24 FARRAR, D Commonwealth Edison Co 5pp 21956 294, 24X
Fiche 50-237, 84/01/24, 8401260013

8401260061 NUREG-0974 S01
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF LINERICK GENERATING STATION, UNITS 1 AND 2 Docket Nos. 50-352 And 50-353 (Philadelphia Electric Company)
* Division of Licensing 83/12/31, 157pp 21990 001 24X
Fiche 50-352, 83/12/31, 8401260061

8401260068 NUREG-1060
ANSWERS TO QUESTIONS ABOUT UPDATED ESTIMATES OF OCCUPATIONAL RADIATION DOSES AT THREE MILE ISLAND, UNIT 2, Docket No 50-320.
* THI Program Office 83/12/31 21pp 21971 263 24X
Fiche 50-320, 83/12/31, 8401260068

8401260071 NUREG-0675 S20
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-320 (Pacific Gas And Electric Company)
* Division of Licensing 83/12/31 50pp 21971 198 24X
Fiche 50-275, 83/12/31, 8401260071

8401260079 NUREG/CR-2325
THE TRANSPORTATION OF RADIOACTIVE MATERIAL (RAM) TO AND FROM U S NUCLEAR POWER PLANTS (Draft Environmental Assessment)
FINLEY, N C ; LUNA, R E. ; MADSEN, M M Sandia Laboratories FIN A-1087 SAND81-0118 83/12/31 Division of Risk Analysis, 100pp Available at NRC *6 00 21989 018

8401260096 NUREG/CP-0048 V03
PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING
SZALEWICZ, S A Szalewicz, S A 84/01/31 705pp, 21986 001

8401260097 NUREG/CP-0048 V02
PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING
SZALEWICZ, S A Szalewicz, S A 84/01/31 370pp, 21988 001

8401260101 NUREG/CR-3525
MECHANISTIC CORE-WIDE MELTDOWN AND RELOCATION MODELING FOR BWR APPLICATIONS
PADOWSKI, M Z ; TALEYARKHAN, R ; LAHY, R T Oak Ridge National Laboratory, FIN B-0452 ORNL/SUB/81-908. 84/01/31, Division of Accident Evaluation (Pre 840101). 75pp, 21971 085.

8401260105 NUREG/CR-3578
STEAM GENERATOR GROUP PROJECT PROGRESS REPORT, Task 3- Health Physics
REECE, W D. ; HOENES, O R ; PARKHURST, M A Battelle Memorial Institute, Pacific Northwest Laboratory FIN-0209. PNL-4711 84/01/31 Division of Engineering Technology. 33pp, 21969 288

8401260108 NUREG/CP-0048 V04
PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY RESEARCH INFORMATION MEETING
SZALEWICZ, S A Szalewicz, S A 84/01/31 470pp, 21969 327.

8401260119 NUREG-0748 V03 N11
OPERATING REACTORS LICENSING ACTIONS SUMMARY, Data As Of November 30, 1983, (Orange Book)
* Division of Data Automation & Management Information 84/01/31, 336pp 21968 912.

8401260192 Forwards addl info re performance testing of relief & safety valves per NUREG-0737, Item II D.1, "Relief & Safety Valves."
SCHUYLER, J D Pacific Gas & Electric Co DCL-84-027, 84/01/23
KNIGHTON, O W Licensing Branch 3, 16pp 21956 167 24X
Fiche 50-275, 84/01/23, 8401260192

8401260246 Forwards Amend 63 to License DPR-71 & safety evaluation. Amend deletes requirements for seismic snubbers on removed control rod drive return line piping
ORDENHUIS, M Operating Reactors Branch 2, 83/12/28, UTLEY, E. E. Carolina Power & Light Co 2pp 21992 075, 24X
Fiche 50-325, 83/12/28, 8401260246

--B401260261 Safety evaluation supporting Amend 63 to License DPR-71
* Office of Nuclear Reactor Regulations Director, 83/12/28, 4pp 21992 093 24X Fiche 50-325, 83/12/28, 8401260246.

8401260420 Forwards 88ER re automatic switchover of RCIC sys. Switchover design now in place satisfies requirements of NUREG-0737, Item II K.3.22 Item complete.
VASSALLO, D B Operating Reactors Branch 2 83/12/29 FARRAR, D L Commonwealth Edison Co 8pp, 21959 317 24X Fiche 50-254, 83/12/29, 8401260420.

8401260509 Forwards in-progress 830726-28 audit of detailed control room design review, per NUREG-0737, Suppl 1, Requirements satisfied except in sys function & task analysis areas & comparison of analysis results w/control room inventory.
KNIGHTON, O W Licensing Branch 3 84/01/12 HARRISON, R J. Public Service Co of New Hampshire 8pp 21959 166, 24X
Fiche 50-443, 84/01/12, 8401260509

--B401260511 "Human Factors Engineering In-Progress Audit of Detailed Control Room Design Review for Public Svc of NH."
* Human Factors Engineering Branch, 84/01/04, 55pp, 21959 169, 24X Fiche 50-443, 84/01/12, 8401260509

8401270146 NUREG-0837 V03 N02
NRC TLD DIRECT RADIATION MONITORING NETWORK Progress Report, April-June 1983.
CORTELLI, F ; THOMPSON, Y ; COHEN, L. Region 1, Office of Director, 83/12/31 137pp 22001 001.

NONDOCKETED ITEMS

- 8401270161 Discusses exploratory shaft const & sealing issues in connection w/salt repository program NUREG/CR-2854, "Evaluation of Alternative Shaft Sinking Technologies for High Level Waste Deep Geologic Repositories" encl W/c NUREG, CHASE, L. Division of Waste Management 00085 83/06/13 NEFF, J O Energy, Dept of 7pp 22002 302.
- 8401270222 Forwards application for amend to License DPR-59, changing Tech Specs to permit isolation of containment atmosphere monitoring sys during operation of post-accident sampling sys
BAYNE, J.P. Power Authority of the State of New York JPN-84-04 84/01/23 VASSALLO, D B Operating Reactors Branch 2 2pp 21973 343 24X Fiche 50-333, 84/01/23, 8401270222.
- 8401270227 Proposed Tech Spec changes re isolation of containment atmosphere monitoring sys during operation of post-accident sampling sys
* Power Authority of the State of New York. 84/01/23 5pp 21973:346 24X Fiche. 50-333, 84/01/23, 8401270222
- 8401270245 Forwards response to Core Performance Branch draft SER open items re post-irradiation monitoring program & inadequate core cooling (NUREG-0737, Item II, F. 2) Indicated responses will be included in future FSAR amend
BOOKER, J.E. Gulf States Utilities Co RB0-16, 829 84/01/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 6pp 21982.141 24X Fiche: 50-458, 84/01/20, 8401270245.
- 8401270254 Responds to open item in SER Section 13.5 1.3 re NUREG-0737, Item I A 1.1, "Shift Technical Advisor." On-shift staff will include shift engineer, fulfilling THI item requirements.
Revised FSAR pages encl
TUCKER, H.B. Duke Power Co 84/01/24 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAH, E O Licensing Branch 4. 10pp 21982.184. 24X Fiche. 50-413, 84/01/24, 8401270254
- 8401270275 Interim Deficiency Rept SDAR-124 re installation of chlorine sensors not conforming to ODC 4.5 & 19, FSAR commitments to Reg Guides 1.78 & 1.95 & NUREG-0737, Item III D 3.4 Sensor relocated & mods to provide adequate calibr instituted
GARY, R.J. Texas Utilities Generating Co SDAR-124 84/01/18 JOHNSON, E.H. Region 4, Office of Director 3pp 21976 007. 24X Fiche: 50-445, 84/01/18, 8401270275
- 8401270302 Forwards "Evacuation Time Analysis, 10-Mile Emergency Planning Zone," per BSR 5 (NUREG-0857) & util 831223 ltr.
VAN BRUNT, E.E. Arizona Public Service Co ANPP-28685-WF0/ 84/01/24. KNIGHTON, G. Licensing Branch 3 2pp. 21975.255 24X Fiche: 50-528, 84/01/24, 8401270302
- 8401270325 Confirms that stack gas monitoring sys declared operable on 831223, NUREG-0737, Items II F 1.1 & II F 1.2 complete
No further action required.
KRICH, R.M. Consumers Power Co 84/01/24. CRUTCHFIELD, D Operating Reactors Branch 5 1p. 21976 315 24X Fiche: 50-155, 84/01/24, 8401270325.
- 8401270336 Forwards LER 83-024/OIT-O & evaluation of SEP Topic IX-3, "Station Svc & Cooling Water Sys"
ORAVES, R.H. Connecticut Yankee Atomic Power Co. 84/01/02. MURLEY, T.E. Region 1, Office of Director 1p. 21981 220 24X Fiche. 50-213, 84/01/02, 8401270336.
- 8401270363 Forwards Amend 36 to FSAR, consisting of responses to NUREG-0737, Item II, E 4.2, revised responses to NRC questions & miscellaneous FSAR test revs & editorial changes.
GOLDBERG, J.H. Houston Lighting & Power Co ST-HL-AE-1036 84/01/25 DENTON, H. Office of Nuclear Reactor Regulation, Director 4pp. 21983.001. 24X Fiche 50-498, 84/01/25, 8401270363
- 8401270376 Forwards "Leakage Reduction Program Test Results," demonstrating licensee compliance w/requirements of NUREG-0737, Item III, D 1.1, Procedure requiring sys walkdown written.
MEDFORD, M.O. Southern California Edison Co 84/01/25. KNIGHTON, G.W. Licensing Branch 3. 2pp 21976.022 24X Fiche: 50-362, 84/01/25, 8401270376.
- 8401270381 "Leakage Reduction Program Test Results,"
* Southern California Edison Co. 84/01/25. 15pp 21976.024. 24X Fiche: 50-362, 84/01/25, 8401270376
- 8401270427 NUREG-0647
SAFETY EVALUATION AND ENVIRONMENTAL ASSESSMENT, THREE MILE ISLAND NUCLEAR STATION, UNIT NO 2, Docket No. 50-320 (Metropolitan Edison Company, Jersey Central Power And Light Company And Pennsylvania Electric Company)
* Office of Nuclear Reactor Regulation, Director. 80/02/28. 24pp. 22002:246 24X Fiche: 50-320, 80/02/28, 8401270427.
- 8401270428 NUREG-0775
FINAL ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF COMANCHE PEAK STEAM ELECTRIC STATION, UNIT NOS 1 AND 2
Docket Nos 50-443 And 50-446 (Texas Utilities Generating Company)
* Office of Nuclear Reactor Regulation, Director. 81/09/30 160pp 22001 143 24X Fiche 50-445, 81/09/30, 8401270428
- 8401270440 Informs of delayed installation of mod to post-accident sampling sys, per NUREG-0737, Item II B 3.2, due to postponed equipment delivery Delay not in violation of 830314 confirmatory order
BAYNE, J.P. Power Authority of the State of New York JPN-83-102 83/12/27 VASSALLO, D B Operating Reactors Branch 2 2pp 21980 239 24X Fiche 50-333, 83/12/27, 8401270440
- 8401270461 Forwards IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance noted.
SHAFER, W.D. Region 3, Office of Director 84/01/16 LIU, L Iowa Electric Light & Power Co 2pp. 21980 279. 24X Fiche 50-331, 84/01/16, 8401270461
- 8401270469 IE Insp Rept 50-331/83-17 on 831101-1230 No noncompliance of deviations identified, Major areas inspected licensee actions on previous insp findings, operational safety, maint, surveillance, plant trips & IE bulletins & circulars.
CLARDY, L.B. Region 3, Office of Director IEB-80-06 84/01/16 12pp 21980 281 24X Fiche 50-331, 84/01/16, 8401270461
- 8401270474 Responds to request for commitments for plant mods & revs to Tech Specs transmitted in NRC evaluation of containment vent & purge issue, per NUREG-0737, Item II E 4.2
DALTROFF, S.L. Philadelphia Electric Co 84/01/25 STOLZ, J.F. Operating Reactors Branch 4 5pp 21981 302 24X Fiche 50-277, 84/01/25, 8401270474
- 8401270513 Forwards DES (NUREG-1033) & FR notice of availability, w/o encls
KNIGHTON, G.W. Licensing Branch 3 84/01/13 MAZUR, D.W. Washington Public Power Supply System 2pp 22002 203 24X Fiche 50-508, 84/01/13, 8401270513
- 8401270515 NUREG/BR-0025 V10 N1
INFORMATION REPORT ON STATE LEGISLATION.
* Office of State Programs, Director 84/01/01. 6pp 22002:192
- 8401300001 Forwards staff comments on detailed control room design review program plan submitted per Suppl 1 to NUREG-0737. Schedule for response to comments requested by 840131
KNIGHTON, G.W. Licensing Branch 3 84/01/10. VAN BRUNT, E.E. Arizona Public Service Co. 9pp. 22027.321 24X Fiche. 50-528, 84/01/10, 8401300001
- 8401300018 NUREG/CR-3502
HIGH DRYOUT QUALITY FILM BOILING AND STEAM COOLING HEAT TRANSFER DATA FROM A ROD BUNDLE
YODER, G.L., ANKLAN, T.M., MORRIS, D.O. Oak Ridge National Laboratory FIN B-0463 ORNL/TM-8794 84/01/31. Division of Accident Evaluation (Pre 840101). 84pp. 22027:334
- 8401300021 Forwards SER re util responses to NUREG-0737, Item II K 2.17, "Potential for Voiding in RCB during Transients," Voids generated in RCB during anticipated transients accounted for in present analysis models.
VARGA, S.A. Operating Reactors Branch 1 IEB-79-06A 84/01/10 CLAYTON, F.L. Alabama Power Co 10pp. 22027:306 24X Fiche: 50-348, 84/01/10, 8401300021
- 8401300030 Forwards "App B, Comparison of Special Lifting Device Design to ANSI N14 6-1978," per 830729 response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants."
BECKHAM, J.T. Georgia Power Co NED 84-019 84/01/23. STOLZ, J.F. Operating Reactors Branch 4 15pp. 21997 248 24X Fiche: 50-321, 84/01/23, 8401300030.
- 8401300062 Confirms completion of pipeline mounted equipment g value comparison program, in response to BSR 4, Section 3.10.1 & operator licensing Item 2 C(5)(b). Uncompleted plant mods scheduled for completion prior to exceeding 5% power
SORENSEN, G.C. Washington Public Power Supply System 602-84-034 84/01/23. SCHWENCER, A. Licensing Branch 2. 1p 21997.157 24X Fiche. 50-397, 84/01/23, 8401300062.
- 8401300075 Informs that based on review of environ qualification files, equipment listed in App 3-B of SER (NUREG-0892) qualified for interim operations per 830916 & 1205 submittals
SORENSEN, G.C. Washington Public Power Supply System 602-84-028 84/01/18. SCHWENCER, A. Licensing Branch 4 2pp. 21997.164 24X Fiche: 50-397, 84/01/18, 8401300075.

NONDOCKETED ITEMS

449

B401300178 Extends completion date for implementation of emergency operating procedures to 840115 per Generic Ltr 82-33 (NUREG-0737, Suppl 1)
STEWART, W L Virginia Electric & Power Co 039 84/01/20
DENTON, H R Office of Nuclear Reactor Regulation, Director
MILLER, J R Operating Reactors Branch 3 2pp 21997 357 24X
Fiche 50-338, 84/01/20, 8401300178

B401300186 Advises that response to Generic Ltr 83-37 re Tech Spec changes for 11 NUREG-0737 items will not be completed until 840319, due to lengthy Unit 2 outage
MARSHALL, J R Arkansas Power & Light Co 01-83-37, 84/01/23
STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 21997 345 24X Fiche 50-313, 84/01/23, 8401300186

B401300250 Forwards responses to 820315 request for addl info, Items 5, 6(b) & 7 re control of heavy loads Ltr completes response to all NRC questions
O'TOOLE, J D Consolidated Edison Co of New York, Inc 84/01/20, 21pp 21995 209 24X
VARGAS, S A Operating Reactors Branch 1 21pp 21995 209 24X
Fiche 50-247, 84/01/20, 8401300250

B401300317 Forwards addl response to Generic Ltr 83-28, describing post-trip review program & providing procedure to meet ltr requirements
KAY, J A Yankee Atomic Electric Co 01-83-28, 84/01/13
CRUTCHFIELD, D Operating Reactors Branch 3 5pp 21995 106, 24X
Fiche 50-029, 84/01/13, 8401300317

B401310017 Forwards request for exemption to install high-range noble gas monitors on auxiliary bldg vent as required by NUREG-0737, Item II F 1 Provisions for Initiating Isolation & measuring release meet intent of NUREG-0737
MILLS, L M Tennessee Valley Authority 84/01/24 ADENBAM, E Licensing Branch 4 8pp 22024 037 24X Fiche 50-390, 84/01/24, 8401310017

B401310047 Forwards safety evaluations confirming satisfactory resolution of Generic Item 8-24 issues & NUREG-0737, Item II E 4 2 re containment vent & purging & valve operability Tech Specs proposed in 1983, ltrs to be handled separately
STOLZ, J F, Operating Reactors Branch 4 84/01/16 BECKHAM, J T Georgia Power Co 3pp 22032 342 24X Fiche 50-321, 84/01/16, 8401310047

B401310066 Forwards draft NUREG-1070, "Severe Accident Program for Nuclear Power Plant Regulation" Draft will be discussed at ACRS subcommittee 840127 meeting Comments requested by 840124 W/a encl
EISENHUT, D G Division of Licensing 84/01/13 SHERWOOD, G G General Electric Co 2pp 22026 360

B401310078 Forwards corrected transmittal ltr & safety evaluation of util response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re accident monitoring instrumentation
STOLZ, J F Operating Reactors Branch 4 84/01/18 WILGUS, W B Florida Power Corp. 1p 22029 347 24X Fiche 50-302, 84/01/18, 8401310078

--8401310082 Forwards safety evaluation of util 821018 response to NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 re accident monitoring instrumentation Requirements of NUREG items met
STOLZ, J F, Operating Reactors Branch 4 84/01/18 WILGUS, W B Florida Power Corp 10pp 22029 349 24X Fiche 50-302, 84/01/18, 8401310078

B401310123 Forwards description of current criteria for meeting NUREG-0737, Item II B 3, "Post-Accident Sampling Capability" Schedule for completing remaining tasks encl Extension until 840801 requested to complete item
GUICH, L T Georgia Power Co NED-84-038, 84/01/26 STOLZ, J F Operating Reactors Branch 4 21pp 22022, 040 24X
Fiche 50-321, 84/01/26, 8401310123

B401310141 Forwards abnormal transient operating guidelines procedures generation package, in response to Generic Ltr 82-33, Package includes addl info requested by NRC at 840106 meeting re implementation of NUREG-0737, Item I C 1.
KUKILL, H D General Public Utilities - QPU Service Corp. 84/01/26, STOLZ, J F, Operating Reactors Branch 4, 3pp 22022, 129, 24X Fiche 50-289, 84/01/26, 8401310141

B401310150 NUREG/CP-0048 V01
PROCEEDINGS OF THE ELEVENTH WATER REACTOR SAFETY INFORMATION MEETING.
BAMENICZ, B A Commerce, Dept. of, National Technical Information Services 84/01/31 Office of Nuclear Regulatory Research, Director. 721pp. Available at NRC #12 00 22030-001

B401310237 Advises that core damage estimate methodology will be completed by 850131, per NUREG-0737, Item II B 3 "Post-Accident Sampling Sys" Estimate used for informational purposes only
MARSHALL, J R Arkansas Power & Light Co 01CAN018418 84/01/24
STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 1p 22021 159 24X Fiche 50-313, 84/01/24, 8401310237

B401310275 Forwards "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3," per 830415 commitment re Suppl 1 to NUREG-0737
WILLIAMS, J W Florida Power & Light Co. L-84-20 84/01/26
EISENHUT, D G Division of Licensing 1p 22018 125 24X
Fiche 50-250, 84/01/26, 8401310275

B401310309 Application to amend License NPF-5, supporting mods associated w/installation of GE analog transmitter trip sys Encl proprietary Rev 1 to NEDE-22154-1, "Analog Trip Sys for Engineered Safeguards Sensor Trip Inputs," withheld
BECKHAM, J T Georgia Power Co NED-84-017 84/01/23 STOLZ, J F Operating Reactors Branch 4 3pp 22021, 001 24X
Fiche 50-321, 84/01/23, 8401310309

B401310325 Forwards description of various actions & procedural requirements used to implement commitment re scheduled maint program to monitor leakage & reduce detected leakage outside containment, per SER & NUREG-0737, Item III D 1 1
COOK, K W Louisiana Power & Light Co W3PB3-3894 84/01/26
KNIGHTON, G W Licensing Branch 3 5pp 22020 329, 24X
Fiche: 50-382, 84/01/26, 8401310325

B401310351 Application for amend to License DPR-54, in partial response to Generic Ltr 83-37 & requirements of NUREG-0737, Items II E 1, II F 1, II F 2 & III D 3 4 concerning control room habitability requirements
RODRIGUEZ, R J Sacramento Municipal Utility District RJR 84-04 84/01/23, EISENHUT, D G Division of Licensing 2pp. 22026 244 24X Fiche 50-312, 84/01/23, 8401310351

--B401310355 Proposed Tech Specs re Generic Ltr 83-37, including both new limiting conditions for operation & new surveillance requirements per THI Action Items II F 1, "Noble Gas Effluent Monitors" & II F 2, "Subcooling Margin Monitor," * Sacramento Municipal Utility District 01-83-37, 84/01/23 5pp 22026 246 24X Fiche 50-312, 84/01/23, 8401310351

B401310359 Endorses BWR Owners Group "Response to NRC Request for Addl Info on Scram Discharge Piping," Equipment qualification for NUREG-0803 not required, based on listed average dose levels for scram discharge vol over plant life
CURTIS, N W Pennsylvania Power & Light Co. PLA-2010 84/01/27
SCHWENCER, A Licensing Branch 2 1p 22026, 254 24X
Fiche: 50-387, 84/01/27, 8401310359

B401310363 Clarifies 810925 ltr re NUREG-0612, "Control of Heavy Loads," Permanent crane rail stops will be installed prior to fuel load to prevent fuel bldg crane travel over spent fuel storage pool throughout remaining plant life
EIER, J D Illinois Power Co U-0690 84/01/26 SCHWENCER, A Licensing Branch 2 1p 22026, 253, 24X Fiche: 50-461, 84/01/26, 8401310363

B401310366 Forwards schedule of commitments adjusted to new fuel load schedule, per util 831216 ltr, Appropriate date changes will appear in next FSAR amend
KAMMER, D B Tennessee Valley Authority, 84/01/27, ADENBAM, E Licensing Branch 4 2pp. 22015-051, 24X Fiche 50-438, 84/01/27, 8401310366

B401310376 Advises that plant mods re final as-built stress reconciliation will be completed by 840131, per util 830616 & 0328 ltrs re hydrodynamic loads outside containment Response resolves NUREG-0892, SER, Confirmatory Item 4.
SORENSEN, C Washington Public Power Supply System 002-84-038 84/01/24 SCHWENCER, A Licensing Branch 2 3pp 22012, 352, 24X
Fiche 50-397, 84/01/24, 8401310376

B401310413 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs as result of mods to satisfy requirements of NUREG-0737, Items II B 1, II F 1, II F 1.3, II F 1.4 & II F 2 & diesel generator testing.
MILLS, L M Tennessee Valley Authority 84/01/25, ADENBAM, E Licensing Branch 4, 2pp. 22019:316 24X Fiche: 50-327, 84/01/25, 8401310413

--B401310425 Proposed Tech Spec changes as result of mods to satisfy requirements of NUREG-0737, Items II B 1, II F 1, II F 1.3, II F 1.4 & II F 2 & diesel generator testing.
* Tennessee Valley Authority 84/01/25 30pp 22019, 318, 24X
Fiche 50-327, 84/01/25, 8401310413

NONDOCKETED ITEMS

B401310449 MUREQ/CR-3070
MEASURED IN-REACTOR DATA AND POSTIRRADIATION OBSERVATIONS
FOR IFA-227
CUNNINGHAM, M E, LANNING, D D Battelle Memorial Institute, Pacific
Northwest Laboratory FIN 8-2043 PNL-4542 84/01/31 Division
of Accident Evaluation (Pre 840101) 36pp Available at NRC
#4 50, 22035 234

ORR CORRESPONDENCE WITH OTHER ORGANIZATIONS

B311300135 Summary of noise surveillance & diagnostics research review
group 830920-21 meetings re results of FY83 program plans
for FY84
LEWIS, O B Instrumentation & Control Branch LEWIS, O B Noise
Surveillance & Diagnostics Research Review Group FIN 8-0191
83/10/20, FARMER, W Office of Nuclear Regulatory Research,
Director, HENDERSON, J Director's Office, Office of Inspection and
Enforcement LOIS, L Office of Nuclear Reactor Regulation,
Director 3pp 21333, 107

B312120090 IE Bulletin 83-08, "Electrical Circuit Breakers
W/Undervoltage Trip Feature in Use in Safety-Related
Applications Other Than Reactor Trip Sys." Svc list encl
DEVOUNO, R C Director's Office, Office of Inspection and
Enforcement 83/12/28 Consolidated Edison Co of New York, Inc
124pp 21731:166 24X Fiche 50-000, 83/12/28, B312120090

B312120093 IE Info Notice 83-84, "Cracked & Broken Piston Rods in
Brown Boveri Electric Type 3HK Breakers." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/12/30 Consolidated Edison Co of New
York, Inc. 127pp, 21826:060 24X Fiche 50-000, 83/12/30, B312120093

B312120104 IE Info Notice 84-02, "Operating Nuclear Power Plant at
Voltage Levels Lower Than Analyzed." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/10, Consolidated Edison Co of New
York, Inc 125pp 21946:053 24X Fiche 50-000, 84/01/10, B312120104

B312120107 IE Info Notice 84-01, "Excess Lubricant in Electric Cable
Sheaths." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/10 Consolidated Edison Co of New
York, Inc. 122pp 21826:184 24X Fiche 50-000, 84/01/10, B312120107

B312120114 IE Info Notice 84-05, "Exercise Frequency." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 84/01/16 Consolidated Edison Co of New
York, Inc. 127pp 21957:142 24X Fiche 50-000, 84/01/16, B312120114

B312120116 IE Info Notice 84-03, "Compliance W/Conditions of License &
Notification of Disability by Licensed Operators." Svc list
encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/18 Consolidated Edison Co of New
York, Inc. 118pp 22000:001 24X Fiche 50-000, 84/01/18, B312120116

B312120117 IE Info Notice 84-04, "Failure of Elastomer Seated Butterfly
Valves Used Only During Cold Shutdowns." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 84/01/18 Consolidated Edison Co of New
York, Inc. 120pp 22000:041 24X Fiche 50-000, 84/01/18, B312120117

B401030219 Forwards evaluation of joint state & local radiological
emergency response 820218 exercise Rept describes
deficiencies requiring schedule of corrective actions Next
rept expected by 831230
KRIMM, R W Federal Emergency Management Agency 83/12/09
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 1p 21681:191, 24X Fiche 50-271, 83/12/09,
B401030219

-B401030222 Evaluation of joint state & local radiological emergency
response 820218 exercise for facility.
* Federal Emergency Management Agency 82/06/09 81pp,
21681:192 24X Fiche: 50-271, 83/12/09, B401030219

B401030244 Forwards "Exercise Evaluation Rept for Salem Exercise on
831026."
KRIMM, R W Federal Emergency Management Agency, 83/12/21,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 2pp 21681:078 24X Fiche, 50-272, 83/12/21,
B401030244

--B401030249 "Exercise Evaluation Rept for Salem Exercise on 831026."
* Federal Emergency Management Agency, 83/11/25, 69pp
21681:080, 24X Fiche: 50-272, 83/12/21, B401030244

B401030246 Forwards progress rept on offsite emergency preparedness at
facility Statement of adequacy of offsite emergency
preparedness will be submitted after State of CA provides
schedule for correction of unresolved deficiencies
KRIMM, R W Federal Emergency Management Agency 83/12/09
JORDAN, E J Division of Emergency Preparedness & Engineering
Response (Post 830103) 12pp 21680:348 24X Fiche 50-312,
83/12/09, B401030246

B401030264 Forwards "Exercise Evaluation Rept of 830927 Exercise of
Offsite Radiological Emergency Preparedness Plans, Rancho
Seco"
KRIMM, R W Federal Emergency Management Agency 83/12/07
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 21681:016 24X Fiche 50-312, 83/12/07,
B401030264

--B401030267 "Exercise Evaluation Rept of 830927 Exercise of Offsite
Radiological Emergency Preparedness Plans, Rancho Seco"
* Federal Emergency Management Agency 83/10/28 61pp
21681:018 24X Fiche 50-312, 83/12/07, B401030264

B401040126 Forwards statement of Sunflower Alliance contention &
specific issues raised re adequacy of offsite emergency
plans Affidavit in support of motion for summary disposition
requested
WOODHEAD, C P Hearing Branch 4 ISSUANCES DL 83/12/29, PERRY, B
Federal Emergency Management Agency 3pp 21702:041 24X
Fiche 50-440, 83/12/29, B401040126

B401040135 Forwards EL Jordan 831228 ltr to RW Krimm (FEMA) re
emergency planning
BORDENICK, B M Hearing Branch 3 ISSUANCES DL-3 83/12/29
LAURENSEN, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing
Board Panel 3pp 21702:071 24X Fiche 50-322, 83/12/29, B401040135

B401050003 Releases public version of radiological emergency response
plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21733:001 24X Fiche 50-397, 83/12/27,
B401050003

--B401050005 Public version of DOE, Richland Operations Ofc radiological
emergency response plan W/831111 ltr
FREMLING, A O Energy, Dept of SORENSEN, O C Washington Public
Power Supply System 002-83-1045 82/01/11 SCHMENCER, A
Licensing Branch 2 383pp 21733:002 24X Fiche 50-397, 83/12/27,
B401050003

B401050029 "Std Guide for Evaluation of Alert & Notification Sys for
Nuclear Power Plants." Certificate of Svc encl Related
correspondence
* Federal Emergency Management Agency ISSUANCES DL-3 83/09/30
60pp 21732:135 24X Fiche 50-322, 83/09/30, B401050029

B401050250 Forwards INPO draft rept, "Evaluation of Big Rock Point
Nuclear Plant." Assertions on Pages 15-17 relevant to
genuine Issues of Facts (6) & (7) under Christa-Maria
Contention 2 & O'Neill Contention IIA re south wall
OALLO, J Isham, Lincoln & Beale OALLO, J Consumers Power Co
ISSUANCES OLA 83/12/29 BLOCH, P B, FARIS, O H, SHON, F J Atomic
Safety and Licensing Board Panel 52pp 21729:163 24X
Fiche 50-155, 83/12/29, B401050250

B401090359 Requests prompt distribution of collated LILCO transition
plan to regional assistance committee members by 840103 &
forwards suggested matrix for util identification of page
changes affected by each rev Certificate of Svc encl
KRIMM, R W Federal Emergency Management Agency 83/12/22
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 6pp 21754:066, 24X Fiche, 50-322, 83/12/22,
B401090359

B401090315 Responds to 830929 request for assistance re emergency
evacuation issue raised by Sensible Maine Power Evacuation
routes will be inspected & exercise evaluation simulation
facility analyzed by 840201,
KRIMM, R W Federal Emergency Management Agency, 83/11/23
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 1p 21750:362 24X Fiche 50-309, 83/11/23,
B401090315

B401090680 Responds to approval request for info collection re 10CFR73
concerning physical protection of plants & mats Request
approved through 851031 under OMB 3150-0002 per Paperwork
Reduction Act,
MACRAE, J B Office of Management & Budget OMB 3150-0002,
83/12/23, SCOTT, B Document Management Branch 2pp, 21768:048,
83/12/23, SCOTT, B Document Management Branch 2pp, 21768:048,

NONDOCKETED ITEMS

451

8401090483 Responds to approval request for info collection re 10CFR33 concerning human uses of byproduct matl Request approved through 841231 under OMB 3150-0010 per Paperwork Reduction Act.
MACRAE, J B Office of Management & Budget OMB 3150-0010
83/12/23 SCOTT, S Document Management Branch 2pp 21768 050

8401090489 Responds to approval request for info collection re 10CFR21.21 concerning notification of failure to comply or existence of defect & 10CFR21.51 concerning maint of records Request approved through 840131 under OMB 3150-0035
MACRAE, J B Office of Management & Budget OMB 3150-0035
83/12/23 SCOTT, S Document Management Branch 2pp 21768 052

8401100490 Responds to approval request for info collection re matl balance rept Request approved through 850331 under OMB 3150-0004 per Paperwork Reduction Act
MACRAE, J B Office of Management & Budget OMB 3150-0004
83/12/23 SCOTT, S Document Management Branch 2pp 21768:195

8401120195 Forwards two ASLB orders addressing emergency planning contentions Encl suppl 830816 matl w/o encl
JOHNSON, Q E Hearing Branch 4 84/01/04 PERRY, S Federal Emergency Management Agency 1p 21793 382 24X
Fiche 50-413, 84/01/04, 8401120195

8401170269 Forwards "Exercise of Offsite Radiological Emergency Preparedness Plans for Surry Nuclear Power Station," evaluation rept
KRIMM, R W Federal Emergency Management Agency 84/01/10
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21831 005 24X Fiche 50-280, 84/01/10
8401170269

--8401170274 "Exercise of Offsite Radiological Emergency Preparedness Plans for Surry Nuclear Power Station," evaluation rept
KRIMM, R W Federal Emergency Management Agency 83/10/31 57pp
21831 007. 24X Fiche 50-280, 84/01/10, 8401170269

8401170409 Forwards exercise rept of 830618 joint exercise of offsite radiological emergency preparedness plans for facilities
KRIMM, R W Federal Emergency Management Agency 84/01/09
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 33pp 21828 225 24X Fiche 50-338, 84/01/09, 8401170408

8401170412 Forwards exercise repts of 820616 full-scale exercise & 830628 small-scale exercise of offsite radiological emergency preparedness plan
KRIMM, R W Federal Emergency Management Agency 84/01/10
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21829 233 24X Fiche 50-277, 84/01/10, 8401170412.

--8401170416 Evaluation of radiological emergency exercise for Peach Bottom Atomic Power Station on 830628
* Federal Emergency Management Agency 83/06/28 20pp
21829 235. 24X Fiche 50-277, 84/01/10, 8401170412

--8401170419 Rept of observations & recommendations re Peach Bottom Atomic Power Station exercise on 820616
* Federal Emergency Management Agency 82/06/16 37pp
21829 235 24X Fiche 50-277, 84/01/10, 8401170412

8401180061 Forwards addendum to 831005, "Exercise of Offsite Radiological Emergency Preparedness Plans " All deficiencies resolved but one Addendum showing status of deficiencies in four past joint exercises encl
KRIMM, R W Federal Emergency Management Agency 84/01/06
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21842 070 24X Fiche 50-344, 84/01/06, 8401180061

--8401180071 Addendum to 831005, "Exercise of Offsite Radiological Emergency Preparedness Plans," Status of deficiencies for four past joint exercises encl
* Federal Emergency Management Agency 83/11/08, 12pp
21842 071 24X Fiche 50-344, 84/01/06, 8401180061

8401180103 Informs that proposed interim finding returned to FEMA Region VII for further processing as described in encl ltr. Interim findings will be submitted upon acceptance.
KRIMM, R W Federal Emergency Management Agency 84/01/13
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 21840 308 24X Fiche 50-482, 84/01/13, 8401180103.

8401180163 Forwards "Part I Exercise Final Rept, LaBalle Nuclear Power Station Joint Radiological Emergency Exercise " Deficiencies did not detract from capability to protect public Approval 350 will remain in effect
KRIMM, R W Federal Emergency Management Agency 84/01/06
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 21840 312 24X Fiche 50-373, 84/01/06, 8401180163

--8401180174 "Part I Exercise Final Rept, LaBalle Nuclear Power Station Joint Radiological Emergency Exercise,"
* Federal Emergency Management Agency 83/07/12 30pp
21840 318 24X Fiche 50-373, 84/01/06, 8401180163

8401180189 Informs that FEMA has confirmed receipt of revised transition plan & revised NUREG-0654 cross-reference for facility
KRIMM, R W Federal Emergency Management Agency 84/01/13
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 21844 081. 24X Fiche 50-322, 84/01/13, 8401180189

8401180246 Forwards exercise repts for 820928 small-scale & 830914 full-scale exercise of offsite radiological emergency preparedness plans for Calvert Cliffs Nuclear Power Station
KRIMM, R W Federal Emergency Management Agency 84/01/06
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp 21844 022 24X Fiche 50-317, 84/01/06, 8401180246

--8401180256 Evaluation of Calvert Cliffs 830914 full-scale exercise for offsite radiological emergency preparedness plans for facilities.
* Federal Emergency Management Agency 83/10/13 43pp.
21844 023 24X Fiche 50-317, 84/01/06, 8401180246.

--8401180263 Evaluation of Calvert Cliffs small-scale exercise for offsite radiological emergency preparedness plans
* Federal Emergency Management Agency 82/09/28 13pp.
21844 067. 24X Fiche 50-317, 84/01/06, 8401180246

8401200225 BECY-83-004A
Provides Commissioners w/info on current status of NPRDS & submits assurance that INPO remains strongly committed to improvement of NPRDS
DIRKSG, W J Office of the Executive Director for Operations.
83/07/05 25pp 21872 112

8401200230 Forwards request for OMB review & supporting statement re registration certification - in vitro testing w/byproduct matl under general license.
MORRY, P Q Office of Administration. 84/01/16 MACRAE, J B Office of Management & Budget 1p 21872 100

8401230610 Partial response to FOIA request for four categories of documents Forwards documents re 830907 std work order for DOE work Search for Category C & D documents in progress.
FELTON, J M Division of Rules and Records. 83/11/22 SHOLLY, S C Union of Concerned Scientists, 1p. 21927 336

--8401230620 Forwards std work order for DOE work, "Classification of Equipment & Activities Important to Safety "
BURDA, A J Director's Office, Office of Inspection and Enforcement FIN A-1353. 83/09/07. ROMATOWSKI, R A. Energy, Dept of 1p 21927 337.

--8401230625 Std work order for DOE work "Classification of Equipment & Activities Important to Safety," issued to Sandia Natl Labs.
BURDA, A J Director's Office, Office of Inspection and Enforcement FIN A-1353 30-83-40. 83/09/07 6pp. 21927:338.

8401240129 Forwards draft Commission paper transmitting fourth semiannual rept re status of NPRDS.
HELYES, C J Director's Office. 84/01/16. MINQUE, R B Office of Nuclear Regulatory Research, Director. BARRY, L W Office of Resource Management, Director DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 21945:084.

8401240496 Forwards FEMA, "HB Robinson Nuclear Power Plant Exercise on 830921-22," final rept.
VERRELLI, D M Division of Project & Resident Programs 84/01/11
UTLEY, E E Carolina Power & Light Co 1p. 21920:102 24X
Fiche: 50-261, 84/01/11, 8401240496.

8401250244 Forwards IE 840111 memo to FEMA responding to FEMA 831222 ltr outlining conditions for expedited review of Revs 2 & 3 to util transition plan.
BORDENICK, B M Hearing Branch 3 ISSUANCES OL-3 84/01/16.
LAURENSEN, J A, KLINE, J R, J. SHON, P. J. Atomic Safety and Licensing Board Panel 6pp. 21941:342 24X Fiche: 50-322, 84/01/16, 8401250244

NONDOCKETED ITEMS

B401250262 Responds to questions raised at meeting to arrange for informal discovery. No NRC-FEMA communications re offsite emergency plans occurred. NRC will issue SER suppl containing comments on FEMA findings. FEMA external correspondence encl. JOHNSON, O E. Hearing Branch 4. 84/01/10. GUILD, R. Guild, R. 17pp. 21944 190. 24X Fiche 50-413.84/01/10.8401250262

--B401250272 Forwards emergency planning contentions admitted by ASLB on 830808. Portions of transcript which constitute rulings on contentions also encl. W/O encl. JOHNSON, O E. Hearing Branch 4. 83/08/16. PERRY, B. Federal Emergency Management Agency. 1p. 21944 207. 24X Fiche 50-413.84/01/10.8401250262.

B401270496 Forwards request for OMB review & supporting statement re 10CFR70 concerning domestic licensing of SNM. MORRIS, P. D. Office of Administration. 84/01/23. MACRAE, J. B. Office of Management & Budget. 1p. 22002.235

B401300200 Requests exemption from participation by States of WI & IL in 840417 emergency exercise. Major elements in governmental emergency plans performed satisfactorily in 1983 FEMA correspondence encl. FARRAR, D. L. Commonwealth Edison Co. 1709D/39-40. 84/01/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 10pp. 21995.337. 24X Fiche:50-295.84/01/18.8401300200

B401300209 Responds to B40109 ltr forwarding correspondence from Croton-Harmon School District in Croton-on-Hudson, NY re Westchester County evacuation plan for school children in event of facility accident. FEMA already responded. KRIMM, R. W. Federal Emergency Management Agency. 84/01/24. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 21994.001. 24X Fiche 50-000.84/01/24.8401300209

--B401300213 Forwards post-exercise assessment of 830928 exercise of radiological emergency preparedness plans of State of NY & Oswego County. KRIMM, R. W. Federal Emergency Management Agency. 84/01/23. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp. 21994.002. 24X Fiche 50-000.84/01/24.8401300209.

--B401300215 Post-exercise assessment of 830928 exercise of radiological emergency preparedness plans of State of NY & Oswego County. PETRONE, F. P. Federal Emergency Management Agency. 83/12/23. 102pp. 21994.004. 24X Fiche:50-000.84/01/24.8401300209.

--B401300219 Post-exercise assessment of exercise of State of NY & Oswego County radiological emergency plans. PETRONE, F. P. Federal Emergency Management Agency. 82/10/29. 62pp. 21994.110. 24X Fiche:50-000.84/01/24.8401300209

PR PROPOSED RULE

B312120126 Board Notification. 84-007 forwards info on Commission 840106 meeting w/Bandia Natl Labs re environ qualification policy statement & proposed rule. EISENHUT, D. O. Division of Licensing. 84/01/12. Atomic Safety and Licensing Board Panel. 2pp. 21941.149.

--B401250320 Draft Commission paper providing info on equipment qualification policy statement & proposed rule & NRC response to Court of Appeals decision. DIRCKS, W. J. Office of the Executive Director for Operations. 84/01/10. 1p. 21941.301.

--B401250323 Forwards slides from presentation on environ qualification during Dec 1983 trip to Sandia in preparation for environ qualification 840106 meeting. PALLADINO, N. J. Commissioners. 84/01/03. GILINSKY, V., ROBERTS, T. M., ABSELSTINE, J. Commissioners. 20pp. 21941.302.

B401050185 Comments supporting proposed rules 10CFR2 & 72 re implementing hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors. COOK, K. W. Louisiana Power & Light Co. 48FR54499 002. 83/12/30. Docketing & Services Branch. 1p. 21727.274.

B401050195 Comments on proposed rule 10CFR2 re role of NRC staff in adjudicatory hearings in initial licensing proceedings for nuclear power reactors. Role of staff should remain unchanged. SILBERO, J. E. Shaw, Pittman, Potts & Trowbridge. 48FR50550 017. 84/01/03. Docketing & Services Branch. 5pp. 21725.304

B401050236 Comments on proposed rule 10CFR2 re NRC role in adjudicatory licensing hearings. Option 4 objectionable. No valid reason seen for resurrecting option under guise of restructuring NRC role in contested proceedings. COHAN, B. Z. Atomic Industrial Forum. 48FR50550 018. 84/01/03. Docketing & Services Branch. 2pp. 21729.144

B401050238 Comments on proposed rule 10CFR2 re rules of practices for domestic licensing proceedings. Role of NRC in adjudicatory licensing hearings. Retention of existing NRC role recommended. REIS, H. F. Newman & Holtzinger. REIS, H. F. Florida Power & Light Co. REIS, H. F. Houston Lighting & Power Co. 48FR50550 019. 84/01/03. Docketing & Services Branch. 8pp. 21731.011

B401050246 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing proceedings. Commission perception that public views current NRC role as that of applicant helper is correct. DOHERTY, J. F. Doherty, J. F. 48FR50550 015. 83/01/03. 2pp. 21729.109

B401050260 Comments on proposed rule 10CFR2 re role of Commission in adjudicatory proceedings. Options 3 & 4 undesirable. Mods to Options 1 & 2 recommended. * LeBeauf, Lamb, Leiby & MacRae. 48FR50550 016. 84/01/03. CHILK, S. J. Office of the Secretary of the Commission. 7pp. 21728.293

B401090266 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing hearings. NRC bias to intervenors reflected in info submitted to Commission. DRAKE, M. Affiliation Unknown. 48FR50550 024. 83/12/29. Commissioners. 1p. 21754.237

B401090339 Comments on proposed rule 10CFR2 Openness in proceedings advocated. Announcing meetings in advance would be step in right direction. COLE, W. E., COLE, M. R. Affiliation Unknown. 48FR50550 020. 83/12/30. Office of the Secretary of the Commission. 1p. 21754.104

B401090341 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing hearings. Option 1 goes farthest toward increasing efficiency w/o sacrificing health & safety protection. PATTERSON, J. D. Middle South Services, Inc. 48FR50550 023. 84/01/03. Docketing & Services Branch. 4pp. 21754.102

B401090349 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing hearings. NRC existing role in licensing process (Option 3) should be retained. CONNER, T. B. Conner & Watterhahn. CONNER, T. B. Philadelphia Electric Co. 48FR50550 022. 84/01/03. CHILK, S. J. Docketing & Services Branch. 10pp. 21754.084

B401090354 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity. Adoption of Option 2 recommended. KILLAR, F. M. Middle South Services, Inc. 48FR54499 005. 84/01/03. CHILK, S. J. Office of the Secretary of the Commission. 3pp. 21754.080.

B401090356 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing hearings. Recommends Option 1, in modified form, recommended. Hearing process & NRC safety review constitute independent processes. FARRAR, D. L. Commonwealth Edison Co. 48FR50550 026. 84/01/03. Office of the Secretary of the Commission. 7pp. 21754.073.

B401090373 Comments on proposed rules 10CFR2 & 72 re hybrid hearing process. Deadline for comments should be extended at least 4 wks. NEMETHY, E. Ecology/Alert. 48FR54499 004. 84/01/02. Docketing & Services Branch. 1p. 21754.045

B401090378 Comments on proposed rule 10CFR2 re role of NRC staff in adjudicatory licensing hearings. Changing role of NRC in hearing process should allow for more effective use of resources in licensing of new plants. SCHERER, A. E. Combustion Engineering, Inc. 48FR50550 025. 84/01/03. Office of the Secretary of the Commission. 2pp. 21753.285

B401090383 Comments on proposed rule 10CFR2 re role of NRC staff in initial licensing hearings. * Bishop, Liberman, Cook, Purcell & Reynolds. 48FR50550 021. 84/01/03. Office of the Secretary of the Commission. 14pp. 21753.271

B40100263 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity at civilian nuclear power reactors. Opposes rules. SAVAGE, J. A. Affiliation Unknown. 48FR54499 006. 84/01/04. NRC - No Detailed Affiliation Given. 2pp. 21759.196.

B401100273 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Supports Option 2 re higher stds for intervention
WITHERS, B D Portland General Electric Co 48FR54499 007
84/01/05 Docketing & Services Branch 2pp 21758 211

B401100281 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Supports Option 2
READ, D F Affiliation Unknown 48FR54499 008 84/01/05
Docketing & Services Branch 3pp 21759 154

B401100360 Comments on proposed rules 10CFR2 & 27 re role of NRC in adjudicatory licensing hearings Regulatory staff should be eliminated as party to individual licensing proceedings
NAHE, E P Westinghouse Electric Corp 48FR50550 027 84/01/03
CHILK, S J Office of the Secretary of the Commission 11pp
21764 020

B401180169 Comments on proposed rules 10CFR30, 40 & 150, "Tritium & Source Matl Repts." Questions whether people using source matl under general license are now subj to new reporting requirements
SOLARI, A J Michigan, Univ of, Medical School 48FR53714 005, 84/01/10
Docketing & Services Branch 1p 21840 311.

B401180207 Comments on proposed rules 10CFR30, 40 & 150, "Tritium & Source Matl Repts." Concurs w/rules Recommends depleted U used & possessed by DOD & Coast Guard in ammunition & munitions be added.
O'NEILL, J O Navy, Dept of 48FR53714 004 84/01/12 Docketing & Services Branch 1p, 21842 359

B401180215 Comments on proposed rule 10CFR2 re rules of practice for domestic licensing proceedings; role of NRC in adjudicatory licensing hearings Favors Option 1, but suggests criteria for NRC participation be established in advance
BRUNNER, J E Consumers Power Co. 48FR50550 028, 84/01/12, Docketing & Services Branch 2pp 21844 211

B401240111 Provides staff response to comments & question re final hydrogen control rule (BECY-83-357) Decision on final rule should be made expeditiously since outcome of several licensing hearings depend on decision
DIRCKS, W J Office of the Executive Director for Operations 83/12/28 PALLADINO, N, GILINSKY, V, ROBERTS, T Commissioners, 10pp 21932 217

--B401240114 Forwards addl questions re final hydrogen rule. Response requested in near future
ROBERTS, T M NRC - No Detailed Affiliation Given 83/11/17, DIRCKS, W J Office of the Executive Director for Operations, 2pp, 21932 230

B401240354 Comments on proposed rule 10CFR50 re immediate notification of significant events Reporting requirement appears to be counter to some of NRC reasons for issuing rule Requests written guidance on intent & implementation.
THORPE, J R General Public Utilities - GPU Service Corp. 48FR14864 023 84/01/17 CHILK, S Office of the Secretary of the Commission, 2pp, 21920 020

B401240361 Comments on proposed rules 10CFR30, 40 & 150, "Tritium & Source Matl Repts." Supports proposal to lower reporting requirements for source matl transfers from 1,000 to 1 kg
READ, D F Affiliation Unknown 48FR53714 006, 84/01/14 Docketing & Services Branch, 2pp 21917:113.

B401240376 Comments on proposed rules 10CFR30, 40 & 150 re recommendation to lower reporting requirements on source matl from 1,000 kg to 1 kg Change would put serious financial & administrative burden on company. Opposes rule.
RIDDLE, D H Nuclear System 48FR53714 007 84/01/16 Docketing & Services Branch 1p, 21908 361

B401250239 Comments on proposed rule 10CFR20 re personnel dosimetry requirements for registrants & licensees. Supports rule
LLOYD, L L Montana, State of 49FR1205 001, 84/01/19, Docketing & Services Branch, 1p, 21941:348

B401250247 Advises recipients that Comment 23 to proposed rule 10CFR50 miscoded Number 23 will not be used again.
* Docketing & Services Branch 48FR14864 84/01/24, Docketing & Services Branch 1p 21943:195

B401250253 Package of three comments opposing proposed rules 10CFR30, 40 & 150 re tritium & source matl repts Paragraphs that exempt depleted U used as shielding should be reworded to include many uses of depleted U.
MOTT, E D Dresser Industries, Inc. ODOM, L Gulf Nuclear, Inc
IRWIN, H R Advanced Medical Systems, Inc 48FR53714 84/01/23 Docketing & Services Branch 5pp 21944 179.

B401250256 Comments on proposed rule 10CFR2 re role of NRC in adjudicatory licensing hearings NRC should remain full party on all substantive aspects of initial licensing proceeding
BIBCHOFF, C A Snell & Wilmer. 48FR50550 029 84/01/19 Docketing & Services Branch 10pp, 21944 114

B401250257 Comments on proposed rule 10CFR50 re immediate notification of significant events Requests Commission consider scope of Paragraph 50.72(b)(2)(vi) in context of overall purpose of rule & provide written guidance on intent & implementation.
THORPE, J R General Public Utilities - GPU Service Corp 48FR14894 022 84/01/17 CHILK, S Office of the Secretary of the Commission, 2pp 21943 248

B401250259 Comments on proposed rules 10CFR30, 40 & 150 re tritium & source matl repts. Specific exemption or alternative should be considered for inventory adjustment of 1 kg
DELBACA, P V Fisher Scientific Co 48FR53714 008 84/01/20, Docketing & Services Branch, 3pp 21944:111.

B401310403 Comments on proposed rules 10CFR30, 40 & 150 re tritium & source matl repts Recommends Paragraph 40.64(d)(3) be added stating that any depleted U metal of depleted U alloys used as penetrators in ammunition be held by DOD
MILLIGAN, R E Navy, Dept. of, Naval Sea Systems Command 48FR53714 013 84/01/23 Docketing & Services Branch, 2pp, 22017:361

B401310411 Comments on proposed rules 10CFR30, 40 & 150 re tritium & source matl repts Requests thorium contained in nickel-thoria alloys be included in exemption from reporting in 10CFR40 & 150
NARUS, R United Technologies Corp. 84/01/19 Docketing & Services Branch, 1p, 22012:362

PRM PETITION FOR RULEMAKING

B401030223 Requests State of MS participation in B40111 proceeding.
BALL, W G Mississippi, State of 83/12/16 Docketing & Services Branch 1p 21728:189.

B401030262 Confirms that 8 Frishman will present testimony on behalf of State of TX at scheduled meeting on B40111 re draft DOE siting guidelines for high level radwaste repositories.
FRISHMAN, S Texas, State of, 48FR50432 83/12/28 CHILK, S J Office of the Secretary of the Commission, 1p, 21728:302

B401030288 Requests opportunity to present oral comments on DOE proposed repository guidelines & NRC concurrence w/guidelines. State proposed rulemaking procedure is better method for NRC to receive public comment.
HECTOR, A O Serious Texans Against Nuclear Dumping, 48FR14873, 83/11/15 Office of the Secretary of the Commission, 1p, 21726, 351

B401090347 Comments on petition for rulemaking PRM 30-37 to limit levels of tritium & deuterium circulating in & around nuclear power plants. Petition opposed on grounds that limits set forth in App B to 10CFR20 provide sufficient protection.
STEWART, W L Virginia Electric & Power Co 48FR50083 003 83/12/30, Docketing & Services Branch, 1p, 21754:096.

B401090358 Comments on petition for rulemaking re nuclear waste repository siting guidelines. Yakima Indian Nation supports request of States of UT & WI that Commission B40111 meeting be delayed
TOUSLEY, D R Harmon & Weiss TOUSLEY, D R Yakima Indian Nation, 48FR50432, 84/01/06 Office of the Secretary of the Commission 1p, 21754:072

B401090479 Comments on petition for rulemaking re NRC concurrence in high level waste repository safety guidelines under Nuclear Waste Policy Act of 1982
KEARNEY, J J Edison Electric Institute, 48FR50432, 84/01/05, CHILK, S J Office of the Secretary of the Commission, 1p, 21753:139.

B401090481 Comments on petition for rulemaking re NRC concurrence in high level waste repository safety guidelines under Nuclear Waste Policy Act of 1982. Intent to participate in public hearing reaffirmed.
BERICK, D M Environmental Policy Institute, 48FR50432, 84/01/04, CHILK, S J Docketing & Services Branch, 1p, 21753:137.

NONDOCKETED ITEMS

8401090482 Comments on petition for rulemaking PRM 60-1, urging NRC to adopt mechanism to concur w/DOE rules on siting of high level waste repositories
LEWIS, M. Lewis, M. 48FR48473 84/01/03 NRC - No Detailed Affiliation Given 1p. 21753 136

8401100196 Comments on petition for rulemaking re NRC concurrence on DOE waste repository siting guidelines
FRISHMAN, S. Texas, State of 48FR50432 84/01/06 CHILK, S. J. Docketing & Services Branch 1p. 21760 218

--8401100198 Testimony of State of TX re NRC concurrence in DOE general guidelines for recommendations of sites for nuclear waste repositories.
FRISHMAN, S. Texas, State of 84/01/11 16pp. 21760 219

8401100202 Comments on proposed rulemaking re NRC concurrence in DOE high level waste repository safety guidelines, proposed 10CFR960
SINDERBRAND, C. Wisconsin, State of 48FR50432 84/01/07 CHILK, S. J. Office of the Secretary of the Commission 16pp. 21760. 248

8401160275 Comments on petition for rulemaking PRM-50-37 re water circulated in & around nuclear power plants not to exceed natural environ concentration of deuterium & tritium for 1 yr Opposes petition
FARRAR, D. L. Commonwealth Edison Co. 48FR50083 004 84/01/09 Docketing & Services Branch. 1p. 21813 330

PROJECTS - PREDOCKET LICENSING

8401050344 Forwards detailed comments in response to 830929 submittal under Project M-34, "Topical SAR for Castor IC Cask 16FBI (Dry Storage)." Rev 2
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/12/21. ROLLINS, J. D. Gesellschaft fuer Nuklear Service, mbH 33pp. 21742. 287.

8401060396 Forwards proprietary "Westinghouse Advanced PHR Pretendering Module 11 - Plant Layout" Rept suppl's matl submitted w/821101 1tr Preliminary design approval targeted for 1985
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2870. 83/12/30 EISENHUT, D. O. Office of Nuclear Reactor Regulation, Director 2pp. 21741. 122.

--8401060399 Requests that proprietary "Westinghouse Advanced PHR Pretendering Module 11 - Plant Layout" be withheld (ref 10CFR2 790)
WIESENHANN, R. A. Westinghouse Electric Corp. AW-83-114. 83/12/30. EISENHUT, D. O. Office of Nuclear Reactor Regulation, Director 1p. 21741. 124.

8401160023 Forwards summary of 831220 meeting in West Valley, NY re update on contamination in monitoring wells installed adjacent to NRC disposal area Attendance list encl
HANNUM, W. H. Energy, Dept. of 23222. 83/12/29. CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch. 6pp. 21823. 357

NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

11030137 Final deficiency rept re broken pin carrier plates on essential raw cooling water (ERCW) motors supplied by Siemens-Allis Initially reported on 830824. Parts for eight ERCW motors to be installed. Also reportable per 10CFR21
MILLS, L. M. Tennessee Valley Authority. 10CFR 050 55E 83/12/19 O'REILLY, J. P. Region 2, Office of Director. 2pp. 21682. 256 24X Fiche: 50-390, 83/12/19, 8401030137.

1401030162 Part 21 rept re adequacy of svc water & circulating water pump house structure. Caused by lack of proper consideration of shrinkage effects in design of compression members. Mods will be completed by 840216
KREIDER, H. Q. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/12/22 Director's Office, Office of Inspection and Enforcement. 3pp. 21680. 326. 24X Fiche: 50-443, 83/12/22, 8401030162.

8401030182 First interim deficiency rept re overtightened studs on Borg Warner gate valve motor operators. Initially reported on 831121 Vendor revising drawings. Next rept expected by 840328 Also reported per Part 21.
MILLS, L. M. Tennessee Valley Authority. 10CFR 050 55E. 83/12/19 O'REILLY, J. P. Region 2, Office of Director. 2pp. 21681. 321 24X Fiche: 50-438, 83/12/19, 8401030182.

8401030202 Final deficiency & Part 21 repts re final design of OE 7700 Series 250-volt dc control ctra Plant operating procedures revised to include methods of clearing obstructions as provided by OE & exam & reforming of draw out contacts
CURTIS, N. W. Pennsylvania Power & Light Co. 10CFR 050 55E 83/12/05 MURLEY, T. E. Region 1, Office of Director 4pp. 21683. 089 24X Fiche 50-387, 83/12/05, 8401030202

8401040318 Revised final deficiency rept, Condition 260 re insufficient flow to HXs in standby svc water loops A & B B&R evaluating design error Also reported per Part 21
SORENSEN, G. C. Washington Public Power Supply System 10CFR 050 55E 83/12/20 MARTIN, J. B. Region 5, Office of Director 3pp. 21708 192 24X Fiche 50-397, 83/12/20, 8401040318

8401040327 Final Deficiency Rept NCR 1986 re linear indications in Nat'l Valve & Mfg Co spool pieces Initially reported on 820924 All subassemblies containing identified matl inspected & repaired Also reportable per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/12/23 O'REILLY, J. P. Region 2, Office of Director 2pp. 21706. 191 24X Fiche: 50-439, 83/12/23, 8401040327

8401040333 Final deficiency rept, Condition 306 re recombiner scrubber drainage impaired by design configuration of connections for water loop seal & process blower on recombiner skid Initially reported on 831215 Also reported per Part 21
SORENSEN, G. C. Washington Public Power Supply System 10CFR 050 55E 83/12/16 MARTIN, J. B. Region 5, Office of Director 3pp. 21705 048 24X Fiche 50-397, 83/12/16, 8401040333

8401040339 Supplemental final deficiency rept re bonnet studs improperly torqued on DHR valves Initially reported on 811222 Completion of corrective actions anticipated by 840116. Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 83/12/22 O'REILLY, J. P. Region 2, Office of Director 1p. 21707 353 24X Fiche 50-438, 83/12/22, 8401040339

8401040431 Interim Deficiency Rept DER 83-75 re bolts securing two D0126SA panel filler assemblies, supplied by Foxboro Improperly torqued Initially reported on 831102 Submittal of final rept expected by 840128 Also reportable per Part 21
VAN BRUNT, E. E. Arizona Public Service Co. 10CFR 050 55E 83/12/05 BISHOP, T. W. Division of Resident Reactor Project & Engineering Programs 3pp. 21708 127 24X Fiche 50-528, 83/12/05, 8401040431

8401050461 Second interim deficiency & Part 21 repts, Item 100 re solid state protection sys supplied by Westinghouse Vendor reviewing design prior to change recommendations Test procedures revised Final rept by 841230
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/12/22 O'REILLY, J. P. Region 2, Office of Director 4pp. 21730 210. 24X Fiche: 50-400, 83/12/22, 8401050461.

8401050470 Fourth interim deficiency rept, Item 117 re welding on Siemens-Allis 6 9-kV switchgear breakers Initially reported on 830211 All Class 1E breakers returned to vendor Final rept expected by 840229 Also reportable per Part 21
PARSONS, R. M. Carolina Power & Light Co. 10CFR 050 55E 83/12/28 O'REILLY, J. P. Region 2, Office of Director 4pp. 21730 201 24X Fiche 50-400, 83/12/28, 8401050470

8401050669 Part 21 rept re defect in Electroswitch Series 20k control switches Engineering completion & procurement of replacement switches expected by 840401 instead of 831231 estimated completion date
HALL, D. P. Illinois Power Co. U-0681 83/12/22 KEPPLER, J. G. Region 3, Office of Director 1p. 21733 360 24X Fiche: 50-461, 83/12/22, 8401050669.

8401060420 Fourth interim deficiency rept re potential failure of Westinghouse gate valves to close under design conditions Initially reported on 801128 Changes completed Final rept by 840301. Also reported per Part 21
PARSONS, R. M. Carolina Power & Light Co. NRC-163 83/12/29 O'REILLY, J. P. Region 2, Office of Director. 9pp. 21741 004. 24X Fiche: 50-400, 83/12/29, 8401060420.

8401100456 Interim significant Deficiency Rept 83-13 re Limitorque valve operator limit switch rotor matl Initially reported 831116. Caused by excessive shrinkage in matl in rotors Rotors replaced. Also reported per Part 21
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System BLNRC 83-0064. 83/12/22 KEPPLER, J. G. Region 3, Office of Director 2pp. 21761. 351. 24X Fiche: 50-000, 83/12/22, 8401100456

8401120223 Supplemental deficiency rept re potential deterioration of isoprene gaskets on standby diesel generators Initially reported on 821217. Unit 2 corrective actions postponed until 870326 Unit 1 work complete Also reported per Part 21
MILLS, L. M. Tennessee Valley Authority 10CFR 050 55E 84/01/05 O'REILLY, J. P. Region 2, Office of Director 1p. 21793. 260 24X Fiche: 50-438, 84/01/05, 8401120223

NONDOCKETED ITEMS

45E

B401120289 Ninth interim deficiency rept re inconsistencies in pipe break LOCA analysis Initially reported on 801121. Review of B&W alternate approaches to resolve problem in progress Also reported per Part 21 Next rept by B40430
MILLS,L.M Tennessee Valley Authority 10CFR 50.55E 84/01/05
O'REILLY,J.P Region 2, Office of Director 2pp 21792.172 24X
Fiche 50-43B,84/01/05,8401120289

B401120350 Interim Part 21 rept re failure of fuel oil mfg by Transamerica Delaval adjacent to main branch tee on Div I diesel generator Initially reported on 831230 Fuel oil line support installed Next rept by B40413
MCQUAY, J.P Mississippi Power & Light Co AECM-83/0822 84/01/03 O'REILLY,J.P Region 2, Office of Director 5pp 21792 027 24X Fiche 50-416,84/01/03,8401120350.

B401120402 Rev 3 to interim Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E not meeting overpressure requirements Initially reported on 820824 Final rept expected by 840214 Also reportable per Part 21.
VAN BRUNT,E.E. Arizona Public Service Co. DER 82-46 83/12/22
BISHOP,T.W Division of Resident,Reactor Project & Engineering Programs 3pp 21791 116 24X Fiche 50-32B,83/12/22,8401120402

B401120427 Part 21 rept re Gilbert Mfg Co nylon bolts used to make connections between positive bus & leg of distribution panel breakers Nylon bolts to be replaced w/brass bolts
PARRISH,H.O Tennessee Valley Authority 84/01/04 O'REILLY,J.P Region 2, Office of Director 4pp 21791 013 24X
Fiche 50-239,84/01/04,8401120427

B401120430 Final Deficiency Rept DER 83-52 re power supplies by Beta Products feeding noise into 125-volt dc bus Beta will install ac filter components to reduce &/or eliminate ac spike interference. Also reportable per Part 21
VAN BRUNT,E.E Arizona Public Service Co 10CFR 50.55E 83/12/22
BISHOP,T.W Division of Resident,Reactor Project & Engineering Programs 4pp 21791 071 24X Fiche 50-32B,83/12/22,8401120430

B401130053 First interim deficiency rept re Transamerica Delaval, Inc GA program Initially reported on 831206 Final configuration for control cabinet indicates drawing Revs K,L & M not incorporated Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority 84/01/05 O'REILLY,J.P Region 2, Office of Director 2pp 21802 334 24X
Fiche 50-000,84/01/05,8401130053

B401130165 Tenth interim deficiency rept re B&W nonconservative analysis of neutron flux Initially reported on 8401105
B&W rept on analysis indicates results acceptable w/o mod to plant hardware on setpoint Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority 84/01/06 O'REILLY,J.P Region 2, Office of Director 1p. 21802 032 24X
Fiche 50-43B,84/01/06,8401130165

B401130365 Final deficiency rept re setpoint program for overpressure mitigating sys Initially reported on 820321 New setpoints will be provided on 840131 by Westinghouse Also reportable under Part 21
MILLS,L.M Tennessee Valley Authority 84/01/06 O'REILLY,J.P Region 2, Office of Director 3pp 21799 337. 24X
Fiche 50-390,84/01/06,8401130365

B401160151 Final deficiency rept re cracks in Pacific Scientific PSA-1 & PSA-3 snubber capstan springs Caused by improper spring forming Snubbers will be corrected prior to completion of first refueling outage. Also reported per Part 21
CURTIS,N.W Pennsylvania Power & Light Co PLA-1991 83/12/27.
MURLEY,T.E Region 1, Office of Director 5pp 21815 327 24X
Fiche: 50-38B,83/12/27,8401160151

B401160283 Part 21 rept re defects in Anchor Darling globe valves previously identified in IE Info Notice 83-70 & OE 831216
Itr. Globe valves will be modified by OE to assure valve operability
HALL,D.P. Illinois Power Co 1605-L 84/01/09 KEPLER,J.O Region 3, Office of Director 2pp 21814 349 24X
Fiche: 50-461,84/01/09,8401160283

--B401160288 Part 21 rept re defects in Anchor Darling globe valves previously identified in IE Info Notice 83-70. "Vibration Induced Valve Failure." Set screws will be locked in place by staking stem collar threads or using locking compound
SHERWOOD,O.O General Electric Co. MC 682 83/12/14
BEYOUNG,R.C Director's Office, Office of Inspection and Enforcement 3pp. 21814-351 24X Fiche 50-461,84/01/09, 8401160283

B401170001 Final deficiency rept re pressurizer level transmitters mfg by ITT Barton w/calibr span inadequate for level process range. Initially reported on 830829 Transmitters will be adjusted & reinstalled by 840220 Also reported per Part 21
MILLS,L.M Tennessee Valley Authority 84/01/09 O'REILLY,J.P. Region 2, Office of Director 3pp. 21834.111 24X
Fiche: 50-390,84/01/09,8401170001.

B401170186 Part 21 rept re loose flexible coupling drive hubs, mfg by Lovejoy Coupling & installed by Transamerica Delaval, on shafts in overspeed governor fuel transfer pump drive insp of hubs in listed facilities recommended Utilis notified.
BOYER,R.E Transamerica Delaval, Inc 84/01/09. Director's Office, Office of Inspection and Enforcement 5pp 2182B:269 24X
Fiche 50-000,84/01/09,8401170186

B401170376 Interim Deficiency Rept PRD-84/01 re incorrect installation of 30-volt dc 22 microfarad capacitor in solid state trip unit Initially reported on 840105 Final rept by 840330. Also reported per Part 21
MCQUAY, J.P Mississippi Power & Light Co PRD-84/-01 84/01/09
O'REILLY,J.P Region 2, Office of Director 4pp 21827 131 24X
Fiche 50-416,84/01/09,8401170376

B401240254 Part 21 rept re problems w/ELMA power supplies bought as spare parts for two mods. Defective wiring, cold solder joints & overall poor quality workmanship found Parts installed only in reactor protection sys
PARRISH,H.O Tennessee Valley Authority 84/01/11 O'REILLY,J.P Region 2, Office of Director 3pp 21712:339 24X
Fiche 50-259,84/01/11,8401240254

B401240264 Final Deficiency Rept NCR 2162 re defective sequencer control cards from Consolidated Control Corp Initially reported on 830112. Failed cards returned to vendor Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority NCR 2162. 84/01/13.
O'REILLY,J.P Region 2, Office of Director. 3pp 21909 359 24X
Fiche 50-43B,84/01/13,8401240264

B401240342 Final Deficiency Rept NCR-2221 re Johnson Machine Works welds on auxiliary feedwater pump room doors. Initially reported on 830210 Doors returned to manufacturer for reworking. Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority. NCR-2221 84/01/13
O'REILLY,J.P Region 2, Office of Director 2pp. 21920.303 24X
Fiche: 50-43B,84/01/13,8401240342

B401240605 Final deficiency rept re governor lube oil cooler on standby diesel generator Initially reported on 820308 Coolers relocated to position below governor. Drawing number will be added to parts list. Also reportable per Part 21
MILLS,L.M Tennessee Valley Authority. 84/01/12 O'REILLY,J.P. Region 2, Office of Director 2pp. 21909 173 24X
Fiche 50-43B,84/01/12,8401240605

B401260248 Final Deficiency Rept DER 83-35 re inverters supplied by Elgar Found to produce voltage spikes on dc supply bus Rept will be sent to Elgar Corp for review & disposition under 10CFR21 Also reportable per Part 21
VAN BRUNT,E.E Arizona Public Service Co DER 83-35 84/01/09
BISHOP,T.W Division of Resident,Reactor Project & Engineering Programs. 4pp 21955 130 24X Fiche 50-52B,84/01/09,8401260248

B401260323 Interim deficiency rept re improper relief valve settings & design pressures & temps found in HPCI,RCIC,RHR,core spray & essential svc water sys. Initially reported on 831118
Hydrotests performed Also reported per Part 21
CURTIS,N.W Pennsylvania Power & Light Co PLA-2006 83/12/20
MURLEY,T.E Region 1, Office of Director 9pp 21955 198. 24X
Fiche 50-38B,83/12/20,8401260323

B401260341 Final Deficiency Rept DER 83-46 re manual overtorquing of Borg-Warner valve during hydrostatic testing, resulting in mounting bolt failure Corrective actions enumerated Also reportable under Part 21.
VAN BRUNT,E.E Arizona Public Service Co DER 83-46. 84/01/09
BISHOP,T.W Division of Resident,Reactor Project & Engineering Programs 4pp 21955:151 24X Fiche 50-52B,84/01/09,8401260341

B401260354 Interim deficiency rept. Item 157 re failure of actuators supplied by Rustin Mfg Co to meet functional test requirements of GH Battis Co Initially reported on 831221.
Next rept by 840220 Also reported under Part 21
PARSONS,R.M Carolina Power & Light Co NRC-169 84/01/18
O'REILLY,J.P Region 2, Office of Director. 1p. 21955:207. 24X
Fiche. 50-400,84/01/18,8401260354.

B401270251 Suppl to final deficiency rept re improper installation of cathodic protection devices on stainless steel piping.
Initially reported on 831202 Deficiency determined to be reportable per Part 21 Brown & Root, Inc will be informed.
OPREA,O.W Houston Lighting & Power Co ST-HL-AE-1047. 84/01/20
COLLINS,J.T. Region 4, Office of Director. 2pp 21982:180. 24X
Fiche. 50-49B,84/01/20,8401270251.

B401300193 Final Deficiency Rept 83-19 for Unit 1 & 83-15 for Unit 2 re pressure drop across Valan 2 1/2-inch stop check valve Initially reported on 830202 Disc drawings revised. Also reportable per Part 21.
MILLS,L.M Tennessee Valley Authority. 83-15 84/01/25
O'REILLY,J.P Region 2, Office of Director 2pp. 21977 350 24X
Fiche: 50-43B,84/01/25,8401300193

NONDOCKETED ITEMS

B401300275 Supplemental deficiency rept re Lambda power module failures Initially reported on 801218 AC26 capacitor substituted for C6 capacitor Corrective action & final rept by B40601 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 84/01/23 O'REILLY,J P
Region 2, Office of Director 1p 21995 361 24X
Fiche 50-438,84/01/23,B401300275

B401300276 Third interim deficiency rept re diesel generator rear bearing Initially reported on 830627 Actions to prevent recurrence under investigation Next rept will be submitted by B40302 Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 84/01/24 O'REILLY,J P
Region 2, Office of Director 4pp 21995 353 24X
Fiche 50-390,84/01/24,B401300276

B401300300 Final deficiency rept re check valve leak in air start sys of standby diesel generators Initially reported on 820209 Defective valves modified by replacing disc assembly per conversion procedure Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 84/01/25 O'REILLY,J P
Region 2, Office of Director 2pp 21996 352 24X
Fiche 50-438,84/01/25,B401300300

B401300325 Second interim deficiency rept re separation of front covers from Bailey meter modules Initially reported on 831004 Next rept will be submitted by B40420 Util awaiting B&W response re disposition, Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 84/01/25 O'REILLY,J P
Region 2, Office of Director 1p 21995 362 24X
Fiche 50-438,84/01/25,B401300325

IA999 QUALITY ASSURANCE INSPECTIONS

B401040385 Ack receipt of 830815 & 0928 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900054/83-01 NRC does not concur w/position that testing lab independent from ASME accepted QA program
POTAPOVS,U Region 4, Office of Director 83/12/02 SCHAU,R L
Dresser Industries, Inc. 1p 21708 050

B401040388 Responds to NRC 830718 & 0913 ltrs re nonconformance noted in GA Program Insp Rept 99900054/83-01 Capacity testing lab not in conflict w/ASME Section III & can be operated independently from Section III QA program.
BRUNSON,B O Dresser Industries, Inc 83/09/28 POTAPOVS,U
Region 4, Office of Director 1p 21708 051

B401040393 Ack receipt of 830815 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900054/83-01 Addl info requested re capacity testing lab in relation to QA program.
POTAPOVS,U Region 4, Office of Director 83/09/13 SCHAU,R L
Dresser Industries, Inc 1p 21708 052

B401040395 Responds to NRC 830718 ltr re nonconformance noted in GA Program Insp Rept 99900054/83-01 Corrective actions all stds will be purchased w/statement of NBS traceability & special torque wrench adapters designed for torquing stud nuts.
BRUNSON,B O Dresser Industries, Inc 83/08/15 POTAPOVS,U
Region 4, Office of Director 5pp 21708 053

B401040433 Ack receipt of 831121 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900716/83-01
POTAPOVS,U Region 4, Office of Director 83/12/16 YARGES,R J
Ruskin Manufacturing Co. 1p 21708 122

B401040438 Responds to NRC 831101 ltr re nonconformance noted in GA Program Insp Rept 99900716/83-01 Corrective actions Section 206 & notice describing regulations reposted.
YARGES,R J Ruskin Manufacturing Co. 83/11/21 POTAPOVS,U
Region 4, Office of Director 4pp 21708 123

B401040482 Ack receipt of 830929 & 1117 ltrs informing NRC of steps taken to correct violations & nonconformance noted in GA Program Insp Rept 99900924/83-01
POTAPOVS,U Region 4, Office of Director 83/12/06 CHIN,A
Radiation Sterilizers, Inc. 1p 21705 338

B401040488 Responds to NRC 830909 ltr re violation & nonconformance noted in GA Program Insp Rept 99900924/83-01 Corrective actions: GA manual being prepared Completion expected by 831130
CHIN,A Radiation Sterilizers, Inc. 83/09/26 POTAPOVS,U
Region 4, Office of Director 4pp 21705 339

B401040492 Ack receipt of 830929 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900924/83-01 Addl info requested within 25 days of receipt of ltr
POTAPOVS,U Region 4, Office of Director 83/10/19 CHIN,A
Radiation Sterilizers, Inc 2pp 21705 343

B401040498 Responds to NRC 831019 ltr re deviation noted in GA Program Insp Rept 99900924/83-01 Corrective actions Procedure 30 revised incorporating comments GA manual comments will be available by next scheduled visit
CHIN,A Radiation Sterilizers, Inc 83/11/08 POTAPOVS,U
Region 4, Office of Director 3pp 21705 345

B401040545 Ack receipt of 830922 & 1206 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900053/83-02
POTAPOVS,U Region 4, Office of Director 83/12/28 CARDN,A E
Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc) 1p 21706 318

B401040550 Responds to NRC 831115 ltr re nonconformance noted in GA Program Insp Rept 99900053/83-02 Corrective actions personnel reinstruction documented by 830908 interofc correspondence
KNIESER,G W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) 83/12/06 POTAPOVS,U Region 4, Office of Director 2pp 21706 319

B401040555 Ack receipt of 830922 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900053/83-02 Addl info requested within 25 days
POTAPOVS,U Region 4, Office of Director 83/11/15 CARDN,A E
Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc) 1p 21706 321.

B401040558 Responds to nonconformance noted in GA Program Insp Rept 99900053/83-02 Corrective actions responsible personnel restructured on necessity to initial & date changes
KNIESER,G W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc) 83/09/22 POTAPOVS,U Region 4, Office of Director 1p 21706 322

B401050147 Forwards GA Program Insp Rept 99900070/81-02 on 811207-11 Nonconformance noted
POTAPOVS,U Region 4, Office of Director 83/12/08 MILLER,J W
Associated Piping & Engineering Corp 2pp 21727 336.

B401050152 GA Program Insp Rept 99900070/81-02 on 811207-11 Noncompliance noted: 21 instances of radiographer altering of radiographs of thin wall small diameter ASME Section III, Class 2 stainless steel piping
DRISKILL,D D, ROBERDS,H W, POTAPOVS,U Region 4, Office of Director 82/02/22 2pp 21727 338

B401050190 Forwards GA Program Insp Rept 99900224/83-02 on 830912-16 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/12/06 KEYES,M A
Bailey Controls Co (subs of Babcock & Wilcox Co) 2pp 21727 255

B401050194 Notice of nonconformance from insp on 830912-16.
* Region 4, Office of Director 83/12/06 1p 21727 257

B401050197 GA Program Insp Rept 99900224/83-02 on 830912-16 Noncompliance noted preliminary rept of safety concerns not prepared & safety concern classification not identified
HAMILTON,J W, BARNES,I Region 4, Office of Director 83/11/29 14pp 21727 258

B401050214 Forwards GA Program Insp Rept 99900797/83-01 on 831031-1104 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/12/06 CLARK,M J
Teledyne McKay 2pp 21728 129

B401050217 Notice of nonconformance from insp on 831031-1104
* Region 4, Office of Director 83/12/06 4pp 21728 131

B401050222 GA Program Insp Rept 99900797/83-01 on 831031-1104 Noncompliance noted Rev 3 to GA Procedure 701 being used at work stations, whereas Rev 4 had been issued 811216 & electrode shop orders not signed & dtd by test welder.
CONWAY,J T BARNES,I Region 4, Office of Director 83/12/02 10pp 21728 133.

B401050224 Forwards GA Program Insp Rept 99900255/83-01 on 831031-1103 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/12/06 HADNAQY,P A
Pacific Scientific 2pp 21729 086

B401050226 Notice of nonconformance from insp on 831031-1103.
* Region 4, Office of Director 83/12/06 1p 21729 088.

NONDOCKETED ITEMS

45

- B401050232 GA Program Insp Rept 99900255/83-01 on 831031-1103 Noncompliances noted no subcontractor certificate of call by for SN-8C-30 coordinate measuring machine maintained Capstan spring supplier not on approved supplier list.
OLLER, R E., HAMILTON, J W., HALE, C J Region 4, Office of Director 83/12/01. 17pp 21729 087
- B401050228 Forwards GA Program Insp Rept 99900921/83-02 on 830808-12 No noncompliance noted
POTAPDOVS, U Region 4, Office of Director 83/12/06 SAOQIOMO, A J Franklin Institute/Franklin Research Center 2pp 21728 199.
- B401050237 GA Program Insp Rept 99900921/83-02 on 830808-12 No noncompliance noted Major areas inspected test repts & associated data packages re testing accomplished at lab for various nuclear cable manufacturers
SMITH, A L., PHILLIPS, H B Region 4, Office of Director 83/12/01 7pp. 21728 201
- B401090241 Ack receipt of 831129 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900819/83-01
POTAPDOVS, U Region 4, Office of Director 83/12/30 GRUNTHALER, G H Guyon Alloys, Inc 1p 21753 359
- B401090248 Responds to NRC 831104 ltr re nonconformance noted in GA Program Insp Rept 99900819/83-01 Corrective actions West Jersey Mfg Co certified matl test rept verifying flange conformance to ASME Section III, Class 2
GRUNTHALER, G H Guyon Alloys, Inc 83/11/29. POTAPDOVS, U. Region 4, Office of Director 3pp 21753 360
- B401090317 Confirms GA program insp at Boston, MA & Cherry Hill, NJ ofcs on 840123-27 & 0204-10, respectively, per 831228 telcon
POTAPDOVS, U Region 4, Office of Director 83/12/30 KELLY, R B. Stone & Webster Engineering Corp 1p 21754 191
- B401090483 Ack receipt of 830901, 1005 & 1201 ltrs informing NRC of steps taken to correct nonconformance & violation noted in GA Program Insp Rept 99900831/83-01
POTAPDOVS, U Region 4, Office of Director 83/12/30 PLEUNIK, B ICD Puerto Rico, Inc 1p 21753 128
- B401090487 Responds to NRC 831108 ltr re nonconformance noted in GA Program Insp Rept 99900831/83-01 Corrective actions GCI review schedule will be established by 840116 & all GCI will be reviewed by 841231
PLEUNIK, B J ICD Puerto Rico, Inc. 83/12/01. POTAPDOVS, U. Region 4, Office of Director 2pp 21753 129
- B401090489 Ack receipt of 830901 & 1005 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900831/83-01 Addl info re mechanical gauges requested within 25 days of ltr date
POTAPDOVS, U. Region 4, Office of Director 83/11/08 PLEUNIK, B ICD Puerto Rico, Inc 1p 21753 131
- B401090491 Responds to NRC 830805 ltr re violation noted in GA Program Insp Rept 99900831/83-01 Corrective actions revised poster received & posted on 830822 Extension to 831005 for responses to nonconformance items requested
PLEUNIK, B J. ICD Puerto Rico, Inc. 83/09/01 POTAPDOVS, U. Region 4, Office of Director 1p 21753 132
- B401090493 Responds to NRC 830805 ltr re nonconformance noted in GA Program Insp Rept 99900831/83-01 Corrective actions suppl to Westinghouse Switchgear Div GA manual will be provided by 840227
PLEUNIK, B. J. ICD Puerto Rico, Inc. 83/10/05 POTAPDOVS, U Region 4, Office of Director 3pp 21753 133
- B401090486 Ack receipt of 831214 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900104/83-02
POTAPDOVS, U. Region 4, Office of Director 83/12/30. MILLER, T. D. Westinghouse Electric Corp 1p. 21753 122
- B401090488 Responds to NRC 831118 ltr re nonconformance noted in GA Program Insp Rept 99900104/83-02. Corrective actions' sequence of operations & weld status sheets completed. No proprietary info encl.
MILLER, T. D Westinghouse Electric Corp PA-83-099 83/12/14 POTAPDOVS, U Region 4, Office of Director 3pp 21753 123.
- B401090525 Ack receipt of 831007 & 1128 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900021/83-01
POTAPDOVS, U Region 4, Office of Director 83/12/30. BOWEN, J E Pullman, Inc 1p. 21753 097
- B401090526 Responds to NRC 831110 ltr re nonconformance noted in GA Program Insp Rept 99900021/83-01. Corrective actions audits will be conducted on rotating basis
GERWIN, E F Pullman, Inc 83/11/28 POTAPDOVS, U Region 4, Office of Director 1p 21753 100
- B401090530 Ack receipt of 831012 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900021/83-01 Clarification of criteria used for site audit requested
POTAPDOVS, U Region 4, Office of Director 83/11/10 BOWEN, J E Pullman, Inc 1p 21753 101
- B401090532 Responds to NRC 830916 ltr re nonconformance noted in GA Program Insp Rept 99900021/83-01 Corrective actions mgt audit conducted annually, auditors advised of nonconformance & instructed to assure full compliance w/procedures
GERWIN, E F Pullman, Inc 83/10/07 POTAPDOVS, U. Region 4, Office of Director 3pp 21753 102
- B401100250 Ack receipt of 830509 & 0720 ltrs informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900279/83-01
POTAPDOVS, U Region 4, Office of Director. 83/11/15 KENNEDY, G. Gould, Inc 1p 21759 217.
- B401100253 Responds to NRC 830617 ltr re violation & nonconformance noted in GA Program Insp Rept 99900279/83-01 Reaffirms position that no violation exists. Commitment to inspect two size KM breakers will be honored.
NELSON, R E Gould, Inc. 83/07/20. POTAPDOVS, U Region 4, Office of Director 1p. 21759 218
- B401100255 Ack receipt of 830509 ltr informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900279/83-01 Addl info required, per 830519 telcon Requested data for completion of corrective action needed.
POTAPDOVS, U Region 4, Office of Director. 83/06/17. KENNEDY, G Gould, Inc 1p 21759 219.
- B401100256 Responds to NRC 830411 ltr re violation & nonconformance noted in GA Program Insp Rept 99900279/83-01. Corrective actions, two KM breakers located in motor control ctrs will be inspected during next routine svc visit at site
KENNEDY, G P, Gould, Inc. 83/05/09 Region 4, Office of Director 4pp. 21759 220
- B401100424 Ack receipt of 830117 & 0325 ltrs requesting NRC withhold entire GA Investigation Rept 99900275/82-01 & associated documents Request denied Rept & documents will be in PDR, except for info determined proprietary
POTAPDOVS, U. Region 4, Office of Director. 83/09/16 PALKO, G Reuter-Stokes, Inc. 2pp 21761 238
- B401100437 Responds to NRC 830225 ltr re 830117 request to withhold portions of rept & related documents requested withheld due to proprietary nature of matl
PALKO, G Reuter-Stokes, Inc 83/03/25. POTAPDOVS, U. Region 4, Office of Director. 2pp. 21761 240
- B401100445 Ack receipt of 830309 ltr & subsequent telcon re agreement to extend time for proprietary review of GA Investigation Rept 99900275/82-01 from 1 wk to 30 days Extension to 830330 granted
POTAPDOVS, U. Region 4, Office of Director 83/03/24 PALKO, G Reuter-Stokes, Inc 1p 21761 242
- B401100453 Confirms 830307 telcon request for time extension from 1 wk to 30 days for proprietary review of GA Investigation Rept 99900275/82-01 & associated documents. Response requested.
PALKO, G Reuter-Stokes, Inc. 83/03/09 POTAPDOVS, U. Region 4, Office of Director 2pp. 21761 243.
- B401100462 Ack receipt of 830117 ltr requesting that GA Investigation Rept 99900275/82-01, including Documents 11, 27 & 35, be withheld per 10CFR2.790. Sufficient specific info re proprietary portions of rept must be provided within 1 wk.
POTAPDOVS, U. Region 4, Office of Director. 83/02/25. PALKO, G Reuter-Stokes, Inc 2pp. 21761 245.
- B401100467 Requests that GA Investigation Rept 99900275/82-01 & associated documents be withheld per 10CFR2.790 for listed reasons.
PALKO, G Reuter-Stokes, Inc 83/01/17. POTAPDOVS, U. Region 4, Office of Director 3pp 21761 247.
- B401100477 Confirms 821216 telcon understandings re request for exemption from disclosing GA Investigation Rept 99900275/82-01.
KEHPE, R. A. Reuter-Stokes, Inc 82/12/23. HERR, R. Region 4, Office of Director. 1p. 21761 250

NONDOCKETED ITEMS

- 8401100482 Forwards QA Investigation Rept 99900275/82-01 on 820621-25 POTAPOVS,U. Region 4, Office of Director 82/12/10 SIMON,R Rauter-Stokes, Inc. 2pp 21761:231
- 8401100487 QA Investigation Rept 99900275/82-01 on 820621-25, based on allegations that employees cannot have film badges assigned & that seismic testing failed to meet proper stds All but film badge allegation unsubstantiated Info deleted HERR,R K Office of Investigation PARKER,L B Region 4, Office of Director SHATTERLY,L W Region 3, Office of Director 82/11/08 27pp 21761:253
- 8401130028 Forwards QA Program Insp Rept 99900283/83-02 on 830829-0902 & notice of nonconformance POTAPOVS,U. Region 4, Office of Director. 83/12/16 MANCHESTER,E BIW Cable Systems, Inc. 2pp 21803:018
- 8401130034 Notice of nonconformance from insp on 830829-0902 * Region 4, Office of Director 83/12/16 1p 21803:020
- 8401130041 QA Program Insp Rept 99900283/83-02 on 830829-0902 Noncompliance noted, adequate documentation neither available nor presented to NRC inspector during insp of type test data files. PARKER,L.B., PHILLIPS,H S Region 4, Office of Director 83/11/24 16pp. 21803:021.
- 8401130039 Ack receipt of 830926,1003,1130 & 1215 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900832/83-01. POTAPOVS,U. Region 4, Office of Director 84/01/06 JERBE,J Power Breakers, Inc. 1p. 21802:357
- 8401130042 Responds to NRC 831108 ltr re nonconformance noted in QA Program Insp Rept 99900832/83-01 Corrective actions, manager of QC engineering will review QC insp checklists. JERBE,J L Power Breakers, Inc 83/12/15 POTAPOVS,U Region 4, Office of Director. 2pp 21802:358
- 8401130046 Confirms 831128 telcon request for 25-day extension to respond to 831108 request for addl info re QA Program Insp Rept 99900832/83-01. FUENTES,J. Power Breakers, Inc. 83/11/30 POTAPOVS,U Region 4, Office of Director 1p 21802:360.
- 8401130051 Ack receipt of 831003 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900832/83-01 Addl info on Items A,B,2 & 9 requested in 25 days. POTAPOVS,U. Region 4, Office of Director. 83/11/08 JERSE,J Power Breakers, Inc 1p 21802:361.
- 8401130055 Responds to NRC 830831 ltr re nonconformance noted in QA Program Insp Rept 99900832/83-01 Corrective actions: procedure developed to assure compliance w/10CFR21 reporting requirements JERBE,J.L. Power Breakers, Inc 83/10/03 POTAPOVS,U. Region 4, Office of Director 18pp 21802:362
- 8401130073 Ack receipt of 831209 ltr informing NRC of steps taken to correct nonconformances & violations noted in QA Program Insp Rept 99900396/83-01. POTAPOVS,U Region 4, Office of Director 84/01/06 SEBHAGIRI,M L. CLON Corp. 1p 21802:318
- 8401130107 Responds to NRC 831013 ltr re nonconformances & violations noted in QA Program Insp Rept 99900396/83-01 Corrective actions: Weld Procedure EP8 30-60-810, Rev B requalified under revised amperage rate & released to depts. SEBHAGIRI,M L CLON Corp 83/12/09. SUTTON,J W. Region 4, Office of Director. 3pp 21802:319
- 401130163 Ack receipt of 831213 ltr informing NRC of steps taken to correct violation & nonconformance noted in QA Program Insp Rept 99900822/83-01 POTAPOVS,U Region 4, Office of Director. 83/01/04 ALTON,J R. Coffer Corp. 1p. 21802:202
- 8401130168 Responds to NRC 831115 ltr re violation & nonconformance noted in QA Program Insp Rept 99900822/83-01. Corrective actions: current copy of 10CFR21 will be posted & manual revised to reflect mfg order info ALTON,J.R. Coffer Corp. 83/12/13. Region 4, Office of Director. 8pp 21802:203.
- 8401130186 Forwards QA Program Insp Rept 99900903/83-02 on 831031-1104 & notice of nonconformance. POTAPOVS,U Region 4, Office of Director 83/12/16 BADLIER,R.C Wyle Laboratories. 2pp. 21802:012.
- 8401130189 Notice of nonconformance from insp on 831031-1104 * Region 4, Office of Director 83/12/16 2pp 21802:014
- 8401130195 QA Program Insp Rept 99900903/83-02 on 831031-1104 Noncompliance noted failure to describe or implement document control instructions for control, review, approval & distribution of engineering manual procedures AGE,J R, PHILLIPS,H S Region 4, Office of Director 83/12/09 11pp 21802:016
- 8401130188 Ack receipt of 831019 & 1130 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900060/83-02 POTAPOVS,U Region 4, Office of Director 83/12/30 PATTARINI,D M Target Rock Corp 1p 21802:006
- 8401130191 Responds to NRC 831117 request for addl info re nonconformance noted in QA Program Insp Rept 99900060/83-02 Production control supervisor advised not to revise or alter existing sys w/o conferring w/QA manager ABRUZZO,G A Target Rock Corp 83-264. 83/11/30 POTAPOVS,U Region 4, Office of Director 2pp 21802:007
- 8401130197 Ack receipt of 831019 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900060/83-02 Addl info re actions taken or planned for Items A & B requested POTAPOVS,U Region 4, Office of Director 83/11/17 PATTARINI,D M. Target Rock Corp 1p 21802:009
- 8401130204 Responds to NRC 831006 ltr re nonconformance noted in QA Program Insp Rept 99900060/83-02 Corrective actions: QA manual revised & procedures released via TRGC Form 54 not approved prior to use. ABRUZZO,G A Target Rock Corp 83-239 83/10/19. POTAPOVS,U Region 4, Office of Director 2pp 21802:010
- 8401130199 Confirms telcon re items in audit rept on FBI quality sys audit. Extension of response time period until 841007 appreciated FLOOD,R W General Electric Co 83/09/26 MCNEILL,W Region 4, Office of Director 1p 21801:360
- 8401130205 Confirms QA program insp at Ramsey & Passaic, NJ plants on 840116-20, per 840104 telcon POTAPOVS,U Region 4, Office of Director 84/01/06 BRODEUR,R J Okanite Co 1p 21801:348
- 8401130226 Forwards QA Program Insp Rept 99900909/83-01 on 831011-14 & notice of nonconformance. POTAPOVS,U Region 4, Office of Director 83/12/13 BESSEY,R L Southwest Research Institute 2pp. 21801:202
- 8401130230 Notice of nonconformance from insp on 831011-14 * Region 4, Office of Director 83/12/13. 2pp 21801:204.
- 8401130235 QA Program Insp Rept 99900909/83-01 on 831011-14. Noncompliance noted deviation/nonconformance repts not filled out for deviations from test procedures for qualification testing HUBBARD,G T, PHILLIPS,H S Region 4, Office of Director 83/12/06 13pp 21801:206
- 8401130262 Forwards QA Program Insp Rept 99900829/83-01 on 831115-17 & notices of violation & nonconformance POTAPOVS,U Region 4, Office of Director. 83/12/16 STAPLETON,G P General Electric Co 3pp 21799:291
- 8401130264 Notice of violation from insp on 831115-17 * Region 4, Office of Director 83/12/16 1p. 21799:294
- 8401130267 Notice of nonconformance from insp on 831115-17 * Region 4, Office of Director 83/12/16 2pp. 21799:295
- 8401130271 QA Program Insp Rept 99900829/83-01 on 831115-17. Violation noted. 10CFR21 manual available for exam outdated. Nonconformance noted quality mgt manual not reviewed annually as required. FOSTER,W E., BARNES,I. Region 4, Office of Director. 83/12/13 8pp 21799:297.
- 8401130348 Forwards QA Program Insp Rept 99900369/83-02 on 831031-1104 & notices of nonconformance & violation POTAPOVS,U Region 4, Office of Director. 83/12/16 NAUMANN,H R Automatic Switch Co 3pp 21799:255.
- 8401130350 Notice of violation from insp on 831031-1104. * Region 4, Office of Director. 83/12/16 1p 21799:258

NONDOCKETED ITEMS

459

--B401130352 Notice of nonconformance from insp on B31031-1104
* Region 4, Office of Director 83/12/16 2pp 21799 259

--B401130354 GA Program Insp Rept 99900369/83-02 on B31031-1104 Violation noted 10CFR21 requirements not imposed on Purchase Orders PV21914, PV22712 & PV85589 Nonconformance noted 10CFR50, App B requirements not imposed on PV85589 HUBBARD, O T, PHILLIPS, H S Region 4, Office of Director 83/12/09 14pp 21799 261

B401130369 Forwards GA Program Insp Rept 99900277/83-02 on B30620-23 & 99900277/83-04 on B30816-17 & notices of nonconformance POTAPQVS, U Region 4, Office of Director 83/12/05 REED, E S Rockbestos Co 3pp 21798 317

--B401130371 Notice of nonconformance from insp on B30620-23.
POTAPQVS, U Region 4, Office of Director 83/12/05 2pp 21798 320.

--B401130372 GA Program Insp Rept 99900277/83-02 on B30620-23. Noncompliance noted failure to establish & implement adequate GA program for safety-related equipment qualification testing SMITH, A L, PHILLIPS, H S Region 4, Office of Director 83/11/01 27pp 21798 322

--B401130375 Notice of nonconformance from insp on B30816-17
* Region 4, Office of Director 83/12/05 1p 21798 349

--B401130376 GA Program Insp Rept 99900277/83-04 on B30816-17 Noncompliance noted records not maintained to furnish evidence that activities affecting quality performed SMITH, A L, PHILLIPS, H S Region 4, Office of Director 83/11/01 7pp. 21798 350

B401130380 Forwards GA Program Insp Rept 99900503/83-04 on B31114-17 No noncompliance noted POTAPQVS, U Region 4, Office of Director 83/12/20 ROE, K. Burns & Roe Co 2pp 21799 280

--B401130382 GA Program Insp Rept 99900503/83-04 on B31114-17. No noncompliance noted Major areas inspected status of previous insp findings. 10CFR21 repts re reactor bldg blocked vent paths & insufficient flow to HX SEARS, P M, MADSEN, O L Region 4, Office of Director. 83/12/15 9pp 21799 282

B401170228 Confirms GA program insp at San Francisco Power Div plant on B40116-19, per B40109 telcon POTAPQVS, U Region 4, Office of Director 84/01/12 STATTON, C D Bechtel Corp 1p 21831 350

B401170256 Forwards GA Program Insp Rept 99900902/83-03 for info & evaluation Ack requested, w/o encl JOHNSON, E H Region 4, Office of Director. 83/11/29 LEDDICK, R S Louisiana Power & Light Co 1p 21832 121 24X Fiche 50-382, 83/11/29, B401170256

B401170277 Forwards GA Program Insp Rept 99900509/83-02 on B31017-21. No noncompliance noted POTAPQVS, U, Region 4, Office of Director 83/12/23, KELLY, R B Stone & Webster Engineering Corp 2pp. 21832 104

--B401170282 GA Program Insp Rept 99900909/83-02 on B31017-21. No noncompliance noted Major areas inspected, computer program procurement practices & error in rotational response spectra for Mark II containment SEARS, P M, MADSEN, O Region 4, Office of Director 83/12/14 15pp. 21832 106.

B401170312 Forwards GA Program Insp Rept 99900902/83-03 re quality & acceptability of product or svc provided by vendor Receipt ack requested w/o encl JOHNSON, E H Region 4, Office of Director 83/11/29 OPREA, O W Houston Lighting & Power Co, 1p. 21833 285. 24X Fiche 50-498, 83/11/29, B401170312

B401170318 Forwards GA Program Insp Rept 99900404/83-03 on B31017-21 No noncompliance noted. POTAPQVS, U Region 4, Office of Director. 83/12/13 SLEMBER, R J Westinghouse Electric Corp 2pp 21831 143.

--B401170325 GA Program Insp Rept 99900404/83-03 on B31017-21. No noncompliance noted Major areas inspected NBSB model used for seismic analysis & W-NTD DB-50 reactor trip breaker undervoltage trip attachment BRICKLEY, R H, MADSEN, O L Region 4, Office of Director. 83/12/06 13pp. 21831 145.

B401170333 Forwards GA Program Insp Rept 99900277/83-03 on B30809-12 & 18-19 & notice of nonconformance POTAPQVS, U Region 4, Office of Director 83/12/20 REED, E S Rockbestos Co 3pp. 21831 080

--B401170337 Notice of nonconformance from insp on B30809-12 & 18-19
* Region 4, Office of Director 83/12/20 3pp 21831 083

--B401170341 GA Program Insp Rept 99900277/83-03 on B30809-12 & 18-19. Noncompliance noted procedure for calibr of irradiation units not followed & all completed test data Sheets B not reviewed FOSTER, W E, BARNES, I Region 4, Office of Director 83/12/20. 23pp 21831 086

B401170354 Ack receipt of B31216 request for extension to B31231 response to Nonconformance B per GA Program Insp Rept 99900537/83-01. NRC erroneously ack extension for Nonconformance A Requests adjustment to records SKJEI, R E URS Corp. 84/01/04 POTAPQVS, U Region 4, Office of Director 1p. 21828 343

B401170407 Ack receipt of B31025 ltr informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900780/82-01 POTAPQVS, U Region 4, Office of Director. 84/01/09. STEVENSON, J O. Magnetrol International, Inc. 1p 21828 294.

B401170410 Forwards GA Program Insp Rept 99900740/83-01 on B31024-28. No noncompliance noted. POTAPQVS, U Region 4, Office of Director 83/12/13 DUVAL, D D Brown Boveri Corp (subs. of Brown Boveri & Co., Ltd.), 2pp 21828 258

--B401170415 GA Program Insp Rept 99900740/83-01 on B31024-28. No noncompliance noted. Major areas inspected equipment deficiencies reported under 10CFR50 55(w) & Part 21 & in LERs. FOSTER, W E, BARNES, I Region 4, Office of Director. 83/11/29 9pp 21828 260

B401170439 Confirms GA program insp at Windsor, CT plant on B40117-20, per B40109 telcon. POTAPQVS, U Region 4, Office of Director. 84/01/12 ETHERIDGE, H R. Combustion Engineering, Inc 1p. 21827 102

B401230170 Forwards GA Program Insp Rept 999000832/83-01 for evaluation of significance of reported finding w/regard to quality & acceptability of product or svc provided by vendor. w/o encl. OAGLIARDO, J E Region 5, Office of Director. 84/01/16 KOESTER, O L Kansas Gas & Electric Co 2pp 21884 307 24X Fiche 50-482, 84/01/16, B401230170.

B401230193 Forwards GA Program Insp Rept 99900404/83-02 for info & action. Util should evaluate significance of reported findings re quality & acceptability of product or svc provided by vendor. w/o encl OAGLIARDO, J E Region 4, Office of Director 84/01/16. KOESTER, O L Kansas Gas & Electric Co. 2pp. 21884 151. 24X Fiche 50-482, 84/01/16, B401230193

B401230196 Forwards GA Program Insp Rept 99900525/83-04 on B31107-11 & 14-18 No noncompliance noted POTAPQVS, U Region 4, Office of Director. 83/12/23 LORENZ, H Oilbert/Commonwealth Cos. 2pp. 21884 128.

--B401230202 GA Program Insp Rept 99900525/83-04 on B31107-11 & 14-18 No noncompliance noted. Major areas inspected: design of exhaust sys for diesel generator & HPCB diesels. HARRELL, P H, MADSEN, O L Region 4, Office of Director. 83/12/20. 21pp. 21884 130

B401230197 Forwards GA Program Insp Rept 99900255/83-01 for evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor w/o encl. OAGLIARDO, J E Region 4, Office of Director. 84/01/16. KOESTER, O L Kansas Gas & Electric Co 2pp. 21884 126 24X Fiche 50-482, 84/01/16, B401230197

B401230208 Forwards GA Program Insp Rept 99900033/83-01 on B30927-28 & 1017-21 & notices of nonconformance & violation. POTAPQVS, U Region 4, Office of Director. 83/12/13. RUPPEL, H D. Westinghouse Electric Corp 3pp. 21884 095.

--B401230210 Notice of violation from insp on B30927-28 & 1017-21
* Region 4, Office of Director 83/12/13. 1p. 21884 098.

--B401230214 Notice of nonconformance from insp on B30927-28 & 1017-21
* Region 4, Office of Director. 83/12/13 2pp 21884 099.

NONDOCKETED ITEMS

- B401230220 QA Program Insp Rept 99900033/83-01 on 830927-28 & 1017-21 Noncompliance noted reactor coolant pump seal procurement documents did not include applicability of 10CFR21 & did not pass requirements for seal housings MCNEIL, W.M., BARNES, I Region 4, Office of Director 83/11/29. 15pp 21884 101
- B401230218 Forwards QA Program Insp Rept 99900319/83-02 for evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendor W/o encl 0A0LIARDO, J E Region 4, Office of Director 84/01/16 KOSTER, Q.L. Kansas Gas & Electric Co 2pp 21884 086 24X Fiche 50-482, 84/01/16, B401230218
- B401230224 Ack receipt of 831214 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900503/83-03 POTAPOVS, U Region 4, Office of Director 84/01/16 ROE, K K Burns & Roe Co ip. 21884 080
- B401230228 Responds to NRC 831115 ltr re nonconformance noted in QA Program Insp Rept 99900503/83-03 Corrective actions engineering & design personnel admonished to exercise greater care when performing design review ROE, K.K. Burns & Roe Co 83/12/14. POTAPOVS, U Region 4, Office of Director. 2pp. 21884 081
- B401230281 Forwards QA Program Insp Rept 99900769/83-02 on 831114-17 & notice of nonconformances Responses requested within 30 days. POTAPOVS, U Region 4, Office of Director. 83/12/23 HESS, L.R. Pacific Air Products Co 2pp. 21883 343.
- B401230287 Notice of nonconformances from insp on 831114-17 * Region 4, Office of Director. 83/12/23 ip 21883.345
- B401230296 QA Program Insp Rept 99900769/83-02 on 831114-17. Noncompliances noted active QC inspector not recertified at end of effective period & final documentation insp operation for shipped dampers not initialed OLLER, R.E., HALE, C.J. Region 4, Office of Director 83/12/19 11pp. 21883.346.
- B401230282 Ack receipt of 831213 ltr informing NRC of steps taken to correct violations & nonconformances noted in QA Program Insp Rept 99900346/83-01 POTAPOVS, U Region 4, Office of Director 84/01/11 FRANCOIS, E.I. Valen Valve Co. ip 21883 357
- B401230291 Responds to NRC 831114 ltr re violation & nonconformances noted in QA Program Insp Rept 99900346/83-01 Corrective actions copy of 10CFR21 posted Field svc repts re jamming disc given to engineering supervisor. FRANCOIS, E.I. Valen Valve Co 83/12/13 POTAPOVS, U Region 4, Office of Director. 2pp 21883.358.
- B401230320 Ack receipt of 831214 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900911/83-03 POTAPOVS, U Region 4, Office of Director 84/01/12 BRUQUEMAN, W.M. General Electric Co ip 21883 307.
- B401230329 Responds to NRC 831117 ltr re nonconformances noted in QA Program Insp Rept 99900911/83-03 Corrective actions. deviation log implemented to record nonconformances Engineering work authorization revised to include dwells. BOHL, L.S. General Electric Co 83/12/14. POTAPOVS, U Region 4, Office of Director ip 21883.308
- B401230358 Ack receipt of 831221 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900917/83-01. POTAPOVS, U Region 4, Office of Director 84/01/16 SMEDIRA, C. Neutron Products, Inc. ip. 21884.249.
- B401230359 Responds to NRC 830722 & 1017 ltrs re nonconformance noted in QA Program Insp Rept 99900917/83-01. Corrective actions: new procedures written for 16 applicable criteria of 10CFR50, App B re environ qualification testing. BAKER, E.L. Neutron Products, Inc. 83/12/21 POTAPOVS, U Region 4, Office of Director ip. 21884.250
- B401230361 Ack receipt of 830922 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900917/83-01. If no nuclear work performed, no response to notice of nonconformance required POTAPOVS, U. Region 4, Office of Director. 83/10/17. SMEDIRA, C. Neutron Products, Inc. ip. 21884.251
- B401230364 Responds to NRC 830722 ltr re nonconformance noted in QA Program Insp Rept 99900917/83-01 Refutes item of noncompliance Revamped QA program for radiation testing to be submitted by Feb 1984 SMEDIRA, C. Neutron Products, Inc 83/07/22 POTAPOVS, U Region 4, Office of Director ip 21884 252
- B401230371 Forwards QA Program Insp Rept 99900209/83-02 of Bergen-Paterson pipe support for info Util should evaluate significance of findings re quality & accountability of vendor product/svc Receipt form encl W/o rept 0A0LIARDO, J E Region 4, Office of Director 84/01/16 KOSTER, Q.L. Kansas Gas & Electric Co 2pp 21877 353 24X Fiche 50-482, 84/01/16, B401230371
- B401230377 Ack receipt of 831209 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900501/83-03 POTAPOVS, U Region 4, Office of Director 84/01/11 WAHL, H W Bechtel Corp ip 21878 239
- B401230380 Responds to NRC 831117 ltr re nonconformance noted in QA Program Insp Rept 99900501/83-03 Corrective actions. training class provided to engineering & QA personnel explaining addl instructions for planning & scoping investigations WAHL, H W Bechtel Corp 83/12/09 POTAPOVS, U Region 4, Office of Director 2pp 21878 240
- B401230381 Ack receipt of 831205 ltr informing NRC of steps taken to correct nonconformance & violation noted in QA Program Insp Rept 99900930/83-01. POTAPOVS, U Region 4, Office of Director. 84/01/12 SUAGEE, F F Research Dynamics, Inc ip 21879 164
- B401230383 Responds to NRC 831110 ltr re nonconformance & violation noted in QA Program Insp Rept 99900930/83-01 Corrective actions encl Procedure RDI-IP-001, "Procedures for Implementing Requirements of 10CFR21," developed SUAGEE, F F. Research Dynamics, Inc RDI-NRCO-001 83/12/05 POTAPOVS, U Region 4, Office of Director 5pp 21879 165
- B401230386 Procedure RDI-IP-001, "Procedures for Implementing Requirements of 10CFR21, Reporting of Defects & Noncompliance " * Research Dynamics, Inc 83/10/06 5pp 21879 170
- B401230430 Ack receipt of 831103 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900500/83-01 POTAPOVS, U. Region 4, Office of Director 84/01/16 REINSCH, H O Bechtel Corp ip. 21882 315
- B401230436 Responds to NRC 831006 ltr re nonconformance noted in QA Program Insp Rept 99900500/83-01 Corrective actions Procedure AD-1.9 revised to require that all supplier performance evaluation repts be reviewed REINSCH, H O Bechtel Corp. 83/11/03 POTAPOVS, U Region 4, Office of Director 8pp 21882 316
- B401230457 Ack receipt of 831208 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900401/83-03 Nonconformance w/Section 17 & of Topical Rept CENPD-210A rescinded POTAPOVS, U Region 4, Office of Director 84/01/09 ETHERIDGE, M R Combustion Engineering, Inc ip 21882 149
- B401230465 Responds to NRC 831108 ltr re nonconformance noted in QA Program Insp Rept 99900401/83-03 Corrective actions design change implemented to prevent actuation of plant protection sys upon removal of any single connector. ETHERIDGE, M R Combustion Engineering, Inc 83/12/08 POTAPOVS, U Region 4, Office of Director. 3pp 21882.150
- B401230484 Forwards QA Program Insp 99900539/83-01 on 831107-14 & notices of nonconformance & violation POTAPOVS, U Region 4, Office of Director. 83/12/23 ALLEN, R.D. MATSCO (subs. of Multi-Amp Corporation). 2pp. 21882.116
- B401230496 Notice of violation from insp on 831107-14. * Region 4, Office of Director 83/12/23 ip 21882.118
- B401230499 Notice of nonconformance from insp on 831107-14 * Region 4, Office of Director. 83/12/23. ip. 21882.119
- B401230503 QA Program Insp Rept 99900539/83-01 on 831107-14 Violation noted procedures not adopted to provide for evaluating deviations Nonconformance noted, two individuals certified w/o required educ BRICKLEY, R.H. Division of Vendor & Technical Programs. HALE, C J Region 4, Office of Director 83/12/20 12pp. 21882.120.

DOCKETED ITEMS

461

B401230502 Ack receipt of B31208 & 1109 ltrs informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900334/B3-01
POTAPDVS,U Region 4, Office of Director 84/01/09 MATHEWS,C
Transamerica Delaval, Inc 1p 21875 308

--B401230505 Responds to NRC B31202 ltr re violation & nonconformance noted in GA Program Insp Rept 99900334/B3-01 Corrective actions product engineering managers will be interviewed to insure understanding of revised drafting room practice
BDEYER,R E Transamerica Delaval, Inc 83/12/08 POTAPDVS,U
Region 4, Office of Director 2pp 21875 309

--B401230508 Ack receipt of B31109 ltr informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900334/B3-01
POTAPDVS,U Region 4, Office of Director 83/12/02 MATHEWS,C
Transamerica Delaval, Inc 1p 21875 311

--B401230512 Responds to NRC B31003 ltr re violation & nonconformance noted in GA Program Insp Rept 99900334/B3-01 Corrective actions Transamerica Delaval submitted Part 21 repts on water pump assembly & fuel injection line failures
BDEYER,R E Transamerica Delaval, Inc 83-01. 83/11/09 Region 4, Office of Director 7pp 21875 312

B401240451 Ack receipt of B31216 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900929/B3-01
POTAPDVS,U Region 4, Office of Director 84/01/11 STERN,F.
Westinghouse Electric Corp 1p 21908 191

--B401240454 Responds to NRC B31117 ltr re nonconformance noted in GA Program Insp Rept 99900929/B3-01 Corrective actions test personnel given indoctrination & training necessary to ensure adequate proficiency in GA procedures
STERN,F Westinghouse Electric Corp 83/12/16 POTAPDVS,U
Region 4, Office of Director 3pp 21908 192

--B401240459 Issue 2, Rev 2 to Procedure GAP-01, "GA Program for Contract Engineering Activities"
Westinghouse Electric Corp 84/01/31 34pp 21908 195

--B401240463 Rev 1 to Procedure GAP-02, "GA Program for Qualification Testing"
HAYES,R C Westinghouse Electric Corp 83/12/15 13pp.
21908 229.

--B401240465 Procedure GAP-03, "Procedures for Compliance W/NRC Regulation 10CFR21 for Reporting of Defects & Nonconformances"
HAYES,R C Westinghouse Electric Corp 83/12/16 4pp
21908 242

B401240483 Confirms GA program insp at San Francisco, CA plant on B40123-25, per B40109 telcon
POTAPDVS,U Region 4, Office of Director 84/01/16 WITTIG,T.
Signa Energy Services 1p 21920 068

B401240532 Confirms GA program insp at Pawtucket, RI plant on B40130-0203, per B40106 telcon.
POTAPDVS,U Region 4, Office of Director 84/01/16 GALKIN,I B.
American Insulated Wire Corp 1p 21907 338

B401240546 Ack receipt of B31026 & 1202 ltrs informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900813/B3-01
POTAPDVS,U Region 4, Office of Director 84/01/09, HART,R J. BIF (subs of General Signal Corp) 1p 21907 102

--B401240564 Responds to NRC B31128 ltr re violation & nonconformance noted in GA Program Insp Rept 99900813/B3-01 Corrective actions: vendor placed on NRC mailing list to receive Part 21 posting requirements
HART,R J. BIF (subs of General Signal Corp.), 83/12/02 POTAPDVS,U Region 4, Office of Director 1p. 21909 103

--B401240578 Ack receipt of B31031 ltr informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900813/B3-01 Addl info describing both measures that have been or will be taken re Part 21 postings requested.
POTAPDVS,U Region 4, Office of Director 83/11/28 HART,R J BIF (subs of General Signal Corp) 1p. 21909 104

--B401240592 Responds to NRC B30815 ltr re violation & nonconformance noted in GA Program Insp Rept 99900813/B3-01 Corrective actions: Part 21 postings visibly posted in shop & scheduling of 1984 audits will be maintained over full 12-month period
HART,R J BIF (subs of General Signal Corp) 83/10/26 POTAPDVS,U Region 4, Office of Director 1p 21909 105

B401240623 Ack receipt of B31004, 12, 21, 28, 1130, 1219 & 23 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900510/B3-02 W/one oversize organization chart Aperture card in PDR
POTAPDVS,U Region 4, Office of Director 84/01/16 BURRESS,H P
United Engineers & Constructors, Inc (subs of Raytheon Co) 1p 21933 007

--B401240625 Forwards addl response to NRC B31110 ltr re Nonconformance B & C noted in GA Program Insp Rept 99900510/B3-02 Corrective actions Administrative Procedure 15 revised & implementation training session held w/site & home ofc personnel
BURRESS,H P United Engineers & Constructors, Inc (subs of Raytheon Co) 83/12/23 POTAPDVS,U Region 4, Office of Director 3pp 21933.008

--B401240629 Advises that verification date extended to B40116 for Nonconformances B & C identified in GA Program Insp Rept 99900510/B3-02
BURRESS,H P United Engineers & Constructors, Inc (subs of Raytheon Co), 83/12/17 POTAPDVS,U Region 4, Office of Director 3pp 21933.011

--B401240633 Ack receipt of B31130 ltr requesting extension until B40120 for corrective action re Nonconformance A noted in GA Program Insp Rept 99900510/B3-02 Request granted
POTAPDVS,U Region 4, Office of Director 83/12/28 CURNANE,R A
United Engineers & Constructors, Inc (subs of Raytheon Co) 1p 21933 013

--B401240634 Requests extension until B40120 for completion of corrective actions for Nonconformance A noted in GA Program Insp Rept 99900510/B3-02
CURNANE,R A United Engineers & Constructors, Inc (subs of Raytheon Co) 83/11/30 POTAPDVS,U Region 4, Office of Director 1p 21933 014

--B401240636 Ack receipt of B31004, 12 & 21 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900510/B3-02 Response to Nonconformances B & C lacked definitive action
POTAPDVS,U Region 4, Office of Director 83/11/10 CURNANE,R A
United Engineers & Constructors, Inc (subs of Raytheon Co) 1p. 21933 015

--B401240639 Forwards corrected B31012 ltr establishing dates for corrective actions for nonconformances noted in GA Program Insp Repts 99900510/B3-02 & B3-01
CURNANE,R A United Engineers & Constructors, Inc (subs of Raytheon Co) 83/10/28 POTAPDVS,U Region 4, Office of Director 1p 21933:016

--B401240641 Responds to NRC B31004 ltr re nonconformance noted in GA Program Insp Rept 99900510/B3-02 Corrective actions established dates for corrective actions will be verified
CURNANE,R A United Engineers & Constructors, Inc. (subs of Raytheon Co.) 83/10/28 POTAPDVS,U Region 4, Office of Director 1p 21933 017

--B401240643 Forwards "Engineering Status Rept on Calculation Review," for info related to corrective actions for procedural deficiencies noted in GA Program Insp Rept 99900510/B3-02.
CURNANE,R A United Engineers & Constructors, Inc. (subs of Raytheon Co). 83/10/21 POTAPDVS,U Region 4, Office of Director 4pp 21933 018.

--B401240644 Responds to NRC B31004-1223 ltrs re nonconformance noted in GA Program Insp Rept 99900510/B3-02 Corrective actions established dates for corrective actions will be verified.
CURNANE,R A United Engineers & Constructors, Inc. (subs of Raytheon Co). 83/10/21 POTAPDVS,U Region 4, Office of Director 1p. 21933 022

--B401240646 Responds to NRC B30907 ltr re nonconformance noted in GA Program Insp Rept 99900510/B3-02 Corrective actions: procedure revised requiring that prior to closing out design deficiency, design process w/verification be reviewed.
CURNANE,R A United Engineers & Constructors, Inc (subs of Raytheon Co). 83/10/04. POTAPDVS,U Region 4, Office of Director 4pp. 21933 023

B401270081 Forwards GA Insp Repts 99900911/B3-02, 99900403/B3-03, 99900927/B3-01 & 99900911/B3-03 for evaluation of significance of findings re QA & acceptability of vendor product or svc Endorsement form and w/o insp repts
JDNHSDN,E H Division of Resident, Reactor Project & Engineering Programs 84/01/20 CAHILL,W J. Gulf States Utilities Co. 4pp 21982.014 24X Fiche 50-45B, 84/01/20, B401270081.

B401270211 Ack receipt of B40104 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900777/B3-01
POTAPDVS,U Region 4, Office of Director 84/01/18 CLARK,M J.
Teledyne McKay 1p 21982.121.

NONDOCKETED ITEMS

- B401270214 Responds to NRC B31206 ltr re nonconformance noted in QA Program Insp Rept 99900797/B3-01 Corrective actions leak test logs updated w/current rev to QA Procedure 701 & responsibility for updating assigned to technician CLARK, H J Teledyne McKay B4/01/04 POTAPOVS, U Region 4, Office of Director. 5pp 21982 122
- B401270246 Forwards QA Program Insp Rept 99900403/B3-04 on B31205-09 & notice of nonconformance POTAPOVS, U Region 4, Office of Director B4/01/09 BRUGGEMAN, W H General Electric Co. 2pp 21982 164
- B401270249 Notice of nonconformance from insp on B31205-09 * Region 4, Office of Director B4/01/09 1p 21982 166
- B401270253 QA Program Insp Rept 99900403/B3-04 on B31205-09 Noncompliance noted failure to process Rev 2 to Field Deviation Disposition Request HHI-1467 into EIS data base to reflect implemented design changes HARRELL, P H, MADSEN, G L Region 4, Office of Director. B4/01/06 10pp 21982 167
- B401270262 Confirms QA program insp at Chicago, IL on B40130-0203 & 13-17, per B40110 telcon. POTAPOVS, U Region 4, Office of Director B4/01/24. PATTERSON, R W Sargent & Lundy, Inc 1p 21982 140
- B401270269 Forwards Rockbestos Co QA Program Insp Repts 99900277/B3-02 & 99900277/B3-04 for action. Significance of reported findings & ack of rept receipt requested w/o encl. GAGLIARDO, J E Region 4, Office of Director ANO-009 B4/01/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21976 111 24X Fiche 50-313, B4/01/20, B401270269
- B401270285 Ack receipt of B30926 & 1214 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900521/B3-02 POTAPOVS, U Region 4, Office of Director B4/01/18 HINKLEMAN, L O Bechtel Corp. 1p 21976 070
- B401270299 Responds to NRC B30826 & 1012 ltrs re nonconformance noted in QA Program Insp Rept 99900521/B3-02 Corrective actions procedures revised to include project engineering responsibility for test requirements for commercial items PATTERSON, R L Bechtel Corp. B3/12/14 POTAPOVS, U Region 4, Office of Director 3pp 21976 071
- B401270305 Ack receipt of B31028 & 1221 ltrs informing NRC of steps taken to correct nonconformance & violation noted in QA Program Insp Rept 99900926/B3-01 POTAPOVS, U Region 4, Office of Director B4/01/23 RANDALL, M W Nuclear Qualification Services 1p 21976 078
- B401270308 Forwards Rev 7 to NRC QA manual, incorporating changes identified in NRC B31216 ltr RANDALL, M Nuclear Qualification Services B3/12/21 POTAPOVS, U Region 4, Office of Director 1p 21976 079
- B401270310 Rev 7 to QA program * Nuclear Qualification Services B3/12/21 11pp. 21976 080
- B401270313 Ack receipt of B31028 ltr responding to NRC B31006 ltr re QA Program Insp Rept 99900926/B3-01. Addl info per B31122 telcon needed re posting of Section 206, Energy Reorganization Act of 1974 POTAPOVS, U Region 4, Office of Director B3/12/16. RANDALL, M W Nuclear Qualification Services 1p 21976 091
- B401270314 Forwards Rev 6 to Nuclear Qualification Svcs QA manual prepared in response to B30719-20 audit establishing procedures required to satisfy deficiencies noted in B31006 ltr RANDALL, M Nuclear Qualification Services B3/10/28 POTAPOVS, U Region 4, Office of Director 1p 21976 092
- B401270317 Rev 6 to QA program * Nuclear Qualification Services B3/10/28. 11pp 21976 093
- B401270422 Forwards QA Program Insp Rept 99900402/B3-01 on B31128-1201 & notice of nonconformance POTAPOVS, U Region 4, Office of Director. B4/01/03. HOUSE, H C QA Technologies, Inc./General Atomic Co 2pp. 21981 237.
- B401270436 Notice of nonconformance from insp on B31128-1201, * Region 4, Office of Director. B4/01/03 1p. 21981 239
- B401270444 QA Program Insp Rept 99900402/B3-01 on B31128-1201 Noncompliance noted 10 audits completed or scheduled to be completed in 1983 will have greater than 12-month lapse since last audit BRICKLEY, R H, MADSEN, G L Region 4, Office of Director B3/12/29 12pp 21981 240
- B401270432 Forwards QA Program Insp Rept 99900400/B3-01 identifying Vendor Program Branch concerns Evaluation of findings re quality & acceptability of product or svc requested w/o encl. GAGLIARDO, J E Region 4, Office of Director ANO-008 B4/01/20 GRIFFIN, J M Arkansas Power & Light Co 2pp 21981 217 24X Fiche 50-313, B4/01/20, B401270432
- B401270438 Forwards QA Program Insp Rept 99900036/B3-02 on B31017-21 & notice of nonconformance POTAPOVS, U Region 4, Office of Director B3/12/30 WILSON, K A Henry Pratt Co 2pp 21981 260
- B401270445 Notice of nonconformance from insp on B31017-21 * Region 4, Office of Director B3/12/30 3pp 21981 262
- B401270451 QA Program Insp Rept 99900056/B3-02 on B31017-21 Noncompliance noted no record of exams of NDT Level III svcs & PD U-02456 for bonding adhesive did not include QA program requirement CONWAY, J T, BARNES, I, Region 4, Office of Director B3/12/23 21pp 21981 265
- B401270450 Ack receipt of B31207 ltr clarifying transfer of amplifier in Models N-E11, N-E13 or E11-E13 Transmitters erroneously identified in QA Program Insp Rept 99900788/B3-01 POTAPOVS, U Region 4, Office of Director B4/01/24 MCKAY, C A Foxboro Corp 1p 21980 250
- B401270454 Responds to NRC B31117 ltr re nonconformance noted in QA Program Insp Rept 99900788/B3-01 Section 4f of insp rept should be corrected to clarify that amplifier in Models N-E11 & E11 E13 transferred to Montreal, Canada SHAW, R O Foxboro Corp B3/12/07 POTAPOVS, U Region 4, Office of Director 1p 21980 251
- B401270458 Ack receipt of B31215 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900505/B3-02, POTAPOVS, U Region 4, Office of Director B4/01/16 TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) 1p 21980 268
- B401270462 Responds to NRC B31122 ltr re nonconformance noted in QA Program Insp Rept 99900505/B3-02 Corrective actions Rev 2 to QA-11-5 of ETR-1001 revised to require check on review of seismic rept TENZER, B E Ebasco Services, Inc (subs of Enserch Corp) B3/12/15 POTAPOVS, U Region 4, Office of Director 4pp 21980 269
- B401270468 Forwards QA Program Insp Rept 99900845/B3-01 on B31115-17 & notices of violation & nonconformance POTAPOVS, U Region 4, Office of Director B4/01/09 LALIKOS, J Titeflex Corp 2pp 21981 226
- B401270471 Notice of violation from insp on B31115-17 * Region 4, Office of Director B4/01/09 1p 21981 228
- B401270473 Notice of nonconformance from insp on B31115-17 * Region 4, Office of Director B4/01/09. 1p 21981 229
- B401270478 QA Program Insp Rept 99900845/B3-01 on B31115-17 Noncompliance noted code stamped w/safety-related metal hose did not comply w/code design & insp requirements NORMAN, D E, BARNES, I Region 4, Office of Director B3/12/29 7pp. 21981 230
- B401270472 Advises that QA program described in Topical Rept QAI-TR-106 implemented satisfactorily COLLINS, J T Region 4, Office of Director B4/01/24 LORENZ, M H Gilbert/Commonwealth Cos 3pp 21981 297
- B401310374 Advises that Svc Info Memo NBR 363 re insp & corrective action for overspeed governor drive coupling issued B40123 vice B40120, per B40109 ltr BARICH, A C Transamerica Delaval, Inc B4/01/23 Director's Office, Office of Inspection and Enforcement 1p 22012 348

NONDOCKETED ITEMS

463

REGULATORY GUIDES

B401090157 Notification of B40105 meeting w/Util in Bethesda, MD to discuss review plans for Reg Guide 1 97 implementation rept
LAZOL, L Licensing Branch 3 83/12/16 KNIGHTON, G W Licensing Branch 3 4pp 21757 225 24X Fiche 50-412, 83/12/16, B401090157

B401090511 Advises that qualification of all installed harsh environ Reg Guide 1 97 Category I or II equipment completed, per util B31113 position Util approval of documentation complete, except for ex-core neutron monitoring sys
CURTIS, N W Pennsylvania Power & Light Co PLA-2017 83/12/30 SCHWENCER, A Licensing Branch 2 2pp 21753 105 24X Fiche 50-388, 83/12/30, B401090511

B40110493 Summarizes ACRS 284th meeting on B31215-16 in Washington, DC re Rev 1 to proposed Reg Guide 1 89, Task EE 042-2 on environ qualification of electrical equipment important to safety for nuclear power plants
RAY, J J ACRS - Advisory Committee on Reactor Safeguards 83/12/19 PALLADINO, N J Commissioners 2pp 21790 345

B401130082 Forwards response to Generic Ltr 82-33 (NUREG-0737, Suppl 1), re compliance w/Reg Guide 1 97 concerning instrumentation for light-water-cooled nuclear plants to assess plant & environ conditions during & following accident
MUSOLF, D Northern States Power Co GL-82-33 83/12/30 Office of Nuclear Reactor Regulation, Director 15pp 21802 058 24X Fiche 50-263, 83/12/30, B401130082

B401130121 Summary of ACRS Subcommittee on Regulatory Activities B30104 meeting w/NRC in Washington, DC re Rev 3 to Reg Guide 1 97, "Instrumentation for Light-Water-Cooled Nuclear Power Plants to Assess Plant & Environ Conditions"
* ACRS - Advisory Committee on Reactor Safeguards 83/02/07 ACRS - Advisory Committee on Reactor Safeguards 8pp 21820 277.

B401240107 Submits technical guidance & methodology for conducting rebuilt emergency diesel generator overload testing, per Rev 1 to Reg Guide 1 10B Preoperational test program must demonstrate full-load-carrying capability
MCCAFFREY, D R Long Island Lighting Co SNRC-1004 84/01/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 21712 288 24X Fiche 50-322, 84/01/16, B401240107

B401240223 Forwards E0&G info re design values for instrumentation from rept submitted w/B30830 ltr, in response to Reg Guide 1 97 Top of tank should be considered at bend line before roof welded on
KAY, J A Yankee Atomic Electric Co FVR 84-08 84/01/17 CRITCHFIELD, D Operating Reactors Branch 3 2pp 21920 240 24X Fiche 50-029, 84/01/17, B401240223

B401260302 Forwards responses to B31017 request re Rev 2 to GA plan Encl updated quality classification list issued B30701 as part of Procedure 4000-ENG-7313 OI Reg Guides 1 37 & 1 39 will be revised to clarify position
KANOA, B K General Public Utilities - GPU Service Corp 4410-B3-L-0263 83/12/22 SNYDER, D J TMI Program Office. 15pp. 21955 158 24X Fiche 50-320, 83/12/22, B401260302

B401300016 Requests that Reg Guide 5 53, Rev 1, Task B0 049-4, "Qualification, Calibr & Error Estimation Methods for Nondestructive Assay" be printed & distributed to subscription list for Div 3 & listed affected licensees
MINOQUE, R B Office of Nuclear Regulatory Research, Director 84/01/17 HILL, E L NRC - No Detailed Affiliation Given 1p 22027 316

B401300166 Advises that radiosensitive subcomponents in REA-SR-37 replaced, per util B31215 commitment & Reg Guide 1 97 re equipment qualification.
BORNSEN, Q C Washington Public Power Supply System 002-B4-029 84/01/18 SCHWENCER, A Licensing Branch 2 1p 21999 120 24X Fiche. 50-397, 84/01/18, B401300166

B401310067 Reg Guide 5 21, Rev 1, Task B0 044-4, "Nondestructive U-235 Enrichment Assay by Gamma Ray Spectrometry"
* Office of Nuclear Regulatory Research, Director 83/12/31 9pp 22032 328.

--B401310072 Value/impact statement of Reg Guide 5 21, Rev 1, Task B0 044-4, "Nondestructive U-235 Enrichment Assay by Gamma Ray Spectrometry" Reg guide should be updated
* Office of Nuclear Regulatory Research, Director 83/12/31 1p 22032 336

B401310275 Forwards "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3," per B30415 commitment re Suppl 1 to NUREG-0737
WILLIAMS, J W Florida Power & Light Co L-84-20 84/01/26 EISENHUT, D Q Division of Licensing 1p 22018 125 24X Fiche 50-250, 84/01/26, B401310275

--B401310277 "Engineering Evaluation of Instrumentation Sys for Reg Guide 1 97, Rev 3"
* Florida Power & Light Co 83/09/30 135pp 22018 126 24X Fiche 50-250, 84/01/26, B401310275

REVIEW GRP NRC RESEARCH REVIEW GROUPS

B311300135 Summary of noise surveillance & diagnostics research review group B30920-21 meetings re results of FY83 program plans for FY84
LEWIS, G S Instrumentation & Control Branch LEWIS, G S Noise Surveillance & Diagnostics Research Review Group FIN B-0191 83/10/20 FARMER, W Office of Nuclear Regulatory Research, Director HENDERSON, J Director's Office, Office of Inspection and Enforcement LDIS, L Office of Nuclear Reactor Regulation, Director 3pp 21333 107

--B309210400 Advises of B30920-21 FY83 program review in Rockville, MD Programs to be reviewed include noise diagnostic methods, noise surveillance & pressure sensor/sensing line sys
LEWIS, G S Instrumentation & Control Branch FIN B-0191 83/08/31 FARMER, W Office of Nuclear Regulatory Research, Director 7pp 21333 110

B312300202 Responds to B30826 ltr expressing concern re use of terms "important to safety" & "safety-related." Terms are not synonymous "important to safety" encompasses broad scope of equipment covered by App A to 10CFR50
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/12/19 ELLIS, T S Hutton & Williams. 3pp 21768 067

--B401090295 Comments on regulatory terms "safety-related" & "important to safety" & nonregulatory term "safety-grade" being used synonymously by nuclear industry & NRC.
ELLIS, T S, IRWIN, D P, EARLEY, A F Hutton & Williams 83/08/26 DIRCKS, W J Office of the Executive Director for Operations 31pp 21768 070

B401100471 Forwards "Methodology Review of 'Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events,' by Science Applications, Inc" Evaluation concluded that economic benefits overstated
WITHERS, B D Steam Generator Owners Group WITHERS, B D Portland General Electric Co 84/01/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21761 304

--B401100476 "Methodology Review of 'Value-Impact Analysis of Recommendations Concerning Steam Generator Tube Degradations & Rupture Events,' by Science Applications, Inc"
MCCORD, R K Applied Decision Analysis, Inc. BANDLIN, M J Affiliation Unknown 83/12/31 27pp 21761 308.

B401170524 Responds to undated ltr re use of term "important to safety" Licensees responsible for developing GA programs for plant design or operation that fulfill requirements of General Design Criterion 1 & App B to 10CFR50
DENTON, H R Office of Nuclear Reactor Regulation, Director 84/01/03 HARSHB, S L Utility Safety Classification Group 2pp 21845 357

--B401170528 Submits suppl to B30826 ltr re safety classification issue Designated individual to speak for NRC requested.
HARSHB, S L Utility Safety Classification Group. 83/11/29 DIRCKS, W J Office of the Executive Director for Operations 4pp. 21845 360.

B401250008 Summary of B31215 meeting in Bethesda, MD w/seismic qualification util group & senior seismic review advisory panel re recommendations for use of non-nuclear plant seismic experience data to evaluate seismic adequacy
CHANG, T Y Generic Issues Branch. 84/01/09. KNIEL, K Generic Issues Branch 3pp 22027 001

B401250008 Summary of B31215 meeting in Bethesda, MD w/seismic qualification util group & senior seismic review advisory panel re recommendations for use of non-nuclear plant seismic experience data to evaluate seismic adequacy
CHANG, T Y Generic Issues Branch 84/01/09 KNIEL, K Generic Issues Branch. 3pp 22027 001

NONDOCKETED ITEMS

--B312220016 Notification of B31215 meeting w/senior Seismic Review Advisory Panel & Seismic Qualification Util Group to discuss findings & recommendations on use of seismic experience data from non-nuclear plants for evaluating equipment
CHANG, T.Y. Generic Issues Branch B3/12/09 KNIEL, K. Generic Issues Branch 6pp 22027 003

B401270238 Forwards summary of CROR activities for Oct-Dec 1983 Summary will be included in EDO weekly rept to Commission for wk ending B40120
SCHWINK, W. Committee to Review Generic Requirements B4/01/24
Committee to Review Generic Requirements 6pp 21982 147

SECY POSITION PAPERS BEFORE THE COMMISSION

B312130434 SECY-B3-467
Requests Commission approval of publication of "Revised General Statement of Policy & Procedure for Enforcement Actions," in FR
DIRCKS, W.J. Office of the Executive Director for Operations B3/11/29. 130pp. 21794 161

B312140411 SECY-B3-498
Supports 10CFR1, Subpart B re statement of functions Ofc of Investigations, in accordance w/FOIA requirements
HAYES, B.B. Office of Investigation B3/12/07 6pp. 21957-136.

B401060162 Forwards SECY-B3-472, "ECCS Analysis Methods" for placement in PDR
BATES, A. Office of the Secretary of the Commission. B3/12/13
SCATTON, L.N.L. Public Document Branch 1p 21745 047

--B401060169 SECY-B3-472
Informs Commission of revised ECCS analysis methods NRC proposes to accept for conformance to App K to 10CFR50
DIRCKS, W.J. Office of the Executive Director for Operations B3/11/17 11pp. 21745-048

D1110183 Forwards errata to SECY-B4-001, "Mod of Commission Memorandum & Order re Operation of Diablo Canyon Nuclear Power Plant," consisting of Encl 1, inadvertently omitted from original submittal.
CHILK, S.J. Office of the Secretary of the Commission CL1-B3-27 34/01/09. PALLADINO, N.J., GILINSKY, V., ROBERTS, T.M. Commissioners 1p. 21772-338. 24X Fiche 50-275, B4/01/09, B401110183

B401110187 SECY-B4-001 ERR
Errata to SECY-B4-001, "Mod of Commission Memorandum & Order re Operation of Diablo Canyon Nuclear Power Plant," consisting of Encl 1.
* NRC - No Detailed Affiliation Given B4/01/09. 6pp 21772.339. 24X Fiche 50-275, B4/01/09, B401110183.

B401170137 Responds to FOIA request for SECY-B3-24 & SECY-B3-153 to be placed in PDR. Forwards documents. SECY-B3-24 partially withheld (ref FOIA Exemption 1). SECY-B3-153 available in PDR.
ELTON, J.M. Division of Rules and Records B3/10/31. PEDRO, J. NUS corp. 1p. 21836-255.

B401170142 SECY-B3-024
Requests approval of proposed ltr to Dept of Commerce re export of licensed nuclear reactor components to India for use in Tarapur Atomic Power Station. Info deleted
DIRCKS, W.J. Office of the Executive Director for Operations B3/01/19 Commissioners. 7pp 21836.296.

B305170230 SECY-B3-153
Recommends that Commission approve FR publication of encl proposed amend to 10CFR50, App E re frequency of full-scale emergency preparedness exercises
DIRCKS, W.J. Office of the Executive Director for Operations B3/04/28. 40pp. 21836-236

B401200225 SECY-B3-004A
Provides Commissioners w/info on current status of NRRS & submits assurance that INPO remains strongly committed to improvement of NRRS
DIRCKS, W.J. Office of the Executive Director for Operations. B3/07/05. 25pp. 21872-112.

B1230052 Final response to FOIA request for four categories of documents Forwards App A documents. Documents also available in PDR.
ELTON, J.M. Division of Rules and Records B3/11/01 ADATO, M. Union of Concerned Scientists 2pp. 21930-271. 24X Fiche 50-289, B3/11/01, B401230052.

--B401230070 SECY-B2-384A
Recommends deferral of NUREG-0737, Item II B 2 2, "Plant Shielding Mods," implementation to first refueling outage following restart
DIRCKS, W.J. Office of the Executive Director for Operations B2/12/06 4pp 21930 276 24X Fiche 50-289, B3/11/01, B401230052

--B401230079 SECY-B3-340
Informs of status of facility restart certification effort & provides update on noncertification item status
DIRCKS, W.J. Office of the Executive Director for Operations B3/08/16 42pp 21930 280 24X Fiche 50-289, B3/11/01, B401230052

B401230103 SECY-B4-002
Provides pertinent info & matl to Commission re DOE waste repository siting guidelines in preparation for B40111 public meeting
DIRCKS, W.J. Office of the Executive Director for Operations B4/01/04 71pp 21932 035

B401240133 SECY-B4-008
Recommends Commission authorize issuance of License XMAT-0290 to Union Carbide Corp to export 231.171 lb graphite to Japan & authorize issuance of License XMAT-0295 upon receipt of favorable Executive Branch judgement
DIRCKS, W.J. Office of the Executive Director for Operations B4/01/09 23pp 21945 060

B401250015 Partial response to FOIA request for all 1982 SECY papers Forwards App A documents Remaining documents under review
FELTON, J.M. Division of Rules and Records B3/10/18 WEIES, E.R. Union of Concerned Scientists 3pp 21960 005 24X Fiche 50-000, B3/10/18, B401250015

--B209010239 SECY-B2-0130
Informs Commission of status of implementation of 10CFR50 48 & App R to 10CFR50 for quarter ending B20630 per BJ Chilk B01103 memo As of B20630, 31 licensees have not completed responses
DIRCKS, W.J. Office of the Executive Director for Operations B2/07/26 8pp 21960.008

--B401250106 SECY-B2-016E
Forwards petition for Supreme Court review of Pans psychological stress issue in TMI-1 restart case filed by solicitor general
MALSCH, M.G. Office of the General Counsel B2/09/02 20pp 21960 016 24X Fiche 50-000, B3/10/18, B401250015

--B401250112 SECY-B2-040
Recommends J Fitzgerald & T Rothschild Newark inquiry rept be made available for comment before decision made based on info reached.
BICKWIT, L. Office of the General Counsel B2/01/29 3pp 21960 044

--B401250117 SECY-B2-044
Requests Commission approval of 1982 audit plan
CUMMING, J. Office of Inspector & Auditor B2/01/29 81pp 21960-047.

--B203040434 SECY-B2-045
Provides quarterly rept updating info on petitions for rulemaking submitted to NRC between Oct-Dec 1981
DIRCKS, W.J. Office of the Executive Director for Operations B2/02/03 21pp 21960 129

--B203050072 SECY-B2-054
Provides update on status of waste mgt legislation & comparison of major bills in Congress Major differences in bills include degree of priority of retrievable monitored storage as alternative to deep geologic storage
DIRCKS, W.J. Office of the Executive Director for Operations B2/02/05 11pp 21960 150

--B203050106 SECY-B2-056
Informs of progress & schedule of Reactor Operator Qualifications Peer Review Panel Meetings on B11116-18 & B20112-13 discussed.
DIRCKS, W.J. Office of the Executive Director for Operations B2/02/09 4pp 21960 161

--B203050118 SECY-B2-064
Describes calculation of proposed civil penalties. Events indicated need for aggressive involvement of higher licensees mgt in assuring safe operation.
DIRCKS, W.J. Office of the Executive Director for Operations B2/02/12. 2pp 21960 165 24X Fiche 50-000, B3/10/18, B401250015

--B203110330 SECY-B2-066
Forwards NUREG-0886, "Steam Generator Tube Experience"
DIRCKS, W.J. Office of the Executive Director for Operations. B2/02/12 68pp. 21960.167.

NONDOCKETED ITEMS

485

- B401250148 SECY-82-073
Summarizes 820212 District Court status hearing in City of West Chicago vs NRC City may drop lawsuit if Commission Order CLI-82-2 disposing of hearing petitions is followed by DES in Spring 1982
BICKWIT, L Office of the General Counsel CLI-82-2 82/02/18 2pp 21960 236
- B204070587 SECY-82-073A
Advises that Judge McCarr denied renewed motion for preliminary injunction filed by City of West Chicago, IL & granted motion to dismiss filed by NRC Opinion follows
BICKWIT, L Office of the General Counsel 82/03/26 1p 21960 235
- B203240020 SECY-82-074
Forwards quarterly summary rept of NRC rulemaking activities
DIRCKS, W J Office of the Executive Director for Operations 82/02/18 137pp 21960 238
- B203120409 SECY-82-079
Informs of dismissal of NFB challenge to Commission Bill 106 order affirming NRC issuance of amend
FITZGERALD, J A Office of the General Counsel 82/02/25 1p. 21961 063
- B203120423 SECY-82-081
Recommends approval of proposed AO determination re seismic design errors Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations 82/02/25 81pp 21961 065 24X Fiche 50-000, 83/10/18, 8401250015
- B401250164 SECY-82-082
Discusses T Devine FOIA Appeal (82-A-1C) re DIA facility rept Authorizes secretary to sign & dispatch attached ltr denying appeal
BICKWIT, L Office of the General Counsel. 82/03/01 20pp 21961 147. 24X Fiche 50-000, 83/10/18, 8401250015
- B203120411 SECY-82-083
Advises of CP&L 820201 petition for review of Commission final rule on interim requirements re hydrogen control.
FITZGERALD, J A Office of the General Counsel 82/03/01. 11pp 21961 167
- B203180400 SECY-82-092
Informs of status of staff action & plans re environ assessment of psychological stress in restart staffing plan Major milestones & resource requirements & draft workshop rept encl
DIRCKS, W J Office of the Executive Director for Operations 82/03/02 102pp 21961 178 24X Fiche 50-000, 83/10/18, 8401250015
- B205050087 SECY-82-092A
Forwards final rept, "Summary Rept-Workshop on Psychological Stress Associated W/Proposed Restart of TMI-1,"
NUREG/CP-0026
DIRCKS, W J Office of the Executive Director for Operations. 82/04/14 151pp 21961 187 24X Fiche 50-000, 83/10/18, 8401250015
- B203180405 SECY-82-099
Recommends approval on encl FR notice of proposed rule 10CFR50, clarifying applicability of license conditions & Tech Specs in emergency
* Office of the Executive Director for Operations. 82/03/03 23pp 21962 073
- B203300068 SECY-82-112
Discusses 820222 brief re emergency preparedness at facilities
FITZGERALD, J A Office of the General Counsel 82/03/16 33pp 21962 096 24X Fiche 50-000, 83/10/18, 8401250015
- B204050459 SECY-82-122
Provides Commission info re adequacy of existing Board notification policy Submits recommendation to accommodate greater role of regions in policy decisions
DIRCKS, W J Office of the Executive Director for Operations. 82/03/18. 3pp 21962 183
- B204070577 SECY-82-132
Notifies Commission of successful defense of Kerr-McGee Nuclear Corp et al vs NRC, et al re lawsuit on U mill licensing requirements
BICKWIT, L Office of the General Counsel 82/03/29 73pp. 21962-166
- B204080204 SECY-82-134
Informs Commission of current status of steam generator insp & repairs following 820129 steam generator tube rupture at facility
DIRCKS, W J Office of the Executive Director for Operations. 82/03/31 3pp 21962 259 24X Fiche 50-000, 83/10/18, 8401250015
- B204220088 SECY-82-141
Informs Commission of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operators & describes routine repts to be submitted on status of OL Tables of pass/fail rates encl
DIRCKS, W J Office of the Executive Director for Operations 82/04/05 4pp 21962 262
- B204300107 SECY-82-143
Provides info on operation & testing of containment isolation valves at facility
DIRCKS, W J Office of the Executive Director for Operations 82/04/05 19pp 21962 266 24X Fiche 50-000, 83/10/18, 8401250015
- B209150435 SECY-82-150A
Describes process of IE evaluation of NRC insp program effectiveness, IE appraisal team role & relationship to evaluation of insp program effectiveness & expansion plans & resource requirements
DIRCKS, W J Office of the Executive Director for Operations 82/08/25 32pp 21962 288
- B204220364 SECY-82-152
Recommends that Commission accept Fitzgerald & Rothschild conclusions re employment of Newark to work on matters re facility
BICKWIT, L Office of the General Counsel 82/04/12 4pp 21962 319 24X Fiche 50-000, 83/10/18, 8401250015.
- B205050098 SECY-82-156
Informs of plan to permit regional administrators to sign proposed civil penalties in certain cases
DIRCKS, W J Office of the Executive Director for Operations 82/04/13 2pp. 21963 066.
- B208060142 SECY-82-157A
Provides status rept on NRR investigation of effects of electromagnetic pulse on nuclear power plants
DIRCKS, W J Office of the Executive Director for Operations 82/07/16 7pp 21963 068
- B204220376 SECY-82-160
Forwards info re sua sponte issue, whether addl primary sys depressurization capability should be added to plant design
MALSCH, M G Office of the General Counsel 82/04/15 80pp 21963 075. 24X Fiche 50-000, 83/10/18, 8401250015.
- B205050587 SECY-82-161
Informs of issuance of draft rept (NUREG-0820) on SEP integrated plant safety assessment w/o encl NUREG-0820.
DIRCKS, W J Office of the Executive Director for Operations 82/04/15 2pp 21963 171 24X Fiche 50-000, 83/10/18, 8401250015
- B205050499 SECY-82-162
Forwards "Rept of Peer Advisory Panel & NRC on Operator Qualifications"
DIRCKS, W J Office of the Executive Director for Operations. 82/04/15 117pp 21963 173
- B205070412 SECY-82-172
Forwards quarterly summary of rules & petition for rulemaking. Rept expanded to include NRC petitions for rulemaking & updates info on all rules & petitions on which NRC has proposed, or is considering action
DIRCKS, W J Office of the Executive Director for Operations. 82/04/23 194pp 21963 298
- B205280489 SECY-82-193
Notifies Commission that J Jaffer petition to suspend license amends for facilities has been denied
MALSCH, M G Office of the General Counsel. 82/05/12. 13pp 21964:158 24X Fiche 50-000, 83/10/18, 8401250015
- B205270663 SECY-82-195
Provides info re qualifications & experience of personnel operating plant during current strike, in response to Chairman Palladino request
DIRCKS, W J Office of the Executive Director for Operations 82/05/14 4pp 21964:154 24X Fiche 50-000, 83/10/18, 8401250015
- B205240404 SECY-82-197
Recommends that Ofc of General Counsel be directed to prepare draft statement of policy indicating Commission intention not to alter licensing procedures.
BICKWIT, L Office of the General Counsel. 82/05/17 34pp. 21964 171

NONDOCKETED ITEMS

- B401250223 SECY-82-197 ERR
Errata to SECY-82-197, replacing Pages 19 & 20 re NRDC vs NRC, DC Circuit Court of Appeals 74-1586 & consolidated cases (decision holding invalid NRC original, interim & final Table S-3 fuel cycle rules)
* Office of the Secretary of the Commission 82/05/20 3pp
21964 207
- B206300094 SECY-82-197C
Advises that on B20610, Solicitor General approved filing of motion for rehearing & reconsideration en banc in S-3 case On B20611, petition for rehearing & suggestion for rehearing filed
SLAGGIE, E L Office of the Executive Legal Director 82/06/14 22pp 21964 210
- B206110164 SECY-82-206
Informs Commission that review of B20125 steam generator tube rupture event completed & permission to restart facility granted.
DIRCKS, W J Office of the Executive Director for Operations 82/03/21 3pp 21964 232. 24X Fiche 50-000, 83/10/18, 8401250015
- B206110014 SECY-82-219
Informs of status of util ability to provide addl senior reactor operator on shift by B20701 per requirements of TMI Item I A 1.3, "Shift Manning Requirements."
DIRCKS, W J Office of the Executive Director for Operations. 82/06/01 6pp 21964-235 24X Fiche 50-000, 83/10/18, 8401250015
- B206110136 SECY-82-223
Discusses Nuclear Club, Inc B20528 suit, filed under FOIA seeking access to Morgan rept
SLAGGIE, E L Office of the General Counsel 82/06/03 1p
21964 241.
- B401250240 SECY-82-241A
Submits request to Comptroller General for advice re payment of awards to intervenors under Equal Access to Justice Act, per Secretary of Commission B20723 memo GAO reply not expected until Sept.
MALSCHE, M O. Office of the General Counsel. 82/08/09 5pp
21964 242
- B206300033 SECY-82-247
Informs of Washington DC Circuit Court B20611 decision favoring NRC in NRDC vs NRC re NFB/Erwin hearing concerning military function rule cases
SHULMAN, H J. Office of the General Counsel 82/06/15 12pp
21964 247
- B207060317 Advises that documents withheld under TC Wheeler B20514 FOIA request re Atlas Machine & Iron Works, Inc can be released
Contemplated referral to FBI never occurred
ROTHSCHILD, T. Office of the General Counsel 82/06/15 19pp
21964 259
- B206300059 SECY-82-250
Informs of NRC plan for certifying completion of TMI-1 restart requirements, in response to B20316 memo
DIRCKS, W J Office of the Executive Director for Operations 82/06/16 16pp. 21964; 278. 24X Fiche 50-000, 83/10/18, 8401250015
- B206290623 SECY-82-262
Informs Commission of B20524 petition for review filed by New England Coalition on Nuclear Pollution & others re Commission final rule on financial qualification, w/DC Circuit
SLAGGIE, E. L. Office of the General Counsel. 82/06/22. 15pp.
21964 298.
- B206300371 SECY-82-263
Discusses Carole Bernstein suit seeking injunction to enjoin NRC from considering granting OL to LAPL Motion planned to dismiss suit for lack of jurisdiction & finality failure to exhaust administrative remedies
SHULMAN, H J. Office of the General Counsel 82/06/24 2pp
21964; 313 24X Fiche 50-000, 83/10/18, 8401250015
- B401250258 SECY-82-269
Forwards draft revised resumption of hearing order before Commission in facility mat'l control & accounting amend
Issuance of order recommended
BICKWIT, L. Office of the General Counsel. 82/06/25 12pp
21964 315.
- B401250263 SECY-82-272
Forwards NRC brief in Lorion vs NRC (DC Circuit Court of Appeals 82-1132) case.
SLAGGIE, E L. Office of the General Counsel. 82/06/28 60pp
21964 327. 24X Fiche 50-000, 83/10/18, 8401250015
- B401250269 SECY-82-285
Discusses T Applegate vs NRC (82-1829) case re allegations that NRC improperly withheld documents & failed to identify others in response to B11123 request for records concerning B10807 OIA rept on IE investigation at facility
SLAGGIE, E L Office of the General Counsel 82/07/06 6pp
21965 026 24X Fiche 50-000, 83/10/18, 8401250015
- B207230676 SECY-82-293
Provides quarterly summary of NRC rules & petitions for rulemaking for B20409-0430
DIRCKS, W J Office of the Executive Director for Operations 82/07/12 204pp 21965 032
- B207230670 SECY-82-297
Informs of T Devine (Govt Accountability Project) B20709 ltr responding to Chairman question at B20616 meeting & requesting investigation of alleged util false statements
BICKWIT, L. Office of the General Counsel 82/07/15 99pp
21965 226 24X Fiche 50-000, 83/10/18, 8401250015
- B208230483 SECY-82-333
Advises of issuance of NUREG-0661, Suppl 1, "Mark I Containment Long-Term Program Safety Evaluation Rept"
NUREG-0661, Suppl 1 & draft notice of availability encl
DIRCKS, W J Office of the Executive Director for Operations 82/08/09 24pp 21965 325
- B401250302 SECY-82-334B
Forwards info re NRC opposition to motion by NRDC & Sierra Club to stay exemption for facility
BICKWIT, L. Office of the General Counsel 82/08/30 43pp
21965 349 24X Fiche 50-000, 83/10/18, 8401250015
- B209200347 SECY-82-346
Informs of current status of NRC efforts re psychological stress associated w/TMI restart Natl Inst of Mental Health is reviewing proposed psychological survey
DIRCKS, W J Office of the Executive Director for Operations 82/08/19 2pp 21966 030 24X Fiche 50-000, 83/10/18, 8401250015
- B401250311 SECY-82-346A
Informs of status of staff effort re psychological stress associated w/TMI-1 restart
DIRCKS, W J Office of the Executive Director for Operations 82/09/13 2pp 21966 032 24X Fiche 50-000, 83/10/18, 8401250015
- B209230146 SECY-82-349
Informs Commission of issuance of NUREG/CR-2837, "BMNL Technical Review of Pressurized Thermal Shock Issues"
DIRCKS, W J Office of the Executive Director for Operations 82/08/20 1p 21966 034
- B209160068 SECY-82-352
Informs Commission of NRC initiatives to improve GA in nuclear project design & const Approval requested to revise NRC statutory authority to permit implementation of representative sys analogous to FAA sys
DIRCKS, W J Office of the Executive Director for Operations 82/08/20 37pp 21966 035 24X Fiche 50-000, 83/10/18, 8401250015
- B209200377 SECY-82-354
Informs of INPO accreditation program for training programs in nuclear power industry for Commission consideration
INPO program is effort to reflect responsive posture by industry to TMI Action Plan Item I A 2.7.
DIRCKS, W J Office of the Executive Director for Operations 82/08/23 2pp 21967 231
- B209210015 SECY-82-357
Informs Commission of Commonwealth of MA B20813 petition to review Order CLI-82-16, denying hearing in Pilgrim enforcement matter
SLAGGIE, E L Office of the General Counsel CLI-82-16 82/08/26 2pp 21966 073
- B401250325 SECY-82-378
Informs of results of facility SEP integrated safety assessment
DIRCKS, W J Office of the Executive Director for Operations. 82/09/15 58pp 21966 129 24X Fiche 50-000, 83/10/18, 8401250015
- B401250322 SECY-82-382
Informs of status of ongoing & completed litigation from Sept 1981 to Sept 1982.
BICKWIT, L. Office of the General Counsel 82/09/17 52pp
21966 075
- B211030044 SECY-82-400
Submits litigation rept for wk of B20927.
SLAGGIE, E L Office of the General Counsel 82/10/01. 32pp
21966 239

NONDOCKETED ITEMS

467

- B21020259 SECY-B2-403
Informs Commission of results of SEP integrated safety assessment
DIRCKS,W J Office of the Executive Director for Operations
82/10/01 115pp 21966 272 24X Fiche 50-000,83/10/18, 8401250015
- B21030079 SECY-B2-406
Submits litigation rept for wk of B21004
SLAGQIE,E L Office of the General Counsel 82/10/08 4pp
21966 296
- B210270322 SECY-B2-407
Advises of issues remaining from B20108 meeting re instrumentation for detection of inadequate core cooling in PHRS Requests action on update recommendations for implementation of NUREG-0737,Item II F 2
DIRCKS,W J Office of the Executive Director for Operations
82/10/07 97pp 21966 303
- B21090063 SECY-B2-422
Submits litigation rept for wk of B21011
SLAGQIE,E L Office of the General Counsel 82/10/19 3pp
21966 300
- B21090002 SECY-B2-430
Informs of NRC brief filed on B21019 re New England Coalition on Nuclear Pollution vs NRC Brief & Certificate of Svc encl
SLAGQIE,E L Office of the General Counsel 82-1581 82/10/22 64pp 21967 047
- B21090006 SECY-B2-432
Informs of issuance of NUREG-0744,Vols I & II,Rev 1, "Resolution of Task A-11,Reactor Vessel Matls Toughness Safety Issue "
DIRCKS,W J Office of the Executive Director for Operations
82/10/22 2pp 21967 111
- B21170003 SECY-B2-445
Responds to Commission request that IE evaluate proposal of assigning two resident inspectors to each const site
Proposal not advocated
DIRCKS,W J Office of the Executive Director for Operations
82/11/01 2pp 21967 113
- B21170008 SECY-B2-450
Submits litigation rept for wk of B21101 Burstein vs NRC & USNRC vs Pane discussed
SLAGQIE,E L Office of the General Counsel 82/11/08 2pp
21967 115 24X Fiche 50-000,83/10/18,8401250015
- B401250353 SECY-B2-473
Recommends issuance of encl order granting in part & denying in part,motion to direct staff to reschedule B21013 meeting re Sandia Lab preliminary evaluation of facility safety study
MALSCH,M O Office of the General Counsel 82/11/30 5pp
21967 121 24X Fiche 50-000,83/10/18,8401250015
- B401250359 SECY-B2-478
Provides info re rotation policy for resident inspectors & assessment of program Pending Congressional approval, policy established to allow resident inspector tour extensions to be approved on case by case basis
DIRCKS,W J Office of the Executive Director for Operations
82/12/06 9pp 21967 126
- B401250363 SECY-B2-488
Provides litigation rept for wk of B21206
SLAGQIE,E L Office of the General Counsel 82/12/14 2pp
21967 138
- B401250370 SECY-B2-496
Informs of results of SEP review Rept will be published & distributed by B21230
DIRCKS,W J Office of the Executive Director for Operations
82/12/21, 66pp 21967 140 24X Fiche 50-000,83/10/18,8401250015
- B301070135 SECY-B2-498
Recommends withdrawal of proposed rule to codify NUREG-0737 requirements for DL applicants,per encl draft FR notice
DIRCKS,W J Office of the Executive Director for Operations
82/12/27 6pp 21967 206
- B301070155 SECY-B2-500
Informs Commission of status of psychological stress survey proposal to predict stress resulting from restart of TMI-1 & reanalyses of three studies of psychological stress caused by accident & aftermath at TMI-2
DIRCKS,W J Office of the Executive Director for Operations
82/12/27 6pp 21967 216 24X Fiche 50-000,83/10/18,8401250015
- B401250376 SECY-B2-501
Provides weekly litigation rept
ROTHSCHILD,T Office of the General Counsel 82/12/28 2pp
21967 214
- B301070163 SECY-B2-502
Informs Commission of status of nonhearing issues on TMI-1 re auxiliary feedwater header problem & make-up nozzle cracking problem at B&W plants & steam generator tube problem at plant
DIRCKS,W J Office of the Executive Director for Operations
82/12/29 3pp 21967 222 24X Fiche 50-000,83/10/18,8401250015
- B401250383 SECY-B2-504
Informs Commission of progress & plans for improving state capabilities to do need-for-power evaluations
DIRCKS,W J Office of the Executive Director for Operations
82/12/30 5pp 21967 225
- B401250163 Further response to FOIA request for documents re emergency operation Facilities Forwards App B documents App A & B documents available in PDR App C documents entirely withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/11/02 D'NEILL,J H Shaw, Pitman, Potts & Troubridge. 6pp 21957 357 24X Fiche 50-000,83/11/02,8401250163
- B401250241 SECY-B2-390
Recommends approval of request for exception under requirements & conditions of COMJA-80-35 & SECY-B2-111 for location of emergency operations facility
DIRCKS,W J Office of the Executive Director for Operations
COMJA-80-35 82/09/21 10pp 21958 293 24X Fiche 50-000,83/11/02,8401250163
- B303110415 SECY-B3-085
Requests Commission disapprove exception for backup emergency operations facility for plant
DIRCKS,W J Office of the Executive Director for Operations
83/02/28 9pp 21958 016 24X Fiche 50-000,83/11/02,8401250163
- B304050512 SECY-B3-111
Requests Commission approval of exception for location of emergency operations facility for facilities
DIRCKS,W J Office of the Executive Director for Operations
83/03/21 7pp 21958 033 24X Fiche 50-000,83/11/02,8401250163
- B305160329 SECY-B3-152
Recommends that Commission concur w/NRC approval of location of emergency operations facilities slightly beyond 20-mile limitations in Suppl 1 to NUREG-0737
DIRCKS,W J Office of the Executive Director for Operations
83/04/28 44pp 21958 041 24X Fiche 50-000,83/11/02,8401250163
- B305160182 SECY-B3-161
Requests Commission authorization for exception to location of backup emergency operations facility 25 miles from plant site
DIRCKS,W J Office of the Executive Director for Operations
83/05/02 5pp 21958 089 24X Fiche 50-000,83/11/02,8401250163
- B306030404 SECY-B3-191
Requests Commission review approval for exception to location of backup emergency operations facility beyond 20 miles from plant
DIRCKS,W J Office of the Executive Director for Operations
COMJA-80-37 83/05/18 8pp 21958 105 24X Fiche 50-000,83/11/02,8401250163
- B306030153 SECY-B3-192
Recommends Commission concurrence w/approval for exception to location of backup emergency operations facility beyond 20 miles for Maine Yankee Atomic power plant.
DIRCKS,W J Office of the Executive Director for Operations
83/05/19 5pp 21958 167 24X Fiche 50-000,83/11/02,8401250163
- B306020457 SECY-B3-199
Requests Commission review NRC disapproval of primary emergency operations facility w/no habitability features
DIRCKS,W J Office of the Executive Director for Operations
83/05/20 7pp 21958 183 24X Fiche 50-000,83/11/02,8401250163
- B306210319 SECY-B3-205
Requests Commission review of staff approval for exception to location of backup emergency operations facility beyond 20-mile limit
DIRCKS,W J Office of the Executive Director for Operations
83/05/26 8pp 21958 232 24X Fiche 50-000,83/11/02,8401250163

NONDOCKETED ITEMS

--8306150117 SECY-83-223

Requests Commission review & disapprove divided emergency operations facility (EOF) concept for facilities
DIRCKS, H J Office of the Executive Director for Operations
83/06/07 7pp 21958 253 24X Fiche 50-000, 83/11/02, 8401250163

STATE PROG STATE PROGRAMS

8312200331 Forwards Suppl 2 to IE Bulletin 83-07 "Apparently Fraudulent Products Sold by Ray Miller, Inc" & IE Info Notice 83-81
"Entry Into High Radiation Areas From Areas Which Are Not Under Direct Surveillance," to all Agreement States
NUSSBAUMER, D A Assistant Director for State Agreements Programs
1EB-83-07 83/12/15 Affiliation Unknown 1p 21589 325

8401030342 NUREG/RR-0025 V09 N8

INFORMATION REPORT ON STATE LEGISLATION
LAWDAU, M Office of State Programs, Director 83/12/15 13pp
21693 319

8401050026 Releases public version of State of MI emergency preparedness plan
FELTON, J M Division of Rules and Records 83/12/27 Document
Management Branch 1p 21734 001 24X Fiche 50-329, 83/12/27,
8401050026

--8401050031 Public version of State of MI emergency preparedness plan.
W/831104 ltr.
BLANCHARD, J J, HOUOH, Q L Michigan, State of 26469 83/09/30
DENTON, H R Office of Nuclear Reactor Regulation, Director
491pp 21734 002 24X Fiche 50-329, 83/12/27, 8401050026

8401050383 Confirms recent NRC telcon w/ Lerret re NRC review of
State of FL radiation control program for agreement matl
Requests discussion of review results on 840217
O'REILLY, J P Region 2, Office of Director 83/12/28 PINGREE, D H
Florida, State of 1p 21730 362

8401050536 Forwards list of questions entitled, "Preliminary Info
Requested for FL Radiation Control Program" Plans to visit
each area compliance ofc during 840206-10 confirmed
WOODRUFF, R L NRC - No Detailed Affiliation Given 83/12/28
JERRETT, L Florida, State of 7pp 21725 268

8401050553 Ack receipt of 831115 & 0923 ltrs in response to comments
& recommendations following 1982 review of State of NC
radiation control program Support of radiation control
program appreciated
O'REILLY, J P Region 2, Office of Director 83/12/22 MORROW, S T
North Carolina, State of 1p 21726 059

8401050661 Discusses review & evaluation of State of SC radiation
control program Program adequate to protect public
health & safety. Request for addl program technical staff
supported Guidelines encl
O'REILLY, J P Region 2, Office of Director 83/12/19 JACKSON, R S
South Carolina, State of 4pp 21724 131

8401060341 Forwards "Rept & Evaluation of State of GA Radiation Control
Program for 811125-830307"
WOODRUFF, R L Region 2, Office of Director 83/12/09
LEDBETTER, J O Georgia, State of 1p 21741 190

--8401060347 "Rept & Evaluation of State of GA Radiation Control Program
for 811125-830307"
* NRC - No Detailed Affiliation Given 83/12/09 73pp
21741-191

8401090663 NUREG-1041
IMPACTS OF NRC PROGRAMS ON STATE AND LOCAL GOVERNMENTS
NUSSBAUMER, D A, LUBENAU, J O Office of State Programs, Director
83/12/31 15pp 21766 296

840110331 Responds to 831114 proposal for agreement between NRC &
State of UT re state assumption of regulatory authority over
certain sources of ionizing radiation Assessment to be
published in FR & acted on after 30-day comment period
PALLADINO, N J Commissioners 83/12/08 MATHESON, S M Utah, State
of 1p 21795 140

--840110333 Requests agreement between NRC & State of UT under which NR
will discontinue & State of UT will assume regulatory
authority over radioisotopes, source U & thorium matl & SNM
insufficient to form critical mass
MATHESON, S M Utah, State of 83/11/14, PALLADINO, N J
Commissioners 2pp 21795 141

840130040 Forwards NP Kirner 831205 ltr re technical assistance to
State of WA on high-integrity containers proposed by CQ&Q &
NuPac Response requested by 831229
NUSSBAUMER, D A Assistant Director for State Agreements Programs
83/12/27 HIGGINBOTHAM, L Low Level Waste Licensing Branch 1p
21817-265

8401160142 Responds to 831125 ltr re NRC review of State of MD
radiation control program Meeting on 840109 requested
WILZACK, A Maryland, State of 83/12/28 MURLEY, T E Region 1,
Office of Director 1p 21815 007

8401180084 Forwards addl info re top impact resistance of high
integrity waste disposal container, including analyses
documenting adequacy of container to withstand 100 lb
impact
SCHNEIDER, K N Assistant Director for State Agreements Programs
84/01/09 JOHNSON, T Division of Waste Management 9pp
21847 327

8401190025 Trip rept of attendance at 831114-16 meetings w/State of SC
in Columbia, SC re high integrity container reviews performed
in conjunction w/State of SC Agreement State compatibility
review
JOHNSON, T C Engineering Branch (Post 831001) 83/12/16
GREEVES, J T Engineering Branch (Post 831001) 8pp 21870 495

8401190028 Forwards evaluation rept on high integrity container review
process of State of SC, performed in conjunction w/
compatibility review of Agreement State program
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch
83/12/19 WOODRUFF, R L Region 2, Office of Director 7pp
21870 288

8401200209 Notifies that SC has been added to list of participants in
840111 public meeting on DOE general guidelines for
recommendation of sites for nuclear waste repositories
PALLADINO, N J Commissioners, 84/01/04 RILEY, R W South
Carolina, State of 1p 21871 242

--8401200214 Notifies that State of WA has been added to list of
participants in 840111 public meeting on DOE general
guidelines for recommendation of sites for nuclear waste
repositories
CHILK, B J Office of the Secretary of the Commission 84/01/04
ROE, C B Olympia, WA 1p 21871 248

--8401200218 Ack receipt of response to 831104 ltr addressing concern for
assuring highest stds on nuclear safety
DEBELLO, A B New York, State of 83/11/28 PALLADINO, N
Commissioners 2pp 21871-258

8401230573 Releases public version of revised State of NY radiological
emergency response plan, revised county radiological
emergency preparedness plan & county radiological plan
procedures
FELTON, J M Division of Rules and Records 84/01/19 Document
Management Branch 1p 21871 166 24X Fiche 50-220, 84/01/19,
8401230573

--8401230576 Forwards public version of revised State of NY radiological
emergency response plan, Rev 3 to Oswego County radiological
emergency preparedness plan & county radiological emergency
plan procedures
MANGAN, C V, DILLENBACK, J R Niagara Mohawk Power Corp. 84/01/06
Document Management Branch 3pp 21871 167 24X
Fiche 50-220, 84/01/19, 8401230573

--8401230578 Public version of revised State of NY radiological emergency
response plan & Rev 3 to Oswego County radiological
emergency preparedness plan.
* Niagara Mohawk Power Corp 83/01/15, 840pp, 21891-170 24X
Fiche 50-220, 84/01/19, 8401230573

8401250514 Forwards application of "Guidelines for NRC Review of
Agreement State Radiation Control Program" & "Comments &
Recommendations for State of CA Radiation Control Program
for Agreement Matl," per review & program evaluation
MARTIN, J B Region 3, Office of Director 84/01/11 RANK, P C
California, State of 7pp 21948 340

8401270120 PND-IV-84-001 on 840117, State of NM Radiation Protection
notified NRC that Smith Pipe & Steel truck discovered
carrying Co-60 contaminated rebar. Shipment distributed
through broker in Phoenix, AZ from sales company in Mexico.
HEYER, R S, DDDA, R J, Region 4, Office of Director 84/01/09 2pp
21982-025

8401270173 Discusses arrangements for 810511-21 technical review of
repository siting activities in Paradox Basin, UT & Palo Duro
Basin, TX. State liaison officers listed
MILLER, H J Division of Waste Management 00025 81/04/30
NEFF, J O Energy, Dept of, 2pp 22002 282

8401270423 Forwards corrective procedures based on results of NRC compatibility review of radiation control program Summary of corrective procedures for radioactive program also encl
BEARE, J A Washington, State of, Dept of Social & Health Services
83/12/23 MARTIN, J B Region 5, Office of Director 36pp
21981 179.

--8401270426 Responds to B11007 inquiry re incorporation of Exxon Nuclear Co. State of WA license WN-1062-1 into NRC license SNM-1227
State must continue to regulate byproduct & source matl used
by Exxon
MUSBAUMER, D A Assistant Director for State Agreements Programs
81/10/26 VERELLEN, R R Washington, State of, Dept of Social & Health Services 2pp 21981 215

8401270515 NUREG/BR-0025 V10 N1
INFORMATION REPORT ON STATE LEGISLATION
* Office of State Programs, Director 84/01/01 6pp 22002 192

8401300128 Notification of contract execution, Mod 2 to "Radiation Monitoring Program Requirements " Contractor NY State Dept of Health.
UNBEL, D Technical Assistance Contracts Branch FIN B-8355
NRC-28-B3-610 84/01/13 MCCOY, J Division of Resource Management & Administration KOTTAN, J J NRC - No Detailed Affiliation Given 1p 22005 030

--8401300141 Mod 2, providing funds for CY84, incorporating environ monitoring at facility & changing assigned NRC representative to "Radiation Monitoring Program Requirements "
LEAVY, W F New York, State of GUSTAVE, R P Division of Contracts FIN B-8355 NRC-28-B3-610 84/01/13 1p 22005 031

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8312050593 Forwards QA program Topical Rept QIBBAR 17A, Amend 7 per B31019 acceptance ltr & Vendor Program Branch rept Rept withheld
KEDDIB, N N Gibbs & Hill, Inc (subs of Dravo Corp). 83/11/21
NRC - No Detailed Affiliation Given 2pp. 21379 023 24X
Fiche 50-368, 83/11/21, 8312050593

8312160165 Forwards proprietary Topical Rept XN-NF-79-59(P)(A), "Methodology for Calculation of Pressure Drop in BWR Fuel Assemblies " Rept withheld (ref 10CFR2 790)
CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 126 B3 83/12/01 THOMAS, C O Standardization & Special Projects Branch 1p 21541 141

8312200575 Forwards proprietary response to Core Performance Branch request for addl info on Topical Rept WCAP-7908 re application of FACTRAN code to safety analysis Response withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2856 83/11/29
THOMAS, C O Standardization & Special Projects Branch 1p 21591 017

--8312200580 Requests 831129 response to Core Performance Branch request for addl info on Topical Rept WCAP-7908 re application of FACTRAN code to safety analysis be withheld (ref 10CFR2 790 & 10CFR9 5(4))
WIESEMANN, R A Westinghouse Electric Corp AW-B3-105 83/11/30
THOMAS, C O Standardization & Special Projects Branch 1p 21591 018

8401040069 Forwards draft IE Info Notice 83-63, Suppl 1 re potential failures of Westinghouse Type SA-1 relays, for comment
BAER, R L Engineering & Generic Communications Branch 83/12/23
BCHMIDT, W J Westinghouse Electric Corp 7pp 21711 319

8401040091 Forwards Procedure LIM-UT-1, Rev 1, "Reg Guide 1.150 Method for Compliance," per commitment at 830831 meeting to provide description of qualification of GE ultrasonic test process for reactor pressure vessel insp
KEPFER, J S Philadelphia Electric Co 83/12/28 EISENHUT, D O Division of Licensing. 2pp. 21703 210 24X Fiche 50-352, 83/12/28, 8401040091.

--8401040095 Rev 1 to Procedure LIM-UT-1, "Reg Guide 1.150 Method for Compliance "
FORBYTHE, F., MILLER, W F General Electric Co 83/10/11 7pp
21703 212 24X Fiche 50-352, 83/12/28, 8401040091

8401040270 Forwards CEN-261(A), "Arkansas Nuclear One, Unit 2, Cycle 4 Shoulder Gap Evaluation," in order to complete response to concerns expressed in NRC 830608 ltr
MARSHALL, J R Arkansas Power & Light Co 2CAN128306 83/12/16, 8401040270
QAGLIARDI, J E Division of Resident, Reactor Project & Engineering Programs. 1p 21701 327 24X Fiche 50-368, 83/12/16, 8401040270.

--8401040275 CEN-261(A)
"Arkansas Nuclear One, Unit 2, Cycle 4 Shoulder Gap Evaluation "
* Combustion Engineering, Inc 83/11/30 7pp 21701:328. 24X
Fiche 50-368, 83/12/16, 8401040270

8401040530 SAI-1-186-07-087-1
"Evaluation of Code Requirements for Using Cold-Formed Stainless Steel in Spent Fuel Storage Racks," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 83/12/16 NRC - No Detailed Affiliation Given 50pp 21706 014

8401050022 Summary of 831213 meeting w/OE in Bethesda, MD re recommended use, maint, testing & reliability of GE AK-2-25 reactor trip breakers List of attendees & points relevant to breaker reliability issue encl
LEY, M Licensing Branch 3 83/12/28 BUTCHER, E Operating Reactors Assessment Branch 3pp 21736 357

8401050164 Forwards Rev 1 to Westinghouse Owners Group "Emergency Response Guidelines: Low Pressure Version" & "Emergency Response Guidelines: High Pressure Version " Rept addressee NUREG-0737, Item 1 C.1 Plant-specific activities may begin
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co 80-111 83/11/30
THOMPSON, H L Division of Human Factors Safety 12pp. 21716 118

--8401050168 Rev 1 to "Emergency Response Guidelines, Low Pressure Version."
* Westinghouse Electric Corp 83/09/01 428pp 21716:130.

--8401050174 Rev 1 to "Emergency Response Guidelines, High Pressure Version "
* Westinghouse Electric Corp 83/09/01 446pp. 21717.198

8401050167 Forwards Endorsements 61 & 32 to NELIA Policy NF-193 & MAELU Policy MF-94, respectively.
ASHBURN, D J Marsh & McLennan, Inc 83/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 21727 328

8401050377 Forwards proprietary & nonproprietary, "Digital Simulation of C-E NSSB " Proprietary rept withheld (ref 10CFR2 790)
MARSHALL, J R Arkansas Power & Light Co. 2CAN128310 83/12/27.
MILLER, J R Operating Reactors Branch 3 5pp 21724 290 24X
Fiche 50-368, 83/12/27, 8401050377.

--8401050584 Nonproprietary "Digital Simulation of C-E NSSB, "
* Combustion Engineering, Inc. 82/01/06 256pp 21724 295 24X
Fiche 50-368, 83/12/27, 8401050577

8401060216 Forwards topical rept evaluation of WCAP-7961, "BART A-1 Computer Code for Best Estimate Analysis of Reflood Transients " Rept acceptable for ref in license applications to extent specified
THOMAS, C O Standardization & Special Projects Branch 83/12/21
RAHE, E P Westinghouse Electric Corp 1p 21744 137

--8401060219 Topical rept evaluation of WCAP-7961, "BART A-1 Computer Code for Best Estimate Analysis of Reflood Transients, " Rept acceptable for ref in license applications to extent specified
* NRC - No Detailed Affiliation Given 83/12/21 21pp. 21744 138

8401060269 Forwards Endorsements 125-126 & 60-61 to NELIA & MAELU Policies NF-34 & MF-59, respectively
ASHBURN, D J Marsh & McLennan, Inc 83/12/28. SALTZMAN, J Assistant Director for State & Licensee Relations 4pp. 21741:264

8401060284 Forwards topical rept evaluation of NEDE-30130, "Steady-State Nuclear Methods " Rept acceptable for ref in license applications to extent specified Proprietary & nonproprietary versions should be published.
THOMAS, C O Standardization & Special Projects Branch. 83/12/22
CHARNLEY, J S General Electric Co 1p 21755:149.

--8401060286 Topical rept evaluation of NEDE-30130, "Steady-State Nuclear Methods " Rept acceptable for inclusion in licensing documentation
FIENO, D Core Performance Branch 83/12/22 6pp 21755.170.

8401060379 Forwards requested info for use in determining fee to be assessed for review of Topical Rept NEDE-30130, "Steady-State Nuclear Methods."
THOMAS, C O Standardization & Special Projects Branch. 83/12/22.
BERKOW, H N Management Analysis Branch 2pp. 21743:360

NONDOCKETED ITEMS

- 8401060414 Confirms 831229 telcon re 840118 mgt meeting to present results of study of multi-badging in regard to exposure control program
LEWIS, R C Division of Project & Resident Programs 83/12/29
PARRIS, H G Tennessee Valley Authority 1p 21740 362
- 8401060516 Summary of 831214 meeting w/C-E Regulatory Response Group re GE AK-2-25 reactor trip breakers & proposed NRC actions
Attendance list & viewgraphs encl
LEY, M Licensing Branch 3 83/12/23 BUTCHER, E Operating
Reactors Assessment Branch 13pp 21744 110
- 8401060549 Forwards info for determining fee to be assessed for review of WCAP-9561, "BART-A-1 Computer Code for Best Estimate Analysis of Reflood Transients"
THOMAS, C D Standardization & Special Projects Branch 83/12/22
BERKOW, H N Management Analysis Branch 2pp 21755 129
- 8401090316 Summary of 831215 meeting w/B&W Regulatory Response Group re GE AK-2-25 reactor trip breaker & proposed staff actions
Agenda & viewgraphs encl
LEY, M Licensing Branch 3 83/12/28 BUTCHER, E Operating
Reactors Assessment Branch 28pp 21768 164
- 8401090392 Notifies of billing for review of NEPE/NEDO-21175-3(P/NP), "BWR Fuel Assembly Evaluation of Combined SBE & LOCA Loadings"
MILLER, W D License Fee Management Branch 83/12/22 QUIRK, J F
General Electric Co 1p 21768 059
- 8401090405 Application for Proposed Tech Spec Change 83-15 to License DPR-35, correcting error in GE Oct 1983 reload licensing submittal for restart from Refueling Outage 6
HARRINGTON, W D Boston Edison Co BECO 83-301 83/12/28
VASSALLO, D B Operating Reactors Branch 2 2pp 21750 246 24X
Fiche 50-293, 83/12/28, 8401090405
- 8401090554 NEDO-21696 ERR 03
Errata & addenda to NEDO-21696, "LOCA Analysis Rept for Pilgrim Nuclear Power Station"
* General Electric Co 83/10/31 3pp 21750 255 24X
Fiche 50-293, 83/12/28, 8401090405
- 8401090556 22A1694 ROO
"GE BWR Supplemental Reload Licensing Submittal for Pilgrim Nuclear Power Station, Unit 1, Reload 6"
VERBRUYE, P A, HILF, C L, CHARLNEY, J S General Electric Co
83/10/31 20pp 21750 258 24X Fiche 50-293, 83/12/28, 8401090405.
- 8401090416 Notifies of billing for review of NEDO-24712, "Core Spray Design Methodology Confirmation Tests," dtd Aug 1979
MILLER, W D License Fee Management Branch 83/12/22 SHERWOOD, D G
General Electric Co 1p 21768 056
- "8401090422 Notifies of billing for review of WCAP-10216, Part A, "Relaxation of Constant Axial Offset Control" & Part B, "FD Surveillance Tech Spec"
MILLER, W D License Fee Management Branch 83/12/29 RAHE, E P
Westinghouse Electric Corp 1p 21768 054
- 8401090428 Requests necessary action to bill Westinghouse for review of WCAP-10216(P). Notification when fee paid requested
MILLER, W D License Fee Management Branch 83/12/29 MANION, W. E.
NRC - No Detailed Affiliation Given 1p 21768 055
- 8401090484 Advises that GA program described in BAW-10096A, Rev 4 implemented satisfactorily Continued acceptability contingent upon maintaining satisfactory level verified by periodic IE insps
COLLINS, J T Region 4, Office of Director 83/12/30 GUILBERT, D E.
Sabcock & Wilcox Co 2pp 21753 126
- 8401090582 Forwards engineering assurance documentation describing program & repts re evaluated area findings & corrective action. Comments requested by 840131
NOVAK, T M Assistant Director for Licensing 83/12/27
VOLLMER, R H Division of Engineering MATTHEW, R J Division of Systems Integration (Post 831003) PARTLOW, J G Division of GA, Safeguards & Inspection Programs (Post 830103) 1p 21756 055 24X
Fiche 50-498, 83/12/27, 8401090582
- 840110042 Discusses evaluation methodology for "Convolution of LOCA Heat Source Uncertainties." Methodology seeks to improve on overly conservative LOCA models while complying w/10CFR30, App K
RAHE, E. P. Westinghouse Electric Corp SED-SA-00560 83/12/27
THOMAS, C. Standardization & Special Projects Branch 2pp 21772, 244
- 840110239 Forwards "Ref Core Rept Vantage 3 Fuel Assembly" & application for withholding proprietary info Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2872 83/12/30
THOMAS, C D Standardization & Special Projects Branch 3pp 21770 233
- 840110246 Requests that proprietary Rept WCAP-10444, "Ref Core Rept Vantage 3 Fuel Assembly," be withheld (ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp AW-83-113 83/12/30
THOMAS, C D Standardization & Special Projects Branch 1p 21770 236
- 840110361 Forwards draft NRC IE Info Notice 83-63, Suppl 1 re potential failures of Westinghouse Type BA-1 differential relays
Comments requested
BAER, R L Division of Emergency Preparedness & Engineering Response (Post 830103) 6835 83/12/23 RHOADS, E W Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 6pp 21794 333
- 8401120118 Ack receipt of CNSI-WF-C-01-NP, "Waste Form Certification - Cement" All correspondence should be addressed to LB Person W/O encl rept review schedule
JOHNSON, T C Engineering Branch (Post 831001) 83/12/07
POPPEL, L K Chem-Nuclear Systems, Inc 1p 21805 202
- 8401120604 Forwards proprietary & nonproprietary version of topical rept, "Polyethylene High-Integrity Containers" W/o proprietary rept
POPPEL, L K Chem-Nuclear Systems, Inc RA-0316-3 83/12/23
JOHNSON, T NRC - No Detailed Affiliation Given 4pp 21803 230
- 8401120608 CNSI-HIC-14871-DI-NP
Nonproprietary version of "Polyethylene High-Integrity Containers"
* Chem-Nuclear Systems, Inc 83/12/23 205pp 21803 242
- 8401130085 Forwards GA Co fuel surveillance rept, "Metallographic Exam of Fuel Rod From Segment 2 - Fort St Vrain Fuel Element 1-2415"
BREV, H L Public Service Co of Colorado P-84001, 84/01/03
COLLINS, J T Region 4, Office of Director 1p 21802 244 24X
Fiche 50-267, 84/01/03, 8401130085
- 8401130089 906968 RA
Issue A to "Metallographic Exam of Fuel Rod From Segment 2 - Fort St Vrain Fuel Element 1-2415"
* GA Technologies, Inc /General Atomic Co 83/11/09 33pp 21802 245 24X Fiche 50-267, 84/01/03, 8401130085
- 8401170169 Responds to 830331 request for addl info on Rev 1 to XN-NF-82-06(P), "Qualification of Exxon Nuclear Fuel For Extended Burnup" Response contained in XN-NF-719(P), "Assessment of Potential Radiological Consequences .."
CHANDLER, J C Exxon Nuclear Co, Inc (subs. of Exxon Corp) JCC-007 84 84/01/13 THOMAS, C D Standardization & Special Projects Branch 2pp 21833 206
- 8401170361 Forwards "Mark III Encroachments 1/10 Linear Froude Scaled Bubble Pressure Equalization Test," functional spec & test plan & procedure. Suggests meeting for observation of test & review in early Feb 1984
ENGLAND, L. A. Containment Issues Owners Group. ENGLAND, L. Gulf States Utilities Co. LAE-08-09B 84/01/11 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp 21829 105
- 8401170363 Rev OK to "Mark III Encroachments 1/10 Linear Froude Scaled Bubble Pressure Equalization Test," functional spec (Test Series 6101)
MINTZ, S, MCNAMARA, E J, MCINTYRE, T R General Electric Co PWA 3695ZZ ROK 84/01/05 17pp 21829 107
- 8401170367 Rev OK to "Mark III Encroachments 1/10 Linear Froude Scaled Bubble Pressure Equalization Test," test spec (Test Series 6101)
MCNAMARA, E J, MCINTYRE, T R General Electric Co PWA 3695ZZ ROK 84/01/05 10pp 21829 124
- 8401170371 Rev A to Procedure 690 109B, "Mark III Encroachments 1/10 Linear Froude Scaled Bubble Pressure Equalization Test," test plan & procedure (Test Series 6101).
MINTZ, S, MCNAMARA, E J, BIELEFELD, E L General Electric Co PWA 3695ZZ ROK 84/01/09 82pp 21829 134.
- 8401170413 Forwards ASME Code rept re overpressure protection in response to DL safety review request for addl info. Question 440 3
MITTL, R L Public Service Electric & Gas Co of New Jersey 84/01/06 SCHWENCER, A. Licensing Branch 2. 1p 21828 314 24X
Fiche 50-354, 84/01/06, 8401170413.

NONDOCKETED ITEMS

471

--B401170420 23A1411 R00
Rev 0 to "Overpressure Protection Rept "
MATA, M. , NAZARENO, E. , IKEMOTO, F. M. General Electric Co 83/01/28
14pp 21828 315 24X Fiche 50-354, 84/01/06, 8401170413

--B401170426 DC23A1411 R00
Rev 0 to "Overpressure Protection Rept "
MATA, M. , NAZARENO, E. , IKEMOTO, F. M. General Electric Co 83/01/28
2pp 21828 329 24X Fiche 50-354, 84/01/06, 8401170413

B401170465 Forwards info supporting request for revalidation of
previously approved route for shipment of irradiated reactor
fuel w/o encl.
KIRKLAND, M. W. General Electric Co 23200 83/12/12 HILLMAN, C. R.
Office of Nuclear Material Safety & Safeguards, Director 1p
21936 303

B401180160 Requests B40118 meeting w/Core Performance Branch & Reactor
Sys Branch to discuss schedule of technical review to be
undertaken re generic review of BWR & PWR plant transient
models & PWR small break LOCA model
CHANDLER, J. C. Exxon Nuclear Co, Inc (subs of Exxon Corp)
JCC 002 B4 84/01/09 THOMAS, C. D. Standardization & Special
Projects Branch 1p 21840 310

B401200037 Forwards Endorsements 31 & 32 to MAELU Policy MF-95
ROBBINS, J. G. Marsh & McLennan, Inc 84/01/13 SALTZMAN, J.
Assistant Director for State & Licensee Relations 3pp 21867 012

B401200055 Forwards proprietary & nonproprietary versions of
"Westinghouse Wet Annular Burnable Absorber Evaluation
Rept " Proprietary version withheld (ref 10CFR2 790)
RAHE, E. P. Westinghouse Electric Corp NS-EPR-2871 83/12/30
THOMAS, C. D. Standardization & Special Projects Branch 2pp
21866 103

--B401200060 Requests proprietary version of "Westinghouse Wet Annular
Burnable Absorber Evaluation Rept," be withheld from public
disclosure (ref 10CFR2 790)
WIEBEMANN, R. A. Westinghouse Electric Corp AW-83-91 83/12/30
THOMAS, C. D. Standardization & Special Projects Branch 9pp
21866 105

--B401200064 WCAP-10377-A
Nonproprietary version of "Westinghouse Wet Annular Burnable
Absorber Evaluation Rept "
KRAHER, F. W. , ARLOTTI, M. G. , KELLER, H. W. Westinghouse Electric Corp
83/10/31 44pp 21866 115

B401200149 Forwards Endorsements 125 & 126 to NELIA Policy NF-1
ROBBINS, J. G. Marsh & McLennan, Inc 84/01/13 SALTZMAN, J.
Assistant Director for State & Licensee Relations 3pp. 21865 358

B401200163 Application for amend to License DPR-65, revising pressure-
temp limits & max heatup rate for RCS.
COUNSIL, W. G. Northeast Nuclear Energy Co (subs of Northeast
Utilities) COUNSIL, W. G. Northeast Utilities 810990 84/01/04
MILLER, J. R. Operating Reactors Branch 3 3pp 21866 212 24X
Fiche 50-336, 84/01/04, 8401200163

--B401200168 TR-N-MCM-008
"Post-Irradiation Evaluation of Reactor Vessel Surveillance
Capsule W-77 "
BYRNE, B. T. , KOZIDL, J. J. , JACQUES, R. C. Combustion Engineering, Inc
82/04/30 117pp 21866 223 24X Fiche 50-336, 84/01/04,
8401200163

B401230494 Forwards "Procedures Generation Package for Seabrook
Station," in response to Generic Ltr 82-33 requirements re
emergency operating procedures Rev 1 to "Westinghouse Owners
Group Emergency Response Guidelines," also encl
DEVINCENTI, B. J. Yankee Atomic Electric Co SBN-616 84/01/17.
KNIGHTON, G. W. Licensing Branch 3 3pp 21874 005 24X
Fiche: 50-443, 84/01/17, 8401230494

--B401230520 Rev 0 to "Seabrook Station Writers Guide for Emergency
Response Procedures "
* Westinghouse Operating Plants Owners Group 0L-82-33.
83/10/31 277pp 21874 242 24X Fiche 50-443, 84/01/17,
8401230494

B401240187 Responds to 831228 ltr re use of Topical Rept NEDO 20566,
"GE Analytical Model for Loss-of-Coolant Analysis in
Accordance w/10CFR50, App K " Rept provides basis for
analysis of core standby cooling sys & initial LOCA
PILANT, J. M. Nebraska Public Power District, NLS8400037 84/01/16
VASSALLO, D. D. Operating Reactors Branch 2 1p 21908 339. 24X
Fiche: 50-298, 84/01/16, 8401240187

B401240195 Forwards request for addl info re TVA GA program, including
info re design review, verification tests, procurement by
const, manufacturer drawings & instruction manuals & const
testing
LEWIS, R. C. Division of Project & Resident Programs 83/12/30
MILLS, L. M. Tennessee Valley Authority 10pp 21910 315

B401240471 Advises that review of NRC evaluation of BART code received
B40103 indicates several addl tasks must be completed within
specific schedule Summary & proposed schedule for completion
listed Table 2-3 re 163 rod blocked bundle test matrix encl
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2876 84/01/11
THOMAS, C. D. Standardization & Special Projects Branch. 8pp
21908 248

B401250006 Forwards Rev 3 to "Class IE Qualification - Qualification of
Class IE Electrical Equipment," per 830908 request Rept
incorporates 830908 ltr & BER Changes make CENPD-253
consistent w/CESBAR-F, Section 3 11
SCHERER, A. E. Combustion Engineering, Inc LD-84-004 84/01/20
THOMAS, C. D. Standardization & Special Projects Branch 1p
21935 001

--B401250007 CENPD-253-A R03
Rev 3 to "Class IE Qualification - Qualification of Class IE
Electrical Equipment "
* Combustion Engineering, Inc 83/12/31. 200pp 21935 002.

B401270159 Requests addl info for review of BAW-10153P, "Extended
Burnup Evaluation " Responses expected by 840213
THOMAS, C. D. Standardization & Special Projects Branch 84/01/13.
TAYLOR, J. H. Babcock & Wilcox Co 3pp 22002 310

B401270166 Forwards request for addl info re XN-NF-82-06(P),
"Qualification of Exxon Nuclear Fuel for Extended Burnup "
Responses requested by 840213
THOMAS, C. E. Standardization & Special Projects Branch 84/01/13
TAYLOR, J. H. Exxon Nuclear Co, Inc (subs of Exxon Corp) 3pp
22002 299

B401270191 Notifies of billing for review of XN-NF-B1-58, "RODEX 2 Fuel
Rod Thermal-Mechanical Response Evaluation Model "
MILLER, W. D. License Fee Management Branch 84/01/16 CHANDLER, J. C.
Exxon Nuclear Co, Inc (subs of Exxon Corp) 1p 22002 271

--B401270196 Requests billing to Exxon Nuclear Co, Inc for review of
XN-NF-B1-58, "RODEX 2 Fuel Rod Thermal-Mechanical Response
Evaluation Model "
MILLER, W. D. License Fee Management Branch 84/01/16 MANION, W. E.
Financial Operations Branch 1p 22002 272

B401270271 Forwards comments on draft IE bulletin, "Undervoltage Trip
Attachments of Reactor Trip Breakers "
WELLS, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northeast
Utilities 84/01/20 DEYOUNG, R. C. Director's Office, Office of
Inspection and Enforcement 3pp 21976 065

B401300273 Application to amend License DPR-68, revising Tech Specs to
accommodate Reload 5, Cycle 6 Class III amend fee encl
MILLS, L. M. Tennessee Valley Authority 84/01/23 DENTON, H. B.
Office of Nuclear Reactor Regulation, Director 2pp. 21994 186
24X Fiche 50-296, 84/01/23, 8401300273

--B401300285 NEDO-20697
"Bottled-up Operation of BWR "
CARROLL, D. G. , ECKERT, E. C. , HOLLAND, L. K. General Electric Co
74NED69, 74/11/30 35pp 21994 268 24X Fiche 50-296, 84/01/23,
8401300273

--B401300310 NEDO-24194A ERR 02
Errata to "LOCA Analysis for Browns Ferry Nuclear Plant
Unit 3," Sheet 2 NSHC determination supporting 840123
application to amend License DPR-68 encl
* General Electric Co 79NED296, 83/11/30 35pp 21995 072
24X Fiche: 50-296, 84/01/23, 8401300273.

B401310007 Comments on IE Info Notice 83-63, Suppl 1, "Potential
Failures of Type BA-1 Relays " Supplemental info re
differential relays adequate. Consequences of failure
include potential loss of devices important to safety
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2879 84/01/20
BAER, R. L. Division of Emergency Preparedness & Engineering Response
(Post 830103) 1p 22023 218

B401310066 Forwards draft NUREG-1070, "Severe Accident Program for
Nuclear Power Plant Regulation " Draft will be discussed at
ACRS subcommittee 840127 meeting Comments requested by
840124 w/o encl
EISENHUT, D. G. Division of Licensing, 84/01/13 SHERWOOD, G. G.
General Electric Co. 2pp 22026 360

NONDOCKETED ITEMS

B401310291 Forwards documentation of agreements reached w/NRC at B31212 meeting Post-accident sampling sys for measurement of dissolved gas adequate. Viewgraphs encl
 BHERMDD, G G General Electric Co MFN-006-B4 B4/01/18
 EISENHUT, D G Division of Licensing. 11pp 22020 345

B401310309 Application to amend License NPF-5, supporting mods associated w/installation of GE analog transmitter trip sys Encl proprietary Rev 1 to NEDE-22154-1, "Analog Trip Sys For Engineered Safeguards Sensor Trip Inputs" withheld
 BECKHAM, J T Georgia Power Co NED-B4-017 B4/01/23 STOLZ, J F
 Operating Reactors Branch 4 3pp 22021 001 24X
 Fiche. 50-321, B4/01/23, B401310309.

B401310352 Forwards simplified diagrams of minor wiring changes, including test sequence descriptions. Completing review of potential undetectable failure of test switch in solid state protection sys discussed in 820606 ltr
 RAHE, E P Westinghouse Electric Corp NS-EPR-2877 B4/01/17
 DEYOUNG, R. Director's Office, Office of Inspection and Enforcement 5pp 22019, 307.

B401310433 Advises that invoice for review of Topical Rept BAH-10149, "Power Train-Hybrid Computer Simulations of B&W Nuclear Power Plant," will be sent under separate cover
 MILLER, W D License Fee Management Branch B4/01/16 TAYLOR, J H
 Babcock & Wilcox Co 1p 22034 349

--B401310437 Requests ofc bill B&W for NRR review of Topical Rept BAH-10149, "Power Train-Hybrid Computer Simulation of B&W Nuclear Power Plant"
 MILLER, W D. License Fee Management Branch B4/01/16 MANION, W E
 Financial Operations Branch 1p 22034 350

WASTE MGT NUCLEAR WASTE MANAGEMENT

B401030262 Confirms that S Frishman will present testimony on behalf of State of TX at scheduled meeting on B40111 re draft DOE siting guidelines for high level radwaste repositories
 FRISHMAN, S Texas, State of. 48FR50432 B3/12/28 CHILK, S J
 Office of the Secretary of the Commission 1p 21728 302

B401030288 Requests opportunity to present oral comments on DOE proposed repository guidelines & NRC concurrence w/guidelines. State proposed rulemaking procedure is better method for NRC to receive public comment
 HECTOR, A G Serious Texans Against Nuclear Dumping 48FR48473
 B3/11/13 Office of the Secretary of the Commission 1p
 21726, 351.

B401090358 Comments on petition for rulemaking re nuclear waste repository siting guidelines Yakima Indian Nation supports request of States of UT & WI that Commission B40111 meeting be delayed
 TOUSLEY, D R Harmon & Weiss, TOUSLEY, D R Yakima Indian Nation
 48FR50432 B4/01/06 Office of the Secretary of the Commission
 1p. 21734, 072.

B401090479 Comments on petition for rulemaking re NRC concurrence in high level waste repository safety guidelines under Nuclear Waste Policy Act of 1982
 KEARNEY, J J. Edison Electric Institute. 48FR50432 B4/01/05.
 CHILK, S J. Office of the Secretary of the Commission 1p
 21753, 138.

B401090481 Comments on petition for rulemaking re NRC concurrence in high level waste repository safety guidelines under Nuclear Waste Policy Act of 1982 Intent to participate in public hearing reaffirmed.
 BERICK, D M Environmental Policy Institute 48FR50432. B4/01/04
 CHILK, S J Docketing & Services Branch. 1p 21753 137.

B401100122 Forwards brief & comments to DOE re guidelines under NRC consideration concerning NRC concurrence/nonconcurrence in DOE waste repository siting guidelines.
 MURPHY, M R. Murphy & Davenport. 48FR50432. B4/01/07 CHILK, S J.
 Office of the Secretary of the Commission. 1p. 21761, 002.

--B401100129 Brief re DOE guidelines for recommendation of sites for nuclear waste repositories & re NRC concurrence NRC concurrence is legal prerequisite. Commission must determine consistency w/Nuclear Waste Policy Act.
 MURPHY, M R. Nebraska, State of. MURPHY, M R Murphy & Davenport
 B4/01/07. 64pp. 21761, 003

B401100134 Requests 45 to 60-day extension for submittal of written comments & oral presentations on DOE radwaste repository siting guidelines. Delay needed to review EPA final rule & NRC guideline evaluation.
 BINDERBRAND, C Wisconsin, State of. 48FR50432. B4/01/03.
 PALLADINO, N J. Commissioners 2pp. 21761, 354

B401100142 Forwards testimony on DOE guidelines for recommendation of sites for nuclear waste repositories to be presented before Commission on B40111, per B31212 order GS Larson will present testimony
 KALITOWSKI, T Minnesota, State of 48FR50432 B4/01/06
 CHILK, S J Office of the Secretary of the Commission 1p
 21760 015

--B401100143 Testimony of GS Larson on general guidelines for recommendation of sites for nuclear waste repositories
 LARSON, G S Minnesota, State of B4/01/11 7pp 21760 016

B401100150 Comments on petition for rulemaking re NRC concurrence on DOE nuclear waste repository guidelines Comment deadline should be extended until at least B40201 Petition for DOE rulemaking encl
 MATHESON, S M Utah, State of 48FR50432 B3/12/22 PALLADINO, N J
 Commissioners 14pp 21760 087

B401100160 Forwards comments on proposed rulemaking re NRC concurrence in DOE radwaste repository siting guidelines
 TOUSLEY, D R Harmon & Weiss TOUSLEY, D R Yakima Indian Nation
 48FR50432 B4/01/09 CHILK, S J Office of the Secretary of the
 Commission 1p 21760 101

--B401100163 Comments on proposed rulemaking re NRC concurrence in DOE radwaste repository siting guidelines. Commission urged to reject guidelines
 WEISS, E R, TOUSLEY, D R Harmon & Weiss WEISS, E R Yakima
 Indian Nation 48FR50423 B4/01/09 32pp 21760 102

B401100196 Comments on petition for rulemaking re NRC concurrence on DOE waste repository siting guidelines
 FRISHMAN, S Texas, State of 48FR50432 B4/01/06 CHILK, S J
 Docketing & Services Branch. 1p 21760 218

--B401100198 Testimony of State of TX re NRC concurrence in DOE general guidelines for recommendations of sites for nuclear waste repositories
 FRISHMAN, S Texas, State of B4/01/11 16pp 21760 219

B401100202 Comments on proposed rulemaking re NRC concurrence in DOE high level waste repository safety guidelines. Proposed 10CFR960.
 BINDERBRAND, C Wisconsin, State of 48FR50432 B4/01/07
 CHILK, S J Office of the Secretary of the Commission. 16pp
 21760, 248

B401100232 Preliminary memorandum adopting State of UT submissions opposing NRC concurrence in DOE repository siting guidelines
 LOCKHART, W J National Parks Association LOCKHART, W J Friends of
 the Earth 48FR50432 B4/01/08 1p 21759 058.

--B401100242 Statement of CJ Duffy & N Barton on behalf of State of UT re review of certain technical aspects of DOE proposed guidelines for siting of nuclear waste repository
 DUFFY, C J, BARTON, N Utah, State of 48FR50432 B4/01/08
 21pp 21759 059

--B401100244 Preliminary memorandum opposing NRC concurrence in DOE B31118 proposed guidelines for recommendation of sites for nuclear waste repositories
 PICKERELL, L. Utah, State of B4/01/08 Commissioners 73pp
 21759 080

B40110219 Comments on proposed rulemaking re NRC concurrence in high level waste repository safety guidelines under Nuclear Waste Policy Act of 1982 Commission ill-served by proposed guidelines & should withhold concurrence
 BERICK, D M Environmental Policy Institute 48FR50432 B4/01/09
 7pp 21772, 287

B40110222 Forwards R Loux, Director of State of NV Nuclear Waste Project Ofc, comments on DOE waste repository siting guidelines Comments will be included in record for B40111 meeting
 DAVENPORT, J H. Murphy & Davenport DAVENPORT, J H Nevada, State
 of. 48FR50432 B4/01/09 CHILK, S J. Office of the Secretary of
 the Commission 1p. 21780, 282

--B40110226 Comments on proposed rule 10CFR960 re NRC concurrence in DOE guidelines for recommendation of sites for nuclear waste repositories Guidelines unacceptable
 LOUX, R., JOHNSON, C Nevada, State of B4/01/09 15pp
 21780, 283

NONDOCKETED ITEMS

473

- 840110430 Forwards addl supportive info to be included w/830701 high integrity container use application, per agreement reached at 83109 meeting. Info consists of revised response to NRC comments, State of WA requested data & drop calculation. SAUER, R E U S Ecology, Inc (Formerly Nuclear Engineering, Inc.) 83/11/29 KIRNER, N Washington, State of 38pp 21795 247
- 840110454 Summary of 831201-02 meetings w/UMTRAP states, Indian Tribes Task Force, NRC, DOE & Jacobs re UMTRAP draft plan for implementation of EPA stds for UMTRAP sites. HAZLE, A J Colorado, State of 83/12/04 Colorado, State of 2pp 21790 352
- 8401120005 Forwards complete Page 2 to 831025 executed DOE Cooperative Agreement DE-AC04-83AL16238 w/Navajo Tribe in support of UMTRAP per Public Law 95-604 Page corrected to reflect agreement effective date. CONE, T C Energy, Dept of 83/12/19 ZAH, P Navajo Nation 3pp 21807 035
- 8401120008 Forwards agenda for BWIP NRC/DOE 840109-12 geochemistry workshops to be held at Thunderbird Inn. OLSON, D L Energy, Dept of 849 83/12/30 HOVIS, J B Yakima Indian Nation FARROW, M J Affiliation Unknown STEVENS, D W Washington, State of 3pp 21807 016
- 8401120009 Advises of NRC 830109-12 visit to DOE/Rockwell to review hydrology data. Participation welcomed. OLSON, D L Energy, Dept of 849 83/12/30 HOVIS, J B Yakima Indian Nation FARROW, M J Affiliation Unknown STEVENS, D W Washington, State of 2pp 21807 014
- 8401120011 Notifies of upcoming Jan-Mar 1984 meetings re waste storage. NEFF, J O Energy, Dept of 00214 83/12/30 CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of FORSYTHE, R Mississippi, State of 1p 21807 013
- 8401120013 Notifies of upcoming Jan & Feb 1984 meetings re waste storage. NEFF, J O Energy, Dept of 00212 83/12/16 CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of FORSYTHE, R Mississippi, State of 1p 21807 012
- 8401120019 Forwards listed BWIP hydrological test interval repts. per discussion at recent BWIP/NRC workshop for underground test plan. OLSON, D L Energy, Dept of 00647 83/12/23 WRIGHT, R J High Level Waste Technical Development Branch 2pp 21807 03B
- 8401120022 SD-BWI-TI-089 R00
"Preliminary Results of Hydrologic Testing Umtanum Basalt Fracture Zone at Borehole RRL-2 (3,781-3,827 ft) "
STRAIT, S R , SPANE, F A Energy, Dept of 00647 83/03/31 36pp 21807 040
- 8401120025 SD-BWI-TI-090 R00
"Preliminary Results of Hydrologic Testing Middle Sentinel Bluffs Vesicular Zone at Borehole RRL-2 (3,057-3,172 ft) "
STRAIT, S R , SPANE, F A Energy, Dept of 00647 83/08/31 25pp 21807 077
- 8401120028 SD-BWI-TI-095 R00
"Preliminary Results of Hydrologic Testing Composite Middle Sentinel Bluffs Basalt Flow Bottom at Borehole RRL-2 (3,247-3,344 ft) "
STRAIT, S R , SPANE, F A Energy, Dept of 00647 82/11/30 36pp 21807 104
- 8401120033 SD-BWI-TI-102 R00
"Preliminary Results of Hydrologic Testing Middle Sentinel Bluffs Flow Top at Borehole RRL-2 (2,981-3,020 ft) "
STRAIT, S R , SPANE, F A Energy, Dept of 00647 83/02/17, 36pp 21807 142
- 8401120037 SD-BWI-TI-105 R00
"Preliminary Results of Hydrologic Testing Composite Umtanum Basalt Flow Top at Borehole RRL-2 (3,568-3,781 ft). "
STRAIT, S R , SPANE, F A Energy, Dept of 00647, 82/11/12 47pp, 21807, 180
- 8401120040 SD-BWI-TI-109 R00
"Preliminary Results of Hydrologic Testing Middle Sentinel Bluffs Basalt Columnade/Entablature (3,175-3,244 ft) at Borehole RRL-2 "
STRAIT, S R , SPANE, F A Energy, Dept. of 00647 82/12/06 37pp, 21807 265
- 8401120046 SD-BWI-TI-130 R00
"Hydrologic Test Results for Rattlesnake Ridge Interbed & Pawona Basalt Flow Top at Borehole DB-15 "
STRAIT, S R , BROWN, W R Energy, Dept of, 00647 83/04/30, 22pp, 21807 304
- 8401120049 SD-BWI-TI-131 R00
"Hydrologic Test Results for Selah Interbed at Borehole DB-15 "
STRAIT, S R , BROWN, W R Energy, Dept of 00647 83/08/31 29pp 21807 326
- 8401120065 SD-BWI-TI-142 R00
"Hydrologic Test Results of Cold Creek Interbed & Asotin Basalt Flow Top at Borehole DB-15 "
STRAIT, S R , BROWN, W R Energy, Dept of, 00647 83/10/31 24pp 21807 351
- 8401120067 SD-BWI-TI-150 R00
"Results of Hydrologic Testing of Cold Creek Interbed & Umtanum Basalt Flow Top at Borehole DB-15."
STRAIT, S R , PRATER, L B Energy, Dept of, 00647 83/09/21 26pp 21808-013
- 8401120092 Ack receipt of 831116 ltr informing NRC of cancellation of joint workshops re environ appraisal review. VIETH, D L Energy, Dept of 83/12/09, COPLAN, B M Division of Waste Management 5pp 21806 206
- 8401120107 Advises that util will use NSA/IMPELL rept, "Methodologies for Classification of Low Level Radwaste From Nuclear Power Plants," in order to comply w/requirements of 10CFR61 Revised process control program due by 840229. BAYNARD, P Y Florida Power Corp. 3F1283-34 83/12/27, STOLZ, J P Operating Reactors Branch 4 2pp, 21805 232 24X
Fiche 50-302, 83/12/27, 8401120107.
- 8401120108 Informs of UMTRA Project Ofc activities. Comments for improvement requested. MORLEY, J A Energy, Dept. of 83/12/16, HIGGINSBOTHAM, L Low Level Waste Licensing Branch, 4pp 21805 228
- 8401120113 Discusses SWIFT II training seminar re harmonic mean & flow parameters for frequency div multiplex groundwater models. Alternative techniques for use of harmonic mean for transmissibility calculations discussed. CRNSTEIN, P , OGDEN, D Geotechnical Branch (Post 831001), 83/12/28 KNAPP, M R Geotechnical Branch (Post 831001) 12pp 21805:209
- 8401120114 Forwards DOE 831203 ltr re vicinity properties associated w/active tailings sites receiving no remedial action. RANDEN, L Wyoming, State of 83/12/13 SMITH, R D Uranium Recovery Field Office 2pp 21805 207
- 8401120117 Forwards annotated outline for program plan, per Operating Plan Commitment 531281 & Mausshardt 831216 memo Draft program plan should be complete by mid-Feb. ALTOHARE, P M NRC - No Detailed Affiliation Given, 83/12/29 BROWNING, R E Division of Waste Management, 4pp 21805:203
- 8401120118 Ack receipt of CNSI-WF-C-01-NP, "Waste Form Certification - Cement " All correspondence should be addressed to LS Person W/o encl rept review schedule. JOHNSON, T C Engineering Branch (Post 831001) 83/12/09 POPPE, L K Chem-Nuclear Systems, Inc. 1p 21805:202.
- 8401120123 Requests assistance to review Durango preliminary DEB & Shiprock environ assessment Draft comments on Shiprock rept due by 840106 Final comments on Durango rept due by 840117. HIGGINSBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 83/12/27, GREEVES, J Engineering Branch (Post 831001) 1p, 21805, 185.
- 8401120125 Forwards comments on Task 3 of decommissioning plan for Maxey Flats, "Evaluation of Alternatives," Sufficient detail given to assess proposed decommissioning alternatives & modeling methodologies. HIGGINSBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch, 83/12/08 NUSBAUMER, D A Assistant Director for State Agreements Programs 18pp 21805 167.
- 8401120126 Provides status of reviews for UMTRAP, consisting of Shiprock, Durango & Salt Lake City sites. HIGGINSBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch, 83/12/23 KNAPP, M Geotechnical Branch (Post 831001), 2pp 21805, 165
- 8401120128 Trip rept of 831116-1B BNWL workshops in Chicago, IL re region to area screening methodology for crystalline rocks. FEETERS, L A Repository Projects Branch (Post 831001) 83/12/16, MILLER, H J Repository Projects Branch (Post 831001), 7pp, 21805 158

NONDOCKETED ITEMS

8401120131 Requests T Johnson comments on Shiprock draft environ assessment re surface water hydrology by 840106 Comments on Durango PDES due by 840117
HIGGINSBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch
83/12/23 MILLER, H. J. Repository Projects Branch (Post 831001)
1p 21805 153

8401120135 Trip rept of 831114-17 Matls Research Soc annual meeting in Boston, MA re scientific basis for nuclear waste mgt
CHANG, K. C., JUNGLING, T. L. Engineering Branch (Post 831001)
83/12/29 GREEVES, J. T. Engineering Branch (Post 831001) 36pp
21805:118

8401120141 Forwards preliminary geotechnical engineering review comments & questions re Rifle PDES Rept does not contain adequate geotechnical engineering info to support alternative environ impacts of remedial actions
GREEVES, J. Engineering Branch (Post 831001) 83/12/22
HIGGINSBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch
11pp 21805:106

8401120147 Forwards Div of Waste Mgt program plan preliminary outline based on fuel cycle transportation plan Draft program plan expected by mid-Feb 1984
BROWNING, R. E. Division of Waste Management 84/01/03
HAUSSHARDT, D. B. Office of Nuclear Material Safety & Safeguards, Director 4pp. 21805:066

8401120173 Forwards response to B Ross 831017 ltr re proposed testing program for waste form stability requirements, 10CFR61
LEE, T. A. Stock Equipment Co 83/12/13 HIGGINSBOTHAM, L. High Level Waste Licensing Management Branch 3pp 21805:001

8401120236 Presentation before NRC at 840111 hearing on DOE siting guidelines presented to Commission on 831122
* Energy, Dept of. 48FR50432 84/01/11 16pp 21794.072

8401120244 Comments on Commission concurrence on DOE proposed repository guidelines as required by Public Law 97-425
HECTOR, A., HANCOCK, D. Serious Texans Against Nuclear Dumping.
48FR50432. 84/01/11. 28pp 21793.232

8401120259 Comments presented before Commission on 840111 re NRC concurrence in DOE proposed general guidelines for recommendation of sites for nuclear waste repositories
CHRISTOFFERSON, Utah, State of 48FR50432 84/01/11 12pp
21792:303

8401120265 Comments on proposed rulemaking re NRC concurrence in DOE high level waste repository siting guidelines (10CFR960)
Guidelines acceptable & should require prompt NRC concurrence so DOE can proceed w/o delay
DAVIS, J. M. Edison Institute, Dearborn, MI DAVIS, J. M. Utility Nuclear Waste Management Group 48FR50432 84/01/11. 8pp
21792:351.

8401120270 Introductory statement of L. Mills re DOE siting guidelines
MILLS, L. Edison Institute, Dearborn, MI. MILLS, L. Utility Nuclear Waste Management Group 48FR50432 84/01/11. 3pp 21792 359

8401120298 Testimony of State of MS by C Deaton re concurrence in DOE general guidelines for recommendation of sites for nuclear waste repositories
DEATON, C. M. Mississippi, State of 48FR50432. 84/01/11. 98pp
21793.074

8401120316 Responds to 831222 request that Commission provide addl procedures for public participation in NRC concurrence in DOE siting guidelines for high level nuclear waste repositories. Procedures provide adequate participation
PALLADINO, N. J. Commissioners 48FR50432 84/01/10. MATHESON, S. M. Utah, State of. 2pp 21792 044.

--8401120331 Requests Commission provide addl procedures for public participation in NRC concurrence in DOE siting guidelines for high level nuclear waste repositories & extend deadline for comments to 840201
MATHESON, S. M. Utah, State of 83/12/22 PALLADINO, N. J. Commissioners. 15pp. 21792:046

8401120323 Comments on proposed rulemaking re DOE high level waste repository site selection guidelines (10CFR960) Final guidelines responsive to concerns raised during extensive review & comment process
BOJBLON, O. L. Environmental Protection Agency 48FR50432 84/01/11. 4pp. 21792:197

8401120448 Forwards PNWL, "BWIP Review," Nov 1983 ltr rept.
OLSON, O. L. Energy, Dept of. 00642 83/12/14 WRIGHT, R. J. Repository Projects Branch (Post 831001) STEVENS, D. Washington, State of. HOVIS, J. B. Hovis, Cockrill, Weaver & Bjur 2pp
21804.107

--8401120451 "BWIP Review," Nov 1983 ltr rept
* Battelle Memorial Institute, Pacific Northwest Laboratory
00642 83/11/30 236pp 21804 109

8401120464 Forwards list of info needed for 840109 trip to Richland, WA to collect hydrogeologic data obtained since Jul 1982
WRIGHT, R. J. Repository Projects Branch (Post 831001) 83/12/21
OLSON, O. L. Energy, Dept of 3pp 21804 092

8401120555 Summary of 831130 meeting w/EEI Util Nuclear Waste Mgt Group in Washington, DC re status of implementation of 10CFR61 to reach acceptable levels of compliance
JOHNSON, T. C. Engineering Branch (Post 831001) 84/01/04
BROWNING, R. E. Division of Waste Management 13pp 21803 092

8401120578 Forwards Chem-Nuclear Sys, Inc topical rept, "Title 10CFR61 Waste Form Certification - Cement," for review & comments
Comments requested by 840102 W/o encl
PERSON, L. S. Low Level Waste Licensing Branch 83/12/09
ORELLA, A. W. Fuel Facilities & Materials Branch GAMMILL, W. Meteorology & Effluent Treatment Branch 1p 21796 361

8401120580 Forwards for insertion, comments on proposed rept to Commission re status of Part 61 implementation
WILLIS, C. A. Meteorology & Effluent Treatment Branch. 83/12/09
JOHNSON, T. C. Low-Level Waste & Uranium Recovery Projects Branch 4pp
21803:107

8401120604 Forwards proprietary & nonproprietary version of topical rept, "Polyethylene High-Integrity Containers " W/o proprietary rept
POPPE, L. K. Chem-Nuclear Systems, Inc RA-0316-3 83/12/23
JOHNSON, T. NRC - No Detailed Affiliation Given 4pp 21803 298

--8401120608 CNSI-HIC-14571-01-NP
Nonproprietary version of "Polyethylene High-Integrity Containers "
* Chem-Nuclear Systems, Inc 83/12/23 205pp 21803 242

8401130040 Forwards NP Kirner 831205 ltr re technical assistance to State of WA on high-integrity containers proposed by E&G & NuPac Response requested by 831229
NUSSBAUMER, D. A. Assistant Director for State Agreements Programs
83/12/27 HIGGINSBOTHAM, L. Low Level Waste Licensing Branch 1p.
21817 265.

8401130045 Submits program for 10CFR61 implementation for review & concurrence as adequate means of implementation of requirements on waste form & classification
MURPHY, W. P. Vermont Yankee Nuclear Power Corp FVY 83-130
83/12/29 HIGGINSBOTHAM, L. Low Level Waste Licensing Branch 3pp
21819 353 24X Fiche 50-271, 83/12/29, 8401130045

8401130047 Discusses proposed methods of implementing requirements of 10CFR61 & outlines addl actions taken prior to shipment of radwaste after 831227
HARRINGTON, W. D. Boston Edison Co BECO-83-297 83/12/20
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director
3pp 21819 350 24X Fiche 50-293, 83/12/20, 8401130047

8401130049 Requests review of applicability of use of Salton sea geothermal field as near-field natural analog for radwaste repository in salt Response by Mar 1984 requested
NEFF, J. D. Energy, Dept of 00211 83/12/28 MILLER, H. High Level Waste Technical Development Branch. 1p 21819 349.

8401130052 Forwards rept re processes affecting rock durability & current testing procedures appropriate for estimating relative rock durability No specific std criteria available to determine if covering will be stable for 1,000 yrs
GREEVES, J. T. Engineering Branch (Post 831001) 83/12/28
HIGGINSBOTHAM, L. Low Level Waste Licensing Branch 8pp 21821 144

8401130057 Requests comments on QNWI-479, "Selection & Durability of Beal Mats for Bedded Salt Repository Preliminary Studies."
NEFF, J. D. Energy, Dept of 00210. 83/12/28 MILLER, H. High Level Waste Technical Development Branch 1p 21821 140

8401130066 Submits questions from customers re using one type of cement Cement type should not affect 10CFR61 test program results.
LEE, T. A. Stock Equipment Co 83/12/28, JOHNSON, T. Division of Fuel Cycle & Material Safety 1p 21821 133

8401130133 Advises that 831027 revised qualifications test program acceptable, per 10CFR61, assuming test results consistent w/ technical position on waste form
LOHMEYER, P. H. Low-Level Waste & Uranium Recovery Projects Branch
83/12/14 PHILLIPS, J. W. Hittman Nuclear & Development Corp. (subs of Hittman Corp) 1p. 21820.112

NONDOCKETED ITEMS

475

8401130151 Comments on DOE recommendations for high level waste repository guidelines DOE should consider sites for which total absence of water can be expected Discussion of objections to DOE B31212-14 meeting conclusions encl
PENBERTHY, L Penberthy Electromelt International, Inc 48FR50452
83/12/15 12pp 21802 116

8401130154 Testimony of DW Stevens on DOE draft program guidelines for repository sites
STEVENS, D W Washington, State of 48FR50432 84/01/11 5pp
21802 130

8401130164 Testimony of JJ Stucker on behalf of State of SC Governor Riley on 840111 in Washington, DC re NRC concurrence in DOE general guidelines for recommendation of sites for nuclear waste repositories
STUCKER, J J South Carolina, State of 48FR50432 84/01/11 13pp
21802:211

8401130466 Requests D Alexander attend & participate in 840109-13 RHO/BWIP geochemistry workshop in Hanford, WA Preliminary agenda encl.
KNAPP, M Geotechnical Branch (Post 831001) 83/12/16 CONTI, E
Waste Management Branch 8pp 21817 357

8401130468 Requests suggestions for agenda items to be discussed at 840131 joint DOE, states & tribes meeting in Fort Collins, CO
Agenda items requested by 840113
MDRLEY, J A Energy, Dept of 83/12/29 HIGGINBOTHAM, L Low Level
Waste Licensing Branch 2pp 21817 355

8401130478 Forwards briefing schedule & agenda for regional inspector briefing on implementation of 10CFR61 Insp procedures & supplemental guide will be forwarded by first wk of Jan 84
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch
83/12/28 LOHAUS, P, JOHNSON, T Division of Waste Management
COBB, L Director's Office, Office of Inspection and Enforcement
2pp 21817 334

8401160015 Forwards "Technical Data Mgt Sys" & refs planned for use in salt repository project environ assessments, in response to NRC 830513 & 1021 ltr Rept includes borehole summaries for States of LA, MS, TX & UT
NEFF, J D Energy, Dept of 00215 83/12/30 MILLER, H High
Level Waste Technical Development Branch 79pp 21823:001

--8401160016 "Technical Data Mgt Sys"
* Energy, Dept of 00215 83/12/30 184pp 21823 080

8401160117 Forwards preliminary outline of application for license for low level radioactive disposal facility per 10CFR61 regulations Meeting requested
LEWIS, M S Chem-Nuclear Systems, Inc TS-0002-4 84/01/02
HIGGINBOTHAM, L Low Level Waste Licensing Branch 4pp 21821 317

8401160373 Further response to FOIA request for documents re cleanup & decision to close down U mill in Edgemont, SD Forwards
W Dirv's 800515 note to J Martin Review of remaining documents subj to request in progress
FELTON, J M Division of Rules and Records 83/11/09 GARBUS, M
Frankfurt, Garbus, Klein & Bell 1p 21836 247

--8401160379 Forwards info re Edgemont, U mill tailings
DIRCKS, W Office of the Executive Director for Operations
80/05/15 MARTIN, J NRC - No Detailed Affiliation Given. 5pp
21836 249

8401160377 Forwards six case histories of mining through rock showing diking in exploratory boreholes as requested at 831129-1202
BWIP/NRC Underground Test Workshop
OLSON, D L Energy, Dept of 83/12/23 WRIGHT, R J High Level
Waste Technical Development Branch 85pp 21824 137

8401170144 Forwards corrected testimony before Commission on 840111
STUCKER, J J South Carolina, State of 84/01/12 CHILK, S J
Office of the Secretary of the Commission 1p 21833:337.

--8401170146 Corrected testimony of JJ Stucker on behalf of South Carolina Governor Riley at 840111 public meeting on NRC concurrence in DOE guidelines for recommendation of sites for nuclear waste repositories
STUCKER, J J South Carolina, State of 84/01/11. 14pp.
21833 338

8401170247 Requests to be included on svc list for all notices of proceeding re NRC concurrence in DOE general guidelines for waste repositories, per Nuclear Waste Policy Act
MCNABE, M Nebraska, State of, 48FR50432 84/01/12 CHILK, S J
Office of the Secretary of the Commission 1p 21833:330.

8401170502 Forwards 831202 telcon rept w/D Brooks of NRC re BWIP/NRC workshop on geochemistry scheduled for 840109
ASH, E B Rockwell International Corp 00645 83/12/15 OLSON, D L
Energy, Dept of 2pp 21847 154

8401170542 Forwards analysis documenting adequacy of buried high integrity container able to withstand impact from 1,000 lb drum dropped from 25 ft Analysis performed by Nuclear Packaging, Inc
SAUER, R E U S Ecology, Inc (formerly Nuclear Engineering, Inc)
83/12/16 KIRNER, N Washington, State of, Dept of Social & Health
Services 8pp 21844 350

8401170545 Forwards telcon repts w/RJ Wright on 831116 & w/RJ Wright, M Logsdon & N Coleman on 831122 re use of cross-hole tracer tests planned by BWIP In-depth NRC technical rept expected by mid-Jan
ASH, E B Rockwell International Corp 883-4418 83/12/09.
OLSON, D L Energy, Dept of. 3pp 21844 345

8401170547 Forwards 831128 telcon rept w/R Coutre of ANL re backfill temps & waste package design
ASH, E B, SMITH, M J Rockwell International Corp 00643 83/12/07
OLSON, D L Energy, Dept of 2pp 21844 343.

8401170556 Advises of change of location for Halifax, VA 840104 public hearings & 840110 work session re UAO rept.
CATON, B Virginia, Commonwealth of, 83/12/28 Virginia,
Commonwealth of, 1p 21844 318

8401170557 Informs that 831213 revised qualification test program acceptable Compliance w/10CFR61 waste stability requirements for waste streams & waste compositions demonstrated.
LOHAUS, P M Low Level Waste Licensing Branch 83/12/29 LEE, T A
Stock Equipment Co 1p 21844 317.

8401180038 Forwards trip rept of 831109-10 site visit to Pathfinder Labs in St Louis, MO & to Midwest Research Inst in Kansas City, MO re nonfuel cycle waste generators
JACKSON, K C Low Level Waste Licensing Branch. 83/12/30
OGILVIE, E J Midwest Research Institute 5pp. 21847 336

8401180084 Forwards addl info re top impact resistance of high integrity waste disposal container, including analyses documenting adequacy of container to withstand 100 lb impact
SCHNEIDER, K N Assistant Director for State Agreements Programs.
84/01/09 JOHNSON, T Division of Waste Management 9pp
21847 327

8401190024 Trip rept of attendance at 831206 BMI/ACRS info meeting in Columbus, OH re NRC-BMI program on long-term performance of mats used for high level waste packaging (FIN B-6764).
Agenda encl
TOKAR, M Engineering Branch (Post 831001) FIN B-6764 83/12/21
REEVES, J T Engineering Branch (Post 831001). 7pp 21870 303

8401190025 Trip rept of attendance at 831114-16 meetings w/State of SC in Columbia, SC re high integrity container reviews performed in conjunction w/State of SC Agreement State compatibility review.
JOHNSON, T C Engineering Branch (Post 831001) 83/12/16
REEVES, J T Engineering Branch (Post 831001) 8pp. 21870.295

8401190028 Forwards evaluation rept on high integrity container review process of State of SC, performed in conjunction w/compatibility review of Agreement State program
HIGGINBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch.
83/12/19 WOODRUFF, R L Region 2, Office of Director 7pp
21870-288

8401190031 Forwards six telcon repts to NRC re BWIP.
ASH, E B, Rockwell International Corp 00654 84/01/04. OLSON, D L
Energy, Dept of. 1p 21870 280.

8401190206 Advises that roster of NRC communicators for interchange of technical info w/BWIP communicators will be modified as listed
WRIGHT, R J. Repository Projects Branch (Post 831001) 00650.
83/12/18 OLSON, D L Energy, Dept of 1p. 21870 015.

8401190278 Responds to 831014 ltr requesting info re updated list of ongoing & completed NRC & contractor repts, list of PDRs & current organization charts.
MILLER, H J. Repository Projects Branch (Post 831001). 00218.
83/12/09 NEFF, J D Energy, Dept of. 2pp. 21870.068.

8401190463 Submits notice of upcoming meetings as result of 830719-20 meetings
NEFF, J D Energy, Dept. of, 00018, 84/01/06 CHRISTOFFERSON
Energy, Dept of 1p. 21861 341

NONDOCKETED ITEMS

- 8401190464 Provides designation of UNTRAP vicinity properties, per 830623 consent order
BAUBLITZ, J E Energy, Dept of NE-24 83/12/27 COFFMAN, F E Energy, Dept of 3pp 21861 338
- 8401190508 Forwards revised draft agenda for 840126-27 meetings w/BALT state representatives in Columbus, OH
NEFF, J O Energy, Dept of 00219 84/01/03 MILLER, H NRC - No Detailed Affiliation Given 1p 21861 348
- 8401190510 Forwards BWIP hydrological test interval rept, "Results & Evaluation of Experimental Vertical Hydraulic Conductivity Testing at Boreholes DC-4 & DC-5"
OLSON, D L Energy, Dept of, 00652 84/01/04 WRIGHT, R J High Level Waste Technical Development Branch 1p 21861 115
- 8401190515 "Results & Evaluation of Experimental Vertical Hydraulic Conductivity Testing at Boreholes DC-4 & DC-5"
BTRAIT, S R. Rockwell International Corp 83/09/30 72pp 21861 116
- 8401190543 Discusses pitting of carbon steel in BWIP groundwaters. Experiment conducted in 10-fold concentrated groundwater at 250 C w/sample partially submerged. Sample showed catastrophic pitting above water line
MCNEIL, M B Waste Management Branch 00653, 84/01/09 WICK, E Engineering Branch (Post 831001) 1p 21861 194
- 8401200209 Notifies that SC has been added to list of participants in 840111 public meeting on DOE general guidelines for recommendation of sites for nuclear waste repositories.
PALLADINO, N J Commissioners 84/01/04, RILEY, R W South Carolina, State of 1p 21871 242
- 8401200210 Responds to 831214 & 30 requests to participate in Commission 840111 public meeting on NRC concurrence in DOE siting guidelines for high level repositories. Participation limited. Request denied
CHILK, S J Office of the Secretary of the Commission 84/01/04 PENBERTHY, L. Penberthy Electromelt International, Inc. 1p 21871 245
- 8401200212 Confirms request to participate in 840111 hearing on DOE guidelines
PENBERTHY, L. Penberthy Electromelt International, Inc 83/12/30 CHILK, S J Office of the Secretary of the Commission 1p 21871 247
- 8401200214 Notifies that State of WA has been added to list of participants in 840111 public meeting on DOE general guidelines for recommendation of sites for nuclear waste repositories.
CHILK, S J Office of the Secretary of the Commission, 84/01/04 ROE, C B Olympia, WA 1p, 21871 248
- 8401230053 Transcript of Commission 840111 meeting in Washington, DC for oral presentations on "NRC Concurrence or Nonconcurrence in DOE Waste Repository Siting Guidelines" Pp 1-264
Supporting documentation encl
* Commissioners 84/01/11, 766pp 21928 225
- 8401230176 Requests identification of all onsite representatives, both mgt & technical staff, at each site being investigated &/or characterized for suitability as high level nuclear waste repository
CALDWELL, L Hanford Oversight Committee 00651 84/01/03 BROWNING, R E Division of Waste Management, 1p 21930 361
- 8401240188 Forwards all State of MN past comments on DOE high level radwaste disposal guidelines, to be attached to State of MN testimony.
LARSON, S B Minnesota, State of 48FR50432 84/01/17 CHILK, S J Office of the Secretary of the Commission 28pp 21908 311
- 8401260007 Forwards summary meeting notes & handouts from BWIP/NRC 831129-1202 workshop on underground test-plan in Richland, WA.
OLSON, D L Energy, Dept of, 00655, 84/01/04 WRIGHT, R J, NRC - No Detailed Affiliation Given STEVENS, D W Washington, State of HAVIS, J B Yakima Indian Nation 2pp, 21991 001
- 8401260010 Summary of BWIP/NRC 831129-1202 workshop on underground test plan in Richland, WA. List of attendees & viewpoints encl.
WRIGHT, R J, NRC - No Detailed Affiliation Given, OLSON, D L, Energy, Dept of, 00655 83/12/02, NRC - No Detailed Affiliation Given 200pp, 21991 003
- 8401260065 DOE/NE-0023/2
"Annual Status Rept on U Mill Tailings Remedial Action Program"
* Energy, Dept of 83/12/31, 32pp 21971 168
- 8401270153 Forwards SECY-83-241 re summary rept on comment ltrs received on draft DOE guidelines for recommendation of sites for repositories & 830513 & 0615 ltrs, as promised during 830719-20 meetings at DOE/DNWI W/O encls.
MATTSON, D R Division of Waste Management 00142 83/08/11 FRISHMAN, S Texas, State of 3pp 22002 358
- 8401270161 Discusses exploratory shaft const & sealing issues in connection w/salt repository program NUREG/CR-2834.
"Evaluation of Alternative Shaft Sinking Technologies for High Level Waste Deep Geologic Repositories" encl W/a NUREG CHASE, L Division of Waste Management 00085 83/06/15 NEFF, J O Energy, Dept of 7pp 22002 302
- 8401270169 Requests designation of individual as NRC contact in connection w/repository siting activities, implementing Nuclear Waste Policy Act of 1982
DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director 00163 83/08/17 MATHESON, S Utah, State of 2pp 22002 292
- 8401270173 Discusses arrangements for 810511-21 technical review of repository siting activities in Paradox Basin, UT & Palo Duro Basin, TX. State liaison officers listed
MILLER, H J Division of Waste Management 00025 81/04/30 NEFF, J O Energy, Dept of 2pp 22002 282
- 8401270516 Trip rept of attendance at 831201-02 conferences w/DOE in Albuquerque, NM re UNTRAP implementation plans
FLORY, C, PENNIFULL, R Low-Level Waste & Uranium Recovery Projects Branch 83/12/20 HIGGINSBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch, 3pp 22002 189
- 8401270519 Forwards summary listing of key documents issued or to be issued to provide guidance in high level waste repository program, per Civilian Radwaste Mgt Info Meeting on 831212-15
MILLER, H J Repository Projects Branch (Post 831001) 84/01/08 Repository Projects Branch (Post 831001) 2pp 22002 169.
- 8401270524 "Selected NRC Products High Level Waste Program, Suppl to NRC Presentation on High Level Waste Prelicensing Consultation & Guidance Process," prepared for Civilian Radwaste Mgt Info Meeting on 831214
* NRC - No Detailed Affiliation Given 83/12/14 18pp 22002 171
- 8401270528 Requests written appeal to DOE for draft BWIP Barrier Matls Test Plan BD-BWI-TP-022. Document needed to determine how site characterization assessment waste package issues resolved to prepare for BWIP waste package 840227 meeting
WICK, E A Engineering Branch (Post 831001) 661 84/01/05 WRIGHT, R J Repository Projects Branch (Post 831001) 1p 22002 147.
- 8401270533 Forwards Rev O to Procedure SD-BWI-PAP-001, "BWIP Performance Assessment Plan," for review & comment Schedule for dissemination outlined. Coordination meeting scheduled for 831221 in Silver Spring, MD
WRIGHT, R J Repository Projects Branch (Post 831001) 83/12/18 GREEVES, J T, KNAPP, M R., JUSTUS, P B NRC - No Detailed Affiliation Given, 2pp 22002 018
- 8401270535 Rev O to Procedure SD-BWI-PAP-001, "BWIP Performance Assessment Plan"
SONNICHSEN, J C Rockwell International Corp 83/03/31 117pp, 22002 020
- 8401300011 Lists upcoming meetings, as result of discussions at 830719-20 meetings.
NEFF, J O Energy, Dept of 00140 83/08/12 TOMSIC, O, FRISHMAN, S, FORSYTHE, R Energy, Dept of 1p 22027 317.
- 8401300038 Forwards revised proposed agreement re info exchange & issue disposition for potential repository sites in salt prior to submittal of license application. Rev includes most comments
NEFF, J O Energy, Dept of 00110 83/01/11, CHASE, L NRC - No Detailed Affiliation Given 4pp 22006 349
- 8401300043 Requests Geotrans, Inc provide type input & output data base for each flow & salt-related benchmark problem & magnetic tapes of input & output file of codes available at PNWL. Info will reduce duplication & improve problem spec.
NEFF, J O Energy, Dept of 83/12/15, MILLER, H NRC - No Detailed Affiliation Given 1p 22006 348
- 8401300049 Forwards minutes of salt state representatives & NRC 831115-16 meetings. Comments requested by 831202 or 05.
CASEY, L Energy, Dept of, 192, 83/12/01 JOHNSON, R. NRC - No Detailed Affiliation Given 16pp 22027 290

NONDOCKETED ITEMS

477

8401300050 Summarizes review of conceptual design rept re bedded salt Series of design meetings should be initiated w/DDE to discuss design concepts & possible conflicts
HART, P High Level Waste Technical Development Branch 00014
81/04/13. MILLER, H J High Level Waste Technical Development Branch 2pp 22006 340

8401300052 Forwards magnetic tape containing WAPPA source code, data base, sample inputs & sample outputs, in response to 831014 request & in accordance w/DDE code distribution procedures Code technical manual encl
JANSEN, G Battelle Memorial Institute 193 83/11/28
BUCKLEY, J T NRC - No Detailed Affiliation Given 16pp 22027 274

8401300053 Forwards final agenda for presite characterization plan consultation 830627-28 meeting between NRC & DOE/NPO re applicability of guidance in BWIP site characterization assessment to salt project
NEFF, J D Energy, Dept of 00082 83/06/27 CASE, L NRC - No Detailed Affiliation Given 2pp 22006 346

8401300063 Advises of rescheduling of meetings Meeting re generic performance assessment issues of definition of disturbed zone & compliance w/EPA std scheduled for 831013 & meeting re repository design & exploratory shaft for 831025-26
NEFF, J D Energy, Dept of 00024 83/09/28 MILLER, H High Level Waste Technical Development Branch 4pp 22006 342

8401300071 Trip rept of 830419-20 info meetings w/DDE in Columbus, OH re salt repositories Agenda encl
REGNIER, E P High Level Waste Licensing Management Branch. 00093
83/03/20 BOYLE, R R High Level Waste Licensing Management Branch 9pp 22006 331

8401300072 Forwards revised draft of agreement between NRC & DOE/NPO on site characterization program & licensing info needs for potential repository sites in salt & proposed first meeting agenda
NEFF, J D Energy, Dept of 00106 83/03/17 CHASE, L. High Level Waste Technical Development Branch 6pp. 22006 325.

8401300077 Notification of 830725-26 workshop in Bethesda, MD to discuss NPO/DNWI BWIP site characterization assessment review Agenda & questions resulting from analysis encl
CHASE, L High Level Waste Technical Development Branch. 00083.
83/06/22 MILLER, H J, GREEVES, J T, JUSTUS, P B High Level Waste Technical Development Branch 4pp 22006 321

8401300079 Forwards draft agenda of 830719-20 meetings w/salt state representatives in Columbus, OH re current & proposed field activities & schedules to coordinate publication & dissemination of major documents
NEFF, J D Energy, Dept of 00156 83/07/08 MILLER, H NRC - No Detailed Affiliation Given 3pp. 22006 318

8401300084 Ack receipt of 821227 ltr transmitting description of issues BNL identified in evaluation of high level waste package performance in salt repository
NEFF, J D Energy, Dept. of 00107 83/02/10 CHASE, L. NRC - No Detailed Affiliation Given 1p 22006 310

8401300092 Discusses USOS 810307 ltr re predictability of geologic & hydrologic characteristics of bedded salt compared to salt domes Ltr advises DOE on how to focus site exploration program & interpretation of specific repository sites
ROBERTSON, J B Interior, Dept of, Geological Survey 00017
83/04/06, MORGAN, R Interior, Dept of, Geological Survey. 2pp. 22006 159

8401300097 Forwards republished analysis of most frequently heard statements re risk from shipment of spent fuel & other high activity shipments.
NEFF, J D Energy, Dept. of 00089 83/06/07 CHASE, L. NRC - No Detailed Affiliation Given 1p 22007 056

--8401300101 SAND82-1250
"Analysis of Recent Council on Economic Priorities Newsletter."
JEFFERSON, R. M., LUNA, R. E., MCCLURE, J D Sandia Laboratories
00089 82/06/30. 56pp 22027 057

8401300099 Summary of NRC-DNWI-DOE 830419-20 meetings in Columbus, OH re performance assessment topics
WEBER, M. F. High Level Waste Licensing Management Branch. 00098
83/05/06 KNAPP, M High Level Waste Licensing Management Branch 12pp. 22006 249

8401300102 Summarizes 830822 meeting w/salt state representatives in Columbus, OH re two EA-related issues: siting guidelines boundary terminology & salt mgt/disposal. List of attendees & viewpoints encl.
NEFF, J D Energy, Dept. of. 00128 83/09/01. MILLER, H. High Level Waste Technical Development Branch 41pp. 22006 208.

8401300105 Forwards response to 830415 questions re exploratory shaft const & sealing AE delaying final design for components that require site specific design info
NEFF, J D Energy, Dept of 220 84/01/11 MILLER, H Division of Waste Management 23pp 22006 185

8401300107 Forwards final agenda for 831013 meeting in Bethesda, MD re performance assessment
NEFF, J D Energy, Dept of 00117. 83/10/07 MILLER, H High Level Waste Technical Development Branch 2pp 22006 183

8401300109 Forwards HJ Miller 830915 ltr to DOE transmitting staff comments on DOE salt repository project info mgt & transfer sys Bone comments still outstanding Major comments will be presented to DOE/DNWI on 830920 in Columbus, OH
JOHNSON, R High Level Waste Technical Development Branch. 00123
83/09/15. MILLER, H J High Level Waste Technical Development Branch 1p 22006 163

--8401300113 Forwards comments on DOE salt repository project mgt info & transfer sys NRC interested in future development of info mgt & transfer sys & would like to coordinate efforts to set up NRC sys in conjunction w/evolving DOE sys
MILLER, H J High Level Waste Technical Development Branch 00123
83/09/15 NEFF, J D Energy, Dept of. 17pp. 22006 164

8401300120 Forwards sample request form for NRC requests for salt repository project samples
NEFF, J D Energy, Dept of 00118 83/10/03 MILLER, H High Level Waste Technical Development Branch 4pp 22005 032.

8401300170 Requests establishment of agreement between DOE Natl Waste Storage Program Ofc (NPD) & NRC re info exchange & issue disposition for potential geologic repository sites in salt. Draft agreement encl
NEFF, J D Energy, Dept of 00111 82/11/10 MARTIN, J B Division of Waste Management 5pp 22005 023

8401300174 Provides progress on proposed salt project workshops re pre-site characterization plan consultation, waste form/waste package & performance assessment Workshops should take place before DOE nomination of site
CHASE, L High Level Waste Technical Development Branch. 00090
83/06/03 MILLER, H J High Level Waste Technical Development Branch 1p 22003 362

8401300177 Trip rept of 831025-26 workshop w/DDE in Columbus, OH re repository design in salt.
SCHMITT, T J Earth Sciences Branch 00184. 83/11/14 MURPHY, A J Earth Sciences Branch 2pp. 22003 360

8401300185 Provides preliminary plans for bedded salt review trip.
WRIGHT, R J High Level Waste Technical Development Branch 00013.
81/03/18 MILLER, H, WHITE, L. High Level Waste Technical Development Branch 2pp 22003 358.

8401300341 Forwards minutes of 831115-16 meetings w/salt state representatives in Columbus, OH re natl waste terminal storage program
NEFF, J D Energy, Dept. of. 207. 83/12/15. MILLER, H. High Level Waste Technical Development Branch. 259pp 22005 036

8401300345 Forwards draft agendas of 831023-26 & 27-28 meetings re performance assessment & exploratory shaft, repository design & in situ testing List of expected attendees & final changes to agenda requested by 831003.
NEFF, J D Energy, Dept. of. 00129. 83/08/31 MILLER, H. High Level Waste Technical Development Branch 4pp. 22003 339

8401300349 Forwards comments on DOE salt repository project info mgt & transfer sys requested at 830719-20 meetings & contractor rept describing experimental, numerical data base for BWIP site data
MILLER, H J High Level Waste Technical Development Branch. 00181.
83/10/21. NEFF, J D Energy, Dept. of. 20pp. 22003 020.

--8401300354 Forwards strawman agreement re site investigation & characterization for discussion & comment
MILLER, H High Level Waste Technical Development Branch
83/09/19. Energy, Dept of. 7pp 22003 040.

--8401300356 "Self Teaching Guide for Prototype Earth Sciences Data Base"
* Teknekron Research, Inc. NRC-02-81-026. 83/09/09. NRC - No Detailed Affiliation Given. 160pp. 22003 047.

8401300360 Requests listed reciprocal info for requested salt repository project rept
NEFF, J D Energy, Dept. of. 315 83/10/14. MILLER, H. High Level Waste Technical Development Branch. 2pp 22003 314

NONDOCKETED ITEMS

B401310179 Notifies of B31024 meeting in Columbus, OH to discuss water use, water rights & transportation re Natl Waste Policy Act assessment
NEFF, J D Energy, Dept of 00124 83/09/14 MILLER, H High
Level Waste Technical Development Branch 1p 22035 361

B401310185 Forwards minutes of B30824 meeting between BMC/NRC waste package project staff & DOE/ONHL re design & organization of accelerated life tests & related statistical techniques
NEFF, J D Energy, Dept of 00126 83/09/08 MILLER, H High
Level Waste Technical Development Branch 6pp 22037 089

B401310189 Forwards final version of minutes of fourth DOE/NRC B31025-26 pre-site characterization plan meeting on repository design, exploratory shaft & in situ testing
NEFF, J D Energy, Dept of 00177 83/11/02 MILLER, H High
Level Waste Technical Development Branch 7pp 22037 082

B401310191 Summarizes B30517 telcon re content of DOE data base beyond current published reports Summary of borehole data for use in summary report or automated data sys will be complete within month
NEFF, J D Energy, Dept of 00092 83/06/02 CHASE, L Division
of Waste Management 2pp 22021 109

--B401310195 Identifies NRC info needs re DOE salt data Current summary of type & amount of data available & data in process of being collected requested List of data of interest to NRC included
CHASE, L High Level Waste Technical Development Branch 00092
83/05/13 NEFF, J D Energy, Dept. of 3pp 22021 111

B401310197 Forwards mod of B30315 MDU re info exchange on salt Version identical except that fourth sentence in Item 6 added
BENNETT, J W Energy, Dept of 00094 83/05/27 BROWNING, R NRC
- No Detailed Affiliation Given 4pp 22021 114

B401310201 Forwards proposed agenda for workshop scheduled for B30627 & 28 re applicability of guidance in BWIP site characterization assessment to salt project waste package & performance assessment
NEFF, J D Energy, Dept of 00086 83/06/13 CHASE, L NRC - No
Detailed Affiliation Given 7pp 22021 118

B401310251 Requests inclusion on svc list for NRC draft decision on concurrence in general guidelines developed by DOE for Nuclear Waste Policy Act
LEUTHILER, N R Western Interstate Energy Board 48FR50432.
84/01/23 CHILK, B J Office of the Secretary of the Commission
1p 22018 331.

B401310255 Documents statements made during B40111 hearing re NRC concurrence in DOE general guidelines for recommendation sites for nuclear waste repositories
KEARNEY, J J Edison Electric Institute 48FR50432 84/01/27
FALLADINO, N J, GILINSKY, V, ROBERTS, T M Commissioners 2pp
22018 261.

B401310281 Forwards DW Stevens B40111 testimony presented before NRC.
STEVENS, D W Washington, State of 48FR50432 84/01/25
CHILK, S J, Office of the Secretary of the Commission 1p.
22018 056

--B401310282 Testimony of DW Stevens re draft program guidelines of DOE under Nuclear Waste Mgt Act of 1982.
STEVENS, D W Washington, State of. 84/01/11 8pp 22018 057

B401310444 Trip report of B30428-29 DOE public hearings in Richton & Jackson, MS re soliciting comments on proposed nomination of sites in salt deposits for detailed site characterization & recommendation of issues for environ assessment.
REONIER, E P High Level Waste Licensing Management Branch. 00131.
83/08/30 BOYLE, R R High Level Waste Licensing Management Branch
9pp 22036 297

B401310452 Advises that EA topical meeting scheduled for B31025 in Columbus, OH expanded to repeat discussion on salt mgt & disposal for individuals unable to attend B30823 meeting Agenda & background matl encl
NEFF, J D Energy, Dept. of 00115 83/10/11 MILLER, H. High
Level Waste Technical Development Branch. 10pp 22037 001

--B401310455 SAND83-0867
"Preliminary Analysis of Cost & Risk of Transporting Nuclear Waste to Potential Candidate Commercial Repository Site"
WILMOT, E. L., MADSEN, M. M., CASHWELL, J. W Sandia Laboratories.
TLC-0434 83/06/30 64pp. 22037 011.

EXPORT LIC EXPORT AND IMPORT LICENSES

B401030285 Submits NRC findings re Exxon Nuclear Co proposed import of 50 kg U, enriched to 4% U-235, from United Kingdom License issued w/o normal 15-day posting period
MOORE, R N Assistant Director for Export/Import & International Safeguards 83/12/08 Assistant Director for Export/Import & International Safeguards 1p 21693 359

B401040373 Application for license to export Model RG-C2-2510-104 uncompensated ion chamber to Brazil
SKARUPA, J D Reuter-Stokes, Inc B-0067 83/11/29 4pp
21755 176

B401040384 Application for license to export three pitch coke sleeves, three green gilson coke sleeves, 15 graphitized pitch coke rods & 15 graphitized gilson coke rods to United Kingdom
* Union Carbide Corp 70-0059-10 83/12/06 1p 21743 362

B401040472 Application for license to export 302 kg U-235, contained in 9,993 kg U, to Japan
OKADA, S Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd.)
MBK-2F1-R3 (B) 83/11/30 1p 21743 359

B401040476 Application for license to export 5 Reuter-Stokes Model RG-P4-0805-134 fission chambers to Finland
SKARUPA, J D Reuter-Stokes, Inc B-0046 83/11/29 3pp.
21754 341

B401040498 Forwards application to export 3,184 g U-zirconium-hydride, contained in 16,000 g U, to Japan
MOWRY, W R GA Technologies, Inc /General Atomic Co IEL-5063.
83/11/29 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 21743 358

--B401040503 Application for license to export 3,184 g U-zirconium-hydride, contained in 16,000 g U, to Japan
MOWRY, W R GA Technologies, Inc /General Atomic Co IEL-5063.
83/11/29 1p 21743 357

B401040507 Application for license to export one Model 703 static meter to United Kingdom
PAGUIN, J L TEKNIS, Inc TUK 3457 83/12/07 1p 21743 356.

B401040623 License for Carpenter Technology Corp to export 170 Zircaloy-4 fuel channels to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 3-908-013N 83/12/21 2pp 21755 101

B401040628 License for Wholepack Corp to export two fission counters, Model RG-P0-1608-110, to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TC-423 83/12/23 2pp 21755 099

B401090045 Ltr of assurance re Edlow Intl Co application to export residual quantities of U hexafluoride heels & 15 kg U-235, contained in 300 kg U, to Sweden
LINDBTROM, M Sweden, Govt of 83/12/08 RAYMOND, J F Energy.
Dept of 1p 21757 280

B401090047 License for Carpenter Technology Corp to export 20 Zircaloy-4 fuel channels to Switzerland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 3-808-002 83/12/21 2pp 21757 278

B401090055 Amend 2 to export license for Edlow Intl Co, adding add'l ultimate consignee
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/26 2pp 21757 272

B401090058 Application for license to export fission counter detector, Model RG-C3-2510-114, to South Africa
SKARUPA, J D Reuter-Stokes, Inc B-0058. 83/12/13 1p
21757 268

B401090063 License for Mitsubishi Intl Corp to export 404 kg U-235, contained in 11,708 kg U, to Japan.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HSA-5483002 83/12/22 1p. 21757 243

B401090067 License for Edlow Intl Co to export 119 kg U-235, contained in 3,439 kg U, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards KLK-17 83/12/28 2pp. 21757 265

NONDOCKETED ITEMS

479

B401090087 License for Teknis, Inc to export 200 mCi tritium, contained in one GM Model 703 static meter, to Ireland
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TUK-3457 83/12/27 2pp 21757 262

B401090092 Application for license to export fuel rod springs to Sweden
HERSCHEL, M M Westinghouse Electric Corp MMH-429 83/12/12 1p 21757 261

B401090096 License for Borg-Warner Corp to export specially designed or prepared carbon & stainless steel valves for use in nuclear reactor to Yugoslavia
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 11003353 83/12/22 1p 21757 259

B401090118 Application for license to export spare parts for loading & unloading fuel elements into reactor to Canada
* General Motors Corp W D #84113 83/12/06 1p 21757 237

B401090173 Ltr of assurance re Exxon Nuclear Co export of 996 kg U-235, contained in 30,440 kg U, to Sweden
DUBOIS, D. European Communities, Commission of 83/12/14
RAYMOND, J Energy, Dept of 1p 21757 215

B401090178 Executive Branch position re Union Carbide Corp application to export 231,171 lb nuclear grade graphite to Japan License should be granted
MCODLDRICK, F. State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 83/12/14 SHEA, J R Office of International Programs, Director 1p. 21757 212

B401090182 Forwards application for license to export nuclear reactor equipment to Turkey.
WILSON, B D General Electric Co BDW-156-B3 83/12/21 SHEA, J R Office of International Programs, Director 2pp 21768 192

--B401090192 Application for license to export nuclear reactor equipment to Turkey
WILSON, B D General Electric Co BDW-83154 83/12/21 1p 21768 194

B401090185 Executive Branch position re Borg-Warner Corp application to export nuclear valves & valve parts to Yugoslavia License should be granted
MCODLDRICK, F. State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 83/12/14 SHEA, J R Office of International Programs, Director 1p 21757 211

B401090298 Application for license to export 333 kg U, contained in 9,655 kg U hexafluoride, to Japan
FOSTER, C M Edlow International Co KLK-20 83/12/23 1p 21768 198

B401090303 License for Sandvik Special Metals Corp to export 600 pieces Zircaloy-4 guide thimble tubes to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 88M-31062 83/12/23 1p 21768 161

B401090306 License for K-C Industries, Inc to export 10 radiation detectors, Model WL 23630, to South Korea
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 5D-441 83/12/23 2pp 21768 157

B401090598 Forwards application for licenses to export two nuclear reactors & initial & reload fuel to Turkey.
WILSON, B D General Electric Co BDW-157-B3 83/12/21, SHEA, J R Office of International Programs, Director 1p 21767 250

--B401090602 Application for license to export 337,000 kg U dioxide, as fuel bundles, to Turkey.
WILSON, B D General Electric Co. BDW-157-B3. 83/12/21 1p. 21767, 251

B401090718 Application for license to export two WX-32964 self-powered detector assemblies to West Germany
NEETHER, W H. Westinghouse Electric Corp 2E 10428 83/12/15 1p. 21757, 333

B401100026 License for Westinghouse to export 100 fuel rod springs to Sweden.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-429 84/01/03 2pp 21776, 033

B401100096 Application for license to export 10 left hand in-core radiation detectors to Korea
* K-C Industries, Inc 5D-441. 83/12/02. 1p 21768 362.

B401100334 Application for license to export 500 mCi Cf-252 encapsulated cermet wire to Japan
SAITO, T Mitsubishi International Corp (subs of Mitsubishi Corp). 83/12/28 1p 21794 357

B401100337 License for Exxon Nuclear Co to import 50 Kg U, enriched to 4% U-235, from United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/08 1p 21794 356

B401100339 Application to amend import license, increasing quantities of U & Pu & extending expiration date to 880731
FOSTER, C M Edlow International Co 83/12/05 WRIGHT, B L Assistant Director for Export/Import & International Safeguards. 1p 21794 355

B401100340 Forwards cancellation form for Order V-B452 Export license application withdrawn
SHARUPA, J D Reuter-Stokes, Inc 83/12/07 HEMBEY, E. NRC - No Detailed Affiliation Given 2pp 21794 353

B401100342 Ltr of assurance re export of 404 kg U-235, contained in 11,708 kg U, to Japan
SHIRAKAWA, T Japan, Govt of 83/12/07 RAYMOND, J F Energy, Dept of. 1p 21794 352

B401100345 Ltr of assurance re export of 119 kg U-235, contained in 3,439 kg U, to Japan.
SHIRAKAWA, T Japan, Govt of. 83/12/07 RAYMOND, J F. Energy, Dept. of 1p 21794 351

B401100349 License for Exxon Nuclear Co to export miscellaneous specially designed hardware for fuel assemblies to West Germany.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/13 2pp 21794 348

B401100351 Application for license to export six Reuter-Stokes Model RS-P6-0805-134 Plesion counters to Austria
SHARUPA, J D Reuter-Stokes, Inc A-9896. 83/12/05 2pp 21794 346

B401100352 Amend 3 to Transnuclear, Inc export license, adding Exxon Nuclear Co as addl supplier
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/07 2pp 21794 344.

B401100355 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/14 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 21794:343

B401100356 Application to amend export license, increasing quantity of SNM to 33 454 kg U-235, contained in 38 kg U
HANNETT, B A Transnuclear, Inc NUK-408 83/12/02 MOORE, R. N. Office of International Programs, Director. 9pp 21795 143

B401100359 Forwards application for export license for minor nuclear export Ltr of assurance required w/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/13 STOIBER, C R State, Dept of, Bureau of Oceans & Intl. Environ. & Scientific Affairs 1p 21794.341.

B401100368 Forwards Edlow Intl 831202 ltr transmitting revised end-us statement for 831121 export license application w/o encl.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards. 83/12/08. RAYMOND, J Energy, Dept of. 1p 21794,331

B401100374 Application to amend export license, changing quantity of matl to 2,007,900 kg U & extending expiration date to 861231.
FITZSIMMONS, J Honeywell, Inc 83/11/29 HEMBEY, E Office of International Programs, Director. 1p 21794 330.

B401100382 Application for license to export 600 pieces Zircaloy-4 guide thimble tubes to Japan.
NICKOLAUS, J W Mitsui & Co. (USA), Inc. (subs. of Mitsui & Co., Ltd.) 88M-31062 83/12/01 1p. 21794:328

B401100386 Forwards application for export license for minor nuclear export, Ltr of assurance required.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/13. RAYMOND, J Energy, Dept. of 1p 21794 291

NONDOCKETED ITEMS

B40110404 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/13 RAYMOND, J Energy, Dept of 1p
21794-308

B40110418 Forwards Reuter-Stokes, Inc 831207 request for withdrawal of export license application W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/13 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 21794 307

B40110424 Forwards Westinghouse 831130 request to withdraw export license application W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/08 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 21794 306

B401120133 Application for license to export Reuter-Stokes Model RB-C6-0201-274 in-core flux probe, containing U-238 coating for use in fast neutrons, to Italy
SKARUPA, J D Reuter-Stokes, Inc 8-0083 83/12/15 1p
21805, 154

B401120561 Application for license to export 150 Zircaloy-4 fuel channels to West Germany
WOZNIAK, D R Carpenter Technology Corp 83/12/20 HEMBY, E, Assistant Director for Export/Import & International Safeguards 3pp. 21803 084

B401120562 Forwards application for amend to export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/26 STOIBER, C State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 21803 083

B401120568 Application for license to export 38 Zircaloy-4 fuel channels to Japan
WOZNIAK, D R Carpenter Technology Corp 83/12/20 HEMBY, E Assistant Director for Export/Import & International Safeguards 3pp 21803 080

B401130061 Informs that License XSNM-2081 may be issued No matl changed circumstances since issuance of License XSNM-2069
MOORE, R. N. Assistant Director for Export/Import & International Safeguards 83/12/22 Assistant Director for Export/Import & International Safeguards 1p 21821 137

B401130065 Informs that License XSNM-2076 may be issued No matl changed circumstances since issuance of License XSNM-2081
MOORE, R. N. Assistant Director for Export/Import & International Safeguards. 83/12/28 Assistant Director for Export/Import & International Safeguards 1p 21821 134

B401130075 Application for license to export 200 Zircaloy-4 fuel channels to West Germany
WOZNIAK, D R Carpenter Technology Corp 83/12/20 HEMBY, E Assistant Director for Export/Import & International Safeguards 3pp 21821 128

B401160040 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/12/30 RAYMOND, J Energy, Dept of 1p
21821 359

B401160080 Application to amend license to export 38 kg U, containing 35 454 kg U-235
DUBOIS, D European Communities, Commission of 83/12/12, RAYMOND, J Energy, Dept of 1p 21821 360

B401160383 License for Saginaw Steering Gear Div, GM Corp to export miscellaneous spare parts for loading & unloading fuel elements in nuclear reactor to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/01/05 1p 21823 356

B401180001 License for Westinghouse to export two self-powered detector assemblies, Model WX-32764, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 10428 84/01/09 1p 21847 362

B401190209 Application for license to export 727 lb natural U ore to Canada
* Cotter Corp 3011KB630-87-7 83/12/28 1p 21870 010

B401190212 Application to amend export license, extending expiration date for 2 addl yrs
MORGENSTERN, A Sigma Chemical Co 84/01/03 HEMBY, E Assistant Director for Export/Import & International Safeguards 1p 21867 047

B401190230 Ltr of assurance re export of nuclear matls to Canada
BOISVENUE, L Canada, Atomic Energy Control Board 83/12/14 RAYMOND, J. F Energy, Dept of 2pp 21870 001

B401190259 License for Edlow Intl Co to export 12.6 kg U-235, contained in 63 kg U, to Canada
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards AECL-2A (83) 84/01/10 2pp 21870 093

B401240133 SECY-84-008
Recommends Commission authorize issuance of License XMAT-0270 to Union Carbide Corp to export 231,171 lb graphite to Japan & authorize issuance of License XMAT-0275 upon receipt of favorable Executive Branch judgement
DIRCKS, W. J. Office of the Executive Director for Operations 84/01/09 23pp. 21945 040

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAHODT, M. M.	B401260222*	50-289 Q	AMBTUTZ, B.	B401270235	50-155 R	AXELRAD, J. A.	B312230327	70-1
AAHODT, N. O.	B401100509	50-289 Q	AMBTUTZ, B.	B401270322	50-155 R	AXELRAD, J. A.	B401060231	50-3
AAHODT, N. O.	B401170336	50-289 Q	ANANDAPPA, A.	B401130234	50-237 B	AXELRAD, J. A.	B401230051	50-3
AAHODT, N. O.	B401170339*	50-289 Q	ANDERSON, M.	B401180117	50-331 R	AXELRAD, W.	B401310290	1&E
AAHODT, N. O.	B401170342*	50-289 Q	ANDERSON, C.	B401240313*	50-354 Q	AXELRAD, W.	B401310344	40-8
AAHODT, N. O.	B401170344*	50-289 Q	ANDERSON, C.	B401240327*	50-271 Q	AXELRAD, W. L.	B401040464	50-4
AAHODT, N. O.	B401260116	50-289 Q	ANDERSON, C. J.	B401100203*	50-334 Q	AXELRAD, W. L.	B401100428	50-4
AAHODT, N. O.	B401260116	50-289 Q	ANDERSON, C. J.	B401240059*	50-272 Q	AXELRAD, W. L.	B401120368	50-2
AAHODT, N. O.	B401260208	50-289 Q	ANDERSON, C. J.	B401240472*	50-423 Q	AXELRAD, W. L.	B401130222	50-1
AAHODT, N. O.	B401260214*	50-289 Q	ANDERSON, C. J.	B401260186*	50-412 Q	AXELRAD, W. L.	B401130289	50-3
ABRAHAM, K.	B401030107*	40-84	ANDERSON, C. O.	B401230442*	50-10 Q	AXELRAD, W. L.	B401160257	50-3
ABRAHAM, K.	B401030146*	FOIA	ANDERSON, M. T.	B401170355*	50-282 Q	AXELRAD, W. L.	B401240170	40-8
ABRUZZO, Q. A.	B401130191*	QA999	ANDERSON, P. H.	B401110214	50-400 Q	AXELRAD, W. L.	B401240358*	40-1
ABRUZZO, Q. A.	B401130204*	QA999	ANDERSON, P. H.	B401110214	50-400 Q	AXELRAD, W. L.	B401300007	50-4
ADAMS, J. W.	B401130224	50-10 P	ANDERSON, P. H.	B401110224*	50-400 Q	AYRAULT, Q.	B401160443	NURE
ADCOCK, J. R.	B401250094	50-170 H	ANDERSON, P. H.	B401110224*	50-400 Q	BACANBAG, V. P.	B309230076*	MISC
ADENBAM, C. Q.	B401110187	50-424 A	ANDERSON, P. L.	B401120299	50-309 R	BACHMANN, R. Q.	B401250200	50-2
ADENBAM, E. Q.	B401110358	50-438 A	ANDERSON, R.	B401050609*	50-358 A	BACHMANN, R. Q.	B401250255	50-2
ADENBAM, E. Q.	B401120440	50-395 P	ANDERSON, R. I.	B401170062	50-509 A	BAER, R. E.	B401040377*	50-4
ADENBAM, E. Q.	B401120443*	50-395 P	ANDERSON, R. J.	B401170383*	50-528 Q	BAER, R. L.	B401060669	TOPRI
ADENBAM, E. Q.	B401130097	50-413 A	ANDONINI, Q. C.	B401170393	50-528 Q	BAER, R. L.	B401110361	TOPRI
ADENBAM, C. Q.	B401130102	50-329 A	ANDONINI, Q. C.	B401200053*	50-528 F	BAER, R. L.	B401230562	MISC
ADENBAM, E. Q.	B401130538	50-395 P	ANDRE, W. B.	B401130220	NUREQ	BAILEY, J. D.	B401030083	50-4
ADENBAM, E. Q.	B401170542*	50-395 P	ANDROBIK, R.	B401160126	50-317 B	BAILEY, J. D.	B401030220	50-4
ADENBAM, E. Q.	B401250071	50-413 F	ANDRUB, N. J.	B401110489	40-4492	BAILEY, J. D.	B401060325	50-4
ADRIANO, D. C.	B401090606	NUREQ	ANG, W. P.	B401060478*	50-390 Q	BAILEY, R. J.	B401190349*	50-3
AGEE, J. R.	B401130195*	QA999	ANG, W. P.	B401090244*	50-333 Q	BAILEY, R. J.	B401240292*	50-3
AGLEB, J. A.	B401050563*	50-250 Q	ANG, W. P.	B401240355*	50-413 Q	BAIR, Q. Q.	B401250231	50-3
AGOSTI, F. E.	B401230330	50-341 A	ANKLAN, T. M.	B401300018	NUREQ	BAIR, Q. Q.	B401120408	50-3
AIKMAN, R.	B401030014	40-84	ANTONACCI, T.	B401120361*	MISC	BAIR, Q. Q.	B401160252	50-3
ALBERTS, J. J.	B401090606	NUREQ	APPEL, R. R.	B401040002	40-872B	BAIR, Q. Q.	B401160304	50-3
ALDRIGHT, R. H.	B401050335*	50-369 Q	APPEL, R. R.	B401090593	40-872B	BAIRD, J. B.	B401170330*	50-2
ALDRIGHT, R. H.	B401050457*	50-324 Q	ARIAS, J.	B401130176	50-250 B	BAIRD, J. B.	B401170422*	50-2
ALDRIGHT, R. H.	B401090138*	50-324 Q	ARIAS, J.	B401170246	50-250 B	BAIRD, J. B.	B401230160*	50-4
ALDRIGHT, R. H.	B401240222*	50-127 Q	ARIAS, J.	B401240099	50-251 B	BAIRD, J. B.	B401230309*	50-2
ALDRIGHT, R. H.	B401240380*	50-369 Q	ARLOTTI, M. O.	B401200064*	TOPREP	BAKER, B.	B401250085*	50-3
ALDEN, H. M.	B401190404	50-277 R	ARNOLD, Q.	B401040228*	FOIA	BAKER, E. L.	B401230359*	QA999
ALEXICH, M. P.	B401040193	50-315 F	ASH, E. B.	B401170502	WASTE MGT	BALL, W. Q.	B401030223	PRM
ALEXICH, M. P.	B401130270	50-315 Q	ASH, E. B.	B401170545	WASTE MGT	BALLINGER, P. L.	B401120401	50-2
ALEXICH, M. P.	B401200074	50-315 P	ASH, E. B.	B401170547	WASTE MGT	BALLINGER, P. L.	B401270475	50-2
ALEXICH, M. P.	B401230374*	50-315 Q	ASH, E. B.	B401190031	WASTE MGT	BARAN, R.	B401120249	50-2
ALEXICH, M. P.	B401240404	50-315 F	ASH, R. F.	B401100483	50-317 F	BARAN, R.	B401270259	50-2
ALEXICH, M. P.	B401250028	50-315 P	ASHBURN, D. J.	B401030167	TOPREP	BARANOW, B. W.	B401100002	50-3
ALEXICH, F.	B401130292	50-315 P	ASHBURN, D. J.	B401060269	TOPREP	BARANOW, B. W.	B401100233*	50-3
ALGER, D. H.	B401250128	50-186 B	ASHBURN, D. J.	B401110001	50-377 J	BARANOW, B. W.	B401100238*	50-3
ALIKONIG, N. A.	B401220592*	CONTRACT	ASHBURN, D. J.	B401200056	50-397 J	BARANOW, B. W.	B401100246	50-3
ALLARD, D. J.	B401100351*	40-672	ASHBURN, D. J.	B401200049	50-397 J	BARANOW, B. W.	B401100257*	50-3
ALLEN, C. H.	B401250028	NUREQ	ASBESTINE, J. K.	B401250192*	50-344 F	BARANOW, B. W.	B401100261*	50-3
ALLEN, M. T.	B401170132	50-325 B	AUSTIN, Q.	B401170020	50-298 R	BARANOW, B. W.	B401100315	50-3
ALLENSPACH, F.	B401160139*	50-219 P	AVANT, D.	B401060008	50-187 R	BARANOW, B. W.	B401100465	50-3
ALLIWOOD, I. J.	B401090393	50-289 Q	AXELRAD, J.	B312190241	1&E	BARANOW, B. W.	B401160079	50-3
ALTOMARE, P. M.	B401120117	WASTE MGT	AXELRAD, J.	B401120343	1&E	BARANOW, B. W.	B401160096	50-3
ALTON, J. R.	B401130168*	QA999	AXELRAD, J.	B401120360	50-324 B	BARANOW, B. W.	B401160124	50-3
AMADON, P.	B401050609*	50-358 A	AXELRAD, J.	B401130280	50-329 B	BARANOW, B. W.	B401170367	50-3
AMICO, P. J.	B401030364	50-245 P	AXELRAD, J.	B401190367	1&E	BARANOW, B. W.	B401190348	50-3

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BARANOW, S. W.	8401190368	50-329 Q	BAXTER, D. E.	8401310429*	GEN TEC 18	BERNABEI, L.	8401180008	50-528 A
BARANOW, S. W.	8401190378	50-329 S	BAXTER, D. E.	8401310435*	GEN TEC 18	BERNARD, H.	8401120135	50-184 P
BARANOW, S. W.	8401190397	50-329 S	BAXTER, T. A.	8401060280	50-400 Q	BERNHOF, S.	8401130324	50-305 S
BARANOW, S. W.	8401190424	50-329 A	BAXTER, T. A.	8401060280	50-400 Q	BERNHOF, S. L.	8401040309	50-305 S
BARANOW, S. W.	8401230340	50-329 R	BAXTER, T. A.	8401060318	50-400 Q	BERNHOF, S. L.	8401040321	50-305 S
BARBIERI, N. J.	8401160263	50-352 D	BAXTER, T. A.	8401060318	50-400 Q	BERNHOF, S. L.	8401060348	50-305 S
BARHAM, C. D.	8401160007	50-261 J	BAXTER, T. A.	8401060318	50-400 Q	BERNHOF, S. L.	8401120378	50-305 S
BARHAM, C. D.	8401160070	50-261 J	BAXTER, T. A.	8401170233	50-400 Q	BERNHOF, S. L.	8401230354	50-305 S
BARHAM, C. D.	8401160121	50-261 J	BAXTER, T. A.	8401170233	50-400 Q	BERNHOF, S. L.	8401230369	50-305 S
BARHAM, C. D.	8401160184	50-261 J	BAXTER, T. A.	8401170302	50-400 Q	BERRY, Z. E.	8401030210	50-251 S
BARHAM, C. D.	8401200024	50-324 J	BAXTER, T. A.	8401170302	50-400 Q	BERRY, Z. E.	8401040419	50-251 S
BARHAM, C. D.	8401200192	50-324 J	BAXTER, T. A.	8401230391	50-400 Q	BERRY, Z. E.	8401050564	50-231 S
BARHAM, C. D.	8401240092	50-261 J	BAXTER, T. A.	8401230391	50-400 Q	BERRY, Z. E.	8401260157	50-250 S
BARHAM, C. D.	8401240256	50-261 J	BAXTER, T. A.	8401230393*	50-400 Q	BEBS, J. E.	8401260497*	50-445 Q
BARHAM, C. D.	8401260023	50-324 J	BAXTER, T. A.	8401230393*	50-400 Q	BEBS, J. E.	8401040359*	50-498 Q
BARHAM, C. D.	8401260210	50-324 J	BAXTER, T. A.	8401230466	50-400 Q	BETTENHAUSEN, L.	8401040167*	50-324 Q
BARICH, A. C.	8401310374	0A999	BAXTER, T. A.	8401230466	50-400 Q	BETTENHAUSEN, L.	8401120218*	50-322 Q
BARLETTA, R. E.	8401130224	50-10 P	BAXTER, T. A.	8401260123	50-400 Q	BETTENHAUSEN, L.	8401240310*	50-352 Q
BARNES, C.	8401230133	40-147B	BAXTER, T. A.	8401260123	50-400 Q	BETTENHAUSEN, L.	8401260204*	50-368 Q
BARNES, J.	8401050197*	0A999	BAYNARD, P. Y.	8401030077	50-302 S	BETTENHAUSEN, L.	8401260309*	50-326 Q
BARNES, J.	8401050222*	0A999	BAYNARD, P. Y.	8401030236	50-302 S	BEVAN, R. B.	8401120458	50-265 P
BARNES, J.	8401100487*	0A999	BAYNARD, P. Y.	8401030274	50-302 S	BEYER, B. R.	8401050384*	50-316 F
BARNES, J.	8401130271*	0A999	BAYNARD, P. Y.	8401040143	50-302 S	BIBB, H. E.	8401050394*	50-335 Q
BARNES, J.	8401170341*	0A999	BAYNARD, P. Y.	8401040248	50-302 S	BIBB, H. E.	8401240447*	50-335 Q
BARNES, J.	8401170415*	0A999	BAYNARD, P. Y.	8401040314	50-302 S	BICEHOUSE, H. J.	8401100241*	50-367 Q
BARNES, J.	8401230220*	0A999	BAYNARD, P. Y.	8401050351*	50-302 Q	BICKFORD, W. E.	8401130220	NUREQ
BARNES, J.	8401270451*	0A999	BAYNARD, P. Y.	8401050612*	50-302 Q	BICKWIT, L.	8204070577*	FD1A
BARNES, J.	8401270478*	0A999	BAYNARD, P. Y.	8401060397*	50-302 Q	BICKWIT, L.	8204070589*	40-2061
BARNES, P. L.	8401040533	50-237 Q	BAYNARD, P. Y.	8401090336*	50-302 Q	BICKWIT, L.	8204220364*	50-275 P
BARNES, P. L.	8401100435	50-295 P	BAYNARD, P. Y.	8401100425*	50-302 Q	BICKWIT, L.	8205240606*	FD1A
BARNES, P. L.	8401170339	50-237 P	BAYNARD, P. Y.	8401120107	50-302 X	BICKWIT, L.	8207230670*	50-356 A
BARNES, P. L.	8401170337	50-454 Q	BAYNARD, P. Y.	8401240429*	50-302 Q	BICKWIT, L.	8401250112*	FD1A
BARNES, P. L.	8401190420	50-454 Q	BAYNARD, P. Y.	8401240568*	50-302 Q	BICKWIT, L.	8401250148*	40-2061
BARNES, P. L.	8401300005	50-295 Q	BAYNARD, P. Y.	8401050641	50-302 S	BICKWIT, L.	8401250164*	50-359 A
BARR, K.	8401100241*	50-387 Q	BAYNE, J. P.	8401040383	50-286 P	BICKWIT, L.	8401250258*	FD1A
BARR, K. P.	8401050335*	50-369 Q	BAYNE, J. P.	8401040387*	50-286 P	BICKWIT, L.	8401250302*	50-337 Q
BARR, K. P.	8401050457*	50-324 Q	BAYNE, J. P.	8401050437	50-286 P	BICKWIT, L.	8401250322*	FD1A
BARR, K. P.	8401050506*	50-395 Q	BAYNE, J. P.	8401100258	50-286 F	BIDINGER, G. H.	8312230300	70-2955
BARR, K. P.	8401050635*	50-259 Q	BAYNE, J. P.	8401100264	50-286 F	BIDINGER, G. H.	8401070779*	70-1113
BARR, K. P.	8401060491*	50-416 Q	BAYNE, J. P.	8401100271	50-286 P	BIDINGER, G. H.	8401200061*	70-36
BARR, K. P.	8401090121*	70-143	BAYNE, J. P.	8401110069	50-286 P	BIELEFELD, E. L.	8401170371*	TOPREF
BARR, K. P.	8401090138*	50-324 Q	BAYNE, J. P.	8401120214	50-333 Q	BIEMLER, S.	8401120289*	50-309 R
BARR, K. P.	8401090252*	50-335 Q	BAYNE, J. P.	8401120242	50-333 S	BIEMLER, S.	8401270261	50-309 P
BARR, K. P.	8401090277*	50-327 Q	BAYNE, J. P.	8401230295	50-333 P	BIEMLER, S.	8401160284*	50-219 P
BARR, K. P.	8401240222*	50-129 Q	BAYNE, J. P.	8401260311	50-333 P	BIER, J. A.	8401260128	50-155 Q
BARR, K. P.	8401240380*	50-369 Q	BAYNE, J. P.	8401270222	50-333 P	BIRKENHEIER, J.	8401240289	50-322 Q
BARRETT, L. H.	8401100334	50-320 Q	BAYNE, J. P.	8401270224*	50-333 P	BIRKENHEIER, J.	8401240289	50-322 Q
BARRETT, L. H.	8401100393	50-320 Q	BAYNE, J. P.	8401270440	50-333 P	BIRKENHEIER, J.	8401250167	50-322 Q
BARRETT, L. H.	8401170397	50-320 Q	BAYNE, J. P.	8401300163	50-333 P	BIRKENHEIER, J.	8401250177	50-322 Q
BARRETT, L. H.	8401180019	50-320 R	BAYNE, J. P.	8401300247	50-333 S	BIRKENHEIER, J.	8401260184	50-322 Q
BARRETT, L. H.	8401190135	50-320 P	BAYNES, J. P.	8312200559	50-286 P	BIRKENHEIER, J.	8401260184	50-322 Q
BARRETT, L. H.	8401250433	50-320 P	BAYNES, J. P.	8401180241	50-333 P	BIRKENHEIER, J.	8401260189*	50-322 Q
BARTH, C. A.	8401040118	50-400 Q	BEALE, K. E.	8401260036*	50-395 F	BIRKENHEIER, J.	8401260189*	50-322 Q
BARTH, C. A.	8401040122	50-400 Q	BEALL, J.	8401300286*	50-443 Q	BISBEE, G. D.	8401100213	50-443 Q
BARTH, C. A.	8401120337	50-400 Q	BEARE, J. A.	8401270423	State Prog	BISBEE, G. D.	8401240250	50-443 Q
BARTOLOZZI, A. R.	8401030093*	40-86	BEAUCHAMP, J. E.	8401300342*	50-213 F	BISCHOFF, C. A.	8401250256	FR
BARTOLOZZI, A. R.	8401030161*	40-86	BEAVER, J.	8401260401*	50-320 F	BISHOP, T. W.	8401030230*	50-312 Q
BARTON, N.	8401100242*	WASTE MOT	BEAVER, J. R.	8401310219*	50-320 F	BISHOP, T. W.	8401030293	50-397 Q
BARTON, W. D.	8401050163	50-213 S	BECKER, B. D.	8401100215	50-454 Q	BISHOP, T. W.	8401100404	50-312 Q
BARTON, W. D.	8401300342*	50-213 F	BECKER, B. D.	8401100215	50-454 Q	BISHOP, T. W.	8401170378	50-528 Q
BARTON, W. D.	8401160073	50-213 S	BECKHAM, J. T.	8401300030	50-321 P	BISHOP, T. W.	8401200018	50-397 Q
BARUTH, E.	8401110494	40-299 F	BECKHAM, J. T.	8401310339	50-321 P	BISHOP, T. W.	8401200027	50-397 Q
BASKIN, K. P.	8401240179*	50-206 H	BECKHAM, J. T.	8401310335	50-321 F	BISHOP, T. W.	8401200072	50-397 Q
BASKIN, K. P.	8401250183	50-206 F	BELANGER, J. L.	8401100434*	50-454 Q	BISHOP, T. W.	8401200191	50-397 Q
BASKIN, K. P.	8401270256	50-361 P	BELANGER, J. L.	8401300008*	50-409 Q	BISHOP, T. W.	8401200208	50-528 Q
BASKIN, K. P.	8401270270*	50-361 P	BELCHER, R. L.	8312220138	50-166 P	BISHOP, T. W.	8401300142	50-206 Q
BASSIN, N.	7903090350*	FD1A	BELIN, R. H.	8401200234*	50-324 P	BISHOP, T. W.	8401300222	50-528 Q
BASSIN, N.	8401040055*	FD1A	BELL, D. D.	8401240617*	50-286 F	BISHOP, T. W.	8401300277	50-312 Q
BASSIN, N.	8401040282*	40-550B	BELL, M. J.	8401180035*	ACRR	BISHOP, T. W.	8401300289	50-528 Q
BASSO, L. F.	8401030268	50-317 S	BELL, N.	8401160199	50-508 Q	BISHOP, T. W.	8401300311	50-312 Q
BASSO, L. F.	8401270137	50-317 S	BEMIS, P. R.	8401050380*	50-324 Q	BISSETT, P.	8401180224*	50-334 Q
BATEMAN, W.	8401240313*	50-354 Q	BEMIS, P. R.	8401050398*	50-400 Q	BISSETT, P.	8401300274*	50-244 Q
BATEMAN, W. H.	8401030262*	50-322 Q	BEMIS, P. R.	8401050525*	50-324 Q	BISSETT, P. H.	8401260369*	50-299 Q
BATES, A.	8401060162	SECY	BEMIS, P. R.	8401060432*	50-324 Q	BLACKMAN, H. B.	8401030335	NUREQ
BATES, T. H.	8401240086	50-275 U	BENIS, P. R.	8401240423*	50-261 Q	BLACKMAN, H. B.	8401130092	NUREQ
BAULITZ, J. E.	8401190464	WASTE MOT	BENIS, P. R.	8401240552*	50-297 Q	BLAIR, R. L.	8401120138*	CONTRACT
BAURACK	8401300133	50-353 S	BENEDICT, P.	8401260286*	50-416 F	BLAKE, E. L.	8312050118	50-289 Q
BAUSER, D. B.	8401260231	50-289 Q	BENNETT, H. A.	8401170035*	FD1A	BLAKE, E. L.	8312050118	50-289 Q
BAUSER, D. B.	8401260231	50-289 Q	BENNETT, J. W.	8401310197	WASTE MOT	BLAKE, E. L.	8401030087	50-289 Q
BAUSER, D. B.	8401300240	50-289 Q	BERCEL, E.	8401240393*	50-322 A	BLAKE, E. L.	8401030087	50-289 Q
BAUSER, D. B.	8401300240	50-289 Q	BERGAN, G. W.	8401270357	50-237 S	BLAKE, E. L.	8401110232	50-289 Q
BAUSER, D. B.	8401300256	50-289 Q	BERGER, J. D.	8401230157	MISC	BLAKE, E. L.	8401110232	50-289 Q
BAUSER, D. B.	8401300256	50-289 Q	BERICK, D. M.	8401090481	WASTE MOT	BLAKE, E. L.	8401240167	50-289 Q
BAUSER, D. B.	8401310283	50-289 Q	BERICK, D. M.	8401110219	WASTE MOT	BLAKE, J. J.	8401050276*	50-424 Q
BAUSER, D. B.	8401310283	50-289 Q	BERNABEI, L.	8401170180	FD1A	BLAKE, J. J.	8401050338*	50-324 Q

PERSONAL AUTHOR INDEX

483

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BLAKE, J. J.	B401050546*	50-390 Q	BOOKER, J. E.	B401310439	50-458 E	BRIGHT, Q. D.	B401310262	50-400 Q
BLAKE, J. J.	B401050672*	50-413 Q	BORCHARDT, R.	B312190342	50-293 Q	BRINKMAN, B.	B312300176	50-336 B
BLAKE, J. J.	B401060317*	50-413 Q	BORDENICK, B. H.	B401040135	50-322 Q	BRITTON, W. H.	B401060351*	70-1151
BLAKE, J. J.	B401060462*	50-390 Q	BORDENICK, B. H.	B401250244	50-322 Q	BRITTON, W. H.	B401240357*	70-1151
BLAKE, J. J.	B401060478*	50-370 Q	BORDENICK, B. H.	B401250250	50-322 Q	BRITTON, W. H.	B401250267*	70-1151
BLAKE, J. J.	B401090119*	50-261 Q	BORDINE, T. C.	B401230042	50-155 P	BROCK, B. L.	B401300282*	70-754
BLAKE, J. J.	B401090130*	50-438 Q	BORDINE, T. C.	B401230253	50-155 V	BROMBERG, B.	B401120122	CONTRACT
BLAKE, J. J.	B401090201*	50-351 Q	BORKOWSKI, R. J.	B401030350	MUREO	BROMBERG, B. J.	B401030079	CONTRACT
BLAKE, J. J.	B401090244*	50-353 Q	BORST, F. J.	B401130020	50-267 P	BROMBERG, B. J.	B401060215	CONTRACT
BLAKE, J. J.	B401090446*	50-424 Q	BORST, F. J.	B401270441	50-267 P	BROMBERG, B. J.	B401060445	CONTRACT
BLAKE, J. J.	B401090451*	50-302 Q	BOTIMER, L. A.	B401100384	50-329 P	BROMBERG, B. J.	B401100042	CONTRACT
BLAKE, J. J.	B401240278*	50-250 Q	BOTIMER, L. A.	B401240266	50-329 A	BROMBERG, B. J.	B401100135	CONTRACT
BLAKE, J. J.	B401240355*	50-413 Q	BOTIMER, L. A.	B401170164	50-329 A	BROMBERG, B. J.	B401230025	CONTRACT
BLANCHARD, J. J.	B401050031*	50-329 F	BOTIMER, L. A.	B401170167	50-329 A	BROMBERG, B. J.	B401090454	CONTRACT
BLAZEY, D. R.	B401270212	50-289 Q	BOUCHARD, Q. H.	B401270404	50-213 B	BROWN, J. C.	B401050374*	50-286 F
BLOCH, P. B.	B401050277	50-445 Q	BOUCHEY, Q. D.	B4011600384	50-397 P	BROWN, J. C.	B401120230	50-286 R
BLOCH, P. B.	B401200148	50-445 Q	BOUCHARD, R. J.	B401040399	50-395 B	BROWN, J. C.	B401240340	50-286 R
BLOCH, P. B.	B401230403	50-440 Q	BOUKNIGHT, R. J.	B401040342	50-395 B	BROWN, J. C.	B401270267	50-286 R
BLOCH, P. B.	B401310222	50-445 Q	BOUKNIGHT, R. J.	B401030443	50-395 B	BROWN, J. C.	B401230432	50-275 U
BLOCH, P. B.	B401160035*	ACRS	BOUKNIGHT, R. J.	B401050597	50-395 B	BROOKS, B. Q.	B401230162	MUREO
BLOUGH, A. R.	B401100287*	50-277 Q	BOUKNIGHT, R. J.	B401240123	50-395 B	BROOKS, B. Q.	B401230549*	50-289 P
BLUM, Q.	B401040317	50-346 B	BOUKNIGHT, R. J.	B401240387	50-395 B	BROOKS, E. H.	B401090230*	50-270 Q
BOARDMAN, J. R.	B401270003*	50-498 Q	BOUKNIGHT, R. J.	B401300241	50-395 B	BROUGHTON, J. Q.	B401310145*	50-289 P
BOGDEN, Q.	B401110583	40-1162	BOUKNIGHT, R. J.	B207110091*	40-86	BROWN, C. H.	B401100440*	50-263 Q
BOGDEN, Q.	B401270157	40-1162	BOURNIA, A.	B401110165	50-373 P	BROWN, H. H.	B401160244	50-322 Q
BOGDEN, Q.	B401310484	40-1162	BOWMAN, D. H.	B401100292	50-352 H	BROWN, J. E.	B401230647*	50-213 F
BOGETT, V.	B401260152*	50-387 F	BOYER, D.	B401160230	50-255 B	BROWN, J. M.	B005070343*	FOIA
BOHL, L. S.	B401230329*	0A999	BOYD, D.	B401300110	50-295 B	BROWN, J. M.	B006200261*	FOIA
BOHVENUE, L.	B401190230	XPORTLIC	BOYD, D. C.	B401190412*	50-315 Q	BROWN, K. J.	B401270160	40-8745
BOLANDER, M. A.	B401310061*	50-261 P	BOYD, D. C.	B401190449*	50-295 Q	BROWN, N.	B401060111*	50-320 F
BOLON, A. E.	B401120268	50-123 B	BOYD, D. C.	B401300318*	50-255 Q	BROWN, R. C.	B401040514*	50-299
BOMBERGER, C.	B312060211*	50-307 P	BOYER, L. E.	B401060145*	50-324 F	BROWN, S. D.	B401090315*	50-289 P
BOMBERGER, C.	B312060347*	50-244 P	BOYER, L. E.	B401060151*	50-324 F	BROWN, W. B.	B401060237	70-143
BONNER, N.	B401040390	50-346 B	BOYER, R. E.	B401170166	50-206 B	BROWN, W. B.	B401060683	70-371
BOOKER, J. E.	B312290417	50-458 E	BOYER, R. E.	B401230505*	0A999	BROWN, W. B.	B401090093	70-734
BOOKER, J. E.	B401040119	50-458 B	BOYER, R. E.	B401230512*	0A999	BROWN, W. B.	B401090120	70-143
BOOKER, J. E.	B401040219*	50-458 B	BOYER, V. B.	B401090368*	50-463 Q	BROWN, W. B.	B401090187	70-734
BOOKER, J. E.	B401040447*	50-458 Q	BRADFORD, L.	B401050216	50-289 Q	BROWN, W. B.	B401090568	70-143
BOOKER, J. E.	B401040476	50-458 B	BRADFORD, L.	B401170311	50-289 Q	BROWN, W. B.	B401090576	70-27
BOOKER, J. E.	B401040525	50-458 B	BRADFORD, L.	B401190174	50-289 Q	BROWN, W. B.	B401090583	70-734
BOOKER, J. E.	B401040528	50-458 E	BRADFORD, W. H.	B401050626*	50-348 Q	BROWN, W. B.	B401090588	70-734
BOOKER, J. E.	B401050169	50-458 E	BRADFORD, W. H.	B401240580*	50-348 Q	BROWN, W. B.	B401090590	70-27
BOOKER, J. E.	B401050210	50-458 A	BRADFORD, W. H.	B401240606*	50-348 Q	BROWN, W. B.	B401090594	70-2745
BOOKER, J. E.	B401050271	50-458 A	BRADHAM, A. B.	B401050111*	50-395 F	BROWN, W. B.	B401090597	70-1257
BOOKER, J. E.	B401060291	50-458 C	BRADLEY, D.	B206130011*	FOIA	BROWN, W. B.	B401090600	70-1201
BOOKER, J. E.	B401090105	50-458 E	BRADLEY, D.	B401060391	50-289 U	BROWN, W. B.	B401090604	70-734
BOOKER, J. E.	B401090153	50-458 F	BRADLEY, E. J.	B401090334	50-352 A	BROWN, W. B.	B401090607	70-1113
BOOKER, J. E.	B401100212	50-458 B	BRADLEY, E. J.	B401190301	50-352 Q	BROWN, W. B.	B401090628	70-2972
BOOKER, J. E.	B401100278	50-458 B	BRADLEY, E. J.	B401300224	50-352 C	BROWN, W. B.	B401090676	70-1151
BOOKER, J. E.	B401100450	50-458 B	BRADLEY, E. J.	B401050037*	50-320 F	BROWN, W. B.	B401090707	70-2985
BOOKER, J. E.	B401110072	50-458 E	BRADY, J. A.	B401050049*	50-320 F	BROWN, W. B.	B401110369	70-27
BOOKER, J. E.	B401130060	50-458 B	BRADY, J. A.	B401050096*	50-289 F	BROWN, W. B.	B401110377	70-734
BOOKER, J. E.	B401130072	50-458 B	BRADY, J. A.	B401050235*	50-289 F	BROWN, W. L.	B401240269	50-275 U
BOOKER, J. E.	B401130139	50-458 B	BRADY, J. A.	B401060111*	50-320 F	BROWN, W. R.	B401120046*	WASTE MOT
BOOKER, J. E.	B401130192	50-458 B	BRADY, J. A.	B401060152*	50-289 F	BROWN, W. R.	B401120049*	WASTE MOT
BOOKER, J. E.	B401130216	50-458 B	BRADY, J. A.	B401310219*	50-320 F	BROWN, W. R.	B401120065*	WASTE MOT
BOOKER, J. E.	B401130263	50-458 B	BRADY, N. F.	B206130010*	FOIA	BROWNE, B. A.	B401110218*	50-400 Q
BOOKER, J. E.	B401130277	50-458 B	BRADY, N. F.	B401120418	50-368 R	BROWNING, R. E.	B401120147	WASTE MOT
BOOKER, J. E.	B401130286	50-458 B	BRADLEY, L. S.	B401270402	50-368 R	BROWNLEE, V. L.	B401050562*	50-369 Q
BOOKER, J. E.	B401130311	50-458 B	BRADLEY, L. S.	B401270347*	50-213 B	BROWNLEE, V. L.	B401090104*	50-369 Q
BOOKER, J. E.	B401130313	50-458 E	BRASSBORD, J. D.	B401270347*	50-213 B	BRUCH, A.	B401040504	50-327 H
BOOKER, J. E.	B401130315	50-458 B	BRENNER, L.	B401050248	50-352 Q	BRUCH, A.	B401050157	50-259 B
BOOKER, J. E.	B401130344	50-458 B	BRENNER, L.	B401060276	50-322 Q	BRUCH, A.	B401050234	50-259 B
BOOKER, J. E.	B401130388	50-458 E	BRENNER, L.	B401090271	50-322 Q	BRUCH, A.	B401050263	50-259 H
BOOKER, J. E.	B401130394	50-458 B	BRENNER, L.	B401240157	50-352 Q	BRUCH, A.	B401170248	50-259 B
BOOKER, J. E.	B401170003	50-458 B	BRENNER, L.	B401240240	50-352 Q	BRUCH, A.	B401170288	50-259 B
BOOKER, J. E.	B401170187	50-458 B	BRENNER, L.	B401310151	50-352 Q	BRUCH, A.	B401300199	50-259 B
BOOKER, J. E.	B401170203	50-458 B	BRENNER, L.	B401310227	50-352 Q	BRUNET, R. R.	B401240151*	50-206 P
BOOKER, J. E.	B401200296*	50-458 F	BREY, H. L.	B401100313	50-267 Q	BRUNNET, R. R.	B401180215	PR
BOOKER, J. E.	B401230122	50-458 B	BREY, H. L.	B401120085	50-267 P	BRUNSON, B. Q.	B401040388*	0A999
BOOKER, J. E.	B401230164	50-458 B	BREY, H. L.	B401230479	50-267 P	BRUNSON, B. Q.	B401040395*	0A999
BOOKER, J. E.	B401230168	50-458 B	BREY, H. L.	B401270180	50-267 P	BRUNSON, B. Q.	B401040395*	0A999
BOOKER, J. E.	B401230265	50-458 B	BRICKLEY, R. H.	B401170325*	0A999	BRUSKE, S. J.	B401310425*	GEN TEC 18
BOOKER, J. E.	B401230276	50-458 B	BRICKLEY, R. H.	B401230503*	0A999	BRUSKE, S. J.	B401310435*	GEN TEC 18
BOOKER, J. E.	B401230297	50-458 B	BRICKLEY, R. H.	B401270444*	0A999	BUCKALEW, W. H.	B401310105	MUREO
BOOKER, J. E.	B401230322	50-458 B	BRIDEN, D. W.	B401190331	50-344 B	BUCKHAM, J. A.	B312200510	HISC
BOOKER, J. E.	B401230322	50-458 B	BRIDEN, D. W.	B401300333*	50-346 F	BUCKHAM, J. A.	B401060407	50-332 Q
BOOKER, J. E.	B401240122	50-458 B	BRIDENBAUGH, D.	B401060370	50-322 Q	BUCKHAM, J. A.	B401060506	50-332 Q
BOOKER, J. E.	B401240127	50-458 B	BRIDENBAUGH, D.	B401240510*	50-352 Q	BUCKHAM, J. A.	B401090066	50-332 Q
BOOKER, J. E.	B401240218	50-458 B	BRIDENBAUGH, D.	B401240309*	50-336 Q	BUCKLEY, J. A.	B401060044	50-315 Q
BOOKER, J. E.	B401240231	50-458 B	BRIGHT, Q. D.	B401200111	50-142 Q	BUCKLEY, J. A.	B401160360	FOIA
BOOKER, J. E.	B401250203	50-458 A	BRIGHT, Q. D.	B401200138	50-142 Q	BUCKLEY, B. C.	B401270521	50-400 Q
BOOKER, J. E.	B401270245	50-458 E	BRIGHT, Q. D.	B401200161	50-142 Q	BUCKLEY, B. C.	B401120541*	CONTRACT
BOOKER, J. E.	B401270332	50-458 B	BRIGHT, Q. D.	B401230403	50-440 Q	BUFE, J. L.	B401030077	50-302
BOOKER, J. E.	B401270339	50-458 B	BRIGHT, Q. D.	B401300237	50-142 Q	BUFE, J. L.	B401040248	50-302
BOOKER, J. E.	B401270503	50-458 B	BRIGHT, Q. D.	B401310156	50-142 Q	BUFE, J. L.	B401120395	50-302

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BUEFE, J. L.	8401120414	50-302 B	CARBIENER, R. E.	8401030276	50-302 S	CHILK, S. J.	8401200116	50-329 0
BUEFE, J. L.	8401230401	50-302 G	CARBIENER, R. E.	8401040143	50-302 S	CHILK, S. J.	8401200124	50-332 0
BUGNO, R. S.	8401050131*	CONTRACT	CARBIENER, R. E.	8401040314	50-302 S	CHILK, S. J.	8401200210*	COMMISSION
BUKHARI, H.	8401250134	NUREQ	CARBIENER, R. E.	8401050641	50-302 S	CHILK, S. J.	8401200214*	COMMISSION
BUNDY, H. F.	8401230523*	50-546 G	CARBIENER, R. E.	8401120419	50-302 S	CHILK, S. J.	8401230061*	50-289 P
BURDA, A. J.	8401230620*	FOIA	CARBIENER, R. E.	8401130160	50-302 S	CHILK, S. J.	8401230067*	50-289 P
BURDA, A. J.	8401230625*	FOIA	CARBIENER, R. E.	8401300323	50-302 S	CHILK, S. J.	8401230388	50-10 0
BURDOIN, J. F.	8401200193*	50-397 0	CARD, C. J.	8401130231	NUREQ	CHILK, S. J.	8401230427	50-289 0
BURGER, F. J.	8401170317	50-271 R	CARDARELLI, R. D.	8401300378*	70-754	CHILK, S. J.	8401230476	50-266 0
BURGER, J. F.	8401270221	50-319 0	CARDONE, T.	8401190291*	50-329 G	CHILK, S. J.	8401230482	50-312 0
BURRESS, B. L.	8401190286*	50-329 G	CAREY, J. J.	8401120403	50-334 R	CHILK, S. J.	8401240259	50-440 0
BURROGRAF, M. Q.	8401050085*	50-285 S	CAREY, J. J.	8401120413	50-334 0	CHILK, S. J.	8401240311	50-289 0
BURIAN, R. J.	8401120552	71-8957	CAREY, J. J.	8401160178	50-334 P	CHILK, S. J.	8401250268*	FOIA
BURKE, B. A.	8401240167	50-315 S	CAREY, J. J.	8401180129	50-334 F	CHILK, S. J.	8401250281*	FOIA
BURKE, B. A.	8401240202*	50-316 S	CAREY, J. J.	8401200043	50-334 J	CHILK, S. J.	8401260111	50-337 0
BURKE, D. J.	8401030447*	50-280 G	CAREY, J. J.	8401200073	50-334 V	CHILK, S. J.	8401260199	50-275 0
BURKE, D. J.	8401050517*	50-280 G	CAREY, J. J.	8401270228	50-334 R	CHILK, S. J.	8401260215	50-312 0
BURKE, D. J.	8401050681*	50-280 G	CARLSON, J.	8401030186	50-318 S	CHILK, S. J.	8401260219	50-443 0
BURKE, D. J.	8401240082*	50-280 G	CARNEY, J.	8401050558	50-265 S	CHILK, S. J.	8401270300	50-358 0
BURKEISTER, P. F.	8401240288	50-482 0	CARNEY, J.	8401270338	50-265 S	CHILK, S. J.	8401300104	50-440 0
BURNETT, P. T.	8401090262*	50-395 0	CARNEY, W.	8401110176	50-322 U	CHILK, S. J.	8401300116	50-289 P
BURNETT, R. F.	8401120167	70-1201	CARPENTER, J. H.	8401310262	50-400 0	CHILK, S. J.	8401300191	50-329 0
BURNHAM, J. B.	8401100088	NUREQ	CARR, A. V.	8401240296	50-413 0	CHILK, S. J.	8401310100	10CFR
BURNS, J. C.	8401240617*	50-286 F	CARROLL, D. Q.	8401300285*	50-296 P	CHILK, S. J.	8401310102	10CFR
BURR, J. R.	8401250366*	CONTRACT	CARTER, R. S.	8401130325	50-184 P	CHILK, S. J.	8401310226	50-289 0
BURR, L. H.	8401170221	50-482 0	CARUSO, R.	8401300028	50-206 0	CHILK, S. J.	8401310267	50-275 0
BURRESS, H. P.	8401240625*	0A999	CASE, E. G.	8401090425	50-416 0	CHIN, A.	8401040488*	0A999
BURRESS, H. P.	8401240629*	0A999	CASEY, L.	8401300049	WASTE MGT	CHIN, A.	8401040498*	0A999
BURSTEIN, S.	8401270045	50-266 P	CASHMELL, J. W.	8401310455*	WASTE MGT	CHINN, T. L.	8401240626*	50-259 F
BUSH, H. W.	8401200095	50-352 0	CATCHPOLE, G. J.	8401110383	40-8745	CHORA, D. K.	8401160443	NUREQ
BUTLER, T. A.	8401090113	50-537 E	CATON, B.	8401170956	WASTE MGT	CHOULES, N. C.	8401240426*	50-483 0
BYRD, R.	8401030215	50-416 S	CATTION, I.	8401250129	NUREQ	CHRISSEOTIMOS, N.	8401040380*	50-254 0
BYRD, R.	8401060312	50-416 S	CEBARE, J. G.	8401270264	50-416 R	CHRISSEOTIMOS, N.	8401190234*	50-263 0
BYRD, R.	8401060421	50-416 S	CHA, J. W.	8401100289*	50-324 P	CHRISTA-MARIA	8401260212	50-155 0
BYRD, R.	8401240160	50-416 S	CHACON, P. R.	8401180210	50-275 0	CHRISTEL, B.	8401130043	50-237 S
BYRD, R.	8401240455	50-416 S	CHAFFEE, A. E.	8401300151*	50-206 0	CHRISTEL, B.	8401300281	50-237 S
BYRD, R.	8401240491	50-416 S	CHAMBERLAIN, D.	8401240507*	50-458 0	CHRISTENSEN, D.	8401040016	FOIA
BYRD, R.	8401240018	50-416 S	CHAMBERS, G. T.	8401240502	50-260 S	CHRISTMAN, J. N.	8401310305	50-322 0
BYRD, R.	8401300179	50-416 S	CHANDLER, J. C.	8312160165	TOPREP	CHRISTMAN, J. N.	8401310305	50-322 0
BYRD, R.	8401300220	50-416 S	CHANDLER, J. C.	8401170169	TOPREP	CHRISTOFFERSON	8401120259	WASTE MGT
BYRD, R.	8401300234	50-416 S	CHANDLER, J. C.	8401180160	TOPREP	CHRISTOPHER, W.	8401260346	50-260 B
BYRD, R.	8401300284	50-416 S	CHANDLER, L. J.	8401040203	50-275 0	CHU, W.	8401250129	NUREQ
BYRD, R. W.	8401030194	50-416 S	CHANDLER, L. J.	8401120286	50-275 0	CHUNG, H. M.	8401160443	NUREQ
BYRD, R. W.	8401030233	50-416 S	CHANDLER, L. J.	8401250235	50-275 0	CHURCHILL, B. W.	8312200353	50-289 0
BYRNE, S. T.	8401200168*	50-336 P	CHANEY, H. D.	8401040570*	50-482 G	CHURCHILL, B. W.	8312200353	50-289 0
BYRON, P. M.	8401100005*	50-341 0	CHANG, K. C.	8401120135	WASTE MGT	CHURCHILL, B. W.	8312200359*	50-289 0
CAHILL, J. M.	8401200304	27-47	CHANG, T. Y.	8312220016*	REVIEW GRP	CHURCHILL, B. W.	8401200359*	50-289 0
CAHILL, W. J.	8401310241	50-458 C	CHANG, T. Y.	8401250008	REVIEW GRP	CHURCHILL, B. W.	8401120264	50-289 0
CAIN, C.	8401270167	40-299	CHAPLIN, S. D.	8401030129	50-320 S	CHURCHILL, B. W.	8401120264	50-289 0
CAIN, C. L.	8401040490*	40-4492	CHAPLIN, S. D.	8401240074	50-320 S	CHURCHILL, B. W.	8401120269*	50-289 0
CAIN, C. L.	8401040510*	40-299	CHAPMAN, L. D.	8401170033*	FOIA	CHURCHILL, B. W.	8401120269*	50-289 0
CAIN, C. L.	8401040514*	40-299	CHARNEY, J. B.	8401090555*	50-293 P	CHURCHILL, B. W.	8401120282*	50-289 0
CALDWELL, L. L.	8401230176	WASTE MGT	CHARNOFF, G.	8401040046*	CONTRACT	CHURCHILL, B. W.	8401160256	50-289 0
CALLIHAN, D.	8401230439	50-454 0	CHARNOFF, G.	8401230451	40-2061	CHURCHILL, B. W.	8401160256	50-289 0
CALBOYAS, C. D.	8401050027	50-206 P	CHARNOFF, G.	8401230451	40-2061	CHURCHILL, B. W.	8401160256	50-289 0
CALBOYAS, C. D.	8401170117	FOIA	CHARNOFF, G.	8401230452*	40-2061	CHURCHILL, B. W.	8401170231	50-289 0
CALVERT, M. B.	8401180216	50-413 0	CHARNOFF, G.	8401230452*	40-2061	CHURCHILL, B. W.	8401170231	50-289 0
CALVERT, M. B.	8401180216	50-413 0	CHASE, L.	8401270161	WASTE MGT	CHURCHILL, B. W.	8401170233	50-289 0
CALVERT, M. B.	8401180228*	50-413 0	CHASE, L.	8401300077	WASTE MGT	CHURCHILL, B. W.	8401170233	50-289 0
CALVERT, M. B.	8401180228*	50-413 0	CHASE, L.	8401300174	WASTE MGT	CHURCHILL, B. W.	8401170235*	50-289 0
CAMPAGNONE, M.	8401040065	50-352 A	CHASE, L.	8401310195*	WASTE MGT	CHURCHILL, B. W.	8401170255*	50-289 0
CAMPAGNONE, M. J.	8401170142	50-352 A	CHAUDHARY, S. K.	8401240604*	50-352 0	CHURCHILL, B. W.	8401180227	50-382 0
CAMPBELL, G. D.	8401170028	50-260 S	CHAUDHARY, S. K.	8401310384*	50-352 0	CHURCHILL, B. W.	8401180227	50-382 0
CAMPBELL, M.	8401030140*	FOIA	CHEN, S.	8304070498*	50-324 P	CHURCHILL, B. W.	8401200156	50-289 0
CAMPBELL, R.	8401240313*	50-354 0	CHIANG, N. J.	8401170006	50-400 S	CHURCHILL, B. W.	8401200156	50-289 0
CAMPE, K. M.	8401250154	50-352 T	CHILK, S. J.	8401030179	50-329 0	CHURCHILL, B. W.	8401260124	50-289 0
CAMPD, L. J.	8401180281*	50-322 T	CHILK, S. J.	8401050200	50-275 0	CHURCHILL, B. W.	8401260124	50-289 0
CANTER, H. L.	8401100413*	50-312 0	CHILK, S. J.	8401050243	50-275 0	CHURCHILL, B. W.	8401260190	50-289 0
CANTER, H. L.	8401300280*	50-312 0	CHILK, S. J.	8401050245	50-508 0	CHURCHILL, B. W.	8401260190	50-289 0
CANTRELL, F. B.	8401050472*	50-259 0	CHILK, S. J.	8401060275	50-312 0	CHURCHILL, B. W.	8401260202	50-289 0
CANTRELL, F. B.	8401050626*	50-348 0	CHILK, S. J.	8401060443	50-275 0	CHURCHILL, B. W.	8401260202	50-289 0
CANTRELL, F. B.	8401240004	50-259 S	CHILK, S. J.	8401090524	10CFR	CHURCHILL, B. W.	8401260207*	50-289 0
CANTRELL, F. B.	8401240359*	50-395 0	CHILK, S. J.	8401100164	50-266 0	CHURCHILL, B. W.	8401260207*	50-289 0
CANTRELL, F. B.	8401240364*	50-395 0	CHILK, S. J.	8401100201	50-289 0	CHURCHILL, B. W.	8401310218	50-289 0
CANTRELL, F. B.	8401240580*	50-348 0	CHILK, S. J.	8401110178	50-483 0	CHURCHILL, B. W.	8401310218	50-289 0
CANTRELL, F. B.	8401240606*	50-348 0	CHILK, S. J.	8401110183	50-275 0	CHURCHILL, B. W.	8401310258	50-289 0
CANTRELL, F. B.	8401260348	50-296 S	CHILK, S. J.	8401120239	50-358 0	CHURCHILL, B. W.	8401310258	50-289 0
CANTRELL, P. F.	8401270333	50-295 S	CHILK, S. J.	8401120243	50-312 0	CHURCHILL, B. W.	8401310329	50-289 0
CAPHTON, D. L.	8401180201*	50-352 0	CHILK, S. J.	8401160370*	FOIA	CHURCHILL, B. W.	8401310329	50-289 0
CAPHTON, D. L.	8401180224*	50-334 0	CHILK, S. J.	8401170222	50-266 0	CILIMBERG, R. L.	8401050300*	50-454 0
CAPHTON, D. L.	8401260369*	50-289 0	CHILK, S. J.	8401170227	50-440 0	CILLIS, M.	8401300258*	50-326 0
CAPHTON, D. L.	8401300274*	50-244 0	CHILK, S. J.	8401170236	50-275 0	CLARDY, L. S.	8401270469*	50-331 0
CAPHTON, D. L.	8401310166*	50-277 0	CHILK, S. J.	8401170474	10CFR	CLARK, A. T.	8401190418*	70-687
CARBAUGH, E. H.	8401130220	NUREQ	CHILK, S. J.	8401180243	50-289 0	CLARK, D.	8401050485	50-265 S
CARBIENER, R. E.	8401030236	50-302 S	CHILK, S. J.	8401190190	50-312 0	CLARK, D.	8401050500	50-265 S

PERSONAL AUTHOR INDEX

485

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLARK, D	8401050512	50-265 S	COLLINS, J T	8401040284	50-458 A	COOK, J W	8401050156	50-329 R
CLARK, D	8401050526	50-265 S	COLLINS, J T	8401040443	50-458 Q	COOK, J W	8401060500*	50-329 Q
CLARK, D E	8401310504	40-8064	COLLINS, J T	8401040448	40-299	COOK, J W	8401170184	50-329 S
CLARK, L	8401230609	FOIA	COLLINS, J T	8401040456*	40-299	COOK, J W	8401170212	50-329 S
CLARK, L	8401240395	50-20 F	COLLINS, J T	8401090484	TOPREP	COOK, J W	8401170430	50-329 S
CLARK, M J	8401270214*	GA999	COLLINS, J T	8401170387	50-482 Q	COOK, J W	8401170447	50-329 S
CLARK, P R	8401170174	50-289 P	COLLINS, J T	8401250237*	50-445 S	COOK, J W	8401190402	50-329 S
CLARK, P R	8401250279	50-320 P	COLLINS, J T	8401270004	50-299 P	COOK, J W	8401230331	50-329 S
CLARK, R	8401160014*	50-259 P	COLLINS, J T	8401270041	50-382 A	COOK, J W	8401230344	50-329 S
CLARK, R J	8401120524	50-259 P	COLLINS, J T	8401270144	50-285 P	COOK, J W	8401310026	50-329 R
CLARK, R J	8401240047	50-259 P	COLLINS, J T	8401270242	50-267 P	COOK, K W	8401040210	50-382 A
CLAYTON, F L	8401030123	50-364 S	COLLINS, J T	8401270263	50-382 Q	COOK, K W	8401040632*	50-382 F
CLAYTON, F L	8401040123	50-348 S	COLLINS, J T	8401270290	50-458 A	COOK, K W	8401050155	PR
CLAYTON, F L	8401040157	50-348 S	COLLINS, J T	8401270376	50-498 A	COOK, K W	8401200046	50-382 F
CLAYTON, F L	8401050448*	50-348 Q	COLLINS, J T	8401270409	50-445 A	COOK, K W	8401200308*	50-382 F
CLAYTON, F L	8401050606*	50-348 Q	COLLINS, J T	8401270420	50-313 P	COOK, K W	8401230421	50-382 E
CLAYTON, F L	8401060465	50-348 S	COLLINS, J T	8401270443	50-482 A	COOK, K W	8401300305	50-382 F
CLAYTON, F L	8401100390	50-348 S	COLLINS, J T	8401270472	GA999	COOK, K W	8401310325	50-382 E
CLAYTON, F L	8401160084	50-348 P	COLLINS, S	8401240126*	50-29 Q	COOK, R J	8401190286*	50-329 Q
CLAYTON, F L	8401170191	50-348 R	COLLINS, S J	8401040405*	50-333 Q	COOK, R J	8401230169	50-329 A
CLAYTON, F L	8401170197	50-364 R	COLLINS, S J	8401180211*	50-220 Q	COOK, R J	8401230497*	50-329 R
CLAYTON, F L	8401170235	50-348 P	COLLINS, T J	8401200107	40-7435	GOONEY, M J	8401030155	50-278 S
CLAYTON, F L	8401240263	50-348 S	COLLINS, W E	8401240200*	50-129 Q	GOONEY, M J	8401120360	50-277 S
CLAYTON, F L	8401240563*	50-348 Q	COLLINS, W E	8401240210*	50-129 Q	GOONEY, M J	8401160189	50-278 S
CLAYTON, F L	8401270125	50-348 Q	COLMAR, R	8401230657	NUREQ	GOONEY, M J	8401190404	50-277 R
CLAYTON, F L	8401300287	50-348 S	COLOMBO, R	8401130206	50-312 R	GOONEY, M J	8401260328	50-277 S
CLEMENTS, B. R.	8401230515	50-445 A	COLOMBO, R W	8401040144	50-312 S	GOOPER, M C	8401120328	50-328 S
CLEMENTS, W L	8401110213	50-289 Q	COLOMBO, R W	8401120353	50-312 S	COPELAND, V Q	8401310340	50-155 Q
CLEMENTS, W L	8401190439*	50-29 Q	COLOMBO, R W	8401160240	50-312 S	COPELAND, V Q	8401050241	50-155 Q
CLEWETT, J	8401300190	50-413 Q	COLOMBO, R W	8401160265	50-312 S	COPELAND, V Q	8401050241	50-155 Q
CLEWETT, J	8401300190	50-413 Q	COMBS, F. C.	8401040141*	FOIA	CORCORAN, J M	8401060357	50-352 Q
CLEWETT, J	8401300194*	50-413 Q	CONDR, R D	8401230157	MIBC	CORCORAN, J M	8401190170*	50-322 Q
CLEWETT, J	8401300194*	50-413 Q	CONE, T C	8401120005	WABTE MOT	CORNIER, W H	8401050233	50-142 Q
CLINE, W E	8401050492*	50-369 Q	CONLON, T E	8401050477*	50-259 Q	CORNIER, W H	8401050247	50-142 Q
COBB, Q H	8401250139*	70-712	CONLON, T E	8401050504*	50-400 Q	CORNIER, W H	8401160247	50-142 Q
COBB, Q H	8401250146*	40-1478	CONLON, T E	8401050610*	50-390 Q	CORNIER, W H	8401170304	50-142 Q
COCHRAN, P	8401050431	50-265 S	CONLON, T E	8401090502*	50-390 Q	CORNIER, W H	8401300425	50-142 Q
COFFEY, J A	8401120202	50-327 S	CONLON, T E	8401240039*	50-424 Q	CORNIER, W H	8401310348	50-142 Q
COFFEY, J A	8401120235	50-327 S	CONLON, T E	8401240332*	50-438 Q	CORNETTE, J. C.	8401060447*	40-8011
COFFEY, J A	8401120356	50-327 S	CONNAUGHTON, K	8401250037*	50-454 Q	COSTELLO, F	8401270146	NUREQ
COFFEY, J A	8401120386	50-328 S	CONNAUGHTON, K	8401310389*	50-454 Q	COTTER, B. F.	8401110204	50-358 Q
COFFEY, J A	8401130093	50-328 S	CONNER	8401300133	50-353 S	COTTER, B. F.	8401110211	50-344 Q
COFFEY, J A	8401130278	50-327 S	CONNER, E	8401100272*	50-289 Q	COTTER, B. F.	8401300232	50-293 Q
COFFEY, J A	8401170028	50-260 S	CONNER, E. L.	8401240604*	50-352 Q	COUNSIL, W Q	8401290178	50-423 K
COFFEY, J A	8401170198	50-328 S	CONNER, E. L.	8401310384*	50-352 Q	COUNSIL, W Q	8401290178	50-423 K
COFFEY, J A	8401240442	50-259 S	CONNER, T. B.	8401040295	50-352 Q	COUNSIL, W Q	84012300205	50-213 F
COFFEY, J A	8401240502	50-260 S	CONNER, T. B.	8401090502*	50-352 Q	COUNSIL, W Q	84012300205	50-213 F
COFFEY, J A	8401260038	50-328 S	CONNER, T. B.	8401040300*	50-352 Q	COUNSIL, W Q	84012300205	50-213 F
COFFEY, J A	8401260077	50-259 S	CONNER, T. B.	8401040300*	50-352 Q	COUNSIL, W Q	8401300143	50-213 P
COFFEY, J A	8401260138	50-259 S	CONNER, T. B.	8401060279	50-354 Q	COUNSIL, W Q	8401040086	50-245 P
COFFEY, J A	8401260321	50-328 S	CONNER, T. B.	8401060279	50-354 Q	COUNSIL, W Q	8401040086	50-245 P
COFFEY, J A	8401260346	50-260 S	CONNER, T. B.	8401090349	PR	COUNSIL, W Q	8401040173	50-213 P
COGURN, T. H.	8401100368	50-368 S	CONNER, T. B.	8401090349	PR	COUNSIL, W Q	8401040226	50-213 F
COHEN, I	8401030256*	50-289 Q	CONNER, T. B.	8401100136	50-354 Q	COUNSIL, W Q	8401050086*	50-213 F
COHEN, I	8401240476*	50-29 Q	CONNER, T. B.	8401100136	50-354 Q	COUNSIL, W Q	8401050265	50-423 V
COHEN, L	8401270146	NUREQ	CONNER, T. B.	8401100146	50-459 Q	COUNSIL, W Q	8401050273	50-423 A
COLBURN, T. Q.	8401110304	50-266 P	CONNER, T. B.	8401100146	50-459 Q	COUNSIL, W Q	8401050273	50-423 A
COLE, C N	8401050056*	FOIA	CONNER, T. B.	8401110208	50-354 Q	COUNSIL, W Q	8401050314	50-423 A
COLE, C N	8401050060*	FOIA	CONNER, T. B.	8401110208	50-354 Q	COUNSIL, W Q	8401050314	50-423 A
COLE, C N	8401050068*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401050071*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401050073*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401050091*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401050095*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401050143*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100090*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100102*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100105*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100107*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100111*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100116*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, C N	8401100118*	FOIA	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLE, R. F.	8401230439	50-494 Q	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLEY, W E	8401090337	PR	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLEY, J L	8401050338*	50-324 Q	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLEY, W. V.	8401200089*	50-261 Q	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLITZ, J. J.	8401270192*	50-289 P	CONNER, T. B.	8401110210	50-354 Q	COUNSIL, W Q	8401060043	50-423 A
COLLICA, C. J.	8401030076*	40-86	CONRAD, J. W.	8401040621	FOIA	COUNSIL, W Q	8401160174	50-423 S
COLLINS, D. J.	8401040430*	50-317 Q	CONTE, R.	8401100272*	50-289 Q	COUNSIL, W Q	8401170329	50-336 P
COLLINS, J. C.	8401190455	40-6659	CONWAY, J. T.	8401050222*	GA999	COUNSIL, W Q	8401170329	50-336 P
COLLINS, J. T.	8401040107	50-313 Q	CONWAY, J. T.	8401270431*	GA999	COUNSIL, W Q	8401170379	50-336 P
COLLINS, J. T.	8401040239	50-445 A	COOK, J.	8401130274	50-333 R	COUNSIL, W Q	8401170379	50-336 P
COLLINS, J. T.	8401040244	50-482 A	COOK, J. W.	8401040200	50-329 S	COUNSIL, W Q	8401170435	50-336 P
COLLINS, J. T.	8401040249	50-498 A	COOK, J. W.	8401040461	50-329 S	COUNSIL, W Q	8401170435	50-336 P
COLLINS, J. T.	8401040252	50-382 A	COOK, J. W.	8401040508	50-329 S	COUNSIL, W Q	8401180204	50-243 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COUNCIL, W. O.	8401180204	50-245 F	CRUTCHFIELD, D.	8401030164	50-213 P	CURTIS, N. W.	8401300217	50-388 A
COUNCIL, W. O.	8401180270*	50-245 G	CRUTCHFIELD, D.	8401030288	50-155 F	CURTIS, N. W.	8401310339	50-387 P
COUNCIL, W. O.	8401180270*	50-245 G	CRUTCHFIELD, D.	8401030336	50-206 F	CURTIS, R. H.	8401120098	MUREQ
COUNCIL, W. O.	8401200163	50-336 P	CRUTCHFIELD, D.	8401050303	50-409 P	CURTIS, R. H.	8401120098	MUREQ
COUNCIL, W. O.	8401200163	50-336 P	CRUTCHFIELD, D.	8401050313	50-155 P	CUTTER, A. B.	8401050615	50-261 P
COUNCIL, W. O.	8401200164	50-213 P	CRUTCHFIELD, D.	8401050425	50-29 P	CUTTER, A. B.	8401100373	50-261 F
COUNCIL, W. O.	8401200164	50-213 P	CRUTCHFIELD, D.	8401050427*	50-29 P	CUTTER, A. B.	8401200040	50-261 F
COUNCIL, W. O.	8401200164	50-213 P	CRUTCHFIELD, D.	8401050440*	50-29 P	CUTTER, A. B.	8401250261	50-324 P
COUNCIL, W. O.	8401230156	50-213 F	CRUTCHFIELD, D.	8401060190	50-155 P	CUTTER, A. B.	8401300184	50-400 A
COUNCIL, W. O.	8401230175	50-423 K	CRUTCHFIELD, D.	8401060196*	50-155 P	CUTTER, A. B.	8401310236	50-261 P
COUNCIL, W. O.	8401230175	50-423 K	CRUTCHFIELD, D.	8401090492	50-206 P	D'ANGELO, A.	8401300151*	50-204 G
COUNCIL, W. O.	8401230178	50-245 F	CRUTCHFIELD, D.	8401100409	50-249 P	DAEMEN, J. J.	8401160434	MUREQ
COUNCIL, W. O.	8401230178	50-245 F	CRUTCHFIELD, D.	8401100415*	50-249 P	DAHLMAN, L. C.	8401170355*	50-282 G
COUNCIL, W. O.	8401230286	50-213 P	CRUTCHFIELD, D.	8401100449	50-213 F	DAHLMAN, L. C.	8401200085*	50-282 G
COUNCIL, W. O.	8401230323	50-423 A	CRUTCHFIELD, D.	8401160125	50-219 P	DALE, L. F.	8401030083	50-416 S
COUNCIL, W. O.	8401230323	50-423 A	CRUTCHFIELD, D.	8401160134*	50-219 P	DALE, L. F.	8401030194	50-416 S
COUNCIL, W. O.	8401230373	50-213 P	CRUTCHFIELD, D.	8401160187	50-155 P	DALE, L. F.	8401030215	50-416 S
COUNCIL, W. O.	8401230373	50-213 P	CRUTCHFIELD, D.	8401160203*	50-155 P	DALE, L. F.	8401030320	50-416 S
COUNCIL, W. O.	8401230467	50-423 F	CRUTCHFIELD, D.	8401160216	50-237 P	DALE, L. F.	8401030323	50-416 S
COUNCIL, W. O.	8401230467	50-423 F	CRUTCHFIELD, D.	8401160221	50-213 P	DALE, L. F.	8401060312	50-416 S
COUNCIL, W. O.	8401230664*	50-213 F	CRUTCHFIELD, D.	8401160280	50-219 P	DALE, L. F.	8401060325	50-416 S
COUNCIL, W. O.	8401260324*	50-245 F	CRUTCHFIELD, D.	8401180087	50-219 P	DALE, L. F.	8401060421	50-416 S
COUNCIL, W. O.	8401270208	50-423 S	CRUTCHFIELD, D.	8401180146	50-219 P	DALE, L. F.	8401060456	50-416 K
COUNCIL, W. O.	8401300171	50-245 P	CRUTCHFIELD, D.	8401180195	50-29 G	DALE, L. F.	8401060477	50-416 S
COUNCIL, W. O.	8401300171	50-245 P	CRUTCHFIELD, D.	8401190120	50-255 F	DALE, L. F.	8401090380*	50-416 G
COUNCIL, W. O.	8401300339*	50-213 F	CRUTCHFIELD, D.	8401190262	50-219 P	DALE, L. F.	8401100336	50-416 P
COUNCIL, W. O.	8401310023	50-336 P	CRUTCHFIELD, D.	8401190409	50-255 P	DALE, L. F.	8401100371	50-416 P
COUNCIL, W. O.	8401310023	50-336 P	CRUTCHFIELD, D.	8401190429	50-155 P	DALE, L. F.	8401100411	50-416 S
COUNTS, M.	8401050111*	50-395 F	CRUTCHFIELD, D.	8401190459	50-206 P	DALE, L. F.	8401130240	50-416 P
COUNTS, M.	8401250318*	50-395 F	CRUTCHFIELD, D.	8401200113	50-244 P	DALE, L. F.	8401180079	50-416 V
COURTER, J.	8208010037*	FOIA	CRUTCHFIELD, D.	8401240397	50-255 P	DALE, L. F.	8401200157	50-416 P
COURTER, J.	8401060391	50-289 U	CRUTCHFIELD, D.	8401250040	50-237 P	DALE, L. F.	8401240160	50-416 S
COWAN, B. Z.	8401050236	PR	CRUTCHFIELD, D.	8401250179	50-237 P	DALE, L. F.	8401240383	50-416 S
COWIE, D. J.	8401200318	FOIA	CRUTCHFIELD, D.	8401260013	50-237 P	DALE, L. F.	8401240450	50-416 S
COWE, E. J.	8401110387	40-4492	CRUTCHFIELD, D.	8401270101	50-255 P	DALE, L. F.	8401240453	50-416 S
COZENS, O.	8401060008	50-187 R	CRUTCHFIELD, D.	8401270198	50-213 P	DALE, L. F.	8401240491	50-416 S
CRAIG, J.	8401120380	50-324 S	CRUTCHFIELD, D.	8401270216	50-206 P	DALE, L. F.	8401250023	50-416 P
CRANDALL, C. B.	8401030117*	40-86	CRUTCHFIELD, D.	8401270235	50-219 P	DALE, L. F.	8401250290	50-416 P
CRANE, P. A.	8401110230	50-275 J	CRUTCHFIELD, D.	8401270286	50-29 P	DALE, L. F.	8401250295	50-416 P
CRANE, P. A.	8401170297	50-275 T	CRUTCHFIELD, D.	8401270479	50-219 P	DALE, L. F.	8401260018	50-416 S
CRANE, P. A.	8401260076	50-275 J	CRUTCHFIELD, D.	8401270487*	50-219 P	DALE, L. F.	8401260031	50-416 S
CRANE, P. A.	8401300214	50-275 Q	CRUTCHFIELD, D.	8401300156	50-255 P	DALE, L. F.	8401260088	50-416 S
CREED, J. R.	8401040480*	50-483 Q	CULLEN, D. P.	8401300401	50-302 S	DALE, L. F.	8401260286*	50-416 F
CREED, J. R.	8401100434*	50-454 Q	CUMMINGS, J. J.	8401230023*	FOIA	DALE, L. F.	8401260338	50-416 S
CREED, J. R.	8401300008*	50-409 Q	CUMMINGS, J. J.	8401230030*	50-280 P	DALE, L. F.	8401270264	50-416 R
CRLENJAK, R. V.	8401240397*	50-321 Q	CUMMINGS, J. J.	8401250117*	FOIA	DALE, L. F.	8401300175	50-416 S
CROCKER, H. W.	8401030256*	50-289 Q	CUNNINGHAM, O. E.	8401110384	70-754	DALE, L. F.	8401300179	50-416 S
CROCKER, H. W.	8401100308*	50-309 Q	CUNNINGHAM, O. H.	8401250205	50-454 A	DALE, L. F.	8401300220	50-416 S
CROCKER, H. W.	8401100400*	50-272 Q	CUNNINGHAM, O. H.	8401250327	50-445 Q	DALE, L. F.	8401300239	50-416 S
CROCKER, H. W.	8401240457*	50-289 Q	CUNNINGHAM, O. H.	8401300221	50-445 Q	DALE, L. F.	8401300263	50-416 S
CROCKER, H. W.	8401240476*	50-29 Q	CUNNINGHAM, M. E.	8401310449	MUREQ	DALE, L. F.	8401300284	50-416 S
CROSS, J. B.	8401060171*	50-416 F	CUDHO, H. M.	8401170150	50-322 Q	DALTRUFF, E. L.	8401240244	50-352 A
CROSSMAN, W. A.	8401040192*	50-382 Q	CUDHO, H. M.	8401180198	50-322 Q	DALTRUFF, S. L.	8401100291	50-277 P
CROSSMAN, W. A.	8401040460*	50-456 Q	CURNANE, R. A.	8401240634*	QA999	DALTRUFF, S. L.	8401170204	50-277 P
CROSSMAN, W. A.	8401040359*	50-498 Q	CURNANE, R. A.	8401240639*	QA999	DALTRUFF, S. L.	8401190328	50-277 F
CROSSMAN, W. A.	8401100327	50-498 S	CURNANE, R. A.	8401240641*	QA999	DALTRUFF, S. L.	8401230173	50-277 F
CROSSMAN, W. A.	8401100375	50-498 S	CURNANE, R. A.	8401240643*	QA999	DALTRUFF, S. L.	8401240201	50-277 G
CROSSMAN, W. A.	8401230160*	50-458 Q	CURNANE, R. A.	8401240644*	QA999	DALTRUFF, S. L.	8401240456	50-352 A
CROSSMAN, W. A.	8401240307*	50-458 Q	CURNANE, R. A.	8401240646*	QA999	DALTRUFF, S. L.	8401250644*	50-277 F
CROSSMAN, W. A.	8401270003*	50-498 Q	CURRAN, D.	8401110171	50-443 Q	DALTRUFF, S. L.	8401250234	50-352 F
CROSSMAN, W. A.	8401270282*	50-382 Q	CURRAN, D.	8401110171	50-443 Q	DALTRUFF, S. L.	8401270236	50-278 Q
CROUSE, R. P.	8401040366	50-346 F	CURRAN, D.	8401200105	50-443 Q	DALTRUFF, S. L.	8401270474	50-277 P
CROUSE, R. P.	8401030275	50-346 F	CURRAN, D.	8401200105	50-443 Q	DALTRUFF, S. L.	8401310153	50-277 P
CROUSE, R. P.	8401170351	50-346 P	CURRAN, J. M.	8401040590	50-361 Q	DALTRUFF, S. L.	8401310272*	50-277 Q
CROUSE, R. P.	8401230483	50-346 P	CURRAN, J. M.	8401240151*	50-206 P	DANCE, H. C.	8401040279	50-280 Q
CROUSE, R. P.	8401240327*	50-346 Q	CURTIS, N. W.	8401030144	50-388 A	DANCE, H. C.	8401050267*	50-424 G
CROUSE, R. P.	8401240477*	50-346 Q	CURTIS, N. W.	8401030202	50-387 S	DANCE, H. C.	8401050327	50-369 Q
CROUSE, R. P.	8401270293	50-346 P	CURTIS, N. W.	8401040142	50-388 A	DANCE, H. C.	8401050379	50-335 Q
CROUSE, R. P.	8401270390	50-346 P	CURTIS, N. W.	8401090367	50-388 A	DANCE, H. C.	8401050387*	50-335 Q
CROUSE, R. P.	8401270394*	50-346 P	CURTIS, N. W.	8401090396	50-387 P	DANCE, H. C.	8401050444	50-280 Q
CROW, W. T.	8312150273*	70-398	CURTIS, N. W.	8401090407*	50-387 P	DANCE, H. C.	8401050473	50-280 Q
CROW, W. T.	8401090779*	70-1113	CURTIS, N. W.	8401090511	50-388 A	DANCE, H. C.	8401050483*	50-280 Q
CROW, W. T.	8401170494	70-143	CURTIS, N. W.	8401100252	50-387 P	DANCE, H. C.	8401050486	50-369 Q
CROW, W. T.	8401190102*	70-2944	CURTIS, N. W.	8401160094	50-388 S	DANCE, H. C.	8401050498*	50-280 Q
CROW, W. T.	8401200061*	70-36	CURTIS, N. W.	8401160101	50-387 P	DANCE, H. C.	8401050522	50-280 Q
CROW, W. T.	8401300091*	40-8231	CURTIS, N. W.	8401160151	50-388 S	DANCE, H. C.	8401050545	50-369 Q
CROW, W. T.	8401310342*	70-2985	CURTIS, N. W.	8401160158	50-388 S	DANCE, H. C.	8401050555	50-338 Q
CROWLEY, B. R.	8401090201*	50-351 Q	CURTIS, N. W.	8401160165	50-388 S	DANCE, H. C.	8401050557	50-338 Q
CRUDEN, D. S.	8401040282	50-358 V	CURTIS, N. W.	8401160215	50-387 E	DANCE, H. C.	8401050588*	50-338 Q
CRUNKLETON, J.	8401160131	50-319 S	CURTIS, N. W.	8401230418	50-387 F	DANCE, H. C.	8401050594*	50-338 Q
CRUTCHFIELD, D.	8310070199*	50-443 F	CURTIS, N. W.	8401240435	50-387 P	DANCE, H. C.	8401050621	50-321 Q
CRUTCHFIELD, D.	8312140824	50-237 P	CURTIS, N. W.	8401250131	50-387 P	DANCE, H. C.	8401050653	50-280 Q
CRUTCHFIELD, D.	8312140235*	50-237 P	CURTIS, N. W.	8401260323	50-388 S	DANCE, H. C.	8401050660	50-424 Q
CRUTCHFIELD, D.	8312140237*	50-237 P	CURTIS, N. W.	8401270210	50-388 S	DANCE, H. C.	8401050665	50-413 Q
CRUTCHFIELD, D.	8401030068	50-219 P	CURTIS, N. W.	8401270301	50-387 F	DANCE, H. C.	8401060301	50-413 Q

PERSONAL AUTHOR INDEX

487

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DANCE, H. C.	8401060353	50-413 V	DENTON, H. R.	8401130120	50-266 F	DIETZ, C. R.	8401060426*	50-324 G
DANCE, H. C.	8401060422	50-280 F	DENTON, H. R.	8401160472*	FOIA	DIETZ, C. R.	8401100161	50-324 R
DANCE, H. C.	8401060446	50-321 F	DENTON, H. R.	8401170518	50-320 U	DIETZ, C. R.	8401110233	50-324 R
DANCE, H. C.	8401060457	50-335 V	DENTON, H. R.	8401170524	REVIEW GRP	DIETZ, C. R.	8401130255	50-325 B
DANCE, H. C.	8401060499	50-321 V	DENTON, H. R.	8401170561*	50-397 P	DIETZ, C. R.	8401170132	50-325 B
DANCE, H. C.	8401090041	50-338 G	DENTON, H. R.	8401180018	50-362 P	DIETZ, C. R.	8401230283	50-325 B
DANCE, H. C.	8401090099	50-369 G	DENTON, H. R.	8401180023*	50-362 P	DIETZ, C. R.	8401230406	50-324 B
DANCE, H. C.	8401090193	50-321 G	DENTON, H. R.	8401180031	50-528 A	DIETZ, C. R.	8401240003	50-324 B
DANCE, H. C.	8401090208	50-335 G	DENTON, H. R.	8401180037*	50-528 A	DIETZ, C. R.	8401240010	50-325 B
DANCE, H. C.	8401090216	50-269 G	DENTON, H. R.	8401190004*	50-374 P	DIETZ, C. R.	8401240070	50-324 B
DANCE, H. C.	8401090225	50-270 G	DENTON, H. R.	8401250440	MISC	DIETZ, C. R.	8401240166	50-324 B
DANCE, H. C.	8401090246	50-335 G	DENTON, H. R.	8401260087	50-362 P	DIETZ, C. R.	8401240498*	50-324 G
DANCE, H. C.	8401090420	50-302 G	DENTON, H. R.	8401260093*	50-362 P	DIETZ, C. R.	8401250172	50-324 R
DANCE, H. C.	8401090472*	50-424 G	DENTON, H. R.	8401310091	MISC	DIETZ, C. R.	8401260019	50-325 B
DANCE, H. C.	8401240075	50-280 G	DERXB, P. S.	8401170374	50-133 R	DIETZ, C. R.	8401260039	50-325 B
DANCE, H. C.	8401240084	50-424 G	DEVINCENIS, J.	8312200113	50-443 B	DIETZ, C. R.	8401260351	50-325 B
DANCE, H. C.	8401240243	50-250 G	DEVINCENIS, J.	8312200113	50-443 B	DIOGOS, R. M.	8401190126	50-213 P
DANCE, H. C.	8401240265*	50-250 G	DEVINCENIS, J.	8401100207	50-443 E	DIOGOS, R. M.	8401190145	50-344 P
DANCE, H. C.	8401240351	50-413 G	DEVINCENIS, J.	8401100207	50-443 E	DIOGOS, R. M.	8401190231	50-309 P
DANCE, H. C.	8401240354*	50-369 G	DEVINCENIS, J.	8401100328*	50-443 G	DIONAN, T. G.	8401030109	50-443 G
DANCE, H. C.	8401240371*	50-369 G	DEVINCENIS, J.	8401100328*	50-443 G	DIONAN, T. G.	8401230382	50-443 G
DANCE, H. C.	8401240438	50-335 G	DEVINCENIS, J.	8401110287	50-443 A	DIONAN, T. G.	8401230382	50-443 G
DANCE, H. C.	8401240477	50-281 G	DEVINCENIS, J.	8401110287	50-443 A	DIONAN, T. G.	8401230423	50-443 G
DANCE, H. C.	8401240497*	50-281 G	DEVINCENIS, J.	8401170343	50-443 A	DIONAN, T. G.	8401230423	50-443 G
DANCE, H. C.	8401240551	50-338 G	DEVINCENIS, J.	8401170343	50-443 A	DIONAN, T. G.	8401230423	50-443 G
DANCE, H. C.	8401240607	50-413 G	DEVINCENIS, J.	8401230343	50-443 A	DIANNI, D. C.	8401110188	50-282 P
DANCE, H. C.	8401310308	50-413 G	DEVINCENIS, J.	8401230343	50-443 A	DILLENBACK, J. R.	8401230576*	50-220 F
DANIELSON, D. H.	8401050300*	50-434 G	DEVINCENIS, J.	8401230494	50-443 F	DINITZ, I.	8401090031	70-2964
DANIELSON, D. H.	8401100486*	50-282 G	DEVINCENIS, J.	8401230494	50-443 F	DINITZ, I.	8401090037	50-374 J
DANIELSON, D. H.	8401230382*	50-409 G	DEVINE, T.	8401250282	50-358 G	DINITZ, I.	8401090083	50-397 J
DARMITZEL, R. W.	8401310239*	50-70 G	DEVINE, T.	8401050609*	50-358 A	DIRCKS, W.	8401030086*	40-86
DAUGHTERY, L. F.	8401240450	50-416 B	DEVINE, T.	8401230390	50-358 G	DIRCKS, W.	8401030397*	50-275 E
DAUGHTERY, L. F.	8401300175	50-416 B	DEVINE, T.	8401230390	50-358 G	DIRCKS, W. J.	8401160379*	FOIA
DAUGHTERY, L. F.	8401300239	50-416 B	DEVINE, T.	8401230589*	50-358 G	DIRCKS, W. J.	8401250283*	50-320 B
DAUGHTERY, L. F.	8401300263	50-416 B	DEVINE, T.	8401230589*	50-358 G	DIRCKS, W. J.	8203040434*	FOIA
DAUGHTERY, L. F.	8401300284	50-416 B	DEVINE, T.	8401230600*	50-358 G	DIRCKS, W. J.	8203050072*	FOIA
DAVENPORT, J. H.	8401110222	WASTE MGT	DEVINE, T.	8401230600*	50-358 G	DIRCKS, W. J.	8203050106*	FOIA
DAVENPORT, J. H.	8401110222	WASTE MGT	DEWEY, L. S.	8401250159	50-354 G	DIRCKS, W. J.	8203050118*	50-293 P
DAVENPORT, K. E.	8401240517*	50-281 G	DEWEY, L. S.	8401250175	50-329 G	DIRCKS, W. J.	8203110330*	FOIA
DAVIS, J. Q.	8401030021*	40-86	DEYOUNG, R. C.	8401200077	50-329 G	DIRCKS, W. J.	8203120423*	50-275 P
DAVIS, J. Q.	8401270169	WASTE MGT	DEYOUNG, R. C.	8208110023*	FOIA	DIRCKS, W. J.	8203180400*	50-289 P
DAVIS, J. M.	8401120265	WASTE MGT	DEYOUNG, R. C.	8303090323*	FOIA	DIRCKS, W. J.	8203240020*	FOIA
DAVIS, J. M.	8401120265	WASTE MGT	DEYOUNG, R. C.	8305160338*	FOIA	DIRCKS, W. J.	8204050459*	FOIA
DAVIS, L. A.	8401170537*	CONTRACT	DEYOUNG, R. C.	8306280028*	50-266 F	DIRCKS, W. J.	8204080204*	50-244 P
DAVIS, L. A.	8401170549*	CONTRACT	DEYOUNG, R. C.	8312070443	50-321 G	DIRCKS, W. J.	8204220088*	FOIA
DAVIS, M. J.	8401050447*	50-280 G	DEYOUNG, R. C.	8312120090	50-3 G	DIRCKS, W. J.	8204300109*	50-135 P
DAVIS, M. J.	8401050517*	50-280 G	DEYOUNG, R. C.	8312270197*	50-352 A	DIRCKS, W. J.	8205050087*	50-289 P
DAVIS, M. J.	8401050681*	50-280 G	DEYOUNG, R. C.	8401030290*	50-358 A	DIRCKS, W. J.	8205050098*	FOIA
DAVIS, M. J.	8401240082*	50-280 G	DEYOUNG, R. C.	8401030424	50-397 A	DIRCKS, W. J.	8205050499*	FOIA
DAVIS, P.	8401310349	50-289 H	DEYOUNG, R. C.	8401040001	50-269 G	DIRCKS, W. J.	8205050587*	50-235 P
DAVIS, R. E.	8401130224	50-10 P	DEYOUNG, R. C.	8401160474*	FOIA	DIRCKS, W. J.	8205070412*	FOIA
DAWSON, D. M.	8401200130	70-1308	DEYOUNG, R. C.	8401170101*	FOIA	DIRCKS, W. J.	8205270663*	50-272 P
DEAGAZIO, A.	8401190100	50-346 F	DEYOUNG, R. C.	8401170104*	FOIA	DIRCKS, W. J.	8206110014*	50-289 P
DEAGAZIO, A. W.	8401230035	50-346 P	DEYOUNG, R. C.	8401170108*	FOIA	DIRCKS, W. J.	8206110164*	50-244 P
DEARASIS, M.	8401230597	FOIA	DEYOUNG, R. C.	8401170114*	FOIA	DIRCKS, W. J.	8206300059*	50-289 P
DEATON, C. M.	8401120298	WASTE MGT	DEYOUNG, R. C.	8401190183	50-358 G	DIRCKS, W. J.	8207230676*	FOIA
DEBS, B. T.	8401080655*	50-259 G	DEYOUNG, R. C.	8401190197*	50-358 G	DIRCKS, W. J.	8208060142*	FOIA
DECKER, T. R.	8401090264*	50-259 G	DEYOUNG, R. C.	8401190203*	50-358 G	DIRCKS, W. J.	8208230483*	FOIA
DELANEY, C. E.	8401080295	50-272 G	DEYOUNG, R. C.	8401230225	50-440 Q	DIRCKS, W. J.	8209010239*	FOIA
DELANEY, C. E.	8401240161	50-272 G	DEYOUNG, R. C.	8401230230*	50-440 Q	DIRCKS, W. J.	8209160068*	50-275 P
DELANEY, C. E.	8401250196	50-272 G	DEYOUNG, R. C.	8401230234*	50-440 Q	DIRCKS, W. J.	82092200347*	50-289 P
DELBELLO, A. B.	8401050316*	50-247 F	DEYOUNG, R. C.	8401300082	50-382 A	DIRCKS, W. J.	82092300377*	FOIA
DELBELLO, A. B.	8401200218*	COMMISSION	DEYOUNG, R. C.	8401310128	MISC	DIRCKS, W. J.	8209230146*	FOIA
DELBELLA, P. V.	8401250259	PR	DEYOUNG, R. C.	8401310441	50-344 Q	DIRCKS, W. J.	8210270322*	FOIA
DELGORDGE, L.	8401100219*	50-454 G	DHIR, V. K.	8401250129	NUREG	DIRCKS, W. J.	8210270322*	FOIA
DELGORDGE, L. O.	8401230426	50-454 G	DICHTER, J. R.	8401310244	50-424 G	DIRCKS, W. J.	8211020259*	50-244 P
DELLA, W. S.	8401250324*	50-390 F	DIEDERICH, G. J.	8401030437	50-373 B	DIRCKS, W. J.	8211090006*	FOIA
DELLA RATTIA, A.	8401260315*	70-135	DIEDERICH, G. J.	8401060268	50-373 B	DIRCKS, W. J.	8211190003*	FOIA
DELLA RATTIA, A.	8401310097*	70-687	DIEDERICH, G. J.	8401060404	50-373 B	DIRCKS, W. J.	8301060498*	50-395 F
DELMEDICO, J.	8401050065*	FOIA	DIEDERICH, G. J.	8401220213	50-373 R	DIRCKS, W. J.	8301070135*	FOIA
DELMEDICO, J.	8401050088*	FOIA	DIEDERICH, G. J.	8401130290	50-373 B	DIRCKS, W. J.	8301070155*	50-289 P
DELMEDICO, J.	8401100078*	FOIA	DIEDERICH, G. J.	8401130341	50-373 B	DIRCKS, W. J.	8301070163*	50-289 P
DELOATCH, V.	8401100092	CONTRACT	DIEDERICH, G. J.	8401160261	50-373 B	DIRCKS, W. J.	8303110418*	50-395 F
DELOATCH, V.	8401130444	CONTRACT	DIEDERICH, G. J.	8401170402	50-373 R	DIRCKS, W. J.	8304050312*	50-280 F
DENISON, E.	8401110053	50-275 R	DIEDERICH, G. J.	8401230404	50-373 B	DIRCKS, W. J.	8305160182*	50-483 F
DENISON, E.	8401110058*	50-275 R	DIETZ, C. R.	8401030062	50-325 B	DIRCKS, W. J.	8305160329*	50-438 P
DENNIS, N.	8401040356	40-6920	DIETZ, C. R.	8401030145	50-325 B	DIRCKS, W. J.	8305170230*	FOIA
DENTON, H. R.	8308180433*	FOIA	DIETZ, C. R.	8401030190	50-325 B	DIRCKS, W. J.	8305260362*	50-245 F
DENTON, H. R.	8312300202	REVIEW GRP	DIETZ, C. R.	8401030248	50-324 B	DIRCKS, W. J.	8306020457*	50-344 F
DENTON, H. R.	8401030286	NUREG	DIETZ, C. R.	8401030257	50-325 B	DIRCKS, W. J.	8306030153*	50-309 F
DENTON, H. R.	8401060531	MISC	DIETZ, C. R.	8401030271	50-324 B	DIRCKS, W. J.	8306030404*	50-346 F
DENTON, H. R.	8401090390	50-482 A	DIETZ, C. R.	8401030327	50-325 B	DIRCKS, W. J.	8306150117*	50-266 F
DENTON, H. R.	8401090398*	50-482 A	DIETZ, C. R.	8401040315	50-325 B	DIRCKS, W. J.	8306170082*	FOIA
DENTON, H. R.	8401110181	50-295 F	DIETZ, C. R.	8401050438	50-325 B	DIRCKS, W. J.	8306210319*	50-382 F
DENTON, H. R.	8401110392	NUREG	DIETZ, C. R.	8401060361	50-325 B	DIRCKS, W. J.	8312130434	SECY

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DIRCKS, W. J.	B312270074*	50-205 P	DOUGHERTY, J. B	8401050202	50-322 Q	EDGAR, G. L.	8401110297	50-337 Q
DIRCKS, W. J.	8401030027*	40-B6	DOUGLASS, R. M.	8401180240	50-317 P	EDGAR, G. L.	8401110297	50-337 Q
DIRCKS, W. J.	8401030029*	40-B6	DOVE, K.	8401040604	FOIA	EDGAR, G. L.	8401170271	50-70 Q
DIRCKS, W. J.	8401030049*	40-B6	DOWNING, G.	8401310070*	50-344 F	EDGAR, G. L.	8401170271	50-70 Q
DIRCKS, W. J.	8401030096*	40-B6	DOYLE, C.	8401300333*	50-344 F	EDGAR, G. L.	8401170286*	50-70 Q
DIRCKS, W. J.	8401030103*	40-B6	DRAKE, M.	8401090266	PR	EDGAR, G. L.	8401310235	50-70 Q
DIRCKS, W. J.	8401030125*	40-B6	DRISKILL, D. D.	8401050152*	GA999	EDGAR, G. L.	8401310235	50-70 Q
DIRCKS, W. J.	8401040017	50-358 R	DRUGA, R. J.	8401030240	50-334 S	EDGEWORTH, P.	8401190354	CONTRACT
DIRCKS, W. J.	8401050192*	FOIA	DRUGA, R. J.	8401120228	50-334 S	EDGEWORTH, P.	8401270531	CONTRACT
DIRCKS, W. J.	8401060169*	SECY	DRUGA, R. J.	8401120313	50-334 S	EDGEWORTH, P.	8401300010	CONTRACT
DIRCKS, W. J.	8401110217*	50-289 Q	DRUGA, R. J.	8401270148	50-334 S	EDINGER, J. E.	8401100353*	50-483 A
DIRCKS, W. J.	8401130474	50-289 P	DUBOIS, D.	8401090173	XPORTLIC	EDISON, R. D.	8401240329*	50-390 Q
DIRCKS, W. J.	8401170142*	FOIA	DUBOIS, D.	8401160050	XPORTLIC	EDLER, S. K.	8401190250	NJREQ
DIRCKS, W. J.	8401200225	SECY	DUBOIS, D. L.	8401090133*	50-298 Q	EDMONSON, L. R.	8401300012*	CONTRACT
DIRCKS, W. J.	8401230070*	50-289 P	DUBRY, N. E.	8401190412*	50-315 Q	EDGAR, K.	8401230363	50-382 K
DIRCKS, W. J.	8401230079*	50-289 P	DUDLEY, N.	8401300286*	50-443 Q	EICHENHOLZ, H.	8401240126*	50-29 Q
DIRCKS, W. J.	8401230103	SECY	DUDLEY, R. F.	8401300173	50-409 P	EISENHUT, D. Q.	8003130530*	FOIA
DIRCKS, W. J.	8401240111	PR	DUFFY, B.	8401170251	50-336 S	EISENHUT, D. Q.	8001230101*	FOIA
DIRCKS, W. J.	8401240133	SECY	DUFFY, C. J.	84010100242*	WASTE MOT	EISENHUT, D. Q.	8003130526*	FOIA
DIRCKS, W. J.	8401250241*	50-312 F	DUGGIN, Q. E.	8401120235	50-327 B	EISENHUT, D. Q.	8309120493	50-361 P
DIRCKS, W. J.	8401250311*	50-289 P	DUGGIN, Q. E.	8401260038	50-328 S	EISENHUT, D. Q.	8310110265*	ACRS
DIRCKS, W. J.	8401250320*	PR	DUGSTAD, D.	8401120240	50-282 R	EISENHUT, D. Q.	8312080191	MTSC
DIRCKS, W. J.	8401250325*	50-255 P	DUGSTAD, D.	8401270452	50-282 R	EISENHUT, D. Q.	8401210094	50-358 A
DIRCKS, W. J.	8401250359*	FOIA	DUKE, B. T.	8401060067*	50-259 P	EISENHUT, D. Q.	8312120093	50-275 E
DIRCKS, W. J.	8401250370*	50-219 P	DUMONT, W. H.	8401030117*	40-B6	EISENHUT, D. Q.	8312120101	50-322 A
DIRCKS, W. J.	8401250385*	FOIA	DUNAWAY, F. R.	8401190449*	50-295 Q	EISENHUT, D. Q.	8312120108	50-247 P
DIRCKS, W. J.	8401270006	50-416 P	DUNAB, W. J.	8401230412	50-266 J	EISENHUT, D. Q.	8312120112	50-358 Q
DIRCKS, W. J.	8401300085	50-358 R	DUNLAP, J. M.	8401100470*	50-333 Q	EISENHUT, D. Q.	8312120120	50-275 R
DIRCKS, W. J.	8401310169*	50-275 U	DUNLAP, J. M.	8401190384*	50-220 Q	EISENHUT, D. Q.	8312120123	50-275 P
DISE, D. P.	8401100381*	50-410 Q	DUNLAP, J. M.	8401240521*	50-247 Q	EISENHUT, D. Q.	8312120126	PR
DISE, D. P.	8401180226	50-220 P	DUPREE, D. C.	8401270481	50-327 R	EISENHUT, D. Q.	8312120127	50-358 A
DISE, D. P.	8401180229*	50-220 P	DURR, J.	8401240318*	50-412 Q	EISENHUT, D. Q.	8312190363	50-3 P
DISE, D. P.	8401190373*	50-410 Q	DURR, J. P.	8401100372*	50-352 Q	EISENHUT, D. Q.	84012050310*	50-409 P
DISPIONO, V. W.	8401040146	FOIA	DURR, J. P.	8401100389*	50-388 Q	EISENHUT, D. Q.	8401050319*	50-155 P
DIXON, G. W.	8401030207	50-395 F	DURR, J. P.	8401180248*	50-352 Q	EISENHUT, D. Q.	8401050382	50-3 P
DIXON, G. W.	8401040399	50-395 S	DUS, R.	8401060404	50-373 S	EISENHUT, D. Q.	8401090163	50-275 E
DIXON, G. W.	8401040542	50-395 S	DWYER, B. J.	8401060391	50-289 U	EISENHUT, D. Q.	8401090221	50-3 P
DIXON, G. W.	8401040578	50-395 Q	DYNNER, A. R.	8401310284	50-322 Q	EISENHUT, D. Q.	8401090531	MTSC
DIXON, G. W.	8401040593	50-395 P	DYNNER, A. R.	8401310284	50-322 Q	EISENHUT, D. Q.	8401090783	50-470 A
DIXON, G. W.	8401050410	50-395 S	DYNNER, A. R.	8401310285*	50-322 Q	EISENHUT, D. Q.	8401090786*	50-470 A
DIXON, G. W.	8401050443	50-395 S	DYNNER, A. R.	8401310285*	50-322 Q	EISENHUT, D. Q.	8401120120*	50-266 P
DIXON, G. W.	8401050597	50-395 S	EAGLE, J.	8401190297	50-254 S	EISENHUT, D. Q.	8401130084	50-3 P
DIXON, G. W.	8401100444	50-395 P	EAPEN, P.	8401240313*	50-354 Q	EISENHUT, D. Q.	8401160011*	50-239 P
DIXON, G. W.	8401120279	50-395 R	EAPEN, P. K.	8401180201*	50-352 Q	EISENHUT, D. Q.	8401170283	50-293 F
DIXON, G. W.	8401120337	50-395 S	EARLEY, A. E.	8401050231	50-322 Q	EISENHUT, D. Q.	8401170484	50-269 F
DIXON, G. W.	8401120371	50-395 P	EARLEY, A. E.	8401050231	50-322 Q	EISENHUT, D. Q.	8401170491*	50-269 F
DIXON, G. W.	8401120410	50-395 S	EARLEY, A. F.	8401040611	50-322 A	EISENHUT, D. Q.	8401170508	50-440 A
DIXON, G. W.	8401170809	50-395 S	EARLEY, A. F.	8401090299*	REVIEW ORP	EISENHUT, D. Q.	8401170530*	50-331 F
DIXON, G. W.	8401240123	50-395 S	EARLEY, A. F.	8401120311	50-322 Q	EISENHUT, D. Q.	8401170560	50-397 P
DIXON, G. W.	8401240132	50-395 S	EARLEY, A. F.	8401120311	50-322 Q	EISENHUT, D. Q.	8401180011*	50-282 F
DIXON, G. W.	8401240138	50-395 P	EARLEY, A. F.	8401190180	50-322 Q	EISENHUT, D. Q.	8401190003	50-374 P
DIXON, G. W.	8401240331*	50-395 Q	EARLEY, A. F.	8401190180	50-322 Q	EISENHUT, D. Q.	8401190086	50-388 A
DIXON, G. W.	8401240387	50-395 S	EBERLY, R.	8401170531*	50-331 F	EISENHUT, D. Q.	8401190089	50-482 A
DIXON, G. W.	8401240390	50-395 Q	EBERSOLE, R.	8401040358	50-346 S	EISENHUT, D. Q.	8401190121	50-503 F
DIXON, G. W.	8401240587	50-395 P	EBERSOLE, R.	8401160227	50-346 S	EISENHUT, D. Q.	8401190179	50-388 A
DIXON, G. W.	8401250316*	50-395 F	EBERT, R. W.	8401180259	50-219 P	EISENHUT, D. Q.	8401190566	50-483 Q
DIXON, G. W.	8401260022	50-395 S	EBNETER, B. D.	8401240313*	50-354 Q	EISENHUT, D. Q.	8401200136	50-366 P
DIXON, G. W.	8401260036*	50-395 F	ECKER, E. C.	8401300285*	50-296 P	EISENHUT, D. Q.	8401200171	50-352 A
DIXON, G. W.	8401260081	50-395 S	ECKER, J. P.	8401050533	70-27	EISENHUT, D. Q.	8401280124	50-206 P
DIXON, G. W.	8401260335	50-395 F	ECONOMOS, N.	8401050672*	50-413 Q	EISENHUT, D. Q.	8401280144	50-263 F
DIXON, G. W.	8401270377	50-395 R	ECONOMOS, N.	8401060317*	50-413 Q	EISENHUT, D. Q.	8401280286*	50-263 F
DIXON, G. W.	8401300241	50-395 S	ECONOMOS, N.	8401090451*	50-302 Q	EISENHUT, D. Q.	8401270937	50-324 P
DIXON, G. W.	8401310005	50-395 P	EDDINGS, H. G.	8401270481	50-327 R	EISENHUT, D. Q.	8401270341*	50-324 P
DIXON, G. W.	8401310022	50-395 Q	EDDLEMAN, W.	8401050209	50-400 Q	EISENHUT, D. Q.	8401300080	50-280 F
DIXON, G. W.	8401310206	50-395 P	EDDLEMAN, W.	8401090335	50-400 Q	EISENHUT, D. Q.	8401310066	TOPREP
DODA, R. J.	8401270120	1&E	EDDLEMAN, W.	8401090346*	50-400 Q	EISENHUT, D. Q.	8401310138	50-528 A
DODDS, R. T.	8401200028*	50-397 Q	EDDLEMAN, W.	8401230438	50-400 Q	EISENHUT, D. Q.	8401310144*	50-528 A
DODDS, R. T.	8401200074*	50-397 Q	EDDLEMAN, W.	8401230443*	50-400 Q	ELLIS, J.	8401030126	50-445 Q
DODDS, R. T.	8401200193*	50-397 Q	EDDELMAN, M. R.	8401050326	50-440 S	ELLIS, J.	8401030175	50-445 Q
DOEBLER, R. C.	8401240635*	50-387 F	EDDELMAN, H. R.	8401050375	50-440 S	ELLIS, J.	8401060360	50-445 Q
DOERFLEIN, L. T.	8401040405*	50-333 Q	EDDELMAN, M. R.	8401050402	50-440 S	ELLIS, J.	8401130106	50-445 Q
DOHERTY, J. F.	8401050246	PR	EDDELMAN, M. R.	8401050446	50-440 S	ELLIS, J.	8401170300	50-445 Q
DONNELLY, L. J.	8401310133*	MTSC	EDDELMAN, M. R.	8401050509	50-440 S	ELLIS, J.	8401190188	50-445 Q
DOOLITTLE, E. L.	8401030098	50-423 A	EDDELMAN, M. R.	8401050620	50-440 S	ELLIS, J.	8401240204	50-445 Q
DOROSHOW, J.	8401050455	50-289 Q	EDDELMAN, M. R.	8401050627	50-400 S	ELLIS, T. S.	8401090295*	REVIEW ORP
DOROSHOW, J.	8401050459*	50-289 Q	EDDELMAN, M. R.	8401100323	50-440 A	ELMORE, M. R.	8401160450	40-4492
DOROSHOW, J.	8401170311	50-289 Q	EDDELMAN, M. R.	8401170391	50-440 A	ELMS, A.	8401170320	50-213 R
DOROSHOW, J.	8401240215	50-289 Q	EDDELMAN, M. R.	8401230280	50-440 S	ELROD, S. A.	8401240082*	50-280 Q
DOROSHOW, J.	8401270209	50-289 Q	EDDELMAN, M. R.	8401230301*	50-440 Q	ELROD, S. A.	8401050394*	50-335 Q
DOROSHOW, J.	8401270288	50-289 Q	EDDELMAN, M. R.	8401230365	50-440 Q	ELROD, S. A.	8401050447*	50-280 Q
DOROSHOW, J.	8401270309	50-289 Q	EDDELMAN, M. R.	8401230375	50-440 S	ELROD, S. A.	8401090566*	50-338 Q
DOROSHOW, J.	8401270369	50-289 Q	EDDELMAN, M. R.	8401260146*	50-440 Q	ELROD, S. A.	8401240447*	50-335 Q
DORSEY, M.	8401130005	CONTRACT	EDGAR, G. L.	8401090344	50-70 Q	ELROD, S. A.	8401240553*	50-338 Q
DOUGHERTY, C. J.	8401100189	50-483 R	EDGAR, G. L.	8401090344	50-70 Q	ELSBASSER, T.	8401100446*	50-423 Q
DOUGHERTY, F. A.	8401170385*	50-329 R	EDGAR, G. L.	8401100149	50-537 Q	ELSBASSER, T.	8401240475*	50-423 Q

PERSONAL AUTHOR INDEX

489

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ELBASSER, T. C	8401100177*	70-820	FELTON, J. M.	8401040225	FOIA	FELTON, J. M.	8401170129	FOIA
ELBASSER, T. C	8401100332*	50-213 G	FELTON, J. M.	8401040606	FOIA	FELTON, J. M.	8401170137	FOIA
ELBASSER, T. C	8401180249*	50-245 G	FELTON, J. M.	8401040611	50-289 G	FELTON, J. M.	8401170148	FOIA
ELBASSER, T. C	8401240126*	50-297 G	FELTON, J. M.	8401040616	FOIA	FELTON, J. M.	8401170170	FOIA
ELBASSER, V. J.	8401100194*	50-358 G	FELTON, J. M.	8401040620	FOIA	FELTON, J. M.	8401170176	50-528 A
EMCH, R.	8401160208*	50-155 F	FELTON, J. M.	8401040623	FOIA	FELTON, J. M.	8401170183	FOIA
EMCH, R. L.	8401270174	50-155 F	FELTON, J. M.	8401040626	50-289 F	FELTON, J. M.	8401180009	50-528 A
EMERY, R. H.	8401040394*	70-2887	FELTON, J. M.	8401040629	50-155 F	FELTON, J. M.	8401200232	50-324 P
EMRIT, R.	8401230637	MUREG	FELTON, J. M.	8401040631	50-382 F	FELTON, J. M.	8401200284	50-348 F
ENG, J.	8401030070*	40-86	FELTON, J. M.	8401050003	50-397 F	FELTON, J. M.	8401200291	50-458 F
ENGLAND, L. A.	8401170361	TOPREP	FELTON, J. M.	8401050018	50-155 F	FELTON, J. M.	8401200303	50-382 F
ENGLAND, L. A.	8401170361	TOPREP	FELTON, J. M.	8401050023	50-280 F	FELTON, J. M.	8401200324	FOIA
ENGLE, L. B.	8401200102	50-280 F	FELTON, J. M.	8401050026	50-329 F	FELTON, J. M.	8401230001	50-289 P
ENNIS, J. D.	8401040289*	50-280 G	FELTON, J. M.	8401050033	50-320 F	FELTON, J. M.	8401230041	FOIA
ERASE, A.	8401170525*	CONTRACT	FELTON, J. M.	8401050035	50-344 F	FELTON, J. M.	8401230052	50-289 P
ERICKSON, J.	8401310456	40-2259	FELTON, J. M.	8401050039	50-320 F	FELTON, J. M.	8401230373	50-220 F
ERIKSON, P. B.	8401060327	50-29 P	FELTON, J. M.	8401050040	FOIA	FELTON, J. M.	8401230599	FOIA
ESELOROTH, P.	8401050318	50-322 S	FELTON, J. M.	8401050043	50-206 P	FELTON, J. M.	8401230603	FOIA
ESELOROTH, P.	8401190389	50-322 S	FELTON, J. M.	8401050046	50-261 F	FELTON, J. M.	8401230610	FOIA
ETHERIDGE, H. R.	8401230463*	04999	FELTON, J. M.	8401050055	50-373 F	FELTON, J. M.	8401230614	FOIA
EVANS, C. A.	8401300189*	50-285 G	FELTON, J. M.	8401050066	50-482 F	FELTON, J. M.	8401230630	50-329 G
EVANS, C. D.	8401270366*	50-373 G	FELTON, J. M.	8401050072	50-277 F	FELTON, J. M.	8401230640	50-298 F
EVERETT, R. J.	8401040289*	40-8102	FELTON, J. M.	8401050075	50-251 S	FELTON, J. M.	8401230650	50-346 F
EVERETT, R. J.	8401040475*	40-8584	FELTON, J. M.	8401050081	50-213 F	FELTON, J. M.	8401230656	50-528 F
EVERETT, R. J.	8401040490*	40-4492	FELTON, J. M.	8401050084	50-295 F	FELTON, J. M.	8401230662	50-213 F
EVERETT, R. J.	8401040810*	40-299	FELTON, J. M.	8401050092	50-289 F	FELTON, J. M.	8401240099	50-321 F
EVERETT, R. J.	8401040814*	40-299	FELTON, J. M.	8401050093	50-317 F	FELTON, J. M.	8401240611	50-259 F
EVERETT, R. J.	8401040819*	40-1162	FELTON, J. M.	8401050099	50-254 F	FELTON, J. M.	8401240615	50-286 F
EVERETT, R. J.	8401270439*	40-2259	FELTON, J. M.	8401050107	50-395 F	FELTON, J. M.	8401240620	50-155 F
EWERT, Q. F.	8401030369	50-329 A	FELTON, J. M.	8401050110	50-338 F	FELTON, J. M.	8401240624	50-348 F
EWERT, Q. F.	8401050434	50-329 A	FELTON, J. M.	8401050115	50-289 F	FELTON, J. M.	8401240630	50-348 F
EWERT, Q. F.	8401100384	50-329 A	FELTON, J. M.	8401050121	50-346 F	FELTON, J. M.	8401240631	50-387 F
EWERT, Q. F.	8401120206	50-329 A	FELTON, J. M.	8401050124	50-322 F	FELTON, J. M.	8401240638	50-348 F
EWERT, Q. F.	8401120273	50-329 A	FELTON, J. M.	8401050134	50-483 F	FELTON, J. M.	8401240647	50-261 F
EWERT, Q. F.	8401170167	50-329 A	FELTON, J. M.	8401050171	FOIA	FELTON, J. M.	8401240649	50-346 F
EWERT, Q. F.	8401170171	50-329 A	FELTON, J. M.	8401050227	50-289 F	FELTON, J. M.	8401240651	50-254 F
EWERT, Q. F.	8401170175	50-329 A	FELTON, J. M.	8401050239	50-295 F	FELTON, J. M.	8401250002	50-348 F
FALZONE, J. M.	8401180035*	ACRS	FELTON, J. M.	8401050251	50-254 F	FELTON, J. M.	8401250012	50-409 F
FALZONE, R. R.	8401100147	50-322 G	FELTON, J. M.	8401050360	50-286 F	FELTON, J. M.	8401250014	50-346 F
FALZONE, R. R.	8401100147	50-322 G	FELTON, J. M.	8401050400	50-280 F	FELTON, J. M.	8401250019	50-135 P
FANNING, M. K.	8401160440	FOIA	FELTON, J. M.	8401050412	50-317 F	FELTON, J. M.	8401250020	50-285 F
FARMER, F.	8401090631*	50-280 P	FELTON, J. M.	8401060014	50-335 F	FELTON, J. M.	8401250027	50-387 F
FARR, B.	8401270226	50-275 U	FELTON, J. M.	8401060018	50-483 F	FELTON, J. M.	8401250035	50-387 F
FARRAR, D. L.	8401040556	50-237 F	FELTON, J. M.	8401060027	50-317 F	FELTON, J. M.	8401250042	50-454 F
FARRAR, D. L.	8401060170	50-454 F	FELTON, J. M.	8401060035	50-483 F	FELTON, J. M.	8401250045	50-483 F
FARRAR, D. L.	8401090356	PR	FELTON, J. M.	8401060040	50-10 G	FELTON, J. M.	8401250050	50-285 F
FARRAR, D. L.	8401160275	PRM	FELTON, J. M.	8401060068	50-271 F	FELTON, J. M.	8401250051	50-252 F
FARRAR, D. L.	8401190322	50-456 A	FELTON, J. M.	8401060074	50-244 F	FELTON, J. M.	8401250057	50-313 F
FARRAR, D. L.	8401230294*	50-373 G	FELTON, J. M.	8401060081	50-269 F	FELTON, J. M.	8401250058	50-331 F
FARRAR, D. L.	8401230306*	50-373 G	FELTON, J. M.	8401060082	50-346 F	FELTON, J. M.	8401250062	50-277 F
FARRAR, D. L.	8401230310*	50-454 G	FELTON, J. M.	8401060097	50-327 F	FELTON, J. M.	8401250068	50-433 F
FARRAR, D. L.	8401230372*	50-373 G	FELTON, J. M.	8401060103	50-320 F	FELTON, J. M.	8401250073	50-483 F
FARRAR, D. L.	8401300200	50-295 F	FELTON, J. M.	8401060106	50-280 F	FELTON, J. M.	8401250081	50-313 F
FARRELL, R. E.	8401120255*	50-315 G	FELTON, J. M.	8401060107	50-155 F	FELTON, J. M.	8401250082	50-10 F
FAWELL, T. W.	8401100132	40-2061	FELTON, J. M.	8401060115	50-348 F	FELTON, J. M.	8401250091	50-244 F
FAY, C. W.	8306280032*	50-266 F	FELTON, J. M.	8401060118	50-155 F	FELTON, J. M.	8401250093	50-263 F
FAY, C. W.	8401030208	50-266 F	FELTON, J. M.	8401060122	50-272 F	FELTON, J. M.	8401250099	50-153 F
FAY, C. W.	8401050284	50-266 F	FELTON, J. M.	8401060132	50-324 F	FELTON, J. M.	8401250105	50-113 F
FAY, C. W.	8401100469	50-266 F	FELTON, J. M.	8401060146	50-289 F	FELTON, J. M.	8401250110	50-259 F
FAY, C. W.	8401130211*	50-266 G	FELTON, J. M.	8401060153	50-289 F	FELTON, J. M.	8401250111	50-29 F
FAY, C. W.	8401130387	50-266 G	FELTON, J. M.	8401060159	50-416 F	FELTON, J. M.	8401250120	50-295 F
FAY, C. W.	8401170192	50-266 R	FELTON, J. M.	8401060181	50-313 F	FELTON, J. M.	8401250127	50-315 F
FAY, C. W.	8401190419	50-266 P	FELTON, J. M.	8401060234	50-373 F	FELTON, J. M.	8401250135	50-295 F
FAY, C. W.	8401240072	50-266 G	FELTON, J. M.	8401060264	50-317 F	FELTON, J. M.	8401250136	40-1478
FAY, C. W.	8401260259*	50-266 F	FELTON, J. M.	8401060270	50-317 F	FELTON, J. M.	8401250141	50-261 F
FAY, C. W.	8401300070	50-266 X	FELTON, J. M.	8401090380	50-289 P	FELTON, J. M.	8401250147	50-322 F
FECHT, B. A.	8401130220	MUREG	FELTON, J. M.	8401090493	FOIA	FELTON, J. M.	8401250163	50-245 F
FEIERABEND, C. D.	8401240332*	50-282 G	FELTON, J. M.	8401100020	FOIA	FELTON, J. M.	8401250309	50-373 F
FEITKNECHT, C.	8401040469	50-334 R	FELTON, J. M.	8401100082	FOIA	FELTON, J. M.	8401250315	50-395 F
FEITKNECHT, C.	8401310295	50-334 R	FELTON, J. M.	8401160365	FOIA	FELTON, J. M.	8401250319	50-390 F
FELTON, J. M.	8401030015	40-86	FELTON, J. M.	8401160373	FOIA	FELTON, J. M.	8401260014	50-409 F
FELTON, J. M.	8401030313	50-305 F	FELTON, J. M.	8401160390	50-440 A	FELTON, J. M.	8401260024	50-313 F
FELTON, J. M.	8401030320	50-483 F	FELTON, J. M.	8401160426	FOIA	FELTON, J. M.	8401260034	50-395 F
FELTON, J. M.	8401030332	50-322 F	FELTON, J. M.	8401160435	FOIA	FELTON, J. M.	8401260037	50-285 F
FELTON, J. M.	8401030344	50-280 F	FELTON, J. M.	8401160439	FOIA	FELTON, J. M.	8401260052	50-29 F
FELTON, J. M.	8401030353	50-338 F	FELTON, J. M.	8401160442	FOIA	FELTON, J. M.	8401260056	50-321 F
FELTON, J. M.	8401030359	50-309 F	FELTON, J. M.	8401160446	50-358 G	FELTON, J. M.	8401260063	50-289 F
FELTON, J. M.	8401030371	50-348 F	FELTON, J. M.	8401160452	FOIA	FELTON, J. M.	8401260135	50-389 F
FELTON, J. M.	8401040014	50-322 F	FELTON, J. M.	8401160460	FOIA	FELTON, J. M.	8401260147	50-387 F
FELTON, J. M.	8401040019	70-938	FELTON, J. M.	8401170015	FOIA	FELTON, J. M.	8401260156	50-309 F
FELTON, J. M.	8401040044	50-329 A	FELTON, J. M.	8401170026	50-289 P	FELTON, J. M.	8401260170	50-155 F
FELTON, J. M.	8401040149	FOIA	FELTON, J. M.	8401170029	FOIA	FELTON, J. M.	8401260178	50-454 F
FELTON, J. M.	8401040159	FOIA	FELTON, J. M.	8401170034	50-440 A	FELTON, J. M.	8401260181	50-348 F
FELTON, J. M.	8401040177	FOIA	FELTON, J. M.	8401170052	FOIA	FELTON, J. M.	8401260189	50-298 F
FELTON, J. M.	8401040188	FOIA	FELTON, J. M.	8401170121	FOIA	FELTON, J. M.	8401260201	50-338 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FELTON, J. M.	8401260213	50-320 F	FIELD, J. S.	8401040319	50-387 R	FRYE, J. H.	8401240276	50-142 Q
FELTON, J. M.	8401260224	50-261 F	FIELD, J. S.	8401170338	50-387 R	FRYE, J. H.	8401300237	50-142 Q
FELTON, J. M.	8401260229	50-346 F	FIELD, J. S.	8401240141	50-387 H	FRYE, J. H.	8401310156	50-142 Q
FELTON, J. M.	8401260234	50-320 F	FIELD, J. S.	8401310346	50-387 R	FUENTES, E. S.	8401170392	50-416 P
FELTON, J. M.	8401260235	50-112 F	FIEND, D.	8401060286*	TDPREP	FUENTES, J.	8401130046*	GA999
FELTON, J. M.	8401260241	50-295 F	FIERST, O. A.	8401300152	MISC	FUHRMAN, O. R.	8312290397	50-317 S
FELTON, J. M.	8401260242	50-315 F	FILBURN, T.	8401100352	50-336 S	FULL, P. F.	8401050617	50-287 E
FELTON, J. M.	8401260245	50-313 F	FINKEL, A.	8401260186*	50-412 Q	FULLER, C.	8401180194	50-267 R
FELTON, J. M.	8401260247	50-295 F	FINKEL, A. E.	8401240472*	50-423 Q	FUNCHEE, J. L.	8303090540*	FOIA
FELTON, J. M.	8401260250	50-266 F	FINLEY, N. C.	8401260079	NJREQ	FURBER, R. K.	8401310220	50-320 H
FELTON, J. M.	8401260253	50-338 F	FIORILLI, G.	8401300302*	50-328 Q	GABRIELLI, E. M.	8401030134	50-312 P
FELTON, J. M.	8401260258	50-295 F	FISH, R. F.	8312290264*	50-312 Q	GABRIELLI, E. M.	8401120353	50-312 S
FELTON, J. M.	8401260260	50-290 F	FITZGERALD, J. A.	8203120409*	FOIA	GABRIELLI, E. M.	8401300313*	50-312 Q
FELTON, J. M.	8401260266	50-348 F	FITZGERALD, J. A.	8203120411*	FOIA	GAD, R. K.	8401030109	50-443 Q
FELTON, J. M.	8401260269	50-416 F	FITZGERALD, J. A.	8203300066*	50-443 A	GAD, R. K.	8401030109	50-443 Q
FELTON, J. M.	8401260287	50-454 F	FITZSIMMONS, J.	8401110374	XPORTLIC	GAD, R. K.	8401030136	50-443 Q
FELTON, J. M.	8401260288	50-289 F	FLACK, E.	8312190241	I&E	GAD, R. K.	8401030136	50-443 Q
FELTON, J. M.	8401260290	50-3 F	FLACK, E.	8401120343	I&E	GAD, R. K.	8401030141*	50-443 Q
FELTON, J. M.	8401260293	50-373 F	FLACK, E.	8401190367	I&E	GAD, R. K.	8401030141*	50-443 Q
FELTON, J. M.	8401260296	50-348 F	FLAGA, W. J.	8401060636	50-315 S	GAD, R. K.	8401030150	50-443 Q
FELTON, J. M.	8401260301	50-313 F	FLAGA, W. J.	8401130177	50-315 S	GAD, R. K.	8401030150	50-443 Q
FELTON, J. M.	8401260312	50-313 F	FLAGA, W. J.	8401300245*	50-315 S	GAD, R. K.	8401090272	50-443 Q
FELTON, J. M.	8401260320	50-245 F	FLAGA, W. J.	8401310414*	50-315 S	GAD, R. K.	8401090272	50-443 Q
FELTON, J. M.	8401260330	50-348 F	FLEENOR, C.	8401170306	CONTRACT	GAD, R. K.	8401090281*	50-443 Q
FELTON, J. M.	8401260376	50-346 F	FLEENOR, C.	8401170319	CONTRACT	GAD, R. K.	8401090281*	50-443 Q
FELTON, J. M.	8401260398	50-320 F	FLEENOR, C.	8401170332	CONTRACT	GAD, R. K.	8401230382	50-443 Q
FELTON, J. M.	8401260403	50-454 F	FLEENOR, C.	8401170343	CONTRACT	GAD, R. K.	8401230382	50-443 Q
FELTON, J. M.	8401260407	50-387 F	FLEENOR, C.	8401180014	CONTRACT	GAD, R. K.	8401230423	50-443 Q
FELTON, J. M.	8401300002	50-298 F	FLETCHER, C. D.	8401310061*	50-261 P	GAD, R. K.	8401230423	50-443 Q
FELTON, J. M.	8401300330	50-346 F	FLOOD, R. W.	8401130197	GA999	GADE, P.	8401030230*	50-312 Q
FELTON, J. M.	8401300336	50-213 F	FLORIA, J. J.	8401060391	50-289 U	GAOLIARDO, J.	8401040422	50-482 Q
FELTON, J. M.	8401300344	50-254 F	FLORY, C.	8401270516	WASTE MGT	GAOLIARDO, J. E.	8401040353	50-285 Q
FELTON, J. M.	8401300350	50-289 F	FLONNER, R. L.	8401120340	MISC	GAOLIARDO, J. E.	8401040374	50-482 Q
FELTON, J. M.	8401300352	50-317 F	FLONNER, R. L.	8401250225	40-2061	GAOLIARDO, J. E.	8401040407	50-285 Q
FELTON, J. M.	8401300357	50-298 F	FORD, R. E.	8401130092	NJREQ	GAOLIARDO, J. E.	8401040421	50-482 Q
FELTON, J. M.	8401300361	50-313 F	FORNEY, W.	8401300143	50-358 S	GAOLIARDO, J. E.	8401040444	50-313 Q
FELTON, J. M.	8401300365	50-320 F	FORNEY, W. L.	8401100054*	50-358 Q	GAOLIARDO, J. E.	8401040446	50-285 Q
FELTON, J. M.	8401300371	50-341 F	FORNEY, W. L.	8401100059*	50-358 Q	GAOLIARDO, J. E.	8401040455	50-482 Q
FELTON, J. M.	8401300373	50-389 F	FORNEY, W. L.	8401100194*	50-358 Q	GAOLIARDO, J. E.	8401040471	50-285 Q
FELTON, J. M.	8401310049	50-295 F	FORBYTHE, E. B.	8401060391	50-289 U	GAOLIARDO, J. E.	8401040497*	50-445 Q
FELTON, J. M.	8401310054	50-373 F	FORBYTHE, F.	8401040095*	50-352 A	GAOLIARDO, J. E.	8401040563	50-482 Q
FELTON, J. M.	8401310060	50-389 F	FORTENBERRY, R.	8401310147*	50-327 F	GAOLIARDO, J. E.	8401002060	50-285 F
FELTON, J. M.	8401310065	50-346 F	FOSTER, C. M.	8401090298	XPORTLIC	GAOLIARDO, J. E.	8401130169	50-482 Q
FELTON, J. M.	8401310071	50-369 F	FOSTER, C. M.	8401110339	XPORTLIC	GAOLIARDO, J. E.	8401130238	50-458 Q
FELTON, J. M.	8401310077	50-295 F	FOSTER, D. O.	8401050264*	50-424 Q	GAOLIARDO, J. E.	8401170241	50-313 Q
FELTON, J. M.	8401310088	50-295 F	FOSTER, D. O.	8401090431*	50-424 Q	GAOLIARDO, J. E.	8401170299	50-313 Q
FELTON, J. M.	8401310109	50-334 F	FOSTER, D. O.	8401090468*	50-424 Q	GAOLIARDO, J. E.	8401170350	50-313 Q
FELTON, J. M.	8401310111	50-387 F	FOSTER, D. O.	8401130152	50-424 S	GAOLIARDO, J. E.	8401170389*	50-482 Q
FELTON, J. M.	8401310126	50-327 F	FOSTER, D. O.	8401130152	50-424 B	GAOLIARDO, J. E.	8401170394*	50-482 Q
FELTON, J. M.	8401310137	50-320 F	FOSTER, D. O.	8401170149	50-424 C	GAOLIARDO, J. E.	8401170418	50-285 Q
FELTON, J. M.	8401310170	50-244 F	FOSTER, D. O.	8401170358	50-424 A	GAOLIARDO, J. E.	8401230170	50-482 Q
FELTON, J. M.	8401310174	50-10 F	FOSTER, D. O.	8401230384	50-424 S	GAOLIARDO, J. E.	8401230193	50-482 Q
FELTON, J. M.	8401310190	50-483 F	FOSTER, D. O.	8401230488	50-424 B	GAOLIARDO, J. E.	8401230197	50-482 Q
FELTON, J. M.	8401310194	50-285 F	FOSTER, D. O.	8401260069	50-424 B	GAOLIARDO, J. E.	8401230218	50-482 Q
FELTON, J. M.	8401310229	50-348 F	FOSTER, J.	8401160261	50-373 S	GAOLIARDO, J. E.	8401230371	50-482 Q
FELTON, J. M.	8401310254	50-263 F	FOSTER, W. E.	8401130271*	GA999	GAOLIARDO, J. E.	8401230402	50-313 P
FELTON, J. M.	8401310458	50-313 F	FOSTER, W. E.	8401170341*	GA999	GAOLIARDO, J. E.	8401270066	50-313 Q
FERGUSON, E. S.	8401100152	71-96	FOSTER, W. E.	8401170415*	GA999	GAOLIARDO, J. E.	8401270097	50-313 Q
FERGUSON, E. S.	8401100156*	71-96	FOURST, B.	8107160006*	FOIA	GAOLIARDO, J. E.	8401270269	50-313 Q
FERKIN, Z. G.	8401050268	50-352 Q	FOHLER, L.	8401300321	50-424 Q	GAOLIARDO, J. E.	8401270432	50-313 Q
FERRIC	8401300169	50-29 S	FRAOOLA, J. R.	8401030350	NJREQ	GAOLIARDO, J. E.	8401300172	50-285 Q
FERRILL, C. M.	8401250194	50-352 T	FRALEY, R. F.	8401250193	50-275 Q	GALLAGHER, D. W.	8401030364	50-245 P
FEY, F. L.	8401310263*	50-263 F	FRAME, P. H.	8401030057*	40-86	GALLO, J.	8401050241	50-155 Q
FEY, F. L.	8401310271*	50-263 F	FRAME, P. H.	8401030102*	40-86	GALLO, J.	8401050241	50-155 Q
FICH, C. R.	8401260243*	50-295 F	FRANCIS, E. I.	8401230291*	GA999	GALLO, J.	8401050250	50-155 Q
FIEDLER, P. B.	8401060148	50-219 P	FRANKLIN, D. A.	8401240172	50-206 H	GALLO, J.	8401050290	50-155 Q
FIEDLER, P. B.	8401060155*	50-219 P	FREDRICKSON, P.	8401240597*	50-438 Q	GALLO, J.	8401050340	50-155 Q
FIEDLER, P. B.	8401100318	50-219 P	FREEMAN, M. D.	8401090205	40-8768	GALLO, J.	8401050340	50-155 Q
FIEDLER, P. B.	8401120249	50-219 R	FRENCH, A. O.	8401050005*	50-397 F	GALLO, J.	8401050366	50-454 Q
FIEDLER, P. B.	8401120435	50-219 B	FRENCH, P. S.	8401310449	40-8829	GALLO, J.	8401050366	50-454 Q
FIEDLER, P. B.	8401130155	50-219 S	FRIEDMAN, L. F.	8401130007	40-8824	GALLO, J.	8401240194	50-155 Q
FIEDLER, P. B.	8401160085	50-219 R	FRIEDMAN, S.	8401050262	WASTE MGT	GALLO, J.	8401240194	50-155 Q
FIEDLER, P. B.	8401160138	50-219 S	FRIEDMAN, S.	8401100196	WASTE MGT	GALLO, R.	8401120420	50-271 S
FIEDLER, P. B.	8401160193	50-219 S	FRIEDMAN, S.	8401100198*	WASTE MGT	GALLO, R.	8401300286*	50-443 Q
FIEDLER, P. B.	8401170154	50-219 P	FRIEDMAN, H. A.	8401180261	50-244 Q	GALLUCCI, R. H.	8401100088	NJREQ
FIEDLER, P. B.	8401170539	71-6346	FROUNFELKER, R.	8401100316	50-255 J	GALLUCCI, R. H.	8401130220	NJREQ
FIEDLER, P. B.	8401240209*	50-217 Q	FROUNFELKER, R.	8401100388	50-255 J	GALM, D. T.	8401120103	70-698
FIEDLER, P. B.	8401240489	50-219 F	FROUNFELKER, R.	8401100447	50-155 J	GAMLIN, R.	8401170032	50-440 A
FIEDLER, P. B.	8401270239	50-219 R	FRYE, J. H.	8401100148	50-142 Q	GARCIA, E. M.	8401100397*	50-288 Q
FIEDLER, J.	8401050269	50-321 J	FRYE, J. H.	8401110179	50-142 Q	GARCIA, J.	8401170425*	50-354 A
FIELDB, H. C.	8401090410	50-395 S	FRYE, J. H.	8401160233	40-2061	GARCIA, P. J.	8401040475*	40-8584
FIELDB, H. C.	8401120410	50-395 S	FRYE, J. H.	8401200111	50-142 Q	GARCIA, P. J.	8401040591*	40-1162
FIELDB, H. C.	8401260022	50-395 S	FRYE, J. H.	8401200138	50-142 Q	GARCIA, P. J.	8401060621	40-3453
FIELDB, J. S.	8401060267	50-388 A	FRYE, J. H.	8401200161	50-142 Q	GARCIA, P. J.	8401310421	40-4492
FIELDB, J. S.	8401060282	50-387 P	FRYE, J. H.	8401230400	50-70 Q	GARCIA, P. J.	8401310431*	40-1162

PERSONAL AUTHOR INDEX

491

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BARDE, B	8401230589*	50-358 G	GILBERT, R A	8401200098	50-237 P	BOSSICK, L V	8401180042*	50-328 A
BARNDNER, R N	8401100221*	50-329 G	GILBERT, R A	8401200098	50-237 P	BOULD, T L	8401160195	50-320 S
BARNDNER, R N	8401190286*	50-329 G	GILCHRIST, R L	8401090615	NUREQ	BOULD, W R	8401260363	50-361 P
BARLAND, W L	8401310508	40-1162	GILCHRIST, R L	8401120095	NUREQ	BOYER, O C	8401230651*	50-329 G
BARLING, R A	8401090593	40-8728	GILDENHORN, A	8401100119	CONTRACT	GRABER, L D	8401040221	FOIA
BARNER, L	8401090292*	50-416 G	GILDENHORN, A	8401110009	CONTRACT	GRABER, L D	8401030064	50-237 S
BARNER, L W	8401050380*	50-324 G	GILDENHORN, A J	8401050016	CONTRACT	GRABER, L D	8401160436	FOIA
BARNER, L W	8401050525*	50-324 G	GILDENHORN, A J	8401060198	CONTRACT	GRABER, L D	8401160448	FOIA
BARNEBS, L W	8401060432*	50-324 G	GILDENHORN, A J	8401060205	CONTRACT	GRAESSER, K L	8401130098	50-304 S
BARRITY, J H	8401050258	50-309 S	GILDENHORN, A J	8401060634	CONTRACT	GRAESSER, K L	8401130334	50-304 S
BARY, R J	8401030205	50-445 A	GILDENHORN, A J	8401110018	CONTRACT	GRAESSER, K L	8401170020	50-295 S
BARY, R J	8401100004	50-445 S	GILDER, M L	8401040028*	50-440 G	GRAESSER, K L	8401190415	50-295 S
BARY, R J	8401100394	50-445 A	GILINSKY, V	8305260328*	50-245 F	GRAESSER, K L	8401190423	50-295 S
BARY, R J	8401170384	50-445 G	GILINSKY, V	8401110305	50-289 G	GRAESSER, K L	8401270333	50-295 S
BARY, R J	8401230410	50-446 S	GILINSKY, V	8401230019*	FOIA	GRAHAM, D	8401160167	50-302 R
BARY, R J	8401270275	50-445 S	GILINSKY, V	8401250182*	FOIA	GRANT, N W	8401120363	50-250 R
BARY, R J	8401270316	50-445 G	GILINSKY, V	8401250185*	50-289 F	GRANT, N W	8401270459	50-250 R
BARY, R J	8401300034	50-445 F	GILINSKY, V	8401250188*	FOIA	GRANT, W B	8401050343*	50-456 G
BARY, R J	8401310330	50-445 A	GILINSKY, V	8401270013*	50-416 P	GRAVES, R H	8401050163	50-213 S
BASKIN, K P	8401100367	50-362 G	GILL, A S	8401160002*	50-220 P	GRAVES, R H	8401120280	50-213 R
BAYNY, R D	8401260294*	50-3 F	GILLET, W T	8401270446	50-315 R	GRAVES, R H	8401160073	50-213 S
BAUSE, E P	8401160438	50-445 S	GILLET, W T	8401270477	50-316 R	GRAVES, R H	8401270062	50-213 S
BAUTAM, A S	8401130070	50-263 P	GILMARTIN, D J	8401160244	50-322 G	GRAVES, R H	8401270257	50-213 R
BAUTAM, A S	8401130343	50-346 P	GILMORE, W E	8401030355	NUREQ	GRAVES, R H	8401270336	50-213 S
BAWDR, R K	8401190169	27-48	GILMORE, W E	8401130092	NUREQ	GRAVES, R H	8401270347*	50-213 S
BEARS, D	8401190115	50-277 P	GINESBERG, T	8401160407*	FOIA	GRAVES, R H	8401270404	50-213 S
BEIER, J Q	8401210363	50-461 A	GIRARD, E H	8401090446*	50-424 G	GREEN, H J	8401030071	50-327 S
BERETY, H F	8401030198	50-289 J	GITNICK, B J	8401130257*	50-324 P	GREEN, H J	8401030225	50-260 S
BERETY, H F	8401260005	50-289 J	GITNICK, B J	8401130266*	50-324 P	GREEN, H J	8401030247	50-327 S
BERETY, H F	8401300308	50-289 J	GITNICK, B J	8401130283*	50-324 P	GREEN, H J	8401040237	50-296 S
BERNER, L	8401240652*	50-254 F	GLANTZ, C S	8401130360	NUREQ	GREEN, H J	8401040436	50-328 S
BERRETS, T F	8401030067	50-382 S	GLASSPIEGEL, H	8401110159	50-440 G	GREEN, H J	8401050422	50-327 S
BERRETS, T F	8401030232	50-382 S	GLASSPIEGEL, H	8401110159	50-440 G	GREEN, H J	8401050651	50-328 S
BERRETS, T F	8401100184	50-382 S	GLENN, J	8312210189	I&E	GREEN, H J	8401120309	50-260 S
BERRETS, T F	8401100266	50-382 S	GLENN, J	8401130317	I&E	GREEN, H J	8401120328	50-328 S
BERRETS, T F	8401100282	50-382 S	GLENN, J	8401240154	I&E	GREEN, H J	8401120336	50-327 S
BERRETS, T F	8401130247	50-382 S	GLENN, J	8401310211	I&E	GREEN, H J	8401120388	50-328 S
BERRETS, T F	8401130282	50-382 S	GLENN, J E	8401030073*	40-86	GREEN, W	8401300333*	50-346 F
BERRETS, T F	8401130316	50-382 S	GLENN, J E	8401040061*	FOIA	GREENAN	8401300169	50-29 S
BERRETS, T F	8401170199	50-382 S	GLENN, J E	8401040115*	FOIA	GREENE, T	8401240106*	50-321 F
BERRETS, T F	8401170201	50-382 S	GLENN, J E	8401040120*	FOIA	GREENKORN, R A	8401260197*	CONTRACT
BERRETS, T F	8401180231*	50-382 G	GLENN, J E	8401040156*	FOIA	GREENMAN, E Q	8401100442*	50-309 G
BERRETS, T F	8401230223	50-382 S	GLENN, J E	8401040161*	FOIA	GREENSLATT, M	8401130037*	CONTRACT
BERRETS, T F	8401230348	50-382 S	GLENN, J E	8401040194*	FOIA	GREEVE, J	8401120141	WASTE MGT
BERRETS, T F	8401230530	50-382 S	GLENN, J E	8401040201*	FOIA	GREEVES, J T	8401130052	WASTE MGT
BERRETS, T F	8401240094	50-382 S	GLENN, J E	8401040211*	FOIA	GREGG, L R	8401050286*	50-440 G
BERRETS, T F	8401240128	50-382 S	GLENN, J E	8401040213*	FOIA	GREGG, L R	8401260343*	50-456 G
BERRETS, T F	8401240453	50-382 S	GLENN, J E	8401040231*	FOIA	GREGG, L R	8401050421*	50-454 G
BERRETS, T F	8401240469	50-382 S	GLENN, J C	8401040236*	FOIA	GREGG, H	8401240313*	50-354 G
BERRETS, T F	8401240550	50-382 S	GLENN, J E	8401040238*	FOIA	GRIER, B H	8401110205*	50-320 U
BERRETS, T F	8401270071	50-382 S	GLENN, J E	8401040251*	FOIA	GRIFFIN, J M	8401120424	50-368 P
BERRETS, T F	8401270076	50-382 S	GLENN, J E	8401040259*	FOIA	GRIFFIN, J M	8401170190	50-368 P
BERRETS, T F	8401270327*	50-382 G	GLENN, J E	8401040271*	FOIA	GRIFFIN, J M	8401180062	50-368 P
BERRETS, T F	8401270500	50-382 S	GLENN, J E	8401040287*	70-83	GRIFFIN, J M	8401300167	50-368 F
BERTHMAN, D I	8401030355	NUREQ	GLOVER, J	8401190415	50-295 S	GROBE, J A	8401100440*	50-263 G
BERTHMAN, D I	8401130092	NUREQ	GODDARD, R J	8401040110	50-155 G	GROSCUP, G W	8401040257	50-247 P
BERTHMAN, E F	8401090526*	GA999	GODDARD, R J	8401250321	50-461 G	GROSCUP, G W	8401240369*	50-3 G
BERTHMAN, E F	8401090532*	GA999	GODDY, A T	8401030176*	50-5 S	GROSB, P J	8401190353	50-537 A
BIANCO, G J	8401300353*	50-289 F	GODDY, A T	8401030241*	50-289 G	GROSBMAN, H	8401170218	50-244 G
BIANCO, T D	8401050477*	50-259 G	GODDY, A T	8401100470*	50-333 G	GROTHENHUIS, M	8401050029	50-324 P
BIBSON, J	8401120196	50-336 R	GODDY, A T	8401190349*	50-322 G	GROTHENHUIS, M	8401190020	50-324 P
BIBSON, J	8401270457	50-336 R	GODDY, A T	8401190384*	50-220 G	GROTHENHUIS, M	8401190237	50-305 P
BIESLER, C W	8401030278	50-305 F	GODDY, A T	8401240295*	50-317 G	GROTHENHUIS, M	8401200128	50-324 P
BIESLER, C W	8401030315*	50-305 F	GODDY, A T	8401240521*	50-247 G	GROTHENHUIS, M	8401250446	50-324 P
BIESLER, C W	8401040240	50-305 F	GODDY, A T	8401260315*	70-135	GROTHENHUIS, M	8401260246	50-325 P
BIESLER, C W	8401040309	50-305 S	GODDY, A T	8401310099*	70-687	GRUNDSTROM, R J	8401310192*	50-483 F
BIESLER, C W	8401040321	50-305 S	GODOL, E M	8401100466	50-373 G	GRUNTHALER, Q H	8401090248*	GA999
BIESLER, C W	8401040378	50-305 G	GOLDBERG, J H	8401060302	50-498 A	GUARINT, F J	8401060391	50-289 U
BIESLER, C W	8401060348	50-305 S	GOLDBERG, J H	8401270363	50-498 K	GUARINT, F J	8312050488	50-321 G
BIESLER, C W	8401100191	50-305 J	GOLDBERG, J R	8401250189	50-289 G	GUCHAR, L T	8401050638	50-366 S
BIESLER, C W	8401100427	50-305 P	GOLDBERG, R	8401090370	50-440 M	GUCHAR, L T	8401130179	50-366 P
BIESLER, C W	8401120378	50-305 S	GOLDEN, M P	8401090370	50-440 M	GUCHAR, L T	8401130340	50-366 P
BIESLER, C W	8401130324	50-305 S	GOLDEN, M P	8401050287	50-286 J	GUCHAR, L T	8401130346	50-321 P
BIESLER, C W	8401160087	50-305 R	GOLDEN, M P	8401060242	50-346 J	GUCHAR, L T	8401130357	50-366 P
BIESLER, C W	8401160278	50-305 S	GODDE, D	8401120113	WASTE MGT	GUCHAR, L T	8401170172	50-321 P
BIESLER, C W	8401190333*	50-305 G	GODDE, D	8401130009	27-39	GUCHAR, L T	8401170345	50-366 S
BIESLER, C W	8401200015	50-305 V	GODMAN, L S	8401050646	50-409 S	GUCHAR, L T	8401190411	50-321 G
BIESLER, C W	8401230354	50-305 S	GODMAN, L S	8401060261	50-409 S	GUCHAR, L T	8401240584*	50-321 G
BIESLER, C W	8401230369	50-305 S	GODMAN, L S	8401120381	50-409 R	GUCHAR, L T	8401260059*	50-321 F
BIESLER, C W	8401230429	50-305 P	GODMAN, L S	8401130001	50-409 S	GUCHAR, L T	8401310123	50-321 P
BIESLER, C W	8401260043	50-305 J	GODMAN, L S	8401130148	50-409 S	GUILL, P F	8401120266	50-269 S
BIESLER, C W	8401310372	50-305 F	GODMAN, L S	8401160254	50-409 S	GUILL, P F	8401170208	50-287 S
BIF, J M	8401260032*	50-313 F	GODMAN, L S	8401160270	50-409 R	GUILL, P F	8401230462	50-269 S
GILBERT, R A	8401040152*	50-382 G	GORDON, C Z	8401100308*	50-309 G	GUINN, F K	8401240338*	70-143
GILBERT, R A	8401160064	50-237 F	GORMAN, B	8401270139	50-333 S	GUINN, F K	8401250298*	70-143

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GUINN, F. K.	8401250300*	70-143	HAIRSTON, W. G.	8401100396*	50-348 S	HARRINGTON, H. R.	8401160307*	50-293 Q
GUINN, F. R.	7902020317*	FOIA	HAIRSTON, W. G.	8401100403*	50-348 S	HARRINGTON, W. D.	8401040179	50-293 P
GUINN, F. R.	7903090070*	FOIA	HAIRSTON, W. G.	8401170191	50-348 R	HARRINGTON, W. D.	8401040209	50-293 P
GUINN, F. R.	7904050423*	FOIA	HAIRSTON, W. G.	8401170197	50-348 R	HARRINGTON, W. D.	8401050293	50-293 R
GUINN, P. R.	8010070383*	FOIA	HAIRSTON, W. G.	8401240267*	50-348 S	HARRINGTON, W. D.	8401090405	50-293 P
GUINN, P. R.	8104060208*	FOIA	HAIRSTON, W. G.	8401240275*	50-348 S	HARRINGTON, W. D.	8401120208	50-293 S
GUINN, P. R.	8104230201*	FOIA	HAIRSTON, W. G.	8401300291*	50-348 S	HARRINGTON, W. D.	8401130047	50-293 X
GUINN, P. R.	8401040029*	FOIA	HAIRSTON, W. G.	8401300294*	50-348 S	HARRINGTON, W. D.	8401160095	50-293 F
GUINN, P. R.	8401040058*	FOIA	HAIRSTON, W. G.	8401300297*	50-348 S	HARRINGTON, W. D.	8401160118	50-293 S
GUINN, P. R.	8401040066*	FOIA	HAIRSTON, W. G.	8401300303*	50-348 S	HARRINGTON, W. D.	8401160175	50-293 S
GUINN, P. R.	8401040071*	FOIA	HAIRSTON, W. G.	8401300306*	50-348 S	HARRINGTON, W. D.	8401170436	50-293 R
GUINN, P. R.	8401040078*	FOIA	HAIST, D. P.	8401200193*	50-377 Q	HARRINGTON, W. D.	8401180074	50-293 F
GUINN, P. R.	8401040080*	FOIA	HALE, C. J.	8401050232*	0A999	HARRINGTON, W. D.	8401190385	50-293 P
GUINN, P. R.	8401040134*	FOIA	HALE, C. J.	8401230296*	0A999	HARRINGTON, W. D.	8401230235	50-293 Q
GUINN, P. R.	8401040151*	FOIA	HALE, C. J.	8401230503*	0A999	HARRINGTON, W. D.	8401230370	50-293 P
GUINN, P. R.	8401040184*	FOIA	HALEY, K. T.	8401120137*	CONTRACT	HARRINGTON, W. D.	8401230415	50-293 Q
GULDEMOND, H. G.	8401270366*	50-373 Q	HALL, B. L.	8401050568*	50-302 Q	HARRINGTON, W. D.	8401240098	50-293 S
GUSTAFSON, L. M.	8401170316	50-275 H	HALL, B. L.	8401240452*	50-406 Q	HARRINGTON, W. D.	8401240103	50-293 S
GUSTAVE, R.	8401100095*	CONTRACT	HALL, B. L.	8401240457*	50-160 Q	HARRINGTON, W. D.	8401240145	50-293 S
GUSTAVE, R.	8401180002	CONTRACT	HALL, D. P.	8401030197	50-461 K	HARRINGTON, W. D.	8401270162	50-293 S
GUSTAVE, R. P.	8401030310*	CONTRACT	HALL, D. P.	8401050385	50-461 S	HARRINGTON, W. D.	8401270243	50-293 S
GUSTAVE, R. P.	8401030345*	CONTRACT	HALL, D. P.	8401050475	50-461 Q	HARRIS, J. R.	8401050504*	50-400 Q
GUSTAVE, R. P.	8401090742*	CONTRACT	HALL, D. P.	8401050527	50-461 Q	HARRIS, J. R.	8401050610*	50-390 Q
GUSTAVE, R. P.	8401130447*	CONTRACT	HALL, D. P.	8401050656	50-461 S	HARRIS, J. R.	8401240089*	50-424 Q
GUSTAVE, R. P.	8401170512*	CONTRACT	HALL, D. P.	8401050669	50-461 S	HARRIS, M. S.	8401050466	50-331 S
GUSTAVE, R. P.	8401170525*	CONTRACT	HALL, D. P.	8401060453	50-461 S	HARRIS, M. S.	8401050566	50-331 S
GUSTAVE, R. P.	8401170537*	CONTRACT	HALL, D. P.	8401140283	50-461 S	HARRIS, M. S.	8401120423	50-331 S
GUSTAVE, R. P.	8401170549*	CONTRACT	HALL, D. P.	8401190234	50-461 S	HARRIS, R.	8401240313*	50-354 Q
GUSTAVE, R. P.	8401180003*	CONTRACT	HALL, D. P.	8401230222	50-461 S	HARRISON, F.	8401110233	50-324 R
GUSTAVE, R. P.	8401180016*	CONTRACT	HALL, D. P.	8401230345*	50-461 Q	HARRISON, F.	8401030293	50-461 E
GUSTAVE, R. P.	8401180024*	CONTRACT	HALL, D. P.	8401230490	50-461 A	HARRISON, G.	8401240018	50-461 F
GUSTAVE, R. P.	8401190332*	CONTRACT	HALL, D. P.	8401310361	50-461 H	HARRISON, J. J.	8401040216	50-329 S
GUSTAVE, R. P.	8401190471*	CONTRACT	HALL, J. R.	8401240393*	50-322 A	HARRISON, J. J.	8401060464	50-329 A
GUSTAVE, R. P.	8401260485*	CONTRACT	HALL, R. E.	8401040253	40-8102	HARRISON, J. J.	8401100221*	50-329 Q
GUSTAVE, R. P.	8401300141*	CONTRACT	HALL, R. E.	8401040467	40-8584	HARRISON, J. J.	8401190286*	50-329 Q
GUTHRIE, B. C.	8401270366*	50-373 Q	HALL, R. E.	8401040484	40-4492	HARRISON, J. J.	8401240535	50-329 A
GWYNN, T. P.	8401100054*	50-358 Q	HALL, R. E.	8401040506	40-299	HARRISON, J. J.	8401270232	50-329 R
GWYNN, T. P.	8401100059*	50-358 Q	HALL, R. E.	8401040511	40-8584	HARRISON, J. J.	8401300137	50-329 A
GWYNN, T. P.	8401100194*	50-358 Q	HALL, R. E.	8401040571	40-1162	HARRISCH, R.	8401130334	50-304 S
HACKNEY, C. A.	8401170330*	50-298 Q	HALL, R. E.	8401270435	40-2239	HARSHE, B. L.	8401170528*	REVIEW GRP
HADLOCK, D. E.	8401090615	NURE9	HAMEL, D. B.	8401050451	50-331 S	HART, G. K.	8401180187	50-275 Q
HADLOCK, D. E.	8401120095	NURE9	HAMEL, D. B.	8401270504	50-331 S	HART, P.	8401300050	WASTE MGT
HADAM, T.	8401100114*	CONTRACT	HAMILTON, J. W.	8401050197*	0A999	HART, R. J.	8401240364*	0A999
HADAM, T.	8401100125*	CONTRACT	HAMILTON, J. W.	8401050232*	0A999	HART, T.	8401240592*	0A999
HADAM, T.	8401100222*	CONTRACT	HAMILTON, P. J.	8401170436	50-293 R	HART, T.	8401060509	50-346 S
HADAM, T. F.	8401030088*	CONTRACT	HAMILTON, P. J.	8401240098	50-293 S	HARTLEY, J. N.	8401160490	40-4492
HADAM, T. F.	8401030369*	CONTRACT	HAMILTON, P. J.	8401240103	50-293 S	HARTMANN, P. L.	8401240332*	50-282 Q
HADAM, T. F.	8401030379*	CONTRACT	HAMILTON, P. J.	8401270162	50-293 S	HASKIN, F. E.	8401160403*	FOIA
HADAM, T. F.	8401030389*	CONTRACT	HAMILTON, P. J.	8401270243	50-293 S	HATHAWAY, G. H.	8401060235	50-341 J
HADAM, T. F.	8401050020*	CONTRACT	HANAUER, B. H.	8207150195*	FOIA	HATHAWAY, G. H.	8401090199	50-341 A
HADAM, T. F.	8401050087*	CONTRACT	HANCOCK, D.	8401120244	WASTE MGT	HAUGHEY, M.	8401130458	50-410 A
HADAM, T. F.	8401050105*	CONTRACT	HAND, C. H.	8401300089	50-337 Q	HAUGHEY, M. F.	8401190293	50-410 A
HADAM, T. F.	8401060201*	CONTRACT	HANNETT, B. A.	8401110356	XPORTLIC	HAUGHEY, M. F.	8401190296	50-410 A
HADAM, T. F.	8401060207*	CONTRACT	HANNON, J.	8401270536	50-275 P	HAUGHEY, M. F.	8401200092	50-410 A
HADAM, T. F.	8401060222*	CONTRACT	HANNUM, W. H.	8401160023	PROJ	HAUGHEY, M. F.	8401270561	50-410 A
HADAM, T. F.	8401060223*	CONTRACT	HARD, J. E.	8401240332*	50-282 Q	HAUGHEY, M. F.	8401310223	50-410 A
HADAM, T. F.	8401060640*	CONTRACT	HARDOROVE, T. W.	8401110581	40-2259	HAVEMANN, B.	8401030063*	FOIA
HADAM, T. F.	8401060648*	CONTRACT	HARDOROVE, T. W.	8401270099	40-2259	HAVIAN, E. R.	8401080221	50-275 Q
HADAM, T. F.	8401090439*	CONTRACT	HARDOROVE, T. W.	8401310421	40-2259	HAVIAN, E. R.	8401050221	50-275 Q
HADAM, T. F.	8401100045*	CONTRACT	HARDIN, A. K.	8401240332*	50-297 Q	HAWKINS, A.	8401120129	CONTRACT
HADAM, T. F.	8401100138*	CONTRACT	HARDING, M. R.	8401030071	50-327 S	HAWKINS, D.	8401310059	CONTRACT
HADAM, T. F.	8401120102*	CONTRACT	HARDING, M. R.	8401030247	50-327 S	HAWKINS, D. A.	8401120097	CONTRACT
HADAM, T. F.	8401120137*	CONTRACT	HARDING, M. R.	8401040436	50-328 S	HAWKINS, D. A.	8401130013	CONTRACT
HADAM, T. F.	8401120138*	CONTRACT	HARDING, M. R.	8401050422	50-327 S	HAWKINS, E. F.	8401060248	40-8586
HADAM, T. F.	8401120598*	CONTRACT	HARDING, M. R.	8401050651	50-328 S	HAWKINS, E. F.	8401060636	40-8745
HADAM, T. F.	8401130008*	CONTRACT	HARDING, M. R.	8401120202	50-327 S	HAWKINS, E. F.	8401090060	40-8348
HADAM, T. F.	8401130018*	CONTRACT	HARDING, M. R.	8401120235	50-327 S	HAWKINS, E. F.	8401100099	40-8064
HADAM, T. F.	8401130020*	CONTRACT	HARDING, M. R.	8401120328	50-328 S	HAWKINS, E. F.	8401310412	40-8728
HADAM, T. F.	8401130445*	CONTRACT	HARDING, M. R.	8401120336	50-327 S	HAWKINS, E. F.	8401310416	40-8681
HADAM, T. F.	8401310068*	CONTRACT	HARDING, M. R.	8401120356	50-327 S	HAWKHURST, J.	8401030236*	50-289 Q
HAGEN, K. A.	8401050071*	FOIA	HARDING, M. R.	8401170198	50-328 S	HAYDEN, T.	8401240208	50-275 U
HAGEN, K. A.	8401050073*	FOIA	HARDING, M. R.	8401260038	50-328 S	HAYES, B. B.	8312140411	SECY
HAGEN, K. A.	8401100102*	FOIA	HARDING, M. R.	8401260321	50-328 S	HAYES, D.	8401040418	50-461 S
HAGEN, K. A.	8401100105*	FOIA	HARELL, E. W.	8401040549	50-338 S	HAYES, D. W.	8401260087*	50-454 Q
HAGER, G. W.	8401060482	50-352 D	HARNESB, J. L.	8401200089*	50-261 Q	HAYES, D. W.	8401310389*	50-454 Q
HAIRSTON, W. G.	8401030123	50-348 S	HARRAN, G.	8401120203	50-245 R	HAYES, R. C.	8401240463*	0A999
HAIRSTON, W. G.	8401040131*	50-348 S	HARRAN, G.	8401270442	50-245 R	HAYES, R. C.	8401240465*	0A999
HAIRSTON, W. G.	8401040136*	50-348 S	HARRELL, E. W.	8401040365	50-339 S	HAYNES, J. Q.	8401030174	50-361 Q
HAIRSTON, W. G.	8401040140*	50-348 S	HARRELL, E. W.	8401050548	50-338 S	HAYNES, J. Q.	8401030287	50-361 S
HAIRSTON, W. G.	8401040157	50-348 S	HARRELL, E. W.	8401130010	50-339 S	HAYNES, J. Q.	8401040187	50-362 S
HAIRSTON, W. G.	8401040359	50-348 S	HARRELL, E. W.	8401230021	50-338 S	HAYNES, J. Q.	8401040301	50-361 S
HAIRSTON, W. G.	8401060469*	50-348 S	HARRELL, E. W.	8401260006	50-339 S	HAYNES, J. Q.	8401040302	50-362 S
HAIRSTON, W. G.	8401060473*	50-348 S	HARRELL, E. W.	8401260015	50-339 S	HAYNES, J. Q.	8401040306	50-362 S
HAIRSTON, W. G.	8401060481*	50-348 S	HARRELL, P. H.	8401230202*	0A999	HAYNES, J. Q.	8401040307	50-362 S
HAIRSTON, W. G.	8401060489*	50-348 S	HARRELL, P. H.	8401270235*	0A999	HAYNES, J. Q.	8401040316	50-361 S

PERSONAL AUTHOR INDEX

493

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HAYNES, J. G.	8401040320	50-206 S	HIGGINBOTHAM, L.	8401190028	WASTE MGT	HOWE, P. W.	8401040468	50-324 P
HAYNES, J. G.	8401040343	50-362 S	HILDEBRAND, D. P.	8401230708*	CONTRACT	HOWE, P. W.	8401030198	50-324 P
HAYNES, J. G.	8401040386	50-362 S	HILDEBRAND, P.	8401060248	40-B586	HOWE, P. W.	8401030478	50-324 Q
HAYNES, J. G.	8401040474	50-361 S	HILDEBRAND, R.	8401060674*	40-B768	HOWE, P. W.	8401030490*	50-324 Q
HAYNES, J. G.	8401120205	50-361 S		8401310416	40-6681	HOWE, P. W.	8401100283	50-324 P
HAYNES, J. G.	8401120219	50-362 S	HILF, C. L.	8401090356*	50-293 P	HOWE, P. W.	8401170431	50-324 P
HAYNES, J. G.	8401120237	50-362 S	HILL, C. Z.	8401310492	40-B584	HOWELL, S. H.	8401030544	50-329 Q
HAYNES, J. G.	8401120247	50-206 R	HILL, D.	8401230031*	CONTRACT	HOYLE, J. C.	8401170479	10CFR
HAYNES, J. G.	8401120248	50-362 S	HILL, W. M.	8401100054*	50-338 Q	HOYT, H. F.	8401030207	50-443 Q
HAYNES, J. G.	8401120256	50-362 S	HILL, W. M.	8401100099*	50-338 Q	HOYT, H. F.	8401170306	50-443 Q
HAYNES, J. G.	8401120263	50-361 R	HILL, W. M.	8401100194*	50-358 Q	HOYT, H. F.	8401310279	50-443 Q
HAYNES, J. G.	8401160198	50-361 S	HIND, J. A.	8401160292	40-B760	HUBBARD, G. T.	8401130235*	GA999
HAYNES, J. G.	8401160206	50-361 S	HIND, J. A.	8401190443	40-B760	HUBBARD, G. T.	8401130354*	GA999
HAYNES, J. G.	8401160210	50-361 S	HIND, J. A.	8401260078	50-315 Q	HUBBARD, R.	8401180102*	50-528 A
HAYNES, J. G.	8401160276	50-362 S	HIND, J. A.	8401260084*	50-315 Q	HUBBARD, G.	8401230096*	50-263 F
HAYNES, J. G.	8401160294	50-362 S	HINDS, J. M.	8401310389*	50-454 Q	HUDSON, G.	8401310271*	50-263 F
HAYNES, J. G.	8401160300	50-362 S	HINDS, J. R.	8401040185	50-275 B	HUDSON, H.	8401160251*	50-275 P
HAYNES, J. G.	8401240382	50-206 F	HINDS, J. R.	8401160255	50-275 B	HUDSON, S. D.	8401180211*	50-220 Q
HAYNES, J. G.	8401260016	50-362 S	HIRSCH, D.	8401030149	50-142 Q	HUDBETH, J. B.	8401030374*	50-348 F
HAYNES, J. G.	8401260073	50-362 S	HIRSCH, D.	8401030157*	50-142 Q	HUDBETH, J. B.	8401240627*	50-348 F
HAYNES, J. G.	8401260074	50-361 S	HIRSCH, D.	8401030185	50-142 Q	HUDBETH, J. B.	8401250003*	50-348 F
HAYNES, J. G.	8401260225	50-362 S	HIRSCH, D.	8401030189	50-142 Q	HUDBETH, J. B.	8401260270*	50-348 F
HAYNES, J. G.	8401260264	50-361 S	HIRSCH, D.	8401030192*	50-142 Q	HUDBETH, J. B.	8401260299*	50-348 F
HAYNES, J. G.	8401260298	50-362 S	HIRSCH, D.	8401030235	50-142 Q	HUETER, L. J.	8401050421*	50-454 Q
HAYNES, J. G.	8401260361	50-361 S	HIRSCH, D.	8401100208	50-142 Q	HUFFMAN, G. N.	8401030361*	70-1151
HAYNES, J. G.	8401260365	50-361 S	HIRSCH, D.	8401100211	50-142 Q	HUFFMAN, G. N.	8401060439	50-335 F
HAYNES, J. G.	8401270231	50-361 R	HIRSCH, D.	8401110161	50-142 Q	HUGHES, W. J.	8401060391	50-269 U
HAYNES, J. G.	8401270234	50-206 R	HIRSCH, D.	8401130187	50-142 Q	HUKILL, H.	8401260066*	50-289 F
HATZ, A. J.	8401110454	WASTE MGT	HIRSCH, D.	8401240081	50-142 Q	HUKILL, H. D.	8312300285	50-289 B
HATZLEY, W.	8401160014*	50-259 P	HIRSCH, D.	8401240153	50-142 Q	HUKILL, H. D.	8401030228	50-289 B
HEASERLIN, S. W.	8401100088	NUREG	HIRSCH, D.	8401240238	50-142 Q	HUKILL, H. D.	8401040415	50-289 P
HEAD, G. F.	8401040347	50-366 P	HIRSCH, D.	8401270201	50-142 Q	HUKILL, H. D.	8401040517	50-289 P
HEARY, W. D.	8401240302*	50-369 S	HIRSCH, D.	8401270374	50-142 Q	HUKILL, H. D.	8401050278	50-289 P
HEATHERLY, T. L.	8401240549*	50-390 Q	HIRSCH, D.	8401300228	50-142 Q	HUKILL, H. D.	8401080333	50-289 P
HEATHERLY, T. L.	8401240608*	50-390 Q	HIRSCH, D.	8401300230*	50-142 Q	HUKILL, H. D.	8401090312	50-289 P
HEBBLE, T. L.	8401030350	NUREG	HODDER, M. H.	8401300126	50-250 Q	HUKILL, H. D.	8401130192	50-289 F
HECTOR, A.	8401120244	WASTE MGT	HODDER, M. H.	8401300130*	50-250 Q	HUKILL, H. D.	8401190370	50-289 R
HECTOR, A. G.	8401030288	PRM	HODDER, M. H.	8401310357	50-250 Q	HUKILL, H. D.	8401230335	50-289 F
HEETTER, W. H.	8401090718	XPORTLIC	HODDER, M. H.	8401310357	50-250 Q	HUKILL, H. D.	8401230478	50-289 S
HEGGERLIN, S. W.	8401130220	NUREG	HODDER, M. H.	8401310364*	50-250 Q	HUKILL, H. D.	8401240251	50-289 P
HEIDER, L. H.	8401040624*	50-29 Q	HODDER, M. H.	8401310364*	50-250 Q	HUKILL, H. D.	8401270190	50-289 P
HEIDER, L. H.	840120261	50-29 R	HOENIG, G. R.	8401260105	NUREG	HUKILL, H. D.	8401310141	50-289 P
HEIDER, L. H.	8401270406	50-29 R	HOFFMAN, D. P.	8401270255	50-155 R	HUNMER, G. D.	8401250122*	CONTRACT
HEITNER, K. L.	8401110173	50-336 P	HOFFMAN, D. P.	8401270322	50-155 R	HUNNICUTT, D.	8401040499*	50-445 Q
HEITNER, K. L.	8401110521	50-309 P	HOFFMAN, D. R.	8401090977	50-374 R	HUNNICUTT, D. M.	8401040291*	50-298 Q
HEITNER, K. L.	8401120175	50-336 P	HOFFMAN, D. R.	8401160477	50-397 P	HUNNICUTT, D. M.	8401040439*	50-482 Q
HELGESON, K. A.	8401270055	70-820	HOLDER, C. F.	8401100442*	50-309 Q	HUNNICUTT, D. M.	8401040472*	50-298 Q
HELLER, J. K.	8401190412*	50-315 Q	HOLDER, E. T.	8401040237	50-296 S	HUNNICUTT, D. M.	8401040484*	50-298 Q
HELLER, J. K.	8401300318*	50-255 Q	HOLDER, E. T.	8401120309	50-260 S	HUNNICUTT, D. M.	8401090133*	50-298 Q
HELMES, C. J.	8312210014*	NUREG	HOLLAN, P. D.	8401040099	50-124 V	HUNNICUTT, D. M.	8401170330*	50-298 Q
HELMES, C. J.	8312300296*	NUREG	HOLLAN, P. D.	8401200012	50-124 P	HUNNICUTT, D. M.	8401170370*	50-267 Q
HELMES, C. J.	8401060536*	MISC	HOLLAND, L. K.	8401300285*	50-296 P	HUNNICUTT, D. M.	8401230309	50-267 Q
HELMES, C. J.	8401240129	ORG	HOLLAND, S. A.	8401090315*	50-289 P	HUNSTAD, A. A.	8401080411	50-282 B
HELMES, C. J.	8401310079	MISC	HOLLAND, W. E.	8401090480*	50-370 Q	HUNSTAD, A. A.	8401090442	50-282 B
HELMICK, C.	8401230416	50-142 Q	HOLLAR, D. E.	8401100217	50-400 Q	HUNT, H. D.	8401240352*	50-438 Q
HEMORICKSON, R.	8401240270	50-116 P	HOLLAR, D. E.	8401100217	50-400 Q	HUNTER, D. R.	8401120255*	50-315 Q
HENRY, W. D.	8401240302*	50-369 S	HOLLEY, W. L.	8401040451*	50-285 Q	HURLEY, J.	8401040171*	50-416 F
HENRY, W. D.	8401240312*	50-369 S	HOLLEY, W. L.	8401040472*	50-298 Q	HUTCHINSON, C. R.	8401250286*	50-416 F
HENRY, W. D.	8401240324*	50-369 S	HOLMES, M. H.	8401270400*	50-267 P	IDEKER, R. L.	8401180145	70-143
HENSLEY, K. D.	8312080260	70-143	HOLMES-RAY, P.	8401240597*	50-321 Q	IKENOTO, F. M.	8401170420*	50-354 A
HERBERT, R. J.	8401100352	50-336 S	HOLONICH, J. J.	8401030419	50-483 A	IRWIN, D. P.	8401030297	50-463 Q
HERBERT, R. J.	8401100352	50-336 S	HOLONICH, J. J.	8401090048	50-482 A	IRWIN, D. P.	8401030297	50-463 Q
HERBERT, R. J.	8401120312	50-336 S	HOLONICH, J. J.	8401230685	50-482 Q	IRWIN, D. P.	8401030302*	50-463 Q
HERMANN, R. A.	8401040610	50-220 P	HOLTZ, J. L.	8401120407*	50-334 R	IRWIN, D. P.	8401030302*	50-463 Q
HERMANN, R. A.	8401060177	50-220 P	HOLTZ, J. L.	8401270228	50-334 R	IRWIN, D. P.	8401030307*	50-463 Q
HERNAN, R.	8401260467	50-302 P	HOLYOAK, R. H.	8401230312*	50-373 F	IRWIN, D. P.	8401030320*	50-463 Q
HERR, R. K.	8401100487	GA999	HOLZNER, M. M.	8401120255*	50-315 Q	IRWIN, D. P.	8401030320	50-322 Q
HERRINGTON, W. N.	8401090615	NUREG	HOLZNER, M. M.	8401190449*	50-295 Q	IRWIN, D. P.	8401030320	50-322 Q
HERRINGTON, W. N.	8401120095	NUREG	HOOD, D.	8401090791	50-329 A	IRWIN, D. P.	8401060386	50-322 Q
HERSCH, H. M.	8401090092	XPORTLIC	HOOKER, C. D.	8401090615	NUREG	IRWIN, D. P.	8401090295	REVIEW ORP
HEUMANN, R. L.	8401300210*	50-454 Q	HOOKER, C. D.	8401120095	NUREG	IRWIN, D. P.	8401090363	50-463 Q
HEYER, R. S.	8401270120	I&E	HOPCRAFT, C. P.	8401130063	71-9160	IRWIN, D. P.	8401190167	50-322 Q
HIATT, S. L.	8401060358	50-440 Q	HOPKINS, J. B.	8401160419	50-395 P	IRWIN, D. P.	8401190167	50-322 Q
HIATT, S. L.	8401100140	50-440 Q	HOPKINS, P. C.	8401100289*	50-324 P	IRWIN, D. P.	8401260195	50-463 Q
HIATT, S. L.	8401160385	50-440 A	HORIN, W. A.	8401190283	50-445 Q	IRWIN, H. R.	8401230253	PR
HIATT, S. L.	8401240333	50-440 Q	HORIN, W. A.	8401190283	50-445 Q	ISENBURG, D.	8401090697	FOIA
HICKEY, J. M.	8401040081*	FOIA	HORIN, W. A.	8401300244	50-445 Q	ISENBURG, P.	8401240220	50-275 U
HICKEY, J. M.	8401040083*	FOIA	HORTON, W.	8401300244	50-445 Q	ISLEY, T.	8401160325	50-346 B
HICKIN, R. A.	8401090754*	CONTRACT	HORTON, W.	8401100030*	FOIA	ISLEY, T.	8401300295	50-346 B
HISTAL, J. J.	8401130290	50-373 S	HORTON, W.	8401100037*	FOIA	JACKI, I.	8401130393	50-346 B
HIGGINBOTHAM, L.	8401120123	WASTE MGT	HORTON, W. H.	8401100040*	FOIA	JACKI, I. N.	8401190386*	50-346 Q
HIGGINBOTHAM, L.	8401120125	WASTE MGT	HOUGH, G. L.	8401100025*	FOIA	JACKI, I. N.	8401190401*	50-305 Q
HIGGINBOTHAM, L.	8401120126	WASTE MGT	HOUGH, G. L.	8401050031*	50-329 F	JACKI, I. N.	8401240332*	50-262 Q
HIGGINBOTHAM, L.	8401120131	WASTE MGT	HOUSTON, R. W.	8401170023*	FOIA	JACKSON, Q.	8401190088*	71-9044
HIGGINBOTHAM, L.	8401130478	WASTE MGT	HOWARD, J. J.	8401060391	50-289 U	JACKSON, K. C.	8401180038	WASTE MGT

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JACOBBS, A	8401030299	CONTRACT	JOHNSON, E. H.	8401100487*	QA999	JORDAN, E. L.	8312120093	50-3 0
JACOBBS, A	8401030329	CONTRACT	JOHNSON, E. H.	8401170256	50-382 d	JORDAN, E. L.	8312120104	50-3 0
JACOBBS, A	8401180021	CONTRACT	JOHNSON, E. H.	8401170312	50-498 d	JORDAN, E. L.	8312120107	50-3 0
JACOBBS, A.	8401260477	CONTRACT	JOHNSON, E. H.	8401170326	50-298 d	JORDAN, E. L.	8312120114	50-3 0
JACOBBS, R. H.	8401180203*	50-247 Q	JOHNSON, E. H.	8401170364	50-267 Q	JORDAN, E. L.	8312120116	50-3 0
JACQUES, R. C.	8401200168*	50-336 P	JOHNSON, E. H.	8401230155	50-438 Q	JORDAN, E. L.	8312120117	50-3 0
JAFFE, D. H.	8401100127	50-317 P	JOHNSON, E. H.	8401230302	50-267 Q	JORDAN, E. L.	8401110403	MISC
JANSEN, O.	8401300032	WASTE MGT	JOHNSON, E. H.	8401240492	50-438 Q	JORDAN, M.	8401100190	50-409 S
JANUSKA, A.	8401050339*	40-8631	JOHNSON, E. H.	8401270001	50-498 Q	JORDAN, M.	8401130393	50-346 S
JANUSKA, A. O.	8401230387*	50-483 Q	JOHNSON, E. H.	8401270081	50-438 Q	JORDAN, M.	8401190386*	50-346 Q
JAFE, F.	8401050633*	50-321 Q	JOHNSON, E. H.	8401270250	50-267 F	JORDAN, W. H.	8401230408	50-289 Q
JAPE, F.	8401090109*	50-390 Q	JOHNSON, Q. E.	8401040195	50-413 Q	JORDAN, W. H.	8401310222	50-443 Q
JAPE, F.	8401090219*	50-269 Q	JOHNSON, Q. E.	8401120195	50-413 Q	JORDAN, W. S.	8401110171	50-443 Q
JAPE, F.	8401090230*	50-270 Q	JOHNSON, Q. E.	8401120214	50-413 Q	JORDAN, W. S.	8401110171	50-443 Q
JAPE, F.	8401090262*	50-395 Q	JOHNSON, Q. E.	8401120224	50-413 Q	JORGENSEN, B. L.	8401300318*	50-255 Q
JAPE, F.	8401090394*	50-416 Q	JOHNSON, Q. E.	8401120252	50-413 Q	JOYNER, J.	8312210189	1&E
JAPE, F.	8401240317*	50-281 Q	JOHNSON, Q. E.	8401120300	50-413 Q	JOYNER, J.	8401180247	1&E
JAPE, F.	8401240613*	50-413 Q	JOHNSON, Q. E.	8401120310	50-413 Q	JOYNER, J.	8401180271	40-8610
JASKA, J. M.	8401300149*	40-7982	JOHNSON, Q. E.	8401120315	50-413 Q	JOYNER, J.	8401240154	1&E
JEFFERS, O.	8401180274*	50-322 T	JOHNSON, Q. E.	8401230101	50-413 Q	JOYNER, J.	8401240478	1&E
JEFFERSON, R. M.	8401300101*	WASTE MGT	JOHNSON, Q. E.	8401250262	50-413 Q	JOYNER, J.	8401300290	50-213 S
JENISON, K.	8401050681*	50-280 Q	JOHNSON, Q. E.	8401250272*	50-413 Q	JOYNER, J.	8401310211	1&E
JENISON, K.	8401090056*	50-338 Q	JOHNSON, H. D.	8401260265*	50-250 F	JOYNER, J. H.	8401030066*	40-86
JENISON, K. M.	8401050397*	50-338 Q	JOHNSON, J. W.	8401030350	MUREG	JOYNER, J. H.	8401030067*	40-86
JENISON, K. M.	8401050614*	50-338 Q	JOHNSON, R.	8401300109	WASTE MGT	JOYNER, J. H.	8401030104*	40-86
JENKINS, O. R.	8401050361*	70-1151	JOHNSON, R. A.	8401180024*	CONTRACT	JULIAN, C.	8401050517*	50-280 Q
JENKINS, O. R.	8401050492*	50-367 Q	JOHNSON, R. A.	8401190471*	CONTRACT	JULIAN, C.	8401240608*	50-390 Q
JENKINS, O. R.	8401060410*	50-348 Q	JOHNSON, R. A.	8401270034	50-263 J	JULIAN, C. A.	8401090117*	50-353 Q
JENKINS, O. R.	8401090264*	50-229 Q	JOHNSON, R. W.	8401240306	50-344 Q	JULIAN, C. A.	8401090134*	50-366 Q
JENS, W. H.	8401100436*	50-16 Q	JOHNSON, R. W.	8401240310*	50-344 Q	JULIAN, C. A.	8401090292*	50-416 Q
JENS, W. H.	8401160271*	50-341 Q	JOHNSON, T. C.	8401120118	WASTE MGT	JULIAN, C. A.	8401090357*	50-518 Q
JENS, W. H.	8401300376*	50-341 F	JOHNSON, T. C.	8401120355	WASTE MGT	JULIAN, C. A.	8401090480*	50-390 Q
JENS, W. H.	8401310319	50-341 F	JOHNSON, T. C.	8401170023	WASTE MGT	JULIAN, C. A.	8401240549*	50-390 Q
JENSEN, D. L.	8401110328*	50-289 U	JOHNSON, W. A.	8401040435*	50-482 Q	JUNGE, M.	8401270059	50-317 S
JERMAN, P.	8401310211	1&E	JOHNSON, W. D.	8401040111*	50-313 Q	JUNGE, M.	8401270281	50-317 S
JERMAN, P. C.	8401040124*	FOIA	JOHNSON, W. D.	8401040152*	50-382 Q	JUNGE, M. A.	8401030186	50-318 S
JERMAN, P. C.	8401040130*	FOIA	JOHNSON, W. D.	8401040291*	50-298 Q	JUNGE, M. A.	8401160067	50-317 S
JERMAN, P. C.	8401040166*	FOIA	JOHNSON, W. D.	8401040364*	50-285 Q	JUNGE, M. A.	8401160093	50-317 S
JERMAN, P. C.	8401040172*	FOIA	JOHNSON, W. D.	8401040377*	50-482 Q	JUNGE, M. A.	8401260251	50-317 S
JERMAN, P. C.	8401040176*	FOIA	JOHNSON, W. D.	8401040411*	50-285 Q	JUNGE, M. A.	8401270065	50-318 S
JERMAN, P. C.	8401040180*	FOIA	JOHNSON, W. D.	8401040439*	50-482 Q	JUNGE, M. A.	8401270137	50-317 S
JERMAN, P. C.	8401040192*	FOIA	JOHNSON, W. D.	8401040451*	50-285 Q	JUNGE, M. A.	8401270334	50-318 S
JERMAN, P. C.	8401040206*	FOIA	JOHNSON, W. D.	8401040457*	50-482 Q	JUNGLING, T. L.	8401120135	WASTE MGT
JERMAN, P. C.	8401040224*	FOIA	JOHNSON, W. D.	8401040466*	50-482 Q	KAHL, W. K.	8401030350	MUREG
JERMAN, P. C.	8401040227*	FOIA	JOHNSON, W. D.	8401040486*	50-298 Q	KAHLE, J.	8401300288	70-143
JERMAN, P. C.	8401040241*	FOIA	JOHNSON, W. D.	8401040494*	50-285 Q	KAHLE, J. B.	8401060491*	50-416 Q
JERMAN, P. C.	8401040246*	FOIA	JOHNSON, W. D.	8401040529*	50-285 Q	KAHLE, J. B.	8401090121*	70-143
JERMAN, P. C.	8401040264*	FOIA	JOHNSON, W. D.	8401040559*	50-498 Q	KALITOWSKI, T.	8401100142	WASTE MGT
JERMAN, P. C.	8401040274*	40-8833	JOHNSON, W. D.	8401040570*	50-482 Q	KALIVIANAKIS, N.	8401050431	50-265 S
JERSE, J. L.	8401130042*	QA999	JOHNSON, W. D.	8401170394*	50-482 Q	KALIVIANAKIS, N.	8401050449	50-254 S
JERSE, J. L.	8401130055*	QA999	JOHNSON, W. D.	8401170422*	50-285 Q	KALIVIANAKIS, N.	8401050485	50-265 S
JESSEN, D.	8401300348*	50-234 F	JOHNSON, W. D.	8401300189*	50-285 Q	KALIVIANAKIS, N.	8401050500	50-265 S
JESSUP, B.	8401120931	CONTRACT	JOHNSON, W. D.	8401120324	50-463 Q	KALIVIANAKIS, N.	8401050512	50-265 S
JESSUP, B.	8401120934	CONTRACT	JONES, D. D.	8401230028*	50-352 A	KALIVIANAKIS, N.	8401050524	50-265 S
JESSUP, B.	8401120959	CONTRACT	JONES, Q. T.	8401120297	50-259 S	KALIVIANAKIS, N.	8401050558	50-265 S
JESSUP, B.	8401120590	CONTRACT	JONES, Q. T.	8401120307	50-259 R	KALIVIANAKIS, N.	8401170024	50-234 R
JESSUP, B.	8401130032	CONTRACT	JONES, Q. T.	8401300181	50-296 S	KALIVIANAKIS, N.	8401170210	50-234 R
JESSUP, B.	8401230705	CONTRACT	JONES, Q. T.	8401300233	50-259 S	KALIVIANAKIS, N.	8401190297	50-254 S
JIERREE, C. C.	8401260271	40-8385	JONES, J. A.	8002190404*	FOIA	KALIVIANAKIS, N.	8401270338	50-265 S
JIERREE, C. C.	8401310422	40-4492	JONES, J. A.	8003130307*	FOIA	KALININS, W. H.	8401090315*	50-289 P
JIERREE, C. C.	8401310446*	40-4492	JONES, J. A.	8008280420*	FOIA	KAMMER, D. S.	8401050456*	50-239 Q
JOHANSEN, J.	8312210189	1&E	JONES, J. T.	8401310404	50-259 S	KAMMER, D. S.	8401060455*	50-390 Q
JOHNSON, A. D.	8401030230*	50-312 Q	JONES, M. K.	8401280324*	50-390 F	KAMMER, D. S.	8401170303	50-390 F
JOHNSON, A. D.	8401200193*	50-397 Q	JONES, R. D.	8401100075	MUREG	KAMMER, D. S.	8401190307	50-390 A
JOHNSON, A. D.	8401300280*	50-312 Q	JONES, R. E.	8401310292	50-261 Q	KAMMER, D. S.	8401200194	50-259 I
JOHNSON, B.	8401240187	50-255 P	JONES, V.	8401120291	50-280 R	KAMMER, D. S.	8401300304	50-390 K
JOHNSON, B. D.	8401040512	50-255 P	JONES, V. H.	8401270372	50-280 R	KAMMER, D. S.	8401310366	50-438 A
JOHNSON, B. D.	8401040532	50-255 P	JONES, W. C.	8401040233	50-285 P	KAMMER, D. S.	8401310369	50-327 P
JOHNSON, B. D.	8401050581	50-255 Q	JONES, W. C.	8401040290	50-285 P	KAMMEYER, D. J.	8401120416	50-344 R
JOHNSON, B. D.	8401230190	50-255 S	JONES, W. C.	8401050085*	50-285 S	KANE, J.	8401040048*	FOIA
JOHNSON, B. D.	8401300223	50-255 P	JONES, W. C.	8401100329	50-285 P	KANE, J.	8401040052*	50-329 A
JOHNSON, B. D.	8401300324	50-255 P	JONES, W. C.	8401100426	50-285 V	KANE, R. S.	8401130265*	50-199 V
JOHNSON, C.	8401020318	50-317 P	JONES, W. C.	8401170158	50-285 Q	KANGA, B. K.	8401030129	50-320 S
JOHNSON, C.	8401110226*	WASTE MGT	JONES, W. C.	8401230131	50-285 F	KANGA, B. K.	8401030135	50-320 S
JOHNSON, C.	8401310014	50-329 A	JONES, W. C.	8401230317	50-285 S	KANGA, B. K.	8401040335	50-320 P
JOHNSON, E.	8401040353	50-498 Q	JONES, W. C.	8401230360	50-285 S	KANGA, B. K.	8401100354*	50-320 Q
JOHNSON, E. H.	8401040145	50-382 Q	JONES, W. C.	8401250022*	50-285 F	KANGA, B. K.	8401100363*	50-320 Q
JOHNSON, E. H.	8401040267	50-298 Q	JONES, W. C.	8401230054*	50-285 F	KANGA, B. K.	8401100398*	50-320 Q
JOHNSON, E. H.	8401040454*	50-438 Q	JONES, W. C.	8401260041*	50-285 F	KANGA, B. K.	8401160195	50-320 S
JOHNSON, E. H.	8401040460*	50-438 Q	JONES, W. C.	8401300157	50-285 F	KANGA, B. K.	8401170401*	50-320 Q
JOHNSON, E. H.	8401040463	50-298 Q	JONES, W. C.	8401310198*	50-285 F	KANGA, B. K.	8401190105	50-320 P
JOHNSON, E. H.	8401040491	50-443 Q	JONES, W. C.	8401310242	50-285 V	KANGA, B. K.	8401240074	50-320 S
JOHNSON, E. H.	8401090110	50-298 Q	JONES, W. C.	8401310302	50-285 P	KANGA, B. K.	8401240302	50-320 P
JOHNSON, E. H.	8401100310	50-267 P	JORDAN, D.	8401300238	50-329 Q	KANGA, B. K.	8401300123	50-320 H
JOHNSON, E. H.	8401100463	50-298 F		8401060619	71-511	KANYO, J. P.	8401090141*	50-483 F

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KANYO, J. P.	B401060022*	50-483 F	KENNY, T. J.	B401100382*	50-286 Q	KNAPP, M.	B401130466	WASTE
KANYO, J. P.	B401060041*	50-483 F	KENYON, B. D.	B401050266	50-387 F	KNIESER, O. W.	B401040530*	QA99
KANYO, J. P.	B401250049*	50-483 F	KENYON, B. D.	B401180327	50-387 R	KNIESER, O. W.	B401040538*	QA99
KANYO, J. P.	B401250075*	50-483 F	KENYON, B. D.	B401170291	50-387 R	KNIGHTON, O. W.	B312230326	50-5
KANYO, J. P.	B401310192*	50-483 F	KENYON, T. J.	B401160413	50-390 A	KNIGHTON, O. W.	B401090091	50-5
KAPLAN, S.	B401130098	50-304 S	KEPPLER, J. G.	B401040031*	50-358 R	KNIGHTON, O. W.	B401090711	50-4
KARMAN, M.	B401040116	50-482 Q	KEPPLER, J. G.	B401040102	50-315 Q	KNIGHTON, O. W.	B401110365	50-5
KARMAN, M.	B401040127	50-482 Q	KEPPLER, J. G.	B401050603	50-358 A	KNIGHTON, O. W.	B401160038	50-4
KARMAN, M.	B401120251	50-482 Q	KEPPLER, J. G.	B401050652	40-8760	KNIGHTON, O. W.	B401190113*	50-5
KARR, J. E.	B401160036	50-329 A	KEPPLER, J. G.	B401160295	50-237 S	KNIGHTON, O. W.	B401190123	50-5
KARR, J. E.	B401270370	50-329 A	KEPPLER, J. G.	B401160209	50-358 A	KNIGHTON, O. W.	B401190144	50-5
KARR, J. E.	B401270498	50-329 A	KEPPLER, J. G.	B401230192	50-358 A	KNIGHTON, O. W.	B401190201	50-5
KARR, J. E.	B401310136	50-329 A	KEPPLER, J. G.	B401240353	40-17	KNIGHTON, O. W.	B401250479	50-4
KARR, J. E.	B401310293	50-329 A	KERNB, R. E.	B401130360	NUREQ	KNIGHTON, O. W.	B401250486	50-2
KARR, J. E.	B401310336	50-329 A	KERS, L.	B401190364*	50-409 Q	KNIGHTON, O. W.	B401260509	50-4
KASSNER, T. F.	B401160443	NUREQ	KESSINGER, W.	B401160264	50-275 S	KNIGHTON, O. W.	B401270405	50-4
KAY, J. A.	B401040561	50-29 P	KESSINGER, W. W.	B401040261	50-275 S	KNIGHTON, O. W.	B401270510	50-5
KAY, J. A.	B401090204	50-29 P	KESSINGER, W. W.	B401120397	50-275 S	KNIGHTON, O. W.	B401270513	50-5
KAY, J. A.	B401100218	50-29 P	KESSINGER, W. W.	B401160296	50-275 S	KNIGHTON, O. W.	B401270535	50-4
KAY, J. A.	B401100402	50-29 F	KESSINGER, W. W.	B401260352	50-275 S	KNIGHTON, O. W.	B401300001	50-5
KAY, J. A.	B401100484	50-29 F	KETZLACH, N.	B401190102*	70-2946	KNIGHTON, O. W.	B401310181	50-5
KAY, J. A.	B401270319	50-29 Q	KIMBALL, J.	B401230192	50-329 Q	KNIGHTON, O. W.	B401310184*	50-5
KAY, J. A.	B401280223	50-29 P	KINNEMAN, J.	B401040356	40-6920	KNIGHTON, O. W.	B401310443	50-4
KAY, J. A.	B401300317	50-29 P	KINNEMAN, J.	B401180247	1&E	KNOP, R.	B401040462	50-5
KEARNEY, J. J.	B401090479	WASTE MGT	KINNEMAN, J.	B401180271	40-8610	KNOP, R.	B401100454	50-5
KEARNEY, J. J.	B401310255	WASTE MGT	KINNEMAN, J. D.	B401030017*	40-86	KNOP, R.	B401230392	50-5
KEATING, D. E.	B401050300*	50-454 G	KINNEMAN, J. D.	B401030030*	40-86	KNOP, R. C.	B401040277	50-5
KEDDIS, N. N.	B312050593	50-584 A	KINNEMAN, J. D.	B401030022*	40-86	KNOP, R. C.	B401040281*	50-4
KEEN, C. S.	B401030370	NUREQ	KINNEMAN, J. D.	B401030025*	40-86	KNOP, R. C.	B401100001	50-5
KEINIG, R. R.	B401190382*	50-334 G	KINNEMAN, J. D.	B401030031*	40-86	KNOP, R. C.	B401100003*	50-5
KEISER, H.	B401060324*	50-387 R	KINNEMAN, J. D.	B401030040*	40-86	KNOP, R. C.	B401100069	50-4
KEISER, H.	B401250031*	50-387 F	KINNEMAN, J. D.	B401030042*	40-86	KNOP, R. C.	B401100072*	50-4
KEISER, H.	B401250039*	50-387 F	KINNEMAN, J. D.	B401030046*	40-86	KNOP, R. C.	B401130278	50-5
KEISER, H.	B401310117*	50-387 F	KINNEMAN, J. D.	B401030048*	40-86	KNOP, R. C.	B401190395	50-4
KEISER, H. W.	B401030184	50-387 S	KINNEMAN, J. D.	B401030050*	40-86	KNOP, R. C.	B401230295	50-4
KEISER, H. W.	B401120260	50-387 S	KINNEMAN, J. D.	B401030052*	40-86	KNOP, R. C.	B401230510	50-5
KEISER, H. W.	B401120320	50-387 S	KINNEMAN, J. D.	B401030053*	40-86	KNOP, R. C.	B401230513*	50-5
KEISER, H. W.	B401130145	50-387 S	KINNEMAN, J. D.	B401030058*	40-86	KNOP, R. C.	B401300227	50-5
KEISER, H. W.	B401130258	50-387 S	KINNEMAN, J. D.	B401030060*	40-86	KNOP, R. C.	B401310356	50-4
KEISER, H. W.	B401130279	50-387 S	KINNEMAN, J. D.	B401030065*	40-86	KNOP, R. C.	B401310386	50-4
KEISER, H. W.	B401160155	50-387 S	KINNEMAN, J. D.	B401030082*	40-86	KOENIG, J. E.	B401030323*	50-5
KEISER, H. W.	B401260221	50-387 S	KINNEMAN, J. D.	B401030089*	40-86	KOENIG, O. L.	B401050070*	50-4
KEISER, H. W.	B401260276	50-387 S	KINNEMAN, J. D.	B401030111*	40-86	KOESTER, O. L.	B401100030	50-4
KEISER, H. W.	B401270017	50-387 S	KINNEMAN, J. D.	B401030114*	40-86	KOESTER, O. L.	B401100405	50-4
KEISER, H. W.	B401270079	50-387 S	KINNEMAN, J. D.	B401030115*	40-86	KOESTER, O. L.	B401100439	50-4
KEISER, H. W.	B401270128	50-387 S	KINNEMAN, J. D.	B401030118*	40-86	KOESTER, O. L.	B401130172*	50-4
KEISER, H. W.	B401270185	50-387 S	KINNEMAN, J. D.	B401030122*	40-86	KOESTER, O. L.	B401130328	50-4
KEISER, H. W.	B401270335	50-387 S	KINNEMAN, J. D.	B401030124*	40-86	KOESTER, O. L.	B401170213	50-4
KEITH, H.	B401160098	50-333 S	KINNEMAN, J. D.	B401030127*	40-86	KOESTER, O. L.	B401170398*	50-4
KEITH, H.	B401160182	50-333 S	KINNEMAN, J. D.	B401030130*	40-86	KOESTER, O. L.	B401180114	50-4
KEITH, H. N.	B401270303	50-333 S	KINNEMAN, J. D.	B401030131*	40-86	KOESTER, O. L.	B401230447	50-4
KELLER, E. L.	B401300108*	40-8331	KINNEMAN, J. D.	B401030132*	40-86	KOESTER, O. L.	B401270189	50-4
KELLER, H. W.	B401200064*	TOPREP	KINNEMAN, J. D.	B401030138*	40-86	KOESTER, O. L.	B401270490	50-4
KELLER, R.	B401300286*	50-443 G	KINNEMAN, J. D.	B401030139*	40-86	KOHLER, A. D.	B401260358	50-5
KELLEY, J. L.	B401050230	50-413 Q	KINNEMAN, J. D.	B401030140*	FOIA	KOLB, L. E.	B401260081	50-5
KELLEY, J. L.	B401050253	50-413 Q	KINNEMAN, J. D.	B401030142*	40-86	KOLB, M. W.	B401120373	50-5
KELLEY, J. L.	B401170268	50-413 Q	KINNEMAN, J. D.	B401030147*	40-86	KONKLIN, J.	B401230392	50-5
KELLEY, J. L.	B401250194	50-413 Q	KINNEMAN, J. D.	B401030151*	40-86	KONKLIN, J. E.	B401040285*	50-5
KELLEY, J. L.	B401310262	50-400 Q	KINNEMAN, J. D.	B401030154*	40-86	KONKLIN, J. E.	B401100005*	50-5
KELLY, E.	B401050318	50-322 S	KINNEMAN, J. D.	B401030156*	40-86	KONKLIN, J. E.	B401100076*	50-4
KELLY, E.	B401190389	50-322 S	KINNEMAN, J. D.	B401030164*	40-86	KONKLIN, J. E.	B401190399*	50-4
KELLY, E. M.	B401100331*	50-322 Q	KINNEMAN, J. D.	B401030168*	40-86	KONKLIN, J. E.	B401230523*	50-5
KELLY, E. M.	B401260177*	50-387 Q	KINNEMAN, J. D.	B401030171*	40-86	KONZEK, Q. J.	B401130220	NUREQ
KELLY, J. A.	B401300189*	50-285 Q	KINNEMAN, J. D.	B401030181*	40-86	KODD, W.	B401160014*	50-5
KELLY, L.	B401120230	50-286 R	KINNEMAN, J. D.	B401040148*	FOIA	KOVACK, T. J.	B401050257*	50-5
KELLY, L.	B401270267	50-286 R	KINTNER, L.	B401090796	50-352 E	KOZLOL, J. J.	B401200168*	50-5
KELLY, M. J.	B401040308	50-275 S	KINTNER, L. L.	B401060376	50-358 A	KOZLOWSKI, O.	B401060400*	50-5
KELLY, M. J.	B401040548	50-275 S	KINTNER, L. L.	B401110162	50-352 A	KOZLOWSKI, O.	B401300383*	50-5
KELLY, M. J.	B401120403	50-275 R	KIRK, G. B.	B401040436	50-328 S	KRAMER, F. W.	B401200064*	TOPREP
KELLY, M. J.	B401170211	50-275 R	KIRK, O. B.	B401050651	50-328 S	KRATZKE, R. T.	B401310477*	70-7
KEMPE, R. A.	B401100477*	QA999	KIRK, O. B.	B401120202	50-327 S	KRAUSE, D. F.	B401060435*	50-5
KEMPER, J. S.	B401040091	50-352 A	KIRK, O. B.	B401120356	50-327 S	KRAUSE, D. F.	B401060440*	50-5
KEMPER, J. S.	B401060290	50-352 Q	KIRK, O. B.	B401120383	50-328 S	KRAUSE, D. F.	B401130337*	50-5
KEMPER, J. S.	B401060357	50-352 Q	KIRK, O. B.	B401170198	50-328 S	KRAUSE, D. F.	B401310030	50-5
KEMPER, J. S.	B401090477	50-352 E	KIRKLAND, M. W.	B401170449	70-2786	KREH, J. L.	B401090361*	70-1
KEMPER, J. S.	B401190445	50-352 F	KIRKLAND, M. W.	B401170465	TOPREP	KREIDER, H. O.	B401030162	50-4
KEMPER, J. S.	B401200049	50-277 R	KIRCH, D. F.	B401300151*	50-206 Q	KRICH, R. M.	B401050376	50-5
KEMPER, J. S.	B401230024	50-352 A	KISTER, H.	B401120420	50-271 S	KRICH, R. M.	B401060406	50-5
KEMPER, J. S.	B401230189	50-352 S	KIZLAR, F. M.	B401090354	PR	KRICH, R. M.	B401100014	50-5
KEMPER, J. S.	B401260239	50-352 S	KLEHS, J.	B401240227	50-275 U	KRICH, R. M.	B401270325	50-5
KEMPER, J. B.	B401260303	50-352 S	KLEIN, T. J.	B401040147	40-1162	KRICH, R. M.	B401300058	50-5
KEMPER, J. B.	B401260372	50-352 S	KLEINSORGE, W. P.	B401030276*	50-424 Q	KRIEGER, R. W.	B401040165	50-5
KEMPER, J. B.	B401270215	50-352 S	KLEINSORGE, W. P.	B401240278*	50-250 Q	KRIMM, R. W.	B401030219	50-5
KEMPER, J. B.	B401310395	50-352 C	KLINE, J. R.	B401230403	50-440 Q	KRIMM, R. W.	B401030244	50-5
KENNEDY, G. P.	B401100256*	QA999	KLINGLER, O.	B401130280	50-329 S	KRIMM, R. W.	B401030246	50-5

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KRIMM, R. W.	B401030264	50-312 F	LEE, J	B401190342*	50-289 Q	LEWIS, R. C.	B401060436	50-348 F
KRIMM, R. W.	B401090359	50-322 Q	LEE, J	B401190344*	50-289 Q	LEWIS, R. C.	B401060441	50-390 Q
KRIMM, R. W.	B401090515	50-309 F	LEE, J	B401300322	50-289 Q	LEWIS, R. C.	B401060442*	50-250 Q
KRIMM, R. W.	B401170269	50-280 F	LEE, J. N.	B401120253	50-338 R	LEWIS, R. C.	B401060448*	50-390 Q
KRIMM, R. W.	B401170274*	50-280 F	LEE, J. N.	B401270484	50-338 R	LEWIS, R. C.	B401060449	50-390 Q
KRIMM, R. W.	B401170408	50-338 F	LEE, O. R.	B401100151	50-267 Q	LEWIS, R. C.	B401060458*	50-390 Q
KRIMM, R. W.	B401170412	50-277 F	LEE, O. R.	B401130293	50-267 Q	LEWIS, R. C.	B401060490	50-424 A
KRIMM, R. W.	B401180061	50-344 F	LEE, O. R.	B401130390	50-267 P	LEWIS, R. C.	B401090323	50-302 Q
KRIMM, R. W.	B401180103	50-482 F	LEE, O. R.	B401130396*	50-267 P	LEWIS, R. C.	B401090332*	50-302 Q
KRIMM, R. W.	B401180163	50-373 F	LEE, O. R.	B401270140	50-267 P	LEWIS, R. C.	B401090374	50-416 Q
KRIMM, R. W.	B401180189	50-322 F	LEE, O. R.	B401270145*	50-267 P	LEWIS, R. C.	B401090385*	50-416 Q
KRIMM, R. W.	B401180246	50-317 F	LEE, O. R.	B4011270395	50-267 P	LEWIS, R. C.	B401090426	50-424 Q
KRIMM, R. W.	B401300209	50-3 F	LEE, T. A.	B401120173	WASTE MGT	LEWIS, R. C.	B401090437*	50-424 Q
KRIMM, R. W.	B401300213*	50-3 F	LEE, T. A.	B401130066	WASTE MGT	LEWIS, R. C.	B401090443*	50-302 Q
KRUEGER, J. E.	B401270350*	50-344 P	LEECH, P. H.	B401270170	50-293 P	LEWIS, R. C.	B401090464	50-424 Q
KRUG, H.	B401050633*	50-321 Q	LEONITTO, J.	B401160445	50-358 Q	LEWIS, R. C.	B401100229	50-280 F
KRUG, H. E.	B401090219*	50-269 Q	LEHNER, J. R.	B401160284*	50-219 P	LEWIS, R. C.	B401100307	50-338 F
KRUMPHOLZ, P. J.	B401170355*	50-282 Q	LEMPGEB, T. E.	B401030121	50-220 B	LEWIS, R. C.	B401170215	50-327 F
KRUZIC, R. W.	B401160020	71-9107	LEMPGEB, T. E.	B401030260	50-220 S	LEWIS, R. C.	B401170321	50-259 F
KUCZYNSKI, L. A.	B401120327	50-387 R	LEMPGEB, T. E.	B401130291	50-220 S	LEWIS, R. C.	B401240142	50-302 P
KUCZYNSKI, L. A.	B401130145	50-387 S	LEMPGEB, T. E.	B401160160	50-220 S	LEWIS, R. C.	B401240195	TOPREP
KUCZYNSKI, L. A.	B401170291	50-387 R	LEMPGEB, T. E.	B401160168	50-220 S	LEWIS, R. C.	B401240317	50-390 Q
KUCZYNSKI, L. A.	B401270017	50-387 S	LEMPGEB, T. E.	B401170007	50-220 R	LEWIS, R. C.	B401240319	50-369 Q
KUCZYNSKI, L. A.	B401270079	50-387 S	LEMPGEB, T. E.	B401240155	50-220 P	LEWIS, R. C.	B401240334	50-438 Q
KUHRTZ, S. G.	B401030188*	40-86	LEMPGEB, T. E.	B401240185	50-220 P	LEWIS, R. C.	B401240341*	50-438 Q
KUMAR, P. A.	B401110313*	50-352 A	LEMPGEB, T. E.	B401250097	50-220 F	LEWIS, R. C.	B401240348*	50-369 Q
KUNCL, L. Q.	B401270083	50-298 P	LEMPGEB, T. E.	B401270137	50-220 S	LEWIS, R. C.	B401240391	50-302 Q
KUPPERMAN, D. B.	B401160443	NUREQ	LENTINE, F. O.	B40100468	50-295 P	LEWIS, R. C.	B401240396*	50-302 Q
KUSHNER, R.	B401260315*	70-135	LENTINE, F. O.	B401300265	50-295 P	LEWIS, R. C.	B401240421	50-302 F
LACEY, W. S.	B401030240	50-334 B	LEBBY, R. P.	B401040114	50-443 Q	LEWIS, R. C.	B401240422*	50-259 Q
LACEY, W. S.	B401040501	50-334 P	LEBBY, R. P.	B401120193	50-443 Q	LEWIS, R. C.	B401240433*	50-302 Q
LACEY, W. S.	B401120228	50-334 B	LEBBY, R. P.	B401250218	50-443 Q	LEWIS, R. C.	B401240443	50-406 Q
LACEY, W. S.	B401120313	50-334 B	LETSCHKE, K.	B401030148	50-322 Q	LEWIS, R. C.	B401240500	50-259 F
LACEY, W. S.	B401270148	50-334 B	LETSCHKE, K.	B401030148	50-322 Q	LEWIS, R. C.	B401240524	50-390 Q
LACEY, W. S.	B401310122*	50-334 F	LETSCHKE, K. J.	B401170278*	50-322 Q	LEWIS, R. C.	B401240533	50-160 Q
LAHEY, R. T.	B401030340	NUREQ	LETSCHKE, K. J.	B401170278*	50-322 Q	LEWIS, R. C.	B401240541*	50-390 Q
LAHEY, R. T.	B401250134	NUREQ	LEWIS, H. A.	B401050681*	50-280 Q	LEWIS, R. C.	B401240586	50-348 Q
LAHY, R. T.	B401260101	NUREQ	LEUTWILER, N. R.	B401310251	WASTE MGT	LEWIS, R. C.	B401240588*	50-321 Q
LAMASTRA, M. A.	B005070405*	70-83	LEVIN, H. A.	B401040379	50-329 A	LEWIS, R. C.	B401240587*	50-348 Q
LAMASTRA, M. A.	B010310427*	FOIA	LEVIN, H. A.	B401060281	50-329 A	LEWIS, R. C.	B401240579	50-321 Q
LAMBERTUS, H.	B401250150*	40-147B	LEVIN, H. A.	B401060294*	50-329 A	LEWIS, R. C.	B401240581*	50-302 Q
LAMBERTUS, H.	B401250153*	40-147B	LEVIN, H. A.	B401120039	50-329 A	LEWIS, R. C.	B401240586	50-390 Q
LAMBERTUS, H.	B401250157*	40-147B	LEVIN, H. A.	B401170380	50-329 R	LEWIS, R. C.	B401240588*	50-321 Q
LANDAU, M.	B401030342	NUREQ	LEVIN, H. A.	B401170385*	50-329 R	LEWIS, R. C.	B401240601*	50-390 Q
LANDIS, K.	B401050394*	50-335 Q	LEVIN, H. A.	B401230158	50-329 A	LEWIS, R. C.	B401240603*	50-390 Q
LANDIS, K.	B401050614*	50-338 Q	LEVIN, H. A.	B401230489	50-329 A	LEWIS, R. C.	B401270010*	50-416 F
LANDIS, K.	B401050622*	50-338 Q	LEVIN, H. A.	B401310327	50-329 A	LEWIS, R. C.	B401300106	50-280 F
LANDIS, K. D.	B401050839*	50-338 Q	LEVINE, J. M.	B401250060*	50-313 F	LEWIS, R. C.	B401300115	50-338 F
LANDIS, K. D.	B401050563*	50-250 Q	LEVINE, J. M.	B401250085*	50-313 F	LEV, M.	B401260217*	50-320 F
LANDIS, K. D.	B401050681*	50-280 Q	LEVINE, J. M.	B401260251*	50-313 F	LEV, M.	B401050022	TOPREP
LANDSMAN, R. B.	B401190286*	50-329 Q	LEVINE, J. M.	B401260305*	50-313 F	LEV, M.	B401060516	TOPREP
LANE, V. H.	B401310297	50-352 Q	LEVINE, J. M.	B401300364*	50-313 F	LEV, M.	B401090316	TOPREP
LANGE, O. R.	B401300269*	50-409 P	LEVY, S.	B401170119*	CONTRACT	LICITRA, E. A.	B401090174	50-528 F
LANKSBURY, R. D.	B401300026*	50-373 Q	LEWIS, O. S.	B309218000*	REVIEW GRP	LICITRA, E. A.	B401180013*	50-528 A
LANNING, D. D.	B401310449	NUREQ	LEWIS, O. S.	B311300135	REVIEW GRP	LIDEN, E. A.	B401040175	50-272 P
LANPHER, L. C.	B401060386	50-322 Q	LEWIS, O. S.	B311300135	REVIEW GRP	LIDEN, E. A.	B401040203	50-272 P
LANPHER, L. C.	B401180288*	50-322 T	LEWIS, J. R.	B4011300220	NUREQ	LIDEN, E. A.	B401100010	50-272 B
LANPHER, L. C.	B401180288*	50-322 T	LEWIS, M.	B401090482	PRM	LIDEN, E. A.	B401100419*	50-272 Q
LANPHER, L. C.	B401200132	50-322 Q	LEWIS, M. I.	B401040372	50-352 H	LIDEN, E. A.	B401110094	50-272 P
LANPHER, L. C.	B401200132	50-322 Q	LEWIS, M. I.	B401100205	50-289 Q	LIDEN, E. A.	B401110149	50-272 F
LARSEN, C.	B401110313*	50-352 A	LEWIS, M. I.	B401100223	50-289 Q	LIDEN, E. A.	B401110153	50-272 F
LARSON, C. E.	B401060354	50-263 R	LEWIS, M. I.	B401180238	50-289 Q	LIDEN, E. A.	B401130134*	50-272 Q
LARSON, O. S.	B401100143*	WASTE MGT	LEWIS, M. B.	B401160117	WASTE MGT	LIDEN, E. A.	B401130143*	50-272 Q
LARSON, O. S.	B401240188	WASTE MGT	LEWIS, R. C.	B401050218	50-389 Q	LIDEN, E. A.	B401160186	50-272 F
LARSON, O. S.	B401310344	40-8760	LEWIS, R. C.	B401050259	50-424 Q	LIDEN, E. A.	B401200185	50-272 F
LASUN, S. R.	B401240358*	40-17	LEWIS, R. C.	B401050388	50-400 Q	LIDEN, E. A.	B401200215	50-272 P
LAUDEN, K.	B401110494	40-299	LEWIS, R. C.	B401050392*	50-400 Q	LIDEN, E. A.	B401230461*	50-272 Q
LAURENBERG, F. R.	B401060391	50-289 U	LEWIS, R. C.	B401050481	50-324 Q	LIDEN, E. A.	B401301265	50-272 R
LAURENBERG, J. A.	B401060362	50-322 Q	LEWIS, R. C.	B401050482	50-338 Q	LIEBERMAN, E. S.	B401190170*	50-322 Q
LAURENBERG, J. A.	B401180206	50-322 Q	LEWIS, R. C.	B401050508*	50-338 Q	LIN, C. C.	B401160284*	50-219 F
LAURENBERG, J. A.	B401240305	50-322 Q	LEWIS, R. C.	B401050510*	50-324 Q	LIN, D.	B401120215	50-373 R
LAURENBERG, J. A.	B401260297*	50-373 F	LEWIS, R. C.	B401050515	50-390 Q	LIN, D. L.	B401170402	50-373 R
LAWLESS, F.	B401060333	40-8084	LEWIS, R. C.	B401050537*	50-390 Q	LINDER, F.	B401030201	50-409 P
LAZO, L.	B401090154	50-412 A	LEWIS, R. C.	B401050540*	50-250 Q	LINDER, F.	B401050646	50-409 B
LAZO, L.	B401090157	50-412 A	LEWIS, R. C.	B401050543	50-302 Q	LINDER, F.	B401060261	50-409 B
LAZO, L.	B401120457	50-412 A	LEWIS, R. C.	B401050559*	50-302 Q	LINDER, F.	B401100011	50-409 P
LE, H. C.	B401260077	50-259 B	LEWIS, R. C.	B401050560	50-348 Q	LINDER, F.	B401100356*	50-409 Q
LEAVY, W. F.	B401300141*	CONTRACT	LEWIS, R. C.	B401080602	50-302 Q	LINDER, F.	B401100369*	50-409 Q
LEDDICK, R. B.	B401180172	50-382 K	LEWIS, R. C.	B401050611*	50-348 Q	LINDER, F.	B401120381	50-409 R
LEDDICK, R. B.	B401240505	50-382 S	LEWIS, R. C.	B401050635*	50-302 Q	LINDER, F.	B401130001	50-409 B
LEDDICK, R. B.	B401270331*	50-382 Q	LEWIS, R. C.	B401080671*	50-280 Q	LINDER, F.	B401130148	50-409 B
LEE, H.	B401250129	NUREQ	LEWIS, R. C.	B401060307	50-413 A	LINDER, F.	B401130207	50-409 P
LEE, J.	B401180202	50-289 H	LEWIS, R. C.	B401060365	50-413 Q	LINDER, F.	B401160254	50-409 B
LEE, J.	B401190336	50-289 Q	LEWIS, R. C.	B401060392*	50-302 Q	LINDER, F.	B401160270	50-409 B
LEE, J.	B401190339*	50-289 Q	LEWIS, R. C.	B401060414	TOPREP	LINDER, F.	B401170202	50-409 F

497

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LINDER, F.	8401230183	50-409 S	LYONS, P J L	8401120432	40-299	HANDIL, I H	84010303010*	CONTRACT
LINDER, F.	8401240303*	50-409 Q	LYONS, P J L	8401310459	40-299	MANEATIS, G A	8401040287	50-273 P
LINDER, F.	8401250103	50-409 P	LYONS, W	8401030370	NUREQ	MANEATIS, G A	8401170294	50-273 Q
LINDER, F.	8401290364*	50-409 F	LYONS, W	8401270059	50-317 S	MANAN, C V	8401230314*	50-220 P
LINDER, F.	8401260001	50-409 F	LYONS, W T	8401160093	50-317 S	MANAN, C V	8312280405	50-220 K
LINDER, F	8401260017*	50-409 F	MACDONALD, C E	8401060328	71-510	MANAN, C V	8401030194	50-220 P
LINDER, F	8401300266	50-409 P	MACDONALD, C E	8401060677	71-9184	MANAN, C V	8401030238	50-410 S
LINDER, F	8401300316	50-409 V	MACDONALD, C E	8401110563	71-9165	MANAN, C V	8401040479	50-410 A
LINDER, F	8401310224*	50-409 Q	MACDONALD, C E	8401110565*	71-9165	MANAN, C V	8401090239	50-220 F
LINDER, R.	8401290303*	50-244 P	MACDONALD, C E	8401110567*	71-9165	MANAN, C V	8401090326	50-220 F
LINDSTROM, M	8401090045	XPORTLIC	MACDONALD, C E	8401170272	71-4909	MANAN, C V	8401100361	50-220 P
LINNEHAN, J J	8401060250	40-8829	MACDONALD, C E	8401170275*	71-4909	MANAN, C V	8401130067	50-220 P
LINNEHAN, J J	8401060604	40-8829	MACDONALD, C E	8401170526	71-6058	MANAN, C V	8401130071*	50-220 P
LINNEHAN, J J	8401060674*	40-8768	MACDONALD, C E	8401170529*	71-6058	MANAN, C V	8401130321	50-410 S
LINENBERGER, G	8401300089	50-537 Q	MACDONALD, C E	8401190103	71-9092	MANAN, C V	8401130342	50-410 S
LINENBERGER, O	8401300232	50-293 Q	MACDONALD, C E	8401190110	71-9093	MANAN, C V	8401160100	50-410 S
LINTAKAS, A	8401060268	50-373 S	MACDONALD, C E	8401200272	71-9853	MANAN, C V	8401190365	50-220 P
LINVILLE, J C	8401240330*	50-272 Q	MACDONALD, C E	8401200280*	71-9853	MANAN, C V	8401190366*	50-220 P
LIPINSKI, D R.	8401180249*	50-245 Q	MACDONALD, C E	8401200293	71-5797	MANAN, C V	8401230308	50-220 P
LITTLE, B H	8401100076*	50-483 Q	MACDONALD, C E	8401200299*	71-5797	MANAN, C V	8401230576*	50-220 F
LITTLE, L W	8401230408	50-289 Q	MACDONALD, C E	8401270526	71-5450	MANAN, C V	8401270092	50-410 A
LITTLE, W S	8401050296	50-454 Q	MACDONALD, C E	8401270530*	71-5450	MANNING, W J	8401240255	50-454 A
LITTLE, W S	8401100481	50-282 Q	MACDONALD, C E	8401310448	71-5797	MANNING, W J	8401240261*	50-454 A
LITTLE, W S	8401120222	50-483 Q	MACDONALD, C E	8401310450*	71-5797	MANN, S. F.	8401240100	50-410 A
LITTLE, W S	8401120225*	50-483 Q	MACDONALD, C E	8401310453	71-9134	MANN, S. F.	8401270108	50-410 S
LITTLE, W S	8401120379	50-409 Q	MACDONALD, C E	8401310454*	71-9134	MANN, S. F.	8401270449	50-410 S
LITTLE, W S	8401260141	50-440 Q	MACDONALD, C E	8401310463	71-94	MANSFIELD, S D.	8401240135	50-302 B
LIU, W.	8401090150*	50-390 Q	MACDONALD, C E	8401310464*	71-94	MARBITO, R	8401040418	50-461 B
LIU, W C	8401050546*	50-390 Q	MACDONALD, C E	8401310466	71-251	MARCHI, M L	8401160278	50-305 S
LIU, W C	8401060462*	50-390 Q	MACDONALD, C E.	8401310467*	71-251	MARGULIES, M B.	8401310248	50-412 Q
LIU, W. C.	8401060478*	50-390 Q	MACDONALD, J B.	8401180265*	50-244 Q	MARIMPIETRI, A.	8401050309*	50-408 F
LLOYD, L L	8401250239	PR	MACHADO, C. K	8401100248	50-416 H	MARKEE, E. H.	8401280154	50-352 T
LOBNER, P.	8401100030*	FOIA	MACHADO, C. K	8401120191	50-416 H	MARKEE, E. J.	8401200057*	COMMISSION
LOBNER, P.	8401100037*	FOIA	MACKAY, S. D.	8401190021	50-324 F	MARKEE, E. J.	8401310172*	50-275 U
LOBNER, P.	8401100040*	FOIA	MACKAY, S. D.	8401260267	50-324 F	MARKT, D.	8401060072*	50-271 F
LOCKHART, W J.	8401100232	WASTE MGT	MACKAY, S. D.	8401260274	50-324 F	MARKT, D.	8401260054*	50-29 F
LOCKHART, W J	8401100232	WASTE MGT	MACRAE, J. B.	8401090680	ORG	MARSHALL, J. R	8401030120	50-368 S
LOCKWOOD, O J	8401130103	NUREQ	MACRAE, J. B.	8401090683	ORG	MARSHALL, J. R.	8401030170	50-313 S
LOHHAUS, P H	8401130133	WASTE MGT	MACRAE, J. B.	8401090689	ORG	MARSHALL, J. R.	8401030291	50-368 S
LOHHAUS, P. H.	8401170597	WASTE MGT	MACRAE, J. B.	8401100490	ORG	MARSHALL, J. R.	8401040212*	50-313 Q
LOIGONN, G A	8401120283*	50-395 R	MADDEN, W	8401030176*	50-3	MARSHALL, J. R.	8401040270	50-368 P
LOIGONN, G A	8401120295*	50-395 R	MADDEN, W. J.	8401240321*	50-247 Q	MARSHALL, J. R	8401040432*	50-313 Q
LOIGONN, G A	8401270379*	50-395 R	MADISON, A.	8401160161	50-237 S	MARSHALL, J. R	8401040485	50-313 P
LOIGONN, G A	8401270392*	50-395 R	MADISON, A.	8401230258	50-373 S	MARSHALL, J. R	8401040541	50-313 P
LOIGONN, G A	8401270393*	50-395 R	MADISON, A. L	8401270366*	50-373 Q	MARSHALL, J. R	8401050577	50-368 P
LONDREB, E. J.	8401170327*	50-344 A	MADSEN, Q	8401170282*	QA999	MARSHALL, J. R	8401060186*	50-313 F
LOND, J N.	8401160259	50-344 S	MADSEN, Q. L.	8401040477	50-298 Q	MARSHALL, J. R	8401100052	50-313 S
LOND, J N.	8401270489	50-344 S	MADSEN, Q. L.	8401130382*	QA999	MARSHALL, J. R	8401100342	50-368 S
LOND, J N.	8401300187	50-344 S	MADSEN, Q. L.	8401170325*	QA999	MARSHALL, J. R	8401100368	50-368 S
LOMENECHER, D.	8401310257	50-289 H	MADSEN, Q. L.	8401230202*	QA999	MARSHALL, J. R.	8401120396	50-313 R
LORTON, J.	8401310139	50-250 Q	MADSEN, Q. L.	8401270253*	QA999	MARSHALL, J. R	8401120418	50-368 R
LOUITO, E. L	8401290159	50-317 R	MADSEN, Q. L.	8401270276*	50-382 Q	MARSHALL, J. R	8401130210	50-313 S
LOUX, R	8401110282*	WASTE MGT	MADSEN, Q. L.	8401270282*	50-382 Q	MARSHALL, J. R	8401130215	50-313 S
LOVE, A R	8401260159	50-352 Q	MADSEN, Q. L.	8401270444*	QA999	MARSHALL, J. R	8401130318	50-313 S
LOVELACE, W.	8401180102*	50-528 A	MADSEN, M. M.	8401260079	NUREQ	MARSHALL, J. R	8401130339*	50-313 Q
LUBENAU, J D	8401090663	NUREQ	MADSEN, M. M.	8401310455*	WASTE MGT	MARSHALL, J. R	8401170264*	50-313 Q
LUCK, W. D.	8401100149	50-537 Q	MAHON, G R.	8401270281	50-317 S	MARSHALL, J. R.	8401170307	50-313 S
LUCKS, A. B	8401100234*	50-329 Q	MAIER, J. E.	8401040137	50-244 P	MARSHALL, J. R.	8401170351	50-368 F
LUCKS, A. B	8401100228*	50-329 Q	MAIER, J. E.	8401040174	50-244 F	MARSHALL, J. R.	8401170377	50-313 F
LUCKS, A. B	8401240610	50-329 A	MAIER, J. E.	8401040346	50-244 P	MARSHALL, J. R.	8401170382	50-313 P
LUDDIN, Q. H	8401110500	40-8829	MAIER, J. E.	8401040348*	50-244 P	MARSHALL, J. R.	8401170487*	50-313 Q
LUEBKE, E. A.	8401200111	50-142 Q	MAIER, J. E.	8401040513	50-244 P	MARSHALL, J. R.	8401230242	50-313 S
LUEBKE, E. A.	8401200138	50-142 Q	MAIER, J. E.	8401100336	50-244 P	MARSHALL, J. R	8401230254	50-368 S
LUEBKE, E. A.	8401200161	50-142 Q	MAIER, J. E.	8401170009	50-244 P	MARSHALL, J. R.	8401230473	50-368 S
LUEBKE, E. A.	8401300237	50-142 Q	MAIER, J. E.	8401170152	50-244 P	MARSHALL, J. R.	8401230492	50-313 Q
LUEHMANN, J D	8401050539*	50-338 Q	MAIER, J. E.	8401170362*	50-244 Q	MARSHALL, J. R.	8401240182	50-313 F
LUEHMANN, J D.	8401050614*	50-338 Q	MAIER, J. E.	8401230227	50-244 P	MARSHALL, J. R.	8401260027*	50-313 F
LUEHMANN, J D.	8401050622*	50-338 Q	MAIER, J. E.	8401250016	50-244 P	MARSHALL, J. R	8401260318*	50-313 F
LUEHMANN, J D	8401090596*	50-338 Q	MAIER, J. E.	8401250019*	50-244 P	MARSHALL, J. R.	8401270399	50-313 R
LUEHMANN, J D	8401240553*	50-338 Q	MAIER, J. E.	8401250095*	50-244 F	MARSHALL, J. R.	8401270402	50-368 R
LUNA, R F	8401030345*	CONTRACT	MAIER, J. E.	8401250104	50-244 F	MARSHALL, J. R	8401270305	50-313 Q
LUNA, R. E.	8401260079	NUREQ	MAIER, J. E.	8401250260	50-244 P	MARSHALL, J. R.	8401310237	50-313 P
LUNA, R. E.	8401300101*	WASTE MGT	MAIER, J. E	8401250275*	50-244 P	MARSHALL, J. R.	8401310312	50-313 P
LUNDVALL, A. E.	8401100176*	50-317 Q	MAIER, J. E.	8401250289	50-244 P	MARSHALL, J. R.	8401310460*	50-313 F
LUNDVALL, A. E	8401130253*	50-317 Q	MAIER, J. E	8401250292*	50-244 P	MARTIN, D. E.	8401090660	40-3453
LUNDVALL, A. E	8401190326	50-317 V	MAIER, J. E.	8401250297*	50-244 P	MARTIN, J. B	8401030226	50-312 (
LUNDVALL, A. E.	8401240277*	50-317 Q	MAIER, J. E	8401250132	50-244 H	MARTIN, J. B.	8401030230*	50-312 (
LUNDVALL, A. E	8401240403	50-317 R	MAIER, J. E.	8401310212*	50-244 F	MARTIN, J. B.	8401250514	State Prop
LYONS, J E	8401110143	50-213 P	MAIER, J. E.	8204220376*	50-382 A	MARTIN, J. D	8401260072	50-397 B
LYONS, J. E.	8401240403	50-213 P	MALBCH, M. G.					
LYONS, P. J	8401110483	40-299	MALBCH, M. G.	8205280489*	50-250 Q	MARTIN, R. E	8401030177	50-352 E
LYONS, P. J.	8401270142	40-299	MALBCH, M. G.	8401250106*	50-289 P	MARTIN, T. T.	8401030169	50-5 Q
LYONS, P. J.	8401270155	40-299	MALBCH, M. G.	8401250240*	FOIA	MARTIN, T. T.	8401030195*	40-86 Q
LYONS, P. J.	8401270172*	40-299	MALBCH, M. G.	8401250333*	50-274 P	MARTIN, T. T.	8401030255	50-289 Q
LYONS, P. J.	8401270179	40-299	MANCHER, R. R.	8401310068*	CONTRACT	MARTIN, T. T.	8401040163	50-334 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ARTIN, T. T.	8401040423	50-317 Q	MCALPINE, E. J.	8401300288	70-143	McKENNA, E. M.	8401270340	50-206 F
ARTIN, T. T.	8401050270	50-272 F	MCBREARTY, R. A.	8401100372*	50-352 Q	McKINNEY, C. J.	8401170209	50-393 S
ARTIN, T. T.	8401100063	50-271 Q	MCCABE, E.	8401190347	50-387 S	McKINNEY, C. J.	8401240132	50-393 S
ARTIN, T. T.	8401100170	50-317 Q	MCCABE, E. C.	8401030262*	50-322 Q	McKINNON, M. A.	8401130220	NUREG
ARTIN, T. T.	8401100199	50-334 Q	MCCABE, E. C.	8401030273*	50-322 Q	McLAUGHLIN, L.	8401040420	50-389 S
ARTIN, T. T.	8401100227	50-387 Q	MCCABE, E. C.	8401100331*	50-322 Q	McLAUGHLIN, L.	8401120326	50-389 S
ARTIN, T. T.	8401100239	70-287 F	MCCABE, E. C.	8401180268*	50-387 Q	McLAUGHLIN, L.	8401260094	50-389 S
ARTIN, T. T.	8401100279	50-247 Q	MCCAFFREY, B. R.	8401090338	50-322 F	MCLEAN, M. A.	8401130220	NUREG
ARTIN, T. T.	8401100300	50-309 Q	MCCAFFREY, B. R.	8401110240	50-322 A	MCLEAREN, T.	8401130443	CONTRACT
ARTIN, T. T.	8401100320	50-443 Q	MCCAFFREY, B. R.	8401240107	50-322 A	MCLEOD, K. W.	8401090606	NUREG
ARTIN, T. T.	8401100343	40-672	MCCAFFREY, B. R.	8401240388	50-322 A	MCNABB, M.	8401170247	WASTE MGT
ARTIN, T. T.	8401100365	50-352 Q	MCCAFFREY, B. R.	8401240411	50-322 E	MCNAMARA, A.	8401180411	50-244 R
ARTIN, T. T.	8401100370	50-410 Q	MCCAFFREY, B. R.	8401240548	50-322 V	MCNAMARA, A. E.	8401270292	50-244 R
ARTIN, T. T.	8401100376	50-388 Q	MCCANN, W. J.	8401160118	50-293 S	MCNAMARA, E. J.	8401170363*	TOPREP
ARTIN, T. T.	8401100385	50-272 Q	MCCANN, W. J.	8401160175	50-293 S	MCNAMARA, E. J.	8401170367*	TOPREP
ARTIN, T. T.	8401100439	70-2427	MCCANN, W. J.	8401240143	50-293 S	MCNAMARA, E. J.	8401170371*	TOPREP
ARTIN, T. T.	8401100460	50-333 Q	MCCLEBKEY, E. B.	8401180212	50-322 Q	MCNEIL, M. B.	8401190343	WASTE MGT
ARTIN, T. T.	8401100460	50-443 F	MCCLEBKEY, E. B.	8401160212	50-322 Q	MCNEIL, W. M.	8401230220*	QA999
ARTIN, T. T.	8401100323	50-269 Q	MCCLURE, J. D.	8401260079	NUREG	MCNEILL, C. A.	8401130235	50-333 S
ARTIN, T. T.	8401160176	50-423 A	MCCLURE, J. D.	8401300101*	WASTE MGT	MCNEILL, C. A.	8401130274	50-333 R
ARTIN, T. T.	8401180193	50-352 Q	MCCOLLOM, K. A.	8401310222	50-445 Q	MCNEILL, C. A.	8401130359	50-333 S
ARTIN, T. T.	8401180214	50-322 Q	MCCORD, R. K.	8401100476*	REVIEW GRP	MCNEILL, C. A.	8401160032	50-333 S
ARTIN, T. T.	8401180221	50-334 Q	MCCORD, R. K.	8401270318*	50-382 Q	MCNEILL, C. A.	8401160098	50-333 S
ARTIN, T. T.	8401180242	50-352 Q	MCCORRICK, G. W.	8401270261	50-309 R	MCNEILL, C. A.	8401160162	50-333 S
ARTIN, T. T.	8401180266	50-245 Q	MCCUMBER, J. T.	8401090185	XPORTLIC	MCNEILL, C. A.	8401270139	50-333 S
ARTIN, T. T.	8401190171	50-272 F	MCDONALD, D. D.	8401050038	FOIA	MCNEILL, C. A.	8401270303	50-333 S
ARTIN, T. T.	8401190345	50-322 Q	MCDONALD, D. D.	8401090704	50-250 P	MCNEILL, C. A.	8401270427	50-333 S
ARTIN, T. T.	8401190376	50-220 Q	MCDONALD, D. D.	8401190337	50-250 P	MEDFORD, M. O.	8401080226	50-206 F
ARTIN, T. T.	8401190433	50-27 Q	MCDONALD, J. Y.	8401050153*	CONTRACT	MEDFORD, M. O.	8401050649	50-361 P
ARTIN, T. T.	8401240056	50-272 Q	MCDUFFIE, H. A.	8401050305	50-400 F	MEDFORD, M. O.	8401100018	50-361 Q
ARTIN, T. T.	8401240274	50-317 Q	MCDUFFIE, H. A.	8401120385	50-261 P	MEDFORD, M. O.	8401100067	50-361 P
ARTIN, T. T.	8401240280	50-317 Q	MCDUFFIE, H. A.	8401180133	50-261 P	MEDFORD, M. O.	8401110270	50-206 F
ARTIN, T. T.	8401240307	50-314 Q	MCDUFFIE, H. A.	8401200188	50-261 P	MEDFORD, M. O.	8401130273	50-206 F
ARTIN, T. T.	8401240308	50-412 Q	MCDUFFIE, H. A.	8401230470	50-400 K	MEDFORD, M. O.	8401170200	50-206 F
ARTIN, T. T.	8401240343	50-3 Q	MCFARLAND, C. R.	8401050323*	50-438 Q	MEDFORD, M. O.	8401180234	50-206 F
ARTIN, T. T.	8401240445	50-289 Q	MCGARRY, J. M.	8401050247	50-413 Q	MEDFORD, M. O.	8401200219	50-206 F
ARTIN, T. T.	8401240466	50-29 Q	MCGARRY, J. M.	8401050247	50-413 Q	MEDFORD, M. O.	8401230487	50-361 F
ARTIN, T. T.	8401240468	50-423 Q	MCGARRY, J. M.	8401160258	50-413 Q	MEDFORD, M. O.	8401240147	50-206 F
ARTIN, T. T.	8401240504	50-352 Q	MCGARRY, J. M.	8401160258	50-413 Q	MEDFORD, M. O.	8401270218	50-206 F
ARTIN, T. T.	8401240513	50-247 Q	MCGARRY, J. M.	8401180222	50-413 Q	MEDFORD, M. O.	8401270376	50-362 P
ARTIN, T. T.	8401240516	50-271 Q	MCGARRY, J. M.	8401180222	50-413 Q	MEDFORD, M. O.	8401310401	50-206 F
ARTIN, T. T.	8401260182	50-412 Q	MCGARRY, J. M.	8401200144	50-413 Q	MENDEZ, R.	8401120225*	50-483 Q
ARTIN, T. T.	8401260194	50-388 Q	MCGARRY, J. M.	8401200144	50-413 Q	MENDEZ, R. C.	8401130281	50-315 S
ARTIN, T. T.	8401260300	50-336 Q	MCGARRY, J. M.	8401240300*	50-413 Q	MESLER, R. B.	8401170340	50-148 F
ARTIN, T. T.	8401260308	70-135	MCGARRY, J. M.	8401240300*	50-413 Q	MEYER, G. W.	8401310166*	50-277 Q
ARTIN, T. T.	8401260367	50-289 Q	MCGARRY, J. M.	8401310343	50-413 Q	MEYER, H. R.	8312270412	NUREG
ARTIN, T. T.	8401300270	50-244 Q	MCGAUGHY, J. P.	8401060165*	50-416 F	MICHEL, E. J.	8401180249	50-322 T
ARTIN, T. T.	8401310094	70-687	MCGAUGHY, J. P.	8401100478	50-416 P	MIGHT, A.	8401120398	50-315 A
ARTIN, T. T.	8401310161	50-277 Q	MCGAUGHY, J. P.	8401120350	50-416 S	MIGHT, A.	8401120412	50-316 R
ARTIN, T. T.	8401310225	70-1331	MCGAUGHY, J. P.	8401170376	50-416 S	WILLER, A.	8401260401*	50-320 F
ARTIN, T. T.	8401310270	50-277 Q	MCGAUGHY, J. P.	8401200001	50-416 P	MILLER, D. E.	8401200286*	50-440 Q
ARTIN, T. T.	8401310350	70-368	MCGAUGHY, R. W.	8312290259	50-331 F	MILLER, D. J.	8401310115*	50-334 F
ATKINSON, A.	8309230072*	MIBG	MCGAUGHY, R. W.	8401090265	50-331 F	MILLER, H.	8401300384*	WASTE MGT
ATKINSON, C. C.	8401120257	50-327 R	MCGAUGHY, R. W.	8401100305*	50-331 Q	MILLER, H. J.	8401120140	40-6500
ATKINSON, C. C.	8401270481	50-327 R	MCGAUGHY, R. W.	8401180219	50-331 F	MILLER, H. J.	8401120575	40-6500
ATA, M.	8401170420*	50-354 A	MCGAUGHY, R. W.	8401240196	50-331 P	MILLER, H. J.	8401190278	WASTE MGT
ATA, M.	8401170424*	50-354 A	MCGAUGHY, R. W.	8401240228	50-331 P	MILLER, H. J.	8401270173	WASTE MGT
ATTHEBON, S. M.	8401100150	WASTE MGT	MCGAUGHY, R. W.	8401250294	50-331 P	MILLER, H. J.	8401270519	WASTE MGT
ATTHEBON, S. M.	8401110333*	COMMISSION	MCGAUGHY, R. W.	8401310024	50-331 Q	MILLER, H. J.	8401300113*	WASTE MGT
ATTHEBON, S. M.	8401120331*	WASTE MGT	MCGEEHEE, R. B.	8401300122	50-416 Q	MILLER, H. J.	8401300349	WASTE MGT
ATTHEBON, S. M.	8312200154	50-206 P	MCGEEHEE, R. B.	8401300122	50-416 Q	MILLER, J. R.	8401030017	50-266 F
ATTHEBON, S. M.	8401100355*	40-8046	MCGINNESS, J.	8401040465	40-2298	MILLER, J. R.	8401090520	50-309 F
ATTHEBON, S. M.	8401050681*	50-280 Q	MCDOLDRICK, F.	8401090178	XPORTLIC	MILLER, J. R.	8401090574	50-309 F
ATTHEBON, S. M.	8401050633*	50-321 Q	MCDOWAN, J. W.	8401060126*	50-348 F	MILLER, J. R.	8401100048	50-266 F
ATTHEBON, S. M.	8401230657	NUREG	MCDOWAN, J. W.	8401240632*	50-348 F	MILLER, J. R.	8401100049*	50-266 F
ATTHEBON, D. R.	8401270153	WASTE MGT	MCDOWAN, J. W.	8401240645*	50-348 F	MILLER, J. R.	8401100130*	50-317 P
ATTHEBON, R.	8203170235*	50-327 A	MCDOWAN, J. W.	8401260185*	50-348 F	MILLER, J. R.	8401110186*	50-336 P
ATTHEBON, R.	8312190346*	50-322 A	MCDOWAN, J. W.	8401260334*	50-348 F	MILLER, J. R.	8401110193*	50-282 P
ATTHEBON, R. J.	8401250394	NUREG	MCDOWAN, J. W.	8401310240*	50-348 F	MILLER, J. R.	8401110198*	50-344 P
ATTHEBON, R. J.	8208230015*	FOIA	MCDOWAN, J. W.	8401040289*	50-280 Q	MILLER, J. R.	8401110330*	50-266 P
ATTHEBON, R. J.	8211160524*	FOIA	MCDOWAN, J. W.	8401050352*	50-327 Q	MILLER, J. R.	8401110326*	50-309 P
ATTHEBON, R. J.	8301260532*	FOIA	MCDOWAN, J. W.	8401050399	50-321 S	MILLER, J. R.	8401120112	50-266 P
ATTHEBON, R. J.	8401040191*	FOIA	MCDOWAN, J. W.	8401050546*	50-302 Q	MILLER, J. R.	8401130124	50-285 P
ATTHEBON, R. J.	8401160454*	FOIA	MCDOWAN, J. W.	8401100480*	50-302 Q	MILLER, J. R.	8401170105	50-336 P
ATTHEBON, R. J.	8401170021*	FOIA	MCDOWAN, J. W.	8401170424*	50-369 Q	MILLER, J. R.	8401170111	50-285 F
ATTHEBON, R. J.	8401170099*	FOIA	MCDOWAN, J. W.	8401240452*	50-406 Q	MILLER, J. R.	8401170317	50-250 P
ATTHEBON, R. J.	8202020366*	50-382 F	MCDOWAN, J. W.	8401240547*	50-160 Q	MILLER, J. R.	8401180006	50-282 F
ATTHEBON, R. J.	8401050398*	50-400 F	MCDOWAN, J. W.	8401300292	50-389 S	MILLER, J. R.	8401190092	50-317 F
ATTHEBON, R. J.	8401250126*	50-259 F	MCDOWAN, J. W.	8401310311*	50-413 Q	MILLER, J. R.	8401190128	50-344 P
ATTHEBON, R. J.	8401270258	50-29 F	MCDOWAN, J. W.	8401180249*	50-322 T	MILLER, J. R.	8401190131	50-309 P
ATTHEBON, R. J.	8401250077*	50-483 F	MCDOWAN, J. W.	8401120286	50-275 Q	MILLER, J. R.	8401190134	50-309 P
ATTHEBON, R. J.	8401180072	NUREG	MCINTOSH, M. D.	8401310075*	50-369 F	MILLER, J. R.	8401190137	50-266 F
ATTHEBON, R. J.	8401190454	50-358 A	MCINTYRE, T. R.	8401170363*	TOPREP	MILLER, J. R.	8401190149	50-282 Q
ATTHEBON, R. J.	8401270440	50-358 A	MCINTYRE, T. R.	8401170367*	TOPREP	MILLER, J. R.	8401190159	50-282 F
ATTHEBON, R. J.	8401240375*	70-27	McKENNA, E. M.	8401260114	50-206 P	MILLER, J. R.	8401190168	50-335 F

499

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER, L. K.	8401230004	50-311 R	MILLS, L. M.	8401170001	50-390 B	MITTL, R. L.	8401170323	50-354 A
MILLER, L. K.	8401240117	50-272 R	MILLS, L. M.	8401170214	50-438 B	MITTL, R. L.	8401170413	50-354 A
MILLER, L. K.	8401310353	50-272 R	MILLS, L. M.	8401170224	50-390 A	MIZUNO, O. B.	8401120245	50-445 Q
MILLER, M. A.	8401100023	50-424 F	MILLS, L. M.	8401170250	50-327 P	MIZUNO, O. B.	8401120332	50-445 Q
MILLER, M. E.	8401090343	50-272 Q	MILLS, L. M.	8401170252	50-390 A	MIZUNO, O. B.	8401250177	50-445 Q
MILLER, M. E.	8401250173	50-537 G	MILLS, L. M.	8401170265	50-390 B	MIZUNO, O. B.	8401250180	50-445 Q
MILLER, M. E.	8401250197	50-537 G	MILLS, L. M.	8401170332	50-390 E	MIZUNO, O. B.	8401250252	50-445 Q
MILLER, M. E.	8401270304	50-272 Q	MILLS, L. M.	8401170365	50-390 B	MOBLEY, B. L.	8401030036*	40-56
MILLER, M. E.	8401300089	50-537 G	MILLS, L. M.	8401170400	50-259 P	MORSCHHELL, R. P.	8401250324*	50-590 F
MILLER, M. I.	8401250201	50-454 Q	MILLS, L. M.	8401170423	50-327 P	MORIYA, P. S.	8401160443	NUREQ
MILLER, M. J.	8401250201	50-454 Q	MILLS, L. M.	8401180156	50-390 F	MORANAHAN, J. A.	8401190185	50-322 Q
MILLER, M. J.	8401300202	50-454 Q	MILLS, L. M.	8401180262	50-390 A	MORANAHAN, J. A.	8401190185	50-322 Q
MILLER, M. J.	8401300202	50-454 Q	MILLS, L. M.	8401200083	50-390 A	MORANAHAN, J. A.	8401240249	50-322 Q
MILLER, M. J.	8401130379	NUREQ	MILLS, L. M.	8401240024	50-390 B	MORANAHAN, J. A.	8401240249	50-322 Q
MILLER, R. L.	8401180147	NUREQ	MILLS, L. M.	8401240085	50-438 B	MONTAGUE, D. F.	8401120533*	CONTRACT
MILLER, T. D.	8401090488*	QA999	MILLS, L. M.	8401240097	50-438 B	MONTANGE, C. H.	8401100120	40-2061
MILLER, W. F.	8401040095*	50-352 A	MILLS, L. M.	8401240149	50-438 B	MONTANGE, C. H.	8401230554	40-2061
MILLER, W. H.	8401090502*	50-390 Q	MILLS, L. M.	8401240168	50-438 B	MONTANGE, C. H.	8401230554	40-2061
MILLER, W. C.	8401090392	TOPREP	MILLS, L. M.	8401240258	50-390 E	MONTETH, J. L.	8401180249	50-322 Y
MILLER, W. C.	8401090416	TOPREP	MILLS, L. M.	8401240264	50-438 B	MONTGOMERY, C. R.	8401300251	50-146 S
MILLER, W. C.	8401090422	TOPREP	MILLS, L. M.	8401240268	50-390 F	MONTGOMERY, D. M.	8401050435*	70-1201
MILLER, W. C.	8401090428*	TOPREP	MILLS, L. M.	8401240323*	50-390 Q	MONTGOMERY, D. M.	8401050408*	70-27
MILLER, W. C.	8401110184	50-245 P	MILLS, L. M.	8401240339*	50-438 Q	MONTGOMERY, J. L.	8401170422*	50-285 Q
MILLER, W. C.	8401110192	50-324 F	MILLS, L. M.	8401240342	50-438 B	MONTGOMERY, J. L.	8401230309*	50-267 Q
MILLER, W. C.	8401120349*	MISC	MILLS, L. M.	8401240407*	50-259 Q	MOONEY, D. J.	8401310419	50-358 Q
MILLER, W. C.	8401170514	50-312 F	MILLS, L. M.	8401240428*	50-259 Q	MOONEY, J. A.	8401050647	50-329 A
MILLER, W. C.	8401190148	50-293 P	MILLS, L. M.	8401240441	50-259 Q	MOONEY, J. A.	8401190329	50-329 A
MILLER, W. C.	8401190495	50-327 P	MILLS, L. M.	8401240482	50-438 B	MOORE, D. E.	8401050352*	50-327 Q
MILLER, W. C.	8401270191	TOPREP	MILLS, L. M.	8401240486	50-390 S	MOORE, D. E.	8401310311*	50-413 Q
MILLER, W. C.	8401270196*	TOPREP	MILLS, L. M.	8401240494	50-390 S	MOORE, J. E.	8401250161	50-400 Q
MILLER, W. D.	8401310433	TOPREP	MILLS, L. M.	8401240522	50-327 F	MOORE, R. N.	8401030285	XPORTLIC
MILLER, W. D.	8401310437*	TOPREP	MILLS, L. M.	8401240536*	50-390 Q	MOORE, R. N.	8401300061	XPORTLIC
MILLER, W. D.	8401310520	50-514 A	MILLS, L. M.	8401240545	50-390 S	MOORE, R. N.	8401300065	XPORTLIC
MILLIGAN, M. H.	8401110240	50-322 A	MILLS, L. M.	8401240574*	50-438 Q	MOORE, S. N.	8401170217	50-261 P
MILLIGAN, R. E.	8401310403	PR	MILLS, L. M.	8401240583	50-438 Q	MOREHOUSE, J. H.	8308190529*	ACRS
MILLS, L.	8401120270	WASTE MGT	MILLS, L. M.	8401240593*	50-390 Q	MORGAN, R. E.	8401030217	50-261 S
MILLS, L.	8401120270	WASTE MGT	MILLS, L. M.	8401240605	50-438 S	MORGAN, R. E.	8401050052	50-261 F
MILLS, L. M.	8401030101	50-438 S	MILLS, L. M.	8401240616*	50-259 F	MORGAN, R. E.	8401050415	50-261 S
MILLS, L. M.	8401030108	50-390 S	MILLS, L. M.	8401250118*	50-259 F	MORGAN, R. E.	8401050474	50-261 S
MILLS, L. M.	8401030137	50-390 S	MILLS, L. M.	8401250321*	50-390 F	MORGAN, R. E.	8401130132	50-261 S
MILLS, L. M.	8401030182	50-438 S	MILLS, L. M.	8401260009	50-390 S	MORGAN, R. E.	8401160107	50-261 R
MILLS, L. M.	8401030231	50-390 S	MILLS, L. M.	8401260012	50-438 S	MORGAN, R. E.	8401240412*	50-261 Q
MILLS, L. M.	8401030252*	50-259 F	MILLS, L. M.	8401260045	50-390 S	MORGAN, R. E.	8401250145*	50-261 F
MILLS, L. M.	8401030303	50-438 S	MILLS, L. M.	8401260165	50-391 S	MORGAN, R. E.	8401260228*	50-261 F
MILLS, L. M.	8401030306	50-439 S	MILLS, L. M.	8401260171	50-438 S	MORGENSTERN, A.	8401190212	XPORTLIC
MILLS, L. M.	8401040242	50-390 S	MILLS, L. M.	8401260344	50-438 S	MORRIS, A. V.	8401260268	50-293 H
MILLS, L. M.	8401040299	50-390 S	MILLS, L. M.	8401260359	50-438 S	MORKIN, K. M.	8401310404	50-259 S
MILLS, L. M.	8401040303	50-390 S	MILLS, L. M.	8401270088	50-390 A	MORLEY, J. A.	8401120108	WASTE MGT
MILLS, L. M.	8401040312	50-438 S	MILLS, L. M.	8401300136	50-390 S	MORLEY, J. A.	8401130468	WASTE MGT
MILLS, L. M.	8401040327	50-439 S	MILLS, L. M.	8401300140	50-438 S	MORRIS, C. A.	8401120247	50-206 R
MILLS, L. M.	8401040339	50-438 S	MILLS, L. M.	8401300193	50-438 S	MORRIS, C. A.	8401120263	50-361 R
MILLS, L. M.	8401040384	50-327 P	MILLS, L. M.	8401300246	50-438 S	MORRIS, C. A.	8401270231	50-361 R
MILLS, L. M.	8401040406	50-390 S	MILLS, L. M.	8401300273	50-296 P	MORRIS, C. A.	8401270234	50-206 R
MILLS, L. M.	8401040493	50-438 S	MILLS, L. M.	8401300275	50-438 S	MORRIS, D. Q.	8401300018	NUREQ
MILLS, L. M.	8401040569	50-390 S	MILLS, L. M.	8401300276	50-390 S	MORRONGIELLO, D.	8401040380*	50-254 Q
MILLS, L. M.	8401040592	50-438 S	MILLS, L. M.	8401300390	50-438 S	MORTON, K. L.	8401120396	50-313 R
MILLS, L. M.	8401040596	50-390 S	MILLS, L. M.	8401300325	50-438 S	MORTON, K. L.	8401270399	50-313 R
MILLS, L. M.	8401050406	50-390 S	MILLS, L. M.	8401310017	50-390 A	MORTON, K. V.	8401030131*	CONTRACT
MILLS, L. M.	8401050523*	50-390 Q	MILLS, L. M.	8401310134	50-259 P	MORTON, K. V.	8401050153*	CONTRACT
MILLS, L. M.	8401050529*	50-390 Q	MILLS, L. M.	8401310135*	50-327 F	MORTON, K. V.	8401090754*	CONTRACT
MILLS, L. M.	8401050581	50-439 S	MILLS, L. M.	8401310217	50-327 P	MORTON, K. V.	8401120533*	CONTRACT
MILLS, L. M.	8401050582	50-390 Q	MILLS, L. M.	8401310413	50-327 P	MORTON, K. V.	8401120541*	CONTRACT
MILLS, L. M.	8401060051	50-259 P	MILLSTEAD, W.	8401230657	NUREQ	MORTON, K. V.	8401120569*	CONTRACT
MILLS, L. M.	8401060101*	50-327 F	MINECK, D. L.	8401050451	50-331 S	MORTON, K. V.	8401120592*	CONTRACT
MILLS, L. M.	8401060445*	50-390 Q	MINECK, D. L.	8401050466	50-331 S	MORTON, K. V.	8401130037*	CONTRACT
MILLS, L. M.	8401060453*	50-390 Q	MINECK, D. L.	8401050566	50-331 S	MORTON, K. V.	8401160462*	CONTRACT
MILLS, L. M.	8401090135*	50-438 Q	MINECK, D. L.	8401120423	50-331 S	MORTON, K. V.	8401190356*	CONTRACT
MILLS, L. M.	8401090372	50-327 F	MINECK, D. L.	8401180117	50-331 R	MORTON, K. V.	8401230706*	CONTRACT
MILLS, L. M.	8401090432	50-390 A	MINECK, D. L.	8401270504	50-331 S	MORTON, K. V.	8401250122*	CONTRACT
MILLS, L. M.	8401100299	50-390 A	MINER, S.	8401170480	50-312 P	MORTON, K. V.	8401250366*	CONTRACT
MILLS, L. M.	8401100345	50-390 S	MINISH, J. Q.	8401060391	50-289 U	MORTON, K. V.	8401260197*	CONTRACT
MILLS, L. M.	8401110004	50-327 P	MINITZ, S.	8401170371*	TOPREP	MORTON, K. V.	8401270339*	CONTRACT
MILLS, L. M.	8401110048	50-390 F	MINNERB, W.	8401230657	NUREQ	MORTON, K. V.	8401300012*	CONTRACT
MILLS, L. M.	8401110082	50-390 A	MINGOUE, R. B.	8401160475*	FOIA	MORTON, K. V.	8401300154*	CONTRACT
MILLS, L. M.	8401110130	50-390 K	MINOQUE, R. B.	8401300016	REPOD	MOTT, E. D.	8401250253	CONTRACT
MILLS, L. M.	8401120223	50-438 S	MINTZ, S.	8401170363*	TOPREP	MOWRY, W. R.	8401060498	XPORTLIC
MILLS, L. M.	8401120277	50-390 S	MINTZ, S.	8401170371*	TOPREP	MOWRY, W. R.	8401060503*	XPORTLIC
MILLS, L. M.	8401120289	50-438 S	MIRAGLIA, F.	8401090763	50-155 P	MOWRY, W. R.	8401190421	70-734
MILLS, L. M.	8401120367	50-390 S	MIRAGLIA, F. J.	8401190247	50-341 F	MROCKZA, E. J.	8401040158	50-245 S
MILLS, L. M.	8401130053	50-438 S	MIRAGLIA, F. J.	8401240570	50-219 P	MROCKZA, E. J.	8401040158	50-245 S
MILLS, L. M.	8401130165	50-438 S	MIRAGLIA, F. J.	8401250030	50-447 A	MROCKZA, E. J.	8312300176	50-336 S
MILLS, L. M.	8401130365	50-390 S	MISAK, A.	8401050449	50-254 S	MROCKZA, E. J.	8312300176	50-336 S
MILLS, L. M.	8401160077	50-259 P	MISAK, A.	8401170210	50-254 R	MROCKZA, E. J.	8401040178	50-245 S
MILLS, L. M.	8401160111	50-390 F	MITTL, R. L.	8401060412	50-354 A	MROCKZA, E. J.	8401040178	50-245 S
MILLS, L. M.	8401160156	50-438 R	MITTL, R. L.	8401060486	50-354 A	MROCKZA, E. J.	8401040183	50-336 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MROCKZKA, E. J.	84011040183	50-336 S	MURRAY, T. D.	8401300295	50-346 S	NEFF, J. D.	8401300170	WASTE MGT
MROCKZKA, E. J.	84011040007	50-245 S	MURRAY, T. D.	840130070*	50-346 F	NEFF, J. D.	8401300341	WASTE MGT
MROCKZKA, E. J.	84011040007	50-245 S	MUSCARA, J.	8401260105	MUREQ	NEFF, J. D.	8401300345	WASTE MGT
MROCKZKA, E. J.	8401100423	50-245 S	MUSELER, M. J.	8401120359	50-382 S	NEFF, J. D.	8401300360	WASTE MGT
MROCKZKA, E. J.	8401100423	50-245 S	MUSOLF, D.	8401050411	50-282 S	NEFF, J. D.	8401310179	WASTE MGT
MROCKZKA, E. J.	8401120194	50-336 R	MUSOLF, D.	8401050442	50-282 S	NEFF, J. D.	8401310185	WASTE MGT
MROCKZKA, E. J.	8401120194	50-336 R	MUSOLF, D.	8401090321	50-263 F	NEFF, J. D.	8401310188	WASTE MGT
MROCKZKA, E. J.	8401120203	50-245 R	MUSOLF, D.	8401120240	50-282 R	NEFF, J. D.	8401310191	WASTE MGT
MROCKZKA, E. J.	8401120203	50-245 R	MUSOLF, D.	8401120314	50-282 X	NEFF, J. D.	8401310201	WASTE MGT
MROCKZKA, E. J.	8401120312	50-336 S	MUSOLF, D.	8401120373	50-263 S	NEFF, J. D.	8401310452	WASTE MGT
MROCKZKA, E. J.	8401120312	50-336 S	MUSOLF, D.	8401120377	50-263 R	NEIGHBORS, J. D.	8401060245	50-305 A
MROCKZKA, E. J.	8401170251	50-336 S	MUSOLF, D.	8401120406	50-263 Q	NEIGHBORS, J. D.	8401090149	50-305 F
MROCKZKA, E. J.	8401170251	50-336 S	MUSOLF, D.	8401130082	50-263 F	NEIGHBORS, J. D.	8401160418	50-280 F
MROCKZKA, E. J.	8401270442	50-245 R	MUSOLF, D.	8401130187	50-263 P	NEIGHBORS, J. D.	8401240014	50-305 F
MROCKZKA, E. J.	8401270442	50-245 R	MUSOLF, D.	8401160128	50-282 Q	NETSLER, J. H.	8401190399*	50-483 Q
MROCKZKA, E. J.	8401270457	50-336 R	MUSOLF, D.	8401170314	50-263 X	NEUFELT, G. M.	8401240344*	50-395 Q
MROCKZKA, E. J.	8401270457	50-336 R	MUSOLF, D.	8401170353	50-282 Q	NELSON, M. A.	8401260046*	50-289 F
MROCKZKA, E. J.	8401300137	50-245 S	MUSOLF, D.	8401170374	50-263 P	NELSON, M. A.	8401260238*	50-320 F
MROCKZKA, E. J.	8401300137	50-245 S	MUSOLF, D.	8401180111	50-282 P	NELSON, R. E.	8401100253*	6A999
MUDD, C. H.	8401060121*	50-348 F	MUSOLF, D.	8401190387	50-282 P	NELSON, R. L.	8401190401*	50-305 Q
MUDD, C. H.	8401240642*	50-348 F	MUSOLF, D.	8401190392*	50-282 P	NEUMETHY, E.	8401090373	PR
MUDD, C. H.	8401120185*	50-348 F	MUSOLF, D.	8401200081	50-282 Q	NEUBER, V.	8401260494	50-443 A
MUDD, C. H.	8401310236*	50-348 F	MUSOLF, D.	8401230216	50-263 P	NEUSE, R. J.	8401100088	MUREQ
MUELLER, R. J.	8401230317	50-285 S	MUSOLF, D.	8401240431	50-282 P	NEWTON, C. A.	8401270123	50-413 A
MUELLER, R. J.	8401230360	50-285 S	MUSOLF, D.	8401270397	50-263 R	NGUYEN, D. V.	8401230028*	50-352 A
MULLEN, M. F.	8401100088	MUREQ	MUSOLF, D.	8401270452	50-282 R	NICHOL, F. A.	8401160443	MUREQ
MULLER, A. R.	8401110245*	50-322 A	MUSOLF, D.	8401310335	50-282 F	NICHOLAS, H. H.	8401260204*	50-388 Q
MULLIKIN, R. P.	8401040499*	50-445 Q	MUSOLF, D. M.	8401060230	50-282 P	NICHOLAS, J. B.	8401040364*	50-285 Q
MULLINS, C. B.	8401300018	MUREQ	MUSOLF, D. M.	8401100180	50-282 P	NICHOLAS, H. H.	8401180218*	50-322 Q
MURDOCK, E. S.	8401270502	40-6622	MUTO, N. J.	8401200099	50-322 T	NICHOLSON, P.	8401250329*	50-434 H
MURDOCK, R. J.	8401160193	50-219 S	MYERS, D. O.	8401090380*	50-324 Q	NICHOLSON, W. Q.	8401270476	50-344 R
MURLEY, T. E.	8401030234	50-289 Q	MYERS, D. O.	8401090525*	50-324 Q	NICKOLA, P. W.	8401130360	MUREQ
MURLEY, T. E.	8401030237*	50-289 Q	MYERS, D. O.	8401060432*	50-324 Q	NICKOLAUS, J. W.	8401110382	XPORTLIC
MURLEY, T. E.	8401030241*	50-289 Q	MYRABO, A. L.	8401120377	50-263 R	NICOLARAS, H.	8401200036	50-263 F
MURLEY, T. E.	8401040185	40-86	MYRABO, A. L.	8401270397	50-263 R	NICOLASI, J.	8401240478	I&E
MURLEY, T. E.	8401160301	50-293 Q	NARDI, A. J.	8401040004	71-4909	NICOLASI, J. F.	8401270009	40-281
MURLEY, T. E.	8401170489	50-352 H	NARDI, A. J.	8401050008	70-1151	NICOLASI, J. F.	8401270220	40-8821
MURLEY, T. E.	8401190377	50-334 Q	NARDI, A. J.	8401110134	70-698	NIEVES, L. A.	8401100088	MUREQ
MURLEY, T. E.	8401240566	50-272 Q	NARDI, A. J.	8401200119	71-251	NIGHTINGALE, E.	8401100054*	50-358 Q
MURPHY, C. E.	8401260244*	50-315 F	NARDI, A. J.	8401310154	70-1143	NIGHTINGALE, E.	8401100059*	50-358 Q
MURPHY, C. E.	8401310409*	50-315 S	NARDDCI, P. B.	8401040133	50-369 S	NIMITZ, R. L.	8401100241*	50-387 Q
MURPHY, D. W.	8401090615	MUREQ	NARDDCI, P. B.	8401040311	50-370 S	NIX, H. C.	8401030112	50-321 S
MURPHY, D. W.	8401130356	MUREQ	NARDDCI, P. B.	8401040328	50-369 S	NIX, H. C.	8401030116	50-366 S
MURPHY, J. D.	8401130088	71-1	NARDDCI, P. B.	8401040332	50-369 S	NIX, H. C.	8401030193	50-321 S
MURPHY, M. E.	8401040291*	50-298 Q	NARDDCI, P. B.	8401040354	50-370 S	NIX, H. C.	8401030242	50-366 S
MURPHY, M. E.	8401040439*	50-482 Q	NARDDCI, P. B.	8401040410	50-370 S	NIX, H. C.	8401040168	50-321 S
MURPHY, M. E.	8401040466*	50-298 Q	NARDDCI, P. B.	8401040535	50-370 S	NIX, H. C.	8401040250	50-366 S
MURPHY, M. R.	8401100122	WASTE MGT	NARDDCI, P. B.	8401040562	50-370 S	NIX, H. C.	8401040334	50-321 S
MURPHY, M. R.	8401100129*	WASTE MGT	NARDDCI, P. B.	8401120226	50-369 S	NIX, H. C.	8401040336	50-321 S
MURPHY, M. R.	8401100129*	WASTE MGT	NARDDCI, P. B.	8401120375	50-370 S	NIX, H. C.	8401040344	50-366 S
MURPHY, W. P.	8401040534	50-271 Q	NARDDCI, P. B.	8401120376	50-369 S	NIX, H. C.	8401060371	50-366 S
MURPHY, W. P.	8401100312*	50-271 Q	NARDDCI, P. B.	8401130069	50-369 S	NIX, H. C.	8401060415	50-366 S
MURPHY, W. P.	8401130045	50-271 X	NARDDCI, P. B.	8401240105	50-370 S	NIX, H. C.	8401060461	50-366 S
MURPHY, W. P.	8401170317	50-271 R	NARDDCI, P. B.	8401240119	50-369 S	NIX, H. C.	8401060511	50-321 S
MURPHY, W. P.	8401170332	50-271 P	NARDDCI, P. B.	8401240130	50-369 S	NIX, H. C.	8401130330	50-321 R
MURPHY, W. P.	8401240464	50-271 P	NARDDCI, P. B.	8401240287	50-370 S	NIX, H. C.	8401230012	50-366 S
MURRAY, B.	8401040364*	50-285 Q	NARDDCI, P. B.	8401240437	50-370 S	NIX, H. C.	8401230201	50-366 S
MURRAY, B.	8401040377*	50-482 Q	NARDDCI, P. B.	8401240594	50-370 S	NIX, H. C.	8401230263	50-366 S
MURRAY, B.	8401040431*	50-285 Q	NARDDCI, P. B.	8401260160	50-369 S	NIX, H. C.	8401230362	50-366 S
MURRAY, B.	8401040472*	50-298 Q	NARROW, L.	8401100389*	50-388 Q	NIX, H. C.	8401240102*	50-321 F
MURRAY, B.	8401040570*	50-482 Q	NARROW, L.	8401180248*	50-352 Q	NIX, H. C.	8401240106*	50-321 F
MURRAY, T. D.	8401040317	50-346 S	NARROW, L.	8401240313*	50-354 Q	NIX, H. C.	8401300259	50-321 S
MURRAY, T. D.	8401040358	50-346 S	NARUS, R.	8401310411	PR	NIX, H. C.	8401300262	50-366 S
MURRAY, T. D.	8401040390	50-346 S	NASH, B.	8401050044*	50-320 F	NIX, H. C.	8401300268	50-321 S
MURRAY, T. D.	8401060091*	50-346 F	NAZARENO, E.	8401170420*	50-354 A	NIX, H. C.	8401300273	50-321 S
MURRAY, T. D.	8401060494	50-346 S	NAZARENO, E.	8401170426*	50-354 A	NIX, H. C.	8401300312	50-366 S
MURRAY, T. D.	8401060509	50-346 S	NEFF, J. D.	8401120011	WASTE MGT	NIX, H. C.	8401300327	50-366 S
MURRAY, T. D.	8401120093	71-9131	NEFF, J. D.	8401120013	WASTE MGT	NIX, H. C.	8401310393	50-321 S
MURRAY, T. D.	8401120322	50-346 S	NEFF, J. D.	8401130049	WASTE MGT	NIX, H. C.	8401310394	50-321 S
MURRAY, T. D.	8401160227	50-346 S	NEFF, J. D.	8401130057	WASTE MGT	NIX, H. C.	8401310398	50-366 S
MURRAY, T. D.	8401160238	50-346 S	NEFF, J. D.	8401160015	WASTE MGT	NIX, H. C.	8401310400	50-366 S
MURRAY, T. D.	8401160259	50-346 S	NEFF, J. D.	8401190463	WASTE MGT	NIXON, W. A.	8401190255	40-2061
MURRAY, T. D.	8401160299	50-346 S	NEFF, J. D.	8401190508	WASTE MGT	NIXON, W. A.	8401240041	40-2061
MURRAY, T. D.	8401160323	50-346 S	NEFF, J. D.	8401300011	WASTE MGT	NOBLE, L. M.	8401310147*	50-327 F
MURRAY, T. D.	8401160330	50-346 S	NEFF, J. D.	8401300043	WASTE MGT	NONDAHL, S. M.	8401270350*	50-344 F
MURRAY, T. D.	8401170178	50-346 R	NEFF, J. D.	8401300053	WASTE MGT	NOONAN, V. S.	8401250447	MISC
MURRAY, T. D.	8401170196	50-346 R	NEFF, J. D.	8401300063	WASTE MGT	NORDERHAUG, L.	8401030245	50-275 S
MURRAY, T. D.	8401170205	50-346 R	NEFF, J. D.	8401300072	WASTE MGT	NORDERHAUG, L. R.	8312292061	50-312 Q
MURRAY, T. D.	8401190331	50-346 S	NEFF, J. D.	8401300079	WASTE MGT	NORDERHAUG, L. R.	8401040213	70-734
MURRAY, T. D.	8401190404	50-346 S	NEFF, J. D.	8401300084	WASTE MGT	NORDERHAUG, L. R.	8401040223*	70-734
MURRAY, T. D.	8401230654*	50-346 F	NEFF, J. D.	8401300097	WASTE MGT	NORDERHAUG, L. R.	8401040565	50-344 F
MURRAY, T. D.	8401230654*	50-346 F	NEFF, J. D.	8401300102	WASTE MGT	NORDERHAUG, L. R.	8401160211	70-734
MURRAY, T. D.	8401270483	50-346 S	NEFF, J. D.	8401300105	WASTE MGT	NORDERHAUG, L. R.	8401160219	50-312 Q
MURRAY, T. D.	8401300009	50-346 S	NEFF, J. D.	8401300107	WASTE MGT	NORDERHAUG, L. R.	8401300183	50-206 Q
MURRAY, T. D.	8401300187	50-346 S	NEFF, J. D.	8401300120	WASTE MGT	NORELIUS, C. E.	8401040138	50-346 P

PERSONAL AUTHOR INDEX

501

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NORELIUS, C E	8401040324	50-254 Q	O'REILLY, J P	8401240214	50-416 Q	PALLADINO, N J	8401110229	50-289 Q
NORELIUS, C E	8401100401	50-440 Q	O'REILLY, J P	8401240242	50-321 V	PALLADINO, N J	8401110244	50-320 U
NORELIUS, C E	8401100407	50-315 Q	O'REILLY, J P	8401240285	50-321 F	PALLADINO, N J	8401110258*	50-320 U
NORELIUS, C E	8401100416*	50-440 Q	O'REILLY, J P	8401240361*	70-1151	PALLADINO, N J	8401110264*	50-320 U
NORELIUS, C E	8401120232	50-315 Q	O'REILLY, J P	8401240362*	70-1151	PALLADINO, N J	8401110265*	COMMISSION
NORELIUS, C E	8401120346	50-346 P	O'REILLY, J P	8401240365*	70-1151	PALLADINO, N J	8401110326*	COMMISSION
NORELIUS, C E	8401160140	50-331 Q	O'REILLY, J P	8401240398	50-259 Q	PALLADINO, N J	8401110327	50-289 U
NORELIUS, C E	8401160274	50-341 Q	O'REILLY, J P	8401240414*	50-259 Q	PALLADINO, N J	8401110331	COMMISSION
NORELIUS, C E	8401190380	50-454 A	O'REILLY, J P	8401240419	50-302 Q	PALLADINO, N J	8401120316	WASTE MOT
NORELIUS, C E	8401230285	50-373 Q	O'REILLY, J P	8401240485	50-327 Q	PALLADINO, N J	8401190493	50-397 U
NORELIUS, C E	8401230315	50-373 Q	O'REILLY, J P	8401240490	50-324 Q	PALLADINO, N J	8401200054	COMMISSION
NORELIUS, C E	8401230351	50-373 Q	O'REILLY, J P	8401250165	50-366 Q	PALLADINO, N J	8401200209	COMMISSION
NORELIUS, C E	8401230434	50-10 Q	O'TOOLE, J D	8401050308	50-247 P	PALLADINO, N J	8401200216*	COMMISSION
NORELIUS, C E	8401230506	50-331 Q	O'TOOLE, J D	8401100158*	50-247 Q	PALLADINO, N J	8401230015*	50-320 P
NORELIUS, C E	8401310163	MISC	O'TOOLE, J D	8401100258*	50-247 Q	PALLADINO, N J	8401230026*	50-289 U
NORMAN, D E	8401270479*	QA999	O'TOOLE, J D	8401260294*	50-3 F	PALLADINO, N J	8401250323*	PR
NORRHO, M L	8401100382*	50-286 Q	O'TOOLE, J D	8401300250	50-247 P	PALLADINO, N J	8401310168	50-275 U
NORRHO, M L	8401180203*	50-247 Q	OBARA, C T	8401230146*	40-7582	PALLADINO, N J	8401310175	COMMISSION
NORRHO, M L	8401240530*	50-272 Q	OBEGARDEN, R H	8401060664	71-6574	PALMER, R A	8401040323	50-315 S
NORRIS, H R	8401160107	50-261 R	OBEGARDEN, R H	8401190300	71-7175	PALMER, R A	8401040340	50-315 S
NORRIS, J	8401120585	50-295 P	ODOM, L	8401250253	PR	PALMER, R A	8401040362*	50-316 S
NORRIS, J A	8401240016	50-295 P	OBETHANN, H J	8401230387*	50-483 Q	PALMER, R A	8401040367*	50-316 S
NORRY, P Q	8401200230	CRQ	ODLE, K H	8401060325	40-8768	PALMER, R A	8401190374*	50-315 S
NORRY, P Q	8401270494	CRQ	OKADA, S	8401060472	XPORTLIC	PALMER, R A	8401190375*	50-315 S
NORTH, H S	8401200023*	50-312 Q	OLESEN, M	8401050294	50-275 H	PALMER, R A	8401240171*	50-316 S
NORTH, H S	8401300188*	50-206 Q	OLLER, R E	8401050232*	QA999	PALMER, R A	8401300198*	50-316 S
NORTON, B	8401100137	50-275 Q	OLLER, R E	8401230294*	QA999	PALMER, R A	8401300201*	50-316 S
NORTON, B	8401100137	50-275 Q	OLLINGER, W H	8401260059*	50-321 F	PALMER, R A	8401300243*	50-315 S
NORTON, B	8401300314	50-275 Q	OLMSTEAD, W J	B312300034	MISC	PALMER, R A	8401300248*	50-315 S
NORTON, B	8401300314	50-275 Q	OLSEN, A F	8401160232	50-13 F	PALMER, R A	8401300257	50-316 S
NOTIGAN, D V	8401270259	50-219 R	OLSON, D L	8401120008	WASTE MOT	PANCIERA, V	8401050648*	50-302 Q
NOUREAKHSH, H P	8401160402*	FDIA	OLSON, D L	8401120009	WASTE MOT	PANCIERA, V	8401090361*	50-302 Q
NOVACHEK, F J	8401100337	50-267 S	OLSON, D L	8401120019	WASTE MOT	PANCIERA, V	8401090476*	50-424 Q
NOVACHEK, F J	8401170193	50-267 B	OLSON, D L	8401120448	WASTE MOT	PANCIERA, V	8401240401*	50-302 Q
NOVACHEK, F J	8401230186	50-267 B	OLSON, D L	8401160377	WASTE MOT	PANCIERA, V	8401240446*	50-302 Q
NOVACHEK, F J	8401270248	50-267 S	OLSON, D L	8401190910	WASTE MOT	PANCIERA, V	8401240589*	50-302 Q
NOVAK, T H	8211180523*	50-440 A	OLSON, D L	8401260007	WASTE MOT	PANCIERA, V W	8401050668*	50-424 Q
NOVAK, T H	8312120098	50-482 A	OLSON, D L	8401260010*	WASTE MOT	PANCIERA, V W	8401240597*	50-321 Q
NOVAK, T H	8312120132	50-443 A	OPEKA, J F	8401030143	50-213 P	PANDEY, F	B304070498*	50-324 P
NOVAK, T H	8312120133	50-329 A	OPEKA, J F	8401040084	50-245 P	PANG, J F	8401240080	I&E
NOVAK, T H	8312120157	50-445 B	OPEKA, J F	8401040084	50-245 P	PANBURN, Q C	8401040249*	40-8102
NOVAK, T H	8401060639*	50-416 P	OPEKA, J F	8401040224	50-213 P	PANBURN, Q C	8401060228	40-8602
NOVAK, T H	8401090582	50-498 A	OPEKA, J F	8401260324*	50-245 F	PANBURN, Q C	8401060246*	40-8602
NOVAK, T H	8401110400	50-456 E	OPREA, G W	8401030266	50-498 B	PANBURN, Q C	8401060643	40-8452
NOVAK, T H	8401170523	50-373 P	OPREA, G W	8401130173	50-498 B	PANBURN, Q C	8401110545	40-8452
NOVAK, T H	8401190008	50-445 A	OPREA, G W	8401240235	50-498 Q	PANBURN, Q C	8401110551*	40-8452
NOVAK, T H	8401190192	50-454 E	OPREA, G W	8401270138	50-498 B	PANNILL, A R	8401170237*	50-400 Q
NOVAK, T H	8401310090	50-498 A	OPREA, G W	8401270240	50-498 B	PANNILL, A R	8401170237*	50-400 Q
MANN, H B	8401300197*	50-413 Q	OPREA, G W	8401270251	50-498 B	PANNILL, A R	8401230468*	50-400 Q
MANN, H B	8401300197*	50-413 Q	OPREA, G W	8401270482	50-498 B	PANNILL, A R	8401230468*	50-400 Q
MUSBAUMER, D A	8312200331	State Prog	ORDERS, W	8401030362*	50-369 Q	PAPAZOULOU, I	8401040331	50-284 P
MUSBAUMER, D A	8401040098*	70-938	ORDERS, W	8401090104*	50-369 Q	PAPAZOULOU, I A	8401040522	50-284 P
MUSBAUMER, D A	8401090643	MUREQ	ORDERS, W T	B312200914	50-369 S	PAPERIELLO, C J	8401040232	50-263 Q
MUSBAUMER, D A	8401130040	WASTE MOT	ORDERS, W T	8401040354	50-370 S	PAPERIELLO, C J	8401050281	50-440 Q
MUSBAUMER, D A	8401250143*	40-147B	ORECHIO, F A	8401040162*	40-86	PAPERIELLO, C J	8401050337	40-8631
MUSBAUMER, D A	8401270426*	State Prog	ORNSTEIN, P	8401120113	WASTE MOT	PAPERIELLO, C J	8401050342	50-456 Q
MYKIRK, J W	8401050090*	50-295 F	OSBAKKEN, M	8401110307*	50-289 Q	PAPERIELLO, C J	8401050418	50-454 Q
O'CONNELL, J	8401180235	50-275 Q	OSBORNE, J D	8401310147*	50-327 F	PAPERIELLO, C J	8401100430	50-16 Q
O'CONNOR, T A	8401130194*	50-289 F	OSTER, J	8401090804	50-373 J	PAPERIELLO, C J	8401130203	50-266 Q
O'NEILL, J	8401230411	50-155 T	OSTER, J	8401200141	50-10 J	PAPERIELLO, C J	8401190330	50-305 Q
O'NEILL, J	8401300254	50-155 Q	OSTER, J	8401200184	50-10 J	PAPERIELLO, C J	8401190360	50-409 Q
O'NEILL, J Q	8401180207	PR	OSTRANDER, N C	8401160249*	50-142 Q	PAPERIELLO, C J	8401230016	50-346 F
O'NEILL, J H	8401050304	50-400 Q	OWBRE, R P	8401040214	50-312 S	PAPERIELLO, C J	8401230129	50-346 F
O'NEILL, J H	8401050304	50-400 Q	OWEN, M F	8401200146*	50-413 Q	PAPERIELLO, C J	8401230143	50-461 F
O'NEILL, J H	8401310292	50-261 Q	PADCHSKI, M Z	8401260101	MUREQ	PAPERIELLO, C J	8401230236	50-358 F
O'NEILL, J H	8401310292	50-261 Q	PAGE, M	8401090736	CONTRACT	PAPERIELLO, C J	8401230259	50-266 F
O'NEILL, T A	8401260117	50-400 Q	PAGE, R Q	B212010495*	40-86	PAPERIELLO, C J	8401230270	50-155 F
O'NEILL, T A	8401260117	50-400 Q	PAGE, R Q	B312150272	70-398	PAPERIELLO, C J	8401230271	50-263 F
O'REILLY, J P	8401040103	50-416 Q	PAGE, R Q	8401030319	40-2061	PAPERIELLO, C J	8401230297	40-2061
O'REILLY, J P	8401040112*	50-416 Q	PAGE, R Q	8401090127	40-2061	PAPERIELLO, C J	8401230304	50-483 F
O'REILLY, J P	8401050383	State Prog	PAGE, R Q	8401190097	70-2946	PAPERIELLO, C J	8401230324	70-925
O'REILLY, J P	8401050553	State Prog	PAGE, R Q	8401190176	40-8801	PAPERIELLO, C J	8401230326	50-409 F
O'REILLY, J P	8401050641	State Prog	PAGE, R Q	8401200052	70-36	PAPERIELLO, C J	8401230347	50-305 F
O'REILLY, J P	8401060260	50-321 P	PAGE, R Q	8401200058*	70-36	PAPERIELLO, C J	8401230379	50-483 Q
O'REILLY, J P	8401060387	50-302 Q	PAGE, R Q	8401250331	70-2985	PAPERIELLO, C J	8401230389	50-440 F
O'REILLY, J P	8401060419	50-250 P	PAGE, R Q	8401250334*	70-2985	PAPERIELLO, C J	8401230417	50-341 F
O'REILLY, J P	8401060431	50-250 Q	PAGE, R Q	8401300088	40-8331	PAPERIELLO, C J	8401230491	50-10 F
O'REILLY, J P	8401060438	50-259 F	PAGE, R Q	8401310334	70-2985	PAPERIELLO, C J	8401230525	50-315 F
O'REILLY, J P	8401060475	50-338 Q	PALMO, Q	8401100437*	QA999	PAPERIELLO, C J	8401240299	50-409 Q
O'REILLY, J P	8401100420	50-302 Q	PALMO, Q	8401100453*	QA999	PAPERIELLO, C J	8401310221	50-409 Q
O'REILLY, J P	8401100475	50-302 Q	PALMO, Q	8401100467*	QA999	PAPERIELLO, C J	8401310250	50-282 Q
O'REILLY, J P	8401110546	50-366 Q	PALLADINO, N	8401200220*	COMMISSION	PAQUIN, J L	8401060907	XPORTLIC
O'REILLY, J P	8401110552*	50-366 Q	PALLADINO, N J	8401050313	50-247 F	PARRIS, O H	8401230420	50-461 Q
O'REILLY, J P	8401170373	50-369 Q	PALLADINO, N J	8401090616	COMMISSION	PARK, J	8401160443	MUREQ
O'REILLY, J P	8401170414	50-369 Q	PALLADINO, N J	8401100126	50-413 U	PARKER, L B	8401100487*	QA999

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, L. B.	8401130041*	QA999	PERRY, W.	8401110234	50-344 Q	POLLARD, R. D.	8401240239*	50-289 Q
PARKER, M. E.	8401100005*	50-341 Q	PETerson, L. S.	8401120578	WASTE MGT	POLLOCK, M. S.	8401040015*	50-322 F
PARKHURST, M. A.	8401130356	NUREG	PETERSEN, H. E.	8401260008	50-285 J	POLLOCK, M. S.	8401040574*	50-322 G
PARKHURST, M. A.	8401260105	NUREG	PETERSON, M. R.	8401050189*	FOIA	POLLOCK, M. S.	8401050128*	50-322 F
PARKINSON, T. F.	8401040099	50-124 V	PETERSON, R. K.	8401310177*	COMMISSION	POPPE, L. K.	8401120604	WASTE MGT
PARR, O. D.	8401170018*	FOIA	PETRICK, N. A.	8401100204	50-482 A	POPPE, L. K.	8401190085	71-9044
PARRIS, H. O.	8401120427	50-259 S	PETRICK, N. A.	8401130153	50-482 A	POPPE, L. K.	8401190093*	71-9044
PARRIS, H. O.	8401200199*	50-259 I	PETRICK, N. A.	8401200059	50-482 A	PORTER, R.	8401130212	50-317 S
PARRIS, H. O.	8401200206*	50-259 I	PETRICK, N. A.	8401200139	50-482 F	PORTER, R. J.	8401160087	50-318 S
PARRIS, H. O.	8401240254	50-259 S	PETRIKAW, R. W.	8401180277*	50-322 T	PORTER, R. J.	8401160126	50-317 S
PARRIS, H. O.	8401250121	50-390 F	PETRIS, N. C.	8401240232	50-275 U	POSEY, W. H.	8401160209	50-358 Q
PARSONS, R. H.	8401030390*	50-400 Q	PETRIS, N. C.	8401030273*	50-322 Q	POSEY, W. H.	8401260226	50-358 H
PARSONS, R. H.	8401030461	50-400 S	PETRONE, C.	8401050318	50-322 S	POTAPOVS, U.	8401040385	QA999
PARSONS, R. H.	8401030470	50-400 S	PETRONE, C.	8401190389	50-322 S	POTAPOVS, U.	8401040393*	QA999
PARSONS, R. H.	8401060420	50-400 S	PETRONE, F. P.	8401300215*	50-3 F	POTAPOVS, U.	8401040433	QA999
PARSONS, R. H.	8401230397*	50-400 Q	PETRONI, F. P.	8401300219*	50-3 F	POTAPOVS, U.	8401040482	QA999
PARSONS, R. H.	8401240326	50-400 S	PETROVSKI, S.	8401190423	50-295 S	POTAPOVS, U.	8401040492*	QA999
PARSONS, R. H.	8401260103	50-400 S	PETTENGILL, H.	8401060246*	40-8602	POTAPOVS, U.	8401050214	QA999
PARSONS, R. H.	8401260176	50-400 S	PETTENGILL, H.	8401110345	40-8452	POTAPOVS, U.	8401040553*	QA999
PARSONS, R. H.	8401260354	50-400 S	PETTENGILL, H. J.	8401060214	40-8102	POTAPOVS, U.	8401050147	QA999
PARSONS, R. H.	8401260356	50-400 S	PETTENGILL, H. J.	8401060233	40-2259	POTAPOVS, U.	8401050152*	QA999
PARTLOW, J. O.	8401060087	50-445 A	PETTENGILL, H. J.	8401060621	40-3453	POTAPOVS, U.	8401050190	QA999
PASCIAK, W.	8401190439*	50-29 Q	PETTENGILL, H. J.	8401060637	40-297	POTAPOVS, U.	8401050214	QA999
PASTVA, M. J.	8401030062	50-325 S	PETTENGILL, H. J.	8401060643	40-8452	POTAPOVS, U.	8401050224	QA999
PASTVA, M. J.	8401030145	50-325 S	PETTENGILL, H. J.	8401060650	40-2259	POTAPOVS, U.	8401050228	QA999
PASTVA, M. J.	8401030190	50-325 S	PETTENGILL, H. J.	8401260271	40-8585	POTAPOVS, U.	8401090241	QA999
PASTVA, M. J.	8401030257	50-325 S	PETTENGILL, H. J.	8401310417	40-8584	POTAPOVS, U.	8401090317	QA999
PASTVA, M. J.	8401030271	50-324 S	PETTENGILL, H. J.	8401310422	40-4492	POTAPOVS, U.	8401090483	QA999
PASTVA, M. J.	8401030327	50-325 S	PETTENGILL, H. J.	8401310431*	40-1162	POTAPOVS, U.	8401090486	QA999
PASTVA, M. J.	8401040315	50-325 S	PETTENGILL, H. J.	8401310446*	40-4492	POTAPOVS, U.	8401090489*	QA999
PASTVA, M. J.	8401050438	50-325 S	PHILLIPS, M. H.	8401040614	FOIA	POTAPOVS, U.	8401090525	QA999
PASTVA, M. J.	8401060361	50-325 S	PHILLIPS, H. B.	8401050237*	QA999	POTAPOVS, U.	8401090530*	QA999
PASTVA, M. J.	8401130255	50-325 S	PHILLIPS, H. B.	8401130041*	QA999	POTAPOVS, U.	8401100250	QA999
PASTVA, M. J.	8401230283	50-325 S	PHILLIPS, H. B.	8401130195*	QA999	POTAPOVS, U.	8401100255*	QA999
PASTVA, M. J.	8401240019	50-325 S	PHILLIPS, H. B.	8401130235*	QA999	POTAPOVS, U.	8401100424	QA999
PASTVA, M. J.	8401240070	50-324 S	PHILLIPS, H. B.	8401130354*	QA999	POTAPOVS, U.	8401100445*	QA999
PASTVA, M. J.	8401260019	50-325 S	PHILLIPS, H. B.	8401130372*	QA999	POTAPOVS, U.	8401100462*	QA999
PASTVA, M. J.	8401260039	50-325 S	PHILLIPS, H. B.	8401130376*	QA999	POTAPOVS, U.	8401100482*	QA999
PATE, R. J.	8401200022*	50-397 Q	PICKERELL, L.	8401100244*	WASTE MGT	POTAPOVS, U.	8401130028	QA999
PATTERSON, J.	8401190364*	50-409 Q	PIEHL, R. H.	8401060315*	50-315 S	POTAPOVS, U.	8401130039	QA999
PATTERSON, J. D.	8401090341	PR	PIEHL, R. H.	8401060428*	50-316 S	POTAPOVS, U.	8401130051*	QA999
PATTERSON, R. L.	8401270299*	QA999	PIEHL, R. H.	8401130345*	50-316 S	POTAPOVS, U.	8401130073	QA999
PATTERSON, W. F.	8401040114	50-443 Q	PIEHL, R. H.	8401130353*	50-316 S	POTAPOVS, U.	8401130163	QA999
PATTERSON, W. F.	8401120193	50-443 Q	PIERINGER, P. A.	8401160131	50-318 S	POTAPOVS, U.	8401130186	QA999
PATTERSON, W. F.	8401120210	50-443 Q	PIERINGER, P. A.	8401160171	50-318 S	POTAPOVS, U.	8401130188	QA999
PATTERSON, W. F.	8401250222	50-443 Q	PIERINGER, P. A.	8401270086	50-318 S	POTAPOVS, U.	8401130197*	QA999
PATTON, J. D.	8401090774	40-8102	PIERRET, J. A.	8401230003	40-7580	POTAPOVS, U.	8401130205	QA999
PATTON, J. D.	8401120178	40-8102	PIERRET, J. A.	8401230013	40-7580	POTAPOVS, U.	8401130226	QA999
PAUL, R. A.	8401230442*	50-10 Q	PIERRET, J. A.	8401230030	40-7580	POTAPOVS, U.	8401130262	QA999
PAUL, G. L.	8401030472*	50-259 Q	PIERRET, J. A.	8401230349	40-7580	POTAPOVS, U.	8401130348	QA999
PAULSON, W. A.	8401030173*	50-213 P	PIERSON, R.	8401050562*	50-369 Q	POTAPOVS, U.	8401130369	QA999
PAULSON, W. A.	8401050674	50-206 P	PIERSON, R.	8401090104*	50-369 Q	POTAPOVS, U.	8401130371*	QA999
PAULSON, W. A.	8401120409	50-206 P	PIGOZZI, B. W.	8401180284*	50-322 T	POTAPOVS, U.	8401130380	QA999
PAULSON, W. A.	8401180244	50-206 P	PILANT, J. M.	8401230643*	50-298 F	POTAPOVS, U.	8401170228	QA999
PAULSON, W. A.	8401180252	50-255 P	PILANT, J. M.	8401240007	50-298 J	POTAPOVS, U.	8401170277	QA999
PAULSON, W. A.	8401230352	50-255 P	PILANT, J. M.	8401240189	50-298 P	POTAPOVS, U.	8401170318	QA999
PAULSON, W. A.	8401300216	50-255 P	PILANT, J. M.	8401260194*	50-298 F	POTAPOVS, U.	8401170333	QA999
PAYIS, G. S.	8401160067	50-317 S	PILANT, J. M.	8401300272*	50-298 F	POTAPOVS, U.	8401170407	QA999
PAYTON, G. J.	8401260257*	50-338 F	PILANT, J. M.	8401300375*	50-298 F	POTAPOVS, U.	8401170410	QA999
PAY, D.	8401230037	FOIA	PINDER, J. E.	8401090606	NUREG	POTAPOVS, U.	8401170439	QA999
PAYNE, S. W.	8401270177	40-8584	PIRTLE, G. L.	8401040480*	50-483 Q	POTAPOVS, U.	8401230196	QA999
PEAK, G. J.	8401120398	50-315 R	PITTMAN, T.	8401230657	NUREG	POTAPOVS, U.	8401230208	QA999
PEAK, G. J.	8401120412	50-316 R	PLAIN, H. H.	8401230008*	FOIA	POTAPOVS, U.	8401230224	QA999
PEDRO, J.	8401170125	FOIA	PLANNER, H. N.	8401270123	50-413 A	POTAPOVS, U.	8401230281	QA999
PEDRO, J.	8401170135	FOIA	PLAYTON, B. J.	8401310423*	40-2259	POTAPOVS, U.	8401230282	QA999
PEERY, W. W.	8401030506*	50-395 Q	PLEUNIK, B. J.	8401090487*	QA999	POTAPOVS, U.	8401230320	QA999
PEERY, W. W.	8401090277*	50-327 Q	PLEUNIK, B. J.	8401090491*	QA999	POTAPOVS, U.	8401230358	QA999
PETERS, L. A.	8401120128	WASTE MGT	PLEUNIK, B. J.	8401090493*	QA999	POTAPOVS, U.	8401230361*	QA999
PELKE, P.	8401100454	50-546 S	PLIM, G.	8401050244*	50-295 F	POTAPOVS, U.	8401230377	QA999
PELLETIER, J.	8401060076*	50-271 F	PLIM, G.	8401250123*	50-295 F	POTAPOVS, U.	8401230381	QA999
PELLETIER, J. P.	8401130033	50-271 S	PLIM, G.	8401250138*	50-295 F	POTAPOVS, U.	8401230430	QA999
PELLETIER, J. P.	8401160127	50-271 S	PLIM, G.	8401260252*	50-295 F	POTAPOVS, U.	8401230457	QA999
PENBERTHY, L.	8401130151	WASTE MGT	PLIM, G.	8401260263*	50-295 F	POTAPOVS, U.	8401230484	QA999
PENBERTHY, L.	8401200212*	COMMISSION	PLIM, G.	8401310051*	50-295 F	POTAPOVS, U.	8401230502	QA999
PENNIFULL, R.	8401270516	WASTE MGT	PLIM, G.	8401310106*	50-295 F	POTAPOVS, U.	8401230508*	QA999
PEREZ, G. P.	8401100413*	50-312 Q	PLISCO, L.	8401180268*	50-387 Q	POTAPOVS, U.	8401240451	QA999
PERLMAN, J.	8401030361	CONTRACT	PLISCO, L.	8401190347	50-387 S	POTAPOVS, U.	8401240483	QA999
PERLMAN, J.	8401030375	CONTRACT	PLISCO, L. R.	8401190216	50-388 A	POTAPOVS, U.	8401240532	QA999
PERLMAN, J.	8401030382	CONTRACT	PLISCO, L. R.	8401260177*	50-387 Q	POTAPOVS, U.	8401240546	QA999
PERLMAN, J.	8401030074	CONTRACT	PLUMLEE, G. L.	8401170370*	50-267 Q	POTAPOVS, U.	8401240578*	QA999
PERLMAN, J.	8401030097	CONTRACT	PODHURST, B. W.	8401160297*	40-8760	POTAPOVS, U.	8401240623	QA999
PERLMAN, J.	8401060203	CONTRACT	PODHURST, B. W.	8401240176*	40-8760	POTAPOVS, U.	8401240633*	QA999
PERLMAN, J.	8401100110	CONTRACT	POLCHOW, J. R.	84010603041*	50-483 F	POTAPOVS, U.	8401240636*	QA999
PERLMAN, J.	8401120556	CONTRACT	POLLARD, R. D.	8401100200	50-289 Q	POTAPOVS, U.	8401270211	QA999
PERLMAN, J.	8401130015	CONTRACT	POLLARD, R. D.	8401240230*	50-289 Q	POTAPOVS, U.	8401270246	QA999

PERSONAL AUTHOR INDEX

503

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
POTAPOV, U	8401270262	GA999	RASKIN, P. D.	8401240095	50-261 T	REYNOLDS, J. R.	8401100159	50-275 Q
POTAPOV, U	8401270285	GA999	RATHUN, L. A.	8401130356	NUREG	REYNOLDS, J. R.	8401160204	50-275 Q
POTAPOV, U	8401270305	GA999	RAWSON, R. J.	8401040189	50-454 Q	REYNOLDS, J. R.	8401160204	50-275 Q
POTAPOV, U	8401270313*	GA999	RAWSON, R. J.	8401120204	50-289 Q	REYNOLDS, J. R.	8401170322	50-275 Q
POTAPOV, U.	8401270422	GA999	RAWSON, R. J.	8401230098	50-289 Q	REYNOLDS, J. R.	8401170322	50-275 Q
POTAPOV, U	8401270438	GA999	RAWSON, R. J.	8401250107	50-289 Q	REYNOLDS, J. R.	8401230435	50-275 Q
POTAPOV, U	8401270450	GA999	RAWSON, R. J.	8401250208	50-454 Q	REYNOLDS, J. R.	8401230435	50-275 Q
POTAPOV, U.	8401270458	GA999	RAY, J. J.	8310310465	ACRB	REYNOLDS, N. S.	8401080191	50-460 Q
POTAPOV, U.	8401270468	GA999	RAY, J. J.	8401060560	ACRB	REYNOLDS, N. S.	8401080191	50-460 Q
POWERS, T. B.	8401130220	NUREG	RAY, J. J.	8401110456	ACRB	REYNOLDS, N. S.	8401110302	50-445 Q
FRATER, L. S.	8401120067*	WASTE MGT	RAY, J. J.	8401110460	ACRB	REYNOLDS, N. S.	8401110302	50-445 Q
PRELL, J. J.	8401240313*	50-354 Q	RAY, J. J.	8401110464	ACRB	REYNOLDS, N. S.	8401190283	50-445 Q
PRELL, J. A.	8401180201*	50-352 Q	RAY, J. J.	8401110473	ACRB	REYNOLDS, N. S.	8401190283	50-445 Q
PREVATTE, R. L.	8401050398*	50-400 Q	RAY, J. J.	8401110493	ACRB	REYNOLDS, N. S.	8401240335	50-269 H
PRICE, E. R.	8401250142*	40-1478	RAY, J. J.	8401110499	ACRB	REYNOLDS, N. S.	8401240335	50-269 H
PROCTOR, S. D.	8401270391*	50-329 Q	RAY, J. J.	8401110572	ACRB	REYNOLDS, N. S.	8401240335	50-269 H
PROCTOR, S. D.	8401270391*	50-329 Q	RAY, J. J.	8401120187	ACRB	REYNOLDS, N. S.	8401240335	50-269 H
PROFFO, A. E.	8401250070*	50-433 F	RAYMOND, W. J.	8401120420	50-271 S	REYNOLDS, N. S.	8401240335	50-269 H
PUGH, C. E.	8401230066	NUREG	RAYNOR, J. W.	8401160171	50-318 S	REYNOLDS, N. S.	8401240335	50-269 H
PULLANI, B.	8401240527*	50-271 Q	RAYNOR, J. W.	8401270086	50-318 S	REYNOLDS, N. S.	8401300244	50-445 Q
PULLANI, B. V.	8401030074	50-271 Q	READ, D. F.	8401100281	PR	REYNOLDS, N. S.	8401300244	50-445 Q
PULLANI, B. V.	8401100203*	50-334 Q	READ, D. F.	8401240561	PR	REYNOLDS, N. S.	8401240313*	50-354 Q
PULLANI, B. V.	8401240059*	50-272 Q	READ, D. F.	8401270375	50-400 Q	REYNOLDS, S. D.	8401240318*	50-412 Q
PUEY, A. M.	8401050050*	50-344 F	REAVIS, J. A.	8401200014	50-369 R	RHINELANDER, J.	8401230554	40-2061
QUAHME, D. L.	8401050341	50-329 A	REAVIS, J. A.	8401200033	50-269 R	RHINELANDER, J.	8401230554	40-2061
QUAHME, D. L.	8401050347	50-329 A	REBELLO, J. E.	8401040046*	CONTRACT	RHODES, G.	8401180268*	50-387 Q
QUAHME, D. L.	8401050350	50-329 Q	REBELLO, J. E.	8401100123*	CONTRACT	RHODES, G. K.	8401040081	50-410 C
QUAHME, D. L.	8401050371	50-329 A	REBELLO, J. E.	8401130129*	CONTRACT	RHODES, G. K.	8401040495	50-410 Q
QUAHME, D. L.	8401050393	50-329 A	REBELLO, J. E.	8401160409*	CONTRACT	RHODES, G. K.	8401230657	NUREG
QUAHME, D. L.	8401060343	50-329 A	REBELLO, J. E.	8401170119*	CONTRACT	RHODES, G. K.	8401110411*	MIBC
QUAHME, D. L.	8401100237	50-329 A	REBELLO, J. E.	8401230204*	CONTRACT	RICHARDS, S.	8401240313*	50-354 Q
QUAHME, D. L.	8401100286	50-329 A	REBELLOWSKI, T.	8401100446*	50-423 Q	RICHARDSON, C. A.	8401200106	71-9143
QUAHME, D. L.	8401100337	50-329 A	REBELLOWSKI, T. A.	8401240475*	50-423 Q	RICHTER, L.	8401300009	50-346 S
QUAHME, D. L.	8401100379	50-329 A	REECE, W. D.	8401260105	NUREG	RIDDLE, D. H.	8401060201*	CONTRACT
QUAHME, D. L.	8401120274	50-329 A	REED, C.	8401100275	50-454 Q	RIDDLE, D. H.	8401240576	PR
QUAHME, D. L.	8401120387	50-329 A	REED, C.	8401230149	50-373 Q	RIDGWAY, D. A.	8401160251	50-482 Q
QUAHME, D. L.	8401160090	50-329 S	REED, C.	8401230293	50-373 Q	RIDGWAY, K. R.	8401260208*	50-155 F
QUAHME, D. L.	8401160145	50-329 A	REED, C.	8401250013	50-237 Q	RIGGS, R.	8308190537*	ACRB
QUAHME, D. L.	8401190335	50-329 A	REED, C.	8401300207*	50-454 Q	RIGGS, R.	8401230657	NUREG
QUAHME, D. L.	8401230146	50-329 A	REED, G. J.	8401060091*	50-346 F	RILEY, E.	8401110167*	50-440 Q
QUAHME, D. L.	8401230356	50-329 A	REED, G. J.	8401260384*	50-346 F	RILEY, J. L.	8401040154	FOIA
QUAHME, D. L.	8401240501	50-329 A	REEVES, E. A.	8401060238	50-348 P	RILEY, J. L.	8401260132	50-413 Q
QUAHME, D. L.	8401240542*	50-329 A	REEVES, E. A.	8401130026	50-348 P	RILEY, J. L.	8401260132	50-413 Q
QUAHME, D. L.	8401270349	50-329 A	REEVES, E. A.	8401130448	50-348 P	RILEY, J. L.	8401260132	50-413 Q
QUAHME, D. L.	8401270367	50-329 A	REEVES, E. A.	8401190261	50-348 P	RILEY, J. L.	8401310323	50-413 Q
QUAHME, D. L.	8401270494	50-329 A	REEVES, E. A.	8401190444	50-348 P	RILEY, J. L.	8401310323	50-413 Q
QUAHME, D. L.	8401310213	50-329 A	REEVES, E. A.	8401200030	50-348 P	RINALDI, F.	8310280277*	50-329 A
QUICK, D. R.	8401240599*	50-438 Q	REEVE, J. O.	8401300038	WASTE MGT	RINALDI, M. J.	8401060391	50-289 U
QUIRK, J. F.	8401110265	50-447 A	REGAN, N. A.	8401130056	70-27	RINENBASK, G.	8312200076	50-321 F
QUIRK, J. F.	8401240523	50-447 A	REGAN, W. H.	8401090436	50-454 M	RISCHLING, J. L.	8401060311*	50-315 S
RADER, R. H.	8401100225	50-354 Q	REGAN, W. H.	8401090442*	50-454 M	RISCHLING, J. L.	8401060430*	50-316 B
RADER, R. H.	8401100225	50-354 Q	REGAN, W. H.	8401250326	50-454 M	RISCHLING, J. L.	8401100340	50-315 B
RADER, R. H.	8401120317	50-354 Q	REGAN, W. H.	8401250328*	50-454 M	RIVENSARK, G.	8401100210	50-321 P
RADER, R. H.	8401120317	50-354 Q	REGNIER, E. P.	8401300071	WASTE MGT	ROBBINS, J. Q.	8401100240	50-413 J
RADER, R. H.	8401130078	50-352 Q	REGNIER, E. P.	8401310444	WASTE MGT	ROBBINS, J. Q.	8401200039	TOPREP
RADER, R. H.	8401130078	50-352 Q	REHM, T. A.	8401040008	COMMISSION	ROBBINS, J. Q.	8401200149	TOPREP
RADER, R. H.	8401130122	50-352 Q	REHM, T. A.	8401050001	COMMISSION	ROBERTS, H. W.	8401040435*	50-482 Q
RADER, R. H.	8401130122	50-352 Q	REHM, T. A.	8401050024	50-528 A	ROBERTS, H. W.	8401050152*	GA999
RADER, R. H.	8401270294	50-354 Q	REID, K. A.	8401270334	50-318 S	ROBERTS, R. C.	8401180265	50-322 T
RADER, R. H.	8401270294	50-354 Q	REIDHAAR, D. L.	8401230416	50-142 Q	ROBERTS, T. H.	8401240114*	PR
RAFEEDIE, D. P.	8401130330	50-321 R	REINBACH, H. O.	8401230436*	GA999	ROBERTSON, J. B.	8401300092	WASTE MGT
RAHE, E. P.	8312200575	TOPREP	REIS, H. F.	8401050238	PR	ROBERTSON, J. C.	8401250055*	50-252 F
RAHE, E. P.	8401060396	PR	REIS, H. F.	8401050238	PR	ROCCO, B. P.	8401230157	MIBC
RAHE, E. P.	8401100360	PR	REIS, H. F.	8401050238	PR	ROCHELLE, J. K.	8401060067*	50-259 F
RAHE, E. P.	8401110042	TOPREP	REIS, H. F.	8401050238	PR	RODINO, P. W.	8401060391	50-289 U
RAHE, E. P.	8401110239	TOPREP	REIS, M. P.	8401260072	50-397 S	RODRIGUEZ, R. J.	8401040144	50-312 B
RAHE, E. P.	8401200055	TOPREP	REMICK, F. J.	8202120297*	FOIA	RODRIGUEZ, R. J.	8401040539	50-312 G
RAHE, E. P.	8401240471	TOPREP	REMBIS, B.	8401260183	50-354 Q	RODRIGUEZ, R. J.	8401100172	50-312 F
RAHE, E. P.	8401310007	TOPREP	REMY, M.	8401060113*	50-280 F	RODRIGUEZ, R. J.	8401120318	50-312 P
RAHE, E. P.	8401310352	TOPREP	RENTZ, F. L.	8401050025*	50-280 F	RODRIGUEZ, R. J.	8401130206	50-312 R
RAHSDALL, J. V.	8401130360	NUREG	RENTZ, F. L.	8401050408*	50-280 F	RODRIGUEZ, R. J.	8401160240	50-312 B
RANDALL, N.	8401270308*	GA999	REPKA, D. A.	8401040132	50-322 Q	RODRIGUEZ, R. J.	8401160265	50-312 B
RANDALL, N.	8401270314*	GA999	REPKA, D. A.	8401250360	50-322 Q	RODRIGUEZ, R. J.	8401240246	50-312 P
RANDAZZA, J. B.	8401170399*	50-309 Q	REQUA, G.	8401040072	50-261 P	RODRIGUEZ, R. J.	8401260098	50-312 B
RANDAZZA, J. B.	8401240175	50-309 P	RESNIKOFF, M.	8401030092*	40-86	RODRIGUEZ, R. J.	8401310261	50-312 P
RANDAZZA, J. B.	8401240284	50-309 P	RESNIKOFF, M.	8401030178*	40-86	RODRIGUEZ, R. J.	8401310351	50-312 P
RANDAZZO, T.	8401300381*	50-341 F	REBT, J.	8401160443	NUREG	ROE, K. K.	8401230228*	GA999
RANDEN, L.	8401100494	40-8102	REVELEY, W. T.	8401100153	50-322 Q	ROE, R. A.	8207110091*	40-86
RANDEN, L.	8401120114	WASTE MGT	REVELEY, W. T.	8401100153	50-322 Q	ROE, R. A.	8207180008*	40-86
RANDEN, L.	8401310496	40-8584	REVELEY, W. T.	8401100206	50-322 Q	ROE, R. A.	8208010047*	FOIA
RANDEN, L. D.	8401310508	40-1162	REVELEY, W. T.	8401100206	50-322 Q	ROE, R. A.	8209150025*	40-86
RAWSON, C. B.	8401310429*	GEN TEC IS	REYES, J. N.	8401310057	50-261 P	ROE, R. A.	8401030024*	40-86
RAPKIN, A.	8401080240	40-2061	REYES, L. A.	8401300086*	50-373 Q	ROE, R. A.	8401030033*	40-86
RASKIN, D. S.	8401170309	50-70 Q	REYNOLDS, A. B.	8401100123*	CONTRACT	ROE, R. A.	8401060391	50-289 U
RASKIN, P. D.	8401240095	50-261 T	REYNOLDS, J. R.	8401100159	50-275 Q	ROGERS, H. R.	8401030071	50-327 B

PERSONAL AUTHOR INDEX

84/01/01 - 84/01/31

84/01/01 - 84/01/31

84/01/01 - 84/01/31

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ROGERS, H. R.	8401030247	50-327 S	RUSSELL, L. B.	8401160131	50-318 S	SCHNELL, D. F.	8401270301	50-483 S
ROGERS, H. R.	8401030422	50-327 S	RUSSELL, L. B.	8401030186	50-318 S	SCHNELL, D. F.	8401310116	50-483 A
ROGERS, H. R.	8401260321	50-328 S	RUSSELL, L. B.	8401030268	50-317 S	SCHNELL, D. F.	8401310368*	50-483 Q
ROGERS, P.	8401030120	50-368 S	RUSSELL, L. B.	8401050101*	50-317 F	SCHOTT, Q. L.	8401310312	ACRS
ROGERS, P.	8401030170	50-313 S	RUSSELL, L. B.	8401050417*	50-317 F	SCHOTT, Q. L.	8401310312	ACRS
ROGERS, P.	8401030291	50-368 S	RUSSELL, L. B.	8401060266*	50-317 F	SCHOTT, Q. L.	8401310513	50-327 D
ROGERS, P.	8401100052	50-313 S	RUSSELL, L. B.	8401060278*	50-317 F	SCHOTT, Q. L.	8401310513	50-327 D
ROGERS, P.	8401100342	50-368 S	RUSSELL, L. B.	8401130212	50-317 S	SCHREIBER, R. E.	8401130220	NJREQ
ROGERS, P.	8401130210	50-313 S	RUSSELL, L. B.	8401160067	50-317 S	SCHROCK, C. A.	8401160278	50-305 S
ROGERS, P.	8401130215	50-313 S	RUSSELL, L. B.	8401160081	50-317 S	SCHROEDER, B. A.	8401160144	50-237 R
ROGERS, P.	8401130318	50-313 S	RUSSELL, L. B.	8401160087	50-318 S	SCHROEDER, C. W.	8401040278*	50-373 Q
ROGERS, P.	8401230242	50-313 S	RUSSELL, L. B.	8401160093	50-317 S	SCHROEDER, C. W.	8401050413	50-374 S
ROGERS, P.	8401230473	50-368 S	RUSSELL, L. B.	8401160126	50-317 S	SCHROEDER, C. W.	8401060271	50-373 P
ROGERS, W. O.	8401190386*	50-346 G	RUSSELL, L. B.	8401160171	50-318 S	SCHROEDER, C. W.	8401090142	50-373 P
ROGERS, W. H.	8401240106*	50-321 F	RUSSELL, L. B.	8401260281	50-317 S	SCHROEDER, C. W.	8401230288	50-373 P
ROMAN, F. R.	8401260163*	50-352 Q	RUSSELL, L. B.	8401270039	50-317 S	SCHROEDER, C. W.	8401230334*	50-373 Q
ROMAN, T. M.	8401170007	50-220 R	RUSSELL, L. B.	8401270065	50-318 S	SCHROEDER, C. W.	8401230338	50-373 F
ROMANO, F. R.	8401110312	50-352 Q	RUSSELL, L. B.	8401270086	50-318 S	SCHROEDER, C. W.	8401230339*	50-373 Q
ROMANO, F. R.	8401110316*	50-352 Q	RUSSELL, L. B.	8401270137	50-317 S	SCHROEDER, C. W.	8401230424	50-373 F
ROMANO, F. R.	8401110319*	50-352 Q	RUSSELL, L. B.	8401270281	50-317 S	SCHROEDER, J. J.	8401170239*	50-400 Q
ROMANO, F. R.	8401110321*	50-352 Q	RUSSELL, L. B.	8401270334	50-318 S	SCHROEDER, J. J.	8401170239*	50-400 Q
ROMANO, F. R.	8401110322*	50-352 Q	RUSSELL, L. B.	8401300358*	50-317 F	SCHUH, J. A.	8401030370	NJREQ
ROMANO, F. R.	8401260142	50-352 Q	RUTHER, W. E.	8401160443	NJREQ	SCHUM, W. B.	8401040457*	50-482 Q
ROMANO, F. R.	8401260149*	50-352 Q	RYAN, T.	8401050372*	50-286 F	SCHUM, W. B.	8401040466*	50-482 Q
ROMANO, F. R.	8401260153*	50-352 Q	RYBAK, B.	8401040329	50-237 P	SCHUMACHER, M.	8401050339*	50-483 P
ROMANO, F. R.	8401260168*	50-352 Q	RYBAK, B.	8401100350	50-237 P	SCHUMACHER, M.	8401260090*	50-315 Q
ROMANO, F. R.	8401260172*	50-352 Q	RYBAK, B.	8401160309	50-237 P	SCHUMACHER, M. C.	8401230387*	50-483 Q
ROMANO, F. R.	8401310328	50-352 Q	RYBAK, B.	8401180232	50-237 P	SCHUSTER, M. D.	8312970264*	50-312 Q
ROMANO, F. R.	8401310333*	50-352 Q	RYBAK, B.	8401230327	50-237 P	SCHUSTER, M. D.	8401300188*	50-206 Q
ROMANO, F. R.	8401310337*	50-352 Q	RYBAK, B.	8401230456	50-249 P	SCHUYLER, J. O.	8401040567	50-275 P
RODD, H.	8312190111	50-361 P	SABADOS, J. W.	8401240375*	70-27	SCHUYLER, J. O.	8401060002	50-275 P
RODD, H.	8401190108	50-362 F	SAITO, T.	8401110334	XPORTLIC	SCHUYLER, J. O.	8401100319	50-275 P
RODNEY, V. L.	8401190011	50-271 P	SALGO, H.	8401050242	50-261 Q	SCHUYLER, J. O.	8401100387	50-275 E
ROSENBERG, E. B.	8401190332*	CONTRACT	SALGO, H.	8401050242	50-261 Q	SCHUYLER, J. O.	8401100417	50-275 E
ROSENBLUM, R. H.	8401270225*	50-206 P	SALGO, H.	8401050283	50-261 Q	SCHUYLER, J. O.	8401120207	50-275 P
ROSENBLUM, R. H.	8401270229*	50-206 P	SALGO, H.	8401050283	50-261 Q	SCHUYLER, J. O.	8401120212*	50-275 P
ROSENTHAL, H.	8401240197	50-275 U	SALIN, J. A.	8401030235	50-333 S	SCHUYLER, J. O.	8401160234	50-275 S
ROSLER, E.	8401100197	50-344 Q	SALTZMAN, J.	8401060334	50-373 J	SCHUYLER, J. O.	8401170156	50-275 P
ROSS, B.	8401060222*	CONTRACT	SALTZMAN, J.	8401060559	70-2949 J	SCHUYLER, J. O.	8401170161*	50-275 P
ROSS, W. J.	8401090119*	50-261 G	SALTZMAN, J.	8401060615	50-397 J	SCHUYLER, J. O.	8401240134	50-275 P
ROSSEBACH, L. W.	8401100382*	50-286 Q	SALTZMAN, J.	8401170511	70-2985	SCHUYLER, J. O.	8401240247	50-275 E
ROSSI, A. R.	8401180274*	50-322 T	SANDERN, G.	8401030018*	FOIA	SCHUYLER, J. O.	8401240410	50-275 F
ROSSI, C.	8401160433	MIBC	SANDERS, C. F.	8401240366	70-1181	SCHUYLER, J. O.	8401240503	50-275 F
ROSSI, C.	8401160449	MIBC	SANDERS, C. F.	8401240528	70-1181	SCHUYLER, J. O.	8401240555	50-275 E
ROSSI, C. E.	8401250166	MIBC	SANDERS, R. L.	8401200089*	50-261 Q	SCHUYLER, J. O.	8401260192	50-275 F
ROSSI, C. E.	8401250469	MIBC	SANDERS, W. F.	8401050468*	50-424 Q	SCHUYLER, J. O.	8401260218	50-275 E
ROTH, J.	8401100177*	70-820	SANDERS, W. F.	8401070476*	50-424 Q	SCHUYLER, J. O.	8401270195*	50-275 Q
ROTHSCHILD, T.	8207060317*	FOIA	SANDLINO, M. J.	8401100476*	REVIEW ORP	SCHWAN, C.	8401030245	50-275 S
ROTHSCHILD, T.	8401250376*	FOIA	SANDQUIST, G. H.	8401300111	50-407 V	SCHWAN, C. A.	8401040223*	70-734
ROUKEMA, M.	8401060391	50-289 U	SAKWER, H. S.	8401270221	50-319 Q	SCHWEDT, A. R.	8401030263*	50-220 S
ROUSE, L. C.	8111160351*	70-938	SARBOUR, B.	8401120322	50-346 R	SCHWEDT, A. R.	8401030265*	50-220 S
ROUSE, L. C.	8401040092*	70-938	SARBOUR, B.	8401170196	50-346 R	SCHWEDT, A. R.	8401160160	50-220 S
ROUSE, L. C.	8401040094*	70-938	SASSER, D. W.	8401090612	NJREQ	SCHWEDT, A. R.	8401160168	50-220 S
ROUSE, L. C.	8401050344	PROJ	SAUER, R. E.	8401110450	WASTE MGT	SCHWEDT, A. R.	8401270133	50-220 S
ROUSE, L. C.	8401110347	70-754	SAUER, R. E.	8401170342	WASTE MGT	SCHWENGER, A.	8401030297	50-352 D
ROUSE, L. C.	8401190416	70-687	SAUNDERS, R. A.	8401120291	50-280 R	SCHWENGER, A.	8401030301*	50-352 D
ROUSE, L. C.	8401310475	70-754	SAUNDERS, R. F.	8312200074	50-281 S	SCHWENGER, A.	8401030309	50-352 D
ROVACH, T. J.	8401300348*	50-254 F	SAUNDERS, R. F.	8401040322	50-281 S	SCHWENGER, A.	8401030316	50-416 P
ROWE, D. B.	8401130129*	CONTRACT	SAUNDERS, R. F.	8401040325	50-280 S	SCHWENGER, A.	8401030321	50-352 A
ROZAK, S.	8401030339*	40-8631	SAUNDERS, R. F.	8401040369	50-280 S	SCHWENGER, A.	8401030417	50-410 A
ROZAK, S.	8401260090*	50-315 Q	SAVAGE, J. A.	8401100263	PR	SCHWENGER, A.	8401040057	50-352 D
ROZAK, S.	8401300233	50-259 S	SCARANO, R. A.	8401200051	50-328 F	SCHWENGER, A.	8401040064*	50-352 D
RUBENSTEIN, L. B.	8401120186*	50-334 P	SCARANO, R. A.	8401300253	50-326 Q	SCHWENGER, A.	8401090101	50-458 H
RUDDY, D.	8401270429	50-333 S	SCHAEFER, D. W.	8401200004	50-275 S	SCHWENGER, A.	8401090108*	50-458 H
RUHLMAN, W. A.	8401160431	FOIA	SCHAPKER, J.	8401040462	50-546 S	SCHWENGER, A.	8401090544	50-416 P
RUITER, G. H.	8401160089	50-305 R	SCHAPKER, J. F.	8401200523*	50-546 Q	SCHWENGER, A.	8401090772	50-353 A
RULAND, W. H.	8401050626*	50-348 Q	SCHAUER, F. P.	8401170090*	FOIA	SCHWENGER, A.	8401100034	50-352 E
RULAND, W. H.	8401240359*	50-395 Q	SCHIEDT, D. J.	8401170229	50-322 Q	SCHWENGER, A.	8401110370	50-352 D
RULAND, W. H.	8401240580*	50-348 Q	SCHIEDT, D. J.	8401170229	50-322 Q	SCHWENGER, A.	8401110477	50-352 A
RULAND, W. H.	8401240606*	50-348 Q	SCHERER, A. E.	8401090378	PR	SCHWENGER, A.	8401110555	50-322 A
RUNNER, W. R.	8401030023*	50-280 F	SCHERER, A. E.	8401200004	TOPREP	SCHWENGER, A.	8401110560	50-458 A
RUNNER, W. R.	8401050408*	50-280 F	SCHMIDT, H. C.	8401050274	50-445 A	SCHWENGER, A.	8401170563*	50-397 P
RUPP, J. L.	8401130214	50-272 S	SCHMIDT, H. C.	8401100349	50-445 A	SCHWENGER, A.	8401190005*	50-374 F
RUPP, J. L.	8401130256	50-272 S	SCHMITT, T. J.	8401300177	WASTE MGT	SCHWENGER, A.	8401190070	50-397 E
RUPP, J. L.	8401130285	50-311 S	SCHNEIDER, K. N.	8401180084	WASTE MGT	SCHWENGER, A.	8401190163	50-373 F
RUPP, J. L.	8401130320	50-311 S	SCHNELL, D. F.	8401030323*	50-483 F	SCHWENGER, A.	8401190224	50-410 A
RUPP, J. L.	8401130327	50-272 S	SCHNELL, D. F.	8401060365*	50-483 S	SCHWENGER, A.	8401230671	50-458 A
RUPP, J. L.	8401130333	50-311 S	SCHNELL, D. F.	8401100339	50-483 A	SCHWENGER, A.	8401230388	50-387 F
RUPP, J. L.	8401240002	50-311 S	SCHNELL, D. F.	8401160179*	50-483 Q	SCHWENGER, A.	8401260200	50-373 P
RUPP, J. L.	8401270087	50-272 S	SCHNELL, D. F.	8401230177	50-483 Q	SCHWENK, G. A.	8401120342*	50-400 Q
RUPP, J. L.	8401270180	50-272 S	SCHNELL, D. F.	8401230231	50-483 S	SCHWINK, W.	8401270238	REVIEW ORP
RUPP, J. L.	8401270464	50-272 S	SCHNELL, D. F.	8401230350	50-483 S	SCINTO, J.	8401160194*	50-155 F
RUSHMORE, J. W.	8401230006	50-220 J	SCHNELL, D. F.	8401240137	50-483 S	SCOTT, A. E.	8401160167	50-261 R
RUSHMORE, J. W.	8401230486	50-220 J	SCHNELL, D. F.	8401240152	50-483 S	SCOTT, D. J.	8401040397	50-237 S
RUBBACHER, G. E.	8401130220	NJREQ	SCHNELL, D. F.	8401270411	50-483 K	SCOTT, D. J.	8401050632	50-10 S

PERSONAL AUTHOR INDEX

505

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SCOTT, D J	8401100458	50-237 S	SHANNON, J B	8401110085	40-8064	SINCLAIR, J R	8401230639*	50-329 Q
SCOTT, D J	8401130043	50-237 S	SHANNON, J B	8401270183	40-8064	SINCLAIR, J R	8401230644*	50-329 Q
SCOTT, D J	8401130184	50-237 S	SHAPAR, H	8006130374*	FOIA	SINDERBRAND, C	8401100134	WASTE MGT
SCOTT, D J	8401130185	50-237 S	SHARPE, T J	8401260138	50-259 S	SINDERBRAND, C	8401100202	WASTE MGT
SCOTT, D J	8401130234	50-237 S	SHATTERLY, L W	8401100487*	QA999	SINGH, M M	8401160462*	CONTRACT
SCOTT, D J	8401160144	50-237 R	SHATTERLY, L W	8401230148*	40-7982	SINISI, J M	8401060247	50-29 J
SCOTT, D J	8401230002	50-237 S	SHAUB, E T	8401260369*	50-289 Q	SINISI, J M	8401060252	50-293 J
SCOTT, D J	8401230010	50-237 S	SHAUB, E T	8401310166*	50-277 Q	SINISI, J M	8401060262	50-29 J
SCOTT, D J	8401250086*	50-10 F	SHAW, R Q	8401270494*	QA999	SINISI, J M	8401130016	50-213 J
SCOTT, D J	8401270357	50-237 S	SHEA, J J	8401160088	50-213 P	SINISI, J M	8401130130	50-213 J
SCOTT, D J	8401300281	50-237 S	SHEA, J J	8401230151	50-213 P	SINISI, J M	8401230477	50-245 J
SCOTT, D J	8401310180*	50-10 F	SHEA, J J	8401230449	50-245 P	SINKIN, L	8401240292	50-498 Q
SCOTT, D M	8401110260	50-219 P	SHEA, J R	8401200320	HIBC	SINKIN, L A	8401180188	50-498 Q
SCOVILLE, J J	8401190253	27-48	SHEARIN, R V	8401190298	50-413 Q	SINKIN, L A	8401180188	50-498 Q
SCOWN, K	8401200022*	50-397 Q	SHEARIN, R V	8401240165	50-413 Q	SINSLON, O L	8401130323	WASTE MGT
SEALE, R L	8401310510	ACRS	SHEARIN, R V	8401300231	50-413 Q	SKARUPA, J D	8401060373	XPORTLIC
SEALE, R L	8401310510	ACRS	SHELOSKY, J T	8401030279*	50-322 Q	SKARUPA, J D	8401060476	XPORTLIC
SEARS, C F	8401050265	50-423 V	SHEMAN, D	8401130058	71-6574	SKARUPA, J D	8401090058	XPORTLIC
SEARS, C F	8401060045	50-423 A	SHEBELHUT, C	8401100194	50-358 Q	SKARUPA, J D	840110340	XPORTLIC
SEARS, C F	8401060045	50-423 A	SHELLEY, W J	8401160103	40-2061	SKARUPA, J D	840110351	XPORTLIC
SEARS, C F	8401160174	50-423 S	SHELLEY, W J	8401230044	40-8768	SKARUPA, J D	8401120133	XPORTLIC
SEARS, C F	8401160174	50-423 S	SHELLEY, W J	8401230328*	70-925	SKJEI, R E	8401170354	QA999
SEARS, C F	8401170379	50-336 P	SHEPPARD, J J	8401050164	TOPREP	SLACKS, S T	8401240200*	50-129 Q
SEARS, C F	8401230175	50-423 K	SHEPPARD, J J	8401050164	TOPREP	SLACKS, S T	8401240210*	50-129 Q
SEARS, C F	8401230175	50-423 K	SHERON, B	8401170018*	FOIA	SLAGGIE, E L	8206110136*	FOIA
SEARS, C F	8401230373	50-213 P	SHERWOOD, G G	8401160288*	50-461 S	SLAGGIE, E L	8206290623*	FOIA
SEARS, C F	8401230373	50-213 P	SHERWOOD, G G	8401310291	TOPREP	SLAGGIE, E L	8206300094*	FOIA
SEARS, C F	8401230467	50-423 F	SHERWOOD, M R	8401310013	50-133 Q	SLAGGIE, E L	8209210015*	FOIA
SEARS, C F	8401230467	50-423 F	SHERWOOD, M R	8401310016*	50-133 Q	SLAGGIE, E L	8211030044*	FOIA
SEARS, P M	8401130382*	QA999	SHERWOOD, M R	8401310146	50-133 Q	SLAGGIE, E L	8211030079*	FOIA
SEARS, P M	8401170282*	QA999	SHERWOOD, M R	8401310146	50-133 Q	SLAGGIE, E L	8211090002*	FOIA
SEGE, Q	8401230657	NUREG	SHICK, V	8401300103*	40-8331	SLAGGIE, E L	8211090063*	FOIA
SEIDLE, W C	8401040111*	50-313 Q	SHIELDS, S W	8401050576	50-546 Q	SLAGGIE, E L	8211190008*	FOIA
SEIDLE, W C	8401040450	50-482 Q	SHIELDS, S W	8401130301*	50-546 Q	SLAGGIE, E L	8401250263*	50-251 Q
SEIDLE, W C	8401040524	50-285 Q	SHIELDS, S W	8401300229*	50-546 Q	SLAGGIE, E L	8401250269*	50-358 Q
SEIDLE, W C	8401130332	50-313 Q	SHIFFER, J D	8401040185	50-275 S	SLAGGIE, E L	8401250363*	FOIA
SEIDLE, W C	8401170394*	50-482 Q	SHIFFER, J D	8401040261	50-275 S	SLAWINSKI, W J	8401260090*	50-315 Q
SEIKEN, S J	8401100456	50-482 S	SHIFFER, J D	8401040308	50-275 S	SMALLEY, J	8401130076*	NUREG
SEIKEN, S J	8401240573	50-482 Q	SHIFFER, J D	8401040548	50-275 S	SMEDIRA, C	8401230364*	QA999
SELAN, J C	8306140082*	50-254 P	SHIFFER, J D	8401120397	50-275 S	SMITH, A L	8401040435*	50-482 G
SELAN, J C	8307190298*	50-220 P	SHIFFER, J D	8401160264	50-275 S	SMITH, A L	8401050237*	QA999
SELAN, J C	8312140428*	50-313 P	SHIFFER, J D	8401160276	50-275 S	SMITH, A L	8401130372*	QA999
SELLS, D E	8401130459	50-335 S	SHIFFER, J D	8401260332	50-275 S	SMITH, A L	8401130376*	QA999
SEARIN, S L	8401310342*	70-2985	SHIFFER, J D	8401160255	50-275 S	SMITH, C	8401060391	50-289 U
SERVER, W L	8401120073	NUREG	SHIRAKAWA, T	8401110342	XPORTLIC	SMITH, C M	8401230039	NUREG
SESHAGIRI, M L	8401130107*	QA999	SHIRAKAWA, T	8401110345	XPORTLIC	SMITH, C M	8401230690	NUREG
SEXTON, D E	8401103133	50-352 A	SHOEMAKER, C J	8401130112	50-322 Q	SMITH, G	8401300290	50-213 S
SEYFRIT, K V	8308090279*	50-313 Q	SHOEMAKER, C J	8401200127	50-352 Q	SMITH, G	8401310099*	70-687
SEYFRIT, K V	8308150373*	50-313 Q	SHOEMAKER, C J	8401260175	50-443 Q	SMITH, H	8401250484	50-237 P
SHACK, W J	8401160443	NUREG	SHOEMAKER, C J	8401260209	50-354 Q	SMITH, I W	8401120306	50-434 T
SHADER, D	8401130322	50-271 J	SHOEMAKER, C J	8401300252	50-519 Q	SMITH, I W	8401230408	50-289 Q
SHAFFER, P W	8401060480	50-409 R	SHOEMAKER, C J	8401310339	50-413 Q	SMITH, I W	8401230439	50-434 Q
SHAFFER, P W	8401260021*	50-409 F	SHOLLY, S C	8401230594	FOIA	SMITH, J	8401060090*	50-269 F
SHAFFER, W	8401100190	50-409 S	SHOLLY, S C	8401230605	FOIA	SMITH, J	8401060094*	50-269 F
SHAFFER, W	8401130393	50-346 S	SHOPENN, N M	8401050254	70-121	SMITH, J C	8401270342	40-6622
SHAFFER, W	8401160230	50-255 S	SHOPENN, N M	8401270439*	40-2259	SMITH, J L	8401030239	50-322 S
SHAFFER, W	8401230298	50-373 S	SHULMAN, H J	8206300033*	FOIA	SMITH, J L	8401030337*	50-322 F
SHAFFER, W	8401300110	50-295 S	SHULMAN, H J	8206300371*	50-382 A	SMITH, J L	8401050505	50-322 A
SHAFFER, W D	8401040375	50-254 Q	SHYLOCK, M B	8401050681*	50-280 Q	SMITH, J L	8401120530	71-5939
SHAFFER, W D	8401100202	50-331 Q	SHYLOCK, M B	8401050539*	50-338 Q	SMITH, J L	8401250151*	50-322 F
SHAFFER, W D	8401100432	50-263 Q	SHYLOCK, M B	8401050614*	50-338 Q	SMITH, J T	8401200099	50-322 T
SHAFFER, W D	8401190380	50-346 Q	SHYLOCK, M B	8401050622*	50-338 Q	SMITH, M H	8401090606	NUREG
SHAFFER, W D	8401190381*	50-346 Q	SHYLOCK, M B	8401090056*	50-338 Q	SMITH, P M	8401170547	WASTE MGT
SHAFFER, W D	8401190383*	50-346 Q	SHYLOCK, M B	8401240553*	50-338 Q	SMITH, R C	8401300154*	CONTRACT
SHAFFER, W D	8401190393	50-305 Q	SILBERBERG, M	8401160400*	FOIA	SMITH, R C	8401030323*	50-317 P
SHAFFER, W D	8401190396*	50-305 Q	SILBERG, J E	8401030152	50-482 Q	SMITH, R D	8401060594	40-8829
SHAFFER, W D	8401190408	50-315 Q	SILBERG, J E	8401030152	50-482 Q	SMITH, R D	8401060612	40-8585
SHAFFER, W D	8401190410*	50-315 Q	SILBERG, J E	8401030153	50-412 Q	SMITH, R D	8401060671	40-8768
SHAFFER, W D	8401190424	50-295 Q	SILBERG, J E	8401030153	50-412 Q	SMITH, R D	8401090404	40-8586
SHAFFER, W D	8401190440*	50-295 Q	SILBERG, J E	8401030158	50-482 Q	SMITH, R D	8401090410	40-8348
SHAFFER, W D	8401230367	50-315 Q	SILBERG, J E	8401030158	50-482 Q	SMITH, R D	8401310410	40-8728
SHAFFER, W D	8401240314	50-282 Q	SILBERG, J E	8401050183	50-482 Q	SMITH, R D	8401310415	40-6659
SHAFFER, W D	8401240316	50-346 Q	SILBERG, J E	8401030183	50-482 Q	SMITH, R D	8401310428	40-1162
SHAFFER, W D	8401240320*	50-282 Q	SILBERG, J E	8401050195	FR	SMITH, R D	8401310442	40-4492
SHAFFER, W D	8401240321*	50-282 Q	SILVER, E Q	8401180072	NUREG	SMITH, R H	8401100400*	50-272 Q
SHAFFER, W D	8401240474	50-346 Q	SILVERMAN, D J	8401300249	50-498 Q	SMITH, W F	8401040291*	50-298 Q
SHAFFER, W D	8401270359	50-373 Q	SILVERMAN, D J	8401300249	50-498 Q	SMITH, W F	8401040439*	50-482 Q
SHAFFER, W D	8401270361*	50-373 Q	SILVERMAN, D J	8401300260	50-498 Q	SMITH, W G	8401040323	50-315 S
SHAFFER, W D	8401270461	50-331 Q	SILVERMAN, D J	8401300260	50-498 Q	SMITH, W G	8401040340	50-315 S
SHAFFER, W D	8401300315	50-255 Q	SIM, S	8401030340	NUREG	SMITH, W G	8401040355	50-316 S
SHAFFER, C J	8312060402*	50-423 K	SIMIU, E	8401310104*	50-498 A	SMITH, W G	8401050441	50-315 S
SHANBANKY, M	8401100241*	50-387 Q	SIMIU, E	8401310108*	50-498 A	SMITH, W G	8401050636	50-315 S
SHANBANKY, M	8401040430*	50-317 Q	SIMPSON, E C	8401240575*	50-302 Q	SMITH, W G	8401050678	50-315 S
SHANNON, J B	8401090191	40-8064	SIMPSON, E C	8401230398	50-395 S	SMITH, W G	8401050695	50-315 S
SHANNON, J B	8401100103*	40-8064	SINCLAIR, J B	8401270492	50-271 P	SMITH, W G	8401060425	50-316 S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SMITH, W. Q.	8401060434	50-316 S	SPRIGGS, G. D.	8401030323*	50-317 P	STEPTOE, P. P.	8401090384*	50-329 Q
SMITH, W. Q.	8401100340	50-315 S	SPULAK, R. Q.	8401030364	50-245 P	STEPTOE, P. P.	8401090384*	50-329 Q
SMITH, W. Q.	8401190177	50-315 S	BRENIAWSKI, D.	8401240358*	40-17	STEPTOE, P. P.	8401240073	50-329 Q
SMITH, W. Q.	8401130331	50-316 S	BRENIAWSKI, D.	8401310290	I&E	STERN, F.	8401240454*	GA999
SMITH, W. Q.	8401130336	50-315 S	BRENIAWSKI, D. J.	8401100262	40-8760	STETKA, T. F.	8401050648*	50-302 Q
SMITH, W. Q.	8401130349	50-315 S	ST LAURENT, N. N.	8401270258	50-29 B	STETKA, T. F.	8401090361*	50-302 Q
SMITH, W. Q.	8401190371	50-315 S	ST MARY, F. A.	8401040104*	FOIA	STETKA, T. F.	8401240401*	50-302 Q
SMITH, W. Q.	8401230319	50-316 S	STACK, D.	8401030364	50-245 P	STETKA, T. F.	8401240446*	50-302 Q
SMITH, W. Q.	8401240063	50-315 S	STADNICK, S.	8401040183	50-336 S	STETKA, T. F.	8401240589*	50-302 Q
SMITH, W. Q.	8401240167	50-315 S	STAHL, D.	8401130379	MUREQ	STEVENS, D. W.	8401130154	WASTE MGT
SMITH, W. Q.	8401240183	50-316 S	STANGE, S. J.	8401040628*	50-289 F	STEVENS, D. W.	8401310281	WASTE MGT
SMITH, W. Q.	8401270446	50-315 R	STANGE, S. J.	8401050037*	50-320 F	STEVENS, D. W.	8401310282*	WASTE MGT
SMITH, W. Q.	8401270477	50-316 R	STANGE, S. J.	8401050049*	50-320 F	STEVENS, J. L.	8401100268	50-309 S
SMITH, W. Q.	8401300195	50-316 S	STANGE, S. J.	8401050119*	50-289 F	STEWART, C. A.	8401180212	50-416 Q
SMITH, W. Q.	8401300242	50-315 S	STANGE, S. J.	8401060111*	50-320 F	STEWART, J. P.	8401300151*	50-206 Q
SMITH, W. Q.	8401300257	50-316 S	STANGE, S. J.	8401060158*	50-289 F	STEWART, W. L.	8401030187	50-280 Q
SMITH, W. Q.	8401310050	50-316 S	STANGE, S. J.	8401310219*	50-320 F	STEWART, W. L.	8401030347*	50-280 F
SMITH, W. Q.	8401310301	50-315 S	STANDLER, C. A.	8401300096*	50-424 Q	STEWART, W. L.	8401030357*	50-338 F
SMITH, W. Q.	8401310301	50-315 S	STANGLER, C. A.	8401300100*	50-424 Q	STEWART, W. L.	8401040229	50-338 F
SMITH, W. Q.	8401310406	50-315 S	STAPLETON, B. W.	8401040480*	50-483 Q	STEWART, W. L.	8401040424	50-338 F
SMOLEN, H.	8401270203	50-352 Q	STAPLETON, B. W.	8401100434*	50-454 Q	STEWART, W. L.	8401040445	50-338 H
SMYTH, C. W.	8401190372	50-289 R	STAROSTECKI, R.	8401030259	50-322 Q	STEWART, W. L.	8401040520	50-338 F
SNELL, W.	8401190364*	50-409 Q	STAROSTECKI, R.	8401030269	50-322 Q	STEWART, W. L.	8401040552	50-280 F
SNOW, S. A.	8401120411	50-244 R	STAROSTECKI, R.	8401040153	50-272 Q	STEWART, W. L.	8401040560	50-280 F
SNOW, S. A.	8401270292	50-244 R	STAROSTECKI, R.	8401040198	50-352 Q	STEWART, W. L.	8401050114*	50-338 F
SNYDER, B. J.	8401170515	50-320 P	STAROSTECKI, R.	8401040382	50-289 Q	STEWART, W. L.	8401050404*	50-280 F
SNYDER, B. J.	8401190226	50-320 P	STAROSTECKI, R.	8401040401	50-333 Q	STEWART, W. L.	8401050464	50-280 Q
SNYDER, G. L.	8401050045*	40-86	STAROSTECKI, R.	8401040569	50-322 Q	STEWART, W. L.	8401050480*	50-280 Q
SNYDER, J.	8401130212	50-317 S	STAROSTECKI, R.	8401040619	50-29 Q	STEWART, W. L.	8401050493*	50-280 Q
SOLARI, A. J.	8401180169	PR	STAROSTECKI, R.	8401100155	50-247 Q	STEWART, W. L.	8401050496*	50-338 Q
SOLINI, J. A.	8401270139	50-333 S	STAROSTECKI, R.	8401100175	70-820	STEWART, W. L.	8401050575*	50-338 Q
SOLLEY, S. W.	8401240442	50-259 S	STAROSTECKI, R.	8401100267	50-289 Q	STEWART, W. L.	8401050579*	50-338 Q
SOMNICHSEN, J. C.	8401270335*	WASTE MGT	STAROSTECKI, R.	8401100270	50-277 Q	STEWART, W. L.	8401050664*	50-280 Q
SOONG, A. L.	8312190273*	70-398	STAROSTECKI, R.	8401100276	50-412 Q	STEWART, W. L.	8401060048	50-338 F
SOONG, A. L.	8401200061*	70-36	STAROSTECKI, R.	8401100303	50-271 Q	STEWART, W. L.	8401060113*	50-280 F
SORENSEN, O. C.	8401030254*	50-397 Q	STAROSTECKI, R.	8401100322	50-322 Q	STEWART, W. L.	8401060296	50-338 J
SORENSEN, O. C.	8401030270	50-397 P	STAROSTECKI, R.	8401100325	50-213 Q	STEWART, W. L.	8401060306	50-280 P
SORENSEN, O. C.	8401040310	50-397 S	STAROSTECKI, R.	8401100374	50-286 Q	STEWART, W. L.	8401090347	PRH
SORENSEN, O. C.	8401040318	50-397 S	STAROSTECKI, R.	8401100408	50-272 Q	STEWART, W. L.	8401090500	50-338 P
SORENSEN, O. C.	8401040333	50-397 S	STAROSTECKI, R.	8401100431	50-309 Q	STEWART, W. L.	8401120253	50-338 R
SORENSEN, O. C.	8401040507	50-397 P	STAROSTECKI, R.	8401100441	50-423 Q	STEWART, W. L.	8401120291	50-280 R
SORENSEN, O. C.	8401040579	50-397 S	STAROSTECKI, R.	8401130131	50-272 Q	STEWART, W. L.	8401160075	50-280 P
SORENSEN, O. C.	8401050003*	50-397 F	STAROSTECKI, R.	8401130249	50-317 Q	STEWART, W. L.	8401170189	50-280 P
SORENSEN, O. C.	8401100185	50-460 K	STAROSTECKI, R.	8401160305*	50-293 Q	STEWART, W. L.	8401170437	50-280 P
SORENSEN, O. C.	8401160069	50-397 P	STAROSTECKI, R.	8401170356	50-244 Q	STEWART, W. L.	8401240225	50-338 P
SORENSEN, O. C.	8401180217	50-397 J	STAROSTECKI, R.	8401170390	50-309 Q	STEWART, W. L.	8401240301	50-338 F
SORENSEN, O. C.	8401240162	50-397 E	STAROSTECKI, R.	8401170406	50-352 H	STEWART, W. L.	8401240409	50-280 F
SORENSEN, O. C.	8401300062	50-397 E	STAROSTECKI, R.	8401180196	50-247 Q	STEWART, W. L.	8401240488*	50-281 Q
SORENSEN, O. C.	8401300066	50-397 P	STAROSTECKI, R.	8401180208	50-220 Q	STEWART, W. L.	8401250044	50-280 P
SORENSEN, O. C.	8401300075	50-397 E	STAROSTECKI, R.	8401180237	50-245 Q	STEWART, W. L.	8401260205*	50-338 F
SORENSEN, O. C.	8401300166	50-397 P	STAROSTECKI, R.	8401180251	50-387 Q	STEWART, W. L.	8401260257*	50-338 F
SORENSEN, O. C.	8401300235	50-397 P	STAROSTECKI, R.	8401190127	50-309 Q	STEWART, W. L.	8401270233	50-280 P
SORENSEN, O. C.	8401310021	50-397 P	STAROSTECKI, R.	8401190370	50-410 Q	STEWART, W. L.	8401270268	50-338 P
SORENSEN, O. C.	8401310027	50-397 P	STAROSTECKI, R.	8401230137	50-293 Q	STEWART, W. L.	8401270372	50-280 R
SORENSEN, O. C.	8401310131	50-397 F	STAROSTECKI, R.	8401230163	50-387 Q	STEWART, W. L.	8401300178	50-338 F
SORENSEN, O. C.	8401310215	50-397 P	STAROSTECKI, R.	8401230454	50-272 Q	STEWART, W. L.	8401300309	50-280 P
SORENSEN, O. C.	8401310276	50-308 A	STAROSTECKI, R.	8401230563	50-309 Q	STEWART, W. L.	8401310210	50-338 P
SORENSEN, O. C.	8401310376	50-397 E	STAROSTECKI, R.	8401240109	50-29 Q	STEWART, W. L.	8401310402	50-338 P
SPANE, F. A.	8401120022*	WASTE MGT	STAROSTECKI, R.	8401240197	50-219 Q	STIER, E. H.	8401250284*	50-320 P
SPANE, F. A.	8401120025*	WASTE MGT	STAROSTECKI, R.	8401240467	50-423 Q	STIER, E. H.	8401250287*	50-320 P
SPANE, F. A.	8401120028*	WASTE MGT	STAROSTECKI, R.	8401240520	50-272 Q	STILLER, M. A.	8401230313*	50-483 F
SPANE, F. A.	8401120033*	WASTE MGT	STAROSTECKI, R.	8401240596	50-352 Q	STODDART, P. Q.	8401060410*	50-348 Q
SPANE, F. A.	8401120037*	WASTE MGT	STAROSTECKI, R.	8401240619*	50-272 Q	STOHR, J. B.	8401050520	70-27
SPANE, F. A.	8401120040*	WASTE MGT	STAROSTECKI, R.	8401260166	50-387 Q	STOHR, J. P.	8401050348	70-1131
SPECTER, S. H.	8401250100*	50-244 F	STAROSTECKI, R.	8401300283	50-443 Q	STOHR, J. P.	8401050355*	70-1131
SPECTER, S. H.	8401310249*	50-244 F	STAROSTECKI, R.	8401310037	50-334 Q	STOHR, J. P.	8401050433	70-1201
SPECTER, A. L.	8401110329*	50-289 U	STAROSTECKI, R.	8401310377	50-352 Q	STOHR, J. P.	8401050599	70-27
SPEIB, T.	8204260021*	FOIA	STAROSTECKI, R.	8401230442*	50-10 Q	STOHR, J. P.	8401060444	40-6011
SPEIB, T. P.	8401190107	MISC	STEFAN, J. J.	8401130451	50-440 A	STOHR, J. P.	8401060490*	40-6011
SPEIBARD, R. L.	8312190222	50-341 Q	STEFANO, J. J.	8401170038*	50-440 A	STOHR, J. P.	8401090112	70-143
SPEIBARD, R. L.	8401040268	50-373 Q	STEINDEL, S. H.	8401270371	50-329 Q	STOHR, J. P.	8401240330	70-143
SPEIBARD, R. L.	8401100344	50-409 Q	STEINDEL, S. H.	8401270371	50-329 Q	STOHR, J. P.	8401240343	70-27
SPEIBARD, R. L.	8401120227	50-315 Q	STEINDEL, S. H.	8401270384	50-329 Q	STOHR, J. P.	8401240346*	70-143
SPEIBARD, R. L.	8401120238*	50-315 Q	STEINDEL, S. H.	8401270384	50-329 Q	STOHR, J. P.	8401240356	70-1151
SPEIBARD, R. L.	8401190315	50-263 Q	STEINKOENIG, K.	8401230609	FOIA	STOHR, J. P.	8401240370	70-27
SPEIBARD, R. L.	8401190321*	50-263 Q	STELLO, V.	8401110247*	50-320 U	STOHR, J. P.	8401240378	70-1151
SPEIBARD, R. L.	8401190324*	50-263 Q	STELLO, V.	8401110255*	50-320 U	STOHR, J. P.	8401250265	70-1151
SPEIBARD, R. L.	8401230366	50-295 V	STEPHENS, H. M.	8401180258	50-482 Q	STOHR, J. P.	8401250285	70-143
SPEIBARD, R. L.	8401270401	50-346 V	STEPHENS, H. M.	8401240067	50-482 Q	STOLZ, J. F.	8312200086*	50-321 P
SPEIBARD, R. L.	8401270486	50-331 V	STEPHENS, V. M.	8401110058*	50-275 R	STOLZ, J. F.	8401090313	50-313 P
SPEIBARD, R. L.	8401300054	50-282 V	STEPHENSON, C. J.	8312300285	50-289 S	STOLZ, J. F.	8401090652	50-269 P
SPITZBERG, D. B.	8401040269*	40-8102	STEPHENS, P. C.	8401090366	50-329 Q	STOLZ, J. F.	8401090708	50-285 P
SPITZBERG, D. B.	8401040478*	40-8584	STEPHENS, P. P.	8401090366	50-329 Q	STOLZ, J. F.	8401120100	50-315 P
SPITZBERG, D. B.	8401040591*	40-1162	STEPHENS, P. P.	8401090375*	50-329 Q	STOLZ, J. F.	8401130103	50-312 P
SPRAUL, J. Q.	8401040291*	50-298 Q	STEPHENS, P. P.	8401090375*	50-329 Q	STOLZ, J. F.	8401160013	50-346 F

PERSONAL AUTHOR INDEX

507

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STOLZ, J F	8401160148	50-312 F	SWIGER, H A	8401240071	50-440 Q	THULL, T B	8401300137	50-245 B
STOLZ, J F	8401170499*	50-312 P	SWIGER, H A	8401240071	50-440 Q	TIETZ, Q	8401050102*	50-254 F
STOLZ, J F	8401170522*	50-312 P	SWINDELL, J E	8401270398	50-259 R	TIETZ, Q	8401050257*	50-254 F
STOLZ, J F	8401190164	50-277 P	SWALEWICZ, S A	8401250125	NJREG	TIETZ, Q	8401050261*	50-254 F
STOLZ, J F	8401190551	50-321 P	SWALEWICZ, S A	8401250162	NJREG	TIFFANY, T A	8401100348	50-309 S
STOLZ, J F	8401230040*	50-346 P	SWALEWICZ, S A	8401260096	NJREG	TILL, J E	8312270412	NJREG
STOLZ, J F	8401240039	50-269 P	SWALEWICZ, S A	8401260097	NJREG	TILLMAN, A.	8401170424*	50-369 Q
STOLZ, J F	8401260083	50-321 P	SWALEWICZ, S A	8401260108	NJREG	TIPPS, B B	8401030112	50-321 S
STOLZ, J F	8401260086*	50-321 P	SWALEWICZ, S A	8401310150	NJREG	TIPPS, B B	8401030116	50-366 S
STOLZ, J F	8401310047	50-321 P	SWALEWICZ, S A	8401303258	50-289 S	TIPPS, B B	8401030193	50-321 S
STOLZ, J F	8401310078	50-302 P	SWALEWICZ, S A	8401303478	50-289 S	TIPPS, B B	8401030242	50-366 S
STOLZ, J F	8401310082*	50-302 P	SWALEWICZ, S A	8401310193	GEN TEC IS	TIPPS, B B	8401040168	50-321 S
STOLZ, J F	8401310165	50-312 P	SWALEWICZ, S A	84013240101	NJREG	TIPPS, B B	8401040250	50-366 S
STOLZ, J F	8401310522	50-289 P	SWALEWICZ, S A	8401320172	50-334 P	TIPPS, B B	8401040334	50-321 S
STORMONT, J C	8401160434	NJREG	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401040336	50-321 S
STOUT, D M	8401130128	40-8829	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401040544	50-366 S
STOUT, D M	8401310501	40-8829	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060371	50-366 S
STRAIT, S R	8401120022*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060411	50-366 S
STRAIT, S R	8401120025*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060461	50-366 S
STRAIT, S R	8401120028*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060511	50-321 S
STRAIT, S R	8401120033*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230012	50-366 S
STRAIT, S R	8401120037*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230207	50-366 S
STRAIT, S R	8401120040*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230263	50-366 S
STRAIT, S R	8401120046*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230366	50-366 S
STRAIT, S R	8401120049*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230369	50-321 S
STRAIT, S R	8401120065*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300262	50-366 S
STRAIT, S R	8401120067*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300268	50-321 S
STRAIT, S R	8401190515*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300312	50-366 S
STRAUSS, K H	831205059B*	50-369 P	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300327	50-366 S
STREETER, J F	8401050407	50-263 V	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401310393	50-321 S
STREETER, J F	8401160172	50-483 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401310394	50-321 S
STREETER, J F	8401160267	50-341 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401310398	50-366 S
STREETER, J F	8401190324*	50-263 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401310400	50-366 S
STREETER, J F	8401230273	50-373 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401050393	50-321 S
STREETER, J F	8401230303	50-454 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300292	50-389 S
STREETER, J F	8401230341	50-461 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401300279	50-387 S
STREETER, J F	8401240420	50-483 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401160421	FOIA
STREETER, J F	8401240426*	50-483 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401190608	WASTE MGT
STREETER, J F	8401300022	50-373 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230404	50-373 S
STREETER, J F	8401300024*	50-373 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060143*	50-324 F
STREETER, J F	8401300026*	50-373 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060151*	50-324 F
STROMBERG, H M	8401310435*	GEN TEC IS	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100144	50-322 Q
STRUMHASSER, M	8401160242	50-275 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230442*	50-10 Q
STRUMHASSER, M	8401170243	50-275 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401260238*	50-320 F
STRUMHASSER, M	8401170249	50-275 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401270192*	50-289 F
STUCKER, J J	8401130164	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401260066*	50-289 F
STUCKER, J J	8401170144	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060391	50-289 U
STUCKER, J J	8401170146*	WASTE MGT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401200074*	50-397 Q
STURZ, F F	8401030279	50-280 Y	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060545*	HISC
SUAREZ, F F	8401230383*	QA999	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401090358	WASTE MGT
SUBRAMANIAN, N	8309010227*	50-219 P	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401090358	WASTE MGT
SUCH, P	8401030110*	40-86	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100160	WASTE MGT
SUERMANN, J F	8401200010	50-269 F	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100160	WASTE MGT
SUGARMAN, R J	8401130170	50-352 A	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100160	WASTE MGT
SUGARMAN, R J	8401160202	50-352 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100163*	WASTE MGT
SUGARMAN, R J	8401160202	50-352 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100163*	WASTE MGT
SUGARMAN, R J	8401180192	50-352 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401250130*	50-315 F
SUGARMAN, R J	8401180192	50-352 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401260244*	50-315 F
SUGARMAN, R J	8401180245	50-358 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401040041	CONTRACT
SULLIVAN, R L	8401050146*	50-483 F	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100121	CONTRACT
SVENSSON, B. A	8401060437*	50-316 S	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401130123	CONTRACT
SVENSSON, B. A	8401120398	50-315 R	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401160391	CONTRACT
SVENSSON, B. A	8401120412	50-316 R	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401170113	CONTRACT
SVENSSON, B. A	8401270446	50-315 R	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401230182	CONTRACT
SVENSSON, B. A	8401270477	50-316 R	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401030206*	50-409 P
SWAN, W B	8401090117*	50-553 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401310084*	HISC
SWAN, W B	8401090134*	50-566 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060180	50-454 E
SWAN, W B	8401090337*	50-518 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401060204	50-454 E
SWAN, W B	8401090480*	50-390 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401090223	50-454 K
SWAN, W B	8401240549*	50-390 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100162	50-454 E
SWAN, W B	8401240608*	50-390 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100181	50-454 E
SWANSON, E R	8401190412*	50-315 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100193	50-454 E
SWARTZ, E D	8401030229	50-237 F	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100265	50-454 A
SWARTZ, E D	8401060416	50-456 A	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100311	50-454 A
SWARTZ, E D	8401100380	50-456 C	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWARTZ, E D	8401130303	50-454 A	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWARTZ, E D	8401170160	50-456 A	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWARTZ, E D	8401060494	50-346 S	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	840110276	50-454 A
SWARTZ, E D	8401190406	50-346 S	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWARTZ, E D	8401030135	50-320 S	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100362	50-454 A
SWENSON, F A	8401260485*	CONTRACT	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWETLAND, P D	8401100332*	50-213 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWETLAND, P D	8401100442*	50-309 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	840110276	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100362	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	840110276	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100362	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	840110276	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100362	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	840110276	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100347	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100362	50-454 A
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100433	50-454 E
SWIGER, J E	8401310124	50-440 Q	SWALEWICZ, S A	8401230392	50-341 A	TIPPS, B B	8401100479	50-454 A
SWIGER, J E	8401310124	50-440 Q						

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TRAPP, L. E.	8401310042*	50-334 Q	TURK, S. E.	8401230198	50-337 Q	VAN BRUNT, E. E.	8401260236	50-328 S
TROFFER, G. J.	8401260238*	50-320 F	TURK, S. E.	8401230202	50-382 Q	VAN BRUNT, E. E.	8401260248	50-328 S
TRDSKOSKI, W. H.	8401310042*	50-334 Q	TURNQUEST, L.	8401100458	50-237 S	VAN BRUNT, E. E.	8401260317	50-328 S
TRDUP, G. L.	8401030433*	70-1201	TURNQUEST, L.	8401130184	50-237 S	VAN BRUNT, E. E.	8401260325	50-328 S
TRDUP, G. L.	8401030608*	70-27	TURNQUEST, L.	8401130185	50-237 S	VAN BRUNT, E. E.	8401260341	50-328 S
TROWBRIDGE, G. F.	8312160014	50-261 Q	TURNQUEST, L.	8401230002	50-237 S	VAN BRUNT, E. E.	8401260349	50-328 S
TROWBRIDGE, G. F.	8312160014	50-261 Q	TURNQUEST, L.	8401230010	50-237 S	VAN BRUNT, E. E.	8401260362	50-328 S
TROWBRIDGE, G. F.	8401300139	50-261 Q	TYE, M. J.	8401170139	50-443 T	VAN BRUNT, E. E.	8401260370	50-329 S
TROWBRIDGE, G. F.	8401300139	50-261 Q	TYE, M. J.	8401170141*	50-443 T	VAN BRUNT, E. E.	8401270277	50-328 E
TUCKER, H. B.	8312030590	50-369 P	UDALL, M. K.	8401100133*	50-413 U	VAN BRUNT, E. E.	8401270302	50-328 E
TUCKER, H. B.	8312200514	50-369 S	UDALL, M. K.	8401230011*	50-289 U	VAN BRUNT, E. E.	8401270467	50-328 A
TUCKER, H. B.	8401030160	50-414 S	UDERITZ, R. A.	8401100301	50-272 P	VAN BRUNT, E. E.	8401300225*	50-328 Q
TUCKER, H. B.	8401030216	50-269 F	UDERITZ, R. A.	8401240628*	50-272 G	VAN BRUNT, E. E.	8401260377	50-328 S
TUCKER, H. B.	8401040133	50-369 S	UDY, A. C.	8312230302*	50-387 F	VAN BRUNT, E. E.	8401310317*	50-328 A
TUCKER, H. B.	8401040234	50-413 A	UDY, A. C.	8401310524*	50-289 P	VAN DE KAMP, J.	8401160242	50-273 Q
TUCKER, H. B.	8401040304	50-269 P	UEBBING, R.	8401160330	50-346 S	VAN LIET, J.	8401130117	50-289 F
TUCKER, H. B.	8401040311	50-370 S	UMBEL, D.	8401050118	CONTRACT	VAN LIET, J. A.	8401230344	50-289 F
TUCKER, H. B.	8401040328	50-369 S	UMBEL, D.	8401050144	CONTRACT	VAN DER MOLEN, H.	8401230657	MR/EG
TUCKER, H. B.	8401040332	50-369 S	UMBEL, D.	8401250119	CONTRACT	VANDEWALLE, D. J.	8401040170	50-235 S
TUCKER, H. B.	8401040410	50-370 S	UMBEL, D.	8401230355	CONTRACT	VANDEWALLE, D. J.	8401230249	50-235 F
TUCKER, H. B.	8401040535	50-370 S	UMBEL, D.	8401260191	CONTRACT	VARGA, S. A.	8401030167	50-315 P
TUCKER, H. B.	8401040562	50-370 S	UMBEL, D.	8401270531	CONTRACT	VARGA, S. A.	8401030304	50-315 P
TUCKER, H. B.	8401030414	50-269 Q	UMBEL, D.	8401300128	CONTRACT	VARGA, S. A.	8401040077	50-334 G
TUCKER, H. B.	8401050617	50-287 B	UMBEL, D.	8401300153	CONTRACT	VARGA, S. A.	8401040084*	50-334 G
TUCKER, H. B.	8401060085*	50-269 F	UNIKIEWICZ, B.	8401270557	50-213 R	VARGA, S. A.	8401060189	50-261 P
TUCKER, H. B.	8401060323	50-413 G	UPRIGHT, C. M.	8401050323*	50-438 G	VARGA, S. A.	8401060192*	50-261 P
TUCKER, H. B.	8401060401	50-413 Q	URYC, B.	8401100480*	50-302 Q	VARGA, S. A.	8401060197	50-261 P
TUCKER, H. B.	8401060417	50-413 S	USI, V.	8401050098*	50-317 F	VARGA, S. A.	8401060210	50-261 P
TUCKER, H. B.	8401060471	50-413 Q	USI, V.	8401050417*	50-317 F	VARGA, S. A.	8401060224	50-261 P
TUCKER, H. B.	8401090311	50-369 F	USI, V.	8401060032*	50-317 F	VARGA, S. A.	8401090162	50-280 P
TUCKER, H. B.	8401090354	50-269 P	USI, V.	8401060274*	50-317 F	VARGA, S. A.	8401090381	50-247 P
TUCKER, H. B.	8401090508	50-269 P	USI, V.	8401300355*	50-317 F	VARGA, S. A.	8401090378	50-303 P
TUCKER, H. B.	8401100386	50-269 I	UTLEY, E. E.	8401230007	50-400 A	VARGA, S. A.	8401090622	50-286 P
TUCKER, H. B.	8401120217	50-369 S	VACCA, P. C.	7909070539*	40-5377	VARGA, S. A.	8401090633	50-280 P
TUCKER, H. B.	8401120226	50-369 S	VACCA, P. C.	8401050045*	FOIA	VARGA, S. A.	8401090633	50-280 P
TUCKER, H. B.	8401120266	50-269 S	VACCA, P. C.	8401050051*	FOIA	VARGA, S. A.	8401090715*	50-230 P
TUCKER, H. B.	8401120375	50-370 B	VACCA, P. C.	8401100084*	FOIA	VARGA, S. A.	8401090751*	50-230 P
TUCKER, H. B.	8401120376	50-369 S	VACCA, P. C.	8401100087*	FOIA	VARGA, S. A.	8401090769	50-334 P
TUCKER, H. B.	8401130049	50-269 S	VAN BRUNT, E. E.	8401120388	50-328 S	VARGA, S. A.	8401100171*	50-313 F
TUCKER, H. B.	8401170208	50-287 S	VAN BRUNT, E. E.	8401030061	50-328 A	VARGA, S. A.	8401120176*	50-334 P
TUCKER, H. B.	8401170359	50-413 A	VAN BRUNT, E. E.	8401030261	50-328 E	VARGA, S. A.	8401120591*	50-293 P
TUCKER, H. B.	8401170381*	50-369 Q	VAN BRUNT, E. E.	8401040129	50-329 S	VARGA, S. A.	8401130030*	50-348 P
TUCKER, H. B.	8401190431	50-369 P	VAN BRUNT, E. E.	8401040220	50-329 S	VARGA, S. A.	8401170495	50-334 F
TUCKER, H. B.	8401200014	50-369 R	VAN BRUNT, E. E.	8401040222	50-328 S	VARGA, S. A.	8401180080	50-348 P
TUCKER, H. B.	8401200033	50-269 R	VAN BRUNT, E. E.	8401040266	50-328 S	VARGA, S. A.	8401190161	50-261 F
TUCKER, H. B.	8401200186	50-369 P	VAN BRUNT, E. E.	8401040298	50-328 S	VARGA, S. A.	8401190243*	50-305 P
TUCKER, H. B.	8401200221	50-269 V	VAN BRUNT, E. E.	8401040313	50-328 S	VARGA, S. A.	8401190264	50-247 P
TUCKER, H. B.	8401230188	50-269 P	VAN BRUNT, E. E.	8401040338	50-330 S	VARGA, S. A.	8401190268*	50-348 P
TUCKER, H. B.	8401230440	50-369 P	VAN BRUNT, E. E.	8401040342	50-328 S	VARGA, S. A.	8401190313	50-334 P
TUCKER, H. B.	8401230462	50-269 S	VAN BRUNT, E. E.	8401040344	50-330 S	VARGA, S. A.	8401190340*	50-230 P
TUCKER, H. B.	8401240008	50-369 S	VAN BRUNT, E. E.	8401040366	50-328 S	VARGA, S. A.	8401190451*	50-348 P
TUCKER, H. B.	8401240119	50-369 S	VAN BRUNT, E. E.	8401040371	50-328 S	VARGA, S. A.	8401200032*	50-348 P
TUCKER, H. B.	8401240130	50-369 S	VAN BRUNT, E. E.	8401040431	50-328 S	VARGA, S. A.	8401200126	50-305 P
TUCKER, H. B.	8401240136	50-369 V	VAN BRUNT, E. E.	8401040581	50-329 S	VARGA, S. A.	8401200133	50-230 P
TUCKER, H. B.	8401240150	50-269 G	VAN BRUNT, E. E.	8401050204	50-328 A	VARGA, S. A.	8401230219	50-305 P
TUCKER, H. B.	8401240171	50-413 F	VAN BRUNT, E. E.	8401100418	50-328 E	VARGA, S. A.	8401230666	50-280 P
TUCKER, H. B.	8401240282	50-370 S	VAN BRUNT, E. E.	8401120209	50-329 S	VARGA, S. A.	8401300021	50-348 P
TUCKER, H. B.	8401240283	50-413 E	VAN BRUNT, E. E.	8401120220	50-328 S	VARNADO, G. B.	8401100025*	FOIA
TUCKER, H. B.	8401240287	50-370 S	VAN BRUNT, E. E.	8401120302	50-328 S	VASCONELLO, J.	8401240493	50-275 U
TUCKER, H. B.	8401240290	50-369 S	VAN BRUNT, E. E.	8401120304	50-328 S	VASSALLO, D.	8401200118	50-324 P
TUCKER, H. B.	8401240325*	50-369 G	VAN BRUNT, E. E.	8401120352	50-328 S	VASSALLO, D.	8401230548	50-333 P
TUCKER, H. B.	8401240367*	50-369 G	VAN BRUNT, E. E.	8401120391	50-328 S	VASSALLO, D.	8401230548	50-333 P
TUCKER, H. B.	8401240389	50-413 S	VAN BRUNT, E. E.	8401120393	50-328 S	VASSALLO, D.	8401230520	50-220 P
TUCKER, H. B.	8401240400	50-414 S	VAN BRUNT, E. E.	8401120399	50-328 S	VASSALLO, D. B.	8401030034*	50-324 P
TUCKER, H. B.	8401240402	50-269 P	VAN BRUNT, E. E.	8401120402	50-328 S	VASSALLO, D. B.	8401030057*	50-324 P
TUCKER, H. B.	8401240404*	50-413 S	VAN BRUNT, E. E.	8401120404	50-328 S	VASSALLO, D. B.	8401060185*	50-220 P
TUCKER, H. B.	8401240437	50-370 S	VAN BRUNT, E. E.	8401120429	50-328 S	VASSALLO, D. B.	8401120528*	50-239 P
TUCKER, H. B.	8401240480	50-369 S	VAN BRUNT, E. E.	8401120430	50-328 S	VASSALLO, D. B.	8401160001	50-220 P
TUCKER, H. B.	8401240594	50-370 S	VAN BRUNT, E. E.	8401130366	50-328 S	VASSALLO, D. B.	8401160003	50-331 P
TUCKER, H. B.	8401260160	50-369 S	VAN BRUNT, E. E.	8401160068	50-328 A	VASSALLO, D. B.	8401160005	50-220 P
TUCKER, H. B.	8401270181	50-413 E	VAN BRUNT, E. E.	8401160226	50-328 S	VASSALLO, D. B.	8401160008	50-239 P
TUCKER, H. B.	8401270194	50-413 A	VAN BRUNT, E. E.	8401160266	50-329 S	VASSALLO, D. B.	8401160012	50-298 P
TUCKER, H. B.	8401270254	50-413 E	VAN BRUNT, E. E.	8401160272	50-328 B	VASSALLO, D. B.	8401160464	50-324 P
TUCKER, H. B.	8401310018	50-369 F	VAN BRUNT, E. E.	8401160321	50-328 S	VASSALLO, D. B.	8401170501	50-331 P
TUCKER, H. B.	8401310073*	50-369 F	VAN BRUNT, E. E.	8401170349	50-328 S	VASSALLO, D. B.	8401170509	50-239 P
TUCKER, H. B.	8401310280	50-413 E	VAN BRUNT, E. E.	8401180073*	50-328 A	VASSALLO, D. B.	8401170527	50-331 F
TUCKER, H. B.	8401310300	50-269 F	VAN BRUNT, E. E.	8401180107	50-328 Q	VASSALLO, D. B.	8401180043	50-333 P
TULODIEBKI, D. B.	8401170385*	50-329 R	VAN BRUNT, E. E.	8401240186	50-328 V	VASSALLO, D. B.	8401180052*	50-333 P
TURANO, H. J.	8401180269	50-322 T	VAN BRUNT, E. E.	8401250084	50-328 F	VASSALLO, D. B.	8401200016	50-324 P
TURCOTTE, R. L.	8401230450	50-131 R	VAN BRUNT, E. E.	8401260011	50-328 S	VASSALLO, D. B.	8401200020*	50-324 P
TURINGSKY, P. J.	8401100154	50-297 H	VAN BRUNT, E. E.	8401260035	50-328 S	VASSALLO, D. B.	8401200037*	50-263 P
TURK, S. E.	8401040108	50-463 Q	VAN BRUNT, E. E.	8401260109	50-328 S	VASSALLO, D. B.	8401200063	50-263 P
TURK, S. E.	8401170286*	50-70 Q	VAN BRUNT, E. E.	8401260120	50-328 S	VASSALLO, D. B.	8401200131*	50-324 P
TURK, S. E.	8401170286*	50-70 Q	VAN BRUNT, E. E.	8401260130	50-328 S	VASSALLO, D. B.	8401230048*	50-324 P
TURK, S. E.	8401250186	50-463 Q	VAN BRUNT, E. E.	8401260180	50-329 S	VASSALLO, D. B.	8401230602	50-324 P

PERSONAL AUTHOR INDEX

509

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
VASSALLO, D. B.	8401230613*	50-324 P	VOIGT, H. H.	8401260223	50-546 Q	WEINKAM, E. J.	8401240034	50-458 A
VASSALLO, D. B.	8401240051*	50-259 P	VOIGT, H. H.	8401260223	50-546 Q	WEINTRAUB, A. A.	8401120007	71-5800 Q
VASSALLO, D. B.	8401250430*	50-324 P	VOLLNER, R.	8312190344*	50-322 A	WEISE, S.	8401240423*	50-261 Q
VASSALLO, D. B.	8401250474	50-293 P	VOLLNER, R. H.	8401170076*	FOIA	WEISMANTLE, J. A.	8401190170*	50-322 Q
VASSALLO, D. B.	8401260255	50-325 P	VORDERBRUGGEN	8401200211*	50-528 Q	WEISS, E. R.	8401100163*	WASTE MGT
VASSALLO, D. B.	8401260420	50-254 P	VOBBURY, F. W.	8312060347*	50-244 P	WEISS, E. R.	8401100163*	WASTE MGT
VASSALLO, D. B.	8401260475	50-259 P	VUMBACO, F. J.	8401100351*	40-672 P	WEISS, E. R.	8401100200	50-289 Q
VASSALLO, D. B.	8401270019	50-220 P	WACHTER, W. J.	8401250303*	50-244 P	WEISS, E. R.	8401240224	50-289 Q
VASSALLO, D. B.	8401270175*	50-293 P	WADE, P. B.	8401230254	50-368 B	WEISS, E. R.	8401240224	50-289 Q
VASSALLO, D. B.	8401270307	50-263 Q	WAGNER, A. G.	8401090292*	50-416 Q	WEISS, E. R.	8401240230*	50-289 Q
VASSALLO, D. B.	8401300023	50-331 P	WAGNER, M. E.	8401040106	50-289 Q	WEISS, E. R.	8401240230*	50-289 Q
VASSALLO, D. B.	8401300025	50-298 P	WAGNER, M. E.	8401120233	50-416 Q	WEISS, E. R.	8401250010	FOIA
VASSALLO, D. B.	8401300027	50-271 P	WAGNER, M. E.	8401120241	50-289 Q	WEISS, E. R.	8401250010	FOIA
VASSALLO, D. B.	8401300033	50-254 P	WAGNER, M. E.	8401120278	50-289 Q	WEISS, E. R.	8401260164	50-289 Q
VASSALLO, D. B.	8401300037	50-324 F	WAGNER, M. J.	8401200193*	50-397 Q	WELLS, C. E.	8401060091*	50-346 F
VASSALLO, D. B.	8401300059	50-254 P	WAHL, H. H.	8401230380*	QA999	WELLS, C. E.	8401260384*	50-346 F
VASSALLO, D. B.	8401310465	50-259 P	WAITE, M. H.	8401250303*	50-244 P	WELLS, D. A.	8312190225*	50-341 Q
VAUGHAN, C.	8401090775	70-1113	WALKER, J. B.	8401300181	50-296 B	WELLS, D. A.	8401030405	50-341 B
VAUGHAN, C. H.	8401030358	70-1113	WALKER, R.	8401160161	50-237 B	WELLS, D. A.	8401030409	50-341 B
VAUGHAN, C. H.	8401170452	70-1113	WALKER, R.	8401230442*	50-10 Q	WELLS, D. A.	8401030450	50-341 B
VAUGHAN, C. H.	8401170455	70-1113	WALKER, R. D.	8401040380*	50-254 Q	WELLS, D. A.	8401030625	50-341 B
VAUGHAN, C. H.	8401200113	71-4907	WALKER, R. D.	8401100440*	50-263 Q	WELLS, D. A.	8401120277*	50-341 Q
VAUGHAN, C. H.	8401240266	71-4907	WALKER, R. D.	8401270365*	50-373 Q	WELLS, D. A.	8401300298	50-341 B
VEAKES, E.	8401160438	MUREQ	WALKER, R. D.	8401270469*	50-331 Q	WELLS, D. A.	8401300301	50-341 Q
VERBRUYE, P. A.	8401090356*	50-293 P	WALKER, S.	8401310488*	40-1162	WELLS, R. K.	8401030309*	50-400 F
VERRELLI, D. H.	8401030251	50-259 F	WALKER, W. J.	7708200203*	FOIA	WELLS, R. W.	8401270271	TOPREP
VERRELLI, D. H.	8401080311	50-436 Q	WALKER, W. J.	8401040028*	FOIA	WELLS, R. W.	8401270271	TOPREP
VERRELLI, D. H.	8401080336	50-324 Q	WALL, G. F.	8401050417*	50-317 F	WELSH, D. J.	8401030437	50-373 B
VERRELLI, D. H.	8401080346	50-327 Q	WALL, R. B.	8401060257*	40-8829	WELSH, D. J.	8401130341	50-373 B
VERRELLI, D. H.	8401080378	50-324 Q	WALLACE, L. E.	8401270221	50-319 Q	WEN, P. C.	8401040167*	50-334 Q
VERRELLI, D. H.	8401080445	50-348 Q	WALLER, W. K.	8401110463	27-48	WENBLAWSKI, F.	8401160223	50-362 B
VERRELLI, D. H.	8401080452	50-257 Q	WALLER, W. K.	8401120156	27-48	WENBLAWSKI, F. A.	8401100391	50-288 Q
VERRELLI, D. H.	8401080454	50-324 Q	WALLER, W. K.	8401190236	27-48	WENBLAWSKI, F. A.	8401100397*	50-288 Q
VERRELLI, D. H.	8401080462*	50-259 Q	WALT, V. H.	8401130359	50-333 B	WENBLAWSKI, F. A.	8401200017	50-312 Q
VERRELLI, D. H.	8401080468	50-259 Q	WANG, C. H.	8401100314	50-243 P	WENBLAWSKI, F. A.	8401200023*	50-312 Q
VERRELLI, D. H.	8401080488	50-400 Q	WARD, K. D.	8401030300*	50-454 Q	WENBLAWSKI, F. A.	8401270188	50-275 Q
VERRELLI, D. H.	8401080499	50-395 Q	WARD, K. D.	8401100486*	50-262 Q	WENBLAWSKI, F. A.	8401300158	50-206 Q
VERRELLI, D. H.	8401080537	50-390 Q	WARD, K. D.	8401120382*	50-409 Q	WENBLAWSKI, F. A.	8401300160*	50-206 Q
VERRELLI, D. H.	8401080587*	50-390 Q	WARDWELL, R. E.	8401310462*	40-299	WENBLAWSKI, F. A.	8401300255*	50-326 Q
VERRELLI, D. H.	8401080649	50-259 Q	WAREMBOURG, D.	8401100337	50-267 S	WENBLAWSKI, F. A.	8401300258*	50-326 Q
VERRELLI, D. H.	8401060338	50-259 V	WAREMBOURG, D.	8401130261	50-267 P	WENBLAWSKI, F. A.	8401300277	70-734
VERRELLI, D. H.	8401060352	50-400 V	WAREMBOURG, D.	8401130306	50-267 B	WENBLAWSKI, F. A.	8401300282*	70-734
VERRELLI, D. H.	8401060408	50-348 Q	WAREMBOURG, D.	8401170193	50-267 S	WEST, D.	8401030072	50-389 B
VERRELLI, D. H.	8401060424	50-324 Q	WAREMBOURG, D.	8401180194	50-267 R	WESTAFER, G. R.	8401030465	50-302 Q
VERRELLI, D. H.	8401060427*	50-324 Q	WAREMBOURG, D.	8401190417	50-267 Q	WESTAFER, G. R.	8401030619*	50-302 Q
VERRELLI, D. H.	8401060485	50-416 Q	WAREMBOURG, D.	8401230186	50-267 B	WESTAFER, G. R.	8401090425*	50-302 Q
VERRELLI, D. H.	8401060501	50-395 V	WAREMBOURG, D.	8401270248	50-267 B	WESTAFER, G. R.	8401090432*	50-302 Q
VERRELLI, D. H.	8401090103	50-390 Q	WAREMBOURG, D.	8401270480	50-267 P	WESTAFER, G. R.	8401100304	50-302 R
VERRELLI, D. H.	8401090111	50-553 Q	WAREMBOURG, D. H.	8401230445	50-267 P	WESTAFER, G. R.	8401100405	50-302 P
VERRELLI, D. H.	8401090114	50-261 Q	WAREMBOURG, D. H.	8401270205	50-267 V	WESTAFER, G. R.	8401120395	50-302 B
VERRELLI, D. H.	8401090125	50-566 Q	WARNICK, R.	8401300143	50-358 B	WESTAFER, G. R.	8401120414	50-302 B
VERRELLI, D. H.	8401090128	50-438 Q	WARNICK, R. F.	8401060474	50-329 Q	WESTAFER, G. R.	8401120419	50-302 B
VERRELLI, D. H.	8401090131	50-324 Q	WARNICK, R. F.	8401100031	50-358 Q	WESTAFER, G. R.	8401130160	50-302 R
VERRELLI, D. H.	8401090141*	50-438 Q	WARNICK, R. F.	8401100036	50-358 Q	WESTAFER, G. R.	8401160167	50-302 R
VERRELLI, D. H.	8401090237	50-259 Q	WARNICK, R. F.	8401100168	50-358 Q	WESTAFER, G. R.	8401160295	50-302 B
VERRELLI, D. H.	8401090255	50-395 Q	WARNICK, R. F.	8401100210	50-329 Q	WESTAFER, G. R.	8401200222	50-302 P
VERRELLI, D. H.	8401090267	50-327 Q	WARNICK, R. F.	8401120473	50-329 R	WESTAFER, G. R.	8401230405	50-302 P
VERRELLI, D. H.	8401090286	50-416 Q	WARNICK, R. F.	8401230493	50-329 R	WESTAFER, G. R.	8401230405	50-302 P
VERRELLI, D. H.	8401090350	50-518 Q	WART, R. J.	8401120095	MUREQ	WESTAFER, G. R.	8401240135	50-302 B
VERRELLI, D. H.	8401090478	50-390 Q	WART, R. J.	8401120095	MUREQ	WESTAFER, G. R.	8401240206	50-302 R
VERRELLI, D. H.	8401090498	50-390 Q	WASTLER, S. L.	8401060250	40-8829	WESTAFER, G. R.	8401240394*	50-302 Q
VERRELLI, D. H.	8401100167	50-348 F	WASTLER, S. L.	8401060556	40-8745	WESTAFER, G. R.	8401240425*	50-302 Q
VERRELLI, D. H.	8401240004	50-259 B	WASTLER, S. L.	8401090060	40-8348	WESTAFER, G. R.	8401200323*	50-302 B
VERRELLI, D. H.	8401240193	50-129 Q	WASTLER, S. L.	8401100097	40-8064	WESTER, R. A.	8401240426*	50-483 Q
VERRELLI, D. H.	8401240205*	50-129 Q	WASTLER, S. L.	8401310412*	40-8728	WESTERMAN, T. F.	8401250243*	50-445 B
VERRELLI, D. M.	8401240213*	50-129 Q	WATERMAN, M. E.	8401310061*	50-261 P	WETHY, C. H.	8401260140*	50-389 F
VERRELLI, D. M.	8401240326	50-395 Q	WATERS, M.	8401230399	50-275 U	WETHY, C. H.	8401260145*	50-389 F
VERRELLI, D. M.	8401240336*	50-395 Q	WATSON, J. J.	8401030309*	50-400 F	WETHY, C. H.	8401300379*	50-389 F
VERRELLI, D. M.	8401240360	50-395 Q	WEAKLEY, S. A.	8401100088	MUREQ	WETHY, C. H.	8401310069*	50-389 F
VERRELLI, D. M.	8401240372	50-124 Q	WEAKLEY, S. A.	8401130220	MUREQ	WETHORE, J. B.	8401300078	50-289 H
VERRELLI, D. M.	8401240408	50-261 Q	WEAVER, J.	8401190497*	50-397 U	WETTERHAHN, M.	8401060290	50-352 Q
VERRELLI, D. M.	8401240413*	50-261 Q	WEBER, M. F.	8401300099	WASTE MGT	WETTERHAHN, M.	8401060290	50-352 Q
VERRELLI, D. M.	8401240496	50-261 F	WEDDINGTON, R. E.	8401060491*	50-416 Q	WETTERHAHN, M. J.	8401060297	50-352 Q
VERRELLI, D. M.	8401240534	50-297 Q	WEEKS, E. D.	8401120374	50-133 R	WETTERHAHN, M. J.	8401060297	50-352 Q
VERRELLI, D. M.	8401240569	50-438 Q	WEINKAM, E. J.	8401040470*	50-458 B	WETTERHAHN, M. J.	8401090256	50-352 Q
VERRELLI, D. M.	8401240587*	50-438 Q	WEINKAM, E. J.	8401060241	50-458 A	WETTERHAHN, M. J.	8401100145	50-352 Q
VERRELLI, D. M.	8401240598	50-348 Q	WEINKAM, E. J.	8401130485	50-458 A	WETTERHAHN, M. J.	8401110238	50-352 Q
VERRELLI, D. M.	8401240638	50-296 B	WEINKAM, E. J.	8401110289	50-458 E	WETTERHAHN, M. J.	8401110238	50-352 Q
VIETH, D. L.	8401120092	WASTE MGT	WEINKAM, E. J.	8401190191	50-458 A	WETTERHAHN, M. J.	8401180183	50-352 Q
VIETTH, A.	8401090647	50-498 F	WEINKAM, E. J.	8401190200	50-458 A	WETTERHAHN, M. J.	8401180183	50-352 Q
VITO, D.	8401240510*	50-352 Q	WEINKAM, E. J.	8401190272	50-458 A	WETTERHAHN, M. J.	8401240091	50-352 Q
WALK, L. K.	8401240635*	50-387 F	WEINKAM, E. J.	8401190285	50-458 E	WETTERHAHN, M. J.	8401240091	50-352 Q
VOSEL, A. M.	8401160081	50-317 B	WEINKAM, E. J.	8401190289	50-458 A	WETTERHAHN, M. J.	8401240174	50-352 Q
VOGT, D. M.	8401180003*	CONTRACT	WEINKAM, E. J.	8401190494	50-458 A	WETTERHAHN, M. J.	8401240174	50-352 Q
VOGT-LOWELL, R. J.	8401050563*	50-250 Q	WEINKAM, E. J.	8401230120	50-458 F	WETTERHAHN, M. J.	8401240181*	50-352 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WETTERHARN, M. J.	8401240181*	50-332 Q	WILLIAMS, J.	8401170444	50-338 S	WITTENBROCK, N.	8401230677	NUREQ
WHEELER, T. A.	8401260079	NUREQ	WILLIAMS, J.	8401180113	50-338 A	WOJTELEWICZ, T.	8401040397	50-237 S
WHICHER, J. M.	8401270378	50-434 Q	WILLIAMS, J.	8401190318	50-338 S	WOLFE, R.	8401250052*	50-483 F
WHICHER, J. M.	8401270378	50-434 Q	WILLIAMS, J.	8401190435	50-338 S	WOLFE, B. J.	8401090365	50-482 Q
WHICHER, J. M.	8401270378	50-434 Q	WILLIAMS, J.	8401230393	50-338 S	WOLFE, B. J.	8401100141	50-289 Q
WHICHER, J. M.	8401300261	50-434 Q	WILLIAMS, J.	8401300125	50-338 A	WOLFE, B. J.	8401170261	50-289 Q
WHICHER, J. M.	8401300261	50-434 Q	WILLIAMS, J.	8401300129	50-338 V	WOLFF, C. E.	8401060243*	40-B602
WHICHER, J. M.	8401300261	50-434 Q	WILLIAMS, J.	8401300153	50-338 S	WOLLETT, S.	8401090748	CONTRACT
WHICHER, J. M.	8401300261	50-434 Q	WILLIAMS, J.	8401310214	50-338 A	WOLLETT, S.	8401190327	CONTRACT
WHIPPLE, B.	8401120261	50-29 R	WILLIAMS, J. H.	8401100287*	50-277 Q	WOLLETT, S.	8401190469	CONTRACT
WHIPPLE, B.	8401270406	50-29 R	WILLIAMS, J. B.	8401060067*	50-239 P	WOLTER, E.	8401260315*	70-133
WHITENER, H. L.	8401090374*	50-416 Q	WILLIAMS, J. W.	8401030072	50-389 S	WONG, A. H.	8401270400*	50-267 P
WHITMAN, D.	8401230647*	50-298 F	WILLIAMS, J. W.	8401030210	50-231 S	WOODARD, C.	8401090279	50-423 Q
WHITMAN, D.	8401260198*	50-298 F	WILLIAMS, J. W.	8401040265	50-335 F	WOODARD, C.	8401200345	50-423 A
WHITMAN, D.	8401300375*	50-298 F	WILLIAMS, J. W.	8401040352	50-230 P	WOODHEAD, C. P.	8401040126	50-440 Q
WHITNEY, O. D.	8401120208	50-293 S	WILLIAMS, J. W.	8401040353*	50-230 P	WOODHEAD, C. P.	8401120294	50-142 Q
WHITNEY, L. E.	8401310445*	50-344 Q	WILLIAMS, J. W.	8401040417	50-231 S	WOODHEAD, C. P.	8401230305	50-142 T
WHITTIER, O. D.	8401040319	50-309 P	WILLIAMS, J. W.	8401040420	50-389 S	WOODHEAD, C. P.	8401120421	50-440 Q
WHITTIER, O. D.	8401030258	50-309 S	WILLIAMS, J. W.	8401040538	50-389 F	WOODHEAD, C. P.	8401230115	50-142 Q
WHITTIER, O. D.	8401100288	50-309 S	WILLIAMS, J. W.	8401050384*	50-333 Q	WOODHEAD, C. P.	8401230190	50-142 Q
WHITTIER, O. D.	8401100348	50-309 S	WILLIAMS, J. W.	8401050532*	50-250 S	WOODRUFF, R. L.	8401050536	State Prog
WHITTIER, O. D.	8401100414	50-309 V	WILLIAMS, J. W.	8401050564	50-251 S	WOODRUFF, R. L.	8401060341	State Prog
WHITTIER, O. D.	8401160143	50-309 F	WILLIAMS, J. W.	8401120326	50-389 S	WOODS, G. R.	8401230416	50-142 Q
WHITTIER, O. D.	8401160159	50-309 P	WILLIAMS, J. W.	8401120363	50-230 R	WOODS, J.	8401060008	50-187 A
WHITTIER, O. D.	8401160269	50-309 P	WILLIAMS, J. W.	8401130159	50-335 P	WOODS, R.	8401160425	GEN TEC IS
WHITTIER, O. D.	8401170287	50-309 P	WILLIAMS, J. W.	8401130176	50-230 S	WOODS, T. Q.	8401240068	50-528 H
WHITTIER, O. D.	8401190129*	50-309 Q	WILLIAMS, J. W.	8401130284	50-230 R	WOOLEVER, E. J.	8401020296*	50-412 Q
WHITTIER, O. D.	8401230121	50-309 F	WILLIAMS, J. W.	8401170246	50-230 S	WOOLEVER, E. J.	8401040169	50-412 Q
WHITTIER, O. D.	8401230455	50-309 S	WILLIAMS, J. W.	8401190358	50-335 V	WOOLEVER, E. J.	8401060285	50-412 A
WHITTIER, O. D.	8401230572*	50-309 Q	WILLIAMS, J. W.	8401200158	50-335 P	WOOLEVER, E. J.	8401130175	50-412 A
WHITTIER, O. D.	8401240101	50-309 P	WILLIAMS, J. W.	8401240088	50-335 P	WOOLEVER, E. J.	8401180151	50-412 A
WHITTIER, O. D.	8401240184	50-309 P	WILLIAMS, J. W.	8401240253*	50-230 Q	WOOLEVER, E. J.	8401260327	50-412 A
WHITTIER, O. D.	8401310304	50-309 P	WILLIAMS, J. W.	8401240415	50-335 F	WOOLEVER, E. J.	8401300224	50-412 F
WHITTLEBEY, K. A.	8401040437*	50-482 Q	WILLIAMS, J. W.	8401260094	50-389 S	WOOLEVER, E. J.	8401300329	50-412 A
WHITTLEBEY, K. A.	8401040466*	50-482 Q	WILLIAMS, J. W.	8401260099	50-231 S	WOOLSEY, R. T.	8111160348*	70-938
WICK, E. A.	8401270528	WASTE MGT	WILLIAMS, J. W.	8401260157	50-230 S	WOOLSEY, R. T.	8401040514*	40-299
WICKSTORM, B.	8401310488*	40-1162	WILLIAMS, J. W.	8401260263*	50-230 F	WOOLSEY, R. T.	8401060233	40-2239
WIDRIE, R. D.	8401130220	NUREQ	WILLIAMS, J. W.	8401270459	50-230 R	WOOLSEY, R. T.	8401060637	40-299
WIEDEMAN, D. Q.	8401040389	70-2887	WILLIAMS, J. W.	8401300114	50-230 Q	WOOLSEY, R. T.	8401060650	40-2239
WIEDEMAN, D. Q.	8401100346	40-8046	WILLIAMS, J. W.	8401310275	50-230 F	WOOLSEY, R. T.	8401270439*	40-2239
WIEDEMAN, D. Q.	8401230142	40-7982	WILLIAMS, N. H.	8401090210	50-443 A	WOOLSEY, R. T.	8401270557	40-2259
WIEDEMAN, D. Q.	8401230144*	40-7982	WILLIAMS, R. E.	8401110437	40-B829	WOZNIAK, D. R.	8401120361	XPORTLIC
WIEDEMAN, D. Q.	8401230148*	40-7982	WILLIAMS, R. E.	8401110441	40-8768	WOZNIAK, D. R.	8401120568	XPORTLIC
WIEDEMAN, D. Q.	8401300146	40-7982	WILTS, C. A.	8401120580	WASTE MGT	WOZNIAK, D. R.	8401130075	XPORTLIC
WIESE, R.	8401160032	50-333 S	WILMOT, E. L.	8401260079	NUREQ	WRAY, J. R.	8401090282*	50-333 Q
WIEBEMANN, R. A.	8401110246*	TOPREP	WILMOT, E. L.	8401300101*	WASTE MGT	WRIGHT, C. L.	8401030217	50-261 S
WIEBEMANN, R. A.	8312200580*	TOPREP	WILMOT, E. L.	8401310455*	WASTE MGT	WRIGHT, C. L.	8401050415	50-261 S
WIEBEMANN, R. A.	8401060399*	PROJ	WILSON, B. D.	8401090182	XPORTLIC	WRIGHT, C. L.	8401050474	50-261 S
WIEBEMANN, R. A.	8401200060*	TOPREP	WILSON, B. D.	8401090192*	XPORTLIC	WRIGHT, C. L.	8401130132	50-261 S
WIEGINS, E.	8401160457	CONTRACT	WILSON, B. D.	8401090598	XPORTLIC	WRIGHT, N. A.	8401250170	50-352 Q
WIGGINS, J. T.	8401240604*	50-352 Q	WILSON, B. D.	8401090602*	XPORTLIC	WRIGHT, R. J.	8401120464	WASTE MGT
WIGGINS, J. T.	8401310384*	50-352 Q	WILSON, J. H.	8401270551	50-382 A	WRIGHT, R. J.	8401190206	WASTE MGT
WIGGINTON, D. L.	8401100166	50-315 P	WILSON, J. L.	8401040326*	50-281 S	WRIGHT, R. J.	8401260100*	WASTE MGT
WILBUR, L. C.	8401160112	50-134 R	WILSON, J. L.	8401040330*	50-281 S	WRIGHT, R. J.	8401270333	WASTE MGT
WILCOVE, M. N.	8401120200	50-352 Q	WILSON, J. L.	8401040331*	50-280 S	WRIGHT, R. J.	8401300185	WASTE MGT
WILCOVE, M. N.	8401250090	50-329 Q	WILSON, J. L.	8401040337*	50-280 S	WUBSTERBARTH, A.	8401100088	NUREQ
WILCOX, J. I.	8401240599*	50-438 Q	WILSON, J. L.	8401040373*	50-280 S	WYANT, F. J.	8401130105	NUREQ
WILEY, D. K.	8401040609	50-289 Q	WILSON, J. L.	8401040376*	50-280 S	WYNARDEN, S. D.	8401030294	40-6940
WILGUS, H. B.	8401050629*	50-302 Q	WILSON, J. L.	8401170188	50-280 S	WYNARDEN, S. D.	8401060226	40-6940
WILGUS, H. B.	8401180200	50-302 P	WILSON, J. L.	8401260003	50-280 S	WYNARDEN, S. D.	8401310053	70-820
WILKS, B. L.	8401120260	50-387 S	WILSON, J. L.	8401310358	50-280 S	WYNARDEN, S. D.	8401310073	40-BB01
WILKS, B. L.	8401130258	50-387 S	WILSON, J. L.	8401310362*	50-280 S	YAGQUE, F. L.	8401160443	NUREQ
WILKS, B. L.	8401160155	50-387 S	WILSON, J. L.	8401310367*	50-280 S	YANDELL, L. A.	8401040411*	50-285 Q
WILKS, B. L.	8401260221	50-387 S	WILSON, J. L.	8401310387	50-281 S	YANDELL, L. A.	8401040494*	50-285 Q
WILKS, B. L.	8401260276	50-387 S	WILZACK, A.	8401160142	State Prog	YANDELL, L. A.	8401040529*	50-285 Q
WILKS, B. L.	8401270128	50-387 S	WINDHAM, R.	8401230647*	50-298 F	YANG, J. W.	8401160402*	FOIA
WILKS, B. L.	8401270185	50-387 S	WINDHAM, R.	8401260198*	50-298 F	YARGER, K.	8401160299	50-346 S
WILKS, B. L.	8401270335	50-387 S	WINGLOW, R.	8401230621	50-329 Q	YARGER, R. J.	8401040438*	QA799
WILLETT, D. J.	8401200028*	50-397 Q	WISE, J. R.	8401040171	FOIA	YIN, I. T.	8401160208*	50-135 P
WILLIAMS, B. M.	8401200091*	50-261 Q	WISE, R.	8401040364*	50-285 Q	YODER, G. L.	8401300018	NUREQ
WILLIAMS, C. C.	8401120229*	50-483 Q	WITHERS, B. D.	8401030106	50-344 P	YORK, J. W.	8401060478*	50-390 Q
WILLIAMS, C. E.	8004280166	71-9010	WITHERS, B. D.	8401040587	50-344 P	YORK, J. W.	8401090150*	50-438 Q
WILLIAMS, J.	8312090216	50-358 S	WITHERS, B. D.	8401050530	50-344 P	YORK, W. C.	8401200160	50-317 J
WILLIAMS, J.	8401030213	50-358 A	WITHERS, B. D.	8401100273	PR	YOST, R. A.	8401240339	50-338 R
WILLIAMS, J.	8401040022*	50-358 R	WITHERS, B. D.	8401100471	REVIEW GRP	YOUNG, K.	8401250296*	50-331 P
WILLIAMS, J.	8401050328	50-358 S	WITHERS, B. D.	8401100471	REVIEW GRP	YOUNG, M. A.	8401120231	50-434 Q
WILLIAMS, J.	8401050419	50-358 Q	WITHERS, B. D.	8401240118	50-344 P	YOUNG, M. A.	8401250078	50-434 Q
WILLIAMS, J.	8401050591	50-358 S	WITHERS, B. D.	8401240144	50-344 P	YOUNG, M. A.	8401250083*	50-434 Q
WILLIAMS, J.	8401100294	50-358 S	WITHERS, B. D.	8401240392	50-344 Q	YOUNG, S. C.	8401110164*	50-440 Q
WILLIAMS, J.	8401100383	50-358 S	WITHERS, B. D.	8401240495	50-344 F	YOUNG, T.	8401030230*	50-312 Q
WILLIAMS, J.	8401120365	50-358 S	WITHERS, B. D.	8401270346	50-344 P	YOUNG, T.	8401040537	50-312 S
WILLIAMS, J.	8401120365	50-358 S	WITHERS, B. D.	8401270431	50-344 P	YOUNG, T.	8401100413*	50-312 Q
WILLIAMS, J.	8401120390	50-358 S	WITHERS, B. D.	8401270434*	50-344 P	YOUNG, T.	8401200211*	50-328 Q
WILLIAMS, J.	8401160220	50-358 A	WITHERS, B. D.	8401310087	50-344 P	YOUNG, T.	8401300280*	50-312 Q
WILLIAMS, J.	8401170194	50-358 R	WITHERS, B. D.	8401310093*	50-344 P	YOUNG, T.	8401300302*	50-328 Q

PERSONAL AUTHOR INDEX

511

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
YOUNG, Y. A	8401090660	40-3453	ZUPKO, J. M	8401270464	50-272 S
YOUNG BLOOD, B. J	8401030351	50-454 A	ZUPKO, J. M	8401310353	50-272 R
YOUNG BLOOD, B. J	8401040613	50-423 A	ZURAKOWSKI, P. R.	8401300282*	70-754
YOUNG BLOOD, B. J	8401120168	50-483 H	ZURAKOWSKI, P. R.	8401310020	70-1470
YOUNG BLOOD, B. J	8401170553	50-440 F			
YOUNG BLOOD, B. J	8401190095	50-483 F			
YOUNG BLOOD, B. J	8401190111	50-445 A			
YOUNG BLOOD, B. J	8401190139	50-456 D			
YOUNG BLOOD, B. J	8401190140	50-445 A			
YOUNG BLOOD, B. J	8401190157	50-482 E			
YOUNG BLOOD, B. J	8401190172	50-440 A			
YOUNG BLOOD, B. J	8401190177	50-482 E			
YOUNG BLOOD, B. J	8401190210	50-423 D			
YOUNG BLOOD, B. J	8401190220	50-440 E			
YOUNG BLOOD, B. J	8401300068	50-423 A			
YOUNG BLOOD, B. J	8401310085	50-358 A			
YOUNGLING, E. J	8401110240	50-322 A			
YTHIER, P.	8401230031*	CONTRACT			
YUKAS, O.	8401160223	50-362 B			
YUKAS, O. P.	8401300160*	50-206 G			
YUNDT, C. P.	8401120321	50-344 B			
YUNDT, C. P.	8401120408	50-344 B			
YUNDT, C. P.	8401120416	50-344 R			
YUNDT, C. P.	8401160252	50-344 B			
YUNDT, C. P.	8401160304	50-344 B			
YUNDT, C. P.	8401270476	50-344 R			
ZAHLER, R. E.	8401060031	FOIA			
ZAHLER, R. E.	8401100139	50-289 G			
ZAHLER, R. E.	8401100139	50-289 G			
ZAHLER, R. E.	8401230460*	40-2061			
ZAHLER, R. E.	8401230460*	40-2061			
ZAHLEUTER, R. J	8401310140	50-322 G			
ZIBULSKY, H.	8401260315*	70-135			
ZIBULSKY, H.	8401310097*	70-687			
ZIBULSKY, R.	8401060488*	50-409 R			
ZIMMERMAN, J. V.	8401060623	XPORTLIC			
ZIMMERMAN, J. V.	8401060628	XPORTLIC			
ZIMMERMAN, J. V.	8401090047	XPORTLIC			
ZIMMERMAN, J. V.	8401090055	XPORTLIC			
ZIMMERMAN, J. V.	8401090063	XPORTLIC			
ZIMMERMAN, J. V.	8401090067	XPORTLIC			
ZIMMERMAN, J. V.	8401090087	XPORTLIC			
ZIMMERMAN, J. V.	8401090096	XPORTLIC			
ZIMMERMAN, J. V.	8401090303	XPORTLIC			
ZIMMERMAN, J. V.	8401090306	XPORTLIC			
ZIMMERMAN, J. V.	8401100026	XPORTLIC			
ZIMMERMAN, J. V.	8401110337	XPORTLIC			
ZIMMERMAN, J. V.	8401110349	XPORTLIC			
ZIMMERMAN, J. V.	8401110352	XPORTLIC			
ZIMMERMAN, J. V.	8401110355	XPORTLIC			
ZIMMERMAN, J. V.	8401110359	XPORTLIC			
ZIMMERMAN, J. V.	8401110368	XPORTLIC			
ZIMMERMAN, J. V.	8401110386	XPORTLIC			
ZIMMERMAN, J. V.	8401110404	XPORTLIC			
ZIMMERMAN, J. V.	8401110418	XPORTLIC			
ZIMMERMAN, J. V.	8401110424	XPORTLIC			
ZIMMERMAN, J. V.	8401120562	XPORTLIC			
ZIMMERMAN, J. V.	8401160040	XPORTLIC			
ZIMMERMAN, J. V.	8401160383	XPORTLIC			
ZIMMERMAN, J. V.	8401180001	XPORTLIC			
ZIMMERMAN, J. V.	8401190259	XPORTLIC			
ZIMMERMAN, S. R.	8401040516	50-261 H			
ZIMMERMAN, S. R.	8401060140*	50-324 F			
ZIMMERMAN, S. R.	8401100422	50-261 P			
ZIMMERMAN, S. R.	8401130250	50-324 P			
ZIMMERMAN, S. R.	8401130335	50-261 X			
ZIMMERMAN, S. R.	8401170181	50-324 P			
ZIMMERMAN, S. R.	8401170245	50-324 P			
ZIMMERMAN, S. R.	8401200086	50-261 G			
ZIMMERMAN, S. R.	8401230244	50-261 G			
ZIMMERMAN, S. R.	8401310015	50-400 K			
ZIMMERMAN, S. R.	8401310245	50-400 R			
ZIMMERMAN, S. R.	8401310399	50-400 R			
ZUMMAL, T. L. R.	8401230204*	CONTRACT			
ZUPKO, J. H.	8401240117	50-272 R			
ZUPKO, J. H.	8401130214	50-272 B			
ZUPKO, J. H.	8401130256	50-272 S			
ZUPKO, J. H.	8401130285	50-311 S			
ZUPKO, J. H.	8401130320	50-311 S			
ZUPKO, J. H.	8401130329	50-272 S			
ZUPKO, J. H.	8401130333	50-311 B			
ZUPKO, J. H.	8401230004	50-311 R			
ZUPKO, J. H.	8401240002	50-311 S			
ZUPKO, J. H.	8401270087	50-272 B			
ZUPKO, J. H.	8401270150	50-272 S			

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ABC Testing	B401200106	71-9143
AEAP, Inc	B401080087*	CONTRACT
Amoco	B401100207	50-289 Q
	B401190336	50-289 Q
	B401190339*	50-289 Q
	B401190342*	50-289 Q
	B401190344*	50-289 Q
	B401260116	50-289 Q
	B401260208	50-289 Q
	B401260214*	50-289 Q
	B401260222*	50-289 Q
Amoco Corp	B401030389*	CONTRACT
Amoco American, Inc	B401120098	NUREG
Advanced Medical Systems, Inc	B401250253	FR
Afrimpt Indussa, Inc.	B401300103*	40-8331
Air Force, Dept of, Armament Laboratory	B401060447*	40-8011
Environment	B401110312	50-352 Q
Air and Water Pollution Patrol	B401110312	50-352 Q
	B401110316*	50-352 Q
	B401110316*	50-352 Q
	B401110319*	50-352 Q
	B401110319*	50-352 Q
	B401110321*	50-352 Q
	B401110321*	50-352 Q
	B401110322*	50-352 Q
	B401110322*	50-352 Q
	B401260142	50-352 Q
	B401260149*	50-352 Q
	B401260153*	50-352 Q
	B401260163*	50-352 Q
	B401260163*	50-352 Q
	B401260163*	50-352 Q
	B401260168*	50-352 Q
	B401260168*	50-352 Q
	B401260172*	50-352 Q
	B401260172*	50-352 Q
	B401310328	50-352 Q
	B401310328	50-352 Q
	B401310333*	50-352 Q
	B401310333*	50-352 Q
	B401310337*	50-352 Q
	B401310337*	50-352 Q
	B401310337*	50-352 Q
	B401030123	50-344 B
	B401030374*	50-348 F
	B401040123	50-348 B
	B401040131*	50-348 B
	B401040136*	50-348 B
	B401040140*	50-348 B
	B401040157	50-348 B
	B401040359	50-348 B
	B401040359	50-348 B
	B401050448*	50-348 Q
	B401050606*	50-348 Q
	B401060121*	50-348 F
	B401060121*	50-348 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B401060126*	50-348 F
	B401060126*	50-348 F
	B401060465	50-348 B
	B401060465	50-348 B
	B401060469*	50-348 B
	B401060473*	50-348 B
	B401060481*	50-348 B
	B401060489*	50-348 B
	B401100390	50-348 B
	B401100396*	50-348 B
	B401100403*	50-348 B
	B401160084	50-348 P
	B401160084	50-348 P
	B401170191	50-348 R
	B401170197	50-364 R
	B401170235	50-348 P
	B401200288*	50-348 F
	B401240263	50-348 B
	B401240263	50-348 B
	B401240267*	50-348 B
	B401240275*	50-348 B
	B401240565*	50-348 Q
	B401240565*	50-348 Q
	B401240627*	50-348 F
	B401240627*	50-348 F
	B401240632*	50-348 F
	B401240632*	50-348 F
	B401240642*	50-348 F
	B401240642*	50-348 F
	B401240643*	50-348 F
	B401240645*	50-348 F
	B401250003*	50-348 F
	B401250003*	50-348 F
	B401260185*	50-348 F
	B401260270*	50-348 F
	B401260299*	50-348 F
	B401260334*	50-348 F
	B401270125	50-348 Q
	B401300287	50-348 B
	B401300287	50-348 B
	B401300291*	50-348 B
	B401300294*	50-348 B
	B401300297*	50-348 B
	B401300303*	50-348 B
	B401300306*	50-348 B
	B401310236*	50-348 F
	B401310236*	50-348 F
	B401310240*	50-348 F
	B401310240*	50-348 F
Allied General Nuclear Services	B312200510	NUREG
	B401060407	50-332 Q
	B401060506	50-332 Q
	B401090066	50-332 A
	B401090083*	50-332 A
American Electric Power Co., Inc.	B401310301	50-315 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
American Electric Power Service Corp.	B401040196*	50-315 F		B401180017*	50-328 A
American Nuclear Corp	B401110489	40-4492		B401180020*	50-328 A
	B401110587	40-4492		B401180020*	50-328 A
American Society of Mechanical Engineers	B401120102*	CONTRACT		B401180020*	50-328 A
American Telephone & Telegraph Co	B401050020*	CONTRACT		B401180022*	50-328 A
/American Bell					
Anchor/Darling Valve Co (subs. of Anchor/Darling Industries, Inc.)	B401040550*	QA999		B401180028*	50-328 A
				B401180028*	50-328 A
	B401040558*	QA999		B401180033*	50-328 A
Amefco, Inc.	B401130098	71-1		B401180073*	50-328 A
Applied Decision Analysis, Inc	B401100476*	REVIEW GRP		B401180075*	50-328 A
Argonne National Laboratory	B401160443	NUREG			
				B401180077*	50-328 A
	B401230062	NUREG		B401180077*	50-328 A
Arizona Public Service Co.	B401030061	50-528 A		B401180082*	50-328 A
	B401030061	50-528 A		B401180082*	50-328 A
	B401030261	50-528 E			
	B401040129	50-529 B		B401180082*	50-328 A
	B401040220	50-529 B		B401180090*	50-328 A
	B401040222	50-528 B		B401180094*	50-328 A
	B401040266	50-528 B		B401180107	50-328 Q
	B401040298	50-528 B		B401180116*	50-328 A
	B401040313	50-528 B			
				B401200053*	50-328 F
	B401040338	50-530 B		B401200053*	50-328 F
	B401040342	50-528 B		B401200053*	50-328 F
	B401040344	50-530 B		B401230661*	50-328 F
	B401040366	50-528 B		B401240068	50-328 H
	B401040366	50-528 B			
	B401040366	50-528 B		B401240186	50-328 V
	B401040371	50-528 B		B401250084	50-328 F
	B401040431	50-528 B		B401260011	50-328 B
	B401040581	50-529 B		B401260011	50-328 B
	B401050204	50-528 A		B401260011	50-328 B
	B401100418	50-528 E		B401260035	50-328 B
	B401100418	50-528 E		B401260109	50-328 B
	B401100418	50-528 E		B401260120	50-328 B
	B401120209	50-529 B		B401260120	50-328 B
	B401120220	50-528 B		B401260120	50-328 B
	B401120220	50-528 B		B401260150	50-328 B
	B401120220	50-528 B		B401260180	50-529 B
	B401120302	50-528 B		B401260236	50-328 B
	B401120302	50-528 B		B401260248	50-328 B
	B401120302	50-528 B		B401260248	50-328 B
	B401120302	50-528 B		B401260248	50-328 B
				B401260317	50-328 B
	B401120304	50-528 B		B401260325	50-328 B
	B401120304	50-528 B		B401260341	50-328 B
	B401120304	50-528 B		B401260349	50-328 B
	B401120352	50-528 B			
	B401120352	50-528 B		B401260362	50-328 B
	B401120352	50-528 B		B401260370	50-529 B
	B401120388	50-528 B		B401270277	50-328 A
	B401120388	50-528 B		B401270302	50-328 E
	B401120388	50-528 B		B401270302	50-328 E
	B401120391	50-528 B			
				B401270302	50-328 E
	B401120391	50-528 B		B401270306*	50-328 E
	B401120391	50-528 B		B401270467	50-328 A
	B401120393	50-528 B		B401270467	50-328 A
	B401120399	50-528 B		B401270467	50-328 A
	B401120402	50-528 B			
				B401300225*	50-32

CORPORATE SOURCE INDEX

515

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401170264*	50-313 Q		8401270086	50-318 S
	8401170307	50-313 S		8401270137	50-317 S
	8401170351	50-368 F		8401270281	50-317 S
	8401170377	50-313 F		8401270334	50-318 S
	8401170377	50-313 F		8401300355*	50-317 F
	8401170382	50-313 P		8401300358*	50-317 F
	8401170487*	50-313 Q	Battelle Memorial Institute	8401300052	WASTE NOT
	8401170487*	50-313 Q	Battelle Memorial Institute, Columbus	8401090742*	CONTRACT
	8401180062	50-368 P	Laboratories		
	8401230242	50-313 S		8401120552	71-5957
	8401230254	50-368 S		8401120553*	71-5957
	8401230473	50-368 S		8401130379	NUREG
	8401230492	50-313 Q	Battelle Memorial Institute, Pacific	8401090615	NUREG
	8401230492	50-313 Q	Northwest Laboratory		
	8401240182	50-313 F		8401100088	NUREG
	8401240335	50-269 H		8401120095	NUREG
	8401250060*	50-313 F		8401120451*	WASTE NOT
	8401250085*	50-313 F			
	8401260027*	50-313 F		8401130220	NUREG
	8401260027*	50-313 F		8401130231	NUREG
	8401260029*	50-313 F		8401130356	NUREG
	8401260029*	50-313 F		8401130360	NUREG
	8401260032*	50-313 F		8401160450	40-4492
	8401260251*	50-313 F			
	8401260251*	50-313 F		8401190250	NUREG
	8401260305*	50-313 F		8401230677	NUREG
	8401260305*	50-313 F		8401260105	NUREG
	8401260316*	50-313 F		8401310449	NUREG
	8401260316*	50-313 F	Bear Creek Uranium Co	8401110551*	40-8452
	8401270399	50-313 R			
	8401270402	50-368 R		8401230380*	QA999
	8401270505	50-313 Q	Bechtel Corp	8401230436*	QA999
	8401300167	50-368 F		8401270299*	QA999
	8401300186	50-313 P		8401300118*	50-250 Q
	8401300186	50-313 P		8401060648*	CONTRACT
	8401300364*	50-313 F			
	8401310237	50-313 P		8401260128	50-155 Q
	8401310312	50-313 P		8401260129*	50-155 Q
	8401310460*	50-313 F		8401060207*	CONTRACT
	8401310460*	50-313 F		8401180216	50-413 Q
	8401120138*	CONTRACT		8401050247	50-413 Q
	8401160263	50-352 D			
	8401100095*	CONTRACT		8401070383	PR
	8401050236	PR		8401110302	50-445 Q
	8401100045*	CONTRACT		8401180222	50-413 Q
	8401240364*	QA999		8401180222	50-413 Q
	8401240392*	QA999		8401180228*	50-413 Q
	8401050533*	70-27			
	8401130056	70-27		8401180228*	50-413 Q
	8401160232	50-13 P		8401190283	50-445 Q
	8401160237*	50-13 P		8401200144	50-413 Q
	8401230549*	50-289 P		8401240300*	50-413 Q
	8312290397	50-317 S		8401240335	50-269 H
	8401030186	50-318 S			
	8401030268	50-317 S		8401300244	50-445 Q
	8401050098*	50-317 F		8401310343	50-413 Q
	8401050101*	50-317 F		8401040179	50-293 P
	8401050417*	50-317 F		8401040181*	50-293 P
	8401050417*	50-317 F		8401040209	50-293 P
	8401060032*	50-317 F			
	8401060266*	50-317 F		8401050293	50-293 R
	8401060274*	50-317 F		8401090405	50-293 P
	8401060278*	50-317 F		8401090409*	50-293 P
	8401060278*	50-317 F		8401120208	50-293 S
	8401100176*	50-317 Q		8401130047	50-293 X
	8401100483	50-317 F			
	8401100483	50-317 F		8401160095	50-293 F
	8401130212	50-317 S		8401160118	50-293 S
	8401130253*	50-317 Q		8401160175	50-293 S
	8401160067	50-317 S		8401160307*	50-293 Q
	8401160081	50-317 S		8401170436	50-293 R
	8401160087	50-318 S			
	8401160093	50-317 S		8401180074	50-293 F
	8401160126	50-317 S		8401190385	50-293 P
	8401160131	50-318 S		8401200268	50-293 H
	8401160171	50-318 S		8401230235	50-293 Q
	8401180240	50-317 P		8401230237*	50-293 Q
	8401190326	50-317 V			
	8401200160	50-317 J		8401230370	50-293 P
	8401240277*	50-317 Q		8401230415	50-293 Q
	8401240403	50-317 R		8401240098	50-293 S
	8401250158	50-317 R		8401240103	50-293 S
	8401260281	50-317 S		8401240145	50-293 S
	8401270059	50-317 S			
	8401270065	50-318 S		8401270162	50-293 S
				8401270243	50-293 S
				8401200318	FOIA
				8401310332*	50-445 A
				8401040351	50-286 P
				8401040522	50-286 P
				8401130224	50-10 P
				8401160284*	50-219 P
				8401160438	NUREG
				8401230228*	QA999
				8401170221	50-482 Q
				8401270271	TOPREP

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
CBS News, CBS, Inc	B401160445	50-358 G		B401060145*	50-324 F
CLOW Corp.	B401130107*	0A999		B401060145*	50-324 F
	B401270350*	50-344 F		B401060151*	50-324 F
California, State of	B401160242	50-275 G		B401060151*	50-324 F
	B401170243	50-275 G		B401060280	50-400 G
	B401170249	50-275 G		B401060280	50-400 G
	B401180187	50-275 G		B401060318	50-400 G
	B401180187	50-275 G		B401060318	50-400 G
	B401180210	50-275 G		B401060343	50-329 A
	B401180210	50-275 G		B401060361	50-325 S
	B401180235	50-275 G		B401060420	50-400 S
	B401230399	50-275 U		B401060420	50-400 S
	B401230399	50-275 U		B401060426*	50-324 G
	B401230432	50-275 U		B401060426*	50-324 G
	B401230432	50-275 U		B401100161	50-324 S
	B401240086	50-275 U		B401100217	50-400 G
	B401240086	50-275 U		B401100283	50-324 F
	B401240199	50-275 U		B401100289*	50-324 F
	B401240199	50-275 U		B401100373	50-261 P
	B401240208	50-275 U		B401100373	50-261 P
	B401240208	50-275 U		B401100422	50-261 P
	B401240220	50-275 U		B401110214	50-400 G
	B401240220	50-275 U		B401110214	50-400 G
	B401240227	50-275 U		B401110218*	50-400 G
	B401240227	50-275 U		B401110224*	50-400 G
	B401240232	50-275 U		B401110224*	50-400 G
	B401240232	50-275 U		B401110233	50-324 R
	B401240269	50-275 U		B401120385	50-261 F
	B401240269	50-275 U		B401120394*	50-261 P
	B401240493	50-275 U		B401130132	50-261 S
	B401240493	50-275 U		B401130250	50-324 P
California, Univ of, Los Angeles, CA	B401270226	50-275 U		B401130255	50-325 S
	B401050233	50-142 G		B401130257*	50-324 P
	B401050249	50-142 G		B401130257*	50-324 P
	B401160247	50-142 G		B401130266*	50-324 P
	B401160249*	50-142 G		B401130266*	50-324 P
	B401170304	50-142 G		B401130283*	50-324 P
	B401230416	50-142 G		B401130335	50-261 X
	B401230425	50-142 G		B401130335	50-261 X
	B401250129	NUREG		B401130335	50-261 X
	B401310348	50-142 G		B401160007	50-261 J
California, Univ of, Santa Barbara, CA	B401250070*	50-433 F		B401160070	50-261 J
Canada, Atomic Energy Control Board	B401190230	XPORTL IC		B401160107	50-261 R
Canyon Research Corp	B401040196*	50-315 F		B401160121	50-261 J
Carolina Environmental Study Group	B401260132	50-413 G		B401160184	50-261 J
	B401310323	50-413 G		B401170006	50-400 S
Carolina Power & Light Co	B401030062	50-325 S		B401170132	50-325 S
	B401030145	50-325 S		B401170181	50-324 P
	B401030190	50-325 S		B401170181	50-324 P
	B401030217	50-261 S		B401170233	50-400 G
	B401030248	50-324 S		B401170233	50-400 G
	B401030248	50-324 S		B401170237*	50-400 G
	B401030257	50-325 S		B401170237*	50-400 G
	B401030271	50-324 S		B401170239*	50-400 G
	B401030327	50-325 S		B401170239*	50-400 G
	B401040317	50-325 S		B401170245	50-324 P
	B401040468	50-324 P		B401170245	50-324 P
	B401040512	50-253 P		B401170302	50-400 G
	B401040515*	50-324 P		B401170302	50-400 G
	B401040516	50-261 H		B401170431	50-324 P
	B401040519*	50-324 P		B401170433*	50-324 P
	B401040527*	50-324 P		B401180133	50-261 P
	B401050052*	50-261 F		B401180135*	50-261 P
	B401050054*	50-261 F		B401200024	50-324 J
	B401050061*	50-261 F		B401200024	50-324 J
	B401050164	TOPREP		B401200040	50-261 P
	B401050198	50-324 P		B401200084	50-261 G
	B401050198	50-324 P		B401200089*	50-261 G
	B401050219*	50-324 P		B401200091*	50-261 G
	B401050219*	50-324 P		B401200188	50-261 P
	B401050304	50-400 G		B401200189*	50-261 P
	B401050304	50-400 G		B401200192	50-324 J
	B401050305	50-400 F		B401200192	50-324 J
	B401050305	50-400 F		B401230007	50-400 A
	B401050390*	50-400 G		B401230009*	50-400 A
	B401050415	50-261 S		B401230244	50-261 G
	B401050438	50-325 S		B401230248*	50-261 G
	B401050461	50-400 S		B401230283	50-325 S
	B401050470	50-400 S		B401230391	50-400 G
	B401050476	50-261 S		B401230391	50-400 G
	B401050478	50-324 G		B401230395*	50-400 G
	B401050490*	50-324 G		B401230395*	50-400 G
	B401050490*	50-324 G		B401230397*	50-400 G
	B401050615	50-261 P		B401230397*	50-400 G
	B401060140*	50-324 F		B401230406	50-324 S

CORPORATE SOURCE INDEX

517

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401230406	50-324 S		8401120390	50-358 S
	8401230466	50-400 Q		8401160220	50-358 A
	8401230466	50-400 Q		8401160224*	50-358 A
	8401230468*	50-400 Q		8401170194	50-358 R
	8401230468*	50-400 Q		8401170206*	50-358 R
	8401230470	50-400 K		8401170444	50-358 S
	8401230474*	50-400 K		8401180113	50-358 A
	8401240003	50-324 S		8401190182*	50-358 A
	8401240003	50-324 S		8401190295	50-358 Q
	8401240019	50-325 S		8401190318	50-358 S
	8401240070	50-324 S		8401190435	50-358 S
	8401240092	50-261 J		8401230393	50-358 S
	8401240166	50-324 S		8401300125	50-358 A
	8401240256	50-261 J		8401300129	50-358 V
	8401240412*	50-261 Q		8401300155	50-358 S
	8401240498*	50-324 Q		8401310214	50-358 A
	8401240498*	50-324 Q	Cincinnati, OH	8401160209	50-358 Q
	8401240506	50-400 S		8401180245	50-358 Q
	8401240648*	50-261 F		8401260226	50-358 H
	8401250145*	50-261 F	Citizens Against Research Bans	8401040016	FOIA
	8401250149*	50-261 F		8401030126	50-445 Q
	8401250172	50-324 R	Citizens Association for Sound Energy	8401030126	50-445 Q
	8401250261	50-324 P		8401030133*	50-445 Q
	8401260019	50-325 S		8401030133*	50-445 Q
	8401260023	50-324 J		8401030175	50-445 Q
	8401260023	50-324 J		8401030175	50-445 Q
	8401260039	50-325 S		8401060360	50-445 Q
	8401260103	50-400 S		8401130106	50-445 Q
	8401260117	50-400 Q		8401170300	50-445 Q
	8401260117	50-400 Q		8401190188	50-445 Q
	8401260176	50-400 S		8401240204	50-445 Q
	8401260210	50-324 J		8401180188	50-498 Q
	8401260210	50-324 J		8401050326	50-440 S
	8401260228*	50-261 F		8401050326	50-440 S
	8401260351	50-325 S		8401050375	50-440 S
	8401260354	50-400 S		8401050375	50-440 S
	8401260356	50-400 S		8401050402	50-440 S
	8401270349	50-329 A		8401050402	50-440 S
	8401300139	50-261 Q		8401050446	50-440 S
	8401300184	50-400 A		8401050446	50-440 S
	8401310015	50-400 K		8401050509	50-440 S
	8401310245	50-400 R		8401050509	50-440 S
	8401310246*	50-400 R		8401050520	50-440 S
	8401310256	50-261 P		8401050520	50-440 S
	8401310272	50-261 Q		8401050527	50-400 S
	8401310399	50-400 R		8401050527	50-400 S
Argenter Technology Corp	8401120561	XPORTLIC		8401100323	50-440 A
	8401120568	XPORTLIC		8401110159	50-440 Q
Center for Law in the Public Interest	8401130075	XPORTLIC		8401110159	50-440 Q
	8401050221	50-275 Q		8401110164*	50-440 Q
	8401100159	50-275 Q		8401110164*	50-440 Q
	8401160204	50-275 Q		8401110167*	50-440 Q
	8401170322	50-275 Q		8401110167*	50-440 Q
Center for Nuclear Responsibility	8401230435	50-275 Q		8401170042*	50-440 A
	8401300126	50-250 Q		8401170391	50-440 A
	8401300130*	50-250 Q		8401170394*	50-440 A
	8401300130*	50-250 Q		8401230280	50-440 S
	8401310139	50-250 Q		8401230301*	50-440 Q
	8401310139	50-250 Q		8401230301*	50-440 Q
	8401310357	50-250 Q		8401230365	50-440 Q
	8401310357	50-250 Q		8401230375	50-440 S
	8401310364*	50-250 Q		8401240071	50-440 Q
	8401310364*	50-250 Q		8401260146*	50-440 Q
Central Florida Univ. of, Garnett, G	8401250366*	CONTRACT		8401260146*	50-440 Q
	8401040046*	CONTRACT		8401310124	50-440 Q
Clea-Nuclear Systems, Inc	8401120604	WASTE MGT		8401090370	50-440 H
	8401120608*	WASTE MGT	Cleveland, OH	8401300190	50-413 Q
	8401160117	WASTE MGT	Clewett, J.	8401300190	50-413 Q
	8401190085	71-9044		8401300194*	50-413 Q
	8401190093*	71-9044		8401300194*	50-413 Q
Chicago Bridge & Iron Co.	8401160020	71-9107		8401000197	50-344 Q
Christa-Maria	8401260212	50-155 Q	Coalition for Safe Power	8401160199	50-308 Q
Cincinnati Gas & Electric Co.	84012090216	50-358 S		8401130168*	QA999
	8401030213	50-358 A	Coffer Corp	8401160454	WASTE MGT
	8401040022*	50-358 R	Colorado State of	8401040275*	50-368 P
	8401040026*	50-358 R	Combustion Engineering, Inc	8401050584*	50-368 P
	8401040292	50-358 V		8401090378	PR
	8401050328	50-358 S		8401200168*	50-336 P
	8401050419	50-358 Q		8401230465*	QA999
	8401050591	50-358 S		8401250006	TOPREP
	8401090315*	50-289 P		8401250009*	TOPREP
	8401100294	50-358 S	Commerce Dept of, National Bureau of	8401130325	50-184 P
	8401100383	50-358 S	Standards	8401310104*	50-498 A
	8401120365	50-358 S			
	8401120365	50-358 S			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Commerce, Dept. of National Technical Information Services	B401310108*	50-498 A		B401090304	50-373 J
	B401030379*	CONTRACT		B401100162	50-454 A
Committee to Bridge the Gap	B401310150	NUREG		B401100162	50-454 A
	B401030149	50-142 Q		B401100162	50-454 A
	B401030197*	50-142 Q			
	B401030185	50-142 Q		B401100162	50-454 A
	B401030187	50-142 Q		B401100181	50-454 E
	B401030192*	50-142 Q		B401100181	50-454 E
	B401030225	50-142 Q		B401100181	50-454 E
	B401100208	50-142 Q			
	B401100211	50-142 Q		B401100181	50-454 E
	B401110161	50-142 Q		B401100193	50-454 E
	B401130197	50-142 Q		B401100193	50-454 E
	B401240081	50-142 Q		B401100193	50-454 E
	B401240193	50-142 Q			
	B401240238	50-142 Q		B401100193	50-454 E
	B401240241*	50-142 Q		B401100215	50-454 Q
	B401270201	50-142 Q		B401100215	50-454 Q
	B401270374	50-142 Q		B401100219*	50-454 Q
	B401300228	50-142 Q		B401100219*	50-454 Q
Commonwealth Edison Co.	B401300230*	50-142 Q		B401100265	50-454 A
	B401030227	50-237 F		B401100265	50-454 A
	B401030227	50-237 F		B401100265	50-454 A
	B401030227	50-237 F		B401100265	50-454 A
	B401030227	50-237 F		B401100265	50-454 A
	B401040278*	50-373 Q		B401100275	50-454 Q
	B401040329	50-237 F		B401100275	50-454 Q
	B401040377	50-237 B		B401100311	50-454 A
	B401040533	50-237 Q		B401100311	50-454 A
	B401040533	50-237 Q		B401100311	50-454 A
	B401040533	50-237 Q			
	B401040533	50-237 Q		B401100311	50-454 A
	B401040533	50-237 Q		B401100347	50-454 E
	B401040534	50-237 F		B401100347	50-454 E
	B401040556	50-237 F		B401100347	50-454 E
	B401050063*	50-373 F		B401100347	50-454 E
	B401050090*	50-295 F		B401100350	50-237 P
	B401050102*	50-254 F		B401100362	50-454 A
	B401050244*	50-295 F		B401100362	50-454 A
	B401050257*	50-254 F		B401100362	50-454 A
	B401050257*	50-254 F		B401100362	50-454 A
	B401050261*	50-254 F		B401100380	50-456 C
	B401050261*	50-254 F		B401100380	50-456 C
	B401050413	50-374 B			
	B401050431	50-265 B		B401100433	50-454 E
	B401050437	50-373 B		B401100433	50-454 E
	B401050449	50-254 B		B401100433	50-454 E
	B401050483	50-265 B		B401100433	50-454 E
	B401050500	50-265 B		B401100433	50-454 E
	B401050512	50-265 B			
	B401050526	50-265 B		B401100455	50-295 P
	B401050538	50-265 B		B401100455	50-295 P
	B401050632	50-10 B		B401100458	50-237 S
	B401060170	50-484 F		B401100468	50-295 P
	B401060170	50-484 F		B401100479	50-454 A
	B401060170	50-484 F			
	B401060180	50-454 E		B401100479	50-454 A
	B401060180	50-454 E		B401110276	50-454 A
	B401060180	50-454 E		B401110276	50-454 A
	B401060180	50-454 E		B401120215	50-373 R
	B401060180	50-454 E		B401130043	50-237 S
	B401060180	50-454 E			
	B401060180	50-454 E		B401130098	50-304 S
	B401060204	50-454 E		B401130184	50-237 S
	B401060204	50-454 E		B401130185	50-237 S
	B401060204	50-454 E		B401130234	50-237 S
	B401060204	50-454 E		B401130290	50-373 S
	B401060204	50-454 E			
	B401060204	50-454 E		B401130303	50-454 A
	B401060259*	50-373 F		B401130303	50-454 A
	B401060268	50-373 S		B401130303	50-454 A
	B401060271	50-373 P		B401130334	50-304 B
	B401060288*	50-373 P		B401130341	50-373 B
	B401060404	50-373 B			
	B401060416	50-456 A		B401160144	50-237 R
	B401060416	50-456 A		B401160260	50-454 E
	B401090142	50-373 P		B401160260	50-454 E
	B401090145*	50-373 P		B401160261	50-373 S
	B401090223	50-454 K		B401160275	PRM
	B401090223	50-454 K			
	B401090223	50-454 K		B401160309	50-237 P
	B401090223	50-454 K		B401160314	50-454 A
	B401090223	50-454 K		B401170020	50-295 R
	B401090223	50-454 K		B401170024	50-254 R
	B401090223	50-454 K		B401170160	50-456 A
	B401090242*	50-454 K			
	B401090242*	50-454 K		B401170160	50-456 A
	B401090336	PR		B401170210	50-254 R
	B401090504	50-373 J		B401170339	50-237 P
				B401170339	50-237 P

CORPORATE SOURCE INDEX

519

AUTHOR
AFFILIATIONACCESSION
NUMBERSUBJECT
CATEGORYAUTHOR
AFFILIATIONACCESSION
NUMBERSUBJECT
CATEGORY

8401170339 50-237 P
8401170339 50-237 P
8401170357 50-454 Q
8401170402 50-373 R
8401180232 50-237 P

8401190297 50-254 S
8401190322 50-456 A
8401190322 50-456 A
8401190413 50-295 S
8401190420 50-454 Q

8401190423 50-295 S
8401200141 50-10 J
8401200141 50-10 J
8401200141 50-10 J
8401200141 50-10 J

8401200141 50-10 J
8401200184 50-10 J
8401200184 50-10 J
8401200184 50-10 J
8401200184 50-10 J

8401200184 50-10 J
8401230002 50-237 S
8401230010 50-237 S
8401230149 50-373 Q
8401230233 50-373 Q

8401230288 50-373 P
8401230288 50-373 P
8401230294* 50-373 Q
8401230306* 50-373 Q
8401230306* 50-373 Q

8401230310* 50-454 Q
8401230327 50-237 P
8401230327 50-237 P
8401230332* 50-237 P
8401230332* 50-237 P

8401230334* 50-373 Q
8401230338 50-373 P
8401230339* 50-373 Q
8401230342* 50-373 Q
8401230372* 50-373 Q

8401230404 50-373 S
8401230424 50-373 P
8401230426 50-456 Q
8401230426 50-456 Q
8401230433* 50-373 P

8401230456 50-249 P
8401230463* 50-249 P
8401240652* 50-254 F
8401250013 50-237 Q
8401250047* 50-454 F

8401250086* 50-10 F
8401250089* 50-10 F
8401250123* 50-295 F
8401250123* 50-295 F
8401250138* 50-295 F

8401250201 50-454 Q
8401250312* 50-373 F
8401250314* 50-373 F
8401260243* 50-295 F
8401260243* 50-295 F

8401260252* 50-295 F
8401260263* 50-295 F
8401260263* 50-295 F
8401260289* 50-454 F
8401260297* 50-373 F

8401260297* 50-373 F
8401260409* 50-454 F
8401260409* 50-454 F
8401270333 50-295 S
8401270338 50-265 S

8401270357 50-237 S
8401300003 50-295 Q
8401300200 50-295 F
8401300202 50-454 Q
8401300202 50-454 Q

8401300207* 50-454 Q
8401300207* 50-454 Q
8401300210* 50-454 Q
8401300210* 50-454 Q
8401300265 50-295 P

8401300265 50-295 P
8401300247* 50-295 P
8401300247* 50-295 P
8401300281 50-237 S
8401300348* 50-254 F

Computer Systems Support Corp
Connecticut Yankee Atomic Power Co

8401300348* 50-254 F
8401310051* 50-295 F
8401310051* 50-295 F
8401310058* 50-373 F
8401310064* 50-373 F

8401310081* 50-295 F
8401310106* 50-295 F
8401310106* 50-295 F
8401310180* 50-10 F
8401310187* 50-10 F

840130020* CONTRACT
8312300205 50-213 F
8401030143 50-213 P
8401040173 50-213 P
8401040226 50-213 P

8401050086* 50-213 F
8401050163 50-213 S
8401090132 50-213 F
8401100392 50-213 P
8401100392 50-213 P

8401120280 50-213 R
8401160073 50-213 S
8401200164 50-213 P
8401200164 50-213 P
8401230156 50-213 F

8401230286 50-213 P
8401230373 50-213 P
8401230373 50-213 P
8401230664* 50-213 F
8401230667* 50-213 F

8401270062 50-213 S
8401270257 50-213 R
8401270336 50-213 S
8401270347* 50-213 S
8401270404 50-213 S

Conner & Wetterhahn

8401300339* 50-213 F
8401300342* 50-213 F
8401040295 50-352 Q
8401040295 50-352 Q
8401040300* 50-352 Q

8401040300* 50-352 Q
8401060279 50-354 Q
8401060290 50-352 Q
8401060297 50-352 Q
8401090256 50-352 Q

8401090349 PR
8401100136 50-354 Q
8401100146 50-459 Q
8401100225 50-354 Q
8401102008 50-354 Q

8401110210 50-354 Q
8401110238 50-352 Q
8401110238 50-352 Q
8401120317 50-354 Q
8401130078 50-352 Q

8401130078 50-352 Q
8401130122 50-352 Q
8401180183 50-352 Q
8401190195 50-352 Q
8401190295 50-356 Q

8401240091 50-352 Q
8401240091 50-352 Q
8401240146 50-352 Q
8401240174 50-352 Q
8401240174 50-352 Q

8401240181* 50-352 Q
8401240181* 50-352 Q
8401240322 50-352 Q
8401240322 50-352 Q
8401240328 50-354 Q

8401270294 50-354 Q
8401300122 50-416 Q
8401300211 50-352 Q
8401300211 50-352 Q
8401300218 50-272 Q

Consolidated Edison Co. of New York, Inc

8401310320 50-352 Q
8401310320 50-352 Q
8401040257 50-247 P
8401050308 50-247 P
8401100158* 50-247 Q

8401100285* 50-247 Q
8401240369* 50-3 Q
8401260294* 50-3 F
8401300250 50-247 P
8401040170 50-255 S

Consumers Power Co.

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B401040200	50-329 S
	B401040200	50-329 S
	B401040461	50-329 S
	B401040461	50-329 S
	B401040308	50-329 S
	B401040508	50-329 S
	B401040532	50-255 P
	B401040630*	50-155 F
	B401050030*	50-155 F
	B401050156	50-329 R
	B401050241	50-155 Q
	B401050250	50-155 Q
	B401050340	50-155 Q
	B401050341	50-329 A
	B401050341	50-329 A
	B401050347	50-329 A
	B401050347	50-329 A
	B401050350	50-329 Q
	B401050350	50-329 Q
	B401050366	50-454 Q
	B401050366	50-454 Q
	B401050369	50-329 A
	B401050371	50-329 A
	B401050371	50-329 A
	B401050376	50-155 P
	B401050381	50-255 Q
	B401050393	50-329 A
	B401050393	50-329 A
	B401050434	50-329 A
	B401050544	50-329 Q
	B401050544	50-329 Q
	B401050647	50-329 A
	B401050647	50-329 A
	B401060112*	50-155 F
	B401060124*	50-155 F
	B401060128*	50-155 F
	B401060406	50-155 S
	B401060500*	50-329 Q
	B401090366	50-329 Q
	B401090366	50-329 Q
	B401090375*	50-329 Q
	B401090375*	50-329 Q
	B401090384*	50-329 Q
	B401090384*	50-329 Q
	B401100014	50-155 P
	B401100237	50-329 A
	B401100237	50-329 A
	B401100286	50-329 A
	B401100286	50-329 A
	B401100316	50-255 J
	B401100357	50-329 A
	B401100357	50-329 A
	B401100379	50-329 A
	B401100379	50-329 A
	B401100384	50-329 A
	B401100384	50-329 A
	B401100388	50-255 J
	B401100447	50-155 J
	B401120206	50-329 A
	B401120206	50-329 A
	B401120273	50-329 A
	B401120274	50-329 A
	B401120274	50-329 A
	B401120387	50-329 A
	B401120387	50-329 A
	B401120426	50-329 A
	B401120426	50-329 A
	B401160090	50-329 S
	B401160090	50-329 S
	B401160145	50-329 A
	B401160145	50-329 A
	B401170164	50-329 A
	B401170167	50-329 A
	B401170171	50-329 A
	B401170175	50-329 A
	B401170184	50-329 S
	B401170212	50-329 S
	B401170212	50-329 S
	B401170430	50-329 S
	B401170430	50-329 S
	B401170447	50-329 S
	B401170447	50-329 S
	B401180215	PR
	B401190329	50-329 A
	B401190329	50-329 A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B401190335	50-329 A
	B401190335	50-329 A
	B401190402	50-329 S
	B401190402	50-329 S
	B401230042	50-155 P
	B401230146	50-329 A
	B401230146	50-329 A
	B401230190	50-255 G
	B401230253	50-155 V
	B401230253	50-155 V
	B401230331	50-329 S
	B401230331	50-329 S
	B401230344	50-329 S
	B401230344	50-329 S
	B401230356	50-329 A
	B401230356	50-329 A
	B401230509	50-329 A
	B401230509	50-329 A
	B401240187	50-255 P
	B401240194	50-155 Q
	B401240501	50-329 A
	B401240501	50-329 A
	B401240509	50-329 S
	B401240542*	50-329 A
	B401240542*	50-329 A
	B401240622*	50-155 F
	B401250102*	50-155 F
	B401250249	50-255 F
	B401260123	50-400 Q
	B401260174*	50-155 F
	B401270255	50-155 R
	B401270291	50-329 A
	B401270291	50-329 A
	B401270322	50-155 R
	B401270325	50-155 P
	B401270353	50-329 A
	B401270353	50-329 A
	B401270367	50-329 A
	B401270367	50-329 A
	B401270371	50-329 Q
	B401270384	50-329 Q
	B401270391*	50-329 Q
	B401270470	50-329 A
	B401270470	50-329 A
	B401270494	50-329 A
	B401270494	50-329 A
	B401300058	50-155 S
	B401300223	50-255 P
	B401300324	50-255 P
	B401310014	50-329 A
	B401310014	50-329 A
	B401310026	50-329 R
	B401310143	50-329 A
	B401310143	50-329 A
	B401310213	50-329 A
	B401310213	50-329 A
	B401310340	50-155 Q
	B401310379	50-329 A
	B401310379	50-329 A
	B401170361	TOPREP
	B401230597	FOIA
	B401170209	XPORTLIC
	B401070754*	CONTRACT
	B401060545*	MISC
	B401090210	50-445 A
	B401030201	50-409 P
	B401030206*	50-409 P
	B401090646	50-409 S
	B401060261	50-409 S
	B401060480	50-409 R
	B401060480*	50-409 R
	B401100011	50-409 P
	B401100358*	50-409 Q
	B401100369*	50-409 Q
	B401120381	50-409 R
	B401130001	50-409 S
	B401130148	50-409 S
	B401130207	50-409 P
	B401160254	50-409 S
	B401160270	50-409 R
	B401170202	50-409 P
	B401230183	50-409 S
	B401240303*	50-409 Q
	B401250103	50-409 P
	B401250114*	50-409 P

Containment Issues Owners Group

Cordia Corp
Cotter Corp
Greene, Inc
Critical Mass Energy Project
Cygna Energy Services

Dairyland Power Cooperative

521

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401060090*	50-269 F
	8401060094*	50-269 F
	8401060323	50-413 G
	8401060401	50-413 G
	8401060417	50-413 B
	8401060471	50-413 G
	8401090311	50-369 F
	8401090364	50-269 P
	8401090364	50-269 P
	8401090364	50-269 P
	8401090508	50-269 P
	8401090508	50-269 P
	8401090508	50-269 P
	8401100386	50-269 I
	8401120217	50-369 B
	8401120226	50-369 B
	8401120266	50-269 B
	8401120375	50-370 B
	8401120376	50-369 B
	8401130069	50-369 B
	8401160298	50-413 G
	8401170208	50-287 B
	8401170359	50-413 A
	8401170359	50-413 A
	8401170360*	50-413 A
	8401170360*	50-413 A
	8401170381*	50-369 G
	8401180216	50-413 G
	8401180216	50-413 G
	8401180222	50-413 G
	8401180222	50-413 G
	8401180228*	50-413 G
	8401180228*	50-413 G
	8401180228*	50-413 G
	8401190298	50-413 G
	8401190298	50-413 G
	8401190431	50-369 P
	8401200014	50-369 R
	8401200033	50-269 R
	8401200144	50-413 G
	8401200144	50-413 G
	8401200146*	50-413 G
	8401200146*	50-413 G
	8401200186	50-369 P
	8401200221	50-269 V
	8401200223*	50-269 V
	8401230188	50-269 P
	8401230440	50-369 P
	8401230462	50-269 B
	8401240008	50-369 B
	8401240105	50-370 B
	8401240119	50-369 B
	8401240130	50-369 B
	8401240136	50-369 V
	8401240130	50-269 G
	8401240165	50-413 G
	8401240165	50-413 G
	8401240171	50-413 F
	8401240171	50-413 F
	8401240282	50-370 B
	8401240283	50-413 E
	8401240283	50-413 E
	8401240287	50-370 B
	8401240290	50-369 B
	8401240290	50-369 B
	8401240290	50-369 B
	8401240290	50-369 B
	8401240290	50-369 B
	8401240296	50-413 G
	8401240296	50-413 G
	8401240297*	50-369 G
	8401240297*	50-369 B
	8401240297*	50-369 B
	8401240300*	50-413 G
	8401240300*	50-413 G
	8401240302*	50-369 B
	8401240302*	50-369 B
	8401240302*	50-369 B
	8401240302*	50-369 B
	8401240312*	50-369 B
	8401240324*	50-369 B
	8401240324*	50-369 B
	8401240324*	50-369 B
	8401240324*	50-369 B

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Duquesne Light Co	B401240324*	50-369 S	Energy Systems Research Group, Inc Energy, Dept of	B401240176*	40-B760
	B401240323*	50-369 Q		B401240095	50-261 T
	B401240325*	50-369 Q		B401050005*	50-397 F
	B401240335	50-269 H		B401060484*	50-409 R
	B401240367*	50-369 Q		B401100149	50-537 Q
	B401240389	50-413 S		B401120005	WASTE MGT
	B401240389	50-413 S		B401120007	71-9800
	B401240400	50-414 S		B401120008	WASTE MGT
	B401240402	50-269 F		B401120009	WASTE MGT
	B401240404*	50-413 S		B401120011	WASTE MGT
	B401240404*	50-413 S		B401120013	WASTE MGT
	B401240437	50-370 S		B401120019	WASTE MGT
	B401240480	50-369 S		B401120022*	WASTE MGT
	B401240594	50-370 S		B401120025*	WASTE MGT
	B401260160	50-369 S		B401120028*	WASTE MGT
	B401270181	50-413 E		B401120033*	WASTE MGT
	B401270196	50-413 A		B401120037*	WASTE MGT
	B401270254	50-413 E		B401120040*	WASTE MGT
	B401270254	50-413 E		B401120046*	WASTE MGT
	B401300197*	50-413 Q		B401120049*	WASTE MGT
	B401300231	50-413 Q		B401120065*	WASTE MGT
	B401300231	50-413 Q		B401120067*	WASTE MGT
	B401310018	50-369 F		B401120092	WASTE MGT
	B401310075*	50-369 F		B401120108	WASTE MGT
	B401310280	50-413 E		B401120236	WASTE MGT
	B401310280	50-413 E		B401120448	WASTE MGT
	B401310300	50-269 F		B401130049	WASTE MGT
	B401030153	50-412 Q		B401130057	WASTE MGT
	B401030240	50-334 S		B401130468	WASTE MGT
	B401040169	50-412 Q		B401160015	WASTE MGT
	B401040469	50-334 R		B401160016*	WASTE MGT
	B401040501	50-334 F		B401160023	PROJ
	B401040503*	50-334 F		B401160377	WASTE MGT
	B401060285	50-412 A		B401190353	50-537 A
	B401100296*	50-412 Q		B401190463	WASTE MGT
	B401120228	50-334 S		B401190464	WASTE MGT
	B401120313	50-334 S		B401190508	WASTE MGT
	B401120403	50-334 R		B401190510	WASTE MGT
	B401120407*	50-334 R		B401260007	WASTE MGT
	B401120413	50-334 Q		B401260010*	WASTE MGT
	B401130175	50-412 A		B401260065	WASTE MGT
	B401160178	50-334 F		B401300011	WASTE MGT
	B401160129	50-334 F		B401300038	WASTE MGT
	B401160131	50-412 A		B401300043	WASTE MGT
	B401200043	50-334 J		B401300049	WASTE MGT
	B401200073	50-334 V		B401300053	WASTE MGT
	B401200073	50-334 V		B401300063	WASTE MGT
	B401260327	50-412 A		B401300072	WASTE MGT
	B401270148	50-334 S		B401300079	WASTE MGT
EQ&G, Inc.	B401270228	50-334 R		B401300084	WASTE MGT
	B401300224	50-412 F		B401300097	WASTE MGT
	B401300329	50-412 A		B401300102	WASTE MGT
	B401310115*	50-334 F		B401300105	WASTE MGT
	B401310122*	50-334 F		B401300107	WASTE MGT
	B401310295	50-334 R		B401300108*	40-B331
	B312230302*	50-387 F		B401300120	WASTE MGT
	B401090631*	50-280 P		B401300170	WASTE MGT
	B401090631*	50-280 P		B401300341	WASTE MGT
	B401100152	71-96		B401300343	WASTE MGT
Ebasco Services, Inc. (subs. of Enserch Corp.)	B401100156*	71-96	Engineers International, Inc Environmental Policy Institute	B401300360	WASTE MGT
	B401120073	NUREG		B401310179	WASTE MGT
	B401130092	NUREG		B401310185	WASTE MGT
	B401310061*	50-261 P		B401310188	WASTE MGT
	B401310429*	GEN TEC IS		B401310191	WASTE MGT
	B401310435*	GEN TEC IS		B401310197	WASTE MGT
	B401310524*	50-289 P		B401310201	WASTE MGT
	B401190434	50-338 A		B401310452	WASTE MGT
	B401270460	50-358 A		B401160462*	CONTRACT
	B401270462*	QA999		B401090481	WASTE MGT
Ecology/Air & Eddleman, W	B401090373	PR	Environmental Protection Agency	B401110219	WASTE MGT
	B401090379	50-400 Q		B401120323	WASTE MGT
	B401090333	50-400 Q		B401170217	50-261 P
	B401090346*	50-400 Q		B401090173	XPORTLIC
	B401230438	50-400 Q		B401160050	XPORTLIC
	B401230443*	50-400 Q		B401090191	40-B064
Edgar, O.L. Edison Electric Institute	B401090344	50-70 Q	Exxon Corp	B401090774	40-B102
	B401090479	WASTE MGT		B401100103*	40-B064
	B401310255	WASTE MGT		B401100103*	40-B064
	B401120265	WASTE MGT		B401110085	40-B064
	B401120270	WASTE MGT		B401120178	40-B102
Edlow International Co.	B401090298	XPORTLIC	Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)	B401120183*	40-B102
	B401110339	XPORTLIC		B401270183	40-B064
	B401160297*	40-B760		B401270183	40-B064
				B401310504	40-B064

CORPORATE SOURCE INDEX

523

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Future Analysis Associates Fansteel Metals (subs. of Fansteel, Inc.)	8401170169	TOPREP		8401030274	50-302 S
	8401180160	TOPREP		8401040143	50-302 S
	8401030243*	50-322 S		8401040248	50-302 S
	8401230013	40-7580		8401040314	50-302 S
	8401230300	40-7580		8401050469	50-302 Q
Fansteel, Inc. Federal Emergency Management Agency	8401230349	40-7580		8401050551*	50-302 Q
	8401230003	40-7580		8401050612*	50-302 Q
	8401030219	50-271 F		8401050619*	50-302 Q
	8401030222*	50-271 F		8401050629*	50-302 Q
	8401030244	50-272 F		8401050641	50-302 S
	8401030246	50-312 F		8401060397*	50-302 Q
	8401030249*	50-272 F		8401090336*	50-302 Q
	8401030264	50-312 F		8401090425*	50-302 Q
	8401030267*	50-312 F		8401090433*	50-302 Q
	8401050229	50-322 Q		8401100304	50-302 R
	8401090359	50-322 Q		8401100406	50-302 P
	8401090515	50-309 F		8401100425*	50-302 Q
	8401170269	50-280 F		8401120107	50-302 X
	8401170274*	50-280 F		8401120395	50-302 S
	8401170408	50-338 F		8401120414	50-302 S
	8401170412	50-277 F		8401120419	50-302 S
	8401170416*	50-277 F		8401130160	50-302 S
	8401170419*	50-277 F		8401160167	50-302 R
	8401180061	50-344 F		8401160298	50-302 S
	8401180071*	50-344 F		8401180200	50-302 P
	8401180103	50-482 F		8401200222	50-302 P
	8401180163	50-373 F		8401200224*	50-302 P
	8401180174*	50-373 F		8401230401	50-302 S
	8401180189	50-322 F		8401230405	50-302 P
	8401180246	50-317 F		8401230413*	50-302 P
	8401180256*	50-317 F		8401240135	50-302 S
	8401180263*	50-317 F		8401240206	50-302 R
	8401300209	50-3 F		8401240219*	50-302 R
	8401300213*	50-3 F		8401240394*	50-302 Q
	8401300215*	50-3 F		8401240425*	50-302 Q
Fisher Scientific Co. Florida Power & Light Co.	8401300219*	50-3 F	Fathoro Corp	8401240429*	50-302 Q
	8401250259	PR		8401240568*	50-302 Q
	8401030072	50-389 S		8401240575*	50-302 Q
	8401030210	50-251 S		8401300323	50-302 S
	8401040265	50-335 F		8401270454*	QA999
	8401040272*	50-335 F	Franklin Institute/Franklin Research Center	8304070498*	50-324 P
	8401040352	50-250 P		8309010227*	50-219 P
	8401040352	50-250 P		8309230076*	MISC
	8401040353*	50-250 P		8312060211*	50-309 P
	8401040353*	50-250 P		8312060347*	50-244 P
	8401040419	50-251 S	Friends of the Earth Future Resources Associates, Inc GA Technologies, Inc /General Atomic Co	8401190332*	CONTRACT
	8401040420	50-389 S		8401100232	WASTE MGT
	8401040538	50-389 F		8401120541*	CONTRACT
	8401040543*	50-389 F		8401030363	70-734
	8401050238	PR		8401060498	XPORTLIC
	8401050384*	50-335 Q	Gamma Diagnostic Laboratories Garvey, Schubert, Adams & Barrer	8401060503*	XPORTLIC
	8401050532*	50-250 Q		8401130089*	50-267 P
	8401050564	50-251 S		8401190421	70-734
	8401060020*	50-335 F		8401040146	FOIA
	8401060023*	50-335 F		8401170062	50-509 A
	8401060025*	50-335 F	General Electric Co	8401030358	70-1113
	8401120326	50-389 S		8401040095*	50-352 A
	8401120363	50-250 R		8401090182	XPORTLIC
	8401120363	50-250 R		8401090192*	XPORTLIC
	8401120363	50-250 R		8401090344	50-70 Q
	8401130159	50-335 P		8401090554*	50-293 P
	8401130176	50-250 S		8401090556*	50-293 P
	8401130284	50-250 R		8401090598	XPORTLIC
	8401170246	50-250 S		8401090602*	XPORTLIC
	8401190358	50-335 V		8401110265	50-447 A
	8401200158	50-335 P		8401110384	70-754
	8401240088	50-335 P		8401130199	QA999
	8401240253*	50-250 Q		8401160288*	50-461 S
	8401240415	50-335 F		8401170271	50-70 Q
	8401260094	50-389 S		8401170286*	50-70 Q
	8401260099	50-251 S		8401170363*	TOPREP
	8401260140*	50-389 F		8401170367*	TOPREP
	8401260145*	50-389 F		8401170371*	TOPREP
	8401260157	50-250 S		8401170403*	50-440 A
	8401260265*	50-250 F		8401170420*	50-354 A
	8401270459	50-250 R		8401170426*	50-354 A
	8401300114	50-250 Q		8401170449	70-2784
	8401300379*	50-389 F		8401170452	70-1113
	8401300383*	50-389 F		8401170455	70-1113
	8401310069*	50-389 F		8401170465	TOPREP
Florida Power Corp	8401310080*	50-389 F		8401200113	71-4909
	8401310275	50-250 F		8401200130	70-1308
	8401310277*	50-250 F		8401230028*	50-352 A
	8401030077	50-302 S		8401230329*	QA999
	8401030236	50-302 S			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
General Motors Corp General Physics Corp. General Public Utilities - GPU Service Corp	8401230398	50-395 S		8401030116	50-366 S
	8401240266	71-4909		8401030193	50-321 S
	8401240523	50-447 A		8401030242	50-366 S
	8401300285*	50-296 P		8401040168	50-321 S
	8401300310*	50-296 P		8401040250	50-366 S
	8401310235	50-70 G		8401040334	50-321 S
	8401310239*	50-70 G		8401040336	50-321 S
	8401310291	TOPREP		8401040347	50-366 P
	8401090118	XPORTLIC		8401040349*	50-366 P
	8401120361*	MISC		8401040544	50-366 S
	84012300285	50-289 S		8401050264*	50-424 G
	8401030129	50-320 S		8401050638	50-366 S
	8401030135	50-320 S		8401060371	50-366 S
	8401030198	50-289 J		8401060415	50-366 S
	8401030258	50-289 S		8401060461	50-366 S
	8401040335	50-320 P		8401060511	50-321 S
	8401040415	50-289 P		8401090431*	50-424 G
	8401040417*	50-289 P		8401090468*	50-424 G
	8401040517	50-289 P		8401130152	50-424 S
	8401040628*	50-289 F		8401130179	50-366 P
	8401050037*	50-320 F		8401130330	50-321 R
Georgia Power Co	8401050044*	50-320 F		8401130340	50-366 P
	8401050049*	50-320 F		8401130346	50-321 P
	8401050096*	50-289 F		8401130357	50-366 P
	8401050119*	50-289 F		8401170149	50-424 C
	8401050235*	50-289 F		8401170172	50-321 P
	8401050278	50-289 P		8401170172	50-321 P
	8401060111*	50-320 F		8401170345	50-366 S
	8401060148	50-219 P		8401170358	50-424 A
	8401060152*	50-289 F		8401190411	50-321 G
	8401060155*	50-219 P		8401230012	50-366 S
	8401060161*	50-219 P		8401230201	50-366 S
	8401060333	50-289 P		8401230263	50-366 S
	8401070312	50-289 P		8401230362	50-366 S
	8401100318	50-219 P		8401230384	50-424 S
	8401100334*	50-320 G		8401230488	50-424 B
	8401100363*	50-320 G		8401230488	50-424 B
	8401100398*	50-320 G		8401230493*	50-424 B
	8401120249	50-219 R		8401230493*	50-424 B
	8401120435	50-219 S		8401240102*	50-321 F
	8401130155	50-219 S		8401240106*	50-321 F
	8401130190	50-289 F		8401240984*	50-321 G
Georgia Power Co	8401130194*	50-289 F		8401260039*	50-321 F
	8401160085	50-219 R		8401260069	50-424 S
	8401160138	50-219 S		8401300030	50-321 P
	8401160193	50-219 S		8401300259	50-321 S
	8401160195	50-320 S		8401300262	50-366 S
	8401170154	50-219 P		8401300268	50-321 S
	8401170174	50-289 P		8401300293	50-321 S
	8401170401*	50-320 G		8401300312	50-366 S
	8401170539	71-6346		8401300327	50-366 S
	8401180259	50-219 P		8401310123	50-321 P
	8401180264*	50-219 P		8401310309	50-321 P
	8401190372	50-289 R		8401310314*	50-321 P
	8401230335	50-289 F		8401310315	50-321 F
	8401230478	50-289 S		8401310315	50-321 F
	8401240074	50-320 S		8401310393	50-321 S
	8401240209*	50-219 G		8401310394	50-321 S
	8401240251	50-289 P		8401310398	50-366 S
	8401240489	50-219 F		8401310400	50-366 S
	8401240554	PR	Georgia, State of	8401310244	50-424 G
	8401250257	PR	Georgians Against Nuclear Energy	8401300096	50-424 G
Georgia Power Co	8401250279	50-320 P		8401300096	50-424 G
	8401250284*	50-320 P		8401300100*	50-424 G
	8401250287*	50-320 P		8401300100*	50-424 G
	8401260005	50-289 J	Gesellschaft fuer Nuklear Service, mbH	8401260523	71-9190
	8401260005	50-289 J		840126527*	71-9190
	8401260066*	50-289 F	Gatty/Petrochemicals Co	8401170455	40-6657
	8401260231	50-289 G	Gibbs & Hill, Inc (subs of Dravo Corp)	8312050393	50-584 A
	8401260302	50-320 P		8401170411*	50-440 A
	8401260401*	50-320 F	Gilbert/Commonwealth Cos	8401090370	50-440 M
	8401270190	50-289 P	Goldberg, Fieldman & Latham, P.C	8401130447*	CONTRACT
	8401270192*	50-289 P	Golder Associates	8401170512*	CONTRACT
	8401270259	50-219 R	Gould, Inc	8401100253*	GA999
	8401300078	50-289 H		8401100256*	GA999
	8401300123	50-320 R	Government Accountability Project	8401170180	FOIA
	8401300256	50-289 G		8401180008	50-328 A
	8401300308	50-289 J		8401230390	50-358 G
	8401310141	50-289 P		8401230589*	50-358 G
	8401310145*	50-289 P		8401230600*	50-358 G
	8401310219*	50-320 F		8401230609	FOIA
	8401310283	50-289 G		8401310287	50-413 G
	8312050488	50-321 G	Gulf Nuclear, Inc.	8401130063	71-9160
	8401030112	50-321 S		8401250253	PR

CORPORATE SOURCE INDEX

525

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Items Utilities Co	B312290417	50-458 E	Hodder, M H	B401310357	50-250 Q
	B401040119	50-458 S		B401310364*	50-250 Q
	B401040219	50-458 S	Honeywell, Inc	B401110374	XPORTRIC
	B401040449*	50-458 Q		B401300149*	40-7982
	B401040476	50-458 S	House of Rep	B207180008*	40-86
	B401040525	50-458 S		B208010037*	FOIA
	B401040528	50-458 E		B208010047*	FOIA
	B401040528	50-458 E		B209150025*	40-86
	B401050169	50-458 E		B401030024*	40-86
	B401050169	50-458 E		B401030033*	40-86
	B401050210	50-458 A		B401110176	50-322 U
	B401050271	50-458 A	House of Rep , Interior & Insular Affairs	B401100133*	50-413 U
	B401060291	50-458 C		B401190497*	50-397 U
	B401060291	50-458 C		B401200057*	COMMISSION
	B401090103	50-458 E		B401230011*	50-289 U
	B401090103	50-458 E		B401310172*	50-275 U
	B401090153	50-458 F	House of Rep , Science & Technology	B207110091*	40-86
	B401100146	50-459 Q	Houston Lighting & Power Co	B401030266	50-498 S
	B401100212	50-458 S		B401050238	PR
	B401100278	50-458 S		B401060302	50-498 A
	B401100450	50-458 S		B401130173	50-498 S
	B401110072	50-458 E		B401240235	50-498 Q
	B401110072	50-458 E		B401270138	50-498 S
	B401130060	50-458 S		B401270138	50-498 S
	B401130072	50-458 S		B401270240	50-498 S
	B401130139	50-458 S		B401270240	50-498 S
	B401130192	50-458 S		B401270251	50-498 S
	B401130216	50-458 S		B401270363	50-498 K
	B401130263	50-458 S		B401270363	50-498 K
	B401130277	50-458 S		B401270368*	50-498 K
	B401130286	50-458 S		B401270368*	50-498 K
	B401130311	50-458 S		B401270482	50-498 S
	B401130313	50-458 E		B401300249	50-498 Q
	B401130313	50-458 E		B401300249	50-498 Q
	B401130315	50-458 S		B401300260	50-498 Q
	B401130344	50-458 S		B401300260	50-498 Q
	B401130388	50-458 E	Hunton & Williams	B401040617	50-322 A
	B401130388	50-458 E		B401050231	50-322 Q
	B401130394	50-458 S		B401050297	50-463 Q
	B401170003	50-458 S		B401050297	50-463 Q
	B401170187	50-458 S		B401050302*	50-463 Q
	B401170203	50-458 S		B401050302*	50-463 Q
	B401170361	TOPREP		B401050307*	50-463 Q
	B401200296*	50-458 F		B401050307*	50-463 Q
	B401200300*	50-458 F		B401050320	50-322 Q
	B401230122	50-458 S		B401090295*	REVIEW ORP
	B401230164	50-458 S		B401090363	50-463 Q
	B401230168	50-458 S		B401100147	50-322 Q
	B401230265	50-458 S		B401100206	50-322 Q
	B401230276	50-458 S		B401120311	50-322 Q
	B401230297	50-458 S		B401160212	50-322 Q
	B401230922	50-458 S		B401170167	50-322 Q
	B401240122	50-458 S		B401170180	50-322 Q
	B401240127	50-458 S		B401170185	50-322 Q
	B401240218	50-458 S		B401240247	50-322 Q
	B401240231	50-458 S		B401310305	50-322 Q
	B401250203	50-458 A	Hydro-Engineering	B401310423*	40-2259
	B401250203	50-458 A	ICD Puerto Rico, Inc.	B401090487*	GA999
	B401270245	50-458 E		B401090491*	GA999
	B401270332	50-458 S		B401090493*	GA999
	B401270337	50-458 S		B401030355	NVREQ
	B401270903	50-458 S	Idaho National Engineering Laboratory	B401030197	50-461 K
	B401310241	50-458 C	Illinois Power Co.	B401030203*	50-461 K
	B401310241	50-458 C		B401030385	50-461 S
	B401310247*	50-458 C		B401050475	50-461 Q
	B401310247*	50-458 C		B401050527	50-461 Q
	B401310439	50-458 E		B401050656	50-461 S
	B401090248*	GA999		B401050669	50-461 S
	B401050309*	50-400 F		B401060433	50-461 S
Days, Inc.				B401160283	50-461 S
ciates, Inc.				B401190334	50-461 S
Oversight Committee	B401230176	WASTE MGT		B401230322	50-461 S
Weiss	B401090358	WASTE MGT		B401230345*	50-461 Q
	B401100153	50-322 Q		B401230490	50-461 A
	B401100160	WASTE MGT		B401310361	50-461 H
	B401100163*	WASTE MGT		B401310363	50-461 A
	B401110171	50-443 Q		B401050240	40-2061
	B401200105	50-443 Q	Illinois, State of	B401110273*	50-206 P
	B401240224	50-289 Q	Impell Corp.	B401110275*	50-206 P
	B401240230*	50-289 Q			
	B401250010	FOIA			
le Group	B401050242	50-261 Q		B401110277*	50-206 P
	B401050283	50-261 Q	Indiana & Michigan Electric Co	B401040193	50-315 F
	B401240075	50-261 T		B401040193	50-315 F
Co	B401060640*	CONTRACT		B401040323	50-315 S
Nuclear & Development Corp	B401130058	71-6574		B401040340	50-315 S
of Hittman Corp.)					

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401040355	50-316 S		8401180219	50-331 F
	8401040362*	50-316 S		8401240176	50-331 P
	8401040367*	50-316 S		8401240228	50-331 P
	8401050441	50-315 S		8401250059*	50-331 F
	8401050636	50-315 S		8401250294	50-331 P
	8401050678	50-315 S		8401250296*	50-331 P
	8401060305	50-315 S		8401270504	50-331 S
	8401060311*	50-315 S		8401310024	50-331 Q
	8401060315*	50-315 S	Iowa State Univ , Ames, IA	8401240270	50-116 P
	8401060425	50-316 S	Isham, Lincoln & Beale	8401050241	50-155 Q
	8401060428*	50-316 S		8401050250	50-155 Q
	8401060430*	50-316 S		8401050340	50-155 Q
	8401060434	50-316 S		8401050366	50-434 Q
	8401060435*	50-316 S		8401090366	50-329 Q
	8401060437*	50-316 S		8401090366	50-329 Q
	8401060440*	50-316 S		8401090375*	50-329 Q
	8401100340	50-315 S		8401090384*	50-329 Q
	8401120398	50-315 R		8401090384*	50-329 Q
	8401120412	50-316 R		8401100213	50-454 Q
	8401130177	50-315 S		8401240073	50-329 Q
	8401130270	50-315 Q		8401240194	50-155 Q
	8401130281	50-315 S		8401250201	50-454 Q
	8401130292	50-315 P		8401270371	50-329 Q
	8401130292	50-315 P		8401270384	50-329 Q
	8401130331	50-316 S		8401270391*	50-329 Q
	8401130336	50-315 S		8401300202	50-454 Q
	8401130336	50-315 S		8401310340	50-155 Q
	8401130337*	50-316 S	J E Edinger Associates, Inc	8401100353*	50-483 A
	8401130345*	50-316 S	JBF Associates	8401120533*	CONTRACT
	8401130349	50-315 S	Jacksonians United for Livable Energy Policies	8401180212	50-416 Q
	8401130349	50-315 S			
	8401130353*	50-316 S	Japan, Govt of	8401110342	XPOR TLIC
	8401190371	50-315 S		8401110345	XPOR TLIC
	8401190374*	50-315 S	John A Blume & Associates, Engineers	8401170153*	50-244 P
	8401190375*	50-315 S	(subs of URS Corp.)		
	8401200076	50-315 P	Joint Intervenor - Diablo Canyon	8401050221	50-275 Q
	8401200076	50-315 P		8401100159	50-275 Q
	8401230317	50-316 S		8401160204	50-275 Q
	8401230374*	50-315 Q		8401170322	50-275 Q
	8401240063	50-315 S		8401230435	50-275 Q
	8401240167	50-315 S	Joint Intervenor - Shearon Harris	8401270375	50-400 Q
	8401240183	50-316 S	Joint Petitioners - TMI	8401260116	50-289 Q
	8401240191*	50-316 S			
	8401240202*	50-316 S	Jones, Brown & Clifford	8401310146	50-133 Q
	8401240406	50-315 F	Justice, Dept of	8401110328*	50-289 U
	8401250028	50-315 P		8401310068*	CONTRACT
	8401250028	50-315 P		8401030117*	40-86
	8401250033*	50-315 P	Justice, Dept of, Attorney General, Office of		
	8401250033*	50-315 P	K-C Industries, Inc	8401100096	XPOR TLIC
	8401250130*	50-315 F			
	8401260244*	50-315 F	Kansas Gas & Electric Co	8401030152	50-482 Q
	8401260244*	50-315 F		8401030155	50-482 T
	8401270446	50-315 R		8401030158	50-482 Q
	8401270477	50-316 R		8401030183	50-482 Q
	8401300195	50-316 S		8401030272	50-482 A
	8401300198*	50-316 S		8401050070*	50-482 F
	8401300201*	50-316 S		8401100330	50-482 S
	8401300242	50-315 S		8401100405	50-482 A
	8401300243*	50-315 S		8401100410*	50-482 A
	8401300245*	50-315 S		8401100439	50-482 S
	8401300245*	50-315 S			
	8401300245*	50-315 S		8401130172*	50-482 Q
	8401300257	50-316 S		8401130328	50-482 S
	8401310050	50-316 S		8401160251	50-482 Q
	8401310301	50-315 S		8401170213	50-482 A
	8401310301	50-315 S		8401170398*	50-482 Q
	8401310406	50-315 S			
	8401310409*	50-315 S		8401180114	50-482 A
	8401310414*	50-315 S		8401230447	50-482 S
	8401090459*	CONTRACT		8401270189	50-482 S
	8401120558*	CONTRACT		8401270490	50-482 Q
	8401200304	27-47		8401170340	50-148 P
	8401300092	WASTE MGT			
	8401310310	50-274 R		8401170344*	50-148 P
	8401120592*	CONTRACT		8401050153*	CONTRACT
	8312290259	50-331 F		8401100120	40-2061
	8401050238	PR			
	8401050451	50-331 S		8401230451	40-2061
	8401050466	50-331 S		8401230452*	40-2061
	8401050566	50-331 S			
	8401090265	50-331 F		8401230460*	40-2061
	8401090275*	50-331 F		8401230554	40-2061
	8401090280*	50-331 F		8401230558*	40-2061
	8401100305*	50-331 Q		8401160103	40-2061
	8401120423	50-331 S		8401250139*	70-712
	8401180117	50-331 R			
				8401250146*	40-1478
				8401250150*	40-1478
				8401250153*	40-1478
				8401250157*	40-1478
				8401090205	40-8768
				8401090214*	40-8768

Information Systems & Network Corp
Intel Corp

Interior, Dept of, Geological Survey

International Energy Associates, Ltd,
Iowa Electric Light & Power Co.

Kansas, Univ of, Lawrence, KS

Kentucky, Univ. of, Lexington, KY
Kerr-McGee Chemical Corp (subs of
Kerr-McGee Corp)

Kerr-McGee Corp

Kerr-McGee Nuclear Corp.

CORPORATE SOURCE INDEX

527

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pyle & Anderson Philip Patrick, Lockhart, Hill, Christopher J Phillips	8401230044	40-8768		8401170201	50-382 S
	8401230328*	70-925		8401180172	50-382 K
	8401110411*	MISC		8401180175*	50-382 K
	8401030148	50-322 Q		8401180227	50-382 Q
	8401160244	50-322 Q		8401180231*	50-382 Q
	8401170229	50-322 Q		8401200046	50-382 F
	8401170276*	50-322 Q		8401200308*	50-382 F
	8401180288*	50-322 T		8401230223	50-382 S
	8401200132	50-322 Q		8401230348	50-382 S
	8401240289	50-322 Q		8401230363	50-382 K
Libr. Dept of Lawrence Livermore Laboratory	8401250167	50-322 Q		8401230421	50-382 E
	8401260184	50-322 Q		8401230530	50-382 S
	8401260189*	50-322 Q		8401240094	50-382 S
	8401310284	50-322 Q		8401240128	50-382 S
	8401310285*	50-322 Q		8401240453	50-382 S
	8401300152	MISC		8401240469	50-382 S
	8306140082*	50-254 P		8401240505	50-382 S
	8307190298*	50-220 P		8401240530	50-382 S
	8312140428*	50-313 P		8401270071	50-382 S
	8401050260	PR		8401270076	50-382 S
LeibowP, Lamb, Leiby & MacRae	8401260223	50-546 Q		8401270327*	50-382 Q
	8401270378	50-454 Q		8401270331*	50-382 Q
	8401300261	50-454 Q		8401270500	50-382 S
	8401040372	50-352 H		8401300305	50-382 F
	8401090482	PRM		8401310325	50-382 E
	8401100205	50-289 Q		8401260159	50-352 Q
	8401100223	50-289 Q		8401300249	50-498 Q
	8401180238	50-289 Q		8401060370	50-322 Q
	8401100292	50-352 H		8401030310*	CONTRACT
	8401030239	50-322 S		8401230337*	50-289 F
Lieberich, PA Long Island Lighting Co	8401030337*	50-322 F	Love, A R Lowenstein, Newman, Reis, Axelrad & Toll MHB Technical Associates MPR Associates, Inc	8401030365*	50-309 F
	8401030339*	50-322 F		8401030367*	50-309 F
	8401030341*	50-322 F		8401040317	50-309 P
	8401040015*	50-322 F		8401050258	50-309 S
	8401040018*	50-322 F		8401100288	50-309 S
	8401040020*	50-322 F		8401100348	50-309 S
	8401040574*	50-322 Q		8401100414	50-309 V
	8401050128*	50-322 F		8401120299	50-309 R
	8401050132*	50-322 F		8401160143	50-309 F
	8401050231	50-322 Q		8401160159	50-309 P
	8401030320	50-322 Q	Maine Yankee Atomic Power Co	8401160269	50-309 P
	8401050505	50-322 A		8401170287	50-309 P
	8401060386	50-322 Q		8401170399*	50-309 Q
	8401090358	50-322 F		8401190129*	50-309 Q
	8401100147	50-322 Q		8401230121	50-309 F
	8401100153	50-322 Q		8401230455	50-309 S
	8401100206	50-322 Q		8401230572*	50-309 Q
	8401110240	50-322 A		8401240101	50-309 P
	8401110245*	50-322 A		8401240175	50-309 P
	8401120311	50-322 Q		8401240180*	50-309 P
	8401120359	50-322 H		8401240184	50-309 P
	8401120530	71-5739		8401240284	50-309 P
	8401160212	50-322 Q		8401240291*	50-309 P
	8401190167	50-322 Q		8401260158*	50-309 F
	8401190170*	50-322 Q		8401270261	50-309 R
	8401190180	50-322 Q		8401310304	50-309 P
	8401190185	50-322 Q	Mallinckrodt, Inc	8401050056*	FOIA
	8401240107	50-322 A		8401050060*	FOIA
	8401240249	50-322 Q		8401050068*	FOIA
	8401240388	50-322 A		8401050071*	FOIA
	8401240411	50-322 E		8401050073*	FOIA
	8401240548	50-322 V		8401050076*	FOIA
	8401250131*	50-322 F		8401050078*	FOIA
	8401250155*	50-322 F		8401050080*	FOIA
	8401310305	50-322 Q		8401050082*	FOIA
	8401030323*	50-317 P		8401050083*	FOIA
Los Alamos Scientific Laboratory	8401090113	50-537 E		8401050091*	FOIA
	8401270123	50-413 A		8401050095*	FOIA
	8401310512	ACRS		8401050100*	FOIA
	8401310513	50-327 Q		8401050103*	FOIA
	8202020366*	50-382 F		8401050106*	FOIA
	8401030067	50-382 S		8401050109*	FOIA
	8401030232	50-382 S		8401050113*	FOIA
	8401040210	50-382 A		8401050117*	FOIA
	8401040632*	50-382 F		8401050120*	FOIA
	8401040633*	50-382 F		8401050123*	FOIA
Louisiana Power & Light Co	8401050185	PR		8401050127*	FOIA
	8401100184	50-382 S		8401050130*	FOIA
	8401100266	50-382 S		8401050133*	FOIA
	8401100282	50-382 S		8401050137*	FOIA
	8401130247	50-382 S		8401050138*	FOIA
	8401130282	50-382 S		8401050143*	FOIA
	8401130316	50-382 S		8401100090*	FOIA
	8401170199	50-382 S		8401100102*	FOIA
				8401100105*	FOIA

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B401100109*	FOIA		B401030220	50-416 S
	B401100111*	FOIA		B401030233	50-416 S
	B401100116*	FOIA		B401060165*	50-416 F
	B401100118*	FOIA		B401060171*	50-416 F
Manhattan College, Riverdale, NY	B401130265	50-199 V		B401060312	50-416 S
Marsh & McLennan, Inc	B401050167	TOPREP		B401060325	50-416 S
	B401050269	50-321 J		B401060421	50-416 S
	B401050269	50-321 J		B401060456	50-416 K
	B401050287	50-286 J		B401060477	50-416 S
	B401060044	50-315 J		B401090380*	50-416 Q
	B401060242	50-346 J		B401100336	50-416 P
	B401060247	50-29 J		B401100371	50-416 P
	B401060252	50-293 J		B401100371	50-416 P
	B401060262	50-29 J		B401100411	50-416 S
	B401060269	TOPREP		B401100478	50-416 P
	B401100240	50-413 J		B401120350	50-416 S
	B401110001	50-397 J		B401130240	50-416 P
	B401130016	50-213 J		B401170376	50-416 S
	B401130130	50-213 J		B401180079	50-416 V
	B401130130	50-213 J		B401180079	50-416 V
	B401130130	50-213 J		B401200001	50-416 P
	B401130130	50-213 J		B401200003*	50-416 P
	B401200039	TOPREP		B401200157	50-416 P
	B401200056	50-397 J		B401200157	50-416 P
	B401200069	50-397 J		B401240160	50-416 S
	B401200149	TOPREP		B401240385	50-416 S
	B401230477	50-245 J		B401240450	50-416 S
Maryland, State of	B401060482	50-352 D		B401240455	50-416 S
Maryland, Univ of, College Park, MD	B401160142	State Prog		B401240491	50-416 S
	B312220138	50-166 P		B401250023	50-416 P
Massachusetts Institute of Technology, Cambridge, MA	B401240395	50-20 F		B401250250	50-416 P
	B401250122*	CONTRACT		B401250250	50-416 P
Materials Engineering Associates, Inc	B401130037*	CONTRACT		B401250295	50-416 P
Metropolitan Edison Co	B312050118	50-289 Q		B401250295	50-416 P
	B312160014	50-261 Q		B401260018	50-416 S
	B312200353	50-289 Q		B401260031	50-416 S
	B312200359*	50-289 Q		B401260088	50-416 S
	B401030087	50-289 Q		B401260286*	50-416 F
	B401060158*	50-289 F		B401260338	50-416 S
	B401100139	50-289 Q		B401270264	50-416 R
	B401110232	50-289 Q		B401300122	50-416 Q
	B401120264	50-289 Q		B401300175	50-416 S
	B401120269*	50-289 Q		B401300179	50-416 S
	B401120282*	50-289 Q		B401300220	50-416 S
	B401160256	50-289 Q		B401300234	50-416 S
	B401170231	50-289 Q		B401300239	50-416 S
	B401170253	50-289 Q		B401300263	50-416 S
	B401170255*	50-289 Q		B401300284	50-416 S
	B401200156	50-289 Q	Mississippi, State of	B401050223	PRM
	B401240169	50-289 Q		B401120298	WASTE MGT
	B401260124	50-289 Q		B401170392	50-416 P
	B401260190	50-289 Q	Missouri, Univ. of, Columbia, MO	B401250128	50-186 S
	B401260202	50-289 Q	Missouri, Univ of, Rolla, MO	B401120268	50-123 S
	B401260207*	50-289 Q	Mitsubishi International Corp (subs of Mitsubishi Corp)	B401110334	XPORTLIC
	B401260217*	50-320 F	Mitsui & Co (USA), Inc (subs of Mitsui & Co, Ltd)	B401060472	XPORTLIC
	B401260238*	50-320 F		B401110382	XPORTLIC
	B401260271*	50-289 F		B401250239	PR
	B401300240	50-289 Q	Montana, State of	B401240212*	50-302 R
	B401300333*	50-289 F	Naval Marine Laboratory	B401100122	WASTE MGT
	B401300367*	50-320 F	Murphy & Davenport	B401100129*	WASTE MGT
	B401310218	50-289 Q		B401110222	WASTE MGT
	B401310258	50-289 Q		B401300264	50-280 J
	B401310329	50-289 Q	Mutual Atomic Energy Liability Underwriters		
Miami Valley Power Project	B401050282	50-358 Q	NL Industries, Inc	B004280166	71-9010
	B401050609*	50-358 A		B401190077*	71-9010
	B401230390	50-358 Q	NUS Corp.	B401040221	FOIA
	B401230399*	50-358 Q		B401050064	50-237 S
	B401230600*	50-358 Q		B401160360	FOIA
Michigan, State of	B401050031*	50-329 F		B401160436	FOIA
Michigan, Univ. of, Medical School	B401180169	PR		B401160448	FOIA
	B401090341	PR		B401170125	FOIA
Middle South Services, Inc	B401090354	PR		B401170135	FOIA
	B401100248	50-416 H		B401300012*	CONTRACT
	B401100248	50-416 H		B401030345*	CONTRACT
	B401120191	50-416 H		B401300154*	CONTRACT
	B401120191	50-416 H		B401190356*	CONTRACT
Milton S. HERSHEY Medical Center, Hershey, PA	B401110309*	50-289 Q	NUSAC, Inc.		
Minnesota, State of	B401100142	WASTE MGT	National Academy of Sciences		
	B401100143*	WASTE MGT	National Aeronautics & Space Admin.		
	B401240188	WASTE MGT		B401100232	WASTE MGT
Minnesota, Univ. of, Minneapolis, MN	B401030370	NUREG	National Parks Association	B401090353	50-289 Q
	B401030083	50-416 S	Naval, Dept. of	B401180207	PR
	B401030194	50-416 S	Naval, Dept. of, Naval Sea Systems Command	B401310403	PR
	B401030215	50-416 S	Nebraska Public Power District	B401120401	50-298 R
				B401230645*	50-298 F
				B401230647*	50-298 F

CORPORATE SOURCE INDEX

529

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401240007	50-298 J		8401230574*	50-220 F
	8401240189	50-298 P		8401230578*	50-220 F
	8401260194*	50-298 F		8401230583*	50-220 F
	8401260198*	50-298 F		8401240100	50-410 A
	8401270083	50-298 F		8401240135	50-220 P
	8401270085*	50-298 P		8401240183	50-220 P
	8401270475	50-298 R		8401250097	50-220 F
	8401300272*	50-298 F		8401270092	50-410 A
	8401300375*	50-298 F		8401270108	50-410 S
Pauka, State of	8401060257*	40-8829		8401270133	50-220 S
	8401100129*	WASTE MGT		8401270449	50-410 S
	8401110500	40-8829	North Carolina Municipal Power Agencies	8401060318	50-400 Q
	8401170247	WASTE MGT	North Carolina State Univ., Raleigh, NC	8401100154	50-297 H
tron Products, Inc.	8401310469	40-8829	North Shore Committee Against Nuclear & Thermal Pollution	8401170276	50-322 Q
	8401230359*	QA999	Northeast Nuclear Energy Co (subs of Northeast Utilities)	8311280178	50-423 K
	8401230364*	QA999		8312300176	50-336 S
ide, State of	8401110222	WASTE MGT		8312300205	50-213 F
England Coalition on Nuclear Pollution	8401110226*	WASTE MGT		8401040086	50-245 P
	8401110171	50-443 Q		8401040138	50-245 S
	8401200105	50-443 Q		8401040178	50-245 S
Hampshire, State of	8401100213	50-443 Q		8401040183	50-336 S
	8401240250	50-443 Q		8401060045	50-423 A
Jersey, State of	8401030070*	40-86		8401060468	50-423 A
	8401030105*	40-86		8401090132	50-213 F
	8401030188*	40-86		8401100007	50-245 S
	8401030191*	40-86		8401100333	50-245 P
	8401040162*	40-86		8401100338*	50-245 P
	8401110260	50-219 P		8401100352	50-336 S
	8401170327*	50-354 A		8401100392	50-213 P
	8401260183	50-354 Q		8401100392	50-213 P
Mexico, Univ. of, Albuquerque, NM	8401250055*	50-252 F		8401100423	50-245 S
Yert, State of	8401050316*	50-247 F		8401120196	50-336 R
	8401170150	50-322 Q		8401120203	50-245 R
	8401180198	50-322 Q		8401120312	50-336 S
	8401200218*	COMMISSION		8401130354	50-423 A
	8401300141*	CONTRACT		8401160147	50-336 P
	8401310140	50-322 Q		8401160174	50-423 S
Yert, State of, Atomic Energy Council	8401180265*	50-244 Q		8401170551	50-336 S
Yert, State of, Energy Office	8401180261	50-244 Q		8401170529	50-336 P
man & Holtzinger	8401050238	PR		8401170379	50-336 P
	8401110297	50-537 Q		8401170435	50-336 P
	8401170271	50-70 Q		8401180204	50-245 F
	8401170271	50-70 Q		8401180204	50-245 F
	8401170309	50-70 Q		8401180270*	50-245 Q
	8401170309	50-70 Q		8401200163	50-336 P
	8401300260	50-498 Q		8401200164	50-213 P
agara Mohawk Power Corp	8401310235	50-70 Q		8401200165*	50-336 P
	8312280405	50-220 K		8401230175	50-423 K
	8312280405	50-220 K		8401230178	50-245 P
	8401030121	50-220 S		8401230178	50-245 P
	8401030196	50-220 P		8401230184*	50-423 K
	8401030238	50-410 B		8401230323	50-423 A
	8401030260	50-220 S		8401230373	50-213 P
	8401030263*	50-220 B		8401230467	50-423 F
	8401030263*	50-220 S		8401260324*	50-245 F
	8401040081	50-410 C		8401270360	50-336 P
	8401040479	50-410 A		8401270442	50-245 R
	8401040495	50-410 Q		8401270457	50-336 R
	8401090239	50-220 F		8401300137	50-245 S
	8401090326	50-220 F		8401300171	50-245 P
	8401100361	50-220 P		8401310023	50-336 P
	8401100364*	50-220 P		8311280178	50-423 K
	8401100381*	50-410 Q	Northeast Utilities	8312060402*	50-423 K
	8401130067	50-220 P		8312060405*	50-423 K
	8401130071*	50-220 P		8312300176	50-336 S
	8401130074*	50-220 P		8312300205	50-213 F
	8401130291	50-220 S		8401040086	50-245 P
	8401130321	50-410 S		8401040178	50-245 S
	8401130342	50-410 S		8401040183	50-336 S
	8401160100	50-410 S		8401060265	50-423 V
	8401160160	50-220 S		8401050273	50-423 A
	8401160168	50-220 R		8401050314	50-423 A
	8401170007	50-220 S		8401060045	50-423 A
	8401180226	50-220 P		8401060468	50-423 A
	8401180229*	50-220 P		8401090132	50-213 F
	8401190365	50-220 P		8401100007	50-245 S
	8401190366*	50-220 P		8401100333	50-245 P
	8401190369*	50-220 P		8401100352	50-336 S
	8401190373*	50-410 Q		8401100392	50-213 P
	8401230006	50-220 J		8401100392	50-213 P
	8401230308	50-220 P		8401100423	50-245 S
	8401230314*	50-220 P		8401100429	50-423 A
	8401230318*	50-220 P		8401120196	50-336 R
	8401230486	50-220 J			

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401120203	50-245 R	Norwalk Hosp , Norwalk, CT	8401030076*	40-86
	8401120312	50-336 S	Nuclear Awareness Network	8401180258	50-482 Q
	8401130364	50-423 A	Nuclear Energy Liability Insurance	8401300264	50-280 J
	8401160147	50-336 P	Association		
	8401160174	50-423 S	Nuclear Fuel Services, Inc (subs of Getty Oil Co)	8312080260	70-143
				8401120145	70-143
	8401170251	50-336 S			
	8401170329	50-336 P		8401240338*	70-143
	8401170379	50-336 P		8401250298*	70-143
	8401170435	50-336 P		8401250300*	70-143
	8401180204	50-245 F		8401100351*	40-672
				8401130068	71-9181
	8401180204	50-245 F	Nuclear Metals, Inc		
	8401180270*	50-245 Q	Nuclear Packaging, Inc		
	8401200163	50-336 P		8401050038	FDIA
	8401230173	50-423 K	Nuclear Pharmacy, Inc	8401270308*	QA999
	8401230178	50-245 P	Nuclear Qualification Services	8401270310*	QA999
				8401270314*	QA999
				8401270317*	QA999
	8401230178	50-245 P			
	8401230323	50-423 A	Nuclear System	8401060201*	CONTRACT
	8401230467	50-423 F		8401240576	FR
	8401270208	50-423 S	O'Neill, J	8401230411	50-155 T
	8401270271	TOPREF		8401300254	50-155 Q
			Oak Ridge Associated Univs	8401030054*	40-86
	8401270442	50-245 R			
	8401270457	50-336 R		8401030057*	40-86
	8401300137	50-245 S		8401030102*	40-86
	8401300171	50-245 P		8401230157	MISC
	8401310023	50-336 P	Oak Ridge National Laboratory	8312270412	NUREG
				8401030097*	40-86
Northeast Utilities Service Co (subs of Northwest Utilities)	8401040158	50-245 S			
				8401030350	NUREG
	8401050273	50-423 A		8401030443	NUREG
	8401050314	50-423 A		8401180072	NUREG
Northern States Power Co	8401200164	50-213 P		8401230039	NUREG
	8401050411	50-282 S		8401230066	NUREG
	8401050442	50-282 S		8401230690	NUREG
	8401060230	50-282 P		8401260101	NUREG
	8401060230	50-282 P		8401300018	NUREG
	8401060354	50-263 R	Office of Management & Budget	8401070680	DRG
	8401090321	50-263 F		8401070683	DRG
	8401090328*	50-263 F		8401090689	DRG
	8401100180	50-282 P		8401100490	DRG
	8401120240	50-282 R		8401310177*	COMMISSION
	8401120314	50-282 X	Ogle Petroleum, Inc	8401110383	40-8743
	8401120373	50-263 S		8401270160	40-8745
	8401120377	50-263 R			
	8401120406	50-263 Q	Ohio Citizens for Responsible Energy	8401060358	50-440 Q
	8401130082	50-263 F		8401100140	50-440 Q
	8401130187	50-263 P		8401160385	50-440 A
	8401160128	50-282 Q		8401240333	50-440 Q
				8401050131*	CONTRACT
	8401160135*	50-282 Q			
	8401170314	50-263 X	Ohio, State of	8401170032	50-440 A
	8401170353	50-282 Q		8401240539	50-358 R
	8401170355*	50-282 Q	Oklahoma, Univ of, Norman, OK	8401260240*	50-112 F
	8401170374	50-263 P	Omaha Public Power District	8401040233	50-285 P
				8401040290	50-285 P
	8401180111	50-282 P		8401040293*	50-285 P
	8401190387	50-282 P		8401050085*	50-285 S
	8401190387	50-282 P		8401100329	50-285 P
	8401190392*	50-282 P		8401100426	50-285 P
	8401190392*	50-282 P		8401170158	50-285 Q
	8401190394*	50-282 P		8401170159*	50-285 Q
	8401190394*	50-282 P		8401230131	50-285 F
	8401200081	50-282 Q		8401230317	50-285 S
	8401200081	50-282 Q		8401230360	50-285 S
	8401200083*	50-282 Q		8401230022*	50-285 F
	8401230216	50-263 P		8401250025*	50-285 F
	8401240431	50-282 P		8401250054*	50-285 F
	8401250096*	50-263 F		8401260008	50-285 J
	8401270054	50-263 J		8401260041*	50-285 F
	8401270054	50-263 J		8401300157	50-285 F
	8401270397	50-263 R		8401310198*	50-285 F
	8401270452	50-282 R		8401310202*	50-285 F
	8401310263*	50-263 F		8401310242	50-285 V
	8401310263*	50-263 F		8401310302	50-285 P
	8401310263*	50-263 F			
			On-Line Computer Systems, Inc	8401060223*	CONTRACT
	8401310263*	50-263 F			
	8401310271*	50-263 F	Oregon State Univ , Corvallis, OR	8401100314	50-243 P
	8401310271*	50-263 F		8401110234	50-344 Q
	8401310271*	50-263 F	Oregon, State of	8312210245	50-275 S
	8401310271*	50-263 F	Pacific Gas & Electric Co	8401040185	50-275 S
				8401040261	50-275 S
	8401310335	50-282 F		8401040308	50-275 S
	8401310335	50-282 F		8401040348	50-275 S
Northern Telecom	8401160440	FDIA		8401040567	50-275 P
Northrop Research & Technical Center	8401060008	50-187 R		8401060002	50-275 P
Norton, Burke, Berry & French	8401100137	50-275 Q		8401060287	50-275 P
	8401300214	50-275 Q			
	8401300214	50-275 Q		8401100137	50-275 Q
	8401300314	50-275 Q		8401100137	50-275 Q
	8401300314	50-275 Q		8401100319	50-275 P

CORPORATE SOURCE INDEX

531

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B401100387	50-275 E		B401160165	50-388 B
	B401100417	50-275 E		B401160215	50-387 E
	B401110230	50-275 J		B401160215	50-387 E
	B401120207	50-275 P		B401170291	50-387 R
	B401120212*	50-275 P		B401170338	50-387 R
	B401120374	50-133 R		B401170338	50-387 R
	B401120397	50-275 G		B401230418	50-387 F
	B401120403	50-275 R		B401240141	50-387 H
	B401160234	50-275 S		B401240141	50-387 H
	B401160234	50-275 S		B401240435	50-387 P
	B401160255	50-275 S		B401240635*	50-387 F
	B401160264	50-275 S		B401250031*	50-387 F
	B401160296	50-275 S		B401250039*	50-387 F
	B401170156	50-275 P		B401250131	50-387 P
	B401170161*	50-275 P		B401250132*	50-387 P
	B401170165*	50-275 P		B401260152*	50-387 F
	B401170211	50-275 R		B401260221	50-387 S
	B401170294	50-275 Q		B401260276	50-387 S
	B401170297	50-275 T		B401260323	50-388 S
	B401170297	50-275 T		B401260413*	50-387 F
	B401170316	50-275 H		B401260413*	50-387 F
	B401240134	50-275 P		B401260422*	50-387 F
	B401240247	50-275 E		B401260422*	50-387 F
	B401240410	50-275 F		B401270017	50-387 S
	B401240410	50-275 F		B401270079	50-387 S
	B401240503	50-275 P		B401270128	50-387 S
	B401240555	50-275 E		B401270185	50-387 S
	B401260076	50-275 J		B401270210	50-388 S
	B401260192	50-275 P		B401270301	50-387 F
	B401260192	50-275 P		B401270335	50-387 S
	B401260218	50-275 E		B401300217	50-388 A
	B401260218	50-275 E		B401310117*	50-387 F
	B401260352	50-275 S		B401310117*	50-387 F
	B401270195*	50-275 Q		B401310346	50-387 R
	B401300214	50-275 Q		B401310359	50-387 P
	B401300214	50-275 Q		B401300268	50-352 Q
	B401300218	50-272 Q		B401270212	50-289 Q
	B401300314	50-275 Q		B401270217*	50-289 Q
	B401300314	50-275 Q		B401040394*	70-2887
	B401090697	FOIA		B401030159	50-278 B
Pacific Northwest Research Center					
Palmetto Alliance	B401260132	50-413 Q		B401040091	50-352 A
	B401300190	50-413 Q		B401040091	50-352 A
	B401300190	50-413 Q		B401040295	50-352 Q
	B401300194*	50-413 Q		B401040295	50-352 Q
	B401300194*	50-413 Q		B401040300*	50-352 Q
	B401300197*	50-413 Q		B401040300*	50-352 Q
	B401310323	50-413 Q		B401050077*	50-277 F-
Pathfinder Mines Corp	B401110581	40-2259		B401050297	50-463 Q
	B401270099	40-2259		B401050297	50-463 Q
	B401270342	40-6622		B401050302*	50-463 Q
	B401270502	40-6622		B401050302*	50-463 Q
	B401310421	40-2259		B401050307*	50-463 Q
	B401310419	50-358 Q		B401050307*	50-463 Q
Paxton & Seasongood	B401130151	WASTE MGT		B401060290	50-352 Q
Pemberton Electromet International, Inc	B401200212*	COMMISSION		B401060290	50-352 Q
Pennsylvania Power & Light Co.	B401030144	50-388 A		B401060297	50-352 Q
	B401030184	50-387 B		B401060297	50-352 Q
	B401030202	50-387 S		B401060357	50-352 Q
	B401040142	50-388 A		B401060357	50-352 Q
	B401080266	50-387 P		B401090334	50-352 A
	B401060267	50-388 A		B401090348*	50-352 F
	B401060282	50-387 P		B401090348*	50-352 F
	B401060282	50-387 P		B401090349	FR
	B401060319	50-387 R		B401090368*	50-463 Q
	B401060319	50-387 R		B401090477	50-352 E
	B401060324*	50-387 R		B401090477	50-352 E
	B401060324*	50-387 R		B401100145	50-352 Q
	B401090367	50-388 A		B401100291	50-277 P
	B401090396	50-387 P		B401110238	50-352 Q
	B401090407*	50-387 P		B401110238	50-352 Q
	B401090417*	50-387 P		B401110303*	50-352 K
	B401090511	50-388 A		B401110303*	50-352 K
	B401100252	50-387 P		B401110308*	50-352 C
	B401100252	50-387 P		B401110308*	50-352 C
	B401120260	50-387 S		B401120360	50-277 S
	B401120320	50-387 S		B401130078	50-352 Q
	B401120327	50-387 R		B401130078	50-352 Q
	B401130145	50-387 S		B401130122	50-352 Q
	B401130258	50-387 S		B401160189	50-278 S
	B401130279	50-387 S		B401170204	50-277 F
	B401160094	50-388 S		B401180183	50-352 Q
	B401160101	50-387 P		B401180183	50-352 Q
	B401160151	50-388 S		B401190195	50-352 Q
	B401160155	50-387 S		B401190301	50-352 Q
	B401160158	50-388 S		B401190301	50-352 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401190328	50-277 P		8401030235	50-333 S
	8401190404	50-277 R		8401040383	50-286 P
	8401190445	50-352 F		8401040387*	50-286 P
	8401190445	50-352 F		8401040392*	50-286 P
	8401200049	50-277 R		8401040437	50-286 P
	8401200049	50-277 R		8401050372*	50-286 F
	8401230024	50-352 A		8401050374*	50-286 F
	8401230024	50-352 A		8401100258	50-286 F
	8401230173	50-277 F		8401100264	50-286 P
	8401230173	50-277 F		8401100268*	50-286 P
	8401230189	50-352 S		8401100271	50-286 P
	8401230189	50-352 S		8401110069	50-286 P
	8401240091	50-352 Q		8401120214	50-333 S
	8401240091	50-352 Q		8401120230	50-286 R
	8401240146	50-352 Q		8401120242	50-333 S
	8401240146	50-352 Q		8401130274	50-333 R
	8401240174	50-352 Q		8401130359	50-333 S
	8401240174	50-352 Q		8401160032	50-333 S
	8401240181*	50-352 Q		8401160098	50-333 S
	8401240181*	50-352 Q		8401160182	50-333 S
	8401240201	50-277 Q		8401180241	50-333 P
	8401240244	50-352 A		8401230255	50-333 P
	8401240322	50-352 Q		8401240340	50-286 R
	8401240322	50-352 Q		8401240617*	50-286 F
	8401240328	50-354 Q		8401260311	50-333 P
	8401240456	50-352 A		8401270139	50-333 S
	8401240460*	50-352 A		8401270222	50-333 P
	8401250064*	50-277 F		8401270224*	50-333 P
	8401250066*	50-277 F		8401270227*	50-333 P
	8401250234	50-352 F		8401270267	50-286 R
	8401250234	50-352 F		8401270303	50-333 S
	8401260195	50-463 Q		8401270429	50-333 S
	8401260239	50-352 S		8401270440	50-333 P
	8401260303	50-352 S		8401300163	50-333 P
	8401260328	50-277 S		8401300247	50-333 S
	8401260372	50-352 S	Power Breakers, Inc	8401130042*	QA999
	8401260372	50-352 S		8401130046*	QA999
	8401270215	50-352 S		8401130055*	QA999
	8401270215	50-352 S	Professional Loss Control, Inc	8401090485*	50-352 E
	8401270236	50-278 Q		8401090490*	50-352 E
	8401270474	50-277 P		8401090494*	50-352 E
	8401300211	50-352 Q		8401090494*	50-352 E
	8401300211	50-352 Q		8401090599*	50-352 E
	8401300226	50-352 C		8401090609*	50-352 E
	8401300226	50-352 C		8401090619*	50-352 E
	8401310153	50-277 P		8401090631*	50-352 E
	8401310153	50-277 P		8401090631*	50-352 E
	8401310157*	50-277 P		8401090632*	50-352 E
	8401310157*	50-277 P		8401090636*	50-352 E
	8401310272*	50-277 Q		8401090636*	50-352 E
	8401310320	50-352 Q		8401090637*	50-352 E
	8401310320	50-352 Q		8401090638*	50-352 E
	8401310395	50-352 C		8401090641*	50-352 E
	8401310395	50-352 C		8401090641*	50-352 E
	8401320095	50-352 Q		8401090642*	50-352 E
Philadelphia, PA	8401270203	50-352 G		8401090646*	50-352 E
	8401100138*	CONTRACT		8401090650*	50-352 E
Planning Research Corp.	8401030106	50-344 P		8401090654*	50-352 E
Portland General Electric Co.	8401030113*	50-344 P		8401090657*	50-352 E
	8401040587	50-344 P		8401090657*	50-352 E
	8401050050*	50-344 F		8401090658*	50-352 E
	8401050058*	50-344 F		8401090661*	50-352 E
	8401050330	50-344 P		8401090661*	50-352 E
	8401100273	PR		8401090665*	50-352 E
	8401100471	REVIEW GRP		8401090666*	50-352 E
	8401120321	50-344 S		8401090668*	50-352 E
	8401120408	50-344 S		8401090671*	50-352 E
	8401120416	50-344 R		8401090671*	50-352 E
	8401160282	50-344 S		8401090672*	50-352 E
	8401160304	50-344 S		8401090672*	50-352 E
	8401240118	50-344 P		8401090674*	50-352 E
	8401240144	50-344 P		8401090675*	50-352 E
	8401240306	50-344 Q		8401090677*	50-352 E
	8401240310*	50-344 Q		8401090679*	50-352 E
	8401240392	50-344 Q		8401090681*	50-352 E
	8401240495	50-344 F		8401090684*	50-352 E
	8401270346	50-344 P		8401090684*	50-352 E
	8401270431	50-344 P		8401090687*	50-352 E
	8401270434*	50-344 P		8401090687*	50-352 E
	8401270437*	50-344 P		8401090688*	50-352 E
	8401270476	50-344 R		8401090691*	50-352 E
	8401310087	50-344 P		8401090691*	50-352 E
	8401310093*	50-344 P		8401090692*	50-352 E
	8401310097*	50-344 P		8401090695*	50-352 E
Power Authority of the State of New York	8312200359	50-286 P		8401090695*	50-352 E

CORPORATE SOURCE INDEX

533

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401070698*	50-352 E		8401060136*	50-272 F
	8401070701*	50-352 E		8401060136*	50-272 F
	8401070701*	50-352 E		8401060277*	50-354 Q
	8401190452*	50-352 F		8401060412*	50-354 A
	8401190457*	50-352 F		8401060486*	50-354 A
	8401190462*	50-352 F		8401060493*	50-354 A
	8401190466*	50-352 F		8401100010*	50-272 B
	8401190466*	50-352 F		8401100136*	50-354 Q
	8401190475*	50-352 F		8401100225*	50-354 Q
	8401190475*	50-352 F		8401100301*	50-272 P
	8401190478*	50-352 F		8401100301*	50-272 P
	8401190478*	50-352 F		8401100317*	50-272 P
	8401190483*	50-352 F		8401100317*	50-272 P
	8401190483*	50-352 F		8401100419*	50-272 Q
	8401190486*	50-352 F		8401100419*	50-272 Q
	8401190486*	50-352 F		8401110094*	50-272 P
	8401190489*	50-352 F		8401110149*	50-272 F
Project Management Corp	8401190489*	50-352 F		8401110153*	50-272 F
	8401100149*	50-537 Q		8401110153*	50-272 F
	8401110297*	50-537 Q		8401110208*	50-354 Q
Public Service Co of Colorado	8401100151*	50-267 Q		8401110210*	50-354 Q
	8401100313*	50-267 Q		8401120317*	50-354 Q
	8401100337*	50-267 S		8401130134*	50-272 Q
	8401130080*	50-267 P		8401130143*	50-272 Q
	8401130085*	50-267 P		8401130214*	50-272 Q
	8401130261*	50-267 P		8401130256*	50-272 B
	8401130288*	50-267 P		8401130285*	50-311 B
	8401130293*	50-267 Q		8401130320*	50-311 B
	8401130306*	50-267 S		8401130329*	50-272 B
	8401130390*	50-267 P		8401130333*	50-311 B
	8401130396*	50-267 P		8401160186*	50-272 F
	8401130400*	50-267 P		8401170323*	50-354 A
	8401170193*	50-267 S		8401170413*	50-354 A
	8401180194*	50-267 R		8401200185*	50-272 F
	8401190417*	50-267 Q		8401200185*	50-272 F
	8401230186*	50-267 S		8401200215*	50-272 P
	8401230445*	50-267 P		8401200215*	50-272 P
	8401230479*	50-267 P		8401230004*	50-311 R
	8401270140*	50-267 P		8401230461*	50-272 Q
	8401270145*	50-267 P		8401230461*	50-272 Q
	8401270151*	50-267 P		8401240002*	50-311 B
	8401270180*	50-267 P		8401240117*	50-272 R
	8401270203*	50-267 V		8401240628*	50-272 Q
	8401270248*	50-267 S		8401240628*	50-272 Q
	8401270393*	50-267 P		8401270087*	50-272 S
	8401270400*	50-267 P		8401270150*	50-272 B
	8401270441*	50-267 P		8401270294*	50-354 Q
Public Service Co of Indiana, Inc	8401270480*	50-267 P		8401270464*	50-272 B
	8401050576*	50-546 S		8401310265*	50-272 R
	8401130301*	50-546 Q		8401310268*	50-272 R
	8401260223*	50-546 Q		8401310353*	50-272 R
Public Service Co of New Hampshire	8401300229*	50-546 Q	Pullman, Inc.	8401070526*	QA999
	8312260113*	50-443 S		8401070532*	QA999
	8401030109*	50-443 Q	Purdue Univ, West Lafayette, IN	8401160402*	FOIA
	8401030109*	50-443 Q		8401160407*	FOIA
	8401030136*	50-443 Q		8401260197*	CONTRACT
	8401030136*	50-443 Q		8401110313*	50-352 A
	8401030141*	50-443 Q	Quadrex Corp	8401180016*	CONTRACT
	8401030141*	50-443 Q	R&D Associates	8401040488*	QA999
	8401030150*	50-443 Q	Radiation Sterilizers, Inc	8401040498*	QA999
	8401030150*	50-443 Q		8401030014*	40-B6
	8401070272*	50-443 Q	Record, Hackensack, NJ	8401030340*	NUREG
	8401070272*	50-443 Q	Rensselaer Polytechnic Institute, Troy, NY		
	8401070281*	50-443 Q		8401250134*	NUREG
	8401070281*	50-443 Q	Research Dynamics, Inc	8401230383*	QA999
	8401100207*	50-443 E		8401230386*	QA999
	8401100207*	50-443 E			
	8401100328*	50-443 Q	Reuter-Stokes, Inc.	8401060379*	XPORTLIC
	840110287*	50-443 A		8401060476*	XPORTLIC
	840110287*	50-443 A		8401070058*	XPORTLIC
	8401170343*	50-443 A		8401100437*	QA999
	8401170343*	50-443 A		8401100453*	QA999
	8401230343*	50-443 A		8401100467*	QA999
	8401230343*	50-443 A		8401100477*	QA999
	8401230343*	50-443 A		8401110340*	XPORTLIC
	8401230382*	50-443 Q		8401110351*	XPORTLIC
	8401230382*	50-443 Q		8401120133*	XPORTLIC
	8401230474*	50-443 F	Riley, J.L.	8401260132*	50-413 Q
	8401230474*	50-443 F	Rio Algom, Ltd	8401060633*	40-B084
	8401230500*	50-443 F	Robert L. Cloud Associates, Inc	8401110053*	50-273 R
	8401230500*	50-443 F		8401110058*	50-273 R
Public Service Electric & Gas Co. of New Jersey	8401040175*	50-272 P	Rochester Gas & Electric Corp	8401040137*	50-244 P
	8401040203*	50-272 P		8401040174*	50-244 F
	8401060127*	50-272 F		8401040346*	50-244 P
	8401060127*	50-272 F		8401040348*	50-244 P
				8401040350*	50-244 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Rockwell International Corp	8401040513	50-244 P	Savannah River Laboratory	8401170035*	FOIA
	8401060077*	50-244 F		8401260079	NUREG
	8401100356	50-244 P		8401300101*	WASTE MGT
	8401120411	50-244 R		8401310455*	WASTE MGT
	8401170009	50-244 P		8401090606	NUREG
	8401170152	50-244 P		8401300251	50-146 S
	8401170362*	50-244 Q		8401060222*	CONTRACT
	8401230227	50-244 P		8401110022*	CONTRACT
	8401250016	50-244 P		8308190529*	ACRS
	8401250019*	50-244 P		8401030364	50-245 P
	8401250021*	50-244 P		8401040530	TOPREP
	8401250095*	50-244 F		8401050436*	50-29 P
	8401250100*	50-244 F		8401100025*	FOIA
	8401250104	50-244 F		8401100030*	FOIA
	8401250109*	50-244 F		8401100037*	FOIA
	8401250260	50-244 P		8401100040*	FOIA
	8401250275*	50-244 P		8401230423	50-443 Q
	8401250282*	50-244 P		8206130010*	FOIA
	8401250287	50-244 P		8206130011*	FOIA
	8401250292*	50-244 P		8401060391	50-289 U
	8401250293*	50-244 P		8401110329*	50-289 U
	8401250297	50-244 P		8401050268	PRM
	8401250297*	50-244 P		8401120244	WASTE MGT
	8401250301*	50-244 P		8312050118	50-289 Q
	8401270292	50-244 R		8312160014	50-261 Q
	8401300132	50-244 H		8312200353	50-289 Q
	8401310212*	50-244 F		8312200357*	50-289 Q
	8401310249*	50-244 F		8401030087	50-289 Q
	8401170502	WASTE MGT		8401030152	50-482 Q
	8401170545	WASTE MGT		8401030153	50-412 Q
Ropes & Gray	8401170547	WASTE MGT		8401030158	50-482 Q
	8401180024*	CONTRACT		8401030163	50-482 Q
	8401190031	WASTE MGT		8401050175	PR
	8401190471*	CONTRACT		8401050304	50-400 Q
	8401190515*	WASTE MGT		8401060031	FOIA
	8401270535*	WASTE MGT		8401060280	50-400 Q
	8401030109	50-443 Q		8401060280	50-400 Q
	8401030109	50-443 Q		8401060318	50-400 Q
	8401030136	50-443 Q		8401060318	50-400 Q
	8401030136	50-443 Q		8401100120	40-2061
Rowe Associates Ruskin Manufacturing Co B. Levy, Inc.	8401030141*	50-443 Q	Serious Texans Against Nuclear Dumping	8401100139	50-289 Q
	8401030141*	50-443 Q		8401100217	50-400 Q
	8401030150	50-443 Q		8401110159	50-440 Q
	8401030150	50-443 Q		8401110214	50-400 Q
	8401090272	50-443 Q		8401110214	50-400 Q
	8401090272	50-443 Q		8401110224*	50-400 Q
	8401090281*	50-443 Q		8401110224*	50-400 Q
	8401090281*	50-443 Q		8401110232	50-289 Q
	8401230382	50-443 Q		8401120244	50-289 Q
	8401230382	50-443 Q		8401120269*	50-289 Q
Sacramento Municipal Utility District	8401230423	50-443 Q	Shaw, Pittman, Potts & Trowbridge	84012200353	50-289 Q
	8401230423	50-443 Q		8312200357*	50-289 Q
	8401130129*	CONTRACT		8401030087	50-289 Q
	8401040438*	QA999		8401030152	50-482 Q
	8401120569*	CONTRACT		8401030153	50-412 Q
	8401170119*	CONTRACT		8401030158	50-482 Q
	8401030134	50-312 P		8401030163	50-482 Q
	8401040144	50-312 S		8401050175	PR
	8401040214	50-312 S		8401050304	50-400 Q
	8401040539	50-312 Q		8401060031	FOIA
Safe Energy for New Haven	8401100172	50-312 F	Seacoast Anti-Pollution League Senate	8401060280	50-400 Q
	8401120318	50-312 P		8401060280	50-400 Q
	8401120353	50-312 S		8401060318	50-400 Q
	8401130206	50-312 R		8401060318	50-400 Q
	8401160240	50-312 S		8401100120	40-2061
	8401160265	50-312 S		8401100139	50-289 Q
	8401240246	50-312 P		8401100217	50-400 Q
	8401260098	50-312 S		8401110159	50-440 Q
	8401300313*	50-312 Q		8401110214	50-400 Q
	8401310261	50-312 P		8401110214	50-400 Q
Sage Energy for New Haven	8401310264*	50-312 P	Science Applications, Inc	8401110224*	50-400 Q
	8401310351	50-312 P		8401110224*	50-400 Q
	8401310355*	50-312 F		8401110232	50-289 Q
	8401270378	50-454 Q		8401120244	50-289 Q
	8401300261	50-454 Q		8401120269*	50-289 Q
	8401050242	50-261 Q		84012200353	50-289 Q
	8401050283	50-261 Q		8312200357*	50-289 Q
	8401030364	50-245 P		8401030087	50-289 Q
	8401040043	NUREG		8401030152	50-482 Q
	8401090612	NUREG		8401030153	50-412 Q
Sandia Laboratories	8401100025*	FOIA	Serious Texans Against Nuclear Dumping	8401030158	50-482 Q
	8401100075	NUREG		8401030163	50-482 Q
	8401130105	NUREG		8401050175	PR
	8401160403*	FOIA		8401050304	50-400 Q
	8401170033*	FOIA		8401060031	FOIA
	8401100025*	FOIA		8401060280	50-400 Q
	8401100075	NUREG		8401060280	50-400 Q
	8401130105	NUREG		8401060318	50-400 Q
	8401160403*	FOIA		8401060318	50-400 Q
	8401170033*	FOIA		8401100120	40-2061

CORPORATE SOURCE INDEX

535

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Shoreham Opponents Coalition	8401310283	50-289 Q		8401040390	50-361 Q
	8401310292	50-261 Q		8401050256	50-206 P
	8401310329	50-289 Q		8401050634	50-361 P
	8401050202	50-322 Q		8401050634	50-361 P
	8401170276	50-322 Q		8401050639*	50-361 P
Siemens Gammasonics, Inc Sierra Club	8401160421	FOIA		8401100018	50-361 Q
	8401310013	50-133 Q		8401100018	50-361 Q
	8401310016*	50-133 Q		8401100067	50-361 P
	8401310146	50-133 Q		8401100067	50-361 P
Sigma Chemical Co	8401190212	XPORTLIC		8401100367	50-362 Q
Silver King Mines, Inc Sinkin, L A	8401060243*	40-8602		8401110270	50-206 P
	8401180188	50-498 Q		8401110281*	50-206 P
	8401240292	50-498 Q		8401120203	50-361 S
	8401090459*	CONTRACT		8401120219	50-362 S
Small Business Administration	8401100045*	CONTRACT		8401120237	50-362 S
Snell & Wilmer South Carolina Electric & Gas Co	8401230031*	CONTRACT		8401120247	50-206 R
	8401250256	PR		8401120248	50-362 S
	8401030207	50-395 F		8401120256	50-362 S
	8401040399	50-395 S		8401120263	50-361 R
	8401040542	50-395 S		8401130273	50-206 F
	8401040578	50-395 Q		8401160198	50-361 S
	8401040593	50-395 P		8401160206	50-361 S
	8401040597*	50-395 P		8401160210	50-361 S
	8401050111*	50-395 F		8401160276	50-362 S
	8401050410	50-395 S		8401160294	50-362 S
	8401050443	50-395 S		8401160300	50-362 S
	8401050597	50-395 S		8401170200	50-206 P
	8401100444	50-395 P		8401180254	50-206 F
	8401120279	50-395 R		8401200219	50-206 P
	8401120283*	50-395 R		8401230487	50-361 F
	8401120285*	50-395 R		8401240147	50-206 P
	8401120290*	50-395 R		8401240151*	50-206 P
	8401120295*	50-395 R		8401240172	50-206 H
	8401120357	50-395 S		8401240172	50-206 H
	8401120371	50-395 P		8401240179*	50-206 H
	8401120410	50-395 S		8401240179*	50-206 H
	8401170209	50-395 S		8401240179*	50-206 H
	8401240123	50-395 S		8401240382	50-206 F
	8401240132	50-395 S		8401240382	50-206 F
	8401240138	50-395 P		8401250183	50-206 F
	8401240143*	50-395 P		8401260016	50-362 S
	8401240331*	50-395 Q		8401260073	50-362 S
	8401240335	50-269 H		8401260074	50-361 S
	8401240387	50-395 S		8401260225	50-362 S
	8401240390	50-395 Q		8401260264	50-361 S
	8401240557	50-395 P		8401260264	50-361 S
	8401240563*	50-395 P		8401260298	50-362 S
	8401250316*	50-395 F		8401260361	50-361 P
	8401250318*	50-395 F		8401260363	50-361 P
	8401260022	50-395 S		8401260365	50-361 S
	8401260036*	50-395 F	Southern Co Services, Inc Spectron Development Laboratories Standardized Nuclear Unit Power Plant System	8401270218	50-206 P
South Carolina, State of	8401260081	50-395 S		8401270225*	50-206 P
	8401260335	50-395 F		8401270229*	50-206 P
	8401270377	50-395 R		8401270231	50-361 R
	8401270379*	50-395 R		8401270234	50-206 R
	8401270382*	50-395 R		8401270266	50-361 P
	8401270383*	50-395 R		8401270266	50-361 P
	8401270385*	50-395 R		8401270270*	50-361 P
	8401270387*	50-395 R		8401270270*	50-361 P
	8401270388*	50-395 R		8401270274*	50-361 P
	8401270389*	50-395 R		8401270376	50-362 P
	8401270392*	50-395 R		8401270381*	50-362 P
	8401270393*	50-395 R		8401310209*	50-395 P
Southampton, NY Southern California Edison Co	8401300241	50-395 S		8401310401	50-206 P
	8401310005	50-395 P		8401310405*	50-206 P
	8401310022	50-395 Q		8401130152	50-424 S
	8401310206	50-395 P		8401230706*	CONTRACT
	8401130164	WASTE MGT		8401100204	50-482 A
	8401170144	WASTE MGT		8401100456	50-482 S
	8401170146*	WASTE MGT		8401130153	50-482 A
	8401170276	50-322 Q		8401200039	50-482 A
	8401030174	50-361 Q		8401200062*	50-482 A
	8401030287	50-361 S		8401200139	50-482 F
	8401040165	50-206 P		8401200139	50-482 F
	8401040187	50-362 S		8401200139	50-482 F
	8401040301	50-361 S		8401200139	50-482 F
	8401040302	50-362 S		8401200145*	50-482 F
	8401040306	50-362 S		8401200145*	50-482 F
	8401040307	50-362 S		8401200145*	50-482 F
	8401040316	50-361 S		8401240573	50-482 Q
	8401040320	50-206 S	Star-News Newspapers, Wilmington, NC State, Dept of, Bureau of Oceans & Intl. Environ & Scientific Affairs	8401200234*	50-324 P
	8401040343	50-362 S		8401090178	XPORTLIC
	8401040386	50-362 S		8401090185	XPORTLIC
	8401040474	50-361 S			
	8401040474	50-361 S			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8401060281	50-329	A
	8401060294*	50-329	A
	8401060294*	50-329	A
	8401120339	50-329	A
	8401120339	50-329	A
	8401120331*	50-329	A
	8401120331*	50-329	A
	8401170380	50-329	R
	8401170385*	50-329	R
	8401230158	50-329	A
	8401230489	50-329	A
	8401230489	50-329	A
	8401310327	50-329	A
	8401310327	50-329	A
Target Rock Corp	8401130191*	GA999	
	8401130204*	GA999	
Taylor Associates	8401130445*	CONTRACT	
Technical Information Project	8401230037	FDIA	
Technical Specialties, Inc	8401050105*	CONTRACT	
Technical Welding Laboratories of Alaska, Inc	8401230031*	CONTRACT	
	8401120098	NUREG	
Teknekron Research, Inc	8401300356*	WASTE MGT	
	8401180003*	CONTRACT	
Teknekron, Inc	8401180123*	50-358	A
Teledyne Engineering Services	8401270214*	GA999	
Teledyne McKay			
Tennessee Valley Authority	8401030071	50-327	B
	8401030101	50-438	B
	8401030101	50-438	B
	8401030108	50-390	B
	8401030108	50-390	B
	8401030137	50-390	B
	8401030182	50-438	B
	8401030182	50-438	B
	8401030225	50-260	B
	8401030231	50-390	B
	8401030231	50-390	B
	8401030247	50-327	B
	8401030252*	50-259	F
	8401030303	50-438	B
	8401030303	50-438	B
	8401030306	50-439	B
	8401040237	50-296	B
	8401040242	50-390	B
	8401040242	50-390	B
	8401040299	50-390	B
	8401040299	50-390	B
	8401040303	50-390	B
	8401040303	50-390	B
	8401040303	50-390	B
	8401040303	50-390	B
	8401040303	50-390	B
	8401040312	50-438	B
	8401040312	50-438	B
	8401040327	50-439	B
	8401040339	50-438	B
	8401040384	50-327	P
	8401040384	50-327	P
	8401040404	50-390	B
	8401040404	50-390	B
	8401040406	50-390	B
	8401040406	50-390	B
	8401040406	50-390	B
	8401040406	50-390	B
	8401040406	50-390	B
	8401040436	50-028	B
	8401040493	50-438	B
	8401040504	50-327	H
	8401040504	50-327	H
	8401040589	50-390	B
	8401040589	50-390	B
	8401040592	50-438	B
	8401040592	50-438	B
	8401040596	50-390	B
	8401040596	50-390	B
	8401050157	50-259	B
	8401050157	50-259	B
	8401050157	50-259	B
	8401050234	50-259	B
	8401050234	50-259	B
	8401050234	50-259	B
	8401050263	50-259	H
	8401050406	50-390	B
	8401050422	50-327	B
	8401050436*	50-259	B
	8401050523*	50-390	B
	8401050523*	50-390	B

CORPORATE SOURCE INDEX

537

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401050581	50-439 B		8401170363	50-390 S
	8401050582*	50-390 Q		8401170365	50-390 S
	8401050631	50-328 S		8401170400	50-259 P
	8401060051	50-259 P		8401170400	50-259 P
	8401060051	50-259 P		8401170400	50-259 P
	8401060051	50-259 P		8401170423	50-327 P
	8401060067*	50-259 P		8401170423	50-327 P
	8401060101*	50-327 F		8401180156	50-390 F
	8401060445*	50-390 Q		8401180156	50-390 F
	8401060445*	50-390 Q		8401180164*	50-390 F
	8401060453*	50-390 Q		8401180164*	50-390 F
	8401060455*	50-390 Q		8401180262	50-390 A
	8401090135*	50-438 Q		8401180262	50-390 A
	8401090135*	50-438 Q		8401190307	50-390 A
	8401090372	50-327 F		8401190307	50-390 A
	8401090372	50-327 F		8401200083	50-390 A
	8401090432	50-390 A		8401200083	50-390 A
	8401090432	50-390 A		8401200194	50-259 I
	8401100299	50-390 A		8401200194	50-259 I
	8401100299	50-390 A		8401200194	50-259 I
	8401100345	50-390 S		8401200194	50-259 I
	8401100345	50-390 S		8401200194	50-259 I
	8401110004	50-327 P		8401200194	50-259 I
	8401110004	50-327 P		8401200194	50-259 I
	8401110048	50-390 F		8401200194	50-259 I
	8401110048	50-390 F		8401200194	50-259 I
	8401110082	50-390 A		8401200194	50-259 I
	8401110082	50-390 A		8401200194	50-259 I
	8401110130	50-390 K		8401200194	50-259 I
	8401110130	50-390 K		8401200194	50-259 I
	8401110132*	50-390 K		8401200194	50-259 I
	8401110132*	50-390 K		8401200194	50-259 I
	8401120202	50-327 S		8401200194	50-259 I
	8401120223	50-438 S		8401200194	50-259 I
	8401120223	50-438 S		8401200194	50-259 I
	8401120235	50-327 S		8401200194	50-259 I
	8401120257	50-327 R		8401200194	50-259 I
	8401120277	50-390 S		8401200194	50-259 I
	8401120277	50-390 S		8401200194	50-259 I
	8401120289	50-438 S		8401200194	50-259 I
	8401120289	50-438 S		8401200194	50-259 I
	8401120297	50-259 S		8401200194	50-259 I
	8401120307	50-259 R		8401200194	50-259 I
	8401120309	50-260 S		8401200194	50-259 I
	8401120328	50-328 S		8401200194	50-259 I
	8401120336	50-327 S		8401200206*	50-259 I
	8401120356	50-327 S		8401200206*	50-259 I
	8401120367	50-390 S		8401200206*	50-259 I
	8401120367	50-390 S		8401200206*	50-259 I
	8401120383	50-328 S		8401200206*	50-259 I
	8401120385	50-328 S		8401200206*	50-259 I
	8401120427	50-259 S		8401200206*	50-259 I
	8401130053	50-438 S		8401200206*	50-259 I
	8401130053	50-438 S		8401200206*	50-259 I
	8401130053	50-438 S		8401200206*	50-259 I
	8401130093	50-328 S		8401200206*	50-259 I
	8401130165	50-438 S		8401200206*	50-259 I
	8401130278	50-327 S		8401200206*	50-259 I
	8401130365	50-390 S		8401200206*	50-259 I
	8401160077	50-259 P		8401240024	50-390 S
	8401160077	50-259 P		8401240085	50-438 S
	8401160111	50-390 F		8401240097	50-438 S
	8401160111	50-390 F		8401240097	50-438 S
	8401160156	50-438 R		8401240149	50-438 S
	8401160156	50-438 R		8401240149	50-438 S
	8401170001	50-390 S		8401240168	50-438 S
	8401170028	50-260 S		8401240254	50-259 S
	8401170198	50-328 S		8401240254	50-259 S
	8401170214	50-438 S		8401240258	50-390 E
	8401170224	50-390 A		8401240258	50-390 E
	8401170224	50-390 A		8401240264	50-438 S
	8401170248	50-259 S		8401240268	50-390 F
	8401170248	50-259 S		8401240268	50-390 F
	8401170248	50-259 S		8401240323*	50-390 Q
	8401170250	50-327 P		8401240329*	50-390 Q
	8401170252	50-390 A		8401240339*	50-438 Q
	8401170252	50-390 A		8401240342	50-438 S
	8401170263	50-390 S		8401240342	50-438 S
	8401170263	50-390 S		8401240407*	50-259 Q
	8401170288	50-259 S		8401240407*	50-259 Q
	8401170288	50-259 S		8401240428*	50-259 Q
	8401170303	50-390 F		8401240442	50-259 S
	8401170303	50-390 F		8401240461	50-259 Q
	8401170332	50-390 E		8401240461	50-259 Q

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401240461	50-259 Q		8401310017	50-390 A
	8401240482	50-438 S		8401310134	50-259 P
	8401240482	50-438 S		8401310135*	50-327 F
	8401240486	50-390 S		8401310147*	50-327 F
	8401240486	50-390 S		8401310217	50-327 P
	8401240494	50-390 S		8401310366	50-438 A
	8401240502	50-260 S		8401310369	50-327 P
	8401240522	50-327 F		8401310404	50-259 S
	8401240536*	50-390 Q		8401310413	50-327 P
	8401240536*	50-390 Q		8401310413	50-327 P
	8401240545	50-390 S		8401310425*	50-327 P
	8401240545	50-390 S		8401310425*	50-327 P
	8401240574*	50-438 Q	Texas Municipal Power Agency	8401310332*	50-445 A
	8401240583*	50-438 Q	Texas Utilities Generating Co	8401030205	50-445 A
	8401240593*	50-390 Q		840100004	50-445 S
	8401240593*	50-390 Q		8401100349	50-445 A
	8401240605	50-438 S		8401100394	50-445 A
	8401240605	50-438 S		8401110302	50-445 Q
	8401240616*	50-259 F		8401170384	50-445 Q
	8401240616*	50-259 F		8401190283	50-445 Q
	8401240616*	50-259 F		8401230410	50-446 S
	8401240621*	50-259 F		8401230515	50-445 A
	8401240621*	50-259 F		8401240335	50-269 H
	8401240626*	50-259 F		8401270275	50-445 S
	8401250118*	50-259 F		8401270316	50-445 Q
	8401250118*	50-259 F		8401270316	50-445 Q
	8401250118*	50-259 F		8401300034	50-445 F
	8401250118*	50-259 F		8401300034	50-445 F
	8401250118*	50-259 F		8401300244	50-445 Q
	8401250118*	50-259 F		8401300244	50-445 Q
	8401250121	50-390 F		8401310330	50-445 A
	8401250126*	50-259 F		8401310330	50-445 A
	8401250126*	50-259 F		8401310332*	50-445 A
	8401250126*	50-259 F		8401310332*	50-445 A
	8401250321*	50-390 F	Texas Utilities Services, Inc	8401050274	50-445 A
	8401250324*	50-390 F	Texas, State of	8401050262	WASTE MGT
	8401260009	50-390 S		8401100196	WASTE MGT
	8401260012	50-438 S		8401100198*	WASTE MGT
	8401260012	50-438 S	Theophilus, Inc	8401160431	FOIA
	8401260038	50-328 S	Three Mile Island Alert	8401050216	50-289 Q
	8401260045	50-390 S		8401050455	50-289 Q
	8401260045	50-390 S		8401050459*	50-289 Q
	8401260077	50-259 S		8401170311	50-289 Q
	8401260138	50-259 S		8401190174	50-289 Q
	8401260165	50-391 S		8401240215	50-289 Q
	8401260171	50-438 S		8401270209	50-289 Q
	8401260171	50-438 S		8401270288	50-289 Q
	8401260321	50-328 S		8401270309	50-289 Q
	8401260344	50-438 S		8401270367	50-289 Q
	8401260346	50-260 S	Toledo Edison Co	8401040317	50-346 S
	8401260359	50-438 S		8401040358	50-346 S
	8401270088	50-390 A		8401040390	50-346 S
	8401270221	50-519 Q		8401040566	50-346 F
	8401270221	50-519 Q		8401050126*	50-346 F
	8401270398	50-259 R		8401050275	50-346 F
	8401270481	50-327 R		8401060086*	50-346 F
	8401300136	50-390 S		8401060091*	50-346 F
	8401300136	50-390 S		8401060494	50-346 S
	8401300140	50-438 S		8401060509	50-346 S
	8401300140	50-438 S		8401120093	71-9151
	8401300181	50-296 S		8401120322	50-346 R
	8401300193	50-438 S		8401160227	50-346 S
	8401300193	50-438 S		8401160238	50-346 S
	8401300199	50-259 S		8401160259	50-346 S
	8401300233	50-259 S		8401160299	50-346 S
	8401300246	50-438 S		8401160325	50-346 S
	8401300246	50-438 S		8401160330	50-346 S
	8401300246	50-438 S		8401170178	50-346 R
	8401300246	50-438 S		8401170196	50-346 R
	8401300246	50-438 S		8401170205	50-346 R
	8401300273	50-296 P		8401190331	50-346 S
	8401300275	50-438 S		8401190351	50-346 P
	8401300275	50-438 S		8401190406	50-346 S
	8401300276	50-390 S		8401230483	50-346 P
	8401300276	50-390 S		8401230634*	50-346 F
	8401300278*	50-296 P		8401240327*	50-346 Q
	8401300296*	50-296 P		8401240479*	50-346 Q
	8401300300	50-438 S		8401240650*	50-346 F
	8401300300	50-438 S		8401250018*	50-346 F
	8401300304	50-390 K		8401260233*	50-346 F
	8401300307*	50-390 K		8401260379*	50-346 F
	8401300307*	50-390 K		8401260384*	50-346 F
	8401300325	50-438 S		8401270293	50-346 P
	8401300325	50-438 S		8401270297*	50-346 P
	8401310017	50-390 A		8401270390	50-346 P

CORPORATE SOURCE INDEX

539

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401270394*	50-346 P		8401240641*	QA999
	8401270483	50-346 S		8401240643*	QA999
	8401300009	50-346 S		8401240644*	QA999
	8401300187	50-346 S		8401240646*	QA999
	8401300295	50-346 S	United Nuclear Corp	8401040002	40-872B
	8401300333*	50-346 F		8401090593	40-872B
Transamerica Delaval, Inc	8401310070*	50-346 F		8401270055	70-B20
	8312200154	50-206 P	United Technologies Corp.	8401310411	PR
	8401170186	50-206 S	Utah, State of	8401100150	WASTE MGT
	8401230505*	QA999		8401100242*	WASTE MGT
	8401230512*	QA999		8401100244*	WASTE MGT
Transnuclear, Inc	8401310374	QA999		8401110333*	COMMISSION
Tufts Univ., School of Medicine	8401110356	XPORTRIC		8401120259	WASTE MGT
	8401170139	50-443 T		8401120331*	WASTE MGT
	8401170139	50-443 T	Utah, Univ. of, Salt Lake City, UT	8401300111	50-407 V
	8401170141*	50-443 T			
Turb, J	8401170141*	50-443 T	Utility Nuclear Waste Management Group	8401120265	WASTE MGT
U S Ecology, Inc (formerly Nuclear	8401170286*	50-70 O		8401120270	WASTE MGT
Engineering, Inc)	8401110450	WASTE MGT	Utility Safety Classification Group	8401170528*	REVIEW ORP
			Velan Valve Co	8401230291*	QA999
	8401110463	27-4B	Vermont Yankee Nuclear Power Corp	8401040534	50-271 Q
	8401120156	27-4B		8401100312*	50-271 Q
	8401170525*	CONTRACT		8401130033	50-271 S
	8401170542	WASTE MGT		8401130045	50-271 X
	8401180147	NUREG		8401130322	50-271 J
	8401190169	27-4B		8401160127	50-271 S
	8401190253	27-4B		8401170317	50-271 R
U S Tool & Die, Inc	8401190254	27-4B		8401170352	50-271 P
URB Corp	8401250303*	50-244 P		8401240464	50-271 P
	8401170153*	50-244 P		8401270492	50-271 P
	8401170354	QA999		8401270497*	50-271 P
	8401310492	40-8584	Veterans Admin Hosp., Omaha, NE	8401230450	50-131 R
Union 76 Minerals Exploration Co	8401060384	XPORTRIC	Vikonica, Inc.	8401100125*	CONTRACT
Union Carbide Corp	8401110483	40-299	Virginia Electric & Power Co	8312200074	50-281 S
	8401110484*	40-299		8401030187	50-280 Q
	8401120432	40-299		8401030187	50-280 Q
	8401270142	40-299		8401030347*	50-280 F
	8401270147*	40-299		8401030347*	50-280 F
	8401270155	40-299		8401030347*	50-280 F
	8401270172*	40-299		8401030357*	50-338 F
	8401270179	40-299			
Union Electric Co	8401310459	40-299		8401040229	50-338 P
	8401030322*	50-483 F		8401040322	50-281 S
	8401030326*	50-483 F		8401040325	50-280 S
	8401030141*	50-483 F		8401040326*	50-281 S
	8401050146*	50-483 F		8401040330*	50-281 S
	8401060022*	50-483 F		8401040331*	50-280 S
	8401060037*	50-483 F		8401040337*	50-280 S
	8401060041*	50-483 F		8401040365	50-337 S
	8401060363	50-483 S		8401040369	50-280 S
	8401100189	50-483 R		8401040373*	50-280 S
	8401100339	50-483 A		8401040376*	50-280 S
	8401160179*	50-483 Q		8401040424	50-338 P
	8401230177	50-483 Q		8401040424	50-338 P
	8401230231	50-483 S		8401040429*	50-338 P
	8401230313*	50-483 F		8401040429*	50-338 P
	8401230330	50-483 S		8401040445	50-338 H
	8401240137	50-483 S		8401040445	50-338 H
	8401240152	50-483 S		8401040520	50-338 P
	8401250049*	50-483 F		8401040520	50-338 P
	8401250052*	50-483 F		8401040549	50-338 S
	8401250075*	50-483 F		8401040552	50-280 F
	8401250077*	50-483 F		8401040552	50-280 F
	8401270411	50-483 K		8401040560	50-280 P
	8401270413*	50-483 K		8401050025*	50-280 F
	8401270501	50-483 S		8401050114*	50-338 F
	8401310116	50-483 A		8401050404*	50-280 F
	8401310120*	50-483 A		8401050408*	50-280 F
	8401310192*	50-483 F		8401050464	50-280 Q
	8401310368*	50-483 Q		8401050480*	50-280 Q
Union Minerals	8401040147	40-1162		8401050480*	50-280 Q
Union of Concerned Scientists	8401100200	50-289 Q		8401050493*	50-280 Q
	8401230594	FOIA		8401050496*	50-338 Q
	8401230605	FOIA		8401050548	50-338 S
	8401240224	50-289 Q		8401050573*	50-338 Q
	8401240230*	50-289 Q			
	8401240239*	50-289 Q		8401050573*	50-338 Q
	8401250010	FOIA		8401050579*	50-338 Q
	8401260164	50-289 Q		8401050579*	50-338 Q
United Engineers & Constructors, Inc	8401030162	50-443 S		8401050644*	50-280 Q
(subs. of Raytheon Co)				8401060048	50-338 F
	8401240625*	QA999		8401060048	50-338 F
	8401240627*	QA999		8401060113*	50-280 F
	8401240634*	QA999		8401060296	50-338 J
	8401240639*	QA999		8401060296	50-338 J
				8401060306	50-280 P

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401090347	PRM		8401310376	50-397 E
	8401090500	50-338 P	Washington, State of	8401130154	WASTE MGT
	8401090500	50-338 P		8401310281	WASTE MGT
	8401090501*	50-338 P		8401310282*	WASTE MGT
	8401090501*	50-338 P	Washington, State of, Dept of Social & Health Services	8401270423	State Prog
	8401120253	50-338 R			
	8401120291	50-280 R	Water, Waste & Land, Inc	8401170537*	CONTRACT
	8401120293	50-338 S		8401170549*	CONTRACT
	8401120293	50-338 S		8401310462*	40-299
	8401130010	50-339 S	Wayne, NJ	8401030053*	40-86
				8401030161*	40-86
	8401160075	50-280 P			
	8401170188	50-280 S	We Try Harder, Inc	8401030088*	CONTRACT
	8401170189	50-280 P	West Bank Radiation Therapy Center,	8401100355*	40-8046
	8401170189	50-280 P	Minneapolis, MN		
	8401170437	50-280 P	West Virginia Univ, Morgantown, WV	8401240200*	50-129 G
				8401240210*	50-129 G
	8401170437	50-280 P	Western Interstate Energy Board	8401310251	WASTE MGT
	8401170440*	50-280 P			
	8401170440*	50-280 P			
	8401230021	50-338 S	Western Nuclear, Inc (subs of Phelps Dodge Corp)	8401110583	40-1162
	8401240225	50-338 P			
				8401270157	40-1162
	8401240301	50-338 F		8401310484	40-1162
	8401240409	50-280 F	Westinghouse Electric Corp	8401310488*	40-1162
	8401240488*	50-281 Q		8312200575	TOPREP
	8401250044	50-280 P			
	8401260003	50-280 S		8312200580*	TOPREP
				8401040004	71-4909
	8401260006	50-339 S		8401040196*	50-315 F
	8401260015	50-339 S		8401050008	70-1151
	8401260205*	50-338 F		8401050011*	70-1151
	8401260205*	50-338 F			
	8401260257*	50-338 F		8401050168*	TOPREP
				8401050174*	TOPREP
	8401270233	50-280 P		8401050351*	70-1151
	8401270248	50-338 P		8401060396	PROJ
	8401270248	50-338 P		8401060399*	PROJ
	8401270248	50-338 P			
	8401270372	50-280 R		8401090092	XPORTLIC
	8401270484	50-338 R		8401090488*	QA999
				8401090718	XPORTLIC
	8401300178	50-338 F		8401100360	PR
	8401300178	50-338 F		8401110042	TOPREP
	8401300309	50-280 P			
	8401310210	50-338 P		8401110134	70-698
	8401310210	50-338 P		8401110140*	70-698
				8401110239	TOPREP
	8401310358	50-280 S		8401110246*	TOPREP
	8401310362*	50-280 S		8401120103	70-698
	8401310367*	50-280 S			
	8401310387	50-281 S		8401120106*	70-698
	8401310402	50-338 P		8401200055	TOPREP
				8401200060*	TOPREP
	8401310402	50-338 P		8401200064*	TOPREP
Virginia Polytechnic Institute & State Univ., Blacksburg, VA	8401040099	50-124 V		8401200119	71-251
Virginia, Commonwealth of,	8401200012	50-124 P		8401240357*	70-1151
Virginia, Univ. of, Charlottesville, VA	8401170356	WASTE MGT		8401240366	70-1151
	8401100114*	CONTRACT		8401240454*	QA999
				8401240457*	QA999
	8401100123*	CONTRACT		8401240463*	QA999
W.R. Grace & Co.	8401030036*	40-86			
WSI Corp.	8401110011*	CONTRACT		8401240465*	QA999
Wall Street Journal	8401230621	50-329 G		8401240471	TOPREP
Washington Public Power Supply System	8401030254*	50-397 G		8401240528	70-1151
				8401250267*	70-1151
	8401030270	50-397 P		8401310007	TOPREP
	8401040310	50-397 S			
	8401040318	50-397 S		8401310154	70-1143
	8401040333	50-397 S		8401310159*	70-1143
	8401040507	50-397 P		8401310352	TOPREP
			Westinghouse Operating Plants Owners Group	8401050164	TOPREP
	8401040579	50-397 S			
	8401050003*	50-397 F		8401230520*	50-443 F
	8401050191	50-460 Q			
	8401100185	50-460 K	Whicker, J M	8401300261	50-454 Q
	8401160069	50-397 P	Williams & Associates	8401110437	40-8629
				8401110441	40-8768
	8401160072*	50-397 P		8401110446*	40-8768
	8401180217	50-397 J	Willowbrook Nursing Home Wayne, NJ,	8401030063*	FOIA
	8401240162	50-397 E			
	8401240335	50-269 H		8401030110*	40-86
	8401240335	50-269 H	Wisconsin Electric Power Co.	8306280032*	50-266 F
				8401030208	50-266 P
	8401260072	50-397 S		8401030208	50-266 P
	8401260398	50-508 G		8401030211*	50-266 P
	8401300062	50-397 E			
	8401300066	50-397 P		8401030211*	50-266 P
	8401300075	50-397 E		8401050284	50-266 P
				8401100469	50-266 P
	8401300166	50-397 P		8401100469	50-266 P
	8401300235	50-397 P		8401130211*	50-266 G
	8401300236*	50-397 P			
	8401310021	50-397 P		8401130387	50-266 Q
	8401310027	50-397 P		8401130387	50-266 Q
				8401170192	50-266 R
	8401310028*	50-397 P		8401190419	50-266 P
	8401310131	50-397 F		8401190422*	50-266 P
	8401310215	50-397 P			
	8401310276	50-508 A		8401230412	50-266 J

CORPORATE SOURCE INDEX

541

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8401240072	50-266 Q
	8401240072	50-266 Q
	8401260259*	50-266 F
	8401260262*	50-266 F
	8401260262*	50-266 F
	8401260501*	50-266 F
	8401260501*	50-266 F
	8401270045	50-266 P
	8401300070	50-266 X
	8401300070	50-266 X
Wisconsin Public Service Corp	8401030278	50-305 P
	8401030280*	50-305 P
	8401030281*	50-305 P
	8401030315*	50-305 F
	8401030317*	50-305 F
	8401040240	50-305 F
	8401040309	50-305 S
	8401040321	50-305 S
	8401040378	50-305 Q
	8401060348	50-305 S
	8401100191	50-305 J
	8401100427	50-305 P
	8401120378	50-305 S
	8401130324	50-305 S
	8401160089	50-305 R
	8401160278	50-305 S
	8401190333*	50-305 G
	8401200015	50-305 V
	8401230354	50-305 S
	8401230369	50-305 S
	8401230429	50-305 P
	8401230444*	50-305 P
	8401260043	50-305 J
	8401310372	50-305 F
Wisconsin, State of	8401100134	WASTE MGT
	8401100202	WASTE MGT
Woodward-Clyde Consultants, Inc	8401190309*	50-390 A
Worcester Polytechnic Institute,	8401160112	50-134 R
Worcester, MA		
Wyoming Fuel Co	8401130128	40-8829
	8401310501	40-8829
Wyoming, State of	8401060525	40-8768
	8401100494	40-8102
	8401110494	40-297
	8401120114	WASTE MGT
	8401270177	40-8584
	8401310456	40-2259
	8401310496	40-8584
	8401310508	40-1162
Yakima Indian Nation	8401090358	WASTE MGT
	8401100140	WASTE MGT
Yankee Atomic Electric Co	8401100143*	WASTE MGT
	8312200113	50-443 S
	8401040561	50-29 P
	8401040624*	50-29 Q
	8401060072*	50-271 F
	8401060076*	50-271 F
	8401090204	50-29 P
	8401100207	50-443 E
	8401100207	50-443 E
	8401100218	50-29 P
	8401100328*	50-443 Q
	8401100402	50-29 F
	8401100484	50-29 F
	8401110287	50-443 A
	8401110287	50-443 A
	8401120261	50-29 R
	8401170319	50-29 G
	8401170343	50-443 A
	8401170343	50-443 A
	8401230343	50-443 A
	8401230343	50-443 A
	8401230494	50-443 F
	8401240223	50-29 P
	8401250116*	50-29 F
	8401260054*	50-29 F
	8401270258	50-29 S
	8401270406	50-29 R
	8401300317	50-29 P
	8401300319*	50-29 P
York Committee for Safe Environment	8401120324	50-443 Q
Zumwalt, L.R	8401230204*	CONTRACT

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
04243	8401160284*	50-219 P		NUREG-0933	8401230657	NUREG	
104-75-7	8401180264*	50-219 P		NUREG-0974 801	8401260061	50-352 D	
186-028-32	8401050436*	50-29 P		NUREG-0993	8401180126	50-272 P	
22A1694 R00	8401090556*	50-293 P		NUREG-1004	8401090198	50-261 P	
23A1411 R00	8401170420*	50-354 A		NUREG-1009	8401160477	50-397 P	
82-863	8401200304	27-47		NUREG-1013	8401090097	50-374 R	
8367-00-0005	8401250303*	50-244 P		NUREG-1026	8401180120	50-456 D	
90696B RA	8401130089*	50-267 P		NUREG-1033	8401250160	50-508 D	
AEB90-R1	8401180082*	50-528 A		NUREG-1041	8401090663	NUREG	
CEB-83-34 R00	8401060067*	50-259 P		NUREG-1060	8401260068	50-320 P	
CEN-261(A)	8401040275*	50-368 P		NUREG/BR-0025 V09 N8	8401030342	NUREG	
CENPD-255-A R03	8401250009*	TOPREP		NUREG/BR-0025 V10 N1	8401270515	NUREG	
CNSI-HIC-14571-01-NP	8401120608*	WASTE MGT		NUREG/CP-004B V01	8401310130	NUREG	
CV-12/HW-01 R00	8401110279*	50-206 P		NUREG/CP-004B V02	8401260097	NUREG	
CV-13 R00	8401110275*	50-206 P		NUREG/CP-004B V03	8401260096	NUREG	
DCR3A1411 R00	8401170426*	50-354 A		NUREG/CP-004B V04	8401260108	NUREG	
DOE/NE-0025/2	8401260065	WASTE MGT		NUREG/CP-004B V05	8401250162	NUREG	
EQO-EA-6400	8401090651*	50-280 P	TAC 4300B	NUREG/CP-004B V06	8401250125	NUREG	
EQO-EA-6453	8401310524*	50-289 P	TAC 61740	NUREG/CR-1755	8401230677	NUREG	
EQO-EA-6468	8401310435*	GEN TEC 18		NUREG/CR-2000 V02N11	8401030443	NUREG	ORNL/NBIC-200
EQO-EA-6473	8401310429*	GEN TEC 18		NUREG/CR-2325	8401260079	NUREG	
EQO-SAAM-6476	8401310061*	50-261 P		NUREG/CR-2522 R01	8401180147	NUREG	SAND81-0118
FAAA-83-12-9	8401030243*	50-322 B	M&T3/7396	NUREG/CR-2679 V02	8401040043	NUREG	SAND82-0904
FW-04 R00	8401110273*	50-206 P		NUREG/CR-2800 502	8401130220	NUREG	PNL-4297
LAC-TR-120	8401030206*	50-409 P		NUREG/CR-2970 V04	8401160443	NUREG	ANL-82-41
NEDO-20697	8401300285*	50-296 P	74NED069	NUREG/CR-3018	8401160438	NUREG	
NEDO-21696 ERR 03	8401090554*	50-293 P		NUREG/CR-3070	8401310449	NUREG	
NEDO-24194A ERR 02	8401300310*	50-296 P	79NED096	NUREG/CR-3088	8401100075	NUREG	PNL-4542
NF-1583 01-1	8401130257*	50-324 P	LAP-83-576	NUREG/CR-3125	8401090615	NUREG	SAND82-0767
NF-1583 02-1 (NP)	8401130266*	50-324 P	LAP-83-576	NUREG/CR-3128	8401090612	NUREG	PNL-4372
NF-1583, 03-1 (NP)	8401130283*	50-324 P	LAP-83-576	NUREG/CR-3154	8401030380	NUREG	SAND82-0679
NP-2704-8R	8401180035*	ACRS		NUREG/CR-3165	8401130284	50-10 P	ORNL/TH-8647
NUREG-0020 V07 N10	8401100097	NUREG		NUREG/CR-3233	8401030364	50-245 P	BNL-NUREG-51648
NUREG-0485 V05 N11	8401200362	NUREG		NUREG/CR-326B DR V01	8401100025*	FOIA	P SAND82-2429
NUREG-0519 507	8401030446	50-373 E		NUREG/CR-326B DR V02	8401100030*	FOIA	SAND83-0963
NUREG-0540 V05 N09	8401030376	NUREG		NUREG/CR-326B DR V03	8401100037*	FOIA	SAND83-0963
NUREG-0540 V05 N10	8401230352	NUREG		NUREG/CR-326B DR V04	8401100040*	FOIA	SAND83-0963
NUREG-0580 V12 N11	8401030373	NUREG		NUREG/CR-3307 V02	8401190250	NUREG	PNL-4705-2
NUREG-0647	8401270427	50-320 P		NUREG/CR-3332	8312270412	NUREG	ORNL-5968
NUREG-0675 820	8401260071	50-275 E		NUREG/CR-3334 V02	8401230066	NUREG	ORNL/TH-8787/V2
NUREG-0675 821	8401170143	50-275 E		NUREG/CR-3343	8401200095	NUREG	PNL-4561
NUREG-0683 501 DRFT	8401090613	50-320 P		NUREG/CR-3359 V03	8401230062	NUREG	ANL-83-11 V III
NUREG-0713 V04	8401230162	NUREG		NUREG/CR-3427 V02	8401130379	NUREG	
NUREG-0748 V03 N10	8401040032	NUREG		NUREG/CR-3430 V01	8401180072	NUREG	ORNL/NBIC-215/V
NUREG-0748 V03 N11	8401260119	NUREG		NUREG/CR-3439 V01	8401230039	NUREG	ORNL/TH-8862/V1
NUREG-0750 V18 N02	8401040089	NUREG		NUREG/CR-3439 V02	8401230090	NUREG	ORNL/TH-8862/V2
NUREG-0775	8401270428	50-445 D		NUREG/CR-3456	8401130360	NUREG	PNL-4814
NUREG-0797 804	8312090111	50-445 E		NUREG/CR-3502	8401300018	NUREG	ORNL/TH-8794
NUREG-0820 501	8312070296	50-255 P		NUREG/CR-3503	8401130231	NUREG	PNL-4209
NUREG-0837 V03 N02	8401270146	NUREG		NUREG/CR-3510	8401160430	40-4492	PNL-4798
NUREG-0857 505	8312090366	50-528 E		NUREG/CR-3525	8401260101	NUREG	ORNL/BUB/B1-908
NUREG-0871 V02 N04	8401030356	NUREG		NUREG/CR-3532	8401130105	NUREG	SAND83-2098
NUREG-0876 803	8312120186	50-454 E		NUREG/CR-3540	8401130356	NUREG	PNL-4677
NUREG-0881 804	8401090322	50-482 E		NUREG/CR-3542	8401030370	NUREG	
NUREG-0892 804	8401040036	50-397 E		NUREG/CR-3556	8401130092	NUREG	EQO-2284

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-3557	8401030355	NUREG	EQG-2285	SECY-82-357	8209210015*	FOIA	CLI-82-16
NUREG/CR-3568	8401100088	NUREG	PNL-4646	SECY-82-378	8401250325*	50-255 P	
NUREG/CR-3574	8401090606	NUREG		SECY-82-382	8401250322*	FOIA	
NUREG/CR-3576	8401030340	NUREG		SECY-82-384A	8401230070*	50-289 P	
NUREG/CR-3577	8401250134	NUREG		SECY-82-390	8401250241*	50-312 F	COMJA-80-35
NUREG/CR-3578	8401260105	NUREG	PNL-4711	SECY-82-400	8211030044*	FOIA	
NUREG/CR-3582	8401120073	NUREG	EQG-M8-4388	SECY-82-403	8211020259*	50-244 P	
NUREG/CR-3586	8401120098	NUREG		SECY-82-406	8211030079*	FOIA	
NUREG/CR-3594	8401160434	NUREG		SECY-82-407	8210270322*	FOIA	
NUREG/CR-3615	8401250129	NUREG		SECY-82-422	8211090063*	FOIA	
F105-4-839-086	8401110058*	50-275 R		SECY-82-430	8211090002*	FOIA	82-1581
QUAD-1-83-016 R04	8401110313*	50-352 A		SECY-82-432	8211090006*	FOIA	
SAI-1-186-07-087-1	8401040530	TOPREP		SECY-82-445	8211190003*	FOIA	
SAND75-0658	8401170035*	FOIA		SECY-82-450	8211190008*	FOIA	
SAND75-6159	8401170033*	FOIA		SECY-82-473	8401250353*	50-274 P	
SAND82-1250	8401300101*	WASTE MGT	00089	SECY-82-478	8401250359*	FOIA	
SAND83-0867	8401310455*	WASTE MGT	TTC-0434	SECY-82-488	8401250363*	FOIA	
SD-BWI-TI-089 R00	8401120022*	WASTE MGT	00647	SECY-82-496	8401250370*	50-219 P	
SD-BWI-TI-090 R00	8401120025*	WASTE MGT	00647	SECY-82-498	8301070135*	FOIA	
SD-BWI-TI-095 R00	8401120028*	WASTE MGT	00647	SECY-82-500	8301070155*	50-289 P	
SD-BWI-TI-102 R00	8401120033*	WASTE MGT	00647	SECY-82-501	8401250376*	FOIA	
SD-BWI-TI-105 R00	8401120037*	WASTE MGT	00647	SECY-82-502	8301070165*	50-289 P	
SD-BWI-TI-109 R00	8401120040*	WASTE MGT	00647	SECY-82-504	8401250385*	FOIA	
SD-BWI-TI-130 R00	8401120046*	WASTE MGT	00647	SECY-83-004A	8401200225	SECY	
SD-BWI-TI-131 R00	8401120049*	WASTE MGT	00647	SECY-83-024	8401170142*	FOIA	
SD-BWI-TI-142 R00	8401120065*	WASTE MGT	00647	SECY-83-085	8303110415*	50-395 F	
SD-BWI-TI-150 R00	8401120067*	WASTE MGT	00647	SECY-83-111	8304050512*	50-250 F	
SECY-82-013C	8209010239*	FOIA		SECY-83-152	8305160385*	50-458 F	
SECY-82-016E	8401250106*	50-289 P		SECY-83-153	8305170230*	FOIA	
SECY-82-040	8401250112*	FOIA		SECY-83-161	8305160182*	50-483 F	
SECY-82-044	8401250117*	FOIA		SECY-83-191	8306030404*	50-346 F	COMJA-80-37
SECY-82-045	8203040434*	FOIA		SECY-83-192	8306030153*	50-309 F	
SECY-82-054	8203050072*	FOIA		SECY-83-199	8306020457*	50-344 F	
SECY-82-056	8203050106*	FOIA		SECY-83-205	8306210319*	50-382 F	
SECY-82-064	8203050118*	50-293 P		SECY-83-223	8306150117*	50-266 F	
SECY-82-066	8203110330*	FOIA		SECY-83-340	8401230079*	50-289 P	
SECY-82-073	8401250148*	40-2061	CLI-82-2	SECY-83-472	8401060169*	SECY	
SECY-82-073A	8204070589*	40-2061		SECY-83-487	8312130434	SECY	
SECY-82-076	8203240020*	FOIA		SECY-83-498	8312140411	SECY	
SECY-82-079	8203120409*	FOIA		SECY-84-001 ERR	8401110187*	50-275 Q	
SECY-82-081	8203120423*	50-275 P		SECY-84-002	8401230103	SECY	
SECY-82-082	8401250164*	50-358 A		SECY-84-008	8401240133	SECY	
SECY-82-083	8203120411*	FOIA		TER-C5506-319	8309010227*	50-219 P	TAC 07944
SECY-82-092	8203180400*	50-289 P		TER-C5506-357	8312060347*	50-244 P	TAC 07992
SECY-82-092A	8203050087*	50-289 P		TER-C5506-365	8312060211*	50-309 P	TAC 08059
SECY-82-099	8203180405*	FOIA		TER-C5506-85/86	8304070498*	50-324 P	TAC 8106
SECY-82-112	8203300068*	50-443 A		TER-C5863-1	8309230076*	MISC	
SECY-82-122	8204030459*	FOIA		TR-N-MCM-008	8401200168*	50-336 P	
SECY-82-132	8204070577*	FOIA		TVA-RLR-001	8401300296*	50-296 P	
SECY-82-134	8204080204*	50-244 P		UCID-19704	8306140082*	50-254 P	
SECY-82-141	8204220088*	FOIA		UCID-19709	8307190298*	50-220 P	
SECY-82-143	8204300109*	50-155 P		UCID-19721	8312140428*	50-313 P	TAC 51736
SECY-82-150A	8209130435*	FOIA		URB/JAB B319	8401170153*	50-244 P	
SECY-82-152	8204220344*	50-275 P		WCAP-10377-A	8401200064*	TOPREP	
SECY-82-156	8205050098*	FOIA					
SECY-82-157A	8208060142*	FOIA					
SECY-82-160	8204220376*	50-382 A					
SECY-82-161	8205050587*	50-255 P					
SECY-82-162	8205050499*	FOIA					
SECY-82-172	8205070412*	FOIA					
SECY-82-193	8205280489*	50-250 Q					
SECY-82-195	8205270663*	50-272 P					
SECY-82-197	8205240606*	FOIA					
SECY-82-197 ERR	8401250223*	FOIA					
SECY-82-177C	8206300094*	FOIA					
SECY-82-204	8206110164*	50-244 P					
SECY-82-219	8206110014*	50-289 P					
SECY-82-223	8206110136*	FOIA					
SECY-82-241A	8401230240*	FOIA					
SECY-82-247	8206300033*	FOIA					
SECY-82-250	8206300059*	50-289 P					
SECY-82-262	8206270623*	FOIA					
SECY-82-263	8206300371*	50-382 A					
SECY-82-269	8401250258*	FOIA					
SECY-82-272	8401250263*	50-251 Q					
SECY-82-285	8401250269*	50-358 Q					
SECY-82-293	8207230676*	FOIA					
SECY-82-297	8207230670*	50-358 A					
SECY-82-333	8208230483*	FOIA					
SECY-82-334B	8401250302*	50-537 Q					
SECY-82-346	8209200347*	50-289 P					
SECY-82-346A	8401250311*	50-289 P					
SECY-82-349	8209230144*	FOIA					
SECY-82-352	8209160068*	50-275 P					
SECY-82-354	8209200377*	FOIA					

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
7812070139	8401230630	83/11/01	50-329 Q
7902020317	8401040019	83/10/14	FOIA
7903090050	8401040019	83/10/14	FOIA
7903090070	8401040019	83/10/14	FOIA
7904050425	8401040019	83/10/14	FOIA
7908070022	8401230630	83/11/01	50-329 Q
7908200203	8401040019	83/10/14	FOIA
7909070539	8401040019	83/10/14	40-3577
7912140299	8401230630	83/11/01	50-329 Q
8001230101	8401170029	83/10/11	FOIA
8002120130	8401230630	83/11/01	50-329 Q
8002190404	8401040019	83/10/14	FOIA
8003130307	8401040019	83/10/14	FOIA
8003130526	8401170029	83/10/11	FOIA
8003130530	8401170029	83/10/11	FOIA
8005070343	8401040019	83/10/14	FOIA
8005070405	8401040019	83/10/14	70-83
8006130374	8401040623	83/10/25	FOIA
8006200261	8401040019	83/10/14	FOIA
8008280420	8401040019	83/10/14	FOIA
8010070383	8401040019	83/10/14	FOIA
8010310427	8401040019	83/10/14	FOIA
8104060208	8401040019	83/10/14	FOIA
8104230201	8401040019	83/10/14	FOIA
8107160006	8401160460	83/10/14	FOIA
8111160348	8401040019	83/10/14	70-938
8111160351	8401040019	83/10/14	70-938
8202020366	8401250163	83/11/02	50-382 F
8202120297	8401250163	83/11/02	FOIA
8203040434	8401250015	83/10/18	FOIA
8203050072	8401250015	83/10/18	FOIA
8203050106	8401250015	83/10/18	FOIA
8203050118	8401250015	83/10/18	50-293 P
8203110330	8401250015	83/10/18	FOIA
8203120409	8401250015	83/10/18	FOIA
8203120411	8401250015	83/10/18	FOIA
8203120423	8401250015	83/10/18	50-275 P
8203170235	8401170052	83/10/03	50-329 A
8203180400	8401250015	83/10/18	50-289 P
8203180405	8401250015	83/10/18	FOIA
8203240020	8401250015	83/10/18	FOIA
8203300068	8401250015	83/10/18	50-443 A
8204050459	8401250015	83/10/18	FOIA
8204070577	8401250015	83/10/18	FOIA
8204070589	8401250015	83/10/18	40-2061
8204080204	8401250015	83/10/18	50-244 P
8204220088	8401250015	83/10/18	FOIA
8204220364	8401250015	83/10/18	50-275 P
8204220376	8401250015	83/10/18	50-382 A
8204260021	8401170015	83/10/25	FOIA

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8204300109	8401250015	83/10/18	50-155 P
8205050087	8401250015	83/10/18	50-289 P
8205050098	8401250015	83/10/18	FOIA
8205050499	8401250015	83/10/18	FOIA
8205050587	8401250015	83/10/18	50-255 P
8205070412	8401250015	83/10/18	FOIA
8205240604	8401250015	83/10/18	FOIA
8205270663	8401250015	83/10/18	50-272 P
8205280489	8401250015	83/10/18	50-250 Q
8206110014	8401250015	83/10/18	50-289 P
8206110136	8401250015	83/10/18	FOIA
8206110164	8401250015	83/10/18	50-244 P
8206130010	8401030015	83/09/20	FOIA
8206130011	8401030015	83/09/20	FOIA
8206290623	8401250015	83/10/18	FOIA
8206300033	8401250015	83/10/18	FOIA
8206300059	8401250015	83/10/18	50-289 P
8206300094	8401250015	83/10/18	FOIA
8206300371	8401250015	83/10/18	50-282 A
8207060317	8401250015	83/10/18	FOIA
8207110091	8401030015	83/09/20	40-86
8207150195	8401170052	83/10/03	FOIA
8207180008	8401030015	83/09/20	40-86
8207230670	8401250015	83/10/18	50-338 A
8207230676	8401250015	83/10/18	FOIA
8208010037	8401030015	83/09/20	FOIA
8208010047	8401030015	83/09/20	FOIA
8208060142	8401250015	83/10/18	FOIA
8208110023	8401160460	83/10/14	FOIA
8208230015	8401160460	83/10/21	FOIA
8208230483	8401250015	83/10/18	FOIA
8209010239	8401250015	83/10/18	FOIA
8209150025	8401030015	83/09/20	40-86
8209150435	8401250015	83/10/18	FOIA
8209160068	8401250015	83/10/18	50-275 P
8209200347	8401250015	83/10/18	50-289 P
8209200377	8401250015	83/10/18	FOIA
8209210015	8401250015	83/10/18	FOIA
8209230144	8401250015	83/10/18	FOIA
8210270322	8401250015	83/10/18	FOIA
8211020259	8401250015	83/10/18	50-244 P
8211030044	8401250015	83/10/18	FOIA
8211030079	8401250015	83/10/18	FOIA
8211090002	8401250015	83/10/18	FOIA
8211090006	8401250015	83/10/18	FOIA
8211090063	8401250015	83/10/18	FOIA
8211160524	8401170052	83/10/03	FOIA
8211180523	8401170034	83/10/21	50-440 A
8211190003	8401250015	83/10/18	FOIA
8211190008	8401250015	83/10/18	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

CESSION NUMBER				ACCESSION NUMBER			
SURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
10495	8401030015	83/09/20	40-86	8401030048	8401030015	83/09/20	40-86
60498	8401250163	83/11/02	50-395 F	8401030049	8401030015	83/09/20	40-86
70133	8401250015	83/10/18	FOIA	8401030050	8401030015	83/09/20	40-86
70155	8401250015	83/10/18	50-289 P	8401030052	8401030015	83/09/20	40-86
70163	8401250015	83/10/18	50-289 P	8401030053	8401030015	83/09/20	40-86
60532	8401170052	83/10/03	FOIA	8401030054	8401030015	83/09/20	40-86
70323	8401160460	83/10/14	FOIA	8401030055	8401030015	83/09/20	40-86
70540	8401160460	83/10/14	FOIA	8401030057	8401030015	83/09/20	40-86
10415	8401250163	83/11/02	50-395 F	8401030058	8401030015	83/09/20	40-86
50512	8401250163	83/11/02	50-250 F	8401030060	8401030015	83/09/20	40-86
70498	8401230602	83/12/27	50-324 P	8401030063	8401030015	83/09/20	FOIA
60182	8401250163	83/11/02	50-483 F	8401030065	8401030015	83/09/20	40-86
60327	8401250163	83/11/02	50-458 F	8401030066	8401030015	83/09/20	40-86
60338	8401170052	83/10/03	FOIA	8401030069	8401030015	83/09/20	40-86
70230	8401170137	83/10/31	FOIA	8401030070	8401030015	83/09/20	40-86
60352	8401250163	83/11/02	50-245 F	8401030073	8401030015	83/09/20	40-86
60362	8401250163	83/11/02	50-245 F	8401030076	8401030015	83/09/20	40-86
20457	8401250163	83/11/02	50-344 F	8401030081	8401030015	83/09/20	40-86
30133	8401250163	83/11/02	50-309 F	8401030082	8401030015	83/09/20	40-86
30404	8401250163	83/11/02	50-346 F	8401030084	8401030015	83/09/20	40-86
40082	8401300059	83/12/29	50-254 P	8401030088	8401030079	83/12/14	CONTRACT
50117	8401250163	83/11/02	50-266 F	8401030089	8401030015	83/09/20	40-86
70082	8401170129	83/10/31	FOIA	8401030092	8401030015	83/09/20	40-86
10319	8401250163	83/11/02	50-382 F	8401030096	8401030015	83/09/20	40-86
60028	8401250163	83/11/02	50-266 F	8401030097	8401030015	83/09/20	40-86
60032	8401250163	83/11/02	50-266 F	8401030102	8401030015	83/09/20	40-86
70298	8401160001	83/12/30	50-220 P	8401030103	8401030015	83/09/20	40-86
70279	8401040107	83/11/28	50-313 Q	8401030104	8401030015	83/09/20	40-86
50373	8401040107	83/11/28	50-313 Q	8401030105	8401030015	83/09/20	40-86
80433	8401170129	83/10/31	FOIA	8401030107	8401030015	83/09/20	40-86
70529	8310310465	83/10/18	ACRS	8401030110	8401030015	83/09/20	40-86
70537	8310310465	83/10/18	ACRS	8401030111	8401030015	83/09/20	40-86
10227	8401180146	84/01/13	50-219 P	8401030113	8401030106	83/12/28	50-344 P
10400	8311300135	83/10/20	REVIEW ORP	8401030114	8401030015	83/09/20	40-86
30072	8401250447	84/01/10	MISC	8401030115	8401030015	83/09/20	40-86
30076	8401250447	84/01/10	MISC	8401030117	8401030015	83/09/20	40-86
70199	8401230494	84/01/17	50-443 F	8401030118	8401030015	83/09/20	40-86
10265	8310310465	83/10/18	ACRS	8401030122	8401030015	83/09/20	40-86
80277	8401040044	83/10/27	50-329 A	8401030124	8401030015	83/09/20	40-86
50595	8312050590	83/11/18	50-369 P	8401030125	8401030015	83/09/20	40-86
50598	8312050590	83/11/18	50-369 P	8401030127	8401030015	83/09/20	40-86
60211	8401090520	83/12/30	50-309 P	8401030130	8401030015	83/09/20	40-86
60347	8401200115	84/01/18	50-244 P	8401030131	8401030015	83/09/20	40-86
60402	8311280178	83/11/29	50-423 K	8401030132	8401030015	83/09/20	40-86
60405	8311280178	83/11/29	50-423 K	8401030133	8401030126	83/12/26	50-445 Q
40235	8312140234	83/12/12	50-237 P	8401030138	8401030015	83/09/20	40-86
40236	8312140234	83/12/12	50-237 P	8401030139	8401030015	83/09/20	40-86
40237	8312140234	83/12/12	50-237 P	8401030140	8401030015	83/09/20	FOIA
40428	8401120100	83/12/19	50-313 P	8401030141	8401030136	83/12/21	50-443 Q
50273	8312150272	83/12/02	70-398	8401030142	8401030015	83/09/20	40-86
90225	8312190222	83/12/09	50-341 Q	8401030146	8401030015	83/09/20	FOIA
90346	8312120101	83/12/27	50-322 A	8401030147	8401030015	83/09/20	40-86
00086	8312260076	83/12/06	50-321 P	8401030151	8401030015	83/09/20	40-86
00087	8312260076	83/12/06	50-321 P	8401030154	8401030015	83/09/20	40-86
00359	8312260353	83/12/15	50-289 Q	8401030156	8401030015	83/09/20	40-86
00580	8312260575	83/11/29	TOPREP	8401030157	8401030149	83/12/27	50-142 Q
10014	8401030286	83/12/20	NUREG	8401030161	8401030015	83/09/20	40-86
20016	8401250008	84/01/09	REVIEW ORP	8401030164	8401030015	83/09/20	40-86
30302	8401250388	83/12/30	50-387 F	8401030168	8401030015	83/09/20	40-86
70074	8312200154	83/12/16	50-206 P	8401030171	8401030015	83/09/20	40-86
70199	8401200171	84/01/10	50-352 A	8401030172	8401030166	83/12/29	50-213 P
90264	8312290261	83/12/15	50-312 Q	8401030173	8401030166	83/12/29	50-213 P
00296	8401110392	84/01/04	NUREG	8401030176	8401030169	83/12/16	50-5 Q
30016	8401030015	83/09/20	40-86	8401030178	8401030015	83/09/20	40-86
30017	8401030015	83/09/20	40-86	8401030181	8401030015	83/09/20	40-86
30018	8401030015	83/09/20	FOIA	8401030188	8401030015	83/09/20	40-86
30020	8401030015	83/09/20	40-86	8401030191	8401030015	83/09/20	40-86
30021	8401030015	83/09/20	40-86	8401030192	8401030185	83/12/27	50-142 Q
30022	8401030015	83/09/20	40-86	8401030195	8401030015	83/09/20	40-86
30024	8401030015	83/09/20	40-86	8401030200	8401030015	83/09/20	40-86
30025	8401030015	83/09/20	40-86	8401030203	8401030197	83/12/20	50-461 K
30027	8401030015	83/09/20	40-86	8401030206	8401030201	83/12/21	50-409 P
30029	8401030015	83/09/20	40-86	8401030211	8401030208	83/12/23	50-266 P
30031	8401030015	83/09/20	40-86	8401030222	8401030219	83/12/09	50-271 F
30033	8401030015	83/09/20	40-86	8401030230	8401030226	83/12/12	50-312 Q
30036	8401030015	83/09/20	40-86	8401030237	8401030234	83/12/14	50-289 Q
30040	8401030015	83/09/20	40-86	8401030241	8401030234	83/12/14	50-289 Q
30042	8401030015	83/09/20	40-86	8401030243	8401030239	83/12/16	50-322 S
30045	8401030015	83/09/20	40-86	8401030249	8401030244	83/12/21	50-272 F
30046	8401030015	83/09/20	40-86	8401030252	8401030251	83/10/13	50-259 F

CROSS REFERENCE OF ENCLOSURES TO
PRINCIPAL DOCUMENTS

547

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401030254	8401030253	83/12/21	50-377 Q	8401040180	8401040019	83/10/14	FOIA
8401030256	8401030255	83/12/14	50-289 Q	8401040181	8401040179	83/12/28	50-293 P
8401030262	8401030259	83/12/14	50-322 Q	8401040184	8401040019	83/10/14	FOIA
8401030263	8401030260	83/12/09	50-220 S	8401040191	8401040188	83/12/01	FOIA
8401030265	8401030260	83/12/09	50-220 S	8401040192	8401040019	83/10/14	FOIA
8401030267	8401030264	83/12/07	50-312 F	8401040194	8401040019	83/10/14	FOIA
8401030273	8401030269	83/12/14	50-322 Q	8401040196	8401040193	83/12/27	50-315 F
8401030280	8401030278	83/12/28	50-305 P	8401040201	8401040019	83/10/14	FOIA
8401030281	8401030278	83/12/28	50-305 P	8401040206	8401040019	83/10/14	FOIA
8401030290	8312120094	83/12/29	50-358 A	8401040211	8401040019	83/10/14	FOIA
8401030301	8401030297	83/12/16	50-352 D	8401040212	8401040107	83/11/28	50-313 G
8401030310	8401030299	83/12/08	CONTRACT	8401040215	8401040019	83/12/27	FOIA
8401030315	8401030313	83/12/27	50-305 F	8401040223	8401040213	83/12/28	70-734
8401030317	8401030313	83/12/27	50-305 F	8401040224	8401040019	83/10/14	FOIA
8401030322	8401030320	83/12/27	50-483 F	8401040227	8401040019	83/10/14	FOIA
8401030323	8401030318	83/12/23	50-317 P	8401040228	8401040225	83/10/21	FOIA
8401030326	8401030320	83/12/27	50-483 F	8401040231	8401040019	83/10/14	FOIA
8401030337	8401030332	83/12/27	50-322 F	8401040236	8401040019	83/10/14	FOIA
8401030339	8401030332	83/12/27	50-322 F	8401040238	8401040019	83/10/14	FOIA
8401030341	8401030332	83/12/27	50-322 F	8401040241	8401040019	83/10/14	FOIA
8401030345	8401030329	83/12/09	CONTRACT	8401040243	8401040232	83/12/27	50-263 G
8401030347	8401030344	83/12/27	50-280 F	8401040246	8401040019	83/10/14	FOIA
8401030357	8401030353	83/12/27	50-338 F	8401040251	8401040019	83/10/14	FOIA
8401030365	8401030359	83/12/27	50-309 F	8401040258	8401040019	83/10/14	FOIA
8401030367	8401030359	83/12/27	50-309 F	8401040259	8401040253	83/10/14	40-8102
8401030369	8401030361	83/12/14	CONTRACT	8401040264	8401040019	83/10/14	FOIA
8401030374	8401030371	83/12/27	50-348 F	8401040269	8401040253	83/10/14	40-8102
8401030379	8401030375	83/12/19	CONTRACT	8401040271	8401040019	83/10/14	FOIA
8401030389	8401030382	83/12/14	CONTRACT	8401040272	8401040265	83/12/30	50-335 F
8401030397	8312120095	83/12/29	50-275 E	8401040273	8401040267	83/12/06	50-298 G
8401040015	8401040014	83/12/27	50-322 F	8401040274	8401040019	83/10/14	40-8833
8401040018	8401040014	83/12/27	50-322 F	8401040275	8401040270	83/12/16	50-368 P
8401040020	8401040014	83/12/27	50-322 F	8401040278	8401040268	83/12/27	50-373 G
8401040022	8401040017	83/12/27	50-358 R	8401040280	8401040267	83/12/06	50-298 G
8401040023	8401040019	83/10/14	FOIA	8401040281	8401040277	83/12/12	50-440 G
8401040025	8401040017	83/12/27	50-358 R	8401040282	8401040019	83/10/14	40-5508
8401040028	8401040019	83/10/14	FOIA	8401040285	8401040277	83/12/12	50-440 G
8401040029	8401040019	83/10/14	FOIA	8401040287	8401040019	83/10/14	70-83
8401040031	8401040017	83/12/27	50-358 R	8401040289	8401040279	83/12/30	50-280 G
8401040046	8401040041	83/12/19	CONTRACT	8401040291	8401040267	83/12/06	50-298 G
8401040048	8401040044	83/10/27	FOIA	8401040293	8401040290	83/12/30	50-285 P
8401040051	8401040019	83/10/14	FOIA	8401040294	8401040019	83/10/14	FOIA
8401040052	8401040044	83/10/27	50-329 A	8401040296	8401040019	83/10/14	FOIA
8401040055	8401040019	83/10/14	FOIA	8401040300	8401040295	83/12/29	50-352 Q
8401040058	8401040019	83/10/14	FOIA	8401040326	8401040322	83/12/21	50-281 S
8401040061	8401040019	83/10/14	FOIA	8401040330	8401040322	83/12/21	50-281* S
8401040064	8401040057	83/12/16	50-352 D	8401040331	8401040325	83/12/21	50-280 S
8401040066	8401040019	83/10/14	FOIA	8401040337	8401040325	83/12/21	50-280 S
8401040071	8401040019	83/10/14	FOIA	8401040348	8401040346	83/12/20	50-244 P
8401040076	8401040019	83/10/14	FOIA	8401040349	8401040347	83/12/21	50-366 P
8401040080	8401040019	83/10/14	FOIA	8401040350	8401040346	83/12/20	50-244 P
8401040083	8401040019	83/10/14	FOIA	8401040353	8401040352	83/12/28	50-250 P
8401040084	8401040077	83/12/15	50-334 Q	8401040362	8401040355	83/12/21	50-316 S
8401040092	8401040019	83/10/14	70-938	8401040364	8401040363	83/10/31	50-285 G
8401040094	8401040019	83/10/14	70-938	8401040367	8401040355	83/12/21	50-316 S
8401040095	8401040091	83/12/28	50-352 A	8401040373	8401040369	83/12/21	50-280 S
8401040098	8401040019	83/10/14	70-938	8401040376	8401040369	83/12/21	50-280 S
8401040104	8401040019	83/10/14	FOIA	8401040377	8401040374	83/10/26	50-482 G
8401040111	8401040107	83/11/28	50-313 Q	8401040380	8401040375	83/12/16	50-254 Q
8401040112	8401040103	83/12/21	50-416 Q	8401040387	8401040383	83/12/29	50-286 P
8401040115	8401040019	83/10/14	FOIA	8401040388	8401040385	83/12/02	GA999
8401040120	8401040019	83/10/14	FOIA	8401040392	8401040383	83/12/29	50-286 P
8401040124	8401040019	83/10/14	FOIA	8401040393	8401040385	83/12/02	GA999
8401040130	8401040019	83/10/14	FOIA	8401040394	8401040389	83/12/30	70-2887
8401040131	8401040123	83/12/22	50-348 S	8401040395	8401040385	83/12/02	GA999
8401040136	8401040019	83/10/14	FOIA	8401040403	8401040401	83/12/19	50-333 G
8401040134	8401040123	83/12/22	50-348 S	8401040405	8401040421	83/12/19	50-333 G
8401040140	8401040123	83/12/22	50-348 S	8401040411	8401040407	83/11/21	50-285 Q
8401040141	8401040019	83/10/14	FOIA	8401040417	8401040415	83/12/29	50-289 P
8401040148	8401040019	83/10/14	FOIA	8401040425	8401040421	83/11/22	50-482 G
8401040151	8401040019	83/10/14	FOIA	8401040427	8401040423	83/12/19	50-317 Q
8401040152	8401040145	83/11/29	50-382 Q	8401040429	8401040424	83/12/27	50-338 P
8401040156	8401040019	83/10/14	FOIA	8401040430	8401040423	83/12/19	50-317 Q
8401040161	8401040019	83/10/14	FOIA	8401040432	8401040422	83/12/12	50-482 G
8401040162	8401040155	83/12/27	40-86	8401040435	8401040421	83/11/22	50-482 G
8401040164	8401040159	83/09/29	FOIA	8401040438	8401040433	83/12/16	GA999
8401040166	8401040019	83/10/14	FOIA	8401040439	8401040422	83/12/12	50-482 G
8401040167	8401040163	83/12/15	50-334 Q	8401040449	8401040443	83/12/16	50-488 G
8401040172	8401040019	83/10/14	FOIA	8401040451	8401040446	83/11/25	50-285 G
8401040174	8401040019	83/10/14	FOIA	8401040452	8401040444	83/10/27	50-313 G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

548

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401040454	8401040443	83/12/16	50-458 Q	8401050090	8401050084	83/12/28	50-295 F
8401040456	8401040448	83/11/03	40-299 Q	8401050091	8401050040	83/10/04	FOIA
8401040457	8401040450	83/09/23	50-482 Q	8401050093	8401050040	83/10/04	FOIA
8401040459	8401040455	83/11/23	50-482 Q	8401050096	8401050092	83/12/28	50-289 F
8401040460	8401040443	83/12/16	50-458 Q	8401050098	8401050093	83/12/28	50-317 F
8401040466	8401040455	83/11/23	50-482 Q	8401050100	8401050040	83/10/04	FOIA
8401040470	8401040443	83/12/16	50-458 Q	8401050101	8401050093	83/12/28	50-317 F
8401040472	8401040463	83/11/03	50-298 Q	8401050102	8401050099	83/12/28	50-254 F
8401040473	8401040467	83/11/15	40-8584	8401050103	8401050040	83/10/04	FOIA
8401040475	8401040467	83/11/15	40-8584	8401050105	8401050097	83/12/14	CONTRACT
8401040480	8401040464	83/12/28	50-483 Q	8401050106	8401050040	83/10/04	FOIA
8401040481	8401040477	83/09/23	50-298 Q	8401050109	8401050040	83/10/04	FOIA
8401040486	8401040477	83/09/23	50-298 Q	8401050111	8401050107	83/12/28	50-395 F
8401040488	8401040482	83/12/06	QA999	8401050113	8401050040	83/10/04	FOIA
8401040490	8401040484	83/10/20	40-4492	8401050114	8401050110	83/12/28	50-338 F
8401040492	8401040482	83/12/06	QA999	8401050117	8401050040	83/10/04	FOIA
8401040494	8401040471	83/10/24	50-285 Q	8401050119	8401050115	83/12/28	50-289 F
8401040498	8401040482	83/12/06	QA999	8401050120	8401050040	83/10/04	FOIA
8401040499	8401040491	83/11/16	50-443 Q	8401050123	8401050040	83/10/04	FOIA
8401040503	8401040501	83/12/23	50-334 P	8401050126	8401050121	83/12/28	50-346 F
8401040510	8401040506	83/11/03	40-299 Q	8401050127	8401050040	83/10/04	FOIA
8401040514	8401040506	83/11/03	40-299 Q	8401050128	8401050124	83/12/28	50-322 F
8401040515	8401040468	83/12/07	50-324 P	8401050130	8401050040	83/10/04	FOIA
8401040519	8401040468	83/12/07	50-324 P	8401050131	8401050118	83/12/12	CONTRACT
8401040527	8401040468	83/12/07	50-324 P	8401050132	8401050124	83/12/28	50-322 F
8401040529	8401040524	83/09/21	50-283 Q	8401050133	8401050040	83/10/04	FOIA
8401040543	8401040538	83/12/27	50-389 F	8401050137	8401050040	83/10/04	FOIA
8401040550	8401040543	83/12/28	QA999	8401050138	8401050040	83/10/04	FOIA
8401040553	8401040545	83/12/28	QA999	8401050141	8401050134	83/12/28	50-483 F
8401040558	8401040545	83/12/28	QA999	8401050143	8401050040	83/10/04	FOIA
8401040559	8401040553	83/12/07	50-498 Q	8401050146	8401050134	83/12/28	50-483 F
8401040570	8401040563	83/10/31	50-482 Q	8401050152	8401050147	83/12/08	QA999
8401040574	8401040569	83/12/81	50-322 Q	8401050153	8401050144	83/10/20	CONTRACT
8401040580	8401040571	83/11/09	40-1162	8401050158	8401050144	83/11/30	TOPREP
8401040591	8401040571	83/11/09	40-1162	8401050174	8401050144	83/11/30	TOPREP
8401040597	8401040593	83/12/28	50-395 P	8401050189	8401050171	83/10/21	FOIA
8401040607	8401040604	83/10/21	FOIA	8401050192	8401050171	83/10/21	FOIA
8401040624	8401040619	83/12/22	50-29 Q	8401050194	8401050190	83/12/06	QA999
8401040628	8401040626	83/12/28	50-289 F	8401050197	8401050190	83/12/06	QA999
8401040630	8401040629	83/12/28	50-155 F	8401050217	8401050214	83/12/06	QA999
8401040632	8401040631	83/12/27	50-382 F	8401050219	8401050198	83/12/29	50-324 P
8401040633	8401040631	83/12/27	50-382 F	8401050222	8401050214	83/12/06	QA999
8401050005	8401050003	83/12/27	50-397 F	8401050226	8401050224	83/12/06	QA999
8401050011	8401050008	83/12/12	70-1151	8401050232	8401050224	83/12/06	QA999
8401050020	8401050016	83/12/14	CONTRACT	8401050235	8401050227	83/12/28	50-289 F
8401050025	8401050023	83/12/28	50-280 F	8401050237	8401050228	83/12/06	QA999
8401050030	8401050018	83/12/28	50-155 F	8401050244	8401050239	83/12/28	50-295 F
8401050031	8401050026	83/12/27	50-329 F	8401050257	8401050251	83/12/28	50-254 F
8401050034	8401050029	83/12/15	50-324 P	8401050261	8401050251	83/12/28	50-254 F
8401050037	8401050033	83/12/27	50-320 F	8401050264	8401050259	83/12/22	50-424 Q
8401050041	8401050029	83/12/15	50-324 P	8401050267	8401050259	83/12/22	50-424 Q
8401050044	8401050039	83/12/27	50-320 F	8401050272	8401050259	83/12/22	50-424 Q
8401050045	8401050040	83/10/04	FOIA	8401050276	8401050259	83/12/22	50-424 Q
8401050048	8401050029	83/12/15	50-324 P	8401050286	8401050281	83/12/21	50-440 Q
8401050049	8401050039	83/12/27	50-320 F	8401050300	8401050296	83/12/28	50-434 Q
8401050050	8401050035	83/12/28	50-344 F	8401050302	8401050297	83/12/29	50-463 Q
8401050051	8401050040	83/10/04	FOIA	8401050307	8401050297	83/12/29	50-463 Q
8401050052	8401050046	83/12/27	50-261 F	8401050309	8401050305	83/12/29	50-400 F
8401050054	8401050046	83/12/27	50-261 F	8401050310	8401050303	83/12/30	50-409 F
8401050056	8401050040	83/10/04	FOIA	8401050316	8401050313	83/12/30	50-247 F
8401050057	8401050029	83/12/15	50-324 P	8401050319	8401050315	83/12/30	50-155 F
8401050058	8401050035	83/12/28	50-344 F	8401050323	8401050311	83/12/05	50-438 Q
8401050060	8401050040	83/10/04	FOIA	8401050335	8401050327	83/12/05	50-369 Q
8401050061	8401050046	83/12/27	50-261 F	8401050338	8401050336	83/12/08	50-324 Q
8401050063	8401050055	83/12/28	50-373 F	8401050339	8401050337	83/12/21	40-8631
8401050065	8401050040	83/10/04	FOIA	8401050343	8401050342	83/12/23	50-436 Q
8401050068	8401050040	83/10/04	FOIA	8401050351	8401050348	83/12/27	70-1151
8401050070	8401050064	83/12/28	50-482 F	8401050352	8401050346	84/01/03	50-327 Q
8401050071	8401050040	83/10/04	FOIA	8401050355	8401050348	83/12/27	70-1151
8401050073	8401050040	83/10/04	FOIA	8401050357	8401050348	83/12/27	70-1151
8401050076	8401050040	83/10/04	FOIA	8401050361	8401050348	83/12/27	70-1151
8401050077	8401050072	83/12/28	50-277 F	8401050372	8401050360	83/12/28	50-286 F
8401050078	8401050040	83/10/04	FOIA	8401050374	8401050360	83/12/28	50-286 F
8401050080	8401050040	83/10/04	FOIA	8401050380	8401050378	83/12/06	50-324 Q
8401050082	8401050040	83/10/04	FOIA	8401050384	8401050379	83/12/28	50-335 Q
8401050083	8401050040	83/10/04	FOIA	8401050387	8401050379	83/12/28	50-335 Q
8401050085	8401050075	83/10/25	50-285 B	8401050389	8401050379	83/12/28	50-335 Q
8401050086	8401050081	83/12/28	50-213 F	8401050390	8401050388	83/12/22	50-400 Q
8401050087	8401050074	83/12/14	CONTRACT	8401050392	8401050388	83/12/22	50-400 Q
8401050088	8401050040	83/10/04	FOIA	8401050394	8401050379	83/12/28	50-335 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

549

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
-----------	--------------------	-------------	------------------

1050395	8401050388	83/12/22	50-400 Q
1050398	8401050388	83/12/22	50-400 Q
1050404	8401050400	83/12/28	50-280 F
1050406	8401050400	83/12/28	50-280 F
1050417	8401050412	83/12/28	50-317 F

1050421	8401050418	83/12/23	50-424 Q
1050427	8401050425	84/01/03	50-29 P
1050432	8401050425	84/01/03	50-29 P
1050435	8401050433	83/12/09	70-1201
1050436	8401050425	84/01/03	50-29 P

1050440	8401050425	84/01/03	50-29 P
1050447	8401050444	83/12/07	50-280 Q
1050448	8401050445	83/12/20	50-348 G
1050456	8401050452	83/12/28	50-259 G
1050457	8401050454	83/12/01	50-324 G

1050459	8401050455	84/01/03	50-289 Q
1050462	8401050452	83/12/28	50-259 G
1050465	8401050452	83/12/28	50-259 G
1050472	8401050452	83/12/28	50-259 G
1050477	8401050468	83/12/02	50-259 G

1050480	8401050473	83/12/15	50-280 G
1050483	8401050473	83/12/15	50-280 G
1050490	8401050481	83/12/19	50-324 G
1050492	8401050486	83/12/02	50-369 G
1050493	8401050473	83/12/15	50-280 G

1050496	8401050482	83/12/20	50-338 Q
1050498	8401050473	83/12/15	50-280 G
1050503	8401050473	83/12/15	50-280 G
1050504	8401050488	83/12/06	50-400 G
1050506	8401050499	83/12/01	50-395 G

1050508	8401050482	83/12/20	50-338 Q
1050510	8401050481	83/12/19	50-324 Q
1050514	8401050481	83/12/19	50-324 Q
1050517	8401050473	83/12/15	50-280 G
1050519	8401050482	83/12/20	50-338 Q

1050523	8401050515	83/12/21	50-390 Q
1050525	8401050481	83/12/19	50-324 Q
1050529	8401050515	83/12/21	50-390 Q
1050532	8401050522	83/12/16	50-250 Q
1050533	8401050520	83/12/21	70-27

1050537	8401050515	83/12/21	50-390 Q
1050539	8401050482	83/12/20	50-338 Q
1050540	8401050522	83/12/16	50-250 Q
1050541	8401050515	83/12/21	50-390 Q
1050546	8401050515	83/12/21	50-390 Q

1050550	8401050522	83/12/16	50-250 Q
1050551	8401050543	84/01/03	50-302 Q
1050559	8401050543	84/01/03	50-302 Q
1050562	8401050545	83/12/06	50-369 Q
1050563	8401050522	83/12/16	50-250 Q

1050568	8401050543	84/01/03	50-302 Q
1050575	8401050557	83/12/14	50-338 Q
1050579	8401050555	83/12/15	50-338 Q
1050582	8401050571	83/12/21	50-390 Q
1050584	8401050577	83/12/27	50-368 F

1050587	8401050571	83/12/21	50-390 Q
1050588	8401050557	83/12/14	50-338 Q
1050594	8401050555	83/12/15	50-338 Q
1050596	8401050571	83/12/21	50-390 Q
1050598	8401050557	83/12/14	50-338 Q

1050605	8401050555	83/12/15	50-338 Q
1050606	8401050560	83/12/16	50-348 Q
1050608	8401050599	83/12/08	70-27
1050609	8401050603	84/01/03	50-358 A
1050610	8401050571	83/12/21	50-390 Q

1050611	8401050560	83/12/16	50-348 Q
1050612	8401050602	83/12/21	50-302 Q
1050614	8401050557	83/12/14	50-338 Q
1050616	8401050560	83/12/16	50-348 Q
1050619	8401050602	83/12/21	50-302 Q

1050622	8401050555	83/12/15	50-338 Q
1050626	8401050560	83/12/16	50-348 Q
1050629	8401050602	83/12/21	50-302 Q
1050633	8401050621	83/12/09	50-321 Q
1050635	8401050602	83/12/21	50-302 Q

1050639	8401050634	84/01/03	50-361 P
1050640	8401050602	83/12/21	50-302 Q
1050648	8401050602	83/12/21	50-302 Q
1050653	8401050649	83/12/08	50-259 Q
1050664	8401050653	83/12/20	50-280 Q

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
-----------	--------------------	-------------	------------------

8401050668	8401050660	83/12/08	50-424 Q
8401050671	8401050653	83/12/20	50-280 Q
8401050672	8401050665	83/12/09	50-413 Q
8401050676	8401050653	83/12/20	50-280 Q
8401050681	8401050653	83/12/20	50-280 Q

8401060020	8401060014	83/12/28	50-335 F
8401060022	8401060018	83/12/28	50-483 F
8401060025	8401060014	83/12/28	50-335 F
8401060032	8401060027	83/12/28	50-317 F
8401060037	8401060018	83/12/28	50-483 F

8401060041	8401060035	83/12/28	50-483 F
8401060067	8401060051	84/01/03	50-239 P
8401060072	8401060068	83/12/28	50-271 F
8401060076	8401060068	83/12/28	50-271 F
8401060077	8401060074	83/12/28	50-244 F

8401060085	8401060081	83/12/28	50-269 F
8401060086	8401060082	83/12/28	50-346 F
8401060090	8401060081	83/12/28	50-269 F
8401060091	8401060082	83/12/28	50-346 F
8401060094	8401060081	83/12/28	50-269 F

8401060101	8401060097	83/12/28	50-327 F
8401060111	8401060103	83/12/27	50-320 F
8401060112	8401060107	83/12/28	50-155 F
8401060113	8401060106	83/12/28	50-280 F
8401060121	8401060115	83/12/27	50-348 F

8401060124	8401060118	83/12/27	50-155 F
8401060126	8401060115	83/12/27	50-348 F
8401060127	8401060122	83/12/28	50-272 F
8401060128	8401060118	83/12/27	50-155 F
8401060136	8401060122	83/12/28	50-272 F

8401060140	8401060132	83/12/27	50-324 F
8401060145	8401060132	83/12/27	50-324 F
8401060150	8401060040	83/10/20	50-10 Q
8401060151	8401060132	83/12/27	50-324 F
8401060152	8401060146	83/12/28	50-289 F

8401060155	8401060148	83/12/21	50-219 P
8401060158	8401060153	83/12/28	50-289 F
8401060161	8401060148	83/12/21	50-219 P
8401060165	8401060159	83/12/28	50-416 F
8401060169	8401060162	83/12/13	SECY

8401060171	8401060159	83/12/28	50-416 F
8401060185	8401060177	83/12/20	50-220 P
8401060186	8401060181	83/12/28	50-313 F
8401060188	8401060177	83/12/20	50-220 P
8401060192	8401060189	83/12/23	50-261 F

8401060196	8401060190	84/01/04	50-155 P
8401060200	8401060190	84/01/04	50-155 P
8401060201	8401060198	83/12/28	CONTRACT
8401060207	8401060203	83/12/14	CONTRACT
8401060219	8401060216	83/12/21	TOPREP

8401060222	8401060205	83/12/28	CONTRACT
8401060223	8401060215	83/12/14	CONTRACT
8401060249	8401060228	83/12/15	40-8602
8401060246	8401060228	83/12/15	40-8602
8401060257	8401060250	83/12/06	40-8829

8401060259	8401060234	83/12/28	50-373 F
8401060266	8401060264	83/12/28	50-317 F
8401060274	8401060270	83/12/28	50-317 F
8401060278	8401060270	83/12/28	50-317 F
8401060286	8401060284	83/12/22	TOPREP

8401060288	8401060271	84/01/04	50-373 P
8401060294	8401060281	84/01/04	50-329 A
8401060311	8401060305	83/12/29	50-315 B
8401060315	8401060305	83/12/29	50-315 B
8401060317	8401060301	83/12/21	50-413 Q

8401060324	8401060319	83/12/29	50-387 R
8401060347	8401060341	83/12/09	State Prog
8401060392	8401060387	83/12/13	50-302 Q
8401060393	8401060387	83/12/13	50-302 Q
8401060397	8401060387	83/12/13	50-302 Q

8401060399	8401060396	83/12/30	PRDJ
8401060410	8401060408	83/12/21	50-348 Q
8401060426	8401060424	83/12/29	50-324 Q
8401060427	8401060424	83/12/29	50-324 Q
8401060428	8401060425	83/12/29	50-316 B

8401060429	8401060424	83/12/29	50-324 Q
8401060430	8401060425	83/12/29	50-316 B
8401060432	8401060424	83/12/29	50-324 Q
8401060435	8401060425	83/12/29	50-316 B
8401060437	8401060434	83/12/16	50-316 B

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401060440	8401060434	83/12/16	50-316 S	8401090389	8401090374	84/01/03	50-416 Q
8401060442	8401060431	83/12/15	50-250 Q	8401090394	8401090374	84/01/03	50-416 Q
8401060443	8401060441	83/12/29	50-390 Q	8401090398	8401090390	83/12/29	50-482 A
8401060447	8401060444	83/12/15	40-8011	8401090407	8401090396	84/01/05	50-387 P
8401060448	8401060441	83/12/29	50-390 Q	8401090409	8401090405	83/12/28	50-293 P
8401060450	8401060444	83/12/15	40-8011	8401090417	8401090396	84/01/05	50-387 P
8401060451	8401060444	83/12/15	40-8011	8401090425	8401090420	84/01/03	50-302 Q
8401060452	8401060431	83/12/15	50-250 Q	8401090428	8401090422	83/12/29	TOPREP
8401060453	8401060449	83/12/29	50-390 Q	8401090431	8401090426	83/12/30	50-424 Q
8401060455	8401060449	83/12/29	50-390 Q	8401090433	8401090420	84/01/03	50-302 Q
8401060458	8401060449	83/12/29	50-390 Q	8401090437	8401090426	83/12/30	50-424 Q
8401060460	8401060449	83/12/29	50-390 Q	8401090439	8401090426	83/12/30	50-424 Q
8401060462	8401060449	83/12/29	50-390 Q	8401090442	8401090436	83/12/29	50-454 M
8401060467	8401060465	83/12/27	50-348 S	8401090443	8401090420	84/01/03	50-302 Q
8401060470	8401060441	83/12/29	50-390 Q	8401090445	8401090420	84/01/03	50-302 Q
8401060473	8401060465	83/12/27	50-348 S	8401090446	8401090426	83/12/30	50-424 Q
8401060478	8401060441	83/12/29	50-390 Q	8401090451	8401090420	84/01/03	50-302 Q
8401060481	8401060465	83/12/27	50-348 S	8401090459	8401090434	83/12/14	CONTRACT
8401060484	8401060480	83/12/30	50-409 R	8401090468	8401090464	83/12/30	50-424 Q
8401060488	8401060480	83/12/30	50-409 R	8401090472	8401090464	83/12/30	50-424 Q
8401060489	8401060465	83/12/27	50-348 S	8401090474	8401090464	83/12/30	50-424 Q
8401060491	8401060485	83/12/02	50-416 Q	8401090476	8401090464	83/12/30	50-424 Q
8401060493	8401060484	83/12/27	50-354 A	8401090480	8401090478	83/12/16	50-390 Q
8401060500	8401060496	84/01/04	50-329 Q	8401090485	8401090477	84/01/04	50-352 E
8401060503	8401060498	83/11/29	XPORTLIC	8401090487	8401090483	83/12/30	QA999
8401060536	8401060531	83/12/14	MISC	8401090488	8401090486	83/12/30	QA999
8401060545	8401060531	83/12/14	MISC	8401090489	8401090483	83/12/30	QA999
8401060625	8401060619	83/12/07	71-511	8401090490	8401090477	84/01/04	50-352 E
8401060639	8401090544	83/12/29	50-416 P	8401090491	8401090483	83/12/30	QA999
8401060640	8401060634	83/12/14	CONTRACT	8401090493	8401090483	83/12/30	QA999
8401060648	8401060645	83/12/14	CONTRACT	8401090494	8401090477	84/01/04	50-352 E
8401060674	8401060671	83/12/13	40-8768	8401090501	8401090500	83/12/30	50-338 P
8401090056	8401090041	83/12/15	50-338 Q	8401090502	8401090498	83/12/12	50-390 Q
8401090083	8401090066	83/12/13	50-332 A	8401090522	8401090520	83/12/30	50-309 P
8401090104	8401090099	83/12/15	50-369 Q	8401090526	8401090525	83/12/30	QA999
8401090108	8401090101	83/12/20	50-458 M	8401090530	8401090525	83/12/30	QA999
8401090109	8401090103	83/12/20	50-390 Q	8401090532	8401090525	83/12/30	QA999
8401090117	8401090111	83/12/14	50-553 Q	8401090554	8401090405	83/12/28	50-293 P
8401090119	8401090114	83/12/20	50-261 Q	8401090556	8401090405	83/12/28	50-293 P
8401090121	8401090112	83/12/20	70-143	8401090599	8401090477	84/01/04	50-352 E
8401090124	8401090110	83/12/23	50-298 Q	8401090602	8401090598	83/12/21	XPORTLIC
8401090137	8401090110	83/12/23	50-298 Q	8401090609	8401090477	84/01/04	50-352 E
8401090134	8401090145	83/12/14	50-566 U	8401090619	8401090477	84/01/04	50-352 E
8401090135	8401090128	84/01/03	50-438 Q	8401090631	8401090477	84/01/04	50-352 E
8401090138	8401090131	83/12/14	50-324 Q	8401090632	8401090477	84/01/04	50-352 E
8401090141	8401090128	84/01/03	50-438 Q	8401090636	8401090477	84/01/04	50-352 E
8401090144	8401090128	84/01/03	50-438 Q	8401090637	8401090477	84/01/04	50-352 E
8401090145	8401090142	84/01/05	50-373 P	8401090638	8401090477	84/01/04	50-352 E
8401090150	8401090128	84/01/03	50-438 Q	8401090641	8401090477	84/01/04	50-352 E
8401090192	8401090182	83/12/21	XPORTLIC	8401090642	8401090477	84/01/04	50-352 E
8401090201	8401090195	83/12/16	50-321 Q	8401090646	8401090477	84/01/04	50-352 E
8401090214	8401090205	83/11/21	40-8768	8401090650	8401090477	84/01/04	50-352 E
8401090219	8401090216	83/12/16	50-269 Q	8401090651	8401090633	83/12/19	50-280 P
8401090230	8401090225	83/12/15	50-270 Q	8401090654	8401090477	84/01/04	50-352 E
8401090242	8401090223	83/12/20	50-454 K	8401090657	8401090477	84/01/04	50-352 E
8401090244	8401090208	83/12/15	50-335 Q	8401090658	8401090477	84/01/04	50-352 E
8401090248	8401090241	83/12/30	QA999	8401090661	8401090477	84/01/04	50-352 E
8401090252	8401090246	83/12/15	50-335 Q	8401090665	8401090477	84/01/04	50-352 E
8401090262	8401090255	83/12/15	50-395 Q	8401090666	8401090477	84/01/04	50-352 E
8401090264	8401090237	83/12/20	50-299 Q	8401090668	8401090477	84/01/04	50-352 E
8401090275	8401090265	84/01/03	50-331 F	8401090671	8401090477	84/01/04	50-352 E
8401090277	8401090267	83/12/15	50-327 Q	8401090672	8401090477	84/01/04	50-352 E
8401090280	8401090265	84/01/03	50-331 F	8401090674	8401090477	84/01/04	50-352 E
8401090281	8401090272	84/01/04	50-443 Q	8401090675	8401090477	84/01/04	50-352 E
8401090292	8401090284	83/12/14	50-416 Q	8401090677	8401090477	84/01/04	50-352 E
8401090295	8312300202	83/12/19	REVIEW GRP	8401090679	8401090477	84/01/04	50-352 E
8401090315	8401090312	84/01/03	50-289 P	8401090681	8401090477	84/01/04	50-352 E
8401090328	8401090321	83/12/28	50-243 F	8401090684	8401090477	84/01/04	50-352 E
8401090336	8401090323	84/01/03	50-302 Q	8401090687	8401090477	84/01/04	50-352 E
8401090346	8401090335	84/01/03	50-400 Q	8401090688	8401090477	84/01/04	50-352 E
8401090348	8401090334	83/12/30	50-352 F	8401090691	8401090477	84/01/04	50-352 E
8401090352	8401090323	84/01/03	50-302 Q	8401090692	8401090477	84/01/04	50-352 E
8401090355	8401090323	84/01/03	50-302 Q	8401090695	8401090477	84/01/04	50-352 E
8401090357	8401090350	83/12/15	50-518 Q	8401090698	8401090477	84/01/04	50-352 E
8401090361	8401090323	84/01/03	50-302 Q	8401090701	8401090477	84/01/04	50-352 E
8401090368	8401090363	84/01/04	50-463 Q	8401090715	8401090704	83/12/23	50-250 P
8401090375	8401090366	84/01/03	50-329 Q	8401090728	8401090704	83/12/23	50-250 P
8401090380	8401090374	84/01/03	50-416 Q	8401090742	8401090736	83/12/22	CONTRACT
8401090384	8401090366	84/01/03	50-329 Q	8401090751	8401090704	83/12/23	50-250 P
8401090385	8401090374	84/01/03	50-416 Q	8401090754	8401090748	83/12/07	CONTRACT

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

551

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401090777	8401090775	83/12/21	70-1113	8401100358	8401100344	84/01/04	50-409 Q
8401090786	8401090783	83/12/21	50-470 A	8401100359	8401100339	83/12/30	50-483 Q
8401100003	8401100001	83/12/22	50-341 Q	8401100363	8401100334	84/01/03	50-320 Q
8401100005	8401100001	83/12/22	50-341 Q	8401100364	8401100361	84/01/03	50-220 P
8401100025	8401100020	83/09/27	FOIA	8401100369	8401100344	84/01/04	50-409 Q
8401100030	8401100020	83/09/27	FOIA	8401100372	8401100365	83/12/23	50-352 Q
8401100037	8401100020	83/09/27	FOIA	8401100381	8401100370	83/12/23	50-410 Q
8401100040	8401100020	83/09/27	FOIA	8401100382	8401100374	83/11/21	50-266 Q
8401100045	8401100042	83/12/14	CONTRACT	8401100389	8401100376	83/12/23	50-388 Q
8401100049	8401100048	83/12/30	50-266 P	8401100396	8401100390	83/12/30	50-348 S
8401100054	8401100051	83/12/23	50-358 Q	8401100397	8401100391	83/12/21	50-288 Q
8401100059	8401100056	83/12/23	50-358 Q	8401100398	8401100393	83/12/28	50-320 Q
8401100072	8401100069	83/12/20	50-483 Q	8401100400	8401100385	83/12/21	50-272 Q
8401100076	8401100069	83/12/20	50-483 Q	8401100403	8401100390	83/12/30	50-348 S
8401100084	8401100082	83/10/11	FOIA	8401100410	8401100405	84/01/06	50-482 A
8401100087	8401100082	83/10/11	FOIA	8401100413	8401100404	83/12/27	50-312 Q
8401100090	8401100082	83/10/11	FOIA	8401100415	8401100409	84/01/04	50-249 P
8401100095	8401100092	83/12/16	CONTRACT	8401100416	8401100401	83/12/23	50-440 Q
8401100098	8401100082	83/10/11	FOIA	8401100419	8401100408	83/12/30	50-272 Q
8401100102	8401100082	83/10/11	FOIA	8401100421	8401100409	84/01/04	50-249 P
8401100103	8401100099	83/12/13	40-8054	8401100425	8401100420	84/01/06	50-302 Q
8401100105	8401100082	83/10/11	FOIA	8401100434	8401100428	84/01/05	50-454 Q
8401100107	8401100082	83/10/11	FOIA	8401100436	8401100430	84/01/05	50-16 Q
8401100111	8401100082	83/10/11	FOIA	8401100437	8401100424	83/09/16	0A999
8401100114	8401100110	83/12/14	CONTRACT	8401100438	8401100435	83/12/23	70-2427
8401100116	8401100082	83/10/11	FOIA	8401100440	8401100432	83/12/20	50-263 Q
8401100118	8401100082	83/10/11	FOIA	8401100442	8401100431	83/12/23	50-309 Q
8401100123	8401100121	83/12/30	CONTRACT	8401100443	8401100424	83/09/16	0A999
8401100125	8401100119	83/12/14	CONTRACT	8401100446	8401100441	83/12/21	50-423 Q
8401100129	8401100122	84/01/07	WASTE MGT	8401100453	8401100424	83/09/16	0A999
8401100130	8401100127	83/12/30	50-317 P	8401100462	8401100424	83/09/16	0A999
8401100131	8401100127	83/12/30	50-317 P	8401100467	8401100424	83/09/16	0A999
8401100133	8401100126	84/01/09	50-413 U	8401100470	8401100460	83/12/23	50-333 Q
8401100138	8401100135	83/12/14	CONTRACT	8401100476	8401100471	84/01/03	REVIEW CRP
8401100143	8401100142	84/01/06	WASTE MGT	8401100477	8401100424	83/09/16	0A999
8401100156	8401100152	83/12/05	71-96	8401100480	8401100475	83/11/28	50-302 Q
8401100158	8401100155	84/01/03	50-247 Q	8401100482	8401100424	83/09/16	0A999
8401100163	8401100160	84/01/09	WASTE MGT	8401100486	8401100481	83/12/23	50-282 Q
8401100171	8401100166	83/11/22	50-315 P	8401100487	8401100424	83/09/16	0A999
8401100176	8401100170	83/12/23	50-317 Q	8401110011	8401110009	83/12/14	CONTRACT
8401100177	8401100175	83/12/21	70-820	8401110022	8401110018	83/12/14	CONTRACT
8401100179	8401100166	83/11/22	50-315 P	8401110038	8401110033	83/12/27	50-275 P
8401100194	8401100188	83/12/23	50-358 Q	8401110132	8401110130	84/01/06	50-390 K
8401100198	8401100196	84/01/06	WASTE MGT	8401110140	8401110134	83/10/13	70-698
8401100203	8401100199	83/12/23	50-334 Q	8401110164	8401110157	84/01/06	50-440 Q
8401100219	8401100215	84/01/06	50-454 Q	8401110167	8401110159	84/01/06	50-440 Q
8401100221	8401100210	84/01/06	50-329 Q	8401110186	8401110173	83/12/30	50-336 P
8401100224	8401100210	84/01/06	50-329 Q	8401110187	8401110183	84/01/09	50-275 Q
8401100228	8401100210	84/01/06	50-329 Q	8401110193	8401110188	83/12/28	50-282 P
8401100233	8401100227	83/12/22	50-387 Q	8401110194	8401110173	83/12/30	50-336 P
8401100234	8401100210	84/01/06	50-329 Q	8401110198	8401110196	83/12/27	50-344 P
8401100238	8401100210	84/01/06	50-329 Q	8401110200	8401110188	83/12/28	50-282 P
8401100241	8401100227	83/12/22	50-387 Q	8401110201	8401110196	83/12/27	50-344 P
8401100242	8401100232	84/01/08	WASTE MGT	8401110217	8401110213	84/01/07	50-289 Q
8401100244	8401100232	84/01/08	WASTE MGT	8401110218	8401110214	84/01/07	50-400 Q
8401100253	8401100250	83/11/15	0A999	8401110224	8401110214	84/01/09	50-400 Q
8401100255	8401100250	83/11/15	0A999	8401110226	8401110222	84/01/09	WASTE MGT
8401100256	8401100250	83/11/15	0A999	8401110245	8401110240	84/01/06	50-322 A
8401100257	8401100210	84/01/06	50-329 Q	8401110246	8401110239	83/12/30	TOPREP
8401100261	8401100210	84/01/06	50-329 Q	8401110247	8401110244	83/12/09	50-320 U
8401100268	8401100264	84/01/04	50-286 P	8401110250	8401110244	83/12/09	50-320 U
8401100272	8401100267	83/12/23	50-289 Q	8401110255	8401110244	83/12/09	50-320 U
8401100277	8401100270	83/12/22	50-277 Q	8401110258	8401110244	83/12/09	50-320 U
8401100285	8401100279	83/12/23	50-247 Q	8401110264	8401110244	83/12/09	50-320 U
8401100287	8401100270	83/12/22	50-277 Q	8401110273	8401110270	84/01/06	50-206 P
8401100289	8401100283	84/01/04	50-324 P	8401110275	8401110270	84/01/06	50-206 P
8401100296	8401100276	84/01/04	50-412 Q	8401110279	8401110270	84/01/06	50-206 P
8401100303	8401100302	84/01/05	50-331 Q	8401110281	8401110270	84/01/06	50-206 P
8401100308	8401100300	83/12/21	50-309 Q	8401110303	8401090334	83/12/30	50-352 K
8401100309	8401100304	84/01/05	50-302 R	8401110308	8401090334	83/12/30	50-352 C
8401100312	8401100303	84/01/05	50-271 Q	8401110309	8401110305	84/01/09	50-289 Q
8401100317	8401100301	83/12/27	50-272 P	8401110313	8401090334	83/12/30	50-352 A
8401100328	8401100320	83/12/23	50-443 Q	8401110316	8401110312	84/01/02	50-352 Q
8401100331	8401100322	83/12/21	50-322 Q	8401110319	8401110312	84/01/02	50-352 Q
8401100332	8401100325	83/12/23	50-213 Q	8401110321	8401110312	84/01/02	50-352 Q
8401100338	8401100333	83/12/28	50-245 P	8401110322	8401110312	84/01/02	50-352 Q
8401100351	8401100343	83/12/27	40-472	8401110324	8401110325	83/12/16	COMMISSION
8401100353	8401100339	83/12/30	50-483 A	8401110328	8401110327	83/12/08	50-289 U
8401100354	8401100334	84/01/03	50-320 Q	8401110329	8401110327	83/12/08	50-289 U
8401100355	8401100346	84/01/03	40-8046	8401110330	8401110304	83/12/28	50-266 P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

552

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401110332	8401110304	83/12/28	50-266 P
8401110333	8401110331	83/12/08	COMMISSION
8401110411	8401110403	83/12/27	MISC
8401110446	8401110441	83/12/01	40-8768
8401110486	8401110483	83/12/09	40-299
8401110526	8401110521	83/12/21	50-309 P
8401110531	8401110521	83/12/21	50-309 P
8401110531	8401110545	83/12/06	40-8452
8401110552	8401110546	83/12/27	50-366 G
8401110565	8401110563	83/12/30	71-9165
8401110567	8401110563	83/12/30	71-9165
84011120022	8401120019	83/12/23	WASTE MGT
84011120025	8401120019	83/12/23	WASTE MGT
84011120028	8401120019	83/12/23	WASTE MGT
84011120033	8401120019	83/12/23	WASTE MGT
84011120037	8401120019	83/12/23	WASTE MGT
84011120040	8401120019	83/12/23	WASTE MGT
84011120046	8401120019	83/12/23	WASTE MGT
84011120049	8401120019	83/12/23	WASTE MGT
84011120065	8401120019	83/12/23	WASTE MGT
84011120067	8401120019	83/12/23	WASTE MGT
84011120102	8401120097	83/12/13	CONTRACT
84011120104	8401120100	83/12/19	50-313 P
84011120106	8401120103	83/12/19	70-698
84011120120	8401120112	83/12/30	50-266 P
84011120137	8401120129	84/01/02	CONTRACT
84011120138	8401120122	83/12/30	CONTRACT
84011120176	8401120172	83/12/13	50-334 P
84011120179	8401120172	83/12/13	50-334 P
84011120183	8401120178	83/12/02	40-8102
84011120186	8401120172	83/12/13	50-334 P
84011120212	8401120207	83/12/28	50-275 P
84011120225	8401120222	83/12/28	50-483 Q
84011120229	8401120222	83/12/28	50-483 Q
84011120238	8401120227	83/12/30	50-315 Q
84011120255	8401120227	83/12/30	50-315 Q
84011120269	8401120264	84/01/09	50-289 Q
84011120282	8401120264	84/01/09	50-289 Q
84011120283	8401120279	83/12/14	50-395 R
84011120285	8401120279	83/12/14	50-395 R
84011120290	8401120279	83/12/14	50-395 R
84011120295	8401120279	83/12/14	50-395 R
84011120331	8401120316	84/01/10	WASTE MGT
84011120342	8401120337	84/01/04	50-400 Q
84011120349	8401120340	84/01/06	MISC
84011120351	8401120339	84/01/04	50-329 A
84011120361	8401120340	84/01/06	MISC
84011120382	8401120379	83/12/28	50-409 G
84011120394	8401120385	84/01/09	50-261 P
84011120407	8401120405	83/12/08	50-334 R
84011120443	8401120440	83/12/23	50-395 P
84011120445	8401120440	83/12/23	50-395 P
84011120451	8401120448	83/12/14	WASTE MGT
84011120527	8401120523	83/11/09	71-9190
84011120528	8401120524	83/12/16	50-259 P
84011120529	8401120524	83/12/16	50-259 P
84011120532	8401120523	83/11/09	71-9190
84011120533	8401120531	83/12/22	CONTRACT
84011120541	8401120534	83/12/21	CONTRACT
84011120553	8401120552	83/12/28	71-2957
84011120558	8401120556	83/12/14	CONTRACT
84011120569	8401120559	83/12/29	CONTRACT
84011120591	8401120585	83/12/23	50-295 P
84011120592	8401120590	83/12/21	CONTRACT
84011120601	8401120585	83/12/23	50-295 P
84011120608	8401120604	83/12/23	WASTE MGT
84011130008	8401130005	83/12/16	CONTRACT
84011130018	8401130013	83/12/15	CONTRACT
84011130020	8401130015	83/12/14	CONTRACT
84011130030	8401130026	83/12/30	50-348 P
84011130034	8401130028	83/12/16	QA999
84011130037	8401130032	83/12/23	CONTRACT
84011130038	8401130026	83/12/30	50-348 P
84011130041	8401130028	83/12/16	QA999
84011130042	8401130039	84/01/06	QA999
84011130046	8401130039	84/01/06	QA999
84011130051	8401130039	84/01/06	QA999
84011130055	8401130039	84/01/06	QA999
84011130071	8401130067	84/01/09	50-220 P
84011130074	8401130067	84/01/09	50-220 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
84011130089	8401130085	84/01/03	50-267 P
84011130107	8401130073	84/01/06	QA999
84011130129	8401130123	83/12/30	CONTRACT
84011130134	8401130131	84/01/09	50-272 G
84011130143	8401130131	84/01/09	50-272 G
84011130168	8401130163	84/01/04	QA999
84011130172	8401130169	84/01/06	50-482 G
84011130189	8401130186	83/12/16	QA999
84011130191	8401130188	83/12/16	QA999
84011130194	8401130190	84/01/07	50-289 F
84011130195	8401130186	83/12/16	QA999
84011130197	8401130188	83/12/16	QA999
84011130204	8401130188	83/12/30	QA999
84011130211	8401130203	84/01/10	50-266 G
84011130230	8401130226	83/12/13	QA999
84011130235	8401130226	83/12/13	QA999
84011130253	8401130249	84/01/09	50-317 G
84011130257	8401130250	84/01/03	50-324 P
84011130264	8401130262	83/12/16	50-324 P
84011130266	8401130250	84/01/03	50-324 P
84011130267	8401130262	83/12/16	QA999
84011130271	8401130262	83/12/16	QA999
84011130283	8401130250	84/01/03	50-324 P
84011130288	8401130261	84/01/06	50-267 P
84011130301	8401130298	84/01/09	50-546 G
84011130337	8401130331	84/01/04	50-316 G
84011130339	8401130332	83/08/02	50-313 G
84011130345	8401130331	84/01/04	50-316 G
84011130350	8401130348	83/12/16	QA999
84011130352	8401130348	83/12/16	QA999
84011130353	8401130331	84/01/04	50-316 G
84011130354	8401130348	83/12/16	QA999
84011130371	8401130369	83/12/05	QA999
84011130372	8401130369	83/12/05	QA999
84011130375	8401130369	83/12/05	QA999
84011130376	8401130369	83/12/05	QA999
84011130382	8401130380	83/12/20	QA999
84011130396	8401130390	83/12/30	50-267 P
84011130400	8401130390	83/12/30	50-267 P
84011130445	8401130443	84/01/11	CONTRACT
84011130447	8401130444	84/01/10	CONTRACT
84011160002	8401160001	83/12/30	50-220 P
84011160009	8401160005	83/12/28	50-260 P
84011160011	8401160008	83/12/19	50-259 P
84011160014	8401160008	83/12/19	50-259 P
84011160016	8401160015	83/12/30	WASTE MGT
84011160072	8401160069	84/01/06	50-397 P
84011160134	8401160125	84/01/12	50-219 P
84011160135	8401160128	84/01/09	50-282 Q
84011160139	8401160125	84/01/12	50-219 P
84011160179	8401160172	84/01/12	50-483 Q
84011160194	8401160187	84/01/11	50-155 P
84011160203	8401160187	84/01/11	50-155 P
84011160208	8401160187	84/01/11	50-155 P
84011160224	8401160220	84/01/06	50-358 A
84011160228	8401160220	84/01/06	50-358 A
84011160237	8401160232	84/01/06	50-13 P
84011160249	8401160247	84/01/10	50-142 Q
84011160271	8401160267	84/01/12	50-341 G
84011160277	8401160274	84/01/12	50-341 G
84011160281	8401160280	84/01/13	50-219 P
84011160284	8401160280	84/01/13	50-219 P
84011160288	8401160283	84/01/09	50-461 S
84011160297	8401160292	84/01/11	40-8760
84011160303	8401160301	84/01/11	50-293 Q
84011160305	8401160301	84/01/11	50-293 Q
84011160307	8401160301	84/01/11	50-293 Q
84011160370	8401160365	83/10/26	FOIA
84011160379	8401160373	83/11/09	FOIA
84011160396	8401160390	83/10/26	FOIA
84011160400	8401160390	83/10/26	FOIA
84011160402	8401160390	83/10/26	FOIA
84011160403	8401160390	83/10/26	FOIA
84011160407	8401160390	83/10/26	FOIA
84011160409	8401160391	84/01/04	CONTRACT
84011160428	8401160426	83/10/28	FOIA
84011160454	8401160452	83/10/21	FOIA
84011160462	8401160457	83/12/28	CONTRACT
84011160472	8401160460	83/10/14	FOIA
84011160474	8401160460	83/10/14	FOIA

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

553

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401160475	8401160460	83/10/14	FOIA	8401170527	8401170326	84/01/06	71-6058
8401170018	8401170015	83/10/25	FOIA	8401170530	8401170327	83/12/19	50-331 F
8401170021	8401170015	83/10/25	FOIA	8401170531	8401170327	83/12/19	50-331 F
8401170023	8401170015	83/10/25	FOIA	8401170537	8401170332	83/11/30	CONTRACT
8401170033	8401170029	83/10/11	FOIA	8401170549	8401170343	83/12/03	CONTRACT
8401170035	8401170029	83/10/11	FOIA	8401170561	8401170360	83/12/20	50-397 P
8401170036	8401170034	83/10/21	50-440 A	8401170562	8401170360	83/12/20	50-397 P
8401170038	8401170034	83/10/21	50-440 A	8401170563	8401170360	83/12/20	50-397 P
8401170042	8401170034	83/10/21	50-440 A	8401180003	8401180002	83/12/27	CONTRACT
8401170044	8401170034	83/10/21	50-440 A	8401180011	8401180006	84/01/09	50-282 F
8401170048	8401170034	83/10/21	50-440 A	8401180013	8401180009	83/10/11	50-528 A
8401170051	8401170034	83/10/21	50-440 A	8401180015	8401180006	84/01/09	50-282 F
8401170076	8401170052	83/10/03	FOIA	8401180016	8401180014	83/12/12	CONTRACT
8401170090	8401170052	83/10/03	FOIA	8401180017	8401180009	83/10/11	50-528 A
8401170099	8401170052	83/10/03	FOIA	8401180020	8401180009	83/10/11	50-528 A
8401170101	8401170052	83/10/03	FOIA	8401180022	8401180009	83/10/11	50-528 A
8401170104	8401170052	83/10/03	FOIA	8401180023	8401180018	83/12/30	50-362 P
8401170108	8401170052	83/10/03	FOIA	8401180024	8401180021	83/12/12	CONTRACT
8401170114	8401170052	83/10/03	FOIA	8401180025	8310310465	83/10/18	ACRB
8401170119	8401170113	83/12/30	CONTRACT	8401180026	8401180009	83/10/11	50-528 A
8401170141	8401170139	84/01/09	50-443 T	8401180028	8401180009	83/10/11	50-528 A
8401170142	8401170137	83/10/31	FOIA	8401180033	8401180009	83/10/11	50-528 A
8401170146	8401170144	84/01/12	WASTE MGT	8401180035	8310310465	83/10/18	ACRB
8401170153	8401170152	84/01/09	50-244 P	8401180036	8401180009	83/10/11	50-528 A
8401170159	8401170158	84/01/10	50-285 Q	8401180037	8401180031	83/12/29	50-328 A
8401170161	8401170156	84/01/11	50-275 P	8401180042	8401180009	83/10/11	50-528 A
8401170165	8401170156	84/01/11	50-275 P	8401180047	8401180009	83/10/11	50-528 A
8401170206	8401170194	84/01/10	50-358 R	8401180048	8401180043	83/12/03	50-333 P
8401170237	8401170233	84/01/13	50-400 Q	8401180052	8401180043	83/12/03	50-333 P
8401170239	8401170233	84/01/13	50-400 Q	8401180067	8401180009	83/10/11	50-528 A
8401170255	8401170253	84/01/13	50-289 Q	8401180071	8401180061	84/01/06	50-344 F
8401170264	8401170259	84/01/10	50-313 Q	8401180073	8401180009	83/10/11	50-528 A
8401170274	8401170269	84/01/10	50-280 F	8401180075	8401180009	83/10/11	50-528 A
8401170275	8401170272	84/01/06	71-4909	8401180077	8401180009	83/10/11	50-528 A
8401170278	8401170276	84/01/12	50-322 Q	8401180082	8401180009	83/10/11	50-528 A
8401170282	8401170277	83/12/23	GA999	8401180088	8401180009	83/10/11	50-528 A
8401170286	8401170271	84/01/16	50-70	8401180089	8401180009	83/10/11	FOIA
8401170289	8401170283	83/12/29	50-293 P	8401180090	8401180009	83/10/11	50-528 A
8401170325	8401170318	83/12/13	GA999	8401180094	8401180009	83/10/11	50-528 A
8401170327	8401170323	84/01/03	50-334 A	8401180097	8401180009	83/10/11	50-528 A
8401170328	8401170326	83/11/08	50-298 Q	8401180102	8401180009	83/10/11	50-528 A
8401170330	8401170326	83/11/08	50-298 Q	8401180106	8401180009	83/10/11	50-528 A
8401170337	8401170333	83/12/20	GA999	8401180116	8401180009	83/10/11	50-528 A
8401170341	8401170333	83/12/20	GA999	8401180123	8401180113	84/01/16	50-358 A
8401170344	8401170340	84/01/11	50-148 P	8401180135	8401180133	84/01/09	50-261 P
8401170355	8401170353	84/01/09	50-282 Q	8401180164	8401180156	84/01/12	50-390 F
8401170360	8401170359	84/01/10	50-413 A	8401180174	8401180163	84/01/06	50-373 F
8401170362	8401170356	84/01/10	50-244 Q	8401180175	8401180172	84/01/13	50-382 K
8401170363	8401170361	84/01/11	TOPREP	8401180197	8401180193	84/01/05	50-352 Q
8401170367	8401170361	84/01/11	TOPREP	8401180201	8401180193	84/01/05	50-352 Q
8401170370	8401170364	83/12/28	50-267 Q	8401180203	8401180196	84/01/03	50-247 Q
8401170371	8401170361	84/01/11	TOPREP	8401180211	8401180208	84/01/06	50-220 Q
8401170381	8401170373	84/01/13	50-369 Q	8401180218	8401180214	84/01/05	50-322 Q
8401170383	8401170378	84/01/12	50-328 Q	8401180224	8401180221	84/01/05	50-334 Q
8401170385	8401170380	84/01/13	50-329 R	8401180228	8401180222	84/01/13	50-413 Q
8401170389	8401170387	83/12/23	50-482 Q	8401180229	8401180226	83/06/10	50-220 P
8401170394	8401170387	83/12/23	50-482 Q	8401180231	8401180227	84/01/13	50-382 Q
8401170396	8401170391	84/01/05	50-440 A	8401180248	8401180242	84/01/05	50-352 Q
8401170398	8401170387	83/12/23	50-482 Q	8401180249	8401180237	84/01/03	50-245 Q
8401170399	8401170390	84/01/10	50-309 Q	8401180256	8401180246	84/01/06	50-317 F
8401170401	8401170397	84/01/12	50-320 Q	8401180257	8401180251	84/01/04	50-387 Q
8401170403	8401170391	84/01/05	50-440 A	8401180260	8401180146	84/01/13	50-219 P
8401170411	8401170391	84/01/05	50-440 A	8401180263	8401180246	84/01/06	50-317 F
8401170415	8401170410	83/12/13	GA999	8401180264	8401180259	84/01/04	50-219 P
8401170416	8401170412	84/01/10	50-277 F	8401180265	8401180261	83/01/10	50-244 Q
8401170419	8401170412	84/01/10	50-277 F	8401180268	8401180231	84/01/04	50-387 Q
8401170420	8401170413	84/01/06	50-354 A	8401180270	8401180266	84/01/10	50-245 Q
8401170422	8401170418	83/12/22	50-285 Q	8401180274	8401180269	84/01/16	50-322 T
8401170424	8401170414	83/11/28	50-369 Q	8401180277	8401180269	84/01/16	50-322 T
8401170426	8401170413	84/01/06	50-354 A	8401180281	8401180269	84/01/16	50-322 T
8401170433	8401170431	84/01/10	50-324 P	8401180284	8401180269	84/01/16	50-322 T
8401170440	8401170437	84/01/11	50-280 P	8401180288	8401180269	84/01/16	50-322 T
8401170487	8401170421	84/01/10	50-313 Q	8401190004	8401190003	83/12/16	50-374 P
8401170491	8401170484	84/01/06	50-269 F	8401190005	8401190003	83/12/16	50-374 P
8401170499	8401170480	84/01/03	50-312 P	8401190077	8004280166	80/03/07	71-9010
8401170504	8401170501	83/12/29	50-331 P	8401190088	8401190085	83/11/16	71-9044
8401170512	8401170506	83/12/15	CONTRACT	8401190093	8401190085	83/11/16	71-9044
8401170522	8401170480	84/01/03	50-312 P	8401190102	8401190097	83/12/29	70-2946
8401170525	8401170519	83/12/02	CONTRACT	8401190113	8401190108	83/12/15	50-362 P
8401170528	8401170524	84/01/05	REVIEW ORP	8401190129	8401190127	84/01/04	50-309 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8401190134	8401190149	83/12/28	50-282	Q	8401200062	8401200059	84/01/16	50-482	A
8401190170	8401190167	84/01/16	50-322	Q	8401200064	8401200055	83/12/30	TOPREP	
8401190182	8401190179	84/01/03	50-358	A	8401200074	8401200072	84/01/06	50-397	Q
8401190197	8401190183	84/01/13	50-358	Q	8401200085	8401200081	83/12/22	50-282	Q
8401190203	8401190183	84/01/13	50-358	Q	8401200089	8401200086	84/01/17	50-261	Q
8401190243	8401190237	83/12/28	50-305	P	8401200091	8401200086	84/01/17	50-261	Q
8401190246	8401190237	83/12/28	50-305	P	8401200121	8401200115	84/01/18	50-244	P
8401190268	8401190261	84/01/09	50-348	P	8401200131	8401200128	83/12/31	50-324	P
8401190276	8401190261	84/01/09	50-348	P	8401200134	8401200128	83/12/31	50-324	P
8401190286	8401190281	84/01/05	50-329	Q	8401200145	8401200139	84/01/13	50-482	F
8401190291	8401190281	84/01/05	50-329	Q	8401200146	8401200144	84/01/18	50-413	Q
8401190309	8401190307	84/01/12	50-390	A	8401200165	8401200163	84/01/04	50-336	P
8401190321	8401190315	83/12/30	50-263	Q	8401200168	8401200163	84/01/04	50-336	P
8401190324	8401190315	83/12/30	50-263	Q	8401200189	8401200188	84/01/13	50-261	P
8401190332	8401190327	84/01/09	CONTRACT		8401200193	8401200191	84/01/05	50-397	Q
8401190333	8401190330	84/01/13	50-305	Q	8401200199	8401200194	84/01/12	50-259	I
8401190339	8401190336	84/01/16	50-289	Q	8401200206	8401200194	84/01/12	50-259	I
8401190340	8401190337	84/01/04	50-250	P	8401200210	8401200209	84/01/04	COMMISSION	
8401190342	8401190336	84/01/16	50-289	Q	8401200211	8401200208	84/01/06	50-261	Q
8401190344	8401190336	84/01/16	50-289	Q	8401200212	8401200209	84/01/04	COMMISSION	
8401190346	8401190337	84/01/04	50-250	P	8401200214	8401200209	84/01/04	COMMISSION	
8401190349	8401190345	84/01/06	50-322	Q	8401200216	8401200209	84/01/04	COMMISSION	
8401190356	8401190354	83/12/27	CONTRACT		8401200218	8401200209	84/01/04	COMMISSION	
8401190364	8401190360	83/12/15	50-409	Q	8401200220	8401200209	84/01/04	COMMISSION	
8401190366	8401190365	84/01/13	50-220	P	8401200223	8401200221	84/01/12	50-269	V
8401190369	8401190365	84/01/13	50-220	P	8401200224	8401200222	84/01/16	50-302	P
8401190373	8401190370	84/01/03	50-410	Q	8401200234	8401200232	84/01/06	50-324	P
8401190374	8401190371	84/01/10	50-315	S	8401200280	8401200272	84/01/13	71-9853	
8401190375	8401190371	84/01/10	50-315	S	8401200288	8401200284	84/01/17	50-348	F
8401190379	8401190377	84/01/06	50-334	Q	8401200296	8401200291	84/01/17	50-458	F
8401190381	8401190380	83/12/07	50-346	Q	8401200299	8401200293	84/01/13	71-5797	
8401190382	8401190377	84/01/06	50-334	Q	8401200300	8401200291	84/01/17	50-458	F
8401190383	8401190380	83/12/07	50-346	Q	8401200308	8401200303	84/01/17	50-382	F
8401190384	8401190376	84/01/06	50-220	Q	8401230005	8401230001	83/11/07	FOIA	
8401190386	8401190380	83/12/07	50-346	Q	8401230008	8401230001	83/11/07	FOIA	
8401190392	8401190387	84/01/13	50-282	P	8401230009	8401230007	84/01/10	50-400	A
8401190394	8401190387	84/01/13	50-282	P	8401230011	8401230001	83/11/07	50-289	U
8401190396	8401190393	83/12/28	50-305	Q	8401230015	8401230001	83/11/07	50-320	P
8401190399	8401190395	83/12/29	50-483	Q	8401230019	8401230001	83/11/07	FOIA	
8401190401	8401190393	83/12/28	50-305	Q	8401230023	8401230001	83/11/07	FOIA	
8401190410	8401190408	83/12/28	50-315	Q	8401230026	8401230001	83/11/07	50-289	U
8401190412	8401190408	83/12/28	50-315	Q	8401230028	8401230024	84/01/16	50-352	A
8401190418	8401190416	83/12/19	70-587		8401230030	8401230001	83/11/07	50-289	P
8401190422	8401190419	84/01/16	50-266	P	8401230031	8401230028	83/12/27	CONTRACT	
8401190432	8401190429	84/01/17	50-155	P	8401230040	8401230035	84/01/12	50-346	P
8401190436	8401190433	84/01/06	50-29	Q	8401230045	8401230035	84/01/12	50-346	P
8401190439	8401190433	84/01/06	50-29	Q	8401230048	8401200232	84/01/06	50-324	P
8401190440	8401190434	83/12/30	50-295	Q	8401230061	8401230052	83/11/01	50-289	P
8401190447	8401190434	83/12/30	50-295	Q	8401230067	8401230052	83/11/01	50-289	P
8401190451	8401190444	84/01/06	50-348	P	8401230070	8401230052	83/11/01	50-289	P
8401190452	8401190445	84/01/13	50-352	F	8401230079	8401230052	83/11/01	50-289	P
8401190457	8401190445	84/01/13	50-352	F	8401230144	8401230142	83/12/14	40-7982	
8401190460	8401190444	84/01/06	50-348	P	8401230148	8401230142	83/12/14	40-7982	
8401190462	8401190445	84/01/13	50-352	F	8401230160	8401230155	83/12/22	50-458	Q
8401190466	8401190445	84/01/13	50-352	F	8401230184	8401230175	84/01/16	50-423	K
8401190471	8401190469	83/12/13	CONTRACT		8401230202	8401230196	83/12/23	0A999	
8401190475	8401190445	84/01/13	50-352	F	8401230204	8401230182	84/01/16	CONTRACT	
8401190478	8401190445	84/01/13	50-352	F	8401230210	8401230208	83/12/13	0A999	
8401190483	8401190445	84/01/13	50-352	F	8401230214	8401230208	83/12/13	0A999	
8401190486	8401190445	84/01/13	50-352	F	8401230220	8401230208	83/12/13	0A999	
8401190489	8401190445	84/01/13	50-352	F	8401230228	8401230224	84/01/16	0A999	
8401190497	8401190493	83/12/21	50-397	U	8401230230	8401230225	84/01/09	50-440	Q
8401190515	8401190510	84/01/04	WASTE MGT		8401230234	8401230225	84/01/09	50-440	Q
8401190542	8401190538	84/01/05	50-395	P	8401230237	8401230235	84/01/12	50-293	Q
8401190544	8401190538	84/01/05	50-395	P	8401230248	8401230244	84/01/13	50-261	Q
8401200003	8401200001	84/01/18	50-416	P	8401230287	8401230281	83/12/23	0A999	
8401200020	8401200016	83/12/28	50-324	P	8401230291	8401230282	84/01/11	0A999	
8401200022	8401200018	84/01/05	50-397	Q	8401230294	8401230285	84/01/13	50-373	Q
8401200023	8401200017	83/12/30	50-312	Q	8401230296	8401230281	83/12/23	0A999	
8401200026	8401200016	83/12/28	50-324	P	8401230301	8401230295	84/01/18	50-440	Q
8401200028	8401200027	84/01/05	50-397	Q	8401230306	8401230279	84/01/16	50-373	Q
8401200032	8401200030	84/01/10	50-348	P	8401230309	8401230302	83/12/22	50-267	Q
8401200034	8401200030	84/01/10	50-348	P	8401230310	8401230303	84/01/17	50-454	Q
8401200037	8401200036	83/12/30	50-263	P	8401230313	8401230304	84/01/05	50-483	F
8401200038	8401200036	83/12/30	50-263	P	8401230314	8401230308	84/01/05	50-220	P
8401200053	8401200051	84/01/16	50-528	F	8401230318	8401230308	84/01/05	50-220	P
8401200057	8401200054	83/12/21	COMMISSION		8401230328	8401230324	84/01/17	70-925	
8401200058	8401200052	83/12/30	70-36		8401230329	8401230320	84/01/12	0A999	
8401200060	8401200055	83/12/30	TOPREP		8401230332	8401230327	84/01/12	50-237	P
8401200061	8401200052	83/12/30	70-36		8401230334	8401230315	84/01/13	50-373	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

555

ACCESSION NUMBER				ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401230337	8401230335	84/01/16	50-289 F	8401240200	8401240193	84/01/05	50-129 Q
8401230339	8401230315	84/01/13	50-373 Q	8401240202	8401240183	84/01/17	50-316 S
8401230342	8401230315	84/01/13	50-373 Q	8401240205	8401240193	84/01/05	50-129 Q
8401230343	8401230341	84/01/17	50-461 Q	8401240209	8401240197	84/01/18	50-219 Q
8401230359	8401230358	84/01/16	0A999	8401240210	8401240193	84/01/05	50-129 Q
8401230361	8401230358	84/01/16	0A999	8401240212	8401240206	84/01/19	50-302 R
8401230364	8401230358	84/01/16	0A999	8401240213	8401240193	84/01/05	50-129 Q
8401230372	8401230351	84/01/13	50-373 Q	8401240216	8401240193	84/01/05	50-129 Q
8401230374	8401230367	84/01/18	50-315 Q	8401240219	8401240206	84/01/19	50-302 R
8401230380	8401230377	84/01/11	0A999	8401240222	8401240193	84/01/05	50-129 Q
8401230383	8401230381	84/01/12	0A999	8401240236	8401240224	84/01/20	50-289 Q
8401230386	8401230381	84/01/12	0A999	8401240239	8401240224	84/01/20	50-289 Q
8401230387	8401230379	84/01/09	50-483 Q	8401240241	8401240238	84/01/16	50-142 Q
8401230395	8401230391	84/01/18	50-400 Q	8401240253	8401240243	84/01/06	50-250 Q
8401230396	8401230390	84/01/11	50-358 Q	8401240261	8401240255	84/01/20	50-434 A
8401230397	8401230391	84/01/18	50-400 Q	8401240265	8401240243	84/01/06	50-250 Q
8401230413	8401230405	84/01/17	50-302 P	8401240267	8401240263	84/01/13	50-348 S
8401230433	8401230424	84/01/13	50-373 P	8401240271	8401240243	84/01/06	50-250 Q
8401230436	8401230430	84/01/16	0A999	8401240275	8401240263	84/01/13	50-348 S
8401230442	8401230434	83/12/21	50-10 Q	8401240277	8401240274	84/01/19	50-317 Q
8401230443	8401230438	84/01/17	50-400 Q	8401240278	8401240243	84/01/06	50-250 Q
8401230444	8401230429	84/01/13	50-305 P	8401240291	8401240284	84/01/19	50-307 P
8401230452	8401230451	84/01/20	40-2061	8401240295	8401240280	84/01/07	50-317 Q
8401230460	8401230451	84/01/20	40-2061	8401240297	8401240270	84/01/13	50-369 S
8401230461	8401230454	84/01/17	50-272 Q	8401240300	8401240296	84/01/20	50-413 Q
8401230463	8401230456	84/01/13	50-249 P	8401240302	8401240290	84/01/13	50-369 S
8401230465	8401230457	84/01/09	0A999	8401240303	8401240299	84/01/20	50-407 Q
8401230468	8401230466	84/01/18	50-400 Q	8401240309	8401240307	84/01/10	50-354 Q
8401230474	8401230470	84/01/17	50-400 K	8401240310	8401240306	84/01/20	50-344 Q
8401230495	8401230488	83/12/16	50-424 B	8401240312	8401240290	84/01/13	50-369 S
8401230496	8401230484	83/12/23	0A999	8401240313	8401240307	84/01/10	50-354 Q
8401230497	8401230493	84/01/18	50-329 R	8401240318	8401240308	84/01/10	50-412 Q
8401230499	8401230484	83/12/23	0A999	8401240320	8401240314	84/01/06	50-282 Q
8401230500	8401230494	84/01/17	50-443 F	8401240321	8401240314	84/01/06	50-282 Q
8401230503	8401230484	83/12/23	0A999	8401240323	8401240317	84/01/03	50-390 Q
8401230505	8401230502	84/01/09	0A999	8401240324	8401240290	84/01/13	50-369 S
8401230508	8401230502	84/01/09	0A999	8401240325	8401240319	84/01/12	50-369 Q
8401230512	8401230502	84/01/09	0A999	8401240327	8401240316	84/01/20	50-346 Q
8401230513	8401230510	84/01/03	50-346 Q	8401240329	8401240317	84/01/03	50-390 Q
8401230520	8401230494	84/01/17	50-443 F	8401240331	8401240326	84/01/11	50-395 Q
8401230523	8401230510	84/01/03	50-346 Q	8401240332	8401240314	84/01/06	50-282 Q
8401230549	8401230544	84/01/09	50-287 P	8401240336	8401240326	84/01/11	50-395 Q
8401230555	8401230554	83/12/21	40-2061	8401240338	8401240330	84/01/10	70-143 Q
8401230572	8401230563	84/01/16	50-309 Q	8401240339	8401240334	84/01/13	50-438 Q
8401230576	8401230573	84/01/19	50-220 F	8401240341	8401240334	84/01/13	50-438 Q
8401230578	8401230573	84/01/19	50-220 F	8401240343	8401240326	84/01/11	50-395 Q
8401230583	8401230573	84/01/19	50-220 F	8401240344	8401240334	84/01/13	50-438 Q
8401230589	8312120112	84/01/10	50-358 Q	8401240346	8401240330	84/01/10	70-143 Q
8401230600	8312120112	84/01/10	50-358 Q	8401240347	8401240334	84/01/13	50-438 Q
8401230612	8312120112	84/01/10	50-358 Q	8401240348	8401240319	84/01/12	50-369 Q
8401230615	8401230602	83/12/27	50-324 P	8401240352	8401240334	84/01/13	50-438 Q
8401230620	8401230610	83/11/22	FOIA	8401240354	8401240319	84/01/12	50-369 Q
8401230625	8401230610	83/11/22	FOIA	8401240355	8401240351	83/12/30	50-413 Q
8401230626	8401230602	83/12/27	50-324 P	8401240357	8401240356	84/01/12	70-1151
8401230639	8401230630	83/11/01	50-329 Q	8401240358	8401240353	83/12/08	40-17
8401230644	8401230630	83/11/01	50-329 Q	8401240359	8401240326	84/01/11	50-395 Q
8401230645	8401230640	84/01/18	50-298 F	8401240361	8401240356	84/01/12	70-1151
8401230647	8401230640	84/01/18	50-298 F	8401240362	8401240356	84/01/12	70-1151
8401230651	8401230630	83/11/01	50-329 Q	8401240364	8401240360	83/12/22	50-395 Q
8401230654	8401230650	84/01/18	50-346 Q	8401240365	8401240356	84/01/12	70-1151
8401230661	8401230656	84/01/18	50-528 F	8401240367	8401240319	84/01/12	50-369 Q
8401230664	8401230662	84/01/18	50-213 F	8401240369	8401240363	84/01/19	50-3
8401230667	8401230662	84/01/18	50-213 F	8401240371	8401240319	84/01/12	50-369 Q
8401230706	8401230705	83/12/21	CONTRACT	8401240373	8401240319	84/01/12	50-369 Q
8401240051	8401240047	83/12/27	50-259 P	8401240375	8401240370	83/12/27	70-27
8401240054	8401240047	83/12/27	50-259 P	8401240380	8401240319	84/01/12	50-369 Q
8401240059	8401240056	84/01/10	50-272 Q	8401240393	8401240388	84/01/16	50-322 A
8401240062	8401240075	83/12/21	50-280 Q	8401240394	8401240391	84/01/11	50-302 Q
8401240069	8401240084	83/12/22	50-424 Q	8401240396	8401240391	84/01/11	50-302 Q
8401240102	8401240099	84/01/18	50-321 F	8401240399	8401240391	84/01/11	50-302 Q
8401240106	8401240099	84/01/18	50-321 F	8401240401	8401240391	84/01/11	50-302 Q
8401240114	8401240111	83/12/28	PR	8401240404	8401240389	84/01/17	50-413 S
8401240126	8401240109	84/01/10	50-29 Q	8401240407	8401240398	84/01/13	50-259 Q
8401240143	8401240138	84/01/18	50-395 P	8401240412	8401240408	84/01/11	50-261 Q
8401240151	8401240147	84/01/19	50-206 P	8401240413	8401240408	84/01/11	50-261 Q
8401240176	8401240170	84/01/20	40-8760	8401240414	8401240398	84/01/13	50-259 Q
8401240179	8401240172	84/01/12	50-206 H	8401240417	8401240408	84/01/11	50-261 Q
8401240180	8401240175	84/01/16	50-309 P	8401240422	8401240398	84/01/13	50-259 Q
8401240181	8401240174	84/01/20	50-352 Q	8401240423	8401240408	84/01/11	50-261 Q
8401240191	8401240183	84/01/17	50-316 S	8401240425	8401240419	84/01/06	50-302 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER					ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8401240426	8401240420	84/01/09	50-483	Q	8401240632	8401240630	84/01/20	50-348	F
8401240428	8401240398	84/01/13	50-239	Q	8401240633	8401240623	84/01/16	QA999	
8401240429	8401240419	84/01/06	50-302	Q	8401240634	8401240623	84/01/16	QA999	
8401240433	8401240419	84/01/06	50-302	Q	8401240635	8401240631	84/01/20	50-387	F
8401240437	8401240419	84/01/06	50-302	Q	8401240636	8401240623	84/01/16	QA999	
8401240446	8401240419	84/01/06	50-302	Q	8401240639	8401240623	84/01/16	QA999	
8401240447	8401240438	83/12/22	50-335	Q	8401240641	8401240623	84/01/16	QA999	
8401240452	8401240443	83/12/28	50-406	Q	8401240642	8401240638	84/01/20	50-348	F
8401240454	8401240451	84/01/11	QA999		8401240643	8401240623	84/01/16	QA999	
8401240457	8401240445	84/01/09	50-289	Q	8401240644	8401240623	84/01/16	QA999	
8401240459	8401240451	84/01/11	QA999		8401240645	8401240638	84/01/20	50-348	F
8401240460	8401240456	84/01/19	50-352	A	8401240646	8401240623	84/01/16	QA999	
8401240463	8401240451	84/01/11	QA999		8401240648	8401240647	84/01/20	50-261	F
8401240465	8401240451	84/01/11	QA999		8401240650	8401240649	84/01/20	50-346	F
8401240470	8401240468	84/01/10	50-423	Q	8401240652	8401240651	84/01/20	50-254	F
8401240472	8401240468	84/01/10	50-423	Q	8401250003	8401250002	84/01/17	50-348	F
8401240473	8401240467	84/01/10	50-423	Q	8401250007	8401250006	84/01/20	TOPREP	
8401240476	8401240466	84/01/10	50-29	Q	8401250018	8401250014	84/01/18	50-346	F
8401240479	8401240474	84/01/20	50-346	Q	8401250019	8401250016	84/01/20	50-244	P
8401240488	8401240477	84/01/11	50-281	Q	8401250021	8401250016	84/01/20	50-244	P
8401240497	8401240477	84/01/11	50-281	Q	8401250022	8401250020	84/01/18	50-285	F
8401240498	8401240490	84/01/06	50-324	Q	8401250025	8401250020	84/01/18	50-285	F
8401240499	8401240492	84/01/05	50-458	Q	8401250031	8401250027	84/01/18	50-387	F
8401240507	8401240492	84/01/05	50-458	Q	8401250033	8401250028	84/01/20	50-315	P
8401240510	8401240504	84/01/10	50-352	Q	8401250039	8401250035	84/01/18	50-387	F
8401240512	8401240477	84/01/11	50-281	Q	8401250047	8401250042	84/01/20	50-454	F
8401240517	8401240477	84/01/11	50-281	Q	8401250049	8401250043	84/01/20	50-483	F
8401240521	8401240513	84/01/10	50-247	Q	8401250052	8401250045	84/01/20	50-483	F
8401240527	8401240516	84/01/10	50-271	Q	8401250054	8401250050	84/01/20	50-285	F
8401240530	8401240520	84/01/10	50-272	Q	8401250055	8401250051	84/01/18	50-252	F
8401240536	8401240524	84/01/04	50-390	Q	8401250059	8401250058	84/01/18	50-331	F
8401240541	8401240524	84/01/04	50-390	Q	8401250060	8401250057	84/01/18	50-313	F
8401240542	8401240535	84/01/20	50-329	A	8401250064	8401250062	84/01/18	50-277	F
8401240544	8401240524	84/01/04	50-390	Q	8401250066	8401250062	84/01/18	50-277	F
8401240547	8401240533	83/12/28	50-160	Q	8401250070	8401250068	84/01/18	50-433	F
8401240549	8401240524	84/01/04	50-390	Q	8401250075	8401250073	84/01/18	50-483	F
8401240552	8401240534	83/12/22	50-297	Q	8401250077	8401250073	84/01/18	50-483	F
8401240553	8401240551	83/12/23	50-388	Q	8401250083	8401250078	84/01/11	50-454	Q
8401240563	8401240557	84/01/18	50-395	P	8401250085	8401250081	84/01/18	50-313	F
8401240564	8401240546	84/01/09	QA999		8401250086	8401250082	84/01/18	50-10	F
8401240565	8401240558	84/01/11	50-348	Q	8401250087	8401250078	84/01/11	50-454	Q
8401240567	8401240558	84/01/11	50-348	Q	8401250089	8401250082	84/01/18	50-10	F
8401240568	8401240562	84/01/09	50-302	Q	8401250095	8401250091	84/01/18	50-244	F
8401240571	8401240558	84/01/11	50-348	Q	8401250096	8401250093	84/01/18	50-243	F
8401240572	8401240570	84/01/20	50-219	P	8401250100	8401250091	84/01/18	50-244	F
8401240574	8401240569	83/12/15	50-438	Q	8401250102	8401250099	84/01/18	50-155	F
8401240575	8401240562	84/01/09	50-302	Q	8401250104	8401250105	83/10/18	50-289	P
8401240577	8401240566	84/01/19	50-272	Q	8401250108	8401250105	84/01/18	50-113	F
8401240578	8401240546	84/01/09	QA999		8401250109	8401250104	84/01/16	50-244	F
8401240580	8401240558	84/01/11	50-348	Q	8401250112	8401250105	83/10/18	FOIA	
8401240581	8401240562	84/01/09	50-302	Q	8401250114	8401250103	84/01/19	50-409	P
8401240583	8401240569	83/12/15	50-438	Q	8401250116	8401250111	84/01/18	50-29	F
8401240584	8401240579	84/01/13	50-321	Q	8401250117	8401250015	83/10/18	FOIA	
8401240585	8401240562	84/01/09	50-302	Q	8401250118	8401250110	84/01/20	50-259	F
8401240587	8401240569	83/12/15	50-438	Q	8401250122	8401250119	84/01/12	CONTRACT	
8401240588	8401240579	84/01/13	50-321	Q	8401250123	8401250120	84/01/18	50-295	F
8401240589	8401240562	84/01/09	50-302	Q	8401250126	8401250110	84/01/20	50-259	F
8401240590	8401240569	83/12/15	50-438	Q	8401250130	8401250127	84/01/18	50-315	F
8401240591	8401240579	84/01/13	50-321	Q	8401250132	8401250131	84/01/21	50-387	P
8401240592	8401240546	84/01/09	QA999		8401250138	8401250135	84/01/18	50-295	F
8401240593	8401240586	84/01/16	50-390	Q	8401250139	8401250136	83/11/04	70-712	
8401240597	8401240579	84/01/13	50-321	Q	8401250142	8401250136	83/11/04	40-1478	
8401240599	8401240569	83/12/15	50-438	Q	8401250143	8401250136	83/11/04	40-1478	
8401240600	8401240596	84/01/10	50-352	Q	8401250145	8401250141	84/01/18	50-261	F
8401240601	8401240586	84/01/16	50-390	Q	8401250146	8401250136	83/11/04	40-1478	
8401240603	8401240586	84/01/16	50-390	Q	8401250148	8401250015	83/10/18	40-2061	
8401240604	8401240596	84/01/10	50-352	Q	8401250149	8401250141	84/01/18	50-261	F
8401240606	8401240598	83/12/29	50-348	Q	8401250150	8401250136	83/11/04	40-1478	
8401240608	8401240586	84/01/16	50-390	Q	8401250151	8401250147	84/01/20	50-322	F
8401240613	8401240607	83/12/28	50-413	Q	8401250152	8401250144	83/12/30	50-263	P
8401240616	8401240611	84/01/20	50-259	F	8401250153	8401250136	83/11/04	40-1478	
8401240617	8401240615	84/01/20	50-286	F	8401250155	8401250147	84/01/20	50-322	F
8401240619	8401240586	84/01/19	50-272	Q	8401250157	8401250136	83/11/04	40-1478	
8401240621	8401240611	84/01/20	50-259	F	8401250164	8401250015	83/10/18	50-358	A
8401240622	8401240620	84/01/20	50-159	F	8401250182	8401250163	83/11/02	FOIA	
8401240625	8401240623	84/01/16	QA999		8401250185	8401250163	83/11/02	50-289	F
8401240626	8401240611	84/01/20	50-259	F	8401250188	8401250163	83/11/02	FOIA	
8401240627	8401240624	84/01/20	50-348	F	8401250192	8401250163	83/11/02	50-344	F
8401240628	8401240566	84/01/19	50-272	Q	8401250217	8312120125	84/01/16	50-275	P
8401240629	8401240623	84/01/16	QA999		8401250223	8401250015	83/10/18	FOIA	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

557

ACCESSION NUMBER

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401250237	8312120157	84/01/23	50-445 S	8401260177	8401260166	84/01/13	50-387 G
8401250240	8401250015	83/10/18	FOIA	8401260185	8401260181	84/01/18	50-348 F
8401250241	8401250163	83/11/02	50-312 F	8401260186	8401260182	84/01/13	50-412 G
8401250243	8312120157	84/01/23	50-445 S	8401260189	8401260184	84/01/17	50-322 Q
8401250258	8401250015	83/10/18	FOIA	8401260194	8401260188	84/01/18	50-298 F
8401250263	8401250015	83/10/18	50-251 Q	8401260197	8401260191	84/01/12	CONTRACT
8401250267	8401250265	83/12/28	70-1151	8401260198	8401260188	84/01/18	50-298 F
8401250268	8401250163	83/11/02	FOIA	8401260204	8401260196	84/01/13	50-388 G
8401250269	8401250015	83/10/18	50-358 Q	8401260205	8401260201	84/01/20	50-338 F
8401250272	8401250262	84/01/10	50-413 Q	8401260207	8401260202	84/01/24	50-289 Q
8401250275	8401250260	84/01/19	50-244 P	8401260214	8401260208	84/01/23	50-289 Q
8401250281	8401250163	83/11/02	FOIA	8401260217	8401260213	84/01/20	50-320 F
8401250282	8401250260	84/01/19	50-244 P	8401260222	8401260208	84/01/23	50-289 Q
8401250283	8401250163	83/11/02	50-320 S	8401260228	8401260224	84/01/20	50-261 F
8401250284	8401250279	84/01/16	50-320 P	8401260233	8401260229	84/01/20	50-346 F
8401250286	8401250163	83/11/02	50-263 F	8401260238	8401260234	84/01/20	50-320 F
8401250287	8401250279	84/01/16	50-320 P	8401260240	8401260235	84/01/20	50-112 F
8401250292	8401250289	84/01/18	50-244 P	8401260243	8401260241	84/01/18	50-295 F
8401250293	8401250289	84/01/18	50-244 P	8401260244	8401260242	84/01/20	50-315 F
8401250296	8401250294	84/01/12	50-331 P	8401260251	8401260245	84/01/18	50-313 F
8401250298	8401250285	83/12/21	70-143	8401260252	8401260247	84/01/18	50-295 F
8401250299	8401250297	84/01/18	50-244 P	8401260255	8401260246	83/12/28	50-325 P
8401250300	8401250285	83/12/21	70-143	8401260257	8401260253	84/01/18	50-338 F
8401250301	8401250297	84/01/18	50-244 P	8401260259	8401260250	84/01/19	50-266 F
8401250302	8401250015	83/10/18	50-537 Q	8401260261	8401260246	83/12/28	50-325 P
8401250303	8401250297	84/01/18	50-244 P	8401260262	8401260250	84/01/19	50-266 F
8401250311	8401250015	83/10/18	50-289 P	8401260263	8401260258	84/01/18	50-295 F
8401250312	8401250309	84/01/18	50-373 F	8401260265	8401260260	84/01/20	50-250 F
8401250314	8401250309	84/01/18	50-373 F	8401260270	8401260266	84/01/18	50-348 F
8401250316	8401250315	84/01/18	50-395 F	8401260286	8401260269	84/01/18	50-416 F
8401250318	8401250315	84/01/18	50-395 F	8401260289	8401260287	84/01/20	50-454 F
8401250320	8312120126	84/01/12	PR	8401260291	8401260288	84/01/20	50-289 F
8401250321	8401250319	84/01/18	50-390 F	8401260294	8401260290	84/01/20	50-3 F
8401250322	8401250015	83/10/18	FOIA	8401260297	8401260293	84/01/20	50-373 F
8401250323	8312120126	84/01/12	PR	8401260299	8401260296	84/01/20	50-348 F
8401250324	8401250319	84/01/18	50-390 F	8401260305	8401260301	84/01/20	50-313 F
8401250325	8401250015	83/10/18	50-255 P	8401260309	8401260300	84/01/10	50-336 Q
8401250328	8401250326	84/01/09	50-454 M	8401260315	8401260308	84/01/12	70-135
8401250329	8401250326	84/01/09	50-454 M	8401260316	8401260312	84/01/20	50-313 F
8401250334	8401250331	84/01/03	70-2985	8401260324	8401260320	84/01/20	50-245 F
8401250333	8401250015	83/10/18	50-274 P	8401260331	8401260327	84/01/16	50-412 A
8401250337	8401250015	83/10/18	FOIA	8401260334	8401260330	84/01/20	50-348 F
8401250363	8401250015	83/10/18	FOIA	8401260337	8401260327	84/01/16	50-412 A
8401250364	8401250012	84/01/18	50-409 F	8401260369	8401260367	84/01/13	50-289 Q
8401250366	8401250355	84/01/12	CONTRACT	8401260379	8401260376	84/01/18	50-346 F
8401250369	8401250012	84/01/18	50-409 F	8401260384	8401260376	84/01/18	50-346 F
8401250370	8401250015	83/10/18	50-219 P	8401260401	8401260398	84/01/20	50-320 F
8401250376	8401250015	83/10/18	FOIA	8401260409	8401260403	84/01/20	50-454 F
8401250385	8401250015	83/10/18	FOIA	8401260413	8401260407	84/01/20	50-387 F
8401250430	8401250446	84/01/11	50-324 P	8401260422	8401260407	84/01/20	50-387 F
8401260002	8401260001	84/01/23	50-324 P	8401260485	8401260477	84/01/05	CONTRACT
8401260010	8401260007	84/01/04	WASTE MGT	8401260501	8401260250	84/01/19	50-266 F
8401260017	8401260014	84/01/18	50-409 F	8401260511	8401260509	84/01/12	50-443 F
8401260021	8401260014	84/01/18	50-409 F	8401270002	8401270001	84/01/05	50-498 Q
8401260027	8401260024	84/01/18	50-313 F	8401270003	8401270001	84/01/05	50-498 Q
8401260029	8401260024	84/01/18	50-313 F	8401270010	8401270006	84/01/13	50-416 P
8401260032	8401260024	84/01/18	50-313 F	8401270013	8401270006	84/01/13	50-416 P
8401260036	8401260034	84/01/18	50-395 F	8401270021	8401270019	83/12/29	50-220 P
8401260041	8401260037	84/01/18	50-285 F	8401270072	8401270066	83/12/20	50-313 Q
8401260054	8401260052	84/01/18	50-29 F	8401270085	8401270083	84/01/18	50-298 P
8401260059	8401260056	84/01/18	50-321 F	8401270145	8401270140	83/12/30	50-267 P
8401260066	8401260063	84/01/18	50-289 F	8401270147	8401270142	84/01/10	40-299
8401260084	8401260078	84/01/11	50-315 Q	8401270151	8401270140	83/12/30	50-267 P
8401260086	8401260083	84/01/04	50-321 P	8401270172	8401270167	83/11/18	40-299
8401260090	8401260078	84/01/11	50-315 Q	8401270175	8401270170	83/12/29	50-293 P
8401260091	8401260083	84/01/04	50-321 P	8401270186	8401270170	83/12/29	50-293 P
8401260093	8401260087	83/12/30	50-362 P	8401270192	8401270190	84/01/19	50-289 P
8401260129	8401260128	84/01/20	50-155 Q	8401270195	8401270188	84/01/23	50-275 Q
8401260140	8401260135	84/01/18	50-389 F	8401270196	8401270191	84/01/16	TOPREP
8401260145	8401260135	84/01/18	50-389 F	8401270214	8401270211	84/01/18	0A999
8401260146	8401260141	84/01/20	50-440 Q	8401270217	8401270212	84/01/24	50-289 Q
8401260149	8401260142	84/01/11	50-352 Q	8401270224	8401270222	84/01/23	50-333 P
8401260152	8401260147	84/01/18	50-387 F	8401270225	8401270218	84/01/24	50-206 P
8401260153	8401260142	84/01/11	50-352 Q	8401270227	8401270222	84/01/23	50-333 P
8401260158	8401260156	84/01/18	50-309 F	8401270229	8401270218	84/01/24	50-206 P
8401260163	8401260142	84/01/11	50-352 Q	8401270249	8401270246	84/01/09	0A999
8401260168	8401260142	84/01/11	50-352 Q	8401270253	8401270246	84/01/09	0A999
8401260172	8401260142	84/01/11	50-352 Q	8401270270	8401270266	84/01/25	50-361 P
8401260174	8401260170	84/01/18	50-155 F	8401270274	8401270266	84/01/25	50-361 P
				8401270276	8401270263	84/01/04	50-382 Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401270282	8401270263	84/01/04	50-382 Q
8401270297	8401270293	84/01/20	50-346 P
8401270299	8401270285	84/01/18	0A999
8401270306	8401270302	84/01/24	50-528 E
8401270308	8401270305	84/01/23	0A999
8401270310	8401270305	84/01/23	0A999
8401270313	8401270305	84/01/23	0A999
8401270314	8401270305	84/01/23	0A999
8401270317	8401270305	84/01/23	0A999
8401270318	8401270263	84/01/04	50-382 Q
8401270327	8401270263	84/01/04	50-382 Q
8401270331	8401270263	84/01/04	50-382 Q
8401270347	8401270346	84/01/02	50-213 S
8401270350	8401270346	84/01/24	50-344 P
8401270361	8401270359	84/01/06	50-373 Q
8401270366	8401270359	84/01/06	50-373 Q
8401270368	8401270363	84/01/25	50-498 K
8401270379	8401270377	84/01/13	50-395 R
8401270381	8401270376	84/01/23	50-362 P
8401270382	8401270377	84/01/13	50-395 R
8401270383	8401270377	84/01/13	50-395 R
8401270385	8401270377	84/01/13	50-395 R
8401270387	8401270377	84/01/13	50-395 R
8401270388	8401270377	84/01/13	50-395 R
8401270389	8401270377	84/01/13	50-395 R
8401270391	8401270384	84/01/23	50-329 Q
8401270392	8401270377	84/01/13	50-395 R
8401270393	8401270377	84/01/13	50-395 R
8401270394	8401270390	84/01/14	50-346 P
8401270400	8401270395	84/01/20	50-267 P
8401270413	8401270411	84/01/13	50-483 K
8401270426	8401270423	83/12/23	State Prog
8401270434	8401270431	84/01/23	50-344 P
8401270436	8401270422	84/01/03	0A999
8401270437	8401270431	84/01/23	50-344 P
8401270439	8401270435	83/12/13	40-2259
8401270444	8401270422	84/01/03	0A999
8401270445	8401270438	83/12/30	0A999
8401270451	8401270438	83/12/30	0A999
8401270454	8401270450	84/01/24	0A999
8401270462	8401270458	84/01/16	0A999
8401270469	8401270461	84/01/16	50-331 Q
8401270471	8401270468	84/01/09	0A999
8401270473	8401270468	84/01/09	0A999
8401270478	8401270468	84/01/09	0A999
8401270487	8401270479	84/01/26	50-219 P
8401270495	8401270479	84/01/26	50-219 P
8401270497	8401270492	84/01/23	50-271 P
8401270518	8401270507	84/01/06	50-263 Q
8401270524	8401270519	84/01/08	WASTE MGT
8401270530	8401270526	84/01/13	71-5450
8401270535	8401270533	83/12/18	WASTE MGT
8401270539	8401270531	83/12/27	CONTRACT
8401270541	8401270537	83/12/29	50-324 P
8401300008	8401300007	84/01/24	50-409 Q
8401300012	8401300010	83/12/23	CONTRACT
8401300024	8401300022	84/01/13	50-373 Q
8401300026	8401300022	84/01/13	50-373 Q
8401300067	8401300059	83/12/29	50-294 P
8401300091	8401300088	84/01/06	40-8331
8401300100	8401300096	84/01/26	50-424 Q
8401300101	8401300097	83/06/07	WASTE MGT
8401300103	8401300088	84/01/06	40-8331
8401300108	8401300088	84/01/06	40-8331
8401300113	8401300109	83/09/15	WASTE MGT
8401300118	8401300114	84/01/24	50-250 Q
8401300130	8401300126	84/01/25	50-250 Q
8401300141	8401300128	84/01/13	CONTRACT
8401300149	8401300146	84/01/19	40-7982
8401300151	8401300142	84/01/19	50-206 Q
8401300154	8401300153	84/01/13	CONTRACT
8401300160	8401300158	84/01/19	50-206 Q
8401300176	8401300172	83/12/06	50-285 Q
8401300182	8401300172	83/12/06	50-285 Q
8401300188	8401300183	84/01/12	50-206 Q
8401300189	8401300172	83/12/06	50-285 Q
8401300194	8401300190	84/01/25	50-413 Q
8401300197	8401300190	84/01/25	50-413 Q
8401300198	8401300195	84/01/18	50-316 S
8401300201	8401300195	84/01/18	50-316 S

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401300207	8401300202	84/01/24	50-454 Q
8401300210	8401300202	84/01/24	50-454 Q
8401300213	8401300209	84/01/24	50-3 F
8401300215	8401300209	84/01/24	50-3 F
8401300219	8401300209	84/01/24	50-3 F
8401300225	8401300222	84/01/25	50-528 Q
8401300229	8401300227	84/01/26	50-546 Q
8401300230	8401300228	84/01/24	50-142 Q
8401300236	8401300235	84/01/20	50-397 P
8401300243	8401300242	84/01/24	50-315 S
8401300245	8401300242	84/01/24	50-315 S
8401300248	8401300242	84/01/24	50-315 S
8401300255	8401300253	84/01/18	50-326 Q
8401300258	8401300253	84/01/18	50-326 Q
8401300267	8401300265	84/01/25	50-295 P
8401300269	8401300266	84/01/19	50-409 P
8401300272	8401300002	84/01/20	50-298 F
8401300274	8401300270	84/01/13	50-244 Q
8401300278	8401300273	84/01/23	50-296 P
8401300280	8401300277	84/01/11	50-312 Q
8401300282	8401300279	84/01/16	70-754
8401300285	8401300273	84/01/23	50-296 P
8401300286	8401300283	84/01/23	50-443 Q
8401300291	8401300287	84/01/20	50-348 S
8401300294	8401300287	84/01/20	50-348 S
8401300296	8401300273	84/01/23	50-296 P
8401300297	8401300287	84/01/20	50-348 S
8401300302	8401300289	84/01/12	50-528 Q
8401300303	8401300287	84/01/20	50-348 S
8401300306	8401300287	84/01/20	50-348 S
8401300307	8401300304	84/01/26	50-390 K
8401300310	8401300273	84/01/23	50-296 P
8401300313	8401300311	84/01/25	50-312 Q
8401300318	8401300315	84/01/05	50-255 Q
8401300319	8401300317	84/01/13	50-29 P
8401300333	8401300330	84/01/25	50-346 F
8401300339	8401300336	84/01/25	50-213 F
8401300342	8401300336	84/01/25	50-213 F
8401300348	8401300344	84/01/26	50-254 F
8401300353	8401300350	84/01/26	50-289 F
8401300354	8401300349	83/10/21	WASTE MGT
8401300355	8401300352	84/01/26	50-317 F
8401300356	8401300349	83/10/21	WASTE MGT
8401300358	8401300352	84/01/26	50-317 F
8401300364	8401300361	84/01/26	50-313 F
8401300367	8401300365	84/01/26	50-320 F
8401300375	8401300357	84/01/26	50-298 F
8401300376	8401300371	84/01/26	50-341 F
8401300378	8401300020	84/01/19	70-754
8401300379	8401300373	84/01/25	50-389 F
8401300381	8401300371	84/01/26	50-341 F
8401300383	8401300373	84/01/25	50-389 F
8401310016	8401310013	84/01/26	50-133 Q
8401310028	8401310027	84/01/20	50-397 P
8401310039	8401310037	84/01/16	50-334 Q
8401310042	8401310037	84/01/16	50-334 Q
8401310051	8401310049	84/01/18	50-295 F
8401310052	8401310047	84/01/16	50-321 P
8401310056	8401310047	84/01/16	50-321 P
8401310058	8401310054	84/01/18	50-373 F
8401310061	8401310057	84/01/16	50-261 P
8401310063	8401310047	84/01/16	50-321 P
8401310064	8401310054	84/01/18	50-373 F
8401310068	8401310059	84/01/19	CONTRACT
8401310069	8401310060	84/01/20	50-389 F
8401310070	8401310065	84/01/18	50-346 F
8401310072	8401310067	83/12/31	REG00
8401310075	8401310071	84/01/18	50-369 F
8401310080	8401310060	84/01/20	50-389 F
8401310081	8401310077	84/01/18	50-295 F
8401310082	8401310078	84/01/18	50-302 P
8401310084	8401310079	84/01/13	MISC
8401310093	8401310087	84/01/27	50-344 P
8401310097	8401310087	84/01/27	50-344 P
8401310098	8401310090	84/01/06	50-498 A
8401310099	8401310094	84/01/16	70-687
8401310104	8401310090	84/01/06	50-498 A
8401310106	8401310088	84/01/18	50-295 F
8401310108	8401310090	84/01/06	50-498 A
8401310115	8401310109	84/01/20	50-334 F

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

559

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401310117	8401310111	84/01/18	50-387 F
8401310120	8401310116	84/01/24	50-483 A
8401310122	8401310109	84/01/20	50-334 F
8401310133	8401310128	83/11/17	MISC
8401310135	8401310126	84/01/18	50-327 F
8401310144	8401310138	83/12/29	50-528 A
8401310145	8401310141	84/01/26	50-289 P
8401310147	8401310126	84/01/18	50-327 F
8401310148	8401310138	83/12/29	50-528 A
8401310157	8401310153	84/01/26	50-277 P
8401310159	8401310154	84/01/04	70-1143
8401310162	8401310158	84/01/11	50-483 A
8401310166	8401310161	84/01/13	50-277 G
8401310167	8401310165	84/01/16	50-312 P
8401310169	8401310168	84/01/09	50-275 U
8401310172	8401310168	84/01/09	50-275 U
8401310177	8401310175	84/01/09	COMMISSION
8401310180	8401310174	84/01/20	50-10 F
8401310184	8401310181	84/01/13	50-508 D
8401310187	8401310174	84/01/20	50-10 F
8401310192	8401310190	84/01/20	50-483 F
8401310195	8401310191	83/06/02	WASTE MGT
8401310198	8401310194	84/01/20	50-285 F
8401310202	8401310194	84/01/20	50-285 F
8401310209	8401310206	84/01/23	50-395 P
8401310212	8401310170	84/01/20	50-244 F
8401310219	8401310137	84/01/18	50-320 F
8401310224	8401310221	84/01/27	80-409 G
8401310232	8401310225	84/01/25	70-1331
8401310236	8401310229	84/01/20	50-348 F
8401310239	8401310235	84/01/30	50-70 Q
8401310240	8401310229	84/01/20	50-348 F
8401310246	8401310245	84/01/26	50-400 R
8401310247	8401310241	84/01/27	50-458 C
8401310249	8401310170	84/01/20	50-244 F
8401310252	8401310250	84/01/26	50-282 G
8401310263	8401310254	84/01/18	50-263 F
8401310264	8401310261	84/01/23	50-312 P
8401310268	8401310265	84/01/26	50-272 R
8401310271	8401310254	84/01/18	50-263 F
8401310272	8401310270	84/01/25	50-277 G
8401310277	8401310275	84/01/26	50-250 F
8401310282	8401310281	84/01/25	WASTE MGT
8401310285	8401310284	84/01/27	50-322 Q
8401310306	8401310297	84/01/27	50-352 G
8401310311	8401310308	84/01/27	50-413 G
8401310314	8401310309	84/01/23	50-321 P
8401310317	8401310313	84/01/27	50-528 A
8401310332	8401310330	84/01/26	50-445 A
8401310333	8401310328	84/01/26	50-332 G
8401310337	8401310328	84/01/26	50-332 G
8401310342	8401310334	84/01/16	70-2985
8401310354	8401310350	84/01/25	70-368
8401310355	8401310351	84/01/23	50-312 P
8401310362	8401310358	84/01/24	50-280 S
8401310364	8401310357	84/01/27	50-250 Q
8401310367	8401310358	84/01/24	50-280 S
8401310368	8401310356	84/01/26	50-483 Q
8401310384	8401310377	84/01/16	50-352 Q
8401310389	8401310386	84/01/20	50-454 Q
8401310405	8401310401	84/01/27	50-204 P
8401310409	8401310406	84/01/23	50-315 S
8401310412	8401310410	84/01/03	40-8728
8401310414	8401310406	84/01/23	50-315 S
8401310423	8401310421	83/12/22	40-2259
8401310425	8401310413	84/01/25	50-327 P
8401310427	8401190193	84/01/12	OEN TEC IS
8401310431	8401310428	84/01/05	40-1162
8401310433	8401190193	84/01/12	OEN TEC IS
8401310437	8401310433	84/01/16	TOPREP
8401310445	8401310441	84/01/17	50-344 G
8401310446	8401310442	83/12/28	40-4492
8401310450	8401310448	84/01/18	71-5797
8401310454	8401310453	84/01/17	71-9134
8401310455	8401310452	83/10/11	WASTE MGT
8401310460	8401310458	84/01/20	50-313 F
8401310462	8401310459	83/12/27	40-299
8401310464	8401310463	84/01/17	71-96
8401310467	8401310466	84/01/17	71-251
8401310477	8401310475	84/01/12	70-754

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8401310488	8401310484	84/01/03	40-1162
8401310524	8401310522	84/01/19	50-289 P

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

- 3 Transmittal and acknowledgement letters.
4. Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER
3. Transmittal and acknowledgement letters
4. Information on scheduling of submittal or review of ER
5. NRC questions, requests for additional information, and applicant responses.
6. Federal register notices citing the availability of items 1 and 2.
- 7 Correspondence relating to the review of ER
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
2. Supplements to the DES and FES.
3. Correspondence relating to the DES and FES.
4. Comments from other federal, state and local government agencies.
5. Transmittal and acknowledgement letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements
7. Backup technical documents submitted in connection with above.
8. Federal register notice citing availability of items 1 and 2.
9. Site visits to obtain information for DES or FES
10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
2. Supplements to SER
3. Correspondence relating to SER
4. Federal register notices citing availability of items 1 and 2.
5. Information on scheduling of SER submittals and review
6. Requests for additional information for use in preparing SER, responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER
8. Transmittal and acknowledgement letters

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys
2. Plant evacuation correspondence.
3. Safeguards Contingency Plans
4. Review of Health Physics Program.
5. Correspondence relating to aforementioned plans.
6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
2. Federal register notices regarding hearings.
3. Requests to make appearances at hearings.
4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
6. Correspondence to and from intervenors.
7. Board orders and decisions.
8. Petitions for Commission action.
9. Legal filings and Commission orders and decisions resulting from item 8

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

L LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- 1 Limited Work Authorizations (LWA) and amendments
- 2 Correspondence pertaining to work performed under LWA s

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1 Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
4. Federal register notices citing availability of items 1 and 2.
5. Correspondence regarding the Final Safety Analysis Report (FSAR).
6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license
- 7 Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8 Information on the Standard Review Plan (STP).
9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
11. Owner's group meeting announcements and reports.
- 12 Quality assurance information.
13. Environmental matters (technical).
14. Emergency core cooling system documents.
15. Radioactive waste information.
- 16 Correspondence regarding expansion of spent fuel storage pool.
- 17 Start-up test reports.
18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.
2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Pre-service and in-service inspections and procedures.
7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).
8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, semiannual, or annual operating reports (other than financial).
- 2 Periodic environmental monitoring, effluent testing, or similar reports.
- 3 Periodic personnel exposure reports.
- 4 Operational Logbooks.
Logbooks on Environmental Data
Logbooks on Radiological Data
Operations Log on Plant Systems Core
Plant Status Summary Sheets.
- 5 Correspondence or other documents relating to the above listed items

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes.

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e
5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as. Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

With an NMSS license and/or a Docket-72 number. For installations on a Docket-72 number will also be identified.

For proposed amendments to possess power reactor spent fuel with spent storage in an independent spent fuel installations may be on a reactor site or at a separate

above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3. Meeting announcements; description of meeting agendas.
4. Committee generated reports, memoranda, and correspondence that are publicly available.
5. Committee related correspondence.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
2. Solicitations (RFP or IFB) issued by the NRC.
3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG -- Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR -- Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved
2. Text of the Proposed Rule (PR).
3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM -- Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.
2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
3. Applicant's Quality Assurance Manual.
4. Early site review information.
5. Backup technical documents submitted in support of the application.
6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.
2. Notices of deviations.
3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
3. NRC inspection reports of defects cited.
4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
2. Notices of deviations.
3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents
2. Letter reports of accomplishments and data reports, for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
3. State Legislative Reports.
4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
2. Revisions, modifications and amendments to topical reports.
3. Correspondence between NRC and vendors pertaining to the review of submittals.
4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are.

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public.
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (11 81)		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 6, No. 1	
4 TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available January 1-31, 1984.				2. (Leave blank)	
7. AUTHOR(S)				3 RECIPIENT'S ACCESSION NO	
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555				5. DATE REPORT COMPLETED MONTH YEAR	
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Same as 9, above.				6 (Leave blank)	
13 TYPE OF REPORT Monthly				PERIOD COVERED (Inclusive dates) January 1-31, 1984	
15 SUPPLEMENTARY NOTES				8 (Leave blank)	
16 ABSTRACT (200 words or less) <p>This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.</p>					
17 KEY WORDS AND DOCUMENT ANALYSIS				17a DESCRIPTORS	
17b. IDENTIFIERS/OPEN-ENDED TERMS					
18 AVAILABILITY STATEMENT Unlimited				19 SECURITY CLASS (This report) Unclassified	
				21 NO OF PAGES	
				20 SECURITY CLASS (This page) Unclassified	
				22 PRICE \$	